Available from

NRC/GPO Sales Program

Superintendent of Documents
Government Printing Office
Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program
Washington, D. C. 20555

NUREG-0540
Vol. 5, No. 5

Title List of Documents Made Publicly Available

May 1-31, 1983

Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

CONTENTS

Preface v
Arrangement of Items by Docket Number ix
Alphabetic Arrangement of Docket Items by Facility Name xv
Docketed Items
  Low Level Radwaste Disposal Sites — Docket 27 1
  Domestic Licensing of Source Material — Docket 40 1
  Domestic Licensing of Production and Utilization Facilities — Docket 50 10
  Domestic Licensing of Special Nuclear Material — Docket 70 431
  Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71 439
  Licensing of Independent Spent Fuel Storage — Docket 72 444
Nondocketed Items
  10 CFR — Commission Meeting Records 445
  ACRS — Adivsory Committee on Reactor Safeguards 446
  ADVCM — NRC Advisory Committees 447
  COMMISSION — NRC Commissioners 448
  CONTRACT — NRC Contracts and Modifications 450
  FOIA — Freedom of Information Act Requests and Releases 455
  GEN TECH IS — Generic Technical Issues 475
  I&E — Inspection and Enforcement 476
  MISC — Public Document Room Miscellaneous 479
  NUREG — NUREG Reports and Related Correspondence 480
  ORG — Correspondence with Other Organizations 497
  PR — Proposed Rule 498
  PROJ — Projects - Predocket Licensing 501
  PT 21 — Noncompliance Reports and Related Correspondence 502
  QA999 — Quality Assurance Inspections 504
  REGGD — Regulatory Guides 509
  RES — Research and Technical Assistance Reports 509
  REVIEW GROUP — NRC Research Review Groups 510
  SECY — Position Papers Before the Commission 512
  STATE PROG — State Programs 512
  TOPREP — Vendor Reports and Related Correspondence 513
  WASTE MGT — Nuclear Waste Management 518
  XPORTLIC — Export and Import Licenses 519
Personal Author Index 525
Corporate Source Index 557
Report Number Index 589
Cross Reference of Enclosures to Principal Documents 591
Appendix A — Definitions of Docket 50 Categories A-1
Appendix B — Definitions of Nondocketed Categories B-1

PREFACE

The *Title List of Documents Made Publicly Available* is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, *docketed* does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information,* last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

A. Application/construction stage documents and correspondence
B. Utility Preliminary Safety Analysis Report (PSAR), amendments
C. Utility Environmental Report (ER), amendments and correspondence
D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
E. NRC Safety Evaluation Report (SER), supplements and correspondence
F. Security, medical, emergency and fire-protection plans
G. Adjudicatory correspondence
H. General correspondence
I. Financial information
J. Insurance and indemnity information
K. Utility Final Safety Analysis Report (FSAR) and amendments
L. Limited work authorization and related correspondence
M. Antitrust correspondence
N. Antitrust hearing transcripts
O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
P. Operating license stage documents and correspondence
Q. Inspection reports, IE Bulletins and correspondence
R. Periodic operating reports and related correspondence
S. Reportable occurrences. LERs and related correspondence
T. Hearing transcripts on non-antitrust matters
U. Congressional/executive correspondence
V. Licensing operators and related correspondence

W. Decommissioning stage documents and correspondence
X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

(1) P. Operating license stage documents & correspondence

(2) (3)
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.
(4) MILLS, L.M. (5) Tennessee Valley Authority. (6) 82/03/04. (7) VASSALLO, D.B. Operating Reactors Branch 2. (8) 1p. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.
(12) (9) (10) (11)

1. NRC/PDR Document category (see Appendix A).
2. NRC Accession Number (year, month, day, and sequence number of item).
3. Description of information contained in the document.
4. Personal author(s). An asterisk in this position indicates that there is no personal author.
5. Corporate, agency or nonindividual source.
6. Date of document described.
7. Recipient of document and NRC or corporate affiliation.
8. Pages in this document.
9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
10. This three-digit portion of this entry is the number of the frame on which this document starts.
11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
.OSURE — Financial Disclosure Information
Freedom of Information Act Requests and Releases
H IS — Generic Technical Issues

I&E — Inspection and Enforcement
MISC — Public Document Room Miscellaneous
NUREG — NUREG Reports and Related Correspondence
ORG — Correspondence with Other Organizations
PR — Proposed Rule
PRM — Petition for Rulemaking
PROJ — Projects—Predocket Licensing
PT21 — Noncompliance Reports and Related Correspondence
QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides
RES — Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
RM — Rulemakings
SECY — Position Papers Before the Commission
STATE PROG — State Programs
TOPREP — Vendor Reports and Related Correspondence
WASH — Regulatory Publications—Pre-NUREG Series
WASTE MGT — Nuclear Waste Management
XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

(1) NUREG—NUREG Reports and Related Correspondence

(2) 8203090207 (3) NUREG/CR-1672 V02

(4) RISK ASSESSMENT METHODOLOGY DEVELOPMENT FOR WASTE ISOLATION IN GEOLOGIC MEDIA. Technical Review of Documents NUREG/CR-1262, NUREG/CR-1376, NUREG/CR-1377, NUREG/CR-1397 & NUREG/CR-1608.

(5) STEVENS, C.A., FULLWOOD, R.A., BASIN, S.L. (6) Science Applications, Inc.

(7) FIN B-6694. (8) SAI-262-81-PA. (9) 82/02/28. (10) Division of Risk Analysis.

(11) 123 p. (12) Available at NRC. (13) $6.00. (14) 12176:217. (15)

1. Nondocketed category
2. NRC Accession Number (year, month, day, and sequence number of item)
3. NRC Report Number
4. Title and description of information contained in the document
5. Personal author(s). An asterisk in this position indicates that there is no personal author.
6. Corporate, agency or other nonindividual source.
7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
8. Secondary report number assigned by originator.
9. Date of document described.
10. NRC organizational recipient.
11. Pages in document.
12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
13. Price for which NRC sells the document.

14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:
   Director
   Division of Technical Information and Document Control
   U.S. Nuclear Regulatory Commission
   Washington, D.C. 20555

   To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:
   National Technical Information Service
   Springfield, Virginia 22161

   To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:
   1717 H Street, N.W.
   Washington, D.C. 20555

   To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

   Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is $0.05 per page except for oversized documents and engineering drawings, which vary from $0.50 to $1.00 per square foot; (2) microform to paper is $0.05 a page for pages on microfiche and is $0.20 a square foot for a full-size print or $0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is $0.10 per microfiche and $0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

   Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page
Low Level Radwaste Disposal Sites — Docket 27		
27-039	Sheffield, IL, U.S. Ecology, Inc	1
27-048	Richland, WA, U.S. Ecology, Inc.	1
Domestic Licensing of Source Material — Docket 40		
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1
40-0215	S. F. Applicance, Ltd., Morris, IL	1
40-0229	Union Carbide Corp., Riverton, WY	1
40-0299	Union Carbide Corp., Grand Junction, CO	1
40-0672	Nuclear Metals, Inc., Concord, MA	2
40-1162	Western Nuclear, Inc., Jeffrey City, WY	4
40-1341	Tennessee Valley Authority, Chattanooga, TN	5
40-1478	Spencer Chemical Co., Kansas City, MO	5
40-2061	Kerr-McGee Chemical Corp., Oklahoma City, OK	5
40-2259	Pathfinder Mines Corp., Riverton, WY	5
40-3079	Technical Operations, Inc., Burlington, MA	5
40-3392	Allied Chemical Corp., Morristown, NJ	5
40-3453	Atlas Mineral, Inc., Denver, CO	5
40-4492	Federal-American Partners, Riverton, WY	6
40-6500	Energy, Dept. of, Canonsburg, PA	6
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	6
40-6659	Getty Oil Co. - Petrotomics Co., Shirley Basin, WY	6
40-7097	MolyCorp, Inc., White Plains, NY	6
40-7580	Fansteel, Inc., North Chicago, IL	6
40-7708	Union Carbide Corp., New York, NY	6
40-7869	Plateau Resources, Ltd., Grand Junction, CO	6
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	7
40-8035	Cotter Corp., Roswell, NM	7
40-8064	Exxon Minerals Co. USA, Houston, TX	7
40-8084	Rio Algom Corp., Moab, UT	7
40-8102	Exxon Co. USA, Houston, TX	7
40-8137	Pacific Technical Corp., Santa Barbara, CA	7
40-8202	Battelle Memorial Institute, Columbus, OH	7
40-8348	Minerals Exploration Co., Los Angeles, CA	8
40-8380	Rocky Mountain Energy Co., Broomfield, CO	8
40-8406	Pesses Co., Solon, OH	8
40-8452	Bear Creek Uranium Co., Casper, WY	8
40-8502	Wyoming Mineral Corp., Lakewood, CO	8
40-8550	Holmes & Narver, Inc., Anaheim, CA	8
40-8584	Minerals Exploration Co., Los Angeles, CA	8
40-8602	Silver King Mines, Inc., Casper, WY	8
40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	8
40-8675	Energy Fuels Nuclear, Inc., Denver, CO	9
40-8681	Energy Fuels Nuclear, Inc., Denver, CO	9
40-8693	Ogle Petroleum, Inc., Santa Barbara, CA	9
40-8697	Rocky Mountain Energy Co., Denver, CO	9
40-8698	Plateau Resources, Ltd., Grand Junction, CO	9
40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	9
40-8722	Brush Wellman, Inc., Cleveland, OH	9
40-8728	Teton Exploration Drilling Co., Inc., Casper, WY	9
40-8745	Ogle Petroleum, Inc., Casper, WY	9
40-8752	Pinal Minerals & Mining, Ltd., Miami, AZ	9
40-8763	AluChem, Inc., Reading, OH	10
40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	10
40-8783	Uranerz USA, Inc., Casper, WY	10
40-8786	Uranium Resources, Inc., Richardson, TX	10
40-8829	Wyoming Fuel Co., Lakewood, CO	10

Docket	Name	Page
Domestic Licensing of Production and Utilization Facilities—Docket 50		
50-3	Indian Point Station, Unit 1	10
50-10	Dresden Nuclear Power Station, Unit 1	11
50-20	Massachusetts Institute of Technology Research Reactor	12
50-29	Yankee-Rowe Nuclear Power Station	12
50-54	Union Carbide Research Reactor	14
50-57	State Univ. of New York Research Reactor	14
50-62	Univ. of Virginia Research Reactor	14
50-70	General Electric Test Reactor	15
50-73	General Electric Nuclear Test Reactor	15
50-89	General Atomic Co.	15
50-97	Cornell Univ. Zero Power Reactor	15
50-111	North Carolina State Univ. Research Reactor	15
50-112	Univ. of Oklahoma Research Reactor	16
50-123	Univ. of Missouri Research Reactor	16
50-128	Texas A&M Univ. Research Reactor	16
50-129	West Virginia Univ. Research Reactor	16
50-131	Omaha Veterans Administration Hospital Research Reactor	16
50-133	Humboldt Bay Power Plant, Unit 3	16
50-142	UCLA Training Reactor	17
50-146	Saxton Nuclear Experimental Facility	18
50-148	Univ. of Kansas Research Reactor	19
50-155	Big Rock Point Nuclear Plant	19
50-156	Univ. of Wisconsin Research Reactor	22
50-157	Cornell Univ. Research Reactor	22
50-163	General Atomic Co.	23
50-170	National Naval Medical Center	23
50-184	National Bureau of Standards Reactor	23
50-192	Univ. of Texas Research Reactor	23
50-193	Rhode Island & Providence Plantations AEC	23
50-201	West Valley Reprocessing Plant	23
50-206	San Onofre Nuclear Station, Unit 1	24
50-213	Haddam Neck Plant	26
50-219	Oyster Creek Nuclear Power Plant	28
50-220	Nine Mile Point Nuclear Station, Unit 1	30
50-225	RPI Critical Experiment	34
50-237	Dresden Nuclear Power Station, Unit 2	34
50-238	Nuclear Ship Savannah	38
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	38
50-245	Millstone Nuclear Power Station, Unit 1	41
50-247	Indian Point Station, Unit 2	43
50-249	Dresden Nuclear Power Station, Unit 3	49
50-250	Turkey Point Plant, Unit 3	52
50-251	Turkey Point Plant, Unit 4	54
50-253	Accelerator Pulsed Fast Assembly	56
50-254	Quad-Cities Station, Unit 1	56
50-255	Palisades Nuclear Plant	59
50-259	Browns Ferry Nuclear Power Station, Unit 1	62
50-260	Browns Ferry Nuclear Power Station, Unit 2	65
50-261	H. B. Robinson Plant, Unit 2	68
50-262	Brigham Young Univ. Research Reactor	71
50-263	Monticello Nuclear Generating Plant	71
50-264	Dow Chemical Co.	72
50-265	Quad-Cities Station, Unit 2	72
50-266	Point Beach Nuclear Plant, Unit 1	74
50-267	Fort St. Vrain Nuclear Generating Station	77
50-269	Oconee Nuclear Station, Unit 1	79
50-270	Oconee Nuclear Station, Unit 2	82
50-271	Vermont Yankee Nuclear Power Station	84
50-272	Salem Nuclear Generating Station, Unit 1	86
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	90
50-277	Peach Bottom Atomic Power Station, Unit 2	95
50-278	Peach Bottom Atomic Power Station, Unit 3	97
50-280	Surry Power Station, Unit 1	100
50-281	Surry Power Station, Unit 2	102
50-282	Prairie Island Nuclear Station, Unit 1	105
50-285	Fort Calhoun Station, Unit 1	107
50-286	Indian Point Station, Unit 3	108
50-287	Oconee Nuclear Station, Unit 3	115

Docket	Name	Page
50-289	Three Mile Island Nuclear Station, Unit 1	118
50-293	Pilgrim Nuclear Power Station, Unit 1	124
50-295	Zion Nuclear Power Station, Unit 1	127
50-296	Browns Ferry Nuclear Power Station, Unit 3	129
50-298	Cooper Nuclear Station	132
50-301	Point Beach Nuclear Plant, Unit 2	134
50-302	Crystal River Nuclear Plant, Unit 3	137
50-304	Zion Nuclear Power Station, Unit 2	140
50-305	Kewaunee Nuclear Power Plant	143
50-306	Prairie Island Nuclear Station, Unit 2	145
50-309	Maine Yankee Atomic Power Plant	147
50-311	Salem Nuclear Generating Station, Unit 2	150
50-312	Rancho Seco Nuclear Generating Station	154
50-313	Arkansas Nuclear One, Unit 1	157
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	161
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	165
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	168
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	171
50-320	Three Mile Island Nuclear Station, Unit 2	174
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	179
50-322	Shoreham Nuclear Power Station	182
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	188
50-324	Brunswick Steam Electric Plant, Unit 2	190
50-325	Brunswick Steam Electric Plant, Unit 1	194
50-327	Sequoyah Nuclear Plant, Unit 1	197
50-328	Sequoyah Nuclear Plant, Unit 2	199
50-329	Midland Plant, Unit 1	202
50-330	Midland Plant, Unit 2	207
50-331	Duane Arnold Energy Center	212
50-332	Barnwell Reprocessing Plant	216
50-333	James A. Fitzpatrick Nuclear Power Plant	216
50-334	Beaver Valley Power Station, Unit 1	219
50-335	St. Lucie Plant, Unit 1	221
50-336	Millstone Nuclear Power Station, Unit 2	224
50-338	North Anna Power Station, Unit 1	227
50-339	North Anna Power Station, Unit 2	230
50-341	Enrico Fermi Atomic Power Plant, Unit 2	233
50-344	Trojan Nuclear Plant	236
50-346	Davis-Besse Nuclear Power Station, Unit 1	237
50-348	Joseph M. Farley Nuclear Plant, Unit 1	241
50-352	Limerick Generating Station, Unit 1	243
50-353	Limerick Generating Station, Unit 2	247
50-354	Hope Creek Nuclear Station, Unit 1	250
50-355	Hope Creek Nuclear Station, Unit 2	251
50-358	William H Zimmer Nuclear Station, Unit 1	251
50-361	San Onofre Nuclear Station, Unit 2	256
50-362	San Onofre Nuclear Station, Unit 3	259
50-364	Joseph M. Farley Nuclear Plant, Unit 2	262
50-366	Edwin I. Hatch Nuclear Plant, Unit 2	263
50-367	Bailly Generating Station	267
50-368	Arkansas Nuclear One, Unit 2	267
50-369	William B. McGuire Nuclear Station, Unit 1	271
50-370	William B McGuire Nuclear Station, Unit 2	274
50-373	LaSalle County Station, Unit 1	278
50-374	LaSalle County Station, Unit 2	284
50-382	Waterford Generating Station, Unit 3	288
50-387	Susquehanna Steam Electric Station, Unit 1	291
50-388	Susquehanna Steam Electric Station, Unit 2	294
50-389	St. Lucie Plant, Unit 2	295
50-390	Watts Bar Nuclear Plant, Unit 1	299
50-391	Watts Bar Nuclear Plant, Unit 2	302
50-395	Virgil C. Summer Nuclear Station, Unit 1	305
50-396	Univ. of Virginia Cavalier Reactor	309
50-397	WPPSS Nuclear Project, Unit 2	309
50-400	Shearon Harris Nuclear Power Plant, Unit 1	311
50-401	Shearon Harris Nuclear Power Plant, Unit 2	315
50-402	Shearon Harris Nuclear Power Plant, Unit 3	319
50-403	Shearon Harris Nuclear Power Plant, Unit 4	319
50-407	Univ. of Utah Research Reactor	319
50-409	La Crosse Boiling Water Reactor	320

Docket	Name	Page
50-410	Nine Mile Point Nuclear Station, Unit 2	321
50-412	Beaver Valley Power Station, Unit 2	325
50-413	Catawba Nuclear Station, Unit 1	327
50-414	Catawba Nuclear Station, Unit 2	330
50-416	Grand Gulf Nuclear Station, Unit 1	333
50-417	Grand Gulf Nuclear Station, Unit 2	337
50-423	Millstone Nuclear Power Station, Unit 3	339
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	340
50-425	Alvin W. Vogtle Nuclear Plant, Unit 2	341
STN-50-437	Floating Nuclear Plant	342
50-438	Bellefonte Nuclear Plant, Unit 1	342
50-439	Bellefonte Nuclear Plant, Unit 2	344
50-440	Perry Nuclear Power Plant, Unit 1	347
50-441	Perry Nuclear Power Plant, Unit 2	351
50-443	Seabrook Nuclear Station, Unit 1	355
50-444	Seabrook Nuclear Station, Unit 2	359
50-445	Comanche Peak Steam Electric Station, Unit 1	362
50-446	Comanche Peak Steam Electric Station, Unit 2	367
STN-50-447	GESSAR-238	372
STN-50-454	Byron Station, Unit 1	372
STN-50-455	Byron Station, Unit 2	377
STN-50-456	Braidwood Station, Unit 1	380
50-457	Braidwood Station, Unit 2	382
50-458	River Bend Station, Unit 1	384
50-459	River Bend Station, Unit 2	387
50-460	WPPSS Nuclear Project, Unit 1	389
50-461	Clinton Power Station, Unit 1	390
50-462	Clinton Power Station, Unit 2	392
50-469	Kuosheng Power Station, Unit 1, Taiwan	393
STN-50-470	CESSAR System 80	393
STN-50-482	Wolf Creek Generating Station	394
STN-50-483	Callway Plant, Unit 1	396
STN-50-491	Cherokee Nuclear Station, Unit 1	401
50-496	Montague Nuclear Power Station, Unit 1	401
	ontague Nuclear Power Station, Unit 2	402
STN-50-498	South Texas Project, Unit 1	403
STN-50-499	South Texas Project, Unit 2	406
50-500	Davis-Besse Nuclear Power Station, Unit 2	409
50-501	Davis-Besse Nuclear Power Station, Unit 3	409
STN-50-502	Haven Nuclear Plant, Unit 1	409
STN-50-503	Haven Nuclear Plant, Unit 2	409
STN-50-508	WPPSS Nuclear Project, Unit 3	409
50-513	WPPSS Nuclear Project, Unit 4	410
50-514	Pebble Springs Nuclear Plant, Unit 1	410
50-515	Pebble Springs Nuclear Plant, Unit 2	411
STN-50-518	Hartsville Nuclear Plant, Unit 1	411
STN-50-519	Hartsville Nuclear Plant, Unit 2	412
STN-50-520	Hartsville Nuclear Plant, Unit 3	412
STN-50-521	Hartsville Nuclear Plant, Unit 4	412
50-522	Skagit Nuclear Power Project, Unit 1	412
50-523	Skagit Nuclear Power Project, Unit 2	413
STN-50-528	Palo Verde Nuclear Station, Unit 1	414
STN-50-529	Palo Verde Nuclear Station, Unit 2	417
STN-50-530	Palo Verde Nuclear Station, Unit 3	419
50-537	Clinch River Breeder Reactor	422
STN-50-546	Marble Hill Nuclear Station, Unit 1	425
STN-50-547	Marble Hill Nuclear Station, Unit 2	427
STN-50-553	Phipps Bend Nuclear Station, Unit 1	429
STN-50-554	Phipps Bend Nuclear Station, Unit 2	430
STN-50-556	Black Fox Station, Unit 1	430
STN-50-557	Black Fox Station, Unit 2	430
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	431
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	431
STN-50-599	Carroll Facility I	431
STN-50-600	Carroll Facility II	431

Domestic Licensing of Special Nuclear Material — Docket 70

70-0008	Battelle Memorial Institute, Columbus, OH	431
70-0025	Rockwell International Corp., Canoga Park, CA	432
70-0027	Babcock & Wilcox, Co., Lynchburg, VA	432

Docket	Name	Page
70-0033	Texas Instruments, Inc., Attleboro, MA	432
70-0082	Nuclear Metals, Inc., West Concord, MA	432
70-0124	Teledyne Isotopes, Inc., Westwood, NJ	433
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	433
70-0371	UNC Naval Products, Inc., Uncasville, CT	433
70-0378	Army, Dept. of, Adelphi, MD	434
70-0466	Maine Maritime Academy, Castine, ME	436
70-0698	Westinghouse Electric Corp , Pittsburgh, PA	436
70-0712	Kerr-McGee Nuclear Corp., Oklahoma City, OK	436
70-0734	GA Technologies, Inc., San Diego, CA	436
70-0754	General Electric Co., Pleasanton, CA	436
70-0820	United Nuclear Corp., Wood River Junction, RI	436
70-0824	Babcock & Wilcox Co., Lynchburg, VA	436
70-0846	Texas Nuclear Corp., Austin, TX	436
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	436
70-0992	David Witherspoon, Inc., Knoxville, TN	437
70-1007	General Electric Co., San Jose, CA	437
70-1113	General Electric Co., Wilmington, NC	437
70-1143	Westinghouse Electric Corp., Pittsburgh, PA	437
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	437
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	438
70-1201	Babcock & Wilcox Co., Lynchburg, VA	438
70-1224	Teleflex, Inc., North Wales, PA	438
70-1257	Exxon Nuclear Co., Inc., Richland, WA	438
70-1301	Florida Power Corp., St. Petersburg, FL	438
70-1308	General Electric Co., San Jose, CA	438
70-1359	IRT Corp., San Diego, CA	439
70-1402	Abington Memorial Hospital, Abington, PA	439
70-1621	Duquesne Light Co., Pittsburgh, PA	439
70-2926	Detroit Edison Co., Detroit, MI	439
70-2932	Texas Utilities Generating Co., Dallas, TX	439
70-2953	Connecticut, Univ. of, Storrs, CT	439
70-2973	Commonwealth Edison Co., Chicago, IL	439
70-2982	Rochester, Univ of, Rochester, NY	439
70-2983	Pennsylvania Power & Light, Allentown, PA	439

Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71

Docket	Name	Page
71-0001	ANEFCO, Inc.	439
71-0143	Ranchers Exploration & Development Co.	440
71-0166	New York Testing Labs, Inc.	440
71-0494	Montana X-Ray, Inc	440
71-0495	Southwest X-Ray Corp	440
71-0496	NUS Corp.	440
71-4986	Model: RA-2, RA-3, RA-J, General Electric Co	440
71-5026	Model: CNS 14-190, Chem-Nuclear Systems, Inc.	440
71-5332	Model: 2030-1, Energy, Dept. of	440
71-5552	Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	440
71-5607	Model: T-2, Energy, Dept. of	440
71-5814	Model: NRBK-41, -42 & -43, Energy, Dept. of	440
71-5874	Model: WAPD-40, Energy, Dept. of	440
71-5875	Model: WAPD-39 & NRBK-44, Energy, Dept. of	441
71-5957	Model: BMI-1, Battelle Columbus Laboratory	441
71-5979	Model: 5979, Alpha-Omega Services, Inc.	441
71-5980	Model: GE-600, General Electric Co.	441
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	441
71-6272	Model: 6272, U.S. Ecology	441
71-6294	Model: UNC-2901, Combustion Engineering Co., Inc.	441
71-6346	Model: FSV-1, General Atomic Co.	441
71-6400	Model: 6400, Westinghouse Electric Corp.	441
71-6495	Model: PADUCAH Demonstration Cask, Energy, Dept. of	441
71-6550	Model: 6-GS-1, Energy, Dept. of	441
71-6553	Model: PADUCAH Tiger, Energy, Dept. of	441
71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	441
71-6639	Model: MH-1A, Energy, Dept. of	441

Docket	Name	Page
71-6708	Model: C-6, Energy, Dept. of	442
71-6717	Model: 6717-B, Gamma Industries	442
71-9010	Model: NLI-1/2, NL Industries, Inc	442
71-9015	Model: TN-8, -8L, No Users	442
71-9033	Model: 660 & 660E, Technical Operations, Inc.	442
71-9044	Model GE-1600, General Electric Co	442
71-9049	Model: GE-500, General Electric Co.	442
71-9070	Model N-55, Energy, Dept. of	442
71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	442
71-9080	Model· 9080, Hittman Nuclear & Development Corp.	442
71-9081	Model. CNSI 1-13C, Chem-Nuclear Systems, Inc.	442
71-9096	Model· CNS 21-300, Chem-Nuclear Systems, Inc.	442
71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	442
71-9103	Model: NLI-6502, No Users	443
71-9105	Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	443
71-9106	Model: BW-20WC-3, Babcock & Wilcox Co.	443
71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc	443
71-9135	Model: Century S & SA, Cen Univ. S & SA, Gamma Industries	443
71-9148	Model. 770, Technical Operations, Inc	443
71-9150	Model: PAT-2, Energy, Dept. of	443
71-9151	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	443
71-9156	Model: IR-50, Industrial Nuclear Co.	443
71-9163	Model: GNG-20, Gulf Nuclear, Inc.	443
71-9175	Model. CNS6-80B, Nuclear Packaging, Inc	443
71-9177	Model NUPAC 10/140, Nuclear Packaging, Inc.	444
71-9180	Model: 500-SU, Automation Industries, Inc.	444
71-9181	Model: PAS-2, Nuclear Packaging, Inc.	444
71-9510	Model: GPHS, Energy, Dept. of	444
71-9788	Model: S5W Reactor Compartment, Energy, Dept. of	444
71-9901	Model: 120, Energy, Dept. of	444

Licensing of Independent Spent Fuel Storage — Docket 72

72-0001	Morris Operations, General Electric Co.	444

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 27		
Richland, WA, U S. Ecology, Inc.	27-048	1
Sheffield, IL, U.S. Ecology, Inc.	27-039	1
Domestic Licensing of Source Material — Docket 40		
Allied Chemical Corp., Morristown, NJ	40-3392	5
AluChem, Inc., Reading, OH	40-8763	10
Atlas Mineral, Inc., Denver, CO	40-3453	5
Battelle Memorial Institute, Columbus, OH	40-8202	7
Bear Creek Uranium Co., Casper, WY	40-8452	8
Brush Wellman, Inc., Cleveland, OH	40-8722	9
Cleveland-Cliffs Iron Co., Cleveland, OH	40-8714	9
Cotter Corp., Roswell, NM	40-8035	7
Energy Fuels Nuclear, Inc., Denver, CO	40-8675	9
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	9
Energy, Dept. of, Canonsburg, PA	40-6500	6
Exxon Co. USA, Houston, TX	40-8102	7
Exxon Minerals Co. USA, Houston, TX	40-8064	7
Fansteel, Inc., North Chicago, IL	40-7580	6
Federal-American Partners, Riverton, WY	40-4492	6
Getty Oil Co. — Petrotomics Co., Shirley Basin, WY	40-6659	6
Holmes & Narver, Inc., Anaheim, CA	40-8550	8
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	5
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	7
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	10
Minerals Exploration Co., Los Angeles, CA	40-8348	8
Minerals Exploration Co., Los Angeles, CA	40-8584	8
MolyCorp, Inc., White Plains, NY	40-7097	6
Nuclear Dynamics, Inc , Phoenix, AZ	40-8663	8
Nuclear Metals, Inc , Concord, MA	40-0672	2
Ogle Petroleum, Inc., Casper, WY	40-8745	9
Ogle Petroleum, Inc., Santa Barbara, CA	40-8693	9
Pacific Technical Corp., Santa Barbara, CA	40-8137	7
Pathfinder Mines Corp., Riverton, WY	40-2259	5
Pathfinder Mines Corp., Shirley Basin, WY	40-6622	6
Pesses Co., Solon, OH	40-8406	8
Pinal Minerals & Mining, Ltd., Miami, AZ	40-8752	9
Plateau Resources, Ltd., Grand Junction, CO	40-7869	6
Plateau Resources, Ltd , Grand Junction, CO	40-8698	9
Rio Algom Corp., Moab, UT	40-8084	7
Rocky Mountain Energy Co., Broomfield, CO	40-8380	8
Rocky Mountain Energy Co., Denver, CO	40-8697	9
S. F. Applicance, Ltd., Morris, IL	40-0215	1
Silver King Mines, Inc., Casper, WY	40-8602	8
Spencer Chemical Co., Kansas City, MO	40-1478	5
Technical Operations, Inc., Burlington, MA	40-3079	5
Tennessee Valley Authority, Chattanooga, TN	40-1341	5
Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	9
Union Carbide Corp., Grand Junction, CO	40-0299	1
Union Carbide Corp., New York, NY	40-7708	6
Union Carbide Corp., Riverton, WY	40-0229	1
Uranerz USA Inc., Casper, WY	40-8783	10
Uranium Resources, Inc., Richardson, TX	40-8786	10
W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Western Nuclear, Inc., Jeffrey City, WY	40-1162	4
Wyoming Fuel Co., Lakewood, CO	40-8829	10
Wyoming Mineral Corp., Lakewood, CO	40-8502	8

Name	Docket	Page
Domestic Licensing of Production and Utilization Facilities — Docket 50		
Accelerator Pulsed Fast Assembly	50-253	56
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	340
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	341
Arkansas Nuclear One, Unit 1	50-313	157
Arkansas Nuclear One, Unit 2	50-368	267
Bailly Generating Station	50-367	267
Barnwell Reprocessing Plant	50-332	216
Beaver Valley Power Station, Unit 1	50-334	219
Beaver Valley Power Station, Unit 2	50-412	325
Bellefonte Nuclear Plant, Unit 1	50-438	342
Bellefonte Nuclear Plant, Unit 2	50-439	344
Big Rock Point Nuclear Plant	50-155	19
Black Fox Station, Unit 1	STN-50-556	430
Black Fox Station, Unit 2	STN-50-557	430
Braidwood Station, Unit 1	STN-50-456	380
Braidwood Station, Unit 2	STN-50-457	382
Brigham Young Univ. Research Reactor	50-262	71
Browns Ferry Nuclear Power Station, Unit 1	50-259	62
Browns Ferry Nuclear Power Station, Unit 2	50-260	65
Browns Ferry Nuclear Power Station, Unit 3	50-296	129
Brunswick Steam Electric Plant, Unit 1	50-325	194
Brunswick Steam Electric Plant, Unit 2	50-324	190
Byron Station, Unit 1	STN-50-454	372
Byron Station, Unit 2	STN-50-455	377
Callaway Plant, Unit 1	STN-50-483	396
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	168
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	171
Carroll Facility I	STN-50-599	431
Carroll Facility II	STN-50-600	431
Catawba Nuclear Station, Unit 1	50-413	327
Catawba Nuclear Station, Unit 2	50-414	330
CESSAR System 80	STN-50-470	393
Cherokee Nuclear Station, Unit 1	STN-50-491	401
Clinch River Breeder Reactor	50-537	422
Clinton Power Station, Unit 1	50-461	390
Clinton Power Station, Unit 2	50-462	392
Comanche Peak Steam Electric Station, Unit 1	50-445	362
Comanche Peak Steam Electric Station, Unit 2	50-446	367
Cooper Nuclear Station	50-298	132
Cornell Univ Research Reactor	50-157	22
Cornell Univ. Zero Power Reactor	50-97	15
Crystal River Nuclear Plant, Unit 3	50-302	137
Davis-Besse Nuclear Power Station, Unit 1	50-346	237
Davis-Besse Nuclear Power Station, Unit 2	50-500	409
Davis-Besse Nuclear Power Station, Unit 3	50-501	409
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	90
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	188
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	161
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	165
Dow Chemical Co.	50-264	72
Dresden Nuclear Power Station, Unit 1	50-10	11
Dresden Nuclear Power Station, Unit 2	50-237	34
Dresden Nuclear Power Station, Unit 3	50-249	49
Duane Arnold Energy Center	50-331	212
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	179
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	263
Enrico Fermi Atomic Power Plant, Unit 2	50-341	233
Floating Nuclear Plant	STN-50-437	342
Fort Calhoun Station, Unit 1	50-285	107
Fort St. Vrain Nuclear Generating Station	50-267	77
General Atomic Co.	50-163	23
General Atomic Co.	50-89	15
General Electric Nuclear Test Reactor	50-73	15
General Electric Test Reactor	50-70	15
GESSAR-238	STN-50-447	372
Grand Gulf Nuclear Station, Unit 1	50-416	333
Grand Gulf Nuclear Station, Unit 2	50-417	337
H. B. Robinson Plant, Unit 2	50-261	68
Haddam Neck Plant	50-213	26

Name	Docket	Page
Hartsville Nuclear Plant, Unit 1	STN-50-518	411
Hartsville Nuclear Plant, Unit 2	STN-50-519	412
Hartsville Nuclear Plant, Unit 3	STN-50-520	412
Hartsville Nuclear Plant, Unit 4	STN-50-521	412
Haven Nuclear Plant, Unit 1	STN-50-502	409
Haven Nuclear Plant, Unit 2	STN-50-503	409
Hope Creek Nuclear Station, Unit 1	50-354	250
Hope Creek Nuclear Station, Unit 2	50-355	251
Humboldt Bay Power Plant, Unit 3	50-133	16
Indian Point Station, Unit 1	50-3	10
Indian Point Station, Unit 2	50-247	43
Indian Point Station, Unit 3	50-286	108
James A. Fitzpatrick Nuclear Power Plant	50-333	216
Joseph M. Farley Nuclear Plant, Unit 1	50-348	241
Joseph M. Farley Nuclear Plant, Unit 2	50-364	262
Kewaunee Nuclear Power Plant	50-305	143
Kuosheng Power Station, Unit 1, Taiwan	50-469	393
La Crosse Boiling Water Reactor	50-409	320
LaSalle County Station, Unit 1	50-373	278
LaSalle County Station, Unit 2	50-374	284
Limerick Generating Station, Unit 1	50-352	243
Limerick Generating Station, Unit 2	50-353	247
Maine Yankee Atomic Power Plant	50-309	147
Marble Hill Nuclear Station, Unit 1	STN-50-546	425
Marble Hill Nuclear Station, Unit 2	STN-50-547	427
Massachusetts Institute of Technology Research Reactor	50-20	12
Midland Plant, Unit 1	50-329	202
Midland Plant, Unit 2	50-330	207
Millstone Nuclear Power Station, Unit 1	50-245	41
Millstone Nuclear Power Station, Unit 2	50-336	224
Millstone Nuclear Power Station, Unit 3	50-423	339
Montague Nuclear Power Station, Unit 1	50-496	401
Montague Nuclear Power Station, Unit 2	50-497	402
Monticello Nuclear Generating Plant	50-263	71
National Bureau of Standards Reactor	50-184	23
National Naval Medical Center	50-170	23
Nine Mile Point Nuclear Station, Unit 1	50-220	30
Nine Mile Point Nuclear Station, Unit 2	50-410	321
North Anna Power Station, Unit 1	50-338	227
North Anna Power Station, Unit 2	50-339	230
North Carolina State Univ Research Reactor	50-111	15
Nuclear Ship Savannah	50-238	38
Oconee Nuclear Station, Unit 1	50-269	79
Oconee Nuclear Station, Unit 2	50-270	82
Oconee Nuclear Station, Unit 3	50-287	115
Omaha Veterans Administration Hospital Research Reactor	50-131	16
Oyster Creek Nuclear Power Plant	50-219	28
Palisades Nuclear Plant	50-255	59
Palo Verde Nuclear Station, Unit 1	STN-50-528	414
Palo Verde Nuclear Station, Unit 2	STN-50-529	417
Palo Verde Nuclear Station, Unit 3	STN-50-530	419
Peach Bottom Atomic Power Station, Unit 2	50-277	95
Peach Bottom Atomic Power Station, Unit 3	50-278	97
Pebble Springs Nuclear Plant, Unit 1	50-514	410
Pebble Springs Nuclear Plant, Unit 2	50-515	411
Perry Nuclear Power Plant, Unit 1	50-440	347
Perry Nuclear Power Plant, Unit 2	50-441	351
Phipps Bend Nuclear Station, Unit 1	STN-50-553	429
Phipps Bend Nuclear Station, Unit 2	STN-50-554	430
Pilgrim Nuclear Power Station, Unit 1	STN-50-293	124
Point Beach Nuclear Plant, Unit 1	50-266	74
Point Beach Nuclear Plant, Unit 2	50-301	134
Prairie Island Nuclear Station, Unit 1	50-282	105
Prairie Island Nuclear Station, Unit 2	50-306	145
Quad-Cities Station, Unit 1	50-254	56
Quad-Cities Station, Unit 2	50-265	72
Rancho Seco Nuclear Generating Station	50-312	154
Rhode Island & Providence Plantations AEC	50-193	23
River Bend Station, Unit 1	50-458	384
River Bend Station, Unit 2	50-459	387

Name	Docket	Page
obert Emmet Ginna Nuclear Plant, Unit 1	50-244	38
PI Critical Experiment	50-225	34
alem Nuclear Generating Station, Unit 1	50-272	86
Salem Nuclear Generating Station, Unit 2	50-311	150
San Onofre Nuclear Station, Unit 1	50-206	24
San Onofre Nuclear Station, Unit 2	50-361	256
San Onofre Nuclear Station, Unit 3	50-362	259
axton Nuclear Experimental Facility	50-146	18
Seabrook Nuclear Station, Unit 1	50-443	355
Seabrook Nuclear Station, Unit 2	50-444	359
Sequoyah Nuclear Plant, Unit 1	50-327	197
Sequoyah Nuclear Plant, Unit 2	50-328	199
Shearon Harris Nuclear Power Plant, Unit 1	50-400	311
Shearon Harris Nuclear Power Plant, Unit 2	50-401	315
Shearon Harris Nuclear Power Plant, Unit 3	50-402	319
Shearon Harris Nuclear Power Plant, Unit 4	50-403	319
Shoreham Nuclear Power Station	50-322	182
Skagit Nuclear Power Project, Unit 1	50-522	412
Skagit Nuclear Power Project, Unit 2	50-523	413
South Texas Project, Unit 1	STN-50-498	403
South Texas Project, Unit 2	STN-50-499	406
St. Lucie Plant, Unit 1	50-335	221
St. Lucie Plant, Unit 2	50-389	295
State Univ. of New York Research Reactor	50-57	14
Surry Power Station, Unit 1	50-280	100
Surry Power Station, Unit 2	50-281	102
Susquehanna Steam Electric Station, Unit 1	50-387	291
Susquehanna Steam Electric Station, Unit 2	50-388	294
Texas A&M Univ. Research Reactor	50-128	16
Three Mile Island Nuclear Station, Unit 1	50-289	118
Three Mile Island Nuclear Station, Unit 2	50-320	174
Trojan Nuclear Plant	50-344	236
Turkey Point Plant, Unit 3	50-250	52
Turkey Point Plant, Unit 4	50-251	54
UCLA Training Reactor	50-142	17
Union Carbide Research Reactor	50-54	14
Univ. of Kansas Research Reactor	50-148	19
Univ of Missouri Research Reactor	50-123	16
Univ. of Oklahoma Research Reactor	50-112	16
Univ of Texas Research Reactor	50-192	23
Univ. of Utah Research Reactor	50-407	319
Univ. of Virginia Cavalier Reactor	50-396	309
Univ. of Virginia Research Reactor	50-62	14
Univ of Wisconsin Research Reactor	50-156	22
Vermont Yankee Nuclear Power Station	50-271	84
Virgil C. Summer Nuclear Station, Unit 1	50-395	305
Waterford Generating Station, Unit 3	50-382	288
Watts Bar Nuclear Plant, Unit 1	50-390	299
Watts Bar Nuclear Plant, Unit 2	50-391	302
West Valley Reprocessing Plant	50-201	23
West Virginia Univ Research Reactor	50-129	16
William B. McGuire Nuclear Station, Unit 1	50-369	271
William B. McGuire Nuclear Station, Unit 2	50-370	274
William H. Zimmer Nuclear Station, Unit 1	50-358	251
Wolf Creek Generating Station	STN-50-482	394
WPPSS Nuclear Project, Unit 1	50-460	389
WPPSS Nuclear Project, Unit 2	50-397	309
WPPSS Nuclear Project, Unit 3	STN-50-508	409
WPPSS Nuclear Project, Unit 4	50-513	410
Yankee-Rowe Nuclear Power Station	50-29	12
Yellow Creek Nuclear Plant, Unit 1	STN-50-566	431
Yellow Creek Nuclear Plant, Unit 2	STN-50-567	431
Zion Nuclear Power Station, Unit 1	50-295	127
Zion Nuclear Power Station, Unit 2	50-304	140

Domestic Licensing of Special Nuclear Material — Docket 70

Abington Memorial Hospital, Abington, PA	70-1402	439
Army, Dept. of, Adelphi, MD	70-0378	434
Babcock & Wilcox Co., Lynchburg, VA	70-0027	432
Babcock & Wilcox Co., Lynchburg, VA	70-1201	438
Babcock & Wilcox Co., Lynchburg, VA	70-0824	436

Name	Docket	Page
Battelle Memorial Institute, Columbus, OH	70-0008	431
Commonwealth Edison Co., Chicago, IL	70-2973	439
Connecticut, Univ of, Storrs, CT	70-2953	439
David Witherspoon, Inc., Knoxville, TN	70-0992	437
Detroit Edison Co., Detroit, MI	70-2926	439
Duquesne Light Co., Pittsburgh, PA	70-1621	439
Exxon Nuclear Co , Inc , Richland, WA	70-1257	438
Florida Power Corp., St. Petersburg, FL	70-1301	438
GA Technologies, Inc., San Diego, CA	70-0734	436
General Electric Co., Pleasanton, CA	70-0754	436
General Electric Co., San Jose, CA	70-1007	437
General Electric Co., San Jose, CA	70-1308	438
General Electric Co., Wilmington, NC	70-1113	437
IRT Corp., San Diego, CA	70-1359	439
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0925	436
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-1193	438
Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0712	436
Maine Maritime Academy, Castine, ME	70-0466	436
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	433
Nuclear Metals, Inc., West Concord, MA	70-0082	432
Pennsylvania Power & Light, Allentown, PA	70-2983	439
Rochester, Univ. of, Rochester, NY	70-2982	439
Rockwell International Corp., Canoga Park, CA	70-0025	432
Teledyne Isotopes, Inc., Westwood, NJ	70-0124	433
Teleflex, Inc., North Wales, PA	70-1224	438
Texas Instruments, Inc., Attleboro, MA	70-0033	432
Texas Nuclear Corp., Austin, TX	70-0846	436
Texas Utilities Generating Co., Dallas, TX	70-2932	439
UNC Naval Products, Inc., Uncasville, CT	70-0371	433
United Nuclear Corp., Wood River Junction, RI	70-0820	436
Westinghouse Electric Corp., Pittsburgh, PA	70-0698	436
Westinghouse Electric Corp., Pittsburgh, PA	70-1151	437
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	437

Name	Docket	Page
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions — Docket 71		
ANEFCO, Inc	71-0001	439
Model 120, Energy, Dept of	71-9901	444
Model 2030-1, Energy, Dept of	71-5332	440
Model. 500-SU, Automation Industries, Inc	71-9180	444
Model: 5979, Alpha-Omega Services, Inc	71-5979	441
Model 6-GS-1, Energy, Dept. of	71-6550	441
Model: 6244, Chem-Nuclear Systems, Inc	71-6244	441
Model 6272, U.S. Ecology	71-6272	441
Model 6400, Westinghouse Electric Corp.	71-6400	441
Model: 660 & 660E, Technical Operations, Inc.	71-9033	442
Model: 6717-B, Gamma Industries	71-6717	442
Model: 770, Technical Operations, Inc	71-9148	443
Model: 9080, Hittman Nuclear & Development Corp.	71-9080	442
Model: BMI-1, Battelle Columbus Laboratory	71-5957	441
Model: BW-20WC-3, Babcock & Wilcox Co.	71-9106	443
Model: C-6, Energy, Dept. of	71-6708	442
Model Century S & SA, Cen. Univ. S & SA, Gamma Industries	71-9135	443
Model: CNS 14-190, Chem-Nuclear Systems, Inc.	71-5026	440
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	442
Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	443
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	441
Model: CNS6-80B, Nuclear Packaging, Inc.	71-9175	443
Model: CNSI 1-13C, Chem-Nuclear Systems, Inc.	71-9081	442
Model: FSV-1, General Atomic Co.	71-6346	441
Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	71-5552	440
Model: GE-1600, General Electric Co.	71-9044	442
Model: GE-500, General Electric Co.	71-9049	442
Model: GE-600, General Electric Co.	71-5980	441
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	443

ame	Docket	Page
odel: GPHS, Energy, Dept. of	71-9510	444
odel: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	442
odel: HN-100, Series 3, Hittman Nuclear & Development Corp	71-9151	443
odel: IR-50, Industrial Nuclear Co.	71-9156	443
odel: KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	442
odel. MH-1A, Energy, Dept. of	71-6639	441
lodel: N-55, Energy, Dept. of	71-9070	442
odel: NLI-1/2, NL Industries, Inc.	71-9010	442
lodel: NLI-6502, No Users	71-9103	443
lodel: NRBK-41, -42, & -43, Energy, Dept. of	71-5814	440
lodel: NUPAC, 10/140, Nuclear Packaging, Inc.	71-9177	444
lodel: PADUCAH Demonstration Cask, Energy, Dept. of	71-6495	441
lodel: PADUCAH Tiger, Energy, Dept of	71-6553	441
lodel: PAS-2, Nuclear Packaging, Inc.	71-9181	444
lodel: PAT-2, Energy, Dept. of	71-9150	443

Name	Docket	Page
Model. RA-2, RA-3, RA-J, General Electric Co.	71-4986	440
Model: Rad-Waste CR.I, Chem-Nuclear Systems, Inc.	71-9105	443
Model: S5W Reactor Compartment, Energy, Dept. of	71-9788	444
Model: T-2, Energy, Dept. of	71-5607	440
Model: TN-8, -8L, No Users	71-9015	442
Model: UNC-2901, Combustion Engineering Co., Inc.	71-6294	441
Model: WAPD-39 & NRBK-44, Energy, Dept. of	71-5875	441
Model: WAPD-40, Energy, Dept. of	71-5874	440
MONTANA X-Ray, Inc.	71-0494	440
New York Testing Labs, Inc.	71-0166	440
NUS Corp.	71-0496	440
Ranchers Exploration & Dev. Co.	71-0143	440
Southwest X-Ray Corp.	71-0495	440
Licensing of Independent Spent Fuel Storage — Docket 72		
Morris Operations, General Electric Co.	72-0001	444

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U S ECOLOGY, INC

8305110180 Trip rept of 821201-02 site visit to Sheffield, IL re site surface vegetation & drainage features
SHAFFNER, J. A. Low Level Waste Licensing Branch 83/01/25.
SCARANO, R A. Low Level Waste Licensing Branch. 3pp. 18434:257

8305030517 Joint motion to continue proceedings until 830718 to provide addl time for settlement negotiations Continued progress has been made. Certificate of Svc encl.
LEBBY, R. P. Hearing Branch 3. WETTERHAHN, M. J. US Ecology, Inc. (formerly Nuclear Engineering). 83/04/29. Atomic Safety and Licensing Board Panel 4pp. 18294 176.

DOCKET 27-048 RICHLAND, WA, U.S. ECOLOGY, INC

8305110155 Forwards monthly SNM receipt & burial rept for Mar 1983 & rept of isotopic activity. W/o encls.
HIPSHER, W. M. US Ecology, Inc. (formerly Nuclear Engineering) 83/04/14. HAWKINS, E. Low Level Waste Licensing Branch. 2pp. 18434:103.

8305110134 Application for mods to License 16-19204-01 facilitating specific radwaste receipt & disposal requirements of 10CFR61 "Licensing Requirements for Land Disposal of Radwaste "
HIPSHER, W. M US Ecology, Inc. (formerly Nuclear Engineering). 83/04/21. HAWKINS, E. Low Level Waste Licensing Branch. 3pp. 18421:359.

8305100379 Forwards IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25, 0301, 09 & 14 & notice of violation.
HIND, J. A. Division of Radiological & Materials Safety Programs 83/04/22. REED, C. Commonwealth Edison Co. 2pp 18377:328. 24X Fiche: 50-237, 83/04/22, 8305100379.

--8305100416 IE Waste Packaging Insp Rept 15000046/83-03 on 830216 Noncompliance noted: dose rate of 3 mrem/h existed in truck cab.
THOMAS, R. D., BOOK, H. E. Region 5, Office of Director. ELSEN, M. J. Washington, State of. 83/02/28. 4pp. 18377:344 24X Fiche: 50-237, 83/04/22, 8305100379.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0086 W. R. GRACE & CO., POMPTON PLAINS, NJ

8305180325 Discusses items of interest, including natl response team, FEB for Kerr-McGee Rare Earth facility & radioactive property in Wayne, NJ.
PAGE, R. G. Uranium Fuel Licensing Branch. 83/05/05 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director. 2pp. 18503:357.

DOCKET 40-0219 S. F. APPLIANCE, LTD., MORRIS, IL

8305120445 Ack receipt of 830228 & 0310 ltrs informing NRC of steps taken to correct violations noted in IE insp of License STB-258.
WIEDEMAN, D. G. Region 3, Office of Director. 83/04/29. JOHNSON, B. J S. F. Appliance, Ltd. 1p. 18431:041.

--8305120471 Responds to NRC 830228 ltr re violations noted in IE insp of License STB-258. Corrective actions: radiation surveys unavailable at time of insp encl & repts of future survey will be kept on file.
JONESON, B. J. S. F. Appliance, Ltd. 83/02/28. WIEDEMAN, D. Region 3, Office of Director. 4pp. 18431:042.

--8305120476 Responds to NRC request for info re addl user of License STB-258 Selection & training of individual should be completed within 1-3 months
JONESON, B J S F Appliance, Ltd 83/03/10. WIEDEMAN, D Region 3, Office of Director 1p. 18431.046

DOCKET 40-0229 UNION CARBIDE CORP., RIVERTON, WY

8305260388 Forwards revised Figure 1 2, "Grading of Reclaimed Surface," w/cross-section locations indicated Rev should replace Figure 1 2 in PJ Lyons 830328 ltr
LUTKIN, M H Water, Waste & Land, Inc. 83/04/08 PETTENGILL, H Uranium Recovery Licensing Branch 3pp 18647.209

DOCKET 40-0299 UNION CARBIDE CORP., GRAND JUNCTION, CO

8305120501 Comments on Union Carbide rept re requirements of 10CFR40.65 & License Conditions 45, 48, 56 & 75. Third Quarter 1982 groundwater data not previously submitted was included w/submittal
WOOLSEY, R. T., PETTENGILL, H J. Uranium Recovery Field Office. 83/04/01 Uranium Recovery Field Office 5pp. 18443 158

8305260386 Advises that licensee will temporarily curtail milling of mine ore through U mill at Gas Hills, WY as of 830401. Heap leach facility will continue to operate
LYONS, P. J. Union Carbide Corp 83/04/02 PETTENGILL, H Uranium Recovery Licensing Branch 1p. 18647:212

8305170583 Comments on 830207 ltr & encls re projected costs for tailings reclamation. Tailings pond reclamation cost analysis & pond summary consistent w/approved plan
WOOLSEY, R T. Uranium Recovery Field Office WOOLSEY, R T Licensing Branch 2. 83/04/10 Uranium Recovery Field Office 2pp 18496:111.

8305160276 Summary of 830414 meeting w/Union Carbide Corp & NRC in Casper, WY re proposed expansion of A-9 tailings disposal site.
KEARNEY, B Wyoming, State of. 83/04/18 Wyoming, State of. 1p. 18475:041

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN, G D. Division of Vendor & Technical Programs 83/04/27.
DAVIS, J G. Office of Nuclear Material Safety & Safeguards, Director.
MICHELSON, C Director's Office 3pp. 18306:198.

8305170599 Reviews 40CFR190 compliance for Third Quarter 1982 for Gas Hills Mill Compliance acceptable, however, ability to perform necessary calculations not demonstrated.
BOLLENBERGER, D., MARTIN, D. E. Low Level Waste Licensing Branch. 83/04/28. Low Level Waste Licensing Branch 4pp 18497:048

8305260389 Forwards State of WY, Dept of Environ Quality memo raising concerns on Union Carbide Corp proposed tailings embankments. State will defer further action until Pettengill can study review to determine if addl info needed.
FREUDENTHAL, N. Wyoming, State of 83/04/28. SMITH, R. D. Uranium Recovery Field Office 2pp. 18647:207.

8305260395 Forwards rept on 830415 spill of heap leach liquor from East Gas Hills Mill. Spill contained in restricted area w/no risk of spill reaching surface waterway
LYONS, P. J. Union Carbide Corp. 83/04/28. BROWN, G. Region 4, Office of Director. 3pp. 18647:186

--8305260399 Forwards rept of 830414 spill of tailings liquor from East Gas Hills Mill. Spill contained within restricted area w/no risk of reaching surface waterway.
LYONS, P. J. Union Carbide Corp. 83/04/29. BROWN, G. Region 4, Office of Director 4pp. 18647:189.

DOCKETED ITEMS

8305260363 Advises that State of WY, Dept of Environ Quality, Water Quality Div has no objections to proposed increase in capacity of A-9 pit tailings area Proposal appears environmentally acceptable Comments listed
GARLAND, W L Wyoming, State of 83/05/04 PETTENGILL, H NRC - No Detailed Affiliation Given 1p 18647 289

8305260368 Lists State of WY, Dept of Environ Quality, Water Quality Div concerns re application to install pumpback well to reverse groundwater gradient below A-9 tailings pond Quarterly repts for groundwater monitoring should be submitted
GARLAND, W L Wyoming, State of 83/05/11 PETTENGILL, H NRC - No Detailed Affiliation Given 1p 18647 288

8305250397 Submits review of 40CFR190 compliance for Fourth Quarter 1982 for Gas Hills Mill Revised data & dose calculations submitted 830427 acceptable
BOLLENBERGER, D , MARTIN, D E Uranium Recovery Licensing Branch
83/05/13 HIGGINBOTHAM, L Low Level Waste Licensing Branch 4pp
18594 323

DOCKET 40-0672 NUCLEAR METALS, INC , CONCORD, MA

8305120224 Addl response to FOIA request for license applications, license & insp repts re Nuclear Metals, Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6)
FELTON, J M Division of Rules and Records 83/03/01 MOONEY, B C Lowell Sun, Lowell, MA. 9pp 18460 050

--8112160259 Forwards urinalysis history form for review by Occupational Health Stds Branch Info requested as result of recent insp at Nuclear Metal in Concord, MA where employees urine showed concentration of U in excess of licenses guide
KINNEMAN, J D Materials Radiological Protection Section.
81/12/07. GRELLA, A W. Fuel Cycle & Materials Safety Section
4pp 18462 186.

--8305120234 Insp Findings & Licensee Ack dtd 620424 of License SMB-179. Insp findings no noncompliance noted.
KLEVIN, P B Atomic Energy Commission 62/04/24 2pp 18460 060

--8305120240 Insp Findings & Licensee Ack dtd 651207 & 09 of License SMB-179 Insp findings no noncompliance noted
* Atomic Energy Commission 65/12/08 1p. 18460.062

--8305120246 Notifies that Nuclear Metals Div of Textron, Inc acquired by Whittaker Corp Approval for transfer of licenses requested
THOMPSON, P. Nuclear Metals, Inc 66/08/11 Atomic Energy Commission 1p 18460 063

--8305120251 IE Insp Findings & Licensee Ack dtd 671227 & 28 of License SMB-179 Insp findings, no noncompliance noted
GRELLA, A W , BROWNE, W. G. Atomic Energy Commission 67/12/28 1p.
18460 064

--8305120257 Forwards IE Insp Findings & Licensee Ack dtd 671227 & 28 No noncompliance noted. W/o encl.
KIRKMAN, R. W. Atomic Energy Commission 68/01/03 ABREAU, M A
Whittaker Corp 1p. 18460·065

--8305120260 IE Insp Findings & Licensee Ack dtd 691202-03 of License SMB-179 Insp findings·no noncompliance noted
SMITH, R H Atomic Energy Commission. 69/12/03 1p. 18460 066

-8305120264 Advises that response to 690822 application for License SMB-179 has not been received Info re issuance of license requested
LEE, M R. Whittaker Corp 69/10/22 NUSSBAUMER, D. A Atomic Energy Commission. 1p 18460:067

-8305120268 Submits list of replacement pages to application for License SNM-65, in response to 690923 comments.
ISSEROW, S. Whittaker Corp. 69/10/22. NUSSBAUMER, D A. Atomic Energy Commission. 2pp 18460·068

-8305120274 IE Insp Findings & Licensee Act dtd 690903 & 04 of Licenses SNM-65 & SMB-179 Insp findings·proper evaluations not made of certain aspects of health physics program per Sections II b 4 through II. b. 6(b) of License Condition 8.
BROWNE, W G. Atomic Energy Commission 69/09/18 1p. 18460:071.

8305120279 Application for renewal of License SMB-179, authorizing possession & use of U-235 solid metal & alloy for fabrication & experimentation
QUMMESON, P U. Whittaker Corp 69/08/22. 3pp. 18460·072

--8305120283 Notifies that License SMB-179 expires on 690930 Renewal application should be filed within 30 days Encl certification of status of source matl activities form should be completed for nonrenewal of license
NUSSBAUMER, D A Atomic Energy Commission 69/07/25 HANNA, W J
Whittaker Corp 1p 18460 075

--8305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & SMB-179 Insp findings, no noncompliance noted
SMITH, R H Atomic Energy Commission 70/07/16. 1p 18460 076

--8305120289 Notifies that no items of noncompliance observed during insp of Licenses SNM-65 & SMB-179 Corrective measures implemented re item of noncompliance during 690903 & 04 insp S Isserow replaced DS Knappel as criticality officer
SMITH, R H. Atomic Energy Commission 70/01/06 Atomic Energy Commission. 1p. 18460:077.

--8305120294 IE Insp Findings & Licensee Ack dtd 710513 & 14 of Licenses SNM-65 & SMB-179. Insp findings, no noncompliance noted. Related info encl
SMITH, R H. Atomic Energy Commission. 71/05/14. 22pp. 18460.078

--8305120298 Discusses 740913 smoke & paper emission from 5-gallon pail of U Fire dept removed pail Smoke & vapor emission ceased. No personnel contamination resulted or radiation released Caused by reaction between metal & oil
GILMAN, A. R Nuclear Metals, Inc. 74/09/13. Region 1, Philadelphia, Office of the Director. 3pp 18460·125

--8305120303 Discusses insp of License SMB-179 radiation control program. License classification should be changed from E-3 to B-1 Next insp scheduled during Nov 1974.
JERMAN, P C. Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22 Atomic Energy Commission, Directorate of Regulatory Operations 1p 18460·128

--8305120307 Forwards Insp Rept 40-0672/74-01 on 740530 & 31. No noncompliance noted.
NELSON, P. R Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22 TUFFIN, W B Nuclear Metals, Inc. 2pp.
18460 129.

--8305120310 Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance noted. Major areas inspected radiation control program.
JERMAN, P. C. ; KNAPP, P J Region 1, Philadelphia, Office of the Director. 74/08/20 9pp 18460.131.

--8305120316 Ack receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr
O'REILLY, J. P. Region 1, Philadelphia, Office of the Director.
74/04/26. TUFFIN, W B. Nuclear Metals, Inc. 1p. 18460 140

--8305120352 Suppls 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler, in response to 740404 telcon. Related info encl.
TUFFIN, W. B. Nuclear Metals, Inc. 74/04/16. O'REILLY, J. P. Region 1, Philadelphia, Office of the Director 5pp. 18460·141.

--8305120356 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-28 & 740108-09 & notice of violation. W/o insp repts.
O'REILLY, J P Region 1, Philadelphia, Office of the Director
74/02/15. TUFFIN, W. B. Nuclear Metals, Inc. 2pp 18460·146

--8305120359 Notice of violation from insp of 731227-28 & 740108-09. Noncompliances noted: failure to conduct adequate evaluations of hand exposures, to survey for airborne U-238 & to analyze environ water & soil samples
* Region 1, Philadelphia, Office of the Director. 74/02/15 3pp.
18460·148

--8305120369 Responds to NRC 740215 ltr re violations noted in Insp Repts 70-0082/73-05 & 40-0672/73-02 Corrective actions' finger dosimeters placed on individual employees monthly on rotating basis. U handling employees surveyed.
TUFFIN, W Nuclear Metals, Inc. 74/03/27. O'REILLY, J. P. Region 1, Philadelphia, Office of the Director 11pp 18460:153.

--8305120372 Insp Repts 40-0672/73-02 & 70-0082/73-05 on 721227-28 & 740108-09. Noncompliance noted: failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products.
JERMAN, P. C. ; KNAPP, P. J. Region 1, Philadelphia, Office of the Director. 74/02/01. 20pp. 18460.164.

--8305120376 Confirms 740104 & 07 telcons re actions taken to correct violations noted in insp on 731227 & 28. Representatives will visit plant on 740107 to evaluate corrective actions.
O'REILLY, J. P. Region 1, Philadelphia, Office of the Director.
74/01/07. TUFFIN, W. B. Nuclear Metals, Inc 3pp. 18460:184.

--8305120450 Forwards Insp Rept 40-0672/75-01 on 750529 & 30 No noncompliance noted Major areas inspected selective exam of procedures & representative records, interviews w/personnel, measurements made by inspector & observations W/o encl
NELSON, P R Region 1, Philadelphia, Office of the Director
75/06/25 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 191

--8305120454 "Nuclear Reactor Fuel Svcs Semiannual Insp II Plan & Field Notes "
EPSTEIN, E , MCCLINTOCK, R Office of Inspection & Enforcement, Office of the Director 75/06/23 16pp 18460 195

--8305120462 IE Insp Rept 40-0672/75-01 on 750529-30 No noncompliance noted Major areas inspected mgt interview re scope of program & operations, external & internal exposures, stack air monitoring, liquid waste & controls
EPSTEIN, E , MCCLINTOCK, R O Region 1, Philadelphia, Office of the Director 75/06/23 4pp 18460 211

--8305120466 IE Insp Findings & Licensee Ack dtd 760610 of License SMB-179 Insp findings no noncompliance noted Radiation data sheet encl
EPSTEIN, E Region 1, Philadelphia, Office of the Director
76/06/10. 9pp 18460 217

--8305120478 Ack receipt of 770510 ltr re violations noted in IE Insp Rept 40-0672/77-01 Records of evaluations denoting true exposure of individual exposed to contamination should be maintained for review during next insp
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/05/31 TUFFIN, W B Nuclear Metals, Inc 1p 18460 251

--8305120480 Responds to NRC 770418 ltr re violations noted in IE Insp Rept 40-0672/77-01 Corrective actions employee will present badge to guard at exit Badge sealed within cleanable mylar envelope.
TUFFIN, W. B Nuclear Metals, Inc 77/05/10 NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 3pp 18460 252

--8305120483 Discusses IE Insp Rept 40-0672/77-01 on 770329 & forwards notice of violation
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/04/18 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 255

--8305120489 Notice of violation from insp on 770329 Noncompliance noted failure to perform surveys to assure compliance w/ 10CFR20 101 & 10CFR20 405 re radiation exposure to personnel monitoring (film) badge for Third Quarter 1976
* Region 1, Philadelphia, Office of the Director 77/04/18 1p 18460 257.

--8305120493 Ack receipt of 780919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-02
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/27 TUFFIN, W B Nuclear Metals, Inc 1p 18460 258

--8305120494 Responds to NRC 780821 ltr re violations noted in IE Insp Rept 40-0672/78-02. Corrective actions. radiation levels along outside rear wall of Butler Bldg 1 reduced to 1 m/h Fencing placed between ends of bldgs
TUFFIN, W B Nuclear Metals, Inc. 78/09/19 Region 1, Philadelphia, Office of the Director 1p. 18460.259

--8305120500 Forwards notice of violation from insp on 780727-28 Results of smear samples within license guidelines
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/08/21 TUFFIN, W B Nuclear Metals, Inc. 3pp. 18460 260

--8305120503 Notice of violation from insp on 780727-28. Two individuals working in restricted area received exposures to skin of 8.54 & 8.19 rems, respectively, during First Quarter CY78.
Draft Insp Rept 78-02 encl
* Region 1, Philadelphia, Office of the Director 78/08/21. 2pp 18460:263

--8305120507 IE Insp Rept 40-0672/78-02 on 780727-28 Noncompliance noted two workers received skin dose in excess of 7.5 rems during First Quarter 1978 & levels outside Butler Bldg exceeded 2 m/h at 2 ft.
GLENN, J E. , MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 78/08/14. 10pp 18460 265

--8305120509 Ack receipt of 780418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-01 Request to amend license must accompany changes to procedures noted in 780418 ltr
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/05/11 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 275

--8305120511 Responds to NRC 780324 ltr re violations noted in IE insp on 780228-0301 Corrective actions personnel instructed to collect floor sweeping in containers color coded to identify scrap containing licensed matl
TUFFIN, W B Nuclear Metals, Inc 78/04/18 Region 1, Philadelphia, Office of the Director 2pp 18460 277

--8305120514 Forwards notice of violation from insp on 780228 & 0301 Methods for detecting radioactive contamination should be reviewed Comments on smoking in restricted area requested
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/03/24 TUFFIN, W B Nuclear Metals, Inc 3pp 18460 279

--8305120515 Notice of violation from insp on 780228 & 0301 Noncompliance noted failure to perform surveys re disposal of licensed matl in waste & radiation exposure to extremities
* Region 1, Philadelphia, Office of the Director 78/03/24 1p 18460 282

--8305120518 IE Insp Rept 40-0672/78-01 on 780228 & 0301 Noncompliance noted failure to evaluate exposure to extremity & to wear ring dosimeter in restricted area Radwaste found in trash dumpster
GLENN, J , MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 78/03/13 8pp 18460 283

--8305120519 Forwards proposed ack ltr to Nuclear Metals 801003 response to notice of violation & 800929 notice of proposed imposition of civil penalty
GRIER, B H Region 1, Philadelphia, Office of the Director
80/11/19 THOMPSON, D Executive Officer for Operations Support
2pp 18461 026

--8305120523 Forwards draft enforcement action ltr & notice of violation & proposed imposition of civil penalty re failure to meet NRC & DOT requirements for shipment of radwaste to Barnwell burial site
GRIER, B H Region 1, Philadelphia, Office of the Director
80/08/26 THOMPSON, D Executive Officer for Operations Support
5pp 18461 107

--8305120527 Amend 2 to License SMB-179, revising Items 6 & 7 re source matl & max possession & use, per 751003 telegram
DRAGONETTE, K S Division of Fuel Cycle & Material Safety
75/10/08 1p 18461 185

--8305120530 Confirms discussions re possible overexposure of employee to airborne concentration of depleted U JB Hursh & KW Skrable engaged as consultants for NRC Assistance requested
KINNEMAN, J D Region 1, Philadelphia, Office of the Director
81/01/15 TUFFIN, W B Nuclear Metals, Inc 3pp 18461 199

--8305120540 Discusses IE Insp Rept 40-0672/80-04 on 801120 Proposed transmittal ltr & notice of violation & proposed imposition of civil penalties encl
GRIER, B H Region 1, Philadelphia, Office of the Director
81/02/03. THOMPSON, D Office of Inspection & Enforcement, Office of the Director 10pp 18461 202

--8305120602 Discusses IE insp on 801120 & forwards notice of violation & proposed imposition of civil penalty
STELLO, V. Director's Office, Office of Inspection and Enforcement
81/02/24 TUFFIN, W B Nuclear Metals, Inc 2pp 18461 229

--8305120609 Notice of violation & proposed imposition of civil penalty in amount of $5,000 Noncompliance noted low specific activity radioactive matl found leaking from Drum 58
STELLO, V Director's Office, Office of Inspection and Enforcement
81/02/26 2pp 18461 231

--8305120620 Ack receipt of 810316 ltr & payment of civil penalty proposed in 810226 ltr
THOMPSON, D Director's Office (Pre 820201) 81/03/27
TUFFIN, W B Nuclear Metals, Inc 1p 18461 238

--8305120623 Discusses licensee 810312 fire Approx 10 lb U chips in drum in waste handling area ignited by spontaneous combustion. Fire spread to flammable matl Wipes in area revealed gross beta contamination.
COSTELLO, F M NRC - No Detailed Affiliation Given 81/04/03
KINNEMAN, J D NRC - No Detailed Affiliation Given 2pp
18461 259

DOCKETED ITEMS

--8305120627 Discusses 810312 fire caused by auto-ignition of 10 lb of encapsulated U turnings
GILMAN, A R Nuclear Metals, Inc 81/04/10 COSTELLO, F Region 1, Philadelphia, Office of the Director (81/03/01) 3pp
18461 261

--8305120630 Forwards IE Insp Rept 40-0672/81-01 on 810219 No noncompliance noted Major areas inspected selective exams of procedures & representative records, interviews w/personnel, measurements & observations by inspector. W/o encl
KINNEMAN, J D Region 1, Philadelphia, Office of the Director (81/03/01) 81/04/16 TUFFIN, W B Nuclear Metals, Inc 2pp
18461 264

--8305120633 Responds to 810724 application to amend source matl License Addl info re incineration of U chips & turnings requested
WANG, J C Division of Fuel Cycle & Material Safety 81/09/29
GILMAN, A R Nuclear Metals, Inc 1p 18461 297

--8305120642 Requests addl info re 810527 application to amend License SMB-179, proposing dilution factor of 143 be applied to air effluent releases from ventilation stacks per 10CFR20 106(d)
WANG, J C Division of Fuel Cycle & Material Safety 81/11/12
GILMAN, A R Nuclear Metals, Inc 2pp 18461 326

--8305130006 Ack receipt of application for renewal of License SMB-179 License will not expire until final action taken by NRC
HICKEY, J. W Division of Fuel Cycle & Material Safety 81/12/28
GILMAN, A R Nuclear Metals, Inc 1p 18462 109

--8305130011 Confirms 820216 conversation w/C Rowe re possible quarterly skin overexposure to employee Detailed rept forthcoming Info deleted
VUMBACO, F. J Nuclear Metals, Inc 82/02/16 KINNEMAN, J. D
Region 1, Office of Director 1p 18462 110

--8305130016 Confirms telcon re application for renewal of License SMB-179 Site visit scheduled for 820304
HICKEY, J W Division of Fuel Cycle & Material Safety 82/02/18
GILMAN, A R Nuclear Metals, Inc 1p 18462 111

--8305130031 Discusses 820126 telcon re small crack in dike during discharge of U neutralized acid waste to lagoon. Possibly caused by freeze-thaw cycle Dike reinforced
KINNEMAN, J D Region 1, Office of Director 82/03/24 Region 1, Office of Director 1p 18462.130

--8305130037 Comments on application for renewal of License SMB-179 Application should provide more specific procedures for frisking personnel & clothing at exits from controlled area
KINNEMAN, J D Region 1, Office of Director 82/04/01
MILLER, V L Office of Nuclear Material Safety & Safeguards, Director 2pp 18462.131

--8305130042 Forwards Rev 2 to "NMI Scrap Packaging Procedures," for disposal of depleted U wastes, in support of Dec 1981 license renewal submittal
VUMBACO, F J Nuclear Metals, Inc 82/05/10 HICKEY, J Division of Fuel Cycle & Material Safety 1p. 18462 154

--8305130053 Forwards 820513 request for addl info re licensee application for renewal application.
HICKEY, J W Division of Fuel Cycle & Material Safety 82/05/13
KINNEMAN, J D Region 1, Office of Director 2pp 18462 174

--8305130062 Ack receipt of 811116 application for renewal of License SMB-179. Addl info re temporary job sites at which source matls will be possessed or used, radiation survey program & waste disposal requested. W/o stated encl.
WANG, J C. Division of Fuel Cycle & Material Safety 82/05/13
GILMAN, A. R. Nuclear Metals, Inc. 4pp 18462: 176

8305060135 Addl response to FOIA request for info re Nuclear Metals, Inc, including incidents of employee overexposures. Forwards App A documents Info partially withheld names of overexposed individuals (ref FOIA Exemption 6)
FELTON, J M Division of Rules and Records. 83/03/03 MOONEY, B C Lowell Sun, Lowell, MA 3pp 18353.165

--8201070110 Confirms 811215 telcon agreement re consulting svcs for probable U overexposure incident described in encl Work involves analysis of health significance of uptake & most likely initial update of depleted U. Guidance & forms encl
HAYNES, R C Region 1, Philadelphia, Office of the Director (81/03/01). 81/12/30 HURSH, J B Hursh, J B 12pp 18353 190.

--8208060242 Forwards rept on last quarter 1981 skin dose to Nuclear Metals, Inc employee
ALLARD, D. J Nuclear Metals, Inc. 82/03/01 KINNEMAN, J. D. Division of Engineering & Technical Programs. 1p 18353·223

--8208060244 Rept on last quarter 1981 skin dose to Nuclear Metals, Inc employee
ALLARD, D J Nuclear Metals, Inc 82/03/01 15pp 18353 224

--8305060141 Submits final rept re 740913 smoke & vapor emission at 5 gallon can of depleted U Analysis of container & surrounding area revealed no spread of contamination Control procedures improved Info partially deleted
GILMAN, A R Nuclear Metals, Inc 74/10/24. ALLEN, W Region 1, Philadelphia, Office of the Director 5pp. 18353 169

--8305060156 Ack receipt of 780630 transmittal of final overexposure rept, per 10CFR20.405(a)
MCCLINTOCK, R O Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/07/13 GILMAN, A R. Nuclear Metals, Inc. 2pp
18353 177

--8305060181 Submits rept re employee whole body overexposure to beta plus gamma radiation, per 10CFR20 405(a)(1) Film badge reevaluation & overexposure of U confirmed 780530. Reassignment of personnel & early alert procedure initiated.
GILMAN, A R Nuclear Metals, Inc 78/06/30 Region 1, Philadelphia, Office of the Director 3pp 18353 180

--8305060189 Forwards JE Glenn 810106 memo re allegations of unsafe conditions & improper firing of employee by Nuclear Metals, Inc No further action planned unless written complaint filed
KINNEMAN, J D Nuclear Metals, Inc 81/01/13 SMITH, Q H. Region 1, Philadelphia, Office of the Director 1p 18353·187

--8305060193 Discusses allegations by former Nuclear Metals, Inc employee re unsafe conditions & improper firing Info partially deleted
GLENN, J. E Region 1, Philadelphia, Office of the Director
81/01/06 KINNEMAN, J D Region 1, Philadelphia, Office of the Director. 2pp 18353 188

--8305060200 Forwards "Analysis of Exposure Involving Depleted U at Nuclear Metals, Apr 1981," consultant rept
HURSH, J B. Rochester, Univ of. 82/02/18 HAYNES, R C Region 1, Office of Director 1p 18353.202

--8305060209 Discusses allegations made by Nuclear Metals, Inc employee re unsafe conditions involving risk of employee contamination. Related info encl Info partially deleted.
ROWE, C Region 1, Office of Director 82/04/22 KINNEMAN, J. D Region 1, Office of Director 1p 18353·241

--8305060214 Notifies of results of inquiries re allegations made by Nuclear Metals, Inc employee. No items of concern represented noncompliance w/NRC regulations or safety hazards
KINNEMAN, J D Region 1, Office of Director 82/04/02
FIATARONE, J V Labor, Dept. of 1p 18353 242

--8305060220 Forwards complaint from Nuclear Metals, Inc employee re unsafe conditions & health hazards at facility Related info encl Info partially deleted
FIATARONE, J. V. Labor, Dept. of 82/02/02 KINNEMAN, J. Region 1, Office of Director 20pp 18353·243

DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY

8305020407 Forwards "Water Quality Sampling Results, Fourth Quarter 1982, Split Rock Mill, Jeffrey City, WY," per License Condition 25 Well 20 data will be submitted in supplemental rept.
BOGDEN, G Western Nuclear, Inc. (subs of Phelps Dodge Corp).
83/03/31 Region 4, Office of Director 1p 18273·220.

--8305020417 "Water Quality Sampling Results, Fourth Quarter 1982, Split Rock Mill, Jeffrey City, WY "
* Western Nuclear, Inc. (subs of Phelps Dodge Corp). 83/03/31.
185pp 18273 221.

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983.
BROWN, Q D Division of Vendor & Technical Programs. 83/04/27
DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director.
3pp. 18306.198

8305250175 Addendum to semiannual environ monitoring rept for Jul-Dec 1982 W/830510 ltr.
BOGDEN, G. Western Nuclear, Inc. (subs. of Phelps Dodge Corp.)
83/05/10. PETTENGILL, H J Uranium Recovery Licensing Branch. 37pp.
18596:311

DOCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOOGA, TN

8305030086 Informs that monitoring locations adequate to meet FEB Section 4 2 criteria re evaluation of any adverse effects of decommissioning on environ & to ensure monitoring of critical pathways
JOHNSON, T L Uranium Recovery Field Office LINEHAN, J J Region 4, Office of Director 83/03/25 Uranium Recovery Field Office 2pp 18310 359

DOCKET 40-1478 SPENCER CHEMICAL CO , KANSAS CITY, MO

8305230112 Final response to FOIA request for insp repts of safety violations at Kerr-McGee Pu plant at Cresant, OK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted
FELTON, J M Division of Rules and Records 83/03/22 WIDMER, R R Affiliation Unknown 1p 18543 154

--8305230207 Forwards Region IV 660729 memo re facility closeout survey results Licensee measurements in 660609 ltr substantiated by Region IV findings.
ROY, O W Atomic Energy Commission 66/08/08 NUSSBAUMER, D A Atomic Energy Commission 1p 18543 222

--8305230222 Discusses closeout insp of Licenses SMB-664 & SNM-695 on 660706 Recommends that licensee be authorized to transfer control of facilities to unlicensed recipient
WALKER, D L. Atomic Energy Commission 66/07/29 DUBINSKI, L Atomic Energy Commission 4pp 18543 223

--8305230233 Requests authorization to release vacated facilities at Cushing, OK to refining div for unrestricted use Bldgs used by nuclear products dept cleaned & decontaminated. Health physics survey indicates contamination below limits
WULLER, D B. Kerr-McGee Nuclear Corp 66/06/09 NUSSBAUMER, D A Atomic Energy Commission 4pp 18543 227

DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , OKLAHOMA CITY, OK

8303280177 Forwards IE Insp Rept 40-2061/83-01 on 830104-06 & 25-28 No noncompliance noted
HIND, J A Region 3, Office of Director 83/02/23 SHELLEY, W J Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp) 2pp 17709 277

--8303280182 IE Insp Rept 40-2061/83-01 on 830104-06 & 25-28 No noncompliance noted Major areas inspected liquid effluent releases & new operational water retention sys, surface water results & work site
NICHOLSON, N A., SCHUMACHER, M C Region 3, Office of Director 83/02/17 7pp 17709 279

8305030706 Discusses items of interest, including DOE 830419 visit to NMSS to examine docket files of Kerr-McGee West Chicago Rare Earths Facility & Detroit Edison Co 830419 visit to discuss proposed license conditions for SNM-1915 for fuel storage.
PAGE, R G Uranium Fuel Licensing Branch 83/04/20 DAVIS, J. G Division of Fuel Cycle & Material Safety 3pp. 18309 105

8305170488 Order extending time until 830520 for Commission to act to review presiding officer 830315 decision
CHILK, S. J. Office of the Secretary of the Commission 83/05/13 Commissioners 1p. 18470 008

8305200570 Order extending time until 830527 for Commission to act to review presiding officer 830315 decision.
CHILK, S. J. Office of the Secretary of the Commission. 83/05/19. Commissioners 1p. 18514 273

8305240080 Confirms 830524 meeting in Glen Ellyn, IL to discuss noncompliance noted in recent insp, corrective actions & enforcement options available to NRC, per 830519 telcon
KEPPLER, J G Region 3, Office of Director. 83/05/19. RAINEY, J C Kerr-McGee Chemical Corp (subs. of Kerr-McGee Corp). 1p 18549 175.

8305240282 Notification of significant licensee 830524 meeting in Glen Ellyn, IL to discuss NRC findings during recent insp, enforcement options available & licensee corrective actions
* Region 3, Office of Director 83/05/20 Region 3, Office of Director. 1p. 18548 201

DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY

8305130295 Reviews surety arrangements for decommissioning & reclamation costs for Lucky McMill Cost analysis & summary acceptable
WOOLSEY, R T Uranium Recovery Field Office 83/03/21 Uranium Recovery Field Office 2pp 18460 034

8305030711 Discusses Pathfinder, Inc 830314 request to reduce number of groundwater quality parameters to be monitored Wells UW-502 & AL-1 should continue to be sampled for entire suite of parameters Cation-anion balances should be reported
KEARNEY, B Wyoming, State of 83/04/05 Wyoming, State of 3pp 18309 090

8305160205 Submits recommendations re 830314 request for reduction in parameters analyzed for groundwater monitoring program
SEIFFERT, S G Wyoming, State of 83/04/13 HARDGROVE, T Pathfinder Mines Corp 1p 18462 361

8305130312 Trip rept of 830415 meeting at Pathfinder mining site re seepage from Tailings Pond 1 Major seepage path identified to be paleochannel within cody shale Efforts to control seepage partially successful
KEARNY, B NRC - No Detailed Affiliation Given 83/04/18 NRC - No Detailed Affiliation Given 2pp 18457 319

8305260357 Advises that TW Hardgrove assumed responsibility of environ coordinator, overseeing radiation protection function in mill dept as of 830411
NUGENT, E L Pathfinder Mines Corp 83/04/22 WOOLSEY, R T Region 4, Office of Director 1p 18647 290

DOCKET 40-3079 TECHNICAL OPERATIONS, INC , BURLINGTON, MA

8305050161 Forwards IE Insp Repts 40-3079/83-01, 30-04576/83-01 & 30-09625/83-01 on 830309 No noncompliance noted
MARTIN, T T. Division of Engineering & Technical Programs 83/04/20 LANDAUER, R Technical Operations, Inc 2pp 18342 222

--8305050166 IE Insp Repts 40-3079/83-01, 30-04576/83-01 & 30-09625/03-01 on 830309 No noncompliance noted Major areas inspected scope of operations, licensee action on previous insp findings & followup on possible defect in exposure device
ROWE, C A , KINNEMAN, J D Region 1, Office of Director 83/04/19 5pp. 18342 224

DOCKET 40-3392 ALLIED CHEMICAL CORP., MORRISTOWN, NJ

8305030671 Forwards request for addl info needed to complete EIA for license renewal Most questions discussed during NRC 830413 site visit but written responses needed for renewal process by 830531
WYNGARDEN, S Uranium Fuel Licensing Branch 83/04/25 YATES, R W Allied Chemical Corp 4pp 18309 231

8305120129 Trip rept of 830419-20 site visit to Metropolis, IL re facility familiarization & initial comments on License SUB-526 renewal application
KOSLA, B Uranium Fuel Licensing Branch 83/05/04. CROW, W T Uranium Fuel Licensing Branch 1p 18435 311

8305240337 Forwards IE Insp Rept 40-3392/83-01 on 830419-20. No noncompliance noted.
PAPERIELLO, C. J Region 3, Office of Director 83/05/09 CIPOLLA, A J. Allied Chemical Corp 2pp 18575 107

--8305240340 IE Insp Rept 40-3392/83-01 on 830419-20 No noncompliance noted Major areas inspected, radiation protection, radwaste mgt, safety committees & conduct of operations
PECK, C C , MILLER, D. E , GREGER, L R Region 3, Office of Director. 83/05/09 4pp. 18575 109.

8305170724 Confirms 830419-20 discussion re format for submittal of renewal application for License SUB-526 Section specifying committed conditions of operation requested
KOSLA, B Uranium Fuel Licensing Branch 83/05/11 YATES, R W Allied Chemical Corp. 1p 18496 185

DOCKET 40-3453 ATLAS MINERAL, INC , DENVER, CO

8305130297 Reviews Third Quarter 1982 environ monitoring data for Moab Mill Sampling & analysis acceptable
GARCIA, P. J , PETTENGILL, H. J Uranium Recovery Field Office, 83/03/21 Uranium Recovery Field Office. 4pp 18460 036

8305120496 Comments on Atlas Minerals rept re 1982 land use survey for Moab Mill in accordance w/Condition 40 of Source Matl License SUA-917 Vendor has performed acceptable land use survey
GARCIA,P J , PETTENGILL,H J Uranium Recovery Field Office 83/04/06 Uranium Recovery Field Office 1p 18443 172

8305130362 Requests extension of due date to 840430 for proposed plan for final reclamation phase mods to Moab Wash site,per License Condition 16 to License SUA-917
BLUBAUGH,R E Atlas Minerals 83/04/22 SMITH,D NRC - No Detailed Affiliation Given 2pp 18443 322

8305170601 Reviews Third Quarter 1982 Pb-210 environ monitoring data for Moab Mill Sampling data acceptable
BRANSCOME,J M Uranium Recovery Field Office 83/05/21 Uranium Recovery Field Office 2pp 18497 046

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

8305200031 Forwards Federal American Partners "Soil Testing Gas Draw, Gas Hills,Fremont County,WY "
SEIFFERT,S Q Wyoming, State of 83/03/23 PETTENGILL,H J Uranium Recovery Field Office 3pp 18540 269

--8305200037 "Soil Testing Gas Draw,Gas Hills,Fremont County,WY " W/four oversize maps Aperture cards are available in PDR
* Federal American Partners 83/02/28 44pp 18540 272

8305130319 Notice of negative declaration re issuance of amend to License SUA-667 for operation of Federal-American Partners U mill in Gas Hills,WY
LINEHAN,J J Uranium Recovery Field Office 83/04/11 1p 18457 316

DOCKET 40-6500 ENERGY, DEPT OF, CANONSBURG, PA

8305180117 Forwards summary of data from radon monitoring network in Canonsburg,PA area for 811030-820129 Maps indicating monitoring locations encl
RUDY,C R Monsanto Co 83/04/15 GROW,W T Division of Fuel Cycle & Material Safety 1p 18503 320

--8305180125 "Mound Radon Program,Summary of Outdoor Canonsburg Monitoring Data," 811030-820129
* Monsanto Co 83/04/15 3pp 18503 321

8305170116 Summarizes possible use of models for groundwater flow & transport in saturated & unsaturated layers for various UMTRA sites
DEB,A K Roy F Weston, Inc 83/04/21 NIXON,W A NRC - No Detailed Affiliation Given 2pp 18496 361

8305180176 Comments on items of interest re listed meetings NMSS meeting notes encl
PAGE,R Q Uranium Fuel Licensing Branch 83/05/12 DAVIS,J G, Office of Nuclear Material Safety & Safeguards,Director 3pp 18502 354

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8305020410 Forwards effluent monitoring data & 40CFR190 rept for Fourth Quarter 1982 per License SUA-442,Amend 2,Condition 37 & corrected Table VIID & VIIE,re ingestion & total dose at Sites 7R & GP 1
SMITH,J C Pathfinder Mines Corp 83/03/24 BROWN,G D Region 4, Office of Director 1p 18281 266

--8305020504 "Environ Monitoring Data W/Dose Calculations,Fourth Quarter 1982 "
* Pathfinder Mines Corp 83/03/24 29pp 18281 267.

8305030277 Forwards effluent monitoring data rept for Fourth Quarter 1982 Corrected Tables VIID re ingestion dose & VIIE re total dose also encl
SMITH,J C. Pathfinder Mines Corp 83/03/24. GARCIA,P Uranium Recovery Licensing Branch 1p 18309 300

8305020491 Comments on State of WY Dept of Environ Quality 830222 ltr re environ monitoring program Deepening seepage collection trench would increase seepage rate & should be considered alternative
WILLIAMS,R E R E. Williams & Associates, Inc 83/03/29 GARCIA,P. Uranium Recovery Licensing Branch 4pp 18284 329.

8305130328 Forwards request for addl info re proposed reclamation plan for tailings impoundments for Shirley Basin Mine,per license renewal review
PETTENGILL,H J Uranium Recovery Field Office 83/03/31 RUSSELL,J E Pathfinder Mines Corp 5pp 18457 272

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs 83/04/27 DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 3pp 18306 198

DOCKET 40-6659 GETTY OIL CO - PETROTOMICS CO , SHIRLEY BASIN, WY

8305020439 Forwards environ sample data for Third Quarter 1982
PFAFF,S J Getty Oil Co (Petrotomics) 83/03/02 NRC - No Detailed Affiliation Given 2pp 18281 146

--8305020443 Environ sample data,Third Quarter 1982
* Getty Oil Co (Petrotomics) 83/03/02 65pp 18281 148

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs, 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 3pp 18306 198

DOCKET 40-7097 MOLYCORP, INC , WHITE PLAINS, NY

8305180200 Submits summary of decommissioning plan for facility Info needed to complete cost estimates included
WARHOL,W N Molycorp, Inc 83/04/21 SOONG,A L NRC - No Detailed Affiliation Given 2pp. 18502 360

DOCKET 40-7580 FANSTEEL, INC , NORTH CHICAGO, IL

8305160004 Application for amend to License SMB-911,authorizing const & operation of pond to receive,settle & store calcium base residues from regular industrial process stream W/four oversize maps Aperture cards available in PDR
DUGGAN,J G, Fansteel Metals (subs of Fansteel,Inc) 83/03/04 Licensing Management Branch 6pp 18462 348

8305160258 Forwards 830304 application for amend to License SMB-911, apparently not received
DUGGAN,J G Fansteel, Inc 83/03/22 NRC - No Detailed Affiliation Given 1p 18475 043

--8305160261 Application for amend to License SMB-911 to construct & operate interior-lined pond to receive,settle & store calcium-base residues from industrial process stream
DUGGAN,J G Fansteel, Inc 83/03/04 NRC - No Detailed Affiliation Given 6pp 18475 044

DOCKET 40-7708 UNION CARBIDE CORP , NEW YORK, NY

8305180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses,from U Fuel Licensing Branch to Region III
PAGE,R Q. Uranium Fuel Licensing Branch 83/05/05 HIND,J A Region 3, Office of Director 1p 18505 075

8305180824 Notifies that official files for License SBM-933 transferred to Region III as of 830401,as part of regional licensing program W/o stated FR notice
PAGE,R Q Uranium Fuel Licensing Branch 83/05/05 BEVERLY,R Q. Union Carbide Corp 1p. 18505 361

8305200154 Confirms 830504 conversation re expiration of License SMB-933 License amended to delete Item 4 expiration date of 770831 License shall remain in effect until NRC action initiated to terminate license
PAGE,R.Q Uranium Fuel Licensing Branch 83/05/16 BEVERLY,R Q Union Carbide Corp 1p 18540 244.

DOCKET 40-7869 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO

8305040047 Forwards "Effluent Monitoring Rept,Jul-Dec 1982 "
GERDEMAN,F W. Plateau Resources, Ltd 83/04/13 Region 4, Office of Director 1p 18336.348.

--8305040052 "Effluent Monitoring Rept,Jul-Dec 1982 "
* Plateau Resources, Ltd 83/04/13 10pp 18336.349

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,Q D Division of Vendor & Technical Programs 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director
3pp 18306 198

8305250199 Recommends mod to License Condition 12 re transfer & disposal of contaminated matl at Shootaring Canyon mill tailings impoundment Mod authorizes Plateau Resources Limited 830221 proposal for use of three-drum slusher
JOHNSON,T L , LINEHAN,J J Uranium Recovery Field Office 83/05/10
Uranium Recovery Field Office 1p 18595 358

DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8305030237 Issues Amend 21 to License SUB-1010,requiring sampling & analyzing of sediment every 6 months SER supporting amend encl
PAGE,R Q Uranium Fuel Licensing Branch 83/04/20 SHELLEY,W J
Kerr-McGee Nuclear Corp 2pp 18309 340

--8305030246 SER supporting Amend 21 to License SUB-1010 re sampling & analyzing sediment
RHODES,M Uranium Fuel Licensing Branch 83/04/20 6pp
18309 343

8305200052 Forwards 1982 completion rept re continued use of barium treated,neutralized solvent extraction raffinate as fertilizer,per Condition 12 of Amend 17 to License SUB-1010 W/two oversize figures Aperture cards in PDR
SHELLEY,W J Kerr-McGee Nuclear Corp 83/04/26 PAGE,R Q Uranium Fuel Licensing Branch 25pp 18528 314

8305180325 Discusses items of interest,including natl response team, FES for Kerr-McGee Rare Earth facility & radioactive property in Wayne,NJ
PAGE,R Q Uranium Fuel Licensing Branch 83/05/05 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 2pp
18503 357

8305120479 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE insp of License SUB-1010 Addl info re corrective actions requested within 10 days of ltr receipt
BROWN,G D Region 4, Office of Director 83/05/10 SHELLEY,W J
Kerr-McGee Corp 1p 18431 057

8305250603 Issues Amend 22 to License SUB-1010,authorizing injection of treated liquid raffinate in Sequoyah waste disposal well SER encl
PAGE,R Q Uranium Fuel Licensing Branch 83/05/18 SHELLEY,W J
Kerr-McGee Nuclear Corp. 1p 18594 316

--8305250604 SER supporting Amend 22 to License SUB-1010,authorizing injection of treated liquid raffinate in Sequoyah waste disposal well
WYNGARDEN,S.D. Uranium Fuel Licensing Branch 83/05/18 5pp
18594 317

DOCKET 40-8035 COTTER CORP , ROSWELL, NM

8305180183 Advises that only solution is cinst of masonry bldg w/concrete floor & roof Cotter has agreed to addl cost Prof drawings & procedures will be forwarded upon agreement w/alternate approach
JARBOE,E D Futura Coatings, Inc 83/04/18 CROW,B NRC - No
Detailed Affiliation Given 2pp 18502 357.

8305040707 Summary of meeting w/State of MO & Futura Chemical Co re possibility of restricting access to pile of contaminated soil w/residues from extraction of U from ore during World War II.Bldg should be constructed to house soil.
PAGE,R Q Uranium Fuel Licensing Branch 83/04/28 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 2pp
18336,333

8305110117 Trip rept of 830421 meeting w/State of MO & Futura Chemical in Hazelwood,MO re State of MO proposals to restrict access to Futura Chemical property
CROW,W.T. Uranium Fuel Licensing Branch 83/05/02 Uranium Fuel
Licensing Branch 1p 18421 315

8305180176 Comments on items of interest re listed meetings.NMSS meeting notes encl
PAGE,R Q Uranium Fuel Licensing Branch 83/05/12 DAVIS,J G
Office of Nuclear Material Safety & Safeguards,Director 3pp
18502,354.

DOCKET 40-8064 EXXON MINERALS CO USA, HOUSTON, TX

8305030719 Forwards summary of U data for Original Pilot In Situ Mine included in 821102 & 830128 quarterly repts
ESTEY,H P Exxon Corp 83/04/06 LINEHAN,J J Uranium Recovery
Field Office 2pp 18310 356

8305170242 Submits review comments on proposed restoration/post-restoration program for Exxon Highland Mill Mods to target restoration value & excursion monitoring program recommended Program acceptable
FREUDENTHAL,N , SMITH,M Wyoming, State of 83/04/11 SMITH,R D
Uranium Recovery Field Office 4pp 18496 177

8305170595 Summarizes review of Expanded Pilot R&D wellfield quarterly rept for Oct-Dec 1982 No followup actions necessary
ROSS,F W , LINEHAN,J J Uranium Recovery Field Office 83/04/21
Uranium Recovery Field Office 2pp 18493 360

8305130363 Ack receipt of Exxon 830419 ltr Dept of Environ Quality does not object to Exxon mod of excursion monitoring program frequency from biweekly to monthly
FREUDENTHAL,N Wyoming, State of 83/04/25 LINEHAN,J Uranium
Recovery Field Office 1p 18443 321

8305260145 Quarterly rept for Jan-Mar 1983 Original pilot observation wells will be sampled monthly until regulatory concurrence received Health physics surveys taken monthly
SHANNON,J B Exxon Corp 83/04/27 LINEHAN,J J Uranium Recovery
Licensing Branch 9pp 18648 254

DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT

8305170585 Comments on 830215 survey rept re land use changes since 820901 rept No change identified which would warrant mods to environ monitoring program
WASTLER,S L , LINEHAN,J J Uranium Recovery Field Office
WASTLER,S L Licensing Branch 1 83/04/08 Uranium Recovery
Field Office 1p 18496 108

8305060462 Elaborates on 830301 telcon re liability of Rio Algom Corp in processing & shipping of U concentrate owned by Brush Wellman Inc Legally definitive answer to question of liability cannot be provided
EVERETT,R J Region 4, Office of Director 83/05/03 LAWTON,M D
Rio Algom, Ltd 2pp 18351 192

DOCKET 40-8102 EXXON CO USA, HOUSTON, TX

8305250195 Informs that Permit Rev TFN 1-6/242 (Permit 218C) will be considered incomplete until finalized reclamation plans submitted
SUNDIN,R E , FREUDENTHAL,N Wyoming, State of 83/03/25
SHANNON,J Exxon Corp 6pp 18596 353

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director
MICHELSON,C Director's Office 3pp 18306 198

DOCKET 40-8137 PACIFIC TECHNICAL CORP , SANTA BARBARA, CA

8305260267 Forwards IE Insp Rept 40-8137/83-01 on 830201-02 of activities under License SUB-1137 No noncompliance noted
BOOK,H E Region 5, Office of Director 83/05/10 FELDMAN,F K
Pacific Armatechnica Corp 2pp 18625 292

--8305260273 IE Insp Rept 40-8137/83-01 on 830201-02 No noncompliance noted Major areas inspected survey conducted in conjunction w/analytical assays of collected soil samples.Range 5 facility cannot be released for unrestricted use
SKOV,D.D , THOMAS,R D , BOOK,H E Region 5, Office of Director
83/05/10 23pp 18625 294

DOCKET 40-8202 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

8305060623 Forwards IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401.No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/05/03 UNGAR,E W
Battelle Memorial Institute, Columbus Laboratories 2pp
18348 251

--8305060634 IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401
No noncompliance noted Major areas inspected radiation protection,radwaste mgt,facility changes & safety committees
PECK,C C , GREGER,L R Region 3, Office of Director 83/04/29
6pp 18348 293

DOCKET 40-8348 MINERALS EXPLORATION CO , LOS ANGELES, CA

8305060222 Discusses groundwater restoration & water quality analysis from land quality div sampling conducted in Dec 1982 Site should not be declared acceptably restored & holes should not be plugged Site should not be claimed as restored
KEARNEY,B Wyoming, State of 83/03/23 Wyoming, State of
10pp 18364 309

8305130298 Comments on outstanding licensing review issues re A-3 Pilot Plant R&D ISL facility Meeting to settle issues recommended
WASTLER,S L Uranium Recovery Field Office 83/04/21 Uranium Recovery Field Office 2pp 18460 040

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CO , BROOMFIELD, CO

8305060226 Suggests presence at 830509-11 or 16-18 meetings w/land & water quality divs to discuss findings for final decision re Rocky Mountain Engineering plans for Nine Mile Lake
BEACH,G Wyoming, State of. 83/04/07. LINEHAN,J Uranium Recovery Field Office 1p 18359 362

8305160274 Recommends 830511 meeting to discuss recent 9-mile proposal in order to draft final decision
BEACH,G Wyoming, State of. 83/04/15 SUNDIN,R , GARLAND,B ,
SHAFFER,R Rocky Mountain Energy Co 1p 18475 042

8305260364 "Nine Mile Lake Quarterly Rept First Quarter 1983."
SPIELES,P R Rocky Mountain Energy Co 83/04/30 SMITH,R D
Region 4, Office of Director 16pp 18648 005

DOCKET 40-8406 PESSES CO , SOLON, OH

8305180759 Lists official docket files & outstanding licensing actions transferred to Region I,effective 830401
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 MARTIN,T T
Division of Engineering & Technical Programs 1p 18506 053.

8305180820 Notifies that official files for License STB-1254 transferred to Region I as of 830401,as part of regional licensing program W/o stated FR notice
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 PESSES,M
Pesses Co 1p. 18505 360

DOCKET 40-8452 BEAR CREEK URANIUM CO , CASPER, WY

8305020363 Forwards "Quarterly Environ Monitoring Rept,Oct-Dec 1982 "
BLOSSOM,J N Bear Creek Uranium Co 83/03/04 Region 4, Office of Director. 1p 18276 344

8305020476 Submits evaluation of licensee 821206 environ monitoring rept for Third Quarter 1982 per 10CFR40 65 Requirements of 10CFR40 65 should be discussed w/licensee during next insp re compliance w/reporting period & rept timeliness
SPITZBERG,D.B Region 4, Office of Director 83/03/09 Region 4, Office of Director 1p. 18283 270

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director
MICHELSON,C Director's Office 3pp 18306 198

8305250245 Discusses review of Bear Creek U Co rept for Third Quarter 1982 Remedial action not indicated
PANGBURN,G C , PETTENGILL,H J Uranium Recovery Field Office
83/04/27 Uranium Recovery Field Office 6pp 18626 355.

8305250591 Comments on environ monitoring data rept for Fourth Quarter 1982 for Bear Creek Rept acceptable
PANGBURN,G C , PETTENGILL,H J Uranium Recovery Field Office
83/04/27 Uranium Recovery Field Office 6pp 18594:331

DOCKET 40-8502 WYOMING MINERAL CORP , LAKEWOOD, CO

8305160209 Informs of acceptance of 830317 data & drawdown maps demonstrating stabilization of well fields
MOONEY,G Wyoming, State of 83/04/11 FAUBER,J R Wyoming Mineral Corp 1p 18471 342

8305260144 "Irigaray Mine Site Quarterly Rept,Jan-Mar 1983 " W/830427 ltr
RUTLEDGE,C Wyoming Mineral Corp 83/04/27 CHANCELLOR,R.
Wyoming, State of 146pp 18648 263

DOCKET 40-8550 HOLMES & NARVER, INC , ANAHEIM, CA

8305250594 Forwards decontamination rept re final alpha survey for License SUA-1307 Acceptance of survey requested W/o encl
PETTENGILL,H.J Uranium Recovery Field Office 83/05/16 BROWN,G.
Region 4, Office of Director 1p 18594 327

DOCKET 40-8584 MINERALS EXPLORATION CO , LOS ANGELES, CA

8305030705 Discusses review of Dames & Moore, "Rept of Engineering Design Study,Tailings Disposal Sys,Sweetwater U Project,Near Rawlins,WY " dtd 820913 Engineer should be present to control field testing
HOWARD,T R R E Williams & Associates, Inc 83/04/04 GARCIA,P.
Uranium Recovery Licensing Branch 1p 18309 108

8305040002 Forwards memo outlining major deficiencies in application to amend modified tailings pond,including liner,aquifer monitoring & leak detection & long-term stability of reclamation pond Review of application incomplete
ENGELMANN,R. Wyoming, State of 83/04/04 DYKERS,L Minerals Exploration Co (subs of Union Oil Co of California). 13pp
18331.254

8305060389 Forwards 830325 ltr of bond transmittal & 830223 bond evaluation from State of WY Dept of Environ Quality per License Condition 17 to License SUA-1350
SNYDER,H L. Union 76 Minerals Exploration Co 83/04/05,
PETTENGILL,H Uranium Recovery Field Office. 9pp 18359:290

8305130317 Forwards request for addl info re proposed operational & reclamation plans for various alternatives for above-grade disposal Response by 830502 requested
PETTENGILL,H J Uranium Recovery Field Office 83/04/07.
SNYDER,H L Minerals Exploration Co (subs of Union Oil Co of California) 2pp 18457 317

8305160211 Notifies of 830510 joint meeting w/NRC re tailings mod license/permit Rev TFN 1 5/294 Comments/issues for discussion requested
BEACH,G Wyoming, State of 83/04/18 SNYDER,L Minerals Exploration Co (subs of Union Oil Co of California) 1p.
18462 362.

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director
3pp 18306 198

DOCKET 40-8602 SILVER KING MINES, INC , CASPER, WY

8305120490 Comments on preoperational environ monitoring rept submitted on 830223 for Morton Ranch Project for License SUA-1356
WOOLSEY,R.T., PETTENGILL,H.J Uranium Recovery Field Office.
83/04/07 Uranium Recovery Field Office 3pp 18440 211.

DOCKET 40-8663 NUCLEAR DYNAMICS, INC , PHOENIX, AZ

8305130336 Advises that general content of 830330 request to renew License SUA-1331 acceptable.Before facility at Oshoto site can be abandoned,plan for decontamination of site facilities must be submitted.
LINEHAN,J J Uranium Recovery Field Office. 83/04/21. STOICK,A F.
Nuclear Dynamics. 2pp. 18457:321

8305240596 Modifies License SUA-1331,License Condition 4,extending expiration date for decommissioning activities to 840430
SMITH,R D Uranium Recovery Field Office 83/04/28 STOICK,A F.
Nuclear Dynamics. 1p. 18594 210

DOCKET 40-8675 ENERGY FUELS NUCLEAR, INC , DENVER, CO

8305160256 Advises of issuance of amend to License SUA-1325 revising License Conditions 6-8 & adding License Condition 30
SMITH,R D Uranium Recovery Field Office 83/04/19 Energy Fuels Nuclear, Inc 2pp 18475 050

--8305160259 Safety evaluation supporting Amend 2 to License SUA-1325 re suspension of environ monitoring program at Hanksville Ore Buying Station
GILLEN,D M , PETTENGILL,H J Uranium Recovery Field Office 83/04/19 3pp 18475 052

DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO

8305020481 Forwards "White Mesa Project Effluent & Monitoring Rept Oct-Dec 1982 "
ROBERTS,H R Energy Fuels Nuclear, Inc 83/02/28 GILLEN,D Uranium Recovery Licensing Branch 1p 18282 300

--8305020484 "White Mesa Project Effluent & Monitoring Rept Oct-Dec 1982 "
* Energy Fuels Nuclear, Inc 83/02/28 31pp 18282 301

8305030499 Forwards fuel cycle & matls LER summary for Mar 1983
BROWN,G D Division of Vendor & Technical Programs 83/04/27
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 3pp 18306 198

DOCKET 40-8693 OGLE PETROLEUM, INC , SANTA BARBARA, CA

8305160251 Advises of issuance of amend to License Condition 2 of License SUA-1336,changing address
SMITH,R D Uranium Recovery Field Office 83/04/14 Ogle Petroleum, Inc 1p 18471 361

DOCKET 40-8697 ROCKY MOUNTAIN ENERGY CO , DENVER, CO

8305060651 Discusses final groundwater restoration - Pattern II Restoration successfully demonstrated at Pattern II for all parameters,except U & pH Lab repts encl
SCHMITTDIEL,P Wyoming, State of 83/03/21 Wyoming, State of 8pp 18359:299

8305030713 Forwards rept on insp & Pattern 2 sampling conducted 830208-09 Rept placed in permanent insp file for Permit 479
MOONEY,G Wyoming, State of 83/04/11 SPIELES,P Rocky Mountain Energy Co 9pp. 18309 081

8305250171 Quarterly rept for Jan-Mar 1983 Both wells will remain shut/down while regulatory agencies evaluate restoration stability If restoration signoff received,well abandonment procedures will be initiated
SPIELES,P R Rocky Mountain Energy Co 83/04/18 SMITH,R D Uranium Recovery Field Office 18pp 18626 330

8305250241 Requests approval for releasing Rocky Mountain Energy from further groundwater restoration for Reno Creek ISL project
MOONEY,G Wyoming, State of 83/04/27 SUNDIN,R E , FREUDENTHAL,N Wyoming, State of 1p. 18626 361

8305250283 Reviews 820716 groundwater stabilization rept for Test Pattern II at Reno Creek.Restoration program should exert greater effort to achieve lower concentrations Licensee should be notified that Pattern II restored
KALMAN,K L , LINEHAN,J J Uranium Recovery Field Office, 83/05/03 Uranium Recovery Field Office 5pp 18595 305

DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO

8305260418 Forwards corrected Page 1 to "Interim Surety Estimates for Decommissioning & Reclamation,Apr 1983," forwarded in 830411 ltr.Encl page entitled "List of Revs" should be inserted after title page.
GERDEMAN,F W. Plateau Resources, Ltd 83/04/12 SMITH,D NRC - No Detailed Affiliation Given 3pp 18629 357

DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO , CLEVELAND, OH

8305060357 Forwards analysis of water samples taken at Collins Draw site Well Fields A & B samples exceeded baseline range for several parameters,including potassium,ammonia,arsenic & selenium
OGLE,K M Wyoming, State of 83/01/31 Wyoming, State of 18pp 18359 272

8305160232 Requests official communication or meeting to determine compliance w/Collins Draw groundwater restoration agreement. License 3RD & WY Environ Quality Act
LOUDERBACK,T E Cleveland-Cliffs Iron Co 83/04/15 MOONEY,G Wyoming, State of 5pp 18471 343

8305260383 Forwards Cleveland-Cliffs 830415 ltr to State of WY Land Quality Div re Collins Draw Project,per 830429 discussions
LOUDERBACK,T E Cleveland-Cliffs Iron Co 83/04/29 ROSS,F Uranium Recovery Licensing Branch 36pp 18647 213

DOCKET 40-8722 BRUSH WELLMAN, INC , CLEVELAND, OH

8305060462 Elaborates on 830301 telcon re liability of Rio Algom Corp in processing & shipping of U concentrate owned by Brush Wellman,Inc Legally definitive answer to question of liability cannot be provided
EVERETT,R J Region 4, Office of Director 83/05/03 LAWTON,M D Rio Algom, Ltd 2pp 18351 192

DOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY

8305030709 Forwards response to 821018 ltr re M Zone restoration stability data,for review & discussion
MCCARTY,C L , PUGEL,P Wyoming, State of 83/03/15 APPEL,D Teton Exploration Drilling Co , Inc 11pp 18309 093

8305030253 Requests review input for restoration & stability of "M" Zone Teton,Levenberger sites & verification sampling as wrap-up
FRANCIS,E Wyoming, State of 83/03/25 GARLAND,G Wyoming, State of 1p 18309 334

--8305030262 Notifies that discussions recently held w/RR Appel of Teton Exploration Co re procedures for declaration of restoration of M Zone aquifer
FRANCIS,E Wyoming, State of 83/03/23 LINEHAN,J Uranium Recovery Licensing Branch 1p 18309 335

--8305030273 Notifies that Land Quality Div Permit 522 was approved w/certain stipulations Upper control limit methodology for U & chloride in land quality permit should be identical to limits specified in NRC licensing action
FREUDENTHAL,N Wyoming, State of 83/03/23 LINEHAN,J Uranium Recovery Licensing Branch 3pp 18309 336

8305130281 First Quarterly Rept for 1983 re pond water level, radiological monitoring,site security checks & site cleanup programs
APPEL,R R Teton Exploration Drilling Co , Inc 83/04/01
SMITH,R D Division of Waste Management 8pp 18457 345

DOCKET 40-8745 OGLE PETROLEUM, INC , CASPER, WY

8305160253 Advises of issuance of amend to License Condition 2 of License SUA-1396,changing address
SMITH,R D Uranium Recovery Field Office 83/04/14 Ogle Petroleum, Inc 1p 18471 362

DOCKET 40-8752 FINAL MINERALS & MINING, LTD , MIAMI, AZ

8305130322 Advises that License SUA-1388 amended by revising License Conditions 3 & 14 & adding License Condition 15
SMITH,R D Uranium Recovery Field Office 83/04/22 Final Minerals & Mining, Ltd 3pp 18457 308.

--8305130325 Advises that License SUA-1388 amended,extending existing license for 1 yr of possession only,during present nonoperational period
GILLEN,D M Uranium Recovery Field Office 83/04/22 Uranium Recovery Field Office 5pp 18457 311

DOCKET 40-8763 ALUCHEM, INC , READING, OH

8305180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses, from U Fuel Licensing Branch to Region III
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 HIND, J A Region 3, Office of Director 1p 18505 075 .

8305160834 Notifies that official files for License SMB-1375 transferred to Region III as of 830401, as part of regional licensing program W/o stated FR notice
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 ZAPLETAL, R P ALUCHEM, Inc 1p 18506 010

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8305130337 Submits review of licensee Quarterly Repts for 1982 re Q Sand R&D In Situ Project No problems or significant data trends identified Reported data within applicable limits
GILLEN, D M Uranium Recovery Field Office 83/04/12 Uranium Recovery Field Office 4pp 18443 353

8305260404 Advises that gamma survey data confirmed Q-sand survey points, except pregnant surge tank area, are near background levels
FREEMAN, M D Kerr-McGee Nuclear Corp 83/05/10 GILLEN, D Uranium Recovery Field Office 1p 18647 185

DOCKET 40-8783 URANERZ USA, INC , CASPER, WY

8305060363 Issues Amend 4 to License SUA-1401, deleting Conditions 13 & 35 & revising Conditions 14, 16, 17 & 19 re well completion data, upper control limits & integrity tests
SMITH, R D Uranium Recovery Field Office 83/03/25 Uranerz USA, Inc 5pp 18353 095

--8305060369 Safety evaluation supporting Amend 4 to License SUA-1401
YOUNG, Y A , ROSS, F W , LINEHAN, J J Uranium Recovery Field Office 83/03/25 9pp 18353 100

8305130330 Advises that no further licensing action necessary for approval of surface discharge from evaporation ponds Intent of License Condition 49 does not apply
SMITH, R D Uranium Recovery Field Office 83/04/15 Uranerz USA, Inc 1p 18443 360

--8305130333 Advises that no amend necessary to allow licensee to discharge water from evaporation ponds License Condition 49 does not apply
YOUNG, Y A , LINEHAN, J J Uranium Recovery Field Office 83/04/13 Uranium Recovery Field Office 2pp 18443 361

DOCKET 40-8786 URANIUM RESOURCES, INC , RICHARDSON, TX

8305160228 Application for amend to License SUA-1400, adjusting technical monitoring requirements during stability to permit nontechnical persons to perform nontechnical insps
PELIZZA, M S Uranium Resources, Inc 83/04/08 LINEHAN, J J Uranium Recovery Field Office 3pp 18471 348

8305250275 Informs that S McArt meets license requirements & qualifications for radiation safety technician
WESTBROOK, K B , LINEHAN, J J Uranium Recovery Field Office, 83/04/28 Uranium Recovery Field Office 1p 18595 331

8305250279 Comments on 821014 decommissioning plan for North Platte facility Info re locations & depths for soil samples, grid spacing used for soil survey & means of stabilizing sand & sludge left in evaporation ponds requested
WESTBROOK, K B , LINEHAN, J J Uranium Recovery Field Office 83/04/29 Uranium Recovery Field Office 3pp 18595 328

8305250270 Submits review of U Resources, Inc 821208 response to notice of violation from insp on 821004-07 Corrective actions acceptable
JOHNSON, T L , LINEHAN, J J Uranium Recovery Field Office 83/05/05 Uranium Recovery Field Office 1p 18595 332

8305250593 Comments on Third & Fourth Quarter 1982 repts & preoperational monitoring info for License SUA-1400 Review of frequency of post-excursion confirmatory samples & consideration of calcium excursion problem recommended
JOHNSON, T L , LINEHAN, J J Uranium Recovery Field Office 83/05/05 Uranium Recovery Field Office 3pp 18594 328

DOCKET 40-8829 WYOMING FUEL CO , LAKEWOOD, CO

8305130288 Forwards administrative order issued by State of NE to Wyoming Fuel Co & questions & statements to be addressed for underground injection control permit application
WALL, R B Nebraska, State of 83/04/18 LINEHAN, J J Uranium Recovery Field Office 12pp. 18457 353

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions NUREG-0654-FEMA-REP-1, Rev 1 stds would place heavy resource burden on state
GIUFFRIDA, L O Federal Emergency Management Agency 83/04/18
PALLADINO, N J. Commissioners 1p 18542 329. 24X
Fiche 50-003, 83/04/18, 8305230670

--8305230676 Seeks clarification of issue re FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan
PALLADINO, N J Commissioners 83/03/30 GIUFFRIDA, L O Federal Emergency Management Agency 2pp 18542 330 24X
Fiche 50-003, 83/04/18, 8305230670

8305020548 Responds to 830107 ltr re Rev 4 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable
VARGA, S A Operating Reactors Branch 1 83/04/20 Consolidated Edison Co of New York, Inc. 1p 18284 257 24X
Fiche 50-003, 83/04/20, 8305020548

8305020575 Responds to 830128 ltr re Rev 3 to safeguards contingency plan Changes consistent w/10CFR50 54(p) & acceptable
VARGA, S A Operating Reactors Branch 1 83/04/20 O'TOOLE, J D Consolidated Edison Co. of New York, Inc 1p 18284 232 24X
Fiche 50-003, 83/04/20, 8305020575

8305040235 Releases public version of rev to emergency plan & emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch. 1p. 18364 188 24X Fiche 50-003, 83/04/22, 8305040235

--8305040242 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
O'TOOLE, J. D Consolidated Edison Co. of New York, Inc. 83/04/07, HAYNES, R C Region 1, Office of Director 2pp 18364 190 24X
Fiche 50-003, 83/04/22, 8305040235

--8305040247 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
LIEBLER, G H Consolidated Edison Co of New York, Inc 83/03/08 Office of Nuclear Reactor Regulation, Director 2pp 18364 192 24X Fiche 50-003, 83/04/22, 8305040235

--8305040249 Public version of rev to Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility."
* Consolidated Edison Co. of New York, Inc 83/03/08 18pp 18364 194 24X Fiche. 50-003, 83/04/22, 8305040235

--8305040254 Public version of revised emergency plan.
* Consolidated Edison Co of New York, Inc. 83/03/07 49pp. 18364 212 24X Fiche 50-003, 83/04/22, 8305040235

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G, Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540.095 24X
Fiche 50-000, 83/05/11, 8305110034.

P Operating license stage documents & correspondence

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441·120 24X
Fiche 50-000, 83/05/02, 8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp. 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/11. Consolidated Edison Co of New York, Inc 114pp 18524.003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche, 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & "Annual Radiological Environ Operating Rept, 1982," per App B to OLs
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/02
ALLAN, J M Region 1, Office of Director 2pp 18392 221 24X
Fiche 50-003, 83/05/02, 8305110302

--8305110307 "Annual Environ Protection Plan Rept for 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 8pp
18392 223 24X Fiche 50-003, 83/05/02, 8305110302

--8305110310 "Annual Radiological Environ Operating Rept, 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 112pp
18392 231 24X Fiche 50-003, 83/05/02, 8305110302

T Hearing transcripts on non-antitrust matters

8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR, per 10CFR9 Commission determination statement encl
CHILK, S J Office of the Secretary of the Commission 83/05/18
Public Document Branch 2pp 18593 063 24X Fiche 50-003, 83/05/18, 8305240566

--8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington, DC
* Commissioners 82/12/22 15pp 18593 065 24X
Fiche 50-003, 83/05/18, 8305240566

--8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington, DC
* Commissioners 82/12/22 59pp 18593 082 24X
Fiche 50-003, 83/05/18, 8305240566

DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO, C J Region 3, Office of Director 83/04/29 REED, C
Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010, 83/04/29, 8305030336

--8305030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29 2pp 18297 139 24X
Fiche 50-010, 83/04/29, 8305030336

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR50, App E Emergency plans upgraded per NUREG-0737, Item III A 2 1 Item complete
CRUTCHFIELD, D Operating Reactors Branch 3 83/05/11 FARRAR, D. L
Commonwealth Edison Co 3pp 18423 040 24X Fiche 50-010, 83/05/11, 8305120116

J. Insurance & indemnity information

8305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Dresden Unit 1 & Endorsement 63 to NELIA Policy NF-201 & Endorsement 53 to MAELU Policy MF-64 for Zion Unit 1 W/o encl Quad Cities endorsements
OSTER, J Commonwealth Edison Co 83/05/13 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 18537 174 24X
Fiche 50-000, 83/05/13, 8305230500

P Operating license stage documents & correspondence

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche, 50-000, 83/05/02, 8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche,50-000,83/03/21,8212060385

8305020467 Forwards IE Insp Repts 50-010/83-06,50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted
STREETER,J F Region 3, Office of Director 83/04/13 REED,C Commonwealth Edison Co 2pp 18283 073 24X Fiche 50-010,83/04/13, 8305020467

--8305020480 IE Insp Repts 50-010/83-06,50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted Major areas inspected operational safety,maint,surveillance,licensee events,plant trips,refueling activities & refueling surveillance
TONGUE,T M , JORDAN,M J , STASEK,S Region 3, Office of Director 83/04/12 16pp 18283 075 24X Fiche 50-010,83/04/13,8305020467,

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383,089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020100 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04
SHAFER,W D Region 3, Office of Director 83/04/25 REED,C Commonwealth Edison Co 1p 18278 243 24X Fiche 50-010,83/04/25, 8305020100

--8305020106 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-010/83-05,50-237/83-05 & 50-249/83-04 Corrective actions Amend 71 reissued & incorporated into Tech Specs Corporate QA dept will audit accounting & followup sys
FARRAR,D L Commonwealth Edison Co 83/03/30 KEPPLER,J.G Region 3, Office of Director 3pp 18278 244 24X Fiche 50-010,83/04/25,8305020100

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28. Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026,

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co, of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO,C.J Region 3, Office of Director 83/04/29 REED,C Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010,83/04/29, 8305030336

--8305030348 Notice of deficiencies from insp on 830103-07,Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29. 2pp. 18297 139 24X Fiche 50-010,83/04/29,8305030336

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305100181 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24
SHAFER,W D. Region 3, Office of Director 83/05/03 REED,C Commonwealth Edison Co 1p. 18374:318 24X Fiche 50-010,83/05/03, 8305100181

--8305100190 Responds to NRC 830311 ltr re deficiencies noted in IE Insp Repts 50-010/82-17,50-237/82-24 & 50-249/82-24 Corrective actions written agreement,EPIP200-11 re PMF for Units 2 & 3 between Corps of Engineers & util to be revised
RYBAK,B Commonwealth Edison Co 83/04/11 KEPPLER,J.G. Region 3, Office of Director 4pp 18374 319 24X Fiche 50-010, 83/05/03,8305100181

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001. 24X Fiche 50-000,83/05/04,8303040031,

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523:248 24X Fiche 50-000,83/05/06,8303040033,

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524·003 24X Fiche 50-000,83/05/11,8303040034,

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647·007 24X Fiche 50-000,83/05/26,8303040046,

DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

S Reportable occurrences: LERs & related correspondence

8305160043 RO 50-20/1983-1 on 830419,main intake valve closed & could not be reopened Caused by piston rod rupture near rod eye, leaving valve in closed position Defective hydraulic cylinder shaft replaced
KNOX,K., CLARK,L Massachusetts Institute of Technology 83/04/29. ALLAN,J M , KINNEY,W Region 1, Office of Director 6pp. 18444 001 24X Fiche, 50-020,83/04/29,8305160043.

DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8305060192 Notifies that emergency plan exercise planned for 830406. Schedule coordinated w/plume emergency planning zone states & FEMA,Region I
KAY,J A Yankee Atomic Electric Co 82/12/16 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18345 224. 24X Fiche, 50-029,82/12/16,8305060192

8305060215 Forwards objectives for 830406 emergency plan exercise,per util 830113 & NRC 830202 ltrs
KAY,J A Yankee Atomic Electric Co 83/02/08 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18345·095 24X Fiche, 50-029,83/02/08,8305060215

8305110010 Forwards "'Emergency Offsite Facility - Out' Emergency Exercise & Evaluation Plan," for 1983
KAY, J A Yankee Atomic Electric Co 83/03/15 HAYNES, R C Region 1, Office of Director 1p 18409 260 24X Fiche 50-029, 83/03/15, 8305110010

--8305110020 "'Emergency Offsite Facility - Out' Emergency Exercise & Evaluation Plan "
* Yankee Atomic Electric Co 83/03/15 106pp 18409 261 24X Fiche 50-029, 83/03/15, 8305110010

8305110049 Comments on implementation of NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 " Onsite & offsite emergency preparedness adequate
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/10 KAY, J A Yankee Atomic Electric Co 3pp 18409 014 24X Fiche 50-029, 83/05/10, 8305110049

8305240227 Forwards IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/10 HEIDER, L H Yankee Atomic Electric Co 2pp 18548 315 24X Fiche 50-029, 83/05/10, 8305240227

--8305240232 IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted Major areas inspected, emergency preparedness & observation of Phase I of annual exercise performed on 830406
MILLER, M T , CROCKER, H W Division of Engineering & Technical Programs 83/05/06 5pp 18548 317 24X Fiche 50-029, 83/05/10, 8305240227

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305250274 Advises that rev to security plan dtd 830209 consistent w/10CFR50 54(p) & acceptable Rev will be withheld (ref 10CFR73 21 & 9 12)
ALLAN, J M Region 1, Office of Director 83/05/18 HEIDER, L H Yankee Atomic Electric Co 3pp 18592 298 24X Fiche 50-029, 83/05/18, 8305250274

J Insurance & indemnity information

8305120200 Forwards Endorsement 104 to NELIA Policy NF-76 & Endorsement 86 to MAELU Policy MF-26
SINISI, J M Marsh & McLennan, Inc 83/05/03 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 18427 355 24X Fiche 50-029, 83/05/03, 8305120200

O. Advisory Committee on Reactor Safeguards reports & correspondence
---

8305180664 Summary of ACRS 830223 meeting w/Subcommittee on SEP in Washington, DC to review facility integrated safety assessment
* ACRS - Advisory Committee on Reactor Safeguards 83/04/07
ACRS - Advisory Committee on Reactor Safeguards 18pp. 18502 327 24X Fiche 50-029, 83/04/07, 8305180664

P Operating license stage documents & correspondence

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X Fiche. 50-000, 83/05/02, 8305020455.

8305170459 Forwards proposed schedule for resolution of SEP integrated assessment open items identified in NUREG-0825, "Integrated Plant Safety Assessment " NRC will be informed immediately of any schedular difficulties.
KAY, J. A Yankee Atomic Electric Co 83/05/02 CRUTCHFIELD, D Operating Reactors Branch 5 5pp. 18469 321 24X Fiche 50-029, 83/05/02, 8305170459.

8305040526 Advises that util action taken per Amend 79 to License DPR-3 re disposal of high level spent fuel through DOE contract & Generic Ltr 83-07 re Nuclear Waste Policy Act of 1982, considered complete.
CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/03. KAY, J A Yankee Atomic Electric Co. 2pp. 18321 242 24X Fiche. 50-029, 83/05/03, 8305040526.

8305100228 Submits addl info re environ qualification of safety-related electrical equipment to suppl 830201 response, providing justification for continued operation for Category I D, II A & II B items
KAY, J A Yankee Atomic Electric Co 83/05/06 EISENHUT, D G Division of Licensing 3pp 18374 131 24X Fiche 50-029, 83/05/06, 8305100228

8305110214 Summary of 830426 meeting w/util & Bechtel re licensee request for relief from installation of reactor vessel water level indication sys Slide presentations encl
LYONS, J E Operating Reactors Branch 5 83/05/06 Operating Reactors Branch 5 59pp 18406 342 24X Fiche 50-029, 83/05/06, 8305110214

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305240358 Responds to Generic Ltr 83-10A re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Util will perform plant-specific study applying RELAP5YA Code described in 830411 ltr Three-phase program described
HEIDER, L H Yankee Atomic Electric Co 83/05/13 EISENHUT, D G Division of Licensing 3pp 18575 101 24X Fiche. 50-029, 83/05/13, 8305240358

8305240364 Forwards updated list on environ qualification of safety-related electrical equipment, noting equipment added & deleted since previous submittal
KAY, J A Yankee Atomic Electric Co 83/05/20 EISENHUT, D G Division of Licensing 6pp 18575 095 24X Fiche 50-029, 83/05/20, 8305240364

8305240490 Forwards revised final SER for SEP Topics VI-2 D, "Mass & Energy Release for Possible Pipe Breaks Inside Containment" & VI-3, "Containment Pressure & Heat Removal Capability "
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/23 KAY, J A Yankee Atomic Electric Co 38pp 18572 030 24X Fiche 50-029, 83/05/23, 8305240490

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308, 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator, " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28, Consolidated Edison Co of New York, Inc. 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche. 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305240227 Forwards IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/05/10
HEIDER,L H Yankee Atomic Electric Co 2pp 18548 315 24X
Fiche 50-029,83/05/10,8305240227

--8305240232 IE Insp Rept 50-029/83-05 on 830405-08 No noncompliance noted Major areas inspected emergency preparedness & observation of Phase I of annual exercise performed on 830406
MILLER,H T , CROCKER,H W Division of Engineering & Technical Programs 83/05/06 5pp 18548 317 24X Fiche 50-029,83/05/10, 8305240227.

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305190017 Requests response to Required Actions 2,3,4 & 5 of IE Bulletin 83-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers " Response required within 10 days of receipt of request
STAROSTECKI,R Division of Project & Resident Programs 83/05/11
HEIDER,L H Yankee Atomic Electric Co 2pp 18501 359 24X
Fiche 50-029,83/05/11,8305190017

8305250427 Forwards IE Insp Rept 50-029/83-04 on 830208-0418 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs. 83/05/11
HEIDER,L H Yankee Atomic Electric Co 2pp 18585 245 24X
Fiche 50-029,83/05/11,8305250427

--8305250431 IE Insp Rept 50-029/83-04 on 830208-0418 No noncompliance noted Major areas inspected actions on previous insp items, operational safety verification reviews,plant maint observation & plant surveillance observation
COLLINS,S J , GALLO,R M Region 1, Office of Director 83/05/09 16pp 18585 247 24X Fiche 50-029,83/05/11,8305250427

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.

S Reportable occurrences, LERs & related correspondence

8305030590 Forwards LER 83-012/01T-0.
AUTIO,H A Yankee Atomic Electric Co 83/04/19 ALLAN,J A Region 1, Office of Director 1p 18305:360 24X Fiche 50-029,83/04/19, 8305030590

--8305030597 LER 83-012/01T-0 on 830405,while performing hot leak insp, bonnet stud found failed on PR-MOV-191.Caused by leakage from globe valve 90-20521AB Valve replaced w/gate valve 8-31552-12-X
FRENCH,L D Yankee Atomic Electric Co 83/04/19 Region 1, Office of Director 2pp 18305 361. 24X Fiche:50-029,83/04/19, 8305030590

8305050263 Forwards LER 83-013/01T-0
AUTIO,H A Yankee Atomic Electric Co. 83/04/27 ALLAN,J Region 1, Office of Director 1p 18338,041 24X Fiche 50-029,83/04/27, 8305050263

--8305050268 LER 83-013/01T-0 on 830413,review of design basis for low temp overpressure protection indicated that events in original basis could exceed pressure restrictions Caused by personnel error Procedures being revised
RICE,D A Yankee Atomic Electric Co 83/04/27 Region 1, Office of Director 2pp 18338 042 24X Fiche 50-029,83/04/27, 8305050263

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8305170495 Ack receipt of 830225 & 0413 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-054/83-01 Current method of conducting monthly channel checks of coolant flow in violation of Tech Specs
STAROSTECKI,R Division of Project & Resident Programs 83/05/10
MCGOVERN,J J Union Carbide Corp 2pp 18470 036 24X
Fiche 50-054,83/05/10,8305170495

--8305170504 Supplemental response to NRC 830210 ltr re violations noted in IE Insp Rept 50-054/83-01 Corrective actions Tech Specs define three channel surveillance insps
RUZICKA,W G Union Carbide Corp 83/04/13 KEIMIG,R R Region 1, Office of Director 4pp 18470 038 24X Fiche 50-054, 83/05/10,8305170495.

--8305170508 Responds to NRC ltr re violations noted in IE Insp Rept 50-054/83-01. Corrective actions:surveillance requirements for monthly channel test of coolant flow met during period 820803-0930.
RUZICKA,W G. Union Carbide Corp 83/02/25 STAROSTECKI,R Division of Project & Resident Programs 3pp 18470 042 24X
Fiche 50-054,83/05/10,8305170495

DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8305020322 Forwards IE Insp Rept 50-057/83-01 on 830214-17 & notices of violation & deviation
STAROSTECKI,R Division of Project & Resident Programs. 83/04/18.
HENRY,L G New York, State Univ of, Buffalo. 2pp 18277.117 24X
Fiche,50-057,83/04/18,8305020322

--8305020324 Notice of violation from insp on 830214-17.
* Region 1, Office of Director 83/04/18 2pp 18277·119. 24X
Fiche 50-057,83/04/18,8305020322.

--8305020327 Notice of deviation from insp on 830214-17
* Region 1, Office of Director. 83/04/18 1p 18277 121 24X
Fiche 50-057,83/04/18,8305020322.

--8305020332 IE Insp Rept 50-057/83-01 on 830214-17 Noncompliance noted· failure to implement instruction in radiation protection for security force,failure to review safety & nuclear safety committee did not meet twice per yr since Sept 1981
KINNEY,W W , ELBAGGER,T C Region 1, Office of Director 83/03/28 12pp. 18277:122 24X Fiche 50-057,83/04/18,8305020322

S. Reportable occurrences, LERs & related correspondence

8305100252 Forwards last page inadvertently omitted from recent submittal re accident analysis of HX leak.
HENRY,L G. New York, State Univ of, Buffalo 83/05/06.
THOMAS,C O Standardization & Special Projects Branch. 2pp.
18373 296. 24X Fiche 50-057,83/05/06,8305100252

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8305270316 Forwards IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs. 83/03/23
BRENIZER,J S Virginia, Univ. of, Charlottesville, VA 1p.
18642.210 24X Fiche.50-062,83/03/23,8305270316

--8305270325 IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted Major areas inspected.radiation protection
PEERY,W.W., BARR,K P Region 2, Office of Director 83/03/21. 6pp. 18642·211 24X Fiche 50-062,83/03/23,8305270316

Q Inspection reports, IE Bulletins & correspondence

8305270316 Forwards IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/23
BRENIZER, J S Virginia, Univ of, Charlottesville, VA 1p
18642 210 24X Fiche 50-062, 83/03/23, 8305270316

--8305270325 IE Insp Rept 50-062/83-01 on 830215-18 No noncompliance noted Major areas inspected radiation protection
PEERY, W W , BARR, K P Region 2, Office of Director 83/03/21
6pp 18642 211 24X Fiche 50-062, 83/03/23, 8305270316

8305270196 Ack receipt of 830414 ltr re IE Insp Rept 50-062/83-01 & omittance of asterisk by name indicating attendance at exit meeting Ltr will be filed w/rept to correct error NRC techniques for measuring radioactivity discussed
VERRELLI, D M Division of Project & Resident Programs 83/05/10
BRENIZER, J S Virginia, Univ of, Charlottesville, VA 1p
18637 232 24X Fiche 50-062, 83/05/10, 8305270196

--8305270226 Ack receipt of 830323 ltr & IE Insp Rept 50-062/83-01 Asterisk next to directors name indicating meeting attendance omitted NRC techniques for measuring radioactivity in water samples requested
BRENIZER, J S Virginia, Univ of, Charlottesville, VA 83/04/14
VERRELLI, D M Division of Project & Resident Programs 1p
18637 233 24X Fiche 50-062, 83/05/10, 8305270196

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

8305120057 Forwards Amend 13 to License TR-1, safety evaluation & notice of issuance & availability Amend deletes physical security requirements of 10CFR50 34c & 10CFR73
THOMAS, C. O Standardization & Special Projects Branch 83/05/03
DARMITZEL, R. W. General Electric Co 2pp 18443 234 24X
Fiche 50-070, 83/05/03, 8305120057

--8305120067 Amend 13 to License TR-1, deleting physical security requirements of 10CFR50 34c & 10CFR73
THOMAS, C O Standardization & Special Projects Branch. 83/05/03
2pp 18443 236 24X Fiche 50-070, 83/05/03, 8305120057

--8305120072 Safety evaluation supporting Amend 13 to License TR-1
* NRC - No Detailed Affiliation Given 83/05/03 2pp
18443 238 24X Fiche 50-070, 83/05/03, 8305120057

--8305120078 Notice of issuance & availability of Amend 13 to License TR-1
SCALETTI, D C Standardization & Special Projects Branch
83/05/03. 2pp 18443 240 24X Fiche 50-070, 83/05/03, 8305120057

Q. Adjudicatory correspondence

8305030532 Order extending time until 830603 for Commission to act to review ALAB-720
CHILK, S. J Office of the Secretary of the Commission 83/04/29
Commissioners 1p 18295 328 24X Fiche 50-070, 83/04/29,
8305030532

8305130035 Memorandum & order extending OE time to respond to ASLB 830408 inquiry into license renewal application until 15 days following svc of Commission decision whether to review ALAB-720
FRYE, J. H Atomic Safety and Licensing Board Panel 83/05/12
General Electric Co. 2pp 18436 315 24X Fiche 50-070, 83/05/12,
8305130035

P Operating license stage documents & correspondence

8305120057 Forwards Amend 13 to License TR-1, safety evaluation & notice of issuance & availability Amend deletes physical security requirements of 10CFR50. 34c & 10CFR73.
THOMAS, C O. Standardization & Special Projects Branch 83/05/03.
DARMITZEL, R. W. General Electric Co 2pp 18443 234. 24X
Fiche. 50-070, 83/05/03, 8305120057

--8305120067 Amend 13 to License TR-1, deleting physical security requirements of 10CFR50. 34c & 10CFR73
THOMAS, C. O. Standardization & Special Projects Branch. 83/05/03
2pp. 18443 236. 24X Fiche 50-070, 83/05/03, 8305120057

--8305120072 Safety evaluation supporting Amend 13 to License TR-1
* NRC - No Detailed Affiliation Given 83/05/03 2pp.
18443 238 24X Fiche. 50-070, 83/05/03, 8305120057

--8305120078 Notice of issuance & availability of Amend 13 to License TR-1
SCALETTI, D C Standardization & Special Projects Branch
83/05/03 2pp 18443 240 24X Fiche 50-070, 83/05/03, 8305120057

DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

P Operating license stage documents & correspondence

8305120089 Forwards Amend 15 to License R-33 & safety evaluation Amend reduces possession limits for unirradiated SNM to 4 kg U-235 as fuel for operation
THOMAS, C O Standardization & Special Projects Branch 83/05/03
DARMITZEL, R W General Electric Co 2pp 18443 186 24X
Fiche 50-073, 83/05/03, 8305120089

--8305120096 Amend 15 to License R-33, reducing possession limits for unirradiated SNM to 4 kg U-235 as fuel for operation
THOMAS, C O Standardization & Special Projects Branch 83/05/03
2pp 18443 188 24X Fiche 50-073, 83/05/03, 8305120089

--8305120100 Safety evaluation supporting Amend 15 to License R-33
* Standardization & Special Projects Branch 83/05/03 1p
18443 190 24X Fiche 50-073, 83/05/03, 8305120089

DOCKET 50-89 GENERAL ATOMIC CO

J Insurance & indemnity information

8305160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAELU Policy MF-59
ASHBURN, D J Marsh & McLennan, Inc 83/05/06 SALTZMAN, J
Assistant Director for State & Licensee Relations 3pp 18450 353
24X Fiche 50-089, 83/05/06, 8305160084

Q Inspection reports, IE Bulletins & correspondence

8305170429 Forwards IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08 & notice of violation
STERNBERG, D M Region 5, Office of Director 83/04/25 PARKER, J W
QA Technologies, Inc /General Atomic Co 2pp 18471 237 24X
Fiche 50-089, 83/04/25, 8305170429

--8305170432 Notice of violation from insp on 830404-08
KIRSCH, D F Region 5, Office of Director 83/04/25 1p
18471 239 24X Fiche 50-089, 83/04/25, 8305170429

--8305170437 IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08 Noncompliance noted failure to conspicuously post high radiation area during performance of reactor experiment
JOHNSON, P H , KIRSCH, D F Region 5, Office of Director 83/04/22
5pp 18471 240 24X Fiche 50-089, 83/04/25, 8305170429

DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

Q Inspection reports, IE Bulletins & correspondence

8305050223 Forwards IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/04/21
STREETT, W B Cornell Univ 2pp 18338 096 24X
Fiche 50-097, 83/04/21, 8305050223

--8305050230 Notice of violation from insp on 830321-23
* Region 1, Office of Director 83/04/21 1p 18338 098 24X
Fiche 50-097, 83/04/21, 8305050223

--8305050236 IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23 Noncompliance noted failure of ward lab safety committee to perform annual audits of operations since 1980 & failure of committee to meet quarterly in 1982
KINNEY, W W , ELSASSER, T C Region 1, Office of Director
83/04/18 6pp 18338 099. 24X Fiche 50-097, 83/04/21, 8305050223

DOCKET 50-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8305270465 Forwards IE Insp Rept 50-111/83-01 on 830405-06 No noncompliance noted
VERRELLI, D. M. Division of Project & Resident Programs 83/04/22
COCKRELL, R Q North Carolina State Univ 1p 18644 154 24X
Fiche 50-111, 83/04/22, 8305270465

--8305270469 IE Insp Rept 50-111/83-01 on 830405-06 No noncompliance noted Major areas inspected radiation protection associated w/termination of R-3 reactor license
KAHLE, J B Region 2, Office of Director BARR, K P Division of Project & Resident Programs 83/04/21 3pp 18644 155 24X
Fiche 50-111, 83/04/22, 8305270465

DOCKET 50-112 UNIV OF OKLAHOMA RESEARCH REACTOR

H General correspondence

8305250478 Informs of C Jensen appointment as director of facility
EGLE, D M Oklahoma, Univ of 83/05/16 MILLER, J Division of Licensing 1p 18589 032 24X Fiche 50-112, 83/05/16, 8305250478

P Operating license stage documents & correspondence

8305170114 Notification of 830517-19 meetings w/Univ of OK & LASL on site to review & evaluate reactor facility in connection w/ application for OL renewal
BERNARD, H Standardization & Special Projects Branch 83/05/12
THOMAS, C O Standardization & Special Projects Branch 2pp
18495 359 24X Fiche 50-112, 83/05/12, 8305170114

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

P Operating license stage documents & correspondence

8305310006 Advises that MK Straka hired as reactor manager, effective 830307
BOLON, A E Missouri, Univ of, Rolla 83/05/23 CARTER, R E
Standardization & Special Projects Branch 2pp 18653 238, 24X
Fiche 50-123, 83/05/23, 8305310006

R Periodic operating reports & related correspondence

8305030375 "Progress Rept, Univ of MO-Rolla Apr 1982 - Mar 1983 "
BOLON, A E , STRAKA, M Missouri, Univ of, Rolla 83/03/31 137pp
18292 179 24X Fiche 50-123, 83/03/31, 8305030375

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8305120524 Forwards Amend 9 to License R-83, safety evaluation, EIA & notice of issuance/negative declaration Amend renews OL for 20 yrs from date of issuance W/o SER
EISENHUT, D G Division of Licensing 83/03/30 ERDMAN, C A Texas A&M Univ , College Station, TX 3pp 18442 001 24X
Fiche 50-128, 83/03/30, 8305120524

--8305120532 Amend 9 to License R-83, renewing OL for 20 yrs from date of issuance
EISENHUT, D G Division of Licensing 83/03/30 69pp 18442 004
24X Fiche 50-128, 83/03/30, 8305120524

--8305120537 EIA supporting Amend 9 to License R-83
* NRC - No Detailed Affiliation Given 83/03/30 6pp
18442 071 24X Fiche 50-128, 83/03/30, 8305120524

--8305120544 Notice of issuance/negative declaration for Amend 9 to License R-83
EISENHUT, D G Division of Licensing 83/03/30 2pp 18442 077
24X Fiche 50-128, 83/03/30, 8305120524

8305050252 Forwards "Completion & Results of Phase I of NSCR Post-Damage Pulse Test Program for Full FLIP TRIGA Core "
FELTZ, D E Texas A&M Univ , College Station, TX 83/04/29
THOMAS, C O, Standardization & Special Projects Branch 1p.
18338 022 24X Fiche 50-128, 83/04/29, 8305050252.

--8305050257 "Completion & Results of Phase I of NSCR Post-Damage Pulse Test Program for Full FLIP TRIGA Core "
JENNINGS, F Texas A&M Univ , College Station, TX. 83/04/13
16pp 18338 023 24X Fiche 50-128, 83/04/29, 8305050252.

G. Inspection reports, IE Bulletins & correspondence

8305090066 Ack receipt of 830412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-128/82-03
MADSEN, G L Region 4, Office of Director 83/05/04 PORTER, W. A.
Texas A&M Univ , College Station, TX. 1p 18363 331, 24X
Fiche. 50-128, 83/05/04, 8305090066

--8305090073 Responds to NRC 830316 ltr re violations noted in IE Insp Rept 50-128/82-03 Corrective actions training sessions conducted for reactor operations personnel to demonstrate proper preparation of ice bath
PORTER, W A Texas A&M Univ , College Station, TX 83/04/12
MADSEN, G L Region 4, Office of Director 8pp 18363 332 24X
Fiche 50-128, 83/05/04, 8305090066

R Periodic operating reports & related correspondence

8305250528 Nineteenth Progress Rept of TX A&M Univ Nuclear Science Ctr 1982 W/830516 ltr
* Texas A&M Univ , College Station, TX 83/04/30 THOMAS, C
Standardization & Special Projects Branch 88pp 18587 347 24X
Fiche 50-128, 83/04/30, 8305250528

DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR

W Decommissioning Stage Documents & Correspondence

8305260308 Requests termination of License R-58 before OL Blackshaw departure on 830630 Facility dismantled per approved procedures following receipt of 800122 authorization.
COLLINS, W E West Virginia Univ 83/05/23 THOMAS, C O
Standardization & Special Projects Branch 28pp 18626·268 24X
Fiche 50-129, 83/05/23, 8305260308

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

P Operating license stage documents & correspondence

8305310012 Forwards response to 830511 questions re exhaust sys, reflector platform, reactor bridge, pneumatic transfer tube terminus assembly, scram circuit relays, radioactivity monitor & automatic regulating channel servo
TURCOTTE, R L Vet Admin. Hosp Omaha, NE 83/05/23 THOMAS, C O
Standardization & Special Projects Branch 9pp 18653 221 24X
Fiche 50-131, 83/05/23, 8305310012

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

F. Security, medical, emergency & fire protection plans

8305020108 Forwards revs to security plan Revs withheld (ref 10CFR73 21)
CRANE, P A Pacific Gas & Electric Co 83/04/25 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18278 241
24X Fiche. 50-133, 83/04/25, 8305020108

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. G Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

P Operating license stage documents & correspondence

8305230407 Informs that backfitting matl will be forwarded as soon as available, in response to 830208 ltr
FURBUSH, M H. Pacific Gas & Electric Co 83/02/23 TOURTELLOTTE, J.
Regulatory Reform Task Force 1p 18543.357 24X
Fiche 50-000, 83/02/23, 8305230407

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J. Commissioners. 2pp. 18542:272 24X
Fiche: 50-000, 83/04/11, 8305230720

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing. 83/05/02. Consolidated Edison Co of New York, Inc. 50pp. 18441·120 24X
Fiche. 50-000, 83/05/02, 8305020455.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D. G Division of Licensing. 83/05/09 Consolidated Edison Co. of New York, Inc 16pp. 18627 153 24X
Fiche· 50-000, 83/05/09, 8305090659.

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp. 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp. 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc. 119pp. 18441 001 24X Fiche. 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06. Consolidated Edison Co of New York, Inc. 115pp. 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp. 18524 003 24X Fiche: 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19. Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007. 24X Fiche: 50-000, 83/05/26, 8303040046.

S. Reportable occurrences, LERs & related correspondence

8305170336 Forwards revised LER 83-001/03L-1.
SHIFFER, J. D. Pacific Gas & Electric Co 83/05/06. MARTIN, J. B. Region 5, Office of Director 1p. 18465:123. 24X Fiche 50-133, 83/05/06, 8305170336

--8305170342 Revised LER 83-001/03L-1 on 830316, fire occurred in 480-volt circuit breaker supplying radwaste pump Caused by fault to ground exacerbated by over capacity of fuse Design change will be implemented to correct overrated fuses
GETTY, B C Pacific Gas & Electric Co 83/05/06 Region 5, Office of Director 2pp 18465 124 24X Fiche 50-133, 83/05/06, 8305170336

DOCKET 50-142 UCLA TRAINING REACTOR

G Adjudicatory correspondence

8305030524 Response to Committee to Bridge the Gap 830414 motion opposing scheduling earlier date for filing of written testimony UCLA wishes to reserve right to modify witness list if new date set for hearing Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles 83/04/29 Atomic Safety and Licensing Board Panel 4pp 18306 358 24X Fiche 50-142, 83/04/29, 8305030524

8305030568 Response to ASLB 830414 order detailing licensee legal position re Committee to Bridge the Gap motion for summary disposition of Contention XVII Summary disposition should not be granted Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles 83/04/29 11pp 18305 324 24X Fiche 50-142, 83/04/29, 8305030568

8305030574 Response to Committee to Bridge the Gap (CBG) 830414 motion to strike portions of UCLA response to CBG request for expedited ruling on Contention XIII Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles 83/04/29 Atomic Safety and Licensing Board Panel 8pp 18303 311 24X Fiche 50-142, 83/04/29, 8305030574

8305030494 Petition for reconsideration of ASLB 830422 order denying motions for summary disposition of Contention II (class of license) Argument completely devoid of merit Certificate of Svc encl
WOODHEAD, C P Hearing Branch 4 83/05/02 Atomic Safety and Licensing Board Panel 13pp 18306 332 24X Fiche 50-142, 83/05/02, 8305030494

8305030582 Memorandum & order denying Committee to Bridge the Gap 830414 motion to strike portions of NRC & UCLA responses & 830315 motion for expedited ruling on Gap 820907 motion for partial summary disposition of Contention XIII
FRYE, J H , BRIGHT, G O , LUEBKE, E A Atomic Safety and Licensing Board Panel 83/05/02 Committee to Bridge the Gap 4pp 18306 094 24X Fiche 50-142, 83/05/02, 8305030582

8305060520 Memorandum & order deferring consideration of NRC 830502 petition for reconsideration of ASLB 830422 memorandum & order denying motions for summary disposition of Contention II Ruling awaits receipt of alternate ASLB member rept
BRIGHT, G O , LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/04 3pp 18351 092 24X Fiche 50-142, 83/05/04, 8305060520

8305090473 Motion for reconsideration of ASLB 830422 memorandum & order to clarify scope of Contention II proceedings Certificate of Svc encl Accounting based on actual use of reactor demonstrates that costs attributed to noncommercial use
CORMIER, W H California, Univ of, Los Angeles 83/05/04 Atomic Safety and Licensing Board Panel 7pp 18362 272 24X Fiche 50-142, 83/05/04, 8305090473

8305100330 Memorandum & order referring UCLA 830504 motion for reconsideration of ASLB 830422 order to alternate ASLB member. Responses to motion should be filed w/alternate ASLB member on schedule to be established
BRIGHT, G O , LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel, 83/05/06 2pp 18378 360 24X Fiche 50-142, 83/05/06, 8305100330

8305100312 Forwards portion of Univ of FL SAR explaining spatial relationships & components of Argonaut in response to ASLB 830425 request
WOODHEAD, C. P. Office of the Executive Legal Director 83/05/09
FRYE, J H , BRIGHT, G O , LUEBKE, E A Atomic Safety and Licensing Board Panel 25pp 18370 100. 24X Fiche 50-142, 83/05/09, 8305100312

8305130076 Memorandum & order denying NRC 810413 motion for summary disposition of Contention XX re physical security NRC directed to physically inventory SNM at UCLA & to rept findings to ASLB & parties
BRIGHT, G O., LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/11 Office of the Executive Legal Director 27pp. 18437 053 24X Fiche. 50-142, 83/05/11, 8305130076

8305130079 Memorandum & order memorializing 830505 telcon Discussions held on NRC testimony filing dates, hearing dates & issues
BRIGHT, G O , LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/11 8pp 18437 080 24X Fiche 50-142, 83/05/11, 8305130079

8305130150 Memorandum & order that sabotage issue will not be considered under Contention XIX Issue will be considered under Contention XX
BRIGHT, G O , LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/11 4pp 18437 178 24X Fiche 50-142, 83/05/11, 8305130150

8305160164 Forwards prof qualifications of six NRC witnesses to appear at Summer & Fall 1983 hearings on safety issues
WOODHEAD, C P Hearing Branch 4 83/05/12 FRYE, J H , BRIGHT, G O , LUEBKE, E A Atomic Safety and Licensing Board Panel 8pp 18446 120 24X Fiche 50-142, 83/05/12, 8305160164

8305160163 Memorandum & order deferring ruling on UCLA, NRC & Committee to Bridge the Gap motions for summary disposition of Contention XVII, pending outcome of inherent safety hearings
BRIGHT, G O , LUEBKE, E A , FRYE, J H Atomic Safety and Licensing Board Panel 83/05/13 California, Univ of, Los Angeles 4pp 18444 030 24X Fiche: 50-142, 83/05/13, 8305160163

305170001 Response to alternate ASLB member 830422 order establishing 830524 hearing date Lists matl facts not in dispute, matl facts in dispute, NRC witnesses & testimony, exhibits & time necessary for NRC presentation Certificate of Svc encl
WOODHEAD, C P Hearing Branch 4 83/05/13 10pp 18466:215 24X Fiche 50-142, 83/05/13, 8305170001

8305170063 Forwards stipulation re preparation for hearing on Contention II
WOODHEAD, C P Hearing Branch 4 83/05/13 LAURENSON, J A Atomic Safety and Licensing Board Panel 1p 18466 253 24X Fiche 50-142, 83/05/13, 8305170063

--8305170067 Stipulation re preparation for hearing on Contention II Lists exhibits to be introduced, witnesses to be called & estimates of time necessary to present case
WOODHEAD, C P Hearing Branch 4 THOMPSON, D Committee to Bridge the Gap CORMIER, W California, Univ of, Los Angeles 83/05/12 7pp 18466 254 24X Fiche 50-142, 83/05/13, 8305170063

8305170325 Discusses 830506 telcon per ASLB 830422 order. Items discussed, including estimates for direct presentation of cases; contained in stipulation forwarded separately Summary of witness testimony in upcoming hearing encl
HIRSCH, D Committee to Bridge the Gap 83/05/13 LAURENSON, J A Atomic Safety and Licensing Board Panel 2pp 18465 225 24X Fiche 50-142, 83/05/13, 8305170325

8305240479 Response to Judge Laurenson 830422 order re Contention II Parties stipulated to witnesses & exhibits Summarizes witnesses testimony UCLA case will be presented in 4 h Certificate of Svc encl
CORMIER, W H California, Univ of, Los Angeles 83/05/13 6pp 18549 332 24X Fiche 50-142, 83/05/13, 8305240479

8305200496 Forwards subpoenas re class-of-license evidentiary hearing, for issuance Subpoenas relate to reactor operational & financial records detailing use & cost allocation for facility Related correspondence
HIRSCH, D Committee to Bridge the Gap 83/05/16 LAURENSON, J A Atomic Safety and Licensing Board Panel 1p 18514 031 24X Fiche 50-142, 83/05/16, 8305200496

8305200652 Forwards L Wayne statement of prof qualifications. Wayne will testify on combustion, chemical reactions, Wigner energy & release & dispersion of radionuclides
HIRSCH, D Committee to Bridge the Gap 83/05/16 WOODHEAD, C Hearing Branch 4. CORMIER, W California, Univ of, Los Angeles NALIBOFF, L Santa Monica, CA 2pp 18519 338 24X Fiche 50-142, 83/05/16, 8305200652

8305240499 Advises that univ has not received statements of prof qualifications of all proposed witnesses in license renewal proceeding. Statements will be forwarded upon receipt
CORMIER, W H California, Univ of, Los Angeles 83/05/18 FRYE, J H , BRIGHT, G O , LUEBKE, E. A Atomic Safety and Licensing Board Panel 1p. 18572:027 24X Fiche 50-142, 83/05/18, 8305240499

305230236 Notice of appearance in proceeding Certificate of Svc encl
YOUNG, M A Hearing Branch 4 83/05/19 3pp 18539 184 24X Fiche, 50-142, 83/05/19, 8305230236.

8305240521 Response supporting UCLA 830504 motion for reconsideration of ASLB 830422 order establishing special prehearing conference for Contention II Issue of commerical use of reactor must be decided. Certificate of Svc encl
WOODHEAD, C. P Hearing Branch 4 83/05/23 Atomic Safety and Licensing Board Panel 6pp 18571 110 24X Fiche 50-142, 83/05/23, 8305240521

H General correspondence

8305050041 Forwards May 1983 Playboy article, "Terrorist Guide to 1984 Olympics," for info
BAY, J H Affiliation Unknown 83/04/28 Atomic Safety and Licensing Board Panel 6pp 18342 086 24X Fiche 50-142, 83/04/28, 8305050041

O Inspection reports, IE Bulletins & correspondence

8305160029 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-142/83-01
BOOK, H E Region 5, Office of Director 83/05/11 WEGST, W F California, Univ of, Los Angeles 1p 18453 007. 24X Fiche 50-142, 83/05/11, 8305160029

--8305160037 Responds to NRC 830323 ltr re violations noted in IE Insp Rept 50-142/83-01 Corrective actions routine survey findings to be routed to radiation safety officer, background & calibr check data entered into log & survey results tabulated
WEGST, W F California, Univ of, Los Angeles. 83/04/29
BOOK, H E Region 5, Office of Director 5pp. 18453 008 24X Fiche 50-142, 83/05/11, 8305160029

T Hearing transcripts on non-antitrust matters

8305200613 Forwards JC Petersen testimony Petersen will testify at 830524 hearing on Contention II
WOODHEAD, C P Hearing Branch 4 83/05/19 LAURENSON, J A Atomic Safety and Licensing Board Panel. 1p 18520 135 24X Fiche 50-142, 83/05/19, 8305200613

--8305200624 Testimony of JC Petersen re Committee to Bridge the Gap Contention II Use of reactor from accounting & financial standpoint discussed Reactor primarily used for educational purposes MA Young notice of appearance encl
PETERSEN, J C Office of State Programs, Director 83/05/19 14pp 18520 136 24X Fiche 50-142, 83/05/19, 8305200613

8305310195 Transcript of 830524 hearing in Los Angeles, CA re proposed license renewal Pp 1-183.
* Atomic Safety and Licensing Board Panel 83/05/24 185pp 18651 023 24X Fiche 50-142, 83/05/24, 8305310195

DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY

H General correspondence

8305020563 Forwards documents & matls to establish LPDR, focusing on decommissioning & possible dismantling of facility W/o encls
BOUDER, J. L Division of Rules and Records 83/04/25 PENNELL, L Baxton, PA 2pp 18284 243 24X Fiche, 50-146, 83/04/25, 8305020563

8305040056 Responds to 830328 ltr expressing concern re possible dismantling of facility Baxton Nuclear Engineering Corp plans to request authorization to dismantle facility during latter 1980s
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/04/25 FULLER, E Affiliation Unknown 2pp. 18336, 323. 24X Fiche 50-146, 83/04/25, 8305040056

P. Operating license stage documents & correspondence

8305180097 Forwards std order for DOE work for "Consultant Svcs, P Naggy, for Hearing Support-Univ of CA Nonpower Reactor License Renewal Application " Cost of project funded by NRR operating reserve requested, W/o encl.
EIGENHUT, D. G. Division of Licensing FIN A-3727 83/04/07
DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p. 18499 362 24X Fiche: 50-146, 83/04/07, 8305180097

DOCKET 50-148 UNIV OF KANSAS RESEARCH REACTOR

Q Inspection reports, IE Bulletins & correspondence

8305200192 Ack receipt of 830414 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-148/83-01
MADSEN,G L Region 4, Office of Director 83/05/16 KRAFT,D C Kansas, Univ of 1p 18517 093 24X Fiche 50-148,83/05/16, 8305200192

--8305200196 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-148/83-01 Corrective actions R Mesler will be appointed member of committee on radiation sources by 830501
KRAFT,D C Kansas, Univ of 83/04/14 MADSEN,G L Region 4, Office of Director 1p 18517 094 24X Fiche 50-148,83/05/16, 8305200192

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F. Security, medical, emergency & fire protection plans

8305110067 Responds to 821105 ltr transmitting changes to suitability, training & qualification plan Changes acceptable except for items identified in encl Change re Item 4 requested per 10CFR50.90 Encl withheld (ref 10CFR73 21)
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/06
VANDEWALLE,D J. Consumers Power Co 1p 18408 111 24X Fiche,50-155,83/05/06,8305110067

8305170404 Forwards description of scope & objectives for emergency exercise scheduled for 830725-26,per NRC 820112 request
VANDEWALLE,D.J Consumers Power Co 83/05/09 KEPPLER,J G Region 3, Office of Director 4pp 18467 358 24X Fiche 50-155,83/05/09, 8305170404

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X Fiche·50-000,83/05/11,8305110034

8305170369 Comments on NUREG-0737,Item III A 2.1, "Emergency Preparedness,Upgrade Emergency Plans to App E, 10CFR50 " Onsite & offsite emergency preparedness adequate Item complete
CRUTCHFIELD,D. Operating Reactors Branch 5 83/05/16
VANDEWALLE,D.J. Consumers Power Co 5pp 18466·077 24X Fiche,50-155,83/05/16,8305170369

8305240376 Ack receipt of 830509 ltr describing scope & objectives of emergency exercise scheduled for 830725-26.Agrees to verbal request for postponement of accountability/assembly drill as part of exercise until plant resumes full operation
PAPERIELLO,C J. Region 3, Office of Director 83/05/19
DEWITT,R.B. Consumers Power Co 1p 18574.282. 24X Fiche·50-155,83/05/19,8305240376.

8305260259 Ack receipt of 830131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-13 Noncompliance 1 withdrawn Updated Tech Specs re fire barriers will be requested.
SPESSARD,R.L. Division of Engineering 83/05/20. DEWITT,R B Consumers Power Co 2pp 18626 083 24X Fiche 50-155,83/05/20, 8305260259

--8305260266 Responds to NRC 821203 ltr re violations noted in IE Insp Rept 50-155/82-13.Corrective actions plant drawings reviewed to verify that all ventilation duct dampers included in new test procedure & emergency lighting test process developed.
VANDEWALLE,D.J. Consumers Power Co 83/01/31. KEPPLER,J.G. Region 3, Office of Director 23pp 18626·085 24X Fiche:50-155,83/05/20,8305260259.

Q Adjudicatory correspondence

8305100404 Comments on licensee proposals to remedy deficiencies identified in ASLB 820914 initial decision re emergency planning.Licensee has provided reasonable assurance of adequate protective measures in event of emergency.
GODDARD,R.J. Hearing Branch 3 83/04/07 1p 18378;029. 24X Fiche·50-155,83/04/07,8305100404.

--8305100409 Comments on FEMA assessments of util responses to ASLB contentions re emergency preparedness program protective measures for offsite population
HIND,J.A. Division of Radiological & Materials Safety Programs. 83/03/31. EISENHUT,D.G. Division of Licensing 2pp 18378 030. 24X Fiche:50-155,83/04/07,8305100404.

--8305100414 Requests assistance in initiating action to assure that deficiencies identified in ASLB 820914 second initial decision corrected Certificate of Svc encl
GRIMES,B K Division of Emergency Preparedness (Pre 830103) 82/11/30 KRIMM,R W Federal Emergency Management Agency 14pp 18378 032 24X Fiche 50-155,83/04/07,8305100404

8305160250 Informs that 830207 ltr re proposed expansion of spent fuel storage capacity forwarded to ASLB for consideration as limited appearance statement No request pending for operating permit Full-term OL granted on 640501
CRUTCHFIELD,D Operating Reactors Branch 5 83/04/28 ANDERSON,J Affiliation Unknown 1p 18472 004 24X Fiche 50-155,83/04/28, 8305160250

8305040534 Responds to 830411 & 13 10CFR2 206 petition requesting no addl fuel be allowed in spent fuel pool until issue of structural adequacy resolved NRC is addressing substantive issues raised by petition No addl action will be taken
DENTON,H R Office of Nuclear Reactor Regulation, Director. 83/05/03 CHRISTA-MARIA Christa-Maria 5pp 18321 109 24X Fiche 50-155,83/05/03,8305040534

--8305040536 Director's Decision DD-83-07 re J Bier & Christa-Maria 10CFR2 206 petition requesting no addl fuel be allowed in spent fuel pool NRC is taking action requested by petitioners so no further action needed at present time
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/05/03 5pp 18321 114 24X Fiche 50-155,83/05/03,8305040534

--8305040537 Forwards SER re spent fuel pool thermal hydraulic analysis supporting request for continued operation Temp of spent fuel pool concrete structure can be maintained below 150 F if normal fuel pool cooling sys lost
CRUTCHFIELD,D Operating Reactors Branch 5 82/07/02.
VANDEWALLE,D Consumers Power Co 2pp 18321 119 24X Fiche 50-155,83/05/03,8305040534

--8305040539 Safety evaluation re spent fuel pool thermal hydraulic analysis supporting request for continued operation
* NRC - No Detailed Affiliation Given 82/07/02 5pp 18321 121 24X Fiche 50-155,83/05/03,8305040534

--8305040540 Notice of issuance of Director's Decision DD-83-07 re J Bier & Christa-Maria 10CFR2 206 petition requesting no addl fuel be allowed in spent fuel pool until issue of pool thermal/structural adequacy resolved
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/03 2pp 18321 145 24X Fiche 50-155,83/05/03,8305040534

--8305040542 Telecopy 10CFR2 206 petition requesting no addl fuel be allowed in spent fuel pool until issue of pool thermal/ structural adequacy resolved
BIER,J Affiliation Unknown CHRISTA-MARIA Christa-Maria 83/04/11 Commissioners 2pp 18321 147 24X Fiche 50-155,83/05/03,8305040534

--8305040543 Telecopy errata to 830503 telecopy 10CFR2 206 petition re addition to spent fuel pool
BIER,J Affiliation Unknown 83/04/12 Commissioners 1p 18321 150 24X Fiche 50-155,83/05/03,8305040534

--8305040545 Advises that concerns raised by Concerned Citizens of Charlevoix 830411 10CFR2 206 petition are issues before ASLB or are being addressed by NRC Petition can be answered briefly & quickly.
LIEBERMAN,J Regional Operations & Enforcement Division 83/04/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18321 151. 24X Fiche 50-155,83/05/03,8305040534

8305040625 Responds to 830411 & 12 10CFR2 206 petitions requesting no addl fuel be allowed in spent fuel pool until issue of structural adequacy resolved NRC is addressing substantive issues raised by petition No addl action will be taken
DENTON,H R. Office of Nuclear Reactor Regulation, Director 83/05/03 BIER,J Affiliation Unknown 5pp 18320:116 24X Fiche·50-155,83/05/03,8305040625

8305060495 Rept results of 830428 conference w/NRC & Christa-Maria in Washington,DC.No basis exists for resolving matters raised by intervenors which would lead to dismissal of emergency planning subcontentions.
GALLO,J Isham, Lincoln & Beale GALLO,J Consumers Power Co 83/05/03 BLOCH,P , PARIS,D H , SHON,F J Atomic Safety and Licensing Board Panel 2pp 18351 154 24X Fiche:50-155,83/05/03, 8305060495

8305100290 Reserves right to contest appropriateness of licensee motion for summary disposition re emergency planning contentions on spent fuel pool mod Disputed issues of fact can be resolved only by hearing Certificate of Svc encl.
SEMMEL,H Antioch School of Law, Washington, DC SEMMEL,H Christa-Maria 83/05/04 BLOCH,P , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 3pp 18371 265 24X Fiche 50-155,83/05/04,8305100290

8305110141 Forwards Charlevoix County 830427 resolution & 830427 ltr to Charlevoix County Board of Commissioners re application for financial assistance to support emergency preparedness plan & funds for training emergency personnel
COPELAND,V.G Isham, Lincoln & Beale 83/05/05 BLOCH,P , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 4pp 18393 038. 24X Fiche 50-155,83/05/05,8305110141

8305120287 Concurs w/H Semmel understanding of Judge Bloch 830503 telcons re emergency planning/spent fuel pool mod ASLB awaiting testimony before taking action
O'NEILL,J O'Neill, J 83/05/09 BLOCH,P.B , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 1p 18431 023 24X Fiche 50-155,83/05/09,8305120287

8305130185 Requests ASLB synthesize existing record & rule on whether any disputed issue of fact exists warranting convening hearing Further deterioration of situation should be avoided
GALLO,J Isham, Lincoln & Beale GALLO,J. Consumers Power Co 83/05/09 BLOCH,P.B , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 2pp 18440 047 24X Fiche 50-155,83/05/09, 8305130185

8305190245 Advises that appeal of ASLAB 830427 Decision ALAB-725,will be filed at appropriate time Extension to 830602 for filing objections requested
O'NEILL,J H O'Neill, J 83/05/16. PALLADINO,N J , ROBERTS,T , AHEARNE,J Commissioners. 1p 18501:303 24X Fiche 50-155,83/05/16,8305190245

8305190366 Motion that all ASLB partial initial decisions be set aside as June 1982 hearings proceeded on basis of util misrepresentation.Monetary & punitive relief also reported
SEMMEL,H Christa-Maria SEMMEL,H Antioch School of Law, Washington, DC 83/05/16 Atomic Safety and Licensing Board Panel 3pp 18500.073 24X Fiche 50-155,83/05/16,8305190366

--8305190371 Advises of util continuing misrepresentation affecting safety & integrity of Commission processes Discrepancies exist in util statements re necessity of unloading entire core to complete 10-yr inservice insp program
SEMMEL,H Antioch School of Law, Washington, DC SEMMEL,H Christa-Maria 83/05/06 PALLADINO,N J , AHEARNE,J , GILINSKY,V Commissioners 2pp. 18500 076 24X Fiche 50-155,83/05/16, 8305190366

--8305190375 Affidavit from H Semmel 830505 telcon w/NRC project manager R Emch Util intends to conduct 10-yr insp w/o removing all fuel from reactor core Fuel that cannot fit in pool will be moved Certificate of Svc encl
SEMMEL,H Christa-Maria 83/05/17. 3pp. 18500 084 24X Fiche.50-155,83/05/16,8305190366

8305200610 Forwards miscellaneous documents w/varying degrees of pertinence to proceeding Documents relate to spent fuel pool thermal/structural analyses
GALLO,J Isham, Lincoln & Beale GALLO,J Consumers Power Co 83/05/18 BLOCH,P B , PARIS,O H , SHON,F.J Atomic Safety and Licensing Board Panel. 17pp 18520 045 24X Fiche;50-155,83/05/18, 8305200610.

8305260180 Advises that funding assistance imperative if emergency planning guidelines to be met Funds needed to complete emergency response personnel training & equip emergency operations ctr W/Certificate of Svc Related correspondence
BREAKEY,T , MUMA,F.E Charlevoix, MI. 83/05/18 Atomic Safety and Licensing Board Panel 8pp 18599 262. 24X Fiche.50-155,83/05/18,8305260180.

8305200548 Order extending time until 830706 for Commission to act to review ALAB-725 Time for filing petitions for Commission review of ALAB-725 extended until 830602
CHILK,S J. Office of the Secretary of the Commission. 83/05/19 Commissioners 1p. 18516:001 24X Fiche 50-155,83/05/19, 8305200548.

8305200639 Confirms 830519 telcon in response to J Gallo 830509 ltr to SJ Chilk Response to H Semmel 830506 communication should be directed to ASLB
STUCKY,S W Docketing & Services Branch. 83/05/19. GALLO,J. Isham, Lincoln & Beale. 1p. 18520·152 24X Fiche;50-155,83/05/19, 8305200639.

8305240528 Motion to reconsider ASLAB 830427 Decision ALAB-725 & for leave to file out-of-time ASLAB should instruct ASLB that ASLB may require analysis of criticality if ASLB enumerates facts that trigger exercise of discretionary judgement.
O'NEILL,J O'Neill, J 83/05/19 Atomic Safety and Licensing Appeal Panel 2pp 18571 189 24X Fiche 50-155,83/05/19, 8305240528

8305240439 Motion for extension until 830613 to reply to intervenors Christa-Maria motion re misrepresentation by licensee Certificate of Svc encl
GALLO,J Consumers Power Co GALLO,J Isham, Lincoln & Beale. 83/05/20 Atomic Safety and Licensing Board Panel 5pp 18571 063 24X Fiche 50-155,83/05/20,8305240439

8305240520 Order granting J O'Neill 830517 motion to consider motion for reconsideration out-of-time Motion for reconsideration of ASLAB 830427 Decision ALAB-725 denied
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 83/05/20 2pp 18571·179 24X Fiche 50-155,83/05/20,8305240520

8305240513 Responds to J Gallo & J O'Neill 830509 ltrs ASLB decision re emergency planning contention should await NRC region & FEMA comments on intervenor 830314 filing concerning util response to ASLB 830914 order
BACHMANN,R Q. Hearing Branch 1 83/05/23 BLOCH,P B , SHON,F J , PARIS,O H Atomic Safety and Licensing Board Panel 2pp. 18571 116 24X Fiche 50-155,83/05/23,8305240513

8305270020 Motion for extension until 830606 to file NRC response to J O'Neill 830519 petition for Commission review of ALAB-725 Motion sent by telex but not received by NRC until 830325 Certificate of Svc encl
BACHMANN,R Q Hearing Branch 1 83/05/23 Commissioners. 3pp 18638.314 24X Fiche:50-155,83/05/23,8305270020

8305310021 Order extending time until 830630 for Commission to act to review Director's Decision DD-83-7
CHILK,S J Office of the Secretary of the Commission 83/05/26 Commissioners 1p 18653 126 24X Fiche 50-155,83/05/26, 8305310021

J. Insurance & indemnity information

8305240280 Forwards Endorsement 96 to NELIA Policy NF-117
FROUNFELKER,R Consumers Power Co 83/05/20 SALTZMAN,J NRC - No Detailed Affiliation Given 2pp 18548.202 24X Fiche 50-155,83/05/20,8305240280

P Operating license stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X Fiche.50-000,83/04/11,8305230720

8305020202 Forwards analysis of SEP Topic XV-8, "Control Rod Misoperation," per integrated assessment 821115-19 meetings. Acceptable fuel damage limit for single control rod withdrawal accident not exceeded Topic resolved
TONER,K.A Consumers Power Co. 83/04/25 CRUTCHFIELD,D Operating Reactors Branch 5. 7pp 18278 135 24X Fiche 50-155,83/04/25, 8305020202

8305020294 Forwards response to NRC 830315 questions on sensitivity studies performed on RETRAN analysis Approval requested prior to scheduled startup following next refueling outage
BORDINE,T C Consumers Power Co 83/04/26 CRUTCHFIELD,D Operating Reactors Branch 5 6pp 18277 244 24X Fiche.50-155,83/04/26,8305020294

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D Q Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp. 18441·120 24X Fiche 50-000,83/05/02,8305020455

8305040166 Advises that action required by Amend 56 to License DPR-6 to initiate negotiations w/DOE re disposal of high level waste or spent nuclear fuel considered complete,based on pursuit of contract w/DOE
CRUTCHFIELD,D. Operating Reactors Branch 5. 83/05/03. VANDEWALLE,D J Consumers Power Co 3pp 18324 031. 24X Fiche 50-155,83/05/03,8305040166

8305040196 Notification of 830509 meeting w/util & NUS in Germantown,MD to discuss thermal analysis of spent fuel pool
EMCH,R.L. Operating Reactors Branch 5 83/05/03 CRUTCHFIELD,D. Operating Reactors Branch 5. 4pp 18323·358 24X Fiche 50-155,83/05/03,8305040196.

8305170410 Responds to 830203 ltr re performance of containment integrated leak rate tests Util does not concur w/ interpretation of App J requirements that corrected results for 1982 Type A test exceeded max allowable leakage limits
VANDEWALLE, D J Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 2pp 18469 246 24X Fiche 50-155, 83/05/06, 8305170410

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305240505 Forwards Rev 1 to CPC-2A "QA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112 Submittal serves as annual rept
VANDEWALLE, D J Consumers Power Co 83/05/11 KEPPLER, J G Region 3, Office of Director 2pp 18575 116 24X Fiche 50-000, 83/05/11, 8305240505

--8305240565 Rev 1 to "QA Program Description for Operational Nuclear Power Plants "
REYNOLDS, J W , DEWITT, R B , COOK, J W Consumers Power Co CPC-2A R01 83/01/10 90pp 18575 118 24X Fiche 50-000, 83/05/11, 8305240505

8305160031 Summary of 830429 meeting w/util & NUS Corp in Germantown, MD re thermal/structural analysis of spent fuel pool List of requested addl info on unresolved issues encl
EMCH, R L. Operating Reactors Branch 5 83/05/13 Operating Reactors Branch 5. 6pp 18453 143 24X Fiche 50-155, 83/05/13, 8305160031.

8305190196 Forwards "SEP Investigation Into Possible Existence of Solution Cavities Beneath Big Rock Point Nuclear Power Plant Near Charlevoix, MI," in response to NRC 821012 SER re SEP Topics II-4 & II-4 B
TONER, K A Consumers Power Co 83/05/13 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18502 267 24X Fiche 50-155, 83/05/13, 8305190196.

--8305190201 "SEP Investigation Into Possible Existence of Solution Cavities Beneath Big Rock Point Nuclear Power Plant Near Charlevoix, MI."
BREWSTER, A., MEISENHEIMER, J Gilbert/Commonwealth Cos 83/02/09 9pp. 18502 269 24X Fiche 50-155, 83/05/13, 8305190196.

8305180292 Forwards safety evaluation approving use of spent fuel pool to licensed capacity of 193 spent fuel assemblies provided reactor not operating or in cold shutdown
CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/16
VANDEWALLE, D Consumers Power Co 4pp 18490 333 24X Fiche: 50-155, 83/05/16, 8305180292

--8305180297 Safety evaluation approving use of spent fuel pool to licensed capacity of 193 spent fuel assemblies provided reactor not operating or in cold shutdown
* Office of Nuclear Reactor Regulation, Director 83/05/16 7pp 18490 337 24X Fiche. 50-155, 83/05/16, 8305180292

8305200610 Forwards miscellaneous documents w/varying degrees of pertinence to proceeding Documents relate to spent fuel pool thermal/structural analyses
GALLO, J Isham, Lincoln & Beale, GALLO, J Consumers Power Co 83/05/18 BLOCH, P. B., PARIS, O H , SHON, F. J Atomic Safety and Licensing Board Panel. 17pp 18520 045 24X Fiche 50-155, 83/05/18, 8305200610.

8305310145 Notification of 830602 meeting w/util & Nuclear Utils Svc in Bethesda, MD to discuss thermal analysis of spent fuel pool.
EMCH, R.L. Operating Reactors Branch 5. 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 3pp. 18659 041 24X Fiche: 50-155, 83/05/26, 8305310145

Q. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc 112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15. Consolidated Edison Co of New York, Inc. 126pp. 18435.155. 24X Fiche: 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170166 Forwards IE Insp Rept 50-155/83-04 on 830101-0304 & 14 & notice of violation
SHAFER, W D Region 3, Office of Director 83/04/27 DEWITT, R B Consumers Power Co 2pp 18469 163 24X Fiche 50-155, 83/04/27, 8305170166

--8305170168 Notice of violation from insp on 830101-0304 & 14
SHAFER, W D Region 3, Office of Director 83/04/27 3pp 18469 165 24X Fiche 50-155, 83/04/27, 8305170166

--8305170174 IE Insp Rept 50-155/83-04 on 830101-0304 & 14 Noncompliance noted ends of pipe & tubing not taped in storage, tape & shipping stickers not chloride-free used on stainless steel & storage areas not maintained clean & dry
WRIGHT, G C , PARKER, M E , BOYD, D C Region 3, Office of Director 83/04/27 9pp 18469 168 24X Fiche 50-155, 83/04/27, 8305170166

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305130215 Forwards Magnaflux Test & Insp Procedures 22 A 36, 22 A 35, 22 A 21 & 27 A 1 used in 830311 demonstration of ultrasonic test performance capability in detection of intergranular stress corrosion cracking, per IE Bulletin 83-02
BORDINE, T C Consumers Power Co 83/05/04 KEPPLER, J G Region 3, Office of Director 8pp 18439.251 24X Fiche 50-155, 83/05/04, 8305130215

--8305130221 Rev 0 to Test & Insp Procedure 22 A 36, "Remote Recording Devices During Ultrasonic Exam "
* Magnaflux, Corp 83/02/25 7pp 18439 259 24X Fiche 50-155, 83/05/04, 8305130215

--8305130233 Rev 2 to Test & Insp Procedure 22 A 35, "Ultrasonic Exam of Austenitic Piping & Branch Connected Welds for Intergranular Stress Corrosion Cracking "
* Magnaflux, Corp 83/03/05 26pp 18439 266 24X Fiche 50-155, 83/05/04, 8305130215

--8305130237 Rev 0 to Test & Insp Procedure 22 A 21, "Ultrasonic Exam General Requirements."
* Magnaflux, Corp. 82/12/30. 14pp 18439 292 24X Fiche 50-155, 83/05/04, 8305130215

--8305130241 Rev 0 to Test & Insp Procedure 27 A 1, "Making & Incrementing of Welds for NDE "
* Magnaflux, Corp 83/02/25 12pp 18439 306 24X Fiche. 50-155, 83/05/04, 8305130215

8305090484 Summary of 830419 meeting w/util in Bethesda,MD re integrated assessment & ranking scheme utilized by util Next meeting will be held onsite on 830509-11 EMCH,R L Operating Reactors Branch 5 83/05/05 Operating Reactors Branch 5 3pp 18360 220 24X Fiche 50-155,83/05/05, 8305090484

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305190317 Responds to Action Item 2 of IE Bulletin 83-02, "Stress Corrosion Cracking in Large-Diameter Stainless Steel Recirculation Sys Piping at BWR Plants " Eleven welds incorporated in inservice insp BORDINE,T C Consumers Power Co 83/05/12 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18501 057 24X Fiche 50-155,83/05/12,8305190317

8305230044 Forwards addl request for relief from performing ultrasonic exam of instrument line nozzle inner radius sections as part of ASME Code inservice insp requirements Notification needed by 830601 if request denied BORDINE,T C. Consumers Power Co. 83/05/16 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 18539,194 24X Fiche 50-155,83/05/16,8305230044

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260259 Ack receipt of 830131 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-155/82-13 Noncompliance 1 withdrawn Updated Tech Specs re fire barriers will be requested SPESSARD,R L Division of Engineering 83/05/20 DEWITT,R B Consumers Power Co 2pp 18626 083 24X Fiche 50-155,83/05/20, 8305260259

--8305260266 Responds to NRC 821203 ltr re violations noted in IE Insp Rept 50-155/82-13 Corrective actions plant drawings reviewed to verify that all ventilation duct dampers included in new test procedure & emergency lighting test process developed VANDEWALLE,D J Consumers Power Co 83/01/31, KEPPLER,J G Region 3, Office of Director. 23pp 18626 085 24X Fiche 50-155,83/05/20,8305260259

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305230270 "Active Mod Projects,Operating PWR,1982 " * Consumers Power Co 82/12/31 4pp. 18576 332 24X Fiche:50-000,82/12/31,8305230270

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping " BROWN,E J Reactor Operations Analysis Branch 83/04/19 SEYFRIT,R V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche. 50-000,83/04/19,8305230573.

DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8305100363 Forwards IE Safeguards Insp Rept 50-156/83-01 on 830404-06 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21 & 2 790) MILLER,J R Region 3, Office of Director 83/05/04 CASHWELL,R J Wisconsin Univ of Madison 2pp 18379 039 24X Fiche 50-156,83/05/04,8305100363

--8305100371 IE Safeguards Insp Rept 50-156/83-01 on 830404-06 Noncompliance noted provisions of 10CFR73.21 not implemented as required Details withheld (ref 10CFR73 21 & 2 790) STAPLETON,B W , CREED,J R Region 3, Office of Director 83/05/04 1p 18379 041 24X Fiche 50-156,83/05/04,8305100363

8305100323 Forwards IE Safeguards Insp Rept 50-156/83-02 on 830419 & 20 No noncompliance noted MILLER,J R Region 3, Office of Director 83/05/06 CASHWELL,R J. Wisconsin Univ of Madison 2pp 18378 322 24X Fiche:50-156,83/05/06,8305100323

--8305100365 IE Safeguards Insp Rept 50-156/83-02 on 830419 & 20 No noncompliance noted.Major areas inspected nuclear matl control & accountability,measurement & controls & shipping & receiving Details withheld (ref 10CFR2 790) KNICELEY,J R , CREED,J R Region 3, Office of Director 83/05/05 1p 18378 324 24X Fiche 50-156,83/05/06,8305100323

G Inspection reports, IE Bulletins & correspondence

8305100363 Forwards IE Safeguards Insp Rept 50-156/83-01 on 830404-06 & notice of violation Notice of violation & rept details withheld (ref 10CFR73.21 & 2.790) MILLER,J R Region 3, Office of Director 83/05/04 CASHWELL,R. J. Wisconsin, Univ of, Madison 2pp 18379 039 24X Fiche. 50-156,83/05/04,8305100363

--8305100371 IE Safeguards Insp Rept 50-156/83-01 on 830404-06 Noncompliance noted provisions of 10CFR73 21 not implemented as required Details withheld (ref 10CFR73 21 & 2 790) STAPLETON,B W , CREED,J R Region 3, Office of Director 83/05/04 1p 18379 041 24X Fiche 50-156,83/05/04,8305100363.

8305100323 Forwards IE Safeguards Insp Rept 50-156/83-02 on 830419 & 20.No noncompliance noted MILLER,J R Region 3, Office of Director 83/05/06 CASHWELL,R. J. Wisconsin, Univ of, Madison 2pp 18378 322. 24X Fiche. 50-156,83/05/06,8305100323.

--8305100365 IE Safeguards Insp Rept 50-156/83-02 on 830419 & 20.No noncompliance noted.Major areas inspected,nuclear matl control & accountability,measurement & controls & shipping & receiving Details withheld (ref 10CFR2 790) KNICELEY,J R , CREED,J R Region 3, Office of Director. 83/05/05 1p 18378.324 24X Fiche 50-156,83/05/06,8305100323

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

8305050223 Forwards IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23 & notice of violation STAROSTECKI,R. Division of Project & Resident Programs 83/04/21. STREETT,W.B. Cornell Univ 2pp 18338 096 24X Fiche. 50-097,83/04/21,8305050223

--8305050230 Notice of violation from insp on 830321-23 * Region 1, Office of Director 83/04/21 1p 18338 098 24X Fiche 50-097,83/04/21,8305050223

--8305050236 IE Insp Repts 50-097/83-01 & 50-157/83-01 on 830321-23. Noncompliance noted:failure of ward lab safety committee to perform annual audits of operations since 1980 & failure of committee to meet quarterly in 1982 KINNEY,W.W., ELSASSER,T C Region 1, Office of Director. 83/04/18 6pp 18338 099 24X Fiche 50-097,83/04/21,8305050223.

DOCKET 50-163 GENERAL ATOMIC CO

J. Insurance & indemnity information

8305160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAELU Policy MF-59
ASHBURN, D J Marsh & McLennan, Inc 83/05/06 BALTZMAN, J
Assistant Director for State & Licensee Relations 3pp 18450 353
24X Fiche 50-089, 83/05/06, 8305160084

G Inspection reports, IE Bulletins & correspondence

8305170429 Forwards IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08 & notice of violation
STERNBERG, D M Region 5, Office of Director 83/04/25 PARKER, J W
QA Technologies, Inc /General Atomic Co 2pp 18471 237 24X
Fiche 50-089, 83/04/25, 8305170429

--8305170432 Notice of violation from insp on 830404-08
KIRSCH, D F Region 5, Office of Director 83/04/25 1p
18471 239 24X Fiche 50-089, 83/04/25, 8305170429

--8305170437 IE Insp Repts 50-089/83-01 & 50-163/83-01 on 830404-08
Noncompliance noted failure to conspicuously post high radiation area during performance of reactor experiment
JOHNSON, P. H , KIRSCH, D F Region 5, Office of Director 83/04/22
5pp 18471 240 24X Fiche 50-089, 83/04/25, 8305170429

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

V. Congressional/Executive Correspondence

8305180437 Responds to 830511 ltr re licensing renewal proceeding Commission cannot respond to substantive matters due to pendency of licensing adjudication before ASLB
FITZGERALD, J A Office of the General Counsel 83/05/17
BOERGERS, M. Maryland, State of 1p 18486 060 24X
Fiche 50-170, 83/05/17, 8305180437

--8305180439 Expresses concern on behalf of Citizens for Nuclear Reactor Safety re licensing renewal proceeding
BOERGERS, M Maryland, State of 83/05/11 PALLADINO, N J
Commissioners 1p 18486.061 24X Fiche 50-170, 83/05/17,
8305180437

DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G Inspection reports, IE Bulletins & correspondence

8305270204 Forwards IE Insp Rept 50-184/83-02 on 830406-08, No noncompliance noted.
STAROSTECKI, R Division of Project & Resident Programs 83/05/13
CARTER, R. S. Commerce, Dept. of, National Bureau of Standards 2pp
18637·304. 24X Fiche, 50-184, 83/05/13, 8305270204

--8305270208 IE Insp Rept 50-184/83-02 on 830406-08 No noncompliance noted Major areas inspected, licensee action on previous insp findings, organization, logs & records, reviews & audits & operator requalification training
KINNEY, W W , ELBASSER, T C Region 1, Office of Director
83/05/12. 8pp. 18637:306 24X Fiche·50-184, 83/05/13, 8305270204

8305250454 Corrects rept number for IE insp on 830406-08 Number should be 50-184/83-03, not 83-02.
STAROSTECKI, R Division of Project & Resident Programs. 83/05/19.
CARTER, R. S Commerce, Dept of, National Bureau of Standards. 2pp
18585.212. 24X Fiche 50-184, 83/05/19, 8305250454

--8305250456 IE Insp Rept 50-184/83-03 on 830406-08, reflecting corrected rept number W/o details.
KINNEY, W. W. , ELBASSER, T C. Region 1, Office of Director
83/05/12. 1p 18585 213. 24X Fiche·50-184, 83/05/19, 8305250454.

DOCKET 50-192 UNIV. OF TEXAS RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

8305100006 Forwards IE Insp Rept 50-192/83-03 on 830310-11, No noncompliance noted
SEIDLE, W. C. Region 4, Office of Director 83/04/11 BAUER, T L
Texas, Univ. of 2pp 18377:206 24X Fiche·50-192, 83/04/11,
8305100006.

--8305100009 IE Insp Rept 50-192/83-03 on 830310-11 No noncompliance noted Major areas inspected reactor facility program organization, audit & review, procedures, surveillance, experiments, environ protection & emergency planning
TAPIA, J I , HUNNICUTT, D M , SEIDLE, W C Region 4, Office of
Director 83/05/08 5pp 18377 208 24X Fiche 50-192, 83/04/11,
8305100006

P Operating license stage documents & correspondence

8305100005 Forwards responses to license renewal questions in NRC 830415 ltr Responses to Questions 4, 5, 6 & 16 provided in encl updated SAR pages
BAUER, T L , KLEIN, D Texas, Univ of 83/05/02 THOMAS, C O
Division of Licensing 22pp 18377 184 24X Fiche 50-192, 83/05/02,
8305100005

G Inspection reports, IE Bulletins & correspondence

8305100006 Forwards IE Insp Rept 50-192/83-03 on 830310-11 No noncompliance noted
SEIDLE, W C Region 4, Office of Director 83/04/11 BAUER, T L
Texas, Univ of 2pp 18377 206 24X Fiche 50-192, 83/04/11,
8305100006

--8305100009 IE Insp Rept 50-192/83-03 on 830310-11 No noncompliance noted Major areas inspected reactor facility program organization, audit & review, procedures, surveillance, experiments, environ protection & emergency planning
TAPIA, J I , HUNNICUTT, D M , SEIDLE, W C Region 4, Office of
Director 83/05/08 5pp 18377 208 24X Fiche 50-192, 83/04/11,
8305100006

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

B Reportable occurrences, LERs & related correspondence

8305240384 RO on 830516, seepage of approx 160 cm3/h in reactor pool water discovered from area below thermal column case Leak will be isolated to determine cause Tech Specs do not specify pool leak rate
DIMEGLIO, A F Rhode Island & Providence Plantation 83/05/17
BERNARD, H Standardization & Special Projects Branch. 1p
18571.041 24X Fiche 50-193, 83/05/17, 8305240384

8305250445 RO on 830516, seepage of reactor pool water discovered below thermal column case Investigation revealed seepage from horizontal const joint in concrete biological shield Procedures initiated to isolate leak
DIMEGLIO, A F Rhode Island & Providence Plantation 83/05/17
KINNEY, W Region 1, Office of Director 1p 18585 283 24X
Fiche 50-193, 83/05/17, 8305250445

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

P Operating license stage documents & correspondence

8305030688 Clarifies definitions of plant & project low level radwastes to be used in developing West Valley Demonstration Project mgt plan & subsequent environ assessment documentation
HANNUM, W H Energy, Dept of, 83/04/01 CLARK, A T Advanced Fuel
& Spent Fuel Licensing Branch 2pp 18309 138 24X
Fiche, 50-201, 83/04/01, 8305030688

8305230015 Forwards Rev 1 to "Functional & Operational Requirements for Component Test Stand," for comments by 830515
HUNNUM, W H. Energy, Dept of, Idaho Operations Ofc 83/04/18.
CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch 1p
18542 232. 24X Fiche 50-201, 83/04/18, 8305230015

--8305230020 Rev 1 to "Functional & Operational Requirements for Component Test Stand "
* West Valley Nuclear Services Co , Inc 83/03/23 22pp
18542 233 24X Fiche 50-201, 83/04/18, 8305230015

8305240614 Requests comments on "Geological Recommendations for Investigation of NRC Disposal Area," by 830527
HANNUM, W H Energy, Dept of, Idaho Operations Ofc 83/04/21
CLARK, A T. Advanced Fuel & Spent Fuel Licensing Branch 1p.
18593 142 24X Fiche. 50-201, 83/04/21, 8305240614

--8305240618 "Geological Recommendations for Investigation of NRC Disposal Area "
* West Valley Nuclear Services Co , Inc 83/03/16 21pp
18593·143. 24X Fiche 50-201, 83/04/21, 8305240614

DOCKET 50-206 SAN ONOFRE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305110059 Advises that onsite & offsite emergency preparedness adequate Emergency plans upgraded per NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 " Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 83/03/09 DIETCH, R
Southern California Edison Co 3pp 18409 106 24X
Fiche 50-206, 83/03/09, 8305110059

8305060372 Forwards Amend 69 to License DPR-13 & notice of issuance & availability Amend deletes Tech Specs requiring audits of emergency & contingency (security) plans once every 12 months
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 DIETCH, R
Southern California Edison Co 3pp 18344 137 24X
Fiche 50-206, 83/05/03, 8305060372

--8305060381 Amend 69 to License DPR-13, deleting Tech Specs requiring audits of emergency & contingency (security) plans by appropriate persons once every 12 months
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 5pp
18344 141 24X Fiche 50-206, 83/05/03, 8305060372

--8305060385 Notice of issuance & availability of Amend 69 to License DPR-13
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 2pp
18344 146 24X Fiche 50-206, 83/05/03, 8305060372

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11, 50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21)
NORDERHAUG, L R Region 5, Office of Director 83/05/12. PAPAY, L T
Southern California Edison Co 2pp 18599 322 24X
Fiche 50-206, 83/05/12, 8305260242

8305240198 Provides info re emergency operations facility in response to NRC request When control room HVAC is upgraded as result of NUREG-0737, Item III D 3 4, technical support ctr HVAC will be reviewed to ensure uniformity of design
BASKIN, K P Southern California Edison Co 83/05/20
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18548 010 24X
Fiche 50-206, 83/05/20, 8305240198

H General correspondence

8305090024 Addl response to FOIA request for documents re 821130 special insp rept Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6) Documents 3 & 4 withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/21 GARDE, B
Government Accountability Project 4pp 18381 158 24X
Fiche 50-206, 83/03/21, 8305090024

8305120178 Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcombe replaces QD Cotton as representative authorized to sign NRC licensing documents
HOLCOMBE, J C San Diego Gas & Electric Co 83/05/06 EISENHUT, D G
Division of Licensing 1p 18427 156 24X Fiche 50-206, 83/05/06, 8305120178

P Operating license stage documents & correspondence

8305060073 Addl response to FOIA request for documents re efforts to make facility more earthquake resistant Documents 1 through 7 listed on app encl Documents 8 through 10 withheld (ref FOIA Exemption 5).
FELTON, J M Division of Rules and Records. 83/03/14 WHARTON, R. J.
San Diego State College 3pp 18365 023 24X Fiche 50-206, 83/03/14, 8305060073

--8203180052 Discusses facility capability to shut down safely for postulated steam line breaks regardless of whether failure seismically induced Unit to remain shut down until issues resolved
DENTON, H R Office of Nuclear Reactor Regulation, Director.
82/03/02 REMICK, F J Office of Policy Evaluations 3pp
18365 121 24X Fiche 50-206, 83/03/14, 8305060073

--8204190027 Updates status of resolution of steam line break & seismic upgrade issues for facility, identified in 820302 memo
DENTON, H R. Office of Nuclear Reactor Regulation, Director
82/04/08 REMICK, F J Office of Policy Evaluations 6pp
18365 126 24X Fiche 50-206, 83/03/14, 8305060073

8305060235 Notification of contract execution, Mod 5 to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1 - Final Rept '" Contractor Univ of California at San Diego
SMITH, P A Division of Contracts FIN B-6531 83/04/25
DENTON, H R Office of Nuclear Reactor Regulation, Director
REITER, L NRC - No Detailed Affiliation Given 1p 18359 352 24X
Fiche. 50-206, 83/04/25, 8305060235

--8305060239 Mod 5, deobligating funds for closeout, to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1 - Final Rept '"
* California, Univ of, San Diego SMITH, P A Division of Contracts, FIN B-6531 83/04/25 1p 18359 353 24X
Fiche 50-206, 83/04/25, 8305060235

8305020427 Forwards "Seismic Evaluation of Reinforced Concrete Masonry Walls," per SEP Topic III-6 re seismic design considerations Results can be compared to test results to assess conservatism of anaylsis methodology
BASKIN, K P Southern California Edison Co 83/04/28
CRUTCHFIELD, D Operating Reactors Branch 5 1p 18281 237. 24X
Fiche 50-206, 83/04/28, 8305020427

--8305020433 "Seismic Evaluation of Reinforced Concrete Masonry Walls "
* Computech Engineering Services, Inc 83/04/30 6pp
18281 238 24X Fiche: 50-206, 83/04/28, 8305020427

8305030414 Forwards final SER re SEP Topic VI-10 A concerning testing of reactor trip sys & ESF & including response-time testing Mods to Tech Specs & equipment to implement response-time testing recommended.
PAULSON, W A Operating Reactors Branch 5 83/04/28 DIETCH, R
Southern California Edison Co 5pp 18306. 242 24X
Fiche 50-206, 83/04/28, 8305030414

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305050038 Forwards final safety assessment rept re SEP Topic II-1.C, "Potential Hazards Due to Nearby Transportation, Institutional, Industrial & Military Facilities " Probability of explosions exceeds current criteria
PAULSON, W A Operating Reactors Branch 5 83/05/03 DIETCH, R
Southern California Edison Co 39pp 18338. 277 24X
Fiche 50-206, 83/05/03, 8305050038

8305060225 Forwards Amend 68 to License DPR-13, safety evaluation & notice of issuance & availability Amend changes Tech Specs & bases to incorporate electrical power availability requirements during refueling or cold shutdown.
PAULSON, W. A Operating Reactors Branch 5 83/05/03 DIETCH, R
Southern California Edison Co 3pp 18345. 076 24X
Fiche 50-206, 83/05/03, 8305060225

--8305060228 Amend 68 to License DPR-13, changing App A Tech Specs & bases to incorporate conditions for electrical power availability during cold shutdown or refueling.
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03. 6pp
18345 079 24X Fiche 50-206, 83/05/03, 8305060225.

--8305060232 Safety evaluation supporting Amend 68 to License DPR-13
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp
18345 085. 24X Fiche 50-206, 83/05/03, 8305060225

--8305060234 Notice of issuances & availability of Amend 68 to License DPR-13
CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/03 2pp
18345. 088 24X Fiche. 50-206, 83/05/03, 8305060225

8305060372 Forwards Amend 69 to License DPR-13 & notice of issuance & availability Amend deletes Tech Specs requiring audits of emergency & contingency (security) plans once every 12 months.
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 DIETCH, R
Southern California Edison Co. 3pp 18344 137 24X
Fiche 50-206, 83/05/03, 8305060372.

--8305060381 Amend 69 to License DPR-13, deleting Tech Specs requiring audits of emergency & contingency (security) plans by appropriate persons once every 12 months
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03. 5pp
18344 141 24X Fiche: 50-206, 83/05/03, 8305060372

--8305060385 Notice of issuance & availability of Amend 69 to License DPR-13
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/03 2pp
18344 146 24X Fiche 50-206, 83/05/03, 8305060372

8305100377 Informs that qualification documentation for resistance temp detectors, limit switches, containment water level monitors & valve indicators will be available prior to return to operation from current outage Numerous delays encountered
KRIEGER, R W Southern California Edison Co 83/05/06
CRUTCHFIELD, D Operating Reactors Branch 5 1p 18379 049 24X
Fiche 50-206, 83/05/06, 8305100377

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120166 Advises of Westinghouse Owners Group schedule for response to TMI Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Two-part program will be undertaken Parts 1 & 2 scheduled for completion by 830731 & 831231, respectively
KRIEGER, R W Southern California Edison Co 83/05/10
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18422 002 24X
Fiche 50-206, 83/05/10, 8305120166

8305120189 Informs that post-implementation review info on NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 will not be provided until 830701 due to higher priority post-TMI work
KRIEGER, R W Southern California Edison Co 83/05/10
CRUTCHFIELD, D Operating Reactors Branch 5 1p 18427 152 24X
Fiche 50-206, 83/05/10, 8305120189

8305240501 Provides status of actions requested in 830401 clarification of 821120 SER on environ qualification of safety-related electrical equipment
BASKIN, K P Southern California Edison Co 83/05/20
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18572 028 24X
Fiche 50-206, 83/05/20, 8305240501

8305240509 Discusses status of activities on environ qualification of safety-related equipment, in response to 10CFR50 49(g) Review of nonsafety-related equipment under 10CFR50 49(b)(2) planned
BASKIN, K P. Southern California Edison Co 83/05/20
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18571 271 24X
Fiche: 50-206, 83/05/20, 8305240509

8305310227 Notifies of decision to refund Class III fee remitted for Proposed Change 108 dtd 820105 to permit raising allowable phosphate discharge limit, as application no longer applicable.
MILLER, W D License Fee Management Branch 83/05/20 DIETCH, R
Southern California Edison Co 1p 18662 259 24X
Fiche: 50-206, 83/05/20, 8305310227

8305250512 Forwards responses to issues raised in 830502-04 meetings re SEP Topic III-6 concerning seismic design considerations Addl info requested at 830502-04 meetings will be provided by 830610
BASKIN, K P Southern California Edison Co 83/05/23
CRUTCHFIELD, D Operating Reactors Branch 5 49pp 18588 104 24X
Fiche: 50-206, 83/05/23, 8305250512

--8305250520 "Balance-of-Plant Mechanical Equipment & Piping Seismic Reevaluation Criteria "
* Bechtel Corp 83/05/20 27pp 18588 153 24X
Fiche 50-206, 83/05/23, 8305250512

8305260263 Notification of 830601 meeting w/util in Bethesda, MD to discuss proposed integrated schedule for implementation of backfit items
PAULSON, W A Operating Reactors Branch 5, 83/05/24 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 18626 003 24X
Fiche: 50-206, 83/05/24, 8305260263

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21, Consolidated Edison Co, of New York, Inc 112pp 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl,
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15, Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305170363 Forwards IE Insp Rept 50-206/83-12 on 830425-29 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/05/03 PAPAY, L T
Southern California Edison Co 2pp 18466 087 24X
Fiche 50-206, 83/05/03, 8305170363

--8305170365 IE Insp Rept 50-206/83-12 on 830425-29 No noncompliance noted Major areas inspected licensee implementation of TMI action item commitments & requirements
KIRSCH, D F Region 5, Office of Director 83/05/03 4pp
18466 089 24X Fiche 50-206, 83/05/03, 8305170363

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11, 50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21)
NORDERHAUG, L R Region 5, Office of Director 83/05/12 PAPAY, L T
Southern California Edison Co 2pp 18599 322 24X
Fiche 50-206, 83/05/12, 8305260242

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305310150 Forwards safety evaluation of conceptual design info submitted on 830928 re proposed redesign of safety injection sys Proposed design acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/27 DIETCH,R Southern California Edison Co 2pp 18653 047 24X Fiche 50-206,83/05/27,8305310150

--8305310153 Safety evaluation of mods to safety injection sys
* NRC - No Detailed Affiliation Given 83/05/27 6pp 18653 049 24X Fiche 50-206,83/05/27,8305310150

DOCKET 50-213 HADDAM NECK PLANT

F Security, medical, emergency & fire protection plans

8305060213 Forwards objectives for 830423 full-scale emergency preparedness exercise info from NRC requested by 830401 re names of personnel attending,social security numbers & security clearance ltrs requested by NRC by 830401
COUNSIL,W G , SEARS,C F Connecticut Yankee Atomic Power Co
COUNSIL,W G Northeast Utilities 83/02/04 HAYNES,R C Region 1, Office of Director 6pp 18345 097 24X Fiche 50-213,83/02/04, 8305060213

8305110069 Forwards "Haddam Neck Plant Emergency Response Exercise "
COUNSIL,W G , WERNER,R P Connecticut Yankee Atomic Power Co 83/03/09 HAYNES,R C Region 1, Office of Director 2pp 18402 338 24X Fiche 50-213,83/03/09,8305110069

--8305110071 "Haddam Neck Plant Emergency Response Exercise " Supporting documentation encl
* Connecticut Yankee Atomic Power Co * Northeast Utilities Service Co 83/04/23 700pp 18402 340 24X
Fiche 50-213,83/03/09,8305110069

8305110569 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18421 089 24X Fiche 50-213,83/04/26, 8305110569

--8305110574 Forwards public version of revised emergency plan implementing procedures,including Procedures EPIP 1 5-2 re notification & communication,EPIP 1 5-7 re radiological dose assessment & EPIP 1 5-14 re evacuation & assembly
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities COUNSIL,W G
* Connecticut Yankee Atomic Power Co 83/03/23 EISENHUT,D G Division of Licensing 2pp 18421 090 24X Fiche 50-213, 83/04/26,8305110569

--8305110579 Public version of revised emergency plan implementing procedures,including Procedures EPIP 1 5-2 re notification & communication,EPIP 1.5-7 re radiological dose assessment & EPIP 1 5-14 re evacuation & assembly
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/15 145pp 18421 092 24X Fiche 50-213,83/04/26, 8305110569

8305100309 Forwards supporting stage-vol & stage-area info re Quabbin Reservoir Study effort requested to assist in disaster contingency planning
BRUTSCH,W A Massachusetts, Commonwealth of, 83/05/04, CRUTCHFIELD,D Operating Reactors Branch 5 CHERY,D L NRC - No Detailed Affiliation Given 1p 18380 086 24X
Fiche 50-213,83/05/04,8305100309

8305170213 Documents agreement reached during 830505 telcon w/NRC re 830131 request for exemption from certain requirements in 10CFR50,App R for control room fire review One channel of pressurizer level indication will be installed at panel
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/05/10 EISENHUT,D G Division of Licensing 2pp 18446 330 24X
Fiche 50-213,83/05/10,8305170213

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305180853 Authorizes refund for review of 821230 & 830408 requests from revised schedule for conducting emergency exercise
MILLER,W O License Fee Management Branch 83/05/11. COUNSIL,W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 1p 18506 030 24X Fiche 50-000,83/05/11,8305180853

8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737,Item III A 2 1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/13 COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18452 349 24X
Fiche 50-000,83/05/13,8305160022

8305250307 Forwards IE Insp Rept 50-213/83-09 on 830307-0410 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/13 COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 18592 035 24X Fiche 50-213,83/05/13,8305250307

--8305250309 IE Insp Rept 50-213/83-09 on 830307-0410 No noncompliance noted Major areas inspected plant operations,review of periodic & special repts,shift logs & operating records, surveillance activities & physical security
REBELOWSKI,T H Region 1, Office of Director ELSASSER,T C Division of Project & Resident Programs 83/05/12 11pp 18592 037 24X Fiche 50-213,83/05/13,8305250307

J Insurance & indemnity information

8305120006 Forwards Endorsements 75 & 66 to NELIA Policy NF-151 & MAELU Policy MF-39,respectively
SINISI,J M Marsh & McLennan, Inc 83/05/05 SALTZMAN,J D Assistant Director for State & Licensee Relations 3pp 18423 073 24X Fiche 50-213,83/05/05,8305120006

P Operating license stage documents & correspondence

8305230616 Forwards info in response to 830208 ltr requesting backfit cost data for operating nuclear units Cost categorized according to NRC imposed,TMI & non-TMI backfits,util-initiated & hybrid backfits
COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL,W G Northeast Utilities 83/03/21 TOURTELLOTTE,J Regulatory Reform Task Force 25pp 18543 038 24X
Fiche 50-000,83/03/21,8305230616

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305100331 Forwards proprietary & nonproprietary versions of "TMI Item II K 3 30 Revised Small Break LOCA Analysis " Proprietary version withheld (ref 10CFR2 790)
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/04/14 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18379 115 24X
Fiche,50-213,83/04/14,8305100331

--8305100335 Nonproprietary version of "TMI Item II K 3 30 Revised Small Break LOCA Analysis "
* Northeast Utilities Service Co 83/04/14 329pp 18379 117 24X Fiche,50-213,83/04/14,8305100331

8305160188 Advises that action required by 830126 Amends 88,51 & 80 to Licenses DPR-21,DPR-61 & DPR-65,respectively & Generic Ltr 83-07 complete,based on util negotiations w/DOE re disposal of high level waste or spent nuclear fuel
CLARK,R A Operating Reactors Branch 3 83/04/20 COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 18462 355 24X
Fiche 50-000,83/04/20,8305160188

8305100385 Forwards affidavit detailing basis for withholding 830414 submittal describing LOCA program (NULAPS),TMI Item II.K 3 30, from public disclosure,per 10CFR2 790
COUNSIL,W G , SEARS,C F Connecticut Yankee Atomic Power Co 83/04/25 CRUTCHFIELD,D Operating Reactors Branch 5 6pp 18378 218 24X Fiche 50-213,83/04/25,8305100385

8305050054 Forwards comments on Generic Ltr 82-32, "Potential Steam Generator Related Requirements." Vendor input should be sought,especially in areas of steam generator tube inservice insp & design considerations
COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities),
COUNSIL,W G Northeast Utilities 83/04/29 EISENHUT,D G, Division of Licensing 6pp 18339 085 24X Fiche,50-000,83/04/29, 8305050054,

8305050112 Provides progress rept on piping mods completed during Cycle 12 refueling outage re SEP Topic III-6, "Seismic Design Considerations," per 820927 commitment
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/04/29
CRUTCHFIELD,D Operating Reactors Branch 5 2pp, 18341 066 24X
Fiche 50-213,83/04/29,8305050112

8305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Manual," per 10CFR50,App E,Section V W/o encls
COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL,W G Northeast Utilities 83/04/29 EISENHUT,D G Division of Licensing 2pp 18362 256 24X Fiche 50-000,83/04/29, 8305090465

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

8305090488 Forwards Amend 56 to License DPR-61 & notice of issuance & availability Amend deletes requirements for monitoring fish impingement on intake screens from App B ETS
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/02 COUNSIL,W G Connecticut Yankee Atomic Power Co 3pp 18361 127 24X Fiche 50-213,83/05/02,8305090488

--8305090491 Amend 56 to License DPR-61,changing ETS Pages 1,2 3-1 through 2 3-3a,3 1-1,5 1-1,5 3-1 & 5 5-1 to delete requirements for monitoring fish impingement on intake screens.
CRUTCHFIELD,D Operating Reactors Branch 5. 83/05/02 9pp 18361 130 24X Fiche 50-213,83/05/02,8305090488

--8305090492 Notice of issuance & availability of Amend 56 to License DPR-61
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/02 2pp 18361 139 24X Fiche 50-213,83/05/02,8305090488

8305160183 Application for amend to License DPR-61,revising Tech Specs re post-accident instrumentation,clarifying definition of containment integrity,adding new containment isolation valve installed & adding new limiting conditions for operation
COUNSIL,W G , SEARS,C F Connecticut Yankee Atomic Power Co 83/05/02 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18445 156 24X Fiche 50-213,83/05/02,8305160183

--8305160189 Proposed Tech Spec re post-accident instrumentation, clarifying definition of containment integrity,adding new containment isolation valve installed & adding new limiting conditions for operation
* Connecticut Yankee Atomic Power Co 83/05/02 22pp 18445 158 24X Fiche 50-213,83/05/02,8305160183

8305090404 Comments on 821229 ltr re rev of procedures concerning river flooding & shutdown outside control room (SEP Topics II-3,B 1 & VII-3) Topics resolved
COUNSIL,W G , SEARS,C F Connecticut Yankee Atomic Power Co 83/05/03 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18362 361 24X Fiche 50-213,83/05/03,8305090404

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D.G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305250510 Application to amend Licenses DPR-61,DPR-21 & DPR-65 deleting 820630 deadline date for conformance w/final rule 10CFR50 49 removing requirement for central equipment qualification file
COUNSIL,W G., SEARS,C.F. Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL,W G Connecticut Yankee Atomic Power Co 83/05/18 CLARK,R A Operating Reactors Branch 3. CRUTCHFIELD,D Operating Reactors Branch 5 3pp 18588 278 24X Fiche 50-000,83/05/18,8305250510

--8305250518 Proposed Tech Spec changes deleting 820630 deadline for environ qualification of electrical equipment
* Northeast Nuclear Energy Co (subs. of Northeast Utilities). 83/05/18 7pp 18588 281 24X Fiche 50-000,83/05/18,8305250510

8305230276 Forwards "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept Response within 60 days of receipt of ltr requested
CRUTCHFIELD,D Operating Reactors Branch 5. 83/05/19 COUNSIL,W G Connecticut Yankee Atomic Co. 2pp 18539 006 24X Fiche 50-213,83/05/19,8305230276

--8305230284 "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept.
BOMBERGER,C , AHMED,N Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-358 DRFT 83/02/15 CLEMENSON,F NRC - No Detailed Affiliation Given. 35pp 18539 008. 24X Fiche 50-213,83/05/19,8305230276

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8304110686 Provides addl info re IE Bulletin 81-03, "Flow Blockage of Cooling Water to Safety Sys Components by Corbicula Sp (Asiatic Clam) & Mytilus Sp (Mussel)," in response to NRC 810410 & 830202 ltrs
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/04/04 JORDAN,E L Director's Office, Office of Inspection and Enforcement 3pp 17915 008 24X Fiche 50-213,83/04/04,8304110686

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270224 "Steam Generator Tube Insp Rept for 1983 Refueling Outage " W/830504 ltr
GRAVES,R H Connecticut Yankee Atomic Power Co 83/04/25 ALLAN,J M Region 1, Office of Director 19pp 18637 213 24X Fiche 50-213,83/04/25,8305270224

8305020395 Ack receipt of 830407 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-06
MARTIN,T T Division of Engineering & Technical Programs 83/04/26 COUNSIL,W G Connecticut Yankee Atomic Power Co 1p 18274 115 24X Fiche 50-213,83/04/26,8305020395

--8305020399 Responds to NRC 830308 ltr re violations noted in IE Insp Rept 50-213/83-06 Corrective actions cure time for drums of solidified waste increased to 7 days & independent check for residual water performed
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/04/07 ALLAN,J M Region 1, Office of Director 4pp 18274 116 24X Fiche 50-213,83/04/26,8305020395

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co, of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co, of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190305 Responds to Items 1,2 & 4 of IE Bulletin 82-02 re degradation of threaded fasteners in RCPB,per NRC 820602 request Maint procedures & QA measures implemented Four steam generator manway studs w/linear indications replaced
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/05/10
ALLAN,J M Region 1, Office of Director 4pp 18501 079 24X
Fiche 50-213,83/05/10,8305190305

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8309250497 Forwards IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/11
COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 18588 255
24X Fiche 50-213,83/05/11,8309250497

--8305250504 IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737,Item II B 2, "Design Review of Plant Shielding "
BAUNACK,W H , EAPEN,P K , PLISCO,L R Region 1, Office of Director 83/05/10 9pp 18588 257 24X Fiche 50-213,83/05/11, 8305250497

8305250307 Forwards IE Insp Rept 50-213/83-09 on 830307-0410.No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/13
COUNSIL,W G Connecticut Yankee Atomic Power Co, 2pp 18592 035
24X Fiche 50-213,83/05/13,8305250307

--8305250309 IE Insp Rept 50-213/83-09 on 830307-0410 No noncompliance noted Major areas inspected plant operations,review of periodic & special repts,shift logs & operating records, surveillance activities & physical security
REBELOWSKI,T H Region 1, Office of Director ELSASSER,T C Division of Project & Resident Programs 83/05/12 11pp 18592 037 24X Fiche 50-213,83/05/13,8305250307

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305250560 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-07
BELLAMY,R R Division of Engineering & Technical Programs 83/05/20 COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 18588 180 24X Fiche 50-213,83/05/20,8305250560

--8305250565 Responds to NRC 830405 ltr re violations noted in IE Insp Rept 50-213/83-07 Corrective actions appropriate procedures will be revised by 830601 to include operational setpoints & high radiation areas will be rekeyed
COUNSIL,W G Connecticut Yankee Atomic Power Co 83/05/04
MARTIN,T T Division of Engineering & Technical Programs. 3pp. 18588 182 24X Fiche 50-213,83/05/20,8305250560

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.

R Periodic operating reports & related correspondence

8305270224 "Steam Generator Tube Insp Rept for 1983 Refueling Outage " W/830504 ltr
GRAVES,R H Connecticut Yankee Atomic Power Co 83/04/25
ALLAN,J M Region 1, Office of Director 19pp 18637 213 24X
Fiche 50-213,83/04/25,8305270224

S Reportable occurrences, LERs & related correspondence

8305230430 Forwards engineering evaluation rept, "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria
ASHE,F Reactor Operations Analysis Branch 83/04/18 SEYFRIT,K V Reactor Operations Analysis Branch 2pp 18545 356 24X
Fiche 50-000,83/04/18,8305230430

--8305230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms," engineering evaluation rept LERs re safety-related battery degradation reviewed.
ASHE,F Reactor Operations Analysis Branch. 83/04/18 5pp. 18545 358 24X Fiche 50-000,83/04/18,8305230430

8305200608 Forwards LER 83-008/03L-0
GRAVES,R H Connecticut Yankee Atomic Power Co 83/05/12
ALLAN,J M Region 1, Office of Director 1p 18526 042 24X
Fiche 50-213,83/05/12,8305200608

--8305200701 LER 83-008/03L-0 on 830414,increase on condenser air radiation monitor indicated primary to secondary steam generator leaks Cause will be identified & steam generator tube repaired during next scheduled refueling outage
WATERS,J J Connecticut Yankee Atomic Power Co 83/05/12
Region 1, Office of Director 1p 18526 043 24X
Fiche 50-213,83/05/12,8305200608

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8305050022 Forwards status,description & schedule for meeting requirements re emergency response capabilities,per Generic Ltr 82-33 (Suppl 1 to NUREG-0737)
FIEDLER,P B General Public Utilities - GPU Service Corp 83/04/15
EISENHUT,D G Division of Licensing 17pp 18342 118 24X
Fiche 50-219,83/04/15,8305050022

8305030365 Forwards Rev 5 to security officer training & qualification plan Rev withheld (ref 10CFR2 790)
FIEDLER,P B General Public Utilities - GPU Service Corp 83/04/26
CRUTCHFIELD,D Operating Reactors Branch 5 1p 18306 215. 24X
Fiche 50-219,83/04/26,8305030365

8305190260 Forwards IE Insp Rept 50-219/83-08 on 830308-0404 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 83/05/05.
FIEDLER,P B General Public Utilities - GPU Service Corp 3pp 18501 247 24X Fiche 50-219,83/05/05,8305190260

--8305190263 Notice of violation from insp on 830308-0404 Safeguards info deleted
* Region 1, Office of Director 83/05/05 1p 18501 249 24X
Fiche 50-219,83/05/05,8305190260

--8305190266 IE Insp Rept 50-219/83-08 on 830308-0404 Noncompliance noted violation of security plan provisions Safeguards info deleted
COWGILL,C , THOMAS,J , KEIMIG,R R Region 1, Office of Director 83/04/28 12pp 18501 250 24X Fiche 50-219,83/05/05,8305190260.

8305110009 Comments on adequacy of implementation of NUREG-0737, Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50 " Offsite & onsite emergency preparedness adequate
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/09 FIEDLER,P B, General Public Utilities - GPU Service Corp 3pp 18409,023 24X
Fiche 50-219,83/05/09,8305110009

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

O Adjudicatory correspondence

8305240536 Affidavit of RE Rogan confirming util commitment to activate emergency operations facility & staff facility w/emergency support director within 1 h of site area or general emergency notification or declaration
ROGAN,R E General Public Utilities - GPU Service Corp 83/05/20
4pp 18576 087 24X Fiche 50-000,83/05/20,8305240536

I Financial information

8305020465 Annual Financial Rept 1982
KUHNS,W G , DIECKAMP,H General Public Utilities - GPU Service Corp. 83/03/03 40pp 18281.072 24X Fiche 50-219,83/04/27,8305020461

J Insurance & indemnity information

8305230037 Forwards Endorsement 87 to NELIA Policy NF-164
GERETY,H F General Public Utilities - GPU Service Corp 83/05/16
SALTZMAN,J. Antitrust & Economic analysis Branch (Utility Finance) 2pp 18539 192 24X Fiche 50-219,83/05/16,8305230037

P Operating license stage documents & correspondence

8305170558 Submits status of analysis of Mark I containment torus-to-drywell vacuum breaker valves for condensation oscillation & chugging loads & util proposed schedule for completion Final analysis scheduled for 830901
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/11
EISENHUT,D G Division of Licensing 2pp 18468 123 24X
Fiche 50-219,80/35/11,8305170558

8305230402 Forwards info on costs incurred from backfitting & upgrading facilities,per 830210 request Mods categorized NRC-required, TMI-lessons learned or util-initiated
DIECKAMP,H General Public Utilities - GPU Service Corp 83/03/08
TOURTELLOTTE,J Regulatory Reform Task Force 9pp 18576 318 24X
Fiche 50-000,83/03/08,8305230402

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305020513 Grants exemption from fee requirements for 830211 application for amend to License DPR-16,deleting nonradiological water quality conditions Reimbursement forthcoming
MILLER,W O. License Fee Management Branch 83/04/25 FIEDLER,P B
General Public Utilities - GPU Service Corp 1p 18284 324 24X
Fiche 50-219,83/04/25,8305020513

8305020362 Forwards plant-specific responses to six NRC questions re safety/relief valve testing (NUREG-0737 Item II D 1),per 821217 request Safety/relief valve discharge piping utilizes Y quencher w/sparger at discharge pipe exit
FIEDLER,P B General Public Utilities - GPU Service Corp 83/04/27
CRUTCHFIELD,D Operating Reactors Branch 5 21pp 18274 058 24X
Fiche 50-219,83/04/27,8305020362

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305040474 Informs that analysis of aircraft traffic for facility per integrated assessment rept (NUREG-0822) followup acceptable.
CRUTCHFIELD,D. Operating Reactors Branch 5 83/05/03 FIEDLER,P B
General Public Utilities - GPU Service Corp. 2pp 18319 315 24X
Fiche 50-219,83/05/03,8305040474

8305110374 Forwards addl info re NUREG-0737,Items II F 1 4,II F 1 5 & II F 1 6 concerning containment pressure,water level & hydrogen monitors,respectively,per 830106 request No obstructions would prevent hydrogen from escaping from core
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/06
CRUTCHFIELD,D Operating Reactors Branch 5 8pp 18406 279 24X
Fiche 50-219,83/05/06,8305110374

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods.Svc list encl
EISENHUT,D G. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305180433 Forwards safety evaluation re BWR Owners Group B01230 response to NUREG-0737,Item II K.3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mods required
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/17, FIEDLER,P.B
General Public Utilities - GPU Service Corp 2pp 18486:195 24X
Fiche 50-219,83/05/17,8305180433

---8305180440 Safety evaluation of BWR Owners Group generic response to NUREG-0737,Item II.K.3.45, "Depressurization W/Other Than Automatic Depressurization Sys " No mods required
* Operating Reactors Branch 5 83/05/17 4pp. 18486 197 24X
Fiche 50-219,83/05/17,8305180433

8305270082 Updates 830415 ltr re installation & operability of post-accident sampling sys per NUREG-0737,Item II B 3 Items agreed upon at 830512 meeting listed.Installation work will be completed during current refueling outage.
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/20
EISENHUT,D.G. Division of Licensing 2pp 18638 289 24X
Fiche 50-219,83/05/20,8305270082

8305310108 Forwards request for addl info on in-plant safety relief valve tests w/Y-quencher device to determine adequacy of hydrodynamic load specs as part of Mark I long-term program Response within 30 days requested
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/27 FIEDLER,P B
General Public Utilities - GPU Service Corp 3pp 18658 060 24X
Fiche 50-219,83/05/27,8305310108

8305310213 Forwards safety evaluation of util 830328 response to NUREG-0737,Item II K 3 21, "Core Spray & LPCI Sys Low Level Initiation " Proposed mod designs acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/27 FIEDLER,P B
General Public Utilities - GPU Service Corp 4pp 18658 142 24X
Fiche 50-219,83/05/27,8305310213

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305040184 Notification of significant licensee 830512 meeting in Forked River,NJ to discuss results of SALP
TRIPP,L E Division of Project & Resident Programs 83/04/22
Division of Project & Resident Programs 1p 18326 336 24X
Fiche 50-219,83/04/22,8305040184

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche.50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8305190260 Forwards IE Insp Rept 50-219/83-08 on 830308-0404 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs. 83/05/05
FIEDLER,P B General Public Utilities - GPU Service Corp 3pp
18501 247 24X Fiche 50-219,83/05/05,8305190260

---8305190263 Notice of violation from insp on 830308-0404.Safeguards info deleted
* Region 1, Office of Director 83/05/05 1p 18501.249 24X
Fiche 50-219,83/05/05,8305190260.

--8305190266 IE Insp Rept 50-219/83-08 on 830308-0404 Noncompliance noted violation of security plan provisions Safeguards info deleted
COWGILL,C , THOMAS,J , KEIMIG,R R Region 1, Office of Director 83/04/28 12pp 18501 250 24X Fiche 50-219,83/05/05,8305190260

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160018 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/82-24
MARTIN,T T Division of Engineering & Technical Programs 83/05/10
FIEDLER,P B General Public Utilities - GPU Service Corp 1p
18452 338 24X Fiche 50-219,83/05/10,8305160018

--8305160023 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-219/82-24 Corrective actions radiological controls personnel will be reinstructed & request for measurement procedures sent to vendor Completion expected by 830531
FIEDLER,P B General Public Utilities - GPU Service Corp 83/04/25 MARTIN,T T Division of Engineering & Technical Programs 2pp 18452 339 24X Fiche 50-219,83/05/10,8305160018

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250291 Forwards IE Insp Rept 50-219/83-05 on 830214-18,0301-04, 21-22,24 & 28 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/05/12
FIEDLER,P B General Public Utilities - GPU Service Corp 2pp
18592 067 24X Fiche 50-219,83/05/12,8305250291

--8305250295 IE Insp Rept 50-219/83-05 on 830214-18,0301-04,21-22,24 & 28 No noncompliance noted Major areas inspected inservice insp activities,including program & procedure review & licensee response to IE Bulletin 82-03
MCBREARTY,R A , DURR,J P Region 1, Office of Director 83/05/05 6pp 18592 069 24X Fiche 50-219,83/05/12,8305250291

8305200500 Forwards response to IE Bulletin 80-13, "Cracking in Core Spray Spargers " Augmented insp program includes in-vessel exam of annulus piping & sparger assemblies by combination of remote visual,ultrasonic & air testing techniques
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/13
Region 1, Office of Director 13pp 18514 018 24X
Fiche 50-219,83/05/13,8305200500.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305240488 Forwards INPO "Evaluation of Oyster Creek Nuclear Generating Station,1982 " Evaluation conducted 821025-1101
BRUNNER,E J Division of Project & Resident Programs 83/05/06
TAYLOR,J M Division of Reactor Programs (Pre 830103) 1p
18571 315 24X Fiche 50-219,83/05/06,8305240488

--8305240476 "Evaluation of Oyster Creek Nuclear Generating Station, 1982 "
* Institute of Nuclear Power Operations 83/03/31 44pp
18571 316 24X Fiche 50-219,83/05/06,8305240488

8305230436 Forwards monthly operating rept for Apr 1983
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/17
Division of Data Automation & Management Information 1p
18538 205 24X Fiche 50-219,83/05/17,8305230436

--8305230437 Monthly operating rept for Apr 1983
BARAN,R General Public Utilities - GPU Service Corp 83/05/02
6pp 18538 207 24X Fiche 50-219,83/05/17,8305230436

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305030441 Forwards LER 83-014/01T-0 Detailed event analysis encl
FIEDLER,P B General Public Utilities - GPU Service Corp 83/04/20
Region 1, Office of Director 3pp 18306 324 24X
Fiche 50-219,83/04/20,8305030441

--8305030447 LER 83-014/01T-0 on 830406,design deficiency discovered in heating coil control circuitry for standby gas treatment sys trains Temporary redundant power feed provided until permanent mod installed during current maint outage
DICKINSON,A C General Public Utilities - GPU Service Corp
83/04/20 Region 1, Office of Director 1p 18306 327 24X
Fiche 50-219,83/04/20,8305030441

8305020459 PNS-I-83-009 on 830427,bomb threat phoned in by unidentified male caller.Evacuation initiated Search conducted w/negative findings Normal operations resumed Authorities notified
MADDEN,W , GODY,A T , JOYNER,J H. Region 1, Office of Director
83/04/27 1p 18283 310 24X Fiche 50-219,83/04/27,8305020459

8305190072 PNO-I-83-051 on 830516,vehicle ran stop sign & struck licensee-owned van carrying radioactive matl Package not damaged & no contamination found Package returned to site for repackaging
THOMAS, CONNER Region 1, Office of Director 83/05/16 1p
18502 068 24X Fiche 50-219,83/05/16,8305190072

DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

C Utility Environmental Report (ER), amends & correspondence

8305230574 Forwards repts in response to FSAR & environ rept - OL stage acceptance review questions per NRC request for addl info to 830419 submittal re OL application List of repts submitted encl
MANGAN,C V Niagara Mohawk Power Corp 83/05/13 EISENHUT,D G
Division of Licensing 3pp 18600 001 24X Fiche 50-410,83/05/13, 8305230574

--8305230585 "316(a) Demonstration Submission,NPDES Permit NY 0001015. "
* Niagara Mohawk Power Corp 83/05/13 224pp 18600 007 24X
Fiche 50-410,83/05/13,8305230574

--8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6," interim rept
* Lawler,Matusky & Skelly Engineers LMSE-82/0091&191-058
82/04/30 82pp 18600 231 24X Fiche 50-410,83/05/13,8305230574.

--8305230592 "316(a) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 217pp
18600 308 24X Fiche. 50-410,83/05/13,8305230574

--8305230599 "316(b) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 325pp
18601 165 24X Fiche 50-410,83/05/13,8305230574

--8305230603 "Fish Tag Rept Summary 1972-76 "
STORR,J F Storr, J F 76/12/31 95pp 18602 130 24X
Fiche 50-410,83/05/13,8305230574

--8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies,Summary Plankton,Benthos,Fish,1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 591pp
18602 225 24X Fiche 50-410,83/05/13,8305230574

--8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies,Fish Impingement,Water Quality,1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 268pp
18604 096 24X Fiche 50-410,83/05/13,8305230574

--8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 1, Apps I-III (a-d) Methods & Matls,Statistical Procedures, Plankton,1973."
* Quirk, Lawler & Matusky Engineers 83/05/13, 508pp
18605 001 24X Fiche 50-410,83/05/13,8305230574

--8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (a-p) Plankton, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 577pp
18606 149 24X Fiche 50-410, 83/05/13, 8305230574

--8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV, V, VI Benthos, Fish, Fish Impingement, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 396pp
18608 006 24X Fiche 50-410, 83/05/13, 8305230574

--8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4, App VII Water Quality, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 291pp
18610 015 24X Fiche 50-410, 83/05/13, 8305230574

--8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV, 1974, "
* Lawler, Matusky & Skelly Engineers 75/12/31 333pp
18609 042 24X Fiche 50-410, 83/05/13, 8305230574

--8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters VII-X), 1974 "
* Lawler, Matusky & Skelly Engineers, 75/12/31 280pp
18610:306 24X Fiche 50-410, 83/05/13, 8305230574

--8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975 "
* Lawler, Matusky & Skelly Engineers LMSE-76/0081&191-033
76/05/31 497pp 18611 226 24X Fiche 50-410, 83/05/13,
8305230574

--8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
* Lawler, Matusky & Skelly Engineers 77/05/31 489pp
18613 001 24X Fiche, 50-410, 83/05/13, 8305230574

--8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies, App I-IX, 1976 "
* Lawler, Matusky & Skelly Engineers 77/05/31 651pp
18614 130 24X Fiche 50-410, 83/05/13, 8305230574

--8305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 "
* Texas Instruments, Inc 78/05/31 215pp 18618 001 24X
Fiche, 50-410, 83/05/13, 8305230574

--8305230681 "316(a) Demonstration Submission, NPDES Permit 070 0X2 2 000632 NY (0003212) "
* Niagara Mohawk Power Corp 83/05/13 150pp 18618 216 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230684 "Intake Considerations, NPDES Permit 070 0X2 2 00632 NY (0003212) "
* Niagara Mohawk Power Corp, 83/05/13 50pp 18619 006 24X
Fiche, 50-410, 83/05/13, 8305230574

--8305230687 "316(a) Demonstration Submission NPDES Permit 070 0X2 2 000633 NY (0003221), "
* Niagara Mohawk Power Corp LMSE-75/0368&191/029 83/05/13
152pp, 18619 053 24X Fiche 50-410, 83/05/13, 8305230574,

--8305230691 "Intake Considerations NPDES Permit 070 0X2 2 000633 NY (0003221) "
* Niagara Mohawk Power Corp, 83/05/13 50pp 18619 205 24X
Fiche: 50-410, 83/05/13, 8305230574

--8305230696 "316(A) Demonstration Submission NPDES Permit NY 0002186 "
* Niagara Mohawk Power Corp, 83/05/13 460pp 18619 249 24X
Fiche 50-410, 83/05/13, 8305230574,

--8305230699 "Intake Considerations, NPDES Permit NY 0002186 "
* Niagara Mohawk Power Corp 83/05/13 149pp 18620 349 24X
Fiche, 50-410, 83/05/13, 8305230574

--8305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 6 - Oswego Steam Station, "
* Stone & Webster Engineering Corp, 77/05/31 52pp 18621 138
24X Fiche, 50-410, 83/05/13, 8305230574

F. Security, medical, emergency & fire protection plans

8305020569 Responds to 830119 ltr re changes to facility security plan. Changes consistent w/10CFR50, 54(p) & acceptable.
VASSALLO, D. B. Operating Reactors Branch 2 83/04/21 SUNBER, J J
Niagara Mohawk Power Corp 2pp 18284, 236 24X
Fiche: 50-220, 83/04/21, 8305020569

8305200386 Forwards IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/25
RHODE, G K Niagara Mohawk Power Corp 2pp 18518 163 24X
Fiche 50-220, 83/04/25, 8305200386

--8305200392 IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance noted Major areas inspected licensee actions on previous insp findings, plant tours, physical security & IE circulars Safeguards info deleted (ref 10CFR73 21 & 10CFR9 5(a)(4))
HUDSON, S D , KISTER, H B Region 1, Office of Director 83/04/13
9pp 18518 165 24X Fiche 50-220, 83/04/25, 8305200386

8305040483 Forwards application for amend to License DPR-63 changing Tech Specs re fire protection program
MANGAN, C V Niagara Mohawk Power Corp 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18319 273 24X
Fiche 50-220, 83/05/02, 8305040483

--8305040493 Application for amend to License DPR-63 changing Tech Specs re fire protection program
MANGAN, C V Niagara Mohawk Power Corp 83/05/02 2pp
18319 274 24X Fiche 50-220, 83/05/02, 8305040483

--8305040500 Proposed Tech Spec changes re fire protection program
* Niagara Mohawk Power Corp 83/05/02 39pp 18319 276 24X
Fiche 50-220, 83/05/02, 8305040483

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305200382 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-220/80-11
MARTIN, T T Division of Engineering & Technical Programs 83/05/17,
RHODE, G K Niagara Mohawk Power Corp 2pp 18517 314 24X
Fiche 50-220, 83/05/17, 8305200382

--8305200383 Responds to NRC 830304 ltr re violations noted in IE Health Physics Appraisal Rept 50-220/80-11 Corrective actions internal exposure control, respiratory protection program surveillance control all closed in Insp 82-20
LEMPGES, T E Niagara Mohawk Power Corp 83/03/31 HAYNES, R
Region 1, Office of Director 29pp 18517 316 24X
Fiche 50-220, 83/05/17, 8305200382

8305240576 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50, " completed Item closed
VASSALLO, D B, Operating Reactors Branch 2 83/05/18 RHODE, G. K
Niagara Mohawk Power Corp 3pp 18594 214 24X
Fiche 50-220, 83/05/18, 8305240576

8305270026 Provides clarification of util position on NUREG-0737, Items I.A 1.3, "Min Shift Crew" & III A 1 2, "Staffing Level for Emergency Situations "
MANGAN, C V, Niagara Mohawk Power Corp 83/05/24 VASSALLO, D. B
Operating Reactors Branch 2 2pp 18638 304 24X
Fiche: 50-220, 83/05/24, 8305270026

P Operating license stage documents & correspondence

8304210050 Clarifies B21220 environ qualification SER. Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review, per encl guidelines, due in 30 days
VASSALLO, D B Operating Reactors Branch 2 83/04/08 RHODE, G K
Niagara Mohawk Power Corp 5pp 18118 347 24X
Fiche 50-220, 83/04/08, 8304210050

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp, 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040483 Forwards application for amend to License DPR-63 changing Tech Specs re fire protection program
MANGAN, C. V. Niagara Mohawk Power Corp 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18319 273 24X
Fiche 50-220, 83/05/02, 8305040483

--8305040493 Application for amend to License DPR-63 changing Tech Specs re fire protection program
MANGAN, C V. Niagara Mohawk Power Corp 83/05/02, 2pp
18319 274 24X Fiche, 50-220, 83/05/02, 8305040483,

--8305040500 Proposed Tech Spec changes re fire protection program
* Niagara Mohawk Power Corp 83/05/02 39pp 18319 276 24X
Fiche 50-220,83/05/02,8305040483

8305050020 Forwards application for amend to License DPR-63,proposing Tech Spec changes to reflect change in surveillance requirements for reactor vessel matl samples
MANGAN,C V Niagara Mohawk Power Corp 83/05/02 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18541 089 24X
Fiche 50-220,83/05/02,8305050020

--8305050031 Application for amend to License DPR-63,proposing Tech Spec changes to reflect change in surveillance requirements for reactor vessel matl samples
MANGAN,C V Niagara Mohawk Power Corp 83/05/02 2pp
18541 090 24X Fiche 50-220,83/05/02,8305050020

--8305230431 Proposed Tech Specs reflecting change in surveillance requirements for reactor vessel matl samples Supporting info encl
* Niagara Mohawk Power Corp 83/05/02 4pp 18541 092 24X
Fiche 50-220,83/05/02,8305050020

8305060043 Forwards application for amend to License DPR-63,revising Tech Spec Section 3 6 5 re radioactive matl sources to clarify inventory requirements
RHODE,G K Niagara Mohawk Power Corp 83/05/03 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18345 103 24X
Fiche 50-220,83/05/03,8305060043

--8305060046 Application for amend to License DPR-63,revising Tech Spec Section 3 6 5 re radioactive matl sources to clarify inventory requirements
RHODE,G K Niagara Mohawk Power Corp 83/05/03 5pp 18345 104
24X Fiche 50-220,83/05/03,8305060043

--8305060048 Proposed Tech Spec Section 3 6 5 re radioactive matl sources,clarifying inventory requirements
* Niagara Mohawk Power Corp 83/05/03 2pp 18345 109 24X
Fiche 50-220,83/05/03,8305060043

8305170027 Forwards Amend 52 to License DPR-63,safety evaluation & notice of issuance & availability Amend changes test duration for containment integrated leak rate test to min of 8 h
HERMANN,R Operating Reactors Branch 2 83/05/04 RHODE,G K
Niagara Mohawk Power Corp 2pp 18494 171 24X
Fiche,50-220,83/05/04,8305170027.

--8305170052 Amend 52 to License DPR-63,changing test duration for containment integrated leak rate test to min of 8 h
VASSALLO,D B Operating Reactors Branch 2 83/05/04 4pp.
18494 173 24X Fiche 50-220,83/05/04,8305170027

--8305170056 Safety evaluation supporting Amend 52 to License DPR-63
* Office of Nuclear Reactor Regulation, Director 83/05/04 2pp
18494 177 24X Fiche 50-220,83/05/04,8305170027

--8305170060 Notice of issuance & availability of Amend 52 to License DPR-63
VASSALLO,D B Operating Reactors Branch 2 83/05/04. 2pp
18494 179 24X Fiche 50-220,83/05/04,8305170027

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305160015 Submits schedule for providing info re NUREG-0737,Item II.B 3, "Post-Accident Sampling Capability " Formal procedure for relating radionuclide concentrations to core damage expected by startup from 1984 refueling outage.
MANGAN,C V. Niagara Mohawk Power Corp 83/05/11. EISENHUT,D.G
Division of Licensing 1p 18453 162 24X Fiche,50-220,83/05/11,
8305160015

8305200345 Advises that justification for continued operation on items for which prior justification not supplied will be submitted by 830520
MANGAN,C V Niagara Mohawk Power Corp 83/05/16 VASSALLO,D.B
Operating Reactors Branch 2 1p 18516 234. 24X
Fiche 50-220,83/05/16,8305200345

8305250514 Forwards safety evaluation re BWR Owners Group response to NUREG-0737,Item II K 3.45,"Depressurization W/Other Than Automatic Depressurization Sys " Action on item complete
VASSALLO,D.B. Operating Reactors Branch 2 83/05/18. RHODE,G K
Niagara Mohawk Power Corp 2pp. 18595 310 24X
Fiche,50-220,83/05/18,8305250514

--8305250523 Safety evaluation supporting BWR Owners Group generic response to Item II K 3 45 of NUREG-0737,"Depressurization W/Other Than Automatic Depressurization Sys "
* NRC - No Detailed Affiliation Given 83/05/18 5pp
18595 312 24X Fiche 50-220,83/05/18,8305250514

8305240402 Forwards info re environ qualification of electrical equipment,per NRC requests for addl info & clarifications Justification for continued operation,completed safety-related equipment list & response to 10CFR50 49 discussed
MANGAN,C V Niagara Mohawk Power Corp 83/05/20 VASSALLO,D B
Operating Reactors Branch 2 104pp 18574 325 24X
Fiche 50-220,83/05/20,8305240402

8305270026 Provides clarification of util position on NUREG-0737,Items I A 1 3, "Min Shift Crew" & III A 1 2, "Staffing Level for Emergency Situations "
MANGAN,C V Niagara Mohawk Power Corp 83/05/24 VASSALLO,D B
Operating Reactors Branch 2 2pp 18638 304 24X
Fiche 50-220,83/05/24,8305270026

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291. 24X Fiche 50-000,83/04/25,8303040025

8305200386 Forwards IE Insp Rept 50-220/83-06 on 830301-31,No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/04/25.
RHODE,G K Niagara Mohawk Power Corp 2pp. 18518 163 24X
Fiche 50-220,83/04/25,8305200386

--8305200392 IE Insp Rept 50-220/83-06 on 830301-31 No noncompliance noted Major areas inspected licensee actions on previous insp findings,plant tours,physical security & IE circulars. Safeguards info deleted (ref 10CFR73 21 & 10CFR9 5(a)(4)).
HUDSON,S D ; KISTER,H B Region 1, Office of Director 83/04/13
9pp 18518 165 24X Fiche 50-220,83/04/25,8305200386

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382:047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28. Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441:170 24X Fiche 50-000,83/05/03,8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282. 24X Fiche:50-000,83/05/04,8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc 119pp. 18441.001 24X Fiche.50-000,83/05/04,8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200382 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Health Physics Appraisal Rept 50-220/80-11
MARTIN, T T Division of Engineering & Technical Programs 83/05/17
RHODE, G K Niagara Mohawk Power Corp 2pp 18517 314 24X
Fiche: 50-220, 83/05/17, 8305200382

--8305200383 Responds to NRC 830304 ltr re violations noted in IE Health Physics Appraisal Rept 50-220/80-11 Corrective actions internal exposure control, respiratory protection program surveillance control all closed in Insp 82-20
LEMPGES, T E Niagara Mohawk Power Corp 83/03/31 HAYNES, R
Region 1, Office of Director 29pp 18517 316 24X
Fiche: 50-220, 83/05/17, 8305200382

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8304110516 Forwards "Nine Mile Point Unit 1 Aquatic Ecology Studies, 1982. "
LEMPGES, T. E. Niagara Mohawk Power Corp 83/03/30 HAYNES, R C
Region 1, Office of Director 1p 17909 074 24X
Fiche: 50-220, 83/03/30, 8304110516

--8304110519 "Nine Mile Point Unit 1 Aquatic Ecology Studies, 1982 "
* Ecological Analysts, Inc NMP11K 83/03/31 102pp
17909:075. 24X Fiche 50-220, 83/03/30, 8304110516

8305160097 Forwards "Annual Environ Operating Rept, Part B - Radiological Rept, 1982 " Nonradiological aquatic ecology studies data rept for 1982 submitted under separate cover
LEMPGES, T E Niagara Mohawk Power Corp 83/04/25 ALLAN, J Region 1, Office of Director 1p. 18450 224. 24X Fiche 50-220, 83/04/25, 8305160097

--8305160103 "Annual Environ Operating Rept, Part B - Radiological Rept, 1982, "
* Niagara Mohawk Power Corp 83/04/30 123pp. 18450 225 24X
Fiche. 50-220, 83/04/25, 8305160097

8305100272 Forwards "Quarterly Task Person-Rem Rept, Jan-Mar 1983, " per Amend 30 to License DPR-63
MANGAN, C. V. Niagara Mohawk Power Corp 83/04/29 EISENHUT, D G
Division of Licensing 1p 18371 301. 24X Fiche 50-220, 83/04/29, 8305100272

--8305100277 "Quarterly Task Person-Rem Rept, Jan-Mar 1983 "
* Niagara Mohawk Power Corp 83/04/29 29pp 18371 302 24X
Fiche: 50-220, 83/04/29, 8305100272

8305170393 Forwards monthly operating rept for Apr 1983
LEMPGES, T. E. Niagara Mohawk Power Corp. 83/05/10 Director's Office, Office of Inspection and Enforcement 1p 18471:205 24X
Fiche: 50-220, 83/05/10, 8305170393

--8305170395 Monthly operating rept for Apr 1983
ROMAN, T. W. Niagara Mohawk Power Corp. 83/05/04 5pp 18471:206
24X Fiche. 50-220, 83/05/10, 8305170393

8305230574 Forwards repts in response to FSAR & environ rept - OL stage acceptance review questions per NRC request for addl info to 830419 submittal re OL application. List of repts submitted encl.
MANGAN, C. V Niagara Mohawk Power Corp 83/05/13 EISENHUT, D G.
Division of Licensing. 3pp. 18600:001 24X Fiche: 50-410, 83/05/13, 8305230574.

--8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6, " interim rept
* Lawler, Matusky & Skelly Engineers LMSE-82/0091&191-058
82/04/30 82pp 18600 231 24X Fiche 50-410, 83/05/13, 8305230574

--8305230603 "Fish Tag Rept Summary 1972-76 "
STORR, J F Storr, J F 76/12/31 95pp 18602 130 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish, 1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 591pp
18602 225 24X Fiche 50-410, 83/05/13, 8305230574

--8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies, Fish Impingement, Water Quality, 1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 268pp
18604 096 24X Fiche 50-410, 83/05/13, 8305230574

--8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 1, Apps I-III (a-d) Methods & Matls, Statistical Procedures, Plankton, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 508pp
18605 001 24X Fiche 50-410, 83/05/13, 8305230574

--8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (e-p) Plankton, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 577pp
18606 149 24X Fiche 50-410, 83/05/13, 8305230574

--8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV, V, VI: Benthos, Fish, Fish Impingement, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 396pp
18608 006 24X Fiche 50-410, 83/05/13, 8305230574

--8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4, App VII Water Quality, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 291pp
18610 015 24X Fiche: 50-410, 83/05/13, 8305230574

--8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV, 1974 "
* Lawler, Matusky & Skelly Engineers 75/12/31 333pp
18609 042 24X Fiche. 50-410, 83/05/13, 8305230574

--8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters VII-X), 1974 "
* Lawler, Matusky & Skelly Engineers 75/12/31, 280pp
18610 306 24X Fiche 50-410, 83/05/13, 8305230574

--8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975 "
* Lawler, Matusky & Skelly Engineers LMSE-76/0081&191-033
76/05/31 497pp 18611 226 24X Fiche: 50-410, 83/05/13, 8305230574

--8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
* Lawler, Matusky & Skelly Engineers 77/05/31, 489pp
18613 001 24X Fiche 50-410, 83/05/13, 8305230574

--8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies, App I-IX, 1976. "
* Lawler, Matusky & Skelly Engineers 77/05/31 651pp
18614 130. 24X Fiche 50-410, 83/05/13, 8305230574

--8305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 "
* Texas Instruments, Inc. 78/05/31 215pp 18618 001 24X
Fiche. 50-410, 83/05/13, 8305230574

S Reportable occurrences, LERs & related correspondence

8305060426 Forwards LER 81-053/03L-1
LEMPGES, T E Niagara Mohawk Power Corp 83/04/27 ALLAN, J M
Region 1, Office of Director 1p 18343 225 24X
Fiche 50-220, 83/04/27, 8305060426

--8305060428 LER 81-053/03L-1: on 811120, discovered that single failure of electrical power supply could either isolate both condenser sys or cause failure to isolate Logic for initiation & isolation of condenser sys reviewed
RANDALL, R. G Niagara Mohawk Power Corp 83/04/18 Region 1, Office of Director 1p. 18343:226 24X Fiche: 50-220, 83/04/27, 8305060426

8305060533 Forwards updated LER 83-020/03X-1
LEMPGES, T E. Niagara Mohawk Power Corp 83/04/27. ALLAN, J. M
Region 1, Office of Director 1p 18347 303 24X
Fiche 50-220, 83/04/27, 8305060533

--8305060540 Updated LER 83-020/03X-1 on 830121,during major outage while performing local leak rate testing,leakage from valves 58 1-01 & 58 1-02 found to exceed Tech Specs Caused by corrosion buildup New clapper installed
RANDALL,R G Niagara Mohawk Power Corp 83/04/27 Region 1, Office of Director 2pp 18347 304 24X Fiche 50-220,83/04/27, 8305060533

8305200283 Forwards LER 83-006/03L-0
LEMPGES,T E Niagara Mohawk Power Corp 83/05/11 ALLAN,J M Region 1, Office of Director 1p 18517 063 24X
Fiche 50-220,83/05/11,8305200283

--8305200290 LER 83-006/03L-0 on 830411,while performing design review, discovered that poured concrete north & west walls of control room would not meet original seismic criteria Mods made to improve wall structural loading capabilities
RANDALL,R G Niagara Mohawk Power Corp 83/05/11 Region 1, Office of Director 1p 18517 064 24X Fiche 50-220,83/05/11, 8305200283

8305270075 LER 83-007/03L-0 on 830419,30-ft wind direction sensor azimuth alignment found misaligned by 9 8 degrees Caused by improper alignment of mounting plates when installed Sensors readjusted & checked W/830519 ltr
IAVENDITTI,A , MANGAN,C V Niagara Mohawk Power Corp 83/05/17
ALLAN,J M Region 1, Office of Director 3pp 18638 298 24X
Fiche 50-220,83/05/17,8305270075

DOCKET 50-225 RPI CRITICAL EXPERIMENT

F Security, medical, emergency & fire protection plans

8305170466 Forwards revised physical security plan,replacing 820426 plan Plan withheld (ref 10CFR2 790 & 73 21)
WICKS,F , HARRIS,D Rensselaer Polytechnic Inst 83/04/26
THOMAS,C O Standardization & Special Projects Branch 1p
18470 005 24X Fiche 50-225,83/04/26,8305170466

8305110388 Forwards IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/04/29
LAHEY,R T Rensselaer Polytechnic Inst 2pp 18406 212 24X
Fiche 50-225,83/04/29,8305110388

--8305110395 IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted Major areas inspected action on previous insp findings,facility operations,organization,logs & records, surveillance activities & emergency procedures
KINNEY,W W , ELSASSER,T C Region 1, Office of Director
83/04/28 6pp 18406 214 24X Fiche 50-225,83/04/29,8305110388

P Operating license stage documents & correspondence

8305170100 Notification of 830523-26 meetings w/Rensselaer Polytechnic Inst & LASL in Schenectady,NY to review & evaluate reactor facility in connection w/application for OL renewal
BERNARD,H Standardization & Special Projects Branch 83/05/12
THOMAS,C O Standardization & Special Projects Branch 2pp
18495 338 24X Fiche 50-225,83/05/12,8305170100

Q Inspection reports, IE Bulletins & correspondence

8305110388 Forwards IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs. 83/04/29
LAHEY,R T Rensselaer Polytechnic Inst 2pp 18406:212 24X
Fiche 50-225,83/04/29,8305110388

--8305110395 IE Insp Rept 50-225/83-02 on 830324-25 No noncompliance noted Major areas inspected action on previous insp findings,facility operations,organization,logs & records, surveillance activities & emergency procedures
KINNEY,W W , ELSASSER,T C. Region 1, Office of Director
83/04/28 6pp 18406 214 24X Fiche 50-225,83/04/29,8305110388

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO,C J Region 3, Office of Director 83/04/29 REED,C.
Commonwealth Edison Co. 2pp. 18297 137 24X Fiche 50-010,83/04/29, 8305030336

--8305030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29 2pp 18297 139 24X
Fiche 50-010,83/04/29,8305030336

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR50,App E Emergency plans upgraded per NUREG-0737,Item III A 2 1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/11 FARRAR,D L.
Commonwealth Edison Co 3pp 18423,040 24X Fiche 50-010,83/05/11, 8305120116

8305240245 Requests schedular exemptions allowing delay in implementing 10CFR50 48 requirements for installation of fire protection mods Request based on AE,manufacturer & const personnel anticipated implementation schedule
RYBAK,B Commonwealth Edison Co 83/05/18 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18548:204 24X
Fiche:50-000,83/05/18,8305240245

P Operating license stage documents & correspondence

8305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in PDR
FELTON,J M Division of Rules and Records, 83/03/29 BREADY,J C
KMC, Inc 1p 18505 230 24X Fiche 50-237,83/03/29,8305180316

--8305180328 Notifies of results of SEP review of facility,
DIRCKS,W J Office of the Executive Director for Operations
SECY-83-017 83/01/12 47pp 18505 246 24X
Fiche 50-237,83/03/29,8305180316

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305040446 Application for amend to Licenses DPR-19 & DPR-25,revising Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & requirement for isolation control rod drive pumps
RYBAK,B Commonwealth Edison Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18322 238. 24X
Fiche 50-237,83/05/02,8305040446

--8305040456 Proposed changes to Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & revise requirement for isolation control rod drive pumps to apply only to single rod scram testing
* Commonwealth Edison Co 83/05/02 2pp. 18322 240 24X
Fiche 50-237,83/05/02,8305040446

8305040488 Responds to 821221 & 830224 requests to withhold info submitted in connection w/application to change Tech Specs re Cycle 9 reload Request approved per 10CFR2.790(b)(5) Attachments 2 & 3 to 821221 & 830224 ltrs will be withheld.
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/02 FARRAR,D L
Commonwealth Edison Co 4pp 18319 266 24X Fiche,50-237,83/05/02, 8305040488

8305040520 Supplemental application for amend to Licenses DPR-19 & DPR-25,proposing changes to Tech Spec 4 3.B 1 b to verify nuclear response to control rod drive w/experienced uncoupling at power levels above 20%
RYBAK,B Commonwealth Edison Co. 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director. 2pp 18321 244 24X
Fiche 50-237,83/05/02,8305040520

--8305040524 Proposed Tech Spec 4 3.B.1 b (Page 56) requiring verification of nuclear response to control rod drive w/experienced uncoupling at power levels above 20%
* Commonwealth Edison Co 83/05/02. 3pp 18321 246 24X
Fiche 50-237,83/05/02,8305040520

8305040551 Application to amend Licenses DPR-19,DPR-25,DPR-29 & DPR-30,changing App A Tech Specs re economic generation control operation
RYBAK,B Commonwealth Edison Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18321:279 24X
Fiche:50-000,83/05/02,8305040551

--8305040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes
* Commonwealth Edison Co 83/05/02 1p 18321 281 24X
Fiche 50-000,83/05/02,8305040551

8305130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods,per 830420 ltr Operation w/RPS mod,installed per 10CFR50 59 & w/o Tech Specs,will not compromise safe operation of facilities
RYBAK,B Commonwealth Edison Co 83/05/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18439 330 24X
Fiche 50-000,83/05/06,8305130209

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130038 Responds to 830316 request for addl info re NUREG-0737,Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-01B
RYBAK,B Commonwealth Edison Co 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X
Fiche 50-000,83/05/10,8305130038

8305120370 Forwards Accident Evaluation Branch SER input re NUREG-0737, Item III D.3 4, "Control Room Habitability " Sys acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/11 FARRAR,D L
Commonwealth Edison Co 6pp 18432 295 24X Fiche 50-237,83/05/11,
8305120370

--8305120374 Advises that licensee proposed program re NUREG-0737,Item III.D 3 4, "Control Room Habitability," acceptable
MURPHY,D W Battelle Memorial Institute, Pacific Northwest Laboratory FIN D-2323 82/03/23 HULMAN,L,G Accident Evaluation Branch 2pp 18432 301 24X Fiche 50-237,83/05/11, 8305120370

8305200707 Forwards request for addl info on NUREG-0737,Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO,D B Operating Reactors Branch 2 83/05/11 FARRAR,D L
Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000,83/05/11,
8305200707

8305200186 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K 3 15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys
DIGGS,R.M. License Fee Management Branch 83/05/12 FARRAR,D L
Commonwealth Edison Co. 1p 18540 228 24X Fiche 50-000,83/05/12,
8305200186

8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment GE affidavit per 10CFR2 790 received Westinghouse affidavit forthcoming
RYBAK,B Commonwealth Edison Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director. 3pp 18490.347 24X
Fiche:50-000,83/05/13,8305180376

8305260290 Commits to resolution of three open items re NUREG-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable
RYBAK,B. Commonwealth Edison Co 83/05/19. DENTON,H R. Office of Nuclear Reactor Regulation, Director 1p 18625.354 24X
Fiche.50-237,83/05/19,8305260290

8305270419 Notifies that response to 830316,0510 & 11 requests for addl info re TMI Item II K 3 28, "Qualification of Automatic Depressurization Sys Accumulators," addressed in 830510 ltr
RYBAK,B. Commonwealth Edison Co 83/05/23 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 1p 18642 298 24X
Fiche:50-000,83/05/23,8305270419

8305310037 Advises that listed items re snubber action plan sent on 830520,per 830513 ltr Submittal of plan for checking for clamp interference during 62-day snubber insp deferred until 830603 to incorporate binding study results.
RYBAK,B Commonwealth Edison Co 83/05/24 KEPPLER,J G. Region 3, Office of Director 18pp. 18653 186 24X Fiche:50-237,83/05/24, 8305310037

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan
GILBERT,R.A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658:063. 24X
Fiche.50-000,83/05/26,8305310086

8305310028 Advises that requirements of NUREG-0737,Item II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved,per 821220 & 801215 submittals
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/27 FARRAR,D L
Commonwealth Edison Co 7pp 18653 213 24X Fiche 50-000,83/05/27,
8305310028

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8304040268 Requests that insp program re IE Bulletin 80-13, "Cracking in Core Spray Spargers," be performed every 3 yrs in conjunction w/reactor vessel internal insp No abnormalities noted per subj bulletin
RYBAK,B Commonwealth Edison Co 83/03/25 KEPPLER,J G Region 3, Office of Director 2pp 17816 282 24X Fiche 50-237,83/03/25,
8304040268

8305020467 Forwards IE Insp Repts 50-010/83-06,50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted
STREETER,J F Region 3, Office of Director 83/04/13 REED,C
Commonwealth Edison Co 2pp 18283 073 24X Fiche 50-010,83/04/13,
8305020467

--8305020480 IE Insp Repts 50-010/83-06,50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted Major areas inspected operational safety,maint,surveillance,licensee events,plant trips,refueling activities & refueling surveillance
TONGUE,T M , JORDAN,M J , STASEK,S Region 3, Office of Director 83/04/12 16pp 18283 075 24X Fiche 50-010,83/04/13,8305020467

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305100379 Forwards IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25,0301,09 & 14 & notice of violation
HIND,J A. Division of Radiological & Materials Safety Programs 83/04/22 REED,C Commonwealth Edison Co 2pp 18377 328 24X
Fiche 50-237,83/04/22,8305100379

--8305100387 Notice of violation from insp on 830222-25,0301,09 & 14
HIND,J A Region 3, Office of Director 83/04/22 2pp
18377 330 24X Fiche 50-237,83/04/22,8305100379

--8305100402 IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25,0301, 09 & 14 Noncompliance noted DOT radiation limits exceeded & failure to follow health physics procedures
PAUL,R A , LOVENDALE,P C , GREGER,L R. Region 3, Office of Director 83/04/21 12pp 18377 332 24X Fiche 50-237,83/04/22, 8305100379

--8305100416 IE Waste Packaging Insp Rept 15000046/83-03 on 830216 Noncompliance noted dose rate of 3 mrem/h existed in truck cab.
THOMAS,R D , BOOK,H E Region 3, Office of Director ELSEN,M J Washington, State of 83/02/28 4pp 18377 344. 24X
Fiche 50-237,83/04/22,8305100379

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25. Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020100 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04
SHAFER,W D Region 3, Office of Director 83/04/25 REED,C.
Commonwealth Edison Co. 1p 18278 243 24X Fiche 50-010,83/04/25,
8305020100.

DOCKETED ITEMS

8305020106 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 Corrective actions Amend 71 reissued & incorporated into Tech Specs Corporate QA dept will audit accounting & followup sys
FARRAR, D L Commonwealth Edison Co 83/03/30 KEPPLER, J G
Region 3, Office of Director 3pp 18278 244 24X
Fiche 50-010, 83/04/25, 8305020100

05120440 Forwards IE Insp Rept 50-237/83-03 on 830111-0324 & notice of violation
LITTLE, W S Region 3, Office of Director 83/04/25 REED, C
Commonwealth Edison Co. 2pp 18431 091 24X Fiche 50-237, 83/04/25, 8305120440

8305120444 Notice of violation from insp on 830111-0324
LITTLE, W S Region 3, Office of Director 83/04/25 1p
18431 093 24X Fiche 50-237, 83/04/25, 8305120440

8305120449 IE Insp Rept 50-237/83-03 on 830111-0324 Noncompliance noted failure to control recirculation riser pipe weld rod stub, unused rod & unused rolls of E308L-16 stainless steel wire
KEY, W J., DANIELSON, D H Region 3, Office of Director 83/04/21
11pp 18431:094 24X Fiche 50-237, 83/04/25, 8305120440.

03040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

103040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382.165. 24X Fiche 50-000, 83/04/28, 8303040027

105060441 Confirms plans to meet w/util on 830505 in Glen Ellyn, IL to discuss status of actions taken re 830317 confirmatory action ltr concerning main steam line snubbers
NORELIUS, C E Division of Project & Resident Programs 83/04/28
REED, C Commonwealth Edison Co 1p 18343.147 24X
Fiche: 50-237, 83/04/28, 8305060441

05100092 Provides status of safe shutdown path support installation, per IE Bulletin 79-14 & util 830416 commitment Remaining accessible hanger & four inaccessible hangers will be completed by mid-May & during Fall 1983 outages, respectively
RYBAK, B Commonwealth Edison Co 83/04/28 KEPPLER, J G Region 3, Office of Director 2pp 18377 218 24X Fiche 50-237, 83/04/28, 8305100092

305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO, C J Region 3, Office of Director 83/04/29 REED, C.
Commonwealth Edison Co 2pp 18297 137. 24X Fiche 50-010, 83/04/29, 8305030336

-8305030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29 2pp 18297 139 24X
Fiche: 50-010, 83/04/29, 8305030336

303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

305100181 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24
SHAFER, W D. Region 3, Office of Director 83/05/03 REED, C
Commonwealth Edison Co. 1p. 18374 318 24X Fiche 50-010, 83/05/03, 8305100181.

-8305100190 Responds to NRC 830311 ltr re deficiencies noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24 Corrective actions written agreement, EPIP200-11 re RMF for Units 2 & 3 between Corps of Engineers & util to be revised
RYBAK, B Commonwealth Edison Co 83/04/11 KEPPLER, J G Region 3, Office of Director 4pp 18374 319 24X Fiche 50-010, 83/05/03, 8305100181.

303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc 112pp. 18382.282 24X Fiche 50-000, 83/05/04, 8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248. 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp. 18524·003 24X Fiche 50-000, 83/05/11, 8303040034.

8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14, piping analysis to restore hot shutdown path piping sys to FSAR requirements by 830215, acceptable.
SPEBBARD, R L Division of Engineering 83/05/18 REED, C
Commonwealth Edison Co. 2pp 18517 116. 24X Fiche. 50-000, 83/05/18, 8305200421

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697.009. 24X Fiche· 50-000, 83/05/19, 8303040040

8305250377 Forwards "GE-NEBB Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B . "
RYBAK, B Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2, 118pp 18578 001 24X
Fiche: 50-000, 83/05/19, 8305250377

--8305250393 "GE-NEBB Electrical Penetration Assembly Qualification Program "
* Bechtel Corp. 83/05/18. 356pp 18578.175 24X
Fiche 50-000, 83/05/19, 8305250377.

--8305250399 Rev 2 to Vols 1 & 2 to "Environ Qualification of Electrical Equipment, Dresden Nuclear Power Station Unit 2 "
* Bechtel Corp 83/05/31. 416pp 18579 171. 24X
Fiche: 50-000, 83/05/19, 8305250377

--8305250407 Rev 2 to Vols 1 & 2 to "Response to IE Bulletin 79-01B for Dresden Nuclear Power Station Unit 3 "
* Bechtel Corp 83/05/31 387pp. 18580.226 24X
Fiche, 50-000, 83/05/19, 8305250377

--8305250413 Rev 2 to Vols 1-3 to "Response to IE Bulletin 79-01B, Quad Cities Nuclear Power Station Units 1 & 2 "
* Bechtel Corp. 83/05/31 786pp. 18581:253 24X
Fiche· 50-000, 83/05/19, 8305250377

8305270395 Notifies that work to be performed on masonry walls, per IE Bulletin 80-11, "Masonry Wall Design," will be completed on 830715. Thirty masonry walls required mods
RYBAK, B Commonwealth Edison Co. 83/05/23 KEPPLER, J G Region 3, Office of Director 1p 18642.335 24X Fiche· 50-237, 83/05/23, 8305270395.

8305310113 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-237/83-03.
LITTLE, W S Region 3, Office of Director 83/05/24 REED, C.
Commonwealth Edison Co. 1p. 18658:070. 24X Fiche 50-237, 83/05/24, 8305310113.

--8305310117 Responds to NRC 830425 ltr re violations noted in IE Insp Rept 50-237/83-03 Corrective actions: uncontrolled welding matls disposed of & personnel instructed re control of welding matls
FARRAR, D.L Commonwealth Edison Co 83/05/19. KEPPLER, J G
Region 3, Office of Director. 2pp. 18658.071 24X
Fiche 50-237, 83/05/24, 8305310113.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc 114pp. 18647 007 24X Fiche. 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305130197 Forwards monthly operating rept for Apr 1983
SCOTT, D J Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement 1p 18440 050 24X Fiche 50-237, 83/05/02, 8305130197

--8305130202 Monthly operating rept for Apr 1983
SCHROEDER, B A Commonwealth Edison Co 83/05/02 18pp 18440 051 24X Fiche 50-237, 83/05/02, 8305130197

B Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
BEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J. Reactor Operations Analysis Branch. 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573

8305060511 Forwards updated LER 83-008/01X-1
SCOTT, D J Commonwealth Edison Co 83/04/25 KEPPLER, J G Region 3, Office of Director 1p 18348 083 24X Fiche 50-237, 83/04/25, 8305060511

--8305060517 Updated LER 83-008/01X-1 on 830115, during inservice insp of recirculation piping, rejectable indications discovered in 10 circumferential welds Caused by intergranular stress corrosion cracking Welds will be examined at mid-cycle
HYLKA, R Commonwealth Edison Co 83/04/25 Region 3, Office of Director 12pp 18348 084 24X Fiche 50-237, 83/04/25, 8305060511

8305060416 Forwards LER 83-024/03L-0
SCOTT, D J Commonwealth Edison Co 83/04/26 KEPPLER, J G Region 3, Office of Director 1p 18343 190 24X Fiche 50-237, 83/04/26, 8305060416

--8305060422 LER 83-024/03L-0. on 830403, while performing core spray operability test, valve MO 1402-4A failed to open Caused by burned out motor Motor replaced
ANANDAPPA, A Commonwealth Edison Co 83/04/26 Region 3, Office of Director. 2pp 18343 191 24X Fiche. 50-237, 83/04/26, 8305060416

8305060590 Forwards LER 83-022/03L-0
SCOTT, D J Commonwealth Edison Co. 83/04/27 KEPPLER, J. G. Region 3, Office of Director. 1p. 18349 011 24X Fiche 50-237, 83/04/27, 8305060590.

--8305060599 LER 83-022/03L-0. on 830403, during refuel outage, no position indication found for core spray injection valve MO 1402-25B Valve would not open Caused by one phase of breaker tripping before design overload reached.
ANANDAPPA, A Commonwealth Edison Co 83/04/27 Region 3, Office of Director 2pp 18349 012 24X Fiche 50-237, 83/04/27, 8305060590

8305060603 Forwards LER 83-023/03L-0
SCOTT, D J Commonwealth Edison Co. 83/04/27 KEPPLER, J G. Region 3, Office of Director 1p. 18348 247 24X Fiche 50-237, 83/04/27, 8305060603

--8305060611 LER 83-023/03L-0 on 830406, during surveillance of component cooling svc water vault floor drain (DDS 4400-1), condensate pump room flood switch actuated & drain valve AO-2-4999-74 failed to close. Cause undetermined. Investigation underway
COYLE, L. M Commonwealth Edison Co. 83/04/27 Region 3, Office of Director. 2pp 18348 248. 24X Fiche 50-237, 83/04/27, 8305060603.

8305060486 Forwards LER 83-029/01T-0
SCOTT, D. J. Commonwealth Edison Co 83/04/29 KEPPLER, J. G. Region 3, Office of Director. 1p 18348 149 24X Fiche 50-237, 83/04/29, 8305060486

--8305060492 LER 83-029/01T-0 on 830418, air leaks found at actuating arms for six torus-to-drywell vacuum breakers Caused by failure of vacuum breaker actuating arm seals All seals replaced w/ improved design. No further leakage problems observed
WHALEN, R. J Commonwealth Edison Co 83/04/29 Region 3, Office of Director 4pp 18348 150 24X Fiche 50-237, 83/04/29, 8305060486

8305170134 Forwards LER 83-025/03L-0
SCOTT, D J Commonwealth Edison Co 83/05/04 KEPPLER, J G Region 3, Office of Director 2pp 18466 267 24X Fiche 50-237, 83/05/04, 8305170134

--8305170140 LER 83-025/03L-0 on 830409, reactor bldg fuel pool channel A high radiation alarm activated, causing reactor bldg vent sys to trip Caused by burned out relay coil Relay coil replaced
MERRITT, S Commonwealth Edison Co 83/05/04 Region 3, Office of Director 1p 18466 269 24X Fiche 50-237, 83/05/04, 8305170134

8305240202 Updated LER 83-011/01X-1 on 830203, NDT performed on new fillet weld Crack found between torus shell & ring girder separating bays 8 & 9 Cause not determined Flaw removed by grinding & filled w/hydrogen electrode deposit W/830504 ltr
TANGHEE, D , SCOTT, D J Commonwealth Edison Co 83/05/04
KEPPLER, J G Region 3, Office of Director 4pp 18548 027 24X Fiche 50-237, 83/05/04, 8305240202

8305170159 Forwards LER 83-027/03L-0
SCOTT, D J Commonwealth Edison Co 83/05/05 KEPPLER, J G Region 3, Office of Director 2pp 18466 294 24X Fiche 50-237, 83/05/05, 8305170159

--8305170163 LER 83-027/03L-0 on 830408, during valve insp, grease discovered on seats & discs Caused by maint procedures not prohibiting personnel placing grease on seat & disc Grease removed, valves repaired & procedures will be revised
STACHNIAK, R Commonwealth Edison Co 83/05/05 Region 3, Office of Director 3pp 18466 296 24X Fiche 50-237, 83/05/05, 8305170159

8305240207 LER 83-026/03L-0 on 830412, during refueling outage, snubber 52 failed during test required to return snubber to store room Cause unknown Investigation underway W/830510 ltr
RHEE, S , SCOTT, D J Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 3pp 18548 016 24X Fiche 50-237, 83/05/10, 8305240207

8305240494 LER 83-028/03L-0 on 830417, during refueling, Channel B fuel pool radiation monitor downscale alarm received Alarm could not be reset Caused by burned out coil in relay 1705-10B Relay replaced w/spare W/830510 ltr
MERRITT, S , SCOTT, D J Commonwealth Edison Co 83/05/10
KEPPLER, J G Region 3, Office of Director 3pp 18571 176 24X Fiche 50-237, 83/05/10, 8305240494

8305240335 LER 83-030/03L-0 on 830421, 24-volt low voltage power supply failed, causing channel A isolation condensor vent monitor, reactor bldg vent & fuel pool area radiation monitor to move downscale Caused by bad voltage regulator W/830511 ltr
MERRITT, S , SCOTT, D J Commonwealth Edison Co. 83/05/11
KEPPLER, J G Region 3, Office of Director 3pp 18574 082 24X Fiche 50-237, 83/05/11, 8305240335

8305200295 Forwards 7-day evaluation, out-of-plant test results & action plan re main steam line snubber failures Investigation of clamp interference & possibility of thermal growth continuing
RYBAK, B Commonwealth Edison Co 83/05/13 KEPPLER, J G Region 3, Office of Director 3pp 18516 324 24X Fiche 50-237, 83/05/13, 8305200295

--8305200301 "Dresden-2 Main Steam Monitoring Procedure 7-Day Data Evaluation "
* Sargent & Lundy, Inc EMD-043449 83/05/09 40pp 18516 327 24X Fiche 50-237, 83/05/13, 8305200295

--8305200307 "Preliminary Test Rept on Dynamic Testing of Dresden 2 Mechanical Pipe Snubbers "
NOTHELFER, T , PLUMMER, M C NUTECH Engineers, Inc * Commonwealth Edison Co CDM058 0011 0007 83/05/11 18pp 18517 004 24X Fiche. 50-237, 83/05/13, 8305200295

8305310182 LER 83-032/03L-0 on 830425, during unit startup, reactor water sample not pulled every 4 h per Tech Spec requirements Caused by lack of communication between technicians during shift change & failure to use flashing sign. W/830517 ltr
TURNQUEST, L , SCOTT, D J Commonwealth Edison Co 83/05/17
KEPPLER, J G. Region 3, Office of Director 3pp 18658. 168 24X Fiche 50-237, 83/05/17, 8305310182

8305310149 LER 83-033/03L-0 on 830426, during testing of MSIV 1D & 2D, half scram occurred on reactor protection sys. Caused by failure of scram interlock contact of limit switch to reset after valve 1B tested Switch adjusted W/830518 ltr
BEVERLY, K , SCOTT, D J Commonwealth Edison Co 83/05/18
KEPPLER, J G. Region 3, Office of Director 3pp. 18659 141 24X Fiche 50-237, 83/05/18, 8305310149

8305310165 LER 83-041/03L-0 on 830506, calibr of drywell pressure switch DIS 1500-4, relay 1530-299 failed to pick up when pressure switch 1301-620 functionally tested Caused by loose connection in wiring circuitry W/830520 ltr
CHRISTEL, B , SCOTT, D J Commonwealth Edison Co 83/05/19
KEPPLER, J G Region 3, Office of Director 3pp 18652 287 24X
Fiche 50-237, 83/05/19, 8305310165

8305310158 LER 83-038/03L-0 on 830505, average power range monitor (APRM) 4 flow biased rod block setpoint found in excess of Tech Spec limit Caused by instrument drift APRM 4 adjusted per Procedure DIS-700-6 W/830520 ltr
BEVERLY, K P , SCOTT, D J Commonwealth Edison Co 83/05/20
KEPPLER, J G Region 3, Office of Director 3pp 18651 224 24X
Fiche 50-237, 83/05/20, 8305310158

DOCKET 50-238 NUCLEAR SHIP SAVANNAH

R Periodic operating reports & related correspondence

8305060577 Forwards semiannual survey repts for 820317-18 & 0916, per Amend 10 to License NS-1 Info contains TLD monitoring badge locations, direct radiation survey, contamination survey results & environ sample analysis rept
QUERRY, J E South Carolina, State of 83/02/28 NRC - No Detailed Affiliation Given 3pp 18347 257 24X
Fiche 50-238, 83/02/28, 8305060577

--8305060582 "Semiannual Survey Rept "
* South Carolina, State of 82/03/18 14pp 18347 260 24X
Fiche 50-238, 83/02/28, 8305060577

--8305060586 "Semiannual Survey Rept "
* South Carolina, State of 82/09/16 9pp 18347, 274 24X
Fiche 50-238, 83/02/28, 8305060577

--8305060613 "Procedure for Testing Controlled Radiation Area Intrusion Alarm "
WALDRUP, U South Carolina, State of 82/12/02 9pp 18347 283
24X Fiche 50-238, 83/02/28, 8305060577

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8304270278 Requests that Rev 8 to security plan be modified to incorporate commitments re frequency of alarm station emergency power annunciator sys tests Resubmittal within 30 days requested
ALLAN, J M Region 1, Office of Director 83/04/21 MAIER, J E
Rochester Gas & Electric Corp 3pp 18232 287 24X
Fiche 50-244, 83/04/21, 8304270278

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G. Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180361 Notification of 830518 meeting w/Westinghouse in Bethesda, MD to discuss NRC review of safety parameter display sys for emergency response facility design & V & V process.
DICK, G.F Operating Reactors Branch 5 83/05/16 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp 18485 223 24X
Fiche: 50-244, 83/05/16, 8305180361

8305310218 Forwards revised Page 3, 6, modifying Rev 18 to security plan re testing frequency of emergency power annunciation sys
Page withheld (ref 10CFR73 21).
MAIER, J E Rochester Gas & Electric Corp 83/05/19 ALLAN, J M
Region 1, Office of Director 1p 18658 148 24X
Fiche: 50-244, 83/05/19, 8305310218

8305270077 Advises that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," complete
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/25, MAIER, J E
Rochester Gas & Electric Corp 3pp 18638 153 24X
Fiche: 50-244, 83/05/25, 8305270077

J. Insurance & indemnity information

8305120110 Forwards Endorsement 86 to NELIA Policy NF-170 & Endorsement 72 to MAELU Policy MF-46.
SINIBI, J M Marsh & McLennan, Inc 83/05/05 SALTZMAN, J D,
Assistant Director for State & Licensee Relations 3pp. 18428, 257,
24X Fiche 50-244, 83/05/05, 8305120110.

O Advisory Committee on Reactor Safeguards reports & correspondence

8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards 83/05/05
ACRS - Advisory Committee on Reactor Safeguards 529pp 18458 225
24X Fiche 50-000, 83/05/05, 8305130290

P Operating license stage documents & correspondence

8305030021 Forwards "Structural Reanalysis Program for RE Ginna Nuclear Power Plant," per SEP Topics II-2 A, III-2, III-4 A & III-7 B
Final design expected to require 18-24 months Final installation expected to require 2 to 2-1/2 yrs
MAIER, J E Rochester Gas & Electric Corp 83/04/22 CRUTCHFIELD, D
Operating Reactors Branch 5. 2pp 18300 128 24X
Fiche 50-244, 83/04/22, 8305030021

--8305030024 "Structural Reanalysis Program for RE Ginna Nuclear Power Plant "
* Rochester Gas & Electric Corp 83/04/22 38pp 18300 130
24X Fiche 50-244, 83/04/22, 8305030021

8305030352 Submits addl info re proposed tubesheet sleeve design, per request Info addresses inspectability, pullout & corrosion potential Fifty tubesheet sleeves will be installed during present refueling outage, per 830420 ltr.
MAIER, J E Rochester Gas & Electric Corp 83/04/26 CRUTCHFIELD, D.
Operating Reactors Branch 5 3pp 18297 099 24X
Fiche 50-244, 83/04/26, 8305030352

8305020060 Forwards info re blocking of safety injection signal during cooldown based on review of PWRs using improper procedure
Response requested within 30 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/04/28 MAIER, J E.
Rochester Gas & Electric Corp 4pp 18279 102 24X
Fiche 50-244, 83/04/28, 8305020060

8305020499 Approves installation of containment closure device to provide containment isolation barrier during refueling activities per 830218 ltr
CRUTCHFIELD, D Operating Reactors Branch 5 83/04/29 MAIER, J E.
Rochester Gas & Electric Corp 2pp 18282 296 24X
Fiche 50-244, 83/04/29, 8305020499

8305060271 Forwards "Containment Vessel Evaluation of Dome Liner & Studs," re SEP Topic III-7.B, "Load Combinations (Containment Liner Analysis) "
MAIER, J E Rochester Gas & Electric Corp 83/04/28 CRUTCHFIELD, D.
Operating Reactors Branch 5 1p. 18344 332 24X
Fiche 50-244, 83/04/28, 8305060271

--8305060277 "Containment Vessel Evaluation of Dome Liner & Studs "
FULTON, J F , HERR, J C , CHEN, C Gilbert/Commonwealth Cos.
83/04/15 51pp 18344 333 24X Fiche 50-244, 83/04/28, 8305060271.

8305060404 Forwards list of safety-related masonry walls per SEP Topics II-2 A, III-2, III-4 A & III-7 B, "Structural Reanalysis Program - Block Walls "
MAIER, J E Rochester Gas & Electric Corp. 83/04/28 CRUTCHFIELD, D.
Operating Reactors Branch 5 3pp 18343 187 24X
Fiche 50-244, 83/04/28, 8305060404

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305130084 Responds to Q Dick & M Wigdon 820301 telcon re fuse coordination on control circuit for level control valve 427
RA Baker 830415 & 19 summaries justifying proper fuse coordination encl
MAIER, J E Rochester Gas & Electric Corp 83/05/02 CRUTCHFIELD, D
Operating Reactors Branch 5 3pp. 18436 266 24X
Fiche: 50-244, 83/05/02, 8305130084

--8305130086 "Level Control Valve 427 Fuse Coordination - Ginna Station "
BRICKB, G , MANLEY, J Rochester Gas & Electric Corp 0383-03
83/04/15. 4pp 18436 269. 24X Fiche 50-244, 83/05/02, 8305130084

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc. 16pp 18627 153 24X
Fiche. 50-000, 83/05/09, 8305090659

8305110426 Notification of 830512 meeting w/util in Bethesda,MD to discuss ongoing steam generator tube sleeving program
DICK,G F Operating Reactors Branch 5 83/05/10 CRUTCHFIELD,D
Operating Reactors Branch 5 2pp 18392 014 24X
Fiche 50-244,83/05/10,8305110426

8305180340 Notification of 830520 meeting w/util in Bethesda,MD to discuss results of tube sleeving Portions of meeting, including discussion of proprietary info,will be closed
DICK,G F Operating Reactors Branch 5 83/05/17 CRUTCHFIELD,D
Operating Reactors Branch 5 3pp 18486 057 24X
Fiche 50-244,83/05/17,8305180340

8305310085 Responds to 10CFR50 49,"Environ Qualification of Electrical Equipment " Status of review contained in 821213 SER Equipment analysis,test,design & procurement may delay establishing final environ qualification by end of 1984
MAIER,J E Rochester Gas & Electric Corp 83/05/19 CRUTCHFIELD,D
Operating Reactors Branch 5 2pp 18655 074 24X
Fiche 50-244,83/05/19,8305310085

8305310125 Forwards Apps A,B,C & D to structural reanalysis program re SEP Topics II-2 A,III-2,III-4 A & III-7 B transmitted by 830422 correspondence
MAIER,J E Rochester Gas & Electric Corp 83/05/19 CRUTCHFIELD,D
Operating Reactors Branch 5 1p 18658 171 24X
Fiche 50-244,83/05/19,8305310125

--8305310133 App A to structural reanalysis program, "Evaluation Rept for NRC SEP Topics II-2 A, 'Severe Weather Phenomena,' III-2, 'Wind & Tornado Loading' & III-7 B, 'Design Codes,Design Criteria & Load Combinations '"
* Rochester Gas & Electric Corp 83/03/31 85pp 18658 172
24X Fiche 50-244,83/05/19,8305310125

--8305310141 App B to structural reanalysis program, "Criticality Analysis for Spent Fuel Storage Racks "
* Pickard, Lowe & Garrick, Inc 83/03/31 5pp 18658 257 24X
Fiche 50-244,83/05/19,8305310125

--8305310157 App C to structural reanalysis program, "Utility Pole Tornado Missile Trajectory Analysis "
TWISDALE,L A , DUNN,W L Applied Research Associates, Inc
83/03/08 23pp 18658,262 24X Fiche 50-244,83/05/19,8305310125

--8305310159 App D to structural reanalysis program, "Uniform Load Test on Wall Panels" & "Physical Testing of Fasteners "
* Pittsburgh Testing Laboratory 83/03/03 112pp 18658 285
24X Fiche.50-244,83/05/19,8305310125

8305310020 Forwards two oversize drawings to assist in review of safety injection & auxiliary cooling sys,in response to NRC request Aperture cards are available in PDR
MAIER,J E Rochester Gas & Electric Corp 83/05/20 CRUTCHFIELD,D
Operating Reactors Branch 5 1p 18655 126 24X
Fiche 50-244,83/05/20,8305310020

8305310232 Submits addl info re potential effects of flood levels from Deer Creek in excess of std project flood,per SEP Topic II-3.B Additional cost of mod to meet PMF unwarranted
MAIER,J E. Rochester Gas & Electric Corp. 83/05/20 CRUTCHFIELD,D
Operating Reactors Branch 5 3pp 18658 084 24X
Fiche 50-244,83/05/20,8305310232

8305260237 Summary of 830512 site meeting w/util re steam generator sleeving program Sleeving mods adequate pending formal submittal of mod procedures,review of insp results & stress analysis Next meeting scheduled for 830520
DICK,G.F Operating Reactors Branch 5 83/05/24 Operating Reactors Branch 5 11pp 18622 076 24X Fiche 50-244,83/05/24,8305260237

8305270060 Forwards safety evaluation of util response to SER, NUREG-0916,Item 3 re effluent radioactivity monitoring sys alarm setpoints & surveillance requirements.Monitoring sys acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/26 MAIER,J.E.
Rochester Gas & Electric Corp 4pp. 18638 333 24X
Fiche:50-244,83/05/26,8305270060

--8305270071 Safety evaluation supporting licensee corrective actions subsequent to 820125 steam generator tube rupture Main steam & air ejector radiation monitoring sys acceptable
* Office of Nuclear Reactor Regulation, Director. 83/05/26 4pp
18638:337. 24X Fiche.50-244,83/05/26,8305270060

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305040547 Requests remittance of Class III fee for Div of Licensing approval of 820115 application for rev to inservice insp program,deleting 25 sleeve limit per steam generator insp
DIGGS,R M License Fee Management Branch 83/04/27 MAIER,J E
Rochester Gas & Electric Corp 1p 18351 231 24X
Fiche 50-244,83/04/27,8305040547

8305050246 Ack receipt of 830111 & 0224 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/82-23 Item C of notice of violation re spent fuel storage grid map rescinded
MARTIN,T T Division of Engineering & Technical Programs 83/04/27
MAIER,J E Rochester Gas & Electric Corp 2pp 18337 335 24X
Fiche 50-244,83/04/27,8305050246

--8305050248 Responds to NRC 821213 ltr re Item 5 e 3 noted in IE Insp Rept 50-244/82-23 Spent fuel storage grid map correctly shows spent fuel assembly in Location A-17 Reevaluation of item requested
MAIER,J E Rochester Gas & Electric Corp 83/02/24 MARTIN,T T
Division of Engineering & Technical Programs 1p 18337 337 24X
Fiche 50-244,83/04/27,8305050246

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305110065 Forwards fee for review of application proposing inservice insp program rev to delete 25 sleeve limitation per steam generator insp,in response to 830427 request
MAIER,J E Rochester Gas & Electric Corp 83/05/05 DIGGS,R M
License Fee Management Branch 2pp 18409 012 24X
Fiche 50-244,83/05/05,8305110065

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250438 Forwards IE Insp Rept 50-244/83-05 on 830301-0407 & notices of deviation & violation Enforcement action considered for failure to perform adequate post-maint test of containment personnel hatch
STAROSTECKI,R Division of Project & Resident Programs 83/05/12
MAIER,J E Rochester Gas & Electric Corp 2pp 18585 214 24X
Fiche 50-244,83/05/12,8305250438

--8305250441 Notice of violation from insp on 830301-31
* Region 1, Office of Director 83/05/12 1p 18585 216 24X
Fiche 50-244,83/05/12,8305250438

--8305250446 Notice of deviation from insp on 830301-31
* Region 1, Office of Director 83/05/12 2pp 18585 217 24X
Fiche 50-244,83/05/12,8305250438

--8305250453 IE Insp Rept 50-244/83-05 on 830301-0407 Noncompliance noted failure to perform post-maint testing,to perform safety analysis for proposed mod & to implement commitments re corrective actions for previously missed surveillance
ZIMMERMAN,R P , BAUNACK,W H Region 1, Office of Director
KISTER,H B Division of Project & Resident Programs 83/04/26
9pp 18585 219 24X Fiche 50-244,83/05/12,8305250438

8305190440 Discusses NDE support to Task Order 5-83,which H Conrad requested CV Dodd to undertake re steam generator eddy current insp Evaluation of effectiveness of insp techniques to identify intergranular attack planned
FRANK,L Materials Engineering Branch FIN B-0775-3 83/05/13
MCCLUNG,R W Oak Ridge National Laboratory 1p 18523 168 24X
Fiche 50-244,83/05/13,8305190440

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270571 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-244/83-03
STAROSTECKI,R. Division of Project & Resident Programs 83/05/19
MAIER,J E Rochester Gas & Electric Corp 1p 18644 355 24X
Fiche 50-244,83/05/19,8305270571

--8305270578 Responds to NRC 830323 ltr re violations noted in IE Insp Rept 50-244/83-03 Corrective actions calculation based on isotopic analysis & monthly releases will be performed for period since initiation of B steam generator leak test.
MAIER,J E Rochester Gas & Electric Corp 83/04/22 ALLAN,J M
Region 1, Office of Director 3pp 18644 356 24X
Fiche 50-244,83/05/19,8305270571

8305260237 Summary of 830512 site meeting w/util re steam generator sleeving program Sleeving mods adequate pending formal submittal of mod procedures,review of insp results & stress analysis Next meeting scheduled for 830520
DICK,G F Operating Reactors Branch 5 83/05/24 Operating Reactors Branch 5 11pp 18622 076 24X Fiche 50-244,83/05/24,8305260237

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305240510 Forwards "RE Ginna Nuclear Power Plant,1982 Evaluation "
BRUNNER,E J Division of Engineering & Technical Programs, 83/05/06 TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) CASE,E.G Office of Nuclear Reactor Regulation, Director 1p 18571 274 24X Fiche 50-244,83/05/06,8305240510.

--8305240519 "RE Ginna Nuclear Power Plant 1982 Evaluation," conducted during wks of 820531 & 0607
* Institute of Nuclear Power Operations 83/05/06 41pp
18571.275 24X Fiche.50-244,83/05/06,8305240510

S Reportable occurrences, LERs & related correspondence

8305230526 LER 83-013/01T-0 results of multi-frequency eddy current exam of steam generator A inlet & outlet revealed no tubes w/indications above plugging limit Twenty-three tubes w/ intergranular attack indications found in generator B
SNOW,B A Rochester Gas & Electric Corp 83/04/19 ALLAN,J M
Region 1, Office of Director 1p 18537 341 24X
Fiche 50-244,83/04/19,8305230526

8305110318 Forwards LER 83-014/03L-0
MAIER,J E Rochester Gas & Electric Corp 83/04/25 ALLAN,J M
Region 1, Office of Director 1p 18406 075 24X
Fiche 50-244,83/04/25,8305110318

--8305110328 LER 83-014/03L-0 on 830329,during refueling calibr,certain steam generator level transmitter outputs shifted low by 2 to 2 5% of span.Caused by instrument drift Transmitters recalibr
EDGAR,E C Rochester Gas & Electric Corp 83/04/25 Region 1, Office of Director 1p 18406 076 24X Fiche 50-244,83/04/25, 8305110318

8305230561 Forwards LER 83-015/03L-0
MAIER,J E Rochester Gas & Electric Corp 83/04/29 ALLAN,J M
Region 1, Office of Director 1p 18537 094 24X
Fiche.50-244,83/04/29,8305230561

--8305230564 LER 83-015/03L-0 on 830412,RHR pump manually tripped following loss of RHR on hot leg of loop Caused by leak in steam generator A temporary cold leg nozzle isolation device,allowing air in RCS & RHR suction line
LARIZZA,G F Rochester Gas & Electric Corp 83/04/29 Region 1, Office of Director 3pp 18537 095 24X Fiche 50-244, 83/04/29,8305230561

8305160114 Forwards LER 83-013/01T-0
MAIER,J E Rochester Gas & Electric Corp 83/05/03 ALLAN,J M.
Region 1, Office of Director 1p 18450 348 24X
Fiche 50-244,83/05/03,8305160114

--8305160119 LER 83-013/01T-0 on 830419,23 tubes in steam generator inlet B showed tube sheet crevice intergranular attach indication above 40% through wall defect Caused by caustics &/or alkaline earth concentrations Tubes sleeved or plugged
MEYER,T A Rochester Gas & Electric Corp 83/05/03 Region 1, Office of Director 2pp. 18450 349 24X Fiche 50-244,83/05/03, 8305160114

8305190170 Forwards LER 83-016/03L-0
MAIER,J E Rochester Gas & Electric Corp 83/05/06 ALLAN,J.M
Region 1, Office of Director 1p. 18502 216 24X
Fiche 50-244,83/05/06,8305190170

--8305190175 LER 83-016/03L-0.on 830418,during maint,pinhole leak discovered on boric acid transfer sys branch connection off boric acid filter outlet.Caused by intergranular attack due to stress corrosion cracking Piping will be replaced.
SCHULER,T R Rochester Gas & Electric Corp 83/05/06 Region 1, Office of Director 2pp 18502 217 24X Fiche 50-244, 83/05/06,8305190170

8305190234 Forwards LER 82-028/03L-0
MAIER,J E Rochester Gas & Electric Corp 83/05/06 ALLAN,J M.
Region 1, Office of Director 1p 18501 315 24X
Fiche 50-244,83/05/06,8305190234

--8305190238 LER 82-028/03L-0 on 821219,while performing nitrogen makeup to accumulator & charging RCS overpressurization sys nitrogen,containment isolation valve AOV-846 opened & closed sluggishly Caused by matl in plug Seat replaced
SCHULER,T.R Rochester Gas & Electric Corp 83/05/06 Region 1, Office of Director 2pp 18501 316 24X Fiche 50-244, 83/05/06,8305190234

8305230452 Forwards LER 83-012/03L-1
MAIER,J E Rochester Gas & Electric Corp 83/05/06. ALLAN,J.M
Region 1, Office of Director 1p 18537 349. 24X
Fiche 50-244,83/05/06,8305230452

--8305230458 LER 83-012/03L-1 on 830323,individual doors for personnel hatch had higher leak rate than allowed Caused by incorrect maint procedure on 821007 requiring only door seal leak testing Procedure revised.Other procedures reviewed
SPECTOR,S M Rochester Gas & Electric Corp 83/05/06 Region 1, Office of Director 23pp 18537.350 24X
Fiche.50-244,83/05/06,8305230452.

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305040022 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18330 065 24X Fiche 50-245, 83/04/25, 8305040022

--8305040034 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/12 EISENHUT, D G Division of Licensing 2pp 18330 066 24X Fiche 50-245, 83/04/25, 8305040022

--8305040039 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 300pp 18330 068 24X Fiche 50-245, 83/04/25, 8305040022

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180853 Authorizes refund for review of 821230 & 830408 requests from revised schedule for conducting emergency exercise
MILLER, W O License Fee Management Branch 83/05/11 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 18506, 030 24X Fiche 50-000, 83/05/11, 8305180853

8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1 Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/13 COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18452 349 24X
Fiche 50-000, 83/05/13, 8305160022

8305230323 Forwards emergency procedures generation package containing procedure guidelines, writers guide & training program in response to NUREG-0737, Suppl 1 (Generic Ltr 82-33), "Requirements for Emergency Response Capability "
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/13
CRUTCHFIELD, D. Operating Reactors Branch 5 1p 18538 264 24X
Fiche 50-245, 83/05/13, 8305230323

--8305230330 "Emergency Procedure Guidelines "
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/13. 55pp 18538 265 24X Fiche 50-245, 83/05/13, 8305230323

--8305230338 Rev 26 to ACP-QA-3 02, "Millstone Point Generating Station Writers Guide for Emergency Operating Procedure "
* Northeast Nuclear Energy Co. (subs of Northeast Utilities) 83/05/13 47pp 18538 321 24X Fiche 50-245, 83/05/13, 8305230323

I. Financial information

8305020093 Forwards "Annual Rept of Electric Utils, Licensees & Others (Class A & Class B)," FERC Form 1
BISHOP, R.W. Northeast Utilities. 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279 109 24X
Fiche. 50-245, 83/04/26, 8305020093

J Insurance & indemnity information

8305120156 Forwards Endorsements 87 & 78 to NELIA Policy NF-173 & MAELU Policy MF-72, respectively
BINISI, J.M. Marsh & McLennan, Inc 83/05/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 3pp 18427 153 24X Fiche 50-245, 83/05/05, 8305120156

P Operating license stage documents & correspondence

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24X
Fiche 50-000, 83/03/11, 8305240249

8305230616 Forwards info in response to 830208 ltr requesting backfit cost data for operating nuclear units Cost categorized according to NRC imposed, TMI & non-TMI backfits, util-initiated & hybrid backfits
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 83/03/21 TOURTELLOTTE, J Regulatory Reform Task Force 25pp 18543 038 24X
Fiche 50-000, 83/03/21, 8305230616

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON, J M Division of Rules and Records 83/03/31 SHOLLY, S C Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000, 83/03/31, 8305240254

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305160188 Advises that action required by 830126 Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & Generic Ltr 83-07 complete, based on util negotiations w/DOE re disposal of high level waste or spent nuclear fuel
CLARK, R A Operating Reactors Branch 3 83/04/20 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 18462 355 24X
Fiche 50-000, 83/04/20, 8305160188

8305030620 Forwards addl info re containment leak rate continuous monitoring, in response to NRC 830121 request W/4 oversize drawings & 7 aperture cards Aperture cards are available in PDR
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/04/26
CRUTCHFIELD, D Operating Reactors Branch 5. 5pp 18302 327 24X
Fiche 50-245, 83/04/26, 8305030620

--8305030624 Rev 1 to SP 639 1, "Primary Containment Nitrogen Make-up & Usage "
SHINE, C Northeast Nuclear Energy Co (subs of Northeast Utilities) SHINE, C Northeast Utilities 78/03/08 3pp 18302 332 24X Fiche 50-245, 83/04/26, 8305030620

--8305030628 Rev 13 to OP 311, "Containment Sys "
MCCOLLUM, W Northeast Nuclear Energy Co (subs of Northeast Utilities), MCCOLLUM, W Northeast Utilities 82/12/09 28pp 18302 335 24X Fiche: 50-245, 83/04/26, 8305030620

8305030404 Informs that value-impact analysis has resulted in cancellation of proposed reroute of reactor water cleanup sys to all feedwater nozzles Reroute unnecessary if triple-sleeve spargers do not leak
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/04/27
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18291 221 24X
Fiche 50-245, 83/04/27, 8305030404

8305020121 Forwards Franklin Research Ctr request for info re structural aspects of plant-unique analysis rept on Mark I containment long-term program concerning torus & vent & piping sys (TER-C5506-317) Response due within 45 days
CRUTCHFIELD, D Operating Reactors Branch 5 83/04/28 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 18278 235 24X Fiche 50-245, 83/04/28, 8305020121

8305050229 Submits progress rept re TMI Items II F 1.1 & II F 1 2 re effluent monitor mods Vendor schedular uncertainties resolved Remaining work consists of training operators, software changes & minor wiring change
COUNSIL, W G, Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL, W G Northeast Utilities. 83/04/29
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18338 062 24X
Fiche 50-245, 83/04/29, 8305050229

8305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Manual," per 10CFR50, App E, Section V W/o encls
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 83/04/29 EISENHUT, D G Division of Licensing 2pp 18362 256 24X Fiche 50-000, 83/04/29, 8305090465

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 30pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305090471 Updated application for amend to License DPR-21, proposing Tech Spec change re reactor protection sys power monitoring, per 821015 proposal Proposed change conforms to STS requirements w/listed exceptions addressed in 830405 ltr
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/02 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18362 267 24X Fiche 50-245, 83/05/02, 8305090471

--8305090474 Proposed Tech Spec 3/4 1-1 re reactor protection sys power monitoring
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/31 2pp 18362 269 24X Fiche 50-245, 83/05/02, 8305090471

8305090426 Forwards Amends 91 & 86 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability Amends change ownership interests in facilities
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 18360 236 24X Fiche 50-245, 83/05/05, 8305090426

--8305090436 Amend 91 to License DPR-21, reflecting merger of Connecticut Light & Power Co & Hartford Electric Light Co
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 5pp 18360 239 24X Fiche 50-245, 83/05/05, 8305090426

--8305090442 Corrected App A Tech Spec Page 5-1 of Amend 91 to License DPR-21, containing captioned amend number & vertical line indicating change
* Division of Licensing 83/05/05 2pp 18360 244 24X Fiche 50-245, 83/05/05, 8305090426

--8305090460 Amend 86 to License DPR-65, reflecting merger of Connecticut Light & Power Co & Hartford Electric Light Co Pages 1 & 2 of Amend 4 to License DPR-21 encl
CLARK, R A Operating Reactors Branch 3 83/05/05 4pp 18360 246 24X Fiche 50-245, 83/05/05, 8305090426

--8305090463 Notice of issuance & availability of Amends 91 & 86 to Licenses DPR-21 & DPR-65, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 2pp 18360 250 24X Fiche 50-245, 83/05/05, 8305090426

8305100368 Advises that w/exception of Item II K 3 31 on compliance w/10CFR50 54, 830324 comments applicable to 830321 draft generic ltr Review of 830324 submittal re comments on draft NUREG-0737 BWR Tech Specs requested
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/05 EISENHUT, D G Division of Licensing 2pp 18378 212 24X Fiche 50-245, 83/05/05, 8305100368

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305180268 Advises that Atwood Morrill vacuum breakers acceptable as-built Chugging impact velocity results in insignificant loading on valve Ten valves modified to replace aluminum casting disks w/more ductile aluminum plate matl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/10 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18490 069, 24X Fiche 50-245, 83/05/10, 8305180268

8305180304 Forwards "SEP Topic VIII-2, Onsite Emergency Power Sys Gas Turbine Generator Preventative Maint Program " Program adequate except for engine-mounted fuel pump, fuel shutoff valve & air start regulating valve
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/10 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18486 293 24X Fiche 50-245, 83/05/10, 8305180304

--8305180311 "SEP Topic VIII-2, Onsite Emergency Power Sys Gas Turbine Generator Preventative Maint Program "
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/31 4pp 18486 295 24X Fiche 50-245, 83/05/10, 8305180304

8305250510 Application to amend Licenses DPR-61, DPR-21 & DPR-65 deleting 820630 deadline date for conformance w/final rule 10CFR50 49 removing requirement for central equipment qualification file
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co 83/05/18 CLARK, R A Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18588 278 24X Fiche 50-000, 83/05/18, 8305250510

--8305250518 Proposed Tech Spec changes deleting 820630 deadline for environ qualification of electrical equipment
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/18 7pp 18588 281 24X Fiche 50-000, 83/05/18, 8305250510

8305270114 Forwards Rev 1 to "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Unit 1," technical rept
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/18 CRUTCHFIELD, D Operating Reactors Branch 5 1p 18640 331 24X Fiche 50-245, 83/05/18, 8305270114

--8305270119 Rev 1 to "Mark I Containment Program Plant-Unique Analysis Rept of Torus Suppression Chamber for Millstone Unit 1," technical rept
* Teledyne Engineering Services TR-5318-1 R01 83/04/04 140pp 18640.332 24X Fiche 50-245, 83/05/18, 8305270114

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089. 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250437 Forwards IE Insp Rept 50-245/83-07 on 830411-14 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/11
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588 075 24X Fiche 50-245,83/05/11,8305250437

--8305250443 IE Insp Rept 50-245/83-07 on 830411-14 No noncompliance noted Major areas inspected actions taken to comply w/NUREG-0737,Item II B 2, "Design Review of Plant Shielding "
BRIGGS,L , EAPEN,P , PLISCO,L Region 1, Office of Director
83/05/09 6pp 18588 077 24X Fiche 50-245,83/05/11,8305250437

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305060501 Forwards LER 83-014/03L-0 Detailed event analysis encl
MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/29 ALLAN,J M Region 1, Office of Director
3pp 18351 139 24X Fiche 50-245,83/04/29,8305060501

--8305060512 LER 83-014/03L-0 on 830331,gas turbine accelerated on air start motor,but failed to achieve ignition Cause unknown Investigation initiated to evaluate & determine cause of event
THULL,T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/04/29 Region 1, Office of Director 1p
18351 142 24X Fiche 50-245,83/04/29,8305060501

8305230549 Forwards LER 83-015/03L-0 Detailed event analysis encl
MROCZKA,E J. Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/10 ALLAN,J M Region 1, Office of Director
2pp 18537 087 24X Fiche 50-245,83/05/10,8305230549

--8305230557 LER 83-015/03L-0 on 830411,during turbine control valve fast closure functional & calibr test,time delay relays 590-125A & 590-125D tripped at 261 & 262 milliseconds,respectively Caused by setpoint drift Relays adjusted & tested
THULL,T S Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/10 Region 1, Office of Director 1p
18537 089 24X Fiche 50-245,83/05/10,8305230549

DOCKET 50-247 INDIAN POINT STATION, UNIT 2

D NRC Draft/Final Environmental Statements, supplS & correspondence

8305030531 Forwards documents presented to NRC witnesses Gallups & Kornegay during 830422 cross-examination
FARRELLY,T J. Consolidated Edison Co of New York, Inc 83/04/28
LEWIS,D Atomic Safety and Licensing Board Panel 24pp 18300 315 24X Fiche 50-247,83/04/28,8305030531

F Security, medical, emergency & fire protection plans

8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions NUREG-0654-FEMA-REP-1, Rev 1 stds would place heavy resource burden on state
GIUFFRIDA,L O Federal Emergency Management Agency. 83/04/18
PALLADINO,N J Commissioners. 1p 18542 329 24X
Fiche 50-003,83/04/18,8305230670.

--8305230676 Seeks clarification of issue re FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan
PALLADINO,N J Commissioners 83/03/30 GIUFFRIDA,L O Federal Emergency Management Agency 2pp 18542 330 24X
Fiche 50-003,83/04/18,8305230670

8305020548 Responds to 830107 ltr re Rev 4 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable
VARGA,S A Operating Reactors Branch 1 83/04/20 Consolidated Edison Co of New York, Inc 1p 18284 257 24X
Fiche 50-003,83/04/20,8305020548

8305020575 Responds to 830128 ltr re Rev 3 to safeguards contingency plan Changes consistent w/10CFR50 54(p) & acceptable
VARGA,S A Operating Reactors Branch 1 83/04/20 O'TOOLE,J D Consolidated Edison Co of New York, Inc 1p 18284 232 24X
Fiche 50-003,83/04/20,8305020575

8305050187 Forwards IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 & notice of violation Notice of violation withheld (ref 10CFR73 21 & 10CFR2 790)
MARTIN,T T Division of Engineering & Technical Programs 83/04/20
O'TOOLE,J D Commonwealth Edison Co 2pp 18341 068 24X
Fiche 50-247,83/04/20,8305050187

--8305050190 IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 Noncompliance noted barrier of one vital area not maintained Safeguards info deleted (ref 10CFR2 790)
BAILEY,R J , QODY,A T Region 1, Office of Director 83/04/12
6pp 18341 070 24X Fiche 50-247,83/04/20,8305050187

8305040235 Releases public version of rev to emergency plan & emergency plan implementing procedure
FELTON,J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18364 188 24X Fiche 50-003,83/04/22,8305040235

--8305040242 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
O'TOOLE,J D Consolidated Edison Co of New York, Inc 83/04/07
HAYNES,R C Region 1, Office of Director 2pp 18364 190 24X
Fiche 50-003,83/04/22,8305040235

--8305040247 Forwards public version of revs to emergency plan & Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
LIEBLER,G H Consolidated Edison Co of New York, Inc 83/03/08
Office of Nuclear Reactor Regulation, Director 2pp 18364 192
24X Fiche 50-003,83/04/22,8305040235

--8305040249 Public version of rev to Emergency Plan Implementing Procedure IP-1045, "Activation of Alternate Emergency Operations Facility "
* Consolidated Edison Co of New York, Inc 83/03/08 18pp
18364 194 24X Fiche 50-003,83/04/22,8305040235

--8305040254 Public version of revised emergency plan
* Consolidated Edison Co of New York, Inc 83/03/07 49pp
18364 212 24X Fiche 50-003,83/04/22,8305040235

8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning,for info Certificate of Svc encl Related correspondence
GLASS,S M Federal Emergency Management Agency 83/04/25
GLEASON,J P , SHON,F J , PARIS,D H Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247,83/04/25,8305020419

8305100427 Forwards IE Insp Rept 50-247/83-10 on 830302-0404 & notices of violation & deviation
STAROSTECKI,R Division of Project & Resident Programs 83/04/25
O'TOOLE,J D Consolidated Edison Co of New York, Inc 2pp
18410 336 24X Fiche 50-247,83/04/25,8305100427

--8305100428 Notice of violation from insp on 830302-0404
* Region 1, Office of Director 83/04/25 2pp 18410 338 24X
Fiche 50-247,83/04/25,8305100427

--8305100431 Notice of deviation from insp on 830302-0404
* Region 1, Office of Director 83/04/25 1p 18410 340 24X
Fiche 50-247,83/04/25,8305100427

--8305100433 IE Insp Rept 50-247/83-10 on 830302-0404 Noncompliance noted failure to meet Tech Spec requirements re reportability of fire barriers,failure to establish QA procedures & failure to meet radwaste processing
FOLEY,T , KOLTAY,P Region 1, Office of Director KISTER,H B
Division of Project & Resident Programs 83/04/19 19pp
18410 341 24X Fiche 50-247,83/04/25,8305100427

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305240312 Informs of full cooperation between licensee & local govt in development & exercise of emergency radiological response plan,contrary to Commissioner Ahearne 830506 statement
HEIMBACH,L New York, State of 83/05/20 PALLADINO,N Commissioners 1p 18548 184 24X Fiche 50-247,83/05/20, 8305240312

8305310049 Responds to 830523 ltr outlining specific proposals for ameliorating facility offsite preparedness situation & views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness
GIUFFRIDA,L D Federal Emergency Management Agency 83/05/25
CUOMO,M N New York, State of 4pp 18653 284 24X
Fiche 50-247,83/05/25,8305310049

O Adjudicatory correspondence

8305030608 Motion for permission to present rebuttal witnesses on subj of prevailing winds,sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence
POTTERFIELD,A Union of Concerned Scientists POTTERFIELD,A Public Interest Research Group, New York KAPLAN,C New York, NY 83/04/19 4pp 18308 050 24X Fiche 50-247,83/04/19,8305030608

--8305030619 Testimony of D Gutman re prevailing wind patterns
GUTMAN,D Union of Concerned Scientists GUTMAN,D Public Interest Research Group, New York GUTMAN,D New York, NY 83/04/19 4pp 18308 054 24X Fiche 50-247,83/04/19,8305030608

--8305030629 Testimony of RR Holt re sample surveys & bystander behavior
HOLT,R R Union of Concerned Scientists HOLT,R R Public Interest Research Group, New York HOLT,R R New York, NY 83/04/19 37pp 18308 058 24X Fiche 50-247,83/04/19,8305030608

--8305030633 Reorganized testimony of JR Thornborough & D Bohning re Contention 6 2 concerning impact of shutdown on physical environ near facility
POSNER,P Parents Concerned About Indian Point 83/04/19 44pp 18308 095 24X Fiche 50-247,83/04/19,8305030608

--8305030641 Motion requesting initiation of studies on human response to radiological emergencies,risks to individuals living near site & difficulty of evacuation in emergency
POTTERFIELD,A Public Interest Research Group, New York
POTTERFIELD,A Union of Concerned Scientists, 83/04/26 Atomic Safety and Licensing Board Panel 8pp 18308 139 24X
Fiche 50-247,83/04/19,8305030608

--8305030646 Affidavit of KT Erickson & AJ Solnit re radiological emergency response plan
ERICKSON,K T Public Interest Research Group, New York
ERICKSON,K T Union of Concerned Scientists ERICKSON,K T Yale Univ , New Haven, CT 83/04/26 42pp 18308 148 24X
Fiche 50-247,83/04/19,8305030608

--8305030652 Motion requesting completeness of record on NRC Questions 3 & 4 re emergency planning issues,including capability for handling phone calls in emergency planning zone during emergency
POTTERFIELD,A , POTTERFIELD,A Union of Concerned Scientists 83/04/25 Atomic Safety and Licensing Board Panel 4pp 18308 180 24X Fiche 50-247,83/04/19,8305030608

8305020428 Motion to strike portions of 830309 emergency drill testimony under Commission Questions 3 & 4 filed by witnesses for various intervenors Certificate of Svc encl Related correspondence
BRANDENBURG,B Consolidated Edison Co of New York, Inc 83/04/22 Atomic Safety and Licensing Board Panel 22pp 18273 075 24X
Fiche 50-247,83/04/22,8305020428

8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning,for info Certificate of Svc encl Related correspondence
GLASS,S M Federal Emergency Management Agency 83/04/25
GLEASON,J P , SHON,F J , PARIS,O H Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247,83/04/25, 8305020419

8305030549 Motion for subpoena to be issued to RW Krimm of FEMA Subpoena necessary to complete record on generic nature of deficiencies cited by FEMA & FEMA change in evaluation criteria Certificate of Svc encl
MORGAN,C Power Authority of the State of New York MORGAN,C Morgan Associates 83/04/26 Atomic Safety and Licensing Board Panel 40pp 18306 147 24X Fiche 50-247,83/04/26,8305030549

8305020401 Motion to amend svc list to add SP Wasserman & delete P Chessin,LR Schwartz & M Oppel Notice of appearance & Certificate of Svc encl
WASSERMAN,S P Metropolitan Transportation Authority New York, NY
WASSERMAN,S P Botein, Hays, Sklar & Herzberg 83/04/27 Atomic Safety and Licensing Board Panel 6pp 18273 067 24X
Fiche 50-247,83/04/27,8305020401

8305020451 Submits info on status of Ray Miller,Inc problems affecting plant,per ASLB request
MOORE,J E Hearing Branch 1 83/04/28 GLEASON,J P , SHON,F J., PARIS,O H Atomic Safety and Licensing Board Panel 88pp 18283 180 24X Fiche 50-247,83/04/28,8305020451

8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination
FARRELLY,T J Consolidated Edison Co of New York, Inc 83/04/28, LEWIS,D Atomic Safety and Licensing Board Panel 24pp 18300 315 24X Fiche 50-247,83/04/28,8305030531

8305040505 Forwards util onsite emergency plans per ASLB request that documents be mailed rather than delivered
BRANDENBURG,B Consolidated Edison Co of New York, Inc 83/04/28
GLEASON,J P , SHON,F J , PARIS,O H Atomic Safety and Licensing Board Panel 1p 18322 110 24X Fiche 50-247,83/04/28,8305040505

8305030583 Forwards summary of training activities re offsite response organizations that might be called upon to respond to onsite emergencies,per ASLB 830225 oral request Util training detailed in 830405 submittal Related correspondence
BRANDENBURG,B Office of the General Counsel 83/04/29 LEWIS,D Atomic Safety and Licensing Board Panel 7pp 18303 355 24X
Fiche 50-247,83/04/29,8305030583

8305040464 Requests official position re long-term operation of facilities
GLEASON,J P , PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 83/05/02 CUOMO,M M New York, State of 2pp 18321 295 24X Fiche 50-247,83/05/02,8305040464

8305050035 Proposes alternative views to questions posed in BJ Chilk 830426 ltr to FEMA re emergency planning & evacuation
FLEISHER,Z S West Branch Conservation Association 83/05/02
PALLADINO,N J , GILINSKY,V , AHEARNE,J F Commissioners 3pp 18342 096 24X Fiche 50-247,83/05/02,8305050035

8305160304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing,Inc
MILES,E B Administrative Contracts Branch FIN B-8855 83/05/02
BASSETT,H S Office of Resource Management, Director FITTI,C Atomic Safety and Licensing Board Panel 1p 18471 247 24X
Fiche 50-247,83/05/02,8305160304

--8305160312 Contract: "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing,Inc
* Central Data Processing, Inc MATTIA,M J Division of Contracts FIN B-8855 83/05/02 2pp 18471 248 24X
Fiche 50-247,83/05/02,8305160304

--8305160316 Solicitation,offer & award to "Conversion of Prefiled Testimony for Indian Point Hearings," to Central Data Processing,Inc
COUCH,M J Central Data Processing, Inc MATTIA,M J, Administrative Contracts Branch FIN B-8855 83/04/26 56pp 18471 250 24X Fiche 50-247,83/05/02,8305160304

8305050037 Forwards NY State Disaster Preparedness Commission 830504 memo re State of NY commitment to continue work to ensure residents protected by best practicable emergency preparedness plan
DAYNE,J P Power Authority of the State of New York 83/05/04
PALLADINO,N J , GILINSKY,V., AHEARNE,J F Commissioners 3pp 18339 105 24X Fiche 50-247,83/05/04,8305050037

8305060496 Forwards NY State Disaster Preparedness Commission 830504 ltr providing State of NY commitment to ensure residents protected by best practicable emergency preparedness plan
DAYNE,J P Power Authority of the State of New York 83/05/04
PALLADINO,N J , GILINSKY,V , AHEARNE,J F Commissioners 3pp 18348 105 24X Fiche 50-247,83/05/04,8305060496

8305060506 Responds to 830426 ltr re Westchester County,NY bus driver issue,Rockland County,NY plan issue & questions raised re FEMA briefing & status rept on offsite emergency preparedness
KRIMM,R W Federal Emergency Management Agency 83/05/04
CHILK,S J Office of the Secretary of the Commission 16pp
18348 331 24X Fiche 50-247,83/05/04,8305060506

--8305060629 Responds to request for clarification of issue on whether state emergency plan can substitute for county which does not have emergency plan State can substitute plan but NUREG-0654 places heavy resource burden on state
GIUFFRIDA,L O Federal Emergency Management Agency 83/04/15
PALLADINO,N J Commissioners 2pp 18348 347 24X
Fiche 50-247,83/05/04,8305060506

8305060468 Order CLI-83-11 advising that Commission will issue order by 830609 suspending plant operation unless FEMA determines significant deficiencies no longer exist or util shows compensating actions taken or deficiencies insignificant
HOYLE,J Office of the Secretary of the Commission 83/05/05 5pp
18348 075 24X Fiche 50-247,83/05/05,8305060468

8305090458 Memo providing citations to decisions referred to in hearing re commitments from bus drivers needed in emergency evacuation plans
PARIS,O H Atomic Safety and Licensing Board Panel 83/05/05 2pp
18362 259 24X Fiche 50-247,83/05/05,8305090458

8305100208 Motion for extension of deadline until 830627 for all parties to submit proposed opinion,findings of fact & recommendations re enforcement action on emergency planning issues.Certificate of Svc encl
BRANDENBURG,B Consolidated Edison Co of New York, Inc MORGAN,C Power Authority of the State of New York MORGAN,C Morgan Associates 83/05/06 PALLADINO,N J , GILINSKY,V , AHEARNE,J F Commissioners 9pp 18374 014 24X Fiche 50-247,83/05/06, 8305100208

8305100204 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11,establishing procedures for decision on enforcement action on emergency planning issues Certificate of Svc encl
WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss 83/05/09 Commissioners 6pp 18374 193 24X
Fiche 50-247,83/05/09,8305100204

8305130064 Motion for reconsideration of ruling denying licensee motion to receive DP McGuire deposition transcript into evidence Licensees entitled to place deposition in record Certificate of Svc encl
BRANDENBURG,B Consolidated Edison Co of New York, Inc MORGAN,C Power Authority of the State of New York MORGAN,C Morgan Associates 83/05/09 Atomic Safety and Licensing Board Panel 13pp 18436.230 24X Fiche 50-247,83/05/09,8305130064

8305120309 Order authorizing ASLB to grant relief from 830527 deadline for filing proposed findings of fact & conclusions of law since oral presentations before Commission to take place on 830526
CHILK,S J Office of the Secretary of the Commission 83/05/10
Atomic Safety and Licensing Board Panel 2pp 18424.100 24X
Fiche 50-247,83/05/10,8305120309

8305160024 Forwards I Levi affidavit clarifying 830211 testimony on suggested method of making sensible probability judgments described in Section 5
HARTZMAN,R M Friends of the Earth HARTZMAN,R M Audubon Society 83/05/10. OLEASON,J P , PARIS,O H , SHON,F.J Atomic Safety and Licensing Board Panel 1p 18452 353 24X Fiche 50-247,83/05/10, 8305160024

--8305160028 Affidavit of I Levi clarifying 830211 testimony re suggested method of making sensible probability judgments described in Section 5
LEVI,I. Friends of the Earth. LEVI,I Audubon Society 83/05/10 2pp 18452.354. 24X Fiche 50-247,83/05/10,8305160024.

8305130030 Memorandum & order granting licensee 830506 motion for extension until 830627 to file proposed findings of fact & recommendations.Date extended until 830829 for ASLB to submit recommendations to Commission
PARIS,O H , SHON,F J Atomic Safety and Licensing Board Panel 83/05/11 Consolidated Edison Co of New York, Inc 2pp
18437.102. 24X Fiche 50-247,83/05/11,8305130030

8305130071 Motion for extension of deadline (to 830615) for filing corrections to transcripts & deadline (to 830624) for filing comments Certificate of Svc encl
BRANDENBURG,B Consolidated Edison Co. of New York, Inc MORGAN,C Power Authority of the State of New York MORGAN,C Morgan Associates 83/05/11 Atomic Safety and Licensing Board Panel 7pp. 18437·045. 24X Fiche 50-247,83/05/11,8305130071

8305190342 Supports immediate plant shutdown Emergency response plan represents theory & not practicality
OALEF,S R Westchester County, NY 83/05/11 PALLADINO,N J Commissioners 6pp 18500 227 24X Fiche 50-247,83/05/11, 8305190342

8305160133 Telecopy order granting licensee 830511 motion for extension of date to file motions to correct transcript Motions due on 830615
GLEASON,J P Atomic Safety and Licensing Board Panel 83/05/13
Consolidated Edison Co of New York, Inc 4pp 18446 116 24X
Fiche 50-247,83/05/13,8305160133

8305160167 Order clarifying Commission 830505 order Comments from parties & general public,relevant to enforcement action,will be considered Public comments to be filed by 830523 Oral presentations limited to licensees & interested govts
CHILK,S J Office of the Secretary of the Commission 83/05/13
Commissioners 4pp 18445 152 24X Fiche 50-247,83/05/13, 8305160167

8305190220 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11 establishing procedures for decision on enforcement action Intervenor entitled to participate as matter of right Certificate of Svc encl
RODRIGUEZ,P Parents Concerned About Indian Point 83/05/13
Commissioners 3pp 18502 143 24X Fiche 50-247,83/05/13, 8305190220

8305200645 Advises that day of reckoning re evacuation plan issue coming on 830609 Interim compensating actions by FEMA cannot compensate for unchangeable factors of problem roads & population density
TOSCANI,K Affiliation Unknown 83/05/15 Commissioners 3pp
18520 122 24X Fiche 50-247,83/05/15,8305200645

8305180143 Order providing time (until 830610) to parties to respond to P Amico,ASLB consultant,830502 ltr summarizing conclusions based on review of testimony & hearing transcripts re Commission Question 1
GLEASON,J P Atomic Safety and Licensing Board Panel 83/05/16
Office of the Executive Legal Director 1p 18490 022 24X
Fiche 50-247,83/05/16,8305180143

--8305180146 Summarizes rept on review of testimony & hearing transcripts re Commission Question 1 Addl testimony recommended on current analytical methods for risk assessment & on issues not dealt w/in probabilistic safety study or NRC analysis
AMICO,P J Applied Risk Technology Corp AMICO,P J Atomic Safety and Licensing Board Panel 83/05/02 GLEASON,J P , SHON,F J , PARIS,O H Atomic Safety and Licensing Board Panel 4pp 18490 023 24X Fiche 50-247,83/05/16,8305180143

8305180424 Requests time to address Commission on 830526 re Commission 830513 order
GDANSKI,S Rockland County, NY 83/05/16 CHILK Commissioners
1p 18485 302 24X Fiche 50-247,83/05/16,8305180424.

8305200605 Requests time to speak on 830526 State of NY claims unsubstantiated NRC should adopt policy of communicating w/public
FLEISHER,Z B West Branch Conservation Association 83/05/16
PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 12pp
18514 090 24X Fiche 50-247,83/05/16,8305200605

8305240535 Citizens advisory committee progress repts re nuclear evacuation & general disaster preparedness plan
* Rockland County, NY 83/05/16 34pp 18576 053 24X
Fiche 50-247,83/05/16,8305240535

8305240508 Forwards Ossining Town Board resolution expressing concerns re emergency plans Deficiencies must be corrected before plan approved
WISHNIE,R G Ossining, NY 83/05/19 Office of the Secretary of the Commission 4pp 18571 260 24X Fiche 50-247,83/05/19, 8305240508

8305240530 Expresses concerns re adequacy & workability of evacuation plans
BOGARDUS,R H Affiliation Unknown 83/05/19 NRC - No Detailed Affiliation Given 2pp 18571 236 24X Fiche 50-247,83/05/19, 8305240530

8305240546 Forwards citizen & group statements expressing concern re plant safety & flawed evacuation plan,in response to Commission Order CLI-83-11
ELLIOTT,N R Yorktown, NY 83/05/19 NRC - No Detailed Affiliation Given. 10pp 18575 266 24X Fiche.50-247,83/05/19, 8305240546

8305240547 Forwards board of trustees of Village of Buchanan statement that plants are safe & provide clean energy
PIERCE,F W Buchanan, NY 83/05/19 PALLADINO,N J Commissioners 2pp 18575 281 24X Fiche 50-247,83/05/19,8305240547

8305270583 Requests concrete actions re emergency evacuation plan in light of FEMA stated deficiencies,in response to Commission 830505 Order CLI-83-11
ELLIOTT,N R Yorktown, NY 83/05/19 Commissioners 1p 18646 343 24X Fiche 50-247,83/05/19,8305270583

8305240454 Motion for leave to submit written comments on NRC 830505 order to suspend facility operations Deficiencies determined to be significant by FEMA are not sufficiently deficient to require suspending operations
JOY,J , HICKS,M M , GALLAGHER,P J Utility Workers Union of America 83/05/20 Commissioners 8pp 18573 164 24X
Fiche 50-247,83/05/20,8305240454

8305240466 Response to Commission 830505 order establishing procedures for decision on enforcement action Emergency planning deficiencies not significant NRC enforcement action unwarranted & improper W/Certificate of Svc
MORGAN,C Power Authority of the State of New York MORGAN,C Morgan Associates 83/05/20 43pp 18573 181 24X
Fiche 50-247,83/05/20,8305240466

8305240527 Views re radiological emergency planning in response to Commission 830505 order FEMA & NRC should rule that plants no longer have significant deficiencies based on improvement & interim compensating actions
BLOCK,J D , BRANDENBURG,B Consolidated Edison Co of New York, Inc 83/05/20 41pp 18571 132 24X Fiche 50-247,83/05/20,8305240527

8305240532 Opinion on NRC 830505 order re FEMA rept on licensee emergency planning & preparedness & possible suspension of plant operations Immediate shutdown urged
KAPLAN,C New York, NY KAPLAN,C National Emergency Civil Liberties Committee 83/05/20 18pp 18571 218 24X
Fiche 50-247,83/05/20,8305240532

8305250337 Submission re Commission 830505 order on intention to shut down facility on 830609 if emergency preparedness problems not resolved Adequate protective action in case of radiological emergency cannot be guaranteed by 830609
GOLDBERG,M L Public Interest Research Group, New York. 83/05/21 17pp 18585 302 24X Fiche 50-247,83/05/21,8305250337.

8305240523 Order providing guidance for 830526 oral presentations to Commission re possible plant shutdown
CHILK,S J Office of the Secretary of the Commission 83/05/23 4pp 18571 119 24X Fiche 50-247,83/05/23,8305240523

8305240538 Forwards comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action
WEISS,E R Harmon & Weiss WEISS,E R Union of Concerned Scientists 83/05/23 PALLADINO,N J , AHEARNE,J F , ASSELSTINE,J.K Commissioners 1p 18576 093 24X Fiche 50-247,83/05/23, 8305240538

--8305240542 Comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action Emergency planning deficiencies fundamental Adequate interim compensating measures impossible Certificate of Svc encl
WEISS,E R Union of Concerned Scientists WEISS,E R Harmon & Weiss 83/05/23 19pp. 18576 094 24X Fiche 50-247,83/05/23, 8305240538

8305240543 Submission re Commission 830505 Order CLI-83-11 Emergency planning must be well developed & detailed w/special emphasis on health & safety of children
POSNER,P Parents Concerned About Indian Point 83/05/23 20pp 18576 113 24X Fiche 50-247,83/05/23,8305240543

8305250223 Submission addressing Commission 830505 order on possible facility closing Requests oral presentation on 830526 re economic impact of facility shutdown Economic impact is not compelling reason for continued operation
CORREN,D Greater New York Council on Energy 83/05/23 12pp 18588 083 24X Fiche 50-247,83/05/23,8305250223

8305270586 Response opposing licensee motion for reconsideration of ASLB denial of licensee motion to admit DP McGuire testimony before trial
THORSEN,E O Rockland County, NY 83/05/24 Atomic Safety and Licensing Board Panel 6pp 18645 355 24X Fiche 50-247,83/05/24, 8305270586

H General correspondence

8305240441 Opines that decision re continued plant operation must weigh health effects of replacement by coal burning plants
JAFFE,H Affiliation Unknown 83/05/16 AHEARNE,J Atomic Safety and Licensing Board Panel 2pp 18571 068 24X
Fiche 50-247,83/05/16,8305240441

8305240517 Supports continued facility operation
SCHULER,R T., HEALEY,J A , IRWIN,R B Affiliation Unknown 83/05/16 PALLADINO,N J Commissioners 27pp 18571 191 24X
Fiche 50-247,83/05/16,8305240517

8305240537 Supports closing down of facility
CINQUEMANI,D , CINQUEMANI,F Affiliation Unknown 83/05/19 Commissioners 1p 18576 039 24X Fiche 50-247,83/05/19, 8305240537

8305270566 Supports shutdown of facilities on 830609
EPSTEIN,R B Affiliation Unknown 83/05/19 Commissioners 2pp 18646 114 24X Fiche 50-247,83/05/19,8305270566

8305240541 Supports suspension of plant operation
GRANNIS,A B New York, State of ELLIOTT,N R Yorktown, NY 83/05/20 NRC - No Detailed Affiliation Given 2pp 18576 091 24X Fiche 50-247,83/05/20,8305240541

8305270575 Package of two citizens ltrs supporting continued facility operation
KUNKEL,T C , WEIGANDT,J T Affiliation Unknown 83/05/20 PALLADINO,N J Commissioners 2pp 18647 125 24X
Fiche 50-247,83/05/20,8305270575

8305240453 Supports continued plant operations Plants should not be held hostage to evacuation process
TODOROVICH,M H Affiliation Unknown 83/05/23 CHILK,S J Office of the Secretary of the Commission 5pp 18575 252 24X
Fiche 50-247,83/05/23,8305240453

P Operating license stage documents & correspondence

8305030456 Application for amend to License DPR-26,changing Tech Specs by permitting extension of 48 h to current 24 h limitation w/containment spray pump 21 out of svc
GROSCUP,G W Consolidated Edison Co of New York, Inc 83/04/28 VARGA,S A Operating Reactors Branch 1 2pp 18306 277 24X
Fiche 50-247,83/04/28,8305030456

--8305030458 Proposed Tech Spec changes,permitting extension of 48 h to current 24 h limitation w/containment spray pump 21 out of svc
Consolidated Edison Co of New York, Inc 83/04/28 1p 18306 279 24X Fiche 50-247,83/04/28,8305030456

8305060355 Confirms 830428 telcon approving proposed Tech Spec amend re containment spray pump
LAINAS,G C Assistant Director for Operating Reactors 83/04/28 O'TOOLE,J D Consolidated Edison Co of New York, Inc 3pp 18353 109 24X Fiche 50-247,83/04/28,8305060355

8305100175 Forwards addl info re instrument accuracy & related data for containment pressure monitors,containment water level monitors & containment hydrogen monitors (NUREG-0737,Items II F 1 4,II F 1 5 & II.F 1 6),per 821118 request
O'TOOLE,J D Consolidated Edison Co of New York, Inc 83/04/29 VARGA,S A Operating Reactors Branch 1 14pp 18374 274 24X
Fiche 50-247,83/04/29,8305100175

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305170644 Clarifies 830105 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review,per encl guidelines,due in 30 days
VARGA,S A Operating Reactors Branch 1 83/05/02 O'TOOLE,J D Consolidated Edison Co of New York, Inc 5pp 18496 349 24X
Fiche. 50-247,83/05/02,8305170644

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N., GILINSKY,V., ROBERTS,T M Commissioners 22pp 18337 139. 24X
Fiche 50-000,83/05/04,8305040323

--8305050287 Forwards "Statisticians View of NRC Statistics," presented to American Stds Assoc Advisory Committee on Nuclear Research
RUBENSTEIN, D Applied Statistics Branch 81/02/04 ABRAMSON, E , BASSETT, H , ABELL, T NRC - No Detailed Affiliation Given 8pp 18337 236 24X Fiche 50-247, 83/05/04, 8305040323

--8301120436 Draft "Random Thoughts on Uncertainties, Risk Analysis & Nuclear Regulation "
RUBENSTEIN, D Reliability & Risk Assessment Branch 81/10/26 12pp 18337 244 24X Fiche 50-247, 83/05/04, 8305040323

--8305050295 Comments on draft ltr from Hanauer to Cooper on NUPPSCO committee Ltr acceptable, however, info re safety classification/terminology issue requires further discussion to standardize term definitions
CONRAN, J NRC - No Detailed Affiliation Given 82/03/18
COFFMAN, F NRC - No Detailed Affiliation Given 5pp 18337 256 24X Fiche 50-247, 83/05/04, 8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods. Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305130018 Forwards application for amend to License DPR-26, proposing change to Tech Spec 3 3 B, allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of svc Class III amend fee encl
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/09
VARGA, S A Operating Reactors Branch 1 1p 18436 317 24X Fiche 50-247, 83/05/09, 8305130018

--8305130022 Application for amend to License DPR-26, proposing change to Tech Spec 3 3 B, allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of svc
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/09 2pp 18436 318. 24X Fiche 50-247, 83/05/09, 8305130018

--8305130024 Proposed Tech Spec 3 3 B (Page 3 3-4), allowing extension of 48 h to current 24 h operating limitation w/containment spray pump 21 out of svc Safety assessment & Affidavit of Svc encl.
* Consolidated Edison Co of New York, Inc 83/05/31 6pp 18436 320 24X Fiche 50-247, 83/05/09, 8305130018

8305180038 Notification of contract execution, Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ
HOYLE, A Administrative Contracts Branch FIN B-8644 83/05/10
DENTON, H Office of Nuclear Reactor Regulation, Director. CODELL, R NRC - No Detailed Affiliation Given 1p 18499 289 24X Fiche 50-247, 83/05/10, 8305180038

--8305180047 Mod 1, extending period of performance to 830630 & changing payment & general provisions, to "Consulting Svc on Indian Point Probabilistic Safety Study "
LEWIS, J P Columbia Univ REBELLO, J E Division of Contracts 83/05/10. 1p. 18499 290 24X Fiche 50-247, 83/05/10, 8305180038

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J.M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8305050187 Forwards IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 & notice of violation Notice of violation withheld (ref 10CFR73.21 & 10CFR2 790)
MARTIN, T T Division of Engineering & Technical Programs. 83/04/20
O'TOOLE, J D Commonwealth Edison Co 2pp. 18341 068. 24X Fiche 50-247, 83/04/20, 8305050187

--8305050190 IE Safeguards Insp Rept 50-247/83-08 on 830228-0304 Noncompliance noted barrier of one vital area not maintained Safeguards info deleted (ref 10CFR2 790)
BAILEY, R J , GODY, A T. Region 1, Office of Director 83/04/12 6pp. 18341 070 24X Fiche 50-247, 83/04/20, 8305050187

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305100427 Forwards IE Insp Rept 50-247/83-10 on 830302-0404 & notices of violation & deviation
STAROSTECKI, R Division of Project & Resident Programs 83/04/25
O'TOOLE, J D Consolidated Edison Co of New York, Inc 2pp 18410 336 24X Fiche 50-247, 83/04/25, 8305100427

--8305100428 Notice of violation from insp on 830302-0404
* Region 1, Office of Director 83/04/25 2pp 18410 338 24X Fiche 50-247, 83/04/25, 8305100427

--8305100431 Notice of deviation from insp on 830302-0404
* Region 1, Office of Director 83/04/25 1p 18410 340 24X Fiche 50-247, 83/04/25, 8305100427

--8305100433 IE Insp Rept 50-247/83-10 on 830302-0404 Noncompliance noted failure to meet Tech Spec requirements re reportability of fire barriers, failure to establish QA procedures & failure to meet radwaste processing
FOLEY, T , KOLTAY, P Region 1, Office of Director KISTER, H B Division of Project & Resident Programs 83/04/19 19pp 18410 341 24X Fiche 50-247, 83/04/25, 8305100427

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020451 Submits info on status of Ray Miller, Inc problems affecting plant, per ASLB request
MOORE, J E Hearing Branch 1 83/04/28 GLEASON, J P , SHON, F J , PARIS, O H Atomic Safety and Licensing Board Panel 88pp 18283 180 24X Fiche 50-247, 83/04/28, 8305020451

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200191 Forwards request for addl info resulting from review of 820816 response to IE Bulletin 80-11, "Masonry Wall Design " Info must be provided within 30 days of ltr receipt
VARGA, S A Operating Reactors Branch 1 83/05/12 O'TOOLE, J D Consolidated Edison Co of New York, Inc. 3pp 18540 225 24X Fiche. 50-247, 83/05/12, 8305200191

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & "Annual Radiological Environ Operating Rept, 1982," per App B to OLs
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/02
ALLAN, J M Region 1, Office of Director 2pp 18392 221 24X
Fiche 50-003, 83/05/02, 8305110302

--8305110307 "Annual Environ Protection Plan Rept for 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 8pp
18392 223 24X Fiche 50-003, 83/05/02, 8305110302

--8305110310 "Annual Radiological Environ Operating Rept, 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 112pp.
18392 231 24X Fiche 50-003, 83/05/02, 8305110302

S Reportable occurrences, LERs & related correspondence

8305030400 Forwards LER 83-006/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/04/15
ALLAN, J M Region 1, Office of Director 1p 18291 219 24X
Fiche 50-247, 83/04/15, 8305030400

--8305030407 LER 83-006/03L-0 on 830316, reactor cavity continuous sump level monitor indicated 3 ft above normal & declared inoperable Caused by drifted output from level transmitter LT 3302 in conservative direction Transmitter recalibr
HINRICHS, G Consolidated Edison Co of New York, Inc 83/04/15
Region 1, Office of Director 1p 18291 220 24X
Fiche 50-247, 83/04/15, 8305030400

8305230430 Forwards engineering evaluation rept, "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria
ASHE, F Reactor Operations Analysis Branch 83/04/18 SEYFRIT, K V
Reactor Operations Analysis Branch 2pp 18545 356 24X
Fiche 50-000, 83/04/18, 8305230430

--8305230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms," engineering evaluation rept, LERs re safety-related battery degradation reviewed
ASHE, F Reactor Operations Analysis Branch 83/04/18 5pp
18545 358 24X Fiche 50-000, 83/04/18, 8305230430

8305030373 Forwards LER 83-007/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/04/21
ALLAN, J M Region 1, Office of Director 1p 18306 235 24X
Fiche 50-247, 83/04/21, 8305030373

--8305030380 LER 83-007/03L-0 on 830322, svc water pump 26 removed from svc due to inoperable strainer. Caused by sheared key connecting drive motor to filter shaft due to excessive debris accumulation within strainer basket Basket cleaned
HINRICHS, G Consolidated Edison Co of New York, Inc 83/04/21.
Region 1, Office of Director 2pp 18306 256 24X
Fiche 50-247, 83/04/21, 8305030373

8305110393 Forwards LER 83-008/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/04/27
ALLAN, J M Region 1, Office of Director 1p 18406 197. 24X
Fiche 50-247, 83/04/27, 8305110393

--8305110403 LER 83-008/03L-0 on 830328, electric heat trace circuit 51B found w/inoperable primary circuit Caused by primary heating element to be open circuit Element replaced, Circuit tested & returned to svc
MOONEY, J Consolidated Edison Co of New York, Inc 83/04/27.
Region 1, Office of Director 1p 18406 198 24X
Fiche 50-247, 83/04/27, 8305110393

8305160075 Forwards LER 83-009/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/04/30.
ALLAN, J M Region 1, Office of Director 1p 18451 004 24X
Fiche 50-247, 83/04/30, 8305160075

--8305160079 LER 83-009/03L-0 on 830331, when operator attempted to start safety injection pump 23 during steady-state operation, pump motor breaker failed to close Caused by seized closing solenoid Breaker replaced
MOONEY, J Consolidated Edison Co of New York, Inc 83/04/30
Region 1, Office of Director 2pp 18451 005 24X
Fiche 50-247, 83/04/30, 8305160075

8305160020 Forwards LER 83-010/03L-0
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/01
ALLAN, J M Region 1, Office of Director 1p 18452 345 24X
Fiche 50-247, 83/05/01, 8305160020

--8305160025 LER 83-010/03L-0 on 830401, svc water pump 25 declared inoperable when pump could not be restarted after pump trip Caused by nylon rope from old cathodic protection sys in travelling screens wrapping around impeller & shaft
HINRICHS, G Consolidated Edison Co of New York, Inc 83/05/01
Region 1, Office of Director 1p 18452 346 24X
Fiche 50-247, 83/05/01, 8305160020

8305250483 LER 83-011/03L-0 on 830413, during inservice valve test, valve 887B in suction line to safety injection pump 22 found inoperative Valve 887A operable Caused by pinched & grounded wire for motor on Limitorque valve operator W/830513 ltr
MOONEY, J , O'TOOLE, J Consolidated Edison Co of New York, Inc
83/05/13 MURLEY, T E Region 1, Office of Director 2pp
18568 251 24X Fiche 50-247, 83/05/13, 8305250483

T Hearing transcripts on non-antitrust matters

8305230001 Transcript of 830322 hearing in White Plains, NY
Pp 10,737-11,117 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/22 612pp
18532 021 24X Fiche 50-247, 83/03/22, 8305230001

8305110002 Excerpts from transcript of 830407 hearing Pp 13,017-13,019
* NRC - No Detailed Affiliation Given 83/04/07 3pp 18409 009
24X Fiche 50-247, 83/04/07, 8305110002

8305030608 Motion for permission to present rebuttal witnesses on subJ of prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence
POTTERFIELD, A Union of Concerned Scientists POTTERFIELD, A.
Public Interest Research Group, New York KAPLAN, C New York, NY.
83/04/19 4pp 18308 050 24X Fiche 50-247, 83/04/19, 8305030608

--8305030619 Testimony of D Gutman re prevailing wind patterns
GUTMAN, D Union of Concerned Scientists GUTMAN, D Public Interest Research Group, New York GUTMAN, D New York, NY
83/04/19 4pp 18308:054 24X Fiche 50-247, 83/04/19, 8305030608.

--8305030627 Testimony of RR Holt re sample surveys & bystander behavior.
HOLT, R R Union of Concerned Scientists HOLT, R R Public Interest Research Group, New York HOLT, R R New York, NY
83/04/19 37pp 18308 058 24X Fiche 50-247, 83/04/19, 8305030608.

--8305030633 Reorganized testimony of JR Thornborough & D Bohning re Contention 6 2 concerning impact of shutdown on physical environ near facility
POSNER, P Parents Concerned About Indian Point 83/04/19 44pp
18308 095 24X Fiche 50-247, 83/04/19, 8305030608

--8305030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site & difficulty of evacuation in emergency
POTTERFIELD, A Public Interest Research Group, New York
POTTERFIELD, A Union of Concerned Scientists 83/04/26. Atomic Safety and Licensing Board Panel 8pp 18308 139 24X
Fiche 50-247, 83/04/19, 8305030608

--8305030652 Motion requesting completeness of record on NRC Questions 3 & 4 re emergency planning issues, including capability for handling phone calls in emergency planning zone during emergency.
POTTERFIELD, A , POTTERFIELD, A Union of Concerned Scientists.
83/04/25 Atomic Safety and Licensing Board Panel 4pp
18308 180 24X Fiche. 50-247, 83/04/19, 8305030608

8305020077 Transcript of 830426 hearing in White Plains, NY Pp 14,419-14,596 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/04/26 210pp
18278 250 24X Fiche 50-247, 83/04/26, 8305020077

8305030386 Transcript of 830427 hearing in White Plains, NY. Pp 14,597-14,702
* Atomic Safety and Licensing Board Panel 83/04/27. 116pp
18292-001 24X Fiche 50-247, 83/04/27, 8305030386

8305040172 Transcript of 830428 hearing in White Plains,NY Pp 14,703-15,087 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/04/28 526pp
18324 297 24X Fiche 50-247,83/04/28,8305040172

8305090425 Testimony of LA Cohen in rebuttal to testimony of D Gutman Testimony to be included w/ASLB 830420 transcript
Certificate of Svc encl
COHEN,L A Consolidated Edison Co of New York, Inc 83/04/28
10pp 18363 321 24X Fiche 50-247,83/04/28,8305090425

8305040347 Transcript of 830429 hearing in White Plains,NY Pp 15,088-15,226 Supplemental testimonies encl
* Atomic Safety and Licensing Board Panel 83/04/29 149pp
18322:242 24X Fiche 50-247,83/04/29,8305040347

8305130327 Transcript of Commission 830505 meeting,discussion & possible vote in Washington,DC re status of emergency planning at facilities Pp 1-22
* Commissioners 83/05/05 27pp 18457 277 24X
Fiche 50-247,83/05/05,8305130327

8305240554 Statement to be incorporated in minutes of Commission 830526 public hearing State/federal govt must force counties to devise evacuation plans Problems w/emergency plans must be resolved before 830609
DI GIACOMO,C Q Cortland, NY 83/05/18 4pp 18576 029. 24X
Fiche 50-247,83/05/18,8305240554

8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR,per 10CFR9 Commission determination statement encl
CHILK,B J Office of the Secretary of the Commission 83/05/18
Public Document Branch 2pp 18593 063 24X Fiche 50-003,83/05/18,
8305240566

--8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners 82/12/22 15pp 18593 065 24X
Fiche 50-003,83/05/18,8305240566

--8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners 82/12/22 59pp 18593 082 24X
Fiche 50-003,83/05/18,8305240566

8305240531 Statement of Clergy,Religious & Laity Concerned About Indian Point.Common citizens reject idea that expertise irrelevant Value of human life is supreme value
* Affiliation Unknown 83/05/20 4pp 18571 105 24X
Fiche:50-247,83/05/20,8305240531.

8305240533 Forwards written testimony on efforts to address deficiencies in emergency response plan since 830505
O'ROURKE,A.P Westchester County, NY 83/05/20. PALLADINO,N J., GILINSKY,V., AHEARNE,J Commissioners 1p 18576.043 24X
Fiche 50-247,83/05/20,8305240533

--8305240539 Testimony of AP O'Rourke re actions taken to improve emergency planning since Commission 830505 order Unions representing bus drivers fully support orientation course on radiological emergency response procedures
O'ROURKE,A P. Westchester County, NY 83/05/20. 6pp 18576.044
24X Fiche 50-247,83/05/20,8305240533

8305240555 Forwards statement for inclusion in special proceeding testimony.
WEISS,T. House of Rep 83/05/20. PALLADINO,N Commissioners 1p
18576:025. 24X Fiche 50-247,83/05/20,8305240555

--8305240558 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile Public safety should be top priority
WEISS,T House of Rep 83/05/19. 3pp 18576 026. 24X
Fiche.50-247,83/05/20,8305240555

8305310002 Testimony of RW Carlisle re potential hazards of nuclear accidents Long-range educ in nuclear radiation should be implemented.Robots should be developed to dismantle plant after meltdown.
CARLISLE,R W. Affiliation Unknown 83/05/20. 3pp 18653 240 24X
Fiche 50-247,83/05/20,8305310002

8305310055 Transcript of Commission 830523 discussion of Indian Point order in Washington,DC.Pp 1-19
* Commissioners. 83/05/23. 23pp 18663.128 24X
Fiche:50-247,83/05/23,8305310055.

U Congressional/Executive Correspondence

8305240555 Forwards statement for inclusion in special proceeding testimony
WEISS,T House of Rep 83/05/20 PALLADINO,N Commissioners 1p
18576 025 24X Fiche 50-247,83/05/20,8305240555

--8305240558 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile Public safety should be top priority
WEISS,T House of Rep 83/05/19 3pp 18576 026 24X
Fiche 50-247,83/05/20,8305240555

8305310059 Commends State of NY commitment of resources & cooperation w/licensees & local govts to implement offsite emergency preparedness plan
PALLADINO,N J Commissioners 83/05/25 CUOMO,M M New York, State of 1p 18653 280 24X Fiche 50-247,83/05/25,8305310059

--8305310070 Expresses concern that addl actions required to satisfy mandates per 10CFR50 54(S)(1) State of NY Disaster Preparedness Commission will work w/utils until Rockland County completes emergency preparedness plans
CUOMO,M M New York, State of 83/05/25 PALLADINO,N J
Commissioners 3pp 18653 281 24X Fiche 50-247,83/05/25,
8305310059

DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO,C J Region 3, Office of Director 83/04/29 REED,C
Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010,83/04/29,
8305030336

--8305030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29 2pp 18297 139 24X
Fiche 50-010,83/04/29,8305030336

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D Q Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche.50-000,83/05/11,8305110034

8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR50,App E Emergency plans upgraded per NUREG-0737,Item III A 2 1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/11 FARRAR,D L
Commonwealth Edison Co 3pp 18423 040 24X Fiche 50-010,83/05/11,
8305120116

8305240245 Requests schedular exemptions allowing delay in implementing 10CFR50 48 requirements for installation of fire protection mods Request based on AE,manufacturer & const personnel anticipated implementation schedule
RYBAK,B Commonwealth Edison Co 83/05/18 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18548 204 24X
Fiche 50-000,83/05/18,8305240245

P. Operating license stage documents & correspondence

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D.Q Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441:120 24X
Fiche 50-000,83/05/02,8305020455

8305040446 Application for amend to Licenses DPR-19 & DPR-25,revising Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & requirement for isolation control rod drive pumps.
RYBAK,B Commonwealth Edison Co 83/05/02 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 18322 238. 24X
Fiche:50-237,83/05/02,8305040446

--8305040456 Proposed changes to Tech Specs to clarify min reactor pressure when conducting scram testing following refueling outage & revise requirement for isolation control rod drive pumps to apply only to single rod scram testing.
* Commonwealth Edison Co 83/05/02 2pp 18322 240 24X
Fiche 50-237,83/05/02,8305040446.

8305040520 Supplemental application for amend to Licenses DPR-19 & DPR-25, proposing changes to Tech Spec 4 3 B 1 b to verify nuclear response to control rod drive w/experienced uncoupling at power levels above 20%
RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321 244 24X
Fiche 50-237, 83/05/02, 8305040520

--8305040524 Proposed Tech Spec 4 3 B 1 b (Page 56) requiring verification of nuclear response to control rod drive w/experienced uncoupling at power levels above 20%
* Commonwealth Edison Co 83/05/02 3pp 18321 246 24X
Fiche 50-237, 83/05/02, 8305040520

8305040551 Application to amend Licenses DPR-19, DPR-25, DPR-29 & DPR-30, changing App A Tech Specs re economic generation control operation
RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321 279 24X
Fiche 50-000, 83/05/02, 8305040551

--8305040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes
* Commonwealth Edison Co 83/05/02 1p 18321 281 24X
Fiche 50-000, 83/05/02, 8305040551

8305130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods, per 830420 ltr Operation w/RPS mod, installed per 10CFR50 59 & w/o Tech Specs, will not compromise safe operation of facilities
RYBAK, B Commonwealth Edison Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18439 330 24X
Fiche 50-000, 83/05/06, 8305130209

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130038 Responds to 830316 request for addl info re NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-01B
RYBAK, B Commonwealth Edison Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X
Fiche 50-000, 83/05/10, 8305130038

8305120370 Forwards Accident Evaluation Branch SER input re NUREG-0737, Item III D 3 4, "Control Room Habitability " Sys acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/11 FARRAR, D L Commonwealth Edison Co 6pp 18432 295 24X Fiche 50-237, 83/05/11, 8305120370

--8305120374 Advises that licensee proposed program re NUREG-0737, Item III D 3 4, "Control Room Habitability," acceptable
MURPHY, D W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/23 HULMAN, L Q Accident Evaluation Branch 2pp 18432 301 24X Fiche 50-237, 83/05/11, 8305120370

8305200707 Forwards request for addl info on NUREG-0737, Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 FARRAR, D L Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000, 83/05/11, 8305200707

8305200186 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K 3 15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys
DIGGS, R M License Fee Management Branch 83/05/12 FARRAR, D L Commonwealth Edison Co 1p 18540 228 24X Fiche 50-000, 83/05/12, 8305200186

8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment GE affidavit per 10CFR2.790 received Westinghouse affidavit forthcoming
RYBAK, B. Commonwealth Edison Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18490 347 24X
Fiche 50-000, 83/05/13, 8305180376

8305260290 Commits to resolution of three open items re NUREG-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable
RYBAK, B Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18625 354 24X
Fiche 50-237, 83/05/19, 8305260290

8305270419 Notifies that response to 830316, 0510 & 11 requests for addl info re TMI Item II K 3 28, "Qualification of Automatic Depressurization Sys Accumulators," addressed in 830510 ltr
RYBAK, B Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18642 298 24X
Fiche 50-000, 83/05/23, 8305270419

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

8305310028 Advises that requirements of NUREG-0737, Item II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved, per 821220 & 801215 submittals
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/27 FARRAR, D L, Commonwealth Edison Co 7pp. 18653 213 24X Fiche 50-000, 83/05/27, 8305310028

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8304040268 Requests that insp program re IE Bulletin 80-13, "Cracking in Core Spray Spargers," be performed every 3 yrs in conjunction w/reactor vessel internal insp No abnormalities noted per subj bulletin
RYBAK, B Commonwealth Edison Co 83/03/25 KEPPLER, J. G. Region 3, Office of Director 2pp 17816 282 24X Fiche 50-237, 83/03/25, 8304040268

8305020467 Forwards IE Insp Repts 50-010/83-06, 50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/04/13 REED, C Commonwealth Edison Co 2pp 18283 073 24X Fiche 50-010, 83/04/13, 8305020467

--8305020480 IE Insp Repts 50-010/83-06, 50-237/83-07 & 50-249/83-06 on 830203-0315 No noncompliance noted Major areas inspected operational safety, maint, surveillance, licensee events, plant trips, refueling activities & refueling surveillance
TONQUE, T M , JORDAN, M J , STASEK, S Region 3, Office of Director, 83/04/12 16pp 18283 075 24X Fiche 50-010, 83/04/13, 8305020467

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche: 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche: 50-000, 83/04/22, 8303040023

8305100379 Forwards IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25, 0301, 09 & 14 & notice of violation
HIND, J A Division of Radiological & Materials Safety Programs 83/04/22 REED, C Commonwealth Edison Co 2pp 18377 328 24X
Fiche 50-237, 83/04/22, 8305100379

--8305100387 Notice of violation from insp on 830222-25, 0301, 09 & 14
HIND, J A Region 3, Office of Director 83/04/22 2pp 18377 330 24X Fiche. 50-237, 83/04/22, 8305100379

--8305100402 IE Insp Repts 50-237/83-08 & 50-249/83-07 on 830222-25, 0301, 09 & 14 Noncompliance noted DOT radiation limits exceeded & failure to follow health physics procedures
PAUL, R A., LOVENDALE, P. C , GREGER, L R Region 3, Office of Director. 83/04/21 12pp 18377 332 24X Fiche: 50-237, 83/04/22, 8305100379

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025.

8305020100 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04
BHAFER, W D Region 3, Office of Director 83/04/25 REED, C Commonwealth Edison Co 1p 18278 243 24X Fiche 50-010, 83/04/25, 8305020100

--8305020106 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-010/83-05, 50-237/83-05 & 50-249/83-04 Corrective actions Amend 71 reissued & incorporated into Tech Specs Corporate QA dept will audit accounting & followup sys
FARRAR, D L Commonwealth Edison Co 83/03/30 KEPPLER, J G Region 3, Office of Director 3pp 18278 244 24X
Fiche 50-010, 83/04/25, 8305020100

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305100092 Provides status of safe shutdown path support installation, per IE Bulletin 79-14 & util 830416 commitment Remaining accessible hanger & four inaccessible hangers will be completed by mid-May & during Fall 1983 outage, respectively
RYBAK, B Commonwealth Edison Co 83/04/28 KEPPLER, J G Region 3, Office of Director 2pp 18377 218 24X Fiche 50-237, 83/04/28, 8305100092

8305030336 Discusses IE Emergency Preparedness Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 on 830208 & forwards notice of deficiencies
PAPERIELLO, C J Region 3, Office of Director 83/04/29 REED, C
Commonwealth Edison Co 2pp 18297 137 24X Fiche 50-010, 83/04/29, 8305030336

--8305030348 Notice of deficiencies from insp on 830103-07 Public info brochures not distributed from Apr 1981 - Dec 1982 & emergency action levels not reviewed w/state & local govt since 810401
* Region 3, Office of Director 83/04/29 2pp 18297 139 24X
Fiche, 50-010, 83/04/29, 8305030336

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305100181 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24
SHAFER, W D Region 3, Office of Director 83/05/03 REED, C
Commonwealth Edison Co 1p. 18374 318 24X Fiche 50-010, 83/05/03, 8305100181.

--8305100190 Responds to NRC 830311 ltr re deficiencies noted in IE Insp Repts 50-010/82-17, 50-237/82-24 & 50-249/82-24, Corrective actions, written agreement, EPIP200-11 re PMF for Units 2 & 3 between Corps of Engineers & util to be revised
RYBAK, B Commonwealth Edison Co 83/04/11 KEPPLER, J G Region 3, Office of Director 4pp 18374 319 24X Fiche 50-010, 83/05/03, 8305100181

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04. Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation, " Svc list encl.
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc. 115pp. 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524, 003 24X Fiche 50-000, 83/05/11, 8303040034.

8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14, piping analysis to restore hot shutdown path piping sys to FSAR requirements by 830215, acceptable
SPESSARD, R L Division of Engineering 83/05/18 REED, C
Commonwealth Edison Co 2pp 18517 116 24X Fiche 50-000, 83/05/18, 8305200421

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B "
RYBAK, B Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2, 118pp 18578 001 24X
Fiche 50-000, 83/05/19, 8305250377

--8305250393 "GE-NEBS Electrical Penetration Assembly Qualification Program "
* Bechtel Corp 83/05/18 356pp 18578 175 24X
Fiche 50-000, 83/05/19, 8305250377

--8305250407 Rev 2 to Vols 1 & 2 to "Response to IE Bulletin 79-01B for Dresden Nuclear Power Station Unit 3 "
* Bechtel Corp 83/05/31 387pp 18580 226 24X
Fiche 50-000, 83/05/19, 8305250377

8305270395 Notifies that work to be performed on masonry walls, per IE Bulletin 80-11, "Masonry Wall Design, " will be completed on 830715 Thirty masonry walls required mods
RYBAK, B Commonwealth Edison Co 83/05/23 KEPPLER, J G Region 3, Office of Director 1p 18642 335 24X Fiche 50-237, 83/05/23, 8305270395

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

8 Reportable occurrences, LERs & related correspondence

8305060581 Forwards LER 83-015/03L-0
SCOTT, D J Commonwealth Edison Co 83/03/25 KEPPLER, J G. Region 3, Office of Director 1p 18349 049 24X Fiche 50-249, 83/03/25, 8305060581

--8305060594 LER 83-015/03L-0 on 830406, during normal operation w/DIG 287-1 in progress, pressure switch PS 3-1554 F would not operate at required pressure Caused by plugged instrument snubber Snubber cleaned & switch replaced
COYLE, L M Commonwealth Edison Co 83/04/25 Region 3, Office of Director 2pp 18349 050 24X Fiche 50-249, 83/03/25, 8305060581

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000, 83/04/19, 83052305/3

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000, 83/04/19, 8305230573

8305020246 Forwards LER 83-013/03L-0
SCOTT, D J Commonwealth Edison Co 83/04/21 KEPPLER, J G Region 3, Office of Director 1p 18277 265 24X Fiche. 50-249, 83/04/21, 8305020246

--8305020256 LER 83-013/03L-0 on 830322, while performing main steam line high flow surveillance, switch 3-261-21 tripped beyond Tech Spec limit Caused by particle on switch gear movement Switch cleaned & retested
ANANDAPPA, A Commonwealth Edison Co 83/04/18 Region 3, Office of Director. 2pp. 18277 266 24X Fiche 50-249, 83/04/21, 8305020246.

8305060563 Forwards LER 83-014/03L-0
SCOTT, D. J. Commonwealth Edison Co 83/04/22 KEPPLER, J G Region 3, Office of Director 1p 18348 259 24X Fiche 50-249, 83/04/22, 8305060563

--8305060571 LER 83-014/03L-0 on 830405, main steam line log radiation monitor 3A experienced loss of high voltage power causing monitor to go downscale Caused by burned out resistor on high voltage power supply Monitor 3A replaced
MERRITT, S Commonwealth Edison Co 83/04/21 Region 3, Office of Director 2pp 18348 260 24X Fiche 50-249, 83/04/22, 8305060563

8305240366 LER 83-016/01T-0 on 830504, station notified that hydraulic snubber 16, replaced in Feb 1983, attached on one and only Caused by insufficient personnel interface Work package procedures revised W/830517 ltr
COEN, R , SCOTT, D J Commonwealth Edison Co 83/05/17 KEPPLER, J G Region 3, Office of Director 4pp 18549 291 24X
Fiche 50-249, 83/05/17, 8305240366

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8305110223 Responds to 811031, 820702 & 830104 requests for exception from Table 1 of NUREG-0737, Suppl 1 requirements re location of emergency operations facility Exception granted
EISENHUT, D G Division of Licensing 83/04/29 UHRIG, R E, Florida Power & Light Co 2pp 18434, 334 24X Fiche 50-250, 83/04/29, 8305110223

8305130008 Informs that emergency offsite facility (EOF) operational w/exception of issuance of Procedure 1212 & installation of dedicated phone lines at near-site support ctr & EOF, per Generic Ltr 82-33
UHRIG, R E Florida Power & Light Co 83/05/09 EISENHUT, D G Division of Licensing 1p 18436 326 24X Fiche 50-250, 83/05/09, 8305130008

8305170104 Notification of 830515 meeting w/util in Bethesda, MD to discuss App R alternative shutdown capability details
MCDONALD, D G Operating Reactors Branch 1 83/05/10 VARGA, S A Operating Reactors Branch 1 2pp 18495 343 24X
Fiche, 50-250, 83/05/10, 8305170104

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305170546 Requests exemption from App R Section III G requiring reactor coolant pump lube oil collection sys to be capable of containing entire lube oil sys inventory Existing sys adequate
UHRIG, R E Florida Power & Light Co 83/05/12 EISENHUT, D. G Division of Licensing. 2pp 18468 029 24X Fiche 50-250, 83/05/12, 8305170546

8305200099 Confirms that Div of Safeguards will conduct safeguards regulatory effectiveness review on 830523-27 Review will evaluate overall effectiveness of security program List of review team members encl
VARGA, S A Operating Reactors Branch 1 83/05/12 UHRIG, R E Florida Power & Light Co 3pp 18540 332 24X
Fiche 50-250, 83/05/12, 8305200099

8305180568 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737, Item III A.2 1, complete Item closed
VARGA, S A Operating Reactors Branch 1 83/05/13 UHRIG, R E Florida Power & Light Co. 3pp 18505 295 24X
Fiche 50-250, 83/05/13, 8305180568

J Insurance & indemnity information

8305040208 Forwards Endorsement 64 to NELIA Policy NF-185 & Endorsement 54 to MAELU Policy NF-55
DUCK, J.R Marsh & McLennan, Inc. 83/04/29 SALTZMAN, J Assistant Director for State & Licensee Relations. 3pp 18323 213 24X
Fiche, 50-250, 83/04/29, 8305040208

P. Operating license stage documents & correspondence

8305050293 Forwards draft SER of NUREG-0737, Item II B 3, "Post-Accident Sampling " Eight of 11 criteria met. Criterion 2, 10 & 11 incomplete Addl info requested to complete review of PASS sys
VARGA, S A Operating Reactors Branch 1 83/04/22. UHRIG, R. E Florida Power & Light Co. 31pp 18352 074. 24X
Fiche: 50-250, 83/04/22, 8305050293

8305040672 Informs that Amend 91 to License DPR-31 & Amend 85 to License DPR-41 & Generic Ltr 83-07 requirements requiring action to initiate negotiations w/DOE re disposal of high level waste or spent nuclear fuel completed
VARGA, S A Operating Reactors Branch 1 83/04/25 UHRIG, R E Florida Power & Light Co 2pp 18336 256 24X
Fiche 50-250, 83/04/25, 8305040672

8305060653 Advises that addl testing in specific cases re use of energy balance technique & arching action for masonry wall qualification not warranted Decision based on technical info presented during & subsequent to 830120 meeting
VARGA, S A Operating Reactors Branch 1 83/04/26 UHRIG, R E Florida Power & Light Co 2pp 18358 360 24X
Fiche 50-250, 83/04/26, 8305060653

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305180854 Forwards safety evaluation of util submittals re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately
VARGA, S A Operating Reactors Branch 1 83/05/02 UHRIG, R E Florida Power & Light Co 2pp 18506 031 24X
Fiche 50-250, 83/05/02, 8305180854

--8305180856 Safety evaluation of util submittals re NUREG-0737, Items II F 1 4 re containment pressure monitor, II F 1 5 on containment water level monitor & II F 1 6 re containment hydrogen monitor. Licensee design acceptable
* Office of Nuclear Reactor Regulation, Director 83/05/02 5pp, 18506 033 24X Fiche 50-250, 83/05/02, 8305180854

8305090432 Forwards justification for continued operation w/electrical equipment in Categories I B & II A identified in Franklin Research Ctr technical evaluation rept per NRC 821213 & 830329 & 31 ltrs
UHRIG, R E Florida Power & Light Co 83/05/04 VARGA, S A Operating Reactors Branch 1 70pp 18363 250 24X
Fiche 50-250, 83/05/04, 8305090432

8305180541 Summarizes 830329-30 site visit re radiation protection & ALARA aspects of steam generator replacement effort
MCDONALD, D G. Operating Reactors Branch 1 83/05/04 UHRIG, R E. Florida Power & Light Co 6pp 18505 078 24X
Fiche 50-250, 83/05/04, 8305180541

8305100165 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETS re terrestrial biological & physical monitoring programs Request dtd 830210 re deletion of groundwater monitoring program withdrawn.
UHRIG, R E Florida Power & Light Co 83/05/05 EISENHUT, D G Division of Licensing 5pp 18374 345 24X Fiche 50-250, 83/05/05, 8305100165

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09. Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305260207 Forwards revised order confirming licensee commitments on NUREG-0737, Item II F.1, "Post-Accident Monitoring," per 830331 & 0411 ltrs Extended completion schedule to 840515 acceptable
VARGA, S. A Operating Reactors Branch 1 83/05/11 UHRIG, R E Florida Power & Light Co 3pp 18629 340 24X
Fiche 50-250, 83/05/11, 8305260207

--8305260211 Revised order confirming licensee commitments on post-TMI related issues
EISENHUT, D. G. Division of Licensing 83/05/11 Florida Power & Light Co. 9pp 18629 343 24X Fiche 50-250, 83/05/11, 8305260207.

8305170520 Application for amend to Licenses DPR-31 & 41 providing requirement for monthly walkdown of all accessible safety-related flow paths to verify correct valve position
UHRIG, R E. Florida Power & Light Co 83/05/13 EISENHUT, D. G. Division of Licensing 4pp 18467 252 24X Fiche 50-250, 83/05/13, 8305170520

--8305170525 Proposed changes to Tech Specs providing requirement for monthly walkdown of all accessible safety-related flowpaths to verify correct valve position.
* Florida Power & Light Co 83/05/13 4pp. 18467.256 24X
Fiche: 50-250, 83/05/13, 8305170520

8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppl 1 to NUREG-0737
UHRIG,R E Florida Power & Light Co 83/05/20 EISENHUT,D G
Division of Licensing 1p 18588 333 24X Fiche 50-000,83/05/20,
8305250472

--8305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan "
* Florida Power & Light Co 83/04/30 34pp 18588 334 24X
Fiche 50-000,83/05/20,8305250472

8305250519 Forwards schedule for qualification or replacement of equipment important to safety per 10CFR50 49 Items identified in technical evaluation rept as not within scope of IE Bulletin 79-01B being evaluated
UHRIG,R E Florida Power & Light Co 83/05/20 VARGA,S A
Division of Licensing 2ipp 18583 319 24X Fiche 50-250,83/05/20,
8305250519

8305310034 Forwards Class I & III fees for proposed license amend re monthly sys walkdowns
UHRIG,R E Florida Power & Light Co 83/05/26 EISENHUT,D G
Division of Licensing 1p 18653 309 24X Fiche 50-250,83/05/26,
8305310034

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319, 24X Fiche 50-000,83/03/21,8212060385

8305270129 Suppls 830203 response to notice of violation contained in IE Insp Repts 50-250/82-37 & 50-251/82-37 Corrective actions procedure revised to require clearance reviews prior to starting unit from cold or hot shutdown
UHRIG,R.E. Florida Power & Light Co 83/03/21 O'REILLY,J P
Region 2, Office of Director 2pp 18638 215 24X
Fiche 50-250,83/03/21,8305270129

8305270568 Forwards IE Insp Rept 50-251/83-08 on 830322-24 No noncompliance noted.
DANCE,H C. Division of Project & Resident Programs 83/04/05
UHRIG,R E Florida Power & Light Co 2pp 18646 338 24X
Fiche 50-251,83/04/05,8305270568

--8305270587 IE Insp Repts 50-250/83-08 & 50-251/83-08 on 830322-24 No noncompliance noted Major areas inspected hydrostatic testing of reconstituted steam generators
KRUG,H E Region 2, Office of Director JAPE,F Division of Engineering & Radiological Safety Programs 83/04/04 3pp
18646 340 24X Fiche,50-251,83/04/05,8305270568

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15. Consolidated Edison Co of New York, Inc 126pp 18435 155. 24X Fiche 50-000,83/04/15,8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025.

8305090085 Forwards safety evaluation & notice of granting of relief from inservice insp requirements for ASME Class 1,2 & 3 components,per 770225 request.
VARGA,S.A. Operating Reactors Branch 1 83/04/26 UHRIG,R E
Florida Power & Light Co. 3pp 18367 126 24X
Fiche 50-250,83/04/26,8305090085

--8305090091 Safety evaluation supporting requests for relief from inservice insp requirements for ASME Class 1,2 & 3 components.
* Office of Nuclear Reactor Regulation, Director 83/04/26 9pp
18367 129. 24X Fiche:50-250,83/04/26,8305090085

--8209150251 "Turkey Point Nuclear Generating Station Units 3 & 4 Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096. SAI-186-028-18
82/09/10. NRC - No Detailed Affiliation Given 35pp.
18367 138. 24X Fiche 50-000,83/04/26,8305090085.

--8305090104 Notice of granting of relief from ASME Section XI inservice insp requirements for ASME Class 1,2 & 3 components
VARGA,S A Operating Reactors Branch 1 83/04/26 2pp
18367 173 24X Fiche 50-250,83/04/26,8305090085

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305030392 Forwards tabulation of equipment qualification proprietary info listed by supplier ref in util response to IE Bulletin 79-01B,per 821213 request
UHRIG,R E Florida Power & Light Co 83/04/29 VARGA,S A
Operating Reactors Branch 1 2pp 18306 262 24X
Fiche 50-250,83/04/29,8305030392

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305120598 Discusses IE Insp Repts 50-250/83-06 & 50-251/83-06 on 830222-25 & 03-04 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY,J P Region 2, Office of Director 83/05/03 UHRIG,R E
Florida Power & Light Co 3pp 18441 333 24X
Fiche 50-250,83/05/03,8305120598

--8305120604 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted on 830201 & 02, self-reading dosimeter of individual found offscale & 11 individuals performed work in high radiation area
O'REILLY,J P Region 2, Office of Director 83/05/03 3pp
18441 336 24X Fiche 50-250,83/05/03,8305120598

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 249 24X Fiche 50-000,83/05/06,8303040033

8305100001 Submits steam generator repair program cleanliness rept Post-contamination & final loop insps & steam generator search & retrieval accomplished to meet primary & secondary side cleanliness commitments
UHRIG,R E Florida Power & Light Co 83/05/06 EISENHUT,D G
Division of Licensing 1p 18377 215 24X Fiche 50-250,83/05/06,
8305100001

8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted.
DANCE,H C Division of Project & Resident Programs 83/05/06
UHRIG,R E Florida Power & Light Co 2pp 18637 329 24X
Fiche. 50-250,83/05/06,8305270215

--8305270219 IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted Major areas inspected,followup on previous insp findings,IE bulletins,post-TMI implementation, surveillance testing & maint activities
VOOT-LOWELL,R , AGLES,J.A Region 2, Office of Director
JULIAN,C. Division of Project & Resident Programs 83/05/05
8pp 18637 331 24X Fiche 50-250,83/05/06,8305270215

8305270376 Forwards IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs. 83/05/06
UHRIG,R E Florida Power & Light Co 2pp 18643 001 24X
Fiche:50-250,83/05/06,8305270376

--8305270384 IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted Major areas inspected licensee program for keeping radiation doses ALARA
DEBS,B T , HOSEY,C M , BARR,K P Region 2, Office of Director 83/05/04 8pp 18643 003 24X Fiche 50-250,83/05/06,8305270376

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573

8305030405 EN-83-027 on 830503,notice of violation & proposed imposition of civil penalty in amount $40,000 to be issued for licensee failure to perform evaluations to ensure dose stds for workers exposed to radiation not exceeded
FLACK,E , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/04/28 1p 18306 312 24X Fiche 50-250,83/04/28, 8305030405

8305110487 Forwards LER 83-007/01T-0
WILLIAMS,J W Florida Power & Light Co 83/05/03 O'REILLY,J P Region 2, Office of Director 1p 18405 051 24X
Fiche 50-250,83/05/03,8305110487

--8305110496 LER 83-007/01T-0 on 830419,manual valves on steam supply lines to auxiliary feedwater pump turbines B & C discovered closed Caused by personnel error in rechanging tags Valves immediately locked open & pumps satisfactorily tested
BERRY,J E Florida Power & Light Co 83/05/03 Region 2, Office of Director 2pp 18405 052 24X Fiche 50-250,83/05/03, 8305110487

8305100098 PNO-II-83-034 on 830504,licensee issued news release re inoperability of two auxiliary feedwater pumps on 830419 Caused by valves inadvertently closed on 830414
JULIAN,C A , LEWIS,R C Region 2, Office of Director 83/05/05 2pp. 18377 255 24X Fiche 50-250,83/05/05,8305100098

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

F Security, medical, emergency & fire protection plans

8305110223 Responds to 811031,820702 & 830104 requests for exception from Table 1 of NUREG-0737,Suppl 1 requirements re location of emergency operations facility Exception granted
EISENHUT,D G Division of Licensing 83/04/29 UHRIG,R E Florida Power & Light Co 2pp 18434 334 24X Fiche 50-250,83/04/29, 8305110223

8305130008 Informs that emergency offsite facility (EOF) operational w/exception of issuance of Procedure 1212 & installation of dedicated phone lines at near-site support ctr & EOF,per Generic Ltr 82-33
UHRIG,R E Florida Power & Light Co 83/05/09 EISENHUT,D G Division of Licensing 1p 18436 326 24X Fiche 50-250,83/05/09, 8305130008

8305170104 Notification of 830515 meeting w/util in Bethesda,MD to discuss App R alternative shutdown capability details,
MCDONALD,D G Operating Reactors Branch 1 83/05/10 VARGA,S A Operating Reactors Branch 1 2pp 18495 343 24X
Fiche 50-250,83/05/10,8305170104

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305170546 Requests exemption from App R Section III O requiring reactor coolant pump lube oil collection sys to be capable of containing entire lube oil sys inventory Existing sys adequate
UHRIG,R E Florida Power & Light Co 83/05/12 EISENHUT,D G Division of Licensing 2pp 18468 029 24X Fiche 50-250,83/05/12, 8305170546

8305200099 Confirms that Div of Safeguards will conduct safeguards regulatory effectiveness review on 830523-27 Review will evaluate overall effectiveness of security program List of review team members encl
VARGA,S A Operating Reactors Branch 1 83/05/12 UHRIG,R E
Florida Power & Light Co 3pp 18540 352 24X
Fiche 50-250,83/05/12,8305200099

8305180568 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737,Item III A 2 1,complete Item closed
VARGA,S A Operating Reactors Branch 1 83/05/13 UHRIG,R E
Florida Power & Light Co 3pp 18505 295 24X
Fiche 50-250,83/05/13,8305180568

J Insurance & indemnity information

8305040208 Forwards Endorsement 64 to NELIA Policy NF-185 & Endorsement 54 to MAELU Policy MF-55
DUCK,J R Marsh & McLennan, Inc 83/04/29 SALTZMAN,J Assistant Director for State & Licensee Relations 3pp 18323 213 24X
Fiche 50-250,83/04/29,8305040208

P Operating license stage documents & correspondence

8305050293 Forwards draft SER of NUREG-0737,Item II B 3, "Post-Accident Sampling " Eight of 11 criteria met Criterion 2,10 & 11 incomplete Addl info requested to complete review of PASS sys
VARGA,S A Operating Reactors Branch 1 83/04/22 UHRIG,R E
Florida Power & Light Co 31pp 18352 074 24X
Fiche 50-250,83/04/22,8305050293

8305040672 Informs that Amend 91 to License DPR-31 & Amend 85 to License DPR-41 & Generic Ltr 83-07 requirements requiring action to initiate negotiations w/DOE re disposal of high level waste or spent nuclear fuel completed
VARGA,S A Operating Reactors Branch 1 83/04/25 UHRIG,R E
Florida Power & Light Co 2pp 18336 256 24X
Fiche 50-250,83/04/25,8305040672

8305060653 Advises that addl testing in specific cases re use of energy balance technique & arching action for masonry wall qualification not warranted Decision based on technical info presented during & subsequent to 830120 meeting
VARGA,S A Operating Reactors Branch 1 83/04/26 UHRIG,R E
Florida Power & Light Co 2pp 18358 360 24X
Fiche 50-250,83/04/26,8305060653

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02, Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305180854 Forwards safety evaluation of util submittals re NUREG-0737, Items II F 1 4,II F 1 5 & II F 1 6 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately
VARGA,S A Operating Reactors Branch 1 83/05/02 UHRIG,R E
Florida Power & Light Co 2pp 18506 031 24X
Fiche 50-250,83/05/02,8305180854

--8305180856 Safety evaluation of util submittals re NUREG-0737,Items II F.1 4 re containment pressure monitor,II F 1 5 on containment water level monitor & II F 1 6 re containment hydrogen monitor Licensee design acceptable
* Office of Nuclear Reactor Regulation, Director 83/05/02 5pp. 18506 033 24X Fiche 50-250,83/05/02,8305180854

8305090432 Forwards justification for continued operation w/electrical equipment in Categories I B & II A identified in Franklin Research Ctr technical evaluation rept per NRC 821213 & 830329 & 31 ltrs
UHRIG,R.E Florida Power & Light Co 83/05/04 VARGA,S A
Operating Reactors Branch 1. 70pp 18363 250 24X
Fiche 50-250,83/05/04,8305090432

8305180541 Summarizes 830329-30 site visit re radiation protection & ALARA aspects of steam generator replacement effort
MCDONALD, D Q Operating Reactors Branch 1 83/05/04 UHRIG, R E
Florida Power & Light Co 4pp 18505 078 24X
Fiche 50-250, 83/05/04, 8305180541

8305100165 Application to amend Licenses DPR-31 & DPR-41, deleting App B ETS re terrestrial biological & physical monitoring programs Request dtd 830210 re deletion of groundwater monitoring program withdrawn
UHRIG, R E Florida Power & Light Co 83/05/05 EISENHUT, D G
Division of Licensing 5pp 18374 345 24X Fiche 50-250, 83/05/05, 8305100165

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305160010 Advises that mods to undervoltage protection sys will not be completed until next refueling outage in Mar 1984, in response to NRC 821028 ltr re adequacy of electric distribution sys voltages
UHRIG, R E Florida Power & Light Co 83/05/11 VARGA, S A
Operating Reactors Branch 1 1p 18456 082 24X
Fiche 50-251, 83/05/11, 8305160010

8305260207 Forwards revised order confirming licensee commitments on NUREG-0737, Item II F 1, "Post-Accident Monitoring," per 830331 & 0411 ltrs Extended completion schedule to 840515 acceptable
VARGA, S A. Operating Reactors Branch 1 83/05/11 UHRIG, R E
Florida Power & Light Co 3pp 18629 340 24X
Fiche: 50-250, 83/05/11, 8305260207

--8305260211 Revised order confirming licensee commitments on post-TMI related issues
EISENHUT, D G Division of Licensing 83/05/11 Florida Power & Light Co 9pp 18629 343 24X Fiche 50-250, 83/05/11, 8305260207

8305170520 Application for amend to Licenses DPR-31 & 41 providing requirement for monthly walkdown of all accessible safety-related flow paths to verify correct valve position
UHRIG, R E Florida Power & Light Co 83/05/13 EISENHUT, D G
Division of Licensing 4pp 18467 252 24X Fiche 50-250, 83/05/13, 8305170520

--8305170525 Proposed changes to Tech Specs providing requirement for monthly walkdown of all accessible safety-related flowpaths to verify correct valve position
* Florida Power & Light Co 83/05/13 4pp 18467 256 24X
Fiche 50-250, 83/05/13, 8305170520

8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppl 1 to NUREG-0737
UHRIG, R E Florida Power & Light Co 83/05/20 EISENHUT, D G
Division of Licensing 1p 18588 333 24X Fiche 50-000, 83/05/20, 8305250472

--8305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan "
* Florida Power & Light Co 83/04/30 34pp 18588 334 24X
Fiche 50-000, 83/05/20, 8305250472

8305250519 Forwards schedule for qualification or replacement of equipment important to safety per 10CFR50 49 Items identified in technical evaluation rept as not within scope of IE Bulletin 79-01B being evaluated
UHRIG, R E Florida Power & Light Co 83/05/20 VARGA, S A
Division of Licensing 21pp 18583 319 24X Fiche 50-250, 83/05/20, 8305250519

8305310034 Forwards Class I & III fees for proposed license amend re monthly sys walkdowns
UHRIG, R, E Florida Power & Light Co 83/05/26 EISENHUT, D, G
Division of Licensing, 1p 18653 309 24X Fiche 50-250, 83/05/26, 8305310034

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co. of New York, Inc 112pp. 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385

8305270129 Suppls 830203 response to notice of violation contained in IE Insp Repts 50-250/82-37 & 50-251/82-37 Corrective actions procedure revised to require clearance reviews prior to starting unit from cold or hot shutdown
UHRIG, R E Florida Power & Light Co 83/03/21 O'REILLY, J P
Region 2, Office of Director 2pp 18638 215 24X
Fiche 50-250, 83/03/21, 8305270129

8305270568 Forwards IE Insp Rept 50-251/83-08 on 830322-24 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
UHRIG, R E Florida Power & Light Co 2pp 18646 338 24X
Fiche 50-251, 83/04/05, 8305270568

--8305270587 IE Insp Repts 50-250/83-08 & 50-251/83-08 on 830322-24 No noncompliance noted Major areas inspected hydrostatic testing of reconstituted steam generators
KRUG, H E Region 2, Office of Director JAPE, F Division of Engineering & Radiological Safety Programs 83/04/04 3pp 18646 340 24X Fiche 50-251, 83/04/05, 8305270568

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 118pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305090085 Forwards safety evaluation & notice of granting of relief from inservice insp requirements for ASME Class 1,2 & 3 components, per 770225 request
VARGA, S A Operating Reactors Branch 1 83/04/26 UHRIG, R E
Florida Power & Light Co 3pp 18367 126 24X
Fiche 50-250, 83/04/26, 8305090085

--8305090091 Safety evaluation supporting requests for relief from inservice insp requirements for ASME Class 1,2 & 3 components
* Office of Nuclear Reactor Regulation, Director 83/04/26 9pp 18367 129 24X Fiche 50-250, 83/04/26, 8305090085

--8209150251 "Turkey Point Nuclear Generating Station Units 3 & 4 Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-028-18 82/09/10 NRC - No Detailed Affiliation Given 35pp 18367 138 24X Fiche 50-000, 83/04/26, 8305090085

--8305090104 Notice of granting of relief from ASME Section XI inservice insp requirements for ASME Class 1,2 & 3 components
VARGA, S A Operating Reactors Branch 1 83/04/26 2pp 18367 173 24X Fiche 50-250, 83/04/26, 8305090085

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp. 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305030392 Forwards tabulation of equipment qualification proprietary info listed by supplier ref in util response to IE Bulletin 79-01B, per 821213 request
UHRIG, R E Florida Power & Light Co 83/04/29 VARGA, S A
Operating Reactors Branch 1 2pp 18306 262 24X
Fiche 50-250, 83/04/29, 8305030392

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305120598 Discusses IE Insp Repts 50-250/83-06 & 50-251/83-06 on 830222-25 & 03-04 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P Region 2, Office of Director 83/05/03 UHRIG, R E Florida Power & Light Co 3pp 18441 333 24X
Fiche 50-250, 83/05/03, 8305120598

--8305120604 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted on 830201 & 02, self-reading dosimeter of individual found offscale & 11 individuals performed work in high radiation area
O'REILLY, J P Region 2, Office of Director 83/05/03 3pp 18441 336 24X Fiche 50-250, 83/05/03, 8305120598

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305100001 Submits steam generator repair program cleanliness rept Post-contamination & final loop insps & steam generator search & retrieval accomplished to meet primary & secondary side cleanliness commitments
UHRIG, R E Florida Power & Light Co 83/05/06 EISENHUT, D G Division of Licensing 1p 18377 215 24X Fiche 50-250, 83/05/06, 8305100001

8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06 UHRIG, R E Florida Power & Light Co 2pp 18637 329 24X
Fiche 50-250, 83/05/06, 8305270215

--8305270219 IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted Major areas inspected followup on previous insp findings, IE bulletins, post-TMI implementation, surveillance testing & maint activities
VOGT-LOWELL, R , AGLES, J A Region 2, Office of Director JULIAN, C Division of Project & Resident Programs 83/05/05 8pp 18637 331 24X Fiche 50-250, 83/05/06, 8305270215

8305270376 Forwards IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06 UHRIG, R E Florida Power & Light Co 2pp 18643 001 24X
Fiche 50-250, 83/05/06, 8305270376

--8305270384 IE Insp Repts 50-250/83-10 & 50-251/83-10 on 830404-06 No noncompliance noted Major areas inspected licensee program for keeping radiation doses ALARA
DEBS, B Y , HOSEY, C M , BARR, K P Region 2, Office of Director 83/05/04 8pp 18643 003. 24X Fiche 50-250, 83/05/06, 8305270376

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co, of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305030168 Forwards third radiological progress rept for steam generator repair program
UHRIG, R E Florida Power & Light Co. 83/04/29 VARGA, S A Operating Reactors Branch 1. 1p 18300 211 24X
Fiche: 50-251, 83/04/29, 8305030168

--8305030173 "Steam Generator Repair Program," radiological progress rept for 830203-0331
* Florida Power & Light Co 83/04/29 30pp 18300 212 24X
Fiche 50-251, 83/04/29, 8305030168

S Reportable occurrences, LERs & related correspondence

8305030405 EN-83-027 on 830503, notice of violation & proposed imposition of civil penalty in amount $40,000 to be issued for licensee failure to perform evaluations to ensure dose stds for workers exposed to radiation not exceeded
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/04/28 1p 18306 312 24X Fiche 50-250, 83/04/28, 8305030405

8305100251 Forwards LER 83-003/01T-0
WILLIAMS, J W Florida Power & Light Co 83/05/02 O'REILLY, J P Region 2, Office of Director 1p 18374 064 24X
Fiche 50-251, 83/05/02, 8305100251

--8305100253 LER 83-003/01T-0 on 830417, during spiral loading of core, fuel assembly X-04 observed leaning across empty core ctr & resting against assembly W-51 Caused by assembly not properly seated on guide pins
BERRY, Z E Florida Power & Light Co 83/05/02 Region 2, Office of Director 3pp 18374 065 24X Fiche 50-251, 83/05/02, 8305100251

DOCKET 50-253 ACCELERATOR PULSED FAST ASSEMBLY

Q Inspection reports, IE Bulletins & correspondence

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15. Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240245 Requests schedular exemptions allowing delay in implementing 10CFR50 48 requirements for installation of fire protection mods Request based on AE, manufacturer & const personnel anticipated implementation schedule
RYBAK, B Commonwealth Edison Co 83/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18548 204 24X
Fiche 50-000, 83/05/18, 8305240245

8305250141 Informs that NUREG-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility item closed.
VASSALLO, D. B Operating Reactors Branch 2 83/05/18 FARRAR, D L Commonwealth Edison Co 3pp 18596 198 24X Fiche 50-254, 83/05/18, 8305250141

J Insurance & indemnity information

8305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Dresden Unit 1 & Endorsement 63 to NELIA Policy NF-201 & Endorsement 53 to MAELU Policy MF-64 for Zion Unit 1 W/o encl Quad Cities endorsements
OSTER, J Commonwealth Edison Co 83/05/13 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 18537 174 24X
Fiche 50-000, 83/05/13, 8305230500

P Operating license stage documents & correspondence

8305020597 Forwards safety evaluation on NUREG-0737, Item II B 2 2, "Plant Shielding Mods for Vital Area Access " Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/04/22 FARRAR, D Commonwealth Edison Co 5pp. 18284 222. 24X Fiche 50-254, 83/04/22, 8305020597

8305020458 Forwards info re NUREG-0737, Item II D 1, "Performance Testing of BWR Safety/Relief Valves," per NRC 830104 request Applicability of load combination info to BWR Owners Group generic test rept acceptable
RYBAK, B Commonwealth Edison Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18283 311 24X
Fiche 50-254, 83/04/27, 8305020458

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EIBENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040551 Application to amend Licenses DPR-19, DPR-25, DPR-29 & DPR-30, changing App A Tech Specs re economic generation control operation
RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18321 279 24X
Fiche 50-000, 83/05/02, 8305040551

--8305040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes
* Commonwealth Edison Co 83/05/02 1p 18321 281 24X
Fiche 50-000, 83/05/02, 8305040551

8305050043 Application for amend to Licenses DPR-29 & DPR-30, changing Tech Specs to limit control rod drive pump isolation from accumulators to single rod scram testing
RYBAK, B. Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18342 083 24X
Fiche 50-254, 83/05/02, 8305050043

8305130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods, per 830420 ltr Operation w/RPS mod, installed per 10CFR50 59 & w/o Tech Specs, will not compromise safe operation of facilities
RYBAK, B Commonwealth Edison Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18439 330 24X
Fiche 50-000, 83/05/06, 8305130209

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EIBENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170716 Advises that action required by 830120 Amend 85 to License DPR-29 & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
VASSALLO, D B Operating Reactors Branch 2 83/05/09 FARRAR, D L Commonwealth Edison Co 2pp 18496 250 24X Fiche 50-254, 83/05/09, 8305170716.

8305130038 Responds to 830316 request for addl info re NUREG-0737, Item II.K.3.28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-01B
RYBAK, B Commonwealth Edison Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X
Fiche 50-000, 83/05/10, 8305130038

8305200707 Forwards request for addl info on NUREG-0737, Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 FARRAR, D L Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000, 83/05/11, 8305200707

8305200186 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K.3.15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys
DIGGS, R M License Fee Management Branch 83/05/12 FARRAR, D L. Commonwealth Edison Co 1p 18540 228 24X Fiche 50-000, 83/05/12, 8305200186

8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment QE affidavit per 10CFR2 790 received. Westinghouse affidavit forthcoming
RYBAK, B. Commonwealth Edison Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18490 347 24X
Fiche 50-000, 83/05/13, 8305180376

8305310231 Advises that responses to NUREG-0737, Item III D 3 4, "Control Room Habitability," acceptable, completing action on item. Safety evaluation encl
VASSALLO, D. B. Licensing Branch 2. 83/05/17 FARRAR, D. L. Commonwealth Edison Co 4pp 18662 255 24X Fiche 50-254, 83/05/17, 8305310231.

8305240573 Notifies that NUREG-0737, Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl
VASSALLO, D B Operating Reactors Branch 2 83/05/18 FARRAR, D L Commonwealth Edison Co 7pp 18593 338 24X Fiche 50-254, 83/05/18, 8305240573

8305270419 Notifies that response to 830316, 0510 & 11 requests for addl info re TMI Item II K 3 28, "Qualification of Automatic Depressurization Sys Accumulators," addressed in 830510 ltr
RYBAK, B Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18642 298 24X
Fiche 50-000, 83/05/23, 8305270419

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

8305310028 Advises that requirements of NUREG-0737, Item II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved, per 821220 & 801215 submittals
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/27 FARRAR, D L Commonwealth Edison Co 7pp 18653 213 24X Fiche 50-000, 83/05/27, 8305310028

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305170167 Forwards response to 830411 notice of violation & proposed imposition of civil penalties re IE Insp Repts 50-254/82-26 & 50-265/82-26 Also includes remittance in amount of $60,000 re inoperable reactor protection sys subchannel
REED,C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 1p 18466 308 24X Fiche 50-254,83/05/09,8305170167

--8305170184 Responds to notice of violation noted in IE Insp Repts 50-254/82-26 & 50-265/82-26 on 821118-22 & 1213-16 Corrective actions Startup Procedure GOP 1-1 revised to include sign-off for verifying clearance of alarm
REED,C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 9pp 18466 309 24X Fiche 50-254,83/05/09,8305170167

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L, Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305310105 Forwards IE Insp Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance noted
SHAFER,W D Region 3, Office of Director 83/05/12 REED,C Commonwealth Edison Co 2pp 18658 031 24X Fiche 50-254,83/05/12, 8305310105

--8305310112 IE Insp Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance noted Major areas inspected operational safety,maint,surveillance,licensee monthly repts,regional requests,LERs & public info & special repts
CHRISSOTIMOS,N , WALKER,R D Region 3, Office of Director 83/05/10 8pp 18658 053 24X Fiche 50-254,83/05/12,8305310105

8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14,piping analysis to restore hot shutdown path piping sys to FSAR requirements by 830215,acceptable
SPESSARD,R L Division of Engineering 83/05/18 REED,C Commonwealth Edison Co 2pp 18517 116 24X Fiche 50-000,83/05/18, 8305200421

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040.

8305250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B "
RYBAK,B Commonwealth Edison Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2,118pp 18578 001 24X Fiche 50-000,83/05/19,8305250377

--8305250393 "GE-NEBS Electrical Penetration Assembly Qualification Program "
* Bechtel Corp 83/05/18 356pp 18578 175 24X Fiche 50-000,83/05/19,8305250377

--8305250413 Rev 2 to Vols 1-3 to "Response to IE Bulletin 79-01B,Quad Cities Nuclear Power Station Units 1 & 2 "
* Bechtel Corp 83/05/31 786pp 18581 253 24X Fiche 50-000,83/05/19,8305250377

8305270216 Ack receipt of 830509 transmittal forwarding full payment of proposed civil penalty Corrective actions will be examined during future insps
AXELRAD,J A Enforcement Staff 83/05/25 REED,C R Commonwealth Edison Co 2pp 18637 323 24X Fiche 50-254,83/05/25,8305270216

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170372 Forwards monthly operating repts for Apr 1983
KALIVIANAKIS,N Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement 1p 18466 055 24X Fiche 50-254,83/05/02,8305170372

--8305170376 Monthly operating repts for Apr 1983
MISAK,A Commonwealth Edison Co 83/05/02 21pp 18466 056. 24X Fiche 50-254,83/05/02,8305170372

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573

8305020142 Forwards LER 83-014/03L-0
KALIVIANAKIS,N Commonwealth Edison Co 83/04/20 KEPPLER,J G Region 3, Office of Director 1p 18284 056 24X Fiche 50-254,83/04/20,8305020142

--8305020154 LER 83-014/03L-0 on 830322,low electrolyte level found in station battery cell 100 Caused by crack in bottom corner of casing Normal loads transferred to Unit 2 250-volt battery on 830324 Cell replaced
IBEN,C A Commonwealth Edison Co 83/04/20 Region 3, Office of Director 3pp 18284 057 24X Fiche 50-254,83/04/20, 8305020142

8305030321 Forwards LER 83-015/03L-0
KALIVIANAKIS,N Commonwealth Edison Co 83/04/22 KEPPLER,J Region 3, Office of Director 1p 18297 048 24X Fiche 50-254,83/04/22,8305030321

--8305030333 LER 83-015/03L-0 on 830405,reactor bldg & control room ventilation sys isolated & standby gas treatment autostarted Caused by failure of relay coil 1701-100A Coil replaced Relay will be replaced
CLARK,D Q Commonwealth Edison Co 83/04/22 Region 3, Office of Director 2pp 18297 049 24X Fiche 50-254,83/04/22, 8305030321

8305060390 Forwards LER 83-016/03L-0
KALIVIANAKIS,N Commonwealth Edison Co 83/04/27 KEPPLER,J G Region 3, Office of Director 1p 18343 155 24X Fiche 50-254,83/04/27,8305060390

--8305060391 LER 83-016/03L-0 on 830331,reactor operator found RHR discharge pressure greater than 90 psig,exceeding Tech Spec range Caused by valve leaking from condensate transfer sys into RHR discharge piping Mod implemented
MISAK,A Commonwealth Edison Co 83/04/27 Region 3, Office of Director 3pp 18343 156 24X Fiche 50-254,83/04/27,8305060390.

8305130212 Forwards LER 83-019/03L-0
KALIVIANAKIS,N Commonwealth Edison Co 83/05/03 KEPPLER,J Region 3, Office of Director 1p 18440 085 24X Fiche 50-254,83/05/03,8305130212

--8305130220 LER 83-019/03L-0 on 830412,1A loop core spray discharge piping pressure indicated above Tech Specs Caused by operator failure to properly bleed down core spray discharge piping & failure of high pressure alarm to annunciate
HEBEL,C Commonwealth Edison Co 83/05/03 Region 3, Office of Director. 3pp 18440 086 24X Fiche 50-254,83/05/03,8305130212

8305240317 LER 83-017/03L-0 on 830412,RHR svc water pump 1-1001-65C taken out of svc to facilitate repair of broken coupling on RHR svc water vault room cooler 1-5745-C drain line Caused by overpressurization of piping W/830510 ltr
LEAVERTON,W , KALIVIANAKIS,N Commonwealth Edison Co 83/05/10 KEPPLER,J G Region 3, Office of Director 2pp 18548 195 24X Fiche 50-254,83/05/10,8305240317

8305240321 LER 83-018/03L-0 on 830412,excessively high discharge pressure & low flow observed from RHR svc water pump 1-1001-65C Caused by anti-rotation pin falling out of valve operator Pin replaced & screw tightened W/830510 ltr
REYNOLDS,S , KALIVIANAKIS,N Commonwealth Edison Co 83/05/10 KEPPLER,J G Region 3, Office of Director 4pp 18548 063 24X Fiche 50-254,83/05/10,8305240321

8305310142 LER 82-027/03L-1 on 830902,due to error in safety classification for procurement of main valve guides in electromatic relief valves,nonsafety-related parts ordered New administrative procedure written W/830516 ltr
KALIVIANAKIS,N., TIETZ,G Commonwealth Edison Co 83/05/16 KEPPLER,J G Region 3, Office of Director 3pp 18655 025 24X Fiche 50-254,83/05/16,8305310142

DOCKET 50-255 PALISADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8305020079 Forwards "Site Emergency Plan 830524-25 Exercise Scenario "
DEWITT,R B Consumers Power Co 83/04/11 KEPPLER,J G Region 3, Office of Director 1p 18279 255 24X Fiche 50-255,83/04/11, 8305020079

--8305020083 "Site Emergency Plan 830524-25 Exercise Scenario "
* Consumers Power Co PALEX-83 83/04/11 19pp 18279 256 24X Fiche 50-255,83/04/11,8305020079

8305020389 Forwards IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted
MILLER,J R Region 3, Office of Director 83/04/27 DEWITT,R B Consumers Power Co 2pp 18276 216 24X Fiche 50-255,83/04/27, 8305020389

--8305020397 IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted Major areas inspected security plan & implementing procedures,security organization - mgt & security program audit Details withheld (ref 10CFR73 21)
BELANGER,J.L , CHRISTOFFER,G , CREED,J R Region 3, Office of Director 83/04/27 2pp 18276 218 24X Fiche 50-255,83/04/27, 8305020389

8305120147 Forwards revised closed circuit television coverage & security sys mods resulting from implementation of technical support ctr Encls withheld (ref 10CFR73 21)
VANDEWALLE,D J Consumers Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 2pp 18427 157 24X
Fiche,50-255,83/05/05,8305120147

8305110074 Responds to 821105 ltr transmitting changes to suitability, training & qualification plan Changes acceptable except for items identified in encl Change re Item 4 requested per 10CFR50 90 Encl withheld (ref 10CFR73 21)
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/09
VANDEWALLE,D J Consumers Power Co 1p 18408 110 24X
Fiche,50-255,83/05/09,8305110074

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305200200 Responds to 830218 ltr providing responses to 821209 regulatory effectiveness review rept as result of 830328-0401 safeguards insp Determinations from 830401 safeguards insp listed.
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/12
VANDEWALLE,D J Consumers Power Co 2pp 18540 217 24X
Fiche 50-255,83/05/12,8305200200

8305240043 Supplx 820602 response to IE Insp Rept 50-255/82-03 Initial responsibility for communications to offsite monitoring team will be kept at technical support ctr until emergency operations facility activated
JOHNSON,B D. Consumers Power Co 83/05/18. KEPPLER,J G Region 3, Office of Director 1p 18549 124 24X Fiche 50-255,83/05/18, 8305240043

8305270007 Forwards safety evaluation accepting licensee plan for safe shutdown after fire in Fire Areas 1-4 or in area of auxiliary shutdown control panel.Plan complies w/10CFR50, App R,Section III G 3 & III L requirements
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/26
VANDEWALLE,D.J Consumers Power Co 2pp 18633 329 24X
Fiche 50-255,83/05/26,8305270007

--8305270010 Safety evaluation accepting licensee plan for safe shutdown after fire in Fire Areas 1-4 or in area of auxiliary shutdown control panel,per 10CFR50,App R,Section III G 3 & III L requirements
* Office of Nuclear Reactor Regulation, Director 83/05/26 15pp 18633 331. 24X Fiche,50-255,83/05/26,8305270007

8305310046 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737,Item III A 2.1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/27
VANDEWALLE,D J Consumers Power Co. 3pp 18653 149 24X
Fiche 50-255,83/05/27,8305310046

J Insurance & indemnity information

8305240290 Forwards Endorsement 78 to NELIA Policy NF-179 & Endorsement 67 to MAELU Policy NF-50
FROUNFELKER,R Consumers Power Co 83/05/20 SALIZMAN,J Office of Nuclear Reactor Regulation, Director 3pp 18548 112 24X
Fiche 50-255,83/05/20,8305240290

P Operating license stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305020066 Forwards SER based on review of NUREG-0737,Item III D 3 4, "Control Room Habitability," submitted in 801219 & 821019 ltrs Control room habitability sys acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 83/04/29
VANDEWALLE,D J Consumers Power Co 6pp 18276 236 24X
Fiche 50-255,83/04/29,8305020066

--8207080328 Notifies that control room meets requirements of SRP 2 2 1 - 2 2 2,2 2 3 & & 4 & General Design Criteria 4 & 19 Conclusions based on present plant sys & presumes implementation of effective HVAC mods by licensee
MURPHY,D W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/24 HULMAN,L G Accident Evaluation Branch 2pp 18276 242 24X Fiche 50-255,83/04/29, 8305020066

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305040312 Advises that action required by Amend 73,Paragraph 3 to License DPR-20 to initiate negotiations w/DOE re disposal of high level or spent nuclear fuel considered complete, based on pursuit of contract w/DOE
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/03
VANDEWALLE,D J Consumers Power Co 2pp 18323 291 24X
Fiche 50-255,83/05/03,8305040312

8305100170 Forwards check in response to 830425 ltr requesting remittance of fee for changes to Tech Specs submitted since 821112
JOHNSON,B D Consumers Power Co 83/05/03 CRUTCHFIELD,D Operating Reactors Branch 5 1p 18370 264 24X
Fiche 50-255,83/05/03,8305100170

8305100279 Forwards application for amend to License DPR-20,changing Tech Specs to allow surveillance tests that require cold shutdown conditions to be performed on refueling cycle frequency rather than current 18-month cycle
VANDEWALLE,D J Consumers Power Co 83/05/05 CRUTCHFIELD,D Operating Reactors Branch 5 1p 18371 272 24X
Fiche 50-255,83/05/05,8305100279

--8305100287 Application for amend to License DPR-20,changing Tech Specs to allow surveillance tests that require cold shutdown conditions to be performed on refueling cycle rather than current 18-month cycle
DEWITT,R B Consumers Power Co 83/05/05 9pp 18371 273 24X
Fiche 50-255,83/05/05,8305100279

--8305100291 Proposed Tech Spec change request re surveillance testing frequency
* Consumers Power Co. 83/05/05 19pp 18371 282 24X
Fiche 50-255,83/05/05,8305100279

8305160090 Forwards response to 830425 10-day info request on environ qualification of safety-related electrical equipment Qualification of Rosemount transmitters will be maintained by periodic replacement of degradable O-rings
TONER,K A Consumers Power Co 83/05/06 CRUTCHFIELD,D Operating Reactors Branch 5 30pp 18450 131 24X Fiche 50-255,83/05/06, 8305160090

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305240505 Forwards Rev 1 to CPC-2A "QA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112 Submittal serves as annual rept
VANDEWALLE,D J Consumers Power Co 83/05/11 KEPPLER,J G Region 3, Office of Director 2pp 18575 116 24X Fiche 50-000,83/05/11, 8305240505

--8305240565 Rev 1 to "QA Program Description for Operational Nuclear Power Plants "
REYNOLDS,J W , DEWITT,R B , COOK,J W Consumers Power Co CPC-2A R01 83/01/10 90pp 18575 118 24X Fiche 50-000,83/05/11, 8305240505

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020389 Forwards IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted
MILLER,J R Region 3, Office of Director 83/04/27 DEWITT,R B Consumers Power Co 2pp 18276 216 24X Fiche 50-255,83/04/27, 8305020389

--8305020397 IE Safeguards Insp Rept 50-255/83-07 on 830328-31 No noncompliance noted Major areas inspected security plan & implementing procedures,security organization - mgt & security program audit Details withheld (ref 10CFR73 21)
BELANGER,J L , CHRISTOFFER,G , CREED,J R Region 3, Office of Director 83/04/27 2pp 18276 218 24X Fiche 50-255,83/04/27, 8305020389

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305040475 Submits results of 821123 split sample from clean waste receiver tank for tritium,Sr-89,Sr-90 & gross beta activity analysis Open item in IE Insp Rept 50-255/82-22 on 821028 resolved
JOHNSON,B D Consumers Power Co 83/04/29 KEPPLER,J G Region 3, Office of Director 1p 18319 145 24X Fiche 50-255,83/04/29, 8305040475

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305200239 Forwards IE Insp Rept 50-255/83-06 on 830301-31 & notice of violation
SHAFER,W D Region 3, Office of Director 83/05/03 DEWITT,R B Consumers Power Co 2pp 18517 107 24X Fiche 50-255,83/05/03, 8305200239

--8305200244 Notice of violation from insp on 830301-31
SHAFER,W D Region 3, Office of Director 83/05/03 1p 18517 109 24X Fiche 50-255,83/05/03,8305200239

--8305200247 IE Insp Rept 50-255/83-06 on 830301-31 Noncompliance noted failure to follow instrument alarm operability surveillance test procedure
JORGENSEN,B L , HELLER,J K , BOYD,D C Region 3, Office of Director 83/04/28 6pp 18517 110 24X Fiche 50-255,83/05/03, 8305200239

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305170295 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-255/83-05
NORELIUS,C E Division of Project & Resident Programs 83/05/05 DEWITT,R B Consumers Power Co 1p 18465 294 24X Fiche 50-255,83/05/05,8305170295

--8305170300 Responds to NRC 830405 ltr re violations noted in IE Insp Rept 50-255/83-05 Corrective actions instruments inspected for proper valve alignment found in correct position Review of instrument calibr data ongoing
VANDEWALLE,D J Consumers Power Co 83/04/21 KEPPLER,J G Region 3, Office of Director 2pp 18465 295 24X Fiche 50-255,83/05/05,8305170295

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190178 Forwards IE Insp Rept 50-255/83-08 on 830328-29 No noncompliance noted
LITTLE,W S Region 3, Office of Director 83/05/06 DEWITT,R.B. Consumers Power Co 2pp 18502 211 24X Fiche 50-255,83/05/06, 8305190178

--8305190183 IE Insp Rept 50-255/83-08 on 830328-29 No noncompliance noted Major areas inspected support structure evaluations & analysis for safety injection & refueling water tank
KEATING,D E , DANIELSON,D H Region 3, Office of Director 83/05/05 3pp 18502 213 24X Fiche 50-255,83/05/06,8305190178

8305240020 Forwards IE Insp Rept 50-255/83-09 on 830406-08 & 11-12 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/05/09 DEWITT,R B Consumers Power Co 2pp 18549 016 24X Fiche 50-255,83/05/09,8305240020

--8305240026 IE Insp Rept 50-255/83-09 on 830406-08 & 11-12 No noncompliance noted Major areas inspected radiation protection program,including qualifications,audits,radiation protection procedures & status of TMI action items
LOVENDALE,P C , GREGER,L R Region 3, Office of Director 83/05/09 8pp 18549 018 24X Fiche 50-255,83/05/09,8305240020.

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.

8305200200 Responds to 830218 ltr providing responses to 821209 regulatory effectiveness review rept as result of 830328-0401 safeguards insp Determinations from 830401 safeguards insp listed
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/12
VANDEWALLE,D J Consumers Power Co 2pp 18540 217 24X Fiche 50-255,83/05/12,8305200200

8305240032 Forwards IE Insp Rept 50-255/83-10 on 830401-30 No noncompliance noted
SHAFER,W D Region 3, Office of Director 83/05/17 DEWITT,R B Consumers Power Co 2pp 18549 115 24X Fiche 50-255,83/05/17, 8305240032

--8305240037 IE Insp Rept 50-255/83-10 on 830401-30 No noncompliance noted Major areas inspected LERs,IE bulletins,operational safety,surveillance,maint,receipt of new fuel & previous insp findings
JORGENSEN,B L , HELLER,J K , BOYD,D C Region 3, Office of Director 83/05/13 7pp 18549 117 24X Fiche 50-255,83/05/17, 8305240032

8305240367 Ack receipt of 830404 ltr informing NRC of changes in steps taken to correct violations noted in IE Insp Rept 50-255/82-15 Changes examined during IE Insp Rept 50-255/83-10 & acceptable
SHAFER,W D Region 3, Office of Director 83/05/17 DEWITT,R.B Consumers Power Co 1p 18574 008 24X Fiche 50-255,83/05/17, 8305240367

--8305240371 Amends response to NRC 820823 ltr re violations noted in IE Insp Rept 50-255/82-15 Corrective actions Surveillance Test MO-24 changed from 1 wk after startup to prior to primary coolant temp of 325 F
JOHNSON, B. D Consumers Power Co 83/04/04 KEPPLER, J G Region 3, Office of Director 3pp 18574 009 24X Fiche 50-255, 83/05/17, 8305240367

8305240043 Suppls 820602 response to IE Insp Rept 50-255/82-03 Initial responsibility for communications to offsite monitoring team will be kept at technical support ctr until emergency operations facility activated
JOHNSON, B D Consumers Power Co 83/05/18 KEPPLER, J G Region 3, Office of Director 1p 18549 124 24X Fiche 50-255, 83/05/18, 8305240043

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305230270 "Active Mod Projects, Operating PWR, 1982 "
* Consumers Power Co 82/12/31 4pp 18576 332 24X Fiche 50-000, 82/12/31, 8305230270

8305100076 Forwards "Annual Environ Operating Rept, 1982 "
JOHNSON, B D Consumers Power Co 83/04/27 KEPPLER, J G Region 3, Office of Director 1p 18377 116 24X Fiche 50-255, 83/04/27, 8305100076

--8305100085 "Annual Environ Operating Rept, 1982 "
* Consumers Power Co 83/04/27 6pp 18377 117 24X Fiche 50-255, 83/04/27, 8305100076

8305110396 Forwards monthly operating rept for Apr 1983
KENNEDY, D M Consumers Power Co 83/05/05 NRC - No Detailed Affiliation Given 1p 18406 190 24X Fiche 50-255, 83/05/05, 8305110396

--8305110402 Monthly operating rept for Apr 1983
PATERSON, D A Consumers Power Co 83/05/05 4pp. 18406 191 24X Fiche 50-255, 83/05/05, 8305110396

8305240410 "1982 Radiological Environ Monitoring Rept (Addl Info)," revised Tables RBD-E-03A & RBD-3-03D
JOHNSON, B D Consumers Power Co 83/05/18 KEPPLER, J G Region 3, Office of Director 4pp 18573 357 24X Fiche 50-255, 83/05/18, 8305240410

B Reportable occurrences, LERs & related correspondence

8305020138 Forwards LER 83-022/01T-0
JOHNSON, B D Consumers Power Co 83/04/21 KEPPLER, J G, Region 3, Office of Director, 1p 18278, 214 24X Fiche 50-255, 83/04/21, 8305020138

--8305020145 LER 83-022/01T-0 on 830411, sample from T-82D safety injection tank showed boron concentration below Tech Spec limit Caused by minor leak past loop check valve & safety injection tank check valve or fill & drain valve.
* Consumers Power Co 83/04/21 Region 3, Office of Director, 1p. 18278 215 24X Fiche 50-255, 83/04/21, 8305020138

8305020173 Forwards LER 83-021/03L-0
JOHNSON, B D Consumers Power Co 83/04/21 KEPPLER, J. G Region 3, Office of Director, 1p. 18284 066 24X Fiche 50-255, 83/04/21, 8305020173

--8305020179 LER 83-021/03L-0 on 830326, sample from safety injection tank D showed boron concentration below 1,720 ppm Tech Spec limit, Caused by minor leakage past loop check valve & safety injection tank check valve or fill & drain valve.
* Consumers Power Co 83/04/21 Region 3, Office of Director 1p 18284 067 24X Fiche, 50-255, 83/04/21, 8305020173

8305030642 Telecopy RO: on 830423, safety injection tank inoperable due to routine sampling Additionally, another tank became inoperable due to low level
KRICH, R M. Consumers Power Co 83/04/25 Region 3, Office of Director 1p, 18305 284 24X Fiche 50-255, 83/04/25, 8305030642

8305030155 Telecopy RO on 830425, two safety injection tanks inoperable Caused by low level & routine testing Tank level restored
KRICH, R M Consumers Power Co 83/04/26 Region 3, Office of Director 1p 18306 331 24X Fiche 50-255, 83/04/26, 8305030155

8305100378 Forwards LER 83-023/01T-0
JOHNSON, B D Consumers Power Co 83/04/27 KEPPLER, J G Region 3, Office of Director 1p 18378 224 24X Fiche 50-255, 83/04/27, 8305100378

--8305100384 LER 83-023/01T-0 on 830415, during routine sampling of safety injection tank D, tank level fell below Tech Spec limit of 186 inches Caused by delayed fill operations when low flow alarm received for cooling water
* Consumers Power Co 83/04/27 Region 3, Office of Director 1p 18378 225 24X Fiche 50-255, 83/04/27, 8305100378

8305100396 Forwards LER 83-014/01T-0
JOHNSON, B D Consumers Power Co 83/04/27 KEPPLER, J G Region 3, Office of Director 1p 18377 356 24X Fiche 50-255, 83/04/27, 8305100396

--8305100403 LER 83-014/01T-0 on 830305, w/safety injection tank D (SIT) inoperable due to routine evolution, second SIT became inoperable due to low level Caused by leakage past fill & drain valve on SIT B while draining SIT D for sampling
* Consumers Power Co 83/04/27 Region 3, Office of Director 1p 18377 356 24X Fiche 50-255, 83/04/27, 8305100396

8305060477 Provides update to corrective actions re safety injection refueling water tank support structure discrepancies reported in LER 83-06 Tank design fix planned for 1985 refueling outage Quarterly insps will continue
VANDEWALLE, D J Consumers Power Co 83/04/28 KEPPLER, J G Region 3, Office of Director 2pp 18348 129 24X Fiche 50-255, 83/04/28, 8305060477

8305100250 Updated RO 83-06 evaluation of discrepancies between as-built & actual design of safety injection refueling water tank support structure indicated sufficient capacity to resist loadings Schedule for mods & design review submitted
VANDEWALLE, D J Consumers Power Co 83/04/28 KEPPLER, J G Region 3, Office of Director 2pp 18410 362 24X Fiche 50-255, 83/04/28, 8305100250

8305060388 Forwards LER 83-024/01T-0
JOHNSON, B D Consumers Power Co 83/04/29 KEPPLER, J G Region 3, Office of Director 1p 18343 154 24X Fiche 50-255, 83/04/29, 8305060388

--8305060393 LER 83-024/01T-0 on 830423, safety injection tanks T-82B & T-82D became inoperable due to low level & routine evolution, respectively Caused by leakage past fill & drain valve Fill & drain valves will be inspected
* Consumers Power Co 83/04/29 Region 3, Office of Director 1p 18343 154 24X Fiche 50-255, 83/04/29, 8305060388

8305100306 Telecopy RO on 830429, sample from T-82D (safety injection tank D) showed boron concentration below Tech Spec limit While attempting to increase boron level, addl safety injection of T-82B occurred T-82D & T-82B restored
KRICH, R M Consumers Power Co 83/05/02 Region 3, Office of Director 1p 18371 158 24X Fiche 50-255, 83/05/02, 8305100306

8305130140 Forwards LER 83-026/01T-0
JOHNSON, B D Consumers Power Co 83/05/09 KEPPLER, J G Region 3, Office of Director 1p 18440 045 24X Fiche 50-255, 83/05/09, 8305130140

--8305130145 LER 83-026/01T-0 on 830428, sample from T-82D (safety tank D) showed boron concentration below Tech Spec limit Caused by boron dilution due to minor leakage past loop check valve Primary coolant leak rate monitored
* Consumers Power Co 83/05/09 Region 3, Office of Director 1p 18440 046 24X Fiche 50-255, 83/05/09, 8305130140

8305130208 Forwards LER 83-027/01T-0
JOHNSON, B D Consumers Power Co 83/05/09 KEPPLER, J G Region 3, Office of Director, 1p 18440 069 24X Fiche 50-255, 83/05/09, 8305130208

--8305130214 LER 83-027/01T-0 on 830428, w/safety injection tank D T-82D inoperable, tank T-82B became inoperable due to low level Caused by leakage past fill & drain valve on tank B Fill & drain valves to be inspected & repaired
* Consumers Power Co 83/05/09 Region 3, Office of Director 1p, 18440 070 24X Fiche 50-255, 83/05/09, 8305130208

8305130225 Forwards LER 83-025/03L-0
JOHNSON, B D. Consumers Power Co 83/05/09 KEPPLER, J G Region 3, Office of Director 1p 18439 327 24X Fiche 50-255, 83/05/09, 8305130225

--8305130230 LER 83-025/03L-0 on 830410, sample from T-82c showed boron concentration below Tech Spec limit of 1720 ppm Caused by minor leakage past loop check valve & SIT check valve Primary coolant leak rate being closely monitored
* Consumers Power Co 83/05/09 Region 3, Office of Director
1p 18439 328 24X Fiche 50-255, 83/05/09, 8305130225

8305240011 LER 83-028/03L-0 on 830415, level of safety injection tank D reached Tech Spec limit of 198 inches Caused by minor leakage past loop check valve Leak rate being closely monitored Valves will be inspected W/830511 ltr
JOHNSON, B D Consumers Power Co 83/05/11 KEPPLER, J G Region 3, Office of Director 2pp 18549 026 24X Fiche 50-255, 83/05/11, 8305240011

8305200407 Ack receipt of 830428 ltr providing updated info re RO 83-06 & proposed schedule for mods to safety injection refueling water tank support structure per FSAR & ACI code Remedial work to be completed during 1985 refueling outage
SPESSARD, R L Region 3, Office of Director 83/05/17
VANDERHALLE, D J Consumers Power Co 2pp 18518 120 24X
Fiche 50-255, 83/05/17, 8305200407

8305270152 PNO-III-83-039 on 830323, util employee entered protected area through open & unmonitored entrance to receive whole body count Individual escorted out of area Region III will investigate
CREED, J , HIND, J Region 3, Office of Director 83/05/23 1p
18638 139 24X Fiche 50-255, 83/05/23, 8305270152

8305310168 LER 83-030/01T-0 on 830509, sample from safety injection tank T-82D showed boron concentration below Tech Spec limit Caused by minor leakage past loop check valve & safety injection tank check or fill & drain valve W/830523 ltr
*, JOHNSON, B D Consumers Power Co. 83/05/23 KEPPLER, J G Region 3, Office of Director 2pp 18652 333 24X Fiche 50-255, 83/05/23, 8305310168

8305310197 LER 83-031/01T-0 on 830509, w/safety injection tank (SIT) D (T-82D) inoperable due to routine evolution, second SIT (T-82B) became inoperable due to low level Caused by leakage past fill & drain valve on SIT B W/830523 ltr
JOHNSON, B D Consumers Power Co 83/05/23 KEPPLER, J G Region 3, Office of Director 2pp 18658 156 24X Fiche 50-255, 83/05/23, 8305310197

8305310202 LER 83-029/03L-0 on 830422, safety injection tank B reached Tech Spec limit of 198 inches Caused by minor leakage past loop check valve Primary coolant leak rate being monitored Tank restored to normal range W/830523 ltr
JOHNSON, B D Consumers Power Co 83/05/23 KEPPLER, J G Region 3, Office of Director 2pp 18651 021 24X Fiche 50-255, 83/05/23, 8305310202

DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2 790)
O'REILLY, J P Region 2, Office of Director 83/01/13 PARRIS, H G
Tennessee Valley Authority 3pp 18363 119 24X
Fiche 50-259, 83/01/13, 8305090191

8305040628 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18329 006 24X Fiche 50-259, 83/04/26, 8305040628

--8305040633 Forwards public version of revised emergency plan implementing procedures, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency
KAMMER, D S Tennessee Valley Authority 83/03/21 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18329 007
24X Fiche 50-259, 83/04/26, 8305040628

--8305040655 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency
* Tennessee Valley Authority 83/03/03 84pp 18329 008 24X
Fiche 50-259, 83/04/26, 8305040628

8305100234 Requests that Figures B 5-4B & B 5-13B be removed from updated FSAR & destroyed & replaced w/encl pages since figures contain info classified as safeguards info per 10CFR73
MILLS, L M Tennessee Valley Authority. 83/05/04. DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18373 266
24X Fiche, 50-259, 83/05/04, 8305100234

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G
Tennessee Valley Authority 3pp 18648 107 24X
Fiche 50-259, 83/05/18, 8305260177

J Insurance & indemnity information

8305160005 Forwards Endorsements 65 & 54 to NELIA Policy NF-198 & MAELU Policy MF-66, respectively
DUCK, J R Marsh & McLennan, Inc 83/05/03 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18456 059 24X
Fiche 50-259, 83/05/03, 8305160005

P Operating license stage documents & correspondence

8305040730 Discusses AEOD/E309, "Potential for Water Hammer Damage During Restart of RHR Pumps at BWR Nuclear Power Plants " Recommendations provided do not extend beyond procedural development & operator awareness
HELTEMES, C J Director's Office 83/04/22 EISENHUT, D Division of Licensing SPEIS, T Division of Safety Technology 1p
18328 067 24X Fiche 50-259, 83/04/22, 8305040730

--8305040737 Forwards AEOD/E309, "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Plants "
RUBIN, S Reactor Operations Analysis Branch 83/04/21
BEYFRIT, K V Reactor Operations Analysis Branch 1p 18683 319
24X Fiche 50-259, 83/04/22, 8305040730

--8305040745 "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Plants," AEOD engineering evaluation rept
RUBIN, S , LANIK, G Director's Office 83/04/30 29pp,
18328 069 24X Fiche, 50-259, 83/04/22, 8305040730

8305040511 Application for amend to Licenses DPR-33, DPR-52 & DPR-68 revising stated isolation logic for Group 7 isolation valves to reflect actual logic.
MILLS, L M Tennessee Valley Authority 83/04/28 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 2pp 18322, 038
24X Fiche 50-259, 83/04/28, 8305040511

--8305040517 Proposed changes to Tech Specs revising stated isolation logic for Group 7 isolation valves to reflect actual logic
* Tennessee Valley Authority 83/04/28 5pp 18322 040 24X
Fiche 50-259, 83/04/28, 8305040511

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180845 Advises that action required by Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste
VASSALLO, D B Operating Reactors Branch 2 83/05/09 PARRIS, H G
Tennessee Valley Authority 2pp 18506 018 24X
Fiche 50-259, 83/05/09, 8305180845

8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983, in response to NRC 830429 request
MILLS, L M Tennessee Valley Authority 83/05/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18437 008 24X
Fiche 50-259, 83/05/10, 8305130003

8305250136 Forwards request for addl info re NUREG-0737, Item II.K 3 28, "Qualification of ADS Accumulators " Info requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 PARRIS, H G.
Tennessee Valley Authority 3pp 18596 204 24X
Fiche: 50-259, 83/05/11, 8305250136

8305260187 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G
Tennessee Valley Authority 2pp 18648 099 24X
Fiche 50-259, 83/05/18, 8305260187

8305250473 Forwards info re status of environ qualification of equipment per 10CFR50 49(g) Qualification status table, schedule for qualifying deficient equipment & addl justification for continued operation encl
HAMMER, D S Tennessee Valley Authority 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 94pp 18585 110
24X Fiche 50-259, 83/05/20, 8305250473

8305260372 Requests remittance of balance due for review of 820921 application to amend Browns Ferry 1 Tech Specs re Cycle 5 MCPR values & 820623 application re physical security plan changes for Sequoyah 1 & 2
MILLER, W O License Fee Management Branch 83/05/20 PARRIS, H G
Tennessee Valley Authority 2pp 18647 284 24X
Fiche 50-000, 83/05/20, 8305260372

8305270021 Notifies that util will submit schedule for performing mods to Mark I containment drywell/wetwell vacuum breakers once calculations complete & mods identified, in response to Generic Ltr 83-08
MILLS, L M Tennessee Valley Authority 83/05/23 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 1p 18638 313 24X
Fiche: 50-259, 83/05/23, 8305270021

8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels " Criteria will be met
MILLS, L M Tennessee Valley Authority 83/05/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18638 306
24X Fiche 50-259, 83/05/24, 8305270030

G Inspection reports, IE Bulletins & correspondence

8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2 790)
O'REILLY, J P Region 2, Office of Director 83/01/13 PARRIS, H G,
Tennessee Valley Authority 3pp 18363 119 24X
Fiche 50-259, 83/01/13, 8305090191

8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33, 50-260/82-33 & 50-296/82-33 will be delayed until 830301
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 18638 071 24X
Fiche 50-259, 83/01/28, 8305270171

8305270177 Forwards 830111 response to notice of violation & proposed imposition of civil penalty erroneously submitted to JP O'Reilly W/o encl
MILLS, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 1p
18637 362 24X Fiche 50-259, 83/02/10, 8305270177

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270514 Forwards IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/30
PARRIS, H G. Tennessee Valley Authority 2pp 18646 182 24X
Fiche: 50-259, 83/03/30, 8305270514

--8305270526 IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19 No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performance & results
WHITENER, H L , JAPE, F Region 2, Office of Director 83/03/28
8pp. 18646 184 24X Fiche 50-259, 83/03/30, 8305270514

8305270202 Concurs w/util 830401 request for extension of commitment dates for responding to violations noted in IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16 until 830901
LEWIS, R C Division of Project & Resident Programs 83/04/07.
PARRIS, H G Tennessee Valley Authority 1p 18637 170 24X
Fiche: 50-259, 83/04/07, 8305270202

--8305270206 Advises that new full compliance date of 830901 required to complete review of procedures, preparation of revs & issuance of revised instructions in response to IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 1p 18637 171 24X
Fiche 50-259, 83/04/07, 8305270202

8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02
VERRELLI, D M Division of Project & Resident Programs 83/04/07
PARRIS, H G Tennessee Valley Authority 1p 18662 132 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270652 Responds to NRC 830210 ltr re violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 Corrective actions radiochemical lab manual Procedure 728 III 2 1 will be revised
MILLS, L M Tennessee Valley Authority 83/03/16 O'REILLY, J P
Region 2, Office of Director 3pp 18662 133 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270658 Forwards IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/02/10
PARRIS, H G Tennessee Valley Authority 2pp 18662 136 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270661 Notice of violation from insp on 830117-18
* Region 2, Office of Director 83/02/10 1p 18662 138 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270666 IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 Noncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis
COLLINS, T R , BARR, K P Region 2, Office of Director 83/02/10
3pp 18662 139 24X Fiche 50-259, 83/04/07, 8305270642

8305270653 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44
VERRELLI, D M Division of Project & Resident Programs 83/04/13
PARRIS, H G Tennessee Valley Authority 1p 18645 201 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270660 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 Corrective actions interim criteria for removal of waste oil & miscellaneous wastes from regulated areas developed
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 5pp 18645 202 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270664 Forwards IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/02/25
PARRIS, H G Tennessee Valley Authority 2pp 18645 207 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270665 Notice of violation from insp on 821115-19
* Region 2, Office of Director 83/02/25 2pp 18645 209 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270668 IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 Noncompliance noted licensee transferred licensed matl to unauthorized recipients & disposed of matl by unapproved means
DEBS, B T , BARR, K P Region 2, Office of Director 82/12/23
7pp. 18645 211 24X Fiche 50-259, 83/04/13, 8305270653

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270266 Forwards IE Insp Repts 50-259/83-13, 50-260/83-13 & 50-296/83-13 on 830329-30 No noncompliance noted Major areas inspected procedures, representative records & observations of demonstrated ultrasonic methodology W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/04/19
PARRIS, H G Tennessee Valley Authority 3pp 18641 326 24X
Fiche 50-259, 83/04/19, 8305270266

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305030625 Forwards addl info re masonry wall per IE Bulletin 80-11, in response to NRC 830128 ltr Results of wall displacement analysis will be submitted by 830715 W/three oversize drawings Aperture cards are in PDR
MILLS,L M Tennessee Valley Authority 83/04/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 18303 001 24X Fiche 50-259,83/04/22,8305030625

--8305030631 Rev 2 to BFN-50-D709, "Detailed Design Criteria for Reevaluation Criteria for Masonry Walls "
* Tennessee Valley Authority 82/03/26 162pp 18303 009 24X Fiche 50-259,83/04/22,8305030625

8305270510 Forwards IE Insp Repts 50-259/83-08,50-260/83-08 & 50-296/83-08 on 830329-31 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/22
PARRIS,H G Tennessee Valley Authority 2pp 18646 065 24X Fiche 50-259,83/04/22,8305270510

--8305270528 IE Insp Repts 50-259/83-08,50-260/83-08 & 50-296/83-08 on 830328-31 No noncompliance noted Major areas inspected mgt & administrative controls,status review of radiological environ monitoring program & insp of monitoring stations
CUNNINGHAM,A L , MONTGOMERY,D M Region 2, Office of Director 83/04/20 5pp 18646 067 24X Fiche 50-259,83/04/22,8305270510

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp. 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270345 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05.
LEWIS,R C Division of Project & Resident Programs 83/05/09
PARRIS,H,G Tennessee Valley Authority 1p 18642 079 24X Fiche 50-259,83/05/09,8305270345

--8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-259/83-05,50-260/83-05 & 50-296/83-05 Corrective actions-conduit mounting supports connected to conduits & supported per General Const Spec G-3.
MILLS,L M Tennessee Valley Authority 83/04/21 O'REILLY,J P Region 2, Office of Director 4pp 18642 080 24X Fiche 50-259,83/05/09,8305270345

--8305270362 Forwards IE Insp Repts 50-259/83-05,50-260/83-05 & 50-296/83-05 on 830126-0225 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/03/16.
PARRIS,H,G Tennessee Valley Authority. 2pp 18642.084. 24X Fiche 50-259,83/05/09,8305270345

--8305270368 Notice of violation from insp on 830126-0225
* Region 2, Office of Director 83/03/16 2pp 18642 086. 24X Fiche 50-259,83/05/09,8305270345

--8305270381 IE Insp Repts 50-259/83-05,50-260/83-05 & 50-296/83-05 on 830126-0225 Noncompliance noted violation of 10CFR50,App B, Criterion V in maint area & violation of Tech Spec re Surveillance Insp 2
PAULK,G L Region 2, Office of Director CANTRELL,F S Division of Project & Resident Programs 83/03/14 8pp 18642 088 24X Fiche 50-259,83/05/09,8305270345

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046.

B Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
BEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573

8305030501 Telecopy RO 50-259/83021 on 830424,130 fuel bundles unloaded from core & placed in high density fuel storage rack in spent fuel storage pool not tested for boron concentration Caused by inadequate procedures
COFFEY,J A Tennessee Valley Authority 83/04/25 Region 2, Office of Director 2pp 18294 168 24X Fiche 50-259,83/04/25, 8305030501.

8305050266 Forwards LER 83-020/01T-0
GREEN,H J Tennessee Valley Authority 83/04/29 O'REILLY,J P Region 2, Office of Director 1p 18338 044 24X Fiche 50-259,83/04/29,8305050266

--8305050272 LER 83-020/01T-0 on 830418,line A,B,C & D MSIVs exceeded allowable leakage rates Caused by deterioration of MSIV seating surfaces during operation Valves will be repaired prior to startup & MSIV improvement program implemented
HOLDER,E T Tennessee Valley Authority 83/04/29 Region 2, Office of Director 2pp. 18338 045 24X Fiche 50-259,83/04/29, 8305050266

8305100081 Forwards updated LER 82-030/03X-1
GREEN,H J Tennessee Valley Authority 83/05/03 O'REILLY,J P. Region 2, Office of Director 1p 18377 262 24X Fiche:50-259,83/05/03,8305100081

--8305100083 Updated LER 82-030/03X-1 on 820506,during normal operation, QE error noted in transient analysis for Cycle 5 Caused by procedural error Min critical power ratio increased by 0.02 (1.6%). Data constants will be changed
LOCHBAUM,D A Tennessee Valley Authority. 83/05/03 Region 2, Office of Director 3pp 18377 263 24X Fiche 50-259,83/05/03, 8305100081.

8305100012 Forwards updated LER 80-049/03X-1
GREEN,H J. Tennessee Valley Authority 83/05/04. O'REILLY,J P Region 2, Office of Director 1p 18377,154 24X Fiche. 50-259,83/05/04,8305100012

--8305100014 Updated LER 80-049/03X-1 on 800620,increase in pressure detected on shell side of RHR 1-C HX Caused by loose locking & full nuts on floating head due to thermal cycling & vibration Locking tabs installed on nuts
HOLDER,E.T. Tennessee Valley Authority 83/05/09 Region 2, Office of Director. 2pp 18377 155 24X Fiche:50-259,83/05/04, 8305100012

8305110355 Forwards LER 83-019/03L-0
GREEN, H J Tennessee Valley Authority 83/05/06 O'REILLY, J P
Region 2, Office of Director 1p 18406 079 24X
Fiche 50-259, 83/05/06, 8305110355

--8305110367 LER 83-019/03L-0 on 830410, smoke detector XS-39-66XM alarmed due to leakage of water into detector Source of water not determined Detector replaced & will be relocated to avoid leakage
MURPHY, D Tennessee Valley Authority 83/05/06 Region 2, Office of Director 2pp 18406 080 24X Fiche 50-259, 83/05/06, 8305110355

8305130085 Forwards LER 83-021/01T-0
GREEN, H J Tennessee Valley Authority 83/05/06 O'REILLY, J P
Region 2, Office of Director 1p 18436 016 24X
Fiche 50-259, 83/05/06, 8305130085

--8305130091 LER 83-021/01T-0 on 830424, 130 fuel bundles unloaded from core into high-density spent fuel storage rack (HDSFSR) did not have required post-installation boron test Caused by personnel failure to verify HDSFSR acceptability
WHITSON, D R Tennessee Valley Authority 83/05/06 Region 2, Office of Director 3pp 18436 017 24X Fiche 50-259, 83/05/06, 8305130085

8305200588 PNO-II-83-039 two intergranular stress corrosion cracks found on recirculation line end cap weld Cracks found during ultrasonic insp per IE Bulletin 83-02 Further weld insps planned
BLAKE, J. J., BUTCHER, R C Region 2, Office of Director 83/05/16
1p 18514 247 24X Fiche 50-259, 83/05/16, 8305200588

8305250402 Telecopy RO 50-259/83024 on 830517, design review of emergency diesel generator room ventilation sys capabilities revealed design temp limits of some electrical components may be exceeded Caused by error in heat dissipation data
COFFEY, J A. Tennessee Valley Authority 83/05/18 Region 2, Office of Director 2pp 18585 333 24X Fiche 50-259, 83/05/18, 8305250402

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of addl sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste
MILLER, W O. License Fee Management Branch 83/04/22 MILLS, L M.
Tennessee Valley Authority 2pp. 18309 193 24X
Fiche 50-000, 83/04/22, 8305030679

DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2.790).
O'REILLY, J.P Region 2, Office of Director 83/01/13 PARRIS, H. G
Tennessee Valley Authority. 3pp 18363 119 24X
Fiche 50-259, 83/01/13, 8305090191

8305040628 Releases public version of revised emergency plan implementing procedures
FELTON, J M. Division of Rules and Records. 83/04/26 Document Management Branch. 1p 18329 006 24X Fiche 50-259, 83/04/26, 8305040628

--8305040633 Forwards public version of revised emergency plan implementing procedures, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
KAMMER, D.B. Tennessee Valley Authority 83/03/21. DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p. 18329 007
24X Fiche 50-259, 83/04/26, 8305040628

--8305040655 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency.
* Tennessee Valley Authority 83/03/03. 84pp. 18329 008. 24X
Fiche. 50-259, 83/04/26, 8305040628.

8305100234 Requests that Figures 8 5-4B & 8.5-13B be removed from updated FSAR & destroyed & replaced w/encl pages since figures contain info classified as safeguards info per 10CFR73.
MILLS, L M Tennessee Valley Authority. 83/05/04 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director. 3pp 18373 266
24X Fiche. 50-259, 83/05/04, 8305100234

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G
Tennessee Valley Authority 3pp 18648 107 24X
Fiche 50-259, 83/05/18, 8305260177

J Insurance & indemnity information

8305160005 Forwards Endorsements 65 & 54 to NELIA Policy NF-198 & MAELU Policy MF-66, respectively
DUCK, J R Marsh & McLennan, Inc 83/05/03 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18456 059 24X
Fiche 50-259, 83/05/03, 8305160005

P Operating license stage documents & correspondence

8303300387 Forwards Amend 85 to License DPR-52, safety evaluation & notice of issuance & availability Amend revises Tech Specs to incorporate limiting conditions for operation during Cycle 5 & reflects procedural mods
CLARK, R J Operating Reactors Branch 2 83/03/11 PARRIS, H G
Tennessee Valley Authority 2pp 17753 211 24X
Fiche 50-260, 83/03/11, 8303300387

--8303300396 Amend 85 to License DPR-52, revising Tech Specs to incorporate limiting conditions for operation during Cycle 5 & reflecting design, equipment & procedural mods made during refueling outage
VASSALLO, D B Operating Reactors Branch 2 83/03/11 77pp
17753 213 24X Fiche 50-260, 83/03/11, 8303300387

--8303300401 Safety evaluation supporting Amend 85 to License DPR-52
* Office of Nuclear Reactor Regulation, Director 83/03/11
12pp 17753 290 24X Fiche 50-260, 83/03/11, 8303300387

--8303300408 Notice of issuance & availability of Amend 85 to License DPR-52
VASSALLO, D B Operating Reactors Branch 2 83/03/11 2pp
17753 302 24X Fiche: 50-260, 83/03/11, 8303300387

8305040511 Application for amend to Licenses DPR-33, DPR-52 & DPR-68 revising stated isolation logic for Group 7 isolation valves to reflect actual logic
MILLS, L M Tennessee Valley Authority 83/04/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18322 038
24X Fiche 50-259, 83/04/28, 8305040511

--8305040517 Proposed changes to Tech Specs revising stated isolation logic for Group 7 isolation valves to reflect actual logic
* Tennessee Valley Authority 83/04/28 5pp. 18322 040. 24X
Fiche 50-259, 83/04/28, 8305040511

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc. 50pp 18441 120. 24X
Fiche 50-000, 83/05/02, 8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche: 50-000, 83/05/09, 8305090659

8305180771 Requests permission for M Tokar, Core Performance Branch, to visit site on 830512 to discuss 821023-1101 test on fuel bundles Fuel failures caused by crud-induced localized corrosion
VASSALLO, D. B Operating Reactors Branch 2 83/05/09 PARRIS, H G
Tennessee Valley Authority 2pp 18506 057 24X
Fiche 50-260, 83/05/09, 8305180771

8305180845 Advises that action required by Amends 86, 83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste
VASSALLO, D B Operating Reactors Branch 2. 83/05/09 PARRIS, H G
Tennessee Valley Authority. 2pp 18506 018 24X
Fiche 50-259, 83/05/09, 8305180845

8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983, in response to NRC 830429 request
MILLS, L M Tennessee Valley Authority 83/05/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18437 008 24X
Fiche 50-259, 83/05/10, 8305130003

8305250136 Forwards request for addl info re NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulators " Info requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 PARRIS, H G
Tennessee Valley Authority 3pp 18596 204 24X
Fiche 50-259, 83/05/11, 8305250136

8305250473 Forwards info re status of environ qualification of equipment per 10CFR50 49(g) Qualification status table, schedule for qualifying deficient equipment & addl justification for continued operation encl
HAMMER, D S Tennessee Valley Authority 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 94pp 18585 110
24X Fiche 50-259, 83/05/20, 8305250473

8305270021 Notifies that util will submit schedule for performing mods to Mark I containment drywell/wetwell vacuum breakers once calculations complete & mods identified, in response to Generic Ltr 83-08
MILLS, L M Tennessee Valley Authority 83/05/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18638 313 24X
Fiche 50-259, 83/05/23, 8305270021

8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels " Criteria will be met
MILLS, L M Tennessee Valley Authority 83/05/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18638 306
24X Fiche 50-259, 83/05/24, 8305270030

G Inspection reports, IE Bulletins & correspondence

8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2 790)
O'REILLY, J P Region 2, Office of Director 83/01/13 PARRIS, H G
Tennessee Valley Authority 3pp 18363 119 24X
Fiche 50-259, 83/01/13, 8305090191

8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33, 50-260/82-33 & 50-296/82-33 will be delayed until 830301
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P
Region 2, Office of Director 1p 18638 071 24X
Fiche 50-259, 83/01/28, 8305270171

8305270177 Forwards 830111 response to notice of violation & proposed imposition of civil penalty erroneously submitted to JP O'Reilly W/o encl
MILLS, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement. 1p
18637 362 24X Fiche 50-259, 83/02/10, 8305270177

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270514 Forwards IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/30
PARRIS, H G Tennessee Valley Authority 2pp 18646 182 24X
Fiche 50-259, 83/03/30, 8305270514

--8305270526 IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19. No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performance & results
WHITENER, H L , JAPE, F Region 2, Office of Director 83/03/28
8pp 18646, 184 24X Fiche 50-259, 83/03/30, 8305270514

8305270202 Concurs w/util 830401 request for extension of commitment dates for responding to violations noted in IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16 until 830901
LEWIS, R. C. Division of Project & Resident Programs 83/04/07
PARRIS, H G Tennessee Valley Authority tp. 18637 170 24X
Fiche 50-259, 83/04/07, 8305270202

--8305270206 Advises that new full compliance date of 830901 required to complete review of procedures, preparation of revs & issuance of revised instructions in response to IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 1p 18637 171 24X
Fiche 50-259, 83/04/07, 8305270202

8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02
VERRELLI, D M Division of Project & Resident Programs 83/04/07
PARRIS, H G Tennessee Valley Authority 1p 18662 132 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270652 Responds to NRC 830210 ltr re violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 Corrective actions radiochemical lab manual Procedure 728 III 2 1 will be revised
MILLS, L M Tennessee Valley Authority 83/03/16 O'REILLY, J P
Region 2, Office of Director 3pp 18662 133 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270658 Forwards IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/02/10
PARRIS, H G Tennessee Valley Authority 2pp 18662 136 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270661 Notice of violation from insp on 830117-18
* Region 2, Office of Director 83/02/10 1p 18662 138 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270666 IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 Noncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis
COLLINS, T R , BARR, K P Region 2, Office of Director 83/02/10
3pp 18662 139 24X Fiche. 50-259, 83/04/07, 8305270642

8305270653 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44
VERRELLI, D M Division of Project & Resident Programs 83/04/13
PARRIS, H G Tennessee Valley Authority 1p 18645 201 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270660 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44, Corrective actions interim criteria for removal of waste oil & miscellaneous wastes from regulated areas developed
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 3pp 18645 202 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270664 Forwards IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 & notice of violation
O'REILLY, J P. Region 2, Office of Director 83/02/25.
PARRIS, H G Tennessee Valley Authority 2pp 18645 207 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270665 Notice of violation from insp on 821115-19
* Region 2, Office of Director 83/02/25 2pp 18645 209 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270668 IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 Noncompliance noted licensee transferred licensed matl to unauthorized recipients & disposed of matl by unapproved means
DEBS, B. T , BARR, K P Region 2, Office of Director 82/12/23
7pp 18645 211 24X Fiche 50-259, 83/04/13, 8305270653

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp. 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270266 Forwards IE Insp Repts 50-259/83-13, 50-260/83-13 & 50-296/83-13 on 830329-30 No noncompliance noted Major areas inspected procedures, representative records & observations of demonstrated ultrasonic methodology W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/04/19
PARRIS, H G Tennessee Valley Authority 3pp 18641 326. 24X
Fiche 50-259, 83/04/19, 8305270266.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305030625 Forwards addl info re masonry wall per IE Bulletin 80-11, in response to NRC 830128 ltr Results of wall displacement analysis will be submitted by 830715 W/three oversize drawings Aperture cards are in PDR
MILLS, L. M Tennessee Valley Authority 83/04/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 18303 001 24X Fiche 50-259, 83/04/22, 8305030625

--8305030631 Rev 2 to DFN-50-0709, "Detailed Design Criteria for Reevaluation Criteria for Masonry Walls "
* Tennessee Valley Authority 82/03/26 162pp 18303 008 24X Fiche 50-259, 83/04/22, 8305030625

8305270510 Forwards IE Insp Repts 50-259/83-08, 50-260/83-08 & 50-296/83-08 on 830329-31 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/22
PARRIS, H G Tennessee Valley Authority 2pp 18646 065 24X Fiche 50-259, 83/04/22, 8305270510

--8305270528 IE Insp Repts 50-259/83-08, 50-260/83-08 & 50-296/83-08 on 830329-31 No noncompliance noted Major areas inspected mgt & administrative controls, status review of radiological environ monitoring program & insp of monitoring stations
CUNNINGHAM, A. L , MONTGOMERY, D M Region 2, Office of Director 83/04/20. 5pp 18646 067 24X Fiche 50-259, 83/04/22, 8305270510

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche, 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation. " Svc list encl,
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06, Consolidated Edison Co of New York, Inc. 115pp 18523, 248 24X Fiche 50-000, 83/05/06, 8303040033,

8305270345 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05
LEWIS, R C, Division of Project & Resident Programs, 83/05/09
PARRIS, H G Tennessee Valley Authority. 1p. 18642 079 24X Fiche, 50-259, 83/05/09, 8305270345

--8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 Corrective actions: conduit mounting supports connected to conduits & supported per General Const Spec G-3
MILLS, L M Tennessee Valley Authority, 83/04/21 O'REILLY, J P Region 2, Office of Director 4pp 18642 080 24X Fiche: 50-259, 83/05/09, 8305270345

--8305270362 Forwards IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 on 830126-0225 & notice of violation
LEWIS, R C Division of Project & Resident Programs, 83/03/16
PARRIS, H. G Tennessee Valley Authority 2pp. 18642 084 24X Fiche: 50-259, 83/05/09, 8305270345.

--8305270368 Notice of violation from insp on 830126-0225
* Region 2, Office of Director 83/03/16 2pp 18642 086 24X Fiche 50-259, 83/05/09, 8305270345

--8305270381 IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 on 830126-0225 Noncompliance noted violation of 10CFR50, App B, Criterion V in maint area & violation of Tech Spec re Surveillance Insp 2
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/03/14 8pp 18642 088 24X Fiche 50-259, 83/05/09, 8305270345

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

B Reportable occurrences, LERs & related correspondence

8305050238 Forwards LER 83-014/03L-0
GREEN, H J Tennessee Valley Authority 83/04/28 O'REILLY, J P Region 2, Office of Director 2pp 18337 299 24X Fiche: 50-260, 83/04/28, 8305050238

--8305050245 LER 83-014/03L-0 on 830330 air operator on main steam relief valve PCV-1-180 found assembled incorrectly Caused by failure to follow reassembly procedures Valve repaired & insp procedure clarified
HOLDER, E T Tennessee Valley Authority 83/04/28 Region 2, Office of Director 2pp 18337 300 24X Fiche 50-260, 83/04/28, 8305050238

8305100031 Forwards LER 83-015/03L-0
GREEN, H J Tennessee Valley Authority 83/05/04 O'REILLY, J P Region 2, Office of Director 1p 18377 144 24X Fiche 50-260, 83/05/04, 8305100031

--8305100036 LER 83-015/03L-0 on 830406, drywell pressure switch 2-PS-64-57A found operating above Tech Spec limit Caused by setpoint drift Static O-ring switch, Model 12N-AA4, recalibr, tested & returned to svc
BASS, G W Tennessee Valley Authority 83/05/04 Region 2, Office of Director 3pp 18377 145 24X Fiche 50-260, 83/05/04, 8305100031

8305100285 Forwards LER 83-016/03L-0
GREEN, H J Tennessee Valley Authority 83/05/04 O'REILLY, J P Region 2, Office of Director 1p 18371 243 24X Fiche, 50-260, 83/05/04, 8305100285

--8305100292 LER 83-016/03L-0, on 830406, drywell pressure switches 2-PS-64-58D, SW 1 & 2 found to operate at setting exceeding Tech Spec limit Caused by setpoint drift Static O-ring switch 12N-AA4 recalibr
BASS, G W Tennessee Valley Authority 83/05/04 Region 2, Office of Director 3pp 18371 244 24X Fiche 50-260, 83/05/04, 8305100285

8305130131 Forwards LER 83-017/03L-0
GREEN, H J Tennessee Valley Authority 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18437 202 24X Fiche 50-260, 83/05/05, 8305130131

--8305130141 LER 83-017/03L-0 on 830409, hydrogen analyzer B, H2AN-76-104 declared inoperable due to receipt of loss-of-flow light 76-88 Caused by moisture collecting in sample lines Lines blown down & dried Moisture collection devices to be added.
LITTLE, G V Tennessee Valley Authority 83/05/05 Region 2, Office of Director 2pp 18437 203 24X Fiche, 50-260, 83/05/05, 8305130131

8305170330 Forwards LER 83-020/03L-0
GREEN, H J Tennessee Valley Authority 83/05/09 O'REILLY, J P Region 2, Office of Director 1p 18465 141 24X Fiche 50-260, 83/05/09, 8305170330

--8305170340 LER 83-020/03L-0 on 830410,during power maneuvers for recirculation sys testing,calculated R factor was less than R setpoint for 2 h 45 minutes Caused by power peaking due to xenon transients from previous power changes
WINGO,M D Tennessee Valley Authority 83/05/09 Region 2, Office of Director 2pp 18465 142 24X Fiche 50-260,83/05/09, 8305170330

8305200420 Forwards LER 83-018/03L-0
GREEN,H J Tennessee Valley Authority 83/05/11 O'REILLY,J P Region 2, Office of Director 1p 18517 159 24X Fiche 50-260,83/05/11,8305200420

--8305200426 LER 83-018/03L-0 on 830413,core max fraction of critical power determined that min critical power ratio exceeded Caused by withdrawal of deep control rods Control rods inserted to reduce core max fraction of critical power
STILES,H Tennessee Valley Authority 83/05/11 Region 2, Office of Director 2pp 18517 160 24X Fiche 50-260,83/05/11, 8305200420

8305200288 Forwards LER 83-019/03L-0
GREEN,H J Tennessee Valley Authority 83/05/12 O'REILLY,J P Region 2, Office of Director 1p 18516 267 24X Fiche 50-260,83/05/12,8305200288

--8305200300 LER 83-019/03L-0 on 830413,w/unit at 72 9% power returning to rated power,calculated R factor less than R setpoint for 4 h 44 minutes Caused by local power peaking Setting adjusted
NOVE,E D Tennessee Valley Authority 83/05/12 Region 2, Office of Director 2pp 18516 268 24X Fiche 50-260,83/05/12, 8305200288

8305250357 LER 83-021/03L-0,on 830423,calculated R factor less than flow bias Tech Spec setpoint Caused by pulling group of eight rods four notches to fully withdrawn position Tech Spec revs submitted W/830520 ltr
LOCHBAUM,D A , GREEN,H J Tennessee Valley Authority 83/05/20 O'REILLY,J P Region 2, Office of Director 3pp 18585 352 24X Fiche 50-260,83/05/20,8305250357

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of addl sum to complete payment of B00731 & 1124 amend applications to permit storage of low level radwaste
MILLER,W O License Fee Management Branch 83/04/22 MILLS,L M Tennessee Valley Authority 2pp 18309 193 24X Fiche 50-000,83/04/22,8305030679.

DOCKET 50-261 H B ROBINSON PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305270390 Forwards IE Insp Rept 50-261/83-09 on 830305-0410 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/26 UTLEY,E E Carolina Power & Light Co 2pp 96207 294 24X Fiche 50-261,83/04/26,8305270390

--8305270401 IE Insp Rept 50-261/83-09 on 830305-0410 No noncompliance noted Major areas inspected Tech Spec compliance,plant tour, operations performance,ROs,housekeeping,site security, surveillance & maint activities & IE bulletin followup
WEISE,B , BEMIS,P , HARDIN,A K Region 2, Office of Director 83/04/25 12pp 18643 059 24X Fiche 50-261,83/04/26,8305270390

8305110618 Notification of 830510 meeting w/util in Bethesda,MD to discuss App R exemption request technical submittal schedule.
REGUA,G Operating Reactors Branch 1 83/05/05 VARGA,S A Operating Reactors Branch 1 2pp 18415 361 24X Fiche:50-261,83/05/05,8305110618.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X Fiche:50-000,83/05/11,8305110034

8305170048 Advises that NUREG-0737,Item III A 2 1, "Amend 10CFR50 & App E," considered complete following comprehensive 2-wk onsite emergency preparedness appraisal
VARGA,S A Operating Reactors Branch 1 83/05/11 UTLEY,E E Carolina Power & Light Co 3pp 18494 181 24X Fiche:50-261,83/05/11,8305170048

G Adjudicatory correspondence

8305030486 Objection to 830412 order following special prehearing conference & motion for referral NRC licensee failed to cite precedent for disallowing Contentions 4,5 & 9 Certificate of Svc encl
MATTHEWS,B A Affiliation Unknown 83/04/26 Atomic Safety and Licensing Board Panel 13pp 18306 201 24X Fiche 50-261,83/04/26, 8305030486

8305030493 Informs that conference call no longer required to determine licensee intentions re sleeving of steam generator tubes
MATTHEWS,B A Affiliation Unknown 83/04/30 MARGULIES,M B Atomic Safety and Licensing Board Panel 1p 18295 303 24X Fiche 50-261,83/04/30,8305030493

8305090470 Request for authorization to reply to Hartsville Group 830426 objection to 830412 order & motion for denial of Contentions 4,5 & 9 Certificate of Svc encl
TROWBRIDGE,Q.F Carolina Power & Light Co TROWBRIDGE,Q F Shaw, Pittman, Potts & Trowbridge 83/05/04 Atomic Safety and Licensing Board Panel 5pp 18360 258 24X Fiche 50-261,83/05/04, 8305090470

8305100413 Grants unopposed applicant request for permission to reply on 830511 to objections to ASLB special prehearing conference order
MARGULIES,M B Atomic Safety and Licensing Board Panel 83/05/06, 1p 18378 079 24X Fiche 50-261,83/05/06,8305100413

8305130092 First set of interrogatories to Hartsville Group on Contention 3 re cost-ineffectiveness of proposed steam generator repair Responses due within 45 days Certificate of Svc encl Related correspondence
TROWBRIDGE,Q F Carolina Power & Light Co TROWBRIDGE,Q.F. Shaw, Pittman, Potts & Trowbridge 83/05/11 Hartsville Group, 6pp. 18437 213 24X Fiche 50-261,83/05/11,8305130092

8305130137 Notice of appearance in proceeding Certificate of Svc encl.
RIDGWAY,D A Shaw, Pittman, Potts & Trowbridge 83/05/11 4pp 18437 187 24X Fiche 50-261,83/05/11,8305130137

8305130162 Response to Hartsville Group 830426 objection to ASLB 830412 order following special prehearing conference & motion for referral Hartsville failed to challenge foundation of ASLB rulings rejecting contentions W/Certificate of Svc
TROWBRIDGE,Q F Carolina Power & Light Co TROWBRIDGE,Q.F Shaw, Pittman, Potts & Trowbridge 83/05/11 Atomic Safety and Licensing Board Panel 14pp 18437:339 24X Fiche.50-261,83/05/11, 8305130162

8305170555 Response opposing Hartsville Group 830426 objection to ASLB 830412 special prehearing conference order No bases furnished for assumption util cannot hire workers to handle proposed steam generator replacement W/Certificate of Svc.
KARMAN,M Hearing Branch 1 83/05/16 Atomic Safety and Licensing Board Panel 7pp 18468 161 24X Fiche 50-261,83/05/16, 8305170555

8305180299 Motion to require NRC responses to Hartsville Group interrogatories & requests to produce Answers necessary for proper decision & not reasonably obtainable from any other source Related correspondence
MATTHEWS,B.A Hartsville Group 83/05/16 Atomic Safety and Licensing Board Panel 1p 18490 344 24X Fiche 50-261,83/05/16, 8305180299

8305180452 First set of interrogatories & requests to produce Affidavit of Svc encl.
MATTHEWS,B.A Hartsville Group 83/05/16 Office of the Executive Legal Director. 38pp 18486.067. 24X
Fiche:50-261,83/05/16,8305180452

8305270014 Order disallowing Hartsville Group 830426 objections to ASLB 830412 order denying request for admission of Contentions 4,5 & 9 Request for referral of Contention 4 to ASLAB denied.Contention does not involve policy issue
MARGULIES,M B Atomic Safety and Licensing Board Panel 83/05/25, Hartsville Group 7pp 18638 318 24X Fiche 50-261,83/05/25, 8305270014

H General correspondence

8305030477 Requests that JC Ruoff be added to svc list for proceeding.
MATTHEWS,B A. Affiliation Unknown 83/04/30 MARGULIES,M,B Atomic Safety and Licensing Board Panel 1p 18308 246 24X Fiche. 50-261,83/04/30,8305030477

8305200600 Requests plant general mgr be placed on distribution list to receive correspondence from Div of Licensing concerning facility
ZIMMERMAN, S R Carolina Power & Light Co 83/05/17 EISENHUT, D G
Division of Licensing 1p 18514 113 24X Fiche 50-261, 83/05/17, 8305200600

J. Insurance & indemnity information

8305160045 Forwards Endorsement 73 to NELIA Policy NF-180
BARHAM, C D Carolina Power & Light Co 83/05/02 SALTZMAN, J
Antitrust & Economic analysis Branch (Utility Finance) 2pp
18453 016 24X Fiche 50-261, 83/05/02, 8305160045

P Operating license stage documents & correspondence

8305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
SMITH, S H Carolina Power & Light Co 83/03/22 TOURTELLOTTE, J
Regulatory Reform Task Force 13pp 18543 277 24X
Fiche 50-000, 83/03/22, 8305230283

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305020453 Forwards addl info per NRC 821210 request re Generic Ltr 82-28 concerning inadequate core cooling sys Procurement of reactor vessel level instrumentation sys completed Sys installation 30% complete
EURY, L W Carolina Power & Light Co 83/04/26 EISENHUT, D G.
Division of Licensing 2pp 18281 222 24X Fiche 50-261, 83/04/26, 8305020453

8305160346 Forwards Amend 76 to License DPR-23, safety evaluation & notice of issuance & availability Amend changes particle size distribution specified for in-place testing of HEPA filters in fuel & control room filter sys
REGUA, G Operating Reactors Branch 1, 83/04/26, UTLEY, E E
Carolina Power & Light Co 2pp, 18472 005 24X
Fiche: 50-261, 83/04/26, 8305160346

--8305160349 Amend 76 to License DPR-23, changing particle size distribution specified for in-place testing of HEPA filters in fuel & control room filter sys
VARGA, S A Operating Reactors Branch 1 83/04/26 5pp
18472.007 24X Fiche 50-261, 83/04/26, 8305160346

--8305160351 Safety evaluation supporting Amend 76 to License DPR-23
* Office of Nuclear Reactor Regulation, Director 83/04/26 2pp
18472:012 24X Fiche 50-261, 83/04/26, 8305160346.

--8305160356 Notice of issuance & availability of Amend 76 to License DPR-23
VARGA, S. A. Operating Reactors Branch 1 83/04/26 2pp
18472.014, 24X Fiche. 50-261, 83/04/26, 8305160346

8305170597 Clarifies 830105 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review per encl guidelines, due in 30 days
VARGA, S. A. Operating Reactors Branch 1 83/04/28 UTLEY, E E.
Carolina Power & Light Co. 5pp 18495 019. 24X
Fiche 50-261, 83/04/28, 8305170597.

8305040362 Responds to 830217 & 0407 requests for addl info re NUREG-0737, Item II.K.3 17, "ECCS Outages " Info compiled from equipment inoperability record which is completed each shift during cold shutdown
HURFORD, W. J. Carolina Power & Light Co 83/04/29 VARGA, S A
Operating Reactors Branch 1, 4pp. 18323 194 24X
Fiche 50-261, 83/04/29, 8305040362

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc, 50pp. 18441 120 24X
Fiche: 50-000, 83/05/02, 8305020455

8305060378 Notification of 830505 meeting w/util in Bethesda, MD to discuss schedule & prioritize open items
REGUA, G. Operating Reactors Branch 1 83/05/02 VARGA, S. A
Operating Reactors Branch 1, 2pp 18353 090 24X
Fiche: 50-261, 83/05/02, 8305060378.

8305060678 Notification of 830506 meeting w/util in Bethesda, MD to discuss technical aspects of steam generator replacement program
REGUA, G Operating Reactors Branch 1 83/05/02 VARGA, S A.
Operating Reactors Branch 1 2pp 18357 324 24X
Fiche 50-261, 83/05/02, 8305060678

8305180596 Forwards EIA of licensee 830331 request for approval of proposed procedures to stabilize in-place low level contaminated soil Radiation risks involved in transfer small
VARGA, S A Operating Reactors Branch 1 83/05/03 UTLEY, E E
Carolina Power & Light Co 5pp 18505 303 24X
Fiche 50-261, 83/05/03, 8305180596

--8305180589 EIA supporting licensee 830331 request for approval of proposed procedures to stabilize in-place low level contaminated soil
* NRC - No Detailed Affiliation Given 83/05/03 3pp
18505 305 24X Fiche: 50-261, 83/05/03, 8305180596

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305200435 Forwards revised & reformatted comprehensive list of NUREG-0737 licensing issues containing status & priority assigned for open items
ZIMMERMAN, S R Carolina Power & Light Co 83/05/17 VARGA, S A
Operating Reactors Branch 1 11pp 18517 134 24X
Fiche 50-261, 83/05/17, 8305200435

8305260022 Requests 1-month extension until 830701 to respond to 830428 ltr re environ qualification of safety-related electrical equipment Environ qualification expertise dedicated to preparing responses to 830105 & 0329 SERs
ZIMMERMAN, S R Carolina Power & Light Co 83/05/20 VARGA, S A
Operating Reactors Branch 1 1p 18599 307 24X
Fiche 50-261, 83/05/20, 8305260022

8305270008 Forwards list of qualified electrical equipment important to safety & response to SERs Final environ qualification scheduled to be completed by 850331
UTLEY, E E Carolina Power & Light Co 83/05/20 VARGA, S A
Operating Reactors Branch 1 615pp 18632 022 24X
Fiche 50-261, 83/05/20, 8305270008

--8305270011 "Qualification Test Rept on In-Containment Cables for CP&L "
MARCONNET, J , JORDAN, H , KIMBRELL, M Wyle Laboratories 45307-1
81/12/23 375pp 18632 262 24X Fiche: 50-261, 83/05/20, 8305270008

8305250249 Forwards Rev 1 to figures from 830331 final steam generator repair rept Corrected page list & figure list encl
EURY, L W Carolina Power & Light Co 83/05/23 VARGA, S. A
Operating Reactors Branch 1 19pp 18592 278 24X
Fiche 50-261, 83/05/23, 8305250249

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc
112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385.

8305270229 Forwards IE Insp Rept 50-261/83-06 on 830307-11. No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs. 83/04/01.
UTLEY, E E Carolina Power & Light Co 2pp 18637 206 24X
Fiche 50-261, 83/04/01, 8305270229

--8305270231 IE Insp Rept 50-261/83-06 on 830307-11 No noncompliance noted. Major areas inspected, radioactive effluents, external exposure control, solid radwaste & preplanning for 1984 steam generator outage.
ALBRIGHT, R. H., BARR, K P Region 2, Office of Director 83/03/25
3pp. 18637 208 24X Fiche. 50-261, 83/04/01, 8305270229

8305270479 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-02
LEWIS, R C Division of Project & Resident Programs 83/04/07.
UTLEY, R E Carolina Power & Light Co 2pp 18644 032. 24X
Fiche 50-261, 83/04/07, 8305270479.

--8305270487 Responds to NRC 830223 ltr re violations noted in IE Insp Rept 50-261/83-02 Corrective actions programs to visually verify positions of valves being developed by GA & onsite nuclear safety groups
STARKEY, R B Carolina Power & Light Co 83/03/25 O'REILLY, J P Region 2, Office of Director 5pp 18644 033 24X
Fiche 50-261, 83/04/07, 8305270479

--8305270494 Forwards IE Insp Rept 50-261/83-02 on 830110-0210 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/02/23
UTLEY, E E Carolina Power & Light Co 2pp 18644 038 24X
Fiche 50-261, 83/04/07, 8305270479

--8305270500 Notice of violation from insp on 830110-0210
* Region 2, Office of Director 83/02/23 2pp 18644 040 24X
Fiche 50-261, 83/04/07, 8305270479

--8305270506 IE Insp Rept 50-261/83-02 on 830110-0210 Noncompliance noted failure to implement equipment control procedures, to initiate prompt corrective action & to maintain annunciator procedures
WEISE, S Region 2, Office of Director BEMIS, P Division of Project & Resident Programs 83/02/22 12pp 18644 042 24X
Fiche 50-261, 83/04/07, 8305270479

8305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/04/11 UTLEY, E E Carolina Power & Light Co 2pp 18644 158 24X
Fiche 50-000, 83/04/11, 8305270461

--8305270474 IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of radwaste containing free liquid & inoperability of standby gas treatment deluge sys
LEWIS, R C Division of Project & Resident Programs 83/04/07
3pp 18644 160 24X Fiche 50-000, 83/04/11, 8305270461

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170654 Requests TLD dosimeter data be collected from steam generator insp activities, for independent determination of beta dose using theoretical model w/gamma calibr factor
VARGA, S A Operating Reactors Branch 1 83/04/26 UTLEY, E E Carolina Power & Light Co 2pp 18496 246 24X
Fiche 50-261, 83/04/26, 8305170654

8305270390 Forwards IE Insp Rept 50-261/83-09 on 830305-0410 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/26
UTLEY, E E Carolina Power & Light Co 2pp 96207 294 24X
Fiche 50-261, 83/04/26, 8305270390

--8305270401 IE Insp Rept 50-261/83-09 on 830305-0410 No noncompliance noted Major areas inspected Tech Spec compliance, plant tour, operations performance, RDs, housekeeping, site security, surveillance & maint activities & IE bulletin followup
WEISE, S , BEMIS, P , HARDIN, A K Region 2, Office of Director 83/04/25 12pp. 18643 059 24X Fiche 50-261, 83/04/26, 8305270390

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305270380 Forwards IE Insp Rept 50-261/83-11 on 830412-15 & 18-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/05/04
UTLEY, E E Carolina Power & Light Co 2pp 18643 050 24X
Fiche 50-261, 83/05/04, 8305270380

--8305270389 IE Insp Rept 50-261/83-11 on 830412-15 & 18-19 No noncompliance noted Major areas inspected seismic analysis for as-built, safety-related piping sys & pipe support baseplates using concrete expansion anchors
ANG, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/02 5pp
18643 052 24X Fiche 50-261, 83/05/04, 8305270380

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200009 Confirms commitments for operation of Cycle 9 Summary tables of steam generator eddy current insp results for May 1983 outage & justification for continued operation encl
EURY, L W Carolina Power & Light Co 83/05/16 VARGA, S A Operating Reactors Branch 1 5pp 18519 077 24X
Fiche 50-261, 83/05/16, 8305200009

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

6 Reportable occurrences, LERs & related correspondence

8305030599 RO on 830424, svc water booster pump B declared inoperable due to bearing failure & plant shutdown commenced following pump A trip due to blown control power fuses Fuses replaced & pump A restarted Investigation continuing
STARKEY, R B Carolina Power & Light Co 83/04/25 O'REILLY, J P Region 2, Office of Director 1p 18303 214 24X
Fiche 50-261, 83/04/25, 8305030599

8305030256 PNO-II-83-030 on 830428, controlled shutdown begun due to steam generator tube leak which increased from 0 1 to 0 308 gpm Licensee plans to keep plant out of svc for 3 wks to repair leak & conduct eddy current testing
HARDIN, A K , VERRELLI, D M Region 2, Office of Director 83/04/28
1p 18300 038 24X Fiche 50-261, 83/04/28, 8305030256

8305050249 RO on 830427, svc water pump A removed from svc for normal preventative maint & replaced w/rebuilt spare pump Post-maint testing resulted in pump over current trip Caused by internal binding of rebuilt pump
STARKEY, R B Carolina Power & Light Co 83/04/28 O'REILLY, J P. Region 2, Office of Director 2pp 18337 340 24X
Fiche 50-261, 83/04/28, 8305050249

8305110251 Forwards LER 83-005/01T-0
STARKEY,R B Carolina Power & Light Co 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18393 286 24X
Fiche 50-261,83/05/06,8305110251

--8305110256 LER 83-005/01T-0 on 830424,svc water booster pump B declared inoperable due to loss of bearing oil Caused by bearing oil slinger being positioned near vent hole Pump inspected & oil replenished
COX,H T Carolina Power & Light Co 83/05/06 Region 2, Office of Director 3pp 18393 287 24X Fiche 50-261,83/05/06, 8305110251

8305250423 LER 83-004/03L-0 on 830419,w/unit at 0% power following reactor trip,auxiliary feedwater pump B tripped on low discharge pressure Caused by pump cavitation resulting from buildup of water vapor inside pump casing W/830518 ltr
COX,H T , STARKEY,R B Carolina Power & Light Co 83/05/18
O'REILLY,J P Region 2, Office of Director 3pp 18583 355 24X
Fiche 50-261,83/05/18,8305250423

DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

P Operating license stage documents & correspondence

8305160129 Requests clarification if license authorizes unloading & shipping of fuel Info on procedures & dismantling plans to decommission L-77 reactors also requested
LAMBERT,N E Brigham Young Univ 83/05/09 CARTER,R E
Standardization & Special Projects Branch 1p 18448 142 24X
Fiche 50-262,83/05/09,8305160129

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305190343 Forwards Rev 1 to NUREG-0728, "NRC Incident Response Plan," in response to 830429 ltr requesting updated ltr of agreement W/o encl
HIND,J A Division of Radiological & Materials Safety Programs 83/05/13 LARSON,C E Northern States Power Co 2pp 18500 225 24X Fiche 50-000,83/05/13,8305190343

8305240572 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 MUSOLF,D M
Northern States Power Co 3pp 18593 345 24X
Fiche 50-263,83/05/18,8305240572

K. Utility Final Safety Analysis Report (FSAR) & amends

8305030603 Forwards Rev 1 to updated FSAR & "Annual Rept of Changes, Tests & Experiments,Jan-Oct 1982 "
MUSOLF,D Northern States Power Co 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18304 001 24X
Fiche 50-263,83/04/29,8305030603

---8305030610 "Annual Rept of Changes,Tests & Experiments,Jan-Oct 1982 "
* Northern States Power Co 83/04/29 12pp 18304 002 24X
Fiche 50-263,83/04/29,8305030603

--8305030613 Rev 1 to updated FSAR
* Northern States Power Co 82/10/31 496pp 18304 014 24X
Fiche 50-263,83/04/29,8305030603

P. Operating license stage documents & correspondence

8303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1,539 MWE (summer) net
HADLEY,C D Northern States Power Co 83/03/15 TOURTELLOTTE,J.
Regulatory Reform Task Force 6pp 18541 041 24X
Fiche 50-000,83/03/15,8303180429

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J. Regulatory Reform Task Force 83/04/11
PALLADINO,N.J. Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305230248 Forwards safety evaluation supporting resolution of NUREG-0737,Item II K 3 22, "Automatic Switchover of RCIC Suction," based on review of util 811231 & 820908 submittals re procedure verification & design mod
VASSALLO,D B Operating Reactors Branch 2 83/05/05 MUSOLF,D M
Northern States Power Co 5pp 18543 244 24X
Fiche 50-263,83/05/05,8305230248

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305240562 Clarifies 830104 safety evaluation on environ qualification of safety-related electrical equipment Requirements of 10CFR50 49 superseded 90-day response to SER Schedule of equipment qualification required by 830520
VASSALLO,D B Operating Reactors Branch 2 83/05/11 MUSOLF,D M
Northern States Power Co 4pp 18593 351 24X
Fiche 50-263,83/05/11,8305240562

8305260201 Forwards request for addl info re 811231 response to NUREG-0737,Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt
VASSALLO,D B Operating Reactors Branch 2 83/05/11 MUSOLF,D M
Northern States Power Co 3pp 18648 067 24X
Fiche 50-263,83/05/11,8305260201

8305240557 Informs that NUREG-0737,Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl
VASSALLO,D B Operating Reactors Branch 2 83/05/18 MUSOLF,D M
Northern States Power Co 7pp 18593 290 24X
Fiche 50-263,83/05/18,8305240557

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305200591 Forwards IE Insp Rept 50-263/83-06 on 830302-0401.No noncompliance noted
SHAFER,W D Region 3, Office of Director 83/05/02 LARSON,C E
Northern States Power Co 2pp 18514 107 24X
Fiche 50-263,83/05/02,8305200591

--8305200611 IE Insp Rept 50-263/83-06 on 830302-0401 No noncompliance noted Major areas inspected operational safety verification onsite review committee,LER followup & regional requests re main steam safety valve excessive blowdown
BROWN,C H , WALKER,R D Region 3, Office of Director 83/04/28 4pp 18514 109 24X Fiche 50-263,83/05/02,8305200591

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc. 119pp 18441 001. 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp. 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305180352 Responds to violations noted in 830411 enforcement ltr Corrective actions combustible gas control sys isolation valve & local leak rate test connection valves closed,leak test connection cap replaced & mgt meeting conducted
LARSON,C E Northern States Power Co 83/05/11 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement. 10pp 18485-268 24X Fiche 50-263,83/05/11,8305180352

8305200291 Ack receipt of 830511 ltr transmitting payment of proposed civil penalty Response to notice of violation & proposed imposition of civil penalty will be evaluated & corrective actions examined during future insps
AXELRAD,J A. Director's Office, Office of Inspection and Enforcement 83/05/18 LARSON,C E Northern States Power Co 1p 18516 323 24X Fiche 50-263,83/05/18,8305200291

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697-009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305030603 Forwards Rev 1 to updated FSAR & "Annual Rept of Changes, Tests & Experiments,Jan-Oct 1982 "
MUSOLF,D Northern States Power Co. 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18304 001 24X Fiche 50-263,83/04/29,8305030603

--8305030610 "Annual Rept of Changes,Tests & Experiments,Jan-Oct 1982 " # Northern States Power Co 83/04/29 12pp 18304 002 24X Fiche 50-263,83/04/29,8305030603

8305160092 Forwards monthly operating rept for Apr 1983
MUSOLF,D. Northern States Power Co 83/05/11 Office of Resource Management, Director 1p 18452 008 24X Fiche 50-263,83/05/11, 8305160092

--8305160098 Monthly operating rept for Apr 1983
MYRABO,A L Northern States Power Co 83/05/03 4pp 18452 009 24X Fiche,50-263,83/05/11,8305160092

S Reportable occurrences, LERs & related correspondence

8305020488 Forwards LER 83-006/01T-0
MUSOLF,D Northern States Power Co 83/04/22 Region 3, Office of Director 1p 18281 247 24X Fiche 50-263,83/04/22,8305020488.

--8305020492 LER 83-006/01T-0 on 830408,HPCI Woodward Governor EGR hydraulic actuator coil failed Caused by lead wire insulation degradation allowing ground fault to EGR housing EGR replaced HPCI satisfactorily tested
WOJCHOUSKI,A V Northern States Power Co 83/04/22 Region 3, Office of Director 1p 18281 248 24X Fiche 50-263,83/04/22, 8305020488

8305260314 PNO-III-83-038 on 830519,reactor placed in hot shutdown to investigate & repair steam leak in drain line between moisture separator & preheater in nonsafety-related turbine sys Addl steam leak found in turbine control valve flange
WALKER,R D , SHAFER,W D Region 3, Office of Director 83/05/20 1p 18625 198 24X Fiche 50-263,83/05/20,8305260314

DOCKET 50-264 DOW CHEMICAL CO

F Security, medical, emergency & fire protection plans

8305030513 Forwards IE Safeguards Insp Rept 50-264/83-01 on 830405-06. No noncompliance noted
MILLER,J R Region 3, Office of Director 83/04/29 RAMPY,L. W. Dow Chemical Co 2pp 18294 173 24X Fiche 50-264,83/04/29, 8305030513

--8305030521 IE Safeguards Insp Rept 50-264/83-01 on 830405-06 No noncompliance noted Major areas inspected facility organization & operation,measurement & statistical control Details withheld (ref 10CFR2 790)
MADEDA,T J , KNICELEY,J R , CREED,J R Region 3, Office of Director 83/04/29 1p 18294 175 24X Fiche:50-264,83/04/29, 8305030513

G Inspection reports, IE Bulletins & correspondence

8305030513 Forwards IE Safeguards Insp Rept 50-264/83-01 on 830405-06. No noncompliance noted
MILLER,J R Region 3, Office of Director 83/04/29. RAMPY,L W Dow Chemical Co 2pp 18294 173 24X Fiche 50-264,83/04/29, 8305030513

--8305030521 IE Safeguards Insp Rept 50-264/83-01 on 830405-06 No noncompliance noted Major areas inspected facility organization & operation,measurement & statistical control Details withheld (ref 10CFR2 790)
MADEDA,T J , KNICELEY,J R , CREED,J R Region 3, Office of Director 83/04/29 1p 18294 175 24X Fiche.50-264,83/04/29, 8305030513

DOCKET 50-265 QUAD-CITIES STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305240245 Requests schedular exemptions allowing delay in implementing 10CFR50 48 requirements for installation of fire protection mods Request based on AE,manufacturer & const personnel anticipated implementation schedule
RYBAK,B Commonwealth Edison Co 83/05/18 DENTON,H.R Office of Nuclear Reactor Regulation, Director 6pp. 18548 204. 24X Fiche 50-000,83/05/18,8305240245

8305250141 Informs that NUREG-0737,Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed
VASSALLO,D.B Operating Reactors Branch 2 83/05/18 FARRAR,D.L. Commonwealth Edison Co 3pp 18596 198 24X Fiche 50-254,83/05/18, 8305250141.

P Operating license stage documents & correspondence

8305020597 Forwards safety evaluation on NUREG-0737, Item II B 2 2, "Plant Shielding Mods for Vital Area Access " Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/04/22 FARRAR, D
Commonwealth Edison Co 5pp 18284 222 24X Fiche 50-254, 83/04/22, 8305020597

8305020458 Forwards info re NUREG-0737, Item II D 1, "Performance Testing of BWR Safety/Relief Valves," per NRC 830104 request Applicability of load combination info to BWR Owners Group generic test rept acceptable
RYBAK, B Commonwealth Edison Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 18283 311 24X
Fiche: 50-254, 83/04/27, 8305020458

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040551 Application to amend Licenses DPR-19, DPR-25, DPR-29 & DPR-30, changing App A Tech Specs re economic generation control operation
RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24X
Fiche, 50-000, 83/05/02, 8305040551

--8305040555 Proposed changes to App A Tech Specs re economic generation control operation W/o detailed changes
* Commonwealth Edison Co 83/05/02 1p 24X
Fiche 50-000, 83/05/02, 8305040551

8305050043 Application for amend to Licenses DPR-29 & DPR-30, changing Tech Specs to limit control rod drive pump isolation from accumulators to single rod scram testing
RYBAK, B Commonwealth Edison Co 83/05/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp 18342 083 24X
Fiche 50-254, 83/05/02, 8305050043

8305130209 Concurs w/NRC changes to draft Tech Specs re reactor protection sys (RPS) protective relaying mods, per 830420 ltr Operation w/RPS mod, installed per 10CFR50 59 & w/o Tech Specs, will not compromise safe operation of facilities
RYBAK, B. Commonwealth Edison Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18439 330 24X
Fiche: 50-000, 83/05/06, 8305130209

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130038 Responds to 830316 request for addl info re NUREG-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-01B
RYBAK, B Commonwealth Edison Co 83/05/10 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X
Fiche 50-000, 83/05/10, 8305130038

8305200707 Forwards request for addl info on NUREG-0737, Item II K.3 28 re qualification of automatic depressurization sys accumulators. Response requested within 45 days
VASSALLO, D. B Operating Reactors Branch 2 83/05/11 FARRAR, D L
Commonwealth Edison Co 5pp 18528 350 24X Fiche 50-000, 83/05/11, 8305200707

8305200186 Notifies that 830425 amend application for proposed Tech Spec changes re TMI Action Item II K 3 15 on isolation of HPCI & RCIC requires fee Application requested from NRC for purpose of preventing inadvertent isolation of sys
DIGGS, R M License Fee Management Branch 83/05/12 FARRAR, D. L
Commonwealth Edison Co. 1p 18540 228 24X Fiche 50-000, 83/05/12, 8305200186

8305180376 Forwards list of proprietary documents & associated pages from technical evaluation repts re environ qualification of electrical equipment GE affidavit per 10CFR2 790 received Westinghouse affidavit forthcoming
RYBAK, B Commonwealth Edison Co 83/05/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp 18490 347 24X
Fiche: 50-000, 83/05/13, 8305180376

8305310231 Advises that responses to NUREG-0737, Item III D 3 4, "Control Room Habitability," acceptable, completing action on Item Safety evaluation encl
VASSALLO, D B Licensing Branch 2 83/05/17 FARRAR, D L
Commonwealth Edison Co 4pp 18662 255 24X Fiche 50-254, 83/05/17, 8305310231

8305240573 Notifies that NUREG-0737, Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl
VASSALLO, D B Operating Reactors Branch 2 83/05/18 FARRAR, D L
Commonwealth Edison Co 7pp 18593 338 24X Fiche 50-254, 83/05/18, 8305240573

8305270419 Notifies that response to 830316, 0510 & 11 requests for addl info re TMI Item II K 3 28, "Qualification of Automatic Depressurization Sys Accumulators," addressed in 830510 ltr
RYBAK, B Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18642 298 24X
Fiche 50-000, 83/05/23, 8305270419

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

8305310028 Advises that requirements of NUREG-0737, Item II F 1.4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved, per 821220 & 801215 submittals
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/27 FARRAR, D L
Commonwealth Edison Co 7pp 18653 213 24X Fiche 50-000, 83/05/27, 8305310028

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18309 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305170167 Forwards response to 830411 notice of violation & proposed imposition of civil penalties re IE Insp Repts 50-254/82-26 & 50-265/82-26 Also includes remittance in amount of $60,000 re inoperable reactor protection sys subchannel
REED,C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 1p 18466 308 24X Fiche 50-254,83/05/09,8305170167

--8305170184 Responds to notice of violation noted in IE Insp Repts 50-254/82-26 & 50-265/82-26 on 821118-22 & 1213-16 Corrective actions Startup Procedure GGP 1-1 revised to include sign-off for verifying clearance of alarm
REED,C Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 9pp 18466 309 24X Fiche 50-254,83/05/09,8305170167

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305310105 Forwards IE Insp Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance noted
SHAFER,W D Region 3, Office of Director 83/05/12 REED,C Commonwealth Edison Co 2pp 18658 051 24X Fiche 50-254,83/05/12,8305310105

--8305310112 IE Insp Repts 50-254/83-06 & 50-265/83-06 on 830219-0422 No noncompliance noted Major areas inspected operational safety,maint,surveillance,licensee monthly repts,regional requests,LERs & public info & special repts
CHRISSOTIMOS,N , WALKER,R D Region 3, Office of Director 83/05/10 8pp 18658 053 24X Fiche 50-254,83/05/12,8305310105

8305200421 Advises that util response to 820714 confirmatory action ltr re IE Bulletin 79-14,piping analysis to restore hot shutdown path piping sys to FSAR requirements by 830215,acceptable
SPESSARD,R L Division of Engineering 83/05/18 REED,C Commonwealth Edison Co 2pp 18517 116 24X Fiche 50-000,83/05/18,8305200421

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305250377 Forwards "GE-NEDB Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B "
RYBAK,B Commonwealth Edison Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2,118pp 18578 001 24X Fiche 50-000,83/05/19,8305250377

--8305250393 "GE-NEDB Electrical Penetration Assembly Qualification Program "
* Bechtel Corp 83/05/18 203pp 18578 174 24X Fiche 50-000,83/05/19,8305250377

--8305250413 Rev 2 to Vols 1-3 to "Response to IE Bulletin 79-01B,Quad Cities Nuclear Power Station Units 1 & 2 "
* Bechtel Corp 83/05/31 786pp 18581 253 24X Fiche 50-000,83/05/19,8305250377

8305270216 Ack receipt of 830509 transmittal forwarding full payment of proposed civil penalty Corrective actions will be examined during future insps
AXELRAD,J A Enforcement Staff 83/05/25 REED,C R Commonwealth Edison Co 2pp 18637 323 24X Fiche 50-254,83/05/25,8305270216

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170372 Forwards monthly operating repts for Apr 1983
KALIVIANAKIS,N Commonwealth Edison Co 83/05/02 Director's Office, Office of Inspection and Enforcement 1p 18466 055 24X Fiche 50-254,83/05/02,8305170372

--8305170376 Monthly operating repts for Apr 1983
MISAK,A Commonwealth Edison Co 83/05/02 21pp 18466 056 24X Fiche 50-254,83/05/02,8305170372

S Reportable occurrences, LERs & related correspondence

8305260286 LER 83-006/03L-0 on 830424,AD 2-203-2D MSIV failed to initiate half scram on reactor protection sys channel B Caused by channel B 10% closure limit switch failure Limit switch replaced w/like-for-like switch W/830516 ltr
FUHS,A , KALIVIANAKIS,N Commonwealth Edison Co 83/05/16
KEPPLER,J Region 3, Office of Director 3pp 18625 351 24X Fiche 50-265,83/05/16,8305260286

8305310152 LER 83-007/01T-0 on 830509,while reviewing out-of-svc documentation,discovered that control rod drives (CRD) 38-07 & 46-55 on Unit 2 & 06-43 on Unit 1 made inoperable w/o verifying shutdown margin or insertion W/830523 ltr
WUNDERLICH,J , KALIVIANAKIS,N Commonwealth Edison Co 83/05/23
KEPPLER,J G Region 3, Office of Director 1p 18653 044 24X Fiche 50-265,83/05/23,8305310152

DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305030523 Requests revs to proposed mods to 10CFR50 App R exemption requests re separation requirements,per 830322 meeting & 830325 & 31 telcons Detailed discussion of revs encl
FAY,C W Wisconsin Electric Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 29pp 18300 286 24X Fiche 50-266,83/04/28,8305030523

8305110540 Forwards exemption from App R in partial response to 820630 ltr & 820929 & 1011 suppls Exemption permits relief from requirements to install fixed suppression sys & fire barriers to separate hydrogen lines from safety equipment
CLARK,R A Operating Reactors Branch 3 83/04/28 FAY,C W Wisconsin Electric Power Co 5pp 18415 104 24X Fiche 50-266,83/04/28,8305110540

--8305110542 Exemption from requirements of 10CFR50,App R,Section III G re fixed fire suppression sys in control room
EISENHUT,D.G Division of Licensing 83/04/28 Wisconsin Electric Power Co 3pp 18415 107 24X Fiche 50-266,83/04/28,8305110540

8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation 1 re fire signaling sys testing withdrawn
SPESSARD,R L Division of Engineering 83/05/09 BURSTEIN,S Wisconsin Electric Power Co 2pp 18464 333 24X Fiche 50-266,83/05/09,8305170241

--8305170252 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include addl performance data Fire protection tests reviewed
FAY,C W Wisconsin Electric Power Co 83/01/21 KEPPLER,J G Region 3, Office of Director 42pp 18464 335 24X Fiche 50-266,83/05/09,8305170241

--8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity
FAY,C W Wisconsin Electric Power Co 83/02/24 KEPPLER,J G Region 3, Office of Director 3pp 18465 015 24X Fiche 50-266,83/05/09,8305170241

8305170138 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05
HIND,J A Division of Radiological & Materials Safety Programs 83/05/10 BURSTEIN,S Wisconsin Electric Power Co 1p 18466 270 24X Fiche 50-266,83/05/10,8305170138

--8305170144 Responds to NRC 830314 ltr re violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 10CFR73 21)
BURSTEIN,S Wisconsin Electric Power Co 83/04/13 HIND,J A Division of Radiological & Materials Safety Programs 1p 18466 271 24X Fiche 50-266,83/05/10,8305170138

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305200021 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/12 FAY, C W
Wisconsin Electric Power Co 3pp 18540 114 24X
Fiche 50-266, 83/05/12, 8305200021

G Adjudicatory correspondence

8305020438 Brief opposing Wisconsin Environ Decade exceptions to ASLB 830204 initial decision authorizing full-scale sleeving Exceptions waived for failure to brief or arguments w/o merits
CHURCHILL, B W Wisconsin Electric Power Co CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge 83/04/29 Atomic Safety and Licensing Appeal Panel 32pp 18281 111 24X Fiche 50-266, 83/04/27, 8305020438

8305100314 Brief in opposition to Wisconsin Environ Decade 830214 appeal of ASLB 830204 memorandum & order LBP-83-4 ASLAB should reject exceptions not briefed & affirm ASLB order re steam generator tube rupture W/Certificate of Svc
BACHMANN, R G Hearing Branch 1 83/05/09 Atomic Safety and Licensing Appeal Panel 18pp 18371 141 24X Fiche 50-266, 83/05/09, 8305100314

8305170291 Opposes Wisconsin Environ Decade 830506 request to provide Westinghouse proprietary info from licensee Decade petition for discretionary Commission review does not entitle petitioner to proprietary info Svc list encl
CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Wisconsin Electric Power Co 83/05/13 MOORE, T S , JOHNSON, W R , GOTCHY, R L Atomic Safety and Licensing Appeal Panel 3pp 18466 121 24X Fiche 50-266, 83/05/13, 8305170291

8305270558 Requests info re date, time & location for Commission meeting on emergency operations facility location Leave to address Commission requested
FAY, C W Wisconsin Electric Power Co 83/05/20 CHILK, B J Office of the Secretary of the Commission 1p 18646 154 24X
Fiche 50-266, 83/05/20, 8305270558

P Operating license stage documents & correspondence

8305230724 Forwards estimated annual regulatory & nonregulatory expenditures in 830208 ltrs re cost of backfitting Combined capacity of facilities is 994 MWe
BURSTEIN, B Wisconsin Electric Power Co 83/02/25 TOURTELLOTTE, J Regulatory Reform Task Force 3pp 18542 269 24X
Fiche 50-266, 83/02/25, 8305230724

8305020272 Forwards Affidavit AW-80-27 in support of request to withhold proprietary info re effect of radiation on insulating matls in Westinghouse medium motor per 10CFR2 790 re encl util draft 830413 ltr
WIESEMANN, R A Westinghouse Electric Corp 83/04/13 THOMAS, C O Division of Licensing 9pp 18277 196 24X Fiche 50-266, 83/04/13, 8305020272.

--8305020292 Nonproprietary version of "Effect of Radiation on Insulating Matls Used in Westinghouse Medium Motors "
BARTKO, J Westinghouse Electric Corp 71-1C2-RADMC-R1 71/04/10 39pp. 18277 205 24X Fiche 50-266, 83/04/13, 8305020272

8305020128 Forwards safety evaluation of util preferred ac power sys conformance to GDC 17 Power sys do not fully meet intent of GDC 17 since sys could be automatically disconnected from 4,160-volt safeguards buses in worst case accident loads
NORELIUS, C E Division of Project & Resident Programs 83/04/25
EISENHUT, D G Division of Licensing 3pp 18278 220 24X
Fiche, 50-266, 83/04/25, 8305020128

--8305020137 Safety evaluation of util preferred ac power sys conformance GDC 17 Proximity of low voltage transformers does not fully meet GDC 17 requirements for physical separation, but deluge sprinkler sys adequate
* NRC - No Detailed Affiliation Given 83/04/25 8pp 18278, 223 24X Fiche 50-266, 83/04/25, 8305020128

8305060001 Forwards EG&G summary of discussion re radiological effluent Tech Specs during 820602-03 plant visit Final draft of proposed radiological effluent Tech Specs & offsite dose calculation manual should be developed within 60 days
CLARK, R. A Operating Reactors Branch 3 83/04/25 FAY, C W
Wisconsin Electric Power Co 45pp 18353 263 24X
Fiche, 50-266, 83/04/25, 8305060001

--8305060007 STANDARD RADIOLOGICAL EFFLUENT TECHNICAL SPECIFICATIONS FOR PRESSURIZED WATER REACTORS SEPTEMBER 1982
* NRC - No Detailed Affiliation Given NUREG-0472 D07 R03 82/09/03 83pp 18353 308 24X Fiche 50-266, 83/04/25, 8305060001

8305090546 Lists drawings needed to review inservice testing program Two sets of full size drawings requested
CLARK, R A Operating Reactors Branch 3 83/04/27 FAY, C W
Wisconsin Electric Power Co 3pp 18381 205 24X
Fiche 50-266, 83/04/27, 8305090546

8305110028 Informs of Class I & III fee classification for 830324 application for Tech Spec changes re auxiliary feedwater sys operability Overpayment for 790926 application for administrative changes will be applied toward current fees
MILLER, W O License Fee Management Branch 83/04/27 FAY, C W
Wisconsin Electric Power Co 2pp 18421 313 24X
Fiche 50-266, 83/04/27, 8305110028

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060408 Requests extension of deadline for environ qualification of equipment until 840330 for Unit 2 & 841101 for both units for environ qualification of all 10CFR50 49(b)(3) equipment items
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 18348 210 24X
Fiche 50-266, 83/05/04, 8305060408

8305110075 Remits license amend approval fee for temporary clarification of Tech Specs re auxiliary feedwater sys operability
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director MILLER, W O License Fee Management Branch 1p 18408 109 24X Fiche 50-266, 83/05/04, 8305110075

8305110181 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 91 re limiting conditions for operation requiring both RHR loops be operable unless reactor sys is in refueling shutdown condition
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18407 122 24X Fiche 50-266, 83/05/04, 8305110181

--8305110187 Tech Spec Change Request 91 re limiting conditions for operation requiring both RHR loops be operable unless reactor sys is in refueling shutdown condition
* Wisconsin Electric Power Co 83/05/04 6pp 18407 125 24X
Fiche 50-266, 83/05/04, 8305110181

8305110201 Forwards addl fees associated w/Tech Spec Change Request 69 to allow repair of degraded steam generator tubes by sleeving
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director DIGGS, R M License Fee Management Branch 1p 18407 111 24X Fiche 50-266, 83/05/04, 8305110201

8305120495 Fowards Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends allow temporary isolation of shared motor driven auxiliary feedwater pumps
COLBURN, T G Operating Reactors Branch 3 83/05/04 FAY, C W
Wisconsin Electric Power Co 4pp 18440 214 24X
Fiche 50-266, 83/05/04, 8305120495

--8305120498 Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, allowing temporary isolation of shared motor driven auxiliary feedwater pumps for unit during startup, shutdown & surveillance testing of other unit
CLARK, R A Operating Reactors Branch 3 83/05/04 6pp
18440 218 24X Fiche 50-266, 83/05/04, 8305120495

--8305120502 Safety evaluation supporting Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 2pp
18440 224 24X Fiche 50-266, 83/05/04, 8305120495

--8305120505 Notice of issuance & availability of Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp
18440 226 24X Fiche 50-266, 83/05/04, 8305120495

8305130009 Updates progress in meeting schedular commitments per NRC 830314 order re implementation of post-TMI Action Item II F 1, "Addl Accident Monitoring Instrumentation "
FAY, C W Wisconsin Electric Power Co 83/05/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3pp 18436 341 24X
Fiche 50-266, 83/05/06, 8305130009

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305240131 Informs that piping & instrumentation diagrams requested in 830427 ltr re inservice testing program will be forwarded under separate cover
FAY,C W Wisconsin Electric Power Co 83/05/19 DENTON,H R
Office of Nuclear Reactor Regulation, Director CLARK,R A
Operating Reactors Branch 3 1p 18549 006 24X
Fiche 50-266,83/05/19,8305240131

8305240497 Forwards list of electric equipment important to safety to be environmentally qualified at facilities Info duplicates 811008 response,per IE Bulletin 79-01B,w/listed exceptions
FAY,C W Wisconsin Electric Power Co 83/05/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 29pp 18571 360
24X Fiche 50-266,83/05/20,8305240497

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305120456 Forwards IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 & notice of violation No reply to Item 2 of notice of violation required
SHAFER,W D Region 3, Office of Director 83/04/25 BURSTEIN,S
Wisconsin Electric Power Co 2pp 18431 029 24X
Fiche 50-266,83/04/25,8305120456

--8305120463 Notice of violation from insp on 830201-0331
SHAFER,W D Region 3, Office of Director 83/04/25 1p
18431 031 24X Fiche 50-266,83/04/25,8305120456

--8305120468 IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 Noncompliance noted personnel failed to check out when exiting containment per Procedure HP 2 4 & two Eberline Model DAI-6CC area radiation monitors not labeled
HAGUE,R L , FITZPATRICK,B , JACKIW,I N Region 3, Office of Director 83/04/22 9pp 18431 032 24X Fiche 50-266,83/04/25, 8305120456

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/03. Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305120408 Submits addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Mechanical corrections installed w/exception of two corrections requiring welding to RHR piping
BURSTEIN,S Wisconsin Electric Power Co 83/05/04 KEPPLER,J G
Region 3, Office of Director 2pp 18431 150 24X
Fiche 50-266,83/05/04,8305120408

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305200229 Clarifies position re maint & testing program for HVAC filter units not controlled by Tech Specs & for respirator fitting program,per IE Insp Repts 50-266/83-03 & 50-301/83-03 dtd 830216 although no noncompliance noted
FAY,C W Wisconsin Electric Power Co 83/05/06 KEPPLER,J G
Region 3, Office of Director 5pp 18517 102 24X
Fiche 50-266,83/05/06,8305200229

8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation 1 re fire signaling sys testing withdrawn
SPESSARD,R L Division of Engineering 83/05/09 BURSTEIN,S
Wisconsin Electric Power Co 2pp 18464 333 24X
Fiche 50-266,83/05/09,8305170241

--8305170252 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include addl performance data Fire protection tests reviewed
FAY,C W Wisconsin Electric Power Co 83/01/21 KEPPLER,J G
Region 3, Office of Director 42pp 18464 335 24X
Fiche 50-266,83/05/09,8305170241

--8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity
FAY,C W Wisconsin Electric Power Co 83/02/24 KEPPLER,J G
Region 3, Office of Director 3pp 18465 015 24X
Fiche 50-266,83/05/09,8305170241

8305170138 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05
HIND,J A Division of Radiological & Materials Safety Programs 83/05/10 BURSTEIN,S Wisconsin Electric Power Co 1p 18466 270 24X Fiche 50-266,83/05/10,8305170138

--8305170144 Responds to NRC 830314 ltr re violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 10CFR73 21)
BURSTEIN,S Wisconsin Electric Power Co 83/04/13 HIND,J A
Division of Radiological & Materials Safety Programs 1p
18466 271 24X Fiche 50-266,83/05/10,8305170138

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc. 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240380 Confirmatory action ltr re NRC 830314 order specifying certain TMI action items as complete or completion dates noted Item II F 1.1, "Noble Gas Effluent Montior," complete, however,main steam line monitors not operational
KEPPLER,J G Region 3, Office of Director 83/05/20 BURSTEIN,S
Wisconsin Electric Power Co 1p 18575 072 24X
Fiche 50-266,83/05/20,8305240380

8305270241 Documents agreement per 830517 conference call re timing requirements for notification of state & local agencies for unusual event or alert,per IE Insp Repts 50-266/83-01 & 50-301/83-01.Procedure to be initiated by 830701
FAY,C W Wisconsin Electric Power Co 83/05/23 KEPPLER,J G
Region 3, Office of Director 1p 18637,161 24X
Fiche 50-266,83/05/23,8305270241

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/03/26,8303040046

R Periodic operating reports & related correspondence

8305160169 Forwards monthly operating repts for Apr 1983
FAY,C W Wisconsin Electric Power Co 83/05/10 NRC - No Detailed Affiliation Given 1p 18446 073 24X
Fiche 50-266,83/05/10,8305160169

--8305160171 Monthly operating repts for Apr 1983
FAY,C W Wisconsin Electric Power Co 83/05/09 9pp 18446 074 24X Fiche 50-266,83/05/10,8305160169

S Reportable occurrences, LERs & related correspondence

8305030376 Forwards updated LER 82-022/01X-2
FAY,C W Wisconsin Electric Power Co 83/04/25 KEPPLER,J G Region 3, Office of Director 1p 18308 216 24X
Fiche 50-266,83/04/25,8305030376

--8305030382 Updated LER 82-022/01X-2 on 821111,eddy current indications of mechanical damage in excess of Tech Spec plugging limit identified Caused by foreign objects in steam generator secondary side Tubes w/mechanical damage plugged
FAY,C W Wisconsin Electric Power Co 83/04/25 Region 3, Office of Director 5pp 18308 217 24X Fiche 50-266,83/04/25, 8305030376

8305130034 NPDES noncompliance notification on 830429,daily max pH effluent limit exceeded Investigation will include review of sampling & analysis techniques,insp of treatment equipment & review of operator logs
FAY,C W Wisconsin Electric Power Co 83/05/05 Wisconsin, State of 2pp 18436 208 24X Fiche 50-266,83/05/05,8305130034

8305190226 Followup to 830331 NPDES noncompliance notification On 830316 & 17,retention pond discharge (Sample Point 501) exceeded pH limit Caused by carryover of lime from water treatment sys
FAY,C W Wisconsin Electric Power Co 83/05/12 Wisconsin, State of 2pp 18500 202 24X Fiche 50-266,83/05/12,8305190226

8305240002 PNO-III-83-037 on 830509,Region III radiation specialist learned that main steam line noble gas monitors not yet installed per 830314 commitment date Ofc of Investigation investigating failure Monitors to be installed by mid June
LOVENDALE,P , PAPERIELLO,C Region 3, Office of Director 83/05/18 1p 18549 138 24X Fiche 50-266,83/05/18,8305240002

8305240379 NPDES noncompliance notification on 830429,pH of retention pond discharge found above limit Caused by demineralized makeup water treatment sys problems re undissolved lime carrying through to pressure filter sys
FAY,C.W Wisconsin Electric Power Co 83/05/18 Wisconsin, State of 1p 18571 040 24X Fiche 50-266,83/05/19,8305240379

DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8305050146 Forwards rev to Chapter 9 of amended security plan Rev withheld (ref 10CFR73 21)
MCBRIDE,L M, Public Service Co of Colorado 83/03/28
COLLINS,J T Region 4, Office of Director 1p 18342 231 24X
Fiche 50-267,83/03/28,8305050146

8305120566 Releases public version of changes to radiological emergency response plan implementing procedures
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18442 079 24X Fiche 50-267,83/05/02, 8305120566

--8305120570 Forwards public version of Issue 4 to Radiological Emergency Response Plan RERP-HOME, "Home Packet for Off-Shift Notifications" & Issue 15 to RERP-PHONE LISTS
WAREMBOURG,D W Public Service Co of Colorado 83/02/16
EISENHUT,D G Division of Licensing COLLINS,J T Region 4, Office of Director 2pp 18442 081 24X Fiche 50-267,83/05/02, 8305120566

--8305120578 Public version of Issue 4 to Radiological Emergency Response Plan RERP-HOME, "Home Packet for Off-Shift Notifications" & Issue 15 to RERP-PHONE LISTS
WAREMBOURG,D W Public Service Co of Colorado 83/02/16 128pp 18442 083 24X Fiche 50-267,83/05/02,8305120566

8305200494 Responds to NRC 830331 ltr re deviation noted in IE Insp Rept 50-267/83-03 on 830117-21 Corrective actions emergency plan implementing procedures revised to state responsibilities of shift supervisor/emergency coordinator
WAREMBOURG,D W Public Service Co of Colorado 83/05/06
COLLINS,J T Region 4, Office of Director 2pp 18513 005 24X
Fiche 50-267,83/05/06,8305200494

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

Q Adjudicatory correspondence

8305200516 Forwards order confirming util commitments on post-TMI-related issues Order based on commitments in util 820317 & 0505 ltrs responding to Generic Ltrs 82-05 & 82-10
MADSEN,G L Region 4, Office of Director 83/04/27 LEE,O R Public Service Co of Colorado 4pp 18516 045 24X
Fiche 50-267,83/04/27,8305200516

--8305200528 Order confirming licensee commitments on post-TMI-related issues Schedule changes acceptable for TMI Items 1 A 3 1, II B 2,II B 3,II B 4 & II F 1
GAGLIARDO,J E Division of Resident, Reactor Project & Engineering Programs 83/04/27 Public Service Co of Colorado 11pp 18516 049 24X Fiche 50-267,83/04/27,8305200516

P Operating license stage documents & correspondence

8305020462 Advises that NRC 830228 requested documentation re nuclear detector decalibr will be transmitted within 30 days Existing drawings described in Encl 3 to 830228 ltr do not reflect proposed changes
BREY,H L Public Service Co of Colorado 83/04/15 COLLINS,J T Region 4, Office of Director 2pp 18283 308 24X
Fiche 50-267,83/04/15,8305020462

8305050214 Forwards application to amend License DPR-34 Amend assures operability of plant protective sys & other critical instrumentation by defining min operable instrument channels & trip settings in response to RO-83-001
LEE,O R Public Service Co of Colorado 83/04/19 COLLINS,J T Region 4, Office of Director 2pp 18338 112 24X
Fiche 50-267,83/04/19,8305050214

--8305050222 Application to amend License DPR-34,revising App A Tech Specs to assure operability of plant protective sys & other critical instrumentation by defining min operable instrument channels & trip settings
LEE,O R Public Service Co of Colorado 83/04/19 8pp 18338 114 24X Fiche 50-267,83/04/19,8305050214

--8305050228 Proposed Tech Spec Tables 4 4-1 - 4 4-4 re instrument operating requirements for plant protective sys,scram,loop shutdown,circulator trip & reactor protective sys rod withdrawal prohibit
* Public Service Co of Colorado 83/04/19 24pp 18338 122 24X Fiche 50-267,83/04/19,8305050214

8305160048 Clarifies proposed changes in undervoltage protection & reiterates schedule for implementation of design changes & mods Existing non-Class IE undervoltage relays will be retained as protection for 4,160-volt buses
BREY,H L Public Service Co of Colorado 83/04/27 COLLINS,J T Region 4, Office of Director 2pp 18453 141 24X
Fiche 50-267,83/04/27,8305160048

8305160053 Forwards comments of util & GA Technologies re interim rept by LASL on PRCV liner hot spots Util does not concur w/categorization of hot spots according to universal & relative degrees of severity
BREY,H L Public Service Co of Colorado 83/04/27 COLLINS,J T Region 4, Office of Director 9pp, 18453 132 24X
Fiche 50-267,83/04/27,8305160053

8305170380 Informs that control room HVAC sys satisfies requirements of single-failure criteria for control room habitability No further mods anticipated
BREY,H L Public Service Co of Colorado 83/04/29 MADSEN,G L Region 4, Office of Director 2pp 18469 211 24X
Fiche 50-267,83/04/29,8305170380

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305200494 Responds to NRC 830331 ltr re deviation noted in IE Insp Rept 50-267/83-03 on 830117-21 Corrective actions emergency plan implementing procedures revised to state responsibilities of shift supervisor/emergency coordinator
WAREMBOURG, D W Public Service Co of Colorado 83/05/06
COLLINS, J T Region 4, Office of Director 2pp 18513 005 24X
Fiche 50-267, 83/05/06, 8305200494

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305200167 Summary of 830428-29 & 0502-04 & 06 meetings in Bethesda, MD re impact of Public Law 97-145 (Shelly Decision) on licensing activities
WAGNER, P C NRC - No Detailed Affiliation Given 83/05/11
GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 3pp 18519 067 24X Fiche 50-267, 83/05/11, 8305200167

8305200178 Requests remittance of RETS amend fee due from review of 810102 application within 15 days of ltr receipt
MILLER, W O License Fee Management Branch 83/05/12 LEE, D R
Public Service Co of Colorado 1p 18540 229 24X
Fiche 50-267, 83/05/12, 8305200178

8305230566 Requests clarification & add'l info re 830415 ltr on control rod drive mechanisms operating temp limitations, within 60 days of ltr receipt Adequate assurance exists for safe interim operation
MADSEN, G L Region 4, Office of Director 83/05/16 LEE, D R
Public Service Co of Colorado 4pp 18537 098 24X
Fiche 50-267, 83/05/16, 8305230566

8305240477 Forwards nuclear detector decalibr documentation per NRC 830228 request Documentation unavailable when originally requested due to plant procedures which permit revs only after mod approved & installation begun W/o documentation
GREY, H L Public Service Co of Colorado 83/05/16 COLLINS, J T
Region 4, Office of Director 3pp 18549 338 24X
Fiche 50-267, 83/05/16, 8305240477

8305310027 Discusses changes to operating procedures for issuance of licensing actions Util will provide State of CO w/copy of amend applications filed w/NRC Util 801001 amend application encl W/o encl
WAGNER, P C Region 4, Office of Director 83/05/20 HAZLE, A J
Colorado, State of 1p 18653 178 24X Fiche 50-267, 83/05/20, 8305310027

8305310090 Requests Fr publication of notice of consideration of 830419 OL amend request & proposed no significant hazards consideration determination & opportunity for hearing
MADSEN, G L Region 4, Office of Director 83/05/20 CLARK, R A
Operating Reactors Branch 3 2pp 18655 127 24X
Fiche 50-267, 83/05/20, 8305310090

8305310111 Forwards fees for radiological ETS changes proposed in 830323 ltr & reformat of Tech Specs into STS developed by EG&G per Jan 1981 request
WAREMBOURG, D Public Service Co of Colorado 83/05/20
COLLINS, J T. Region 4, Office of Director 3pp 18658 048 24X
Fiche 50-267, 83/05/20, 8305310111

8305310229 Requests FR publication of notice of proposed issuance of amend to OL, proposing no significant hazards consideration determination since proposed amend incorporates present NRC guidelines
MADSEN, G L Region 4, Office of Director 83/05/20 CLARK, R A
Operating Reactors Branch 3 2pp 18658 082 24X
Fiche 50-267, 83/05/20, 8305310229

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305060546 Forwards revised "Initial Approach to Power Tests (B-Series)," Interim Rept 26 for period ending 830222
WAREMBOURG, D Public Service Co of Colorado 83/04/13
COLLINS, J T Region 4, Office of Director 2pp 18348 302. 24X
Fiche 50-267, 83/04/13, 8305060546

--8305060552 "Initial Approach to Power Tests (B-Series)," Interim Rept 26 for period ending 830222
* Public Service Co of Colorado, 83/02/22 2pp 18348.304
24X Fiche 50-267, 83/04/13, 8305060546

8305090489 Forwards revised "Rept of Changes, Tests & Experiments Not Requiring Prior Commission Approval Per 10CFR50 59(a) for 1982 "
WAREMBOURG, D Public Service Co of Colorado 83/04/25
COLLINS, J T Region 4, Office of Director 2pp 18360 113. 24X
Fiche 50-267, 83/04/25, 8305090489

--8305090565 Revised "Rept of Changes, Tests & Experiments Not Requiring Commission Approval per 10CFR50 59(a) for 1982 "
* Public Service Co of Colorado 83/04/25 37pp. 18360 115
24X Fiche 50-267, 83/04/25, 8305090489

8305230426 Forwards monthly operating rept for Apr 1983
WAREMBOURG, D Public Service Co of Colorado 83/05/12
Director's Office, Office of Inspection and Enforcement 1p
18538 219 24X Fiche 50-267, 83/05/12, 8305230426

--8305230427 Monthly operating rept for Apr 1983
FULLER, C H Public Service Co of Colorado 83/05/10 8pp
18538 220 24X Fiche 50-267, 83/05/12, 8305230426

S Reportable occurrences, LERs & related correspondence

8305060479 Forwards LER 83-016/03L-0 Detailed event analysis encl
WAREMBOURG, D Public Service Co of Colorado 83/04/28
COLLINS, J T Region 4, Office of Director 5pp 18348 155 24X
Fiche 50-267, 83/04/28, 8305060479

--8305060484 LER 83-016/03L-0 on 830331, two Class 1 hydraulic shock suppressors found inoperable Caused by fully extended snubbers, due to thermal pipe movement One snubber adjusted & other replaced
* Public Service Co of Colorado 83/04/28 Region 4, Office of Director 1p 18348 160 24X Fiche 50-267, 83/04/28, 8305060479

DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305270326 Forwards IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269, 83/05/06, 8305270326

--8305270338 IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing, maint & operations & annual emergency drill
BRYANT, J Region 2, Office of Director 83/05/06 9pp
18641 144 24X Fiche 50-269, 83/05/06, 8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18643 011 24X
Fiche 50-269, 83/05/06, 8305270374

--8305270387 IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN, G N Region 2, Office of Director 83/05/03 10pp
18643, 013 24X Fiche 50-269, 83/05/06, 8305270374

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

J Insurance & indemnity information

8305260261 Forwards Endorsements 55 & 56 to MAELU Policy NF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101, respectively, for McGuire
LAWSON, L T Duke Power Co 83/05/20 SALTZMAN, J Office of Resource Management, Director 19pp 18626 120 24X
Fiche 50-000, 83/05/20, 8305260261

P Operating license stage documents & correspondence

8305090078 Forwards Amends 120, 120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules
CONNER, E L Operating Reactors Branch 4 83/04/15 TUCKER, H B
Duke Power Co 4pp 18381 140 24X Fiche 50-269, 83/04/15, 8305090078

--8305090111 Amends 120, 120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Spec withdrawal schedule for reactor vessel surveillance capsules
STOLZ, J F Operating Reactors Branch 4 83/04/15 8pp
18381 144 24X Fiche 50-269, 83/04/15, 8305090078

--8305090124 Safety evaluation supporting Amends 120, 120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/15 2pp
18381 152 24X Fiche 50-269, 83/04/15, 8305090078

--8305090138 Notice of issuance & availability of Amends 120, 120 & 117 to Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 83/04/15 2pp
18381 154 24X Fiche 50-269, 83/04/15, 8305090078

8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "Control of Heavy Loads (C-10), Oconee Nuclear Power Station, Units 1, 2 & 3 " Phase 1 actions acceptable per NUREG-0612
STOLZ, J F Operating Reactors Branch 4 83/04/20 TUCKER, H B
Duke Power Co 3pp 18457 179 24X Fiche 50-269, 83/04/20, 8305130294

--8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612)
* Office of Nuclear Reactor Regulation, Director 83/04/20 1p
18457 182 24X Fiche 50-269, 83/04/20, 8305130294

--8304070286 "Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1, 2 & 3," technical evaluation rept
ROBERTS, S Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-374/375/37 83/03/31 CLEMENSON, F NRC
- No Detailed Affiliation Given 28pp 18457 183 24X
Fiche 50-269, 83/04/20, 8305130294

8305020372 Forwards corrections & updates to 830418 ltr supporting 830418 application for amend to License DPR-38, postponing certain instrument surveillance requirements
TUCKER, H B Duke Power Co 83/04/22 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18276 290 24X Fiche 50-269, 83/04/22, 8305020372

--8305020375 Corrected & updated proposed Tech Spec changes re instrument surveillance requirements
* Duke Power Co 83/04/22 17pp 18276 292 24X
Fiche 50-269, 83/04/22, 8305020372

8305090608 Forwards safety evaluation in support of continued PWR operation w/Dresser primary safety valves re TMI Action Item II D 1 EPRI data on tests of certain models of Dresser safety valves under review on generic basis
STOLZ, J F Operating Reactors Branch 4 83/04/27 TUCKER, H B
Duke Power Co 2pp 18367 111 24X Fiche 50-269, 83/04/27, 8305090608

--8305090612 SER in support of continued PWR operation w/Dresser primary safety valves (TMI Action Item II D 1)
* Operating Reactors Branch 4 83/04/27 13pp 18367 113 24X
Fiche 50-269, 83/04/27, 8305090608

8305040564 Forwards proposed App A to offsite dose calculation manual, supporting radiological effluent Tech Spec per 830209 ltr Submittal constitutes final revised offsite dose calculation manual
TUCKER, H B Duke Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 1p 18320 083 24X Fiche 50-269, 83/04/28, 8305040564

--8305040568 App A to, "Oconee Nuclear Station Site Specific Info "
* Duke Power Co 83/04/28 32pp 18320 084 24X
Fiche 50-269, 83/04/28, 8305040564

8305200103 Forwards safety evaluation on standby shutdown facility Design meets requirements, except for process monitoring instruments for source range flux monitoring & steam generator pressure indication
STOLZ, J F Operating Reactors Branch 4 83/04/28 TUCKER, H B
Duke Power Co 4pp 18576 154 24X Fiche 50-269, 83/04/28, 8305200103

--8305200106 Safety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication
* Office of Nuclear Reactor Regulation, Director 83/04/28
17pp 18576 158 24X Fiche 50-269, 83/04/28, 8305200103

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda, MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & justification for continued operation
MINER, S Operating Reactors Branch 4 83/05/02 STOLZ, J
Operating Reactors Branch 4 2pp 18353 092 24X
Fiche 50-000, 83/05/02, 8305060365

8305180034 Forwards Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage
EISENHUT, D G Division of Licensing 83/05/05 TUCKER, H B Duke Power Co 3pp 18499 245 24X Fiche 50-269, 83/05/05, 8305180034

--8305180045 Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to delay certain surveillance requirements until next refueling outage
STOLZ, J F Operating Reactors Branch 4 83/05/05 21pp
18499 248 24X Fiche 50-269, 83/05/05, 8305180034

--8305180059 Safety evaluation supporting Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 5pp
18499 269 24X Fiche 50-269, 83/05/05, 8305180034

--8305180068 Notice of issuance & availability of Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 83/05/05 2pp
18499 274 24X Fiche 50-269, 83/05/05, 8305180034

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180151 Forwards request for addl info re details on void formation during natural circulation cooldown, per 810505 Generic Ltr 81-21 Response dtd 811105 inadequate
STOLZ, J F Operating Reactors Branch 4 83/05/09 TUCKER, H B, Duke Power Co 4pp 18502 344 24X Fiche 50-269, 83/05/09, 8305180151

8305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCS temp between 250 F & 225 F rather than present 200 F Preparation of proposed Tech Specs re purging in progress
TUCKER, H B Duke Power Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18437 154 24X Fiche 50-269, 83/05/10, 8305130025

8305230499 Notification of 830608 meeting w/util in Bethesda, MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed
SUERMANN, J F Operating Reactors Branch 4 83/05/16 STOLZ, J F
Operating Reactors Branch 4 2pp 18541 274 24X
Fiche 50-000, 83/05/16, 8305230499

8305250479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation, per NUREG-0737, TMI Action Item II B 4 provided Response to IE Bulletin 79-01B will be revised
TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Licensing Branch 4 27pp 18589 005 24X Fiche 50-269, 83/05/19, 8305250479

8305270259 Application to amend License DPR-38, changing core protection safety limits, protective sys max allowable setpoints & rod position limits
TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 4pp 18641 224 24X Fiche 50-269, 83/05/19, 8305270259

--8305270279 Proposed Tech Spec changes re core protection safety limits, protective sys max allowable setpoints & rod position limits
* Duke Power Co 83/05/19 17pp 18641 228 24X
Fiche 50-269, 83/05/19, 8305270259

--8305270294 "Generic Startup Physics Test Program "
* Duke Power Co 83/03/31 22pp. 18641 245 24X
Fiche 50-269, 83/05/19, 8305270259

--8305270309 "Oconee Unit 1 Cycle 8 Reload Rept "
* Babcock & Wilcox Co BAW-1774 83/02/28 46pp 18641, 267, 24X Fiche 50-269, 83/05/19, 8305270259

8305310081 Submits addl info re safety-related environ qualification of electrical equipment, per 10CFR50 49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18655 123 24X
Fiche 50-269, 83/05/20, 8305310081

8305310083 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads Util assessment of asymmetric loads problem acceptable
STOLZ, J F Operating Reactors Branch 4 83/05/20 TUCKER, H B Duke Power Co 2pp 18662 311 24X Fiche 50-269, 83/05/20, 8305310083

--8305310089 Safety evaluation accepting util analysis of asymmetric LOCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided
* Operating Reactors Branch 4 83/05/20 74pp 18662 313 24X
Fiche 50-269, 83/05/20, 8305310083

G Inspection reports, IE Bulletins & correspondence

8305200303 Forwards order imposing civil monetary penalties transmitted to licensee on 821012, for transmittal to Ofc of FR for publication W/o encl
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/10/15 Docketing & Services Branch 1p
18517 062 24X Fiche 50-269, 82/10/15, 8305200303

8305200544 Submits addl response to 820625 notice of violation, per NRC 821012 request Directive 4 2 5, "Procedure for Implementing Independent Verification Requirements," will be revised Payment of civil penalty encl
TUCKER, H B Duke Power Co 82/11/11 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 4pp 18515 356 24X
Fiche 50-269, 82/11/11, 8305200544

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270403 Forwards IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18642 321 24X
Fiche 50-269, 83/04/05, 8305270403

--8305270411 IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted Major areas inspected operations, surveillance testing, maint, event rept review & emergency procedure review
BRYANT, J , FALCONER, D Region 2, Office of Director, IGNATONIS, A J Division of Project & Resident Programs 83/04/04
12pp 18642 323 24X Fiche 50-269, 83/04/05, 8305270403

8305270497 Forwards IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18646 192 24X
Fiche 50-269, 83/04/05, 8305270497

--8305270518 IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREG-0737, Items II B 2, "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys "
COLLINS, T R , BARR, K P Region 2, Office of Director 83/04/01
7pp 18646 194 24X Fiche 50-269, 83/04/05, 8305270497

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383, 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025,

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co, of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270326 Forwards IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/06
TUCKER,H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269,83/05/06,8305270326

--8305270338 IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing,maint & operations & annual emergency drill
BRYANT,J , FALCONER,D Region 2, Office of Directr
BROWNLEE,V L Division of Project & Resident Programs 83/05/06
9pp. 18641 144 24X Fiche,50-269,83/05/06,8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs, 83/05/06
TUCKER,H B Duke Power Co 2pp 18643 011 24X
Fiche,50-269,83/05/06,8305270374

--8305270387 IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN,O N Region 2, Office of Director JENKINS,O R Division of Emergency Preparedness & Materials Safety 83/05/03 10pp 18643 013 24X Fiche 50-269,83/05/06,8305270374

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concern re open pressurization line test valve on Unit 3 discussed
O'REILLY,J P Region 2, Office of Director 83/05/11 TUCKER,H B Duke Power Co 2pp 18642 280 24X Fiche 50-269,83/05/11, 8305270425.

--8305270435 IE Enforcement Conference Repts 50-269/83-12,50-270/83-12 & 50-287/83-12 on 830323 & 0419 Major areas discussed open pressurization line isolation valve on emergency hatch on 830317 & corrective actions
DANCE,H C Division of Project & Resident Programs 83/05/10
3pp 18642·282 24X Fiche 50-269,83/05/11,8305270425

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp, 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305310081 Submits addl info re safety-related environ qualification of electrical equipment,per 10CFR50 49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 18655 123 24X Fiche 50-269,83/05/20,8305310081

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170455 Forwards monthly operating repts for Apr 1983
TUCKER,H B Duke Power Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18470 142 24X
Fiche 50-269,83/05/13,8305170455

--8305170460 Monthly operating repts for Apr 1983
REAVIS,J A Duke Power Co 83/05/13 16pp 18470 143 24X
Fiche 50-269,83/05/13,8305170455

S Reportable occurrences, LERs & related correspondence

8109040024 PND-II-81-052A on 810715,while performing reactor vessel insp w/remote video cameras,loose parts discovered in bottom of vessel Parts identified as missing from internal vessel structures Caused by corrosion fatigue
BRYANT,J C Region 2, Atlanta, Office of the Director (81/03/01)
81/08/07 1p 18326 300 24X Fiche 50-269,81/08/07,8109040024

8305050341 Forwards AEOD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR,RES & IE
BROWN,E J , ASHE,F S Reactor Operations Analysis Branch 83/04/13
SEYFRIT,K V Reactor Operations Analysis Branch 2pp 18352 051
24X Fiche 50-000,83/04/13,8305050341

--8305050353 "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment," AEOD engineering evaluation rept
BROWN,E J , ASHE,F S Director's Office 83/04/13 7pp
18352 053 24X Fiche 50-000,83/04/13,8305050341

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305170324 Forwards LER 83-012/01T-0 Detailed event analysis encl
TUCKER,H B Duke Power Co 83/04/22 O'REILLY,J P Region 2, Office of Director 4pp 18465 227 24X Fiche 50-269,83/04/22, 8305170324

--8305170338 LER 83-012/01T-0 on 830408,emergency discharge valve to Keowee Tailrace CCW-8 opened w/o command,rendering condenser circulating water emergency discharge sys inoperable Caused by shorted conductor Conductor replaced
PETTY,J C Duke Power Co 83/04/22 Region 2, Office of Director 1p 18465 231 24X Fiche 50-269,83/04/22,8305170324.

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co., Ltd)
83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000,83/04/27,8305110324

8305050254 ROs 269/83-10 & 287/83-04 re 821212 & 830303 loss of containment integrity Mgt audit in progress Summary list of completed & remaining activities,w/projected completion dates,encl
TUCKER,H B Duke Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 15pp 18338 001 24X Fiche 50-269,83/04/29, 8305050254

8305170561 Forwards updated LER 83-012/01T-1 Detailed event analysis encl
TUCKER,H B Duke Power Co 83/05/05 O'REILLY,J P Region 2, Office of Director 2pp 18468 125 24X Fiche 50-269,83/05/05, 8305170561

--8305170566 Updated LER 83-012/01T-1 on 830421,emergency discharge valve to Keowee Tailrace CCW-8 opened w/o command,rendering condenser circulating water emergency discharge sys inoperable Caused by component failure
PETTY,J C Duke Power Co 83/05/05 Region 2, Office of Director 1p 18468 127 24X Fiche 50-269,83/05/05,8305170561

8305250556 Notifies that noble gas monitor-stack high-range radiation monitor (NUREG-0737,Item II F 1(1)) reported as being operable in 830318 order,became inoperable on 830426 Caused by moisture contamination New monitors ordered
TUCKER,H B Duke Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 2pp 18588 185 24X Fiche 50-269,83/05/19,8305250556

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305270326 Forwards IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/06
TUCKER,H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269,83/05/06,8305270326

--8305270338 IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing,maint & operations & annual emergency drill
BRYANT,J Region 2, Office of Director 83/05/06 9pp
18641 144 24X Fiche 50-269,83/05/06,8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/06
TUCKER,H B Duke Power Co 2pp 18643 011 24X
Fiche 50-269,83/05/06,8305270374

--8305270387 IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN,G N Region 2, Office of Director 83/05/03 10pp
18643 013 24X Fiche 50-269,83/05/06,8305270374

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

J Insurance & indemnity information

8305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101,respectively,for McGuire
LAWSON,L T Duke Power Co 83/05/20 SALTZMAN,J Office of Resource Management, Director 19pp 18626 120 24X
Fiche 50-000,83/05/20,8305260261

P Operating license stage documents & correspondence

8305090078 Forwards Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules
CONNER,E L Operating Reactors Branch 4 83/04/15 TUCKER,H B
Duke Power Co 4pp 18381 140 24X Fiche 50-269,83/04/15, 8305090078

--8305090111 Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55, respectively,revising Tech Spec withdrawal schedule for reactor vessel surveillance capsules
STOLZ,J F Operating Reactors Branch 4 83/04/15 8pp
18381 144 24X Fiche 50-269,83/04/15,8305090078

--8305090124 Safety evaluation supporting Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively
* Office of Nuclear Reactor Regulation, Director 83/04/15 2pp
18381 152 24X Fiche 50-269,83/04/15,8305090078

--8305090138 Notice of issuance & availability of Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively
STOLZ,J F Operating Reactors Branch 4 83/04/15 2pp
18381 154 24X Fiche 50-269,83/04/15,8305090078

8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "Control of Heavy Loads (C-10),Oconee Nuclear Power Station,Units 1,2 & 3 " Phase 1 actions acceptable per NUREG-0612
STOLZ,J F Operating Reactors Branch 4 83/04/20 TUCKER,H B
Duke Power Co 3pp 18457 179 24X Fiche 50-269,83/04/20, 8305130294

--8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612)
* Office of Nuclear Reactor Regulation, Director 83/04/20 1p
18457 182 24X Fiche 50-269,83/04/20,8305130294

--8304070286 "Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1,2 & 3," technical evaluation rept
ROBERTS,S Franklin Institute/Franklin Research Center
NRC-03-81-130 TER-C5506-374/375/37 83/03/31 CLEMENSON,F NRC
- No Detailed Affiliation Given 28pp 18457 183 24X
Fiche 50-269,83/04/20,8305130294

8305090608 Forwards safety evaluation in support of continued PWR operation w/Dresser primary safety valves re TMI Action Item II D 1 EPRI data on tests of certain models of Dresser safety valves under review on generic basis
STOLZ,J F Operating Reactors Branch 4 83/04/27 TUCKER,H B
Duke Power Co 2pp 18367 111 24X Fiche 50-269,83/04/27, 8305090608

8305040564 Forwards proposed App A to offsite dose calculation manual, supporting radiological effluent Tech Spec per 830209 ltr Submittal constitutes final revised offsite dose calculation manual
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 18320 083 24X Fiche 50-269,83/04/28,8305040564

--8305040568 App A to, "Oconee Nuclear Station Site Specific Info "
* Duke Power Co 83/04/28 32pp 18320 084 24X
Fiche 50-269,83/04/28,8305040564

8305200103 Forwards safety evaluation on standby shutdown facility Design meets requirements,except for process monitoring instruments for source range flux monitoring & steam generator pressure indication
STOLZ,J F Operating Reactors Branch 4 83/04/28 TUCKER,H B
Duke Power Co 4pp 18576 154 24X Fiche 50-269,83/04/28, 8305200103,

--8305200106 Safety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication
* Office of Nuclear Reactor Regulation, Director 83/04/28
17pp 18576 158 24X Fiche 50-269,83/04/28,8305200103

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda,MD to discuss core barrel failure at Rancho Seco & Crystal River 3,future plans for resolving problem & justification for continued operation
MINER,G Operating Reactors Branch 4 83/05/02 STOLZ,J
Operating Reactors Branch 4 2pp 18353 092 24X
Fiche 50-000,83/05/02,8305060365

8305180034 Forwards Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage
EISENHUT,D G Division of Licensing 83/05/05 TUCKER,H B Duke Power Co 3pp 18499 245 24X Fiche 50-269,83/05/05,8305180034

--8305180045 Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55, respectively,revising Tech Specs to delay certain surveillance requirements until next refueling outage
STOLZ,J F Operating Reactors Branch 4 83/05/05 21pp
18499 248 24X Fiche,50-269,83/05/05,8305180034

--8305180059 Safety evaluation supporting Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 5pp
18499 269 24X Fiche 50-269,83/05/05,8305180034

--8305180068 Notice of issuance & availability of Amends 121, 121 & 118 to Licenses DPR-38, DPR-47 & DPR-55, respectively
STOLZ, J F Operating Reactors Branch 4 83/05/05 2pp
18499 274 24X Fiche 50-269, 83/05/05, 8305180034

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180151 Forwards request for addl info re details on void formation during natural circulation cooldown, per 810505 Generic Ltr 81-21 Response dtd 811105 inadequate
STOLZ, J F Operating Reactors Branch 4 83/05/09 TUCKER, H B
Duke Power Co 4pp 18502 344 24X Fiche 50-269, 83/05/09,
8305180151

8305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCS temp between 250 F & 225 F rather than present 200 F Preparation of proposed Tech Specs re purging in progress
TUCKER, H B Duke Power Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18437 154 24X Fiche 50-269, 83/05/10, 8305130025

8305230499 Notification of 830608 meeting w/util in Bethesda, MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed
SUERMANN, J F Operating Reactors Branch 4 83/05/16 STOLZ, J F
Operating Reactors Branch 4 2pp 18541 274 24X
Fiche 50-000, 83/05/16, 8305230499

8305250479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation, per NUREG-0737, TMI Action Item II B 4 provided Response to IE Bulletin 79-01B will be revised
TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Licensing Branch 4 27pp 18589 005 24X Fiche 50-269, 83/05/19, 8305250479

8305310081 Submits addl info re safety-related environ qualification of electrical equipment, per 10CFR50 49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18655 123 24X
Fiche 50-269, 83/05/20, 8305310081

8305310083 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads Util assessment of asymmetric loads problem acceptable
STOLZ, J F Operating Reactors Branch 4 83/05/20 TUCKER, H B
Duke Power Co 2pp 18662 311 24X Fiche 50-269, 83/05/20,
8305310083

--8305310089 Safety evaluation accepting util analysis of asymmetric LOCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided
* Operating Reactors Branch 4 83/05/20 74pp 18662 313 24X
Fiche 50-269, 83/05/20, 8305310083

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl,
TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270403 Forwards IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18642 321 24X
Fiche 50-269, 83/04/05, 8305270403

--8305270411 IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted Major areas inspected operations, surveillance testing, maint, event rept review & emergency procedure review
BRYANT, J , FALCONER, D Region 2, Office of Director
IGNATONIS, A J Division of Project & Resident Programs 83/04/04
12pp 18642 323 24X Fiche 50-269, 83/04/05, 8305270403

8305270497 Forwards IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18646 192 24X
Fiche 50-269, 83/04/05, 8305270497

--8305270518 IE Insp Repts 50-269/83-09, 50 270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREG-0737, Items II B 2, "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys "
COLLINS, T R , BARR, K P Region 2, Office of Director 83/04/01
7pp 18646 194 24X Fiche 50-269, 83/04/05, 8305270497

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 143 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270326 Forwards IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269, 83/05/06, 8305270326

--8305270338 IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing, maint & operations & annual emergency drill
BRYANT, J , FALCONER, D Region 2, Office of Director
BROWNLEE, V L Division of Project & Resident Programs 83/05/06
9pp 18641 144 24X Fiche 50-269, 83/05/06, 8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18643 011 24X
Fiche 50-269, 83/05/06, 8305270374

--8305270387 IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/03 10pp
18643 013 24X Fiche 50-269, 83/05/06, 8305270374

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concern re open pressurization line test valve on Unit 3 discussed
O'REILLY,J P Region 2, Office of Director 83/05/11 TUCKER,H B Duke Power Co 2pp 18642 280 24X Fiche 50-269,83/05/11, 8305270425

--8305270435 IE Enforcement Conference Repts 50-269/83-12,50-270/83-12 & 50-287/83-12 on 830323 & 0419 Major areas discussed open pressurization line isolation valve on emergency hatch on 830317 & corrective actions
DANCE,H C Division of Project & Resident Programs 83/05/10 5pp 18642 282 24X Fiche 50-269,83/05/11,8305270425

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305310081 Submits addl info re safety-related environ qualification of electrical equipment,per 10CFR50 49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 18655 123 24X Fiche 50-269,83/05/20,8305310081

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170455 Forwards monthly operating repts for Apr 1983
TUCKER,H B Duke Power Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18470 142 24X
Fiche 50-269,83/05/13,8305170455

--8305170460 Monthly operating repts for Apr 1983
REAVIS,J A Duke Power Co 83/05/13 16pp 18470 143 24X
Fiche 50-269,83/05/13,8305170455

S Reportable occurrences, LERs & related correspondence

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL,D B Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000,83/04/27,8305110324.

8305110323 Forwards LER 83-006/03L-0 Detailed event analysis encl
TUCKER,H B Duke Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 3pp 18406 143 24X Fiche 50-270,83/04/29, 8305110323

--8305110335 LER 83-006/03L-0.on 830401,after pumping down reactor bldg normal sump level,valve 2LWD-1 found cycling open & shut since work completion Caused by component malfunction Valve locked shut Valve will be disassembled for repair
PETTY,J C Duke Power Co 83/04/29 Region 2, Office of Director 1p 18406 146 24X Fiche 50-270,83/04/29,8305110323

8305250556 Notifies that noble gas monitor-stack high-range radiation monitor (NUREG-0737,Item II F 1(1)) reported as being operable in 830318 order,became inoperable on 830426 Caused by moisture contamination New monitors ordered.
TUCKER,H B Duke Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 2pp 18588 185 24X Fiche.50-269,83/05/19,8305250556

DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION

F Security, medical, emergency & fire protection plans

8305190310 Forwards IE Safeguards Insp Rept 50-271/83-08 on 830404-08 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/05/05
MURPHY,W P Vermont Yankee Nuclear Power Corp 3pp 18501 066
24X Fiche 50-271,83/05/05,8305190310

--8305190311 Notice of violation from insp on 830404-08 Safeguards info deleted (ref 10CFR73 21)
* Region 1, Office of Director 83/05/05 1p 18501 069 24X
Fiche 50-271,83/05/05,8305190310

--8305190313 IE Safeguards Insp Rept 50-271/83-08 on 830404-08 Noncompliance noted vital area barrier degraded w/o compensatory measures in effect Safeguards info deleted (ref 10CFR73 21)
SMITH,G C , DUNLAP,J M , GODY,A T Region 1, Office of Director 83/04/22 4pp 18501 070 24X Fiche 50-271,83/05/05,8305190310

8305200708 Responds to 830128 ltr re changes identified as Rev 7 to physical security plan Changes do not decrease effectiveness of plan,w/exception of changes on Page 9-2 & Figure 9-1 Bullet-resistant structure requirements unclear
VASSALLO,D B Operating Reactors Branch 2 83/05/09 SINCLAIR,J B.
Vermont Yankee Nuclear Power Corp 2pp 18528 355 24X
Fiche 50-271,83/05/09,8305200708

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240591 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed.Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 SINCLAIR,J.B
Vermont Yankee Nuclear Power Corp 3pp 18594 211 24X
Fiche 50-271,83/05/18,8305240591

8305310212 Fowards errata to 830128 Rev 7 to security plan Errata withheld (ref 10CFR73 21)
SINCLAIR,J B Vermont Yankee Nuclear Power Corp 83/05/23
VASSALLO,D B Operating Reactors Branch 2 1p 18658 134 24X
Fiche 50-271,83/05/23,8305310212

P Operating license stage documents & correspondence

8305020552 Forwards request for addl info needed to review structural aspects of util plant-unique analysis rept for Mark I containment long-term program Response requested within 45 days.
VASSALLO,D B Operating Reactors Branch 2 83/04/14, SINCLAIR,J B.
Vermont Yankee Nuclear Power Corp 8pp 18284 249 24X
Fiche 50-271,83/04/14,8305020552

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs,Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305170069 Forwards Amend 79 to License DPR-28,safety evaluation & notice of issuance & availability Amend modifies organizational placement of shift technical advisors
ROONEY,V L, Operating Reactors Branch 2 83/05/02, SINCLAIR,J.B.
Vermont Yankee Nuclear Power Corp 2pp 18495 185, 24X
Fiche 50-271,83/05/02,8305170069

--8305170071 Amend 79 to License DPR-28,modifying organizational placement of shift technical advisors
VASSALLO,D B Operating Reactors Branch 2, 83/05/02 7pp
18495.187 24X Fiche:50-271,83/05/02,8305170069

--8305170072 Safety evaluation supporting Amend 79 to License DPR-28,
* Office of Nuclear Reactor Regulation, Director 83/05/02, 2pp
18495.194 24X Fiche:50-271,83/05/02,8305170069

--8305170075 Notice of issuance & availability of Amend 79 to License DPR-28
VASSALLO,D B Operating Reactors Branch 2, 83/05/02 2pp
18495.196, 24X Fiche 50-271,83/05/02,8305170069

8305230068 Advises that action required by Amend 74 to License DPR-28 & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 18543 150 24X
Fiche 50-271, 83/05/05, 8305230068

8305230115 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved
VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 5pp 18546 344 24X
Fiche 50-271, 83/05/05, 8305230115

8305230279 Forwards safety evaluation of plant mods & design review of shielding for vital areas per NUREG-0737, Item II B 2 2 Required mods completed & acceptable
VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 6pp 18543 268 24X
Fiche 50-271, 83/05/05, 8305230279

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130103 Forwards Rev 0 to "Improved Dynamic Vacuum Breaker Valve Response for Vermont Yankee," in response to NRC 830202 Generic Ltr 83-08
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/11
VASSALLO, D. B Operating Reactors Branch 2 1p 18438 061 24X
Fiche 50-271, 83/05/11, 8305130103

--8305130104 Rev 0 to "Improved Dynamic Vacuum Breaker Valve Response for Vermont Yankee "
BILANIN, A J Continuum Dynamics, Inc 83/05/11 20pp
18438 062 24X Fiche 50-271, 83/05/11, 8305130103

8305230312 Forwards request for addl info needed to complete review of util 810515 response to NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulators " Response requested within 45 days of receipt of ltr
VASSALLO, D B Operating Reactors Branch 2 83/05/11 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 3pp 18543 301 24X
Fiche 50-271, 83/05/11, 8305230312

8305200517 Forwards list of additions & deletions of safety-related shock suppressors installed to conform w/acceptance criteria in NUREG-0661 Proposed change to Tech Specs will be submitted by 830601
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/17,
VASSALLO, D B Operating Reactors Branch 2 3pp 18516 080 24X
Fiche: 50-271, 83/05/17, 8305200517

8305240195 Forwards summary of NUREG-0737 Tech Spec review to determine consistency w/guidance criteria provided in 830110 Generic Ltr 83-02.
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/17
VASSALLO, D B Operating Reactors Branch 2 5pp 18548 032 24X
Fiche. 50-271, 83/05/17, 8305240195

8305260296 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mod to plant design or operations required Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 18629 330 24X
Fiche: 50-271, 83/05/18, 8305260296

8305250569 Proposed Change 108 to License DPR-28, App A, revising Tech Specs re safety-related shock suppressors Rev makes number of snubbers installed concurrent w/completion of Mark I containment long-term program
HEIDER, L H Vermont Yankee Nuclear Power Corp 83/05/20 Office of Nuclear Reactor Regulation, Director 2pp 18588 216 24X
Fiche: 50-271, 83/05/20, 8305250569

--8305250574 Proposed Tech Specs re safety-related shock suppressors, making number of snubbers installed concurrent w/completion of Mark I containment long-term program
* Vermont Yankee Nuclear Power Corp 83/05/20 6pp 18588 218
24X Fiche: 50-271, 83/05/20, 8305250569

8305260114 Informs that response to NUREG-0737, Item II K 3.13 re RCIC restart complete for facility, based on 830415 commitment to follow GE Owners Group conceptual design
VASSALLO, D B Operating Reactors Branch 2 83/05/20 SINCLAIR, J. B
Vermont Yankee Nuclear Power Corp 2pp 18649.065. 24X
Fiche: 50-271, 83/05/20, 8305260114.

8305270141 Requests exemption from schedular requirements of equipment qualification final rule (10CFR50 48(d)) Final submittal expected by 830610 Delay due to late receipt of Franklin Research Ctr rept
SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/05/20
EISENHUT, D G Division of Licensing 2pp 18638 206 24X
Fiche: 50-271, 83/05/20, 8305270141

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305120488 Addl response to FOIA request for six categories of documents Forwards App A documents
FELTON, J M Division of Rules and Records 83/03/25 HIATT, S L
Ohio Citizens for Responsible Energy 2pp 18457 211 24X
Fiche 50-271, 83/03/25, 8305120488

--8207300178 Details of IE Investigation Rept 50-271/82-12 on 820606-10 No noncompliance noted Major areas investigated licensee actions in withholding info re 820424 loss of feedwater transient Proprietary details deleted (ref 10CFR2 790)
* Region 1, Office of Director 82/07/20 38pp 18457 217 24X
Fiche 50-271, 83/03/25, 8305120488

--8305130223 Forwards chronology of Region I actions re 820424 loss of feedwater event, insp investigation, documentations, meetings w/state & licensee officials, evaluations of appropriate enforcement action & processing civil penalty
HOLODY, D J Region 1, Office of Director 82/10/13 AXELRAD, J
Director's Office, Office of Inspection and Enforcement 3pp
18457 262. 24X Fiche 50-271, 83/03/25, 8305120488

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305190187 Forwards IE Insp Rept 50-271/83-06 on 830329-0401. No noncompliance noted
MARTIN, T. T Division of Engineering & Technical Programs 83/05/04
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 18502.260
24X Fiche 50-271, 83/05/04, 8305190187

--8305190191 IE Insp Rept 50-271/83-06 on 830329-0401 No noncompliance noted Major areas inspected radiation protection program advanced planning & preparation, training, contaminated hydrolaser & followup on previous insp findings
CLEMONS, P , SHANBAKY, M Region 1, Office of Director 83/04/25, 5pp 18502 262 24X Fiche 50-271, 83/05/04, 8305190187

8305090184 EN-83-031 on 830510, notice of violation & proposed imposition of civil penalties in amount of $40,000 will be issued to util Action based on Tech Spec limiting condition for operation violation re secondary containment integrity
BARBER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/05 1p 18364 001 24X Fiche 50-271, 83/05/05, 8305090184

8305190310 Forwards IE Safeguards Insp Rept 50-271/83-08 on 830404-08 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/05
MURPHY, W P Vermont Yankee Nuclear Power Corp 3pp 18501 046
24X Fiche 50-271, 83/05/05, 8305190310

--8305190311 Notice of violation from insp on 830404-08 Safeguards info deleted (ref 10CFR73 21)
* Region 1, Office of Director 83/05/05 1p 18501 069 24X
Fiche 50-271, 83/05/05, 8305190310

--8305190313 IE Safeguards Insp Rept 50-271/83-08 on 830404-08 Noncompliance noted vital area barrier degraded w/o compensatory measures in effect Safeguards info deleted (ref 10CFR73 21)
SMITH, G C , DUNLAP, J M , GODY, A T Region 1, Office of Director 83/04/22 4pp 18501 070 24X Fiche 50-271, 83/05/05, 8305190310

8305230253 Advises that responsibility for evaluating util proposed actions in response to IE Bulletin 83-02 re recirculation sys pipe cracks & restart approval, transferred to Div of Licensing
VASSALLO, D B Operating Reactors Branch 2 83/05/05 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 18543 249 24X
Fiche 50-271, 83/05/05, 8305230253

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305250572 Discusses IE insp on 830321-25 & forwards notice of violation & proposed imposition of civil penalty
ALLAN, J M Region 1, Office of Director 83/05/10 MURPHY, W P
Vermont Yankee Nuclear Power Corp 3pp 18594 347 24X
Fiche 50-271, 83/05/10, 8305250572

--8305250577 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted on 830321, secondary containment integrity not maintained when irradiated fuel rods & bundles moved within fuel pool
ALLAN, J M Region 1, Office of Director 83/05/10 4pp
18594 350 24X Fiche 50-271, 83/05/10, 8305250572

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305250447 Forwards IE Mgt Meeting Rept 50-271/83-10 on 830419 to discuss intergranular stress corrosion cracking of recirculation sys
STAROSTECKI, R Division of Project & Resident Programs 83/05/11
MURPHY, W P Vermont Yankee Nuclear Power Corp 2pp 18585 204
24X Fiche 50-271, 83/05/11, 8305250447

--8305250450 IE Mgt Meeting Rept 50-271/83-10 on 830419 Major areas discussed intergranular stress corrosion cracking problems & response to IE Bulletin 83-02
HOLDEN, C F , GALLO, R M Region 1, Office of Director 83/04/21
4pp 18585 206 24X Fiche 50-271, 83/05/11, 8305250447

8303040040 IE Info Notice 83-31, "Error In ADLPIPE Computer Program." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305270045 Discusses review of relief requests from inservice insp requirements per 10CFR50 55a(g) Relief granted for requirements impractical to implement SER, technical evaluation & FR notice of granting of relief encl
VASSALLO, D B Operating Reactors Branch 2 83/05/19 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 3pp 18661 171 24X
Fiche 50-271, 83/05/19, 8305270045

--8305270050 Safety evaluation granting in part & denying in part, requests for relief from inservice insp requirements per 10CFR50 55a(g)
* Office of Nuclear Reactor Regulation, Director 83/05/19
12pp 18661 174 24X Fiche 50-271, 83/05/19, 8305270045

--8305270052 "VT Yankee Nuclear Power Station Inservice Insp Program." technical evaluation rept
* Science Applications, Inc NRC-03-82-096 186-028-24
82/09/02 NRC - No Detailed Affiliation Given 62pp
18661 186 24X Fiche 50-271, 83/05/19, 8305270045

--8305270055 Notice of granting of relief from ASME Code Section XI inservice insp requirements
VASSALLO, D B Operating Reactors Branch 2 83/05/19 2pp
18661 249 24X Fiche 50-271, 83/05/19, 8305270045

8305250480 Clarifies 830324 response to util 821203 ltr re IE Insp Rept 50-271/82-13, redirecting attention to requirement to maintain related records of maint performed by licensee on package at licensee site, as noted in IE Info Notice 83-10
MARTIN, T T Division of Engineering & Technical Programs 83/05/20
MURPHY, W P Vermont Yankee Nuclear Power Corp 1p 18588 253
24X Fiche 50-271, 83/05/20, 8305250480

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305170006 Forwards monthly operating rept for Apr 1983
MURPHY, W P. Vermont Yankee Nuclear Power Corp 83/05/12 Office of Resource Management, Director 1p 18466 142 24X
Fiche 50-271, 83/05/12, 8305170006

--8305170007 Monthly operating rept for Apr 1983
BURGER, F J Vermont Yankee Nuclear Power Corp 83/05/09 7pp
18466 143 24X Fiche 50-271, 83/05/12, 8305170006

S Reportable occurrences, LERs & related correspondence

8305050341 Forwards AEOD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR, RES & IE
BROWN, E J , ASHE, F S Reactor Operations Analysis Branch 83/04/13
SEYFRIT, K V Reactor Operations Analysis Branch 2pp 18352 051
24X Fiche 50-000, 83/04/13, 8305050341

--8305050353 "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment," AEOD engineering evaluation rept
BROWN, E J , ASHE, F S Director's Office 83/04/13, 7pp
18352 053 24X Fiche 50-000, 83/04/13, 8305050341

8305050101 Forwards LER 83-011/03L-0
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/04/25,
ALLAN, J M Region 1, Office of Director 1p 18341 336 24X
Fiche 50-271, 83/04/25, 8305050101

--8305050108 LER 83-011/03L-0 on 830325, during visual insp, shock suppressor MS-6 on main steam A piping found w/no visible fluid in sight glass & failed to lock up Caused by damaged lenztee Snubber cleaned & rebuilt
PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/04/25,
Region 1, Office of Director 1p 18341 337 24X
Fiche, 50-271, 83/04/25, 8305050101

V Operator Examinations

8305240343 Withdraws commitment re NUREG-0737, Item I A I 3, "Licensing Exam Criteria " Recommendations to delete requirement for use of simulator exam as part of operator license exam program approved per 821012 Generic Ltr 82-18 & SECY 82-232
HEIDER, L H Vermont Yankee Nuclear Power Corp. 83/05/19
VASSALLO, D B Operating Reactors Branch 2 2pp 18572 359 24X
Fiche 50-271, 83/05/19, 8305240343

DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305130307 Releases public version of revised emergency plan
FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18456 335 24X Fiche 50-272, 83/05/02, 8305130307

--8305130308 Forwards public version of Rev 2 to emergency plan Receipt form encl
* Jersey Central Power & Light Co 83/04/04 VARGA,S A
Operating Reactors Branch 1 1p 18456 336 24X
Fiche 50-272,83/05/02,8305130307

--8305130309 Public version of Rev 2 to emergency plan
BURGE,C A , MIDURA,H J Jersey Central Power & Light Co
83/04/04 188pp 18456 337 24X Fiche 50-272,83/05/02,
8305130307

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305270043 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation re security access control denied
STAROSTECKI,R Division of Project & Resident Programs 83/05/23
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
18638 345 24X Fiche 50-272,83/05/23,8305270043

--8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl Encls withheld (ref 10CFR73 21)
UDERITZ,R A Public Service Electric & Gas Co of New Jersey
83/05/05 Region 1, Office of Director 3pp 18638 347 24X
Fiche 50-272,83/05/23,8305270043

O Adjudicatory correspondence

8305170493 Order extending time until 830527 for Commission to act to review Director's Decision DD-83-6
CHILK,S J Office of the Secretary of the Commission 83/05/13
Commissioners 1p 18470 024 24X Fiche 50-272,83/05/13,
8305170493

8305310008 Order extending time until 830601 for Commission to act to review Director's Decision DD-83-6
CHILK,S J Office of the Secretary of the Commission 83/05/27
Commissioners 1p 18653 230 24X Fiche 50-272,83/05/27,
8305310008

I Financial information

8305200067 Forwards Annual Financial Repts for 1982
FRYLING,R Public Service Electric & Gas Co of New Jersey
83/05/17. Office of Nuclear Reactor Regulation, Director 1p
18516 198 24X Fiche 50-000,83/05/17,8305200067

J Insurance & indemnity information

8305160157 Forwards Endorsements 58 & 45 to NELIA Policy NF-230 & MAELU Policy MF-90,respectively
GOLDEN,M P Marsh & McLennan, Inc 83/05/02 SALTZMAN,J
Assistant Director for State & Licensee Relations 3pp 18445 089
24X Fiche 50-272,83/05/02,8305160157

P Operating license stage documents & correspondence

8305050013 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys (TMI Action Item II F 2) Westinghouse reactor vessel level instrumentation sys, described in 801231,810206 & 1207 submittals,utilized
LIDEN,E.A Public Service Electric & Gas Co of New Jersey
83/04/22 VARGA,S A Operating Reactors Branch 1 27pp
18339 028 24X Fiche 50-272,83/04/22,8305050013

8305020186 Clarifies 830422 response to NRC 830420 ltr, Item 2,II D 10CFR50 54(f),re Westinghouse treatment of undervoltage trip attachment delivered disassembled
UDERITZ,R A Public Service Electric & Gas Co of New Jersey
83/04/27 EISENHUT,D G. Division of Licensing 2pp 18278 192
24X Fiche 50-272,83/04/27,8305020186

8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07,NUREG-0612, "Control of Heavy Loads," to confirm & clarify items discussed in 820804 telcon
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/04/27 VARGA,S A Operating Reactors Branch 1 8pp 18399 007
24X Fiche 50-272,83/04/27,8305110154

--8305110156 PSE-0108, "Maint Procedures "
* Public Service Electric & Gas Co of New Jersey 83/04/27
1,317pp 18399 101 24X Fiche 50-272,83/04/27,8305110154

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305090457 Application to amend Licenses DPR-70 & DPR-75,revising safety Tech Specs by raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/05/04 VARGA,S A Operating Reactors Branch 1 2pp 18360 252
24X Fiche 50-272,83/05/04,8305090457

--8305090459 Proposed changes to safety Tech Specs,raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1
* Public Service Electric & Gas Co of New Jersey 83/05/04
4pp 18360 254 24X Fiche 50-272,83/05/04,8305090457

8305170079 Forwards Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively,safety evaluation & notice of issuance & availability Amends raise trip setpoint & allowable value of steam generator water level low-low reactor trip
FISCHER,D Operating Reactors Branch 1 83/05/05 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 18495 211
24X Fiche 50-272,83/05/05,8305170079

--8305170084 Amends 53 & 21 to License DPR-70 & DPR-75,respectively, raising trip setpoint & allowable value of steam generator water level low-low reactor trip
VARGA,S A Operating Reactors Branch 1 83/05/05 8pp
18495 214 24X Fiche 50-272,83/05/05,8305170079

--8305170087 Safety evaluation supporting Amends 53 & 21 to Licenses DPR-70 & DPR-75,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18495 222 24X Fiche 50-272,83/05/05,8305170079

--8305170090 Notice of issuance & availability of Amends 53 & 21 to Licenses DPR-70 & DPR-75,respectively
VARGA,S A Operating Reactors Branch 1 83/05/05 2pp
18495 224 24X Fiche 50-272,83/05/05,8305170079

8305170117 Forwards Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively,safety evaluation & notice of issuance & availability Amends change partial power multiplier from 0 2 to 0 3
FISCHER,D Operating Reactors Branch 1 83/05/05 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 18496 001
24X Fiche 50-272,83/05/05,8305170117

--8305170119 Amends 52 & 20 to Licenses DPR-70 & DPR-75,respectively, changing partial power multiplier from 0 2 to 0 3
VARGA,S A Operating Reactors Branch 1 83/05/05 13pp
18496 004 24X Fiche 50-272,83/05/05,8305170117

--8305170124 Safety evaluation supporting Amends 52 & 20 to Licenses DPR-70 & DPR-75,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18496 017. 24X Fiche 50-272,83/05/05,8305170117

--8305170129 Notice of issuance & availability of Amends 52 & 20 to Licenses DPR-70 & DPR-75,respectively
VARGA,S A Operating Reactors Branch 1 83/05/05 2pp
18496 019 24X Fiche 50-272,83/05/05,8305170117

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 193 24X
Fiche 50-000,83/05/09,8305090659

8305170328 Forwards schedule for qualification or replacement of unqualified equipment for Categories I B,II A,II C & IV identified in SER on environ qualification of safety-related electrical equipment
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/05/09 VARGA,S A Operating Reactors Branch 1 16pp
18465 153 24X Fiche 50-272,83/05/09,8305170328

8305230504 Forwards affidavit & fee for review of 830504 application to amend Licenses DPR-70 & DPR-75
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/05/11 VARGA,S A Operating Reactors Branch 1 2pp 18537 170
24X Fiche 50-272,83/05/11,8305230504

8305310221 Requests assessment on operability of 10-inch pressure/vacuum relief valves used for purge or vent of containments to demonstrate that valves will operate in event of DBA-LOCA Info requested within 15 days
VARGA,S A Operating Reactors Branch 1 83/05/19 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 7pp 18662 261 24X Fiche 50-272,83/05/19,8305310221

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020258 Ack receipt of 830407 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-272/83-09 & 50-311/83-08
MARTIN,T T Division of Engineering & Technical Programs 83/04/26 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 1p. 18277 269 24X Fiche 50-272,83/04/26,8305020258

--8305020267 Responds to NRC 830310 ltr re violation noted in IE Insp Repts 50-272/83-09 & 50-311/83-08 Corrective actions Procedure RP7 004 revised to incorporate more extensive bracing for future low-specific activity box shipments
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 83/04/07 MARTIN,T T Division of Engineering & Technical Programs 2pp 18277 269 24X Fiche 50-272,83/04/26,8305020258

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047. 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp. 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8305090397 EN-83-032 on 830505,notice of violation & proposed imposition of civil penalties in amount of $850,000 to be issued Action based on violation of Tech Spec requirements re reactor trip breaker failure
KLINGLER,G , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/05/05 1p 18363 359 24X Fiche 50-272,83/05/05, 8305090397.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190163 Forwards IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/05/06 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 18502 240 24X Fiche 50-272,83/05/06,8305190163

--8305190169 Notice of violation from insp on 830321-25
* Region 1, Office of Director 83/05/06 1p 18502 242 24X Fiche 50-272,83/05/06,8305190163

--8305190174 IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25. Noncompliance noted failure to adhere to radiation protection procedures & failure to use suitable measurements of airborne radioactivity,per 10CFR20 103(a)(3)
NIMITZ,R L , SHANBAKY,M Region 1, Office of Director 83/05/06 13pp 18502 243 24X Fiche 50-272,83/05/06,8305190163

8305160085 Forwards response to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/82-33 & 50-311/82-31 on 820405-1016 Corrective actions,operational test group established to verify testing requirements Civil penalty fee encl
UDERITZ,R A Public Service Electric & Gas Co of New Jersey. 83/05/09, DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 7pp 18451 027 24X Fiche 50-272,83/05/09,8305160085

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program. " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040.

8305240285 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10
MARTIN,T T Division of Engineering & Technical Programs. 83/05/19. UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 18548 107 24X Fiche.50-272,83/05/19,8305240285

--8305240291 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10 Corrective actions all badges improperly issued destroyed Individual responsible no longer in security mgt position
UDERITZ,R A Public Service Electric & Gas Co of New Jersey. 83/04/25 Region 1, Office of Director 1p 18548 109 24X Fiche 50-272,83/05/19,8305240285

8305270043 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation re security access control denied
STAROSTECKI,R Division of Project & Resident Programs 83/05/23 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp. 18638.345 24X Fiche 50-272,83/05/23,8305270043

--8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl Encls withheld (ref 10CFR73.21)
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 83/05/05 Region 1, Office of Director 3pp 18638 347 24X Fiche 50-272,83/05/23,8305270043

8305270164 Ack receipt of 830509 ltr forwarding payment of proposed civil penalty Response to notice of violation & proposed imposition of civil penalty will be evaluated & corrective actions examined during future insp
AXELRAD,J.A. Enforcement Staff 83/05/25 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp 18638 064 24X Fiche:50-272,83/05/25,8305270164.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046.

R Periodic operating reports & related correspondence

8305170018 Forwards monthly operating rept for Apr 1983
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/05/10 Director's Office, Office of Inspection and Enforcement
1p 18466 163 24X Fiche 50-272, 83/05/10, 8305170018

--8305170021 Monthly operating rept for Apr 1983
MILLER, L K Public Service Electric & Gas Co of New Jersey
83/05/10 15pp 18466 164 24X Fiche 50-272, 83/05/10, 8305170018

S Reportable occurrences, LERs & related correspondence

8305200497 PNO-I-83-049 all licensee commitments required for restart completed Actions to assess & mitigate svc water biofouling in support of plant heatup anticipated to occur on 830518 completed
NORRHOLM, L , COLLINS, S Region 1, Office of Director 83/05/17
1p 18514 032 24X Fiche 50-272, 82/05/17, 8305200497

8305020150 Forwards 830414 & 26 ltrs documenting review of corrective action program re 830222 & 25 reactor trip breaker failures Ltrs previously transmitted at 830414 & 26 meetings
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/04/27 EISENHUT, D G Division of Licensing 2pp 18277 278
24X Fiche 50-272, 83/04/27, 8305020150

--8305020160 "Preliminary Review of PSE&G Co Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station Unit 1 "
* Basic Energy Technology Associates 83/04/14 6pp 18277 280
24X Fiche 50-272, 83/04/27, 8305020150

8305040630 Notifies of CRGR Meeting 36 on 830429 to discuss findings of Salem Generic Implications Task Force
STELLO, V Committee to Review Generic Requirements 83/04/27
EISENHUT, D G Office of Nuclear Reactor Regulation, Director
JORDAN, F L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 18336 306 24X Fiche 50-272, 83/04/27, 8305040630

8305030450 PNO-I-83-041 on 830425, while closing reactor trip breaker 1B to test newly installed reactor manual trip switches, breaker would not latch in closed position Caused by unattached coil spring at latch mechanism end
LAZARUS, W , KEIMIG, R Region 1, Office of Director 83/04/28 1p
18306 249 24X Fiche 50-272, 83/04/28, 8305030450

8305040262 Forwards summary listing short- & long-term actions & completion schedules re 830222 & 25 reactor trip breaker events. Corrective action program will also be applied to Unit 2 currently scheduled to return to svc in June 1983
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/04/28 EISENHUT, D G Division of Licensing 11pp 18323 249
24X Fiche 50-272, 83/04/28, 8305040262

8305060476 Forwards LER 83-009/99X-0 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/04/28 ALLAN, J Region 1, Office of Director 4pp 18348 161
24X Fiche 50-272, 83/04/28, 8305060476

--8305060482 LER 83-009/99X-0 on 830130, during routine plant cooldown, inadvertent safety injection occurred due to low pressurizer pressure Caused by operator overlooking decreasing pressure All safety-related equipment functioned as designed
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/04/20. Region 1, Office of Director 1p 18348 165 24X
Fiche 50-272, 83/04/28, 8305060476

8305090244 Responds to 830329 memo re mgt & technical issues of ATWS events Issues to be addressed in NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant " RHR capability addressed in Unresolved Safety Issue A-45
DENTON, H R. Office of Nuclear Reactor Regulation, Director
83/04/29 EPLER, E P Epler, E P 8pp 18381 084 24X
Fiche: 50-272, 83/04/29, 8305090244.

--8305090255 Requests comments re need for effective leadership in light of ATWS event, failure of RHR sys & small break mitigation & failure of institutions to employ best available technology
EPLER, E P Epler, E. P 83/03/29 PALLADINO, N J Commissioners
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards.
CULLER, F L Electric Power Research Institute 10pp 18381 091.
24X Fiche 50-272, 83/04/29, 8305090244

8305170064 Responds to 830412 petition & 0418 amend, requesting that NRC order PSE&G to show cause why facility restart should not be restrained Petition denied based on encl Director's Decision
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/29 RODRIGUEZ, J H New Jersey, State of 3pp 18494 184
24X Fiche 50-272, 83/04/29, 8305170064

--8305170085 Director's Decision DD 83-6, denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart until listed actions taken
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/29 8pp 18494 187 24X Fiche 50-272, 83/04/29, 8305170064

--8305170095 Safety evaluation re restart of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue
* Office of Nuclear Reactor Regulation, Director 83/04/28
45pp 18494 195 24X Fiche 50-272, 83/04/29, 8305170064

--8305170106 "Evaluation of Failure to Trip, of Reactor Trip Circuit Breakers on 830222 & 25, Salem Nuclear Generating Station Unit 1," interim technical evaluation rept
TOMAN, G J Franklin Institute/Franklin Research Center
NRC-03-81-130 83/04/07 SHEMANSKI, P NRC - No Detailed
Affiliation Given 71pp 18494 241 24X Fiche 50-272, 83/04/29,
8305170064

--8305170110 Notice of issuance of Director's Decision DD 83-6 denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart
CASE, E G Office of Nuclear Reactor Regulation, Director
83/04/29 2pp 18494 336 24X Fiche 50-272, 83/04/29, 8305170064

8305170674 GENERIC IMPLICATIONS OF ATWS EVENTS AT THE SALEM NUCLEAR POWER PLANT Generic Implications
* Office of Nuclear Reactor Regulation, Director NUREG-1000 V01
83/04/30 149pp Available at NRC $6 50 18481 183 24X
Fiche 50-272, 83/04/30, 8305170674

8305170232 Informs Commission of findings of Salem ATWS generic implications task force re overall mgt capability & performance & reactor trip sys reliability
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-158 83/05/02 159pp 18476 184 24X
Fiche 50-272, 83/05/02, 8305170232

8305100004 PNS-I-83-011 on 830504, security officer received bomb threat on inside plant telephone line from male caller Search initiated No bomb found Call considered hoax
MCKEOWN, GODY, JOYNER Region 1, Office of Director 83/05/04 1p
18377-291 24X Fiche 50-272, 83/05/04, 8305100004

8305100258 PNO-I-83-046 on 830428, diesel generator 1C tripped off bus during 1 h test Caused by biofouling in svc water sys Licensee plans comprehensive program of svc water sys chlorination & insp to evaluate extent of biofouling
NORRHOLM, L , TRIPP, L , KEIMIG, R Region 1, Office of Director
83/05/04 2pp 18373 317 24X Fiche 50-272, 83/05/04, 8305100258

8305120434 PNS-I-83-013 on 830502, Lower Alloways Creek, NJ, police dept informed licensee of planned, peaceful demonstration to protest facility restart scheduled for 830508 No press release planned
MCKEOWN, L , GODY, A T , JOYNER, J Region 1, Office of Director
83/05/06 1p 18431 131 24X Fiche 50-272, 83/05/06, 8305120434

8305180830 Forwards 830506 order confirming commitment to implement &/or maintain items specified in 830428 ltr re reactor trip breaker failures
EISENHUT, D G Division of Licensing 83/05/06 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 3pp 18506 001
24X Fiche 50-272, 83/05/06, 8305180830

--8305180836 Order confirming licensee commitments to implement &/or maintain items specified in 830428 ltr re reactor trip breaker failures, effective immediately
EISENHUT, D G Division of Licensing 83/05/06 Public Service
Electric & Gas Co of New Jersey 4pp 18506 004 24X
Fiche 50-272, 83/05/06, 8305180830

8305200394 Forwards supplemental LER 82-078/01X-1 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/05/09 ALLAN, J Region 1, Office of Director 5pp 18518 110
24X Fiche 50-272, 83/05/09, 8305200394

--8305200397 Supplemental LER 82-078/01X-1 on 821017, during routine containment purge, abnormal decrease of radioactivity levels observed as indicated by containment plant vent monitor Caused by sample line left capped
FRAHM, R Public Service Electric & Gas Co of New Jersey 83/05/04 Region 1, Office of Director 1p 18518 115 24X Fiche 50-272, 83/05/09, 8305200394

8305190336 PND-I-83-050 on 830513, 100 gallons of contaminated water discharged from auxiliary bldg sump onto ground between auxiliary & fuel handling bldgs Cause under investigation No offsite release occurred Contaminated soil removed
BUMMERS, R . TRIPP, L Region 1, Office of Director 83/05/13 1p 18500 233 24X Fiche 50-272, 83/05/13, 8305190336

8305250238 PND-I-83-052 on 830520, plant went critical for first time since 830225 Reactor startup & required reactor trip breaker testing completed within 24 h Power ascension to 100% expected over next several days
NORRHOLM, L , JACOBS, R , GREENMAN, E Region 1, Office of Director 83/05/23 1p 18592 358 24X Fiche 50-272, 83/05/23, 8305250238

T Hearing transcripts on non-antitrust matters

8305020529 Unofficial transcript of Commission 830426 public meeting re possible vote on restart in Washington, DC Pp 1-107
* Commissioners 83/04/26 127pp 18284 075 24X
Fiche 50-272, 83/04/26, 8305020529

8305170089 Transcript of Commission 830512 meeting in Washington, DC to discuss evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation encl
* Commissioners 83/05/12 81pp 18495 226 24X
Fiche 50-272, 83/05/12, 8305170089

8305230130 Transcript of Commission 830518 public meeting in Washington, DC re evaluation of implications of facility event (Part I) Pp 1-82 Supporting documentation encl
* Commissioners 83/05/18 97pp 18577 110 24X
Fiche 50-272, 83/05/18, 8305230130

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305030180 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18310 001 24X Fiche 50-275, 83/04/22, 8305030180

--8305030188 Forwards public version of Rev 0 to Emergency Plan Implementing Procedures EP-RB-12, "Mid & High-Range Vent Monitors" & EP G-3, "Notification of Offsite Organizations "
CRANE, P A Pacific Gas & Electric Co 83/04/06 MARTIN, J B Region 5, Office of Director 2pp 18310 002 24X
Fiche 50-275, 83/04/22, 8305030180

--8305030193 Public version of Rev 0 to Emergency Plan Implementing Procedures EP-RB-12, "Mid & High-Range Vent Monitors" & EP G-3, "Notification of Offsite Organizations "
* Pacific Gas & Electric Co 83/04/06 19pp 18310 004 24X
Fiche 50-275, 83/04/22, 8305030180

8305040320 Forwards Amend Request 83-03 to License DPR-76, changing containment isolation valves, organization & quantities of fire detection instruments
CRANE, P A Pacific Gas & Electric Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18319 331 24X
Fiche 50-275, 83/05/02, 8305040320

--8305040328 Amend Request 83-03 to License DPR-76, changing containment isolation valve list, organization & quantities of fire detection instruments
SCHUYLER, J D , CRANE, P A Pacific Gas & Electric Co 83/05/02 2pp 18319 332 24X Fiche 50-275, 83/05/02, 8305040320

--8305040473 Proposed Tech Specs re containment isolation valves, administrative controls & fire detection instrumentation
* Pacific Gas & Electric Co 83/05/02 19pp 18319 334 24X
Fiche 50-275, 83/05/02, 8305040320

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G, Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305190157 Notifies that rept documenting previous exemptions & justifying differences between existing or proposed fire protection features & features specified in Sections III G, III J, L & O of App R will be submitted by 830610
CRANE, P A Pacific Gas & Electric Co 83/05/13 EISENHUT, D G Division of Licensing 1p 18502 256 24X Fiche 50-275, 83/05/13, 8305190157

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

8305310130 Forwards application for amend to License DPR-76, changing portions of Tech Specs 3 7.9 1 re fire suppression water sys & 4 7 9 4 re Halon sys
CRANE, P A Pacific Gas & Electric Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18655 028 24X
Fiche 50-275, 83/05/23, 8305310130

--8305310135 Application for amend to License DPR-76, changing portions of Tech Specs 3 7 9 1 & 4 7 9 4 increasing high pressure pump capacity to 2,250 gpm & eliminating need for replacing Halon sys w/5-yr svc life remaining
SCHUYLER, J D , CRANE, P A Pacific Gas & Electric Co 83/05/23 2pp 18655 029 24X Fiche 50-275, 83/05/23, 8305310130

--8305310140 Proposed Tech Specs 3 7 9 1 re fire suppression water sys & 4 7 9 4 re Halon sys
* Pacific Gas & Electric Co 83/05/23 4pp 18655 031 24X
Fiche 50-275, 83/05/23, 8305310130

G Adjudicatory correspondence

8305060451 Advises that informant alleging PG&E/Bechtel misconduct declined to meet w/NRC, fearing PG&E/Bechtel reprisals
FLEISCHAKER, D Fleischaker, D S 83/05/03 EISENHUT, D G Division of Licensing 3pp 18343 140 24X Fiche 50-275, 83/05/03, 8305060451

8305090438 Advises that since 830423 correspondence, informant contacted Joint Intervenors re allegations of Bechtel/util misconduct Fear of reprisals prevented informant from meeting or calling NRC
FLEISCHAKER, D Fleischaker, D S FLEISCHAKER, D Joint Intervenors-Diablo Canyon 83/05/03 EISENHUT, D G Division of Licensing 3pp 18362 354 24X Fiche 50-275, 83/05/03, 8305090438

8305110212 First request for document production by Governor Deukmejian & Joint Intervenors Related correspondence
STRUMWASSER, M California, State of REYNOLDS, J R Joint Intervenors-Diablo Canyon 83/05/06 Pacific Gas & Electric Co 8pp 18407 100 24X Fiche 50-275, 83/05/06, 8305110212

8305110217 Certifies svc of first set of interrogatories & first document production request on listed parties on 830506
STRUMWASSER, M California, State of 83/05/06 5pp 18407 095 24X Fiche 50-275, 83/05/06, 8305110217

8305110383 First set of interrogatories by Governor Deukmejian & Joint Intervenors Sworn response requested within 14 days Related correspondence
STRUMWASSER, M California, State of REYNOLDS, J R Joint Intervenors-Diablo Canyon 83/05/06 Pacific Gas & Electric Co 26pp 18406 230 24X Fiche 50-275, 83/05/06, 8305110383

8305120285 Motion to reopen record on const QA issue to receive significant new evidence of recently established deficiencies in const QA & QC program Certificate of Svc encl
REYNOLDS, J R. Joint Intervenors-Diablo Canyon REYNOLDS, J R Center for Law in the Public Interest 83/05/10 Atomic Safety and Licensing Appeal Panel 39pp 18427 159 24X
Fiche 50-275, 83/05/10, 8305120285

8305160127 Advises that NRC cannot pinpoint when NRC responsibilities to Commission re independent design verification program sufficiently complete to permit discovery against NRC Final repts due by 830630
CHANDLER, L J Hearing Branch 2 83/05/13 MOORE, T S , BUCK, J H , JOHNSON, W R Atomic Safety and Licensing Appeal Panel 2pp 18448 185. 24X Fiche 50-275, 83/05/13, 8305160127

8305260182 Motion to reopen record on const QA Info discovered on util QA program design & const deficiencies & on const contractor QA program deficiencies
KAUFMAN, P H California, State of 83/05/17 Atomic Safety and Licensing Appeal Panel 38pp 18599 024 24X Fiche 50-275, 83/05/17, 8305260182

--8305260183 Declaration of RB Hubbard re breakdown in const QA
Describes events occurring since issuance of 830326
supplemental affidavit demonstrating util QA/QC const
program noncompliance Certificate of Svc encl
HUBBARD, R B California, State of 83/05/06 50pp 18599 063
24X Fiche 50-275, 83/05/17, 8305260182

8305200457 Decision ALAB-728, affirming ASLB 810717 Partial Initial
Decision LBP-81-21 authorizing fuel loading & low power
testing Johnson opinion, dissenting in part, encl
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/05/18
64pp 18519 340 24X Fiche 50-275, 83/05/18, 8305200457

8305270622 Answers to Governor Deukmejian & Joint Intervenors 830506
first set of Interrogatories 1(a) through (f), 8(a), (c) &
(d), 9(a), (c) & (d), 10(a) & (c) & 11(a) & (c) re independent
design verification review Certificate of Svc encl
CRANE, P A Pacific Gas & Electric Co 83/05/23 DEUKMEJIAN, G
California, State of 200pp 18645 001 24X Fiche 50-275, 83/05/23,
8305270622

H General correspondence

8305180622 Responds to 830328 ltr re eight allegations by anonymous
individual Preliminary evaluation of allegations underway
Meeting w/util planned in near future to solicit evaluation
on subj
EISENHUT, D G Division of Licensing 83/04/21 FLEISCHAKER, D
Fleischaker, D S 8pp 18505 317 24X Fiche 50-275, 83/04/21,
8305180622

P Operating license stage documents & correspondence

8305230407 Informs that backfitting matl will be forwarded as soon as
available, in response to 830208 ltr
FURBUSH, M H Pacific Gas & Electric Co 83/02/23 TOURTELLOTTE, J
Regulatory Reform Task Force 1p 18543 357 24X
Fiche 50-000, 83/02/23, 8305230407

8305230720 Forwards list of utils responding to requests for cost
figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305030191 Board Notification 83-51 forwards info re QA/QC allegations
at facilities Region V currently investigating allegations
EISENHUT, D G Division of Licensing 83/04/15 PALLADINO, J ,
GILINSKY, V , AHEARNE, J, Commissioners 1p 18309 350 24X
Fiche 50-275, 83/04/15, 8305030191

--8305030200 Recommends QA/QC allegations be brought to attention of
ASLB
CREWS, J L Division of Resident, Reactor Project & Engineering
Programs 83/04/13 EISENHUT, D G Division of Licensing 3pp
18309 351 24X Fiche 50-275, 83/04/15, 8305030191

8305020388 Responds to 830322 request for addl info on instrumentation
sys for detection of inadequate core cooling (Generic Ltr
82-28) Installation completed & sys currently being tested
Status of conformance w/NUREG-0737, Item II F 2 encl
SCHUYLER, J O Pacific Gas & Electric Co 83/04/27 EISENHUT, D G
Division of Licensing 7pp 18276 329 24X Fiche 50-275, 83/04/27,
8305020388

8305090282 Board Notification 83-54 notifies of status of activities
performed under independent design verification program re
safety issue on design adequacy
EISENHUT, D G Division of Licensing 83/04/27 PALLADINO, N J ,
GILINSKY, V A., AHEARNE, J F Commissioners 4pp 18366 105 24X
Fiche 50-275, 83/04/27, 8305090282

8305100422 Summary of 830419 meeting w/util in San Francisco, CA re
areas of review for component cooling water sys
VIETTI, A Licensing Branch 3 83/04/28 Licensing Branch 3
3pp 18621 200 24X Fiche 50-275, 83/04/28, 8305100422

8305030510 Application to amend License DPR-76, requesting extension
of 45 days for relief from Tech Spec 3/4 9 7 for mods to
fuel handling bldg per License Amend 3 Conditions &
procedures applicable to Amend 3 remain in effect
CRANE, P A Pacific Gas & Electric Co 83/04/29 KNIGHTON, G W
Licensing Branch 3 2pp 18295 089 24X Fiche 50-275, 83/04/29,
8305030510

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees
re new procedures for providing public notice concerning
issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040320 Forwards Amend Request 83-03 to License DPR-76, changing
containment isolation valves, organization & quantities of
fire detection instruments
CRANE, P A Pacific Gas & Electric Co 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18319 331 24X
Fiche 50-275, 83/05/02, 8305040320

--8305040328 Amend Request 83-03 to License DPR-76, changing containment
isolation valve list, organization & quantities of fire
detection instruments
SCHUYLER, J O , CRANE, P A Pacific Gas & Electric Co 83/05/02
2pp 18319 332 24X Fiche 50-275, 83/05/02, 8305040320

--8305040473 Proposed Tech Specs re containment isolation valves,
administrative controls & fire detection instrumentation
* Pacific Gas & Electric Co 83/05/02 19pp 18319 334 24X
Fiche 50-275, 83/05/02, 8305040320

8305050198 Forwards schedule for submitting component cooling water sys
info discussed at 830419 meeting in response to request for
addl info at 830128 meeting
CRANE, P A Pacific Gas & Electric Co 83/05/03 EISENHUT, D G
Division of Licensing 3pp 18342 259 24X Fiche 50-275, 83/05/03,
8305050198

8305040323 Board Notification 83-057 forwards differing prof opinions
re sys interaction & safety classification Info relates to
Board Notifications 83-17 & 83-44 re Unresolved Safety Issue
A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N
Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04,
8305040323

8305120611 Board Notification 83-59 forwards info re component
cooling water sys discussed at 830419 meeting w/PG&E in
San Francisco, CA
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N J ,
GILINSKY, V , AHEARNE, J Commissioners 3pp 18440 228 24X
Fiche 50-275, 83/05/04, 8305120611

--8305120621 Transcript of 830419 public meeting in San Francisco, CA re
review of component cooling water sys Pp 1-121
* Commissioners 83/04/19 123pp 18440 231 24X
Fiche 50-275, 83/05/04, 8305120611

8305200266 Board Notification 83-061 forwards Joint Intervenors 830428
ltr requesting meeting w/informant to discuss allegations
re design verification program per Commission Order
CLI-81-30
EISENHUT, D G Assistant Director for Licensing 83/05/04
PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 3pp
18540 198 24X Fiche 50-275, 83/05/04, 8305200266

--8305200273 Advises of informant refusal to meet w/NRC to discuss
allegations re design verification program Individual
fearful of PG&E/Bechtel reprisals
FLEISCHAKER, D Fleischaker, D S FLEISCHAKER, D Joint
Intervenors-Diablo Canyon 83/04/28 EISENHUT, D G Assistant
Director for Licensing 5pp 18540 201 24X
Fiche 50-275, 83/05/04, 8305200266

8305120085 Board Notification 83-55 forwards info on allegations re
const QA at Facilities
EISENHUT, D G Division of Licensing 83/05/05 PALLADINO, N J ,
GILINSKY, V , AHEARNE, J Commissioners 3pp 18422 236 24X
Fiche 50-275, 83/05/05, 8305120085

--8305120093 Forwards sworn statements of V Tennyson & R Roam re
allegations of matl violations of NRC QA regulations at
facilities
VAN DE KAMP, J California, State of 83/04/12 EISENHUT, D G
Division of Licensing 90pp 18422 239 24X
Fiche 50-275, 83/05/05, 8305120085

--8305120099 Transcript of 830325 interview w/VH Tennyson re alleged
deficiencies in implementation of HP Foley Const Co QA
program
TENNYSON, V H Affiliation Unknown 83/03/25 73pp 18422 329
24X Fiche 50-275, 83/05/05, 8305120085

8305180024 Forwards Amend 5 to License DPR-76 & notice of issuance &
availability Amend grants relief for 45 days to allow for
movement of loads in excess of 2,500 lb to make mods in fuel
handling bldg
KNIGHTON, G W Licensing Branch 3 83/05/05 CRANE, P A Pacific
Gas & Electric Co 6pp 18499 276 24X Fiche 50-275, 83/05/05,
8305180024

--8305180025 Amend 5 to License DPR-76, extending relief request to 45
days for mods in fuel handling bldg
KNIGHTON, G W Licensing Branch 3 83/05/05 5pp 18499 281
24X Fiche 50-275, 83/05/05, 8305180024

--8305180032 Notice of issuance & availability of Amend 5 to License DPR-76
KNIGHTON, G W Licensing Branch 3 83/05/05 2pp 18499 286
24X Fiche 50-275, 83/05/05, 8305180024

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120042 Responds to 830420 & 21 requests for clarification of specific items re pressure/temp analysis for pipe break outside containment submitted in 830413 ltr
CRANE, P A Pacific Gas & Electric Co 83/05/09 EISENHUT, D G
Division of Licensing 5pp 18423 048 24X Fiche 50-275, 83/05/09, 8305120042

8305120325 Forwards response to NUREG-0612, "Control of Heavy Loads " Ack of receipt of matl requested
CRANE, P A Pacific Gas & Electric Co 83/05/09 KNIGHTON, G W
Licensing Branch 3 222pp 18432 042 24X Fiche 50-275, 83/05/09, 8305120325

8305120333 Forwards Rev 1 to "Pump & Valve Inservice Testing Program, Diablo Canyon Power Plant, Unit 1 " Requests for relief from ASME Code Section XI requirements included
CRANE, P A Pacific Gas & Electric Co 83/05/10 KNIGHTON, G W
Licensing Branch 3 2pp 18431 317 24X Fiche 50-275, 83/05/10, 8305120333

--8305120339 Rev 1 to "Pump & Valve Inservice Testing Program, Diablo Canyon Power Plant, Unit 1 "
* Pacific Gas & Electric Co 83/05/10 83pp 18431 319 24X
Fiche 50-275, 83/05/10, 8305120333

8305160172 Forwards Rev 2 to Test Procedure 42 7, "Natural Circulation Boron Mixing Test" & pretest rept Receipt ack requested
CRANE, P A Pacific Gas & Electric Co 83/05/11 KNIGHTON, G W
Licensing Branch 3 1p 18446 128 24X Fiche 50-275, 83/05/11, 8305160172

--8305160176 Rev 2 to Test Procedure 42 7, "Natural Circulation Boron Mixing Test "
REIS, M P Pacific Gas & Electric Co 83/04/06 59pp 18446 129
24X Fiche 50-275, 83/05/11, 8305160172

8303040044 Board Notification 83-66 forwards review of WCAP-10297(P), "Dropped Rod Methodology for Negative Flux Rate Trip Plants " Rod issue resolved by analysis in rept Plants beyond first cycle must perform analysis Comments encl
EISENHUT, D G Division of Licensing 83/05/13 PALLADINO, N ,
GILINSKY, V , AHEARNE, J Commissioners 21pp 18541 068 24X
Fiche 50-000, 83/05/13, 8303040044

8305240375 Forwards info on component cooling water sys, items 1, 2 & 3 a - 3 e, addressing seismic qualification, basis for 64 F ocean temp & max flow/single failure analysis requested at 830419 meeting to resolve remaining issues
CRANE, P A Pacific Gas & Electric Co 83/05/18 EISENHUT, D G
Division of Licensing 34pp 18571 006 24X Fiche 50-275, 83/05/18, 8305240375

8305270296 Forwards Rev 3 to "Interface Between Independent Design Verification Program Participants, Plant & Designated Other Parties " Comments requested
COOPER, W E Teledyne Engineering Services 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co.
1p 18644 339 24X Fiche 50-275, 83/05/20, 8305270296

--8305270305 Rev 3 to "Interface Between Independent Design Verification Program Participants, Plant & Designated Other Parties "
COOPER, W E Teledyne Engineering Services 83/05/18 15pp
18644 340 24X Fiche 50-275, 83/05/20, 8305270296

8305310130 Forwards application for amend to License DPR-76, changing portions of Tech Specs 3 7 9 1 re fire suppression water sys & 4 7 9 4 re Halon sys
CRANE, P A Pacific Gas & Electric Co 83/05/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18655.028, 24X
Fiche 50-275, 83/05/23, 8305310130

--8305310135 Application for amend to License DPR-76, changing portions of Tech Specs 3 7.9 1 & 4 7 9 4 increasing high pressure pump capacity to 2,250 gpm & eliminating need for replacing Halon sys w/5-yr svc life remaining
SCHUYLER, J D , CRANE, P A Pacific Gas & Electric Co 83/05/23
2pp 18655 029. 24X Fiche 50-275, 83/05/23, 8305310130

--8305310140 Proposed Tech Specs 3 7 9 1 re fire suppression water sys & 4 7 9 4 re Halon sys
* Pacific Gas & Electric Co 83/05/23 4pp 18655 031 24X
Fiche 50-275, 83/05/23, 8305310130

8305270317 Notifies of 830602 meeting w/util & independent design verification program group in Boston, MA to followup 830512 discussions re turbine bldg, polar crane & auxiliary bldg & redistribution of moments & forces
COOPER, W E , CRAGIN, J G Teledyne Engineering Services 83/05/27
MANEATIS, G A , DENTON, H R , MARTIN, J B NRC - No Detailed
Affiliation Given 1p 18642 223 24X Fiche 50-275, 83/05/27,
8305270317

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305170332 Forwards IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/04/08 CRANE, P A
Pacific Gas & Electric Co 2pp 18465 133 24X
Fiche 50-275, 83/04/08, 8305170332

--8305170339 IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 No noncompliance noted Major areas inspected, surveillance testing, maint & TMI task action plan items
CARLSON, J D , MENDONCA, M M , KIRSCH, D F Region 5, Office of Director 83/04/05 6pp 18465 135 24X Fiche 50-275, 83/04/08, 8305170332

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305170496 Forwards IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted
BOOK, H E Region 5, Office of Director 83/04/22 CRANE, P A
Pacific Gas & Electric Co 2pp 18470 045 24X
Fiche 50-275, 83/04/22, 8305170496

--8305170501 IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted Major areas inspected implementation of NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation "
GARCIA, E M , WENSLAWSKI, F A , BOOK, H E Region 5, Office of Director 83/04/22 7pp 18470 047 24X Fiche 50-275, 83/04/22, 8305170496

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026.

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L, Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 292 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260257 Forwards IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830330-0406 & 25-29 W/o notice of violation
BISHOP,T W Region 5, Office of Director 83/05/19 CRANE,P A Pacific Gas & Electric Co 2pp 18625 172 24X
Fiche 50-275,83/05/19,8305260257

--8305260262 IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830330-0406 & 25-29 Noncompliance noted failure to comply w/procedural requirements for processing of nonconformance repts & to conduct welder requalification
CARLSON,J D , HERNANDEZ,O H , MENDONCA,M M Region 5, Office of Director 83/05/19 24pp 18625 174 24X Fiche 50-275,83/05/19, 8305260257

8305240390 Forwards IE Insp Rept 50-275/83-16 on 830425-0504 No noncompliance noted
FAULKENBERRY,B Region 5, Office of Director 83/05/20 CRANE,P A Pacific Gas & Electric Co 3pp 18573 121 24X
Fiche,50-275,83/05/20,8305240390

--8305240393 IE Insp Rept 50-275/83-16 on 830425-0504 No noncompliance noted Major areas inspected action initiated by licensee in response to gauges discovered in reactor coolant pipe
Details withheld (ref 10CFR2 790)
SCARANO,R A , BISHOP,T W , MCQUEEN,A D Region 5, Office of Director 83/05/18 2pp 18573 124 24X Fiche 50-275,83/05/20, 8305240390

8305260270 Forwards IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 & SALP rept for Jul 1981 - Dec 1982
MARTIN,J B Region 5, Office of Director 83/05/23 CRANE,P A Pacific Gas & Electric Co 2pp 18626 211 24X
Fiche 50-275,83/05/23,8305260270

--8305260272 IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 No noncompliance noted Major areas discussed SALP rept for Jul 1981 - Dec 1982,including design,const & operations
MORRILL,P J , KIRSCH,D F Region 5, Office of Director 83/05/20 2pp 18626 213 24X Fiche 50-275,83/05/23,8305260270

--8305260274 Submits comments on draft SALP rept for Jul 1981 - Dec 1982 discussed at 830407 meeting SALP rept will be used as guide for assigning priorities & allocating resources to maintain & improve mgt controls &/or quality of work
CRANE,P A Pacific Gas & Electric Co 83/04/27 MARTIN,J B Region 5, Office of Director 2pp 18626 238 24X
Fiche,50-275,83/05/23,8305260270

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R. Periodic operating reports & related correspondence

8305180427 Advises that no open item repts issued 830321-0408. Individuals assigned to independent design verification program completed acceptable conflict of interest statement
REEDY,R F R F Reedy, Inc 83/04/13. DENTON,H R Office of Nuclear Reactor Regulation, Director MANEATIS,G A Pacific Gas & Electric Co ENGELKEN,R H Region 5, Office of Director 2pp 18485:298. 24X Fiche 50-275,83/04/13,8305180427

8305030271 Forwards Rev 1 to "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys" & "Verification of Mechanical/Nuclear Design of Auxiliary Feedwater Sys," Interim Technical Repts 20 & 22 W/o Rept 20
KRECHTING,J E Stone & Webster Engineering Corp 83/04/25
DENTON,H R Office of Nuclear Reactor Regulation, Director
ENGELKEN,R H Region 5, Office of Director MANEATIS,G A Pacific Gas & Electric Co 1p 18300 091 24X Fiche 50-275,83/04/25, 8305030271

--8305030282 "Verification of Mechanical/Nuclear Design of Auxiliary Feedwater Sys," Interim Technical Rept 22
SESTAK,F Stone & Webster Engineering Corp STRATOULY,D C Teledyne Engineering Services 83/04/20 36pp 18300 093 24X Fiche 50-275,83/04/25,8305030271

8305030538 Forwards Rev 1 to "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 20
KRECHTING,J E Stone & Webster, Inc 83/04/25 DENTON,H R Office of Nuclear Reactor Regulation, Director ENGELKEN,R H Region 5, Office of Director MANEATIS,G A Pacific Gas & Electric Co 1p 18305 229 24X Fiche 50-275,83/04/25,8305030538

--8305030545 Rev 1 to "Verification of Mechanical/Nuclear Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 20
SESTAK,F , STRATOULY,D C Stone & Webster, Inc 83/04/20 34pp 18305 230 24X Fiche 50-275,83/04/25,8305030538

8305030573 Forwards Rev 1 to "Diablo Canyon Unit 1 Independent Design Verification Program Electrical Equipment Analysis," Interim Technical Rept 33
DENISON,E Robert L Cloud Associates, Inc 83/04/29 DENTON,H R Office of Nuclear Reactor Regulation, Director MARTIN,J B Region 5, Office of Director MANEATIS,G H Pacific Gas & Electric Co 1p 18301 295 24X Fiche 50-275,83/04/29,8305030573

--8305030581 Rev 1 to "Diablo Canyon Unit 1 Independent Design Verification Program Electrical Equipment Analysis," Interim Technical Rept 33
DENISON,E Robert L Cloud Associates, Inc P105-4-839-033 R01 83/04/28 53pp 18301 296 24X Fiche 50-275,83/04/29,8305030573

8305050299 Forwards "Diablo Canyon Nuclear Power Plant Unit 1, Independent Design Verification Program," final rept, in response to Commission order
COOPER,W E Teledyne Engineering Services 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director MARTIN,J B Region 5, Office of Director MANEATIS,G A Pacific Gas & Electric Co 2pp 18337 001 24X Fiche 50-275,83/05/02,8305050299

--8305050303 "Diablo Canyon Nuclear Power Plant Unit 1, Independent Design Verification Program," Final rept
* Teledyne Engineering Services 83/05/02 126pp 18337 003 24X Fiche 50-275,83/05/02,8305050299

8305200723 Comments on Rev 0 to Interim Technical Rept (ITR) 36 & Rev 1 to ITR 36,evaluating S&W audit of GF Atkinson & Wismer & Becker const QA Closing out engineering open item opposed Repts should be revised
NOVAK,T M Assistant Director for Licensing 83/05/02 COOPER,W E Affiliation Unknown 3pp 18540 092 24X Fiche 50-275,83/05/02, 8305200723

8305230206 Board Notification 83-56 forwards "Independent Design Verification Program - Semimonthly Status Rept for Apr 1983" & "Interim Technical Rept 42 - RF Reedy Independent Design Verification Program Phase II Review & Audit "
EISENHUT,D G Division of Licensing 83/05/03 PALLADINO,N J , QILINSKY,V , AHEARNE,J F Commissioners 4pp 18543 001 24X Fiche 50-275,83/05/03,8305230206

8305100173 Forwards Rev 1 to "Verification of Auxiliary Feedwater Sys Electrical Design," Interim Technical Rept 25 & Rev 1 to "Verification of Control Room Ventilation & Pressurization Sys Electrical Design," Interim Technical Rept 26
KRECHTING,J E Stone & Webster Engineering Corp 83/05/04
DENTON,H R Office of Nuclear Reactor Regulation, Director
ENGELKEN,R H Region 5, Office of Director MANEATIS,G A Pacific Gas & Electric Co 1p 18377 060 24X Fiche 50-275,83/05/04, 8305100173

--8305100179 Rev 1 to "Verification of Auxiliary Feedwater Sys Electrical Design," Interim Technical Rept 25
SESTAK,F Stone & Webster Engineering Corp 83/04/29 26pp 18377 062 24X Fiche 50-275,83/05/04,8305100173

--8305100185 Rev 1 to "Verification of Control Room Ventilation & Pressurization Sys Electrical Design," Interim Technical Rept 26
SESTAK,F Stone & Webster Engineering Corp 83/05/02 25pp 18377 089 24X Fiche 50-275,83/05/04,8305100173

8305120203 Forwards Rev 1 to Interim Technical Rept 21, "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room " & Rev 1 to Interim Technical Rept 24, "Verification of 4,160 "
KRECHTING, J E Stone & Webster Engineering Corp 83/05/09
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18427 100 24X Fiche 50-275, 83/05/09, 8305120203

--8305120211 Rev 1 to "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurization Sys," Interim Technical Rept 21
SESTAK, F Stone & Webster Engineering Corp 83/05/03 21pp 18427 102 24X Fiche 50-275, 83/05/09, 8305120203

--8305120216 Rev 1 to "Verification of 4,160-Volt Safety-Related Electrical Distribution Sys," Interim Technical Rept 24
SESTAK, F Stone & Webster Engineering Corp 83/05/04 28pp 18427 124 24X Fiche 50-275, 83/05/09, 8305120203

8305230216 Board Notification 83-65 forwards info items re design verification program
EISENHUT, D G Division of Licensing 83/05/11 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 4pp 18544 001 24X Fiche 50-275, 83/05/11, 8305230216

--8305230224 Forwards Rev 0 to "Diablo Canyon Unit 1 Independent Design Verification Program - HXs," Interim Technical Rept 43
DENISON, E Robert L Cloud Associates, Inc 83/04/15
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G H Pacific Gas & Electric Co 1p 18544 163 24X Fiche 50-275, 83/05/11, 8305230216

8305160185 Board Notification 83-68 forwards Teledyne Engineering Svcs, "Diablo Canyon Nuclear Power Plant, Unit 1, Final Rept, Independent Design Verification Program " Final installment of rept scheduled for submittal by 830630
EISENHUT, D G Division of Licensing 83/05/12 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp 18474 239 24X Fiche 50-275, 83/05/12, 8305160185

8305170511 Forwards Rev 1 to "Verification of Pressure, Temp, Humidity & Submergence Environs Used For Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room ," Interim Technical Rept 14
KRECHTING, J E Stone & Webster Engineering Corp 83/05/12
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18468 323 24X Fiche 50-275, 83/05/12, 8305170511

--8305170517 Rev 1 to "Verification of Pressure, Temp, Humidity & Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation ," Interim Technical Rept 14
SESTAK, F, STRATOULY, D C Stone & Webster Engineering Corp 83/05/09 45pp 18468 324 24X Fiche 50-275, 83/05/12, 8305170511

8305180377 Advises that no open item repts issued since last semimonthly rept
KRECHTING, J E Stone & Webster Engineering Corp 83/05/13
DENTON, H R Office of Nuclear Reactor Regulation, Director
MANEATIS, G A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 1p 18490 346 24X Fiche 50-275, 83/05/13, 8305180377

8305180395 Forwards "Diablo Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimonthly rept for May 1983
COOPER, W E Teledyne Engineering Services 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18485 303 24X Fiche 50-275, 83/05/13, 8305180395

--8305180403 "Diablo Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimonthly rept for May 1983
* Teledyne Engineering Services 83/05/13 28pp 18485 304 24X Fiche 50-275, 83/05/13, 8305180395

8305180417 Forwards Rev 0 to Open Item Repts 1121 & 1122 for May 1983 Responsible individuals assigned by RL Cloud have completed acceptance statement re potential or apparent conflicts of interest
DENISON, E Robert L Cloud Associates, Inc 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G H Pacific Gas & Electric Co 3pp 18485 353 24X Fiche 50-275, 83/05/13, 8305180417

8305240238 Forwards "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509 Rept submitted per NRC Order CLI-81-30
CRANE, P A Pacific Gas & Electric Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director 1p 18548 221 24X Fiche 50-275, 83/05/13, 8305240238

--8305240242 "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509
* Pacific Gas & Electric Co 83/05/13 65pp 18548 222 24X Fiche 50-275, 83/05/13, 8305240238

8305200358 Forwards "Independent Design Verification Program Final Rept," second draft submittal Next submittal scheduled for 830530 Final submittal scheduled for 830630
COOPER, W E Teledyne Engineering Services 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 2pp 18518 016 24X Fiche 50-275, 83/05/16, 8305200358

--8305200364 "Independent Design Verification Program Final Rept," second draft submittal
* Teledyne Engineering Services 83/05/16 73pp 18518 018 24X Fiche 50-275, 83/05/16, 8305200358

8305230213 Forwards Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 28
KRECHTING, J E Stone & Webster Engineering Corp 83/05/18
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18539 145 24X Fiche 50-275, 83/05/18, 8305230213

--8305230221 Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 28
SESTAK, F Stone & Webster Engineering Corp 83/05/13 30pp 18539 146 24X Fiche 50-275, 83/05/18, 8305230213

8305230556 Forwards Rev 1 to "Verification of Instrument & Control Design of Auxiliary Feedwater Sys," Interim Technical Rept 27
KRECHTING, J E Stone & Webster Engineering Corp 83/05/18
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18537 102 24X Fiche 50-275, 83/05/18, 8305230556

--8305230559 Rev 1, "Verification of Instrument & Control Design of Auxiliary Feedwater Sys," Interim Technical Rept 27
SESTAK, F Stone & Webster Engineering Corp 83/05/13 37pp 18537 103 24X Fiche 50-275, 83/05/18, 8305230556

8305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program
EISENHUT, D G Division of Licensing 83/05/18 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp 18595.001 24X Fiche 50-275, 83/05/18, 8305250066

--8305250186 Transcript of 830504 public meeting to review design verification project in San Francisco, CA Pp 1-236
* Commissioners 83/05/04 43pp 18595.005 24X Fiche 50-275, 83/05/18, 8305250066

8305250466 Forwards Rev 0 to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys," Interim Technical Rept 45 Meeting announcement encl
KRECHTING, J E Stone & Webster Engineering Corp 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director
MANEATIS, G A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 2pp 18585 228 24X Fiche 50-275, 83/05/20, 8305250466

--8305250467 Rev 0 to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys," Interim Technical Rept 45
SESTAK, F Stone & Webster Engineering Corp 83/05/17 17pp 18585 230 24X Fiche 50-275, 83/05/20, 8305250466

8305310186 Forwards Rev 1, to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Pressurization Sys, Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18.
KRECHTING, J E Stone & Webster Engineering Corp 83/05/26
DENTON, H R. Office of Nuclear Reactor Regulation, Director
MANEATIS, G. A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 1p. 18652 347 24X Fiche 50-275, 83/05/26, 8305310186

--8305310191 Rev 1 to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys,Control Room Ventilation & Pressurization,Sys,Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18
SESTAK,F Stone & Webster Engineering Corp 83/05/24 28pp
18652 349 24X Fiche 50-275,83/05/26,8305310186

S Reportable occurrences, LERs & related correspondence

8305030313 PNS-V-83-005 on 830426,region dispatched reactive insp team to review findings & status to date of licensee investigation of safety significance of recent vandalism event on 830419 involving gauges in coolant pipe
MCGUEEN,A D , NORDERHAUG,L R Region 5, Office of Director
83/04/27 1p 18297 069 24X Fiche 50-275,83/04/27,8305030313

8305060580 PNO-V-83-019 on 830502,6 5 Richter scale earthquake occurred appror 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected
KIRSCH,D F Region 5, Office of Director 83/05/03 1p
18349 057 24X Fiche 50-275,83/05/03,8305060580

8305240397 LER 83-004/08T-0 on 830419,grinding wheel & rotary file gauges found on main coolant sys piping on main coolant pump 3 discharge side Caused intentionally by unknown persons Gauges removed by grinding & blending W/830503 ltr
KELLY,W J , SHIFFER,J D Pacific Gas & Electric Co 83/05/03
MARTIN,J B Region 5, Office of Director 3pp 18549 275 24X
Fiche 50-275,83/05/03,8305240397

8305160009 PNO-V-83-021 on 830429,leak discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity
KIRSCH,D F Region 5, Office of Director 83/05/10 1p
18456 081 24X Fiche 50-275,83/05/10,8305160009

8305130187 PNO-V-83-022 on 830509,while performing addl ultrasonic exams,RCS piping in area of one weld determined less than min wall thickness specified by code Caused by welds being ground smooth during original preservice exam
KIRSCH,D F Region 5, Office of Director 83/05/11 1p
18439 347 24X Fiche 50-275,83/05/11,8305130187

8305270249 LER 83-003/03L-0 on 830414,control operator unable to achieve satisfactory check source reading on liquid radwaste discharge line radiation monitor (RE-18) Caused by missing check source from monitoring mechanism W/830513 ltr
SHIFFER,J D , KELLY,W J Pacific Gas & Electric Co 83/05/13
MARTIN,J B Region 5, Office of Director 4pp 18637 152 24X
Fiche 50-275,83/05/13,8305270249

T Hearing transcripts on non-antitrust matters

8305110093 Transcript of 830419 public meeting re component cooling water sys in San Francisco,CA Pp 1-121
* NRC - No Detailed Affiliation Given 83/04/19 124pp
18434.112 24X Fiche 50-275,83/04/19,8305110093

8305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at 830419 meeting w/PG&E in San Francisco,CA
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N J ,
GILINSKY,V , AHEARNE,J Commissioners 3pp 18440 228 24X
Fiche 50-275,83/05/04,8305120611

--8305120621 Transcript of 830419 public meeting in San Francisco,CA re review of component cooling water sys Pp 1-121
* Commissioners 83/04/19 123pp 18440 231 24X
Fiche 50-275,83/05/04,8305120611

8305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program
EISENHUT,D G Division of Licensing 83/05/18 PALLADINO,N ,
GILINSKY,V , AHEARNE,J Commissioners 3pp 18595 001 24X
Fiche 50-275,83/05/18,8305250066

--8305250186 Transcript of 830504 public meeting to review design verification project in San Francisco,CA Pp 1-236
* Commissioners 83/05/04 43pp 18595 005 24X
Fiche 50-275,83/05/18,8305250066

U Congressional/Executive Correspondence

8305100124 Supplemental testimony of JG Keppler re QA
KEPPLER,J G Region 3, Office of Director 83/03/25 6pp
18375.197 24X Fiche 50-000,83/03/25,8305100124

--8305100111 Responds to 811113 ltr re implications of recent seismic design errors at facility Due to design errors,util license suspended on 811119 pending completion of independent design review & receipt of schedule for completing mods
PALLADINO,N J Commissioners 82/02/01 DINGELL,J D House of Rep , Energy & Commerce 2pp 18375 228 24X
Fiche 50-000,83/03/25,8305100124

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305040716 Summary of 830405 meeting w/util in Bethesda,MD re status of App R concerning fire protection program mods at facility
GEARS,G E Operating Reactors Branch 4 83/04/25 Operating Reactors Branch 4 3pp 18328 106 24X Fiche 50-277,83/04/25,8305040716

8305100359 Describes plans for completing fire protection mods re Sections III F,III G,III J & III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided
BOYER,V S Philadelphia Electric Co 83/05/02 EISENHUT,D G
Division of Licensing 6pp 18379 033 24X Fiche 50-277,83/05/02,8305100359

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305190522 Notification of 830526 meeting w/util in Bethesda,MD to discuss alternative safe shutdown,App R
GEARS,G Operating Reactors Branch 4 83/05/17 STOLZ,J
Operating Reactors Branch 4 2pp 18523 156 24X
Fiche 50-277,83/05/17,8305190522

Q Adjudicatory correspondence

8304040470 Order extending time until 830429 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl
CHILK,S J Office of the Secretary of the Commission 83/03/31
Commissioners 3pp 17807 049 24X Fiche 50-000,83/03/31,8304040470

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE,J C Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 196 24X Fiche 50-000,83/05/05,8305060250

8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO,N J Commissioners 83/05/11 2pp 18436 228 24X
Fiche 50-000,83/05/11,8305130060

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/12
Commissioners 1p 18437 033 24X Fiche 50-000,83/05/12,8305130061

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/19
Commissioners 1p 18514 283 24X Fiche 50-000,83/05/19,8305200560

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl
CHILK,S J Office of the Secretary of the Commission 83/05/27
14pp 18653 311 24X Fiche 50-000,83/05/27,8305310017

J Insurance & indemnity information

8305240307 Forwards Endorsements 1,2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection
BRADLEY,E J Philadelphia Electric Co 83/05/17 SALTZMAN,J
Assistant Director for State & Licensee Relations 4pp 18548 141
24X Fiche 50-277,83/05/17,8305240307

8305120203 Forwards Rev 1 to Interim Technical Rept 21, "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room " & Rev 1 to Interim Technical Rept 24, "Verification of 4,160 "
KRECHTING, J E Stone & Webster Engineering Corp 83/05/09
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18427 100 24X Fiche 50-275, 83/05/09, 8305120203

--8305120211 Rev 1 to "Verification of Effects of High Energy Line Cracks & Moderate Energy Line Breaks for Auxiliary Feedwater Sys & Control Room Ventilation & Pressurization Sys," Interim Technical Rept 21
SESTAK, F Stone & Webster Engineering Corp 83/05/03 21pp 18427 102 24X Fiche 50-275, 83/05/09, 8305120203

--8305120216 Rev 1 to "Verification of 4,160-Volt Safety-Related Electrical Distribution Sys," Interim Technical Rept 24
SESTAK, F Stone & Webster Engineering Corp 83/05/04 28pp 18427 124 24X Fiche 50-275, 83/05/09, 8305120203

8305230216 Board Notification 83-65 forwards info items re design verification program
EISENHUT, D G Division of Licensing 83/05/11 PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 4pp 18544 001 24X Fiche 50-275, 83/05/11, 8305230216

--8305230224 Forwards Rev 0 to "Diablo Canyon Unit 1 Independent Design Verification Program - HXs," Interim Technical Rept 43
DENISON, E Robert L Cloud Associates, Inc 83/04/15
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G H Pacific Gas & Electric Co 1p 18544 163 24X Fiche 50-275, 83/05/11, 8305230216

8305160185 Board Notification 83-68 forwards Teledyne Engineering Svcs, "Diablo Canyon Nuclear Power Plant, Unit 1, Final Rept, Independent Design Verification Program " Final installment of rept scheduled for submittal by 830630
EISENHUT, D G Division of Licensing 83/05/12 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp 18474 239 24X Fiche 50-275, 83/05/12, 8305160185

8305170511 Forwards Rev 1 to "Verification of Pressure, Temp, Humidity & Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room ," Interim Technical Rept 14
KRECHTING, J E Stone & Webster Engineering Corp 83/05/12
DENTON, H R Office of Nuclear Reactor Regulation, Director
ENGELKEN, R H Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18468 323 24X Fiche 50-275, 83/05/12, 8305170511

--8305170517 Rev 1 to "Verification of Pressure, Temp, Humidity & Submergence Environs Used for Safety-Related Equipment Spec Outside Containment for Auxiliary Feedwater Sys & Control Room Ventilation ," Interim Technical Rept 14
SESTAK, F, STRATOULY, D C Stone & Webster Engineering Corp 83/05/09 45pp 18468 324 24X Fiche 50-275, 83/05/12, 8305170511

8305180377 Advises that no open item repts issued since last semimonthly rept
KRECHTING, J E Stone & Webster Engineering Corp 83/05/13
DENTON, H R Office of Nuclear Reactor Regulation, Director
MANEATIS, G A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 1p 18490 346 24X Fiche 50-275, 83/05/13, 8305180377

8305180395 Forwards "Diablo Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimonthly rept for May 1983
COOPER, W E Teledyne Engineering Services 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18485 303 24X Fiche 50-275, 83/05/13, 8305180395

--8305180403 "Diablo Canyon Nuclear Power Plant, Unit 1, Independent Design Verification Program," second Friday semimonthly rept for May 1983
* Teledyne Engineering Services 83/05/13 28pp 18485 304 24X Fiche 50-275, 83/05/13, 8305180395

8305180417 Forwards Rev 0 to Open Item Repts 1121 & 1122 for May 1983 Responsible individuals assigned by RL Cloud have completed acceptance statement re potential or apparent conflicts of interest
DENISON, E Robert L Cloud Associates, Inc 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B, Region 5, Office of Director MANEATIS, G H Pacific Gas & Electric Co 3pp 18485 353 24X Fiche 50-275, 83/05/13, 8305180417

8305240238 Forwards "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509 Rept submitted per NRC Order CLI-81-30
CRANE, P A Pacific Gas & Electric Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director 1p 18548 221 24X Fiche 50-275, 83/05/13, 8305240238

--8305240242 "Diablo Canyon Verification Program," Semimonthly Status Rept 37 for period 830419-0509
* Pacific Gas & Electric Co 83/05/13 65pp 18548 222 24X Fiche 50-275, 83/05/13, 8305240238

8305200358 Forwards "Independent Design Verification Program Final Rept," second draft submittal Next submittal scheduled for 830530 Final submittal scheduled for 830630
COOPER, W E Teledyne Engineering Services 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 2pp 18518 016 24X Fiche 50-275, 83/05/16, 8305200358

--8305200364 "Independent Design Verification Program Final Rept," second draft submittal
* Teledyne Engineering Services 83/05/16 73pp 18518 018 24X Fiche 50-275, 83/05/16, 8305200358

8305230213 Forwards Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 28
KRECHTING, J E Stone & Webster Engineering Corp 83/05/18
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18539 145 24X Fiche 50-275, 83/05/18, 8305230213

--8305230221 Rev 1 to "Verification of Instrument & Control Design of Control Room Ventilation & Pressurization Sys," Interim Technical Rept 28
SESTAK, F Stone & Webster Engineering Corp 83/05/13 30pp 18539 146 24X Fiche 50-275, 83/05/18, 8305230213

8305230556 Forwards Rev 1 to "Verification of Instrument & Control Design of Auxiliary Feedwater Sys," Interim Technical Rept 27
KRECHTING, J E Stone & Webster Engineering Corp 83/05/18
DENTON, H R Office of Nuclear Reactor Regulation, Director
MARTIN, J B Region 5, Office of Director MANEATIS, G A Pacific Gas & Electric Co 1p 18537 102 24X Fiche 50-275, 83/05/18, 8305230556

--8305230559 Rev 1, "Verification of Instrument & Control Design of Auxiliary Feedwater Sys," Interim Technical Rept 27
SESTAK, F Stone & Webster Engineering Corp 83/05/13 37pp 18537 103 24X Fiche 50-275, 83/05/18, 8305230556

8305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program
EISENHUT, D G Division of Licensing 83/05/18 PALLADINO, N, GILINSKY, V, AHEARNE, J Commissioners 3pp 18595 001 24X Fiche 50-275, 83/05/18, 8305250066

--8305250186 Transcript of 830504 public meeting to review design verification project in San Francisco, CA Pp 1-236
* Commissioners 83/05/04 43pp 18595 005 24X Fiche 50-275, 83/05/18, 8305250066

8305250466 Forwards Rev 0 to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys," Interim Technical Rept 45 Meeting announcement encl
KRECHTING, J E Stone & Webster Engineering Corp 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director
MANEATIS, G A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 2pp 18585 228 24X Fiche 50-275, 83/05/20, 8305250466

--8305250467 Rev 0 to "Addl Verification of Redundancy of Equipment & Power Supplies in Shared Safety-Related Sys," Interim Technical Rept 45
SESTAK, F Stone & Webster Engineering Corp 83/05/17 17pp 18585 230 24X Fiche 50-275, 83/05/20, 8305250466

8305310186 Forwards Rev 1, to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys, Control Room Ventilation & Pressurization Sys, Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18
KRECHTING, J E Stone & Webster Engineering Corp 83/05/26
DENTON, H R Office of Nuclear Reactor Regulation, Director
MANEATIS, G A Pacific Gas & Electric Co MARTIN, J B Region 5, Office of Director 1p 18652 347 24X Fiche 50-275, 83/05/26, 8305310186

--8305310191 Rev 1 to "Verification of Fire Protection Provided for Auxiliary Feedwater Sys,Control Room Ventilation & Pressurization Sys,Safety-Related Portion of 4160-Volt Electric Sys," Interim Technical Rept 18
SESTAK,F Stone & Webster Engineering Corp 83/05/24 28pp
18652 349 24X Fiche 50-275,83/05/26,8305310186

S Reportable occurrences, LERs & related correspondence

8305030313 PNS-V-83-005 on 830426,region dispatched reactive insp team to review findings & status to date of licensee investigation of safety significance of recent vandalism event on 830419 involving gauges in coolant pipe
MCQUEEN,A D , NORDERHAUG,L R Region 5, Office of Director
83/04/27 1p 18297 069 24X Fiche 50-275,83/04/27,8305030313

8305060580 PNO-V-83-019 on 830502,6 5 Richter scale earthquake occurred approx 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected
KIRSCH,D F Region 5, Office of Director 83/05/03 1p
18349 057 24X Fiche 50-275,83/05/03,8305060580

8305240397 LER 83-004/08T-0 on 830419,grinding wheel & rotary file gauges found on main coolant sys piping on main coolant pump 3 discharge side Caused intentionally by unknown persons Gauges removed by grinding & blending W/830503 ltr
KELLY,W J , SHIFFER,J D Pacific Gas & Electric Co 83/05/03
MARTIN,J B Region 5, Office of Director 3pp 18549 275 24X
Fiche 50-275,83/05/03,8305240397

8305160009 PNO-V-83-021 on 830429,leak discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity
KIRSCH,D F Region 5, Office of Director 83/05/10 1p
18456 081 24X Fiche 50-275,83/05/10,8305160009

8305130187 PNO-V-83-022 on 830509,while performing addl ultrasonic exams,RCS piping in area of one weld determined less than min wall thickness specified by code Caused by welds being ground smooth during original preservice exam
KIRSCH,D F Region 5, Office of Director 83/05/11 1p
18439 347 24X Fiche 50-275,83/05/11,8305130187

8305270249 LER 83-003/03L-0 on 830414,control operator unable to achieve satisfactory check source reading on liquid radwaste discharge line radiation monitor (RE-18) Caused by missing check source from monitoring mechanism W/830513 ltr
SHIFFER,J D , KELLY,W J Pacific Gas & Electric Co 83/05/13
MARTIN,J B Region 5, Office of Director 4pp 18637 152 24X
Fiche 50-275,83/05/13,8305270249

T Hearing transcripts on non-antitrust matters

8305110093 Transcript of 830419 public meeting re component cooling water sys in San Francisco,CA Pp 1-121
* NRC - No Detailed Affiliation Given 83/04/19 124pp
18434 112 24X Fiche 50-275,83/04/19,8305110093

8305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at 830419 meeting w/PG&E in San Francisco,CA
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N J ,
OILINSKY,V , AHEARNE,J Commissioners 3pp 18440 228 24X
Fiche 50-275,83/05/04,8305120611

--8305120621 Transcript of 830419 public meeting in San Francisco,CA re review of component cooling water sys Pp 1-121
* Commissioners 83/04/19 123pp 18440 231 24X
Fiche 50-275,83/05/04,8305120611

8305250066 Board Notification 83-69 forwards technical repts & transcript of 830504 public meeting re design verification program
EISENHUT,D G Division of Licensing 83/05/18 PALLADINO,N ,
OILINSKY,V , AHEARNE,J Commissioners 3pp 18595 001 24X
Fiche 50-275,83/05/18,8305250066

--8305250186 Transcript of 830504 public meeting to review design verification project in San Francisco,CA Pp 1-236
* Commissioners. 83/05/04 43pp 18595 005 24X
Fiche 50-275,83/05/18,8305250066

U Congressional/Executive Correspondence

8305100124 Supplemental testimony of JG Keppler re QA
KEPPLER,J G Region 3, Office of Director 83/03/25 6pp
18375 197 24X Fiche 50-000,83/03/25,8305100124

--8305100141 Responds to 811113 ltr re implications of recent seismic design errors at facility Due to design errors,util license suspended on 811119 pending completion of independent design review & receipt of schedule for completing mods
PALLADINO,N J Commissioners 82/02/01 DINGELL,J D House of Rep , Energy & Commerce 5pp 18375 228 24X
Fiche 50-000,83/03/25,8305100124

DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305040716 Summary of 830405 meeting w/util in Bethesda,MD re status of App R concerning fire protection program mods at facility
GEARS,G E Operating Reactors Branch 1 83/04/25 Operating Reactors Branch 4 3pp 18328 106 24X Fiche 50-277,83/04/25,8305040716

8305100359 Describes plans for completing fire protection mods re Sections III F,III G,III J & III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided
BOYER,V S Philadelphia Electric Co 83/05/02 EISENHUT,D G
Division of Licensing 6pp 18379 033 24X Fiche 50-277,83/05/02,8305100359

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305190522 Notification of 830526 meeting w/util in Bethesda,MD to discuss alternative safe shutdown,App R
GEARS,G Operating Reactors Branch 4 83/05/17 STOLZ,J
Operating Reactors Branch 4 2pp 18523 156 24X
Fiche 50-277,83/05/17,8305190522

Q Adjudicatory correspondence

8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl
CHILK,S J Office of the Secretary of the Commission 83/03/31
Commissioners 3pp 17807 049 24X Fiche 50-000,83/03/31,8304040470

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE,J C Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 196 24X Fiche 50-000,83/05/05,8305060250

8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO,N J Commissioners 83/05/11 2pp 18436 228 24X
Fiche 50-000,83/05/11,8305130060

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/12
Commissioners 1p 18437 033 24X Fiche 50-000,83/05/12,8305130061

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/19
Commissioners 1p 18514 283 24X Fiche 50-000,83/05/19,8305200560

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl
CHILK,S J Office of the Secretary of the Commission 83/05/27
14pp 18653 311 24X Fiche 50-000,83/05/27,8305310017

J Insurance & indemnity information

8305240307 Forwards Endorsements 1,2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection
BRADLEY,E J Philadelphia Electric Co 83/05/17 SALTZMAN,J
Assistant Director for State & Licensee Relations 41pp 18548 141
24X Fiche 50-277,83/05/17,8305240307

P Operating license stage documents & correspondence

8305040704 Summary of 830323 meeting w/util in Bethesda,MD re technical presentation on GE-hybrid control rods assemblies currently proposed for installation
GEARS,G E Operating Reactors Branch 4 83/04/22 Operating Reactors Branch 4 3pp 18336 335 24X Fiche 50-277,83/04/22,8305040704

8305020099 Responds to 830322 ltr re clarification of safety evaluation for environ qualification of safety-related electrical equipment Revised justifications for continued operation encl
DALTROFF,S L Philadelphia Electric Co 83/04/27 STOLZ,J F Operating Reactors Branch 4 12pp 18279 241 24X
Fiche 50-277,83/04/27,8305020099

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305050021 Forwards application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing
BRADLEY,E J Philadelphia Electric Co 83/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18342 106 24X
Fiche 50-277,83/05/04,8305050021

--8305050027 Application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing
DALTROFF,S L , BRADLEY,E J Philadelphia Electric Co 83/05/04 6pp 18342 107 24X Fiche 50-277,83/05/04,8305050021

--8305050033 Proposed changes to Tech Specs re limitations on & monitoring requirements for iodine concentrations in reactor coolant
* Philadelphia Electric Co 83/05/04 5pp 18342 113 24X
Fiche 50-277,83/05/04,8305050021

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305170401 Forwards scheme explaining degraded grid voltage relay circuit provided in 830310 ltr,per 830331 conference call between GE Gears & MB Ryan During surveillance test,each undervoltage relay is made to operate individually
DALTROFF,S L Philadelphia Electric Co 83/05/13 STOLZ,J F Operating Reactors Branch 4 4pp 18469 242 24X
Fiche 50-277,83/05/13,8305170401

8305180414 Forwards Peach Bottom procedures supplementing util 830516 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick
BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER,A Licensing Branch 2 2pp 18482 007 24X Fiche 50-000,83/05/16,8305180414

--8305180426 Procedure HPD/CD-3, "Airborne Activity Survey Techniques," including techniques for constant air monitors,portable fixed filter samplers & charcoal cartridges
* Philadelphia Electric Co 83/05/16 15pp 18482-009 24X
Fiche 50-000,83/05/16,8305180414

--8305180431 Procedure HPD/CD-65, "Field Use of Low Vol Portable Air Sampler "
* Philadelphia Electric Co 83/05/16 2pp 18482 024 24X
Fiche 50-000,83/05/16,8305180414

--8305180438 Procedure HPA-63d, "Calibr of Ventilation Sys Radiation Monitors "
* Philadelphia Electric Co 83/05/16 8pp. 18482 026 24X
Fiche 50-000,83/05/16,8305180414

--8305180443 Procedure HPA-77, "Determination of Max Permissible Concentration Hours "
* Philadelphia Electric Co 83/05/16 5pp 18482 034 24X
Fiche 50-000,83/05/16,8305180414

8305230318 Notification of 830520 meeting w/util in Bethesda,MD to discuss pipe cracks
GEARS,G Operating Reactors Branch 4 83/05/16 STOLZ,J Operating Reactors Branch 4 2pp 18543 304 24X
Fiche 50-277,83/05/16,8305230318

8305240428 Forwards electric equipment mod schedule for qualification or replacement of remaining electrical equipment & qualification programs for equipment not previously described,per 830322 request
DALTROFF,S L Philadelphia Electric Co 83/05/20 STOLZ,J F Operating Reactors Branch 4 6pp 18574 186 24X
Fiche 50-277,83/05/20,8305240428

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co of New York, Inc 112pp 18308 317 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305030139 Forwards notice of violation from insp on 820520-0806
STAROSTECKI,R Division of Project & Resident Programs 83/04/18 DALTROFF,S L Philadelphia Electric Co 2pp 18300 282 24X
Fiche 50-277,83/04/18,8305030139

--8305030145 Notice of violation from insp on 820520-0806 Noncompliance noted during performance of Special Procedure 518, containment penetration block valves were in closed & tagged closed condition
* Region 1, Office of Director 83/04/18 1p 18300 284 24X
Fiche 50-277,83/04/18,8305030139

8305050141 Forwards IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/04/21 DALTROFF,S L Philadelphia Electric Co 2pp 18341 108 24X
Fiche 50-277,83/04/21,8305050141

--8305050147 IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted Major areas inspected induction heating stress improvement procedures used to mitigate intergranular stress corrosion cracking
REYNOLDS,S D Region 1, Office of Director DURR,J Division of Engineering & Technical Programs 83/04/21 8pp 18341 110 24X
Fiche 50-277,83/04/21,8305050141

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025.

8305020343 Confirms 830506 enforcement conference in King of Prussia,PA to discuss operation in excess of limiting condition for operation for primary containment integrity & inadequate review of proposed mods
STAROSTECKI,R. Division of Project & Resident Programs 83/04/25. DALTROFF,S L Philadelphia Electric Co. 2pp 18276 325 24X
Fiche 50-277,83/04/25,8305020343

8305060513 Forwards payment in response to NRC 830329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidavit encl
BOYER,V S Philadelphia Electric Co 83/04/27. Director's Office, Office of Inspection and Enforcement 36pp 18348 167 24X
Fiche: 50-277,83/04/27,8305060513

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28. Consolidated Edison Co. of New York, Inc 115pp 18382:047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305110261 Forwards IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/04/29
DALTROFF, S L Philadelphia Electric Co 3pp 18393 160 24X
Fiche 50-277,83/04/29,8305110261

--8305110265 Notice of violation from insp on 830315-21
* Region 1, Office of Director 83/04/29 1p 18393 163 24X
Fiche 50-277,83/04/29,8305110261

--8305110267 IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21
Noncompliance noted failure to post radiation area around reactor water cleanup skid
COLLINS, D J , SHANBAKY, M M Region 1, Office of Director
83/04/28 11pp 18393 164 24X Fiche 50-277,83/04/29,8305110261

8305200100 Forwards safety evaluation & technical evaluation rept re util requests for relief from inservice insp requirements
Portion of requests granted
STOLZ, J F Operating Reactors Branch 4 83/05/02 BAUER, E Q
Philadelphia Electric Co. 4pp 18540 154 24X
Fiche: 50-277,83/05/02,8305200100

--8305200107 Safety evaluation re requests for relief from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 83/05/02 8pp
18540 158 24X Fiche, 50-277,83/05/02,8305200100

--8305200110 "Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 186-028-14
82/09/10 NRC - No Detailed Affiliation Given 27pp
18540 166 24X Fiche 50-277,83/05/02,8305200100

--8305200238 Notice of granting relief from ASME Code insp requirements
STOLZ, J F Operating Reactors Branch 4 83/05/02 2pp
18540 196 24X Fiche 50-277,83/05/02,8305200100

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp. 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524.003 24X Fiche 50-000,83/05/11,8303040034.

8305250299 Forwards IE Insp Repts 50-277/83-20 & 50-278/83-10 on 830321-25 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs. 83/05/13
DALTROFF, S L Philadelphia Electric Co 2pp 18592 048 24X
Fiche 50-277,83/05/13,8305250299

---8305250303 Notice of violation from insp on 830321-25
* Region 1, Office of Director 83/05/13 2pp 18592.050 24X
Fiche: 50-277,83/05/13,8305250299

---8305250306 IE Insp Repts 50-277/83-10 & 50-278/83-10 on 830321-25
Noncompliance noted: lack of administrative controls, nontraceability of instrument usage & exceeding instrument calibr due date in measuring & test equipment area
SHAUB, E T , MEYER, G W , PRELL, J A Region 1, Office of Director
83/05/11 15pp 18592 052 24X Fiche 50-277,83/05/13,8305250299

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

*8305120473 LER 83-008/03L-0 on 830407, HPCI high steam flow isolation switch DPIS-2-23-77 setpoint found above Tech Spec limit Caused by setpoint drift of Barton Model 288 Instrument recalibr, tested & returned to svc
COONEY, M J Philadelphia Electric Co 83/04/21 ALLAN, J M Region 1, Office of Director 1p 18431 071 24X Fiche 50-277,83/04/21, 8305120473

8305120358 LER 83-009/03L-0 on 830324, during surveillance testing, smoke detector in drywell failed to provide audible alarm code or annunciate in control room Caused by defective detector circuit board Board replaced, tested & returned to svc
COONEY, M J Philadelphia Electric Co 83/04/22 ALLAN, J M Region 1, Office of Director 1p 18434 047 24X Fiche 50-277,83/04/22, 8305120358

8305060513 Forwards payment in response to NRC 830329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidavit encl
BOYER, V S Philadelphia Electric Co 83/04/27 Director's Office, Office of Inspection and Enforcement 36pp 18348 167 24X Fiche 50-277,83/04/27,8305060513

8305060387 PNO-I-83-045 on 830503, shutdown initiated due to containment pressure increase to 0 6 psi & unidentified containment leakage of 3 4 gpm Recirculation pump cooling water leakage noted
MCCABE, E , KEIMIG, R Region 1, Office of Director 83/05/03 1p
18343 165 24X Fiche 50-277,83/05/03,8305060387

8305110316 LER 83-007/03L-0 on 830404, narrow range torus level transmitter LT 8027A determined to be out of calibr Caused by instrument drift Instrument recalibr & returned to svc
COONEY, M J Philadelphia Electric Co 83/05/03 ALLAN, J M Region 1, Office of Director 1p 18393 159 24X Fiche 50-277,83/05/03, 8305110316

8305060558 PNO-I-83-045A on 830503, drywell entry identified packing leak on recirculation pump discharge header cross connect motor operated valve MO-65A Cause not stated Region I will respond to media inquiries
MCCABE, KEIMIG Region 1, Office of Director 83/05/04 1p
18348 262 24X Fiche 50-277,83/05/04,8305060558

8305270235 LER 83-011/01P on 830506, ultrasonic testing indicated crack in RHR shutdown cooling suction line Caused by intergranular stress corrosion cracking Crack analysis program implemented to determine corrective actions
FLEISCHMANN, R Philadelphia Electric Co 83/05/06 ALLAN, J M
Region 1, Office of Director 2pp 18637 198 24X
Fiche 50-277,83/05/06,8305270235

8305120412 PNO-I-83-045B on 830503, ultrasonic testing conducted on Sample 2 recirculation riser welds & one RHR weld on Unit 2 to determine if Unit 3 crack indications exist on Unit 2 RHR showed cracks on both pipe & elbow side
BLOUGH, MCCABE Region 1, Office of Director 83/05/09 1p
18431 153 24X Fiche, 50-277,83/05/09,8305120412

8305270184 LER 83-012/01P on 830511, insp of fire barrier penetrations revealed inadequacies in penetration seals Caused by const or design error & inadequate initial insp Fire watches posted & addl insps initiated
FLEISCHMANN, R Philadelphia Electric Co 83/05/12 ALLAN, J M
Region 1, Office of Director 2pp 18637 359 24X
Fiche 50-277,83/05/12,8305270184.

DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8305040716 Summary of 830405 meeting w/util in Bethesda, MD re status of App R concerning fire protection program mods at facility
GEARS, O E Operating Reactors Branch 4 83/04/25 Operating Reactors Branch 4 3pp 18328 106 24X Fiche 50-277,83/04/25, 8305040716

8305100359 Describes plans for completing fire protection mods re Sections III F, III G, III J & III M of App R Exemptions requested for schedule relief to permit completion of mods by certain dates Justification for operation provided
BOYER, V S Philadelphia Electric Co 83/05/02 EISENHUT, D G
Division of Licensing 6pp 18379 033 24X Fiche 50-277, 83/05/02, 8305100359

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305190522 Notification of 830526 meeting w/util in Bethesda, MD to discuss alternative safe shutdown, App R
GEARS, G Operating Reactors Branch 4 83/05/17 STOLZ, J
Operating Reactors Branch 4 2pp 18523 156 24X
Fiche 50-277, 83/05/17, 8305190522

G Adjudicatory correspondence

8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl
CHILK, S J Office of the Secretary of the Commission 83/03/31
Commissioners 3pp 17807 049 24X Fiche 50-000, 83/03/31, 8304040470

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE, J C Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 196 24X Fiche 50-000, 83/05/05, 8305060250

8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO, N J Commissioners 83/05/11 2pp 18436 228 24X
Fiche 50-000, 83/05/11, 8305130060

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/05/12
Commissioners 1p 18437 033 24X Fiche 50-000, 83/05/12, 8305130061

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/05/19
Commissioners 1p 18514 283 24X Fiche 50-000, 83/05/19, 8305200560

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl
CHILK, S J Office of the Secretary of the Commission 83/05/27
14pp 18653 311 24X Fiche 50-000, 83/05/27, 8305310017

J Insurance & indemnity information

8305240307 Forwards Endorsements 1, 2 & 3 to MAELU Certificates M-8 & M-9 for secondary financial protection
BRADLEY, E J Philadelphia Electric Co 83/05/17 SALTZMAN, J
Assistant Director for State & Licensee Relations 41pp 18548 141
24X Fiche 50-277, 83/05/17, 8305240307

P Operating license stage documents & correspondence

8305040704 Summary of 830323 meeting w/util in Bethesda, MD re technical presentation on GE-hybrid control rods assemblies currently proposed for installation
GEARS, G E Operating Reactors Branch 4 83/04/22 Operating Reactors Branch 4 3pp 18336 335 24X Fiche 50-277, 83/04/22, 8305040704

8305020099 Responds to 830322 ltr re clarification of safety evaluation for environ qualification of safety-related electrical equipment Revised justifications for continued operation encl
DALTROFF, S L Philadelphia Electric Co 83/04/27 STOLZ, J F
Operating Reactors Branch 4 12pp 18279 241 24X
Fiche 50-277, 83/04/27, 8305020099

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060684 Notification of 830506 meeting w/util in Bethesda, MD to discuss recent crack-like indications discovered in recirculation sys
GEARS, G Operating Reactors Branch 4 83/05/03 STOLZ, J
Operating Reactors Branch 4 2pp 18357 311 24X
Fiche 50-278, 83/05/03, 8305060684

8305050021 Forwards application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing
BRADLEY, E J Philadelphia Electric Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18342 106 24X
Fiche 50-277, 83/05/04, 8305050021

--8305050027 Application for amend to Licenses DPR-44 & DPR-56 changing Tech Spec re limitations on & monitoring requirements for iodine concentrations in reactor coolant & coolant leak testing
DALTROFF, S L , BRADLEY, E J Philadelphia Electric Co 83/05/04
6pp 18342 107 24X Fiche 50-277, 83/05/04, 8305050021

--8305050033 Proposed changes to Tech Specs re limitations on & monitoring requirements for iodine concentrations in reactor coolant
* Philadelphia Electric Co 83/05/04 5pp 18342 113 24X
Fiche 50-277, 83/05/04, 8305050021

8305180007 Forwards Amend 92 to License DPR-56, safety evaluation & notice of issuance & availability Amend revises Tech Specs for reactor operation w/Reload 5 core during Cycle 6
GEARS, G E Operating Reactors Branch 4 83/05/04 BAUER, E G
Philadelphia Electric Co 4pp 18497 161 24X
Fiche 50-278, 83/05/04, 8305180007

--8305180008 Amend 92 to License DPR-56, permitting reactor operation w/Reload 5 core during Cycle 6
STOLZ, J F Operating Reactors Branch 4 83/05/04 12pp
18497 165 24X Fiche 50-278, 83/05/04, 8305180007

--8305180011 Safety evaluation supporting Amend 92 to License DPR-56
* Office of Nuclear Reactor Regulation, Director 83/05/04
19pp 18497 177 24X Fiche 50-278, 83/05/04, 8305180007

--8305180014 Notice of issuance & availability of Amend 92 to License DPR-56
STOLZ, J F Operating Reactors Branch 4 83/05/04 2pp
18497 196 24X Fiche 50-278, 83/05/04, 8305180007

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170401 Forwards scheme explaining degraded grid voltage relay circuit provided in 830310 ltr, per 830331 conference call between GE Gears & MB Ryan During surveillance test, each undervoltage relay is made to operate individually
DALTROFF, S L Philadelphia Electric Co 83/05/13 STOLZ, J F.
Operating Reactors Branch 4 4pp 18469 242 24X
Fiche 50-277, 83/05/13, 8305170401

8305180414 Forwards Peach Bottom procedures supplementing util 830516 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick
BRADLEY, E J Philadelphia Electric Co 83/05/16 SCHWENCER, A
Licensing Branch 2 2pp 18482 007 24X Fiche 50-000, 83/05/16, 8305180414

--8305180426 Procedure HPO/CO-3, "Airborne Activity Survey Techniques," including techniques for constant air monitors, portable fixed filter samplers & charcoal cartridges
* Philadelphia Electric Co 83/05/16 15pp 18482.009 24X
Fiche 50-000, 83/05/16, 8305180414

--8305180431 Procedure HPO/CO-65, "Field Use of Low Vol Portable Air Sampler "
* Philadelphia Electric Co 83/05/16 2pp 18482 024. 24X
Fiche 50-000, 83/05/16, 8305180414

--8305180438 Procedure HPA-63d, "Calibr of Ventilation Sys Radiation Monitors "
* Philadelphia Electric Co 83/05/16 8pp 18482 026 24X
Fiche 50-000,83/05/16,8305180414

--8305180443 Procedure HPA-77, "Determination of Max Permissible Concentration Hours "
* Philadelphia Electric Co 83/05/16 5pp 18482 034 24X
Fiche 50-000,83/05/16,8305180414

8305230318 Notification of 830520 meeting w/util in Bethesda,MD to discuss pipe cracks
GEARS,G Operating Reactors Branch 4 83/05/16 STOLZ,J
Operating Reactors Branch 4 2pp 18543 304 24X
Fiche 50-277,83/05/16,8305230318

8305240428 Forwards electric equipment mod schedule for qualification or replacement of remaining electrical equipment & qualification programs for equipment not previously described,per 830322 request
DALTROFF,S L Philadelphia Electric Co 83/05/20 STOLZ,J F
Operating Reactors Branch 4 6pp 18574 186 24X
Fiche 50-277,83/05/20,8305240428

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305030139 Forwards notice of violation from insp on 820520-0806
STAROSTECKI,R Division of Project & Resident Programs 83/04/18
DALTROFF,S L Philadelphia Electric Co 2pp 18300 282 24X
Fiche 50-277,83/04/18,8305030139

--8305030145 Notice of violation from insp on 820520-0806 Noncompliance noted during performance of Special Procedure 518, containment penetration block valves were in closed & tagged closed condition
* Region 1, Office of Director 83/04/18 1p 18300 284 24X
Fiche 50-277,83/04/18,8305030139

8305050141 Forwards IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/04/21
DALTROFF,S L Philadelphia Electric Co 2pp 18341 108 24X
Fiche 50-277,83/04/21,8305050141

--8305050147 IE Insp Repts 50-277/83-08 & 50-278/83-08 on 830307-09 No noncompliance noted.Major areas inspected induction heating stress improvement procedures used to mitigate intergranular stress corrosion cracking
REYNOLDS,S D Region 1, Office of Director DURR,J Division of Engineering & Technical Programs 83/04/21 8pp 18341 110 24X
Fiche 50-277,83/04/21,8305050141

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020343 Confirms 830506 enforcement conference in King of Prussia,PA to discuss operation in excess of limiting condition for operation for primary containment integrity & inadequate review of proposed mods
STAROSTECKI,R Division of Project & Resident Programs 83/04/25
DALTROFF,S L Philadelphia Electric Co 2pp 18276 325 24X
Fiche 50-277,83/04/25,8305020343.

8305060513 Forwards payment in response to NRC 830329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidavit encl
BOYER,V.S. Philadelphia Electric Co 83/04/27 Director's Office, Office of Inspection and Enforcement 36pp. 18348 167 24X
Fiche 50-277,83/04/27,8305060513.

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305110261 Forwards IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/04/29
DALTROFF,S L Philadelphia Electric Co 3pp 18393 160 24X
Fiche 50-277,83/04/29,8305110261

--8305110265 Notice of violation from insp on 830315-21
* Region 1, Office of Director 83/04/29 1p 18393 163 24X
Fiche 50-277,83/04/29,8305110261

--8305110267 IE Insp Repts 50-277/83-07 & 50-278/83-07 on 830315-21 Noncompliance noted failure to post radiation area around reactor water cleanup skid
COLLINS,D J , SHANDAKY,M M Region 1, Office of Director
83/04/28 11pp 18393 164 24X Fiche 50-277,83/04/29,8305110261

8305200100 Forwards safety evaluation & technical evaluation rept re util requests for relief from inservice insp requirements Portion of requests granted
STOLZ,J F Operating Reactors Branch 4 83/05/02 BAUER,E G
Philadelphia Electric Co 4pp 18540 154 24X
Fiche 50-277,83/05/02,8305200100

--8305200107 Safety evaluation re requests for relief from inservice insp requirements
* Office of Nuclear Reactor Regulation, Director 83/05/02 8pp
18540 158 24X Fiche 50-277,83/05/02,8305200100

--8305200110 "Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 186-028-14
82/09/10 NRC - No Detailed Affiliation Given 27pp
18540 166 24X Fiche 50-277,83/05/02,8305200100

--8305200238 Notice of granting relief from ASME Code insp requirements
STOLZ,J F Operating Reactors Branch 4 83/05/02 2pp
18540 196 24X Fiche 50-277,83/05/02,8305200100

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250299 Forwards IE Insp Repts 50-277/83-20 & 50-278/83-10 on 830321-25 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/05/13
DALTROFF,S L Philadelphia Electric Co 2pp 18592 048 24X
Fiche 50-277,83/05/13,8305250299

--8305250303 Notice of violation from insp on 830321-25
* Region 1, Office of Director 83/05/13 2pp 18592 050 24X
Fiche 50-277,83/05/13,8305250299

--8305250306 IE Insp Repts 50-277/83-10 & 50-278/83-10 on 830321-25
Noncompliance noted lack of administrative controls, nontraceability of instrument usage & exceeding instrument calibr due date in measuring & test equipment area
SHAUB,E T , MEYER,G W , PRELL,J A Region 1, Office of Director
83/05/11 15pp 18592 052 24X Fiche 50-277,83/05/13,8305250299

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

E Reportable occurrences, LERs & related correspondence

8305110340 Forwards LER 83-011/01T-0 Detailed event analysis submitted
COONEY,M J Philadelphia Electric Co 83/04/21 ALLAN,J M Region 1, Office of Director 3pp 18406 154 24X Fiche 50-278,83/04/21, 8305110340

--8305110349 LER 83-011/01T-0 on 830407, loss of control rod position indication occurred from control rods 22-47,38-31 & 34-15 Caused by improper use of jumper procedure on 830311,26 & 0402 Jumpers removed Jumper procedure suspended
COONEY,M J Philadelphia Electric Co 83/04/21 Region 1, Office of Director 1p 18406 157 24X Fiche 50-278,83/04/21, 8305110340

8305030118 PNO-I-83-038, on 830425, three 1-inch long axial indications & one circumferential indication in heat affected zone of recirculation pump riser discovered Caused by intergranular stress corrosion cracking
BLOUGH, MCCABE Region 1, Office of Director 83/04/26 1p
18308 187 24X Fiche 50-278,83/04/26,8305030118

8305270117 LER 83-012/01P, on 830425, analysis of radiographs & ultrasonic testing data indicated presence of four crack-like indications in Q reactor recirculation sys riser of loop A Caused by intergranular stress corrosion cracking
FLEISCHMANN,R Philadelphia Electric Co 83/04/26 ALLAN,J M Region 1, Office of Director 2pp 18638 166 24X
Fiche 50-278,83/04/26,8305270117

8305020337 PNO-I-83-038A on 830427, recirculation loop A riser exam completed One weld in each of two risers had crack indications Data forwarded to GE for more detailed analysis Licensee addressing repair method & impact on outage
BLOUGH, MCCABE,E Region 1, Office of Director 83/04/27 1p
18277-134 24X Fiche 50-278,83/04/27,8305020337

8305060513 Forwards payment in response to NRC 830329 notice of violation & imposition of civil penalties re valving error events & radiation protection violations Corrective actions, bills for collection & affidavit encl
BOYER,V S Philadelphia Electric Co 83/04/27 Director's Office, Office of Inspection and Enforcement 36pp 18348-167 24X
Fiche 50-277,83/04/27,8305060513

8305270184 LER 83-012/01P on 830511, insp of fire barrier penetrations revealed inadequacies in penetration seals Caused by const or design error & inadequate initial insp Fire watches posted & addl insps initiated
FLEISCHMANN,R Philadelphia Electric Co 83/05/12 ALLAN,J M
Region 1, Office of Director 2pp 18637 359 24X
Fiche 50-277,83/05/12,8305270184

DOCKET 50-280 SURRY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs, as stated
STEWART,W L Virginia Electric & Power Co 83/03/24 MCGUIRE,D R
Division of Emergency Preparedness & Materials Safety 1p
18342-200 24X Fiche 50-000,83/03/24,8305050126

8305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/29
STEWART,W L Virginia Electric & Power Co 2pp. 18644-287 24X
Fiche 50-280,83/04/29,8305270423.

--8305270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event followup & LERs
BURKE,D J , DAVIS,M J Region 2, Office of Director JULIAN,C
Division of Project & Resident Programs 83/04/29 7pp.
18644 289 24X Fiche 50-280,83/04/29,8305270423

8305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EOF) updating 820408 response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities
STEWART,W L Virginia Electric & Power Co 83/05/06 DENTON,H R,
Office of Nuclear Reactor Regulation, Director EISENHUT,D G
Division of Licensing 13pp 18436 215 24X Fiche 50-000,83/05/06, 8305130058

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305180169 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737, Item III A 2 1 requirements complete
VARGA,S A Operating Reactors Branch 1 83/05/13 STEWART,W L
Virginia Electric & Power Co 3pp 18502 351 24X
Fiche 50-280,83/05/13,8305180169

P Operating license stage documents & correspondence

8305060658 Forwards safety evaluation re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1.6 on containment pressure, water level & hydrogen monitors Util 801210 submittal & 830218 rev acceptable Environ qualification to be reviewed separately
VARGA,S A Operating Reactors Branch 1 83/04/22 STEWART,W L
Virginia Electric & Power Co 2pp 18357 357 24X
Fiche 50-280,83/04/22,8305060658

--8305060663 Safety evaluation re TMI Action Plan Items (NUREG-0737) II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 5, "Containment Hydrogen Monitor " Designs acceptable
* Office of Nuclear Reactor Regulation, Director 83/04/22 5pp
18357 359 24X Fiche 50-280,83/04/22,8305060658

8305090321 Forwards Amend 87 to License DPR-32, safety evaluation & notice of issuance & availability Amend revises Tech Specs to raise control rod bank insertion limits
NEIGHBORS,J D Operating Reactors Branch 1 83/04/26 STEWART,W L
Virginia Electric & Power Co 2pp 18367 245 24X
Fiche 50-280,83/04/26,8305090321

--8305090327 Amend 87 to License DPR-32, revising Tech Specs to raise control rod bank insertion limits
VARGA,S A Operating Reactors Branch 1 83/04/26 5pp
18367 247 24X Fiche 50-280,83/04/26,8305090321

--8305090331 Safety evaluation supporting Amend 87 to License DPR-32
* Office of Nuclear Reactor Regulation, Director 83/04/26 2pp
18367 252 24X Fiche 50-280,83/04/26,8305090321

--8305090335 Notice of issuance & availability of Amend 87 to License DPR-32
VARGA,S A Operating Reactors Branch 1 83/04/26 2pp
18367.254. 24X Fiche 50-280,83/04/26,8305090321.

8305090045 Forwards Amend 88 to Licenses DPR-32 & DPR-37, safety evaluation & notice of issuance & availability Amends revise Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers
NEIGHBORS,J D Operating Reactors Branch 1 83/04/27 STEWART,W L
Virginia Electric & Power Co 2pp 18381 184 24X
Fiche 50-280,83/04/27,8305090045

--8305090051 Amend 88 to Licenses DPR-32 & DPR-37, revising Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers
VARGA,S A Operating Reactors Branch 1, 83/04/27 8pp
18381 186 24X Fiche 50-280,83/04/27,8305090045

--8305090062 Safety evaluation supporting Amend 88 to Licenses DPR-32 & DPR-37.
* Office of Nuclear Reactor Regulation, Director 83/04/27. 2pp.
18381 194 24X Fiche 50-280,83/04/27,8305090045

--8305090070 Notice of issuance & availability of Amend 88 to Licenses DPR-32 & DPR-37
VARGA,S A Operating Reactors Branch 1 83/04/27 2pp
18381,196 24X Fiche 50-280,83/04/27,8305090045

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060556 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Specs to allow optimization of core loading patterns & provide addl operating flexibility by changing existing fractional power limit
STEWART, W L Virginia Electric & Power Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 8pp 18348 263 24X
Fiche 50-280, 83/05/02, 8305060556

--8305060561 Proposed Tech Spec pages allowing optimization of core loading patterns & providing addl operating flexibility by changing existing fractional power limit
* Virginia Electric & Power Co 83/05/02 22pp 18348 271 24X
Fiche 50-280, 83/05/02, 8305060556

8305100108 Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472 "Offsite Dose Calculation Manual" also encl
STEWART, W L Virginia Electric & Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 3pp 18371 346 24X
Fiche 50-280, 83/05/04, 8305100108

--8305100111 Proposed revs to radiological effluent Tech Specs, in accordance w/Rev 3 to NUREG-0472
* Virginia Electric & Power Co 83/05/04 87pp 18371 349 24X
Fiche 50-280, 83/05/04, 8305100108

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180372 Forwards response to 830404 ltr re Category IV equipment Equipment qualification file packages submitted in support of specific identified items. Response to 830126 ltr re proposed corrective actions expected by 830520
STEWART, W L Virginia Electric & Power Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 771pp 18483 120 24X
Fiche 50-280, 83/05/11, 8305180372

8305200163 Responds to 830126 & 0404 requests to review proprietary matl contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment Info no longer requires proprietary protection
STEWART, W L. Virginia Electric & Power Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 1p 18519 070 24X
Fiche 50-280, 83/05/11, 8305200163

8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
STEWART, W L Virginia Electric & Power Co 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director. EISENHUT, D. G Division of Licensing 19pp 18513 182 24X Fiche 50-000, 83/05/12, 8305200499

8305260232 Submits schedule for replacement or mod of safety-related equipment for environ qualification per 10CFR50 49(g) criteria Master list of equipment encl
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H. R Office of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 60pp 18622 127 24X
Fiche. 50-280, 83/05/20, 8305260232

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270565 Forwards IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/29
STEWART, W L. Virginia Electric & Power Co. 2pp 18647 172. 24X
Fiche: 50-280, 83/03/29, 8305270565

--8305270574 IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted Major areas inspected inservice testing of pumps & valves, secondary coolant chemisty program, inservice insp & LERS
GIRARD, E H , ROSS, W J , BLAKE, J J Region 2, Office of Director 83/03/25 9pp 18647 174 24X Fiche 50-280, 83/03/29, 8305270565

8305270483 Forwards IE Insp Repts 50-280/83-08 & 50-281/83-08 on 830201-28 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/04
STEWART, W L Virginia Electric & Power Co 2pp 18662 142 24X
Fiche 50-280, 83/04/04, 8305270483

--8305270490 IE Insp Repts 50-280/83-08 & 50-281/83-08 on 830201-28 No noncompliance noted Major areas inspected plant operations & operating records, plant maint & surveillance, plant security, followup of events & LERs
BURKE, D J , DAVIS, M J Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 83/04/01 5pp 18662 144 24X Fiche 50-280, 83/04/04, 8305270483

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 087 24X Fiche 50-000, 83/04/22, 8303040023

8305100315 Forwards response to 830324 notice of violation & proposed imposition of civil penalty Corrective actions engineering safeguards valve check list revised & added to startup procedure & sys valve lineups now required
STEWART, W L Virginia Electric & Power Co 83/04/22 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 18370 001 24X Fiche 50-280, 83/04/22, 8305100315

8305270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety
O'REILLY, J P Region 2, Office of Director 83/04/22 STEWART, W L Virginia Electric & Power Co 2pp 18646 001 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270527 Forwards SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
LEWIS, R C Division of Project & Resident Programs 83/02/10
STEWART, W L Virginia Electric & Power Co 2pp 18646 003 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270541 SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
* Region 2, Office of Director 83/02/10 49pp 18646.005 24X
Fiche 50-000, 83/04/22, 8305270513

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305090029 Grants 830316 request for relief from 1980 ASME Section XI requirements for inservice insp hydrostatic tests. Relief permits drain & manual isolation valve replacement in main steam sys w/o performing hydrostatic tests for entire sys.
VARGA, S A Operating Reactors Branch 1 83/04/27 STEWART, W L Virginia Electric & Power Co 3pp 18381 200 24X
Fiche 50-280, 83/04/27, 8305090029

--8305090037 Notice of granting of relief from ASME Code requirements for inservice insp hydrostatic tests
VARGA, S A Operating Reactors Branch 1 83/04/27 2pp 18381 203 24X Fiche 50-280, 83/04/27, 8305090029

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp. 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/29
STEWART,W L Virginia Electric & Power Co 2pp 18644 287 24X
Fiche 50-280,83/04/29,8305270423

--8305270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records,maint & surveillance,security event followup & LERs
BURKE,D J , DAVIS,M J Region 2, Office of Director JULIAN,C
Division of Project & Resident Programs 83/04/29 7pp
18644 289 24X Fiche 50-280,83/04/29,8305270423

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305090139 Forwards payment of civil penalty imposed for valve infraction reported in Enforcement Action EA 82-143
STEWART,W L Virginia Electric & Power Co 83/05/03 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 3pp
18364 049 24X Fiche 50-280,83/05/03,8305090139

8305270242 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05
DANCE,H C Division of Project & Resident Programs 83/05/03
STEWART,W L Virginia Electric & Power Co 1p 18642 025 24X
Fiche 50-280,83/05/03,8305270242

--8305270248 Responds to NRC 830311 ltr re violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05 Corrective actions Administrative Procedure ADM-8 reviewed w/staff assistant & notice of violation & response posted
STEWART,W L Virginia Electric & Power Co 83/04/08
O'REILLY,J P Region 2, Office of Director 2pp 18642 026 24X
Fiche 50-280,83/05/03,8305270242

--8305270252 Forwards IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 & notice of violation
DANCE,H C Division of Project & Resident Programs 83/03/11
STEWART,W L Virginia Electric & Power Co 2pp 18642 028 24X
Fiche 50-280,83/05/03,8305270242

--8305270257 Notice of violation from insp on 830207-11
* Region 2, Office of Director 83/03/11 1p 18642 030 24X
Fiche 50-280,83/05/03,8305270242

--8305270265 IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 Noncompliance noted failure to post notice of violation & licensee response to IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821221
HOSEY,C M , BARR,K P Region 2, Office of Director 83/03/08
7pp 18642 031 24X Fiche 50-280,83/05/03,8305270242

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305090224 EN-83-030 on 830509,notice of violation & proposed imposition of civil penalty in amount of $40,000 issued to licensee Action based on serious weaknesses in internal & external dose monitoring & procedural compliance
FLACK,E , AXELRAD,J Director's Office, Office of Inspection and
Enforcement 83/05/04 1p 18363 349 24X Fiche 50-280,83/05/04,
8305090224

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305250541 Discusses IE insp on 830321-25 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY,J P Region 2, Office of Director 83/05/09 STEWART,W L
Virginia Electric & Power Co 3pp 18595 344 24X
Fiche 50-280,83/05/09,8305250541

--8305250546 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted radiation program failed to meet 10CFR20 requirements & Tech Spec provisions in area of worker protection
O'REILLY,J P Region 1, Office of Director 83/05/09 5pp
18595 347 24X Fiche 50-280,83/05/09,8305250541

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New
York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034,

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New
York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305100115 Forwards LERs 83-018/03L-0 & 83-019/03L-0
WILSON,J L Virginia Electric & Power Co 83/05/03 O'REILLY,J P
Region 2, Office of Director 1p 18375 043 24X
Fiche 50-280,83/05/03,8305100115

--8305100120 LER 83-018/03L-0 on 830411,Type C testing (PT-16 4 containment isolation valve leakage) performed during Spring 1983 refueling outage disclosed as-found leakage exceeding allowable rate Caused by normal wear Valves repaired
WILSON,J L Virginia Electric & Power Co 83/05/03 Region 2,
Office of Director 2pp 18375 044 24X Fiche 50-280,83/05/03,
8305100115

--8305100129 LER 83-019/03L-0 on 830408,performance of Periodic Test 1-PT-398-2 revealed snubbers 1-WFPD-HSS-15,1-RC-HSS-115, 1-SI-HSS-27A,1-RH-HSS-12 & 1-SI-HSS-28 inoperable.Caused by fluid leaks & loose pipe clamp Snubbers replaced
WILSON,J L Virginia Electric & Power Co 83/05/03, Region 2,
Office of Director 2pp 18375 046 24X Fiche 50-280,83/05/03,
8305100115

8305130198 Forwards updated LER 83-068/03X-1
WILSON,J L Virginia Electric & Power Co 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18440 077 24X
Fiche 50-280,83/05/06,8305130198

--8305130203 Updated LER 82-068/03X-1 on 820614,fire detection sys discovered to have lost program,rendering sys inoperable Probably caused by inadvertently reset program button Sys reprogrammed & central processing unit installed
WILSON,J L Virginia Electric & Power Co 83/05/06 Region 2,
Office of Director 3pp 18440 079 24X Fiche 50-280,83/05/06,
8305130198

8305130228 Forwards LER 83-020/03L-0
WILSON,J L Virginia Electric & Power Co 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18439 332 24X
Fiche 50-280,83/05/06,8305130228

--8305130243 LER 83-020/03L-0 on 830408,20 of 58 snubbers failed to meet acceptance criteria stipulated in periodic test Caused by seal degradation Snubbers either readjusted,repaired or replaced
WILSON,J L Virginia Electric & Power Co 83/05/06 Region 2,
Office of Director 3pp 18439 333 24X Fiche 50-280,83/05/06,
8305130228

8305130142 PNO-II-83-038 on 830510,safety injection pumps inadvertently actuated during heatup in preparation for restart Caused by loss of vital dc electrical bus Damaged batteries replaced
JENISON,K M , JULIAN,C A Region 2, Office of Director 83/05/10
1p 18438 131 24X Fiche 50-280,83/05/10,8305130142

DOCKET 50-281 SURRY POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs,as stated
STEWART,W L Virginia Electric & Power Co 83/03/24 MCGUIRE,D R
Division of Emergency Preparedness & Materials Safety 1p
18342.200 24X Fiche 50-000,83/03/24,8305050126

8305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/29
STEWART, W L Virginia Electric & Power Co 2pp 18644 287 24X
Fiche 50-280, 83/04/29, 8305270423

--8305270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event followup & LERs
BURKE, D J Region 2, Office of Director 83/04/29 7pp
18644 289 24X Fiche 50-280, 83/04/29, 8305270423

8305060100 Requests exemption from 10CFR50 48(c)(4), allowing completion of mods to 10CFR50, App R, Section III G 3 during second refueling outage after 830517
STEWART, W L Virginia Electric & Power Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 18345 111 24X
Fiche 50-281, 83/05/03, 8305060100

8305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EOF) updating 820408 response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities
STEWART, W L Virginia Electric & Power Co 83/05/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 13pp 18436 215 24X Fiche 50-000, 83/05/06, 8305130058

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180169 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737, Item III A 2 1 requirements complete
VARGA, S A Operating Reactors Branch 1 83/05/13 STEWART, W L
Virginia Electric & Power Co 3pp 18502 351 24X
Fiche 50-280, 83/05/13, 8305180169

P. Operating license stage documents & correspondence

8305060658 Forwards safety evaluation re NUREG-0737, Items II F 1 4, II F 1.5 & II F 1 6 on containment pressure, water level & hydrogen monitors Util 801210 submittal & 830218 rev acceptable Environ qualification to be reviewed separately
VARGA, S A Operating Reactors Branch 1 83/04/22 STEWART, W L
Virginia Electric & Power Co 2pp 18357 357 24X
Fiche 50-280, 83/04/22, 8305060658

--8305060663 Safety evaluation re TMI Action Plan Items (NUREG-0737) II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1.5, "Containment Hydrogen Monitor " Designs acceptable
* Office of Nuclear Reactor Regulation, Director 83/04/22 5pp
18357 359 24X Fiche 50-280, 83/04/22, 8305060658

8305090045 Forwards Amend 88 to Licenses DPR-32 & DPR-37, safety evaluation & notice of issuance & availability Amends revise Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers
NEIGHBORS, J D Operating Reactors Branch 1 83/04/27 STEWART, W L
Virginia Electric & Power Co 2pp 18381 184 24X
Fiche 50-280, 83/04/27, 8305090045

--8305090051 Amend 88 to Licenses DPR-32 & DPR-37, revising Tech Specs to change schedule requirements for functional testing of 50 KIPS & snubbers
VARGA, S A Operating Reactors Branch 1 83/04/27 8pp
18381 186 24X Fiche 50-280, 83/04/27, 8305090045

--8305090062 Safety evaluation supporting Amend 88 to Licenses DPR-32 & DPR-37
* Office of Nuclear Reactor Regulation, Director 83/04/27 2pp
18381 194 24X Fiche 50-280, 83/04/27, 8305090045

--8305090070 Notice of issuance & availability of Amend 88 to Licenses DPR-32 & DPR-37
VARGA, S A Operating Reactors Branch 1 83/04/27 2pp
18381 196 24X Fiche 50-280, 83/04/27, 8305090045

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D. G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche, 50-000, 83/05/02, 8305020455

8305060556 Application for amend to Licenses DPR-32 & DPR-37, changing Tech Specs to allow optimization of core loading patterns & provide addl operating flexibility by changing existing fractional power limit
STEWART, W L Virginia Electric & Power Co 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 8pp 18348 263 24X
Fiche 50-280, 83/05/02, 8305060556

--8305060561 Proposed Tech Spec pages allowing optimization of core loading patterns & providing addl operating flexibility by changing existing fractional power limit
* Virginia Electric & Power Co 83/05/02 22pp 18348 271 24X
Fiche 50-280, 83/05/02, 8305060556

8305100108 Application to amend Licenses DPR-32 & DPR-37, revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472 "Offsite Dose Calculation Manual" also encl
STEWART, W L Virginia Electric & Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 3pp 18371 346 24X
Fiche 50-280, 83/05/04, 8305100108

--8305100111 Proposed revs to radiological effluent Tech Specs, in accordance w/Rev 3 to NUREG-0472
* Virginia Electric & Power Co 83/05/04 87pp 18371 349 24X
Fiche 50-280, 83/05/04, 8305100108

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120244 Forwards Rev 1 to "Reload Safety Evaluation for Surry 2 Cycle 7 (Pattern JB2) " Tech Specs approved through Amends 86 & 87, require no addl changes Reload core design will be verified
STEWART, W L Virginia Electric & Power Co 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 3pp 18424 183 24X
Fiche 50-281, 83/05/09, 8305120244

--8305120250 Rev 1 to "Reload Safety Evaluation for Surry 2 Cycle 7 (Pattern JB2) "
SMITH, N A , SUHAL, G M , CROSS, R W Virginia Electric & Power Co
282 R01 83/03/31 20pp 18424 186 24X Fiche 50-281, 83/05/09, 8305120244

8305180372 Forwards response to 830404 ltr re Category IV equipment Equipment qualification file packages submitted in support of specific identified items Response to 830126 ltr re proposed corrective actions expected by 830520
STEWART, W L Virginia Electric & Power Co 83/05/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 771pp 18483 120 24X
Fiche 50-280, 83/05/11, 8305180372

8305200163 Responds to 830126 & 0404 requests to review proprietary matl contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment Info no longer requires proprietary protection
STEWART, W L Virginia Electric & Power Co 83/05/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 18519 070 24X
Fiche 50-280, 83/05/11, 8305200163

8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
STEWART, W L Virginia Electric & Power Co 83/05/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 19pp 18513 182 24X Fiche 50-000, 83/03/12, 8305200499

8305260232 Submits schedule for replacement or mod of safety-related equipment for environ qualification per 10CFR50 49(g) criteria Master list of equipment encl
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 60pp 18622 127 24X
Fiche 50-280, 83/05/20, 8305260232

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270565 Forwards IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/29
STEWART, W L Virginia Electric & Power Co 2pp 18647 172 24X
Fiche 50-280, 83/03/29, 8305270565

--8305270574 IE Insp Repts 50-280/83-06 & 50-281/83-06 on 830222-25 No noncompliance noted Major areas inspected inservice testing of pumps & valves, secondary coolant chemisty program, inservice insp & LERs
GIRARD, E H , ROSS, W J , BLAKE, J J Region 2, Office of Director
83/03/25 9pp 18647 174 24X Fiche 50-280, 83/03/29, 8305270565

8305270483 Forwards IE Insp Repts 50-280/83-08 & 50-281/83-08 on 830201-28 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/04
STEWART, W L Virginia Electric & Power Co 2pp 18662 142 24X
Fiche 50-280, 83/04/04, 8305270483

--8305270490 IE Insp Repts 50-280/83-08 & 50-281/83-08 on 830201-28 No noncompliance noted Major areas inspected plant operations & operating records, plant maint & surveillance, plant security, followup of events & LERs
BURKE, D J , DAVIS, M J Region 2, Office of Director JULIAN, C A
Division of Project & Resident Programs 83/04/01 5pp
18662 144 24X Fiche 50-280, 83/04/04, 8305270483

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New
York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New
York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety
O'REILLY, J P Region 2, Office of Director 83/04/22 STEWART, W L
Virginia Electric & Power Co 2pp 18646 001 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270527 Forwards SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
LEWIS, R C Division of Project & Resident Programs 83/02/10
STEWART, W L Virginia Electric & Power Co 2pp 18646 003 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270541 SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
* Region 2, Office of Director 83/02/10 45pp 18646 005 24X
Fiche 50-000, 83/04/22, 8305270513

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New
York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305270423 Forwards IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/29
STEWART, W L Virginia Electric & Power Co 2pp 18644-287 24X
Fiche 50-280, 83/04/29, 8305270423

--8305270439 IE Insp Repts 50-280/83-11 & 50-281/83-11 on 830301-31 No noncompliance noted Major areas inspected plant operations & operating records, maint & surveillance, security event followup & LERs
BURKE, D J , DAVIS, M J Region 2, Office of Director JULIAN, C.
Division of Project & Resident Programs, 83/04/29 7pp
18644 289 24X Fiche 50-280, 83/04/29, 8305270423

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305060061 Advises that first 10-yr inservice insp program interval extended to 841108, per ASME Section XI 1974 Edition, Summer 1975 addenda
STEWART, W L Virginia Electric & Power Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director VARGA, S A
Operating Reactors Branch 1 1p 18345 051 24X
Fiche 50-281, 83/05/03, 8305060061

8305270242 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05
DANCE, H C Division of Project & Resident Programs 83/05/03
STEWART, W L Virginia Electric & Power Co 1p 18642 025. 24X
Fiche 50-280, 83/05/03, 8305270242

--8305270248 Responds to NRC 830311 ltr re violations noted in IE Insp Repts 50-280/83-05 & 50-281/83-05 Corrective actions Administrative Procedure ADM-8 reviewed w/staff assistant & notice of violation & response posted
STEWART, W L Virginia Electric & Power Co 83/04/08
O'REILLY, J P Region 2, Office of Director 2pp 18642 026 24X
Fiche 50-280, 83/05/03, 8305270242

--8305270252 Forwards IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/03/11
STEWART, W L Virginia Electric & Power Co 2pp 18642 028 24X
Fiche, 50-280, 83/05/03, 8305270242

--8305270257 Notice of violation from insp on 830207-11
* Region 2, Office of Director 83/03/11 1p 18642 030 24X
Fiche 50-280, 83/05/03, 8305270242

--8305270265 IE Insp Repts 50-280/83-05 & 50-281/83-05 on 830207-11 Noncompliance noted failure to post notice of violation & licensee response to IE Insp Repts 50-280/82-33 & 50-281/82-33 on 821221
HOSEY, C M , BARR, K P. Region 2, Office of Director 83/03/08
7pp 18642 031 24X Fiche 50-280, 83/05/03, 8305270242

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04. Consolidated Edison Co of New
York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation. " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033.

8305250541 Discusses IE insp on 830321-25 & forwards notice of violation & proposed imposition of civil penalty
O'REILLY, J P. Region 2, Office of Director 83/05/09 STEWART, W L.
Virginia Electric & Power Co 3pp 18595 344 24X
Fiche 50-280, 83/05/09, 8305250541

--8305250546 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted radiation program failed to meet 10CFR20 requirements & Tech Spec provisions in area of worker protection
O'REILLY, J P Region 1, Office of Director 83/05/09 5pp
18595 347 24X Fiche 50-280, 83/05/09, 8305250541

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co. of New
York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/19 Consolidated Edison Co of New
York, Inc 114pp 18697.009. 24X Fiche 50-000, 83/05/19, 8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305050118 Forwards LERs 83-015/03L-0 & 83-016/03L-0
WILSON, J L Virginia Electric & Power Co 83/04/27 O'REILLY, J P
Region 2, Office of Director 1p 18341 338 24X
Fiche 50-281, 83/04/27, 8305050118

--8305050121 LER 83-016/03L-0 on 830329, signal from B steam line pressure transmitter PT-2-485 increased approx 300 mv, rendering transmitter inoperable Cause not determined Basis adjusted & transmitter calibr & returned to svc
WILSON, J L Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 2pp 18341 339 24X Fiche 50-281, 83/04/27, 8305050118

--8305050130 LER 83-015/03L-0 on 830402, PT-27A revealed that amp readings for heat tracing Panel 10 circuit 1B & Panel 11 circuits 2A, 4A & 6B below acceptance criteria Caused by excessive heat Defective heat tracing replaced & design change initiated
WILSON, J L Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 2pp 18341 341 24X Fiche 50-281, 83/04/27, 8305050118

8305130125 Forwards LERs 83-017/03L-0 & 83-018/03L-0
WILSON, J L Virginia Electric & Power Co 83/05/06 O'REILLY, J P
Region 2, Office of Director 1p 18437 291 24X
Fiche 50-281, 83/05/06, 8305130125

--8305130130 LER 83-017/03L-0 on 830408, at 100% power, amp readings for heat tracing panels 8 & 9, circuit 20B discovered below acceptable limits Caused by excessive heat Defective heat tracing replaced Design changes implemented
WILSON, J L Virginia Electric & Power Co 83/05/06 Region 2, Office of Director 2pp 18437 292 24X Fiche 50-281, 83/05/06, 8305130125

--8305130136 LER 83-018/03L-0 on 830406, at 100% power, control rod B-6 dropped to fully inserted position causing quadrant power tilt or turbine runback Cause unknown Fuses & other components operable Control rod withdrawn
WILSON, J L Virginia Electric & Power Co 83/05/06 Region 2, Office of Director 2pp 18437 294 24X Fiche 50-281, 83/05/06, 8305130125

8305230424 Forwards LERs 83-019/03L-0 & updated 80-005/01X-1
WILSON, J L Virginia Electric & Power Co 83/05/13 O'REILLY, J P
Region 2, Office of Director 1p 18538 188 24X
Fiche: 50-281, 83/05/13, 8305230424

--8305230432 LER 83-019/03L-0 on 830415, MOV-LCV-2115D failed to open during performance of PT18 6 Caused by motor leads not making contact due to loose plug in terminal strip in motor control ctr, Terminal strip properly seated
WILSON, J L Virginia Electric & Power Co 83/05/13 Region 2, Office of Director 2pp 18538 189 24X Fiche 50-281, 83/05/13, 8305230424

--8305230451 Updated LER 80-005/01X-1 on 800306, Type A testing revealed leakage through recirculation spray diaphragm plate seal welds Caused by lack of fusion & slag inclusion in weld areas Defects repaired
WILSON, J L Virginia Electric & Power Co 83/05/13 Region 2, Office of Director 3pp 18538 191 24X Fiche 50-281, 83/05/13, 8305230424

DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8305030214 Releases public version of revised emergency plan implementing procedures
FELTON, J.M. Division of Rules and Records 83/04/22 Document Management Branch 1p 18310 155 24X Fiche 50-282, 83/04/22, 8305030214

--8305030221 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-2 re classification of emergencies, F3-5 re emergency notification & F3-9 re emergency evacuation.
WARD, E C Northern States Power Co 83/04/08 Region 3, Office of Director 1p 18310 156 24X Fiche 50-282, 83/04/22, 8305030214.

--8305030226 Public version of revised emergency plan implementing procedures, including Procedure F3-2 re classification of emergencies, F3-5 re emergency notification & F3-9 re emergency evacuation
SCHULLKE, D A Northern States Power Co 83/03/22 129pp 18310 157 24X Fiche 50-282, 83/04/22, 8305030214

8305170657 Forwards exemption from 10CFR50, App R, Subsection III G 2 re separation, fire barrier & suppression requirements where both trains of redundant safe shutdown components located within same fire area, per 820630 & 1022 requests
CLARK, R A Operating Reactors Branch 3 83/05/04 MUSOLF, D M
Northern States Power Co 4pp 18481 072 24X
Fiche 50-282, 83/05/04, 8305170657

--8305170666 Exemption from 10CFR50, App R, Subsection III G 2 re separation, fire barrier & suppression requirements where both trains of redundant safe shutdown components located within same fire area
EISENHUT, D G Division of Licensing 83/05/04 Northern States Power Co 7pp 18481 076 24X Fiche 50-282, 83/05/04, 8305170657

--8305170683 Safety evaluation re exemptions from 10CFR50, App R, Section III G 2 requirement for maint of one train of equipment necessary for safe shutdown, w/o fire damage Exemptions should be denied in four areas & granted in five areas
* Office of Nuclear Reactor Regulation, Director 82/10/27
21pp 18481 083 24X Fiche 50-282, 83/05/04, 8305170657

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305190343 Forwards Rev 1 to NUREG-0728, "NRC Incident Response Plan," in response to 830429 ltr requesting updated ltr of agreement W/o encl
HIND, J A Division of Radiological & Materials Safety Programs
83/05/13 LARSON, C E Northern States Power Co 2pp 18500 225
24X Fiche 50-000, 83/05/13, 8305190343

8305200023 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/13 MUSOLF, D M
Northern States Power Co 3pp 18540 117 24X
Fiche 50-282, 83/05/13, 8305200023

8305230523 Forwards clarifying info in support of 830311 exemption requests for 10CFR50 4B, App R re Fire Areas 58, 59, 73 & 74
MUSOLF, D Northern States Power Co 83/05/16 Office of Nuclear Reactor Regulation, Director 62pp 18536 329 24X
Fiche 50-282, 83/05/16, 8305230523

8305240389 Advises that date for next annual emergency preparedness exercise revised to 840313, per 830128 telcon
PAPERIELLO, C. J Region 3, Office of Director 83/05/19
LARSON, C E Northern States Power Co 1p 18575 069 24X
Fiche 50-282, 83/05/19, 8305240389

P Operating license stage documents & correspondence

8303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1,539 MWE (summer) net
HADLEY, C D Northern States Power Co 83/03/15 TOURTELLOTTE, J
Regulatory Reform Task Force 6pp 18541 041 24X
Fiche 50-000, 83/03/15, 8303180429

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305020320 Forwards Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements," per 780201 submittal
MUSOLF, D Northern States Power Co 83/04/19 Office of Nuclear Reactor Regulation, Director 2pp 18277 146 24X
Fiche 50-282, 83/04/19, 8305020320

--8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
* Northern States Power Co 83/04/19 21pp 18277 148 24X
Fiche, 50-282, 83/04/19, 8305020320

8305060013 Advises that action required by 830202 Amends 61 & 55 to Licenses DPR-42 & DPR-60, respectively & Generic Ltr 83-07 completed, based on util actively negotiating w/DOE re disposal of high level waste or spent nuclear fuel
CLARK, R A Operating Reactors Branch 3 83/04/21 MUSOLF, D M Northern States Power Co 2pp 18354 311 24X
Fiche 50-282, 83/04/21, 8305060013

8305060108 Advises that requirements of NUREG-0737, TMI Action Plan Items II F 1 4, II F 1 5 & II F 1 6 met & items resolved Criteria requiring equipment to be environmentally qualified will be reviewed under environ qualification program
CLARK, R A Operating Reactors Branch 3 83/04/21 MUSOLF, D M Northern States Power Co 9pp 18354 268 24X
Fiche 50-282, 83/04/21, 8305060108

8305060023 Forwards safety evaluation & technical evaluation rept for environ qualification of safety-related electrical equipment Justification for continued operation & schedule for proposed corrective action requested by 830520
CLARK, R A Operating Reactors Branch 3 83/04/25 MUSOLF, D M Northern States Power Co 3pp 18354 322 24X
Fiche 50-282, 83/04/25, 8305060023

--8305060036 Safety evaluation re environ qualification of safety-related electric equipment Major qualification deficiencies identified in Franklin Research Ctr technical evaluation rept Tables 4-1, 4-2, 4-3 & 4-4 must be resolved
* Office of Nuclear Reactor Regulation, Director 83/04/25 7pp 18354 325 24X Fiche 50-282, 83/04/25, 8305060023

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305120389 Forwards response to NRC 830425 ltr transmitting safety evaluation for environ qualification of safety-related electrical equipment Rosemount 1153 Series A transmitters should be reclassified as Category II C equipment items
MUSOLF, D Northern States Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 29pp 18433 124 24X
Fiche 50-282, 83/05/05, 8305120389

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305020320 Forwards Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements," per 780201 submittal
MUSOLF, D Northern States Power Co 83/04/19 Office of Nuclear Reactor Regulation, Director 2pp 18277 146 24X
Fiche 50-282, 83/04/19, 8305020320

--8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
* Northern States Power Co 83/04/19 21pp 18277 148 24X
Fiche 50-282, 83/04/19, 8305020320

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305240029 Forwards IE Insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No noncompliance noted
SHAFER, W D Region 3, Office of Director 83/05/06 LARSON, C E Northern States Power Co 2pp 18549 095 24X
Fiche 50-282, 83/05/06, 8305240029

--8305240061 IE Insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No noncompliance noted Major areas inspected plant operational safety, maint, surveillance, review of operating events, LERs, fire penetration seals & IE bulletins
FEIERABEND, C D , WILLIAMS, D L , JACKIW, I N Region 3, Office of Director 83/05/05 18pp 18549 097 24X Fiche 50-282, 83/05/06, 8305240029

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305160056 Forwards monthly operating repts for Apr 1983
MUSOLF, D Northern States Power Co 83/05/11 Office of Resource Management, Director 1p 18451 036 24X Fiche 50-282, 83/05/11, 8305160056.

--8305160076 Monthly operating repts for Apr 1983
DUGSTAD, D Northern States Power Co 83/05/04 8pp 18451 037 24X Fiche 50-282, 83/05/11, 8305160056

S Reportable occurrences, LERs & related correspondence

8305240166 LER 83-010/03L-0 on 830417, reactor coolant sample found missing after load changing operations for turbine testing Sample taken 2 h late Caused by lack of communication Load changing procedure will be revised W/830516 ltr
HUNSTAD, A A , MUSOLF, D Northern States Power Co 83/05/16 Region 3, Office of Director 2pp 18549 237 24X
Fiche 50-282, 83/05/16, 8305240166

DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305100226 Revised pages to radiological emergency response plan
* Omaha Public Power District 83/03/18 180pp 18372 324 24X
Fiche 50-285,83/03/18,8305100226

8305040614 Releases public version of updated radiological emergency response plan
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18335 276 24X Fiche 50-285,83/04/25, 8305040614

--8305040619 Forwards public version of updated radiological emergency response plan Receipt form encl
JONES,W C Omaha Public Power District 83/03/24 Region 4, Office of Director 1p 18335 277 24X Fiche 50-285,83/04/25, 8305040614

--8305040624 Public version of updated radiological emergency response plan
* Omaha Public Power District 83/03/04 162pp 18335 278 24X
Fiche 50-285,83/04/25,8305040614

8305030425 Responds to 830318 ltr requesting reaffirmation of 810610 ltr re role of NRC in radiological emergency response While ltr reflects current policy,ltr of agreement not intended
SEIDLE W C Region 4, Office of Director 83/04/29 FRANCO,F F Omaha Public Power District 2pp 18306 250 24X
Fiche 50-285,83/04/29,8305030425

--8305030429 Requests reaffirmation of NRC 810610 ltr of agreement re role of NRC in radiological emergency response
JONES,W C Omaha Public Power District 83/03/18 COLLINS,J T Region 4, Office of Director 2pp 18306 252 24X
Fiche 50-285,83/04/29,8305030425

--8305030435 Responds to 810601 ltr discussing role of NRC during radiation emergency Primary role is to monitor licensee activities associated w/incident & to provide technical assistance,if requested
COLLINS,J T Region 4, Office of Director 81/06/10 JONES,W C Omaha Public Power District 1p 18306 254 24X
Fiche 50-285,83/04/29,8305030425

8305120594 Releases public version of revised radiological emergency response plan
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p, 18441 339 24X Fiche 50-285,83/05/02, 8305120594

--8305120603 Forwards public version of revised radiological emergency response plan W/o encl
JONES,W C Omaha Public Power District 83/03/24 COLLINS,J T Region 4, Office of Director 1p 18441 340 24X
Fiche 50-285,83/05/02,8305120594

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305200060 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1 Item closed
CLARK,R A Operating Reactors Branch 3 83/05/11 JONES,W C Omaha Public Power District 3pp 18540,123 24X
Fiche,50-285,83/05/11,8305200060

I. Financial information

8305060069 Forwards Annual Financial Rept 1982
JONES,W C Omaha Public Power District 83/04/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18345 027 24X
Fiche 50-285,83/04/29,8305060069

--8305060091 Annual Financial Rept 1982
SPENCE,G P Omaha Public Power District 83/04/29 24pp 18345 028. 24X Fiche 50-285,83/04/29,8305060069

P Operating license stage documents & correspondence

8305230588 Forwards backfitting & regulatory impact cost data for hardware & nonhardware-related backfits Requirement for adding one addl senior reactor operator to each operating shift will cost $600,000 per yr
REZNICEK,G W Omaha Public Power District 83/03/04 TOURTELLOTTE,J Regulatory Reform Task Force 16pp 18541 322 24X Fiche 50-285,83/03/04 8305230588

8305160027 Ack receipt of Commission 830404 ltr clarifying SER on environ qualification of safety-related electrical equipment in harsh environ Justification for continued operation of valve positioner,cable & motor brake encl
JONES,W C Omaha Public Power District 83/04/11 CLARK,R A Operating Reactors Branch 3 10pp 18452 359 24X
Fiche 50-285,83/04/11,8305160027

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305030156 Revised amend application re heatup & cooldown curves Amend revises 830304 amend application
JONES,W C Omaha Public Power District 83/04/28 CLARK,R A Operating Reactors Branch 3 1p 18399 101 24X
Fiche 50-285,83/04/28,8305030156

--8305030160 Revised Tech Specs for 830304 amend application,changing heatup & cooldown curves
* Omaha Public Power District 83/04/28 17pp 18300 194 24X
Fiche 50-285,83/04/28,8305030156

8305060186 Forwards response to 830311 ltr requesting addl info re proposed spent fuel storage rack mod New analysis indicates spent fuel can be adequately cooled even w/4 h loss of spent fuel pool cooling
JONES,W C Omaha Public Power District 83/04/29 CLARK,R A Operating Reactors Branch 3 40pp 18344 152 24X
Fiche 50-285,83/04/29,8305060186

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305310240 Requests addl info for control of heavy loads review, including info open items for updated "Control of Heavy Loads "
CLARK,R A Operating Reactors Branch 3 83/05/17 JONES,W C Omaha Public Power District 2pp 18662 180 24X
Fiche 50-285,83/05/17,8305310240

--8305310241 "Control of Heavy Loads (C-10),Omaha Public Power District, Fort Calhoun Station," updated draft technical evaluation rept
VOSBURY,F , BOMBERGER,C , SARGENT,I H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-356 DRFT 82/11/29
CLEMENSON,F NRC - No Detailed Affiliation Given 52pp 18662 182 24X Fiche 50-285,83/05/17,8305310240

8305240474 Provides 90-day response to SER & addl info per 10CFR50 49(g) & 830404 clarification ltr Position on outstanding items in technical evaluation rept & description of methods used to identify equipment discussed
JONES,W C Omaha Public Power District 83/05/20 CLARK,R A Operating Reactors Branch 3 36pp 18549 296 24X
Fiche 50-285,83/05/20,8305240474

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305100241 Forwards IE Insp Rept 50-285/83-09 during Mar 1983 & notice of violation
SEIDLE,W C Region 4, Office of Director 83/04/22 JONES,W C
Omaha Public Power District 2pp 18374 108 24X
Fiche 50-285,83/04/22,8305100241

--8305100242 Notice of violation from insp during Mar 1983
* Region 4, Office of Director 83/04/22 1p 18374 110 24X
Fiche 50-285,83/04/22,8305100241

--8305100244 IE Insp Rept 50-285/83-09 during Mar 1983 Noncompliance noted failure to document performance steps added by Procedure Change 10222 to Section F 3 (Pumps SI-1A & SI-1B) of Surveillance Test ST-SI/CS-1
YANDELL,L A , JOHNSON,W D Region 4, Office of Director
83/04/21 11pp 18374 111 24X Fiche 50-285,83/04/22,8305100241

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 119pp, 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305230464 Forwards IE Insp Rept 50-285/83-08 on 830404-08 & notice of deviation
SEIDLE,W C Region 4, Office of Director 83/05/06 JONES,W C
Omaha Public Power District 2pp 18537 151 24X
Fiche 50-285,83/05/06,8305230464

--8305230467 Notice of deviation from insp on 830404-08
* Region 4, Office of Director 83/05/06 2pp 18537 153 24X
Fiche 50-285,83/05/06,8305230464.

--8305230475 IE Insp Rept 50-285/83-08 on 830404-08 Noncompliance noted documentation for continuing training of QA personnel not established & maintained & procedures requirement to meet audit finding 30-day response time not met
MURPHY,M E , MCCRORY,S L , WESTERMAN,T Region 4, Office of Director, 83/05/02 9pp 18537 155 24X Fiche 50-285,83/05/06, 8305230464

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240173 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-02 Corrective actions will be reviewed during future insp
SEIDLE,W C Region 4, Office of Director 83/05/20 JONES,W C
Omaha Public Power District 1p 18548 037 24X
Fiche 50-285,83/05/20,8305240173

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007. 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305160111 Forwards "Reactor Containment Bldg Integrated Leak Rate Test, Jan 1983 "
JONES,W C Omaha Public Power District 83/05/11 DENTON,H R.
Office of Nuclear Reactor Regulation, Director 1p 18450 161 24X
Fiche 50-285,83/05/11,8305160111

--8305160116 "Reactor Containment Bldg Integrated Leak Rate Test, Jan 1983 "
* Omaha Public Power District 83/05/11 44pp 18450 162 24X
Fiche 50-285,83/05/11,8305160111

8305170465 Forwards monthly operating rept for Apr 1983
JONES,W C Omaha Public Power District 83/05/12 DEYDUNG,R C
Director's Office, Office of Inspection and Enforcement 1p
18470 112 24X Fiche 50-285,83/05/12,8305170465

--8305170470 Monthly operating rept for Apr 1983
MATHEWS,T P Omaha Public Power District 83/05/12 11pp
18470 113 24X Fiche 50-285,83/05/12,8305170465

DOCKET 50-286 INDIAN POINT STATION, UNIT 3

D NRC Draft/Final Environmental Statements, suppls & correspondence

8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination
FARRELLY,T.J Consolidated Edison Co of New York, Inc 83/04/28
LEWIS,D Atomic Safety and Licensing Board Panel 24pp 18300 315
24X Fiche 50-247,83/04/28,8305030531

F Security, medical, emergency & fire protection plans

8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions NUREG-0654-FEMA-REP-1, Rev 1 stds would place heavy resource burden on state
GIUFFRIDA,L D Federal Emergency Management Agency 83/04/18
PALLADINO,N J Commissioners 1p 18542 329 24X
Fiche 50-003,83/04/18,8305230670

--8305230676 Seeks clarification of issue re FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan
PALLADINO,N J Commissioners 83/03/30 GIUFFRIDA,L D Federal Emergency Management Agency 2pp 18542 330 24X
Fiche 50-003,83/04/18,8305230670

8305050073 Informs that licensee 830216 commitment re interim fire protection mods generally acceptable Present Tech Specs should be revised to comply w/interim mods Sample Tech Specs encl
VARGA,S A Operating Reactors Branch 1 83/04/21 BAYNE,J P.
Power Authority of the State of New York 3pp 18352 014. 24X
Fiche:50-286,83/04/21,8305050073

--8305050076 Sample Tech Specs re interim fire protection mods concerning alternate shutdown sys
* Operating Reactors Branch 1 83/04/21 1pp 18352.017 24X
Fiche 50-286,83/04/21,8305050073

8305110538 Forwards safety evaluation of util compliance w/10CFR50, App R, Sections III G 3 & IIII L Long-term compliance acceptable except for three items Spurious operation can be corrected by closing valves Response needed in 30 days
VARGA, S A Operating Reactors Branch 1 83/04/21 BAYNE, J P Power Authority of the State of New York 3pp 18419 286 24X Fiche 50-286, 83/04/21, 8305110538

--8305110543 Safety evaluation of util compliance w/10CFR50, App R Proposed alternate shutdown capability performance goals of reactivity, inventory, DHR reactor pressure & process control met, subj to listed exceptions
* Office of Nuclear Reactor Regulation, Director 83/04/21 17pp 18419 289 24X Fiche 50-286, 83/04/21, 8305110538

--8305110546 "Process Monitoring Instrumentation "
* NRC - No Detailed Affiliation Given 83/04/21 3pp 18419 306 24X Fiche 50-286, 83/04/21, 8305110538

8305030284 Notification of 830429 meeting util in Bethesda, MD to discuss steam generator chemistry & fire protection interim measures
POLK, P J Operating Reactors Branch 1 83/04/22 VARGA, S A Operating Reactors Branch 1 4pp 18309 330 24X Fiche 50-286, 83/04/22, 8305030284

8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning, for info Certificate of Svc encl Related correspondence
GLASS, S M Federal Emergency Management Agency 83/04/25 GLEASON, J P Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247, 83/04/25, 8305020419

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305160088 Advises that no basis exists to further delay facility startup per 821018 amend application re steam generator tube sleeving & 830503 order concerning emergency preparedness
SINCLAIR, L W Power Authority of the State of New York 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18450 357 24X Fiche 50-286, 83/05/12, 8305160088

8305240099 Submits current status of App R fire protection activities per 830518 request Installation of equipment committed to in 830216 ltr completed, 820701 proposed design installed & addl Tech Specs for equipment mods will be submitted
BAYNE, J P Power Authority of the State of New York 83/05/19 VARGA, S A Operating Reactors Branch 1 2pp 18548 341 24X Fiche 50-286, 83/05/19, 8305240099

8305240234 Documents NRC/util telcon re seismic qualification documentation for auxiliary feedwater sys & proposed fire protection Tech Specs Tech Specs on quarterly surveillance of alternate electrical feed sys to be submitted
BAYNE, J P Power Authority of the State of New York 83/05/20 VARGA, S A Operating Reactors Branch 1 2pp 18548 309 24X Fiche 50-286, 83/05/20, 8305240234

8305240312 Informs of full cooperation between licensee & local govt in development & exercise of emergency radiological response plan, contrary to Commissioner Ahearne 830506 statement
HEIMBACH, L New York, State of 83/05/20 PALLADINO, N Commissioners 1p 18548 184 24X Fiche 50-247, 83/05/20, 8305240312

8305240338 Forwards response to 830421 ltr re App R fire protection review, Section III G 3 & III L Exemption from schedular requirements for Sections 50 48(c) & (d) for mods prior to startup from Cycle 4/5 refueling outage requested
BAYNE, J P Power Authority of the State of New York 83/05/20 VARGA, S A Operating Reactors Branch 1 4pp 18575 258 24X Fiche 50-286, 83/05/20, 8305240338

8305310049 Responds to 830523 ltr outlining specific proposals for ameliorating facility offsite preparedness situation & views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness
GIUFFRIDA, L O Federal Emergency Management Agency 83/05/25 CUOMO, M N New York, State of 4pp 18633 284 24X Fiche 50-247, 83/05/25, 8305310049

G Adjudicatory correspondence

8305030583 Forwards summary of training activities re offsite response organizations that might be called upon to respond to onsite emergencies, per ASLB 830225 oral request Util training detailed in 830405 submittal Related correspondence
BRANDENBURG, B Office of the General Counsel 83/04/29 LEWIS, D Atomic Safety and Licensing Board Panel 7pp 18303 355 24X Fiche 50-247, 83/04/29, 8305030583

8305030608 Motion for permission to present rebuttal witnesses on subj of prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence
POTTERFIELD, A Union of Concerned Scientists POTTERFIELD, A Public Interest Research Group, New York KAPLAN, C New York, NY 83/04/19 4pp 18308 050 24X Fiche 50-247, 83/04/19, 8305030608

--8305030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site & difficulty of evacuation in emergency
POTTERFIELD, A Public Interest Research Group, New York POTTERFIELD, A Union of Concerned Scientists 83/04/26 Atomic Safety and Licensing Board Panel 8pp 18308 139 24X Fiche 50-247, 83/04/19, 8305030608

--8305030646 Affidavit of KT Erickson & AJ Solnit re radiological emergency response plan
ERICKSON, K T Public Interest Research Group, New York ERICKSON, K T Union of Concerned Scientists ERICKSON, K T Yale Univ, New Haven, CT 83/04/26 4pp 18308 148 24X Fiche 50-247, 83/04/19, 8305030608

--8305030652 Motion requesting completeness of record on NRC Questions 3 & 4 re emergency planning issues, including capability for handling phone calls in emergency planning zone during emergency
POTTERFIELD, A, POTTERFIELD, A Union of Concerned Scientists 83/04/25 Atomic Safety and Licensing Board Panel 4pp 18308 180 24X Fiche 50-247, 83/04/19, 8305030608

8305020428 Motion to strike portions of 830309 emergency drill testimony under Commission Questions 3 & 4 filed by witnesses for various intervenors Certificate of Svc encl Related correspondence
BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/04/22 Atomic Safety and Licensing Board Panel 22pp 18273 075 24X Fiche 50-247, 83/04/22, 8305020428

8305020419 Forwards "Indian Point Plans Verification Analysis" re emergency planning, for info Certificate of Svc encl Related correspondence
GLASS, S M Federal Emergency Management Agency 83/04/25 GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 62pp 18273 128 24X Fiche 50-247, 83/04/25, 8305020419

8305030549 Motion for subpoena to be issued to RW Krimm of FEMA Subpoena necessary to complete record on generic nature of deficiencies cited by FEMA & FEMA change in evaluation criteria Certificate of Svc encl
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/04/26 Atomic Safety and Licensing Board Panel 40pp 18306 147 24X Fiche 50-247, 83/04/26, 8305030549

8305020401 Motion to amend svc list to add SP Wasserman & delete P Chessin, LR Schwartz & M Oppel Notice of appearance & Certificate of Svc encl
WASSERMAN, S P Metropolitan Transportation Authority New York, NY WASSERMAN, S P Botein, Hays, Sklar & Herzberg 83/04/27 Atomic Safety and Licensing Board Panel 6pp 18273 067 24X Fiche 50-247, 83/04/27, 8305020401

8305020451 Submits info on status of Ray Miller, Inc problems affecting plant, per ASLB request
MOORE, J E Hearing Branch 1 83/04/28 GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 88pp 18283 180 24X Fiche 50-247, 83/04/28, 8305020451

8305030531 Forwards documents presented to NRC witnesses Bellups & Kornegay during 830422 cross-examination
FARRELLY, T J Consolidated Edison Co of New York, Inc 83/04/28 LEWIS, D Atomic Safety and Licensing Board Panel 24pp 18300 315 24X Fiche 50-247, 83/04/28, 8305030531

8305040505 Forwards util onsite emergency plans per ASLB request that documents be mailed rather than delivered
BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/04/28 GLEASON, J P, SHON, F J, PARIS, D H Atomic Safety and Licensing Board Panel 1p 18322 110 24X Fiche 50-247, 83/04/28, 8305040505

8305040464 Requests official position re long-term operation of facilities
GLEASON, J P , PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel 83/05/02 CUOMO, M M New York, State of 2pp
18321 295 24X Fiche 50-247, 83/05/02, 8305040464

8305050035 Proposes alternative views to questions posed in SJ Chilk 830426 ltr to FEMA re emergency planning & evacuation
FLEISHER, Z S West Branch Conservation Association 83/05/02
PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 3pp
18342 096 24X Fiche 50-247, 83/05/02, 8305050035

8305160304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc
MILES, E B Administrative Contracts Branch FIN B-8855 83/05/02
BASSETT, H S Office of Resource Management, Director FITTI, C
Atomic Safety and Licensing Board Panel 1p 18471 247 24X
Fiche 50-247, 83/05/02 8305160304

--8305160312 Contract "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc
* Central Data Processing, Inc MATTIA, M J Division of Contracts FIN B-8855 83/05/02 2pp 18471 248 24X
Fiche 50-247, 83/05/02, 8305160304

--8305160316 Solicitation, offer & award to "Conversion of Prefiled Testimony for Indian Point Hearings," to Central Data Processing, Inc
COUCH, M J Central Data Processing, Inc MATTIA, M J
Administrative Contracts Branch FIN B-8855 83/04/26 56pp
18471 250 24X Fiche 50-247, 83/05/02, 8305160304

8305060500 Expresses concern that FEMA 830415 post-exercise assessment of 830309 emergency planning exercise presents incomplete picture of present status of offsite radiological emergency planning Certificate of Svc encl
DAYNE, J P Power Authority of the State of New York 83/05/03
PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 17pp
18348 112 24X Fiche 50-286, 83/05/03, 8305060500

8305050037 Forwards NY State Disaster Preparedness Commission 830504 memo re State of NY commitment to continue work to ensure residents protected by best practicable emergency preparedness plan
DAYNE, J P Power Authority of the State of New York 83/05/04
PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 3pp
18339 105 24X Fiche 50-247, 83/05/04, 8305050037

8305060496 Forwards NY State Disaster Preparedness Commission 830504 ltr providing State of NY commitment to ensure residents protected by best practicable emergency preparedness plan
DAYNE, J P Power Authority of the State of New York 83/05/04
PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 3pp
18348 105 24X Fiche 50-247, 83/05/04, 8305060496

8305060506 Responds to 830426 ltr re Westchester County, NY bus driver issue, Rockland County, NY plan issue 5 questions raised re FEMA briefing & status rept on offsite emergency preparedness
KRIMM, R W Federal Emergency Management Agency 83/05/04
CHILK, S J Office of the Secretary of the Commission 16pp
18348 331 24X Fiche 50-247, 83/05/04, 8305060506

--8305060627 Responds to request for clarification of issue on whether state emergency plan can substitute for county which does not have emergency plan State can substitute plan but NUREG-0654 places heavy resource burden on state
GIUFFRIDA, L O Federal Emergency Management Agency 83/04/15
PALLADINO, N J Commissioners 2pp 18348 347 24X
Fiche 50-247, 83/05/04, 8305060506

8305060468 Order CLI-83-11 advising that Commission will issue order by 830609 suspending plant operation unless FEMA determines significant deficiencies no longer exist or util shows compensating actions taken or deficiencies insignificant
HOYLE, J Office of the Secretary of the Commission 83/05/05 5pp
18348 075 24X Fiche 50-247, 83/05/05, 8305060468

8305090458 Memo providing citations to decisions referred to in hearing re commitments from bus drivers needed in emergency evacuation plans
PARIS, D H Atomic Safety and Licensing Board Panel 83/05/05 2pp
18362 259 24X Fiche 50-247, 83/05/05, 8305090458

8305100208 Motion for extension of deadline until 830627 for all parties to submit proposed opinion, findings of fact & recommendations re enforcement action on emergency planning issues Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan Associates 83/05/06 PALLADINO, N J , GILINSKY, V , AHEARNE, J F,
Commissioners 9pp 18374 014 24X Fiche 50-247, 83/05/06,
8305100208

8305100204 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11, establishing procedures for decision on enforcement action on emergency planning issues Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/05/09 Commissioners 6pp 18374 193 24X
Fiche 50-247, 83/05/09, 8305100204

8305130064 Motion for reconsideration of ruling denying licensee motion to receive DP McGuire deposition transcript into evidence Licensees entitled to place deposition in record Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan Associates 83/05/09 Atomic Safety and Licensing Board Panel
15pp 18436 230 24X Fiche 50-247, 83/05/09, 8305130064

8305120309 Order authorizing ASLB to grant relief from 830527 deadline for filing proposed findings of fact & conclusions of law since oral presentations before Commission to take place on 830526
CHILK, S J Office of the Secretary of the Commission 83/05/10
Atomic Safety and Licensing Board Panel 2pp 18424 100 24X
Fiche 50-247, 83/05/10, 8305120309

8305160024 Forwards I Levi affidavit clarifying 830211 testimony on suggested method of making sensible probability judgments described in Section 5
HARTZMAN, R M Friends of the Earth HARTZMAN, R M Audubon Society
83/05/10 GLEASON, J P , PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel 1p 18452 353 24X Fiche 50-247, 83/05/10,
8305160024

--8305160028 Affidavit of I Levi clarifying 830211 testimony re suggested method of making sensible probability judgments described in Section 5
LEVI, I Friends of the Earth LEVI, I Audubon Society
83/05/10 2pp 18452 354 24X Fiche 50-247, 83/05/10, 8305160024

8305130030 Memorandum & order granting licensee 830506 motion for extension until 830627 to file proposed findings of fact & recommendations Date extended until 830829 for ASLB to submit recommendations to Commission
PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel
83/05/11 Consolidated Edison Co of New York, Inc 2pp
18437 102 24X Fiche 50-247, 83/05/11, 8305130030

8305130071 Motion for extension of deadline (to 830615) for filing corrections to transcripts & deadline (to 830624) for filing comments Certificate of Svc encl
BRANDENBURG, B Consolidated Edison Co of New York, Inc MORGAN, C
Power Authority of the State of New York MORGAN, C Morgan Associates 83/05/11 Atomic Safety and Licensing Board Panel
7pp 18437 045 24X Fiche 50-247, 83/05/11, 8305130071

8305190342 Supports immediate plant shutdown Emergency response plan represents theory & not practicality
GALEF, S R Westchester County, NY 83/05/11 PALLADINO, N J
Commissioners 6pp 18500 227 24X Fiche 50-247, 83/05/11,
8305190342

8305160133 Telecopy order granting licensee 830511 motion for extension of date to file motions to correct transcript Motions due on 830615
GLEASON, J P Atomic Safety and Licensing Board Panel 83/05/13
Consolidated Edison Co of New York, Inc 4pp 18446 116 24X
Fiche 50-247, 83/05/13, 8305160133

8305160167 Order clarifying Commission 830505 order Comments from parties & general public, relevant to enforcement action, will be considered Public comments to be filed by 830523 Oral presentations limited to licensees & interested govts
CHILK, S J Office of the Secretary of the Commission 83/05/13
Commissioners 4pp 18445 152 24X Fiche 50-247, 83/05/13,
8305160167

8305190220 Motion for opportunity to address issues outlined in Commission 830505 Order CLI-83-11 establishing procedures for decision on enforcement action Intervenor entitled to participate as matter of right Certificate of Svc encl
RODRIGUEZ, P Parents Concerned About Indian Point 83/05/13
Commissioners 3pp 18502 143 24X Fiche 50-247, 83/05/13,
8305190220

8305200645 Advises that day of reckoning re evacuation plan issue coming on 830609 Interim compensating actions by FEMA cannot compensate for unchangeable factors of problem roads & population density
TOSCANI, S Affiliation Unknown 83/05/15 Commissioners 3pp
18520 122 24X Fiche 50-247, 83/05/15, 8305200645

8305180143 Order providing time (until 830610) to parties to respond to P Amico, ASLB consultant, 830502 ltr summarizing conclusions based on review of testimony & hearing transcripts re Commission Question 1
GLEASON, J P Atomic Safety and Licensing Board Panel 83/05/16 Office of the Executive Legal Director 1p 18490 022 24X Fiche 50-247, 83/05/16, 8305180143

--8305180146 Summarizes rept on review of testimony & hearing transcripts re Commission Question 1 Addl testimony recommended on current analytical methods for risk assessment & on issues not dealt w/in probabilistic safety study or NRC analysis
AMICO, P J Applied Risk Technology Corp AMICO, P J Atomic Safety and Licensing Board Panel 83/05/02 GLEASON, J P, SHON, F J, PARIS, O H Atomic Safety and Licensing Board Panel 4pp 18490 023 24X Fiche 50-247, 83/05/16, 8305180143

8305180424 Requests time to address Commission on 830526 re Commission 830513 order
GDANSKI, S Rockland County, NY 83/05/16 CHILK Commissioners 1p 18485 302 24X Fiche 50-247, 83/05/16, 8305180424

8305200605 Requests time to speak on 830526 State of NY claims unsubstantiated NRC should adopt policy of communicating w/public
FLEISHER, Z S West Branch Conservation Association 83/05/16 PALLADINO, N J, GILINSKY, V, AHEARNE, J Commissioners 12pp 18514 090 24X Fiche 50-247, 83/05/16, 8305200605

8305240535 Citizens advisory committee progress repts re nuclear evacuation & general disaster preparedness plan
* Rockland County, NY 83/05/16 34pp 18576 053 24X Fiche 50-247, 83/05/16, 8305240535

8305240508 Forwards Ossining Town Board resolution expressing concerns re emergency plans Deficiencies must be corrected before plan approved
WISHNIE, R G Ossining, NY 83/05/19 Office of the Secretary of the Commission 4pp 18571 260 24X Fiche 50-247, 83/05/19, 8305240508

8305240530 Expresses concerns re adequacy & workability of evacuation plans
BOGARDUS, R H Affiliation Unknown 83/05/19 NRC - No Detailed Affiliation Given 2pp 18571 236 24X Fiche 50-247, 83/05/19, 8305240530

8305240546 Forwards citizen & group statements expressing concern re plant safety & flawed evacuation plan, in response to Commission Order CLI-83-11
ELLIOTT, N R Yorktown, NY 83/05/19 NRC - No Detailed Affiliation Given 10pp 18575 266 24X Fiche 50-247, 83/05/19, 8305240546

8305240547 Forwards board of trustees of Village of Buchanan statement that plants are safe & provide clean energy
PIERCE, F W Buchanan, NY 83/05/19 PALLADINO, N J Commissioners 2pp 18575 281 24X Fiche 50-247, 83/05/19, 8305240547

8305270583 Requests concrete actions re emergency evacuation plan in light of FEMA stated deficiencies, in response to Commission 830505 Order CLI-83-11
ELLIOTT, N R Yorktown, NY 83/05/19 Commissioners 1p 18646 343 24X Fiche 50-247, 83/05/19, 8305270583

8305240454 Motion for leave to submit written comments on NRC 830505 order to suspend facility operations Deficiencies determined to be significant by FEMA are not sufficiently deficient to require suspending operations
JOY, J, HICKS, M M, GALLAGHER, P J Utility Workers Union of America 83/05/20 Commissioners 8pp 18573 164 24X Fiche 50-247, 83/05/20, 8305240454

8305240466 Response to Commission 830505 order establishing procedures for decision on enforcement action Emergency planning deficiencies not significant NRC enforcement action unwarranted & improper W/Certificate of Svc
MORGAN, C Power Authority of the State of New York MORGAN, C Morgan Associates 83/05/20 43pp 18573 181 24X Fiche 50-247, 83/05/20, 8305240466

8305240527 Views re radiological emergency planning in response to Commission 830505 order, FEMA & NRC should rule that plants no longer have significant deficiencies based on improvement & interim compensating actions
BLOCK, J D, BRANDENBURG, B Consolidated Edison Co of New York, Inc 83/05/20 41pp 18571 132 24X Fiche 50-247, 83/05/20, 8305240527

8305240535 Opinion on NRC 830505 order re FEMA rept on licensee emergency planning & preparedness & possible suspension of plant operations Immediate shutdown urged
KAPLAN, C New York NY KAPLAN, C National Emergency Civil Liberties Committee 83/05/20 18pp 18571 218 24X Fiche 50-247 83/05/20, 8305240535

8305250337 Submission re Commission 830505 order on intention to shut down facility on 830609 if emergency preparedness problems not resolved Adequate protective action in case of radiological emergency cannot be guaranteed by 830609
GOLDBERG, M L Public Interest Research Group, New York 83/05/21 17pp 18585 302 24X Fiche 50-247, 83/05/21, 8305250337

8305240523 Order providing guidance for 830526 oral presentations to Commission re possible plant shutdown
CHILK, S J Office of the Secretary of the Commission 83/05/23 4pp 18571 119 24X Fiche 50-247, 83/05/23, 8305240523

8305240538 Forwards comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action
WEISS, E R Harmon & Weiss WEISS, E R Union of Concerned Scientists 83/05/23 PALLADINO, N J, AHEARNE, J F, ASSELSTINE, J K Commissioners 1p 18576 093 24X Fiche 50-247, 83/05/23, 8305240538

--8305240542 Comments on Commission Order CLI-83-11 establishing procedures for decision on enforcement action Emergency planning deficiencies fundamental Adequate interim compensating measures impossible Certificate of Svc encl
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/05/23 19pp 18576 094 24X Fiche 50-247, 83/05/23, 8305240538

8305240543 Submission re Commission 830505 Order CLI-83-11 Emergency planning must be well developed & detailed w/special emphasis on health & safety of children
POSNER, P Parents Concerned About Indian Point 83/05/23 20pp 18576 113 24X Fiche 50-247, 83/05/23, 8305240543

8305250223 Submission addressing Commission 830505 order on possible facility closing Requests oral presentation on 830526 re economic impact of facility shutdown Economic impact is not compelling reason for continued operation
CORREN, D Greater New York Council on Energy 83/05/23 12pp 18588 083 24X Fiche 50-247, 83/05/23, 8305250223

8305270586 Response opposing licensee motion for reconsideration of ASLB denial of licensee motion to admit DP McGuire testimony before trial
THORSEN, E D Rockland County, NY 83/05/24 Atomic Safety and Licensing Board Panel 6pp 18645 355 24X Fiche 50-247, 83/05/24, 8305270586

H General correspondence

8305240441 Opines that decision re continued plant operation must weigh health effects of replacement by coal burning plants
JAFFE, H Affiliation Unknown 83/05/16 AHEARNE, J Atomic Safety and Licensing Board Panel 2pp 18571 068 24X Fiche 50-247, 83/05/16, 8305240441

8305240517 Supports continued facility operation
SCHULER, R T, HEALEY, J A, IRWIN, R B Affiliation Unknown 83/05/16 PALLADINO, N J Commissioners 27pp 18571 191 24X Fiche 50-247, 83/05/16, 8305240517

8305240537 Supports closing down of facility
CINQUEMANI, D, CINQUEMANI, F Affiliation Unknown 83/05/19 Commissioners 1p 18576 039 24X Fiche 50-247, 83/05/19, 8305240537

8305270566 Supports shutdown of facilities on 830609
EPSTEIN, R B Affiliation Unknown 83/05/19 Commissioners 2pp 18646 114 24X Fiche 50-247, 83/05/19, 8305270566

8305240541 Supports suspension of plant operation
GRANNIS, A B New York, State of ELLIOTT, N R Yorktown, NY 83/05/20 NRC - No Detailed Affiliation Given 2pp 18576 091 24X Fiche 50-247, 83/05/20, 8305240541

8305270575 Package of two citizens ltrs supporting continued facility operation
KUNKEL, T C, WEIGANDT, J T Affiliation Unknown 83/05/20 PALLADINO, N J Commissioners 2pp 18647 125 24X Fiche 50-247, 83/05/20, 8305270575

8305240453 Supports continued plant operations Plants should not be held hostage to evacuation process
TODOROVICH,M H Affiliation Unknown 83/05/23 CHILK,S J Office of the Secretary of the Commission 3pp 18575 252 24X
Fiche 50-247,83/05/23,8305240453

J Insurance & indemnity information
--- --- ---

8305120208 Forwards Endorsement 65 to NFLIA Policy NF-208 & Endorsement 55 to MAELU Policy MF-77
GOLDEN,M P Marsh & McLennan, Inc 83/05/03 SALTZMAN,J
Assistant Director for State & Licensee Relations 3pp 18427 358
24X Fiche 50-000,83/05/03,8305120208

P Operating license stage documents & correspondence
--- --- ---

8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Force effort,per 821221 ltr
DYSON,J S Power Authority of the State of New York 83/03/02
TOURTELLOTTE,J Regulatory Reform Task Force 2pp 18541 338 24X
Fiche 50-000,83/03/02,8305230597

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305030284 Notification of 830429 meeting util in Bethesda,MD to discuss steam generator chemistry & fire protection interim measures
POLK,P J Operating Reactors Branch 1 83/04/22 VARGA,S A
Operating Reactors Branch 1 4pp 18309 330 24X
Fiche 50-286,83/04/22,8305030284

8305020381 Forwards description of mods to control room ceiling eggcrate ceiling supports to be implemented prior to startup from current refueling outage
BAYNE,J P Power Authority of the State of New York 83/04/28
VARGA,S A Operating Reactors Branch 1 5pp 18276 211 24X
Fiche 50-286,83/04/28,8305020381

8305030408 Forwards Rev 2 to "Fracture Mechanics Analysis of Indian Point Unit 3 Nuclear Generating Station Steam Generator Girth Weld Cracks " Response re util approach requested by 830504
BAYNE,J P Power Authority of the State of New York 83/04/28
VARGA,S A Operating Reactors Branch 1 4pp 18291 223 24X
Fiche 50-286,83/04/28,8305030408

--8305030412 Rev 2 to "Fracture Mechanics Analysis of Indian Point Unit 3 Nuclear Generating Station Steam Generator Girth Weld Cracks "
COTTER,K H , PARIS,P C Fracture Proof Design Corp 83-154 R02
83/04/11 113pp 18291 227 24X Fiche 50-286,83/04/28,
8305030408

305170637 Clarifies 821220 environ qualification SER Justifications for continued operation (JCO) should be reviewed to ensure that JCO exists for all equipment that may not be qualified Proprietary review,per encl guidelines,due in 30 days
VARGA,S A Operating Reactors Branch 1 83/04/28 BAYNE,J P
Power Authority of the State of New York 6pp 18496 354 24X
Fiche 50-286,83/04/28,8305170637

305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

305060397 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions " Rept withheld (ref 10CFR2 790)
BAYNE,J P Power Authority of the State of New York 83/05/03
VARGA,S A Operating Reactors Branch 1 2pp 18348 203 24X
Fiche 50-286,83/05/03,8305060397

-8305060407 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions " Rept withheld (ref 10CFR2 790)
COTTER,K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18348 205 24X
Fiche 50-286,83/05/03,8305060397

--8305060417 Submits application for withholding from public disclose, "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions "
COTTER,K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 4pp 18348 206 24X
Fiche 50-286,83/05/03,8305060397

8305060427 Forwards application for amend to License DPR-64,changing Tech Specs 4 2-3,4 2-3a,6 11 & Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point
BAYNE,J P Power Authority of the State of New York 83/05/03
VARGA,S A Operating Reactors Branch 1 2pp 18343 227 24X
Fiche 50-286,83/05/03,8305060427

--8305060446 Application for amend to License DPR-64,changing Tech Specs 4 2-3,4 2-3a,6 11 & Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point
BAYNE,J P Power Authority of the State of New York 83/05/03
4pp 18343 229 24X Fiche 50-286,83/05/03,8305060427

--8305060449 Proposed changes to Tech Specs 4 2-3,4 2-3a,6 11 & Table 4 2-1 to amend License Condition 2 I 3 to include condenser hot well monitoring as process sampling point
* Power Authority of the State of New York 83/05/03 6pp
18343 233 24X Fiche 50-286,83/05/03,8305060427

8305060431 Forwards application for amend to License DPR-64,changing Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment isolation valve mods & NRC & util organizational changes
BAYNE,J P Power Authority of the State of New York 83/05/03
VARGA,S A Operating Reactors Branch 1 3pp 18351 199 24X
Fiche 50-286,83/05/03,8305060431

--8305060432 Application for amend to License DPR-64,changing Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment isolation valve mods & NRC & util organizational changes.
BAYNE,J P Power Authority of the State of New York 83/05/03
1p 18351 202 24X Fiche 50-286,83/05/03,8305060431

--8305060433 Proposed changes to Tech Specs 6 9 1,6 9 1 4,6 9 1 7, 6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment isolation valve mods & organizational changes W/one oversize drawing Aperture card is available in PDR
* Power Authority of the State of New York 83/05/03 13pp
18351 203 24X Fiche 50-286,83/05/03,8305060431

8305060439 Forwards draft Rev 1 to Vol 1 of "Sys Interaction Study," incorporating organizational changes Comments requested by 830515
BAYNE,J P Power Authority of the State of New York 83/05/03
VARGA,S A Operating Reactors Branch 1 2pp 18343 303 24X
Fiche 50-286,83/05/03,8305060439

--8305060440 Draft Rev 1 to Vol 1 of "Sys Interaction Study "
* Ebasco Services, Inc (subs of Enserch Corp) 83/05/03
91pp 18343 305 24X Fiche 50-286,83/05/03,8305060439

8305130117 Forwards Rev 2 to Procedure SOP-SG-2, "Secondary Plant Chemistry Control" & Rev 2 to Procedure RE-CS-12, "Routine Chemistry Specs & Frequency," in response to NRC 830421 ltr & discussion at 830429 meeting
BAYNE,J P Power Authority of the State of New York 83/05/03
VARGA,S A Operating Reactors Branch 1 1p 18438 009. 24X
Fiche 50-286,83/05/03,8305130117

--8305130120 Rev 2 to Procedure RE-CS-012, "Routine Chemistry Specs & Frequency "
KERNS,M Power Authority of the State of New York 83/05/02
18pp 18438 010 24X Fiche 50-286,83/05/03,8305130117

--8305130123 Rev 2 to Procedure SOP-SG-2, "Secondary Plant Chemistry Control "
GILLEN,J Power Authority of the State of New York 83/05/02
16pp 18438 029 24X Fiche 50-286,83/05/03,8305130117

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N
Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,
8305040323

8305110053 Forwards application for amend to License DPR-64, changing Tech Specs re safety limit, reactor core & control rod & power distribution limits, shutdown reactivity & deleting refs to three-loop operation
BAYNE, J P Power Authority of the State of New York 83/05/05
VARGA, S A Operating Reactors Branch 1 2pp 18408 003 24X
Fiche 50-286, 83/05/05, 8305110053

--8305110058 Application for amend to License DPR-64, changing Tech Specs re safety limit, reactor core & control rod & power distribution limits, shutdown reactivity & deleting refs to three-loop operation
BAYNE, J P Power Authority of the State of New York 83/05/05
1p 18408 005 24X Fiche 50-286, 83/05/05, 8305110053

--8305110063 Proposed Tech Spec changes re safety limit, reactor core & control rod & power distribution limits, shutdown reactivity Refs to three-loop operation deleted since facility restricted to 10% power
* Power Authority of the State of New York 83/05/05 27pp
18408 006 24X Fiche 50-286, 83/05/05, 8305110053

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130039 Forwards supplemental info to 821012 response re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " Response to NRC Question 9(b) not presently available Info will be submitted by 830615
BAYNE, J P Power Authority of the State of New York 83/05/10
EISENHUT, D G Division of Licensing 16pp 18437 010 24X
Fiche 50-286, 83/05/10, 8305130039

8305180038 Notification of contract execution, Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ
HOYLE, A Administrative Contracts Branch FIN D-8644 83/05/10
DENTON, H Office of Nuclear Reactor Regulation, Director CODELL, R
NRC - No Detailed Affiliation Given 1p 18499 289 24X
Fiche 50-247, 83/05/10, 8305180038

--8305180047 Mod 1, extending period of performance to 830630 & changing payment & general provisions, to "Consulting Svc on Indian Point Probabilistic Safety Study "
LEWIS, J P Columbia Univ REBELLO, J E Division of Contracts
83/05/10 1p 18499 290 24X Fiche 50-247, 83/05/10, 8305180038

8305160088 Advises that no basis exists to further delay facility startup per 821018 amend application re steam generator tube sleeving & 830503 order concerning emergency preparedness
SINCLAIR, L W Power Authority of the State of New York 83/05/12
DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp
18450 357 24X Fiche 50-286, 83/05/12, 8305160088

8305200405 Forwards Rev 3, to "Fracture Mechanics Analysis of Steam Generator Girth Weld Cracks "
BAYNE, J P Power Authority of the State of New York 83/05/16
VARGA, S A Operating Reactors Branch 1 1p 18517 175 24X
Fiche 50-286, 83/05/16, 8305200405

--8305200412 Rev 3 to "Fracture Mechanics Analysis of Steam Generator Girthweld Cracks "
COTTER, K H , PARIB, P C Fracture Proof Design Corp 83-154 R03
83/05/03 119pp 18517 176 24X Fiche 50-286, 83/05/16, 8305200405

8305240529 Responds to request for info re seismic qualification of auxiliary feedwater sys "Alarm Response Procedures Panel SCF Condensate & Boiler Feed ARP-6," revised to include listed manual actions
BAYNE, J D Power Authority of the State of New York 83/05/18
VARGA, S A Operating Reactors Branch 1 2pp 18571 123 24X
Fiche 50-286, 83/05/18, 8305240529.

8305240349 Forwards addl info re ability of purge & vent valves to function against accident containment pressures, per 830208 ltr
BAYNE, J P Power Authority of the State of New York 83/05/19
VARGA, S A Operating Reactors Branch 1 15pp 18574 056 24X
Fiche, 50-286, 83/05/19, 8305240349

8305240090 Submits verification of steam generator repair info requested in 830520 telcon Addl info re dose breakdown by major task & total dose for sleeving & girth weld repairs encl
BAYNE, J P. Power Authority of the State of New York 83/05/20
VARGA, S A Operating Reactors Branch 1 6pp 18548 335. 24X
Fiche 50-286, 83/05/20, 8305240090

8305240234 Documents NRC/util telcon re seismic qualification documentation for auxiliary feedwater sys & proposed fire protection Tech Specs Tech Specs on quarterly surveillance of alternate electrical feed sys to be submitted
BAYNE, J P Power Authority of the State of New York 83/05/20
VARGA, S A Operating Reactors Branch 1 2pp 18548 309 24X
Fiche 50-286, 83/05/20, 8305240234

8305240328 Forwards, "Identification & Listing of Electrical Equipment Important to Safety per 10CFR50 49 " Nonsafety-related electric equipment w/failure that would prohibit accomplishment of safety functions not identified
BAYNE, J P Power Authority of the State of New York 83/05/20
VARGA, S A Operating Reactors Branch 1 36pp 18549 239 24X
Fiche 50-286, 83/05/20, 8305240328

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305050280 Forwards request for addl info re secondary water chemistry program concerning steam generator girth weld inservice insp NRC approval of program necessary prior to plant startup Meeting re subj requested as soon as possible
VARGA, S A Operating Reactors Branch 1 83/04/21 BAYNE, J P
Power Authority of the State of New York 5pp 18352 065 24X
Fiche 50-286, 83/04/21, 8305050280

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305100405 Forwards IE Insp Rept 50-286/83-07 on 830316-0415 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/25
BRONS, J C Power Authority of the State of New York 2pp
18378 046 24X Fiche 50-286, 83/04/25, 8305100405

--8305100410 IE Insp Rept 50-286/83-07 on 830316-0415 No noncompliance noted Major areas inspected regular & backshift insps of operations, surveillance, maint, monthly operating rept review, design changes & mods & repair work update
KENNY, T J , ROSSBACH, L W , KISTER, H Region 1, Office of Director
83/04/22 9pp 18378 057 24X Fiche 50-286, 83/04/25, 8305100405

8303040024 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040024

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020451 Submits info on status of Ray Miller, Inc problems affecting plant, per ASLB request.
MOORE, J E Hearing Branch 1 83/04/28 GLEASON, J P Atomic Safety and Licensing Board Panel 88pp 18263 180 24X
Fiche 50-247, 83/04/28, 8305020451

8303040028 IE Info Notice 83-26, "Failure Discharge Line Vacuum Breakers " Svc lis
JORDAN, E L Division of Emergency Prepa
Response (Post 830103), 83/05/03 Co
York, Inc 122pp 18441 170 24X Fiche

8303040030 IE Info Notice 83-27, Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment ' Svc list encl
JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, Criteria for Protective Action Recommendations for General Emergencies Svc list encl
JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305110167 Advises that util will perform mid-cycle insp of steam generator girth welds Preliminary results & corrective measures will be forwarded to NRC 5 days prior to plant startup
BAYNE, J P Power Authority of the State of New York 83/05/05
VARGA, S A Operating Reactors Branch 1 1p 18407 121 24X Fiche 50-286,83/05/05,8305110167

8303040033 IE Info Notice 83-29, Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250503 Forwards IE Insp Rept 50-286/83-09 on 830418-22 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/05/12
BRONS, J C Power Authority of the State of New York 2pp 18584 001 24X Fiche 50-286,83/05/12,8305250503

--8305250509 IE Insp Rept 50-286/83-09 on 830418-22 No noncompliance noted Major areas inspected status of repair operations for cracked upper shell to transition cone closure weld on four steam generators
REYNOLDS, S D , DURR, J Region 1, Office of Director 83/05/06
9pp 18584 003 24X Fiche 50-286,83/05/12,8305250503

8305250226 Forwards IE Insp Rept 50-286/83-05 on 830328-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/13
BRONS, J C Power Authority of the State of New York 2pp 18627 017 24X Fiche 50-286,83/05/13,8305250226

--8305250230 IE Insp Rept 50-286/83-05 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements of NUREG-0737, Item II B 2, "Design Review of Plant Shielding "
HAVERKAMP, D R , KENNY, T J , EAPEN, P K Region 1, Office of Director 83/05/12 12pp 18627 019 24X Fiche 50-286,83/05/13, 8305250226

8305250538 Notification of 830520 significant licensee meeting w/util in Buchanan, NY to present results of SALP repts
KISTER, H B Region 1, Office of Director 83/05/17 Region 1, Office of Director 2pp 18594 354 24X Fiche 50-000,83/05/17, 8305250538

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305110302 Forwards "Annual Environ Protection Plan Rept for 1982" & "Annual Radiological Environ Operating Rept, 1982," per App B to OLs
O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/02
ALLAN, J M Region 1, Office of Director 2pp 18392 221 24X Fiche 50-003,83/05/02,8305110302

--8305110307 "Annual Environ Protection Plan Rept for 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 8pp
18392 223 24X Fiche 50-003,83/05/02,8305110302

--8305110310 "Annual Radiological Environ Operating Rept, 1982 "
* Consolidated Edison Co of New York, Inc 83/05/02 112pp
18392 231 24X Fiche 50-003,83/05/02,8305110302

S Reportable occurrences, LERs & related correspondence

8305030294 PNS-I-83-008 on 830424, security officer overheard voices from storage trailer in protected area Officers apprehended four contractor employees exiting trailer rear window Search revealed marijuana cigarette Employees suspended
MCKEOWN, L , GODY, A T , JOYNER, J H Region 1, Office of Director
83/04/25 1p 18297 144 24X Fiche 50-286,83/04/25,8305030294

8305110439 PNS-I-83-012 on 830505, licensee informed Region 1 that contract health physics employee of Inst for Resource Mgt arrested on suspected multiple federal drug-related charges Individual access to site voided as of 830505
MCKEOWN, BAILEY, GODY Region 1, Office of Director 83/05/05 1p
18405 087 24X Fiche 50-286,83/05/05,8305110439

T Hearing transcripts on non-antitrust matters

8305230001 Transcript of 830322 hearing in White Plains, NY Pp 10,737-11,117 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/03/22 612pp
18532 021 24X Fiche 50-247,83/03/22,8305230001

8305110002 Excerpts from transcript of 83040/ hearing Pp 13,017-13,019,
* NRC - No Detailed Affiliation Given 83/04/07 3pp 18409 009
24X Fiche 50-247,83/04/07,8305110002

8305030608 Motion for permission to present rebuttal witnesses on subj of prevailing winds, sample surveys & bystander behavior Discussion of issues could not have been anticipated prior to presentation of evidence
POTTERFIELD, A Union of Concerned Scientists POTTERFIELD, A Potterfield, A 83/04/19 4pp 18308 050 24X
Fiche 50-247,83/04/19,8305030608

--8305030619 Testimony of D Gutman re prevailing wind patterns
GUTMAN, D Union of Concerned Scientists GUTMAN, D Public Interest Research Group, New York GUTMAN, D New York, NY
83/04/19 4pp 18308 054 24X Fiche 50-247,83/04/19,8305030608

--8305030629 Testimony of RR Holt re sample surveys & bystander behavior
HOLT, R R Union of Concerned Scientists HOLT, R R Public Interest Research Group, New York HOLT, R R New York, NY
83/04/19 37pp 18308 058 24X Fiche 50-247,83/04/19,8305030608

--8305030633 Reorganized testimony of JR Thornborough & D Bohning re Contention 6 2 concerning impact of shutdown on physical environ near facility
POSNER, P Parents Concerned About Indian Point 83/04/19 44pp
18308 095 24X Fiche 50-247,83/04/19,8305030608

--8305030641 Motion requesting initiation of studies on human response to radiological emergencies, risks to individuals living near site & difficulty of evacuation in emergency
POTTERFIELD, A Public Interest Research Group, New York
83/04/26 Atomic Safety and Licensing Board Panel 8pp
18308 139 24X Fiche 50-247,83/04/19,8305030608

--8305030652 Motion requesting completeness of record on NRC Questions 3 & 4 re emergency planning issues, including capability for handling phone calls in emergency planning zone during emergency
POTTERFIELD, A Union of Concerned Scientists 83/04/25 Atomic Safety and Licensing Board Panel 4pp 18308 180 24X
Fiche 50-247,83/04/19,8305030608

8305020077 Transcript of 830426 hearing in White Plains, NY Pp 14,419-14,596 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/04/26 210pp
18278 250 24X Fiche 50-247,83/04/26,8305020077

8305030386 Transcript of 830427 hearing in White Plains, NY Pp 14,597-14,702
* Atomic Safety and Licensing Board Panel 83/04/27 116pp
18292 001 24X Fiche 50-247,83/04/27,8305030386

8305040172 Transcript of 830428 hearing in White Plains, NY Pp 14,703-15,087 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/04/28 526pp
18324 297 24X Fiche 50-247,83/04/28,8305040172

8305090425 Testimony of LA Cohen in rebuttal to testimony of D Gutman Testimony to be included w/ASLB 830420 transcript Certificate of Svc encl.
COHEN, L A Consolidated Edison Co of New York, Inc 83/04/28
10pp 18363 321 24X Fiche 50-247,83/04/28,8305090425

8305040347 Transcript of 830429 hearing in White Plains,NY Pp 15,088-15,226 Supplemental testimonies encl
* Atomic Safety and Licensing Board Panel 83/04/29 149pp
18322 242 24X Fiche 50-247,83/04/29,8305040347

8305130327 Transcript of Commission 830505 meeting,discussion & possible vote in Washington,DC re status of emergency planning at facilities Pp 1-22
* Commissioners 83/05/05 27pp 18457 277 24X
Fiche 50-247,83/05/05,8305130327

8305240554 Statement to be incorporated in minutes of Commission 830526 public hearing State/federal govt must force counties to devise evacuation plans Problems w/emergency plans must be resolved before 830609
DI GIACOMO,C G Cortland, NY 83/05/18 4pp 18576 029 24X
Fiche 50-247,83/05/18,8305240554

8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR,per 10CFR9 Commission determination statement encl
CHILK,S J Office of the Secretary of the Commission 83/05/18
Public Document Branch 2pp 18593 063 24X Fiche 50-003,83/05/18,8305240566

--8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners 82/12/22 19pp 18593 065 24X
Fiche 50-003,83/05/18,8305240566

--8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners 82/12/22 59pp 18593 082 24X
Fiche 50-003,83/05/18,8305240566

8305240531 Statement of Clergy,Religious & Laity Concerned About Indian Point Common citizens reject idea that expertise irrelevant Value of human life is supreme value
* Affiliation Unknown 83/05/20 4pp 18571 105 24X
Fiche 50-247,83/05/20,8305240531

8305240533 Forwards written testimony on efforts to address deficiencies in emergency response plan since 830505
O'ROURKE,A P Westchester County, NY 83/05/20 PALLADINO,N J ,
GILINSKY,V , AHEARNE,J Commissioners 1p 18576 043 24X
Fiche 50-247,83/05/20,8305240533

--8305240539 Testimony of AP O'Rourke re actions taken to improve emergency planning since Commission 830505 order Unions representing bus drivers fully support orientation course on radiological emergency response procedures
O'ROURKE,A P Westchester County, NY 83/05/20 6pp 18576 044
24X Fiche 50-247,83/05/20,8305240533

8305240555 Forwards statement for inclusion in special proceeding testimony
WEISS,T House of Rep 83/05/20 PALLADINO,N Commissioners 1p
18576 025 24X Fiche 50-247,83/05/20,8305240555

--8305240558 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile Public safety should be top priority
WEISS,T. House of Rep 83/05/19 3pp 18576 026 24X
Fiche 50-247,83/05/20,8305240555

8305310002 Testimony of RW Carlisle re potential hazards of nuclear accidents Long-range educ in nuclear radiation should be implemented Robots should be developed to dismantle plant after meltdown
CARLISLE,R W Affiliation Unknown 83/05/20 3pp 18653 240 24X
Fiche 50-247,83/05/20,8305310002

8305310055 Transcript of Commission 830523 discussion of Indian Point order in Washington,DC Pp 1-19
* Commissioners 83/05/23 23pp 18663 128 24X
Fiche 50-247,83/05/23,8305310055

U Congressional/Executive Correspondence

8305240555 Forwards statement for inclusion in special proceeding testimony
WEISS,T House of Rep 83/05/20 PALLADINO,N Commissioners 1p
18576 025 24X Fiche 50-247,83/05/20,8305240555

--8305240558 Statement of T Weiss re proposed evacuation plans Plants should be shut down permanently Planning for nuclear accident futile.Public safety should be top priority
WEISS,T House of Rep 83/05/19 3pp 18576 026 24X
Fiche 50-247,83/05/20,8305240555

8305310059 Commends State of NY commitment of resources & cooperation w/licensees & local govts to implement offsite emergency preparedness plan
PALLADINO,N J Commissioners 83/05/25 CUOMO,M M New York, State of 1p 18653 280 24X Fiche 50-247,83/05/25,8305310059

--8305310070 Expresses concern that addl actions required to satisfy mandates per 10CFR50 54(S)(1) State of NY Disaster Preparedness Commission will work w/utils until Rockland County completes emergency preparedness plans
CUOMO,M M New York, State of 83/05/25 PALLADINO,N J
Commissioners 3pp 18653 281 24X Fiche 50-247,83/05/25,8305310059

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8305270326 Forwards IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/06
TUCKER,H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269,83/05/06,8305270326

--8305270338 IE Insp Repts 50-269/83-13,50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing,maint & operations & annual emergency drill
BRYANT,J Region 2, Office of Director 83/05/06 9pp
18641 144 24X Fiche 50-269,83/05/06,8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/06
TUCKER,H B Duke Power Co 2pp 18643 011 24X
Fiche 50-269,83/05/06,8305270374

--8305270387 IE Insp Repts 50-269/83-10,50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN,G N Region 2, Office of Director 83/05/03 10pp
18643 013 24X Fiche 50-269,83/05/06,8305270374

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

J Insurance & indemnity information

8305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101,respectively,for McGuire
LAWSON,L T Duke Power Co 83/05/20 SALTZMAN,J Office of Resource Management, Director 19pp 18626 120 24X
Fiche 50-000,83/05/20,8305260261

P Operating license stage documents & correspondence

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659,Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515,2787 & 2802)
SHOLLY,S C Union of Concerned Scientists 83/03/11 FELTON,J M
Division of Rules and Records 1p 18593 178 24X
Fiche 50-000,83/03/11,8305240249

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON,J M Division of Rules and Records 83/03/31 SHOLLY,S C
Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000,83/03/31,8305240254

--8305240259 Forwards comments on draft rept re Reactor Safety Study Methodology Applications Program for Facility Changes indicated in areas of validity of sys criteria & correctness & appropiateness of assumptions in sys analysis
PARKER,W O Duke Power Co 80/09/22 BERNERD,R Probabilistic Analysis Staff (Pre 801119) 11pp 18593 181 24X
Fiche 50-000,83/03/31,8305240254

8305090078 Forwards Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability Amends revise Tech Spec withdrawal schedule for reactor vessel surveillance capsules
CONNER,E L Operating Reactors Branch 4 83/04/15 TUCKER,H B Duke Power Co 4pp 18381 140 24x Fiche 50-269,83/04/15, 8305090078

--8305090111 Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55, respectively,revising Tech Spec withdrawal schedule for reactor vessel surveillance capsules
STOLZ,J F Operating Reactors Branch 4 83/04/15 8pp 18381 144 24X Fiche 50-269,83/04/15,8305090078

--8305090124 Safety evaluation supporting Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively
* Office of Nuclear Reactor Regulation, Director 83/04/15 2pp 18381 152 24X Fiche 50-269,83/04/15,8305090078

--8305090138 Notice of issuance & availability of Amends 120,120 & 117 to Licenses DPR-38,DPR-47 & DPR-55,respectively
STOLZ,J F Operating Reactors Branch 4 83/04/15 2pp 18381 154 24X Fiche 50-269,83/04/15,8305090078

8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "Control of Heavy Loads (C-10),Oconee Nuclear Power Station,Units 1,2 & 3 " Phase 1 actions acceptable per NUREG-0612
STOLZ,J F Operating Reactors Branch 4 83/04/20 TUCKER,H B Duke Power Co 3pp 18457 179 24X Fiche 50-269,83/04/20, 8305130294

-8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612)
* Office of Nuclear Reactor Regulation, Director 83/04/20 1p 18457 182 24X Fiche 50-269,83/04/20,8305130294

-8304070286 "Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1,2 & 3," technical evaluation rept
ROBERTS,S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-374/375/37 83/03/31 CLEMENSON,F NRC - No Detailed Affiliation Given 28pp 18457 183 24X Fiche 50-269,83/04/20,8305130294

305090608 Forwards safety evaluation in support of continued PWR operation w/Dresser primary safety valves re TMI Action Item II D 1 EPRI data on tests of certain models of Dresser safety valves under review on generic basis
STOLZ,J F Operating Reactors Branch 4 83/04/27 TUCKER,H B Duke Power Co 2pp 18367 111 24X Fiche 50-269,83/04/27, 8305090608

305040564 Forwards proposed App A to offsite dose calculation manual, supporting radiological effluent Tech Spec per 830209 ltr Submittal constitutes final revised offsite dose calculation manual
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 1p 18320 083 24X Fiche 50-269,83/04/28,8305040564

8305040568 App A to, "Oconee Nuclear Station Site Specific Info "
* Duke Power Co 83/04/28 32pp 18320 084 24X Fiche 50-269,83/04/28,8305040564

05200103 Forwards safety evaluation on standby shutdown facility Design meets requirements,except for process monitoring instruments for source range flux monitoring & steam generator pressure indication
STOLZ,J F Operating Reactors Branch 4 83/04/28 TUCKER,H B Duke Power Co 4pp 18576 154 24X Fiche 50-269,83/04/28, 8305200103

8305200106 Safety evaluation re standby shutdown facility Design acceptable except on availability of source range flux monitor & steam generator pressure indication
* Office of Nuclear Reactor Regulation, Director 83/04/28 17pp 18576 158 24X Fiche 50-269,83/04/28,8305200103

5020455 Generic Ltr 83-19 to all power reactor & testing licensees e new procedures for providing public notice concerning ssuance of amends to OLs Svc list encl
IBENHUT,D G Division of Licensing 83/05/02 Consolidated dison Co of New York, Inc 50pp 18441,120 24X iche 50-000,83/05/02,8305020455

5060365 Notification of 830506 meeting w/B&W Owners Group in ethesda,MD to discuss core barrel failure at Rancho Seco & rystal River 3,Future plans for resolving problem & ustification for continued operation
INER,S Operating Reactors Branch 4 83/05/02 STOLZ,J erating Reactors Branch 4 2pp 18353 092 24X he 50-000,83/05/02,8305060365

8305090435 Forwards safety evaluation of implementation of asymmetric fault for control rod 6-3 during Cycle 7 Method for restoring normal operating flexibility can be undertaken w/o affecting plant safety
THIES,A C Duke Power Co 83/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 3pp 18363 071 24X Fiche 50-287,83/05/04,8305090435

8305180034 Forwards Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively,safety evaluation & notice of issuance & availability Amends revise Tech Specs to delay certain surveillance requirements until next refueling outage
EISENHUT,D G Division of Licensing 83/05/05 TUCKER,H B Duke Power Co 3pp 18499 245 24X Fiche 50-269,83/05/05,8305180034

--8305180045 Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55, respectively,revising Tech Specs to delay certain surveillance requirements until next refueling outage
STOLZ,J F Operating Reactors Branch 4 83/05/05 21pp 18499 248 24X Fiche 50-269,83/05/05,8305180034

--8305180059 Safety evaluation supporting Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 5pp 18499 269 24X Fiche 50-269,83/05/05,8305180034

--8305180068 Notice of issuance & availability of Amends 121,121 & 118 to Licenses DPR-38,DPR-47 & DPR-55,respectively
STOLZ,J F Operating Reactors Branch 4 83/05/05 2pp 18499 274 24X Fiche 50-269,83/05/05,8305180034

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche,50-000,83/05/09,8305090659

8305180151 Forwards request for addl info re details on void formation during natural circulation cooldown,per 810505 Generic Ltr 81-21 Response dtd 811105 inadequate
STOLZ,J F Operating Reactors Branch 4 83/05/09 TUCKER,H B Duke Power Co 4pp 18502 344 24X Fiche 50-269,83/05/09, 8305180151

8305130025 Submits info supporting determination that critical path outage time could be saved if containment purging commenced at RCS temp between 250 F & 225 F rather than present 200 F Preparation of proposed Tech Specs re purging in progress
TUCKER,H B Duke Power Co 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 2pp 18437 154 24X Fiche 50-269,83/05/10,8305130025

8305230499 Notification of 830608 meeting w/util in Bethesda,MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed
SVERMANN,J F Operating Reactors Branch 4 83/05/16 STOLZ,J F Operating Reactors Branch 4 2pp 18541 274 24X Fiche 50-000,83/05/16,8305230499

8305230479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation,per NUREG-0737,TMI Action Item II B 4 provided Response to IE Bulletin 79-01B will be revised
TUCKER,H B Duke Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Licensing Branch 4 27pp 18589 005 24X Fiche 50-269,83/05/19,8305230479

8305310081 Submits addl info re safety-related environ qualification of electrical equipment,per 10CFR50.49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18655 123 24X Fiche 50-269,83/05/20,8305310081

8305310083 Forwards SER based on review of mechanical response to primary coolant sys subjected to asymmetric LOCA loads Util assessment of asymmetric loads problem acceptable
STOLZ,J F Operating Reactors Branch 4 83/05/20 TUCKER,H B Duke Power Co 2pp 18662 311 24X Fiche 50-269,83/05/20, 8305310083

--8305310089 Safety evaluation accepting util analysis of asymmetric LOCA loads Reasonable assurrance that reactor can be brought to cold shutdown safely provided
* Operating Reactors Branch 4 83/05/20 74pp 18662 313 24X Fiche 50-269,83/05/20,8305310083

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270403 Forwards IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18642 321 24X
Fiche 50-269, 83/04/05, 8305270403

--8305270411 IE Insp Repts 50-269/83-08, 50-270/83-08 & 50-287/83-08 on 830211-0310 No noncompliance noted Major areas inspected operations, surveillance testing, maint, event rept review & emergency procedure review
BRYANT, J , FALCONER, D Region 2, Office of Director
IONATONIB, A J Division of Project & Resident Programs 83/04/04
12pp 18642 323 24X Fiche 50-269, 83/04/05, 8305270403

8305270497 Forwards IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/05
TUCKER, H B Duke Power Co 2pp 18646 192 24X
Fiche 50-269, 83/04/05, 8305270497

--8305270518 IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREG-0737, Items II B 2, "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys "
COLLINS, T R , BARR, K P Region 2, Office of Director 83/04/01
7pp 18646 194 24X Fiche 50-269, 83/04/05, 8305270497

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270326 Forwards IE Insp Repts 50-269/83-13, 50-270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18641 142 24X
Fiche 50-269, 83/05/06, 8305270326

--8305270330 IE Insp Repts 50-269/83-13, 50 270/83-13 & 50-287/83-13 on 830311-0410 No noncompliance noted Major areas inspected surveillance testing, maint ? operations & annual emergency drill
BRYANT, J , FALCONER, D Region 2, Office of Director
BROWNLEE, V L Division of Project & Resident Programs 83/05/06
9pp 18641 144 24X Fiche 50-269, 83/05/06, 8305270326

8305270374 Forwards IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
TUCKER, H B Duke Power Co 2pp 18643 011 24X
Fiche 50-269, 83/05/06, 8305270374

--8305270387 IE Insp Repts 50-269/83-10, 50-270/83-10 & 50-287/83-10 on 830405-06 No noncompliance noted Major areas inspected emergency preparedness exercise
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/03 10pp
18643 013 24X Fiche 50-269, 83/05/06, 8305270374

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305270425 Forwards IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 No noncompliance noted Concern re open pressurization line test valve on Unit 3 discussed
O'REILLY, J P Region 2, Office of Director 83/05/11 TUCKER, H B Duke Power Co 2pp 18642 280 24X Fiche 50-269, 83/05/11, 8305270425

--8305270435 IE Enforcement Conference Repts 50-269/83-12, 50-270/83-12 & 50-287/83-12 on 830323 & 0419 Major areas discussed open pressurization line isolation valve on emergency hatch on 830317 & corrective actions
DANCE, H C Division of Project & Resident Programs 83/05/10
5pp 18642 282 24X Fiche 50-269, 83/05/11, 8305270425

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305310081 Submits addl info re safety-related environ qualification of electrical equipment, per 10CFR50 49(g) & IE Bulletin 79-01B Electrical isolation provided for all reactor protective sys & engineered safeguards protective sys
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 3pp 18655 123 24X Fiche 50-269, 83/05/20, 8305310081

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305170455 Forwards monthly operating repts for Apr 1983
TUCKER, H B Duke Power Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18470 142 24X
Fiche 50-269, 83/05/13, 8305170455

--8305170460 Monthly operating repts for Apr 1983
REAVIS, J A Duke Power Co 83/05/13 16pp 18470 143 24X
Fiche 50-269, 83/05/13, 8305170455

S Reportable occurrences, LERs & related correspondence

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/27 STELLO, V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000, 83/04/27, 8305110324

8305050254 RDs 269/83-10 & 287/83-04 re 821212 & 830303 loss of containment integrity Mgt audit in progress Summary list of completed & remaining activities w/projected completion dates, encl
TUCKER, H B Duke Power Co 83/04/29 O'REILLY, J P Region 2, Office of Director 15pp 18338 001 24X Fiche 50-269, 83/04/29, 8305050254

8305250556 Notifies that noble gas monitor-stack high-range radiation monitor (NUREG-0737, Item II F 1(1)) reported as being operable in 830318 order, became inoperable on 830426 Caused by moisture contamination New monitors ordered
TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 18588 185 24X Fiche 50-269, 83/05/19, 8305250556

DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305030693 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18309 116 24X Fiche 50-289, 83/04/22, 8305030693

--8305030695 Public version of Rev 6 to Emergency Plan Implementing Procedure 1004 6, "Addl Assistance & Notification "
STANGE, S J General Public Utilities - GPU Service Corp
83/03/17 21pp 18309 117 24X Fiche 50-289, 83/04/22, 8305030693

8305050300 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18352 169 24X Fiche 50-289, 83/04/25, 8305050300

--8305050304 Forwards public version of Rev 3 to Emergency Plan Implementing Procedure 1004 12, "Environ Monitoring "
Receipt form encl
NASH, B General Public Utilities - GPU Service Corp 83/02/23
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p
18352 170 24X Fiche 50-289, 83/04/25, 8305050300

--8305050307 Public version of Rev 3 to Emergency Plan Implementing Procedure 1004 12, "Environ Monitoring "
STANGE, S J General Public Utilities - GPU Service Corp
83/02/15 14pp 18352 171 24X Fiche 50-289, 83/04/25, 8305050300

8305100143 Submits status of offsite emergency preparedness issues re FEMA regional verifications through 830304 & data received through 830331 concerning schedule for completion of issues at facilities
KRIMM, R W Federal Emergency Management Agency 83/04/26
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 9pp 18375 001 24X Fiche 50-289, 83/04/26, 8305100143

8305130180 Advises that emergency preparedness briefings conducted for major employers & operators in locations within emergency planning zone plume exposure pathway Partial initial decision conditions satisfied
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/09
STOLZ, J F Operating Reactors Branch 4 1p 18440 084 24X
Fiche 50-289, 83/05/09, 8305130180

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305190158 Clarifies 830331 ltr re reactor coolant pump trip on 25 F subcooling margin w/respect to qualification of saturation margin monitor sys Sys evaluated per Generic Ltr 82-33 & 830415 ltr Schedule for instrumentation upgrading unknown
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/13
EISENHUT, D G Division of Licensing 1p 18502 239 24X
Fiche 50-289, 83/05/13, 8305190158

Adjudicatory correspondence

8305040054 Discusses status of B&W-GPU lawsuit document review Next rept expected within 2 wks
DIRCKS, W J Office of the Executive Director for Operations
83/04/20 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners
2pp 18336 325 24X Fiche 50-289, 83/04/20, 8305040054

--8305040068 Staff requirements memo re 830330 briefing on investigation & possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wks
CHILK, S J Office of the Secretary of the Commission 83/04/08
DIRCKS, W J Office of the Executive Director for Operations
HAYES, B D NRC - No Detailed Affiliation Given CUMMINGS, J J
Office of Inspector & Auditor 2pp 18336 327 24X
Fiche 50-289, 83/04/20, 8305040054

8305230700 Requests cooperation in informing NRC of outstanding safety concerns re facilities Prompt notification re allegations of safety concerns requested
PLAINE, H H Office of the General Counsel 83/04/20 DEVINE, T
Government Accountability Project 2pp 18542 323 24X
Fiche 50-289, 83/04/20, 8305230700

8305090504 Requests written statement under oath of affirmation as to whether or not indices discussed at 830412-14 meetings represent complete listing of all dispositions & exhibits developed for B&W-GPU lawsuit
DIRCKS, W J Office of the Executive Director for Operations
83/04/21 ARNOLD, R C General Public Utilities - GPU Service Corp
2pp 18381 252 24X Fiche 50-289, 83/04/21, 8305090504

8305030591 Reply to NRC 830412 proposed opinion, findings of fact & conclusions of law in reopened hearing Objects to nature of NRC proposed condition requiring dispatch of auxiliary operator Certificate of Svc encl
BAXTER, T A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 82/04/28 6pp 18303 349 24X
Fiche 50-289, 83/04/28, 8305030591

8305100406 Response opposing NRC oral motion to extend time for reply to intervenor motion to reopen restart hearing Sufficient time already provided Delay unnecessary Certificate of Svc & amended Certificate of Svc encl
AAMODT, M M Aamodts, The 83/04/30 PALLADINO, N , AHEARNE, J , GILINSKY, V Commissioners 4pp 18377 352 24X
Fiche 50-289, 83/04/30, 8305100406

8305050053 Motion for extension until 830513 to respond to Aamodt 830416 motion to reopen record of restart proceeding Time needed so NRC response will not be filed before other parties due to manner of receipt Certificate of Svc encl
WAGNER, M E Hearing Branch 4 GOLDBERG, J R Hearing Branch 2
83/05/03 Commissioners 10pp 18342 069 24X
Fiche 50-289, 83/05/03, 8305050053

8305090481 Motion for extension of time to respond to Aamodt motion to reopen record of restart proceeding
WAGNER, M E Office of the General Counsel GOLDBERG, J R Hearing Branch 2 83/05/03 1p 18362 340 24X Fiche 50-289, 83/05/03, 8305090481

8305100205 Discusses selective withholding of info in 830201 memo forwarding Board Notification 83-08 re TMI-1 restart hearing Certificate of Svc encl
AAMODT, M M Aamodts, The 83/05/03 EISENHUT, D G Division of Licensing 2pp 18374 035 24X Fiche 50-289, 83/05/03, 8305100205

8305100212 Motion for summary disposition of B&W/GPU trial record No genuine issue of matl fact exists & TMI Alert entitled to favorable decision Svc list encl
BRADFORD, L Three Mile Island Alert 83/05/03 Atomic Safety and Licensing Appeal Panel 5pp 18374 188 24X Fiche 50-289, 83/05/03, 8305100212

8305090431 Distribution of Rockwell rept re investigation of Hartman allegations concerning TMI-2 as part of TMI-1 restart proceeding Certificate of Svc encl
TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/05/04 4pp 18362 357 24X
Fiche 50-289, 83/05/04, 8305090431

8305060258 Order granting addl time until 830601 to submit addl comments on NRC review of GPU vs B&W trial record Trial & exhibits in NRC possession placed in PDR & LPDR Comments may be filed after 830601
HOYLE, J C Office of the Secretary of the Commission 83/05/05
Union of Concerned Scientists 4pp 18345 218 24X
Fiche 50-289, 83/05/05, 8305060258

8305100283 Contends that planned change in reactor coolant pump trip setting & in throttling high pressure injection criteria does not affect evidence presented on performance under LOCA conditions Certificate of Svc encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Metropolitan Edison Co 83/05/05 EDLES, G J , BUCK, J H , GOTCHY, R L Atomic Safety and Licensing Appeal Panel 4pp
18371 268 24X Fiche 50-289, 83/05/05, 8305100283

8305100357 Comments on ASLAP 830420 memo suggesting, inter alia, that Commission explore two concerns re facility PORV prior to restart Resolution of PORV corrosion issue already being pursued Certificate of Svc encl
BAXTER, T A Metropolitan Edison Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/05 8pp 18379 093 24X
Fiche 50-289, 83/05/05, 8305100357

8305100310 Submits facts re personnel changes since close of record on mgt issues, per licensee 811001 procedures for info Resumes & svc list encl
BAUSER, D B Shaw, Pittman, Potts & Trowbridge BAUSER, D B Metropolitan Edison Co 83/05/06 EDLES, G J , BUCK, J H , KOHL, C N Atomic Safety and Licensing Appeal Panel 13pp 18370 125 24X
Fiche 50-289, 83/05/06, 8305100310

8305100163 Errata to Aamodt comments re NRC review of GPU vs B&W trial transcript & motions to reopen record of restart proceeding
* Aamodts, The 83/05/09 1p 18374 272 24X
Fiche 50-289, 83/05/09, 8305100163

8305100231 Responds to MI Lewis 830418 request for relief re leak rate issue Recommends deferring consideration of request until info relevant to concerns provided as part of NRC revalidation effort Certificate of Svc encl
GOLDBERG, J R , WAGNER, M E Office of the Executive Legal Director 83/05/09 Commissioners 9pp 18373 288 24X
Fiche 50-289, 83/05/09, 8305100231

8305100299 Order denying People Against Nuclear Energy 820603 motion for hearing on psychological stress issue
CHILK, S J Office of the Secretary of the Commission 83/05/09 People Against Nuclear Energy 1p 18370 138 24X
Fiche 50-289, 83/05/09, 8305100299

8305120292 Reply opposing Aamodts 830416 motion to reopen record on mgt issues Motion unclear & fails to meet Commission & ASLAB stds Info previously available Certificate of Svc encl
TROWBRIDGE, G F Metropolitan Edison Co TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/05/09 Atomic Safety and Licensing Appeal Panel 14pp 18424 106 24X Fiche 50-289, 83/05/09, 8305120292

8305160073 Petition for review of ASLB 821210 decision, ALAB-705, ruling that NRC need not publicly disclose & consider potential consequences of serious nuclear accident prior to restart authorization W/Certificate of Svc Related correspondence
WEISS, E R Union of Concerned Scientists WEISS, E R Harmon & Weiss 83/05/09 U S Court of Appeals for District of Columbia Circuit 8pp 18453 035 24X Fiche 50-289, 83/05/09, 8305160073

8305120319 Order referring TMI Alert 830503 motion re GPU vs B&W trial documents to Commission Motion effectively constitutes request for mod or reconsideration of Commission 830505 order
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/05/10 2pp 18424 096 24X Fiche 50-289, 83/05/10, 8305120319

8305160012 Notifies that copies of in-house 1978 mgt audit rept referred to in Aamodt 830416 motion to reopen & in licensee 830509 reply will be distributed Certificate of Svc encl
TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge 83/05/12 4pp 18456 085 24X Fiche 50-289, 83/05/12, 8305160012

8305160130 Order granting, in part, TMI Alert motion to permit overnight removal of documents re GPU vs B&W trial transcripts Only nonindexed set of documents can be removed
CHILK, S J Office of the Secretary of the Commission 83/05/13 Three Mile Island Alert 2pp 18446 114 24X Fiche 50-289, 83/05/13, 8305160130

8305170039 Answer opposing Aamodt 830416 motion to reopen record Stds for reopening record not met Hartman allegations re falsification of leak rate data not significant info to warrant reopening record
GOLDBERG, J R Hearing Branch 2 WAGNER, M E Hearing Branch 4 83/05/13 Atomic Safety and Licensing Appeal Panel 19pp 18466 183 24X Fiche 50-289, 83/05/13, 8305170039

--8305170044 Affidavit of LP Crocker that 780109-20 mgt audit does not affect testimony given on organization & mgt of TMI-1 Audit was of station mgt structure & policies in effect over 1 yr prior to TMI-2 accident
CROCKER, L P Licensee Qualifications Branch 83/05/05 2pp 18466 202 24X Fiche 50-289, 83/05/13, 8305170039

--8305170047 Affidavit of FR Allenspach that 780214 mgt audit does not change testimony given on Aamodt Contention 2 re upgrading performance of licensee technicians & mgt personnel
ALLENSPACH, F R Licensee Qualifications Branch 83/05/04 2pp 18466 204 24X Fiche 50-289, 83/05/13, 8305170039

--8305170051 Affidavit of RR Keimig that 780109-20 mgt audit does not change testimony on issue of util mgt competency for facility operation
KEIMIG, R R Division of Project & Resident Programs 83/05/05 1p 18466 206 24X Fiche 50-289, 83/05/13, 8305170039

--8305170054 Affidavit of BA Boger re Aamodt comments on GPU vs B&W trial transcript relationship to previous testimony
BOGER, B A Division of Licensing 83/05/12 2pp 18466 207 24X Fiche 50-289, 83/05/13, 8305170039

--8305170058 Affidavit of F Kantor re util onsite technical support ctr & nearsite emergency operations facility Both facilities found acceptable Util currently designing safety parameter displays Certificate of Svc encl
KANTOR, F Emergency Preparedness Branch 83/05/12 6pp 18466 209 24X Fiche 50-289, 83/05/13, 8305170039

8305180277 Forwards two consultant repts & ltrs prepared for GPU mgt re mgt competence phase Ltrs clarify repts Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Metropolitan Edison Co 83/05/16 EDLES, G J , BUCK, J H , KOHL, C N Atomic Safety and Licensing Appeal Panel 211pp 18490 071 24X
Fiche 50-289, 83/05/16, 8305180277

8305240216 Advises that 830323 ltr requesting immediate halt to all work at TMI-1 & 2, w/exception of maint necessary for safety, will receive consideration as request for action under 10CFR2 206 FR notice encl
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/17 KING, R Three Mile Island Public Interest Resource Center 2pp 18593 306 24X Fiche 50-289, 83/05/17, 8305240216

--8305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at TMI-1 & 2
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/17 1p 18593 308 24X Fiche 50-289, 83/05/17, 8305240216

8305200632 Forwards NRC 830519 memo to Commission re results of NRC revalidation of NRC position on mgt integrity issues
GOLDBERG, J R Hearing Branch 2 83/05/19 EDLES, G J , KOHL, C N , BUCK, J H Atomic Safety and Licensing Appeal Panel 4pp 18520 125 24X Fiche 50-289, 83/05/19, 8305200632

8305200669 Formal demand for adjudicatory hearing on OL amend re steam generator tube repairs & petition to intervene Amend presents significant hazards consideration Hearing required Certificate of Svc encl
DOROSHOW, J Three Mile Island Alert 83/05/19 Commissioners 14pp 18519 159 24X Fiche 50-289, 83/05/19, 8305200669

8305240536 Affidavit of RC Rogan confirming util commitment to activate emergency operations facility & staff facility w/emergency support director within 1 h of site area or general emergency notification or declaration
ROGAN, R E General Public Utilities - GPU Service Corp 83/05/20 4pp 18576 087 24X Fiche 50-000, 83/05/20, 8305240536

8305240287 Motion for leave to file affidavit by R Rogan re testing & verification of emergency operations subsequent to Dec 1982 Affidavit needed as factual evidence before Commission for staffing plan approval W/o encl
ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Trowbridge 83/05/23 Commissioners 2pp 18548 110 24X Fiche 50-289, 83/05/23, 8305240287

8305240444 Supplemental comments re immediate effectiveness of partial initial decision on mgt issues ASLB credibility & TMI-1 safety questionable in light of new evidence
DOROSHOW, J Three Mile Island Alert 83/05/23 Commissioners 3pp 18574 088 24X Fiche 50-289, 83/05/23, 8305240444

8305240449 Motion to reopen record to remedy deficiencies re licensee mgt competency & integrity & provide right to examine relevant matl evidence in context of full adjudicatory hearing
DOROSHOW, J Three Mile Island Alert 83/05/23 Atomic Safety and Licensing Appeal Panel 19pp 18573 133 24X Fiche 50-289, 83/05/23, 8305240449

--8305240457 Comments on IE Insp Rept 50-289/83-10 & review to revalidate NRC position re Hartman allegations Conclusions on mgt integrity inconclusive due to open issues identified & not considered in revalidation program Certificate of Svc encl
DIRCKS, W J Office of the Executive Director for Operations 83/05/19 PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 6pp 18573 152 24X Fiche 50-289, 83/05/23, 8305240449

8305240486 Forwards licensee reply opposing NRC staff brief on review of ALAB-698 per 830321 order setting forth briefing schedule on emergency planning issues in restart proceeding
Certificate of Svc encl W/o licensee reply
ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 83/05/23
Docketing & Services Branch 4pp 18572 333 24X
Fiche 50-289,83/05/23,8305240486

8305240487 Reply opposing NRC brief on review of ALAB-698 re emergency planning NRC should dismiss util petition for review & affirm that part of decision being challenged by NRC
TROWBRIDGE,G F , ZAHLER,R E , RIDGWAY,D A Metropolitan Edison Co
83/05/23 Commissioners 43pp 18572 070 24X
Fiche 50-289,83/05/23,8305240487

8305240525 Advises of change to Page 7 of NRC 830513 answer to Aamodt motion to reopen record,based on mod to inspector preliminary conclusion re organization & structure
GOLDBERG,J R Hearing Branch 2 83/05/23 EDLES,G J , KOHL,C N , BUCK,J H Atomic Safety and Licensing Appeal Panel 1p 18571 174
24X Fiche 50-289,83/05/23,8305240525

8305250202 Forwards licensee response opposing NRC brief on review of ALAB-698,filed per Commission 830321 Order CLI-83-7 re briefing schedule on emergency planning Certificate of Svc encl
ZAHLER,R E Shaw, Pittman, Potts & Trowbridge ZAHLER,R E
Metropolitan Edison Co 83/05/23 Docketing & Services Branch
4pp 18584 012 24X Fiche 50-289,83/05/23,8305250202

--8305250208 Motion to file RE Rogan affidavit,supporting licensee response opposing NRC brief on review of ALAB-698
ZAHLER,R E General Public Utilities - GPU Service Corp
ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 83/05/23
Commissioners 2pp 18584 016 24X Fiche 50-289,83/05/23,
8305250202

--8305250225 Response opposing NRC brief on review of ALAB-698 Commission should dismiss 830321 petition for review & affirm ALAB-698, authorizing licensee to organize & staff emergency response facility
ZAHLER,R E Metropolitan Edison Co ZAHLER,R E Shaw, Pittman, Potts & Trowbridge 83/05/23 Commissioners 43pp 18584 022,
24X Fiche 50-289,83/05/23,8305250202

8305250324 Order permitting parties to restart proceeding to submit written comments on NRC "Rept on Insp & Review Effort to Revalidate NRC Staff Position re Hartman Allegations" & on 830524 meeting,by 830531 & 830603,respectively
CHILK,S J Office of the Secretary of the Commission 83/05/23
Metropolitan Edison Co 3pp 18592 032 24X Fiche 50-289,83/05/23,
8305250324

8305270604 Decision ALAB-729,permitting restart subj to Commission determination re safety of facility operation w/o endangering public
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 83/05/26
223pp 18643 148 24X Fiche 50-289,83/05/26,8305270604

O Advisory Committee on Reactor Safeguards reports & correspondence

8305180620 Summary of ACRS Subcommittees on Metal Components & TMI-1 830128 meeting in Washington,DC re review of potential steam generator generic requirements & current steam generator repair program
* ACRS - Advisory Committee on Reactor Safeguards 83/04/12
ACRS - Advisory Committee on Reactor Safeguards 19pp 18504 001
24X Fiche 50-289,83/04/12,8305180620

Operating license stage documents & correspondence

8305230402 Forwards info on costs incurred from backfitting & upgrading facilities,per 830210 request Mods categorized NRC-required, TMI-lessons learned or util-initiated
DIECKAMP,H General Public Utilities - GPU Service Corp 83/03/08
TOURTELLOTTE,J Regulatory Reform Task Force 9pp 18576,318 24X
Fiche 50-000,83/03/08,8305230402

305270022 Forwards "Rept on Mental Health Effects of TMI Accident "
BROMET,E J Pittsburgh, Univ of 83/03/08 SHANKMAN,S F Site Analysis Branch 1p 18634 001 24X Fiche 50-320,83/03/08,
8305270022

-8305270035 "Psychological Stress Among TMI Area Residents & Mediation of Response by Support & Coping "
BAUM,A , SCHAEFFER,M A , COLLINS,D L Uniformed Services Univ of the Health Sciences NRC-03-82-125 83/03/08 NRC - No Detailed Affiliation Given 34pp 18634 088 24X
Fiche 50-320,83/03/08,8305270022

--8305270040 Forwards final rept, "Reanalysis of TMI Telephone Survey Data "
HOUTS,P S Pennsylvania State Univ NRC-03-82-123 83/03/01
REGAN,W NRC - No Detailed Affiliation Given 1p 18634 122
24X Fiche 50-320,83/03/08,8305270022

--8305270046 "Reanalysis of TMI Telephone Survey Data," final rept
HOUTS,P S , MILLER,R W , LINDELL,M Pennsylvania State Univ
83/02/28 NRC - No Detailed Affiliation Given 125pp
18634 123 24X Fiche 50-320,83/03/08,8305270022

--8305270048 Draft "Restarting TMI-1 Social & Psychological Impacts on Communities "
SORENSEN,J , SODERSTROM,J Oak Ridge National Laboratory
BOLIN,R New Mexico State Univ 83/03/08 NRC - No Detailed Affiliation Given 207pp 18634 248 24X Fiche 50-320,83/03/08,
8305270022

8305090351 Forwards EH Gischel affidavit & memo re allegations on safety-related mods & tests, Investigation underway
ARNOLD,R C General Public Utilities - GPU Service Corp 83/04/04
BARRETT,L General Public Utilities - GPU Service Corp 25pp
18367 220 24X Fiche 50-289,83/04/04,8305090351

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305110513 Board Notification BN-83-34A provides util response to NRC 830304 ltr re resolution of TMI Action Item II.K 3 5, "Automatic Trip of Reactor Coolant Pumps "
EISENHUT,D G Division of Licensing 83/04/28 PALLADINO,N ,
GILINSKY,V , AHEARNE,J Commissioners 4pp 18416 345 24X
Fiche 50-289,83/04/28,8305110513

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda,MD to discuss core barrel failure at Rancho Seco & Crystal River 3,future plans for resolving problem & justification for continued operation
MINER,R Operating Reactors Branch 4 83/05/02 STOLZ,J
Operating Reactors Branch 4 2pp 18353 092 24X
Fiche 50-000,83/05/02,8305060365

8305060394 Requests Data Design Lab,Inc be approved as consultant to perform 2-yr probationary in-depth audit of qualification & requalification training & testing program required by ASLB 820728 partial initial decision
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/03
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
18343,166 24X Fiche 50-289,83/05/03,8305060394

8305090453 Advises that all info requested by NRC re environ qualification technical evaluation rept provided in util 820302,0324 & 0623 ltrs Addl info to resolve Category IV items will be provided upon request
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/03
STOLZ,J F Operating Reactors Branch 4 1p 18362 353 24X
Fiche 50-289,83/05/03,8305090453

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N
Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,
8305040323

8305180099 Forwards Amend 85 to License DPR-50,safety evaluation & notice of issuance & availability Amend permits controlling explosive gas mixtures in waste holdup sys by limiting hydrogen to 2% by vol w/o limit on oxygen concentration
STOLZ,J F Operating Reactors Branch 4 83/05/05 HUKILL,H D
General Public Utilities - GPU Service Corp 5pp 18503 287 24X
Fiche 50-289,83/05/05,8305180099

--8305180104 Amend 85 to License DPR-50,permitting controlling explosive gas mixtures in waste holdup sys by limiting hydrogen to 2% by vol w/o limit on oxygen concentration
STOLZ,J F Operating Reactors Branch 4 83/05/05 4pp
18503 292 24X Fiche 50-289,83/05/05,8305180099

--8305180126 Safety evaluation supporting Amend 85 to License DPR-50
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18503 296 24X Fiche 50-289,83/05/05,8305180099

--8305180128 Notice of issuance & availability of Amend 85 to License DPR-50
STOLZ, J F Operating Reactors Branch 4 83/05/05 2pp
18503 298 24X Fiche 50-289, 83/05/05, 8305180099

8305120055 Forwards Training Procedure 6210-ADM-2604 01, Rev 1-00, "Control of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02, Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program "
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/06
STOLZ, J F Operating Reactors Branch 4 1p 18428 233 24X
Fiche 50-289, 83/05/06, 8305120055

--8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 01, "Control of Exams for Units 1 & 2 "
* General Public Utilities - GPU Service Corp 83/04/26 7pp
18428 234 24X Fiche 50-289, 83/05/06, 8305120055

--8305120068 Rev 1-00 to Training Procedure 6210-ADM-2610 02, "Operator Training Instructors & Supervisors "
* General Public Utilities - GPU Service Corp 83/04/26 16pp
18428 241 24X Fiche 50-289, 83/05/06, 8305120055

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130065 Forwards application for amend to License DPR-50, including Tech Spec Change Request 125 Amend permits non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/09
STOLZ, J F Operating Reactors Branch 4 2pp 18437 034 24X
Fiche 50-289, 83/05/09, 8305130065

--8305130070 Application to amend App A of License DPR-50, including Tech Spec Change Request 125 Amend permits non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators
HUKILL, H D General Public Utilities - GPU Service Corp
83/05/09 2pp 18437 036 24X Fiche 50-289, 83/05/09, 8305130065

--8305130074 Tech Spec Change Request 125 permitting non-nuclear heatup for precritical testing & subsequent operation using repaired steam generators
* General Public Utilities - GPU Service Corp 83/05/09 7pp
18437 038 24X Fiche 50-289, 83/05/09, 8305130065

8305170105 Notification of 830517 meeting w/util & C-E in Bethesda, MD to discuss aspects of steam generator repair, including leak test results, PORV & pressurizer corrosion & third-party review
SILVER, H Operating Reactors Branch 4 83/05/13 STOLZ, J F
Operating Reactors Branch 4 2pp 18495 345 24X
Fiche 50-289, 83/05/13, 8305170105

8305190158 Clarifies 830331 ltr re reactor coolant pump trip on 25 F subcooling margin w/respect to qualification of saturation margin monitor sys Sys evaluated per Generic Ltr 82-33 & 830415 ltr Schedule for instrumentation upgrading unknown
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/13
EISENHUT, D. G Division of Licensing 1p 18502 239 24X
Fiche 50-289, 83/05/13, 8305190158

8305180277 Forwards two consultant repts & ltrs prepared for GPU mgt re mgt competence phase Ltrs clarify repts Svc list encl
BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L
Metropolitan Edison Co 83/05/16 EDLES, G J , BUCK, J H , KOHL, C N
Atomic Safety and Licensing Appeal Panel 211pp 18490 071 24X
Fiche 50-289, 83/05/16, 8305180277

8305200502 Forwards master lists & sys component evaluation worksheets for NUREG-0737 environ qualification of electrical equipment mods installed in harsh area
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/16
STOLZ, J F Operating Reactors Branch 4 83pp 18513 082 24X
Fiche 50-289, 83/05/16, 8305200502

8305240028 Notification of 830518 meeting w/util in Bethesda, MD to discuss steam generator repair aspects of leak test & eddy current test results & PORV & pressurizer corrosion.
SILVER, H Operating Reactors Branch 4 83/05/16 STOLZ, J F.
Operating Reactors Branch 4 2pp 18577 330 24X
Fiche 50-289, 83/05/16, 8305240028

8305200173 Forwards Rev 1 to "Steam Generator Tube Rupture Procedure Guidelines," technical data rept
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/17.
STOLZ, J F Operating Reactors Branch 4 1p 18519 004 24X
Fiche 50-289, 83/05/17, 8305200173

--8305200179 Rev 1 to Procedure TDR 406, "Steam Generator Tube Rupture Procedure Guidelines," technical data rept
* General Public Utilities - GPU Service Corp 83/05/08 59pp
18519 005 24X Fiche 50-289, 83/05/17, 8305200173

8305200632 Forwards NRC 830519 memo to Commission re results of NRC revalidation of NRC position on mgt integrity issues
GOLDBERG, J R Hearing Branch 2 83/05/19 EDLES, G J , KOHL, C N ,
BUCK, J H Atomic Safety and Licensing Appeal Panel 4pp
18520 125 24X Fiche 50-289, 83/05/19, 8305200632

8305250588 Responds to 830415 staff requirements memo re schedule for decision on license amend request to permit operation of steam generators Schedule for decision contingent upon outcome of significant hazards determination
DIRCKS, W J Office of the Executive Director for Operations
83/05/19 CHILK, S J Office of the Secretary of the Commission
9pp 18594 337 24X Fiche 50-289, 83/05/19, 8305250588

--8305250590 Staff requirements memo re 830415 briefing on status of TMI-1 steam generator repairs Commission requested info on differing dates for decision on license amend request depending on significant hazards determination
CHILK, S J Office of the Secretary of the Commission 83/04/25
DIRCKS, W J Office of the Executive Director for Operations 1p
18594 346 24X Fiche 50-289, 83/05/19, 8305250588

8305250269 Forwards Suppl 1 to, "Rept of Third-Party Review of TMI-1, Steam Generator Repair "
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/20
STOLZ, J F Operating Reactors Branch 4 2pp 18592 302 24X
Fiche 50-289, 83/05/20, 8305250269

--8305250271 Suppl 1 to, "Rept of Third-Party Review of TMI-1, Steam Generator Repair "
BROWN, S D , HOLLAND, S A , KALNINS, A General Public Utilities -
GPU Service Corp 83/05/16 22pp 18592 304 24X
Fiche 50-289, 83/05/20, 8305250269

8305260094 Provides info identifying electrical equipment important to safety within scope of 10CFR50 49(g) already qualified Schedules for qualification of post-accident instrumentation encl
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp
18599 314 24X Fiche 50-289, 83/05/20, 8305260094

8305310205 Advises that installation of two Controlotron sonic flow devices on each flow path to once-through steam generators satisfies requirements of restart SER (NUREG-0680), 811214 partial initial decision & NUREG-0737, Item II E 1
HUKILL, H D General Public Utilities - GPU Service Corp 83/05/24
STOLZ, J F Operating Reactors Branch 4 1p 18658 139 24X
Fiche 50-289, 83/05/24, 8305310205

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "DWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020226 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-289/83-05
STAROSTECKI, R Division of Project & Resident Programs 83/04/26
HUKILL, H D General Public Utilities - GPU Service Corp 2pp
18277 296 24X Fiche 50-289, 83/04/26, 8305020226

--8305020232 Responds to NRC 830314 ltr re violations noted in IE Insp Rept 50-289/83-05 Corrective actions formal action items re steam generator tube repair program issued w/date extensions
HUKILL,H D General Public Utilities - GPU Service Corp
83/04/13 Region 1, Office of Director 3pp 18277 298 24X
Fiche 50-289,83/04/26,8305020226

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 116pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305110331 Forwards IE Insp Rept 50-289/83-07 on 830321-24 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/04/29
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
18406 165 24X Fiche 50-289,83/04/29,8305110331

--8305110338 IE Insp Rept 50-289/83-07 on 830321-24 No noncompliance noted Major areas inspected licensee actions & program to repair steam generators A & B
GRAY,E , REYNOLDS,S , DURR,J P Region 1, Office of Director
83/04/22 6pp 18406 167 24X Fiche 50-289,83/04/29,8305110331

8305160194 Forwards IE Insp Rept 50-289/83-08 on 830228-0329 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/02
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
18445 128 24X Fiche 50-289,83/05/02,8305160194

--8305160199 IE Insp Rept 50-289/83-08 on 830228-0329 No noncompliance noted Major areas inspected licensee action on previous insp findings,plant operation,LERs & restart mods
CONTE,R , BARR,K , O'NEILL,B Region 1, Office of Director
83/04/29 11pp 18445 130 24X Fiche 50-289,83/05/02,8305160194

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250495 Forwards IE Insp Rept 50-289/83-09 on 830328-0408 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/05/13
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
18627 001 24X Fiche 50-289,83/05/13,8305250495

--8305250500 Notice of violation from insp on 830328-0408
Region 1, Office of Director 83/05/13 2pp 18627 003 24X
Fiche 50-289,83/05/13,8305250495

--8305250505 IE Insp Rept 50-289/83-09 on 830328-0408 Noncompliance noted failure to reset feeder breakers to safeguards busses & failure to adequately inspect piping
BISSETT,P , COGAN,N , GREGG,H Region 1, Office of Director
83/05/11 9pp 18627 005 24X Fiche 50-289,83/05/13,8305250495

8305230455 Forwards IE Insp Rept 50-289/83-10 on 830420-22 & 25-28 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/05/17
HUKILL,H D General Public Utilities - GPU Service Corp 2pp
18647 001 24X Fiche 50-289,83/05/17,8305230455

--8305230460 IE Insp Rept 50-289/83-10 on 830420-22 & 25-28 No noncompliance noted Major areas inspected conduct of operations procedures & training program re procedural adherence for new employees & requalification program
ALLENSPACH,F R , CAPHTON,D L , COGAN,N J Region 1, Office of Director 83/05/16 67pp 18537 200 24X Fiche 50-289,83/05/17,8305230455

8305250183 Forwards IE Insp Rept 50-289/83-10 on 830420-22 & 25-28 Joint headquarters/Region I insp initiated to evaluate effectiveness of GPU actions to ensure adherence to procedures since issuance of NUREG-0080,Suppl J
REHM,T A Office of the Executive Director for Operations
83/05/18 PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners
1p 18596 001 24X Fiche 50-289,83/05/18,8305250183

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260085 Responds to IE Bulletin 82-04, "Deficiencies in Primary Containment Electrical Penetration Assemblies " No electrical primary containment penetrations mfg by Bunker Ramo Co in use at facility
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/20
Region 1, Office of Director 1p 18599 308 24X
Fiche 50-289,83/05/20,8305260085

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305020210 Forwards "TMI Aquatic Study,Monthly Rept for Mar 1983 "
RESSLER,W C General Public Utilities - GPU Service Corp 83/04/28
HICKEY,C NRC - No Detailed Affiliation Given 1p 18278 167
24X Fiche 50-289,83/04/28,8305020210

--8305020215 "TMI Aquatic Study,Monthly Rept for Mar 1983 "
NARDACCI,G A Ichthyological Associates, Inc 83/04/28 21pp
18278 168 24X Fiche 50-289,83/04/28,8305020210

8305060458 Forwards "Annual Environ Operating Rept,1982," "Ecological Study of Susquehanna River Near TMI" & "Hydraulic Survey "
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18349 058 24X
Fiche 50-289,83/04/29,8305060458

--8305060460 "Annual Environ Operating Rept,1982 "
General Public Utilities - GPU Service Corp 82/12/31 18pp
18349 060 24X Fiche 50-289,83/04/29,8305060458

--8305060464 "Hydraulic Survey," annual rept
General Public Utilities - GPU Service Corp 82/06/03 13pp
18349 078 24X Fiche 50-289,83/04/29,8305060458

--8305060465 "Ecological Study of Susquehanna River Near TMI," annual rept for 1982
NARDACCI,G A Ichthyological Associates, Inc 83/04/30 633pp
18349 091 24X Fiche 50-289,83/04/29,8305060458

8305060649 Forwards "TMI Nuclear Station Radiological Environ Monitoring Rept,1982 " W/o encl
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18348 250 24X
Fiche 50-289,83/04/29,8305060649

8305270203 "Changes to Sys & Procedures Described in FSAR per 10CFR50 59 "
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/10
HAYNES,R C Region 1, Office of Director 17pp 18637 244 24X
Fiche 50-289,83/05/10,8305270203

8305190240 Forwards monthly operating rept for Apr 1983
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/13
MCDONALD,W C Office of Resource Management, Director 1p
18501 304 24X Fiche 50-289,83/05/13,8305190240

--8305190247 Monthly operating rept for Apr 1983
SMYTH,C W General Public Utilities - GPU Service Corp 83/05/13
10pp 18501 305 24X Fiche 50-289,83/05/13,8305190240

S Reportable occurrences, LERs & related correspondence

8305030436 RO 83-11 on 830326,DHR 1A shaft bearings failed,making pump inoperable Caused by design change to pump bearing lube oil sys Sys returned to original configuration Review of existing sys in progress
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/18
Region 1, Office of Director 2pp 18306 272 24X
Fiche 50-289,83/04/18,8305030436

8305030095 Forwards LER 83-006/03L-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/19
Region 1, Office of Director 1p 18300 344 24X
Fiche 50-289,83/04/19,8305030095

--8305030127 LER 83-006/03L-0 on 830320,no flow existed through hydrogen & oxygen rotameters of waste gas sys analyzer Caused by dirt blockage in regulator & flow setting Pump discharge pressure regulator setting raised
SZCZECH,R A General Public Utilities - GPU Service Corp
83/04/19 Region 1, Office of Director 3pp 18300 345 24X
Fiche 50-289,83/04/19,8305030095

8305030102 Forwards LER 83-010/03L-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/20
Region 1, Office of Director 1p 18300 340 24X
Fiche 50-289,83/04/20,8305030102

--8305030112 LER 83-010/03L-0 on 830321,waste gas sys Hays gas analyzer alarm indicated incorrect concentration of oxygen Caused by dirty amplifier low channel gain potentiometer & switch contacts Components cleaned
SZCZECH,R A General Public Utilities - GPU Service Corp
83/04/20 Region 1, Office of Director 3pp 18300 341 24X
Fiche 50-289,83/04/20,8305030102

8305110346 Forwards LER 83-007/03L-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/25
Region 1, Office of Director 1p 18406 140 24X
Fiche 50-289,83/04/25,8305110346

--8305110351 LER 83-007/03L-0 on 830325,automatic termination & alarm failed to occur when dilution flow fell below min setpoint during liquid effluent release Caused by sticking of trip interlock pneumatic relay Procedures modified
SZCZECH,R A General Public Utilities - GPU Service Corp
83/04/25 Region 1, Office of Director 2pp 18406 141 24X
Fiche 50-289,83/04/25,8305110346

8305030534 PNO-I-83-039 small fire occurred beneath auxiliary boiler A located in turbine bldg Caused by small amount of oil on concrete pad Fire extinguished using hand extinguisher
CONTE,R , KEIMIG,R Region 1, Office of Director 83/04/26 1p
18308 190 24X Fiche 50-289,83/04/26,8305030534

8305030094 PNO-I-83-040 on 830428,protesters arrived at north gate Gate closed & access established through south gate No press release planned
CONTE,R , KEIMIG,R Region 1, Office of Director 83/04/28 1p
18300 179 24X Fiche 50-289,83/04/28,8305030094

8305110286 Forwards LER 83-009/03L-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18393 251 24X
Fiche 50-289,83/04/29,8305110286

--8305110287 LER 83-009/03L-0 on 830330,during surveillance/calibr of waste gas sys,Hays gas analyzer,oxygen meter failed to respond to calibr gas Cause unknown Maint checks performed & circuit components cleaned
SZCZECH,R A General Public Utilities - GPU Service Corp
83/04/29 Region 1, Office of Director 2pp 18393 252 24X
Fiche 50-289,83/04/29,8305110286

8305110333 Forwards LER 83-011/01T-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18406 173 24X
Fiche 50-289,83/04/29,8305110333

--8305110342 LER 83-011/01T-0 on 830415,while in long-term shutdown DH-P1A shaft bearings failed,making pump inoperable Caused by improperly authorized mod to component & inadequate mod set up Pump repaired Maint job tickets reviewed
STEPHENSON,C J General Public Utilities - GPU Service Corp
83/04/29 Region 1, Office of Director 3pp 18406 174 24X
Fiche 50-289,83/04/29,8305110333

8305200547 Forwards LER 83-012/03L-0
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/06
Region 1, Office of Director 1p 18515 360 24X
Fiche 50-289,83/05/06,8305200547

--8305200551 LER 83-012/03L-0 on 830406 while performing functional testing of hydraulic snubbers,snubber MS-209 failed to lock in tension direction Caused by damaged piston seal ring Snubber overhauled & tested satisfactorily
SZCZECH,R A General Public Utilities - GPU Service Corp
83/05/06 Region 1, Office of Director 3pp 18515 361 24X
Fiche 50-289,83/05/06,8305200547

T Hearing transcripts on non-antitrust matters

8305310071 Transcript of Commission 830524 briefing in Washington,DC re NRC revalidation of mgt competence for restart Pp 1-57 Viewgraphs encl
* Commissioners 83/05/24 73pp 18663 025 24X
Fiche 50-289,83/05/24,8305310071

U Congressional,Executive Correspondence

8305230703 Urges resolution of remaining questions re facility restart Delay in resolving restart issue unacceptable when jobs at stake Restart issue should receive high priority this Spring
BROYHILL,J T , MOORHEAD,C J , RITTER,D House of Rep , Energy & Commerce 83/03/16 PALLADINO,N Commissioners 3pp 18542 317
24X Fiche 50-289,83/03/16,8305230703

8305040138 Forwards proposed Chairman testimony before Udall Subcommittee 830406 hearing re developments since Apr 1982 at TMI,responding to items in Congressman Udall 830413 ltr W/o proposed testimony
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/04/20 DIRCKS,W J Office of the Executive Director for Operations 2pp 18327 011 24X Fiche 50-289,83/04/20,8305040138

--8305040145 Enumerates items to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982
UDALL,M K House of Rep , Interior & Insular Affairs 83/04/13
PALLADINO,N Commissioners 2pp 18327 013 24X
Fiche 50-289,83/04/20,8305040138

8305230435 Forwards response to Question 20 in 830223 ltr re NRC review of B&W/GPU trial record
PALLADINO,N J Commissioners 83/04/28 UDALL,M K House of Rep , Interior & Insular Affairs 2pp 18542 051 24X
Fiche 50-289,83/04/28,8305230435

--8305230440 Informs of dissenting opinion re Commission majority decision blocking General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Decision will hamper ability of individual Commissioners to obtain needed info
GILINSKY,V Commissioners 83/04/07 SIMPSON,A K Senate, Environment & Public Works 2pp 18542 053 24X
Fiche 50-289,83/04/28,8305230435

--8305230443 Responds to Chairman Palladino 830309 request for views on legality of Commission decision directing Executive Director for Operations,rather than Ofc of General Counsel, to review B&W/GPU trial record Actions supported
PLAINE,H H E Office of the General Counsel 83/03/25
PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 5pp
18542 055 24X Fiche 50-289,83/04/28,8305230435

--8305230446 Provides Commission response to Commissioner Gilinsky 830407 ltr disagreeing w/Commission majority decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Commission actions justified
PALLADINO,N J Commissioners 83/04/19 UDALL,M K House of Rep , Interior & Insular Affairs 4pp 18542 060 24X
Fiche 50-289,83/04/28,8305230435

--8305230453 Disagrees w/Commission majority views in Chairman Palladino 830419 ltr justifying Commission decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding
ASSELSTINE,J K Commissioners 83/04/25 UDALL,M K House of Rep , Interior & Insular Affairs 3pp 18542 064 24X
Fiche 50-289,83/04/28,8305230435

8305230377 Responds to questions in 830323 ltr re steam generator tube rupture scenario at TMI-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items provided on 830325
PALLADINO,N J Commissioners 83/05/05 MARKEY,E J House of Rep , Interior & Insular Affairs 8pp 18683 307 24X
Fiche 50-289,83/05/05,8305230377

--8305230388 Requests further response to issues in 830121 ltr re steam generator tube degradation at TMI-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items also requested
MARKEY,E J House of Rep , Interior & Insular Affairs 83/03/23
PALLADINO,N J Commissioners 2pp 18542 019 24X
Fiche 50-289,83/05/05,8305230377

V Operator Examinations

8305120055 Forwards Training Procedure 6210-ADM-2604 01,Rev 1-00, "Control of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02,Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program "
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/06
STOLZ,J F Operating Reactors Branch 4 1p 18428 233 24X
Fiche 50-289,83/05/06,8305120055

--8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 01, "Control of Exams for Units 1 & 2 "
* General Public Utilities - GPU Service Corp 83/04/26 7pp
18428 234 24X Fiche 50-289,83/05/06,8305120055

DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305050144 Forwards IE Insp Rept 50-293/83-05 on 830301-04 No noncompliance noted
MARTIN,T T Division of Engineering & Technical Programs 83/04/20
HARRINGTON,W D Boston Edison Co 2pp 18342 203 24X
Fiche 50-293,83/04/20,8305050144

--8305050151 IE Insp Rept 50-293/83-05 on 830301-04 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal performed on 810713-24 & public notification sys
SMITH,R , MILLER,M T , CROCKER,H W Region 1, Office of Director
83/04/12 17pp 18342 205 24X Fiche 50-293,83/04/20,8305050144

8305020056 Responds to 830128 ltr forwarding Rev 2 to safeguards contingency plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable
VASSALLO,D B Operating Reactors Branch 2 83/04/22 MORISI,A V
Boston Edison Co 1p 18308 288 24X Fiche 50-293,83/04/22,
8305020056

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305170173 Provides schedule for changes to Tech Specs addressing fire protection issues re smoke detection,Halon sys & alternate shutdown panels
HARRINGTON,W D Boston Edison Co 83/05/13 VASSALLO,D B
Operating Reactors Branch 2 3pp 18466 318 24X
Fiche 50-293,83/05/13,8305170173

8305230450 Resubmits requests for App R technical & schedular exemptions,per 830329 meeting w/NRC W/three overslze figures Aperture cards are available in PDR
HARRINGTON,W D Boston Edison Co 83/05/17 VASSALLO,D B
Operating Reactors Branch 2 36pp 18537 267 24X
Fiche 50-293,83/05/17,8305230450

8305240571 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18
HARRINGTON,W D Boston Edison Co 3pp 18594 217 24X
Fiche 50-293,83/05/18,8305240571

General correspondence

8305130153 Requests that WD Harrington be primary recipient of all NRC correspondence re License DPR-35 AV Morisi should be added to list for future correspondence addressed to WD Harrington & RD Machon & CJ Mathis should be deleted from list
HARRINGTON,W D Boston Edison Co 83/05/09 VASSALLO,D B
Operating Reactors Branch 2 2pp 18437 176 24X
Fiche 50-293,83/05/09,8305130153

J Insurance & indemnity information

8305120059 Forwards Endorsements 77 & 61 to NELIA Policy NF-188 & MAELU Policy MF-58,respectively
SINISI,J M Marsh & McLennan, Inc 83/05/09 SALTZMAN,J D
Assistant Director for State & Licensee Relations 3pp 18423 055
24X Fiche 50-293,83/05/05,8305120059

P Operating license stage documents & correspondence

8304180590 Forwards response to questions re single recirculation loop operation at facility
HARRINGTON,W D Boston Edison Co 83/04/11 VASSALLO,D B
Licensing Branch 2 3pp 17999 212 24X Fiche 50-293,83/04/11,
8304180590

8305040295 Summary of 830414 meeeting w/util re plans concerning long-term program for scheduling necessary work items Viewgraphs encl
ECCLESTON,K T Operating Reactors Branch 2 83/04/21
VASSALLO,D B Operating Reactors Branch 2 37pp 18327 032 24X
Fiche 50-293,83/04/21,8305040295

8305060266 Forwards Amend 68 to License DPR-35,safety evaluation & notice of issuance & availability Amend reflects installation of alarm switches on torus drywell vacuum breakers
ECCLESTON,K T Operating Reactors Branch 2 83/04/22 MORISI,A V
Boston Edison Co 2pp 18359 332 24X Fiche 50-293,83/04/22,
8305060266

--8305060279 Amend 68 to License DPR-35,changing Tech Specs & associated bases to reflect installation of alarm switches on torus drywell vacuum breakers
VASSALLO,D B Operating Reactors Branch 2 83/04/22 8pp
18359 334 24X Fiche 50-293,83/04/22,8305060266

--8305060287 Safety evaluation supporting Amend 68 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 83/04/22 2pp
18359 342 24X Fiche 50-293,83/04/22,8305060266

--8305060291 Notice of issuance & availability of Amend 68 to License DPR-35
VASSALLO,D B Operating Reactors Branch 2 83/04/22 2pp
18359 344 24X Fiche 50-293,83/04/22,8305060266

8305120163 Forwards Amend 69 to License DPR-35,safety evaluation & notice of issuance & availability Amend incorporates revs to reflect organizational changes re nuclear activities,both onsite & offsite
ECCLESTON,K T Operating Reactors Branch 2 83/04/26 MORISI,A V
Boston Edison Co 2pp 18435 266 24X Fiche 50-293,83/04/26,
8305120163

--8305120169 Amend 69 to License DPR-35,incorporating revs to reflect organizational changes re nuclear activities,both onsite & offsite
VASSALLO,D B Operating Reactors Branch 2 83/04/26 13pp
18435 268 24X Fiche 50-293,83/04/26,8305120163

--8305120180 Safety evaluation supporting Amend 69 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 83/04/26 6pp
18435 281 24X Fiche 50-293,83/04/26,8305120163

--8305120187 Notice of issuance & availability of Amend 69 to License DPR-35
VASSALLO,D B Operating Reactors Branch 2 83/04/26 2pp
18435 287 24X Fiche 50-293,83/04/26,8305120163

8305090200 Forwards response to NUREG-0737 Item II K 3 13, "RCIC Automatic Restart " RCIC sys modified such that reactor high water level signal will automatically close RCIC turbine steam supply valve,should valve be open
HARRINGTON,W D Boston Edison Co 83/04/29 VASSALLO,D B
Operating Reactors Branch 2 1p 18363 361 24X
Fiche 50-293,83/04/29,8305090200

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305180197 Forwards Amend 70 to License DPR-35,safety evaluation & notice of issuance & availability.Amend revises Tech Specs to change critical power ratio limits & to increase safety relief valve simmer margin
ECCLESTON,K T Operating Reactors Branch 2 83/05/03 MORISI,V A
Boston Edison Co 2pp 18503 333 24X Fiche 50-293,83/05/03,
8305180197

--8305180204 Amend 70 to License DPR-35, revising Tech Specs to change min critical power ratio limits & to increase safety relief valve simmer margin
VASSALLO, D B Operating Reactors Branch 2 83/05/03 5pp
18503 335 24X Fiche 50-293, 83/05/03, 8305180197

--8305180216 Safety evaluation supporting Amend 70 to License DPR-35
* Office of Nuclear Reactor Regulation, Director 83/05/03 1p
18503 340 24X Fiche 50-293, 83/05/03, 8305180197

--8305180229 Notice of issuance & availability of Amend 70 to License DPR-35
ROONEY, V L Operating Reactors Branch 2 83/05/03 2pp
18503 341 24X Fiche 50-293, 83/05/03, 8305180197

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305160044 Requests rescheduling of completion date for torus internal mods re torus catwalk extension support legs & ring girder/shell weld near T-quenchers to 850221
HARRINGTON, W D Boston Edison Co 83/05/10 VASSALLO, D B
Operating Reactors Branch 2 3pp 18453 013 24X
Fiche 50-293, 83/05/10, 8305160044

8305160061 Requests that completion date for scram discharge vol mods be modified to 830223 Info to support schedular relief discussed
HARRINGTON, W D Boston Edison Co 83/05/10 VASSALLO, D B
Operating Reactors Branch 2 2pp 18451 045 24X
Fiche 50-293, 83/05/10, 8305160061

8305260175 Forwards request for addl info re NUREG-0737, Item II K 3 28 on qualification of automatic depressurization sys accumulators Response within 45 days requested
VASSALLO, D B Operating Reactors Branch 2 83/05/11 MORISI, A V
Boston Edison Co 3pp 18648 110 24X Fiche 50-293, 83/05/11, 8305260175

8305170345 Notifies that response to 28 questions re "Mark I Containment Long-Term Program - Plant Unique Analysis Rept - Structural Evaluation," delayed until 830722, per 830429 & 0505 telcons
HARRINGTON, W D Boston Edison Co 83/05/13 VASSALLO, D B
Operating Reactors Branch 2 1p 18465 122 24X
Fiche 50-293, 83/05/13, 8305170345

8305170418 Responds to 830202 request for plant-unique calculations forming bases for mods to vacuum breakers on Mark I containments or justifications for as-built acceptability, per Generic Ltr 83-08 Mod schedule discussed
HARRINGTON, W D Boston Edison Co 83/05/13 EISENHUT, D G
Division of Licensing 2pp 18469 288 24X Fiche 50-293, 83/05/13, 8305170418.

8305190147 Discusses issuance of revised policy statement re util position on NUREG-0737, Item I C 6, "Verify Performance of Operating Experience " Policy will be integrated into existing operations procedure by 830812
HARRINGTON, W D Boston Edison Co 83/05/13 VASSALLO, D B
Operating Reactors Branch 2 1p 18502 070 24X
Fiche 50-293, 83/05/13, 8305190147

8305240560 Informs that NUREG-0737, Item II F 1, "Containment High Range Radiation Monitor," completed Item closed Safety evaluation encl
VASSALLO, D B Operating Reactors Branch 2 83/05/13 MORISI, A V
Boston Edison Co 4pp 18593 356 24X Fiche 50-293, 83/05/13, 8305240560

8305200447 Provides commitment in response to final rule re environ qualification of safety-related electrical equipment Qualification plan encl
HARRINGTON, W D Boston Edison Co 83/05/17 VASSALLO, D B
Operating Reactors Branch 2 11pp 18516 092 24X
Fiche 50-293, 83/05/17, 8305200447

8305200259 Submits justification for continued operation until environ qualification of equipment in Categories I b, II a & IV qualified, per 830413 request Info requested on safety evaluation items will be addressed in future ltr
HARRINGTON, W D Boston Edison Co 83/05/18 VASSALLO, D G
Operating Reactors Branch 2 184pp 18518 177 24X
Fiche 50-293, 83/05/18, 8305200259

8305260130 Informs that NUREG-0737, Item II K 3 45 re depressurization w/other than automatic depressurization sys would not contribute to plant safety & no plant design or operation mod required Safety evaluation encl
VASSALLO, D B Operating Reactors Branch 2 83/05 18
HARRINGTON, W D Boston Edison Co 2pp 18649 052 24X
Fiche 50-293, 83/05/18, 8305260130

8305260379 Requests remittance of two Class III fees for review of 830405 application to amend License DPR-35, changing max critical power ratio limits & increasing safety relief valve simmer margin
DIGGS, R M License Fee Management Branch 83/05/20 MORISI, A V
Boston Edison Co 1p 18647 250 24X Fiche 50-293 83/05/20, 8305260379

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305050144 Forwards IE Insp Rept 50-293/83-05 on 830301-04 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/04/20
HARRINGTON, W D Boston Edison Co 2pp 18342 203 24X
Fiche 50-293, 83/04/20, 8305050144

--8305050151 IE Insp Rept 50-293/83-05 on 830301-04 No noncompliance noted Major areas inspected followup of emergency preparedness items from prior appraisal performed on 810713-24 & public notification sys
SMITH, R , MILLER, M T , CROCKER, H W Region 1, Office of Director 83/04/12 17pp 18342 205 24X Fiche 50-293, 83/04/20, 8305050144

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305050250 Updates 830310 response to IE Bulletin 83-01, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " No check valves located in cooling water sys at facility Failure mechanism identified in bulletin not possible
HARRINGTON, W D Boston Edison Co 83/04/27 ALLAN, J Region 1, Office of Director 1p 18337 334 24X Fiche 50-293, 83/04/27, 8305050250

8305060029 Notification of significant licensee 830510 meeting in Boston, MA to discuss performance improvement program
ELSASSER, T C Region 1, Office of Director 83/04/27 Region 1, Office of Director 1p 18354 308 24X Fiche 50 293, 83/04/27, 8305060029

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305160137 Forwards IE Insp Rept 50-293/83-07 on 830322-0418 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/05/02
HARRINGTON, W D Boston Edison Co 2pp 18446 048 24X
Fiche 50-293, 83/05/02, 8305160137

--8305160139 Notice of violation from insp on 830322-0418
* Division of Project & Resident Programs 83/05/02 1p
18446 050 24X Fiche 50-293, 83/05/02 8305160137

--8305160142 IE Insp Rept 50-293/83-07 on 830322-0418 Noncompliance noted failure to implement station procedure for insp & cleaning of standby gas treatment sys inlet plenum
JOHNSON J , EICHENHOLZ,H Region 1, Office of Director
ELSASSER,T Division of Project & Resident Programs 83/04/28
15pp 18446 051 24X Fiche 50-293,83/05/02,8305160137

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 115pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 093 24X Fiche 50-000,83/05/11,8303040034

8305230429 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-03
STAROSTECKI,R Division of Project & Resident Programs 83/05/13
HARRINGTON,W D Boston Edison Co 1p 18538 215 24X
Fiche 50-293,83/05/13,8305230429

--8305230434 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-293/83-03 Corrective actions personnel counseled on procedural adherence re radiation samples not taken or counted & Memo CR 83-39 issued concerning nonadherence
HARRINGTON,W D Boston Edison Co 83/04/27 STAROSTECKI,R
Division of Project & Resident Programs 3pp 18538 216 24X
Fiche 50-293,83/05/13,8305230429

8305270073 Provides clarification re prior IE bulletin correspondence Inaccuracy due to brief review time allowed by IE Bulletin 80-01 No consequence to safety evident Expanded sampling of bulletin review being implemented
HARRINGTON,W D Boston Edison Co 83/05/13 ALLAN,J Region 1,
Office of Director 3pp 18638 282 24X Fiche 50-293,83/05/13,
8305270073

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

. Periodic operating reports & related correspondence

8305020134 Forwards photographic matl from 1981 & 82 annual main breakwater surveys Survey for 1983 in progress Aerial portion will be postponed while review of 830228 request in progress
HARRINGTON,W D Boston Edison Co 83/04/26 VASSALLO,D B
Operating Reactors Branch 2 1p 18278 218 24X
Fiche 50-293,83/04/26,8305020134

8305100138 Forwards "Marine Ecology Studies re Operation of Pilgrim Station,Semiannual Rept 21,1982 "
HARRINGTON,W D Boston Edison Co 83/04/29 Environmental
Protection Agency 2pp 18376 004 24X Fiche 50-293,83/04/29,
8305100138

--8305100144 "Marine Ecology Studies re Operation of Pilgrim Station, Semiannual Rept 21,1982 "
ANDERSON,R D , SCOTTON,L N Boston Edison Co NUCG-E1 83/04/30
414pp 18376 006 24X Fiche 50-293,83/04/29,8305100138

8305160134 Forwards "Environ Radiological Monitoring Program for 1982, Rept 15
HARRINGTON,W D Boston Edison Co 83/05/09 ALLAN,J Region 1,
Office of Director 1p 18447 231 24X Fiche 50-293,83/05/09,
8305160134

--8305160136 "Environ Radiological Monitoring Program 1982," Rept 15
* Boston Edison Co 83/04/30 158pp 18447 232 24X
Fiche 50-293,83/05/09,8305160134

8305230535 Forwards "NPDES Discharge Monitoring Rept,Jan-Mar 1983 "
MATHIS,C J Boston Edison Co 83/05/12 Environmental Protection
Agency MCMAHON,T C Massachusetts, Commonwealth of, 1p
18537 062 24X Fiche 50-293,83/05/12,8305230535

--8305230537 "NPDES Discharge Monitoring Rept,Jan-Mar 1983 "
MATHIS,C J Boston Edison Co 83/05/13 14pp 18537 064 24X
Fiche 50-293,83/05/12,8305230535

8305170529 Forwards monthly operating rept for Apr 1983
HARRINGTON,W D Boston Edison Co 83/05/13 Director's Office,
Office of Inspection and Enforcement 1p 18467 027 24X
Fiche 50-293,83/05/13,8305170529

--8305170532 Monthly operating rept for Apr 1983
WHITNEY,G G Boston Edison Co 83/05/13 6pp 18467 028 24X
Fiche 50-293,83/05/13,8305170529

S Reportable occurrences, LERs & related correspondence

8304110696 Forwards LER 83-010/03L-0
MATHIS,C J Boston Edison Co 83/03/24 HAYNES,R C Region 1,
Office of Director 1p 17914 059 24X Fiche 50-293,83/03/24,
8304110696

--8304110706 LER 83-010/03L-0 on 830222,two of four motor operator mounting cap screws found backed out of core spray valve MOV 1400-4A Caused by sys vibration Cap screws installed w/thread compound applied Redundant MOV 1400-4B inspected
WHITNEY,G G Boston Edison Co 83/03/24 Region 1, Office of
Director 2pp 17914 060 24X Fiche 50-293,83/03/24,8304110696

8305110334 Forwards LER 83-015/03L-0
HARRINGTON,W D Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 177 24X Fiche 50-293,83/04/25,8305110334

--8305110341 LER 83-015/03L-0 on 830331,standby gas treatment sys train opened w/o proving operability of redundant train Caused by miscommunication between insp crew & control room Need for proper communications emphasized
WHITNEY,G G Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 178 24X Fiche 50-293,83/04/25,8305110334

8305110356 Forwards LER 83-014/03L-0
HARRINGTON,W D Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 130 24X Fiche 50-293,83/04/25,8305110356

--8305110365 LER 83-014/03L-0 on 830329,drywell airborne leak detection sys (C-19) particulate channel found reading downscale Caused by loose connector pin Pin repaired & unit returned to svc
WHITNEY,G G Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 131 24X Fiche 50-293,83/04/25,8305110356

8305110384 Forwards LER 83-017/03L-0
HARRINGTON,W D Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 199 24X Fiche 50-293,83/04/25,8305110384

--8305110392 LER 83-017/03L-0 on 830403,drywell airborne leak detection sys (C-19) found inoperable Caused by overheated sample air due to improper thermostatic control of heat tracing for sample lines Lagging on lines removed
WHITNEY,G G Boston Edison Co 83/04/25 Region 1, Office of
Director 1p 18406 200 24X Fiche 50-293,83/04/25,8305110384

8305230516 Forwards LER 83-016/03L-0
HARRINGTON,W D Boston Edison Co 83/04/27 Region 1, Office of
Director 1p 18537 311 24X Fiche 50-293,83/04/27,8305230516

--8305230521 LER 83-016/03L-0 on 830402,overload annunciation received when MOV-220-2 switched open during scram recovery Probably caused by spurious annunciator from overload mechanism in Cutler-Hammer motor control ctr Valve returned to svc
WHITNEY,G G Boston Edison Co 83/04/27 Region 1, Office of
Director 1p 18537 312 24X Fiche 50-293,83/04/27,8305230516

8305160145 Telecopy LER 83-020/01X-0 on 830502, daily surveillance testing per Tech Spec Section 4 11 D not performed Caused by failure to revise procedures & inadvertent removal of sections from Tech Specs Procedures revised
GRAHAM, E T Boston Edison Co 83/05/02 Region 1, Office of Director 1p 18446 085 24X Fiche 50-293, 83/05/02, 8305160145

8305190024 Forwards LER 83-022/03L-0
HARRINGTON, W D Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18502 041 24X Fiche 50-293, 83/05/04, 8305190024

--8305190029 LER 83-022/03L-0 on 830413, overload on valve motor 1301-17 resulted in loss of high pressure core cooling backup capability Caused by oxidation in motor end bell & motor brushes, due to humidity caused by leaking valve packing
CROWDER, J D Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18502 042 24X Fiche 50-293, 83/05/04, 8305190024

8305230533 Forwards LER 83-018/03L-0
HARRINGTON, W D Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18537 060 24X Fiche 50-293, 83/05/04, 8305230533

--8305230538 LER 83-018/03L-0 on 830408, during insp standby gas treatment sys B heater contact & wiring found burnt, rendering sys inoperable Caused by high resistance due to loose wires at contactor terminal Contactor & wires replaced
GRAHAM, E T Boston Edison Co 83/05/04 Region 1, Office of Director 1p 18537 061 24X Fiche 50-293, 83/05/04, 8305230533

8305190176 Forwards LER 83-021/03L-0
HARRINGTON, W D Boston Edison Co 83/05/09 Region 1, Office of Director 1p 18502 257 24X Fiche 50-293, 83/05/09, 8305190176

--8305190181 LER 83-021/03L-0 on 830411, during Surveillance Test 8 7 4 3, primary containment isolation valve AO-5033B failed to meet 10-s closing time requirements Caused by lubricant infiltrating solenoid valve components Components replaced
BRIXEY, P Boston Edison Co 83/05/09 Region 1, Office of Director 2pp 18502 258 24X Fiche 50-293, 83/05/09, 8305190176

8305190326 Forwards updated LER 82-008/01X-1
HARRINGTON, W D Boston Edison Co 83/05/09 Region 1, Office of Director 1p 18500 318 24X Fiche 50-293, 83/05/09, 8305190326

--8305190330 Updated LER 82-008/01X-1 on 820331, HPCI injection valve MO-2301-8 failed to open in required manner Caused by missing wire jumper intended to bypass motor operator torque switch Jumper installed & valve tested satisfactorily
VENDER, J Boston Edison Co 83/05/09 Region 1, Office of Director 2pp 18500 319 24X Fiche 50-293, 83/05/09, 8305190326

8305230509 Forwards updated LER 83-014/03X-1
HARRINGTON, W D Boston Edison Co 83/05/09 Region 1, Office of Director 1p 18537 324 24X Fiche 50-293, 83/05/09, 8305230509

--8305230515 Updated LER 83-014/03X-1 on 830329, drywell airborne leak detection sys (C-19) particulate channel found reading downscale Caused by loose connector pin Pin repaired
WHITNEY, G G Boston Edison Co 83/05/09 Region 1, Office of Director 1p 18537 325 24X Fiche 50-293, 83/05/09, 8305230509

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305100122 Forwards post-exercise evaluation for 810729 exercise, final rept of reexercise on 811007 & final exercise rept of 830118 exercise No significant deficiencies cited
KRIMM, R W Federal Emergency Management Agency 83/04/08
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 2pp 18375 048 24X Fiche 50-295, 83/04/08, 8305100122

--8305100126 "Zion Nuclear Generating Station Small-Scale Joint Emergency Exercise, 830118," final rept
* Federal Emergency Management Agency 83/03/04 71pp
18375 050 24X Fiche 50-295, 83/04/08, 8305100122

--8305100131 "Zion Nuclear Power Station Reexercise, WI/Kenosha County (Small-Scale) 811007," final rept
* Federal Emergency Management Agency 82/04/30 32pp
18375 121 24X Fiche 50-295, 83/04/08, 8305100122

--8305100136 "Post-Exercise Evaluation, Exercise of State & Local Radiological Emergency Response Plans for IL & WI (Near Zion Nuclear Power Station) "
* Federal Emergency Management Agency 81/07/29 44pp
18375 153 24X Fiche 50-295, 83/04/08, 8305100122

830503007[illegible] Releases public version of Rev [illegible] emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18326 103 1K Fiche 50-295 83/04/22, 8305030076

--8305030081 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests "
PLIML G Commonwealth Edison Co 83/04/06 DENTON H R NRC - No Detailed Affiliation Given 1p 18326 104 24X Fiche 50-295, 83/04/22, 8305030076

--8305030091 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests " Procedure Change Request A-83-51 encl
NYKIRK, J W Commonwealth Edison Co 83/03/25 5pp 18326 105 24X Fiche 50-295, 83/04/22, 8305030076

8305030104 Releases public version of Rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Reports 83/04/22 Document Management Branch 1p 18309 354 24X Fiche 50-295, 83/04/22, 8305030104

--8305030114 Forwards public version of Re 11 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group "
PLIML G Commonwealth Edison Co 83/04/06 DENTON H R NRC - No Detailed Affiliation Given 1p 18309 355 24X Fiche 50-295 83/04/22, 8305030104

--8305030117 Public version of Rev 11 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group " Procedure Change Request A-83-88 encl
NYKIRK, J W Commonwealth Edison Co 83/04/25 7pp 18309 356 24X Fiche 50-295, 83/04/22 8305030104

8305060673 Releases public version of Rev [illegible] emergency plan implementing procedure
FELTON, J M Division of Rules and Reports 83/04/25 Document Management Branch 1p 18357 326 24X Fiche 50-295, 83/04/25 8305060673

--8305060679 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 550-2 "Division Emergency Kit & Emergency Operations Facility Radiological Equipment " Procedure change request encl
PLIML G Commonwealth Edison Co 83/03/09 DENTON H R NRC - No Detailed Affiliation Given 3pp 18357 327 24X Fiche 50-295, 83/04/25, 8305060673

--8305060686 Public version of Re 5 to Emergency Plan Implementing Procedure EPIP 550-2, "Division Emergency Kit " Emergency Operations Facility Radiological Equipment "
* Commonwealth Edison Co 83/03/08 5pp 18357 330 24X Fiche 50-295, 83/04/25, 8305060673

8305060410 Forwards IE Safeguards Insp Repts 50 295/83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld (ref 10CFR73 21)
KEPPLER, J G Region 3, Office of Director 83/05/03 O'CONNOR, J J Commonwealth Edison Co 3pp 18341 2[illegible] 24X Fiche 50-295, 83/05/03, 8305060410

--8305060418 IE Safeguards Insp Repts 50 295/83-06 & 50 304/83-07 on 830315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Details withheld (ref 10CFR73 21)
BELANGER, J L , MADEDA, T J , CREED, J R Region 3, Office of Director 83/04/29 1p 18343 242 24X Fiche 50-295, 83/05/03, 8305060410

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18940 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240246 Advises that requirements of NUREG 0737 Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to Meet App E to 10CFR50," satisfied
VARGA, S A Operating Reactors Branch 1 83/05/16 FARRAR, D L Commonwealth Edison Co 3pp 18593 103 24X Fiche 50-295, 83/05/16, 8305240246

J Insurance & indemnity information

8305230500 Forwards Endorsement 144 to NELIA Policy NF-43 & Endorsement 121 to MAELU Policy MF-22 for Dresden Unit 1 & Endorsement 63 to NFLIA Policy NF-201 & Endorsement 53 to MAELU Policy MF-64 for Zion Unit 1 W/o encl Quad Cities endorsements
OSTER, J Commonwealth Edison Co 83/05/13 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 18537 174 24X
Fiche 50-000, 83/05/13, 8305230500

O Advisory Committee on Reactor Safeguards reports & correspondence

8305160246 Comments on SSMRP risk analysis Risks from seismic events should be analyzed separately from internal events w/results treated independently Only upper limits need be estimated to determine if risks acceptable
DAVIS, P R Affiliation Unknown DAVIS, P R ACRS - Advisory Committee on Reactor Safeguards 83/04/16 BARENT, D ACRS - Advisory Committee on Reactor Safeguards 1p 18472 001 24X
Fiche 50-295, 83/04/16, 8305160246

P Operating license stage documents & correspondence

8303300001 Forwards Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends delete nonradiological water quality-related requirements
VARGA, S A Operating Reactors Branch 1 83/03/11 FARRAR, D L
Commonwealth Edison Co 3pp 17751 292 24X Fiche 50-295, 83/03/11, 8303300001

--8303300002 Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively, deleting nonradiological water quality-related requirements
VARGA, S A Operating Reactors Branch 1 83/03/11 6pp
17751 295 24X Fiche 50-295, 83/03/11, 8303300001

--8303300003 Notice of issuance & availability of Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively
VARGA, S A Operating Reactors Branch 1 83/03/11 2pp
17751 356 24X Fiche 50-295, 83/03/11, 8303300001

8304270053 Agrees w/830311 ltr demonstrating that Tech Specs indicate conditions under which protection sys channels may be bypassed during cooldown Review closed
VARGA, S A Operating Reactors Branch 1 83/04/12 FARRAR, D L
Commonwealth Edison Co 2pp 18254 150 24X Fiche 50-295, 83/04/12, 8304270053

8305180691 Forwards revised order modifying completion dates for NUREG-0737, Items II B 2, "Plant Shielding," II B 3, "Post Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation "
VARGA, S A Operating Reactors Branch 1 83/04/28 FARRAR, D L
Commonwealth Edison Co 2pp 18505 181 24X Fiche 50-295, 83/04/28, 8305180691

--8305180702 Revised order modifying completion dates for NUREG-0737, Items II B 2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation," per Generic Ltrs 82-05 & 82-10
EISENHUT, D G Division of Licensing 83/04/28 Commonwealth Edison Co 9pp 18505 183 24X Fiche 50-295, 83/04/28, 8305180691

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
ISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040317 Responds to NRC request for addl info re TMI action plan items Matl supports util position that nonsafety-related equipment falls outside scope of Franklin Research Ctr review Justification not necessary
LENTINE, F G Commonwealth Edison Co 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18323 289 24X
Fiche 50-295, 83/05/02, 8305040317

8305110144 Ack receipt of 830318 ltr, providing basis for not paying addl fee for 801107 application re assurance of redundancy in DHR capability Fees include cost of prof staff hours expended & associated contractual svcs Addl fee due
MILLER, W O License Fee Management Branch 83/05/03 LENTINE, F G
Commonwealth Edison Co 2pp 18421 347 24X Fiche 50-295, 83/05/03, 8305110144

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18477 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170218 Forwards response to 830208 & 0317 requests for addl info re NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor "
LENTINE, F G Commonwealth Edison Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 18466 332 24X
Fiche 50-295, 83/05/13, 8305170218

8305240506 Forwards fee for Amends 65 & 62 to Licenses DPR-39 & DPR-48, respectively
LENTINE, F G Commonwealth Edison Co 83/05/18 MILLER, W O
License Fee Management Branch 2pp 18571 264 24X
Fiche 50-295, 83/05/18, 8305240506

8305240473 Provides addl info re probabilistic safety study, discussed during 830331 NRC site visit Formal document verification of fan operability not previously required Procedures revised to include operability of fan coolers
LENTINE, F G Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18549 355 24X
Fiche 50-295, 83/05/19, 8305240473

8305250077 Forwards Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by 10CFR50 49 for Zion Units 1 & 2 "
LENTINE, F G Commonwealth Edison Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18589 042 24X
Fiche 50-295, 83/05/19, 8305250077

--8305250084 Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by 10CFR50 49 for Zion Units 1 & 2 "
* Sargent & Lundy, Inc 83/05/20 776pp 18589 046 24X
Fiche 50-295, 83/05/19, 8305250077

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D
Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305100262 Forwards IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 & notice of violation
SHAFER, W D Region 3, Office of Director 83/04/20 REED, C
Commonwealth Edison Co 2pp 18372 242 24X Fiche 50-295, 83/04/20, 8305100262

--8305100266 Notice of violation from insp on 830118-0304
SHAFER, W D Region 3, Office of Director 83/04/20 1p
18372 244 24X Fiche 50-295, 83/04/20, 8305100262

--8305100271 IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 Noncompliance noted failure to notify NRC of unplanned release while purging & drawing routine sample
WATERS, J R , HARTMANN, P L , DUNAWAY, F R Region 3, Office of Director 83/04/20 13pp 18372 245 24X Fiche 50-295, 83/04/20, 8305100262

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170337 Forwards IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311, 14-17, 22-23 & 0407 & notices of violation & deviation
PAPERIELLO, C J Region 3, Office of Director 83/04/27 REED, C,
Commonwealth Edison Co 2pp 18465 274 24X Fiche 50-295, 83/04/27, 8305170337

--8305170344 Notice of violation from insp on 830311,14-17,22-23 & 0407
PAPERIELLO,C J Region 3, Office of Director 83/04/27 2pp
18465 276 24X Fiche 50-295,83/04/27,8305170337

--8305170348 Notice of deviation from insp on 830311,14-17,22-23 & 0407
* Region 3, Office of Director 83/04/27 1p 18465 278 24X
Fiche 50-295,83/04/27,8305170337

--8305170353 IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311,14-17,
22-23 & 0407 Noncompliance noted contamination surveys of
transfer canal workers exhibiting nasal contamination not
documented Fuel pool samples not analyzed
LOVENDALE,P C , MILLER,D E , GREGER,L R Region 3, Office of
Director 83/04/25 11pp 18465 279 24X Fiche 50-295,83/04/27,
8305170337

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of
Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High
Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305020252 EN-83-028 on 830503,notice of violation & proposed
imposition of civil penalty in amount of $10,000 to be
issued Action based on failure to control access into
protected & vital areas & unauthorized entry
ROSANO,R Director's Office, Office of Inspection and Enforcement
83/04/28 1p 18277 277 24X Fiche 50-295,83/04/28,8305020252

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve
Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305060410 Forwards IE Safeguards Insp Repts 50-295/83-06 &
50-304/83-07 on 830315 & notice of violation Notice of
violation withheld (ref 10CFR73 21)
KEPPLER,J G Region 3, Office of Director 83/05/03 O'CONNOR,J J
Commonwealth Edison Co 3pp 18343 239 24X Fiche 50-295,
83/05/03,8305060410

--8305060418 IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on
830315 Noncompliance noted unauthorized entry into
protected & vital area & failure to rept safeguards event
Details withheld (ref 10CFR73 21)
BELANGER,J L , MADEDA,T J , CREED,J R Region 3, Office of
Director 83/04/29 1p 18343 242 24X Fiche 50-295,83/05/03,
8305060410

8303040030 IE Info Notice 83-27, "Operational Response to Events
Concerning Deliberate Acts Directed Against Plant
Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action
Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack
Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency
Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New
York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305200351 Forwards results of investigation on Br-82 source &
significance in containments,per 830216 committal
Investigation result of IE Insp Repts 50-295/82-30 &
50-304/82-27
LENTINE,F O Commonwealth Edison Co 83/05/17 KEPPLER,J G
Region 3, Office of Director 4pp 18516 247 24X
Fiche 50-295,83/05/17,8305200351

8303040040 IE Info Notice 83-31 Error in ADLPIPE Computer Program "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New
York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305310095 Forwards responses to violation & deviation noted in IE Insp
Repts 50-295/83-07 & 50-304/83-06 on 830311-0417 Corrective
actions personnel whole body count initiated to document
internal contamination
FARRAR,D L Commonwealth Edison Co 83/05/25 KEPPLER,J G Region
3, Office of Director 4pp 10658 074 24X Fiche 50-295,83/05/25,
8305310095

8303040046 IE Info Notice 83-33 "Nonrepresentative Sampling of
Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305120013 Forwards monthly operating repts for Apr 1983
GRAESSER,K L Commonwealth Edison Co 83/05/09 Director's
Office, Office of Inspection and Enforcement 1p 18423 058 24X
Fiche 50-295,83/05/09,8305120013

--8305120016 Monthly operating repts for Apr 1983
AUSTIN,G Commonwealth Edison Co 83/05/09 11pp 18423 059
24X Fiche 50-295 83/05/09,8305120013

S Reportable occurrences, LERs & related correspondence

8305060443 Forwards updated LER 83-004/99X-1 canceling original rept
GRAESSER,K L Commonwealth Edison Co 83/04/08 KEPPLER,J G
Region 3, Office of Director 1p 18343 131 24X
Fiche 50-295,83/04/08,8305060443

--8305060444 Updated LER 83-004/99X-1,canceling original rept
SCHULTZ,L Commonwealth Edison Co 83/04/08 Region 3, Office
of Director 1p 18343 132 24X Fiche 50-295,83/04/08,
8305060443

8305060528 Forwards LER 83-011/03L-0
GRAESSER,K L Commonwealth Edison Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 1p 18351 088 24X
Fiche 50-295,83/04/29,8305060528

--8305060544 LER 83-011/03L-0 on 830401,steam generator blowdown monitor
IRE-0019 failed low Caused by failure of high voltage power
supply due to normal wear Power supply replaced & monitor
returned to svc
JAKUBAITIS,T C Commonwealth Edison Co 83/04/29 Region 3,
Office of Director 1p 18351 089 24X Fiche 50-295,83/04/29,
8305060528

8305060567 Forwards LER 83-010/03L-0
GRAESSER,K L Commonwealth Edison Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 1p 18349 055 24X
Fiche 50-295,83/04/29,8305060567

--8305060572 LER 83-010/03L-0 on 830413,1A feedwater flow transmitter
1FT-510 found out-of-tolerance 3 3% low & 5 8% high on
830329 Caused by transmitter ferrite disk & coil loose from
mountings Transmitters repaired & recalibr
CANTWELL,P F Commonwealth Edison Co 83/04/29 Region 3,
Office of Director 1p 18349 056 24X Fiche 50-295,83/04/29,
8305060567

8305240311 LER 83-012,03L-0 on 830413,Class 1 pipe tunnel iodine
monitor 1RTPR078 failed low Caused by personnel performing
calibr of QRT-PR078 on 830412 incorrectly adjusting high
voltage setting W/830513 ltr
WILLIAMS,V S , GRAESSER,K L Commonwealth Edison Co 83/05/13
KEPPLER,J G Region 3, Office of Director 2pp 18548 182 24X
Fiche 50-295,83/05/13,8305240311

DOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3

F Security, medical, emergency & fire protection plans

8305090191 Discusses IE Security Insp Repts 50-259/82-47,50-260/82-47 &
50-296/82-47 on 821220 & forwards notice of violation &
proposed imposition of civil penalty Encls withheld (ref
10CFR2 790)
O'REILLY,J P Region 2, Office of Director 83/01/13 PARRIS,H G
Tennessee Valley Authority 3pp 18363 119 24X
Fiche 50-259,83/01/13,8305090191

8305040626 Releases public version of re ised emergency plan implementing procedures
FELTON, ' M Di ision of Rules and Regards 83/04/26 Document Management Branch 1p 18327 006 24X Fiche 50-259,83/04/26, 8305040628

--8305040633 Forwards public version of revised emergency plan implementing procedures, including Procedure IP-2 re notification of unusual event IP-3 re alert & IP-4 re site area emergency
KAMMER, D S Tennessee Valley Authority 83/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18329 007 24X Fiche 50-259,83/04/26,8305040628

--8305040655 Public version of revised emergency plan implementing procedure, including Procedure IP-2 re notification of unusual event, IP-3 re alert & IP-4 re site area emergency
* Tennessee Valley Authority 83/03/03 81pp 18329 008 24X Fiche 50-259,83/04/26,8305040628

8305100234 Requests that Figures B 5-4B & B 5-13B be removed from updated FSAR & destroyed & replaced w/encl pages since figures contain info classified as safeguards info per 10CFR73
MILLS, L M Tennessee Valley Authority 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18373 266 24X Fiche 50 259,83/05/04,8305100234

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G Tennessee Valley Authority 3pp 18648 107 24X
Fiche 50 259,83/05/18,8305260177

J Insurance & indemnity information

8305160005 Forwards Endorsements 65 & 54 to NELIA Policy NF-198 & MAELU Policy MF-66, respectively
DUCK, J R Marsh & McLennan, Inc 83/05/03 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18456 059 24X
Fiche 50-259,83/05/03,8305160005

P Operating license stage documents & correspondence

8305040511 Application for amend to Licenses DPR-33, DPR-52 & DPR-68 revising stated isolation logic for Group 7 isolation valves to reflect actual logic
MILLS, L M Tennessee Valley Authority 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18322 038 24X Fiche 50-259,83/04/28,8305040511

--8305040517 Proposed changes to Tech Specs revising stated isolation logic for Group 7 isolation valves to reflect actual logic
* Tennessee Valley Authority 83/04/28 5pp 18322 040 24X Fiche 50-259,83/04/28,8305040511

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50 000,83/05/02,8305020455

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50 000,83/05/09,8305090659

8305180845 Advises that action required by Amends 86,83 & 57 to Licenses DPR-33, DPR-52 & DPR-68, respectively & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste
VASSALLO, D B Operating Reactors Branch 2 83/05/09 PARRIS, H G Tennessee Valley Authority 2pp 18506 018 24X
Fiche 50-259,83/05/09,8305180845

8305130003 Advises that plant-unique analysis for mods per Mark I containment program will be submitted in Dec 1983, in response to NRC 830429 request
MILLS, L M Tennessee Valley Authority 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18437 008 24X
Fiche 50-259,83/05/10,8305130003

8305250136 Forwards request for addl info re NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulators " Info requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 PARRIS, H G Tennessee Valley Authority 3pp 18596 204 24X
Fiche 50-259,83/05/11,8305250136

8305260187 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G Tennessee Valley Authority 2pp 18648 099 24X
Fiche 50-259,83/05/18,8305260187

8305250473 Forwards info re status of environ qualification of equipment per 10CFR50 49(g) Qualification status table, schedule for qualifying deficient equipment & addl justification for continued operation encl
KAMMER, D S Tennessee Valley Authority 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 94pp 18585 110 24X Fiche 50-259,83/05/20,8305250473

8305270021 Notifies that util will submit schedule for performing mods to Mark I containment drywell/wetwell vacuum breakers once calculations complete & mods identified, in response to Generic Ltr 83-08
MILLS, L M Tennessee Valley Authority 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18638 313 24X
Fiche 50-259,83/05/23,8305270021

8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels " Criteria will be met
MILLS, L M Tennessee Valley Authority 83/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18638 306 24X Fiche 50-259,83/05/24,8305270030

Q Inspection reports, IE Bulletins & correspondence

8305090191 Discusses IE Security Insp Repts 50-259/82-47, 50-260/82-47 & 50-296/82-47 on 821220 & forwards notice of violation & proposed imposition of civil penalty Encls withheld (ref 10CFR2 790)
O'REILLY, J P Region 2, Office of Director 83/01/13 PARRIS, H G Tennessee Valley Authority 3pp 18363 119 24X
Fiche 50-259,83/01/13,8305090191

8305270171 Advises that full compliance in response to violation noted in IE Insp Repts 50-256/82-33, 50-260/82-33 & 50-296/82-33 will be delayed until 830301
MILLS, L M Tennessee Valley Authority 83/01/28 O'REILLY, J P Region 2, Office of Director 1p 18638 071 24X
Fiche 50-259,83/01/28,8305270171

8305270177 Forwards 830111 response to notice of violation & proposed imposition of civil penalty erroneously submitted to JP O'Reilly W/o encl
MILLS, L M Tennessee Valley Authority 83/02/10 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18637 362 24X Fiche 50-259,83/02/10,8305270177

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270514 Forwards IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/30 PARRIS, H G Tennessee Valley Authority 2pp 18646 182 24X
Fiche 50-259,83/03/30,8305270514

--8305270526 IE Insp Repts 50-259/83-06, 50-260/83-06 & 50-296/83-06 on 830214-19 No noncompliance noted Major areas inspected witnessing primary containment integrated leak rate test & review of procedure, preparation, performance & results
WHITENER, H L , JAPE, F Region 2, Office of Director 83/03/28 8pp 18646 184 24X Fiche 50-259,83/03/30,8305270514

8305270202 Concurs w/util 830401 request for extension of commitment dates for responding to violations noted in IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16 until 830901
LEWIS, R C Division of Project & Resident Programs 83/04/07
PARRIS, H G Tennessee Valley Authority 1p 18637 170 24X
Fiche 50-259, 83/04/07, 8305270202

--8305270206 Advises that new full compliance date of 830901 required to complete review of procedures, preparation of revs & issuance of revised instructions in response to IE Insp Repts 50-259/82-16, 50-260/82-16 & 50-296/82-16
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 1p 18637 171 24X
Fiche 50-259, 83/04/07, 8305270202

8305270642 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02
VERRELLI, D M Division of Project & Resident Programs 83/04/07
PARRIS, H G Tennessee Valley Authority 1p 18662 132 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270652 Responds to NRC 830210 ltr re violations noted in IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 Corrective actions radiochemical lab manual Procedure 728 III 2 1 will be revised
MILLS, L M Tennessee Valley Authority 83/03/16 O'REILLY, J P
Region 2, Office of Director 3pp 18662 133 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270658 Forwards IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/02/10
PARRIS, H G Tennessee Valley Authority 2pp 18662 136 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270661 Notice of violation from insp on 830117-18
* Region 2, Office of Director 83/02/10 1p 18662 138 24X
Fiche 50-259, 83/04/07, 8305270642

--8305270666 IE Insp Repts 50-259/83-02, 50-260/83-02 & 50-296/83-02 on 830117-18 Noncompliance noted failure to use 3-liter sample of RHR svc water in Marinelli beaker for isotopic analysis
COLLINS, T R , BARR, K P Region 2, Office of Director 83/02/10
3pp 18662 139 24X Fiche 50-259, 83/04/07, 8305270642

8305270653 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44
VERRELLI, D M Division of Project & Resident Programs 83/04/13
PARRIS, H G Tennessee Valley Authority 1p 18645 201 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270660 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 Corrective actions interim criteria for removal of waste oil & miscellaneous wastes from regulated areas developed
MILLS, L M Tennessee Valley Authority 83/04/01 O'REILLY, J P
Region 2, Office of Director 5pp 18645 202 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270664 Forwards IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 & notice of violation
O'REILLY, J P Region 2, Office of Director 83/02/25
PARRIS, H G Tennessee Valley Authority 2pp 18645 207 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270665 Notice of violation from insp on 821115-19
* Region 2, Office of Director 83/02/25 2pp 18645 209 24X
Fiche 50-259, 83/04/13, 8305270653

--8305270668 IE Insp Repts 50-259/82-44, 50-260/82-44 & 50-296/82-44 on 821115-19 Noncompliance noted licensee transferred licensed matl to unauthorized recipients & disposed of matl by unapproved means
DEDS, B T , BARR, K P Region 2, Office of Director 82/12/23
7pp 18645 211 24X Fiche 50-259, 83/04/13, 8305270653

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270266 Forwards IE Insp Repts 50-259/83-13, 50-260/83-13 & 50-296/83-13 on 830329-30 No noncompliance noted Major areas inspected, procedures, representative records & observations of demonstrated ultrasonic methodology W/o encl
VERRELLI, D M Division of Project & Resident Programs 83/04/19
PARRIS, H G. Tennessee Valley Authority 3pp 18641 326 24X
Fiche 50-259, 83/04/19, 8305270266

8303040023 IE Info Notice 83-22, "BWR Safety Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305030625 Forwards addl info re masonry wall per IE Bulletin 80-11, in response to NRC 830128 ltr Results of wall displacement analysis will be submitted by 830715 W/three oversize drawings Aperture cards are in PDR
MILLS, L M Tennessee Valley Authority 83/04/22 DENTON, H R
Office of Nuclear Reactor Regulation, Director 7pp 18303 001
24X Fiche 50-259, 83/04/22, 8305030625

--8305030631 Rev 2 to DFN-50-D/09 "Detailed Design Criteria for Reevaluation Criteria for Masonry Walls "
* Tennessee Valley Authority 82/03/26 162pp 18303 008 24X
Fiche 50-259, 83/04/22, 8305030625

8305270510 Forwards IE Insp Repts 50-259/83-08, 50-260/83-08 & 50-296/83-08 on 830329-31 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/22
PARRIS, H G Tennessee Valley Authority 2pp 18646 065 24X
Fiche 50-259, 83/04/22, 8305270510

--8305270528 IE Insp Repts 50-259/83-08, 50-260/83-08 & 50-296/83-08 on 830328-31 No noncompliance noted Major areas inspected mgt & administrative controls, status review of radiological environ monitoring program & insp of monitoring stations
CUNNINGHAM, A L , MONTGOMERY, D M Region 2, Office of Director
83/04/20 5pp 18646 067 24X Fiche 50-259, 83/04/22, 8305270510

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270345 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05
LEWIS, R C Division of Project & Resident Programs 83/05/09
PARRIS, H G Tennessee Valley Authority 1p 18642 079 24X
Fiche 50-259, 83/05/09, 8305270345

--8305270355 Responds to NRC 830316 ltr re violations noted in IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 Corrective actions conduit mounting supports connected to conduits & supported per General Const Spec G-3
MILLS, L M Tennessee Valley Authority 83/04/21 O'REILLY, J P
Region 2, Office of Director 4pp 18642 080 24X
Fiche 50-259, 83/05/09, 8305270345

--8305270362 Forwards IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 on 830126-0225 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/16
PARRIS H G Tennessee Valley Authority 2pp 18642 084 24X
Fiche 50-259, 83/05/09, 8305270345

--8305270368 Notice of violation from insp on 830126-0225
* Region 2, Office of Director 83/03/16 2pp 18642 086 24X
Fiche 50-259, 83/05/09, 8305270345

--8305270381 IE Insp Repts 50-259/83-05, 50-260/83-05 & 50-296/83-05 on 830126-0225 Noncompliance noted violation of 10CFR50, App B, Criterion V in maint area & violation of Tech Spec re Surveillance Insp 2
PAULK, G L Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs 83/03/14 8pp 18642 088 24X
Fiche 50-259, 83/05/09, 8305270345

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305030266 Forwards LER 83-023/03L-0
GREEN, H J Tennessee Valley Authority 83/04/26 O'REILLY, J P
Region 2, Office of Director 1p 18300 047 24X
Fiche 50-296, 83/04/26, 8305030266

--8305030272 LER 83-023/03L-0 on 830330, during normal operation, while performing Surveillance Instruction SI 4 2 8-69, pressure switch PS-3-204C had as-found setpoint of 1123 psig Caused by instrument drift Switch recalibr
IRBY, D J Tennessee Valley Authority 83/04/26 Region 2, Office of Director 3pp 18300 048 24X Fiche 50-296, 83/04/26, 8305030266

8305100107 Forwards LER 83-024/01T-0
GREEN, H J Tennessee Valley Authority 83/05/03 O'REILLY, J P
Region 2, Office of Director 1p 18375 026 24X
Fiche 50-296, 83/05/03, 8305100107

--8305100113 LER 83-024/01T-0 on 830419, personnel notified that MCHGR for rod withdrawal error scenario exceeded 1% plastic strain linear heat generation rate limit for eight LTA bundles Cause not stated Procedures for reviewing work revised
STILES, H A Tennessee Valley Authority 83/05/03 Region 2, Office of Director 2pp 18375 027 24X Fiche 50-296, 83/05/03, 8305100107

8305170030 Forwards LER 83-026/03L-0
GREEN, H J Tennessee Valley Authority 83/05/09 O'REILLY, J P
Region 2, Office of Director 1p 18466 180 24X
Fiche 50-296, 83/05/09, 8305170030

--8305170034 LER 83-026/03L-0 on 830411, while establishing EECW flow rate to emergency diesel 3 generator cooler following mod, head on HX found cracked, rendering generator inoperable Caused by mfg defect Crack in cast iron head repaired
HOLDER, E T Tennessee Valley Authority 83/05/09 Region 2, Office of Director 2pp 18466 181 24X Fiche 50-296, 83/05/09, 8305170030

8305250508 LER 83-025/03L-0 on 830419, during normal operation, drywell temp indicators IS-64-67, TI-64-52A & TM 64-52 drifted out of tolerance & beyond Tech Spec limit Instruments recalibr & functional tested W/830517 ltr
BASS, O W , GREENE, H J Tennessee Valley Authority 83/05/17
O'REILLY, J P Region 2, Office of Director 3pp 18588 296 24X
Fiche 50-296, 83/05/17, 8305250508

8305310054 LER 83-027/03L-0 on 830418, offgas post-treatment radiation monitors (3-RM-90-265/266) rendered inoperable Caused by sample pump failure due to normal end-of-life operation Sample pump replaced W/830517 ltr
GREEN, H J Tennessee Valley Authority 83/05/17
Region 2, Office of Director 3pp 18653 183 24X
13/05/17, 8305310054

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of addl sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste
MILLER, W O License Fee Management Branch 83/04/22 MILLB, L M
Tennessee Valley Authority 2pp 18309 193 24X
Fiche 50-000, 83/04/22, 8305030679

DOCKET 50-298 COOPER NUCLEAR STATION

F Security, medical, emergency & fire protection plans

8305180026 Forwards Amend 82 to License DPR-46, safety evaluation & notice of issuance & availability Amend modifies fire sys clean water supply, plant staff working hours, reactor protection sys power monitoring sys & snubber listings
VASSALLO, D B Operating Reactors Branch 2 83/04/29 PILANT, J M
Nebraska Public Power District 2pp 18497 052 24X
Fiche 50-298, 83/04/29, 8305180026

--8305180039 Amend 82 to License DPR-46, modifying standby gas treatment testing requirements, App J testing, scram discharge vol, fire protection sys clean water supply, snubber listings & reactor power sys power monitoring sys
VASSALLO, D B Operating Reactors Branch 2 83/04/29 71pp
18497 054 24X Fiche 50-298, 83/04/29, 8305180026

--8305180050 Safety evaluation supporting Amend 82 to License DPR-46
* Office of Nuclear Reactor Regulation, Director 83/04/29
11pp 18497 125 24X Fiche 50-298, 83/04/29, 8305180026

--8305180071 Notice of issuance & availability of Amend 82 to License DPR-46
VASSALLO, D B Operating Reactors Branch 2 83/04/29 2pp
18497 136 24X Fiche 50-298, 83/04/29, 8305180026

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305250145 Informs that NUREG-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M
Nebraska Public Power District 3pp 18596 193 24X
Fiche 50-298, 83/05/18, 8305250145

8305260301 Forwards IE Insp Rept 50-298/83-05 on 830321-25 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/05/23 PILANT, J M
Nebraska Public Power District 2pp 18626 265 24X
Fiche 50-298, 83/05/23, 8305260301

--8305260304 IE Insp Rept 50-298/83-05 on 830321-25 No noncompliance noted Major areas inspected security plan implementing procedures, security organization, records & repts & access control Details withheld (ref 10CFR73 21)
EVANS, C A , KELLY, J A , WESTERMAN, T F Region 4, Office of Director 83/05/20 1p 18626 267 24X Fiche 50-298, 83/05/23, 8305260301

I Financial information

8305060380 Forwards Annual Financial Rept 1982
PILANT, J M Nebraska Public Power District 83/05/07 Office of Nuclear Reactor Regulation, Director 1p 18344 036 24X
Fiche 50-298, 83/05/07, 8305060380

--8305060383 Annual Financial Rept 1982
HILL, D W , KOSMAN, H D , HERRINGTON, F A Nebraska Public Power District 83/05/03 43pp 18344 037 24X Fiche 50-298, 83/05/07, 8305060380

P Operating license stage documents & correspondence

8305030588 Forwards response to 830215 request for addl info re NUREG-0737, Item II B 3 re post-accident sampling sys Areas discussed include radiological & chemical analysis capacity & reactor coolant gas analysis
PILANT, M Nebraska Public Power District 83/04/22 VASSALLO, D B
Operating Reactors Branch 2 4pp 18305 354 24X
Fiche 50-298, 83/04/22, 8305030588

8305020449 Application to amend License DPR-46, changing Tech Specs to incorporate NUREG-0737 items per 830110 Generic Ltr 83-02
PILANT, J M Nebraska Public Power District 83/04/27
VASSALLO, D B Operating Reactors Branch 2 3pp 18283 173 24X
Fiche 50-298, 83/04/27, 8305020449

--8305020464 Proposed Tech Specs changes re Generic Ltr 83-02 concerning NUREG-0737 items
* Nebraska Public Power District 83/04/27 3pp 18283 176
24X Fiche 50-298, 83/04/27, 8305020449

8305030393 Confirms commitment to inform regional administrator of any changes in NPDES permit & of violations of permit
PILANT, J M Nebraska Public Power District 83/04/29
VASSALLO, D B Operating Reactors Branch 2 1p 18308 196 24X
Fiche 50-298, 83/04/29, 8305030393

8305030554 Forwards "Wetwell-Drywell Vacuum Breaker Valves Long-Term Program Structural Evaluation "
PILANT, J M Nebraska Public Power District 83/04/29
VASSALLO, D B Operating Reactors Branch 2 2pp 18306 126 24X
Fiche 50-298, 83/04/29, 8305030554

--8305030564 "Wetwell-Drywell Vacuum Breaker Valves Long-Term Program Structural Evaluation "
* EDS Nuclear, Inc 04-0640-0062 R01 83/04/30 12pp
18306 128 24X Fiche 50-298, 83/04/29, 8305030554

8305050113 Application to amend License DPR-46, extending Mark I program completion date for 90 days for weld repair Class II amend fee forwarded
PILANT, J M Nebraska Public Power District 83/04/29
VASSALLO, D B Operating Reactors Branch 2 2pp 18341 334 24X
Fiche 50-298, 83/04/29, 8305050113

8305180026 Forwards Amend 82 to License DPR-46, safety evaluation & notice of issuance & availability Amend modifies fire sys clean water supply, plant staff working hours, reactor protection sys power monitoring sys & snubber listings
VASSALLO, D B Operating Reactors Branch 2 83/04/29 PILANT, J M
Nebraska Public Power District 2pp 18497 052 24X
Fiche 50-298, 83/04/29, 8305180026

--8305180039 Amend 82 to License DPR-46, modifying standby gas treatment testing requirements, App J testing, scram discharge vol, fire protection sys clean water supply, snubber listings & reactor power sys power monitoring sys
VASSALLO, D B Operating Reactors Branch 2 83/04/29 71pp
18497 054 24X Fiche 50-298, 83/04/29, 8305180026

--8305180050 Safety evaluation supporting Amend 82 to License DPR-46
* Office of Nuclear Reactor Regulation, Director 83/04/29
11pp 18497 125 24X Fiche 50-298, 83/04/29, 8305180026

--8305180071 Notice of issuance & availability of Amend 82 to License DPR-46
VASSALLO, D B Operating Reactors Branch 2 83/04/29 2pp
18497 136, 24X Fiche 50-298, 83/04/29, 8305180026

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 30pp 18441 120 24X
Fiche, 50-000, 83/05/02, 8305020455

8305160337 Forwards Amend 83 to License DPR-46, safety evaluation & notice of issuance & availability Amend lowers MSIV low reactor water isolation setpoint to Level 1 & opening & closing setpoints of two safety relief valves
SIEGEL, B Operating Reactors Branch 2 83/05/04 PILANT, J M
Nebraska Public Power District 2pp 18471 306 24X
Fiche 50-298, 83/05/04, 8305160337

--8305160340 Amend 83 to License DPR-46, revising MSIV low reactor water level isolation setpoint, opening & closing setpoints of two safety relief valves & protective instrumentation section
VASSALLO, D B Operating Reactors Branch 2 83/05/04, 20pp
18471 308 24X Fiche 50-298, 83/05/04, 8305160337

--8305160341 Safety evaluation supporting Amend 83 to License DPR-46
* Office of Nuclear Reactor Regulation, Director 83/05/04 5pp
18471 328 24X Fiche 50-298, 83/05/04, 8305160337

--8305160342 Notice of issuance & availability of Amend 83 to License DPR-46
VASSALLO, D B Operating Reactors Branch 2 83/05/04 2pp
18471 333 24X Fiche 50-298, 83/05/04, 8305160337

8305180547 Forwards order extending completion date for installation of plant mods needed to comply w/NUREG-0661 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
VASSALLO, D B Operating Reactors Branch 2 83/05/05 PILANT, J M
Nebraska Public Power District 2pp 18505 081 24X
Fiche 50-298, 83/05/05, 8305180547

--8305180548 Order modifying 810113 & 820915 orders, extending completion date for installation of plant mods needed to comply w/NUREG-0661 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
PURPLE, R A Division of Licensing 83/05/05 Nebraska Public Power District 4pp 18505 086 24X Fiche 50-298, 83/05/05, 8305180547

8305230242 Forwards safety evaluation of util 820831 submittal re procedure verification & design mod per NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Suction " Requirements met
VASSALLO, D B Operating Reactors Branch 2 83/05/05 PILANT, J M
Nebraska Public Power District 5pp 18543 232 24X
Fiche 50-298, 83/05/05, 8305230242

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305260170 Forwards request for add'l info re NUREG-0737, Item II K 3 28 on qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 PILANT, J M
Nebraska Public Power District 4pp 18648 113 24X
Fiche 50-298, 83/05/11, 8305260170

8305250266 Forwards Draft 7 of Rev 3 to NUREG-0742, "Std Radiological Effluent Tech Specs for PWRs," as guidance in developing final submission of radiological effluent Tech Specs Tech Specs requested within 60 days W/o encl
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M
Nebraska Public Power District 2pp 18595 336 24X
Fiche 50-298, 83/05/18, 8305250266

8305260300 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Alternative modes would not contribute to plant safety No mods required
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M
Nebraska Public Power District 2pp 18629 316 24X
Fiche 50-298, 83/05/18, 8305260300

8305270369 Responds to 10CFR50 49(g), "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants" & NRC 830408 ltr requests List of equipment important to safety encl
PILANT, J M Nebraska Public Power District 83/05/20
VASSALLO, D B Operating Reactors Branch 2 36pp 18642 136 24X
Fiche 50-298, 83/05/20, 8305270369

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

DOCKETED ITEMS

)3040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of
team Generators at PWRs " Svc list encl
)RDAN,E L Division of Emergency Preparedness & Engineering
esponse (Post 830103) 83/04/28 Consolidated Edison Co of New
ork, Inc 11Spp 18382 047 24x Fiche 50-000,83/04/28,8303040026

3040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High
emp Trip Setpoint Adjustment " Svc list encl
ORDAN,E L Division of Emergency Preparedness & Engineering
esponse (Post 830103) 83/04/28 Consolidated Edison Co of New
ork, Inc 11Spp 18382 165 24X Fiche 50-000,83/04/28,8303040027

5170329 Forwards IE Insp Rept 50-298/83-03 on 830328-0401 No
oncompliance noted
ADSEN,G L Region 4, Office of Director 83/04/29 PILANT,J M
ebraska Public Power District 2pp 18465 144 24X
iche 50-298,83/04/29,8305170329

305170333 IE Insp Rept 50-298/83-03 on 830328-0401 No noncompliance
noted Major areas inspected training & surveillance
REDANO,R T , WESTERMAN,T F Region 4, Office of Director
83/04/28 7pp 18465 146 24X Fiche 50-298,83/04/29,8305170329

040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve
scharge Line Vacuum Breakers " Svc list encl
RDAN,E L Division of Emergency Preparedness & Engineering
sponse (Post 830103) 83/05/03 Consolidated Edison Co of New
rk, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

040030 IE Info Notice 83-27, "Operational Response to Events
ncerning Deliberate Acts Directed Against Plant
uipment " Svc list encl
RDAN,E L Division of Emergency Preparedness & Engineering
sponse (Post 830103) 83/05/04 Consolidated Edison Co of New
rk, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

)40031 IE Info Notice 83-28, "Criteria for Protective Action
ommendations for General Emergencies " Svc list encl
DAN,E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 83/05/04 Consolidated Edison Co of New
k, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

40033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack
ormation " Svc list encl
DAN,E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 83/05/06 Consolidated Edison Co of New
k, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

40034 IE Info Notice 83-30, "Misapplication of Generic Emergency
rating Procedures (EOP) Guidelines " Svc list encl
DAN,E L Division of Emergency Preparedness & Engineering
ponse (Post 830103) 83/05/11 Consolidated Edison Co of New
k, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

00328 Ack receipt of Apr 1983 mgt appraisal rept written by LRS
sultants, Inc Application for withholding requested within
days of ltr receipt
EN,G L Region 4, Office of Director 83/05/13 PILANT,J M
raska Public Power District 1p 18517 055 24X
e 50-298,83/05/13,8305200328

0040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
list encl
AN,E L Division of Emergency Preparedness & Engineering
onse (Post 830103) 83/05/19 Consolidated Edison Co of New
, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

0301 Forwards IE Insp Rept 50-298/83-05 on 830321-25 No
ompliance noted
EN,G L Region 4, Office of Director 83/05/23 PILANT,J M
aska Public Power District 2pp 18626 265 24X
e 50-298,83/05/23,8305260301

260304 IE Insp Rept 50-298/83-05 on 830321-25 No noncompliance
ted Major areas inspected security plan implementing
ocedures, security organization, records & repts & access
ntrol Details withheld (ref 10CFR73 21)
ANS,C A , KELLY,J A , WESTERMAN,T F Region 4, Office of
rector 83/05/20 1p 18626 267 24X Fiche 50-298,83/05/23,
05260301

0046 IE Info Notice 83-33, "Nonrepresentative Sampling of
aminated Oil " Svc list encl
N,E L Division of Emergency Preparedness & Engineering
onse (Post 830103) 83/05/26 Consolidated Edison Co of New
Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305060574 Forwards LER 83-003/03L-0 Detailed event analysis submitted
THOMASON,P V Nebraska Public Power District 83/04/29
COLLINS,J T Region 4, Office of Director 2pp 18349 005 24X
Fiche 50-298,83/04/29,8305060574

--8305060584 LER 83-003/03L-0 on 830403, indication & control power for
reactor bldg exhaust valve HN-260MV failed, resulting in
valve not automatically closing on isolation signal Caused
by burned out lamp Lamp & fuse replaced
WIRE,W R Nebraska Public Power District 83/04/29 Region 4,
Office of Director 1p 18349 007 24X Fiche 50-298,83/04/29,
8305060574

8305120433 Forwards LER 83-004/03L-0 Detailed event analysis
submitted
THOMASON,P V Nebraska Public Power District 83/04/29
COLLINS,J T Region 4, Office of Director 2pp 18431 133 24X
Fiche 50-298,83/04/29,8305120433

--8305120439 LER 83-004/03L-0 on 830409, during SP 6 1 4, contacts of
relay 917-5A-K7D failed to open Cause not determined Relay
coil replaced & proper operation verified All ac HFA relays
on essential sys will be tested during Spring 1983 outage
KRAUSE,R W Nebraska Public Power District 83/04/29 Region
4, Office of Director 1p 18431 135 24X Fiche 50-298,83/04/29,
8305120433

8305200344 PNO-IV-83-019 on 830517, indications of intergranular stress
corrosion cracking in heat-affected zone of welds in RCS
identified Data forwarded to GE for detailed analysis RCS
loops inspected
DUBOIS,D , WESTERMAN,T F Region 4, Office of Director 83/05/17
1p 18516 233 24X Fiche 50-298,83/05/17,8305200344

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305030523 Requests revs to proposed mods to 10CFR50 App R exemption
requests re separation requirements, per 830322 meeting &
830325 & 31 telcons Detailed discussion of revs encl
FAY,C W Wisconsin Electric Power Co 83/04/28 DENTON,H R
Office of Nuclear Reactor Regulation, Director CLARK,R A
Operating Reactors Branch 3 29pp 18300 286 24X
Fiche 50-266,83/04/28,8305030523

8305110540 Forwards exemption from App R in partial response to 820630
ltr & 820929 & 1011 supplS Exemption permits relief from
requirements to install fired suppression sys & fire
barriers to separate hydrogen lines from safety equipment
CLARK,R A Operating Reactors Branch 3 83/04/28 FAY,C W
Wisconsin Electric Power Co 5pp 18415 104 24X
Fiche 50-266,83/04/28,8305110540

--8305110542 Exemption from requirements of 10CFR50, App R, Section III G
re fixed fire suppression sys in control room
EISENHUT,D G Division of Licensing 83/04/28 Wisconsin
Electric Power Co 3pp 18415 107 24X Fiche 50-266,83/04/28,
8305110540

8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-266/82-17 &
50-301/82-17 Violation 1 re fire signaling sys testing
withdrawn
SPESSARD,R L Division of Engineering 83/05/09 BURSTEIN,S
Wisconsin Electric Power Co 2pp 18464 333 24X
Fiche 50-266,83/05/09,8305170241

--8305170252 Responds to NRC 821130 ltr re violations noted in IE Insp
Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual
fire pump capacity test revised to include addl performance
data Fire protection tests reviewed
FAY,C W Wisconsin Electric Power Co 83/01/21 KEPPLER,J G
Region 3, Office of Director 42pp 18464 335 24X
Fiche 50-266,83/05/09,8305170241

--8305170263 Responds to C Ramsey question re largest single fire water
flow requirement at facilities Sprinklers for diesel
generator rooms supplied from svc water sys capacity
FAY,C W Wisconsin Electric Power Co 83/02/24 KEPPLER,J G
Region 3, Office of Director 3pp 18465 015 24X
Fiche 50-266,83/05/09,8305170241

8305170138 Ack receipt of 830413 ltr informing NRC of steps taken to
correct violations noted in IE Safeguards Insp Repts
50-266/83-05 & 50-301/83-05
HIND,J A Division of Radiological & Materials Safety Programs
83/05/10 BURSTEIN,S Wisconsin Electric Power Co 1p 18466 270
24X Fiche 50-266,83/05/10,8305170138

--8305170144 Responds to NRC 830314 ltr re violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 10CFR73 21)
BURSTEIN, S Wisconsin Electric Power Co 83/04/13 HIND, J A Division of Radiological & Materials Safety Programs 1p 18466 271 24X Fiche 50-266, 83/05/10, 8305170138

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305200021 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/12 FAY, C W Wisconsin Electric Power Co 3pp 18540 114 24X
Fiche 50-266, 83/05/12, 8305200021

8305270241 Documents agreement per 830517 conference call re timing requirements for notification of state & local agencies for unusual event or alert, per IE Insp Repts 50-266/83-01 & 50-301/83-01 Procedure to be initiated by 830701
FAY, C W Wisconsin Electric Power Co 83/05/23 KEPPLER, J G Region 3, Office of Director 1p 18637 161 24X
Fiche 50-266, 83/05/23, 8305270241

Q Adjudicatory correspondence

8305020438 Brief opposing Wisconsin Environ Decade exceptions to ASLB 830204 initial decision authorizing full-scale sleeving Exceptions waived for failure to brief or arguments w/o merits
CHURCHILL, D W Wisconsin Electric Power Co CHURCHILL, D W Shaw, Pittman, Potts & Trowbridge 83/04/29 Atomic Safety and Licensing Appeal Panel 32pp 18281 111 24X Fiche 50-266, 83/04/27, 8305020438

8305100314 Brief in opposition to Wisconsin Environ Decade 830214 appeal of ASLB 830204 memorandum & order LBP-83-4 ASLAB should reject exceptions not briefed & affirm ASLB order re steam generator tube rupture W/Certificate of Svc
BACHMANN, R G Hearing Branch 1 83/05/09 Atomic Safety and Licensing Appeal Panel 18pp 18371 141 24X Fiche 50-266, 83/05/09, 8305100314

8305270558 Requests info re date, time & location for Commission meeting on emergency operations facility location Leave to address Commission requested
FAY, C W Wisconsin Electric Power Co 83/05/20 CHILK, S J Office of the Secretary of the Commission 1p 18646 154 24X
Fiche 50-266, 83/05/20, 8305270558

P Operating license stage documents & correspondence

8305230724 Forwards estimated annual regulatory & nonregulatory expenditures in 830208 ltrs re cost of backfitting Combined capacity of facilities is 994 MWe
BURSTEIN, S Wisconsin Electric Power Co 83/02/25 TOURTELLOTTE, J Regulatory Reform Task Force 3pp 18542 269 24X
Fiche 50-266, 83/02/25, 8305230724

8305020272 Forwards Affidavit AW-80-27 in support of request to withhold proprietary info re effect of radiation on insulating matls in Westinghouse medium motor per 10CFR2 790 re encl util draft 830413 ltr
WIESEMANN, R A Westinghouse Electric Corp 83/04/13 THOMAS, C O Division of Licensing 9pp 18277 196 24X Fiche 50-266, 83/04/13, 8305020272

--8305020292 Nonproprietary version of "Effect of Radiation on Insulating Matls Used in Westinghouse Medium Motors "
BARTKO, J Westinghouse Electric Corp 71-1C2-RADMC-R1 71/04/10 39pp 18277 205 24X Fiche 50-266, 83/04/13, 8305020272

8305020128 Forwards safety evaluation of util preferred ac power sys conformance to GDC 17 Power sys do not fully meet intent of GDC 17 since sys could be automatically disconnected from 4,160-volt safeguards buses in worst case accident loads
NORELIUS, C E Division of Project & Resident Programs 83/04/25 EISENHUT, D G Division of Licensing 3pp 18278 220 24X
Fiche 50-266, 83/04/25, 8305020128

--8305020137 Safety evaluation of util preferred ac power sys conformance GDC 17 Proximity of low voltage transformers does not fully meet GDC 17 requirements for physical separation, but deluge sprinkler sys adequate
* NRC - No Detailed Affiliation Given 83/04/25 8pp 18278 223 24X Fiche 50-266, 83/04/25, 8305020128

8305060001 Forwards EG&G summary of discussion re radiological effluent Tech Specs during 820602-03 plant visit Final draft of proposed radiological effluent Tech Specs & offsite dose calculation manual should be developed within 60 days
CLARK, R A Operating Reactors Branch 3 83/04/25 FAY, C W Wisconsin Electric Power Co 45pp 18353 263 24X
Fiche 50-266, 83/04/25, 8305060001

8305090546 Lists drawings needed to review inservice testing program Two sets of full size drawings requested
CLARK, R A Operating Reactors Branch 3 83/04/27 FAY, C W Wisconsin Electric Power Co 3pp 18381 205 24X
Fiche 50-266, 83/04/27, 8305090546

8305110028 Informs of Class I & III fee classification for 830324 application for Tech Spec changes re auxiliary feedwater sys operability Overpayment for 790926 application for administrative changes will be applied toward current fees
MILLER, W O License Fee Management Branch 83/04/27 FAY, C W Wisconsin Electric Power Co 2pp 18421 313 24X
Fiche 50-266, 83/04/27, 8305110028

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060408 Requests extension of deadline for environ qualification of equipment until 840330 for Unit 2 & 841101 for both units for environ qualification of all 10CFR50 49(b)(3) equipment items
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 18348 210 24X
Fiche 50-266, 83/05/04, 8305060408

8305110075 Remits license amend approval fee for temporary clarification of Tech Specs re auxiliary feedwater sys operability
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, W O Licen Fee Management Branch 1p 18408 109 24X Fiche 50-266, 83/05/04, 8305110075

8305110181 Application to amend Licenses DPR-24 & DPR-27, consisting of Tech Spec Change Request 91 re limiting conditions for operation requiring both RHR loops be operable unless reactor sys is in refueling shutdown condition
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18407 122 24X Fiche 50-266, 83/05/04, 8305110181

--8305110187 Tech Spec Change Request 91 re limiting conditions for operation requiring both RHR loops be operable unless reactor sys is in refueling shutdown condition
* Wisconsin Electric Power Co 83/05/04 6pp 18407 125 24X
Fiche 50-266, 83/05/04, 8305110181

8305110201 Forwards addl fees associated w/Tech Spec Change Request 69 to allow repair of degraded steam generator tubes by sleeving
BURSTEIN, S Wisconsin Electric Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director DIGGS, R M License Fee Management Branch 1p 18407 111 24X Fiche 50-266, 83/05/04, 8305110201

8305120495 Fowards Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability Amends allow temporary isolation of shared motor driven auxiliary feedwater pumps
COLBURN, T G Operating Reactors Branch 3 83/05/04 FAY, C W Wisconsin Electric Power Co 4pp 18440 214 24X
Fiche 50-266, 83/05/04, 8305120495

--8305120498 Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively, allowing temporary isolation of shared motor driven auxiliary feedwater pumps for unit during startup, shutdown & surveillance testing of other unit
CLARK, R A Operating Reactors Branch 3 83/05/04 6pp 18440 218 24X Fiche 50-266, 83/05/04, 8305120495

--8305120502 Safety evaluation supporting Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 2pp 18440 224 24X Fiche 50-266, 83/05/04, 8305120495

--8305120505 Notice of issuance & availability of Amends 73 & 78 to Licenses DPR-24 & DPR-27, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp 18440 226 24X Fiche 50-266, 83/05/04, 8305120495

8305130009 Updates progress in meeting schedular commitments per NRC 830314 order re implementation of post-TMI Action Item II F 1, "Addl Accident Monitoring Instrumentation "
FAY,C W Wisconsin Electric Power Co 83/05/06 DENTON,H R
Office of Nuclear Reactor Regulation, Director CLARK,R A
Operating Reactors Branch 3 3pp 18436 341 24X
Fiche 50-266,83/05/06,8305130009

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 14pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305170619 Forwards approved exemption dtd 830509 for schedular requirements for installation of RCS high point gas vents allowing delay in installation of sys until 840101
CLARK,R A Operating Reactors Branch 3 83/05/09 FAY,C W
Wisconsin Electric Power Co 3pp 18497 008 24X
Fiche 50-301,83/05/09,8305170619

--8305170645 Exemption from schedular requirements for installation of RCS high point gas vents allowing delay in installation of sys util 840101
PURPLE,R A Division of Licensing 83/05/09 Wisconsin Electric Power Co 4pp 18497 011 24X Fiche 50-301,83/05/09, 8305170619

8305240131 Informs that piping & instrumentation diagrams requested in 830427 ltr re inservice testing program will be forwarded under separate cover
FAY,C W Wisconsin Electric Power Co 83/05/19 DENTON,H R
Office of Nuclear Reactor Regulation, Director CLARK,R A
Operating Reactors Branch 3 1p 18549 006 24X
Fiche 50-266,83/05/19,8305240131

8305240497 Forwards list of electric equipment important to safety to be environmentally qualified at facilities Info duplicates 811008 response,per IE Bulletin 79-01B,w/listed exceptions
FAY,C W Wisconsin Electric Power Co 83/05/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 29pp 18571 360 24X Fiche 50-266,83/05/20,8305240497

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 117pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305120456 Forwards IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 & notice of violation No reply to Item 2 of notice of violation required
SHAFER,W D Region 3, Office of Director 83/04/25 BURSTEIN,S
Wisconsin Electric Power Co 2pp 18431 029 24X
Fiche 50-266,83/04/25,8305120456

--8305120463 Notice of violation from insp on 830201-0331
SHAFER,W D Region 3, Office of Director 83/04/25 1p
18431 031 24X Fiche 50-266,83/04/25,8305120456

--8305120468 IE Insp Repts 50-266/83-04 & 50-301/83-04 on 830201-0331 Noncompliance noted personnel failed to check out when exiting containment per Procedure HP 2 4 & two Eberline Model DAI-6CC area radiation monitors not labeled
HAGUE,R L , FITZPATRICK,D , JACKIW,I N Region 3, Office of Director 83/04/22 9pp 18431 032 24X Fiche 50-266,83/04/25, 8305120456

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305120408 Submits addl response to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piping Sys " Mechanical corrections installed w/exception of two corrections requiring welding to RHR piping
BURSTEIN,S Wisconsin Electric Power Co 83/05/04 KEPPLER,J G
Region 3, Office of Director 2pp 18431 150 24X
Fiche 50-266,83/05/04,8305120408

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305200229 Clarifies position re maint & testing program for HVAC filter units not controlled by Tech Specs & for respirator fitting program,per IE Insp Repts 50-266/83-03 & 50-301/83-03 dtd 830216 although no noncompliance noted
FAY,C W Wisconsin Electric Power Co 83/05/06 KEPPLER,J G
Region 3, Office of Director 5pp 18517 102 24X
Fiche 50-266,83/05/06,8305200229

8305170241 Ack receipt of 830121 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Violation 1 re fire signaling sys testing withdrawn
SPESSARD,R L Division of Engineering 83/05/09 BURSTEIN,S
Wisconsin Electric Power Co 2pp 18464 333 24X
Fiche 50-266,83/05/09,8305170241

--8305170252 Responds to NRC 821130 ltr re violations noted in IE Insp Repts 50-266/82-17 & 50-301/82-17 Corrective actions annual fire pump capacity test revised to include addl performance data Fire protection tests reviewed
FAY,C W Wisconsin Electric Power Co 83/01/21 KEPPLER,J G
Region 3, Office of Director 42pp 18464 335 24X
Fiche 50-266,83/05/09,8305170241

--8305170263 Responds to C Ramsey question re largest single fire water flow requirement at facilities Sprinklers for diesel generator rooms supplied from svc water sys capacity
FAY,C W Wisconsin Electric Power Co 83/02/24 KEPPLER,J G
Region 3, Office of Director 3pp 18465 015 24X
Fiche 50-266,83/05/09,8305170241

8305170138 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05
HIND,J A Division of Radiological & Materials Safety Programs 83/05/10 BURSTEIN,S Wisconsin Electric Power Co 1p 18466 270 24X Fiche 50-266,83/05/10,8305170138

--8305170144 Responds to NRC 830314 ltr re violations noted in IE Safeguards Insp Repts 50-266/83-05 & 50-301/83-05 Corrective actions withheld (ref 10CFR73 21)
BURSTEIN,S Wisconsin Electric Power Co 83/04/13, HIND,J A
Division of Radiological & Materials Safety Programs 1p
18466 271 24X Fiche 50-266,83/05/10,8305170138

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 10524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 10697 009 24X Fiche 50-000,83/05/19,8303040040

8305240380 Confirmatory action ltr re NRC 830314 order specifying certain TMI action items as complete or completion dates noted Item II F 1 1, "Noble Gas Effluent Montior," complete, however,main steam line monitors not operational
KEPPLER,J G Region 3, Office of Director 83/05/20 BURSTEIN,S
Wisconsin Electric Power Co 1p 18575 072 24X
Fiche 50-266,83/05/20,8305240380

8305270241 Documents agreement per 830517 conference call re timing requirements for notification of state & local agencies for unusual event or alert,per IE Insp Repts 50-266/83-01 & 50-301/83-01 Procedure to be initiated by 830701
FAY,C W Wisconsin Electric Power Co 83/05/23 KEPPLER,J G
Region 3, Office of Director 1p 18637 161 24X
Fiche 50-266,83/05/23,8305270241

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305160169 Forwards monthly operating repts for Apr 1983
FAY,C W Wisconsin Electric Power Co 83/05/10 NRC - No
Detailed Affiliation Given 1p 18446 073 24X
Fiche 50-266,83/05/10,8305160169

--8305160171 Monthly operating repts for Apr 1983
FAY,C W Wisconsin Electric Power Co 83/05/09 9pp 18446 074
24X Fiche 50-266,83/05/10,8305160169

S Reportable occurrences, LERs & related correspondence

8305030275 Forwards LER 83-002/01T-0
FAY,C W Wisconsin Electric Power Co 83/04/26 KEPPLER,J G
Region 3, Office of Director 1p 18300 084 24X
Fiche 50-301,83/04/26,8305030275

--8305030280 LER 83-002/01T-0 on 830412,during eddy current exam of steam generator tubes,16 tubes in steam generator A & 2 tubes in steam generator B had indications greater than Tech Specs Caused by corrosion Tubes will be repaired
FAY,C W Wisconsin Electric Power Co 83/04/26 Region 3, Office of Director 6pp 18300 085 24X Fiche 50-301,83/04/26, 8305030275

8305130034 NPDES noncompliance notification on 830429,daily max pH effluent limit exceeded Investigation will include review of sampling & analysis techniques,insp of treatment equipment & review of operator logs
FAY,C W Wisconsin Electric Power Co 83/05/05 Wisconsin, State of 2pp 18436 208 24X Fiche 50-266,83/05/05,8305130034

8305240331 LER 83-006/03L-0 on 830419,time delay setpoint of contact from time delay relay 2-TDRC/A06 & 4,160-volt degraded grid voltage relay 2-275/A06 set above Tech Spec limit Caused by bumping or mispositioning time set knob W/830510 ltr
FAY,C W Wisconsin Electric Power Co 83/05/10 KEPPLER,J G
Region 3, Office of Director 3pp 18575 113 24X
Fiche 50-301,83/05/10,8305240331

8305240350 LER 83-005/01T-0 on 830428,body-to-bonnet leak on A loop RTD bypass isolation valve RC-559A & boric acid wastage of four studs discovered Leakage caused stud wastage Studs & nuts replaced & valve on other loop examined W/830511 ltr
FAY,C W Wisconsin Electric Power Co 83/05/11 KEPPLER,J G
Region 3, Office of Director 4pp 18574 071 24X
Fiche 50-301,83/05/11,8305240350

8305190226 Followup to 830331 NPDES noncompliance notification On 830316 & 17,retention pond discharge (Sample Point 501) exceeded pH limit Caused by carryover of lime from water treatment sys
FAY,C W Wisconsin Electric Power Co 83/05/12 Wisconsin, State of, 2pp 18500 202 24X Fiche 50-266,83/05/12,8305190226.

8305240412 LER 83-003/01T-0 has been cancelled
FAY,C W Wisconsin Electric Power Co 83/05/12 KEPPLER,J G
Region 3, Office of Director 2pp 18573 352 24X
Fiche 50-301,83/05/12,8305240412

8305240002 PNO-III-83-037 on 830509,Region III radiation specialist learned that main steam line noble gas monitors not yet installed per 830314 commitment date Ofc of Investigation investigating failure Monitors to be installed by mid June
LOVENDALE,P , PAPERIELLO,C Region 3, Office of Director 83/05/18
1p 18549 138 24X Fiche 50-266,83/05/18,8305240002

8305240379 NPDES noncompliance notification on 830429,pH of retention pond discharge found above limit Caused by demineralized makeup water treatment sys problems re undissolved lime carrying through to pressure filter sys
FAY,C W Wisconsin Electric Power Co 83/05/18 Wisconsin, State of 1p 18571 040 24X Fiche 50-266,83/05/18,8305240379

DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

8305270456 Forwards IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/28
HANCOCK,J A Florida Power Corp 2pp 18644 163 24X
Fiche 50-302,83/03/28,8305270456

--8305270466 IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted Major area inspected emergency preparedness exercise
HUFFMAN,G N , JENKINS,G R Region 2, Office of Director
83/03/28 11pp 18644 165 24X Fiche 50-302,83/03/28,8305270456

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305270209 Forwards IE Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/25
WILGUS,W S Florida Power Corp 2pp 18637 314 24X
Fiche 50-302,83/05/25,8305270209

--8305270212 IE Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted Major areas inspected site orientation, review of security plan & security organization-mgt Details withheld (ref 10CFR73 21)
MOORE,D E , URYC,B Region 2, Office of Director MCGUIRE,D R
Division of Emergency Preparedness & Materials Safety 83/05/24
2pp 18637 316 24X Fiche 50-302,83/05/25,8305270209

J Insurance & indemnity information

8305040204 Forwards Endorsements 58 & 44 to NELIA Policy NF-195 & MAELU Policy MF-91,respectively
DUCK,J R Marsh & McLennan, Inc 83/04/29 SALTZMAN,J Assistant Director for State & Licensee Relations 3pp 18323 216 24X
Fiche 50-302,83/04/29,8305040204

8305190022 Forwards Endorsements 59 & 45 to NELIA Policy NF-195 & MAELU Policy MF-91,respectively
DUCK,J R Marsh & McLennan, Inc 83/05/12 SALTZMAN,J Assistant Director for State & Licensee Relations 3pp 18502 036 24X
Fiche 50-302,83/05/12,8305190022

P Operating license stage documents & correspondence

8303280319 Forwards order confirming licensee commitments on post-TMI-related issues Order based on commitments contained in util responses to NRC Generic Ltrs 82-05 & 82-10
STOLZ,J F Operating Reactors Branch 4 83/03/14 HANCOCK,J A
Florida Power Corp 3pp 17713 234 24X Fiche 50-302,83/03/14, 8303280319

--8303280325 Order confirming licensee commitments on post-TMI-related issues
PURPLE,R A Assistant Director for Licensing 83/03/14
Florida Power Corp 10pp 17713 237 24X Fiche 50-302,83/03/14, 8303280319

8305230393 Forwards analysis of estimated backfitting costs per 830208 ltr Estimated $174 million spent for backfitting Backfitting expenditures will average 40% of annual expenditures from 1977 through 1985
HANCOCK J A Florida Power Corp 83/03/25 TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18543 358 24X Fiche 50-302, 83/03/25, 8305230393

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X Fiche 50-000, 83/04/11, 8305230720

8305120037 Forwards generic safety evaluation supporting continued operation of PWRs w/Dresser primary safety valves Safety valve ring settings acceptable
STOLZ, J F Operating Reactors Branch 4 83/04/28 WILGUS, W S Florida Power Corp 2pp 18443 242 24X Fiche 50-302, 83/04/28, 8305120037

8305030036 Proposes mod design to fulfill monthly testing requirement of IEEE-279-1971 consistent w/testing for first & second level undervoltage relay protection sys Monthly relay bench calibr test will verify absence of relay setpoint drift
WESTAFER, G R Florida Power Corp 83/04/29 STOLZ, J F Operating Reactors Branch 4 2pp 18300 356 24X Fiche 50-302, 83/04/29, 8305030036

8305030050 Advises that justification for continued operation will be included in 830520 submittal per 830223 ltr re environ qualification of electrical equipment, in response to 830323 ltr Facility presently shut down for refueling
WESTAFER, G R Florida Power Corp 83/04/29 STOLZ, J F Operating Reactors Branch 4 1p 18300 351 24X Fiche 50-302, 83/04/29, 8305030050

8305090462 Forwards B&W "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits," per 830331 commitment
WESTAFER, G R Florida Power Corp 83/04/29 STOLZ, J F Operating Reactors Branch 4 1p 18362 153 24X Fiche 50-302, 83/04/29, 8305090462

--8305090464 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits "
* Babcock & Wilcox Co 77 1140899-01 83/04/29 29pp 18362 154 24X Fiche 50-302, 83/04/29, 8305090462

8305200378 Submits response to NRC 830222 ltr re exemption from 10CFR50 44(c)(3)(iii), "Reactor Vessel Head Heat " Interim exemption extending implementation deadline requested prior to restart from refueling outage scheduled for 830709
WESTAFER, G R Florida Power Corp 83/04/29 EISENHUT, D G Division of Licensing 3pp 18518 106 24X Fiche 50-302, 83/04/29, 8305200378

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda, MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & justification for continued operation
MINER, S Operating Reactors Branch 4 83/05/02 STOLZ, J Operating Reactors Branch 4 2pp 18353 092 24X Fiche 50-000, 83/05/02, 8305060365

8305130002 Notifies of preliminary plan to implement 820104 amend to regulation re hydrogen recombiner requirement scheduled for Spring 1985 refueling outage External recombiner must be safety-grade to ensure accident survivability
WESTAFER, G R Florida Power Corp 83/05/06 STOLZ, J F Operating Reactors Branch 4 2pp 18436 327 24X Fiche 50-302, 83/05/06, 8305130002

8305130012 Advises that preliminary offsite dose calculation manual (radiological effluent Tech Specs) submitted on 830427
WESTAFER, G R Florida Power Corp 83/05/06 STOLZ, J F Operating Reactors Branch 4 1p 18440 043 24X Fiche 50-302, 83/05/06, 8305130012

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305130067 Advises that util endorses Rev 3 to BAW-10092P & BAW-10154P as response to NUREG-0737, Item II K 3 30, "Revised Small Break LOCA Methods to Show Compliance W/10CFR50, App K " Work on item will not commence until repts approved by NRC
WESTAFER, G R Florida Power Corp 83/05/09 STOLZ, J F Operating Reactors Branch 4 1p 18436 245 24X Fiche 50-302, 83/05/09, 8305130067

8305190344 Forwards commitments for qualification of insp, exam & testing & audit personnel to eliminate possible conflicts & misunderstandings
WESTAFER, G R Florida Power Corp 83/05/13 EISENHUT, D G Division of Licensing 2pp 18500 020 24X Fiche 50-302, 83/05/13, 8305190344

8305240359 Updates suatus of reactor internals bolting problem All upper core barrel bolts will be replaced & backup ultrasonic exam on surveillance specimen holder tube bolts performed by 830520 Basis for decisions & plans discussed
BAYNARD, P Y Florida Power Corp 83/05/20 STOLZ, J F Operating Reactors Branch 4 2pp 18571 004 24X Fiche 50-302, 83/05/20, 8305240359

8305270092 Forwards "Crystal River Unit 3 Environ Qualification Status," per 10CFR50 49
BAYNARD, P Y Florida Power Corp 83/05/20 STOLZ, J F Operating Reactors Branch 4 2pp 18639 001 24X Fiche 50-302, 83/05/20, 8305270092

--8305270095 "Crystal River Unit 3 Environ Qualification Status "
* NUS Corp 83/05/20 416pp 18639 003 24X Fiche 50-302, 83/05/20, 8305270092

Q Inspection reports, IE Bulletins & correspondence

8305270295 Provides implementation dates for policies & procedures necessary to meet commitment per requirements of ANSI N45 2 9-1974 Three-phase plan developed to resolve deficiencies identified in IE Insp Rept 50-302/82-20
BAYNARD, P Y Florida Power Corp 83/02/16 O'REILLY, J P Region 2, Office of Director 2pp 18641 185 24X Fiche 50-302, 83/02/16, 8305270295

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270456 Forwards IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/28 HANCOCK, J A Florida Power Corp 2pp 18644 163 24X Fiche 50-302, 83/03/28, 8305270456

--8305270466 IE Insp Rept 50-302/83-06 on 830222-23 No noncompliance noted Major area inspected emergency preparedness exercise
HUFFMAN, G N , JENKINS, G R Region 2, Office of Director 83/03/28 11pp 18644 165 24X Fiche 50-302, 83/03/28, 8305270456

8305270112 Forwards IE Insp Rept 50-302/83-08 on 830307-11 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/06 WILGUS, W S Florida Power Corp 2pp 18638 234 24X Fiche 50-302, 83/04/06, 8305270112

--8305270121 IE Insp Rept 50-302/83-08 on 830307-11 No noncompliance noted Major areas inspected gaseous effluents, IE info notices & semiannual effluent & waste disposal rept
KAHLE, J B Region 2, Office of Director DARR, K P Division of Emergency Preparedness & Materials Safety 83/03/25 5pp 18638 236 24X Fiche 50-302, 83/04/06, 8305270112

8305270347 Forwards IE Insp Rept 50-302/83-05 on 830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/06 WILGUS, W S Florida Power Corp 2pp 18642 106 24X Fiche 50-302, 83/04/06, 8305270347

--8305270354 IE Insp Rept 50-302/83-05 on 830314-18 No noncompliance noted Major areas inspected radiological environ monitoring, including mgt & administrative controls & status review of radiological environ monitoring program
CUNNINGHAM, A L , KUZO, G B Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Radiological Safety Programs 83/04/06 5pp 18642 108 24X Fiche 50-302, 83/04/06, 8305270347

8305270499 Ack receipt of 830311 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-29
LEWIS,R C Division of Project & Resident Programs 83/04/13
WILGUS,W S Florida Power Corp 1p 18646 082 24X
Fiche 50-302,83/04/13,8305270499

--8305270503 Responds to NRC 830210 ltr re violations noted in IE Insp Rept 50-302/82-29 Disagrees w/violation re log entry for action statements
WESTAFER,G R Florida Power Corp 83/03/11 O'REILLY,J P
Region 2, Office of Director 4pp 18646 083 24X
Fiche 50-302,83/04/13,8305270499

--8305270509 Forwards IE Insp Rept 50-302/82-29 on 821124-1217 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/02/10
HANCOCK,J A Florida Power Corp 2pp 18646 087 24X
Fiche 50-302,83/04/13,8305270499

--8305270516 Notice of violation from insp on 821124-1217
* Region 2, Office of Director 83/02/16 2pp 18646 089 24X
Fiche 50-302,83/04/13,8305270499

--8305270525 IE Insp Rept 50-302/82-29 on 821124-1217 Noncompliance noted failure to log entry & exit from Tech Spec action statement & failure to maintain functional test manual initiation of reactor bldg isolation function
STETKA,T F Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/01/31 11pp 18646 091 24X
Fiche 50-302,83/04/13,8305270499

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305090584 Forwards FR notice granting relief from ASME Code Section XI requirements,per util 830221 & 0314 requests
STOLZ,J F Operating Reactors Branch 4 83/04/27 WILGUS,W S
Florida Power Corp 2pp 18367 350 24X Fiche 50-302,83/04/27,8305090584

--8305090589 Notice of granting relief from ASME Code Section XI requirements re nozzle vessel inservice insp
STOLZ,J F Operating Reactors Branch 4 83/04/27 2pp
18367 352 24X Fiche 50-302,83/04/27,8305090584

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305270247 Ack receipt of 830209 & 0408 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/82-32
DANCE,H C Division of Project & Resident Programs 83/04/29
WILGUS,W S Florida Power Corp 1p 18641 210 24X
Fiche 50-302,83/04/29,8305270247

--8305270253 Responds to NRC 830111 ltr re violations noted in IE Insp Rept 50-302/82-32 Corrective actions welder qualification records reviewed & welder qualification status tracking program being developed
WESTAFER,G R Florida Power Corp 83/04/08 O'REILLY,J P
Region 2, Office of Director 2pp 18641 211 24X
Fiche 50-302,83/04/29,8305270247

--8305270258 Responds to NRC 830111 ltr re violations noted in IE Insp Rept 50-302/82-32 Corrective actions welder post-qualified on 820803
WESTAFER,G R Florida Power Corp 83/02/09 O'REILLY,J P
Region 2, Office of Director 2pp 18641 213 24X
Fiche 50-302,83/04/29,8305270247

--8305270260 Forwards IE Insp Rept 50 302/82-32 on 821213-16 & notice of violation
DANCE,H C Division of Project & Resident Programs 83/01/11
HANCOCK,J A Florida Power Corp 2pp 18641 215 24X
Fiche 50-302,83/04/29,8305270247

--8305270264 Notice of violation from insp on 821213-16
* Region 2, Office of Director 83/01/11 1p 18641 217 24X
Fiche 50-302,83/04/29,8305270247

--8305270269 IE Insp Rept 50 302/82-32 on 821213-16 Noncompliance noted failure to meet ASME Code Section IX welder performance qualification requirements
ECONOMOS,N Region 2, Office of Director BLAKE,J J Division of Emergency Preparedness & Materials Safety 83/01/05 6pp
18641 218 24X Fiche 50-302,83/04/29,8305270247

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000 83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83 31, "Error in ANLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270280 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-04
LEWIS,R C Division of Project & Resident Programs 83/05/20
WILGUS,W S Florida Power Corp 1p 18642 038 24X
Fiche 50-302,83/05/20,8305270280

--8305270312 Informs that util response to NRC 830323 ltr re violations noted in IE Insp Rept 50-302/83-04 will be submitted on 830429 Addl reviews will determine if abnormal & emergency procedural review accomplished & documented
WESTAFER,G R Florida Power Corp 83/04/25 O'REILLY,J P
Region 2, Office of Director 1p 18642 039 24X
Fiche 50-302,83/05/20,8305270280

--8305270318 Responds to NRC 830323 ltr re violations noted in IE Insp Rept 50-302/83-04 Corrective actions plant operating QA manual,abnormal & emergency procedures,reviewed & procedure review listing in TDP-203 to be revised by 830601
WESTAFER,G R Florida Power Corp 83/04/29 O'REILLY,J P
Region 2, Office of Director 2pp 18642 040 24X
Fiche 50-302,83/05/20,8305270280

8305270209 Forwards IE Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/25
WILGUS,W S Florida Power Corp 2pp 18647 314 24X
Fiche 50-302,83/05/25,8305270209

--8305270212 IE Safeguards Insp Rept 50-302/83-12 on 830502-06 No noncompliance noted Major areas inspected site orientation, review of security plan & security organization-mgt Details withheld (ref 10CFR73 21)
MOORE, D E , URYC, B Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/05/24 2pp 18637 316 24X Fiche 50-302, 83/05/25, 8305270209

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305130043 Forwards monthly operating rept for Apr 1983
WESTAFER, G R Florida Power Corp 83/05/09 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18437 026 24X Fiche 50-302, 83/05/09, 8305130043

--8305130047 Monthly operating rept for Apr 1983
BOGART, D , CULVER, M W Florida Power Corp 83/05/02 4pp 18437 027 24X Fiche 50-302, 83/05/09, 8305130043

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573

8305050016 Forwards LER 83-018/01T-0
WESTAFER, G R Florida Power Corp 83/04/27 O'REILLY, J P Region 2, Office of Director 1p 18339 059 24X Fiche 50-302, 83/04/27, 8305050016

--8305050025 LER 83-018/01T-0 on 830413, preliminary repts received from B&W indicating that 51 of 120 upper core barrel bolts ultrasonically tested may be defective Cause unknown Investigation underway Supplemental rept will be written
BUFE, J L Florida Power Corp 83/04/27 Region 2, Office of Director 2pp 18339 060 24X Fiche 50-302, 83/04/27, 8305050016

8305110380 Forwards LER 83-017/01T-0 Detailed event analysis encl
HENRY, P C Florida Power Corp 83/05/02 O'REILLY, J P Region 2, Office of Director 2pp 18406 223 24X Fiche 50-302, 83/05/02, 8305110380

--8305110390 LER 83-017/01T-0 on 830418, during surface & visual NDE of reactor head & internals, lifting devices revealed several indications on tripod, turnbuckle & latchblock Caused by improper mfg Indications repaired
HUGHES, P G Florida Power Corp 83/05/02 Region 1, Office of Director 1p 18406 225 24X Fiche 50-302, 83/05/02, 8305110380

8305130179 Forwards LER 83-019/03L-0
WESTAFER, G R Florida Power Corp 83/05/06 O'REILLY, J P Region 2, Office of Director 1p 18440 082 24X Fiche 50-302, 83/05/06, 8305130179

--8305130188 LER 83-019/03L-0 on 830406, breaker in engineered safeguards (ES) motor control ctr 3B1 shorted, rendering ES bus 3B (480-volt) & associated equipment inoperable Caused by personnel not properly aligning breaker connectors
HUGHES, P G Florida Power Corp 83/05/06 Region 2, Office of Director 1p 18440 083 24X Fiche 50-302, 83/05/06, 8305130179

8305170399 Forwards LER 83-020/03L-0
WESTAFER, G R Florida Power Corp 83/05/09 O'REILLY, J P Region 2, Office of Director 1p 18471 221 24X Fiche 50-302, 83/05/09, 8305170399

--8305170402 LER 83-020/03L-0 on 830409, discovered that surveillance interval for fire detection instrumentation in emergency diesel generator & control rooms exceeded by 6 months Caused by procedural inadequacy Procedure SP-411 will be revised
BUFE, J L Florida Power Corp 83/05/09 Region 2, Office of Director 2pp 18471 222 24X Fiche 50-302, 83/05/09, 8305170399

8305260309 Interim deficiency rept re core support structure bolting Initially reported on 830419 Evaluation of corrective action in progress Next rept will be sent by 831101
COOK, J W Consumers Power Co 83/05/19 KEPPLER, J G Region 3, Office of Director 3pp 18625 200 24X Fiche 50-000, 83/05/19, 8305260309

--8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
TAYLOR, J H Babcock & Wilcox Co 83/04/22 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp 18625 210 24X Fiche 50-000, 83/05/19, 8305260309

DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305100122 Forwards post-exercise evaluation for 810729 exercise, final rept of reexercise on 811007 & final exercise rept of 830118 exercise No significant deficiencies cited
KRIMM, R W Federal Emergency Management Agency 83/04/08
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 18375 048 24X Fiche 50-295, 83/04/08, 8305100122

--8305100126 "Zion Nuclear Generating Station Small-Scale Joint Emergency Exercise, 830118," final rept
* Federal Emergency Management Agency 83/03/04 71pp 18375 050 24X Fiche 50-295, 83/04/08, 8305100122

--8305100131 "Zion Nuclear Power Station Reexercise, WI/Kenosha County (Small-Scale) 811007," final rept
* Federal Emergency Management Agency 82/04/30 32pp 18375 121 24X Fiche 50-295, 83/04/08, 8305100122

--8305100136 "Post-Exercise Evaluation, Exercise of State & Local Radiological Emergency Response Plans for IL & WI (Near Zion Nuclear Power Station) "
* Federal Emergency Management Agency 81/07/29 44pp 18375 153 24X Fiche 50-295, 83/04/08, 8305100122

8305030076 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18326 103 24X Fiche 50-295, 83/04/22, 8305030076

--8305030084 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests "
PLIML, G Commonwealth Edison Co 83/04/06 DENTON, H R NRC - No Detailed Affiliation Given 1p 18326 104 24X Fiche 50-295, 83/04/22, 8305030076

--8305030091 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests " Procedure Change Request A-83-51 encl
NYKIRK, J W Commonwealth Edison Co 83/03/25 5pp 18326 105 24X Fiche 50-295, 83/04/22, 8305030076

8305030104 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18309 354 24X Fiche 50-295, 83/04/22, 8305030104

--8305030114 Forwards public version of Rev 11 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group "
PLIML, G Commonwealth Edison Co 83/04/06 DENTON, H R NRC - No Detailed Affiliation Given 1p 18309 355 24X Fiche 50-295, 83/04/22, 8305030104

--8305030117 Public version of Rev 11 to Emergency Plan Implementing Procedure EPIP 320-1, "Activation of Generating Station Emergency Plan Station Group " Procedure Change Request A-83-88 encl
NYKIRK, J W Commonwealth Edison Co 83/03/25 7pp 18309 356 24X Fiche 50-295, 83/04/22, 8305030104

8305060673 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18357 326 24X Fiche 50-295, 83/04/25, 8305060673

--8305060679 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment " Procedure change request encl
PLIML,G Commonwealth Edison Co 83/03/09 DENTON,H R NRC - No Detailed Affiliation Given 3pp 18357 327 24X
Fiche 50-295,83/04/25,8305060673

--8305060686 Public version of Rev 5 to Emergency Plan Implementing Procedure EPIP 550-2, "Environ Emergency Kit & Emergency Operations Facility Radiological Equipment "
* Commonwealth Edison Co 83/03/08 5pp 18357 330 24X
Fiche 50-295,83/04/25,8305060673

8305060410 Forwards IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld (ref 10CFR73 21)
KEPPLER,J G Region 3, Office of Director 83/05/03 O'CONNOR,J J Commonwealth Edison Co 3pp 18343 239 24X Fiche 50-295,
83/05/03,8305060410

--8305060418 IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Details withheld (ref 10CFR73 21)
BELANGER,J L Region 3, Office of Director 83/04/29 1p 18343 242 24X Fiche 50-295,83/05/03,8305060410

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240246 Advises that requirements of NUREG-0737,Item III A 2 f, "Emergency Preparedness,Upgrade Emergency Plans to Meet App E to 10CFR50," satisfied
VARGA,S A Operating Reactors Branch 1 83/05/16 FARRAR,D L Commonwealth Edison Co 3pp 18593 303 24X Fiche 50-295,83/05/16,
8305240246

O Advisory Committee on Reactor Safeguards reports & correspondence

8305160246 Comments on SSMRP risk analysis Risks from seismic events should be analyzed separately from internal events w/results treated independently Only upper limits need be estimated to determine IP risks acceptable
DAVIS,P R Affiliation Unknown DAVIS,P R ACRS - Advisory Committee on Reactor Safeguards 83/04/16 OKRENT,D ACRS - Advisory Committee on Reactor Safeguards 1p 18472 001 24X
Fiche 50-295,83/04/16,8305160246

P Operating license stage documents & correspondence

8303300001 Forwards Amends 82 & 72 to Licenses DPR-39 & DPR-48, respectively & notice of issuance & availability Amends delete nonradiological water quality-related requirements
VARGA,S A Operating Reactors Branch 1 83/03/11 FARRAR,D L Commonwealth Edison Co 3pp 17751 292 24X Fiche 50-295,83/03/11,
8303300001

--8303300002 Amends 82 & 72 to Licenses DPR-39 & DPR-48,respectively, deleting nonradiological water quality-related requirements
VARGA,S A Operating Reactors Branch 1 83/03/11 61pp 17751 295 24X Fiche 50-295,83/03/11,8303300001

--8303300003 Notice of issuance & availability of Amends 82 & 72 to Licenses DPR-39 & DPR-48,respectively
VARGA,S A Operating Reactors Branch 1 83/03/11 2pp 17751 356 24X Fiche 50-295,83/03/11,8303300001

8304270053 Agrees w/830311 ltr demonstrating that Tech Specs indicate conditions under which protection sys channels may be bypassed during cooldown Review closed
VARGA,S A Operating Reactors Branch 1 83/04/12 FARRAR,D L Commonwealth Edison Co 2pp 18254 150 24X Fiche 50-295,83/04/12,
8304270053

8305180691 Forwards revised order modifying completion dates for NUREG-0737,Items II B 2, "Plant Shielding," II B 3, "Post Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation "
VARGA,S A Operating Reactors Branch 1 83/04/28 FARRAR,D L Commonwealth Edison Co 2pp 18505 181 24X Fiche 50-295,83/04/28,
8305180691

--8305180702 Revised order modifying completion dates for NUREG-0737, Items II B 2, "Plant Shielding " II B 3, "Post-Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation," per Generic Ltrs 82-05 & 82-10
EISENHUT,D G Division of Licensing 83/04/28 Commonwealth Edison Co 9pp 18505 183 24X Fiche 50-295,83/04/28,8305180691

8305040317 Responds to NRC request for add'l info re TMI action plan items Matl supports util position that nonsafety-related equipment falls outside scope of Franklin Research Ctr review Justification not necessary
LENTINE,F G Commonwealth Edison Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18323 289 24X
Fiche 50-295,83/05/02,8305040317

8305110144 Ack receipt of 830318 ltr,providing basis for not paying add'l fee for 801107 application re assurance of redundancy in DHR capability Fees include cost of prior staff hours expended & associated contractual svcs Add'l fee due
MILLER,W O License Fee Management Branch 83/05/03 LENTINE,F G Commonwealth Edison Co 2pp 18421 347 24X Fiche 50-295,83/05/03,
8305110144

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305170218 Forwards response to 830208 & 0317 requests for add'l info re NUREG-0737,Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor "
LENTINE,F G Commonwealth Edison Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 8pp 18466 332 24X
Fiche 50-295,83/05/13,8305170218

8305240506 Forwards fee for Amends 65 & 62 to Licenses DPR-39 & DPR-48, respectively
LENTINE,F G Commonwealth Edison Co 83/05/18 MILLER,W O License Fee Management Branch 2pp 18571 264 24X
Fiche 50-295,83/05/18,8305240506

8305240473 Provides add'l info re probabilistic safety study,discussed during 830331 NRC site visit Formal document verification of fan operability not previously required Procedures revised to include operability of fan coolers
LENTINE,F G Commonwealth Edison Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18549 355 24X
Fiche 50-295,83/05/19,8305240473

8305250077 Forwards Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by 10CFR50 49 for Zion Units 1 & 2 "
LENTINE,F G Commonwealth Edison Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18589 042 24X
Fiche 50-295,83/05/19,8305250077

--8305250084 Rev 2 to "Environ Qualification of Electrical Equipment Important to Safety Covered by 10CFR50 49 for Zion Units 1 & 2 "
* Sargent & Lundy, Inc 83/05/20 776pp 18589 046 24X
Fiche 50-295,83/05/19,8305250077

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan
GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000,83/05/26,8305310086

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305100262 Forwards IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 & notice of violation
SHAFER,W D Region 3, Office of Director 83/04/20 REED,C Commonwealth Edison Co 2pp 18372 242 24X Fiche 50-295,83/04/20,
8305100262

--8305100271 IE Insp Repts 50-295/83-02 & 50-304/83-02 on 830118-0304 Noncompliance noted failure to notify NRC of unplanned release while purging & drawing routine sample WATERS, J R , HARTMANN, P L , DUNAWAY, F R Region 3 Office of Director 83/04/20 13pp 18372 245 24X Fiche 50-295, 83/04/20, 8305100262

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, Inoperable Containment Atmosphere Sensing Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

830517033/ Forwards IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311, 14-17, 22-23 & 0407 & notices of violation & deviation PAPERIELLO, C J Region 3, Office of Director 83/04/27 REED, C Commonwealth Edison Co 2pp 18465 274 24X Fiche 50-295, 83/04/27, 8305170337

--8305170344 Notice of violation from insp on 830311, 14-17, 22-23 & 0407 PAPERIELLO, C J Region 3 Office of Director 83/04/27 2pp 18465 276 24X Fiche 50-295, 83/04/27, 8305170337

--8305170348 Notice of deviation from insp on 830311, 14-17, 22-23 & 0407 " Region 3, Office of Director 83/04/27 1p 18465 278 24X Fiche 50-295, 83/04/27, 8305170337

--8305170353 IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311, 14-17, 22-23 & 0407 Noncompliance noted contamination surveys of transfer canal workers exhibiting nasal contamination not documented Fuel pool samples not analyzed LOVENDALE, P C , MILLER, D E , GREGER, L R Region 3, Office of Director 83/04/25 11pp 18465 279 24X Fiche 50-295, 83/04/27, 8305170337

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020252 EN-83-028 on 830503, notice of violation & proposed imposition of civil penalty in amount of $10,000 to be issued Action based on failure to control access into protected & vital areas & unauthorized entry ROSANO, R Director's Office, Office of Inspection and Enforcement 83/04/28 1p 18277 277 24X Fiche 50-295, 83/04/28, 8305020252

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305060410 Forwards IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 & notice of violation Notice of violation withheld (ref 10CFR73 21) KEPPLER, J G Region 3, Office of Director 83/05/03 O'CONNOR, J J Commonwealth Edison Co 3pp 18343 239 24X Fiche 50-295, 83/05/03, 8305060410

--8305060418 IE Safeguards Insp Repts 50-295/83-06 & 50-304/83-07 on 830315 Noncompliance noted unauthorized entry into protected & vital area & failure to rept safeguards event Details withheld (ref 10CFR73 21) BELANGER, J L , MADEDA, T J , CREED, J R Region 3, Office of Director 83/04/29 1p 18343 242 24X Fiche 50-295, 83/05/03, 8305060410

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030,

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200351 Forwards results of investigation on Dr-82 source & significance in containments, per 830216 committal Investigation result of IE Insp Repts 50-295/82-30 & 50-304/82-27 LENTINE, F G Commonwealth Edison Co 83/05/17 KEPPLER, J G Region 3, Office of Director 4pp 18516 247 24X Fiche 50-295, 83/05/17, 8305200351

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305310095 Forwards responses to violation & deviation noted in IE Insp Repts 50-295/83-07 & 50-304/83-06 on 830311-0417 Corrective actions personnel whole body count initiated to document internal contamination FARRAR, D L Commonwealth Edison Co 83/05/25 KEPPLER, J G Region 3, Office of Director 4pp 18658 074 24X Fiche 50-295, 83/05/25, 8305310095

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305120013 Forwards monthly operating repts for Apr 1983 GRAESSER, K L Commonwealth Edison Co 83/05/09 Director's Office, Office of Inspection and Enforcement 1p 18423 058 24X Fiche, 50-295, 83/05/09, 8305120013

--8305120016 Monthly operating repts for Apr 1983 AUSTIN, G Commonwealth Edison Co 83/05/09 11pp 18423 059 24X Fiche 50-295, 83/05/09, 8305120013

S Reportable occurrences, LERs & related correspondence

8305030440 Forwards LER 83-009/03L-0 GRAESSER, K L Commonwealth Edison Co 83/04/25 KEPPLER, J G Region 3, Office of Director 1p 18306 265 24X Fiche 50-304, 83/04/25, 8305030440

--8305030446 LER 83-009/03L-0 on 830324, failed fuel letdown monitor 2RTPR27 found out of tolerance low Caused by electronic instrument drift Radiation monitor recalibr & returned to svc WILLIAMS, V S Commonwealth Edison Co 83/04/25 Region 3, Office of Director 1p 18306 266 24X Fiche 50-304, 83/04/25, 8305030440

8305130196 Forwards LER 83-010/03L-0 GRAESSER, K L Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 1p 18439 353 24X Fiche 50-304, 83/05/10, 8305130196

--8305130211 LER 83-010/03L-0 on 830411, during Purge 0-83-285 of containment, radiation monitors 2RT-PR25, 2RT-PR26 & 1RT-PR26 taken out of svc for maint to calibr instrument Caused by operator error Operator reinstructed in procedures LINDSAY, F J Commonwealth Edison Co 83/05/10 Region 3, Office of Director 1p 18439 354 24X Fiche 50-304, 83/05/10, 8305130196

8305240214 LER 83-011/03L-0 on 830413,while purging containment during refueling outage,recorder trace for 2RT-PR25 did not return to normal following source check Caused by sticking of print head due to oxidation on slide-wire W/830511 ltr
JAKUBAITIS,T C , GRAESSER,K L Commonwealth Edison Co 83/05/11
KEPPLER,J G Region 3, Office of Director 2pp 18548 025 24X
Fiche 50-304,83/05/11,8305240214

8305310160 LER 83-012/03L-0 on 830426,steam generator 2A steam pressure transmitter 2PT-516 found out of tolerance Caused by instrument drift on transmitter Transmitter recalibr & returned to svc W/830525 ltr
CANTWELL,P F , GRAESSER,K L Commonwealth Edison Co 83/05/25
KEPPLER,J G Region 3, Office of Director 2pp 18651 228 24X
Fiche 50-304,83/05/25,8305310160

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

830504000/ Releases public version of rev to emergency plan
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18331 008 24X Fiche 50-305,83/04/25, 8305040007

--8305040009 Forwards public version of Rev 1 to emergency plan
GIESLER,C W Wisconsin Public Service Corp 83/04/14
DENTON,H R Office of Nuclear Reactor Regulation, Director 1p
18331 009 24X Fiche 50-305,83/04/25,8305040007

--8305040014 Public version of Rev 1 to emergency plan
* Wisconsin Public Service Corp 83/04/06 238pp 18331 010
24X Fiche 50-305,83/04/25,8305040007

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

P Operating license stage documents & correspondence

8305230728 Forwards listing of regulatory-induced major plant mods & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 79-01,79-02 & 79-14 mods provided
GIESLER,C W Wisconsin Public Service Corp 83/03/25
TOURTELLOTTE,J Regulatory Reform Task Force 6pp 18542 263 24X
Fiche 50-305,83/03/25,8305230728

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305040090 Advises that Rev 1 to XN-NF-79-49-(P) classified proprietary,per 830222 ltr
VARGA,S A Operating Reactors Branch 1 83/04/22 GIESLER,C W
Wisconsin Public Service Corp 2pp 18328 240 24X
Fiche 50-305,83/04/22,8305040090

8305030600 Application for Amend 54 to License DPR-43,revising limiting conditions for operation,surveillance requirements & administrative controls
GIESLER,C W Wisconsin Public Service Corp 83/04/29 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 18303 182
24X Fiche 50-305,83/04/29,8305030600

--8305030602 Proposed Tech Specs revising limiting conditions for operation,surveillance requirements & administrative controls
* Wisconsin Public Service Corp 83/04/29 25pp 18303 187
24X Fiche 50-305,83/04/29,8305030600

8305110050 Forwards Amend 49 to License DPR-43,safety evaluation & notice of issuance & availability Amend changes Tech Specs re RCS leakage,condensate storage tank supply & auxiliary feedwater pump testing
GROTENHUIS,M Operating Reactors Branch 1 83/04/29 GIESLER,C W
Wisconsin Public Service Corp 2pp 18420 324 24X
Fiche 50-305,83/04/29,8305110050

--8305110052 Amend 49 to License DPR-43,changing Tech Specs re RCS leakage,condensate storage tank supply & auxiliary feedwater pump testing
VARGA,S A Operating Reactors Branch 1 83/04/29 8pp
18420 326 24X Fiche 50-305,83/04/29,8305110050

- 8305110055 Safety evaluation supporting amend 49 to License DPR-43
* Office of Nuclear Reactor Regulation Director 83/04/29 4pp
18420 334 24X Fiche 50-305,83/04/29 8305110050

--830511005a Notice of issuance / availability of Amend 49 to License DPR-43
VARGA,S A Operating Reactors Branch 1 83/04/29 2pp
18420 338 24X Fiche 50-305,83/04/29,8305110050

830504066' Forwards request for addl info re PORV/SV failures & challenges
VARGA,S A Operating Reactors Branch 1 83/05/02 GIESLER,C W
Wisconsin Public Service Corp 3pp 18336 262 24X
Fiche 50-305,83/05/02,8305040667

8305180573 Forwards SER supporting licensee responses to NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, Containment Hydrogen Monitor "
VARGA,S A Operating Reactors Branch 1 83/05/02 GIESLER,C W
Wisconsin Public Service Corp 2pp 18505 308 24X
Fiche 50-305,83/05/02,8305180573

--8305180580 Safety evaluation supporting licensee responses to NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, "Containment Hydrogen Monitor "
* Office of Nuclear Reactor Regulation Director 83/05/02 6pp
18505 310 24X Fiche 50-305,83/05/02,8305180573

8305100102 Advises that defective under voltage trip device delivered to Franklin Research Ctr Device probably failed during preoperational testing,possibly due to bottom tripping pin occasionally sticking in downward position
GIESLER,C W Wisconsin Public Service Corp 83/05/06 VARGA,S A
Operating Reactors Branch 1 2pp 18377 252 24X
Fiche 50-305,83/05/06,8305100102

8305100114 Forwards review of existing specs re containment cooling sys operability No mods required Revised section 3 3 "ESF & Auxiliary Sys," will be consistent w/NUREG-0452 & will be submitted as part of Amend 55
GIESLER,C W Wisconsin Public Service Corp 83/05/06 VARGA S A
Operating Reactors Branch 1 6pp 18375 220 24X
Fiche 50-305,83/05/06,8305100114

830511000J Forwards evaluation of loss of discharge back pressure on pump operability re NUREG-0737,Item II F 1 1 / 830131 SER, per IE Bulletin 80-04 Operability of auxiliary feedwater pumps after extended operation at runout flow addressed
GIESLER,C W Wisconsin Public Service Corp 83/05/06 VARGA,S A
Operating Reactors Branch 1 9pp 18408 280 24X
Fiche 50-305,83/05/06,8305110003

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305170150 Forwards addl info requested in 830502 ltr re PORV/SV failures & challenges Further ref should be made to 820625 response to NUREG-0737,Item II D 1
GIESLER,C W Wisconsin Public Service Corp 83/05/13 VARGA,S A
Operating Reactors Branch 1 3pp 18466 291 24X
Fiche 50-305,83/05/13,8305170150

8305230300 Application for Amend 49 to License DPR-43 re RCS leakage, condensate storage tank supply & auxiliary feedwater pump testing
GIESLER,C W Washington Public Power Supply System 83/05/13
GROTENHUIS,M NRC - No Detailed Affiliation Given 9pp 18539 120
24X Fiche 50-305,83/05/13,8305230300

--8305230308 Proposed changes to Tech Specs re RCS leakage,condensate storage tank supply & auxiliary feedwater pump testing
* Washington Public Power Supply System 83/05/13 6pp
18539 129 24X Fiche 50-305,83/05/13,8305230300

8305270009 Discusses 000410 ltr re use of term operable in Tech Specs which may not address multiple outages Tech Specs will be amended to incorporate STS instructions Proposed amend will be submitted within 30 days
GIESLER,C W Wisconsin Public Service Corp 83/05/24 VARGA,S A
Operating Reactors Branch 1 2pp 18638 350 24X
Fiche 50-305,83/05/24,8305270009

Q Inspection reports IE Bulletins * correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21 8212060385

8305230728 Forwards listing of regulatory-induced major plant mods & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 79-01,79-02 & 79-14 mods provided
GIESLER,C W Wisconsin Public Service Corp 83/03/25
TOURTELLOTTE,J Regulatory Reform Task Force 6pp 18542 263 24X
Fiche 50-305,83/03/25,8305230728

8305020349 Forwards IE Insp Rept 50-305/83-01 on 830103-0302 & notice of violation
NORELIUS,C E Division of Project & Resident Programs 83/04/11
GIESLER,C W Wisconsin Public Service Corp 2pp 18277 051 24X
Fiche 50-305,83/04/11,8305020349

--8305020352 Notice of violation from insp on 830103-0302
STREETER,J F Division of Project & Resident Programs 83/04/11
3pp 18277 053 24X Fiche 50-305,83/04/11,8305020349

--8305020356 IE Insp Rept 50-305/83-01 on 830103-0302 Noncompliance noted from SP0422-27, temporary changes made to Maint Procedure 5B-18469 w/o review or approval
NELSON,R L , JACKIW,I N Region 3, Office of Director 83/04/07
8pp 18277 056 24X Fiche 50-305,83/04/11,8305020349

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305040117 Discusses results of review of relief requests Relief granted in part from requirements of Section XI of ASME Code or other requirements as appropriate
VARGA,S A Operating Reactors Branch 1 83/04/19 GIESLER,C W
Wisconsin Public Service Corp 3pp 18328 117 24X
Fiche 50-305,83/04/19,8305040117

--8305040122 Safety evaluation supporting requests for relief from inservice insp requirements of Section XI of ASME Code for Class 1,2 & 3 components
* Office of Nuclear Reactor Regulation, Director 83/04/19 9pp
18328 120 24X Fiche 50-305,83/04/19,8305040117

--8305040125 Notice of granting relief from ASME Code requirements
VARGA,S A Operating Reactors Branch 1 83/04/19 2pp
18328 129 24X Fiche 50-305,83/04/19,8305040117

8305040518 Forwards IE Insp Rept 50-305/83-05 on 830314 & 15 No noncompliance noted
LITTLE,W S Region 3, Office of Director 83/04/20 GIESLER,C W
Wisconsin Public Service Corp 2pp 18321 256 24X
Fiche 50-305,83/04/20,8305040518

--8305040522 IE Insp Rept 50-305/83-05 on 830314 & 15 No noncompliance noted Major areas inspected licensee action re IE Bulletin 80-11, "Masonry Wall Design "
NORTON,J F , WILLIAMS,C C Region 3 Office of Director
83/04/15 5pp 18321 258 24X Fiche 50-305,83/04/20,8305040518

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305030314 Forwards addl info in response to IE Bulletin 80-11 re seismic qualification of masonry walls W/23 aperture cards Aperture cards are available in PDR
GIESLER,C W Wisconsin Public Service Corp 83/04/29 VARGA,S A
Operating Reactors Branch 1 12pp 18306 224 24X
Fiche 50-305,83/04/29,8305030314

8305050106 Forwards results of 1983 steam generator eddy current & fiber optics visual exams,per Tech Spec 4 2 b 5 a Summary of return to power SER encl Facility placed in C2 category, requiring next insp within 24 months
GIESLER,C W Wisconsin Public Service Corp 83/05/02 VARGA,S A
Operating Reactors Branch 1 13pp 18342 154 24X
Fiche 50-305,83/05/02,8305050106

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305100087 Confirms 830624 meeting in Glen Ellyn,IL to discuss SALP for facility
NORELIUS,C E Division of Project & Resident Programs 83/05/04
GIESLER,C W Wisconsin Public Service Corp 1p 18377 225 24X
Fiche 50-305,83/05/04,8305100087

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270486 Forwards IE Insp Rept 50-305/83-03 on 830314-18,25,31 & 0407 & notice of violation
HIND,J A Region 3, Office of Director 83/05/06 GIESLER,C W
Wisconsin Public Service Corp 2pp 18644 011 24X
Fiche 50-305,83/05/06,8305270486

--8305270493 Notice of violation from insp on 830314-18
HIND,J A Region 3, Office of Director 83/05/05 1p
18644 013 24X Fiche 50-305,83/05/06,8305270486

--8305270502 IE Insp Rept 50-305/83-03 on 830314-18,25,31 & 0407 Noncompliance noted failure to meet steam generator blowdown analysis sensitivity requirement of Tech Spec Table 4 11-1 & failure to collect environ precipitation sample
NICHOLSON,N A , ROSAK,S , SCHUMACHER,M C Region 3, Office of Director 83/05/04 10pp 18644 014 24X Fiche 50-305,83/05/06, 8305270486

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305180261 Responds to 830411 notice of violation & proposed imposition of civil penalty re capped containment pressure sensing lines NRC conclusions & actions inappropriate Violation isolated event & does not merit civil penalty
ZIEMER,P D Wisconsin Public Service Corp 83/05/11 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 31pp
18490 029 24X Fiche 50-305,83/05/11,8305180261

8305240104 Forwards clarifications & corrections to inservice insp program safety evaluation dtd 830419 Status of relief requests noted
VARGA,S A Operating Reactors Branch 1 83/05/16 GIESLER,C W
Wisconsin Public Service Corp 3pp 18593 360 24X
Fiche 50-305,83/05/16,8305240104

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33 'Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305310164 Submits results for First Quarter 1983 confirmatory measurements program for liquid waste sample & NRC spiked charcoal 1 & 2
RICHMOND,J S Washington Public Power Supply System 83/04/30
ROZAK,S Region 3, Office of Director 2pp 18652 285 24X
Fiche 50-305,83/04/30,8305310164

8305050106 Forwards results of 1983 steam generator eddy current & fiber optics visual exams,per Tech Spec 4 2 b 5 a Summary of return to power SER encl Facility placed in C2 category, requiring next insp within 24 months
GIESLER,C W Wisconsin Public Service Corp 83/05/02 VARGA,S A Operating Reactors Branch 1 13pp 18342 154 24X
Fiche 50-305,83/05/02,8305050106

8305130250 Forwards monthly operating rept for Apr 1983
GIESLER,C W Wisconsin Public Service Corp 83/05/10 Director s Office, Office of Inspection and Enforcement 1p 18439 214 24X
Fiche 50-305,83/05/10,8305130250

--8305130251 Monthly operating rept for Apr 1983
RUITER,G H Wisconsin Public Service Corp 83/05/02 5pp
18439 215 24X Fiche 50-305,83/05/10,8305130250

8305310154 Forwards annual environ radioactivity monitoring repts for 1982 W/o encl
MCDONNELL,L J Wisconsin, State of NRC-05-80-275 83/05/23
KEPPLER,J G Region 3, Office of Director 1p 18659 140 24X
Fiche 50-000,83/05/23,8305310154

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305100389 Forwards updated LER 83-005/03X-1
GIESLER,C W Wisconsin Public Service Corp 83/05/03 KEPPLER,J G
Region 3, Office of Director 1p 18377 326 24X
Fiche 50-305,83/05/03,8305100389

--8305100397 Updated LER 83-005/03X-1 on 830216,during surveillance test on diesel generator 1B,svc water outlet CV (SW-301B) from diesel oil cooler failed to open fully when diesel started Caused by erosion of ball,causing sticking Valve replaced
BERNHOFT,B L , THORGERSEN,J G Wisconsin Public Service Corp
83/05/03 Region 3, Office of Director 1p 18377 327 24X
Fiche 50-305,83/05/03,8305100389

8305170267 Forwards updated LER 82-030/01X-2
GIESLER,C W Wisconsin Public Service Corp 83/05/06 KEPPLER,J G
Region 3, Office of Director 1p 18465 020 24X
Fiche 50-305,83/05/06,8305170267

--8305170271 Updated LER 82-030/01X-2 on 821004,sensing lines on six safety-related containment pressure transmitters found capped off inside containment Caused by personnel error during maint Caps removed
SCHROCK,C A Wisconsin Public Service Corp 83/05/06 Region 3, Office of Director 40pp 18465 021 24X
Fiche 50-305,83/05/06,8305170267

8305170323 Forwards description of equipment failure of seismic monitoring sys,detected on 830408 Transverse motion sensor on one of three triaxial accelerometers failed Sensor provides no alarm or control function Sys will be upgraded
GIESLER,C W Wisconsin Public Service Corp 83/05/06 KEPPLER,J G
Region 3, Office of Director 2pp 18469 189 24X
Fiche 50-305,83/05/06,8305170323

8305270198 LER 83-012 03L-0 on 830427 containment vent activity monitor (R-21) discovered out of svc caused by inadequacy in administrative & procedural controls Refueling operations suspended per Tech Specs R-21 returned to svc W/830520 ltr
BERNHOFT,B L , THORGERSEN,J G , GIESLER,C W Wisconsin Public Service Corp 83/05/20 KEPPLER,J G Region 3 Office of Director
3pp 18677 167 24X Fiche 50-305,83/05/20,8305270198

DOCKET 50-306 PRAIRIE ISLAND NUCLEAR GENERATING UNIT 2

F Security medical, emergency & fire protection plans

8305030214 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18310 155 24X Fiche 50-282,83/04/22,
8305030214

--8305030221 Forwards public version of revised emergency plan implementing procedures,including Procedures F3-2 re classification of emergencies,F3-5 re emergency notification & F3-9 re emergency evacuation
WARD,E C Northern States Power Co 83/04/08 Region 3, Office of Director 1p 18310 156 24X Fiche 50-282,83/04/22,
8305030214

--8305030226 Public version of revised emergency plan implementing procedures,including Procedure F3-2 re classification of emergencies F3-5 re emergency notification & F3-9 re emergency evacuation
SCHULLKE,D A Northern States Power Co 83/03/22 129pp
18310 157 24X Fiche 50-282,83/04/22,8305030214

8305170657 Forwards exemption from 10CFR50,App R,Subsection III G 2 re separation,fire barrier & suppression requirements where both trains of redundant safe shutdown components located within same fire area,per 820630 & 1021 requests
CLARK,R A Operating Reactors Branch 3 83/05/04 MUSOLF,D M
Northern States Power Co 4pp 18481 072 24X
Fiche 50-282,83/05/04,8305170657

--8305170666 Exemption from 10CFR50,App R Subsection III G 2 re separation,fire barrier & suppression requirements where both trains of redundant safe shutdown components located within same fire area
EISENHUT,D G Division of Licensing 83/05/04 Northern States Power Co 7pp 18481 076 24X Fiche 50-282,83/05/04,8305170657

--8305170683 Safety evaluation re exemptions from 10CFR50,App R,Section III G 2 requirement for maint of one train of equipment necessary for safe shutdown,w/o fire damage Exemptions should be denied in four areas & granted in five areas
* Office of Nuclear Reactor Regulation, Director 82/10/27
21pp 18481 083 24X Fiche 50-282,83/05/04,8305170657

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305190343 Forwards Rev 1 to NUREG-0728, 'NRC Incident Response Plan, in response to 830429 ltr requesting updated ltr of agreement W/o encl
HIND,J A Division of Radiological & Materials Safety Programs
83/05/13 LARSON,C E Northern States Power Co 2pp 18500 225
24X Fiche 50-000,83/05/13,8305190343

8305200023 Notifies that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK,R A Operating Reactors Branch 3 83/05/13 MUSOLF,D M
Northern States Power Co 3pp (8540 11) 24X
Fiche 50-282,83/05/13,8305200023

8305230523 Forwards clarifying info in support of 830311 exemption requests for 10CFR50 48,App R re Fire Areas 58,59,73 & 74
MUSOLF,D Northern States Power Co 83/05/16 Office of Nuclear Reactor Regulation, Director 62pp 18536 329 24X
Fiche 50-282,83/05/16,8305230523

8305240389 Advises that date for next annual emergency preparedness exercise revised to 840313,per 830128 telcon
PAPERIELLO,C J Region 3, Office of Director 83/05/19
LARSON,C E Northern States Power Co 1p 18575 069 24X
Fiche 50-282,83/05/19,8305240389

P Operating license stage documents & correspondence

8303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1,539 MWE (summer) net
HADLEY,C D Northern States Power Co 83/03/15 TOURTELLOTTE,J Regulatory Reform Task Force 6pp 18541 041 24X
Fiche 50-000,83/03/15,8303180429

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305020320 Forwards Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements," per 780201 submittal
MUSOLF,D Northern States Power Co 83/04/19 Office of Nuclear Reactor Regulation, Director 2pp 18277 146 24X
Fiche 50-282,83/04/19,8305020320

--8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
* Northern States Power Co 83/04/19 21pp 18277 148 24X
Fiche 50-282,83/04/19,8305020320

8305060013 Advises that action required by 830202 Amends 61 & 55 to Licenses DPR-42 & DPR-60,respectively & Generic Ltr 83-07 completed,based on util actively negotiating w/DOE re disposal of high level waste or spent nuclear fuel
CLARK,R A Operating Reactors Branch 3 83/04/21 MUSOLF,D M
Northern States Power Co 2pp 18354 311 24X
Fiche 50-282,83/04/21,8305060013

8305060108 Advises that requirements of NUREG-0737,TMI Action Plan Items II F 1 4,II F 1 5 & II F 1 6 met & items resolved Criteria requiring equipment to be environmentally qualified will be reviewed under environ qualification program
CLARK,R A Operating Reactors Branch 3 83/04/21 MUSOLF,D M
Northern States Power Co 9pp 18354 268 24X
Fiche 50-282,83/04/21,8305060108

8305060023 Forwards safety evaluation & technical evaluation rept for environ qualification of safety-related electrical equipment Justification for continued operation & schedule for proposed corrective action requested by 830520
CLARK,R A Operating Reactors Branch 3 83/04/25 MUSOLF,D M
Northern States Power Co 3pp 18354 322 24X
Fiche 50-282,83/04/25,8305060023

--8305060036 Safety evaluation re environ qualification of safety-related electric equipment Major qualification deficiencies identified in Franklin Research Ctr technical evaluation rept Tables 4-1,4-2,4-3 & 4-4 must be resolved
* Office of Nuclear Reactor Regulation, Director 83/04/25 7pp 18354 325 24X Fiche 50-282,83/04/25,8305060023

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305120389 Forwards response to NRC 830425 ltr transmitting safety evaluation for environ qualification of safety-related electrical equipment Rosemount 1153 Series A transmitters should be reclassified as Category II C equipment items
MUSOLF,D Northern States Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 29pp 18433 124 24X
Fiche 50-282,83/05/05,8305120389

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Devatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305020320 Forwards Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements," per 780201 submittal
MUSOLF,D Northern States Power Co 83/04/19 Office of Nuclear Reactor Regulation, Director 2pp 18277 146 24X
Fiche 50-282,83/04/19,8305020320

--8305020329 Rev 8 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements "
* Northern States Power Co 83/04/19 21pp 18277 148 24X
Fiche 50-282,83/04/19,8305020320

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305240029 Forwards IE Insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No noncompliance noted
SHAFER,W D Region 3, Office of Director 83/05/06 LARSON,C E
Northern States Power Co 2pp 18549 095 24X
Fiche 50-282,83/05/06,8305240029

--8305240061 IE Insp Repts 50-282/83-06 & 50-306/83-05 on 830216-0331 No noncompliance noted Major areas inspected plant operational safety,maint,surveillance,review of operating events,LERs, fire penetration seals & IE bulletins
FEIERABEND,C D , WILLIAMS,D L , JACKIW,I N Region 3, Office of Director 83/05/05 18pp 18549 097 24X Fiche 50-282,83/05/06, 8305240029

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305160056 Forwards monthly operating repts for Apr 1983
MUSOLF,D Northern States Power Co 83/05/11 Office of Resource Management, Director 1p 18451 036 24X Fiche 50-282,83/05/11, 8305160056

--8305160076 Monthly operating repts for Apr 1983
DUGSTAD,D Northern States Power Co 83/05/04 8pp 18451 037 24X Fiche 50-282,83/05/11,8305160056

S Reportable occurrences, LERs & related correspondence

8305240153 LER 83-009/03L-0 on 830416,spike occurred in RCS activity up to 3 26 uCi/gm dose equivalent I-131 Caused by washout of fission products from fuel pin defects following reactor shutdown & RCS cooldown & depressurization W/830516 ltr
HUNSTAD,A A , MUSOLF,D Northern States Power Co 83/05/16 Region 3, Office of Director 7pp 18549 009 24X
Fiche 50-306,83/05/16,8305240153

DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT

F Security, medical, emergency & fire protection plans

8305120421 Ack receipt of FEMA 830421 ltr & "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise " Emergency preparedness does not provide reasonable assurance that protective measures will be taken
ALLAN,J M Region 1, Office of Director 83/05/04 RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18433 153 24X
Fiche 50-309,83/05/04,8305120421

--8305120426 Forwards "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant," conducted on 821211
MCLOUGHLIN,D Federal Emergency Management Agency 83/04/21 DIRCKS,W J Office of the Executive Director for Operations 1p 18433 155 24X Fiche 50-309,83/05/04,8305120421

--8305120427 "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant "
* Federal Emergency Management Agency 83/03/31 83pp 18433 156 24X Fiche 50-309,83/05/04,8305120421

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305200341 Forwards description of change to tamper indication & revised security plan pages Encls withheld (ref 10CFR73 21)
GARRITY,J H Maine Yankee Atomic Power Co 83/05/17 Office of Nuclear Reactor Regulation, Director 2pp 18516 230 24X
Fiche 50-309,83/05/17,8305200341

8305230127 Forwards emergency operating procedures generation package, per NUREG-0737,Suppl I (Generic Ltr 82-33) "Requirements for Emergency Response Capability "
GARRITY,J H Maine Yankee Atomic Power Co 83/05/17 CLARK,R A Operating Reactors Branch 3 3pp 18531 263 24X
Fiche 50-309,83/05/17,8305230127

--8305230137 Rev 5 to Procedure EOP 2-70-1, "Safety Injection "
* Maine Yankee Atomic Power Co 83/05/17 5pp 18531 294 24X
Fiche 50-309,83/05/17,8305230127

--8305230140 Rev 12 to Procedure EOP 2-70-2, "LOCA"
* Maine Yankee Atomic Power Co 83/05/17 9pp 18531 299 24X
Fiche 50-309,83/05/17,8305230127

--8305230142 Rev 4 to Procedure EOP 2-70-3, "Steam Generator Tube Rupture "
* Maine Yankee Atomic Power Co 83/05/17 7pp 18531 308 24X
Fiche 50-309,83/05/17,8305230127

--8305230146 Rev 14 to Procedure EOP 2-70-4, "Steam Line Break "
* Maine Yankee Atomic Power Co 83/05 17 6pp 18531 315 24X
Fiche 50-309,83/05/17,8305230127

--8305230151 Rev 7 to Procedure 2 70-5, "Emergency Boration "
* Maine Yankee Atomic Power Co 83/05/17 9pp 18531 321 24X
Fiche 50-309,83/05/17,8305230127

--8305230154 Rev 11 to Procedure EOP 2-70-6, "Loss of Feedwater "
* Maine Yankee Atomic Power Co 83/05/17 5pp 18531 330 24X
Fiche 50-309,83/05/17,8305230127

--8305230157 Rev 5 to Procedure EOP 2-70-7, "Total Loss of Forced Reactor Coolant Flow/Natural Circulation "
* Maine Yankee Atomic Power Co 83/05/17 4pp 18531 335 24X
Fiche 50-309,83/05/17,8305230127

--8305230162 Rev 8 to Procedure EOP 2-70-8, "Emergency Loop Shutdown "
* Maine Yankee Atomic Power Co 83/05/17 3pp 18531 339 24X
Fiche 50-309,83/05/17,8305230127

--8305230167 Rev 7 to Procedure EOP 2-70-9, "Loss of Offsite Power "
* Maine Yankee Atomic Power Co 83/05/17 14pp 18531 342 24X
Fiche 50-309,83/05/17,8305230127

--8305230175 Rev 8 to Procedure EOP 2-70-10, "Control Room Evaluation "
* Maine Yankee Atomic Power Co 83/05/17 5pp 18531 356 24X
Fiche 50-309,83/05/17,8305230127

--8305230181 "Maine Yankee Procedure Writing Guidelines "
* Maine Yankee Atomic Power Co 83/05/17 22pp 18531 361 24X
Fiche 50-309,83/05/17,8305230127

G Adjudicatory correspondence

8305030565 Forwards State of ME first set of interrogatories & requests for production of documents Certificate of Svc encl
STERN,P Maine, State of 83/04/29 Docketing & Services Branch 2pp 18306 001 24X Fiche 50-309,83/04/29,8305030565

--8305030567 First set of interrogatories & requests for production of documents Certificate of Svc encl
AHRENS,P , STERN,P Maine, State of 83/04/29 Office of the Executive Legal Director 85pp 18306 003 24X
Fiche 50-309,83/04/29,8305030565

8305040533 Response opposing Sensible Maine Power 830426 renewed 820827 motion for more complete & specific disclosure by applicant & for stay Motion is not motion to compel & is founded upon erroneous assumption Certificate of Svc encl
DIGNAN,T G , GAD,R K Maine Yankee Atomic Power Co DIGNAN,T G Ropes & Gray 83/04/29 Atomic Safety and Licensing Board Panel 6pp 18321 235 24X Fiche 50-309,83/04/29,8305040533

8305160099 Reply opposing applicant answer opposing Sensible Maine Power 830427 renewed motion for more complete & specific disclosure by applicant Applicant answer misleading Certificate of Svc encl
MILLER,D S Sensible Maine Power MILLER,D S Miller,D S 83/05/11 Atomic Safety and Licensing Board Panel 4pp 18452 019 24X Fiche 50-309,83/05/11,8305160099

8305200068 Informs that 830405 methodology submittal re radiation environ for equipment qualification inside containment acceptable,per NUREG-0588 Submittal also provides ref for radiation levels outside containment
CLARK,R A Operating Reactors Branch 3 83/05/13 GARRITY,J H Maine Yankee Atomic Power Co 2pp 18540 128 24X
Fiche 50-309,83/05/13,8305200068

8305190255 Motion to compel answers to interrogatories & production of documents & request for leave to file motion Hearing cannot be conducted on basis of assertions,suppositions, similarities or generalities Certificate of Svc encl
MILLER,D S Sensible Maine Power MILLER,D S Miller,D S 83/05/14 Atomic Safety and Licensing Board Panel 21pp 18501 262 24X Fiche 50-309,83/05/14,8305190255

8305170552 Response opposing Sensible Maine Power 830511 motion for complete & specific disclosure by,util & motion for stay of proceedings Extreme relief sought before motion to compel discovery filed W/Certificate of Svc
GODDARD,R J Hearing Branch 3 83/05/16 Atomic Safety and Licensing Board Panel 7pp 18468 033 24X Fiche 50-309,83/05/16, 8305170552

8305240493 First set of interrogatories & requests for production of documents Certificate of Svc encl
MILLER, D S Sensible Maine Power MILLER D S Miller, D S
83/05/17 Office of the Executive Legal Director 23pp
18575 229 24X Fiche 50-309, 83/05/17, 8305240493

8305240483 Motion for extension of discovery period until 830904 Util conduct of willful nondisclosure necessitates extension Certificate of Svc encl
MILLER, D S Sensible Maine Power 83/05/18 Atomic Safety and Licensing Board Panel 4pp 18572 313 24X Fiche 50-309, 83/05/18, 8305240483

8305240386 Forwards second set of interrogatories & requests for production of documents to NRC Certificate of Svc encl
AHRENS, P , STERN, P Maine, State of 83/05/19 Atomic Safety and Licensing Board Panel 36pp 18571 070 24X Fiche 50-309, 83/05/19, 8305240386

H General correspondence

8305310238 Responds to constituent 830419 ltrs re Commission action on util performance during 821211 emergency preparedness exercise
DIRCKS, W J Office of the Executive Director for Operations
83/05/20 COHEN, W S Senate 5pp 18662 246 24X
Fiche 50-309, 83/05/20, 8305310238

--8305310239 Requests response to encl constituent ltrs re util failure to pass FEMA emergency preparedness test
COHEN, W S Senate 83/04/19 KAMMERER, C C Office of Congressional Affairs 5pp 18662 250 24X Fiche 50-309, 83/05/20, 8305310238

I Financial information

8305200314 Forwards Securities & Exchange Commission Form 10-Q, Quarterly Financial Rept for Jan-Mar 1983
HOWE, R S Maine Yankee Atomic Power Co 83/05/13 NRC - No Detailed Affiliation Given 15pp 18517 023 24X
Fiche 50-309, 83/05/13, 8305200314

8305200578 Forwards 1981 & 82 annual financial info filed w/Securities & Exchange Commission, per 10CFR50 71 b
GARRITY, J H Maine Yankee Atomic Power Co 83/05/17 CLARK, R A Operating Reactors Branch 3 103pp 18514 143 24X
Fiche 50-309, 83/05/17, 8305200578

P Operating license stage documents & correspondence

8303240026 Discusses review of 820408, 0601, 1103 & 830216 submittals on YAEC-1296P, "DNBR Limit Methodology & Application to ME Yankee Plant " Critical heat flux correlation acceptable for application to facility reload w/14x14 fuel assemblies
CLARK, R A Operating Reactors Branch 3 83/03/09 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 17690 299 24X
Fiche 50-309, 83/03/09, 8303240026

--8303240029 Safety evaluation supporting application to reload w/14x14 fuel assemblies & min I 20 DNBR limit
* Office of Nuclear Reactor Regulation, Director 83/03/09 7pp 17690 301 24X Fiche 50-309, 83/03/09, 8303240026

--8301060137 "Review of YAEC-1296P - DNBR Limit Methodology & Application to Maine Yankee Plant "
HESSON, G M Battelle Memorial Institute, Pacific Northwest Laboratory FATE-82-114 82/12/31 NRC - No Detailed Affiliation Given 7pp 17690 308 24X Fiche 50-309, 83/03/09, 8303240026

8305020600 Forwards revised instrumentation & control concerns & positions on feedwater trip sys Meeting to discuss concerns within 45 days requested
CLARK, R A Operating Reactors Branch 3 83/04/20 GARRITY, J H
Maine Yankee Atomic Power Co 7pp 18284 215 24X
Fiche 50-309, 83/04/20, 8305020600

8305050220 Forwards "Maine Yankee Cycle 7 Startup Test Rept," per Tech Spec 5 9 1 2
GARRITY, J H Maine Yankee Atomic Power Co 83/04/25 ALLAN, J M
Region I, Office of Director 1p 18338 064 24X
Fiche 50-309, 83/04/25, 8305050220

--8305050225 "Maine Yankee Cycle 7 Startup Test Rept "
* Maine Yankee Atomic Power Co 83/04/25 11pp 18338.065 24X
Fiche 50-309, 83/04/25, 8305050220

8305060042 Forwards safety evaluation supporting continued operation w/Dresser safety valve ring settings which do not allow discharge full rated flow Summary of specific info also encl
CLARK, R A Operating Reactors Branch 3 83/04/25 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 18354 334 24X
Fiche 50-309, 83/04/25, 8305060042

--8305060049 Safety evaluation supporting continued operation by PWRs w/Dresser safety valves which do not allow discharge full rated flow
* Office of Nuclear Reactor Regulation, Director 83/04/18 10pp 18354 336 24X Fiche 50-309, 83/04/25, 8305060042

8305030491 Forwards response to 821210 Generic Ltr 82-28 re inadequate core cooling instrumentation sys, including reactor coolant inventory sys description, conformance summary to NUREG-0737, Item II F 2 & proposed implementation schedule
RANDAZZA, J B Maine Yankee Atomic Power Co 83/04/29
EISENHUT, D G Division of Licensing 34pp 18295 118 24X
Fiche 50-309, 83/04/29, 8305030491

--8305030496 Rev 10 to Emergency Operating Procedure EOP 2-70-0, "Emergency Shutdown From Power "
* Maine Yankee Atomic Power Co 83/04/29 28pp 18295 152 24X
Fiche 50-309, 83/04/29, 8305030491

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305160201 Responds to util 821007 proposed Tech Spec changes re purge & vent sys Proposed leak test interval unacceptable Six-month test interval for passive valves, w/testing after each use & 3-month interval for active valves recommended
CLARK, R A Operating Reactors Branch 3 83/05/02 GARRITY, J H
Maine Yankee Atomic Power Co 3pp 18471 339 24X
Fiche 50-309, 83/05/02, 8305160201

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305130078 Responds to request for addl info re TMI Item II E 4 2 6, "Containment Ventilation Sys 8-Inch Globe Valve " Analyses to demonstrate valve qualification continuing
GARRITY, J H Maine Yankee Atomic Power Co 83/05/09 CLARK, R A
Operating Reactors Branch 3 2pp 18436 329 24X
Fiche 50-309, 83/05/09, 8305130078

8305170612 Requests addl info re 830218 proposed Cycle 7 supplementary changes to Tech Specs allowing operation w/YAEC-1 critical heat flux correlation
CLARK, R A Operating Reactors Branch 3 83/05/09 GARRITY, J H
Maine Yankee Atomic Power Co 2pp 18497 020 24X
Fiche 50-309, 83/05/09, 8305170612

8305130054 Ack receipt of 821103 ltr re intention to complete Phase II of control of heavy loads issue (NUREG-0612) Final technical evaluation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested
GARRITY, J H Maine Yankee Atomic Power Co 83/05/10 CLARK, R A
Operating Reactors Branch 3 2pp 18437 031 24X
Fiche 50-309, 83/05/10, 8305130054

8305130128 Responds to 10CFR50 54(f) info request re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," (Generic Ltr 83-10A) Plant-specific study applies RELAP5YA code, per 820819 & 830114 ltrs
FRIZZLE, C D Maine Yankee Atomic Power Co 83/05/10 EISENHUT, D G Division of Licensing 4pp 18437 191 24X Fiche 50-309, 83/05/10, 8305130128

8305230381 Denies request for exemption from requirements of App J to perform Type C tests w/air or nitrogen as medium for certain containment valves Basis for conclusion contained in encl safety evaluation & technical evaluation rept
EISENHUT, D G Division of Licensing 83/05/11 GARRITY, J H Maine Yankee Atomic Power Co 3pp 18577 024 24X Fiche 50-309, 83/05/11, 8305230381

--8305230399 Safety evaluation re App J review concerning containment testing program Proposed revs to Tech Spec 4 4 unacceptable
* Division of Licensing 83/05/11 3pp 18577 027 24X
Fiche 50-309, 83/05/11, 8305230381

--8206300177 "Containment Leakage Rate Testing (A-04)," technical evaluation rept
DELGATZO,T J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-2B 82/06/28 HUANG,Y S NRC - No Detailed Affiliation Given 36pp 18577 030 24X
Fiche 50-309,83/05/11,8305230381

8305230571 Advises that addl info required to satisfy current requirements re operational QA program Telcon on 830510 addressed general subjs to be discussed Specific questions to be provided 1 wk prior to 830525 meeting in Augusta,ME
MARTIN,T T Division of Engineering & Technical Programs 83/05/11
RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18537 317 24X
Fiche 50-309,83/05/11,8305230571

8305190308 Submits justification for continued operation for listed items not addressed in previous environ qualification of electrical equipment submittals,including equipment qualification pending mod
GARRITY,J H Maine Yankee Atomic Power Co 83/05/12 CLARK,R A
Operating Reactors Branch 3 5pp 18501 074 24X
Fiche 50-309,83/05/12,8305190308

8305200469 Forwards "Reactor Containment Bldg Integrated Leak Rate Test,820929-1001," including Type A tests performed during Cycle 6/7 refueling outage & Type B & C tests performed since last Type A test
GARRITY,J H Maine Yankee Atomic Power Co 83/05/16 CLARK,R A
Operating Reactors Branch 3 1p 18516 120 24X
Fiche 50-309,83/05/16,8305200469

--8305200473 "Reactor Containment Bldg Integrated Leak Rate Test,820929-1001 "
QIGGEY,C A Maine Yankee Atomic Power Co 83/05/16 77pp 18516 121 24X Fiche 50-309,83/05/16,8305200469

8305230383 Forwards update to 801106 ltr re shielding design summary per TMI Item II B 2 Update contains details of results of shielding review No supplemental SER required from NRC as result of relocation & future mods
GARRITY,J H Maine Yankee Atomic Power Co 83/05/18 CLARK,R A
Operating Reactors Branch 3 8pp 18538 235 24X
Fiche 50-309,83/05/18,8305230383

8305240270 Proposes alternative to NRC 820903 request to upgrade auxiliary feedwater sys automatic initiation logic channel testing per TMI Item II E 1 2 Monthly test of bistables actuation setpoints recommended
GARRITY,J H Maine Yankee Atomic Power Co 83/05/18 CLARK,R A
Operating Reactors Branch 3 2pp 18548 210 24X
Fiche 50-309,83/05/18,8305240270

8305240266 Forwards updated list re current status of electrical equipment important to safety within scope of 10CFR50 49 Nonqualified equipment scheduled to be qualified or replaced by end of next refueling outage
GARRITY,J H Maine Yankee Atomic Power Co 83/05/20 CLARK,R A
Operating Reactors Branch 3 6pp 18548 298 24X
Fiche 50-309,83/05/20,8305240266

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435,155 24X Fiche 50-000,83/04/15,8303040021

8305030350 Forwards IE Insp Rept 50-309/83-05 on 830406-07 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 83/04/19
RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18297 102 24X
Fiche 50-309,83/04/19,8305030350

--8305030353 IE Insp Rept 50-309/83-05 on 830406-07 Noncompliance noted inadequate control of safety-related maint of HPSI subsys & failure to maintain two operable safety injection trains per Tech Specs
KELLY,E M Region 1, Office of Director GALLO,R Division of Project & Resident Programs 83/04/13 5pp 18297 104, 24X
Fiche 50-309,83/04/19,8305030350

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020386 Ack receipt of 830412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/82-17
MARTIN,T T Division of Engineering & Technical Programs 83/04/26
RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18276 244 24X
Fiche 50-309,83/04/26,8305020386

--8305020393 Responds to NRC 830225 ltr re violations noted in IE Insp Rept 50-309/82-17 Corrective actions personnel responsible for shipping radioactive matl reminded that all required insps must be documented Procedure 9 1 15 revised
GARRITY,J H Maine Yankee Atomic Power Co 83/04/12 ALLAN,J M
Region 1, Office of Director 4pp 18276 246 24X
Fiche 50-309,83/04/26,8305020386

8305110314 Forwards IE Insp Rept 50-309/83-04 conducted by State of SC on 821217 No noncompliance noted,however State of SC identified violation w/DOT regulations
MARTIN,T T Division of Engineering & Technical Programs 83/04/27
RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18393 186 24X
Fiche 50-309,83/04/27,8305110314

--8305110320 IE Insp Rept 50-309/83-04 conducted by State of SC on 821217 No noncompliance noted Major areas inspected review of shipping papers placarding & marking State of SC identified violation re DOT regulations
CLEMONS,P , SHANBAKY,M Region 1, Office of Director 83/04/17
4pp 18393 188 24X Fiche 50-309,83/04/27,8305110314

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250310 Forwards IE Insp Rept 50-309/83-02 on 830301-11 & notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/05/11
RANDAZZA,J B Maine Yankee Atomic Power Co 2pp 18592 105 24X
Fiche 50-309,83/05/11,8305250310

--8305250312 Notice of violation from insp on 830301-11
* Region 1, Office of Director 83/05/11 5pp 18592 107 24X
Fiche 50-309,83/05/11,8305250310

--8305250314 IE Insp Rept 50-309/83-02 on 830301-11 Noncompliance noted failure to complete all design activities before declaration of sys operability
EAPEN,P K , MEYER,G , NAPUDA,G Region 1, Office of Director 83/04/27 39pp 18592 112 24X Fiche 50-309,83/05/11,8305250310

8305190079 EN-83-034 on 830520,notice of violation & proposed imposition of civil penalty in amount of $40,000 to be issued Action based on violation re operating reactor w/one train of HPSI incapable of automatically starting
BARBER,G , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/05/17 1p 18502 069 24X Fiche 50-309,83/05/17, 8305190079

8305250429 Suppls response to 830324 ltr & completes response to IE Bulletin 83-04, "Failure of Undrvoltage Trip Function of Reactor Trip Breakers " Description of reactor trip breaker incidents not previously reported encl
GARRITY,J H Maine Yankee Atomic Power Co 83/05/18 ALLAN,J M Region 1, Office of Director 3pp 18585 271 24X Fiche 50-309,83/05/18,8305250429

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270434 Discusses IE insp on 830406-07 & forwards notice of violation & proposed imposition of civil penalty
ALLAN,J M Director's Office, Office of Inspection and Enforcement 83/05/20 RANDAZZA,J B Maine Yankee Atomic Power Co 4pp 18642 235 24X Fiche 50-309,83/05/20,8305270434

--8305270445 Notice of violation & proposed imposition of civil penalty in amount of $40,000 Noncompliance noted one of two HPSI subsys inoperable for 29 days & other HPSI subsys inoperable for 7 h during 29-day period
ALLAN,J M Region 1, Office of Director 83/05/20 3pp 18642 239 24X Fiche 50-309,83/05/20,8305270434

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

8305310067 Provides results of reevaluation of design adequacy of two masonry walls per IE Bulletin 80-11 identified in 821021 ltr Both walls located in spent fuel bldg,one adjacent to ventilation penthouse & other south of pool
GARRITY,J H Maine Yankee Atomic Power Co 83/05/26 CLARK,R A Operating Reactors Branch 3 4pp 18653 174 24X
Fiche 50-309,83/05/26,8305310067

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573

8305060538 Forwards LER 83-009/03L-0
GARRITY,J H Maine Yankee Atomic Power Co 83/04/25 ALLAN,J M Region 1, Office of Director 1p 18348 327 24X
Fiche 50-309,83/04/25,8305060538

--8305060549 LER 83-009/03L-0 on 830405,spare HPSI pump failed to start during monthly ECCS surveillance resulting in degraded mode condition per Tech Spec 3 6 B Caused by ground racked up in pump breaker cubicle on 830307
NELSON,R H Maine Yankee Atomic Power Co 83/04/25 Region 1, Office of Director 3pp 18348 328 24X Fiche 50-309,83/04/25, 8305060538

8305110344 LER 83-014/03L-0 on 830425,during steady-state full power operation,Section 207 of 115 kV incoming line became unavailable Caused by lightning during electric strom which struck & damaged one phase of line Line repaired
WOOD,E C Maine Yankee Atomic Power Co 83/04/26 Region 1, Office of Director 2pp 18406 184 24X Fiche 50-309,83/04/26, 8305110344

8305060494 Forwards updated LER 83-012/01T-1
GARRITY,J H Maine Yankee Atomic Power Co 83/04/28 ALLAN,J M Region 1, Office of Director 1p 18348 101 24X
Fiche 50-309,83/04/28,8305060494

--8305060503 Updated LER 83-012/01T-1 on 830406,drain valves opened to replace seal water supply filter FL-34B Valves opened again 5 days later to replace head gasket Caused by insufficient identification of valves in plant drawings
WHITNEY,M A Maine Yankee Atomic Power Co 83/04/28 Region 1, Office of Director 3pp 18348 102 24X Fiche 50-309,83/04/28, 8305060494

8305110425 Forwards LER 83-010/03L-0
GARRITY,J H Maine Yankee Atomic Power Co 83/05/03 ALLAN,J M Region 1, Office of Director 1p 18405 092 24X
Fiche 50-309,83/05/03,8305110425

--8305110433 LER 83-010/03L-0 on 830407,nonqualified RCS loop 2 resistance temp detector (RTD) input to subcooling margin monitor failed,causing erroneous monitor readings Cause unknown RTD leads disconnected & replaced
MORRISON,G M Maine Yankee Atomic Power Co 83/05/03 Region 1, Office of Director 2pp 18405 093 24X Fiche 50-309, 83/05/03,8305110425

8305160065 Forwards LER 83-011/03L-0
GARRITY,J H Maine Yankee Atomic Power Co 83/05/03 ALLAN,J M Region 1, Office of Director 1p 18451 001 24X
Fiche 50-309,83/05/03,8305160065

--8305160082 LER 83-011/03L-0 on 830404,reactor protection sys symmetric offset channel B found w/value less negative than other three channels Caused by failed Bell & Howell multiplier, divider module Spare module installed & channel calibr
TAYLOR,J M Maine Yankee Atomic Power Co 83/05/03 Region 1, Office of Director 2pp 18451 002 24X Fiche 50-309,83/05/03, 8305160065

8305200467 RO on 830408 & 15,fluctuations observed in real time computer-calculated containment weight of air & containment weight of air monitoring sys Probably caused by recirculation fan failure
GARRITY,J H Maine Yankee Atomic Power Co 83/05/03 ALLAN,J M Region 1, Office of Director 2pp 18516 118 24X
Fiche 50-309,83/05/03,8305200467

8305200529 Forwards evaluation summary rept & resolution of LER-82-037/03L-0 dtd 821115 re shock suppressor bushing failures Lab analysis revealed Torrington ball bushings mfg from brittle AISI 5160 steel Brushing replaced
GARRITY,J H Maine Yankee Atomic Power Co 83/05/09 ALLAN,J M Region 1, Office of Director 3pp 18516 027 24X
Fiche 50-309,83/05/09,8305200529

8305230472 Forwards LER 83-013/03L-0
GARRITY,J H Maine Yankee Atomic Power Co 83/05/10 ALLAN,J M Region 1, Office of Director 1p 18537 142 24X
Fiche 50-309,83/05/10,8305230472

--8305230483 LER 83-013/03L-0 on 830411,diesel fire pump failed to develop sufficient discharge pressure during fire suppression water sys test Caused by level float switch & check valve failures Valve replaced & switch cleaned
LAFLAMME,S J Maine Yankee Atomic Power Co 83/05/10 Region 1, Office of Director 2pp 18537 143 24X Fiche 50-309, 83/05/10,8305230472

8305200360 Forwards LER 83-015/03L-0
GARRITY,J H Maine Yankee Atomic Power Co 83/05/12 ALLAN,J M Region 1, Office of Director 1p 18518 144 24X
Fiche 50-309,83/05/12,8305200360

--8305200374 LER 83-015/03L-0 on 830414,during maint on svc water pump P-29A,pump P-29C spuriously tripped Cause unknown Pump restarted & tested satisfactorily
MCGRATH,R Maine Yankee Atomic Power Co 83/05/12 Region 1, Office of Director 2pp 18518 145 24X Fiche 50-309,83/05/12, 8305200360

DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305130307 Releases public version of revised emergency plan
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18456 335 24X Fiche 50-272,83/05/02, 8305130307

--8305130308 Forwards public version of Rev 2 to emergency plan Receipt form encl
* Jersey Central Power & Light Co 83/04/04 VARGA,S A
Operating Reactors Branch 1 1p 18456 336 24X
Fiche 50-272,83/05/02,8305130307

--8305130309 Public version of Rev 2 to emergency plan
BURGE,C A , MIDURA,H J Jersey Central Power & Light Co
83/04/04 188pp 18456 337 24X Fiche 50-272,83/05/02,
8305130307

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305270043 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation re security access control denied
STAROSTECKI,R Division of Project & Resident Programs 83/05/23
UDERITZ,R A Public Service Electric & Gas Co of New Jersey 2pp
18638 345 24X Fiche 50-272,83/05/23,8305270043

--8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl
Encls withheld (ref 10CFR73 21)
UDERITZ,R A Public Service Electric & Gas Co of New Jersey
83/05/05 Region 1, Office of Director 3pp 18638 347 24X
Fiche 50-272,83/05/23,8305270043

Q Adjudicatory correspondence

8305170493 Order extending time until 830527 for Commission to act to review Director's Decision DD-83-6
CHILK,S J Office of the Secretary of the Commission 83/05/13
Commissioners 1p 18470 024 24X Fiche 50-272,83/05/13,
8305170493

8305310008 Order extending time until 830601 for Commission to act to review Director's Decision DD-83-6
CHILK,S J Office of the Secretary of the Commission 83/05/27
Commissioners 1p 18653 230 24X Fiche 50-272,83/05/27,
8305310008

I Financial information

8305200067 Forwards Annual Financial Repts for 1982
FRYLING,R Public Service Electric & Gas Co of New Jersey
83/05/17 Office of Nuclear Reactor Regulation, Director 1p
18516 198 24X Fiche 50-000,83/05/17,8305200067

J Insurance & indemnity information

8305160157 Forwards Endorsements 58 & 45 to NELIA Policy NF-230 & MAELU Policy MF-90,respectively
GOLDEN,M P Marsh & McLennan, Inc 83/05/02 SALTZMAN,J
Assistant Director for State & Licensee Relations 3pp 18445 089
24X Fiche 50-272,83/05/02,8305160157

P Operating license stage documents & correspondence

8305050013 Forwards response to Generic Ltr 82-28 re inadequate core cooling instrumentation sys (TMI Action Item II F 2) Westinghouse reactor vessel level instrumentation sys, described in 801231,810206 & 1207 submittals,utilized
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/04/22 VARGA,S A Operating Reactors Branch 1 27pp
18339 028 24X Fiche 50-272,83/04/22,8305050013

8305020186 Clarifies 830422 response to NRC 830420 ltr,item 2,II D 10CFR50 54(f),re Westinghouse treatment of undervoltage trip attachment delivered disassembled
UDERITZ,R A Public Service Electric & Gas Co of New Jersey
83/04/27 EISENHUT,D G Division of Licensing 2pp 18278 192
24X Fiche 50-272,83/04/27,8305020186

8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07,NUREG-0612, "Control of Heavy Loads," to confirm & clarify items discussed in 820804 telcon
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/04/27 VARGA,S A Operating Reactors Branch 1 8pp 18399 007
24X Fiche 50-272,83/04/27,8305110154

--8305110156 PSE-0108, "Maint Procedures "
* Public Service Electric & Gas Co of New Jersey 83/04/27
1,317pp 18399 101 24X Fiche 50-272,83/04/27,8305110154

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305090457 Application to amend Licenses DPR-70 & DPR-75,revising safety Tech Specs by raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1
LIDEN,E A Public Service Electric & Gas Co of New Jersey
83/05/04 VARGA,S A Operating Reactors Branch 1 2pp 18360 252
24X Fiche 50-272,83/05/04,8305090457

--8305090459 Proposed changes to safety Tech Specs,raising trip setpoint & allowable value of steam generator water level low-low reactor trip in Table 2 2-1
* Public Service Electric & Gas Co of New Jersey 83/05/04
4pp 18360 254 24X Fiche 50-272,83/05/04,8305090457

8305170015 Forwards Amend 19 to License DPR-75,safety evaluation & notice of issuance & availability Amend removes cycle dependent values of Fxy as function of core height & provides values by means of peaking factor limit rept
FISCHER,D Operating Reactors Branch 1 83/05/05 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 18494 155
24X Fiche 50-311,83/05/05,8305170015

--8305170019 Amend 19 to License DPR-75,removing cycle dependent values of Fxy as function of core height & provides values by means of peaking factor limit rept
VARGA,S A Operating Reactors Branch 1 83/05/05 9pp
18494 158 24X Fiche 50-311,83/05/05,8305170015

--8305170023 Safety evaluation supporting Amend 19 to License DPR-75
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18494 167 24X Fiche 50-311,83/05/05,8305170015

--8305170028 Notice of issuance & availability of Amend 19 to License DPR-75
VARGA,S A Operating Reactors Branch 1 83/05/05 2pp
18494 169 24X Fiche 50-311,83/05/05,8305170015

8305170079 Forwards Amends 53 & 21 to Licenses DPR-70 & DPR-75, respectively,safety evaluation & notice of issuance & availability Amends raise trip setpoint & allowable value of steam generator water level low-low reactor trip
FISCHER,D Operating Reactors Branch 1 83/05/05 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 18495 211
24X Fiche 50-272,83/05/05,8305170079

--8305170084 Amends 53 & 21 to License DPR-70 & DPR-75,respectively, raising trip setpoint & allowable value of steam generator water level low-low reactor trip
VARGA,S A Operating Reactors Branch 1 83/05/05 8pp
18495 214 24X Fiche 50-272,83/05/05,8305170079

--8305170088/ Safety evaluation supporting Amends 53 & 21 to Licenses DPR-70 & DPR-75,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18495 222 24X Fiche 50-272,83/05/05,8305170079

--8305170090 Notice of issuance & availability of Amends 53 & 21 to Licenses DPR-70 & DPR-75,respectively
VARGA,S A Operating Reactors Branch 1 83/05/05 2pp
18495 224 24X Fiche 50-272,83/05/05,8305170079

8305170117 Forwards Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively,safety evaluation & notice of issuance & availability Amends change partial power multiplier from 0 2 to 0 3
FISCHER,D Operating Reactors Branch 1 83/05/05 UDERITZ,R A
Public Service Electric & Gas Co of New Jersey 3pp 18496 001
24X Fiche 50-272,83/05/05,8305170117

--8305170119 Amends 52 & 20 to Licenses DPR-70 & DPR-75,respectively, changing partial power multiplier from 0 2 to 0 3
VARGA,S A Operating Reactors Branch 1 83/05/05 13pp
18496 004 24X Fiche 50-272,83/05/05,8305170117

--8305170124 Safety evaluation supporting Amends 52 & 20 to Licenses DPR-70 & DPR-75,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18496 017 24X Fiche 50-272,83/05/05,8305170117

--8305170129 Notice of issuance & availability of Amends 52 & 20 to Licenses DPR-70 & DPR-75, respectively
VARGA, S A Operating Reactors Branch 1 83/05/05 2pp
18496 019 24X Fiche 50-272, 83/05/05, 8305170117

8305110007 Forwards addl fee required for 821007 amend application
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/05/06 MILLER, W D License Fee Management Branch 2pp
18409 258 24X Fiche 50-311, 83/05/06, 8305110007

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305170328 Forwards schedule for qualification or replacement of unqualified equipment for Categories I B, II A, II C & IV identified in SER on environ qualification of safety-related electrical equipment
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/05/09 VARGA, S A Operating Reactors Branch 1 16pp
18465 153 24X Fiche 50-272, 83/05/09, 8305170328

8305230504 Forwards affidavit & fee for review of 830504 application to amend Licenses DPR-70 & DPR-75
LIDEN, E A Public Service Electric & Gas Co of New Jersey
83/05/11 VARGA, S A Operating Reactors Branch 1 2pp 18537 170
24X Fiche 50-272, 83/05/11, 8305230504

8305230094 Advises of rev to Cycle 2 reload analysis & effect on reload safety evaluation & approved amends to Tech Specs Rev due to fuel grid strap damage during Feb refueling Revised design evaluated by Westinghouse per WCAP-9273
LIDEN, E A Public Service Electric & Gas Co of New Jersey.
83/05/16 VARGA, S A Operating Reactors Branch 1 3pp 18539 177
24X Fiche 50-311, 83/05/16, 8305230094

8305310221 Requests assessment on operability of 10-inch pressure/vacuum relief valves used for purge or vent of containments to demonstrate that valves will operate in event of DBA-LOCA Info requested within 15 days
VARGA, S A Operating Reactors Branch 1 83/05/19 UDERITZ, R A
Public Service Electric & Gas Co of New Jersey 7pp 18662 261
24X Fiche 50-272, 83/05/19, 8305310221

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020258 Ack receipt of 830407 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-272/83-09 & 50-311/83-08
MARTIN, T T Division of Engineering & Technical Programs 83/04/26
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 1p
18277 268 24X Fiche 50-272, 83/04/26, 8305020258

tion noted in IE Insp
ns
nsive
ents
New Jersey
Technical
4/26, 8305020258

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305190163 Forwards IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25 & notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/05/06
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
18502 240 24X Fiche 50-272, 83/05/06, 8305190163

--8305190174 IE Insp Repts 50-272/83-14 & 50-311/83-11 on 830321-25 Noncompliance noted failure to adhere to radiation protection procedures & failure to use suitable measurements of airborne radioactivity, per 10CFR20 103(a)(3)
NIMITZ, R L , SHANBAKY, M Region 1, Office of Director 83/05/06
13pp 18502 243 24X Fiche 50-272, 83/05/06, 8305190163

8305160085 Forwards response to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/82-33 & 50-311/82-31 on 820405-1016 Corrective actions operational test group established to verify testing requirements Civil penalty fee encl
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/05/09 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp 18451 027 24X Fiche 50-272, 83/05/09, 8305160085

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305240285 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10
MARTIN, T T Division of Engineering & Technical Programs 83/05/19
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
18548 107 24X Fiche 50-272, 83/05/19, 8305240285

--8305240291 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-272/83-11 & 50-311/83-10 Corrective actions all badges improperly issued destroyed Individual responsible no longer in security mgt position
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/04/25 Region 1, Office of Director 1p 18548 109 24X
Fiche 50-272, 83/05/19, 8305240285

8305270043 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Request to further mitigate violation re security access control denied
STAROSTECKI, R Division of Project & Resident Programs 83/05/23.
UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp
18638 343 24X Fiche 50-272, 83/05/23, 8305270043

--8305270053 Responds to NRC 830405 ltr re violations noted in IE Insp Repts 50-272/83-08 & 50-311/83-07 Corrective actions & request for reduction in severity level of violation encl Encls withheld (ref 10CFR73 21)
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/05/05 Region 1, Office of Director 3pp 18438 347 24X
Fiche 50-272, 83/05/23, 8305270043

8305270164 Ack receipt of 830509 ltr forwarding payment of proposed civil penalty Response to notice of violation & proposed imposition of civil penalty will be evaluated & corrective actions examined during future insp
AXELRAD, J A Enforcement Staff 83/05/25 UDERITZ, R A Public Service Electric & Gas Co of New Jersey 2pp 18638 064 24X
Fiche 50-272, 83/05/25, 8305270164

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305170142 Forwards monthly operating rept for Apr 1983
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/05/10 Director's Office, Office of Inspection and Enforcement 1p 18466 272 24X Fiche 50-311, 83/05/10, 8305170142

--8305170147 Monthly operating rept for Apr 1983
MILLER, L K Public Service Electric & Gas Co of New Jersey
83/05/10 11pp 18466 273 24X Fiche 50-311, 83/05/10, 8305170142

S Reportable occurrences, LERs & related correspondence

8304180491 Forwards LER 83-002/03L-0 Detailed event analysis encl
MIDURA, H J Public Service Electric & Gas Co of New Jersey
83/04/06 HAYNES, R C Region 1, Office of Director 3pp
17996 353 24X Fiche 50-311, 83/04/06, 8304180491

--8304180513 LER 83-002/03L-0 on 830314, discovered pressurizer code safety valves 2PR3, 2PR4 & 2PR5, tested by Wyle Labs during 830224-25, lifted below 2,485 psig plus/minus 1% pressure range & displayed heavy audible & visual seat leakage
DICKEY, F Public Service Electric & Gas Co of New Jersey
83/04/06 Region 1, Office of Director 1p 17996 356 24X
Fiche 50-311, 83/04/06, 8304180491

8305110271 Forwards supplemental LER 83-083/03X-1 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/04/26 ALLAN, J Region 1, Office of Director 3pp 18393 151
24X Fiche 50-311, 83/04/26, 8305110271

--8305110274 Supplemental LER 82-083/03X-1 on 820812, during routine surveillance, control room operator received low svc water flow indication on containment fan coil unit (CFCU) 25 Caused by oysters or silt restricting CFCU flow
FRAHM, R , ZUPKO, J M Public Service Electric & Gas Co of New Jersey 83/04/20 Region 1, Office of Director 1p
18393 154 24X Fiche 50-311, 83/04/26, 8305110271

8305040630 Notifies of CRGR Meeting 36 on 830429 to discuss findings of Salem Generic Implications Task Force
STELLO, V Committee to Review Generic Requirements 83/04/27
EISENHUT, D G Office of Nuclear Reactor Regulation, Director
JORDAN, F L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 18336 306 24X Fiche 50-272, 83/04/27, 8305040630

8305040262 Forwards summary listing short- & long-term actions & completion schedules re 830222 & 25 reactor trip breaker events Corrective action program will also be applied to Unit 2 currently scheduled to return to svc in June 1983
UDERITZ, R A Public Service Electric & Gas Co of New Jersey
83/04/28 EISENHUT, D G Division of Licensing 11pp 18323 249
24X Fiche 50-272, 83/04/28, 8305040262

8305160096 Forwards LER 83-012/03L-0 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/04/28 ALLAN, J Region 1, Office of Director 3pp 18452 015
24X Fiche 50-311, 83/04/28, 8305160096

--8305160102 LER 83-012/03L-0, on 830406, 10-ton Cardox sys pilot valve found in closed position & all low pressure sys declared inoperable Caused by inadequacies in sys recharging operation on 830304 Procedures revised
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/04/27 Region 1, Office of Director 1p 18452 018 24X
Fiche 50-311, 83/04/28, 8305160096

8305060480 Forwards LER 83-011/03L-0 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/04/29 ALLAN, J Region 1, Office of Director 3pp 18348 131
24X Fiche 50-311, 83/04/29, 8305060480

--8305060489 LER 83-011/03L-0 on 830401, discovered that monthly testing of control room emergency air conditioning sys was overlooked Caused by insp order sys card requiring testing being erroneously stated Card revised
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/04/27 Region 1, Office of Director 1p 18348 134 24X
Fiche 50-311, 83/04/29, 8305060480

8305090244 Responds to 830329 memo re mgt & technical issues of ATWS events Issues to be addressed in NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant " RHR capability addressed in Unresolved Safety Issue A-45
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/29 EPLER, E P Epler, E P 8pp 18381 084 24X
Fiche 50-272, 83/04/29, 8305090244

--8305090255 Requests comments re need for effective leadership in light of ATWS event, failure of RHR sys & small break mitigation & failure of institutions to employ best available technology
EPLER, E P Epler, E P 83/03/29 PALLADINO, N J Commissioners
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards
CULLER, F L Electric Power Research Institute 10pp 18381 091
24X Fiche 50-272, 83/04/29, 8305090244

8305170064 Responds to 830412 petition & 0418 amend, requesting that NRC order PSE&G to show cause why facility restart should not be restrained Petition denied based on encl Director's Decision
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/29 RODRIGUEZ, J H New Jersey, State of 3pp 18494 184
24X Fiche 50-272, 83/04/29, 8305170064

--8305170085 Director's Decision DD 83-6, denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart until listed actions taken
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/29 8pp 18494 187 24X Fiche 50-272, 83/04/29, 8305170064

--8305170095 Safety evaluation re restart of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue
* Office of Nuclear Reactor Regulation, Director 83/04/28
45pp 18494 195 24X Fiche 50-272, 83/04/29, 8305170064

--8305170110 Notice of issuance of Director's Decision DD 83-6 denying Public Advocate of NJ 830412 petition & 0418 amend requesting issuance of order to show cause why facility should not be restrained from restart
CASE, E G Office of Nuclear Reactor Regulation, Director
83/04/29 2pp 18494 336 24X Fiche 50-272, 83/04/29, 8305170064

8305170674 GENERIC IMPLICATIONS OF ATWS EVENTS AT THE SALEM NUCLEAR POWER PLANT Generic Implications
* Office of Nuclear Reactor Regulation, Director NUREG-1000 VOl
83/04/30 149pp Available at NRC $6 50 18481 187 24X
Fiche 50-272, 83/04/30, 8305170674

8305170232 Informs Commission of findings of Salem ATWS generic implications task force re overall mgt capability & performance & reactor trip sys reliability
DIRCKS, W J Office of the Executive Director for Operations
SECY-83-158 83/05/02 159pp 18476 184 24X
Fiche 50-272, 83/05/02, 8305170232

8305100004 PNS-1-83-011 on 830504, security officer received bomb threat on inside plant telephone line from male caller Search initiated No bomb found Call considered hoax
MCKEOWN, GODY, JOYNER Region 1, Office of Director 83/05/04 1p
18377 251 24X Fiche 50-272, 83/05/04, 8305100004

8305160118 Forwards LER 83-015/03L-0 Detailed event analysis encl
ZUPKO, J M Public Service Electric & Gas Co of New Jersey
83/05/05 ALLAN, J Region 1, Office of Director 3pp 18450 126
24X Fiche 50-311, 83/05/05, 8305160118

--8305160123 LER 83-015/03L-0 on 830407, during routine shutdown for refueling, testing results of four mechanical snubbers revealed that devices did not meet Tech Spec requirements Cause not stated Snubbers returned to manufacturer
FRAHM, R Public Service Electric & Gas Co of New Jersey
83/05/04 Region 1, Office of Director 1p 18450 129 24X
Fiche 50-311, 83/05/05, 8305160118

8305120434 PNS-I-83-013 on 830502 Lower Alloways Creek,NJ,police dept informed licensee of planned,peaceful demonstration to protest facility restart scheduled for 830508 No press release planned
MCKEOWN,L , GODY,A T , JOYNER,J Region 1, Office of Director 83/05/06 1p 18431 131 24X Fiche 50-272,83/05/06,8305120434

8305160052 Forwards LER 83-013/03L-0 Detailed event analysis encl
ZUPKO,J M Public Service Electric & Gas Co of New Jersey 83/05/06 ALLAN,J Region 1, Office of Director 5pp 18453 023 24X Fiche 50-311,83/05/06,8305160052

--8305160057 LER 83-013/03L-0 on 830409,during routine shutdown,lube oil temp increases observed on charging pump 22 Caused by restricted svc water flow to pump due to oyster shells & miscellaneous mollusks Shells removed
FRAHM,R Public Service Electric & Gas Co of New Jersey 83/05/04 Region 1, Office of Director 1p 18453 028 24X Fiche 50-311,83/05/06,8305160052

8305170367 Forwards LER 83-006/04L-0 Detailed event analysis encl
ZUPKO,J M Public Service Electric & Gas Co of New Jersey 83/05/06 ALLAN,J Region 1, Office of Director 4pp 18466 082 24X Fiche 50-311,83/05/06,8305170367

--8305170370 LER 83-006/04L-0 on 830408,decreased sensitivity of Channel 2R41C plant vent noble gas monitor rendered waste gas discharge line automatic isolation feature inoperable Caused by leakage on monitor sample lines & internal connections
FRAHM,R Public Service Electric & Gas Co of New Jersey 83/05/04 Region 1, Office of Director 1p 18466 086 24X Fiche 50-311,83/05/06,8305170367

8305180830 Forwards 830506 order confirming commitment to implement &/or maintain items specified in 830428 ltr re reactor trip breaker failures
EISENHUT,D G Division of Licensing 83/05/06 UDERITZ,R A Public Service Electric & Gas Co of New Jersey 3pp 18506 001 24X Fiche 50-272,83/05/06,8305180830

--8305180836 Order confirming licensee commitments to implement &/or maintain items specified in 830428 ltr re reactor trip breaker failures,effective immediately
EISENHUT,D G Division of Licensing 83/05/06 Public Service Electric & Gas Co of New Jersey 4pp 18506 004 24X Fiche 50-272,83/05/06,8305180830

8305200537 Forwards LER 83-014/03L-0 Detailed event analysis encl
ZUPKO,J M Public Service Electric & Gas Co of New Jersey 83/05/11 ALLAN,J Region 1, Office of Director 3pp 18514 253 24X Fiche 50-311,83/05/11,8305200537

--8305200546 LER 83-014/03L-0 on 830413 & 18,operating loads on 2A 4-kV & 460-volt vital buses tripped Caused by spurious operation of safeguards equipment control sys RHR pump 21 restarted Contract written for further investigation
FRAHM,R Public Service Electric & Gas Co of New Jersey 83/05/11 Region 1, Office of Director 1p 18514 256 24X Fiche 50-311,83/05/11,8305200537

8305250501 LER 83-016/04L-0 on 830418 & 22,small amounts of low level liquid radwaste released to util-controlled area from waste monitoring tank 21 Caused by leakage from liquid waste sys components Valve 1LW13 flange tightened W/830518 ltr
FRAHM,R , ZUPKO,J M Public Service Electric & Gas Co of New Jersey 83/05/11 ALLAN,J Region 1, Office of Director 3pp 18588 291 24X Fiche 50-311,83/05/11,8305250501

T Hearing transcripts on non-antitrust matters

8305020529 Unofficial transcript of Commission 830426 public meeting re possible vote on restart in Washington,DC Pp 1-107
* Commissioners 83/04/26 127pp 18284 075 24X
Fiche 50-272,83/04/26,8305020529

8305170089 Transcript of Commission 830512 meeting in Washington,DC to discuss evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation encl
* Commissioners 83/05/12 81pp 18495 226 24X
Fiche 50-272,83/05/12,8305170089

8305230130 Transcript of Commission 830518 public meeting in Washington,DC re evaluation of implications of facility event (Part I) Pp 1-82 Supporting documentation encl
* Commissioners 83/05/18 97pp 18577 110 24X
Fiche 50-272,83/05/18,8305230130

DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION

F Security, medical, emergency & fire protection plans

8305160195 Addl response to FOIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress
FELTON,J M Division of Rules and Records 83/03/31 CLARK,R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312,83/03/31,8305160195

--8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility
GIBSON,J Standardization & Special Projects Branch 82/10/18 MINER,S Operating Reactors Branch 4 2pp 18462 194 24X Fiche 50-312,83/03/31,8305160195

--8305160222 Forwards SALP evaluation input,per Sternberg 821014 memo Info consists of safeguards licensing portion
MCCORKLE,Q W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG,L Region 5, Office of Director 3pp 18462 235 24X Fiche 50-312,83/03/31,8305160195

8305100099 Requests status of NRC review of Rev 4 to security training & qualifications plan Response dtd 821012 fully responsive to Region V requirements,per NRC 821103 request
HAMMOND,W J Sacramento Municipal Utility District 83/05/04 STOLZ,J F Operating Reactors Branch 4 1p 18377 254 24X Fiche 50-312,83/05/04,8305100099

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305240314 Forwards IE Safeguards Insp Rept 50-312/83-13 on 830503-05 No noncompliance noted Rept withheld (ref 10CFR73 21)
NORDERHAUG,L R Region 5, Office of Director 83/05/18 RODRIGUEZ,R J Sacramento Municipal Utility District 2pp 18548 193 24X Fiche 50-312,83/05/18,8305240314

Q Adjudicatory correspondence

8305130099 Forwards licensee 830428 ltr re emergency feedwater instrumentation & control (EFIC) sys & upgraded auxiliary feedwater sys,NUREG-0737,Items II E 1 2 & II K 2 10 Ltr provides new info on mod completion schedule W/svc list
BAXTER,T A Shaw, Pittman, Potts & Trowbridge BAXTER,T A Sacramento Municipal Utility District 83/05/11 ROSENTHAL,A S , BUCK,J H, KOHL,C N Atomic Safety and Licensing Appeal Panel 3pp 18437 223 24X Fiche 50-312,83/05/11,8305130099

P Operating license stage documents & correspondence

8305230583 Forwards backfit cost info in response to 830208 ltr Two 3,500 kW standby diesel generators,diesel generator bldg, auxiliary bldg addition,associated electrical equipment & new computer sys added per NUREG-0737
MATTIMOE,J J Sacramento,Municipal Utility District 83/03/16 TOURTELLOTTE,J Regulatory Reform Task Force 4pp 18541 318 24X Fiche,50-312,83/03/16,8305230583

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X Fiche 50-000,83/04/11,8305230720

8305060419 Application for proposed Amend 93 to License DPR-54,changing titles for positions within mgt structure
RODRIGUEZ,R J Sacramento Municipal Utility District 83/04/19 EISENHUT,D G Division of Licensing 1p 18343 273 24X Fiche 50-312,83/04/19,8305060419

--8305060421 Proposed Tech Specs for Amend 93 to License DPR-54,changing titles for positions within mgt structure
* Sacramento Municipal Utility District 83/04/19 5pp 18343 274 24X Fiche 50-312,83/04/19,8305060419

8305020592 Notifies that IAEA representatives plan to visit facility on 830505 & 06 to svc cameras & audit records
STOLZ,J F Operating Reactors Branch 4 83/04/21 RODRIGUEZ,R J. Sacramento Municipal Utility District 2pp 18284 227 24X Fiche 50-312,83/04/21,8305020592

8305020383 Confirms 830502 submittal date for proposed solution to three remaining open items on NRC review of upgraded auxiliary feedwater sys per NUREG-0737, Item II E 1 1 Contractor requested to provide cost estimate for study
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/27
STOLZ, J F Operating Reactors Branch 4 1p 18276 313 24X
Fiche 50-312, 83/04/27, 8305020383

8305020384 Forwards response to 821115 request for addl info re NUREG-0737, Items II E 1 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/11 oversize drawings Aperture cards are available in PDR
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28
STOLZ, J F Operating Reactors Branch 4 3pp 18283 329 24X
Fiche 50-312, 83/04/28, 8305020384

--8305020392 Rev 3 to "Auxiliary Feedwater Sys Sys Description "
* Babcock & Wilcox Co BWNP-20004 (6-76) R3 83/04/04 94pp
18283 332 24X Fiche 50-312, 83/04/28, 8305020384

8305020415 Forwards results of analysis of station electrical distribution sys voltages & comparison of test & analytical results Differences between test voltages & analytically derived voltages within 3% value
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28
STOLZ, J F Operating Reactors Branch 4 7pp 18273 117 24X
Fiche 50-312, 83/04/28, 8305020415

8305030577 Board Notification BN-83-21C forwards generic evaluation for B&W designed plants Designs maintain DHR by natural circulation through steam generators under transient & accident conditions
EISENHUT, D G Division of Licensing 83/04/28 Atomic Safety and Licensing Appeal Panel 2pp 18305 335 24X Fiche 50-312, 83/04/28, 8305030577

--8305030587 Forwards generic evaluation for all B&W designed plants to maintain DHR by natural circulation Design acceptable
MATTSON, R J Division of Systems Integration (post 811005)
THOMPSON, H L Division of Human Factors Safety 83/04/18
EISENHUT, D G Division of Licensing 15pp 18305 338 24X
Fiche 50-312, 83/04/28, 8305030577

8305110126 REVIEW OF THE RANCHO SECO NUCLEAR GENERATING STATION UNIT NO 1 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYSIS Docket No 50-312 (Sacramento Municipal Utility District)
ILDERG, D , YOUNGBLOOD, R , PAPAZOGLOU, I A Brookhaven National Laboratory FIN A-3393 NUREG/CR-3013 83/04/30 Division of Safety Technology 49pp Available at NRC $4 75 18416 266 24X
Fiche 50-312, 83/04/30, 8305110126

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060365 Notification of 830806 meeting w/B&W Owners Group in Bethesda, MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & justification for continued operation
MINER, G Operating Reactors Branch 4 83/05/02 STOLZ, J
Operating Reactors Branch 4 2pp 18353 092 24X
Fiche 50-000, 83/05/02, 8305060365

8305060415 Forwards resolution of open items re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys," per 830215 evaluation & 830314 telcon No significant radiation effects anticipated
LATHAM, W K Sacramento Municipal Utility District 83/05/02
STOLZ, J F Operating Reactors Branch 4 2pp 18343 279 24X
Fiche 50-312, 83/05/02, 8305060415

8305060429 Forwards response to 830405, 06 & 07 ltrs & 830419 telcon requesting addl info on spent fuel pool expansion
LATHAM, W K Sacramento Municipal Utility District 83/05/02
STOLZ, J F Operating Reactors Branch 4 16pp 18343 243 24X
Fiche 50-312, 83/05/02, 8305060429

8305060638 Requests remittance of fee for 830125 application re organizational changes within 15 days of receipt of ltr
DIGGS, R M License Fee Management Branch 83/05/02 RODRIGUEZ, R J Sacramento Municipal Utility District 1p 18359 200 24X
Fiche 50-312, 83/05/02, 8305060638

8305060645 Advises that Class III fee appropriate for each listed application filed w/NRR for review Request of 830331 for exemption from order, confirming commitment to implement NUREG-0737, not exempt from fees
MILLER, W O. License Fee Management Branch 83/05/02
RODRIGUEZ, R J Sacramento Municipal Utility District 2pp
18358, 362 24X Fiche 50-312, 83/05/02, 8305060645

8305090553 Requests remittance of fee due for review of 830217 amend application re implementation of NUREG-0737 items, providing justification for imposition of fees in response to 830401 ltr contesting fee
MILLER, W O License Fee Management Branch 83/05/02
RODRIGUEZ, R J Sacramento Municipal Utility District 1p
18367 360 24X Fiche 50-312, 83/05/02, 8305090553

8305100344 Submits info re NUREG-0737, Item II E 1 1, "Auxiliary Feedwater Sys Upgrade Review," per 830407 request Info resolves protection of sys from internal missiles & addl protection required for condensate storage tank
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/02
STOLZ, J F Operating Reactors Branch 4 2pp 18378 231 24X
Fiche 50-312, 83/05/02, 8305100344

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305100229 Forwards response to questions raised during 830422 telcon re util plans concerning NUREG-0737, Item II F 1, "Containment Instrumentation Upgrades " Dedicated recorder for hydrogen concentration will be provided
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/06
STOLZ, J F Operating Reactors Branch 4 3pp 18374 128 24X
Fiche 50-312, 83/05/06, 8305100229

8305100296 Advises that util reviewed all items in Categories I D, II A & IV of technical evaluation rept to verify that adequate justifications for continued operation of safety-related electrical equipment exist
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/06
STOLZ, J F Operating Reactors Branch 4 2pp 18371 247 24X
Fiche 50-312, 83/05/06, 8305100296

8305100338 Forwards responses to 830419 questions re 830106 submittal of proposed mod for reactor cavity annular seal plate storage Three primary fission product boundaries designed to withstand concurrent LOCA & seismic loads
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/06
STOLZ, J F Operating Reactors Branch 4 2pp 18378 327 24X
Fiche 50-312, 83/05/06, 8305100338

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18427 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305310171 Provides supplemental info re proposed Amend 86 to License DPR-54, per NRC 830419 verbal request Method of calculating losses in tendons & reduction off lejacking force of detensioned tendons discussed
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/11
MINOR, S NRC - No Detailed Affiliation Given 27pp 18652 299
24X Fiche 50-312, 83/05/11, 8305310171

Q Inspection reports, IE Bulletins & correspondence

8305160192 FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility
CLARK, R San Francisco Examiner 83/02/22 FELTON, J M Division of Rules and Records 1p 18462 190 24X Fiche 50-312, 83/02/22, 8305160192

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305160255 Partial response to FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility
FELTON, J M Division of Rules and Records 83/03/24 CLARK, R San Francisco Examiner 2pp 18472 241 24X Fiche 50-312, 83/03/24, 8305160255

--8211150068 Discusses performance evaluation of SALP for facility LERs contained adequate info enabling knowledgeable readers to understand events; however, LER 81-39 failed to adequately inform reader of event
SEYFRIT, K V Reactor Operations Analysis Branch 82/11/05
STERNBERG, D M Division of Resident/Reactor Project & Engineering Programs 1p 18473 005 24X Fiche 50-312, 83/03/24, 8305160255

--8305160271 Notification of 830105 meeting w/util in Sacramento, CA to discuss SALP for Jul 1981 - Sept 1982 Meeting agenda encl
* Region 5, Office of Director 82/12/02 Region 5, Office of Director 3pp 18473 018 24X Fiche 50-312, 83/03/24, 8305160255

8305160195 Addl response to FOIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress
FELTON, J M Division of Rules and Records 83/03/31 CLARK, R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312, 83/03/31, 8305160195

--8211030191 Provides results of reactor operator & senior reactor operator exams administered Jul 1981-Sept 1982, as input to SALP rept All operators passed exams
BECKHAM, D H Operator Licensing Branch 82/10/19 MINER, S Sacramento Municipal Utility District 15pp 18462 211 24X Fiche 50-312, 83/03/31, 8305160195

--8211180501 Forwards NRR input for util SALP, per 821014 memo
MINER, S Operating Reactors Branch 4 82/11/16 STERNBERG, D M Region 5, Office of Director 7pp 18462 226 24X Fiche 50-312, 83/03/31, 8305160195

--8305160200 Notifies that SALP board scheduled to meet 821123 Evaluation period remains Jul 1981 - Sept 1982
ENGELKEN, R H Region 5, Office of Director 82/10/04 DENTON, H R Office of Nuclear Reactor Regulation, Director DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director MICHELSON, C Director's Office 1p 18462 193 24X Fiche 50-312, 83/03/31, 8305160195

--8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility
GIBSON, J Standardization & Special Projects Branch 82/10/18 MINER, S Operating Reactors Branch 4 2pp 18462 194 24X Fiche 50-312, 83/03/31, 8305160195

--8305160213 Forwards draft NRR SALP input re licensing activities for Jul 1981 - Sept 1982 Comments received by 821115 will be considered in final rept
MINER, S Operating Reactors Branch 4 82/11/10 EISENHUT, D G Division of Licensing MATTSON, R Division of Systems Integration (post 811005) VOLLMER, R Division of Engineering 15pp 18462 196 24X Fiche 50-312, 83/03/31, 8305160195

--8305160218 Forwards SALP for Jul 1981 - Sept 1982 Overall performance of licensed activities acceptable Prof & responsive attitude in dealings w/NRC & in day-to-day conduct of safety-related activities noteworthy
STERNBERG, D M Region 5, Office of Director 82/12/15 ENGELKEN, R H Region 5, Office of Director 2pp 18462 233 24X Fiche 50-312, 83/03/31, 8305160195

--8305160222 Forwards SALP evaluation input, per Sternberg 821014 memo Info consists of safeguards licensing portion
MCCORKLE, G W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG, L Region 5, Office of Director 3pp 18462 235 24X Fiche 50-312, 83/03/31, 8305160195

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020483 Forwards calculations showing that wall enclosing nuclear svc station transformer can withstand 101 mph wind & associated wind generated missiles, per IE Bulletin 80-11 Shield structure will be installed by 830901
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28 STOLZ, J F Operating Reactors Branch 4 6pp 18282 337 24X Fiche 50-312, 83/04/28, 8305020483

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305100381 Informs that 3 months needed to assess impact upon pump operability & potential for auxiliary feedwater pump cavitation, in response to IE Bulletin 80-04 Next rept will be provided by 831104
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/06 STOLZ, J F Operating Reactors Branch 4 2pp 18378 214 24X Fiche 50-312, 83/05/06, 8305100381

8305230456 Forwards supplemental info to 830324 response to IE Bulletin 83-04 re control rod drive breaker failures Commitment to in-place funtional test of breakers prior to startup ack Summary of maint history encl
RODRIGUEZ, R J. Sacramento Municipal Utility District 83/05/09 MARTIN, J B Region 5, Office of Director 167pp 18538 011 24X Fiche 50-312, 83/05/09, 8305230456

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305240314 Forwards IE Safeguards Insp Rept 50-312/83-13 on 830503-05 No noncompliance noted Rept withheld (ref 10CFR73 21)
NORDERHAUG, L R Region 5, Office of Director 83/05/18 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 18548 193 24X Fiche 50-312, 83/05/18, 8305240314

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305270080 Requests extension to 831015 to provide schedule for accomplishing proposed actions to close outstanding issue re IE Bulletin 79-01B Items Exemptions from 10CFR50 49 & Rev 2 to Reg Guide 1 97
RODRIGUEZ, R J Sacramento Municipal Utility District 83/05/20 STOLZ, J F Operating Reactors Branch 4 2pp 18638 291 24X Fiche 50-312, 83/05/20, 8305270080

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc S Northeast Utilities Service Co 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305240326 Monthly operating rept for Apr 1983 W/830513 ltr
COLOMBO, R , DUBRE, R.P Sacramento Municipal Utility District 83/04/30 Director's Office, Office of Inspection and Enforcement 6pp 18549 279 24X Fiche 50-312, 83/04/30, 8305240326

S Reportable occurrences, LERs & related correspondence

8305160255 Partial response to FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility
FELTON, J M Division of Rules and Records 83/03/24 CLARK, R San Francisco Examiner 2pp 18472 241 24X Fiche 50-312, 83/03/24, 8305160255

--8211100028 Provides engineering evaluation of 810807 turbine/reactor trip Event review agrees w/licensee Event had little effect on plant safety Automatic functions occurred substantially as expected given concurrent operator actions
PELLET, J L Reactor Operations Analysis Branch 82/10/26
SEYFRIT, K V Reactor Operations Analysis Branch 4pp 18472 290 24X Fiche 50-312, 83/03/24, 8305160255

--8211110645 Discusses licensee reporting of 810807 turbine/reactor trip Proposed LER rule would require more detailed & complete event rept W/o encl
ORNSTEIN, H L Reactor Operations Analysis Branch 82/11/04
SEYFRIT, K V Reactor Operations Analysis Branch 3pp 18473 006 24X Fiche 50-312, 83/03/24, 8305160255

8305030287 Forwards LER 83-013/03L-0 Detailed event analysis submitted
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/12
MARTIN, J B Region 5, Office of Director 2pp 18300 058 24X Fiche 50-312, 83/04/12, 8305030287

--8305030290 LER 83-013/03L-0 on 830318, reactor bldg purge discharge fan A-536 carbon adsorber filter bank & auxiliary/spent fuel bldg filter sys A-524B found below Tech Spec for iodide removal Charcoal will be replaced by 830601
COLOMBO, R W Sacramento Municipal Utility District 83/04/12
Region 5, Office of Director 1p 18300 060 24X
Fiche 50-312, 83/04/12, 8305030287

8305030551 Forwards LER 83-014/01T-0 Detailed event analysis submitted
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/19
MARTIN, J B Region 5, Office of Director 2pp 18303 334 24X
Fiche 50-312, 83/04/19, 8305030551

--8305030561 LER 83-014/01T-0 on 830406, reactor bldg purge inlet & outlet valves failed local leak rate surveillance test Caused by damaged seats for valves SFV-53504 & SFV-53605 & seats for valves SFV-53604 & SFV-53504 needing adjustment
COLOMBO, R W Sacramento Municipal Utility District 83/04/19
Region 5, Office of Director 1p 18303 336 24X
Fiche 50-312, 83/04/19, 8305030551

8305130163 RO 83-016 on 830331, listed snubbers failed acceptance criteria, per Surveillance Test SP 201 10B Snubbers reworked Surveillance Insp 201 10A will be performed prior to coming out of cold shutdown
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28
MARTIN, J B Region 5, Office of Director 2pp 18437 337 24X
Fiche 50-312, 83/04/28, 8305130163

8305130219 Forwards LER 83-017/03L-0 Detailed event analysis submitted
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28
MARTIN, J B Region 5, Office of Director 2pp 18439 320 24X
Fiche 50-312, 83/04/28, 8305130219

--8305130231 LER 83-017/03L-0 on 830331, testing of reactor coolant pump power relays revealed five devices unacceptable Cause of failure unknown Relays sent to manufacturer for repair Addl info will be provided
COLOMBO, R W Sacramento Municipal Utility District 83/04/28
Region 5, Office of Director 1p 18439 322 24X
Fiche 50-312, 83/04/28, 8305130219

8305130105 RO 83-01 on 830408, following mgt safety review committee Fire Protection Audit 27, determined reactor coolant pump fire detectors not tested per Tech Spec requirements Caused by misapplication of Tech Spec provision
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/29
MARTIN, J B Region 5, Office of Director 2pp 18436 012, 24X
Fiche 50-312, 83/04/29, 8305130105

8305130160 RO 83-02 on 830326, motor driven fire pump P-440 administratively taken out of svc due to necessity to drain cooling tower circulating water basin during outage Recovery procedure established
LATHAM, W K Sacramento Municipal Utility District 83/05/02
MARTIN, J B Region 5, Office of Director 1p 18438 116 24X
Fiche 50-312, 83/05/02, 8305130160

8305260309 Interim deficiency rept re core support structure bolting Initially reported on 830419 Evaluation of corrective action in progress. Next rept will be sent by 831101
COOK, J W Consumers Power Co 83/05/19 KEPPLER, J G Region 3, Office of Director. 3pp 18625 200 24X Fiche 50-000, 83/05/19, 8305260309

--8305260311 Deficiency rept re ultrasonic test abnormal indications in upper barrel bolting of reactor internals Initially reported on 830328 Results of internal bolt insp discussed Addl info will be forwarded
TAYLOR, J H Babcock & Wilcox Co 83/04/11 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 5pp
18625 205 24X Fiche 50-000, 83/05/19, 8305260309

--8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
TAYLOR, J H Babcock & Wilcox Co 83/04/22 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 3pp
18625 210 24X Fiche 50-000, 83/05/19 8305260309

8305270115 PNS-V-83-007 on 830520, while performing security duties, upon approaching truck being offloaded, security officer observed individual throwing article into cab Investigation revealed cocaine in small glass container Police notified
SCHAEFER, D W, NORDERHAUG, L R Region 5, Office of Director
83/05/23 1p 18638 165 24X Fiche 50-312, 83/05/23, 8305270115

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

F Security, medical, emergency & fire protection plans

8305200326 Forwards list of emergency response open items for which no written response required Open items resulting from recent emergency exercise will be reflected in future rept
MARSHALL, J R Arkansas Power & Light Co 83/04/08 COLLINS, J T
Region 4, Office of Director 2pp 18516 308 24X
Fiche 50-313, 83/04/08, 8305200326

8304270424 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18244 027 24X Fiche 50-313, 83/04/22, 8304270424

--8304270426 Forwards public version of revised emergency plan implementing procedures, including Procedures 1, 2 & 6 re assignment of personnel to emergency response organization, notifications & emergency response ctrs, respectively
MARSHALL, J R Arkansas Power & Light Co 83/04/05 COLLINS, J T
Region 4, Office of Director 1p 18244 028 24X
Fiche 50-313, 83/04/22, 8304270424

--8304270427 Public version of revised emergency plan implementing procedures, including Procedures 1, 2 & 6 re assignment of personnel to emergency response organization, notifications & emergency response ctrs, respectively
* Arkansas Power & Light Co 83/03/07 86pp 18244 029 24X
Fiche 50-313, 83/04/22, 8304270424

8305060575 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18359 190 24X Fiche 50-313, 83/04/25, 8305060575

--8305060583 Forwards public version of revised Emergency Plan Implementing Procedures 1904 06 re radiological plume tracking & dose integration & 1904 06 re protective action recommendations
* Arkansas Power & Light Co 83/04/14 NRC - No Detailed Affiliation Given 1p 18359 191 24X Fiche 50-313, 83/04/25, 8305060575

--8305060591 Public version of revised Emergency Plan Implementing Procedures 1904 06 re radiological plume tracking & dose integration & 1904 07 re protective action recommendations
LEVINE, J M Arkansas Power & Light Co 83/04/14 8pp
18359 192 24X Fiche 50-313, 83/04/25, 8305060575

8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months
CLARK, R A Operating Reactors Branch 3 83/04/29 GRIFFIN, J
Arkansas Power & Light Co 4pp 18434 262 24X
Fiche 50-313, 83/04/29, 8305110193

--8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan
CLARK, R A Operating Reactors Branch 3 83/04/29 9pp
18434 266 24X Fiche 50-313, 83/04/29, 8305110193

--8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 83/04/29 2pp
18434 275 24X Fiche 50-313, 83/04/29, 8305110193

8305160288 Releases public version of revised nuclear contingency plan procedures
FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18462 334 24X Fiche 50-313, 83/05/02, 8305160288

--8305160290 Forwards public version of revised Nuclear Contingency Plan Procedures 1, 2, 3, 5, 6, 7, 8, 9, 12, 13, 14 & 15 W/o encl
MARSHALL, J R Arkansas Power & Light Co 83/04/05 COLLINS, J T Region 4, Office of Director 1p 18462 335 24X
Fiche 50-313, 83/05/02, 8305160288

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305170677 Forwards exemption from Section III L 1 of App R to 10CFR50 requirements to achieve cold shutdown within 72 h w/o use of offsite power
STOLZ, J F Operating Reactors Branch 4 83/05/11 GRIFFIN, J M
Arkansas Power & Light Co 3pp 18496 321 24X
Fiche 50-313, 83/05/11, 8305170677

--8305170685 Exemption from Section III L 1 to App R to 10CFR50 requirements to achieve cold shutdown within 72 h w/o use of offsite power
EISENHUT, D G Division of Licensing 83/05/11 Arkansas Power & Light Co 5pp 18496 324 24X Fiche 50-313, 83/05/11, 8305170677

8305180161 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," complete
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/05/11 GRIFFIN, J M Arkansas Power & Light Co 3pp 18502 346 24X Fiche 50-313, 83/05/11, 8305180161

H General correspondence

8305240139 Advises that correspondence distribution to Region IV will be modified to original plus three copies, per B Johnson request
MARSHALL, J R Arkansas Power & Light Co 83/04/22 SEIDLE, W C
Region 4, Office of Director 1p 18548 334 24X
Fiche 50-313, 83/04/22, 8305240139

J Insurance & indemnity information

8305090421 Forwards NELIA & MAELU Certificates of Insurance to comply w/10CFR50 54w Submittals from 830331 & 0422 misinterpreted to comply w/10CFR140 & 140 15a
MARSHALL, J R Arkansas Power & Light Co 83/05/03 STOLZ, J F
Operating Reactors Branch 4 COLLINS, J T Region 4, Office of Director DINITZ, I NRC - No Detailed Affiliation Given 6pp
18363 065 24X Fiche 50-313, 83/05/03, 8305090421

8305190363 Forwards NELIA & MAELU secondary financial protection Certificates of Insurance 48 & 68, respectively, for CY83, per 10CFR140 15(a)
MARSHALL, J R Arkansas Power & Light Co 83/05/11 DINITZ, I
Antitrust & Economic analysis Branch (Utility Finance) 41pp
18500 032 24X Fiche 50-313, 83/05/11, 8305190363

P Operating license stage documents & correspondence

8305230364 Forwards cost info associated w/backfitting nuclear units, per JL Maulden 830224 commitment
MARSHALL, J R Arkansas Power & Light Co 83/03/11 TOURTELLOTTE, J
Regulatory Reform Task Force 11pp 18546 234 24X
Fiche 50-313, 83/03/11, 8305230364

8303240480 Forwards "Structural Evaluation of AR Nuclear One-Unit 1 & Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
MARSHALL, J R Arkansas Power & Light Co 83/03/22 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 17678 109 24X Fiche 50-313, 83/03/22, 8303240480

--8303240497 "Structural Evaluation of AR Nuclear One-Unit 1 Spent Fuel Storage Facility for Consolidated Fuel Storage "
STURKEY, J J , BALLARD, T A Structural Dynamics Research Corp
APL-01-014 83/01/15 74pp 17678 110 24X
Fiche 50-313, 83/03/22, 8303240480

--8303240495 "Structural Evaluation of Arkansas Nuclear One-Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
STURKEY, J J , BALLARD, T A Structural Dynamics Research Corp
APL-02-013 82/11/24 79pp 17678 191 24X
Fiche 50-313, 83/03/22, 8303240480

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 2pp
18542 272 24X Fiche 50-000, 83/04/11, 8305230720

8305090147 Forwards Amend 77 to License DPR-51, safety evaluation & notice of issuance & availability Amend revises language for Tech Spec re inservice insp requirements for Class 1, 2 & 3 components
STOLZ, J F Operating Reactors Branch 4 83/04/18 GRIFFIN, J M
Arkansas Power & Light Co 4pp 18367 266 24X
Fiche 50-313, 83/04/18, 8305090147

--8305090154 Amend 77 to License DPR-31, revising language of Tech Specs re inservice insp requirements for Class 1, 2 & 3 components to conform w/codes & Std Rule 10CFR50 55a
STOLZ, J F Operating Reactors Branch 4 83/04/18 7pp
18367 270 24X Fiche 50-313, 83/04/18, 8305090147

--8305090160 Safety evaluation supporting Amend 77 to License DPR-51
* Office of Nuclear Reactor Regulation, Director 83/04/18
10pp 18367 277 24X Fiche 50-313, 83/04/18, 8305090147

--8209200375 "AR Nuclear One Unit 1 Inservice Insp Program," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-028-39
82/09/17 NRC - No Detailed Affiliation Given 16pp
18367 287 24X Fiche 50-313, 83/04/18, 8305090147

--8305090179 Notice of issuance & availability of Amend 77 to License DPR-51
STOLZ, J F Operating Reactors Branch 4 83/04/18 2pp
18367 304 24X Fiche 50-313, 83/04/18, 8305090147

8305200541 Forwards revised schedule for completion of licensing procedures upgrade, per regulatory response & commitment control program Delay due to continuing support requirements for Unit 1 outage Upgrade to be completed by 830527
MARSHALL, J R Arkansas Power & Light Co 83/04/25 COLLINS, J T
Region 4, Office of Director 2pp 18514 264 24X
Fiche 50-313, 83/04/25, 8305200541

8305110625 Forwards corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/04/27 GRIFFIN, J M Arkansas Power & Light Co 2pp 18417 357 24X Fiche 50-313, 83/04/27, 8305110625

--8305110626 Corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/27 2pp
18417 359 24X Fiche 50-313, 83/04/27, 8305110625

8305050125 Ack receipt of 830427 ltr w/corrections to safety evaluation for proposed spent fuel pool storage expansion Statement 15 corrected to indicate divers will not be permitted to exceed 1 rem whole body, per 830428 discussion w/G Vissing
MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 18341 347 24X Fiche 50-313, 83/04/28, 8305050125

8305050216 Advises that responses to Items 2 & 3 in NRC 830322 ltr re emergency feedwater sys will be submitted by 830530, per discussion w/G Vissing Response to Item 1 or schedule for response will also be provided
MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J R
Operating Reactors Branch 4 1p 18338 105 24X
Fiche 50-313, 83/04/28, 8305050216

8305090440 Forwards response to 830329 request for addl info re justifications for continued operation for Category I B, II A & IV items Previous response reviewed for necessary changes per Franklin Research Ctr evaluation
MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J F
Operating Reactors Branch 4 128pp 18363 122 24X
Fiche 50-313, 83/04/28, 8305090440

8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months
CLARK, R A Operating Reactors Branch 3 83/04/29 GRIFFIN, J
Arkansas Power & Light Co 4pp 18434 262 24X
Fiche 50-313, 83/04/29, 8305110193

--8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan
CLARK, R A Operating Reactors Branch 3 83/04/29 9pp
18434 266 24X Fiche 50-313, 83/04/29, 8305110193

--8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 83/04/29 2pp
18434 275 24X Fiche 50-313, 83/04/29, 8305110193

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda, MD to discuss core barrel failure at Rancho Seco & Crystal River 3, future plans for resolving problem & justification for continued operation
MINER, S Operating Reactors Branch 4 83/05/02 STOLZ, J
Operating Reactors Branch 4 2pp 18353 092 24X
Fiche 50-000, 83/05/02, 8305060365

8305120504 Forwards Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to require verification of leak testing of purge valves
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 83/05/03 GRIFFIN, J Arkansas Power & Light Co
3pp 18443 141 24X Fiche 50-313, 83/05/03, 8305120504

--8305120506 Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, revising Tech Specs to require verification of leak rate testing of purge valves
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/05/03 9pp 18443 144 24X
Fiche 50-313, 83/05/03, 8305120504

--8305120508 Safety evaluation supporting Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp
18443 153 24X Fiche 50-313, 83/05/03, 8305120504

--8305120512 Notice of issuance & availability of Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/03 2pp
18443 156 24X Fiche 50-313, 83/05/03, 8305120504

8305090333 Forwards responses to NRC 830406 request for addl info re use of RADCAL gamma thermometer (RGT) for inadequate core cooling instrumentation RGT consists of sheathed thermocouples, heater rod, core tube & jacket tube
MARSHALL, J R Arkansas Power & Light Co 83/05/04 EISENHUT, D G
Division of Licensing 8pp 18363 341 24X Fiche 50-313, 83/05/04, 8305090333

8305100351 Corrects statement in 830328 response to NRC questions re precautions taken to minimize personnel exposure to radiation during spent fuel storage expansion Self-reading dosimeters will be worn outside diving suits, not inside
MARSHALL, J R Arkansas Power & Light Co 83/05/04 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 18379 058 24X Fiche 50-313, 83/05/04, 8305100351

8305180694 Forwards SER resolving Multi-Plant Action Item B-04, "Reactor Vessel Overpressure Protection," as part of low temp overpressure mitigating sys review Review of electrical instrumentation & control aspects continuing
STOLZ, J F Operating Reactors Branch 4 83/05/05 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18505 192 24X
Fiche 50-313, 83/05/05, 8305180694

--8305180743 Safety evaluation resolving Multi-Plant Action Item B-04, "Reactor Vessel Overpressure Protection "
* Office of Nuclear Reactor Regulation, Director 83/05/05
10pp 18505 194 24X Fiche 50-313, 83/05/05, 8305180694

8305230019 Forwards Amend 80 to License DPR-51, safety evaluation & notice of issuance & availability Amends revise Tech Specs re surveillance requirements of post tensioned prestressed concrete containment tendons W/o encls
VISSING, G S Operating Reactors Branch 1 83/05/05 GRIFFIN, J M
Arkansas Power & Light Co 1p 18541 362 24X
Fiche 50-313, 83/05/05, 8305230019

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18677 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180847 Notifies of unacceptability of delay of proposed Tech Specs re snubber surveillance in order to include ANSI Std, ANSI/ASME OM1-1982, "Exam & Performance Testing of Nuclear Power Plant Dynamics Restraints (Snubbers) " Std not adopted
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/05/09 GRIFFIN, J M Arkansas Power & Light Co 2pp 18506 024 24X Fiche 50-313, 83/05/09, 8305180849

8305170622 Forwards list of current unresolved issues for radiological effluent Tech Specs remaining as result of 820622-24 meetings Final submittal requested within 30 days
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 83/05/10 GRIFFIN, J M Arkansas Power & Light Co 7pp 18497 001 24X Fiche 50-313, 83/05/10, 8305170622

8305230128 Forwards SER supporting licensee compliance w/NUREG-0737, Item II B 2 2, "Required Plant Mods," & design review of plant shielding requirements for access to vital areas
CLARK, R A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 83/05/11 GRIFFIN, J M Arkansas Power & Light Co 2pp 18546 349 24X Fiche 50-313, 83/05/11, 8305230128

--8305230145 Safety evaluation supporting licensee compliance w/NUREG-0737, Item II B 2, "Design Review of Plant Shielding Access to Vital Areas "
* Office of Nuclear Reactor Regulation, Director 83/05/11 2pp
18546 351 24X Fiche 50-313, 83/05/11, 8305230128

8305240399 Discusses 830315 commitment to provide results of B&W supplemental ECCS calculations addressing impact of cladding models presented in NUREG-0630, "Results of Bounding Analysis " Revised NUREG-0630 being prepared by B&W
MARSHALL, J R Arkansas Power & Light Co 83/05/18 STOLZ, J F
Operating Reactors Branch 4 2pp 18571 042 24X
Fiche 50-313, 83/05/18, 8305240399

8305270065 Forwards list of electrical equipment important to safety & schedule for qualification provisions or replacement of remaining equipment, per 10CFR50 49 Aging-related maint/surveillance requirements will be addressed by NRC deadline
MARSHALL, J R Arkansas Power & Light Co 83/05/20 STOLZ, J F
Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 27pp 18638 252 24X Fiche 50-313, 83/05/20, 8305270065

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8304150143 Forwards IE Insp Repts 50-313/83-07 & 50-368/83-03 on 830201-28 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/03/30 GRIFFIN, J M
Arkansas Power & Light Co 2pp 17983 226 24X
Fiche 50-313, 83/03/30, 8304150143

--8304150147 Notice of violation from insp on 830201-28
* Region 4, Office of Director 83/03/30 3pp 17983 228 24X
Fiche 50-313, 83/03/30, 8304150143

--8304150154 IE Insp Repts 50-313/83-03 & 50-368/83-03 on 830201-28 Noncompliance noted failure to adhere to requirements of refueling shuffle procedure, use of unapproved info sources & required verification signatures missing
CALLAN, L J , CUMMINS, J E , JOHNSON, N D Region 4, Office of Director 83/03/24 10pp 17983 231 24X Fiche 50-313, 83/03/30, 8304150143

8305100348 Forwards IE Insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/04/14 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18379 019 24X
Fiche 50-313, 83/04/14, 8305100348

--8305100353 Notice of violation from insp on 830314-18
* Region 4, Office of Director 83/04/14 2pp 18379 021 24X
Fiche 50-313,83/04/14,8305100348

--8305100361 IE Insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18
Noncompliance noted failure to conduct design change reviews
by offsite engineering group & failure to follow procedure
re forms used in closeout of design change packages
JAUDON,J P , MURPHY,M E , JOHNSON,W D Region 4, Office of
Director 83/04/12 10pp 18379 023 24X Fiche 50-313,83/04/14,
8305100348

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New
York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305090147 Forwards Amend 77 to License DPR-51,safety evaluation &
notice of issuance & availability Amend revises language for
Tech Spec re inservice insp requirements for Class 1,2 & 3
components
STOLZ,J F Operating Reactors Branch 4 83/04/18 GRIFFIN,J M
Arkansas Power & Light Co 4pp 18367 266 24X
Fiche 50-313,83/04/18,8305090147

--8305090154 Amend 77 to License DPR-31,revising language of Tech Specs
re inservice insp requirements for Class 1,2 & 3 components
to conform w/codes & Std Rule 10CFR50 55a
STOLZ,J F Operating Reactors Branch 4 83/04/18 7pp
18367 270 24X Fiche 50-313,83/04/18,8305090147

--8305090160 Safety evaluation supporting Amend 77 to License DPR-51
* Office of Nuclear Reactor Regulation, Director 83/04/18
10pp 18367 277 24X Fiche 50-313,83/04/18,8305090147

--8209200375 "AR Nuclear One Unit 1 Inservice Insp Program," technical
evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-186-028-39
82/09/17 NRC - No Detailed Affiliation Given 16pp
18367 287 24X Fiche 50-313,83/04/18,8305090147

--8305090179 Notice of issuance & availability of Amend 77 to License
DPR-51
STOLZ,J F Operating Reactors Branch 4 83/04/18 2pp
18367 304 24X Fiche 50-313,83/04/18,8305090147

8303040022 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New
York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere
Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New
York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305030325 Ack receipt of 830324 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-313/83-01 &
50-368/83-01
SEIDLE,W C Region 4, Office of Director 83/04/27 GRIFFIN,J M
Arkansas Power & Light Co 1p 18297 044 24X
Fiche 50-313,83/04/27,8305030325

--8305030331 Responds to NRC 830217 ltr re violations noted in IE Insp
Repts 50-313/83-01 & 50-368/83-01 Corrective actions revised
procedure incorporating three sample requirements into Step
7 2 4 & provided proper training for applicable personnel
MARSHALL,J R Arkansas Power & Light Co 83/03/24 SEIDLE,W C
Region 4, Office of Director 3pp 18297 045 24X
Fiche 50-313,83/04/27,8305030325

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of
Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High
Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305020436 Forwards IE Insp Rept 50-313/83-06 on 830301-31 & notice of
violation
KELLY,J A Region 4, Office of Director 83/04/28 Region 4,
Office of Director 1p 18284 031 24X Fiche 50-313,83/04/28,
8305020436

--8305020445 Forwards IE Insp Repts 50-313 83-06 & 50-368/83-06 on
830301-31 & notice of violation Notice of violation
withheld (ref 10CFR2 790)
SEIDLE,W C Region 4, Office of Director 83/04/18 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18284 032 24X
Fiche 50-313,83/04/28,8305020436

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve
Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events
Concerning Deliberate Acts Directed Against Plant
Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action
Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack
Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305120445 Ack receipt of 830406 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-313/82-36 &
50-368/82-37
SEIDLE,W C Region 4, Office of Director 83/05/06 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18431 072 24X
Fiche 50-313,83/05/06,8305120445

--8305120451 Responds to NRC 830309 ltr re violations noted in IE Insp
Repts 50-313/82-36 & 50-368/82-37 Corrective actions Form
1609 010A re calculation of max permissible concentration
revised to require health physics supervisor signature
MARSHALL,J R Arkansas Power & Light Co 83/04/06 SEIDLE,W C
Region 4, Office of Director 4pp 18431 074 24X
Fiche 50-313,83/05/06,8305120445

8305230337 Forwards IE Insp Repts 50-313/83-07 & 50-368/83-07 on
830418-22 No noncompliance noted
SEIDLE,W C Region 4, Office of Director 83/05/06 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18538 256 24X
Fiche 50-313,83/05/06,8305230337

--8305230348 IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No
noncompliance noted Major areas inspected test & experiment
& procurement programs & receipt,storage & handling of
equipment & matls program
JAUDON,J P , JOHNSON,W D Region 4, Office of Director 83/05/03
4pp 18538 258 24X Fiche 50-313,83/05/06,8305230337

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency
Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New
York, Inc 114pp 18524.003 24X Fiche 50-000,83/05/11,8303040034

8305170351 Discusses implications of indications on upper core barrel
bolts discovered during ultrasonic exams Replacement of
seven affected bolts not necessary Restart of facility may
proceed w/o undue risk to public
MARSHALL,J R Arkansas Power & Light Co 83/05/11 STOLZ,J F
Operating Reactors Branch 4 4pp 18467 023 24X
Fiche 50-313,83/05/11,8305170351

8305200313 Ack receipt of 830427 ltr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-313/83-02 &
50-368/83-02
SEIDLE,W C Region 4, Office of Director 83/05/13 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18517 056 24X
Fiche 50-313,83/05/13,8305200313

--8305200319 Responds to NRC 830325 ltr re violations noted in IE Insp
Repts 50-313/83-02 & 50-368/83-02 Corrective actions
administrative controls implemented to provide adequate
procedural controls re safety-related equipment
MARSHALL,J R Arkansas Power & Light Co 83/04/27 SEIDLE,W C
Region 4, Office of Director 4pp 18517 058 24X
Fiche 50-313,83/05/13,8305200313

8305230014 Supports restart of facility based on 830511 ltr re results of insp of 120 upper core barrel bolts & subsequent evaluation of upper core barrel bolt issue Responsibility for issue transferred to NRR
STOLZ, J F Operating Reactors Branch 4 83/05/13 CAVANAUGH, W
Arkansas Power & Light Co 1p 18542 231 24X
Fiche. 50-313, 83/05/13, 8305230014.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/19. Consolidated Edison Co of New York, Inc 114pp 18697 009. 24X Fiche 50-000, 83/05/19, 8303040040

8305240049 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-03 & 50-368/83-03 Addl info re order/sequence & temporary placement of fuel assemblies requested
BEIDLE, W C Region 4, Office of Director 83/05/19 GRIFFIN, J M
Arkansas Power & Light Co 2pp 18549 125 24X
Fiche 50-313, 83/05/19, 8305240049

--8305240054 Responds to NRC 830330 ltr re violations noted in IE Insp Repts 50-313/83-03 & 50-368/83-03 Corrective actions Procedure 1000.36, "Control of Miscellaneous Info Sources," reviewed w/personnel by dept heads to establish compliance.
MARSHALL, J.R. Arkansas Power & Light Co 83/05/02 BEIDLE, W.C.
Region 4, Office of Director. 6pp 18549 127 24X
Fiche 50-313, 83/05/19, 8305240049

8305310194 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-04 & 50-368/83-04.
BEIDLE, W.C. Region 4, Office of Director 83/05/25. GRIFFIN, J.M
Arkansas Power & Light Co 1p. 18658.152 24X
Fiche: 50-313, 83/05/25, 8305310194.

--8305310199 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-313/83-04 & 50-368/83-04. Corrective actions: Rev 5 to QA topical rept, reflecting design activity changes, will be submitted for approval by 830610
MARSHALL, J R Arkansas Power & Light Co. 83/05/12 BEIDLE, W.C.
Region 4, Office of Director. 3pp 18658.153 24X
Fiche 50-313, 83/05/25, 8305310194

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc. & Northeast Utilities Service Co 114pp 18647:007.
24X Fiche: 50-000, 83/05/26, 8303040046.

R. Periodic operating reports & related correspondence

8305040453 Forwards last intake impingemsnt data for Mar 1983 ETS 4.1.2 1(2) reporting requirement deleted, per Amends 72 & 40 contained in 830311 ltr.
MARSHALL, J.R Arkansas Power & Light Co. 83/04/29 STOLZ, J.F.
Operating Reactors Branch 4. 1p. 18322:131. 24X
Fiche: 50-313, 83/04/29, 8305040453.

--8305040459 Intake impingement data for Mar 1983.
* Arkansas Power & Light Co 83/04/21 11pp 18322:132. 24X
Fiche 50-313, 83/04/29, 8305040453

S. Reportable occurrences, LERs & related correspondence

8305200445 Forwards NPDES noncompliance rept, per Permit AR0001392
MARSHALL, J.R. Arkansas Power & Light Co. 83/04/04. COLLINS, J.T.
Region 4, Office of Director. 1p 18516:109. 24X
Fiche: 50-313, 83/04/04, 8305200445.

--8305200451 NPDES noncompliance rept: on 830323, discovered oil & grease concentrations from Outfall 003 exceeded Permit AR0001392 limits. Caused by startup activities on Unit 1. Rev of operating procedures being considered to prevent recurrence.
CAVANAUGH, W. Arkansas Power & Light Co. 83/03/30. WHITTINGTON, D.
Region 4, Office of Director 2pp. 18516:110. 24X
Fiche: 50-313, 83/04/04, 8305200445.

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping."
BROWN, E. J. Reactor Operations Analysis Branch. 83/04/19.
SEYFRIT, K. V Reactor Operations Analysis Branch. 1p. 18541:342
24X Fiche. 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept. Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping.
BROWN, E. J. Reactor Operations Analysis Branch. 83/04/19. 9pp.
18541:343. 24X Fiche 50-000, 83/04/19, 8305230573.

8305260260 NPDES noncompliance notification on 830413, routine analysis revealed average oil & grease concentration of 25 mg/l & pollutant load of 27 9 lb per day Caused by bearing failure on turbine Bearing repaired W/830426 ltr
GRIFFIN, J , MARSHALL, J R Arkansas Power & Light Co 83/04/20
COLLINS, J T Region 4, Office of Director WHITTINGTON, D.
Environmental Protection Agency 3pp 18629 074 24X
Fiche 50-313, 83/04/20, 8305260260

8305030385 Forwards LER 83-009/03L-0
MARSHALL, J R Arkansas Power & Light Co 83/04/25. BEIDLE, W.C.
Region 4, Office of Director 1p 18306 239 24X
Fiche 50-313, 83/04/25, 8305030385

--8305030390 LER 83-009/03L-0 on 830405, during hot shutdown after refueling outage, discovered that nonqualified diaphragm was used to repair pressure switch PS-7303 in standby hydrogen purge sys Qualified pressure switch obtained & installed
ROGERS, P Arkansas Power & Light Co 83/04/25 Region 4,
Office of Director 2pp 18306 260 24X Fiche 50-313, 83/04/25,
8305030385

8305060452 Forwards LER 83-005/03L-0
MARSHALL, J R Arkansas Power & Light Co. 83/04/25 BEIDLE, W C
Region 4, Office of Director. 1p 18348 068 24X
Fiche 50-313, 83/04/25, 8305060452

--8305060454 LER 83-005/03L-0 on 830328, motors for svc water pumps P-4B & P-4C observed to have upper oil reservoir piping altered Caused by installation of oil drain to facilitate draining oil from upper oil reservoir
ROGERS, P Arkansas Power & Light Co 83/04/25 Region 4,
Office of Director 1p 18348 069 24X Fiche. 50-313, 83/04/25,
8305060452

8305200490 NPDES noncompliance notification: on 830413, sample from Outfall 003, oily water separator, revealed average oil & grease concentration of 25 mg/l & pollutant load at 27 9 lbs per day. Caused by bearing failure on Unit 1 turbine
MARSHALL, J R Arkansas Power & Light Co 83/04/26 COLLINS, J.T
Region 4, Office of Director 3pp 18514 036 24X
Fiche: 50-313, 83/04/26, 8305200490

8305120414 Forwards LER 83-010/03L-0
MARSHALL, J R. Arkansas Power & Light Co 83/05/02 BEIDLE, W C.
Region 4, Office of Director 1p. 18434 095 24X
Fiche 50-313, 83/05/02, 8305120414

--8305120418 LER 83-010/03L-0 on 830405, outboard bearing temp for steam driven emergency feedwater pump P-74 exceeded limits Caused by improperly set balance drum clearance during maint Balance drum clearances reset.
ROGERS, P Arkansas Power & Light Co 83/05/02 Region 4,
Office of Director. 1p 18434:096 24X Fiche. 50-313, 83/05/02,
8305120414.

DOCKET 50-315 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305170270 Rev 4 to PMP 2080 EPP.008, "Initiating Manning of Emergency Response Facilities & Calling Off-Duty Plant Personnel "
* Indiana & Michigan Electric Co 83/04/19. 13pp 18463 167. 24X
Fiche 50-315, 83/04/19, 8305170270

--8305170274 Replacement pages, to PMP 2081. EPP. 027, "Unit Vent Emergency Release Rate Determination "
* Indiana & Michigan Electric Co 83/04/29. 7pp. 18463:180.
24X Fiche. 50-315, 83/04/19, 8305170270

8305040259 Releases public version of temporary change to rev to App B, hosp assistance plan
FELTON, J.M. Division of Rules and Records 83/04/25. Document
Management Branch 1p 18326 347 24X Fiche 50-315, 83/04/25,
8305040259.

--8305040265 Forwards public version of Temporary Change 1 to Rev 4 to App B, hosp assistance plan.
* Indiana & Michigan Electric Co. 83/04/13. GRIMES, B. NRC - No
Detailed Affiliation Given. 1p 18326 348. 24X
Fiche: 50-315, 83/04/25, 8305040259

--8305040268 Public version of Temporary Change 1 to Rev 4 to App B, hosp assistance plan
* Indiana & Michigan Electric Co. 83/04/13. 4pp. 18326:349
24X Fiche 50-315, 83/04/25, 8305040259.

8305120108 Forwards fee re review of alternate safe shutdown capability per 10CFR170 22 & 830331 application
ALEXICH, M P American Electric Power Service Corp 83/05/06
DENTON, H R Office of Nuclear Reactor Regulation, Director
DIGGS, R M NRC - No Detailed Affiliation Given 2pp 18423 043
24X Fiche 50-315, 83/05/06, 8305120108

8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation
SHAFER, W D Region 3, Office of Director 83/05/06 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 18548 126 24X Fiche 50-315, 83/05/06, 8305240302

--8305240309 IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 Noncompliance noted failure to complete Tech Spec surveillance & to establish fire watch in timely manner
SWANSON, E. R , DUBRY, N E , BOYD, D C Region 3, Office of Director 83/05/06 11pp 18548 130 24X Fiche 50-315, 83/05/06, 8305240302

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche: 50-000, 83/05/11, 8305110034

8305160745 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
* Operating Reactors Branch 1 83/05/13 DOLAN, J Indiana & Michigan Electric Co 2pp. 18506 045 24X Fiche: 50-315, 83/05/13, 8305160745

8305200438 Forwards FEMA evaluation of prompt notification sys proposed for Warren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be examined by NRC during next emergency preparedness insp
HIND, J A Division of Radiological & Materials Safety Programs 83/05/20 SOUTHWOOD, R J Michigan, State of. 1p 18513.001 24X
Fiche 50-315, 83/05/20, 8305200438

--8305200465 Responds to 821213 ltr re potential inadequacies of public notification sys at Warren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding population
ANDERSON, J T Federal Emergency Management Agency 83/04/01
KEPPLER, J G Region 3, Office of Director 3pp 18513 002 24X
Fiche 50-315, 83/05/20, 8305200438

J Insurance & indemnity information

8305160026 Forwards Endorsement 57 to NELIA Policy NF-206 & Endorsement 46 to MAELU Policy MF-79
BUCKLES, J Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18452 356 24X
Fiche 50-315, 83/04/28, 8305160026

P Operating license stage documents & correspondence

8305230368 Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs," providing cost analysis, per 830208 request
WHITE, W S American Electric Power Co , Inc 83/03/30
TOURTELLOTTE, J Regulatory Reform Task Force 7pp 18544 356 24X
Fiche 50-315, 83/03/30, 8305230368

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542-272 24X
Fiche: 50-000, 83/04/11, 8305230720

8305040354 Forwards Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs for oxygen content in waste decay tanks & correct 830207 Amends 69 & 51
WIGGINTON, D L Operating Reactors Branch 1 83/04/25. DOLAN, J
Indiana & Michigan Electric Co 2pp 18326 310 24X
Fiche: 50-315, 83/04/25, 8305040354

--8305040363 Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs for oxygen content in waste decay tanks & correcting 830207 Amends 69 & 51
VARGA, S A Operating Reactors Branch 1 83/04/25 16pp.
18326 312 24X Fiche 50-315, 83/04/25, 8305040354

--8305040374 Safety evaluation supporting Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively.
* Office of Nuclear Reactor Regulation, Director 83/04/25 3pp
18326.328 24X Fiche 50-315, 83/04/25, 8305040354

--8305040382 Notice of issuance & availability of Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively.
VARGA, S A Operating Reactors Branch 1 83/04/25. 2pp.
18326 331 24X Fiche 50-315, 83/04/25, 8305040354

8305030257 Responds to 821209 ltr requesting comments on Science Applications, Inc draft final rept, "Value-Impact Analysis of Recommendation re Steam Generator Tube Degradations & Rupture Events" (Generic Ltr 82-32)
HERING, R F American Electric Power Service Corp 83/04/26.
DENTON, H R Office of Nuclear Reactor Regulation, Director. 7pp.
18300 039 24X Fiche 50-315, 83/04/26, 8305030257

8305040649 Requests review of responses to SER for environ qualification equipment items for which justification for continued operation not previously submitted.
VARGA, S A Operating Reactors Branch 1 83/04/27. DOLAN, J
Indiana & Michigan Electric Co 3pp 18336: 272 24X
Fiche. 50-315, 83/04/27, 8305040649

8305030519 Advises that separate iodine particulate sampling sys installed & temporary mods performed on vent monitoring sys, per NRC 830314 order re NUREG-0737, Item II. F. 1, Attachment 2. Unit 1 sys operational. Unit 2 sys will be completed shortly
ALEXICH, M P American Electric Power Service Corp 83/04/29
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
18295·326 24X Fiche 50-315, 83/04/29, 8305030519

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs. Svc list encl.
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc 50pp. 18441 120 24X
Fiche· 50-000, 83/05/02, 8305020455.

8305170711 Requests ref for assumptions & methodology used in estimating post-accident radiation environs to complete environ equipment qualification review. Discussion of source terms & containment type should be included
VARGA, S A Operating Reactors Branch 1 83/05/02. DOLAN, J.
Indiana & Michigan Electric Co 2pp 18496.256 24X
Fiche 50-315, 83/05/02, 8305170711

8305090359 Requests submittal of Class I & III fees for 811111 & 830225 applications for amend to Licenses DPR-58 & DPR-74 re Tech Spec changes to reflect revised surveillance requirements for safety-related snubbers
DIGGS, R M License Fee Management Branch. 83/05/04 DOLAN, J.
Indiana & Michigan Electric Co 1p. 18367.219 24X
Fiche. 50-315, 83/05/04, 8305090359

8305170076 Forwards Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability. Amends permits storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment to 4% U-235.
WIGGINTON, D L Operating Reactors Branch 1 83/05/04. DOLAN, J.
Indiana & Michigan Electric Co 2pp 18495·166 24X
Fiche. 50-315, 83/05/04, 8305170076

--8305170080 Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, permitting storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment up to 4% U-235
VARGA, S A Operating Reactors Branch 1 83/05/04 9pp.
18495 169. 24X Fiche· 50-315, 83/05/04, 8305170076

--8305170109 Safety evaluation supporting Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04. 5pp.
18495 178. 24X Fiche· 50-315, 83/05/04, 8305170076

--8305170112 Notice of issuance & availability of Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively
VARGA, S A Operating Reactors Branch 1 83/05/04. 2pp.
18495 183 24X Fiche: 50-315, 83/05/04, 8305170076.

8305180536 Advises that action required by Amends 67 & 49 to Licenses DPR-58 & DPR-74, respectively & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
VARGA, S A Operating Reactors Branch 1 83/05/04. DOLAN, J.
Indiana & Michigan Electric Co 2pp 18505 076. 24X
Fiche: 50-315, 83/05/04, 8305180536

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods. Svc list encl
EISENHUT, D G. Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627·153 24X
Fiche: 50-000, 83/05/09, 8305090659

8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl
HERING, R F Indiana & Michigan Electric Co 83/05/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 18448 105
24X Fiche 50-315, 83/05/10, 8305160121

--8305160126 Proposed Tech Spec Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI
* Indiana & Michigan Electric Co 83/05/10 32pp 18448 109
24X Fiche 50-315, 83/05/10, 8305160121

8305180838 Advises that info provided in 821115 & 1214 ltrs re TMI Items II F 1 1 & II F 1 2 on particulate monitors resolved concerns Info acceptable
VARGA, S A Operating Reactors Branch 1 83/05/10 DOLAN, J
Indiana & Michigan Electric Co 2pp 18506 013 24X
Fiche 50-315, 83/05/10, 8305180838

8305160104 Application for amend to License DPR-58, proposing Tech Spec changes to allow Cycle 8 operation w/Westinghouse 15x15 optimized fuel assemblies Approval requested by 830701 Class III fee transmitted by util 830207 ltr
HUNTER, R S Indiana & Michigan Electric Co 83/05/11 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18451 080
24X Fiche 50-315, 83/05/11, 8305160104

--8305160108 Proposed Tech Spec changes to allow Cycle 8 operation w/ Westinghouse 15x15 optimized fuel assemblies Supporting documentation encl
* Indiana & Michigan Electric Co 83/05/11 285pp 18451 083
24X Fiche 50-315, 83/05/11, 8305160104

8305260281 Responds to NRC final rule 10CFR50 49 re electric equipment environ qualification Right to amend response reserved until meeting w/NRC scheduled to resolve environ qualification deficiencies
HERING, R F Indiana & Michigan Electric Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 16pp 18625 320
24X Fiche 50-315, 83/05/20, 8305260281

8305310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Teledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits
HUNTER, R S Indiana & Michigan Electric Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18658 065
24X Fiche 50-315, 83/05/27, 8305310088

G Inspection reports, IE Bulletins & correspondence

8305200294 Forwards order imposing civil monetary penalties transmitted to licensee on 821014, for transmittal to Ofc of FR for publication W/o encl.
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/10/15 Docketing & Services Branch 1p
18516 271 24X Fiche 50-315, 82/10/15, 8305200294

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305020347 Forwards IE Insp Repts 50-315/83-01 & 50-316/83-01 on 830117-21 & 0217. No noncompliance noted
NORELIUS, C E. Division of Project & Resident Programs 83/04/15
DOLAN, J E. American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 2pp 18274 094 24X
Fiche. 50-315, 83/04/15, 8305020347

--8305020348 IE Insp Repts 50-315/83-01 & 50-316/83-01 on 830117-21 & 0217 No noncompliance noted Major areas inspected QA/QC organization & program work controls, design controls & control of contractor activities
DUBRY, N , HELLER, J , HOLZMER, M Region 3, Office of Director
83/04/14 11pp. 18274 096 24X Fiche. 50-315, 83/04/15, 8305020347

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, 'Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 113pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 292 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation
SHAFER, W D Region 3, Office of Director 83/05/06 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 18548 126 24X Fiche 50-315, 83/05/06, 8305240302

--8305240306 Notice of violation from insp on 830215-0331
SHAFER, W D Region 3, Office of Director 83/05/06 2pp
18548 128 24X Fiche 50-315, 83/05/06, 8305240302

--8305240309 IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 Noncompliance noted failure to complete Tech Spec surveillance & to establish fire watch in timely manner
SWANSON, E R , DUBRY, N E , BOYD, D C Region 3, Office of Director
83/05/06 11pp 18548 130 24X Fiche 50-315, 83/05/06, 8305240302

8305170485 Confirms arrangements for 830622 meeting in Glen Ellyn, IL to discuss SALP for facilities
NORELIUS, C E Division of Project & Resident Programs 83/05/09
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 1p 18470 068 24X
Fiche 50-315, 83/05/09, 8305170485

8305170503 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-315/82-21 & 50-316/82-21 Info closes out open items re comparison limits of Sr-90 sample taken during 821115-19 insp
PAPERIELLO, C J Region 3, Office of Director 83/05/09 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 18470 011 24X Fiche 50-315, 83/05/09, 8305170503

8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl
HERING, R F Indiana & Michigan Electric Co 83/05/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 18448 105
24X Fiche 50-315, 83/05/10, 8305160121

--8305160126 Proposed Tech Spec Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI
* Indiana & Michigan Electric Co 83/05/10 32pp 18448 109
24X Fiche 50-315, 83/05/10, 8305160121

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305240078 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02
SHAFER, N D Region 3, Office of Director 83/05/17 DOLAN, J E American Electric Power Service Corp. DOLAN, J E Indiana & Michigan Electric Co 1p 18548 328 24X Fiche 50-315, 83/05/17, 8305240078

--8305240086 Responds to NRC 830329 ltr re violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02 Corrective actions: ltr reemphasizing need to insure testing w/approved procedures sent to all chemical section personnel
HUNTER, R S Indiana & Michigan Electric Co 83/04/28
KEPPLER, J G Region 3, Office of Director 2pp 18548 329 24X Fiche 50-315, 83/05/17, 8305240078

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305090363 Advises of submittal of "Annual Environ Operating Rept 1982" under separate cover
HERING, R F Indiana & Michigan Electric Co. 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18363 360. 24X Fiche 50-315, 83/05/03, 8305090363

8305160054 Forwards "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept, 1982 "
HERING, R F Indiana & Michigan Electric Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18453 300. 24X Fiche 50-315, 83/05/03, 8305160054

--8305160062 "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept, 1982 "
* Indiana & Michigan Electric Co * American Electric Power Co , Inc 83/05/03 535pp 18453 301 24X Fiche 50-315, 83/05/03, 8305160054

S Reportable occurrences, LERs & related correspondence

8303280126 Forwards updated LER 82-101/01X-1
SMITH, W G Indiana & Michigan Electric Co 83/03/17 KEPPLER, J G Region 3, Office of Director 1p. 17706 352 24X Fiche: 50-315, 83/03/17, 8303280126

--8303280136 Updated LER 82-101/01X-1 on 821123, during surveillance test, motor operated valve WMO-753 to west turbine driven auxiliary feed pump would not open Caused by valve & exhaust fan for turbine driven auxiliary feed pump room malfunction
PALMER, R A Indiana & Michigan Electric Co 83/03/17 Region 3, Office of Director 2p 17706 353 24X Fiche 50-315, 83/03/17, 8303280126

8305130097 Forwards LER 83-024/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/04/15 KEPPLER, J G Region 3, Office of Director 1p 18437 284 24X Fiche 50-315, 83/04/15, 8305130097

--8305130101 LER 83-024/03L-0 on 830317, during normal operation, Fire Door 517 from contractor access control to auxiliary bldg would not close properly Caused by extended dead bolt lock preventing doors from closing Dead bolt removed
JACQUES, P H Indiana & Michigan Electric Co 83/04/15 Region 3, Office of Director. 1p 18437 285 24X Fiche 50-315, 83/04/15, 8305130097

8305020141 Forwards LER 83-025/01T-0
SMITH, W G Indiana & Michigan Electric Co 83/04/19 KEPPLER, J G. Region 3, Office of Director 1p. 18284 064 24X Fiche. 50-315, 83/04/19, 8305020141.

--8305020151 LER 83-025/01T-0 on 830405, cable vault halon sys failed to meet design concentrations & declared inoperable Cause unknown Review of test data & sys review continuing
JACQUES, P Indiana & Michigan Electric Co 83/04/19 Region 3, Office of Director 1p 18284 065 24X Fiche: 50-315, 83/04/19, 8305020141

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V. Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19. 9pp 18541 343 24X Fiche: 50-000, 83/04/19, 8305230573.

8305020440 RO on 830420, waste gas holdup sys exceeded oxygen & hydrogen limits Cause not stated Proposed Tech Spec changes increasing oxygen concentration limit will be reviewed by 830422 Followup rept will be submitted within 14 days.
SMITH, W G Indiana & Michigan Electric Co 83/04/20. KEPPLER, J. G Region 3, Office of Director 1p 18283 091 24X Fiche 50-315, 83/04/20, 8305020440

8305020299 Forwards LER 83-027/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/04/22 KEPPLER, J G. Region 3, Office of Director 1p 18277 112 24X Fiche 50-315, 83/04/22, 8305020299

--8305020312 LER 83-027/03L-0 on 830111, AB diesel engine removed from svc to repair minor fuel oil leak on front bank injector pump 5 Gasket replaced on pressure screw Engine returned to svc on 830112
ROBINSON, D Indiana & Michigan Electric Co 83/04/22. Region 3, Office of Director. 2pp 18277 113 24X Fiche: 50-315, 83/04/22, 8305020299

8305020317 Forwards LER 83-026/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/04/22. KEPPLER, J. G. Region 3, Office of Director 1p 18277 173 24X Fiche 50-315, 83/04/22, 8305020317

--8305020321 LER 83-026/03L-0 on 830324, during QA audit on PMI-2270, hole found in fire barrier penetration seal F-6107 Cause unknown. Seal repaired
ROBINSON, D Indiana & Michigan Electric Co 83/04/22. Region 3, Office of Director 1p 18277 174 24X Fiche: 50-315, 83/04/22, 8305020317

8305060400 Forwards LERs 83-028/03L-0, 83-029/03L-0 & 83-030/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/04/29 KEPPLER, J G Region 3, Office of Director 1p 18343 286. 24X Fiche 50-315, 83/04/29, 8305060400

--8305060406 LER 83-028/03L-0 on 830331, after completion of surveillance test on solid state protection sys train A & review by maint supervisor, sys declared inoperable to troubleshoot possible problem w/safety injection reset time delay
PALMER, R A Indiana & Michigan Electric Co. 83/04/29. Region 3, Office of Director. 2pp 18343 287. 24X Fiche 50-315, 83/04/29, 8305060400

--8305060411 LER 83-029/03L-0 on 830405, control room access Fire Door 412 would not operate properly Caused by extension rod being pulled loose from door frame shoe Shoe set screws replaced & extensibn rod reinstalled
ROBINSON, D. Indiana & Michigan Electric Co 83/04/29 Region 3, Office of Director. 1p 18343.289 24X Fiche: 50-315, 83/04/29, 8305060400

--8305060414 LER 83-030/03L-0 on 830402, while on tour, security guard discovered Diesel Room AB cardox sys isolated w/no one in room Caused by personnel error Operator instructed on proper procedures for exiting carbon dioxide protected areas.
KRAUSE, D F. Indiana & Michigan Electric Co 83/04/29 Region 3, Office of Director. 1p. 18343.290 24X Fiche: 50-315, 83/04/29, 8305060400

8305120396 Forwards LER 83-031/03L-0.
SMITH, W. G Indiana & Michigan Electric Co 83/05/04. KEPPLER, J. G. Region 3, Office of Director. 1p 18431 027. 24X Fiche 50-315, 83/05/04, 8305120396

--8305120399 LER 83-031/03L-0 on 830407, while attempting to exit upper containment outer door of personnel airlock would not open Caused by interlock cable being out of adjustment Cable replaced
CARTEAUX, P Indiana & Michigan Electric Co 83/05/04 Region 3, Office of Director 1p 18431 028 24X Fiche 50-315, 83/05/04, 8305120396

8305170441 Forwards LER 83-032/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/05/06 KEPPLER, J G Region 3, Office of Director 1p 18471 228 24X
Fiche 50-315, 83/05/06, 8305170441

--8305170444 LER 83-032/03L-0 on 830407, during normal operation, QA insp of containment revealed several items of loose debris & inadequately restrained items Items removed or properly secured
CARTEAUX, P Indiana & Michigan Electric Co 83/05/06 Region 3, Office of Director 1p 18471 229 24X Fiche 50-315, 83/05/06, 8305170441

8305130178 Forwards LER 83-033/03L-0
SMITH, W G Indiana & Michigan Electric Co 83/05/09 KEPPLER, J G Region 3, Office of Director 1p 18439 360 24X
Fiche 50-315, 83/05/09, 8305130178

--8305130191 LER 83-033/03L-0 on 830409, during normal operation, following daily routine particulate filter change on lower containment airborne monitor, train B ERS-1400 failed to operate Cause unknown Flush channel cleared
PALMER, R A Indiana & Michigan Electric Co 83/05/09 Region 3, Office of Director 2pp 18439 361 24X Fiche 50-315, 83/05/09, 8305130178

8305130206 RO on 830506, discovered that chemical vol control sys holdup tanks not sampled in 12 h time period required when automatic gas analyzer inoperable Sample performed approx 4-5 h late
SMITH, W G Indiana & Michigan Electric Co 83/05/09 KEPPLER, J G Region 3, Office of Director 1p 18439 357 24X
Fiche 50-315, 83/05/09, 8305130206

8305240329 LER 83-034/03L-0 on 830413, pyralarm detector alarmed & found unplugged, rendering Fire Zone 4 detectors inoperable Caused by failure to plug in alarm after conduit installation Pyralarm reinstalled & sys verified operable W/830513 ltr
PIEHL, R H , SMITH, W G Indiana & Michigan Electric Co 83/05/13 KEPPLER, J G Region 3, Office of Director 2pp 18549 356 24X
Fiche 50-315, 83/05/13, 8305240329

8305240330 LER 83-035/03L-0 on 830414, deluge valves for instrument room purge exhaust 1-HV-CIPX-1 & control room cleanup sys 1-HV-ACRF-1 would not open upon actuation signal Caused by failure of time delay circuit boards W/830513 ltr
PALMER, R A , SMITH, W G Indiana & Michigan Electric Co 83/05/13 KEPPLER, J G Region 3, Office of Director 3pp 18574 085 24X
Fiche 50-315, 83/05/13, 8305240330

8305240345 LER 83-036/03L-0 on 830418, eight charcoal filter fill hole covers on 12-HV-AFX spent fuel storage pool exhaust ventilation sys found loose Caused by lack of procedure specifying correct matl New procedure written W/830516 ltr
ROBINSON, D , SMITH, W G Indiana & Michigan Electric Co 83/05/16 KEPPLER, J G Region 3, Office of Director 2pp 18572 361 24X
Fiche 50-315, 83/05/16, 8305240345

8305240362 Forwards revised LERs 82-110/03X-1 & 82-111/03X-1
SMITH, W G Indiana & Michigan Electric Co 83/05/16 KEPPLER, J G Region 3, Office of Director 1p 18574 003 24X
Fiche 50-315, 83/05/16, 8305240362

--8305240370 Revised LER 82-110/03X-1 on 821230, while performing ice condenser tour, intermediate deck door discovered frozen shut Cause of moisture unknown Ice removed Doors operable No further problems observed
CAMP, M J Indiana & Michigan Electric Co 83/05/16 Region 3, Office of Director 1p 18574 004 24X Fiche 50-315, 83/05/16, 8305240362

--8305240374 Revised LER 82-111/03X-1 on 821109, during normal operation, auxiliary cable vault experienced inadvertent carbon dioxide discharge Caused by isolation of main carbon dioxide tank Valve isolating tank closed & main isolation reopened
KRAUSE, D F Indiana & Michigan Electric Co 83/05/16 Region 3, Office of Director 3pp 18574 005 24X Fiche 50-315, 83/05/16, 8305240362

8305270087 Updated LER 81-041/03X-1 on 810902, electrical ground traced to B train heaters from boron injection tank Caused by burned-up heater element & associated power cable Heater & power cable replaced W/830519 ltr
WIZNER, D G , SMITH, W G Indiana & Michigan Electric Co 83/05/19 KEPPLER, J G Region 3, Office of Director 3pp 18638 183 24X
Fiche 50-315, 83/05/19, 8305270087

8305270107 LER 83-037/01T-0 on 830416, 12-h grab sampling requirement of Tech Specs not met Caused by individual attempting to repair hydrogen monitor unable to obtain sampling at required time W/830519 ltr
PALMER, R A SMITH, W G Indiana & Michigan Electric Co 83/05/19 KEPPLER, J G Region 3, Office of Director 3pp 18638 241 24X
Fiche 50-315, 83/05/19, 8305270107

8305270444 LER 83-038/03L-0 on 830421, during normal operation, design discrepancy in wiring discovered in lower containment airborne monitor Train A Caused by voltage dips in wiring Wiring corrected & monitor returned to svc W/830520 ltr
PALMER, R A , SMITH, W G Indiana & Michigan Electric Co 83/05/20 KEPPLER, J G Region 3, Office of Director 3pp 18642 242 24X
Fiche 50-315, 83/05/20, 8305270444

DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305170270 Rev 4 to PMP 2080 EPP 008, "Initiating Manning of Emergency Response Facilities & Calling Off-Duty Plant Personnel "
* Indiana & Michigan Electric Co 83/04/19 13pp 18463 167 24X
Fiche 50-315, 83/04/19, 8305170270

--8305170274 Replacement pages, to PMP 2081 EPP 027, "Unit Vent Emergency Release Rate Determination "
* Indiana & Michigan Electric Co 83/04/29 7pp 18463 180
24X Fiche 50-315, 83/04/19, 8305170270

8305040259 Releases public version of temporary change to rev to App B, hosp assistance plan
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18326 347 24X Fiche 50-315, 83/04/25, 8305040259

--8305040265 Forwards public version of Temporary Change 1 to Rev 4 to App B, hosp assistance plan
* Indiana & Michigan Electric Co 83/04/13 GRIMES, B NRC - No Detailed Affiliation Given 1p 18326 348 24X
Fiche 50-315, 83/04/25, 8305040259

--8305040268 Public version of Temporary Change 1 to Rev 4 to App B, hosp assistance plan
* Indiana & Michigan Electric Co 83/04/13 4pp 18326 349
24X Fiche 50-315, 83/04/25, 8305040259

8305120108 Forwards fee re review of alternate safe shutdown capability per 10CFR170 22 & 830331 application
ALEXICH, M P American Electric Power Service Corp 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director DIGGS, R M NRC - No Detailed Affiliation Given 2pp 18423 043
24X Fiche 50 315, 83/05/06, 8305120108

8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation
SHAFER, W D Region 3, Office of Director 83/05/06 DOLAN, J E American Electric Power Service Corp 2pp 18548 126 24X
Fiche 50-315, 83/05/06, 8305240302

--8305240306 Notice of violation from insp on 830215-0331
SHAFER, W D Region 3, Office of Director 83/05/06 2pp
18548 128 24X Fiche 50-315, 83/05/06, 8305240302

--8305240309 IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 Noncompliance noted failure to complete tech Spec surveillance & to establish fire watch in timely manner
SWANSON, E R Region 3, Office of Director 83/05/06 11pp
18548 130 24X Fiche 50-315, 83/05/06, 8305240302

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180745 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50, " completed Item closed
* Operating Reactors Branch 1 83/05/13 DOLAN, J Indiana & Michigan Electric Co 2pp 18506 045 24X Fiche 50-315, 83/05/13, 8305180745

8305200458 Forwards FEMA evaluation of prompt notification sys proposed for Warren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be examined by NRC during next emergency preparedness insp
HIND, J A Division of Radiological & Materials Safety Programs 83/05/20 SOUTHWOOD, R J Michigan, State of 1p 18513 001 24X Fiche 50-315, 83/05/20, 8305200458

--8305200465 Responds to 821213 ltr re potential inadequacies of public notification sys at Warren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding population
ANDERSON, J T Federal Emergency Management Agency 83/04/01 KEPPLER, J G Region 3, Office of Director 3pp 18513 002 24X Fiche 50-315, 83/05/20, 8305200458

J Insurance & indemnity information

8305160026 Forwards Endorsement 57 to NELIA Policy NF-206 & Endorsement 46 to MAELU Policy MF-79
BUCKLES J Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18452 356 24X Fiche 50-315, 83/04/28, 8305160026

P Operating license stage documents & correspondence

8305230368 Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs," providing cost analysis, per 830208 request
WHITE, W S American Electric Power Co , Inc 83/03/30 TOURTELLOTTE, J Regulatory Reform Task Force 7pp 18544 356 24X Fiche 50-315, 83/03/30, 8305230368

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO N J Commissioners 2pp 18542 272 24X Fiche 50-000, 83/04/11, 8305230720

8305040354 Forwards Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs for oxygen content in waste decay tanks & correct 830207 Amends 69 & 51
WIGGINTON, D L Operating Reactors Branch 1 83/04/25 DOLAN, J Indiana & Michigan Electric Co 2pp 18326 310 24X Fiche 50-315, 83/04/25, 8305040354

--8305040363 Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively, revising Tech Specs for oxygen content in waste decay tanks & correcting 830207 Amends 69 & 51
VARGA, S A Operating Reactors Branch 1 83/04/25 16pp 18326 312 24X Fiche 50-315, 83/04/25, 8305040354

--8305040374 Safety evaluation supporting Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/25 3pp 18326 328 24X Fiche 50-315, 83/04/25, 8305040354

--8305040382 Notice of issuance & availability of Amends 72 & 54 to Licenses DPR-58 & DPR-74, respectively
VARGA S A Operating Reactors Branch 1 83/04/25 2pp 18326 331 24X Fiche 50-315, 83/04/25, 8305040354

8305030257 Responds to 821209 ltr requesting comments on Science Applications, Inc draft Final rept, "Value-Impact Analysis of Recommendation re Steam Generator Tube Degradations & Rupture Events" (Generic Ltr 82-32)
HERING, R F American Electric Power Service Corp 83/04/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 18300 039 24X Fiche 50-315, 83/04/26, 8305030257

8305040649 Requests review of responses to SER for environ qualification equipment items for which justification for continued operation not previously submitted
VARGA, S A Operating Reactors Branch 1 83/04/27 DOLAN, J Indiana & Michigan Electric Co 3pp 18336 272 24X Fiche 50-315, 83/04/27, 8305040649

8305030519 Advises that separate iodine particulate sampling sys installed & temporary mods performed on vent monitoring sys, per NRC 830314 order re NUREG-0737, Item II F 1, Attachment 2 Unit 1 sys operational Unit 2 sys will be completed shortly
ALEXICH, M P American Electric Power Service Corp 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18295 326 24X Fiche 50-315, 83/04/29, 8305030519

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305170711 Requests ref for assumptions & methodology used in estimating post-accident radiation environs to complete environ equipment qualification review Discussion of source terms & containment type should be included
VARGA, S A Operating Reactors Branch 1 83/05/02 DOLAN, J Indiana & Michigan Electric Co 2pp 18496 256 24X Fiche 50-315, 83/05/02, 8305170711

8305180814 Requests addl info re Mercord pressure switch, including details of functional verification during testing Info requested within 45 days of receipt of ltr
VARGA, S A Operating Reactors Branch 1 83/05/02 DOLAN, J Indiana & Michigan Electric Co 2pp 18505 354 24X Fiche 50-316, 83/05/02, 8305180814

8305090359 Requests submittal of Class I & III fees for 811111 & 830225 applications for amend to Licenses DPR-58 & DPR-74 re Tech Spec changes to reflect revised surveillance requirements for safety-related snubbers
DIGGS, R M License Fee Management Branch 83/05/04 DOLAN, J Indiana & Michigan Electric Co 1p 18367 219 24X Fiche 50-315, 83/05/04, 8305090359

8305170076 Forwards Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability Amends permits storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment to 4% U-235
WIGGINTON, D L Operating Reactors Branch 1 83/05/04 DOLAN, J Indiana & Michigan Electric Co 2pp 18495 166 24X Fiche 50-315, 83/05/04, 8305170076

--8305170080 Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively, permitting storage of Westinghouse 15x15 optimized fuel assemblies w/U enrichment up to 4% U-235
VARGA, S A Operating Reactors Branch 1 83/05/04 9pp 18495 169 24X Fiche 50-315, 83/05/04, 8305170076

--8305170109 Safety evaluation supporting Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 5pp 18495 178 24X Fiche 50-315, 83/05/04, 8305170076

--8305170112 Notice of issuance & availability of Amends 73 & 55 to Licenses DPR-58 & DPR-74, respectively
VARGA, S A Operating Reactors Branch 1 83/05/04 2pp 18495 183 24X Fiche 50-315, 83/05/04, 8305170076

8305180536 Advises that action required by Amends 67 & 49 to Licenses DPR-58 & DPR-74, respectively & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
VARGA, S A Operating Reactors Branch 1 83/05/04 DOLAN, J Indiana & Michigan Electric Co 2pp 18505 076 24X Fiche 50-315, 83/05/04, 8305180536

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl
HERING, R F Indiana & Michigan Electric Co 83/05/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18448 105. 24X Fiche 50-315, 83/05/10, 8305160121

--8305160126 Proposed Tech Spec Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI
* Indiana & Michigan Electric Co 83/05/10 32pp 18448 109 24X Fiche 50-315, 83/05/10, 8305160121

8305180838 Advises that info provided in 821115 & 1214 ltrs re TMI Items II F 1 1 & II F 1 2 on particulate monitors resolved concerns Info acceptable
VARGA, S A Operating Reactors Branch 1 83/05/10 DOLAN, J Indiana & Michigan Electric Co 2pp 18506 013 24X Fiche 50-315, 83/05/10, 8305180838

8305260281 Responds to NRC final rule 10CFR50 49 re electric equipment environ qualification Right to amend response reserved until meeting w/NRC scheduled to resolve environ qualification deficiencies
HERING, R F Indiana & Michigan Electric Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 18625 220 24X Fiche 50-315, 83/05/20, 8305260281

8305310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Teledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits
HUNTER, R S Indiana & Michigan Electric Co 83/05/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18658 065
24X Fiche 50-315, 83/05/27, 8305310088

G Inspection reports, IE Bulletins & correspondence

8305200294 Forwards order imposing civil monetary penalties transmitted to licensee on 821014, for transmittal to Ofc of FR for publication W/o encl
AXELRAD, J A Director's Office, Office of Inspection and Enforcement 82/10/15 Docketing & Services Branch 1p
18516 271 24X Fiche 50-315, 82/10/15, 8305200294

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305020347 Forwards IE Insp Repts 50-315/83-01 & 50-316/83-01 on 830117-21 & 0217 No noncompliance noted
NORELIUS, C E Division of Project & Resident Programs 83/04/15
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 2pp 18274 094 24X
Fiche 50-315, 83/04/15, 8305020347

--8305020348 IE Insp Repts 50-315/83-01 & 50-316/83-01 on 830117-21 & 0217 No noncompliance noted Major areas inspected QA/QC organization & program work controls, design controls & control of contractor activities
DUBRY, N , HELLER, J , HOLZMER, M Region 3, Office of Director
83/04/14 11pp 18274 096 24X Fiche 50-315, 83/04/15, 8305020347

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305240302 Forwards IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 & notice of violation
SHAFER, W D Region 3, Office of Director 83/05/06 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 2pp 18548 126 24X Fiche 50-315, 83/05/06, 8305240302

--8305240306 Notice of violation from insp on 830215-0331
SHAFER W D Region 3, Office of Director 83/05/06 2pp
18548 128 24X Fiche 50-315, 83/05/06, 8305240302

--8305240309 IE Insp Repts 50-315/83-04 & 50-316/83-05 on 830215-0331 Noncompliance noted failure to complete Tech Spec surveillance & to establish fire watch in timely manner
SWANSON, E R , DUBRY, N E , BOYD, D C Region 3, Office of Director
83/05/06 11pp 18548 130 24X Fiche 50-315, 83/05/06, 8305240302

8305170485 Confirms arrangements for 830623 meeting in Glen Ellyn, IL to discuss SALP for facilities
NORELIUS, C E Division of Project & Resident Programs 83/05/09
DOLAN, J E American Electric Power Service Corp DOLAN, J E
Indiana & Michigan Electric Co 1p 18470 068 24X
Fiche 50-315, 83/05/09, 8305170485

8305170503 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-315/82-21 & 50-316/82-21 Info closes out open items re comparison limits of Sr-90 sample taken during 821115-19 insp
PAPERIELLO, C J Region 3, Office of Director 83/05/09 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 18470 011 24X Fiche 50-315, 83/05/09, 8305170503

8305160121 Application to amend Licenses DPR-58 & DPR-74, adding Tech Spec Section 4 0 5 to incorporate inservice insp & testing requirements of ASME Code Section XI Class III fee for Unit 1 & Class I fee for Unit 2 encl
HERING, R F Indiana & Michigan Electric Co 83/05/10 DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp 18448 105
24X Fiche 50-315, 83/05/10, 8305160121

--8305160126 Proposed Tech Spec Section 4 0 5, incorporating inservice insp & testing requirements of ASME Code Section XI
* Indiana & Michigan Electric Co 83/05/10 32pp 18448 109
24X Fiche 50-315, 83/05/10, 8305160121

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305240078 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02
SHAFER, W D Region 3, Office of Director 83/05/17 DOLAN, J E
American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 1p 18548 328 24X Fiche 50-315, 83/05/17, 8305240078

--8305240086 Responds to NRC 830329 ltr re violations noted in IE Insp Repts 50-315/83-02 & 50-316/83-02 Corrective actions ltr reemphasizing need to insure testing w/approved procedures sent to all chemical section personnel
HUNTER, R S Indiana & Michigan Electric Co 83/04/28
KEPPLER, J G Region 3, Office of Director 2pp 18548 329 24X
Fiche 50-315, 83/05/17, 8305240078

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305090363 Advises of submittal of "Annual Environ Operating Rept 1982" under separate cover
HERING, R F Indiana & Michigan Electric Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18363 360 24X
Fiche 50-315, 83/05/03, 8305090363

8305160054 Forwards "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept, 1982 "
HERING, R F Indiana & Michigan Electric Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18453 300 24X
Fiche 50-315, 83/05/03, 8305160054

--8305160062 "DC Cook Nuclear Plant Units 1 & 2 Annual Environ Operating Rept,1982 "
* Indiana & Michigan Electric Co * American Electric Power Co , Inc 83/05/03 535pp 18453 301 24X Fiche 50-315,83/05/03, 8305160054

S Reportable occurrences, LERs & related correspondence

8305130166 Forwards LER 83-035/03L-0
SMITH,W G Indiana & Michigan Electric Co 83/04/15 KEPPLER,J G
Region 3, Office of Director 1p 18438 113 24X
Fiche 50-316,83/04/15,8305130166

--8305130174 LER 83-035/03L-0 on 830312,during surveillance testing on main turbine stop valves,reset function for proximity switch on stop valve C failed to operate Trip function made inoperable for replacement on 830319 Cause unknown
PALMER,R A Indiana & Michigan Electric Co 83/04/15 Region 3, Office of Director 1p 18438 114 24X Fiche 50-316,83/04/15, 8305130166

8305020072 Forwards LER 83-036/01T-0
SMITH,W G Indiana & Michigan Electric Co 83/04/19 KEPPLER,J G
Region 3, Office of Director 1p 18279 253 24X
Fiche 50-316,83/04/19,8305020072

--8305020078 LER 83-036/01T-0 on 830414,cable vault halon sys declared inoperable after failing to meet design concentrations while performing nonroutine test Cause not determined Review of test data & testing continuing
JACQUES,P Indiana & Michigan Electric Co 83/04/19 Region 3, Office of Director 1p 18279 254 24X Fiche 50-316,83/04/19, 8305020072

8305020440 RO on 830420,waste gas holdup sys exceeded oxygen & hydrogen limits Cause not stated.Proposed Tech Spec changes increasing oxygen concentration limit will be reviewed by 830422 Followup rept will be submitted within 14 days
SMITH,W G Indiana & Michigan Electric Co 83/04/20 KEPPLER,J G
Region 3, Office of Director 1p 18283 091 24X
Fiche 50-315,83/04/20,8305020440

8305020161 Forwards LERs 83-037/03L-0 & 83-038/03L-0
SMITH,W G Indiana & Michigan Electric Co 83/04/22 KEPPLER,J G
Region 3, Office of Director 1p 18284 068 24X
Fiche 50-316,83/04/22,8305020161

--8305020171 LER 83-037/03L-0 on 830323,Fire Door 386 found unlatched during normal operation Caused by insufficient closer mechanism force Door closer mechanism adjusted
ROBINSON,D Indiana & Michigan Electric Co 83/04/22 Region 3, Office of Director 1p 18284 069 24X Fiche 50-316,83/04/22, 8305020161

--8305020177 LER 83-038/03L-0 on 830405,four logic test positions tested unsatisfactorily during solid-state protection sys (train A) surveillance test Caused by failed universal card A-304 Logic card replaced Sys operability verified
PALMER,R A Indiana & Michigan Electric Co 83/04/22 Region 3, Office of Director 1p 18284 070 24X Fiche 50-316,83/04/22, 8305020161

8305020192 Forwards LER 83-039/01T-0
SMITH,W G Indiana & Michigan Electric Co 83/04/22 KEPPLER,J G
Region 3, Office of Director 1p 18277 286 24X
Fiche 50-316,83/04/22,8305020192

--8305020198 LER 83-039/01T-0 on 830408,potential for violating RCS temp average used in DNB analysis discovered during proposed Tech Spec review Administrative temp average limit of 575 F imposed
PALMER,R A Indiana & Michigan Electric Co 83/04/22 Region 3, Office of Director 5pp 18277 287 24X Fiche 50-316, 83/04/22,8305020192

8305120318 Forwards LER 83-040/03L-0
SMITH,W G Indiana & Michigan Electric Co 83/05/04 KEPPLER,J G
Region 3, Office of Director 1p 18431 081 24X
Fiche 50-316,83/05/04,8305120318

--8305120324 LER 83-040/03L-0 on 830422,CCW west HX outlet to miscellaneous svc valves failed to operate within inservice insp (ISI) time limits.Caused by infrequent ISI testing ISI testing frequency increased from quarterly to monthly
ROBINSON,D Indiana & Michigan Electric Co 83/05/04 Region 3, Office of Director 1p 18431 082 24X Fiche 50-316,83/05/04, 8305120318

8305170446 Forwards LER 83-041/03L-0
SMITH,W G Indiana & Michigan Electric Co 83/05/06 KEPPLER,J G
Region 3, Office of Director 1p 18469 313 24X
Fiche 50-316,83/05/06,8305170446

--8305170451 LER 83-041/03L-0 on 830407,during normal operation,GA insp of containment revealed several items of loose debris & inadequately restrained items Items removed or properly secured
CARTEAUX,P Indiana & Michigan Electric Co 83/05/06 Region 3, Office of Director 1p 18469 314 24X Fiche 50-316,83/05/06, 8305170446

8305130206 RO on 830506,discovered that chemical vol control sys holdup tanks not sampled in 12 h time period required when automatic gas analyzer inoperable Sample performed approx 4-5 h late
SMITH,W G Indiana & Michigan Electric Co 83/05/09 KEPPLER,J G
Region 3, Office of Director 1p 18439 357 24X
Fiche 50-315,83/05/09,8305130206

8305240145 LER 83-042/03L-0 on 830427,check valve NS-262(CCW seal water to H2 sampling pumps) found leaking Caused by dirt buildup on valve seating surfaces Valve internals cleaned Seating surfaces checked W/830517 ltr
ROBINSON,D , SMITH,W G Indiana & Michigan Electric Co 83/05/17, KEPPLER,J G Region 3, Office of Director 2pp 18549 007 24X
Fiche 50-316,83/05/17,8305240145

8305270223 Forwards LERs 83-043/03L-0 & 83-044/03L-0
SMITH,W G Indiana & Michigan Electric Co 83/05/20 KEPPLER,J G
Region 3, Office of Director 1p 18637 236 24X
Fiche 50-316,83/05/20,8305270223

--8305270227 LER 83-043/03L-0 on 830425,review of train A & B lower containment airborne monitors,ERS-2300 & 2400,revealed incorrect wiring per approved physical prints Monitors removed from svc & corrections made
PALMER,R A Indiana & Michigan Electric Co 83/05/20 Region 3, Office of Director 1p 18637 234 24X Fiche 50-316,83/05/20, 8305270223

--8305270230 LER 83-044/03L-0 on 830421,20 psig difference between pressurizer pressure channels existed Caused by pressure transmitters for NPP-152 & 153 drifting Transmitters satisfactorily calibr
PALMER,R A Indiana & Michigan Electric Co 83/05/20 Region 3, Office of Director 1p 18637 235 24X Fiche 50-316,83/05/20, 8305270223

8305310179 LER 83-045/03L-0 on 830424,upper containment normal range area & lower containment airborne monitor channels declared inoperable due to bad data in channel parameter files Caused by unverified terminal printouts W/830524 ltr
PALMER,R A , SMITH,W G Indiana & Michigan Electric Co 83/05/24
KEPPLER,J G Region 3, Office of Director 3pp 18652 282 24X
Fiche 50-316,83/05/24,8305310179

DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

F, Security, medical, emergency & fire protection plans

8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/04/19
LUNDVALL,A E Baltimore Gas & Electric Co 2pp 18300 243 24X
Fiche 50-317,83/04/19,8305030198

--8305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures,plant operation,radiation protection,physical security & fire protection
ARCHITZEL,R E , TRIMBLE,D C , MCCABE,E C Division of Project & Resident Programs 83/04/18 22pp 18300 245 24X
Fiche 50-317,83/04/19,8305030198

8305060077 Forwards exemption request for relief from requirement for installation of fixed/automatic fire suppression sys in control room complex & intake structure,per 830304 request
CLARK,R A Operating Reactors Branch 3 83/04/21 LUNDVALL,A E
Rochester Gas & Electric Corp 3pp 18359 264 24X
Fiche 50-317,83/04/21,8305060077

--8305060084 Exemption from requirements for installation of fixed/automatic fire suppression sys in control room complex & intake structure
EISENHUT,D G Division of Licensing 83/04/21 Baltimore Gas & Electric Co. 5pp 18359 267 24X Fiche 50-317,83/04/21, 8305060077

8305060627 Releases public version of rev to emergency plan implementing procedure
FELTON,J M. Division of Rules and Records 83/04/25. Document Management Branch 1p. 18359 201 24X Fiche 50-317,83/04/25, 8305060627

--8305060631 Forwards public version of Rev 9, Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8, Change 1 to ERPIP 4 5 3 re guide for selection of respirators
* Baltimore Gas & Electric Co 83/04/07 NRC - No Detailed Affiliation Given 1p 18359 202 24X Fiche 50-317, 83/04/25, 8305060627

--8305060635 Public version of Rev 9, Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8, Change 1 to ERPIP 4 5 3 re guide for selection of respirators
RUSSELL, J B Baltimore Gas & Electric Co 83/03/30 6pp 18359 203 24X Fiche 50-317, 83/04/25, 8305060627

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

J Insurance & indemnity information

8305260302 Forwards Endorsement 53 to NELIA Policy NF-216 & Endorsement 42 to MAELU Policy MF-76
GAMMIE, G B Baltimore Gas & Electric Co 83/05/23 DINITZ, I Assistant Director for State & Licensee Relations 3pp 18625 163 24X Fiche 50-317, 83/05/23, 8305260302

P Operating license stage documents & correspondence

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24X
Fiche 50-000, 83/03/11, 8305240249

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON, J M Division of Rules and Records 83/03/31 SHOLLY, S C Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000, 83/03/31, 8305240254

--8305240269 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RSSMAP) analysis If rept is to be published, clear statement of program assumptions & limitations should be included
TIERNAN, J A Baltimore Gas & Electric Co 82/03/05 BURDICK, G R Office of Nuclear Regulatory Research, Director 35pp 18593 255 24X Fiche 50-000, 83/03/31, 8305240254

8305040783 Forwards Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to increase steam generator min pressurization temp
JAFFE, D H Operating Reactors Branch 3 83/04/21 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18327 204 24X
Fiche 50-317, 83/04/21, 8305040783

--8305040789 Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively, increasing steam generator min pressurization temp, correcting typographical error & limiting overtime for personnel involved in safety-related activities
CLARK, R A Operating Reactors Branch 3 83/04/21 34pp 18327 206 24X Fiche 50-317, 83/04/21, 8305040783

--8305040793 Safety evaluation supporting Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/21 3pp 18327 240. 24X Fiche 50-317, 83/04/21, 8305040783

--8305040795 Notice of issuance & availability of Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively
CLARK, R A Operating Reactors Branch 3 83/04/21 2pp 18327 243 24X Fiche 50-317, 83/04/21, 8305040783

8305060045 Forwards SER supporting util responses to NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Items resolved
CLARK, R A Operating Reactors Branch 3 83/04/21 LUNDVALL, A E Baltimore Gas & Electric Co 9pp 18354 299 24X
Fiche 50-317, 83/04/21, 8305060045

8305060396 Submits improvement program to decrease personnel error/action-related events Two types of personnel awareness programs initiated Training staff increased & instructor matls upgraded
TIERMAN, J A Baltimore Gas & Electric Co 83/04/27 CLARK, R A Operating Reactors Branch 3 3pp 18343 174 24X
Fiche 50-317, 83/04/27, 8305060396

8305060402 Application for amend to Licenses DPR-53 & DPR-69, changing Tech Spec to clarify wording of surveillance requirements for sealed souces each time reactor startup occurs Fee encl
LUNDVALL, A E Baltimore Gas & Electric Co 82/04/27 CLARK, R A Operating Reactors Branch 3 5pp 18343 291 24X
Fiche 50-317, 83/04/27, 8305060402

--8305060405 Proposed Tech Spec changes, clarifying wording of surveillance requirements for sealed sources each time reactor startup occurs
* Baltimore Gas & Electric Co 83/04/27 7pp 18343 296 24X
Fiche 50-317, 83/04/27, 8305060402

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305180768 Advises that action required by Amend 61 to License DPR-69 & Amend 80 to License DPR-53 complete since util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
JAFFE, D H Operating Reactors Branch 3 83/05/04 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18506 055 24X
Fiche 50-317, 83/05/04, 8305180768

8305170246 Forwards Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Spec requirements for equipment hatch & safety-related air filter sys
JAFFE, D H Operating Reactors Branch 3 83/05/05 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18477 011 24X
Fiche 50-317, 83/05/05, 8305170246

--8305170259 Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively, revising Tech Spec surveillance requirements for equipment hatch & safety-related air filter sys
CLARK, R A Operating Reactors Branch 3 83/05/05 64pp 18477 014 24X Fiche 50-317, 83/05/05, 8305170246

--8305170266 Safety evaluation supporting Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 7pp 18477 078 24X Fiche 50-317, 83/05/05, 8305170246

--8305170273 Notice of issuance & availability of Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/05 2pp 18477 085 24X Fiche 50-317, 83/05/05, 8305170246

8305180556 Forwards Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, safety evaluation & notice of issuance & availability Amends allow periodic testing of control element assemblies w/inoperable reed switch stack sys
JAFFE, D H Operating Reactors Branch 3 83/05/05 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18505 090 24X
Fiche 50-317, 83/05/05, 8305180556

--8305180579 Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively, allowing periodic testing of control element assemblies w/inoperable reed switch stack sys
CLARK, R A Operating Reactors Branch 3 83/05/05 17pp 18505 093 24X Fiche 50-317, 83/05/05, 8305180556

--8305180607 Safety evaluation supporting Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 4pp 18505 111 24X Fiche 50-317, 83/05/05, 8305180556

--8305180614 Notice of issuance & availability of Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/05 2pp 18505 119 24X Fiche 50-317, 83/05/05, 8305180556

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305190293 Responds to 830325 ltr re current qualification status & plans for completion of environ qualification of all safety-related electrical equipment Extension to 850430 for completion requested for Unit 1
LUNDVALL, A.E Baltimore Gas & Electric Co 83/05/10 CLARK, R A Operating Reactors Branch 3 4pp 18501 107 24X
Fiche 50-317, 83/05/10, 8305190293

8305200078 Forwards request for addl info re 830504 submittal on main steam line break analysis Operation justified pending completion of revised analysis
CLARK, R A Operating Reactors Branch 3 83/05/10 LUNDVALL, A E Baltimore Gas & Electric Co 3pp 18541 038 24X
Fiche 50-317, 83/05/10, 8305200078

8305260294 Forwards response to 830405 draft technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per 830518 telcon
ASH, R E Baltimore Gas & Electric Co 83/05/24 EISENHUT, D G Division of Licensing 2pp 18625 161 24X Fiche 50-317, 83/05/24, 8305260294

8305270029 Forwards marked-up proposed Tech Spec 3/4 6 E 6 re containment tendon surveillance
PATTERSON, M D Baltimore Gas & Electric Co 83/05/24 JAFFE, D H Operating Reactors Branch 3 3pp 18638 310 24X
Fiche 50-317, 83/05/24, 8305270029

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/19 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18300 243 24X
Fiche 50-317, 83/04/19, 8305030198

--8305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures, plant operation, radiation protection, physical security & fire protection
ARCHITZEL, R E , TRIMBLE, D C , MCCABE, E C Division of Project & Resident Programs 83/04/18 22pp 18300 245 24X
Fiche 50-317, 83/04/19, 8305030198

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020340 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-01 & 50-318/83-01
BELLAMY, R R Region 1, Office of Director 83/04/26 LUNDVALL, A E Baltimore Gas & Electric Co 1p 18277 065 24X
Fiche 50-317, 83/04/26, 8305020340

--8305020344 Responds to NRC 830303 ltr re violations noted in IE Insp Repts 50-317/83-01 & 50-318/83-01 Corrective actions changes made to Radiation Safety Procedures 2-306 & 2-305 for max air flow & protection factor, respectively
LUNDVALL, A E Baltimore Gas & Electric Co 83/03/30 MARTIN, T T Division of Engineering & Technical Programs 2pp 18277 066 24X Fiche 50-317, 83/04/26, 8305020340

8305110276 Forwards IE Insp Repts 50-317/83-09 & 50-318/83-09 on 830406-08 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/04/27 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18393 237 24X
Fiche 50-317, 83/04/27, 8305110276

--8305110277 IE Insp Repts 50-317/83-09 & 50-318/83-09 on 830406-08 No noncompliance noted Major areas inspected environ monitoring program for operations, including mgt controls, program for QC of analytical measurements & implementation of program
JANG, J C , PASCIAK, W J Region 1, Office of Director 83/04/26 4pp 18393 239 24X Fiche 50-317, 83/04/27, 8305110276

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305060412 Submits description of analyses of main steam line break inside containment per IE Bulletin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 CLARK, R A Operating Reactors Branch 3 8pp 18343 265 24X
Fiche 50-317, 83/05/04, 8305060412

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200620 Forwards info in response to remaining open issues in IE Bulletin 80-04 re main steam line break inside containment, supplementing 830504 ltr Installation of main feedwater sys trip scheduled for completion by 831117
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/17 CLARK, R A Operating Reactors Branch 3 3pp 18520 062 24X
Fiche 50-317, 83/05/17, 8305200620

--8305200628 Discusses analyses of potential consequences of main steam line break inside containment w/failed-open main feedwater regulating valve & provides justification for continued operation, per IE Bulletin 80-04 Related info encl
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/17 CLARK, R A Operating Reactors Branch 3 30pp 18520 065 24X
Fiche 50-317, 83/05/17, 8305200620

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305200631 Forwards meteorological data for semiannual effluent repts for 1982
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 ALLAN, J M
Region 1, Office of Director 1p 18519 173 24X
Fiche 50-317, 83/05/04, 8305200631

--8305200644 "Calvert Cliffs Nuclear Power Plant, Meteorological Data," Jan-June 1982
* Baltimore Gas & Electric Co 83/05/04 68pp 18519 174 24X
Fiche 50-317, 83/05/04, 8305200631

--8305200650 "Calvert Cliffs Nuclear Power Plant, Meteorological Data," Jul-Dec 1982
* Baltimore Gas & Electric Co 83/05/04 68pp 18519 241 24X
Fiche 50-317, 83/05/04, 8305200631

8305200564 Forwards monthly operating repts for Apr 1983
LOTITO, E M Baltimore Gas & Electric Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18514 128 24X
Fiche 50-317, 83/05/13, 8305200564

--8305200584 Monthly operating repts for Apr 1983
LOTITO, E Baltimore Gas & Electric Co 83/05/15 10pp 18514 129 24X Fiche 50-317, 83/05/13, 8305200564

Reportable occurrences, LERs & related correspondence

8305040727 Advises of intention to address AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," by using NRR Ofc Ltr 40
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/04/12 MCLTEMES, C J Director's Office 1p 18328 098 24X
Fiche 50 317, 83/04/12, 8305040727

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50 000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573

8305020509 Nonroutine radiological environ operating rept During First Quarter 1983, sampling of gamma-emitting radionuclides indicated presence of AM-110m w/higher than permitted concentration
FUHRMAN, G R Baltimore Gas & Electric Co 83/04/21 Region 1, Office of Director 2pp 18281 264 24X Fiche 50-317, 83/04/21, 8305020509

8305110352 Forwards LER 83-016/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/04/27 ALLAN, J M
Region 1, Office of Director 1p 18406 127 24X
Fiche 50-317, 83/04/27, 8305110352

--8305110363 LER 83-016/03L 0 on 830328, during transfer of resin from miscellaneous waste ion exchanger to solid waste, hole developed in sight glass for resin transfer line Caused by attempt to open resin clog Piping mods developed
JUNGE, M A , UNKLE, T J Baltimore Gas & Electric Co 83/04/27
Region 1, Office of Director 2pp 18406 128 24X
Fiche 50 317, 83/04/27, 8305110352

8305270072 RO 50-317/83-19 on 830426, while raising RCS pressure to 400 psig, PORV ERV 404 inadvertently opened Valve immediately isolated by shutting upstream valve Complete description of event & corrective actions will be submitted
RUSSELL, L B Baltimore Gas & Electric Co 83/04/27 ALLAN, J M
Region 1, Office of Director 2pp 18638 302 24X
Fiche 50-317, 83/04/27, 8305270072

8305270603 RO 83-21 confirms operation ctr 830430 verbal notification of error in assumption used for main steam line break (MSLB) accident analysis Reanalysis performed of MSLB event assuming failure of main feed regulating valve
RUSSELL, L B Baltimore Gas & Electric Co 83/05/02 ALLAN, J M
Region 1, Office of Director 1p 18646 102 24X
Fiche 50-317, 83/05/02, 8305270603

8305060530 PND-I-83-044 on 830503, effect of continued feedwater flow due to failed open feedwater regulating valve incorporated per addl questions re licensee response to IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break "
ARCHITZEL, MCCABE Region 1, Office of Director 83/05/03 1p 18347 292 24X Fiche 50-317, 83/05/03, 8305060530

8305060412 Submits description of analyses of main steam line break inside containment per IE Bulletin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 CLARK, R A
Operating Reactors Branch 3 8pp 18343 265 24X
Fiche 50-317, 83/05/04, 8305060412

8305190287 Forwards LER 83-022/04X-0
RUSSELL, L B Baltimore Gas & Electric Co 83/05/05 ALLAN, J M
Region 1, Office of Director 1p 18501 111 24X
Fiche 50-317, 83/05/05, 8305190287

--8305190290 LER 83-022/04X-0 on 821118, higher than normal radioactive Ag-110m levels found in oyster samples Caused by natural tendency of oysters to bioconcentrate environ silver All releases in CY82-83 within allowable ETS limits
BROBST, G E Baltimore Gas & Electric Co 83/05/05 Region 1, Office of Director 1p 18501 112 24X Fiche 50-317, 83/05/05, 8305190287

8305230510 Forwards LER 83-019/01T-0
RUSSELL, L B Public Service Electric & Gas Co of New Jersey 83/05/05 ALLAN, J M Region 1, Office of Director 1p 18536 315
24X Fiche 50-317, 83/05/05, 8305230510

--8305230513 LER 83-019/01T-0 on 830426, PORV ERV-404 opened while raising RCS pressure Caused by failure of control room operator to monitor RCS pressure carefully Short circuit caused loss of control power to ERV-402 during troubleshooting
WENDERLICH, R L Baltimore Gas & Electric Co 83/05/05 Region 1, Office of Director. 2pp 18536 316 24X Fiche 50-317, 83/05/05, 8305230510

8305230555 Forwards LER 83-018/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/05/05 ALLAN, J M
Region 1, Office of Director 1p 18537 331 24X
Fiche 50-317, 83/05/05, 8305230555

--8305230560 LER 83-018/03L-0 on 830408, during maint, emergency diesel generator failed to start Probably caused by inadvertent admission of air into fuel oil sys during maint Investigation continuing
JUNGE, M A , PAVIS, G S Baltimore Gas & Electric Co 83/05/05
Region 1, Office of Director 2pp 18537 332 24X
Fiche 50-317, 83/05/05, 8305230555

DOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/19
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18300 243 24X
Fiche 50-317, 83/04/19, 8305030198

--8305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures, plant operation, radiation protection, physical security & fire protection
ARCHITZEL, R E Division of Project & Resident Programs 83/04/18
22pp 18300 245 24X Fiche 50-317, 83/04/19, 8305030198

8305060077 Forwards exemption request for relief from requirement for installation of fixed/automatic fire suppression sys in control room complex & intake structure, per 830304 request
CLARK, R A Operating Reactors Branch 3 83/04/21 LUNDVALL, A E
Rochester Gas & Electric Corp 3pp 18359 264 24X
Fiche 50-317, 83/04/21, 8305060077

--8305060084 Exemption from requirements for installation of fixed/automatic fire suppression sys in control room complex & intake structure
EISENHUT, D G Division of Licensing 83/04/21 Baltimore Gas & Electric Co 5pp 18359 267 24X Fiche 50-317, 83/04/21, 8305060077

8305060627 Releases public version of rev to emergency plan implementing procedure
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18359 201 24X Fiche 50-317, 83/04/25, 8305060627

--8305060631 Forwards public version of Rev 9,Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8,Change 1 to ERPIP 4 9 3 re guide for selection of respirators
* Baltimore Gas & Electric Co 83/04/07 NRC - No Detailed Affiliation Given 1p 18359 202 24X Fiche 50-317,83/04/25,8305060627

--8305060635 Public version of Rev 9,Change 2 to Emergency Plan Implementing Procedure ERPIP 4 4 7 re post-accident sampling apparatus & Rev 8,Change 1 to ERPIP 4 5 3 re guide for selection of respirators
RUSSELL,J B Baltimore Gas & Electric Co 83/03/30 6pp 18359 203 24X Fiche 50-317,83/04/25,8305060627

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 099 24X
Fiche 50-000,83/05/11,8305110034

J Insurance & indemnity information

8305260302 Forwards Endorsement 53 to NELIA Policy NF-216 & Endorsement 42 to MAELU Policy MF-76
OAMMIE,G B Baltimore Gas & Electric Co 83/05/23 DINITZ,I Assistant Director for State & Licensee Relations 3pp 18625 163 24X Fiche 50-317,83/05/23,8305260302

P Operating license stage documents & correspondence

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659,Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515,2787 & 2802)
SHOLLY,S C Union of Concerned Scientists 83/03/11 FELTON,J M Division of Rules and Records 1p 18593 178 24X
Fiche 50-000,83/03/11,8305240249

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON,J M Division of Rules and Records 83/03/31 SHOLLY,S C Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000,83/03/31,8305240254

--8305240269 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RSSMAP) analysis If rept is to be published,clear statement of program assumptions & limitations should be included
TIERNAN,J A Baltimore Gas & Electric Co 82/03/05 BURDICK,G R Office of Nuclear Regulatory Research, Director 35pp 18593 255 24X Fiche 50-000,83/03/31,8305240254

8305040783 Forwards Amends 82 & 65 to Licenses DPR-53 & DPR-69, respectively,safety evaluation & notice of issuance & availability Amends revise Tech Specs to increase steam generator min pressurization temp
JAFFE,D H Operating Reactors Branch 3 83/04/21 LUNDVALL,A E Baltimore Gas & Electric Co. 2pp 18327 204 24X
Fiche 50-317,83/04/21,8305040783

--8305040789 Amends 82 & 65 to Licenses DPR-53 & DPR-69,respectively, increasing steam generator min pressurization temp, correcting typographical error & limiting overtime for personnel involved in safety-related activities
CLARK,R A Operating Reactors Branch 3 83/04/21 34pp 18327 206 24X Fiche 50-317,83/04/21,8305040783

--8305040793 Safety evaluation supporting Amends 82 & 65 to Licenses DPR-53 & DPR-69,respectively
* Office of Nuclear Reactor Regulation, Director 83/04/21 3pp 18327 240 24X Fiche 50-317,83/04/21,8305040783

--8305040795 Notice of issuance & availability of Amends 82 & 65 to Licenses DPR-53 & DPR-69,respectively
CLARK,R A Operating Reactors Branch 3 83/04/21 2pp 18327 243 24X Fiche 50-317,83/04/21,8305040783

8305060045 Forwards SER supporting util responses to NUREG-0737, Items II.F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Items resolved
CLARK,R A Operating Reactors Branch 3 83/04/21 LUNDVALL,A E Baltimore Gas & Electric Co 9pp 18354 299 24X
Fiche 50-317,83/04/21,8305060045

8305060396 Submits improvement program to decrease personnel error/ action-related events Two types of personnel awareness programs initiated Training staff increased & instructor mats upgraded
TIERMAN,J A Baltimore Gas & Electric Co 83/01/27 CLARK,R A Operating Reactors Branch 3 3pp 18343 174 24X
Fiche 50-317,83/04/27,8305060396

8305060402 Application for amend to Licenses DPR-53 & DPR-69,changing Tech Spec to clarify wording of surveillance requirements for sealed sources each time reactor startup occurs Fee encl
LUNDVALL,A E Baltimore Gas & Electric Co 82/04/27 CLARK,R A Operating Reactors Branch 3 5pp 18343 291 24X
Fiche 50-317,83/04/27,8305060402

--8305060405 Proposed Tech Spec changes,clarifying wording of surveillance requirements for sealed sources each time reactor startup occurs
* Baltimore Gas & Electric Co 83/04/27 7pp 18343 296 24X
Fiche 50-317,83/04/27,8305060402

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305180768 Advises that action required by Amend 61 to License DPR-69 & Amend 80 to License DPR-53 complete since util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
JAFFE,D H Operating Reactors Branch 3 83/05/04 LUNDVALL,A E Baltimore Gas & Electric Co 2pp 18506 055 24X
Fiche 50-317,83/05/04,8305180768

8305170246 Forwards Amends 83 & 66 to Licenses DPR-53 & DPR-69, respectively,safety evaluation & notice of issuance & availability Amends revise Tech Spec requirements for equipment hatch & safety-related air filter sys
JAFFE,D H Operating Reactors Branch 3 83/05/05 LUNDVALL,A E Baltimore Gas & Electric Co 3pp 18477 011 24X
Fiche 50-317,83/05/05,8305170246

--8305170259 Amends 83 & 66 to Licenses DPR-53 & DPR-69,respectively, revising Tech Spec surveillance requirements for equipment hatch & safety-related air filter sys
CLARK,R A Operating Reactors Branch 3 83/05/05 64pp 18477 014 24X Fiche 50-317,83/05/05,8305170246

--8305170266 Safety evaluation supporting Amends 83 & 66 to Licenses DPR-53 & DPR-69,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 7pp 18477 078 24X Fiche 50-317,83/05/05,8305170246

--8305170273 Notice of issuance & availability of Amends 83 & 66 to Licenses DPR-53 & DPR-69,respectively
TRAMMELL,C M Operating Reactors Branch 3 83/05/05 2pp 18477 085 24X Fiche 50-317,83/05/05,8305170246

8305180556 Forwards Amends 84 & 67 to Licenses DPR-53 & DPR-69, respectively,safety evaluation & notice of issuance & availability Amends allow periodic testing of control element assemblies w/inoperable reed switch stack sys
JAFFE,D H Operating Reactors Branch 3 83/05/05 LUNDVALL,A E Baltimore Gas & Electric Co 3pp 18505 090 24X
Fiche 50-317,83/05/05,8305180556

--8305180579 Amends 84 & 67 to Licenses DPR-53 & DPR-69,respectively, allowing periodic testing of control element assemblies w/inoperable reed switch stack sys
CLARK,R A Operating Reactors Branch 3 83/05/05 17pp 18505 093 24X Fiche 50-317,83/05/05,8305180556

--8305180607 Safety evaluation supporting Amends 84 & 67 to Licenses DPR-53 & DPR-69,respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 4pp 18505 111 24X Fiche 50-317,83/05/05,8305180556

--8305180614 Notice of issuance & availability of Amends 84 & 67 to Licenses DPR-53 & DPR-69,respectively
TRAMMELL,C M Operating Reactors Branch 3 83/05/05 2pp 18505 119 24X Fiche 50-317,83/05/05,8305180556

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8309190293 Responds to 830325 ltr re current qualification status & plans for completion of environ qualification of all safety-related electrical equipment Extension to 850430 for completion requested for Unit 1
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/10 CLARK, R A
Operating Reactors Branch 3 4pp 18501 107 24X
Fiche 50-317 83/05/10, 8305190293

8305200078 Forwards request for addl info re 830504 submittal on main steam line break analysis Operation justified pending completion of revised analysis
CLARK, R A Operating Reactors Branch 3 83/05/10 LUNDVALL, A E
Baltimore Gas & Electric Co 3pp 18541 038 24X
Fiche 50-317, 83/05/10, 8305200078

8305260294 Forwards response to 830405 diart technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per 830518 telcon
ASH, R E Baltimore Gas & Electric Co 83/05/24 EISENHUT, D G
Division of Licensing 2pp 18629 161 24X Fiche 50-317, 83/05/24, 8305260294

8305270029 Forwards marked-up proposed Tech Spec 3/4 6 1 6 re containment tendon surveillance
PATTERSON, M D Baltimore Gas & Electric Co 83/05/24 JAFFE, D H
Operating Reactors Branch 3 3pp 18638 310 24X
Fiche 50-317, 83/05/24, 8305270029

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305030198 Forwards IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/19
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18300 243 24X
Fiche 50-317, 83/04/19, 8305030198

--8305030208 IE Insp Repts 50-317/83-07 & 50-318/83-07 on 830315-0412 No noncompliance noted Major areas inspected control room, accessible plant structures, plant operation, radiation protection, physical security & fire protection
ARCHITZEL, R E , TRIMBLE, D C , MCLABE, E C Division of Project & Resident Programs 83/04/18 22pp 18300 245 24X
Fiche 50-317, 83/04/19, 8305030198

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020340 Ack receipt of 830320 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-01 & 50-318/83-01
BELLAMY, R R Region 1, Office of Director 83/04/26 LUNDVALL, A E
Baltimore Gas & Electric Co 1p 18277 065 24X
Fiche 50-317, 83/04/26, 8305020340

--8305020344 Responds to NRC 830303 ltr re violations noted in IE Insp Repts 50-317/83-01 & 50-318/83-01 Corrective actions changes made to Radiation Safety Procedures 2-306 & 2-305 for max air flow & protection factor, respectively
LUNDVALL, A E Baltimore Gas & Electric Co 83/03/30 MARTIN, T T
Division of Engineering & Technical Programs 2pp 18277 066
24X Fiche 50-317, 83/04/26, 8305020340

8305110276 Forwards IE Insp Repts 50-317/83-09 & 50-318/83-09 on 830406-08 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/04/27
LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18393 237 24X
Fiche 50-317, 83/04/27, 8305110276

--8305110277 IE Insp Repts 50-317/83-09 & 50-318/83-09 on 830406-08 No noncompliance noted Major areas inspected environ monitoring program for operations, including mgt controls, program for QC of analytical measurements & implementation of program
JANG, J C , PASCIAK, W J Region 1, Office of Director 83/04/26
4pp 18393 239 24X Fiche 50-317, 83/04/27, 8305110276

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305060412 Submits description of analyses of main steam line break inside containment per IE Bulletin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 CLARK, R A
Operating Reactors Branch 3 8pp 18343 265 24X
Fiche 50-317, 83/05/04, 8305060412

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200620 Forwards info in response to remaining open issues in IE Bulletin 80-04 re main steam line break inside containment, supplementing 830504 ltr Installation of main feedwater sys trip scheduled for completion by 831117
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/17 CLARK, R A
Operating Reactors Branch 3 3pp 18520 062 24X
Fiche 50-317, 83/05/17, 8305200620

--8305200628 Discusses analyses of potential consequences of main steam line break inside containment w/failed-open main feedwater regulating valve & provides justification for continued operation, per IE Bulletin 80-04 Related info encl
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/17 CLARK, R A
Operating Reactors Branch 3 30pp 18520 065 24X
Fiche 50-317, 83/05/17, 8305200620

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305200631 Forwards meteorological data for semiannual effluent repts for 1982.
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04 ALLAN, J M
Region 1, Office of Director 1p 18519 173 24X
Fiche 50-317, 83/05/04, 8305200631

--8305200644 "Calvert Cliffs Nuclear Power Plant, Meteorological Data," Jan-June 1982
* Baltimore Gas & Electric Co 83/05/04. 68pp 18519.174. 24X
Fiche 50-317, 83/05/04, 8305200631

8305200564 Forwards monthly operating repts for Apr 1983
LOTITO, E M Baltimore Gas & Electric Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p. 18514.128 24X
Fiche 50-317, 83/05/13, 8305200564.

--8305200584 Monthly operating repts for Apr 1983
LOTITO, E Baltimore Gas & Electric Co 83/05/15. 10pp
18514 129. 24X Fiche 50-317, 83/05/13, 8305200564

S Reportable occurrences, LERs & related correspondence

8305040727 Advises of intention to address AEOD/E304, "Investigation of Backflow Protection in Common Equipment & Floor Drain Sys to Prevent Flooding of Vital Equipment in Safety-Related Compartments," by using NRR Ofc Ltr 40.
DENTON, H R. Office of Nuclear Reactor Regulation, Director
83/04/12 HELTEMES, C J Director's Office. 1p 18328.098. 24X
Fiche 50-317, 83/04/12, 8305040727

8305030383 Forwards LER 83-015/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/04/18 ALLAN, J M.
Region 1, Office of Director 1p 18308:198 24X
Fiche: 50-318, 83/04/18, 8305030383

--8305030388 LER 83-015/03L-0 on 830321, invalid in-core detector linear heat rate alarm revealed incorrect alarm setpoints entered on 830307 Caused by improper alarm setpoint forms Setpoints corrected & forms clarified
PIERINGER, P A , BOWMAN, M E. Baltimore Gas & Electric Co
83/04/18. Region 1. Office of Director 1p 18308 199 24X
Fiche 50-318, 83/04/18, 8305030383

8305020509 Nonroutine radiological environ operating rept During First Quarter 1983, sampling of gamma-emitting radionuclides indicated presence of AM-110m w/higher than permitted concentration
FUHRMAN, G R Baltimore Gas & Electric Co 83/04/21 Region 1, Office of Director 2pp 18281 264. 24X Fiche. 50-317, 83/04/21, 8305020509

8305160081 LER 83-019/03L-0 has been canceled
RUSSELL, L B Baltimore Gas & Electric Co 83/04/22 ALLAN, J M
Region 1, Office of Director 1p 18450 356. 24X
Fiche 50-318, 83/04/22, 8305160081

8305040146 Forwards evaluation rept on loss of saltwater flow to svc water HXs Removal of locked open nonsafety-related HX discharge valves recommended
CINTULA, T C. Reactor Operations Analysis Branch. 83/04/25
SEYFRIT, K V Reactor Operations Analysis Branch 1p. 18327 015
24X Fiche 50-318, 83/04/25, 8305040146

--8305040150 "Loss of Salt Water Flow to Svc Water HXs," evaluation rept
CINTULA, T C. Director's Office 83/04/25 7pp. 18327·016 24X
Fiche·50-318, 83/04/25, 8305040146

8305060530 PNO-I-83-044 on 830503, effect of continued feedwater flow due to failed open feedwater regulating valve incorporated per addl questions re licensee response to IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break .. "
ARCHITZEL, MCCABE Region 1, Office of Director. 83/05/03. 1p
18347.292 24X Fiche 50-317, 83/05/03, 8305060530.

8305060412 Submits description of analyses of main steam line break inside containment per IE Bulletin 80-04 resulting in 830430 LER Feedwater sys mods being initiated Continued operation justified.
LUNDVALL, A E Baltimore Gas & Electric Co 83/05/04. CLARK, R A.
Operating Reactors Branch 3. 8pp. 18343.265 24X
Fiche: 50-317, 83/05/04, 8305060412.

8305190348 Forwards LER 83-023/03L-0.
RUSSELL, L B. Baltimore Gas & Electric Co. 83/05/05 ALLAN, J. M
Region 1, Office of Director. 1p. 18500·023 24X
Fiche 50-318, 83/05/05, 8305190348

--8305190352 LER 83-023/03L-0 on 830405, control power fuse for main vent RMS panel (1C22F) blew due to short circuit Caused by short when control circuit relay auxiliary contacts jumpered. Electricians cautioned Wiring properly labeled
JUNGE, M A., BASSO, L F. Baltimore Gas & Electric Co 83/05/05.
Region 1, Office of Director 1p 18500.024. 24X
Fiche 50-318, 83/05/05, 8305190348

8305230522 Forwards LER 83-022/03L-0
RUSSELL, L B Baltimore Gas & Electric Co 83/05/05 ALLAN, J M
Region 1, Office of Director 1p 18536 327 24X
Fiche 50-318, 83/05/05, 8305230522

--8305230528 LER 83-022/03L-0 on 830411, during surveillance testing, auxiliary feedwater actuating sys channel ZF setpoint for steam generator delta pressure found out-of-spec Caused by E/I isolator output drifting low Isolator replaced
PIERINGER, P. A , BASSO, L F Baltimore Gas & Electric Co. 83/05/05
Region 1, Office of Director. 1p 18536.328 24X
Fiche 50-318, 83/05/05, 8305230522.

DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305040575 Releases public version of rev to emergency preparedness procedure
FELTON, J M Division of Rules and Records. 83/04/25 Document Management Branch 1p. 18351.242 24X Fiche·50-320, 83/04/25, 8305040575.

--8305040580 Public version of Rev 4 to Emergency Preparedness Procedure 1054 8, "Callout of Onsite & Offsite Duty Roster Personnel."
BEAVER, J R., BARTON, J J. General Public Utilities - GPU Service Corp. 83/04/11 16pp. 18351.244. 24X Fiche 50-320, 83/04/25, 8305040575.

8305050377 Releases public version of rev to emergency plan implementing procedure.
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p. 18352:163 24X Fiche: 50-320, 83/04/25, 8305050377

--8305050381 Public version of Rev 1 to Emergency Plan Implementing Procedure 1054.28, "Activation of Technical Support Ctr."
STANOE, S J General Public Utilities - GPU Service Corp
83/03/17 5pp 18352.164 24X Fiche 50-320, 83/04/25, 8305050377.

8305100143 Submits status of offsite emergency preparedness issues re FEMA regional verifications through 830304 & data received through 830331 concerning schedule for completion of issues at facilities.
KRIMM, R W. Federal Emergency Management Agency. 83/04/26
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 9pp. 18375·001 24X Fiche·50-289, 83/04/26, 8305100143.

8305060082 Informs of addl mod to schedule for fire detection capability in chemical cleaning bldg. Scheduled completion date extended to 830715.
KANGA, B K General Public Utilities - GPU Service Corp 83/04/29
SNYDER, B J. TMI Program Office 1p 18345.050 24X
Fiche·50-320, 83/04/29, 8305060082

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EISENHUT, D. G. Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc. 16pp 18540·095. 24X
Fiche 50-000, 83/05/11, 8305110034

8305200563 Forwards clarification of security plan, per NRC 821116 request Clarification withheld (ref 10CFR2.790)
KANGA, B. K GPU General Public Utilities - GPU Service Corp 83/05/16.
SNYDER, B J TMI Program Office 1p. 18514:269. 24X
Fiche 50-320, 83/05/16, 8305200563

L. Adjudicatory correspondence

8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl
CHILK, S. J. Office of the Secretary of the Commission. 83/03/31.
Commissioners 3pp 17807:049. 24X Fiche. 50-000, 83/03/31, 8304040470

8305040054 Discusses status of B&W-GPU lawsuit document review. Next rept expected within 2 wks.
DIRCKS, W J. Office of the Executive Director for Operations.
83/04/20 PALLADINO, N , GILINSKY, V , AHEARNE, J. Commissioners.
2pp. 18336:325. 24X Fiche: 50-289, 83/04/20, 8305040054.

--8305040068 Staff requirements memo re 830330 briefing on investigation & possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wks
CHILK,S J Office of the Secretary of the Commission 83/04/08
DIRCKS,W J Office of the Executive Director for Operations
HAYES,B B NRC - No Detailed Affiliation Given CUMMINGS,J J Office of Inspector & Auditor. 2pp 18336 327 24X Fiche 50-289,83/04/20,8305040054

8305230700 Requests cooperation in informing NRC of outstanding safety concerns re facilities Prompt notification re allegations of safety concerns requested
PLAINE,H H Office of the General Counsel 83/04/20 DEVINE,T Government Accountability Project 2pp 18542 323 24X Fiche:50-289,83/04/20,8305230700

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE,J C Office of the Secretary of the Commission 83/05/05 Commissioners 1p 18345:196 24X Fiche.50-000,83/05/05, 8305060250

8305130060 Response opposing intervenor motion for recusation.Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO,N J Commissioners 83/05/11 2pp 18436 228. 24X Fiche:50-000,83/05/11,8305130060.

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/12 Commissioners 1p 18437 033. 24X Fiche.50-000,83/05/12, 8305130061.

8305240216 Advises that 830323 ltr requesting immediate halt to all work at TMI-1 & 2,w/exception of maint necessary for safety,will receive consideration as request for action under 10CFR2.206 FR notice encl
DENTON,H.R Office of Nuclear Reactor Regulation, Director 83/05/17. KING,R Three Mile Island Public Interest Resource Center. 2pp. 18593 306 24X Fiche 50-289,83/05/17,8305240216

--8305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at TMI-1 & 2
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/05/17. 1p. 18593·308. 24X Fiche 50-289,83/05/17,8305240216

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK,S.J Office of the Secretary of the Commission 83/05/19. Commissioners 1p. 18514 283 24X Fiche 50-000,83/05/19, 8305200560.

8305240536 Affidavit of RE Rogan confirming util commitment to activate emergency operations facility & staff facility w/emergency support director within 1 h of site area or general emergency notification or declaration
ROGAN,R E. General Public Utilities - GPU Service Corp 83/05/20. 4pp. 18576·087 24X Fiche 50-000,83/05/20,8305240536

8305250376 Confirms T Poindexter & MN Wilcove 830527 telcon committing to discuss outstanding contentions.
WILCOVE,M.N. Hearing Branch 2. 83/05/23 JOHNSRUD,J H Environmental Coalition on Nuclear Power 1p. 18585·349 24X Fiche:50-320,83/05/23,8305250376

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl
CHILK,S.J. Office of the Secretary of the Commission 83/05/27. 14pp. 18653.311. 24X Fiche.50-000,83/05/27,8305310017.

H. General correspondence

8305120015 Requests that LP King,site operations director,be deleted from future correspondence & JJ Chwastyk,manager,plant operations be added to distribution list
KANGA,B.K. General Public Utilities - GPU Service Corp. 83/05/06 SNYDER,B.J. TMI Program Office 1p. 18428.232 24X Fiche:50-320,83/05/06,8305120015.

P. Operating license stage documents & correspondence

8305270022 Forwards "Rept on Mental Health Effects of TMI Accident " BROMET,E.J. Pittsburgh, Univ of. 83/03/08. SHANKMAN,S.F. Site Analysis Branch. 1p. 18634 001 24X Fiche·50-320,83/03/08, 8305270022.

--8305270027 "Rept on Mental Health Effects of TMI Accident " BROMET,E J Pittsburgh, Univ of. 83/02/28 NRC - No Detailed Affiliation Given 79pp 18634 002 24X Fiche 50-320,83/03/08, 8305270022

--8305270035 "Psychological Stress Among TMI Area Residents & Mediation of Response by Support & Coping "
BAUM,A , SCHAEFFER,M A , COLLINS,D L Uniformed Services Univ of the Health Sciences NRC-03-82-125 83/03/08 NRC - No Detailed Affiliation Given 34pp 18634 089 24X Fiche 50-320,83/03/08,8305270022

--8305270040 Forwards final rept, "Reanalysis of TMI Telephone Survey Data "
HOUTS,P S Pennsylvania State Univ NRC-03-82-123 83/03/01 REGAN,W NRC - No Detailed Affiliation Given 1p 18634 122 24X Fiche 50-320,83/03/08,8305270022

--8305270046 "Reanalysis of TMI Telephone Survey Data," final rept HOUTS,P S , MILLER,R W , LINDELL,M Pennsylvania State Univ 83/02/28 NRC - No Detailed Affiliation Given 125pp 18634 123 24X Fiche 50-320,83/03/08,8305270022

--8305270048 Draft "Restarting TMI-1.Social & Psychological Impacts on Communities "
SORENSEN,J , BODERSTROM,J. Oak Ridge National Laboratory. BOLIN,R. New Mexico State Univ 83/03/08 NRC - No Detailed Affiliation Given 207pp 18634 248 24X Fiche 50-320,83/03/08, 8305270022

8305200101 FOIA request for name of manufacturer of fuel rods used at facility
WHITED,P J Affiliation Unknown 83/03/23 FELTON,J M Division of Rules and Records 1p 18541 005 24X Fiche 50-320,83/03/23, 8305200101

8305200087 Responds to FOIA request for name of manufacturer of fuel rods used at facility Fuel rods mfg by B&W
FELTON,J M Division of Rules and Records 83/03/31 WHITED,P J Affiliation Unknown 1p 18541 004 24X Fiche 50-320,83/03/31, 8305200087

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X Fiche 50-000,83/04/11,8305230720

8305020530 Presents NRC review of & recommendations on util 830131 revised schedule & cost info re recovery
DIRCKS,W.J Office of the Executive Director for Operations SECY-83-140 83/04/15 33pp 18284·261 24X Fiche 50-320, 83/04/15,8305020530

8305040686 Requests responses re relief from surveillance requirements of equipment which would result in excessive exposure Tech Spec change requests,scheduling for recovering affected sys & rev to recovery plan requested
BARRETT,L.H. TMI Program Office 83/04/27 KANGA,B K General Public Utilities - GPU Service Corp 3pp 18336 329 24X Fiche.50-320,83/04/27,8305040686

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co. of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

8305120055 Forwards Training Procedure 6210-ADM-2604 01,Rev 1-00, "Control of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02,Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program "
HUKILL,H.D General Public Utilities - GPU Service Corp. 83/05/06. STOLZ,J F. Operating Reactors Branch 4 1p 18428 233 24X Fiche·50-289,83/05/06,8305120055

--8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 01, "Control of Exams for Units 1 & 2."
* General Public Utilities - GPU Service Corp. 83/04/26 7pp 18428·234. 24X Fiche:50-289,83/05/06,8305120055

8305180238 Forwards Amend 21 to License DPR-73,safety evaluation & notice of issuance & availability.Amend consists of changes to radiological environ monitoring program requirements in Tech Specs.
SNYDER,B J TMI Program Office 83/05/06. KANGA,B K. General Public Utilities - GPU Service Corp. 3pp 18503·001 24X Fiche·50-320,83/05/06,8305180238.

--8305180245 Amend 21 to License DPR-73, consisting of changes to radiological environ monitoring program requirements in Tech Specs.
SNYDER, B J TMI Program Office 83/05/06 34pp 18503 004 24X Fiche 50-320, 83/05/06, 8305180238

--8305180249 Safety evaluation supporting Amend 21 to License DPR-73 e Office of Nuclear Reactor Regulation, Director 83/05/06 10pp. 18503:038. 24X Fiche 50-320, 83/05/06, 8305180238.

--8305180253 Notice of issuance & availability of Amend 21 to License DPR-73
SNYDER, B. J TMI Program Office 83/05/06. 3pp. 18503 048 24X Fiche 50-320, 83/05/06, 8305180238

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G. Division of Licensing. 83/05/09. Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche: 50-000, 83/05/09, 8305090659

8305170435 Provides status of activities re makeup & purification demineralizer resin sampling & characterization Results will be available by end of May. Delay should not adversely impact commitment of mid-1983 resin removal techniques assessment
KANGA, B.K General Public Utilities - GPU Service Corp 83/05/12
BARRETT, L H TMI Program Office. 3pp. 18469 303 24X
Fiche: 50-320, 83/05/12, 8305170435.

8305170448 Responds to 830427 ltr re questions on ALARA exception to Tech Spec surveillance. Several surveillances performed, w/exception of small portions in high radiation areas
KANGA, B K General Public Utilities - GPU Service Corp. 83/05/13
BARRETT, L H TMI Program Office. 7pp 18469 306. 24X
Fiche: 50-320, 83/05/13, 8305170448

8305200073 Forwards list of application dates, fees paid, fees applicable & fee determination for each application.
MILLER, W O Office of Administration. 83/05/17 ARNOLD, R C General Public Utilities - GPU Service Corp 5pp 18540.131 24X Fiche 50-320, 83/05/17, 8305200073

8305250255 Forwards Rev 0 to "SER for Radiation Characterization Under Reactor Vessel Head."
KANGA, B.K General Public Utilities - GPU Service Corp 83/05/19
BARRETT, L. H TMI Program Office 1p 18592:326 24X
Fiche: 50-320, 83/05/19, 8305250255

--8305250263 Rev 0 to "SER for Radiation Characterization Under Reactor Vessel Head."
* General Public Utilities - GPU Service Corp. 83/05/17. 27pp 18592.327 24X Fiche: 50-320, 83/05/19, 8305250255

8305310058 Forwards Rev 0 to "SER for Radiation Characterization Under Reactor Vessel Head (Polar Crane Not Available)," for review & approval. Activity scheduled to begin mid-June 1983
KANGA, B.K General Public Utilities - GPU Service Corp 83/05/25.
BARRETT, L. H TMI Program Office. 1p. 18655.076 24X
Fiche 50-320, 83/05/25, 8305310058.

--8305310103 Rev 0 to "SER for Radiation Characterization Under Reactor Vessel Head (Polar Crane Not Available)."
* General Public Utilities - GPU Service Corp 83/05/17 27pp. 18655.077. 24X Fiche: 50-320, 83/05/25, 8305310058.

8305310118 Forwards responses to NRC 830121 comments on Rev 3 to general project design criteria. Responses will be incorporated into Rev 4, if acceptable
KANGA, B K General Public Utilities - GPU Service Corp 83/05/25.
SNYDER, B. J. TMI Program Office 4pp 18658:087 24X
Fiche: 50-320, 83/05/25, 8305310118

8305310156 Forwards addendum to underhead characterization SER re core topography. Document demonstrates that proposed acoustic survey of core can be accomplished w/o undue risk & should be considered addendum to previously submitted SERs
KANGA, B K. General Public Utilities - GPU Service Corp. 83/05/26
BARRETT, L H. TMI Program Office. 8pp. 18653.036. 24X
Fiche: 50-320, 83/05/26, 8305310156

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/03/21. Consolidated Edison Co. of New York, Inc 112pp 18308:319 24X Fiche: 50-000, 83/03/21, 8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305030151 Forwards IE Insp Rept 50-320/83-04 on 830227-0403 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/19
KANGA, B K General Public Utilities - GPU Service Corp 2pp 18300 274 24X Fiche 50-320, 83/04/19, 8305030151

--8305030164 IE Insp Rept 50-320/83-04 on 830227-0403 No noncompliance noted Major areas inspected licensee action on previous insp findings, routine plant operations, LERs, health physics review, reactor bldg entries & radioactive matl shipments
WIEBE, J , BARR, K , MOSLAK, T Region 1, Office of Director 83/04/19 6pp 18300 276. 24X Fiche 50-320, 83/04/19, 8305030151

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040029 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040029

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523:248 24X Fiche. 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697.009. 24X Fiche: 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647.007 24X Fiche 50-000, 83/05/26, 8303040046.

R Periodic operating reports & related correspondence

8305040163 Forwards TMI Program Ofc weekly status rept for wk of 830410-16
BARRETT, L H TMI Program Office 83/04/18 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 10pp 18327 001 24X Fiche 50-320, 83/04/18, 8305040163

8305040170 Forwards TMI Program Ofc weekly status rept for wk of 830417-23
BARRETT, L H TMI Program Office 83/04/25 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 9pp 18327 023 24X Fiche 50-320, 83/04/25, 8305040170

8305020210 Forwards "TMI Aquatic Study, Monthly Rept for Mar 1983 "
RESSLER, W C General Public Utilities - GPU Service Corp 83/04/28
HICKEY, C NRC - No Detailed Affiliation Given 1p 18278 167
24X Fiche 50-289, 83/04/28, 8305020210

--8305020215 "TMI Aquatic Study, Monthly Rept for Mar 1983 "
NARDACCI, G A Ichthyological Associates, Inc 83/04/28 21pp
18278 168 24X Fiche 50-289, 83/04/28, 8305020210

8305030462 Forwards recovery sys description & technical evaluation rept annual updates for auxiliary bldg emergency liquid cleanup sys (EPICOR II), solid radwaste staging modules & submerged demineralizer sys, per 820204 ltr
KANGA, B K General Public Utilities - GPU Service Corp 83/04/28
SNYDER, B J TMI Program Office 2pp 18293 228 24X
Fiche 50-320, 83/04/28, 8305030462

--8305030470 "Recovery Program Sys Description, Auxiliary Bldg Emergency Liquid Clean-up Sys (EPICOR II) "
* General Public Utilities - GPU Service Corp 83/03/31 52pp.
18293 230. 24X Fiche 50-320, 83/04/28, 8305030462

--8305030478 "TMI-Unit 2 Sys Description of Submerged Demineralization Sys (SDS) "
* General Public Utilities - GPU Service Corp 83/03/31 204pp
18293 282 24X Fiche 50-320, 83/04/28, 8305030462

--8305030484 Rev 1 to "TMI-Unit 2 Recovery Program, Solid Waste Staging Facility Sys Description "
* General Public Utilities - GPU Service Corp 83/04/28 21pp
18294 126 24X Fiche 50-320, 83/04/28, 8305030462

8305060458 Forwards "Annual Environ Operating Rept, 1982, " "Ecological Study of Susquehanna River Near TMI" & "Hydraulic Survey "
HUKILL, H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18349.058 24X
Fiche 50-289, 83/04/29, 8305060458

--8305060460 "Annual Environ Operating Rept, 1982 "
* General Public Utilities - GPU Service Corp 82/12/31 18pp
18349 060 24X Fiche 50-289, 83/04/29, 8305060458

--8305060464 "Hydraulic Survey, " annual rept
* General Public Utilities - GPU Service Corp 82/06/03. 13pp
18349.078 24X Fiche 50-289, 83/04/29, 8305060458

--8305060465 "Ecological Study of Susquehanna River Near TMI, " annual rept for 1982
NARDACCI, G A Ichthyological Associates, Inc 83/04/30. 633pp
18349 091. 24X Fiche 50-289, 83/04/29, 8305060458

8305060649 Forwards "TMI Nuclear Station Radiological Environ Monitoring Rept, 1982 " W/o encl
HUKILL, H D General Public Utilities - GPU Service Corp 83/04/29
Region 1, Office of Director 1p 18348 250. 24X
Fiche. 50-289, 83/04/29, 8305060649

8305060668 Forwards TMI Program Ofc weekly status rept for wk of 830424-30
BARRETT, L H TMI Program Office 83/05/02 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J. TMI Program Office 8pp. 18357 348 24X Fiche 50-320, 83/05/02, 8305060668

8305240603 Forwards TMI Program Ofc weekly status rept for wk of 830501-07
BARRETT, L H TMI Program Office. 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director. SNYDER, B. J TMI Program Office. 7pp. 18593 167. 24X Fiche. 50-320, 83/05/09, 8305240603

8305240561 Forwards TMI Program Ofc weekly status rept for wk of 830508-14.
BARRETT, L H TMI Program Office 83/05/16 DENTON, H R. Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 9pp 18593 328. 24X Fiche. 50-320, 83/05/16, 8305240561.

8305250385 "Quarterly Dose Assessment Rept, First Quarter 1983 "
KANGA, B K General Public Utilities - GPU Service Corp 83/05/18
ALLAN, J M Region 1, Office of Director 5pp 18595 342 24X
Fiche 50-320, 83/05/18, 8305250385

8305240348 Periodic groundwater monitoring program rept for Mar 1982 - Apr 1983
KANGA, B K General Public Utilities - GPU Service Corp. 83/05/19
BARRETT, L H TMI Program Office 38pp 18574 017 24X
Fiche 50-320, 83/05/19, 8305240348

S Reportable occurrences, LERs & related correspondence

8305030527 Forwards LER 83-010/01L-0
KANGA, B K General Public Utilities - GPU Service Corp 83/04/20
ALLAN, J M Region 1, Office of Director 1p 18295 323 24X
Fiche 50-320, 83/04/20, 8305030527

--8305030535 LER 83-010/01L-0 on 830322, in-core thermocouple H-3 began to exhibit erratic behavior Cause unknown To date, no adverse trend in overall core thermocouple sys behavior apparent
CHAPLIN, B D General Public Utilities - GPU Service Corp.
83/04/20 Region 1, Office of Director 2pp 18295 324 24X
Fiche 50-320, 83/04/20, 8305030527

8305110370 Forwards LER 83-011/01L-0
KANGA, B K General Public Utilities - GPU Service Corp 83/04/25.
ALLAN, J M Region 1, Office of Director 1p 18406.275 24X
Fiche 50-320, 83/04/25, 8305110370

--8305110378 LER 83-011/01L-0. on 830325, verified that 3 h rated fire damper not installed in fire wall separating fuel handling bldg from reactor bldg annulus area Caused by AE error during const of plant Hourly firewatch posted.
CHAPLIN, B D General Public Utilities - GPU Service Corp
83/04/25 Region 1, Office of Director 3pp 18406 276. 24X
Fiche 50-320, 83/04/25, 8305110370

8305110321 Forwards LER 83-012/03L-0
KANGA, B K General Public Utilities - GPU Service Corp. 83/04/28
ALLAN, J M Region 1, Office of Director 1p 18406 071 24X
Fiche 50-320, 83/04/28, 8305110321

--8305110326 LER 83-012/03L-0 on 830329, following inadvertent discharge of one zone of air intake tunnel Halon sys, pressure of Halon bottle EI-4C discovered to be below allowable limit Caused by personnel errors Bottle repressurized
WELLS, R General Public Utilities - GPU Service Corp. 83/04/28.
Region 1, Office of Director 3pp 18406.072 24X
Fiche 50-320, 83/04/28, 8305110321

8305310001 Forwards updated LERs
KANGA, B K General Public Utilities - GPU Service Corp 83/05/19
ALLAN, J M Region 1, Office of Director 2pp 18653 060 24X
Fiche 50-320, 83/05/19, 8305310001

--8305310004 Updated LER 80-001/99X-1 on 800126, 60 amp molded case circuit breaker for generator auxiliaries found tripped. Caused by defective internal connection on A phase Breaker replaced
CHAPLIN, B. D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 062. 24X
Fiche 50-320, 83/05/19, 8305310001

--8305310007 Updated LER 80-003/01X-1 on 800218, emergency diesel generator B out of svc for annual maint, violating Tech Specs requiring both emergency diesel generators to be operable Caused by change in Tech Specs.
CHAPLIN, B D General Public Utilities - GPU Service Corp.
83/05/19 Region 1, Office of Director 2pp. 18653 064. 24X
Fiche 50-320, 83/05/19, 8305310001

--8305310010 Updated LER 80-007/01X-1 on 800222, exhaust fan AH-E8C removed from svc for maint, violating Interim Recovery Tech Specs Caused by inability to restore unit to operable status within action period. Fan repaired
CHAPLIN, B D General Public Utilities - GPU Service Corp
83/05/19. Region 1, Office of Director 2pp. 18653 066. 24X
Fiche 50-320, 83/05/19, 8305310001

--8305310014 Updated LER 80-012/01X-1. on 800413, exhaust flow of fuel handling bldg HVAC sys fell below recovery operation plan requirement Caused by either sys imbalance or flow rate requiring rev Fan lineup altered
CHAPLIN, B D General Public Utilities - GPU Service Corp.
83/05/19. Region 1, Office of Director. 2pp 18653 068. 24X
Fiche 50-320, 83/05/19, 8305310001.

--8305310019 Updated LER 80-049/01X-1 on 801027,discovered that valve LTB-V171 ASME Code stamped by unauthorized valve supply house Caused by unauthorized use of ASME UV code stamp by North American Safety Valve Industries,Inc
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 3pp 18653 070 24X
Fiche 50-320,83/05/19,8305310001

--8305310024 Updated LER 80-054/03X-1 on 801117,emergency diesel generator DF-X-1B failed to start Caused by not maintaining diesel at high enough shutdown ambient temp due to heater failure Heater & contactor replaced
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 3pp 18653 073 24X
Fiche 50-320,83/05/19,8305310001

--8305310030 Updated LER 80-055/03X-1 on 801127,emergency diesel generator DF-X-1B failed to start Caused by failure to maintain diesel at high enough shutdown ambient temp due to heater failure Heater & contactor replaced
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19. Region 1, Office of Director 3pp 18653 076 24X
Fiche 50-320,83/05/19,8305310001

--8305310036 Updated LER 80-056/01X-1 on 801212,core floor tank level instrumentation A inoperable Cause unknown Tech Spec 3 3 3 6 revised to delete core floor tank level indicators from specs
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director. 3pp 18653 079 24X
Fiche 50-320,83/05/19,8305310001

--8305310041 Updated LER 80-057/03X-1 on 801217,air intake tunnel chlorine monitor declared inoperable due to failure to respond upon exposure to chlorine vapors Caused by dirty probe Probe cleaned & returned to svc
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 082 24X
Fiche 50-320,83/05/19,8305310001

--8305310047 Updated LER 81-004/03X-1 on 810204,emergency diesel generator DF-X-1B failed to start Caused by low diesel ambient temp Pump motor repaired on 810302
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 084 24X
Fiche 50-320,83/05/19,8305310001

--8305310056 Updated LER 81-008/03X-1 on 810416,diesel driven fire pump failed to start Caused by failed battery Diesel switched to B bank.Preventive maint procedure written to replace fire svc diesel batteries A & B every 5 yrs
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 087 24X
Fiche.50-320,83/05/19,8305310001

--8305310061 Updated LER 81-010/01X-1 on 810420,shift & daily check logsheet not consistent w/recovery Tech Specs in that seven instruments received daily rather than per shift checks Caused by errors in procedure logsheet Procedure revised
SWARTZWELDER,R General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 3pp 18653,089 24X
Fiche 50-320,83/05/19,8305310001

--8305310066 Updated LER 81-012/03X-1 on 810422,emergency diesel generator A failed to develop output voltage Caused by corrosion & pitting of relay contacts Relay replaced Surveillance Procedure 4603-R1 revised
CHAPLIN,S D. General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director. 3pp 18653 092 24X
Fiche.50-320,83/05/19,8305310001

--8305310072 Updated LER 81-020/03X-1 on 810830,fuel handling bldg ventilation sys inoperable due to high pressure differential & low exhaust flow rate.Caused by excessive loading of prefilters & first bank HEPA filters
CHAPLIN,S D General Public Utilities - GPU Service Corp.
83/05/19 Region 1, Office of Director 3pp. 18653 095 24X
Fiche 50-320,83/05/19,8305310001

--8305310078 Updated LER 81-022/03X-1.on 810909,channel calibr of gas partitioner performed past scheduled expiration date Caused by heavy manpower loads in conducting Unit 1 hot functional tests Instrument calibr
SWARTZWELDER,R General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp. 18653 097 24X
Fiche 50-320,83/05/19,8305310001.

--8305310080 Updated LER 81-023/03X-1 on 810911,control bldg charcoal filters lab tested to acceptance criteria of 95% rather than 99%,as required Caused by misinterpretation of Reg Guide 1.52.New filters Installed.
SWARTZWELDER,R. General Public Utilities - GPU Service Corp
83/05/19. Region 1, Office of Director. 2pp 18653 099 24X
Fiche 50-320,83/05/19,8305310001

--8305310087 Updated LER 81-032/03X-1 on 811105,while reviewing operating records,discovered that exhaust flow fell below Tech Specs min on 811028 Caused by low auxiliary bldg supply flow rate & problems w/design & operation of supply damper
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 3pp 18653 101 24X
Fiche 50-320,83/05/19,8305310001

--8305310091 Updated LER 81-034/01X-1 on 811201,in-core thermocouple F-12 inoperable Caused by polarity of thermocouple being reversed Procedures revised to prevent future occurrence
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 3pp 18653 104 24X
Fiche 50-320,83/05/19,8305310001

--8305310096 Updated LER 81-035/03X-1 on 811201,wind direction monitoring instrument inoperable Caused by ice formation on instrument Instrument deiced & permanent weather station heater jacket installed
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 107 24X
Fiche 50-320,83/05/19,8305310001

--8305310101 Updated LER 81-036/03X-1 on 811214,wind direction monitoring instrument inoperable Caused by ice formation on instrument Instrument deiced & permanent weather station heater jacket installed on instrument
CHAPLIN,S D General Public Utilities - GPU Service Corp.
83/05/19 Region 1, Office of Director 2pp 18653 109 24X
Fiche 50-320,83/05/19,8305310001

--8305310107 Updated LER 81-038/03X-1 on 811228,wind direction & wind speed monitoring instruments inoperable Caused by ice formation on instruments Instruments heat traced as temporary measure
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 111 24X
Fiche 50-320,83/05/19,8305310001

--8305310114 Updated LER 82-034/01X-1 on 821021,once-through steam generator A level indication failed Caused by separated electrical connector,failed power supply & inadequate procedure Valves opened & level indicators repaired
CHAPLIN,S D General Public Utilities - GPU Service Corp
83/05/19 Region 1, Office of Director 2pp 18653 113 24X
Fiche 50-320,83/05/19,8305310001

T Hearing transcripts on non-antitrust matters

8305040086 Transcript of 830422 briefing in Washington,DC re TMI-2 cleanup Pp 1-98
* Commissioners 83/04/22 124pp 18328 242 24X
Fiche 50-320,83/04/22,8305040086

8305120312 Forwards transcripts,including corrections,re investigation by EH Stier of allegations by GPU & Bechtel
KANGA,B K General Public Utilities - GPU Service Corp 83/05/06
BARRETT,L H TMI Program Office 1p 18433 241 24X
Fiche 50-320,83/05/06,8305120312

--8305120317 Testimony of JC Auger re investigation of allegations by GPU & Bechtel Pp 1-13
AUGER,J C General Public Utilities - GPU Service Corp 83/03/31
13pp 18433 242 24X Fiche 50-320,83/05/06,8305120312

--8305120323 Testimony of JJ Chwastyk re investigation of allegations by GPU & Bechtel Pp 1-16
CHWASTYK,J J General Public Utilities - GPU Service Corp
83/03/31 16pp 18433 257 24X Fiche 50-320,83/05/06,8305120312

--8305120326 Testimony of R Gummo re investigation of allegations by GPU & Bechtel Pp 1-12
GUMMO,R General Public Utilities - GPU Service Corp 83/04/06
14pp 18433 275. 24X Fiche: 50-320,83/05/06,8305120312

--8305120330 Testimony of EJ Kitler re investigation of allegations by GPU & Bechtel Pp 1-7
KITLER,E J Bechtel Corp 83/04/06 9pp 18433 289 24X
Fiche 50-320,83/05/06,8305120312

--8305120335 Testimony of QA Kunder re investigation of allegations by GPU & Bechtel Pp 1-15.
KUNDER,G A General Public Utilities - GPU Service Corp
83/04/13 18pp. 18433 298 24X Fiche 50-320,83/05/06,8305120312

--8305120338 Testimony of WJ Marshall re investigation of allegations by GPU & Bechtel Pp 1-14
MARSHALL,W J General Public Utilities - GPU Service Corp
83/04/06 16pp 18433 316 24X Fiche 50-320,83/05/06,8305120312.

--8305120341 Testimony of JF Perry re investigation of allegations by GPU & Bechtel Pp 1-14
PERRY J F General Public Utilities - GPU Service Corp 83/04/06 16pp 18433 332 24X Fiche 50-320,83 05/06,8305120312

--8305120344 Testimony of RF Ryan re investigation of allegations by GPU & Bechtel Pp 1-4
RYAN,R F Babcock & Wilcox Co 83/04/06 6pp 18433 348 24X Fiche 50-320,83/05/06,8305120312

--8305120347 Testimony of LC Rogers re investigation of allegations by GPU & Bechtel Pp 1-8
ROGERS,L C Babcock & Wilcox Co 83/01 01 9pp 18433 354 24X Fiche 50-320,83/05/06,8305120312

--8305120350 Testimony of DG Smith re investigation of allegations by GPU & Bechtel Pp 1-5
SMITH,D G General Public Utilities - GPU Service Corp 83/04/06 7pp 18433 363 24X Fiche 50-320,83/05/06,8305120312

--8305120355 Testimony of JA Smith re investigation of allegations by GPU & Bechtel Pp 1-15
SMITH,J A Gilbert/Commonwealth Cos 83/03/31 17pp 18434 007 24X Fiche 50-320,83/05/06,8305120312

--8305120357 Testimony of RP Warren re investigation of allegations by GPU & Bechtel Pp 1-10
WARREN,R P General Public Utilities - GPU Service Corp 83/03/31 12pp 18434 024 24X Fiche 50-320,83/05/06,8305120312

8305230189 Forwards marked-up excerpt from NRC testimony from Udall 830426 hearing on facility,consisting of Pages 69-81 Memo dtd 830506 & original excerpt also encl
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/05/17 KAMMERER,C Office of Congressional Affairs 20pp 18577 249 24X Fiche 50-320,83/05/17,8305230189

--8305230199 Forwards transcript of Commissioners statement before House Subcommittee on Energy & Environ 830426 hearing in Washington,DC Transcript should be edited & returned by 830518
KAMMERER,C Office of Congressional Affairs 83/05/06
PALLADINO,N , GILINSKY,V , AHEARNE,J F Commissioners 1p 18577 271 24X Fiche 50-320,83/05/17,8305230189

--8305230209 Transcript of Commissioners statement at House Subcommittee on Energy & Environ 830426 hearing in Washington,DC Pp 68-86
PALLADINO,N , GILINSKY,V , AHEARNE,J F Commissioners 83/04/26 18pp 18577 272 24X Fiche 50-320,83/05/17,8305230189

U Congressional/Executive Correspondence

8305040138 Forwards proposed Chairman testimony before Udall Subcommittee 830406 hearing re developments since Apr 1982 at TMI,responding to items in Congressman Udall 830413 ltr W/o proposed testimony
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/20 DIRCKS,W J Office of the Executive Director for Operations 2pp 18327 011 24X Fiche 50-289,83/04/20,8305040138

--8305040145 Enumerates items to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982
UDALL,M K House of Rep , Interior & Insular Affairs 83/04/13
PALLADINO,N Commissioners 2pp 18327 013 24X
Fiche 50-289,83/04/20,8305040138

8305230435 Forwards response to Question 20 in 830223 ltr re NRC review of B&W/GPU trial record
PALLADINO,N J Commissioners 83/04/28 UDALL,M K House of Rep , Interior & Insular Affairs 2pp 18542 051 24X
Fiche 50-289,83/04/28,8305230435

--8305230440 Informs of dissenting opinion re Commission majority decision blocking General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Decision will hamper ability of individual Commissioners to obtain needed info
GILINSKY,V Commissioners 83/04/07 SIMPSON,A K Senate, Environment & Public Works 2pp 18542 053 24X
Fiche 50-289,83/04/28,8305230435

--8305230443 Responds to Chairman Palladino 830309 request for views on legality of Commission decision directing Executive Director for Operations,rather than Ofc of General Counsel, to review B&W/GPU trial record Actions supported
PLAINE,H H E Office of the General Counsel 83/03/25
PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 5pp 18542 055 24X Fiche 50-289,83/04/28,8305230435

--8305230446 Provides Commission response to Commissioner Gilinsky 830407 ltr disagreeing w/Commission majority decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Commission actions justified
PALLADINO,N J Commissioners 83/04/19 UDALL,M K House of Rep , Interior & Insular Affairs 4pp 18542 060 24X
Fiche 50-289,83/04/28,8305230435

--8305230453 Disagrees w/Commission majority views in Chairman Palladino 830419 ltr justifying Commission decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding
ASSELSTINE,J K Commissioners 83/04/25 UDALL,M K House of Rep , Interior & Insular Affairs 3pp 18542 064 24X
Fiche 50-289,83/04/28,8305230435

V Operator Examinations

8305120055 Forwards Training Procedure 6210-ADM-2604 01,Rev 1-00, "Control of Exams for Units 1 & 2," & Procedure 6210-ADM-2610 02,Rev 1-00, "Operator Training Instructor Indoctrination/Qualification Training Program "
HUKILL,H D General Public Utilities - GPU Service Corp 83/05/06
STOLZ,J F Operating Reactors Branch 4 1p 18428 233 24X
Fiche 50-289,83/05/06,8305120055

--8305120064 Rev 1-00 to Training Procedure 6210-ADM-2604 01, "Control of Exams for Units 1 & 2 "
* General Public Utilities - GPU Service Corp 83/04/26 7pp 18428 234 24X Fiche 50-289,83/05/06,8305120055

DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305030685 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18309 141 24X Fiche 50-321,83/04/25, 8305030685

--8305030687 Forwards public version of revised emergency plan implementing procedures,including Procedures HNP-4734 re general emergency - Savannah River Operations Ofc & HNP-4527 re alert - security force
NIX,H C Georgia Power Co 83/04/07 Office of Nuclear Reactor Regulation, Director 1p 18309 142 24X Fiche 50-321,83/04/25, 8305030685

--8305030690 Public version of revised emergency plan implementing procedures,including Procedures HNP-4734 re general emergency - Savannah River Operations & HNP-4527 re alert - security force
ROGERS,W H , NIX,H Georgia Power Co 83/04/04 50pp 18309 143 24X Fiche 50-321,83/04/25,8305030685

8305040648 Releases public version of revised pages to emergency plan
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18336 275 24X Fiche 50-321,83/04/25, 8305040648

--8305040654 Forwards public version of revised Pages C-3 & P-1 to emergency plan
OLLINGER,W H Georgia Power Co 83/03/31 NRC - No Detailed Affiliation Given 1p 18336 276 24X Fiche 50-321,83/04/25, 8305040648

--8305040659 Public version of revised Pages C-3 & P-1 to emergency plan
* Georgia Power Co 83/02/28 2pp 18336 277 24X
Fiche 50-321,83/04/25,8305040648

8305060469 Clarifies requests for exemptions from 10CFR50 48 & App R requirements in response to NRC request at 830330 meeting Rev to 820701 response to be submitted by 830530
GUCWA,L T Georgia Power Co 83/04/28 STOLZ,J F Operating Reactors Branch 4 11pp 18351 179 24X Fiche 50-321,83/04/28, 8305060469

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305250530 Submits info on compliance w/Branch Technical Position 9 5-1 re qualification of fire protection engineers Qualification requirements met through maint of staff at affiliated svc company, Southern Co Svcs, Inc
GUCWA, L T Georgia Power Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18588 229 24X Fiche 50-321, 83/05/19, 8305250530

H General correspondence

8305030261 Requests changes in correspondence routines due to recent mgt changes
GUCWA, L T Georgia Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18300 046 24X Fiche 50-000, 83/04/28, 8305030261

J Insurance & indemnity information

8305040202 Forwards Endorsement 78 to NELIA Policy NF-215 & Endorsement 63 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18324 028 24X Fiche 50-321, 83/04/28, 8305040202

8305200270 Forwards Endorsement 79 to NELIA Policy NF-215 & Endorsement 64 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc 83/05/16 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18516 256 24X Fiche 50-321, 83/05/16, 8305200270

8305230027 Forwards Endorsement 80 to NELIA Policy NF-215 & Endorsement 66 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc 83/05/16 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18539 160 24X Fiche 50-321, 83/05/16, 8305230027

P Operating license stage documents & correspondence

8304120027 Forwards revised order confirming licensee commitments on post-TMI-related issues, correcting info re implementation schedule for Item II B 3, "Post-Accident Sampling "
STOLZ, J F Operating Reactors Branch 4 83/03/30 BECKHAM, J T Georgia Power Co 4pp 17957 320 24X Fiche 50-321, 83/03/30, 8304120027

--8304120042 Order revising schedule for submittal of info re Item II B 3, "Post-Accident Sampling," from 830401 to 830701
PURPLE, R A Division of Licensing 83/03/30 Georgia Power Co 10pp 17957 324 24X Fiche 50-321, 83/03/30, 8304120027

8305040769 Forwards safety evaluation & technical evaluation rept re TMI Items I A 2 1 4 "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4 "Training for Mitigating Core Damage " Programs satisfy NUREG-0737 requirements
STOLZ, J F Operating Reactors Branch 4 83/04/20 BECKHAM, J T Georgia Power Co 3pp 18327 300 24X Fiche 50-321, 83/04/20, 8305040769

--8207080458 "Improvements in Training & Requalification Programs as Required by TMI Action Items I A 2 1 & II B 4," technical evaluation rept
* Science Applications, Inc SAI-186-029-34 82/07/01 NRC - No Detailed Affiliation Given 14pp 18327 303 24X Fiche 50-321, 83/04/20, 8305040769

8305030634 Application to amend Licenses DPR-57 & NPF-5, revising Tech Specs re TMI Action Plan Items I A 1 1 3, I A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4
BECKHAM, J T Georgia Power Co 83/04/22 STOLZ, J F Operating Reactors Branch 4 8pp 18305 285 24X Fiche 50-321, 83/04/22, 8305030634

--8305030665 Revised Tech Specs re TMI Action Plan Items I A 1 1 3, I A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4
* Georgia Power Co 83/04/22 31pp 18305 293 24X Fiche 50-321, 83/04/22, 8305030634

8305040748 Summary of 830223-24 meetings w/util & EG&G in Atlanta, GA re proposed radiological effluent Tech Specs
RIVENBARK, G W Operating Reactors Branch 4 83/04/22 STOLZ, J F Operating Reactors Branch 4 15pp 18327 179 24X Fiche 50-321, 83/04/22, 8305040748

8305060671 Forwards EG&G 830404 ltr transmitting list of NRC comments on unresolved items from proposed radiological effluent Tech Specs Earlier scheduled date for final submittal requested
STOLZ, J F Operating Reactors Branch 4 83/04/22 BECKHAM, J T Georgia Power Co 2pp 18358 001 24X Fiche 50-321, 83/04/22, 8305060671

--8304220257 Forwards list of major radiological effluent Tech Spec items from licensee proposal that were not resolved at Atlanta meeting Differences between Unit 1 & Unit 2 proposals are minor Commitment date for next submittal not identified
SERRANO, W EG&G, Inc 83/04/04 WILLIS, C A NRC - No Detailed Affiliation Given 3pp 18358 003 24X Fiche 50-321, 83/04/22, 8305060671

8305060051 Forwards Rev 1 to "Design Rept for Recirculation Sys & RHR Sys Weld Overlay Repairs & Flaw Evaluation at EI Hatch Nuclear Power Plant, Unit 1 "
GUCWA, L T Georgia Power Co 83/04/28 STOLZ, J F Operating Reactors Branch 4 2pp 18345 226 24X Fiche 50-321, 83/04/28, 8305060051

--8305060055 Rev 1 to "Design Rept for Recirculation Sys & RHR Sys Weld Overlay Repairs & Flaw Evaluation at EI Hatch Nuclear Power Plant, Unit 1 "
CHARNLEY, J E , RICCARDELLA, P NUTECH Engineers, Inc QPC-04-104 R01 83/03/04, 100pp 18345 228 24X Fiche 50-321, 83/04/28, 8305060051

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305060306 Requests that portion of 830422 response to Generic Ltr 83-02 be withdrawn Portion re Item II F 1, "Addl Accident Monitoring Instrumentation," will be reevaluated upon receipt of NRC guidance
GUCWA, L T Georgia Power Co 83/05/02 STOLZ, J F Operating Reactors Branch 4 1p 18344 323 24X Fiche 50-321, 83/05/02, 8305060306

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche, 50-000, 83/05/09, 8305090659

8305200453 Commits to submit results of plant-unique calculations re acceptability of mod to torus vacuum breakers by 830615, in response to Generic Ltr 83-08
GUCWA, L T Georgia Power Co 83/05/16 STOLZ, J F Operating Reactors Branch 4 1p 18519 085 24X Fiche 50-321, 83/05/16, 8305200453

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270491 Ack receipt of 830328 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-02
DANCE, H C Division of Project & Resident Programs 83/04/07 KELLY, R J Georgia Power Co 1p 18646 072 24X Fiche 50-366, 83/04/07, 8305270491

--8305270523 Forwards IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/02/25 KELLY, R J Georgia Power Co 2pp 18646 075 24X Fiche 50-366, 83/04/07, 8305270491

--8305270550 IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 Noncompliance noted failure to make 24-h telephone rept within required time limit
CRLENJAK, R V , HOLMES-RAY, P Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/02/23 4pp. 18646 078. 24X Fiche 50-366, 83/04/07, 8305270491

8305270570 Requests that docket number in 830322 IE Insp Rept 50-336/83-05 be changed to 50-366/83-05 due to administrative error
DANCE, H C Division of Project & Resident Programs 83/04/08 KELLY, R J Georgia Power Co 1p 18646 113 24X Fiche 50-321, 83/04/08, 8305270570

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270332 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04
DANCE,H C Division of Project & Resident Programs 83/04/27
KELLY,R J Georgia Power Co 1p 18642 066 24X
Fiche 50-321,83/04/27,8305270332

--8305270336 Responds to NRC 830318 ltr re violations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04 Corrective actions training directive issued to appropriate personnel stressing prompt notification of unusual event
BECKHAM,J T Georgia Power Co 83/04/18 O'REILLY,J P Region 2, Office of Director 2pp 18642 067 24X Fiche 50-321, 83/04/27,8305270332

--8305270343 Forwards IE Insp Repts 50-321/83-04 & 50-366/83-04 on 830207-11 & notice of violation
DANCE,H C Division of Project & Resident Programs 83/03/18
KELLY,R J Georgia Power Co 2pp 18642 069 24X
Fiche 50-321,83/04/27,8305270332

--8305270351 Notice of violation from insp on 830207-11
* Region 2, Office of Director 83/03/18 1p 18642 071 24X
Fiche 50-321,83/04/27,8305270332

--8305270357 IE Insp Repts 50-321/83-04 & 50-366/83-04 on 830207-11 Noncompliance noted failure to make proper notification to NRC following liquid radwaste release on 821209
WRAY,J R Region 2, Office of Director BARR,K P Division of Emergency Preparedness & Materials Safety 83/03/10 7pp
18642 072 24X Fiche 50-321,83/04/27,8305270332

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160144 Submits 30-day response to SER & technical evaluation rept re environ qualification of Class IE equipment (IE Bulletin 79-01B) Final plans for resolving qualification of items in Categories I B,II A & II B will be transmitted by 830520
GUCWA,L T Georgia Power Co 83/05/06 STOLZ,J F Operating Reactors Branch 4 394pp 18444 044 24X Fiche 50-321,83/05/06, 8305160144

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305270350 Forwards IE Insp Repts 50-321/83-11 & 50-366/83-11 on 830411-15 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/11
KELLY,R J Georgia Power Co 2pp 18644 323 24X
Fiche 50-321,83/05/11,8305270350

--8305270356 IE Insp Repts 50-321/83-11 & 50-366/83-11 on 830411-15 No noncompliance noted.Major areas inspected licensee action on previous enforcement matters,QA program,design mods,test & experiments program & procurement program
BELISLE,G A , DEBBAGE,A G , UPRIGHT,C M Region 2, Office of Director 83/05/11 14pp 18644 325 24X Fiche 50-321,83/05/11, 8305270350

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche:50-000,83/05/19,8303040040

8305270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program
GUCWA,L T Georgia Power Co. 83/05/19 STOLZ,J F Operating Reactors Branch 4 1p 18638 217 24X Fiche 50-321,83/05/19, 8305270128

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305180279 Forwards monthly operating repts for Apr 1983
NIX,H C Georgia Power Co 83/05/06 Director's Office, Office of Inspection and Enforcement 1p 18490 282 24X
Fiche 50-321,83/05/06,8305180279

--8305180284 Monthly operating repts for Apr 1983
REDWANZ,F J Georgia Power Co 83/05/06 12pp 18490 295 24X
Fiche 50-321,83/05/06,8305180279

S Reportable occurrences: LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305050030 Forwards LER 83-040/03L-0
NIX,H C Georgia Power Co 83/04/21 O'REILLY,J P Region 2, Office of Director 1p 18342 092 24X Fiche 50-321,83/04/21, 8305050030

--8305050040 LER 83-040/03L-0 on 830325,reactor bldg exhaust vent A radiation monitor D11-K609A as-found data unacceptable & monitor declared inoperable Caused by instrument drift. D11-K609A calibr & returned to svc on 830325
TIPPS,S B Georgia Power Co 83/04/21 Region 2, Office of Director 3pp 18342 093 24X Fiche 50-321,83/04/21,8305050030

8305050083 Forwards updated LER 83-036/01X-1
NIX,H C Georgia Power Co 83/04/21 O'REILLY,J P. Region 2, Office of Director 1p 18342 020 24X Fiche 50-321,83/04/21, 8305050083

--8305050087 Updated LER 83-036/01X-1 on 830323,plant review board determined lack of administrative control existed in complying w/Procedure HNP-6921 because of matl condition of cable trays Caused by lack of specific instructions
TIPPS,S B Georgia Power Co 83/04/21 Region 2, Office of Director 5pp 18342 021 24X Fiche 50-321,83/04/21,8305050083

8305110269 Forwards LER 83-043/03L-0
NIX,H C Georgia Power Co 83/04/26 O'REILLY,J P Region 2, Office of Director 1p 18393 222 24X Fiche 50-321,83/04/26, 8305110269

--8305110272 LER 83-043/03L-0 on 830331,RHR svc water pump B did not reach required Tech Spec pressure Caused by air release valve for loop B failing to seat off Rubber seat & float replaced & float cage realigned
TIPPS,S B Georgia Power Co 83/04/26 Region 2, Office of Director 3pp 18393 223 24X Fiche 50-321,83/04/26,8305110269

8305110270 Forwards LER 83-044/03L-0
NIX,H C Georgia Power Co 83/04/26 O'REILLY,J P Region 2, Office of Director 1p 18393 294 24X Fiche 50-321,83/04/26, 8305110270

--8305110273 LER 83-044/03L-0 on 830404,while performing matl condition insp,sys engineer found two of four bolts not installed in valve operator mount at valve bonnet on RHR loop A min flow bypass valve Replacement bolts installed & torqued
TIPPS,S B Georgia Power Co 83/04/26 Region 2, Office of Director 3pp 18393 297 24X Fiche 50-321,83/04/26,8305110270

8305110431 Forwards LER 83-041/03L-0
NIX,H C Georgia Power Co 83/04/26 O'REILLY,J P Region 2, Office of Director 1p 18405 088 24X Fiche 50-321,83/04/26, 8305110431

--8305110434 LER 83-041/03L-0 on 830329,following Group 5 isolation, outboard reactor water cleanup isolation valve failed to open Caused by overheated D-C drive motor on valve operator Drive motor replaced
TIPPS,S B Georgia Power Co 83/04/26 Region 2, Office of Director 3pp 18405 089 24X Fiche 50-321,83/04/26,8305110431

8305110404 Forwards LER 83-042/03L-0
NIX,H C Georgia Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 1p 18392 008 24X Fiche 50-321,83/04/29, 8305110404

--8305110412 LER 83-042/03L-0 on 830330,1/2 scram received Caused by scram discharge valve high level RPS relay burning & failing in tripped condition Relay replaced & satisfactorily tested
TIPPS,S B Georgia Power Co 83/04/29 Region 2, Office of Director 3pp 18392 009 24X Fiche 50-321,83/04/29,8305110404

8305130138 PNO-II-83-032 on 830501,contractor employee suffered broken arm,fractured pelvis & possible skull fracture in machine shop accident Caused by cotton glove caught by valve stem pulling person into lathe w/contaminated valve
ROGGE,J F , DANCE,H C Region 2, Office of Director 83/05/02 2pp 18437 277 24X Fiche 50-321,83/05/02,8305130138

8305170178 Supplemental narrative summary to Rev 5 to RO 50-321/1979-021 Updated data on tritium levels in groundwater samples during First Quarter 1983 encl No radionuclides above background identified
NIX,H C Georgia Power Co 83/05/02 O'REILLY,J P Region 2, Office of Director 3pp 18466 321 24X Fiche 50-321,83/05/02, 8305170178

8305110289 Forwards LER 83-046/03L-0
NIX,H C Georgia Power Co 83/05/03 O'REILLY,J P Region 2, Office of Director 1p 18393 308 24X Fiche 50-321,83/05/03, 8305110289

--8305110293 LER 83-046/03L-0 on 830411,channel A torus water level narrow range recorder T48-R607A,operated erractically Caused by dirty control amplifier plug connection Connection cleaned Procedure HNP-1-5372 run successfully
TIPPS,S B Georgia Power Co 83/05/03 Region 2, Office of Director 3pp 18393 309 24X Fiche 50-321,83/05/03,8305110289

8305170254 Forwards LER 83-031/03L-0
NIX,H C Georgia Power Co 83/05/05 O'REILLY,J P Region 2, Office of Director 1p 18466 130 24X Fiche 50-321,83/05/05, 8305170254

--8305170262 LER 83-031/03L-0 on 830409,dioxide recorder pen on primary containment atmosphere hydrogen dioxide recorder 1P33-R601A read downscale & primary containment atmosphere sample sys outlet pumps found not running Caused by component failure.
TIPPS,S B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp 18466 131 24X Fiche 50-321,83/05/05,8305170254

8305170434 Forwards LER 83-034/03L-0
NIX,H C Georgia Power Co 83/05/05 O'REILLY,J P Region 2, Office of Director 1p 18469 297 24X Fiche 50-321,83/05/05, 8305170434

--8305170438 LER 83-034/03L-0 on 830407,control room air intake isolation valve 1241-F011 closed late during Procedure HNP-1-3973 Caused by faulty operator & lack of damper shaft lubrication Shafts lubricated
TIPPS,S B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp 18469 298 24X Fiche 50-321,83/05/05,8305170434

8305170442 Forwards updated LER 83-036/01X-2
NIX,H C Georgia Power Co 83/05/05 O'REILLY,J P Region 2, Office of Director 1p 18471 230 24X Fiche 50-321,83/05/05, 8305170442

--8305170445 Updated LER 83-036/01X-2 on 830320,22,23 & 0405,matl condition of cable trays found out of compliance w/Procedure HNP-6921 Caused by lack of administrative control & nonspecific procedure instructions Procedure revised
SUMNER,H L Georgia Power Co 83/05/05 Region 2, Office of Director 6pp 18471 231 24X Fiche 50-321,83/05/05,8305170442

8305110364 RO 50-366/83-01 on 830125 & 0314,Units 2 & 1,respectively, had spray/sprinkler sys taken out of svc for mods & could not be restored to operable status within 14 days per Tech Specs Continuous fire watches maintained
NIX,H C Georgia Power Co 83/05/06 O'REILLY,J P Region 2, Office of Director 3pp 18406 262 24X Fiche 50-321,83/05/06, 8305110364

8305230568 Forwards LER 83-047/03L-0
NIX,H C Georgia Power Co 83/05/09 O'REILLY,J P Region 2, Office of Director 1p 18537 305 24X Fiche,50-321,83/05/09, 8305230568

--8305230577 LER 83-047/03L-0 on 830412,02 recorder pens on primary containment atmosphere H202 recorders 1P33-R601A & R601B read 17% & 3 35%,respectively Caused by tubing cap missing & open sample valve in analyzer sample line A Cap replaced.
TIPPS,S B Georgia Power Co 83/05/09 Region 2, Office of Director 3pp 18537 306 24X Fiche 50-321,83/05/09,8305230568

8305270234 Updated LER 83-036/01X-3 on 830320,lack of administrative control existed in complying w/cable & cable tray installation Procedure HNP-6921 because of matl condition of cable trays Caused by inadequate procedures W/830516 ltr
TIPPS,S B , NIX,H C Georgia Power Co 83/05/16 O'REILLY,J P Region 2, Office of Director 9pp 18637 186 24X Fiche 50-321,83/05/16,8305270234

8305310166 LER 83-045/03L-0 on 830423,while performing MSIV trip test, D outboard MSIV (1B21-F028D) found to close slower than Tech Spec limit Caused by maladjusted actuator flow control needle valve W/830516 ltr
TIPPS,S B , NIX,H C Georgia Power Co 83/05/16 O'REILLY,J P Region 2, Office of Director 4pp 18652 335 24X Fiche 50-321,83/05/16,8305310166

8305310180 Updated LER 83-040/03X-1,on 830325,reactor bldg exhaust vent radiation monitors D11-K609A & B found inoperable Caused by instrument drift & cable failure between detector & trip unit Monitor calibr W/830516 ltr
TIPPS,S B , NIX,H C Georgia Power Co 83/05/16 O'REILLY,J P Region 2, Office of Director 5pp 18659 135 24X Fiche 50-321,83/05/16,8305310180

8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration
HAISLER,R K Litton Industries,Inc 83/05/20 KEPPLER,J G Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20, 8305270625

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

A Application/construction stage documents & correspondence

8305060144 Responds to FOIA Requests 82-455,82-471 & 82-479 re suppression pool dynamic loads Encls to Documents 3 & 4 & rept encl w/Document 7 withheld (ref FOIA Exemption 4)
FELTON,J M Division of Rules and Records 83/03/17 HAFNER,B Affiliation Unknown 2pp 18364 261 24X Fiche 50-322,83/03/17, 8305060144

--8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vent clearing & steam quenching phenomena Schedule coordinated w/GE & other utils
WOFFORD, A W Long Island Lighting Co 75/06/03 STOLZ, J F Light Water Reactors Branch 1 4pp 18364 266 24X
Fiche 50-322, 83/03/17, 8305060144

--8305060155 Requests addl info re suppression pool temp limit Responses to Questions 1, 2, 4 & 5 will be provided by GE Question 3 must be answered by util
KNIEL, K Light Water Reactors Branch 2 77/08/31 WOFFORD, A W Long Island Lighting Co 2pp 18364 283 24X
Fiche 50-322, 83/03/17, 8305060144

--8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to Questions 1, 2, 4 & 5 Submittal date for response to Question 3 will be provided
BURKE, T J Long Island Lighting Co 77/09/26 KNIEL, K Light Water Reactors Branch 2 1p 18364 287 24X
Fiche 50-322, 83/03/17, 8305060144

8305160095 Corrects serial number of 830415 ltr transmitting Rev 3 to inservice testing program Correct identifier should be SNRC-857, not SNRC-859.
SMITH, J L Long Island Lighting Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18450 351 24X
Fiche 50-322, 83/05/03, 8305160095

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305240342 Forwards minutes of 830421 meeting w/util & S&W re clarification of addl items in independent design review
KING, J P Teledyne Engineering Services 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18571 001 24X Fiche 50-322, 83/05/06, 8305240342

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305190491 Notification of 830524 meeting w/Suffolk County representatives in Bethesda, MD to discuss extension of CP
CARUSO, R Licensing Branch 2 83/05/16 SCHWENCER, A Licensing Branch 2 4pp 18523 159. 24X Fiche 50-322, 83/09/16, 8305190491

8305240447 Provides status of implementation of SER recommendations re NUREG-0737, Item II K 3 16, "Feasability Study - Challenges & Valve Failures " Preventive maint program will be available for site review in 2 months
SMITH, J L Long Island Lighting Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18572 338 24X
Fiche 50-322, 83/05/20, 8305240447

8305270001 Forwards final classification of ICR 5633-18 re pipe support design calculations from independent design review Item closed
LANDERS, D F Teledyne Engineering Services 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18638 327 24X Fiche 50-322, 83/05/20, 8305270001

8305250373 Forwards Teledyne Engineering Svcs 830506 ltr to HR Denton w/attachment re independent design verification program
BORDENICK, B M Hearing Branch 3 83/05/24 BRENNER, L ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 7pp 18592 093 24X Fiche 50-322, 83/05/24, 8305250373

8305310050 Responds to 830324 ltr re environ qualification of GE switches (Type CR 2940). List of switch locations & summary of generic environ qualification testing encl Switch failure would not adversely affect shutdown capability
SMITH, J L Long Island Lighting Co 83/05/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 12pp 18653 152 24X
Fiche 50-322, 83/05/25, 8305310050

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305040508 Forwards Rev 2 to "4160V Metal Encl Switchgear - General Maint," providing description of inservice insp & testing programs to assure seismic integrity of electrical & mechanical components (SER Issue 8)
SMITH, J L Long Island Lighting Co 83/04/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 9pp 18321 023 24X
Fiche 50-322, 83/04/22, 8305040508

--8305040514 Rev 2 to Procedure 32 050 02, "4160V Metal Encl Switchgear - General Maint "
ROSE, J J Long Island Lighting Co 83/01/31 6pp 18322 032 24X Fiche 50-322, 83/04/22, 8305040508

8305040303 Forwards monthly status of equipment summary list including balance-of-plant & NSSS equipment to assist in review of SER Issue 8 on dynamic qualification, per 821110 & 23 ltrs
SMITH, J L Long Island Lighting Co 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 18323 306 24X
Fiche 50-322, 83/04/29, 8305040303

8305160070 Responds to SER Issue 48, "High Energy Line Breaks (HELB)" & 830124 request to consider addl single failure within sys used to mitigate event Postulated worst-case scenarios listed Occurrence of events unlikely Issue closed
SMITH, J L Long Island Lighting Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18450 116 24X
Fiche 50-322, 83/05/11, 8305160070

8305270013 Forwards monthly status list of active safety-related equipment per SER Issue 8 re dynamic qualification level
SMITH, J L Long Island Lighting Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 52pp 18633 277 24X
Fiche 50-322, 83/05/23, 8305270013

F Security, medical, emergency & fire protection plans

8305120378 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18
MARTIN, T T Division of Engineering & Technical Programs 83/05/05 POLLOCK, M S Long Island Lighting Co 1p 18432 303 24X
Fiche 50-322, 83/05/05, 8305120378

--8305120380 Responds to NRC 820930 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18 Corrective actions permanent responsibility for emergency planning assigned to emergency planning coordinator
POLLOCK, M S Long Island Lighting Co 83/04/21 MARTIN, T T Division of Engineering & Technical Programs 12pp 18432 304 24X Fiche 50-322, 83/05/05, 8305120378

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

O Adjudicatory correspondence

8305100223 Forwards Teledyne Engineering Svcs 830311 ltr transmitting latest classification of items from independent design review of facility
BORDENICK, B M Hearing Branch 3 83/03/18 BRENNER, L ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18374 068. 24X Fiche 50-322, 83/03/18, 8305100223

8305100255 Forwards Teledyne Engineering Svcs 830315 ltr transmitting latest classification of items from independent design review of facility
BORDENICK, B M Hearing Branch 3 83/03/21 BRENNER, L ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18373 298 24X Fiche 50-322, 83/03/21, 8305100255

8305100238 Forwards resolution of Suffolk County Contention 13(d) re util failure to provide sufficient QA/QC personnel during operation of facility Approval requested
BORDENICK, B M Hearing Branch 3 83/04/01 BRENNER, L ,
CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 2pp 18373 271 24X Fiche 50-322, 83/04/01, 8305100238

--8305100239 Resolution of Suffolk County Contention 13(d) re util failure to provide sufficient QA/QC personnel during operation Util will prepare detailed projection of QA staff requirements for 12-month period Contention withdrawn
BORDENICK, B M Hearing Branch 3 EARLEY, A F Long Island Lighting Co * Suffolk County, NY 83/03/31 Atomic Safety and Licensing Board Panel 6pp 18373 273 24X
Fiche 50-322, 83/04/01, 8305100239

8305100222 Second proposed opinion, findings of fact & conclusions of law in form of partial initial decision re DL application concerning QA/QC & environ qualification
BORDENICK, B M , REPKA, D A Hearing Branch 3 83/04/18 Atomic Safety and Licensing Board Panel 119pp 18373 144 24X
Fiche 50-322, 83/04/18, 8305100222

8305030560 Reply to Suffolk County & NRC proposed QA/QC & environ qualification opinions, findings & conclusions
* Long Island Lighting Co * Hunton & Williams 83/04/25 294pp 18301 001 24X Fiche 50-322, 83/04/25, 8305030560

8305020390 Memorandum & order providing for further filings on Suffolk County motion to reopen record on Contention 11 ASLB will rule on motion to reopen as part of initial decision on merits of Contention 11
BRENNER, L Atomic Safety and Licensing Board Panel 83/04/28 6pp 18276 319 24X Fiche 50-322, 83/04/28, 8305020390

8305030557 Forwards proposed stipulation re Suffolk County Contention 13(a) on QA/QC operations Util & Suffolk County agreed to stipulation NRC review incomplete but no objections anticipated
EARLEY, A F Hunton & Williams 83/04/28 BRENNER, L Atomic Safety and Licensing Board Panel 6pp 18305 278 24X
Fiche 50-322, 83/04/28, 8305030557

8305100196 Response in opposition to Suffolk County 830408 motion to compel applicant to file written rept re Teledyne Engineering Svcs design review of facility Interim meetings could result in duplicative efforts Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/04/28 Atomic Safety and Licensing Board Panel 7pp 18374 304 24X Fiche 50-322, 83/04/28, 8305100196

8305100398 Forwards Teledyne Engineering Svcs 830406 ltr transmitting summary of 830330 meeting re classification of Item ICR 5633-1 concerning piping attached to horizontal beams from independent design review of facility
BORDENICK, B M Hearing Branch 3 83/04/28 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18378 001 24X Fiche 50-322, 83/04/28, 8305100398

8305040461 Advises that util will serve alternative means for implementing offsite emergency plan during wk of 830516 Related correspondence
CHRISTMAN, J N Hunton & Williams CHRISTMAN, J N Long Island Lighting Co 83/04/29 BRENNER, L , CARPENTER, J H , MORRIS, P A Atomic Safety and Licensing Board Panel 1p 18322 144 24X
Fiche 50-322, 83/04/29, 8305040461

8305030488 Advises of LILCO application for renewal of License 31-17432-01 Application prepared per Reg Guide 10 5 Certificate of Svc encl
BORDENICK, B M Hearing Branch 3 83/05/02 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18294 160 24X Fiche 50-322, 83/05/02, 8305030488

8305050001 Motion for revised schedule re contentions Three-wk time limit for submission of contentions should be deleted Parties directed to meet within 2 wks of receipt of util revised plan to agree on schedule for contention submission
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/02 Atomic Safety and Licensing Board Panel 7pp. 18339 063 24X
Fiche 50-322, 83/05/02, 8305050001

--8305050005 Withdrawal of 830408 motion to compel util to file written rept re Teledyne Engineering Svc design review During 830422 telcon, util & NRC disclosed most info requested in motion Alternative relief requested Certificate of Svc encl
DYNNER, A. R. Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/02 Atomic Safety and Licensing Board Panel 13pp 18339 070 24X
Fiche. 50-322, 83/05/02, 8305050001

8305050007 Motion for leave to file new contention re emergency diesel generators, ASLB not required to balance lateness factors Certificate of Svc encl
MILLER, M S Suffolk County, NV MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/02 Atomic Safety and Licensing Board Panel. 17pp 18339 001 24X Fiche 50-322, 83/05/02, 8305050007

8305050024 Supplemental proposed transcript corrections Certificate of Svc encl
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02 5pp 18340 001 24X Fiche 50-322, 83/05/02, 8305050024

--8305050029 Revised proposed opinion, findings of fact & conclusions of law in form of partial initial decision
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02 367pp 18340 006 24X Fiche 50-322, 83/05/02, 8305050024

8305040429 Corrections to ASLB 830420 Memorandum & Order LBP-83-22, denying Suffolk County motion to terminate OL proceeding
BRENNER, L Atomic Safety and Licensing Board Panel 83/05/03 2pp 18322 126 24X Fiche 50-322, 83/05/03, 8305040429

8305060459 Memorandum & order ack Suffolk County 830502 withdrawal of motion to compel util to file written rept re Teledyne Engineering Svc design review Motion for util & NRC to provide info on review denied as overly broad
BRENNER, L Atomic Safety and Licensing Board Panel 83/05/04 Suffolk County, NY 4pp 18351 194 24X Fiche 50-322, 83/05/04, 8305060459

8305060518 Motion for expeditious Commission ruling on issues transferred from ASLAB re emergency planning Suffolk County motion to terminate OL proceeding is threshold issue pervading all aspects of proceeding W/Certificate of Svc
BROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/04 Commissioners 18pp 18351 009 24X Fiche 50-322, 83/05/04, 8305060518

8305100391 Forwards updated Apps B & E to util 830117 proposed partial initial decision Schedule for completion of plant continues to indicate physical readiness to load fuel by Aug 1983
REVELEY, W T Hunton & Williams 83/05/04 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 105pp 18378 091 24X Fiche 50-322, 83/05/04, 8305100391

8305090129 Forwards executed stipulation re Suffolk County Contention 13(a) on QA/QC operation Parties intend to submit addendum to stipulation
BORDENICK, B M Hearing Branch 3 83/05/05 BRENNER, L Atomic Safety and Licensing Board Panel 1p 18363 350 24X
Fiche 50-322, 83/05/05, 8305090129

--8305090136 Stipulation resolving Suffolk County Contention 13(a) re QA/QC operations
BORDENICK, B M Hearing Branch 3 EARLEY, A F Long Island Lighting Co DYNNER, A R Suffolk County, NY 83/05/05 5pp 18363 351 24X Fiche 50-322, 83/05/05, 8305090129

8305090505 Order confirming 1-wk extension of schedule to file contentions following receipt of revised emergency plan
BRENNER, L Atomic Safety and Licensing Board Panel 83/05/05 2pp 18362 012 24X Fiche 50-322, 83/05/05, 8305090505

8305100157 Response to ASLB 830428 memorandum & order providing for further filings on Suffolk County motion to reopen record on Contention 11 Applicant response insufficient to address full scope of concern Certificate of Svc encl
LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/05 Atomic Safety and Licensing Board Panel 17pp 18374 235 24X
Fiche 50-322, 83/05/05, 8305100157

8305100256 Protests exclusion of North Shore Committee (NSC) from hastily convened 830504 conference call to hear ASLB decision on Suffolk County 830502 motion for rev of schedule Certificate of Svc encl
SHAPIRO, R Cammer & Shapiro 83/05/05 BRENNER, L , MORRIS, P A , CARPENTER, J H Atomic Safety and Licensing Board Panel 3pp 18374 059 24X Fiche 50-322, 83/05/05, 8305100256

8305100274 Supports Suffolk County 830502 motion for schedule rev Limited resources available to County emphasizes desirability of County proposal Interchange between parties clarify concerns & focus contentions when filed.
SHAPIRO, R Cammer & Shapiro 83/05/05 BRENNER, L , MORRIS, P A , CARPENTER, J H Atomic Safety and Licensing Board Panel 1p 18371 241 24X Fiche 50-322, 83/05/05, 8305100274

8305100380 Forwards 830421 ltr & attachments from Teledyne Engineering Svcs to NRC re independent design update program for facility Certificate of Svc encl
BORDENICK, B M Office of the Executive Legal Director 83/05/05 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp 18379 050 24X Fiche 50-322, 83/05/05, 8305100380

8305100201 Objects to ASLAB exclusion of Town of Southampton, NY from 830504 conference call re offsite emergency planning Town of Southampton will hold comments on offsite emergency planning until receipt of new util plan Certificate of Svc encl
LATHAM, S D Twomey, Latham & Shea 83/05/06 BRENNER, L Atomic Safety and Licensing Board Panel 6pp 18374 029 24X
Fiche 50-322, 83/05/06, 8305100201

8305100224 Forwards Teledyne Engineering Svcs 830419 ltr requesting verification of receipt of controlled documents re independent design review of facility
BORDENICK, B M Hearing Branch 3 83/05/06 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
4pp 18374 134 24X Fiche 50-322, 83/05/06, 8305100224

--8305100225 Forwards transmittal forms indicating that NRC confirmation for receipt of controlled documents re independent design review of facility not yet received Verification of receipt requested
KEATING, L A Teledyne Engineering Services 83/04/19
DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp
18374 138 24X Fiche 50-322, 83/05/06, 8305100224

8305120297 Forwards revised proposed opinion, supplemental proposed findings of fact, revised findings of fact & conclusions of law in form of partial initial decision on Suffolk County/ Shoreham Opponents Coalition Contention 7B
LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
LETSCHE, K J Suffolk County, NY 83/05/09 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
3pp 18430 178 24X Fiche 50-322, 83/05/09, 8305120297

--8305120300 Revised proposed opinion, supplemental proposed findings of fact, revised findings of fact & conclusions of law in form of partial initial decision on Suffolk County/Shoreham Opponents Coalition Contention 7B W/Certificate of Svc
BROWN, H H Suffolk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/09 202pp 18430 181 24X
Fiche 50-322, 83/05/09, 8305120297

8305120329 Forwards corrected Page 59 to Suffolk County revised opinion
LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
LETSCHE, K J Suffolk County, NY 83/05/09 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
1p 18431 315 24X Fiche 50-322, 83/05/09, 8305120329

--8305120332 Corrected Page 59 to Suffolk County revised opinion
* Suffolk County, NY 83/05/09 1p 18431 316 24X
Fiche 50-322, 83/05/09, 8305120329

8305130069 Addendum to 830502 motion for leave to file new contention re emergency diesel generators clarifying Suffolk County views on reopening of evidentiary record Petition to reopen record not required Certificate of Svc encl
MILLER, M S Suffolk County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/10 Atomic Safety and Licensing Board Panel 5pp 18436 246 24X Fiche 50-322, 83/05/10, 8305130069

8305130072 Expresses indignation at ASLB failure to include author in 830505 telephone conference w/ASLB, util, Suffolk County & NRC Shoreham Opponents Coalition full-fledged participant in proceeding & should be included in future discussions
DOUGHERTY, J B Dougherty, J B DOUGHERTY, J B Shoreham Opponents Coalition 83/05/10 BRENNER, L Atomic Safety and Licensing Board Panel 1p 18437 052 24X Fiche 50-322, 83/05/10, 8305130072

8305130077 Repts that filing of util alternate means for implementing offsite emergency planning will be unavoidably delayed until wk of 830523
CHRISTMAN, J N Hunton & Williams CHRISTMAN, J N Long Island Lighting Co 83/05/10 BRENNER, L , CARPENTER, J H , MORRIS, P A Atomic Safety and Licensing Board Panel 1p 18436 263 24X
Fiche 50-322, 83/05/10, 8305130077

8305130090 Designates WJ Dircks as NRC representative on State of NY fact finding panel on facility
PALLADINO, N J Commissioners 83/05/10 CUOMO, M M New York, State of 1p 18437 006 24X Fiche 50-322, 83/05/10, 8305130090

--8305130204 Requests designation of appropriate NRC representative to State of NY fact finding panel on facility
CUOMO, M M New York, State of 83/04/22 PALLADINO, N J Commissioners 1p 18437 007 24X Fiche 50-322, 83/05/10, 8305130090

8305130050 Notice of ASLB constitution JA Laurenson, chairman & JR Kline & MB Livingston, members.
COTTER, B P Atomic Safety and Licensing Board Panel 83/05/11
2pp 18436 210 24X Fiche 50-322, 83/05/11, 8305130050

8305130068 Memorandum & Order CLI-83-13 accepting ASLAB 830426 referral of ASLB 830426 order referring ASLB 830420 order denying Suffolk County motion to terminate proceeding NRC obliged to consider util plan in absence of state/local plans
CHILK, S J Office of the Secretary of the Commission 83/05/12
6pp 18436 298 24X Fiche 50-322, 83/05/12, 8305130068

8305160006 Answer to Suffolk County 830504 motion for expeditious Commission ruling on issues transferred from ASLAP Motion should be denied except for request for briefing of certified question Certificate of Svc encl
CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams 83/05/12 Commissioners 17pp 18456 062 24X
Fiche 50-322, 83/05/12, 8305160006

8305160131 Order directing change of svc on emergency planning submissions
LAURENSON, J A Atomic Safety and Licensing Board Panel 83/05/12
1p 18448 141 24X Fiche 50-322, 83/05/12, 8305160131

8305170545 Forwards revised NRC proposed opinion, findings of fact & conclusions of law in form of partial initial decision Error exists in pagination Page 5 omitted
RAWSON, R J Hearing Branch 4 83/05/16 BRENNER, L , MORRIS, P A , CARPENTER, J L Atomic Safety and Licensing Board Panel 2pp
18468 121 24X Fiche 50-322, 83/05/16, 8305170545

8305170563 Revised proposed opinion, findings of fact & conclusions of law in form of partial initial decision Certificate of Svc encl
REPKA, D A Hearing Branch 3 83/05/16 213pp 18467 034 24X
Fiche 50-322, 83/05/16, 8305170563

8305190208 Supplemental paragraphs to be included in proposed opinion & supplemental proposed findings on Suffolk County Contention 11 re valve failures Certificate of Svc encl
FLANAGAN, D O Long Island Lighting Co FLANAGAN, D O Hunton & Williams 83/05/16 9pp 18501 330 24X Fiche 50-322, 83/05/16, 8305190208

8305190271 Affidavit of EJ Youngling that portions of Suffolk County proposed contention on diesel generators unsupported by facts, insubstantial in nature or remedied Prof qualifications encl
YOUNGLING, E J Long Island Lighting Co 83/05/16 34pp
18501 113 24X Fiche 50-322, 83/05/16, 8305190271

8305190378 Forwards motion opposing Suffolk County motion to add diesel generator contention Certificate of Svc encl
EARLEY, A F Hunton & Williams EARLEY, A F Long Island Lighting Co 83/05/16 BRENNER, L , CARPENTER, J H , MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 18500 234 24X
Fiche 50-322, 83/05/16, 8305190378

--8305190382 Response opposing Suffolk County 830502 motion to add emergency diesel generator contention County fails to meet stds for reopening record, for late-filed contentions & for particularity of contentions
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/16 Atomic Safety and Licensing Board Panel
34pp 18500 237 24X Fiche 50-322, 83/05/16, 8305190378

8305200651 Motion for 1-day extension until 830524 to file supplemental SC/SOC 73 reply findings NRC 830516 supplemental findings not served on util counsel until 830517
EARLEY, A F Long Island Lighting Co 83/05/17 Atomic Safety and Licensing Board Panel 3pp 18519 309 24X Fiche 50-322, 83/05/17, 8305200651

8305200590 Response opposing Suffolk County 830502 motion for leave to file new contention re emergency diesel generators Interested county must observe all procedural requirements applicable to parties Certificate of Svc encl
BORDENICK, B M , REPKA, D A Hearing Branch 3 83/05/18 Atomic Safety and Licensing Board Panel 14pp 18514 058 24X
Fiche 50-322, 83/05/18, 8305200590

--8305200594 Final deficiency rept re failure of liquid carbon dioxide storage tank/piping & affect on operability of emergency diesel generators. Issue not reportable per 10CFR50 55(e)
MILLIGAN, M H Long Island Lighting Co 81/11/12 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) 2pp
18514 074 24X Fiche 50-322, 83/05/18, 8305200590

8305240548 Advises that County will file motion for leave to respond to util 830516 & NRC 830518 response to Suffolk County motion to add emergency diesel generator contention Filing will contain important new info Related correspondence
DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips
DYNNER, A R Suffolk County, NY 83/05/19 BRENNER, L J , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel
1p 18575 283 24X Fiche 50-322, 83/05/19, 8305240548

8305240432 Order granting util 830517 request for extension until 830524 to file supplemental proposed findings on Contention 7B
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/20
Long Island Lighting Co 1p 18575 257 24X Fiche 50-322,83/05/20, 8305240432

8305240460 Order permitting Suffolk County to reply,by 830531,to util 830516 & NRC 830518 arguments opposing County motion to admit new emergency diesel generator contention
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/20
Suffolk County, NY 4pp 18573 160 24X Fiche 50-322,83/05/20, 8305240460

8305270553 Forwards 820930 Torrey Pines rept,Vol II (program results), Vol III (potential finding repts) & environ qualification rept for Class IE equipment,Vols I & II per 830520 telcon W/o encls
LANE,V M Atomic Safety and Licensing Board Panel 83/05/20
MCCAFFREY,B Long Island Lighting Co 1p 18662 114 24X Fiche 50-322,83/05/20,8305270553

8305250367 Forwards ASLAB 830518 Decision ALAB-728 re Suffolk County/ Shoreham Opponents Coalition Contention 7D Areas addressed include NRC obligation re unresolved safety issues & regulatory requirements
RAWSON,R J Hearing Branch 4 83/05/23 BRENNER,L , MORRIS,P A , CARPENTER,J L Atomic Safety and Licensing Board Panel 66pp 18591 102 24X Fiche 50-322,83/05/23,8305250367

8305250334 Order approving "Resolution of Suffolk County Contention 13(a) - QA/QC - Operations," dtd 830505 & Addendum 1,dtd 830516
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/24
Office of the Executive Legal Director 2pp 18595 359 24X Fiche 50-322,83/05/24,8305250334

8305250373 Forwards Teledyne Engineering Svcs 830506 ltr to HR Denton w/attachment re independent design verification program
BORDENICK,B M Hearing Branch 3 83/05/24 BRENNER,L , CARPENTER,J L , MORRIS,P A Atomic Safety and Licensing Board Panel 7pp 18592 093 24X Fiche 50-322,83/05/24,8305250373

8305310040 Vol 3 of reply to proposed opinions,findings & conclusions of Suffolk County & NRC re safety classification & sys interaction Certificate of Svc encl
Long Island Lighting Co # Hunton & Williams 83/05/24 293pp 18654 092 24X Fiche 50-322,83/05/24,8305310040

8305310051 Vol 2 of reply to proposed opinions,findings & conclusions of Suffolk County & NRC re safety classification & sys interaction
EARLEY,A F Long Island Lighting Co EARLEY,A F Hunton & Williams 83/05/24 127pp 18653 325 24X Fiche 50-322,83/05/24, 8305310051

8305260271 Suppls to 830211 proposed opinion & findings of fact on Suffolk County Contention II re passive mechanical valve failures Suppls to be used only if ASLB reopens record Certificate of Svc encl
REPKA,D A Hearing Branch 3 83/05/25 9pp 18625 355 24X Fiche 50-322,83/05/25,8305260271

8305270595 Order approving encl proposed corrections to 830405,06 & 08 transcripts
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/25
Long Island Lighting Co 30pp 18645 283 24X Fiche 50-322,83/05/25,8305270595

8305270563 Order directing clarification by 830610 of Contention SC 11, passive mechanical valve failure & IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/26
Long Island Lighting Co 8pp 18645 313 24X Fiche 50-322, 83/05/26,8305270563

8305310063 Submission of data re cracked engine block on emergency diesel generator 103 pursuant to ALAB-143 & ALAB-291 Certificate of Svc encl
DYNNER,A R Suffolk County, NY DYNNER,A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/26 4pp 18653 179 24X Fiche 50-322,83/05/26,8305310063

H General correspondence

8305190059 Urges denial of LILCO request for extension of CP,citing lack of adequate evacuation plan for Suffolk County residents
PELL,W R Southold, NY 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18502 063 24X Fiche 50-322,83/05/11,8305190059

8305180366 Responds to 830404 ltr re offsite emergency planning Commission 830512 order directed ASLB to consider any util emergency plan submitted
FITZGERALD,J A Office of the General Counsel 83/05/17 NEVEL,M Shelter Island,NY 1p 18486 359 24X Fiche 50-322,83/05/17, 8305180366

--8305180367 Supports Suffolk County 830223 motion to terminate OL proceeding & motion for clarification
NEVEL,M Shelter Island,NY 83/04/04 PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 2pp 18486 360 24X Fiche 50-322,83/05/17,8305180366

8305180430 Responds to 830406 ltr re offsite emergency planning Commission 830512 order directed ASLB to consider any util emergency plan submitted
FITZGERALD,J A Office of the General Counsel 83/05/17 RUNCO,F Sag Harbor, NY 1p 18483 114 24X Fiche 50-322,83/05/17, 8305180430

--8305180459 Supports Suffolk County 830223 motion to terminate OL proceeding & motion for certification
RUNCO,F , BRANNEN,J , KERN,P Sag Harbor, NY 83/04/06
PALLADINO,N J , GILINSKY,V , AHEARNE,J F Commissioners 2pp 18483 115 24X Fiche 50-322,83/05/17,8305180430

--8305180461 Urges denial of util request to extend CP expiration date Suffolk County determination that evacuation is impossible disposes of OL question
RUNCO,F , BRANNEN,J , VAN KOVICS,J Sag Harbor, NY 83/04/06
DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18483 117 24X Fiche 50-322,83/05/17,8305180430

8305180445 Responds to 830411 ltr re offsite emergency planning Commission 830512 order directed ASLB to consider any util emergency plan submitted
FITZGERALD,J A Office of the General Counsel 83/05/17
GREENBAUM,R East Hampton, NY 1p 18486 062 24X Fiche 50-322,83/05/17,8305180445

--8305180448 Supports Suffolk County 830223 motion to terminate OL proceeding & motion for certification Portion of ltr to HR Denton encl
GREENBAUM,R Hampton, NH 83/04/11 PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 4pp 18486 063 24X Fiche 50-322,83/05/17,8305180445

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305050109 Responds to NRC request for addl info on IE Bulletin 81-03 re application of hypochlorite to control growth of biofouling organisms in salt svc water sys NPDES permit & EPA regulations allow discharge of chlorine for 2 h
POLLOCK,M S Long Island Lighting Co 83/04/21 JORDAN,E L QA Branch 3pp 18341 329. 24X Fiche 50-322,83/04/21,8305050109

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305040508 Forwards Rev 2 to "4160V Metal Encl Switchgear - General Maint," providing description of inservice insp & testing programs to assure seismic integrity of electrical & mechanical components (SER Issue B)
SMITH,J L Long Island Lighting Co 83/04/22 DENTON,H R. Office of Nuclear Reactor Regulation, Director 9pp 18321 023 24X Fiche 50-322,83/04/22,8305040508

--8305040514 Rev 2 to Procedure 32 050 02, "4160V Metal Encl Switchgear - General Maint "
ROSE,J J Long Island Lighting Co 83/01/31 6pp 18322 032 24X Fiche 50-322,83/04/22,8305040508

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305040780 Board Notification 83-053 forwards notice of violation & proposed imposition of civil penalty based upon applicant approving preoperational test results for diesel generator test even though acceptance criteria not satisfied
NOVAK,T M Assistant Director for Licensing 83/04/25 Atomic Safety and Licensing Board Panel 4pp 18327 246 24X
Fiche 50-322,83/04/25,8305040780

--8305040785 Discusses IE insp on 821130-1231 & forwards notice of violation & notice of proposed imposition of civil penalty
ALLAN,J M Director's Office, Office of Inspection and Enforcement 83/04/12 POLLOCK,M S Long Island Lighting Co 3pp 18327 250 24X Fiche 50-322,83/04/25,8305040780

--8305040790 Notice of violation & notice of proposed imposition of civil penalty in amount of $40,000 Noncompliance noted applicant approved diesel generator preoperational tests results even though acceptance criteria not satisfied
ALLAN,J M Director's Office, Office of Inspection and Enforcement 83/04/12 3pp 18327 253 24X
Fiche 50-322,83/04/25,8305040780

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305120378 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18
MARTIN,T T Division of Engineering & Technical Programs 83/05/05
POLLOCK,M S Long Island Lighting Co 1p 18432 303 24X
Fiche 50-322,83/05/05,8305120378

--8305120380 Responds to NRC 820930 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-322/82-18 Corrective actions permanent responsibility for emergency planning assigned to emergency planning coordinator
POLLOCK,M S, Long Island Lighting Co 83/04/21 MARTIN,T T Division of Engineering & Technical Programs 12pp 18432 304 24X Fiche 50-322,83/05/05,8305120378

8305190031 Forwards IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/05
POLLOCK,M S Long Island Lighting Co 2pp 18502 043 24X
Fiche 50-322,83/05/05,8305190031

--8305190038 IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted Major areas inspected NUREG-0737 items,followup on previous insp findings & review of licensee controls over portable radio transmissions in plant areas
WIGGINS,J T , GALLO,R M Region 1, Office of Director 83/05/03 13pp 18502 045 24X Fiche 50-322,83/05/05,8305190031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305120301 Ack receipt of 830219 & 0305 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-322/83-02
STAROSTECKI,R Division of Project & Resident Programs 83/05/06
POLLOCK,M S Long Island Lighting Co 2pp 18424 125 24X
Fiche 50-322,83/05/06,8305120301

--8305120306 Responds to NRC 830121 ltr re violations noted in IE Insp Rept 50-322/83-02 Corrective action analysis performed on welds on control rod drive piping supports to determine any necessary rework
POLLOCK,M S Long Island Lighting Co 83/02/19 STAROSTECKI,R Division of Project & Resident Programs 16pp 18424 127 24X
Fiche 50-322,83/05/06,8305120301

--8305120311 Responds to NRC 830121 ltr re violations noted in IE Insp Rept 50-322/83-02 Corrective actions Reactor Controls,Inc to modify procedures &/or drawings to ensure specific gap requirement included for weld configurations
POLLOCK,M S Long Island Lighting Co 83/03/05 STAROSTECKI,R Division of Project & Resident Programs 43pp 18424 143 24X
Fiche 50-322,83/05/06,8305120301

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305180244 Requests withdrawal or reduction of proposed civil penalty Facts & circumstances re emergency diesel generator test merit reconsideration of severity level & should be classified as lesser violation
MUSELER,W J Long Island Lighting Co 83/05/12 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 11pp 18486 299 24X Fiche 50-322,83/05/12,8305180244

--8305180324 Responds to notice of violation & proposed imposition of civil penalty (EA 83-20) Addl facts discussed place circumstances noted by IE inspector in different perspective
MUSELER,W J Long Island Lighting Co 83/05/12 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 23pp 18486 310 24X Fiche 50-322,83/05/12,8305180244

--8305180331 Responds to 830224 ltr re violations noted in IE Insp Rept 50-322/82-35 on 821130-1231 Corrective actions strip chart recorder designated as primary instrument in reperformance of high load test
POLLOCK,M S Long Island Lighting Co 83/03/16 STAROSTECKI,R Division of Project & Resident Programs 13pp 18486 333 24X
Fiche 50-322,83/05/12,8305180244

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305020561 Submits daily highlight On 830420,ASLB issued memorandum & order denying Suffolk County motion to terminate OL proceeding In separate order,ASLB referred ruling on County motion to ASLAB for interlocutory review
CARUSO,R Licensing Branch 2 83/04/22 DENTON,H R , CASE,E G , CARTER,J Office of Nuclear Reactor Regulation, Director 2pp 18284 245 24X Fiche 50-322,83/04/22,8305020561

S Reportable occurrences, LERs & related correspondence

8305030274 Interim deficiency rept re apparent cracking in cylinder heads on emergency standby diesel generators Initially reported on 830308 Program to replace cylinder heads will prevent any potential impact on engine operability
MILLIGAN,M H Commonwealth Edison Co 83/04/15 ALLEN,J M Region 1, Office of Director 4pp 18296 190 24X Fiche 50-322,83/04/15, 8305030274

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000, 83/04/26, 8305120392

8305120328 Final deficiency rept re failure of rocker arm assembly holddown capscrew on Transamerica Delaval emergency standby diesel generators Initially reported on 830330 Capscrews replaced Changeouts completed per E&DCR F-45462
SMITH, J L Long Island Lighting Co 83/05/04 ALLAN, J M Region 1, Office of Director 4pp 18431 311 24X Fiche 50-322, 83/05/04, 8305120328

8305200549 Corrects ltr identification number submitted for 830504 final deficiency rept re rocker arm assembly holddown screw SNRC-873 should be SNRC-893
BRANDI, V A Long Island Lighting Co 83/05/12 Region 1, Office of Director 1p 18516 002 24X Fiche 50-322, 83/05/12, 8305200549

T Hearing transcripts on non-antitrust matters

8305050024 Supplemental proposed transcript corrections Certificate of Svc encl
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02, 5pp 18340 001 24X Fiche 50-322, 83/05/02, 8305050024

--8305050029 Revised proposed opinion, findings of fact & conclusions of law in form of partial initial decision
EARLEY, A F Long Island Lighting Co EARLEY, A F Hunton & Williams 83/05/02 367pp 18340 006 24X Fiche 50-322, 83/05/02, 8305050024

8305180082 Transcript of Commission 830512 affirmation/discussion & vote on SECY-83-157 concerning facility OL in Washington, DC
Pp 1-4
* Commissioners 83/05/12 7pp 18503 279 24X
Fiche 50-322, 83/05/12, 8305180082

8305270595 Order approving encl proposed corrections to 830405, 06 & 08 transcripts
BRENNER, L Atomic Safety and Licensing Board Panel 83/05/25
Long Island Lighting Co. 30pp 18645 283 24X
Fiche 50-322, 83/05/25, 8305270595

U Congressional/Executive Correspondence

8304040391 Responds to 830321 ltr re offsite emergency planning Commission studying filings before ASLB to determine if Commission action appropriate
FITZGERALD, J A Office of the General Counsel 83/03/30
SAWICKI, J New York, State of 1p 17809.210 24X
Fiche 50-322, 83/03/30, 8304040391

--8304040394 Supports Suffolk County 830223 request for Commission decision on whether OL proceedings should be terminated
SAWICKI, J New York, State of 83/03/21 PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 1p 17809 211 24X
Fiche 50-322, 83/03/30, 8304040391

8305180252 Responds to 830329 ltr re offsite emergency planning Commission 830512 order directed ASLB to consider any util emergency plan submitted
FITZGERALD, J. A Office of the General Counsel 83/05/17
BEHAN, J L New York, State of. 1p. 18490 027 24X
Fiche 50-322, 83/05/17, 8305180252

--8305180260 Supports Suffolk County Executive P Cohalan 830223 request for Commission to assume jurisdiction over question of whether OL proceedings should be terminated
BEHAN, J L New York, State of 83/03/29 Commissioners 1p 18490 028 24X Fiche 50-322, 83/05/17, 8305180252

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305230407 Informs that backfitting matl will be forwarded as soon as available, in response to 830208 ltr
FURBUSH, M H Pacific Gas & Electric Co 83/02/23 TOURTELLOTTE, J Regulatory Reform Task Force 1p 18543 357 24X
Fiche 50-000, 83/02/23, 8305230407

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305030191 Board Notification 83-51 forwards info re QA/QC allegations at facilities Region V currently investigating allegations
EISENHUT, D G Division of Licensing 83/04/15 PALLADINO, J , GILINSKY, V , AHEARNE, J Commissioners 1p 18309 350 24X
Fiche 50-275, 83/04/15, 8305030191

--8305030200 Recommends QA/QC allegations be brought to attention of ASLB
CREWS, J L Division of Resident, Reactor Project & Engineering Programs 83/04/13 EISENHUT, D G Division of Licensing 3pp 18309 351 24X Fiche 50-275, 83/04/15, 8305030191

8305020388 Responds to 830322 request for addl info on instrumentation sys for detection of inadequate core cooling (Generic Ltr 82-28) Installation completed & sys currently being tested Status of conformance w/NUREG-0737, Item II F 2 encl
SCHUYLER, J O Pacific Gas & Electric Co 83/04/27 EISENHUT, D G Division of Licensing 7pp 18276 329 24X Fiche 50-275, 83/04/27, 8305020388

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305120085 Board Notification 83-55 forwards info on allegations re const QA at facilities
EISENHUT, D G Division of Licensing 83/05/05 PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 3pp 18422 236 24X
Fiche 50-275, 83/05/05, 8305120085

--8305120093 Forwards sworn statements of V Tennyson & R Roam re allegations of matl violations of NRC QA regulations at facilities
VAN DE KAMP, J California, State of 83/04/12 EISENHUT, D G Division of Licensing 90pp 18422 239 24X
Fiche 50-275, 83/05/05, 8305120085

--8305120099 Transcript of 830325 interview w/VH Tennyson re alleged deficiencies in implementation of HP Foley Const Co QA program
TENNYSON, V H Affiliation Unknown 83/03/25 73pp 18422 329 24X Fiche 50-275, 83/05/05, 8305120085

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8303040044 Board Notification 83-66 forwards review of WCAP-10297(P), "Dropped Rod Methodology for Negative Flux Rate Trip Plants " Rod issue resolved by analysis in rept Plants beyond first cycle must perform analysis Comments encl
EISENHUT, D G Division of Licensing 83/05/13 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 21pp 18541 068 24X
Fiche 50-000, 83/05/13, 8303040044

8305270317 Notifies of 830602 meeting w/util & independent design verification program group in Boston, MA to followup 830512 discussions re turbine bldg, polar crane & auxiliary bldg & redistribution of moments & forces
COOPER, W E , CRAGIN, J G Teledyne Engineering Services 83/05/27, MANEATIS, G A , DENTON, H R , MARTIN, J B NRC - No Detailed Affiliation Given 1p 18642 223 24X Fiche 50-275, 83/05/27, 8305270317.

F Security, medical, emergency & fire protection plans

8305030180 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records, 83/04/22 Document Management Branch 1p 18310 001 24X Fiche 50-275, 83/04/22, 8305030180

--8305030188 Forwards public version of Rev 0 to Emergency Plan Implementing Procedures EP-RB-12, "Mid & High-Range Vent Monitors" & EP G-3, "Notification of Offsite Organizations."
CRANE, P A Pacific Gas & Electric Co 83/04/06 MARTIN, J B. Region 5, Office of Director 2pp 18310 002 24X
Fiche 50-275, 83/04/22, 8305030180

--8305030193 Public version of Rev 0 to Emergency Plan Implementing Procedures EP-RB-12, "Mid & High-Range Vent Monitors" & EP 0-3, "Notification of Offsite Organizations "
* Pacific Gas & Electric Co 83/04/06 19pp 18310 004 24X Fiche 50-275,83/04/22,8305030180

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13,8305240213

Q Adjudicatory correspondence

8305090438 Advises that since 830423 correspondence, informant contacted Joint Intervenors re allegations of Bechtel/util misconduct Fear of reprisals prevented informant from meeting or calling NRC
FLEISCHAKER,D Fleischaker, D S FLEISCHAKER,D Joint Intervenors-Diablo Canyon 83/05/03 EISENHUT,D G Division of Licensing 3pp 18362 354 24X Fiche 50-275,83/05/03,8305090438

8305110212 First request for document production by Governor Deukmejian & Joint Intervenors Related correspondence
STRUMWASSER,M California, State of REYNOLDS,J R Joint Intervenors-Diablo Canyon 83/05/06 Pacific Gas & Electric Co 8pp 18407 100 24X Fiche 50-275,83/05/06,8305110212

8305110217 Certifies svc of first set of interrogatories & first document production request on listed parties on 830506
STRUMWASSER,M California, State of 83/05/06 5pp 18407 095 24X Fiche 50-275,83/05/06,8305110217

8305110383 First set of interrogatories by Governor Deukmejian & Joint Intervenors Sworn response requested within 14 days Related correspondence
STRUMWASSER,M California, State of REYNOLDS,J R Joint Intervenors-Diablo Canyon 83/05/06 Pacific Gas & Electric Co 26pp 18406 230 24X Fiche 50-275,83/05/06,8305110383

8305120285 Motion to reopen record on const QA issue to receive significant new evidence of recently established deficiencies in const QA & QC program Certificate of Svc encl
REYNOLDS,J R Joint Intervenors-Diablo Canyon REYNOLDS,J R Center for Law in the Public Interest 83/05/10 Atomic Safety and Licensing Appeal Panel 39pp 18427 159 24X Fiche 50-275,83/05/10,8305120285

8305160127 Advises that NRC cannot pinpoint when NRC responsibilities to Commission re independent design verification program sufficiently complete to permit discovery against NRC Final repts due by 830630
CHANDLER,L J Hearing Branch 2 83/05/13 MOORE,T S , BUCK,J H , JOHNSON,W R Atomic Safety and Licensing Appeal Panel 2pp 18448 185 24X Fiche 50-275,83/05/13,8305160127

8305260182 Motion to reopen record on const QA Info discovered on util QA program design & const deficiencies & on const contractor QA program deficiencies
KAUFMAN,P H California, State of 83/05/17 Atomic Safety and Licensing Appeal Panel 38pp 18599 024 24X Fiche 50-275, 83/05/17,8305260182

--8305260183 Declaration of RB Hubbard re breakdown in const QA. Describes events occurring since issuance of 830326 supplemental affidavit demonstrating util QA/QC const program noncompliance Certificate of Svc encl
HUBBARD,R.B. California, State of 83/05/06 50pp 18599 063 24X Fiche 50-275,83/05/17,8305260182

8305200657 Decision ALAB-728, affirming ASLB 810717 Partial Initial Decision LBP-81-21 authorizing fuel loading & low power testing Johnson opinion, dissenting in part, encl
BHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 83/05/18 64pp 18519 340 24X Fiche 50-275,83/05/18,8305200657

8305270622 Answers to Governor Deukmejian & Joint Intervenors 830506 first set of Interrogatories 1(a) through (f),8(a),(c) & (d),9(a),(c) & (d),10(a) & (c) & 11(a) & (c) re independent design verification review Certificate of Svc encl
CRANE,P A Pacific Gas & Electric Co 83/05/23 DEUKMEJIAN,G California, State of 200pp 18645 001 24X Fiche 50-275,83/05/23, 8305270622

H General correspondence

8305180622 Responds to 830328 ltr re eight allegations by anonymous individual Preliminary evaluation of allegations underway Meeting w/util planned in near future to solicit evaluation on subj
EISENHUT,D G Division of Licensing 83/04/21 FLEISCHAKER,D Fleischaker, D S 8pp 18505 317 24X Fiche 50-275,83/04/21, 8305180622

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305170332 Forwards IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 No noncompliance noted
BISHOP,T W Region 5, Office of Director 83/04/08 CRANE,P A Pacific Gas & Electric Co 2pp 18465 133 24X Fiche 50-275,83/04/08,8305170332

--8305170339 IE Insp Repts 50-275/83-12 & 50-323/83-09 on 830306-0402 No noncompliance noted Major areas inspected surveillance testing, maint & TMI task action plan items
CARLSON,J D , MENDONCA,M M , KIRSCH,D F Region 5, Office of Director 83/04/05 6pp 18465 135 24X Fiche 50-275,83/04/08, 8305170332

8305060299 Advises that top cover gaskets in 12 Namco EA180 limit switches replaced per manufacturer recommendation in IE Bulletin 79-28 No further action necessary
CRANE,P A Pacific Gas & Electric Co 83/04/14 MARTIN,J B Region 5, Office of Director 1p 18344 322 24X Fiche 50-323,83/04/14,8305060299

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp. 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260257 Forwards IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830330-0406 & 25-29 W/o notice of violation
BISHOP,T W Region 5, Office of Director 83/05/19 CRANE,P A Pacific Gas & Electric Co 2pp 18625 172 24X
Fiche 50-275,83/05/19,8305260257

--8305260262 IE Insp Repts 50-275/83-13 & 50-323/83-10 on 830330-0406 & 25-29 Noncompliance noted failure to comply w/procedural requirements for processing of nonconformance repts & to conduct welder requalification
CARLSON,J D , HERNANDEZ,G H , MENDONCA,M M Region 5, Office of Director 83/05/19 24pp 18625 174 24X Fiche 50-275,83/05/19, 8305260257

8305260270 Forwards IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 & SALP rept for Jul 1981 - Dec 1982
MARTIN,J B Region 5, Office of Director 83/05/23 CRANE,P A Pacific Gas & Electric Co 2pp 18626 211 24X
Fiche 50-275,83/05/23,8305260270

--8305260272 IE Mgt Meeting Repts 50-275/83-18 & 50-323/83-14 on 830407 No noncompliance noted Major areas discussed SALP rept for Jul 1981 - Dec 1982,including design,const & operations
MORRILL,P J , KIRSCH,D F Region 5, Office of Director 83/05/20 2pp 18626 213 24X Fiche 50-275,83/05/23,8305260270

--8305260274 Submits comments on draft SALP rept for Jul 1981 - Dec 1982 discussed at 830407 meeting SALP rept will be used as guide for assigning priorities & allocating resources to maintain & improve mgt controls &/or quality of work
CRANE,P A Pacific Gas & Electric Co 83/04/27 MARTIN,J B Region 5, Office of Director 2pp 18626 258 24X
Fiche 50-275,83/05/23,8305260270

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305060580 PNO-V-83-019 on 830502,6 5 Richter scale earthquake occurred approx 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected
KIRSCH,D F Region 5, Office of Director 83/05/03 1p 18349 057 24X Fiche 50-275,83/05/03,8305060580

U Congressional/Executive Correspondence

8305100124 Supplemental testimony of JG Keppler re GA
KEPPLER,J G Region 3, Office of Director 83/03/25 6pp 18375 197 24X Fiche 50-000,83/03/25,8305100124

--8305100141 Responds to 811113 ltr re implications of recent seismic design errors at facility Due to design errors,util license suspended on 811119 pending completion of independent design review & receipt of schedule for completing mods
PALLADINO,N J Commissioners 82/02/01 DINGELL,J D House of Rep , Energy & Commerce 5pp 18375 220 24X
Fiche 50-000,83/03/25,8305100124

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305200625 Forwards Rev 8 to industrial security plan Changes do not decrease effectiveness of plan or level of security Encl withheld (ref 10CFR73 21 & 2 790)
HOWE,P W Carolina Power & Light Co 83/04/20 O'REILLY,J P Region 2, Office of Director 2pp 18520 042 24X
Fiche 50-324,83/04/20,8305200625

8305200597 Forwards change to provisions of industrial security plan Change will not decrease effectiveness of plan or level of security Encl withheld (ref 10CFR73 21)
HOWE,P W Carolina Power & Light Co 83/04/28 O'REILLY,J P Region 2, Office of Director 1p 18514 106 24X
Fiche 50-324,83/04/28,8305200597

8305100100 Forwards IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted
VERRELLI,A Division of Project & Resident Programs 83/05/05 UTLEY,E E Carolina Power & Light Co 2pp 18375 033 24X
Fiche 50-324,83/05/05,8305100100

--8305100109 IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted Major areas inspected audit review,security plan,records,assessment aids,alarm stations & training/qualification Details withheld (ref 10CFR73 21)
TOBIN,W J , HALL,B Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 83/05/04 1p 18375 035 24X Fiche 50-324,83/05/05,8305100100

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305260134 Informs that NUREG-0737,Item III A 2 1 re emergency plan upgrade to meet 10CFR50,App E requirements complete for facility Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 UTLEY,E E Carolina Power & Light Co 3pp 18649 049 24X
Fiche 50-324,83/05/18,8305260134

J Insurance & indemnity information

8305160135 Forwards Endorsement 48 to NELIA Policy NF-218
BARHAM,C D Carolina Power & Light Co 83/05/02 SALTZMAN,J NRC - No Detailed Affiliation Given 2pp 18446 066 24X
Fiche 50-324,83/05/02,8305160135

P Operating license stage documents & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root,Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000,83/03/09,8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE,J F Commissioners 5pp 18497 228 24X Fiche 50-000,83/03/09,8305180001

8305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
SMITH,S H Carolina Power & Light Co 83/03/22 TOURTELLOTTE,J Regulatory Reform Task Force 13pp 18543 277 24X
Fiche 50-000,83/03/22,8305230283

8305230720 Forwards list of utils responding to requests for cost figures on backfitting.
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305030288 Application for amend to License DPR-62 revising Tech Specs to delete 8 5/ MAPLHGR reduction penalty Sketches of clamp on core spray sparger, described in 820520 ltr encl, per NRC request Class III license fee Forwarded on 821229
HOWE, P W Carolina Power & Light Co 83/04/28 VASSALLO, D B
Operating Reactors Branch 2 11pp 18300 062 24X
Fiche 50-324, 83/04/28, 8305030288

--8305030293 Proposed changes to Tech Specs deleting 8 5% MAPLHGR reduction penalty
* Carolina Power & Light Co 83/04/28 7pp 18300 073 24X
Fiche 50-324, 83/04/28, 8305030288

8305030463 Application for amend to Licenses DPR-62 & DPR-71, supplementing 820616 request for miscellaneous Tech Spec revs originally scheduled for completion during 820901 refueling outage Outage & mods to be completed by 830624
HOWE, P W Carolina Power & Light Co 83/04/28 VASSALLO, D B
Operating Reactors Branch 2 2pp 18308 222 24X
Fiche 50-324, 83/04/28, 8305030463

--8305030481 Proposed Tech Specs re safety-related hydraulic snubbers, post-accident monitoring instrumentation, gas analyzer sys, reactor coolant leakage detection sys & remote shutdown monitoring instrumentation
* Carolina Power & Light Co 83/04/28 19pp 18308 224 24X
Fiche 50-324, 83/04/28, 8305030463

8305190099 Forwards safety evaluation for TMI Action Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage " Training & requalification programs acceptable
VASSALLO, D B Operating Reactors Branch 2 83/04/29 UTLEY, E E
Carolina Power & Light Co 3pp 18523 175 24X
Fiche 50-324, 83/04/29, 8305190099

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305090380 Ack receipt of 830131 ltr requesting addl info re NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulator Sys " Info requested from GE Response will be submitted by 830630
ZIMMERMAN, S R Carolina Power & Light Co 83/05/05 VASSALLO, D B
Operating Reactors Branch 2 1p 18363 340 24X
Fiche 50-324, 83/05/05, 8305090380

8305090456 Confirms 830419 responses to questions raised during 830418 telcon re spent fuel pool expansion
ZIMMERMAN, S R Carolina Power & Light Co 83/05/05 VASSALLO, D B
Operating Reactors Branch 2 2pp 18362 265 24X
Fiche 50-324, 83/05/05, 8305090456

8305180040 Forwards Amend 80 to License DPR-62, safety evaluation & notice of issuance & availability Amend changes Tech Specs re limiting values of MAPLHGR & abrogates uniform reduction of 8 5% in limiting MAPLHGR values
MACKAY, S D Operating Reactors Branch 2 83/05/05 UTLEY, E E
Carolina Power & Light Co 2pp 18497 291 24X
Fiche 50-324, 83/05/05, 8305180040

--8305180048 Amend 80 to License DPR-62, changing Tech Specs re limiting values of MAPLHGR & abrogating uniform reduction of 8 5% in limiting MAPLHGR values
VASSALLO, D B Operating Reactors Branch 2 83/05/05 10pp
18499 293 24X Fiche 50-324, 83/05/05, 8305180040

--8305180057 Safety evaluation supporting Amend 80 to License DPR-62
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp
18499 303 24X Fiche 50-324, 83/05/05, 8305180040

--8305180061 Notice of issuance & availability of Amend 80 to License DPR-62
VASSALLO, D B Operating Reactors Branch 2 83/05/05 2pp
18499 305 24X Fiche 50-324, 83/05/05, 8305180040

8305180563 Forwards revised order establishing 830930 completion date for implementing NUREG-0737, Items II B 3 re post-accident sampling & II F 1 1 & II F 1 5 re accident monitoring
VASSALLO, D B Operating Reactors Branch 2 83/05/05 UTLEY, E E
Carolina Power & Light Co 2pp 18504 354 24X
Fiche 50-324, 83/05/05, 8305180563

--8305180566 Revised order confirming licensee commitments to implement NUREG-0737, Items II B 3 re post-accident sampling & II F 1 1 & II F 1 5 re accident monitoring, by 830930
PURPLE, R A Division of Licensing 83/05/05 Carolina Power & Light Co 5pp 18504 356 24X Fiche 50-324, 83/05/05, 8305180563

8305230178 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Suction " Mods acceptable
VASSALLO, D B Operating Reactors Branch 2 83/05/05 UTLEY, E E
Carolina Power & Light Co 5pp 18546 356 24X
Fiche 50-324, 83/05/05, 8305230178

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120003 Responds to 830316 ltr requesting review of RCIC sys automatic restart per TMI Action Item II K 3 13 Acceptance criteria identified in ltr satisfied
ZIMMERMAN, S R Carolina Power & Light Co 83/05/09 VASSALLO, D B
Operating Reactors Branch 2 1p 18423 076 24X
Fiche 50-324, 83/05/09, 8305120003

8305260285 Forwards request for addl info re 810123 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/05/11 UTLEY, E E
Carolina Power & Light Co 3pp 18629 337 24X
Fiche 50-324, 83/05/11, 8305260285

8305240004 Informs that currently scheduled Unit 1 startup date is 830612 Outage critical path 8 days behind, but recovery plan instituted to make up time Requests Tech Spec changes be issued no later than 830612
HURFORD, W J Carolina Power & Light Co 83/05/17 VASSALLO, D B
Operating Reactors Branch 2 1p 18549 051 24X
Fiche 50-324, 83/05/17, 8305240004

8305240434 Commits to submit results of plant-unique calculations forming bases for mod program on Mark I containment vacuum breakers by 830630 in response to Generic Ltr 83-08 Calculations presented in listed documents
HOWE, P W Carolina Power & Light Co 83/05/19 VASSALLO, D B
Operating Reactors Branch 2 2pp 18571 061 24X
Fiche 50-324, 83/05/19, 8305240434

8305260320 Forwards NEDO-24582, "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 " Attachment detailing pressure/temp calculations also encl
ZIMMERMAN, S R Carolina Power & Light Co 83/05/24 VASSALLO, D B
Operating Reactors Branch 2 1p 18625 058 24X
Fiche 50-324, 83/05/24, 8305260320

--8305260325 "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant, Units 1 & 2 "
* General Electric Co NEDO-24582 R01 81/10/31 61pp
18625 059 24X Fiche 50-324, 83/05/24, 8305260320

G Inspection reports, IE Bulletins & correspondence

8305270531 Submits results of split sample taken from floor drain sample tank B for tritium & radiostrontium, per IE Insp Repts 50-324/82-09 & 50-325/82-09
DIETZ, C R Carolina Power & Light Co 83/02/25 O'REILLY, J P
Region 2, Office of Director 1p 18646 129 24X
Fiche 50-324, 83/02/25, 8305270531

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/04/11 UTLEY, E E
Carolina Power & Light Co 2pp 18644 158 24X
Fiche 50-000, 83/04/11, 8305270461

--8305270474 IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of radwaste containing free liquid & inoperability of standby gas treatment deluge sys
LEWIS, R C Division of Project & Resident Programs 83/04/07
3pp. 18644 160 24X Fiche 50-000, 83/04/11, 8305270461

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165. 24X Fiche 50-000,83/04/28,8303040027

8305270250 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-07 & 50-325/83-07
VERRELLI,D M Division of Project & Resident Programs 83/04/29
UTLEY,E E Carolina Power & Light Co 1p 18641 187 24X
Fiche 50-324,83/04/29,8305270250

--8305270256 Responds to NRC 830317 ltr re violations noted in IE Insp Repts 50-324/83-07 & 50-325/83-07 Corrective actions procedure revised & accepted by QA reflecting actual testing method & contractor personnel counseled
DIETZ,C R Carolina Power & Light Co 83/04/15 O'REILLY,J P Region 2, Office of Director 2pp 18641 188 24X
Fiche. 50-324,83/04/29,8305270250

--8305270263 Forwards IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/03/17
UTLEY,E E Carolina Power & Light Co 2pp 18641 190 24X
Fiche. 50-324,83/04/29,8305270250

--8305270268 Notice of violation from insp on 830131-0203 & 07-11
* Region 2, Office of Director 83/03/17 1p 18641:192 24X
Fiche 50-324,83/04/29,8305270250.

--8305270276 IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 Noncompliance noted failure to follow inservice insp procedure for recording angle beam data
COLEY,J L , BLAKE,J J Region 2, Office of Director 83/03/04
8pp 18641 193 24X Fiche 50-324,83/04/29,8305270250

8305060620 Responds to NRC 830218 ltr transmitting notice of violation & proposed imposition of civil penalties,per IE Insp Repts 50-324/82-28 & 50-325/82-28 Relay tests completed satisfactorily.
UTLEY,E.E Carolina Power & Light Co. 83/03/02 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 27pp 18349 022 24X Fiche:50-324,83/03/02,8305060620

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/03 Consolidated Edison Co of New York, Inc 122pp 18441 170. 24X Fiche 50-000,83/03/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co of New York, Inc 112pp. 18382 282. 24X Fiche.50-000,83/03/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Proactive Action Recommendations for General Emergencies " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/04 Consolidated Edison Co. of New York, Inc 119pp 18441:001 24X Fiche 50-000,83/03/04,8303040031

8305100100 Forwards IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15.No noncompliance noted
VERRELLI,A Division of Project & Resident Programs 83/03/03
UTLEY,E.E Carolina Power & Light Co 2pp 18375 033 24X
Fiche:50-324,83/03/03,8305100100

--8305100109 IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted Major areas inspected audit review,security plan,records,assessment aids,alarm stations & training/qualification Details withheld (ref 10CFR73 21)
TOBIN,W J , HALL,B Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 83/03/04
1p 18375 035 24X Fiche 50-324,83/03/03,8305100100

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/03/06,8303040033

8305270580 Ack receipt of 830318 & 0422 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45
LEWIS,R C Division of Project & Resident Programs 83/03/06
UTLEY,E E Carolina Power & Light Co 1p 18644 225 24X
Fiche 50-324,83/03/06,8305270580

--8305270588 Responds to NRC 830207 ltr re violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45 Corrective actions required rev to Q-list procedure will not be completed until 830527
DIETZ,C R Carolina Power & Light Co 83/03/23 O'REILLY,J P Region 2, Office of Director 1p 18644 226 24X
Fiche 50-324,83/03/06,8305270580

--8305270599 Clarifies response to Violations B & C in IE Insp Repts 50-324/82-45 & 50-325/82-45 Program for determining type of alarm devices needing periodic calibr will not be completed by 830730
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P Region 2, Office of Director 2pp 18644 227 24X
Fiche 50-324,83/03/06,8305270580

--8305270610 Responds to violations noted in IE Insp Rept 50-324/82-45 & 50-325/82-45 Corrective actions engineering supervisor of discipline group responsible for performing review of tables for inconsistencies internal to procedure
DIETZ,C R Consumers Power Co 83/03/18 O'REILLY,J P Region 2, Office of Director 4pp 18644 229 24X Fiche 50-324, 83/03/06,8305270580

--8305270617 Ack receipt of 830207 ltr transmitting IE Insp Repts 50-324/82-45 & 50-325/82-45 Util continuing evaluation of violations Response to rept will be submitted by 830318
DIETZ,C R Carolina Power & Light Co 83/03/08 O'REILLY,J P Region 2, Office of Director 1p 18644 233 24X
Fiche 50-324,83/03/06,8305270580

--8305270621 Forwards IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/02/07
UTLEY,E E Carolina Power & Light Co 2pp 18644 234 24X
Fiche 50-324,83/03/06,8305270580

--8305270628 Notice of violation from insp on 821115-1215
* Region 2, Office of Director 83/02/07 2pp 18644 236 24X
Fiche 50-324,83/03/06,8305270580

--8305270635 IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215 Noncompliance noted failure to adequately review procedure changes,to establish calibr procedures & to followup on corrective actions.
MYERS,D O , GARNER,L W , BEMIS,P Region 2, Office of Director 83/02/02 10pp 18644 238 24X Fiche 50-324,83/03/06,8305270580

8305270333 Forwards IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/10
UTLEY,E E Carolina Power & Light Co 2pp 18641 123 24X
Fiche 50-324,83/03/10,8305270333

--8305270342 IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted Major areas inspected independent insp effort & observation of inservice insp work & work activities
COLEY,J L , BLAKE,J J Region 2, Office of Director 83/03/03
6pp 18641 125 24X Fiche 50-324,83/03/10,8305270333

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/03/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/19 Consolidated Edison Co of New York, Inc 114pp 18697 009. 24X Fiche 50-000,83/03/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305100412 Forwards monthly operating repts for Apr 1983
DIETZ,C R Carolina Power & Light Co 83/05/05 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 1p
18378 066 24X Fiche 50-324,83/05/05,8305100412

--8305100417 Monthly operating repts for Apr 1983
HARRISON,F Carolina Power & Light Co 83/05/03 12pp
18378 067 24X Fiche 50-324,83/05/05,8305100412

S Reportable occurrences, LERs & related correspondence

8305030355 Forwards LER 83-016/03L-0
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18306 294 24X
Fiche 50-324,83/04/20,8305030355

--8305030361 LER 83-016/03L-0 on 830323,reactor bldg exhaust ventilation high-high alarm occurred concurrent w/Group 6 primary containment isolation signal Caused by failure of relay K2 in indication & trip unit D12-K609A Relay replaced
PASTVA,M J Carolina Power & Light Co 83/04/20 Region 2,
Office of Director 2pp 18306 295 24X Fiche 50-324,83/04/20,
8305030355

8305030497 Nonroutine radiological environ event rept Results of 830308 gamma analysis of bottom sediment revealed high Co-60 concentration Samples will be taken monthly for Oct 1982 - June 1983 to determine if trends can be predicted
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 2pp 18306 183 24X
Fiche 50-324,83/04/20,8305030497

8305030530 RO fire barrier limiting conditions for operation issued on 830317 & 20 exceeded 7-day time frame to permit completion of mods in control,diesel generator & augmented offgas bldgs Continuous stationed fire watches maintained
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18306 362 24X
Fiche 50-324,83/04/20,8305030530

8305030612 Forwards supplemental LER 83-002/03L-1.
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18303 343 24X
Fiche 50-324,83/04/20,8305030612

--8305030618 Supplemental LER 83-002/03L-1 on 830102,indicator 2-CAC-LR-2602 showed high suppression pool level Caused by incorrect input signal to indicator due to change in trickle flow to wet ref leg of LR-2602 indicator transmitter
PASTVA,M J Carolina Power & Light Co 83/04/20 Region 2,
Office of Director 2pp 18303 344 24X Fiche 50-324,83/04/20,
8305030612

8305030387 Part 21 rept re pipe clamps for snubber/struts oriented in off-axis direction Initially reported on 830224 & by IE Info Notice 83-13 Clamps will be replaced by end of Fall 1983 refueling outage
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P
Region 2, Office of Director 2pp 18292 316 24X
Fiche 50-324,83/04/22,8305030387

8305030411 Forwards updated LER 82-126/03L-1
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P.
Region 2, Office of Director 1p 18293 226 24X
Fiche 50-324,83/04/22,8305030411

--8305030419 Updated LER 82-126/03L-1 on 821024 & 25,standby liquid control sys piping heat tracing on lines between sys accumulators 2-C41-A003A & B & common discharge line inoperable Caused by electrical failure Mods planned
PASTVA,M J Carolina Power & Light Co 83/04/22. Region 2,
Office of Director 1p 18293 227 24X Fiche 50-324,83/04/22,
8305030411

8305030512 Forwards LER 83-002/03L-0.
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P
Region 2, Office of Director 1p 18308 191 24X
Fiche 50-324,83/04/22,8305030512

--8305030536 LER 83-002/03L-0 on 830328,suppression pool level indicator 2-CAC-LR-2602 showed level of -31 2 inches while redundant indicators 2-CAC-LI-2601-1 & 2601-3 showed -28 5 inches Caused by change in trickle flow to wet ref leg
PASTVA,M J Carolina Power & Light Co 83/04/22 Region 2,
Office of Director 2pp 18308 192 24X Fiche 50-324,83/04/22,
8305030512

8305030540 Forwards LER 83-037/03L-0
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P
Region 2, Office of Director 1p 18303 332 24X
Fiche 50-324,83/04/22,8305030540

--8305030547 LER 83-037/03L-0 on 830325,RHR Div II suppression pool cooling valve 2-E11-F024B could not be opened using either valve motor operator or manual operator Caused by loose antirotation device setscrew Setscrew tightened
PASTVA,M J Carolina Power & Light Co 83/04/22 Region 2,
Office of Director 2pp 18303 333 24X Fiche 50-324,83/04/22,
8305030540

8305030291 Supplemental response to Part 21 rept re postulated pipe crack in HPCI,RCIC,reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program
DIETZ,C R Carolina Power & Light Co. 83/04/26 O'REILLY,J P
Region 2, Office of Director 1p 18300 061 24X
Fiche 50-324,83/04/26,8305030291

8305050265 Forwards LER 83-038/03L-0
DIETZ,C R Carolina Power & Light Co 83/04/28 O'REILLY,J P
Region 2, Office of Director 1p 18338 039 24X
Fiche 50-324,83/04/28,8305050265.

--8305050267 LER 83-038/03L-0 on 830401,inoperative & rod block signal received from rod block monitors A & B upon selecting indicated control rods Caused by defective multiplexer cards in monitors Cards replaced & monitors returned to svc
PASTVA,M J Carolina Power & Light Co 83/04/28 Region 2,
Office of Director 1p 18338 040 24X Fiche 50-324,83/04/28,
8305050265

8305050242 Forwards LER 83-042/03L-0
DIETZ,C R Carolina Power & Light Co 83/04/29 O'REILLY,J P
Region 2, Office of Director 1p 18337 297 24X
Fiche 50-324,83/04/29,8305050242

--8305050244 LER 83-042/03L-0 on 830330,suppression pool level indicators 2-CAC-LI-2601,3 & 2-CAC-LI-3342 showed upward trend in level indication Caused by closed demineralized water root valve, preventing transmitters from sensing actual level
PASTVA,M J Carolina Power & Light Co 83/04/29 Region 2,
Office of Director 1p 18337 298 24X Fiche 50-324,83/04/29,
8305050242

8305130177 Forwards LER 83-044/03L-0
DIETZ,C R Carolina Power & Light Co 83/05/04. O'REILLY,J P
Region 2, Office of Director 1p 18440 091 24X
Fiche 50-324,83/05/04,8305130177

--8305130184 LER 83-044/03L-0 on 830408 & 09,during unit startup & power operations,control rods 02-27(02),34-03(04),34-23(02) & 30-11(03) had no indications for identified positions Caused by failed position reed switches.Reed switches replaced
PASTVA,M J Carolina Power & Light Co 83/05/04 Region 2,
Office of Director 1p 18440 092 24X Fiche 50-324,83/05/04,
8305130177

8305130167 Forwards LER 83-045/03L-0
DIETZ,C R Carolina Power & Light Co 83/05/05 O'REILLY,J P
Region 2, Office of Director 1p 18437 301 24X
Fiche 50-324,83/05/05,8305130167

--8305130172 LER 83-045/03L-0 on 830408,routine channel check of reactor level instrumentation revealed reactor level instrument 2-B21-LT-N017D-1 indicating higher actual level Caused by leak on bypass valve N017D-1 stem packing Packing adjusted
PASTVA,M J Carolina Power & Light Co 83/05/05 Region 2,
Office of Director 1p 18437 302 24X Fiche 50-324,83/05/05,
8305130167.

8305130170 Forwards LER 83-046/03L-0
DIETZ,C R Carolina Power & Light Co 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18439 191 24X
Fiche 50-324,83/05/06,8305130170

--8305130176 LER 83-046/03L-0 on 830410,wires to terminals 13 & 14 in terminal box for MSIV 2-B21-F028A found reversed Cause undetermined Wires reterminated to proper terminals
POULK,R M Carolina Power & Light Co. 83/05/06 Region 2,
Office of Director 1p 18439 192 24X Fiche 50-324,83/05/06,
8305130170

8305200538 Forwards supplemental LER 83-033/03L-1
DIETZ,C R Carolina Power & Light Co 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18514 260 24X
Fiche 50-324,83/05/06,8305200538

--8305200543 Supplemental LER 83-033/03L-1 on 830223,while performing
high steam line radiation channel calibr & functional test,
main steam line instrumant channels found out of calibr
Caused by instrument drift Drawers recalibr
POULK,R M Carolina Power & Light Co 83/05/06 Region 2,
Office of Director 3pp 18514 261 24X Fiche 50-324,83/05/06,
8305200538

DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305200625 Forwards Rev 8 to industrial security plan Changes do not
decrease effectiveness of plan or level of security Encl
withheld (ref 10CFR73 21 & 2 790)
HOWE,P W Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 2pp 18520 042 24X
Fiche 50-324,83/04/20,8305200625

8305200597 Forwards change to provisions of industrial security plan
Change will not decrease effectiveness of plan or level of
security Encl withheld (ref 10CFR73 21)
HOWE,P W Carolina Power & Light Co 83/04/28 O'REILLY,J P
Region 2, Office of Director 1p 18514 106 24X
Fiche 50-324,83/04/28,8305200597

8305100100 Forwards IE Safeguards Insp Repts 50-324/83-13 &
50-325/83-13 on 830411-15 No noncompliance noted
VERRELLI,A Division of Project & Resident Programs 83/05/05
UTLEY,E E Carolina Power & Light Co 2pp 18375 033 24X
Fiche 50-324,83/05/05,8305100100

--8305100109 IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on
830411-15 No noncompliance noted Major areas inspected audit
review,security plan,records,assessment aids,alarm stations
& training/qualification Details withheld (ref 10CFR73 21)
TOBIN,W J Region 2, Office of Director 83/05/04 1p
18375 035 24X Fiche 50-324,83/05/05,8305100100

8305110034 Generic Ltr 83-21 to all licensees of operating reactors,
applicants for OLs & holders of CPs re clarification of
access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305260134 Informs that NUREG-0737,Item III A 2 1 re emergency plan
upgrade to meet 10CFR50,App E requirements complete for
facility Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 UTLEY,E E
Carolina Power & Light Co 3pp 18649 049 24X
Fiche 50-324,83/05/18,8305260134

J Insurance & indemnity information

8305160135 Forwards Endorsement 48 to NELIA Policy NF-218
BARHAM,C D Carolina Power & Light Co 83/05/02 SALTZMAN,J NRC
- No Detailed Affiliation Given 2pp 18446 066 24X
Fiche 50-324,83/05/02,8305160135

P Operating license stage documents & correspondence

8305180001 Add1 response to FOIA request for seven categories of
documents re Brown & Root,Inc & South Texas project Forwards
App B documents Documents also available in PDR Add1
documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N
Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000,83/03/09,8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing
Major Brown & Root Corp nuclear const work & weld deficiency
status summarized Licensee will complete visual insp &
comply w/corrective actions in encl AWS Code
STELLO,V Office of Inspection & Enforcement, Office of the
Director 80/09/25 AHEARNE,J F Commissioners 5pp
18497 228 24X Fiche 50-000,83/03/09,8305180001

8305230283 Forwards capital cost analysis for backfitting expenditures
reflecting both actual costs & estimates for mods planned or
in progress
SMITH,S H Carolina Power & Light Co 83/03/22 TOURTELLOTTE,J
Regulatory Reform Task Force 13pp 18543 277 24X
Fiche 50-000,83/03/22,8305230283

8305230720 Forwards list of utils responding to requests for cost
figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305030463 Application for amend to Licenses DPR-62 & DPR-71,
supplementing 820616 request for miscellaneous Tech Spec
revs originally scheduled for completion during 820901
refueling outage Outage & mods to be completed by 830624
HOWE,P W Carolina Power & Light Co 83/04/28 VASSALLO,D B
Operating Reactors Branch 2 2pp 18308 222 24X
Fiche 50-324,83/04/28,8305030463

--8305030481 Proposed Tech Specs re safety-related hydraulic snubbers,
post-accident monitoring instrumentation,gas analyzer sys,
reactor coolant leakage detection sys & remote shutdown
monitoring instrumentation
* Carolina Power & Light Co 83/04/28 19pp 18308 224 24X
Fiche 50-324,83/04/28,8305030463

8305190099 Forwards safety evaluation for TMI Action Items I A 2 1 4,
"Upgrading of Reactor Operator & Senior Reactor Operator
Training" & II B 4, "Training for Mitigating Core Damage "
Training & requalification programs acceptable
VASSALLO,D B Operating Reactors Branch 2 83/04/29 UTLEY,E E
Carolina Power & Light Co 3pp 18523 175 24X
Fiche 50-324,83/04/29,8305190099

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees
re new procedures for providing public notice concerning
issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305060176 Application to amend License DPR-71 revising Tech Specs to
complete third refueling outage & begin Cycle 4 operation
Proposed changes revise control rod scram insertion time
requirements
HOWE,P W Carolina Power & Light Co 83/05/02 VASSALLO,D B
Operating Reactors Branch 2 2pp 18345 328 24X
Fiche 50-325,83/05/02,8305060176

--8305060180 Proposed Tech Spec changing control rod scram insertion tim
requirements to complete third refueling outage & begin
Cycle 4 operation
* Carolina Power & Light Co 83/05/02 30pp 18345 330 24X
Fiche 50-325,83/05/02,8305060176

8305090380 Ack receipt of 830131 ltr requesting add1 info re
NUREG-0737,Item II K 3 28, "Qualification of ADS Accumulator
Sys " Info requested from GE Response will be submitted by
830630
ZIMMERMAN,S R Carolina Power & Light Co 83/05/05 VASSALLO,D B
Operating Reactors Branch 2 1p 18363 340 24X
Fiche 50-324,83/05/05,8305090380

8305090456 Confirms 830419 responses to questions raised during 830418
telcon re spent fuel pool expansion
ZIMMERMAN,S R Carolina Power & Light Co 83/05/05 VASSALLO,D B
Operating Reactors Branch 2 2pp 18362 265 24X
Fiche 50-324,83/05/05,8305090456

8305230178 Forwards safety evaluation of util submittal re procedure
verification & design mod per NUREG-0737,Item II K 3 22,
"Automatic Switchover of RCIC Suction " Mods acceptable
VASSALLO,D B Operating Reactors Branch 2 83/05/05 UTLEY,E E
Carolina Power & Light Co. 5pp. 18546 356 24X
Fiche 50-324,83/05/05,8305230178

8305100362 Forwards Y1003J01A53, "Supplemental Reload Licensing
Submittal for Brunswick Steam Electric Plant,Unit 1,
Reload 3(W/o Recirculation Pump Trip)," inadvertently
omitted from 830502 Tech Spec rev request
ZIMMERMAN,S R Carolina Power & Light Co 83/05/06 VASSALLO,D B
Operating Reactors Branch 2 1p 18379 059 24X
Fiche 50-325,83/05/06,8305100362

--8305100370 "Supplemental Reload Licensing Submittal for Brunswick Steam
Electric Plant,Unit 1,Reload 3 (W/o Recirculation Pump
Trip) "
ZANARDI,G , HILL,R T , CHARNLEY,J S General Electric Co.
Y1003J01A53 83/01/31. 28pp 18379 060 24X
Fiche 50-325,83/05/06,8305100362

8305090659 Generic Ltr 83-20 to all operating reactor licensees &
holders of CPs re integrated scheduling for implementation
of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305120003 Responds to 830316 ltr requesting review of RCIC sys automatic restart per TMI Action Item II K 3 13 Acceptance criteria identified in ltr satisfied
ZIMMERMAN, S R Carolina Power & Light Co 83/05/09 VASSALLO, D B
Operating Reactors Branch 2 1p 18423 076 24X
Fiche 50-324, 83/05/09, 8305120003

8305260285 Forwards request for addl info re 810123 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/05/11 UTLEY, E E
Carolina Power & Light Co 3pp 18629 337 24X
Fiche 50-324, 83/05/11, 8305260285

8305240004 Informs that currently scheduled Unit 1 startup date is 830612 Outage critical path 8 days behind, but recovery plan instituted to make up time Requests Tech Spec changes be issued no later than 830612
HURFORD, W J Carolina Power & Light Co 83/05/17 VASSALLO, D B
Operating Reactors Branch 2 1p 18549 051 24X
Fiche 50-324, 83/05/17, 8305240004

8305240434 Commits to submit results of plant-unique calculations forming bases for mod program on Mark I containment vacuum breakers by 830630 in response to Generic Ltr 83-08 Calculations presented in listed documents
HOWE, P W Carolina Power & Light Co 83/05/19 VASSALLO, D B
Operating Reactors Branch 2 2pp 18571 061 24X
Fiche 50-324, 83/05/19, 8305240434

8305260320 Forwards NEDO-24582, "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 " Attachment detailing pressure/temp calculations also encl
ZIMMERMAN, S R Carolina Power & Light Co 83/05/24 VASSALLO, D B
Operating Reactors Branch 2 1p 18625 058 24X
Fiche 50-324, 83/05/24, 8305260320

--8305260325 "Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 "
* General Electric Co NEDO-24582 R01 81/10/31 61pp
18625 059 24X Fiche 50-324, 83/05/24, 8305260320

Q Inspection reports, IE Bulletins & correspondence

8305270531 Submits results of split sample taken from floor drain sample tank D for tritium & radiostrontium, per IE Insp Repts 50-324/82-09 & 50-325/82-09
DIETZ, C R Carolina Power & Light Co 83/02/25 O'REILLY, J P
Region 2, Office of Director 1p 18646 129 24X
Fiche: 50-324, 83/02/25, 8305270531

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co, of New York, Inc
12pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270461 Forwards IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/04/11 UTLEY, E E
Carolina Power & Light Co 2pp 18644 158 24X
Fiche 50-000, 83/04/11, 8305270461

--8305270474 IE Enforcement Conference Repts 50-261/83-10, 50-324/83-12 & 50-325/83-12 on 830328 No noncompliance noted Major areas discussed shipment of radwaste containing free liquid & inoperability of standby gas treatment deluge sys
LEWIS, R C Division of Project & Resident Programs 83/04/07
3pp 18644 160 24X Fiche 50-000, 83/04/11, 8305270474

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp, 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co, of New York, Inc 112pp 18383 089 24X Fiche, 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305270250 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/83-07 & 50-325/83-07
VERRELLI, D M Division of Project & Resident Programs 83/04/29
UTLEY, E E Carolina Power & Light Co 1p 18641 187 24X
Fiche 50-324, 83/04/29, 8305270250

--8305270256 Responds to NRC 830317 ltr re violations noted in IE Insp Repts 50-324/83-07 & 50-325/83-07 Corrective actions procedure revised & accepted by QA reflecting actual testing method & contractor personnel counseled
DIETZ, C R Carolina Power & Light Co 83/04/15 O'REILLY, J P
Region 2, Office of Director 2pp 18641 188 24X
Fiche 50-324, 83/04/29, 8305270290

--8305270263 Forwards IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/03/17
UTLEY, E E Carolina Power & Light Co 2pp 18641 190 24X
Fiche 50-324, 83/04/29, 8305270250

--8305270276 IE Insp Repts 50-324/83-07 & 50-325/83-07 on 830131-0203 & 07-11 Noncompliance noted failure to follow inservice insp procedure for recording angle beam data
COLEY, J L , BLAKE, J J Region 2, Office of Director 83/03/04
8pp 18641 193 24X Fiche 50-324, 83/04/29, 8305270250

8305060620 Responds to NRC 830218 ltr transmitting notice of violation & proposed imposition of civil penalties, per IE Insp Repts 50-324/82-28 & 50-325/82-28 Relay tests completed satisfactorily
UTLEY, E E Carolina Power & Light Co 83/05/02 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 27pp
18349 022 24X Fiche 50-324, 83/05/02, 8305060620

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305100100 Forwards IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted
VERRELLI, A Division of Project & Resident Programs 83/05/05
UTLEY, E E Carolina Power & Light Co 2pp 18375 033 24X
Fiche 50-324, 83/05/05, 8305100100

--8305100109 IE Safeguards Insp Repts 50-324/83-13 & 50-325/83-13 on 830411-15 No noncompliance noted Major areas inspected audit review, security plan, records, assessment aids, alarm stations & training/qualification Details withheld (ref 10CFR73 21)
TOBIN, W J , HALL, B Region 2, Office of Director MCGUIRE, D R
Division of Emergency Preparedness & Materials Safety 83/05/04
1p 18375 035 24X Fiche 50-324, 83/05/05, 8305100100

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270580 Ack receipt of 830318 & 0422 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45
LEWIS, R C Division of Project & Resident Programs 83/05/06
UTLEY, E E Carolina Power & Light Co 1p 18644 225 24X
Fiche 50-324, 83/05/06, 8305270580

--8305270598 Responds to NRC 830207 ltr re violations noted in IE Insp Repts 50-324/82-45 & 50-325/82-45 Corrective actions required rev to Q-list procedure will not be completed until 830527
DIETZ,C R Carolina Power & Light Co 83/05/23 O'REILLY,J P
Region 2, Office of Director 1p 18644 226 24X
Fiche 50-324,83/05/06,8305270580

--8305270599 Clarifies response to Violations B & C in IE Insp Repts 50-324/82-45 & 50-325/82-45 Program for determining type of alarm devices needing periodic calibr will not be completed by 830730
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J P
Region 2, Office of Director 2pp 18644 227 24X
Fiche 50-324,83/05/06,8305270580

--8305270610 Responds to violations noted in IE Insp Rept 50-324/82-45 & 50-325/82-45 Corrective actions engineering supervisor of discipline group responsible for performing review of tables for inconsistencies internal to procedure
DIETZ,C R Consumers Power Co 83/03/18 O'REILLY,J P Region 2, Office of Director 4pp 18644 229 24X Fiche 50-324, 83/05/06,8305270580

--8305270617 Ack receipt of 830207 ltr transmitting IE Insp Repts 50-324/82-45 & 50-325/82-45 Util continuing evaluation of violations Response to rept will be submitted by 830318
DIETZ,C R Carolina Power & Light Co 83/03/08 O'REILLY,J P
Region 2, Office of Director 1p 18644 233 24X
Fiche 50-324,83/05/06,8305270580

--8305270621 Forwards IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/02/07
UTLEY,E E. Carolina Power & Light Co 2pp 18644.234 24X
Fiche 50-324,83/05/06,8305270580

--8305270628 Notice of violation from insp on 821115-1215
* Region 2, Office of Director 83/02/07 2pp 18644 236 24X
Fiche 50-324,83/05/06,8305270580

--8305270635 IE Insp Repts 50-324/82-45 & 50-325/82-45 on 821115-1215 Noncompliance noted failure to adequately review procedure changes,to establish calibr procedures & to followup on corrective actions
MYERS,D O , GARNER,L W , BEMIS,P. Region 2, Office of Director 83/02/02 10pp 18644 238 24X Fiche 50-324,83/05/06,8305270580

8305270333 Forwards IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/05/10
UTLEY,E E Carolina Power & Light Co 2pp 18641·123 24X
Fiche 50-324,83/05/10,8305270333

--8305270342 IE Insp Repts 50-324/83-14 & 50-325/83-14 on 830418-21 No noncompliance noted Major areas inspected independent insp effort & observation of inservice insp work & work activities
COLEY,J L , BLAKE,J J Region 2, Office of Director 83/05/05
6pp 18641 125 24X Fiche 50-324,83/05/10,8305270333

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647.007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305100412 Forwards monthly operating repts for Apr 1983
DIETZ,C R Carolina Power & Light Co 83/05/05 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p
18378 066 24X Fiche 50-324,83/05/05,8305100412

--8305100417 Monthly operating repts for Apr 1983.
HARRISON,F Carolina Power & Light Co 83/05/03 12pp.
18378 067 24X Fiche 50-324,83/05/05,8305100412

S Reportable occurrences, LERs & related correspondence

8305030497 Nonroutine radiological environ event rept Results of 830308 gamma analysis of bottom sediment revealed high Co-60 concentration Samples will be taken monthly for Oct 1982 - June 1983 to determine if trends can be predicted
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 2pp 18306 183 24X
Fiche 50-324,83/04/20,8305030497

8305030505 RO 7-day specified time frame of four fire barrier limiting conditions for operation exceeded,to permit work in augmented offgas & control bldgs for installation of two plant mods Fire watches will remain in effect
DIETZ,C R Carolina Power & Light Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18308 197 24X
Fiche 50-325,83/04/20,8305030505

8305030387 Part 21 rept re pipe clamps for snubber/struts oriented in off-axis direction Initially reported on 830224 & by IE Info Notice 83-13 Clamps will be replaced by end of Fall 1983 refueling outage
DIETZ,C R Carolina Power & Light Co 83/04/22 O'REILLY,J.P
Region 2, Office of Director 2pp 18292 316 24X
Fiche 50-324,83/04/22,8305030387

8305030465 Forwards LER 83-017/03L-0
DIETZ,C R Carolina Power & Light Co 83/04/25 O'REILLY,J P.
Region 2, Office of Director 1p 18309 243 24X
Fiche 50-325,83/04/25,8305030465

--8305030473 LER 83-017/03L-0 on 830326-28 & 0402,listed control rods had no indications for identified positions Caused by loose prototypic inlet piping connectors in each rod attributed to undervessel work Plant mods scheduled
PASTVA,M J Carolina Power & Light Co 83/04/25 Region 2, Office of Director 1p 18308 244 24X Fiche 50-325,83/04/25, 8305030465

8305030291 Supplemental response to Part 21 rept re postulated pipe crack in HPCI,RCIC,reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program
DIETZ,C R Carolina Power & Light Co 83/04/26 O'REILLY,J P.
Region 2, Office of Director 1p 18300 061 24X
Fiche 50-324,83/04/26,8305030291

8305050201 RO review of fire protection sys documentation revealed 17 sys limiting conditions for operation exceeding respective time frames not reported to NRC Plant operations instructions revised & special training provided
DIETZ,C R Carolina Power & Light Co 83/04/26 O'REILLY,J P
Region 2, Office of Director 2pp. 18342 152 24X
Fiche 50-325,83/04/26,8305050201

8305050143 RO on 830325,fire barrier limiting condition for operation generated to permit accessing fire door in augmented offgas bldg Caused by temporary routing of flush lines for plant mod Mod work completed on 830411
DIETZ,C.R Carolina Power & Light Co 83/04/28 O'REILLY,J P
Region 2, Office of Director 1p 18341 104 24X
Fiche 50-325,83/04/28,8305050143

8305110282 Forwards LER 83-014/03L-0
DIETZ,C R Carolina Power & Light Co 83/05/04 O'REILLY,J.P
Region 2, Office of Director 1p 18393 248 24X
Fiche 50-325,83/05/04,8305110282

--8305110284 LER 83-014/03L-0 on 830406 & 08,during ongoing refueling, control rods 46-35,22-19,14-11,42-31 & 46-31 had no indications for identified positions Caused by loose or defective prototypic inlet piping connectors
PASTVA,M J Carolina Power & Light Co 83/05/04 Region 2, Office of Director 2pp 18393 249 24X Fiche 50-325,83/05/04, 8305110282

8305130108 RO on 830404,fire barrier limiting conditions for operation initiated on penetration seal CB-2-301 of Fire Door 221 Caused by need to allow ambient air circulation due to inoperability of computer room air conditioner
DIETZ,C R Carolina Power & Light Co 83/05/05 O'REILLY,J P
Region 2, Office of Director, 1p 18437 290 24X
Fiche 50-325,83/05/05,8305130108

DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/23
PARRIS, H G Tennessee Valley Authority 2pp 18641 153 24X
Fiche 50-327, 83/03/23, 8305270313

--8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection, shipment of radioactive matl, IE Bulletin 80-10, IE Circular 82-49 & health physics retraining
COLLINS, T R , BARR, K P Region 2, Office of Director 83/03/22
9pp. 18641 155 24X Fiche 50-327, 83/03/23, 8305270313

8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan
NOVAK, T M Assistant Director for Licensing 83/05/04 PARRIS, H G Tennessee Valley Authority 5pp 18503 343 24X
Fiche 50-327, 83/05/04, 8305180213

--8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan
EISENHUT, D G Division of Licensing 83/05/04 4pp 18503 348
24X Fiche 50-327, 83/05/04, 8305180213

--8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/04 2pp 18503 352 24X
Fiche 50-327, 83/05/04, 8305180213

--8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 3pp
18503 354 24X Fiche 50-327, 83/05/04, 8305180213

8305100101 Responds to 830505 telcon request re review of proposed physical security plan Plan to be revised by plant operations review committee Changes have not reduced nuclear safety.
MILLS, L M Tennessee Valley Authority 83/05/05 ADENSAM, E
Licensing Branch 4 1p 18377 114 24X Fiche 50-327, 83/05/05, 8305100101.

8305130041 Withdraws 801231 request for Tech Spec change re number of fire detectors Change no longer necessary
KAMMER, D S Tennessee Valley Authority 83/05/09 ADENSAM, E
Licensing Branch 4 1p 18436.262 24X Fiche 50-327, 83/05/09, 8305130041.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305260372 Requests remittance of balance due for review of 820921 application to amend Browns Ferry 1 Tech Specs re Cycle 5 MCPR values & 820623 application re physical security plan changes for Sequoyah 1 & 2
MILLER, W G License Fee Management Branch. 83/05/20 PARRIS, H G
Tennessee Valley Authority 2pp 18647 284 24X
Fiche: 50-000, 83/05/20, 8305260372

8305310167 Forwards rev to util 830303 response to NRC 821112 request for addl info on fire protection program Rev clarifies instrumentation loops, identified by fire shutdown logic diagram, as being required for hot & cold shutdown
MILLS, L M Tennessee Valley Authority 83/05/27 ADENSAM, E
Licensing Branch 4 6pp 18652 290 24X Fiche: 50-327, 83/05/27, 8305310167

J Insurance & indemnity information

8305040243 Forwards Endorsements 32 & 26 to NELIA Policy NF-247 & MAELU Policy MF-102, respectively
DUCK, J R Marsh & McLennan, Inc 83/04/29 SALTZMAN, J Assistant
Director for State & Licensee Relations 3pp 18323 244 24X
Fiche: 50-327, 83/04/29, 8305040243

P Operating license stage documents & correspondence

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M
Division of Rules and Records 1p 18593 178 24X
Fiche 50-000, 83/03/11, 8305240249

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305110246 Forwards Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs re upper head injection accumulator water level setpoint & tolerances
ADENSAM, E G Licensing Branch 4 83/05/03 PARRIS, H G Tennessee
Valley Authority 3pp 18434 298 24X Fiche 50-327, 83/05/03, 8305110246

--8305110249 Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, revising Tech Specs re upper head injection accumulator water level setpoint & tolerance
ADENSAM, E G Licensing Branch 4 83/05/03 8pp 18434 301 24X
Fiche 50-327, 83/05/03, 8305110246

--8305110250 Safety evaluation supporting Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp
18434 309 24X Fiche 50-327, 83/05/03, 8305110246

--8305110253 Notice of issuance & availability of Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/03 3pp 18434 312 24X
Fiche 50-327, 83/05/03, 8305110246

8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan
NOVAK, T M Assistant Director for Licensing 83/05/04 PARRIS, H G
Tennessee Valley Authority 5pp 18503 343 24X
Fiche 50-327, 83/05/04, 8305180213

--8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan
EISENHUT, D G Division of Licensing 83/05/04 4pp 18503 348
24X Fiche 50-327, 83/05/04, 8305180213

--8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/04 2pp 18503 352 24X
Fiche 50-327, 83/05/04, 8305180213

--8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 3pp
18503 354 24X Fiche 50-327, 83/05/04, 8305180213

8305160362 Forwards Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends change Tech Specs to reflect Class IE bus installation
ADENSAM, E G Licensing Branch 4 83/05/05 PARRIS, H G Tennessee
Valley Authority 2pp 18472 016 24X Fiche 50-327, 83/05/05, 8305160362

--8305160366 Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs to reflect installation of second level of undervoltage protecton for Class IE buses
ADENSAM, E. G Licensing Branch 4 83/05/05 24pp 18472 018
24X Fiche 50-327, 83/05/05, 8305160362

--8305160368 Safety evaluation supporting Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 3pp
18472 042 24X Fiche 50-327, 83/05/05, 8305160362

--8305160369 Notice of issuance & availability of Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/05 4pp 18472 045 24X
Fiche 50-327, 83/05/05, 8305160362

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305130029 Informs that corrected Page 3/4 6-20 to Amend 20 to License DPR-77 will be reissued Page includes valve FCV-77-20 in Table 3 6-2 Valve inadvertently omitted from original issuance due to clerical error
KAMMER,D S Tennessee Valley Authority 83/05/09 ADENSAM,E Licensing Branch 4 1p 18437 009 24X Fiche 50-327,83/05/09, 8305130029

8305170145 Responds to 830426 ltr re SER on environ qualification of safety-related electrical equipment Review identified no item in NRC Category II B requiring justification for continued operation
MILLS,L M Tennessee Valley Authority 83/05/12 ADENSAM,E Licensing Branch 4 1p 18466 284 24X Fiche 50-327,83/05/12, 8305170145

8305240394 Forwards info re environ qualification of electric equipment important to safety,per 10CFR50 49(g) Listing of electrical equipment & schedule for qualification or replacement of remaining equipment provided
KAMMER,D S Tennessee Valley Authority 83/05/20 ADENSAM,E Licensing Branch 4 79pp 18574 197 24X Fiche 50-327,83/05/20, 8305240394

8305310053 Application for amend to Licenses DPR-77 & DPR-79 requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys
MILLS,L M Tennessee Valley Authority 83/05/25 ADENSAM,E G Licensing Branch 4 2pp 18653 166 24X Fiche 50-327,83/05/25, 8305310053

--8305310057 Proposed Tech Spec requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys
* Tennessee Valley Authority 83/05/25 6pp 18653 168 24X Fiche 50-327,83/05/25,8305310053

8305310189 Advises that Tech Spec changes authorized by Amend 29 to License DPR-77 & Amend 18 to License DPR-79 will be implemented upon completion of undervoltage mods,scheduled to occur before Unit 2 refueling outage
MILLS,L M Tennessee Valley Authority 83/05/26 ADENSAM,E Licensing Branch 4 1p 18658 151 24X Fiche 50-327,83/05/26, 8305310189

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/23 PARRIS,H G Tennessee Valley Authority 2pp 18641 153 24X Fiche 50-327,83/03/23,8305270313

--8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection,shipment of radioactive matl,IE Bulletin 80-10, IE Circular 82-49 & health physics retraining
COLLINS,T R , BARR,K P Region 2, Office of Director 83/03/22 9pp 18641 155 24X Fiche 50-327,83/03/23,8305270313

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382.282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697.009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

8305310077 Advises that reinsp of low pressure turbine disks during Cycle 1 refueling outage revealed four minor indications determined to be assembly scratches or tool marks & not cracks License Condition 2 C (8) satisfied
MILLS,L M Tennessee Valley Authority 83/05/26 ADENSAM,E Licensing Branch 4, 1p 18655 122 24X Fiche 50-327,83/05/26, 8305310077

R Periodic operating reports & related correspondence

8305240323 Monthly operating repts for Apr 1983 W/830513 ltr
MASON,C C , DUPREE,D Tennessee Valley Authority 83/05/09 NRC - No Detailed Affiliation Given 24pp 18548 040 24X Fiche 50-327,83/05/09,8305240323

S Reportable occurrences, LERs & related correspondence

8304190499 Forwards LER 83-043/01T-0
GREEN,H J Tennessee Valley Authority 83/04/13 O'REILLY,J P Region 2, Office of Director 1p 18054 026 24X Fiche 50-327,83/04/13,8304190499

--8304190537 LER 83-043/01T-0 on 830331,all four 125-volt dc vital battery channels declared inoperable due to failure to perform weekly insp surveillance within required frequency Caused by personnel error Performance test completed.
ROGERS,H R. , HARDING,M R Tennessee Valley Authority 83/04/13 Region 2, Office of Director 2pp 18054 027 24X Fiche 50-327,83/04/13,8304190499

8305030176 Forwards LER 83-045/03L-0
GREEN,H J Tennessee Valley Authority 83/04/26 O'REILLY,J P. Region 2, Office of Director. 1p 18300 267 24X Fiche 50-327,83/04/26,8305030176

--8305030183 LER 83-045/03L-0 on 830401,06 & 10,steam generator 1 wide-range level channel declared inoperable after failing low Caused by faulty recorder 1-LR-3-43,probably due to defective switches in connector Recorder replaced
ROGERS,H R , HARDING,M R Tennessee Valley Authority 83/04/26
Region 2, Office of Director 1p 18300 268 24X
Fiche 50-327,83/04/26,8305030176

8305030569 Forwards LER 83-048/03L-0
GREEN,H J Tennessee Valley Authority 83/04/26 O'REILLY,J P
Region 2, Office of Director 1p 18303 300 24X
Fiche 50-327,83/04/26,8305030569

--8305030579 LER 83-048/03L-0 on 830328,discovered that on 820911 & 830108,certain main steam safety relief valves failed to meet required setpoint criteria Caused by normal aging of valve spring & ambient temp variations Valves adjusted
CARVER,A M , HARDING,M R Tennessee Valley Authority 83/04/26
Region 2, Office of Director 2pp 18303 301 24X
Fiche 50-327,83/04/26,8305030569

8305050183 Forwards LER 83-047/03L-0
GREEN,H J Tennessee Valley Authority 83/04/27 O'REILLY,J P
Region 2, Office of Director 1p 18338 151 24X
Fiche 50-327,83/04/27,8305050183

--8305050206 LER 83-047/03L-0 on 830409,RCS subcooling margin monitor declared inoperable due to failure of plant computer Computer failure caused by memory parity error Computer restarted & monitor restored
ROGERS,H R , HARDING,M R Tennessee Valley Authority 83/04/27
Region 2, Office of Director 1p 18338 152 24X
Fiche 50-327,83/04/27,8305050183

8305050123 Forwards LER 83-053/03L-0
GREEN,H J Tennessee Valley Authority 83/04/29 O'REILLY,J P
Region 2, Office of Director 1p 18341 037 24X
Fiche 50-327,83/04/29,8305050123

--8305050128 LER 83-053/03L-0 on 830331,during review of maint requests, discovered that on 830319 steam generator blowdown isolation valve 1-FC-1-14 would not stay open & Surveillance Instruction SI-166 6 post-maint stroke test not performed
CARVER,A M , HARDING,M R Tennessee Valley Authority 83/04/29
Region 2, Office of Director 1p 18341 038 24X
Fiche 50-327,83/04/29,8305050123

8305110325 Forwards LER 83-054/03L-0
GREEN,H J Tennessee Valley Authority 83/05/05 O'REILLY,J P
Region 2, Office of Director 1p 18406 160 24X
Fiche 50-327,83/05/05,8305110325

--8305110329 LER 83-054/03L-0 on 830406,while performing Special Test 88-STEAR-INST-83-3,containment isolation valve 1-FCV-1-182 failed to open Valve repaired but failed again 2 days later Caused by excessive wear Parts replaced
LUDWIG,W C , HARDING,M R Tennessee Valley Authority, 83/05/05
Region 2, Office of Director, 1p 18406 161 24X
Fiche 50-327,83/05/05,8305110325

8305110373 Forwards LER 83-052/03L-0
GREEN,H J Tennessee Valley Authority 83/05/05 O'REILLY,J P
Region 2, Office of Director 1p 18406 256 24X
Fiche 50-327,83/05/05,8305110373

--8305110382 LER 83-052/03L-0 on 830407,while running shortened interval of Surveillance Instruction 196,two of four level switches found out of tolerance Probably caused by instrument drift or calibr techniques Switches calibr
LUDWIG,W C , HARDING,M R, Tennessee Valley Authority 83/05/05
Region 2, Office of Director 2pp 18406 257 24X
Fiche 50-327,83/05/05,8305110373

8305200577 Forwards LER 83-055/03L-0
GREEN,H J Tennessee Valley Authority 83/05/12 O'REILLY,J P
Region 2, Office of Director 1p 18514 126 24X
Fiche 50-327,83/05/12,8305200577

--8305200581 LER 83-055/03L-0 on 830415,bank D movable control assembly declared inoperable due to failure to move rods after receiving rod control sys urgent alarm Caused by blown phase C ref voltage fuse FU-10 Fuse replaced
ROGERS,H R , HARDING,M R Tennessee Valley Authority 83/05/12
Region 2, Office of Director 1p 18514 127 24X
Fiche 50-327,83/05/12,8305200577

8305200427 Forwards LER 83-056/01T-0
GREEN,H.J. Tennessee Valley Authority 83/05/13 O'REILLY,J P
Region 2, Office of Director, 1p 18517 151 24X
Fiche: 50-327,83/05/13,8305200427,

--8305200432 LER 83-056/01T-0 on 830503,upper containment airlock inner door discovered inoperable Caused by sheared stud & failed cam follower bearing on latching mechanism Mechanism repaired & returned to svc
LUDWIG,W C , HARDING,M R Tennessee Valley Authority 83/05/03
Region 2, Office of Director 3pp 18517 152 24X
Fiche 50-327,83/05/13,8305200427

8305230530 Forwards LER 83-056/01T-0
GREEN,H J Tennessee Valley Authority 83/05/16 O'REILLY,J P
Region 2, Office of Director 1p 18537 055 24X
Fiche 50-327,83/05/16,8305230530

--8305230536 LER 83-056/01T-0 on 830503,inner door to upper containment airlock discovered inoperable Caused by sheared stud on latching mechanism & failed cam follower bearing allowing outer door to open while inner door not closed
LUDWIG,W C , HARDING,M R Tennessee Valley Authority 83/05/16
Region 2, Office of Director 3pp 18537 056 24X
Fiche 50-327,83/05/16,8305230530

8305250526 LER 83-058/03L-0 on 830420,while in Mode 1,turbine bldg sump radiation monitor declared inoperable due to failure to meet surveillance requirements Caused by debris from sump blocking flow switch Flow switch cleaned W/830518 ltr
ROGERS,H R , HARDING,M R , GREEN,H J Tennessee Valley Authority
83/05/18 O'REILLY,J P Region 2, Office of Director 2pp
18593 341 24X Fiche 50-327,83/05/18,8305250526

8305250532 LER 83-063/03L-0 on 830421,pressurizer PORV 1-PCV-6F-340A failed to open Caused by failed coil in ASCO solenoid model LB831654 Valve will be repaired at first outage of sufficient duration W/830518 ltr
HARDING,M R , LUDWIG,W C , GREEN,H J Tennessee Valley Authority
83/05/18 O'REILLY,J P Region 2, Office of Director 2pp
18588 227 24X Fiche 50-327,83/05/18,8305250532

8305260307 NPDES noncompliance notification on 830326 & 28,temp rise between upstream ambient monitor & downstream river monitor exceeded 5 4 F limit Caused by low riverflows Cooling tower & increased riverflows used to eliminate delta temp changes
EL-ASHRY,M T Tennessee Valley Authority 83/05/23 MARLAR,J
Environmental Protection Agency 8pp 18625 336 24X
Fiche 50-327,83/05/23,8305260307

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of addl sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste
MILLER,W O License Fee Management Branch 83/04/22 MILLS,L M
Tennessee Valley Authority 2pp 18309 193 24X
Fiche 50-000,83/04/22,8305030679

DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/23
PARRIS,H G Tennessee Valley Authority 2pp 18641 153 24X
Fiche 50-327,83/03/23,8305270313

--8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection,shipment of radioactive matl,IE Bulletin 80-10, IE Circular 82-49 & health physics retraining
COLLINS,T R Region 2, Office of Director 83/03/22 9pp
18641 155 24X Fiche 50-327,83/03/23,8305270313

8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively,safety evaluation & notice of issuance & availability Amends revise license conditions to include Commission approved guard training & qualification plan
NOVAK,T M Assistant Director for Licensing 83/05/04 PARRIS,H G
Tennessee Valley Authority 5pp 18503 343 24X
Fiche 50-327,83/05/04,8305180213

--8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79,respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan
EISENHUT,D G Division of Licensing 83/05/04 4pp 18503 348
24X Fiche 50-327,83/05/04,8305180213

--8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79,respectively
ADENSAM,E G Licensing Branch 4 83/05/04 2pp 18503 352 24X
Fiche 50-327,83/05/04,8305180213

--8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 3pp 18503 354. 24X Fiche 50-327, 83/05/04, 8305180213

8305100101 Responds to 830505 telcon request re review of proposed physical security plan Plan to be revised by plant operations review committee Changes have not reduced nuclear safety
MILLS, L M Tennessee Valley Authority 83/05/05 ADENSAM, E Licensing Branch 4 1p 18377 114 24X Fiche 50-327, 83/05/05, 8305100101

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche. 50-000, 83/05/11, 8305110034

8305260372 Requests remittance of balance due for review of 820921 application to amend Browns Ferry 1 Tech Specs re Cycle 5 MCPR values & 820623 application re physical security plan changes for Sequoyah 1 & 2.
MILLER, W. O License Fee Management Branch 83/05/20 PARRIS, H G Tennessee Valley Authority. 2pp 18647 284 24X Fiche 50-000, 83/05/20, 8305260372

8305310167 Forwards rev to util 830303 response to NRC 821112 request for addl info on fire protection program. Rev clarifies instrumentation loops, identified by fire shutdown logic diagram, as being required for hot & cold shutdown
MILLS, L M Tennessee Valley Authority 83/05/27 ADENSAM, E Licensing Branch 4 6pp 18652 290 24X Fiche 50-327, 83/05/27, 8305310167

J Insurance & indemnity information

8305040243 Forwards Endorsements 32 & 26 to NELIA Policy NF-247 & MAELU Policy MF-102, respectively
DUCK, J R Marsh & McLennan, Inc 83/04/29 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18323 244 24X Fiche: 50-327, 83/04/29, 8305040243

P. Operating license stage documents & correspondence

8305040084 Ack receipt of 830304 application for rev of License Condition 2.C(14) Fee exemption request denied Payment of Class II fee requested
DIGGS, R M License Fee Management Branch 83/04/26 PARRIS, H G Tennessee Valley Authority. 1p 18336.332 24X Fiche 50-328, 83/04/26, 8305040084

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305110246 Forwards Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends revise Tech Specs re upper head injection accumulator water level setpoint & tolerances
ADENSAM, E. G Licensing Branch 4 83/05/03 PARRIS, H G Tennessee Valley Authority. 3pp. 18434 298 24X Fiche 50-327, 83/05/03, 8305110246.

--8305110249 Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively, revising Tech Specs re upper head injection accumulator water level setpoint & tolerance.
ADENSAM, E G. Licensing Branch 4 83/05/03 8pp 18434 301. 24X Fiche 50-327, 83/05/03, 8305110246

--8305110250 Safety evaluation supporting Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp 18434 309. 24X Fiche 50-327, 83/05/03, 8305110246

--8305110253 Notice of issuance & availability of Amends 28 & 17 to Licenses DPR-77 & DPR-79, respectively.
ADENSAM, E. G. Licensing Branch 4 83/05/03 3pp 18434 312 24X Fiche. 50-327, 83/05/03, 8305110246

8305180213 Forwards Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability. Amends revise license conditions to include Commission approved guard training & qualification plan
NOVAK, T M Assistant Director for Licensing. 83/05/04. PARRIS, H G Tennessee Valley Authority 5pp 18503.343 24X Fiche: 50-327, 83/05/04, 8305180213

--8305180224 Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively, revising license conditions to include Commission approved guard training & qualification plan & safeguards contingency plan
EISENHUT, D G Division of Licensing 83/05/04 4pp 18503 348 24X Fiche 50-327, 83/05/04, 8305180213

--8305180234 Notice of issuance & availability of Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/04 2pp 18503 352 24X Fiche 50-327, 83/05/04, 8305180213

--8305180248 Safety evaluation supporting Amends 30 & 19 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/04 3pp 18503 354 24X Fiche 50-327, 83/05/04, 8305180213

8305160362 Forwards Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, safety evaluation & notice of issuance & availability Amends change Tech Specs to reflect Class IE bus installation
ADENSAM, E G Licensing Branch 4 83/05/05 PARRIS, H G Tennessee Valley Authority 2pp 18472 016 24X Fiche 50-327, 83/05/05, 8305160362

--8305160366 Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively, changing Tech Specs to reflect installation of second level of undervoltage protecton for Class IE buses
ADENSAM, E G. Licensing Branch 4 83/05/05 24pp 18472 018 24X Fiche 50-327, 83/05/05, 8305160362

--8305160368 Safety evaluation supporting Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 3pp 18472 042 24X Fiche 50-327, 83/05/05, 8305160362

--8305160369 Notice of issuance & availability of Amends 29 & 18 to Licenses DPR-77 & DPR-79, respectively
ADENSAM, E G Licensing Branch 4 83/05/05 4pp 18472 045 24X Fiche 50-327, 83/05/05, 8305160362

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627.153 24X Fiche 50-000, 83/05/09, 8305090659

8305130029 Informs that corrected Page 3/4 6-20 to Amend 20 to License DPR-77 will be reissued Page includes valve FCV-77-20 in Table 3 6-2 Valve inadvertently omitted from original issuance due to clerical error
KAMMER, D S Tennessee Valley Authority 83/05/09 ADENSAM, E Licensing Branch 4 1p. 18437 009 24X Fiche 50-327, 83/05/09, 8305130029

8305170145 Responds to 830426 ltr re SER on environ qualification of safety-related electrical equipment Review identified no item in NRC Category II B requiring justification for continued operation
MILLS, L M Tennessee Valley Authority 83/05/12 ADENSAM, E Licensing Branch 4 1p 18466 284 24X Fiche 50-327, 83/05/12, 8305170145

8305240394 Forwards info re environ qualification of electric equipment important to safety, per 10CFR50 49(g) Listing of electrical equipment & schedule for qualification or replacement of remaining equipment provided
KAMMER, D S Tennessee Valley Authority 83/05/20 ADENSAM, E Licensing Branch 4 79pp 18574 197 24X Fiche 50-327, 83/05/20, 8305240394

8305310053 Application for amend to Licenses DPR-77 & DPR-79 requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys
MILLS, L M Tennessee Valley Authority 83/05/25 ADENSAM, E G Licensing Branch 4 2pp 18653 166 24X Fiche 50-327, 83/05/25, 8305310053

--8305310057 Proposed Tech Spec requesting temporary change in Limiting Condition for Operation 3 8 2 1 a for onsite power distribution sys
* Tennessee Valley Authority 83/05/25 6pp 18653 168 24X Fiche 50-327, 83/05/25, 8305310053

8305310189 Advises that Tech Spec changes authorized by Amend 29 to License DPR-77 & Amend 18 to License DPR-79 will be implemented upon completion of undervoltage mods, scheduled to occur before Unit 2 refueling outage
MILLS, L M Tennessee Valley Authority 83/05/26 ADENSAM, E Licensing Branch 4. 1p 18658 151 24X Fiche 50-327, 83/05/26, 8305310189.

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270313 Forwards IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/23
PARRIS, H G Tennessee Valley Authority 2pp 18641 153 24X
Fiche 50-327,83/03/23,8305270313

--8305270322 IE Insp Repts 50-327/83-03 & 50-328/83-03 on 830214-18 No noncompliance noted Major areas inspected radiation protection, shipment of radioactive matl, IE Bulletin 80-10, IE Circular 82-49 & health physics retraining
COLLINS, T R , BARR, K P Region 2, Office of Director 83/03/22 9pp 18641 155 24X Fiche 50-327,83/03/23,8305270313

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18393 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305240323 Monthly operating repts for Apr 1983 W/830513 ltr
MASON, C C , DUPREE, D Tennessee Valley Authority 83/05/09 NRC - No Detailed Affiliation Given 24pp 18548 040 24X
Fiche 50-327,83/05/09,8305240323

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000,83/04/19,8305230573

8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
MILLS, L M Tennessee Valley Authority 83/04/27 O'REILLY, J P
Region 2, Office of Director 3pp 18341 083 24X
Fiche 50-000,83/04/27,8305050152

8305050218 Forwards LER 83-046/03L-0
GREEN, H J Tennessee Valley Authority 83/04/27 O'REILLY, J P
Region 2, Office of Director 1p 18338 092 24X
Fiche 50-328,83/04/27,8305050218

--8305050224 LER 83-046/03L-0 on 830401, RCS subcooling margin monitor declared inoperable due to failure of plant computer Computer failure caused by attempt to run program loaded on faulty disc Program reloaded to different area of disc
ROGERS, H R , HARDING, M R. Tennessee Valley Authority 83/04/27
Region 2, Office of Director 1p 18338 093 24X
Fiche 50-328,83/04/27,8305050218

8305050211 Forwards LER 83-051/03L-0
GREEN, H J Tennessee Valley Authority 83/04/29 O'REILLY, J P
Region 2, Office of Director 1p 18338-110 24X
Fiche 50-328,83/04/29,8305050211

--8305050217 LER 83-051/03L-0 on 830401, safety injection sys boron injection tank inlet shutoff valve 2-FCV-63-40 would not operate Caused by dirty motor starter contactors Contactors cleaned & screw connections tightened
CARVER, A M , HARDING, M R Tennessee Valley Authority 83/04/29
Region 2, Office of Director 1p 18338 111 24X
Fiche 50-328,83/04/29,8305050211

8305110409 Forwards LER 83-050/03L-0
GREEN, H J Tennessee Valley Authority. 83/05/06 O'REILLY, J P
Region 2, Office of Director. 1p 18392 002 24X
Fiche 50-328,83/05/06,8305110409

--8305110419 LER 83-050/03L-0 on 830413, control rod D-8 failed to move w/rest of bank upon demand & became misaligned by more than 12 steps Caused by inoperable lift coil due to open connection at vessel head
ROGERS, H R., HARDING, M R Tennessee Valley Authority 83/05/06
Region 2, Office of Director 1p 18392 003 24X
Fiche 50-328,83/05/06,8305110409

8305250342 LER 83-060/03L-0 on 830419, automatic control valve 2-LCV-3-154 in auxiliary feedwater sys failed to open on demand Caused by incorrect size of metering orifice Correct parts installed W/830519 ltr
GREEN, H J , ROGERS, H R , HARDING, M R Tennessee Valley Authority 83/05/18 O'REILLY, J P Region 2, Office of Director 4pp. 18585 355 24X Fiche 50-328,83/05/18,8305250342

8305250380 LER 83-062/03L-0 on 830421, three of four level switches in upper head injection sys discovered out of tolerance On 830505, all four switches found out of tolerance Caused by instrument drift Switches recalibr W/830518 ltr
LUDWIG, W C , HARDING, M R Tennessee Valley Authority. 83/05/18. O'REILLY, J P Region 2, Office of Director. 2pp 18585 347 24X
Fiche 50-328,83/05/18,8305250380

8305250400 LER 83-064/03L-0 on 830420,auxiliary feedwater automatic valve 2-LCV-3-148 failed to close on demand from control board Caused by failure of Beckman Model 8813-2098-0200 controller due to faulty voltage W/830518 ltr
ROGERS,H R , HARDING,M R , GREEN,H J Tennessee Valley Authority 83/05/18 O'REILLY,J P Region 2, Office of Director 2pp 18585 035 24X Fiche 50-328,83/05/18,8305250400

8305250433 LER 83-059/03L-0 on 830422,while in Mode 1,rod position indication For rod C-5 in shutdown bank D misaligned by 12 steps & declared inoperable Cause unknown Rod position indicator & cable verified W/830519 ltr
HARDING,M R , GREEN,H J Tennessee Valley Authority 83/05/19 O'REILLY,J P Region 2, Office of Director 2pp 18585 287 24X Fiche 50-328,83/05/19,8305250433

8305260307 NPDES noncompliance notification on 830326 & 28,temp rise between upstream ambient monitor & downstream river monitor exceeded 5 4 F limit Caused by low riverflows Cooling tower & increased riverflows used to eliminate delta temp changes
EL-ASHRY,M T Tennessee Valley Authority 83/05/23 MARLAR,J Environmental Protection Agency 8pp 18625 336 24X Fiche 50-327,83/05/23,8305260307

X Onsite Storage of Low Level Waste

8305030679 Requests remittance of addl sum to complete payment of 800731 & 1124 amend applications to permit storage of low level radwaste
MILLER,W O License Fee Management Branch 83/04/22 MILLS,L M Tennessee Valley Authority 2pp 18309 193 24X
Fiche 50-000,83/04/22,8305030679

DOCKET 50-329 MIDLAND PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305060379 Notification of contract execution,Mod 6 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 " Contractor Geotechnical Engineers, Inc
FIELDS,J A Division of Contracts NRC-03-82-092 83/04/12
VOLLMER,R H Division of Engineering KANE,J NRC - No Detailed Affiliation Given 1p 18353 026 24X Fiche 50-329,83/04/12,
8305060379

--8305060384 Mod 6,modifying monthly business ltr reporting requirements, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 "
POULOS,S J Geotechnical Engineers, Inc GUSTAVE,R P Division of Contracts NRC-03-82-092 83/04/12 3pp 18353 087 24X
Fiche 50-329,83/04/12,8305060379

8304220515 Forwards revised affidavits for individuals previously employed by NRC now working on independent design & const verification program Clarification of "providing safety evaluation" also submitted
LEVIN,H A TERA Corp 83/04/21 KEPPLER,J G Region 3, Office of Director 15pp 18133 273 24X Fiche 50-329,83/04/21,8304220515

8305020565 Responds to 830325 ltr re TERA Corp QA & engineering plans for independent design & const verification program for facilities NRC comments on reporting requirements proposed by TERA Corp at 830413 meeting will be provided
REHM,T Office of the Executive Director for Operations 83/04/22
GORDE,B P Government Accountability Project 2pp 18284 238, 24X
Fiche 50-329,83/04/22,8305020565

8305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Topical Rept CPC-1A, "QA Manual for Midland Nuclear Plant,Vol 1 "
MILLER,W O License Fee Management Branch 83/04/25 BYRD,W Consumers Power Co 1p 18367 361 24X Fiche 50-329,83/04/25,
8305090551

8305170131 Informs of review completion for listed activities re remedial soils work Concurrence requested
MILLER,D B Consumers Power Co 83/04/28 HARRISON,J J Region 3, Office of Director 2pp 18466 265 24X Fiche 50-329,83/04/28,
8305170131

8305170539 Forwards Vol 5 of "Seismic Margin Review Diesel Generator Bldg "
COOK,J W Consumers Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18469 036 24X
Fiche 50-329,83/04/28,8305170539

--8305170544 Vol 5 of "Seismic Margin Review Diesel Generator Bldg "
WEBLEY,D A , KENNEDY,R P , KINCAID,R H Structural Mechanics Associates SMA 13701 05R003 V05 83/04/30 113pp 18469 041 24X Fiche 50-329,83/04/28,8305170539

8305170422 Forwards change specs for "Pier W11 - Load Recycling Procedure," for remedial soils work,per NRC-util work authorization procedure
MILLER,D B Consumers Power Co 83/04/29 HARRISON,J J Region 3 Office of Director 2pp 18469 286 24X Fiche 50-329,83/04/29
8305170422

8305060483 Documents 830413 telcon Util commitment to provide keeping air ejector radiation monitors deleted from FSAR Chapter 11 5 Potential relaxation of tritium sampling requirement discussion deferred pending effluent Tech Spec review
COOK,J W Consumers Power Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18345,360 241
Fiche 50-329,83/05/02,8305060483

8305170467 Requests concurrence w/proposed changes to approved work activity to perform load test at Pier 11W
MILLER,D B Consumers Power Co 83/05/02 HARRISON,J J Region 3 Office of Director 2pp 18470 075 24X Fiche 50-329,83/05/02,
8305170467

8305110140 Accepts TERA Corp as independent third-party to perform review of design & const verification program re Unit 2 auxiliary feedwater sys
NOVAK,T M Assistant Director for Licensing 83/05/03 COOK,J W Consumers Power Co 7pp 18421 351 24X Fiche 50-329,83/05/03,
8305110140

8305170397 Requests authorization for remedial soils work to install Bulkheads E10 & W10 & to install,load & excavate Piers 8E, 8W, 10E & 10W
MILLER,D B Consumers Power Co 83/05/03 HARRISON,J J Region 3 Office of Director 1p 18469 231 24X Fiche 50-329,83/05/03,
8305170397

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04,
8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche: 50-000,83/05/09,8305090659

8305190065 Requests authorization to begin Remedial Soils Work Activities 407050400,shallow probing for Phase II & 202550104,SWPS-install & terminate cable
MILLER,D B Consumers Power Co 83/05/09 HARRISON,J J Region 3 Office of Director 1p 18502 067 24X Fiche 50-329,83/05/09,
8305190065

8305200389 Confirms 830510 telcon authorizing minor soil excavation from buried pipes outside of valve pits
MILLER,D B Consumers Power Co 83/05/10 HARRISON,J J Region 3 Office of Director 1p. 18518 174 24X Fiche 50-329,83/05/10,
8305200389

8305170321 Forwards comments on review of TERA independent design const verification program from 830413 meeting Program scope omitted sys walk-down or turn-over & program interfaces
WARNICK,R F Region 3, Office of Director 83/05/11 NOVAK,T M Assistant Director for Licensing 3pp 18465 239 24X
Fiche 50-329,83/05/11,8305170321

8305190280 Forwards "Evaluation of Pressures in Lines of Grouting Equipment - Crack Repair Borated Water Storage Tank Foundations," in response to unresolved item in 830118 ltr Mixing ratios for positive displacement pumps within specs
MILLER,D B Consumers Power Co 83/05/12 HARRISON,J J Region 3 Office of Director 1p 18501 148 24X Fiche 50-329,83/05/12,
8305190280.

--8305190284 "Evaluation of Pressures in Lines of Grouting Equipment - Crack Repair Borated Water Storage Tank Foundations "
MEISENHEIMER,J , WIELAND,R H Consumers Power Co 83/05/05 8p
18501 149 24X Fiche 50-329,83/05/12,8305190280

8305240353 Documents 830512 discussion re remedial soils work authorization Three addl shallow holes on south side of diesel generator bldg constitute only minor change
MILLER,D B Consumers Power Co 83/05/13 HARRISON,J J Region 3, Office of Director 1p 18573 361 24X Fiche 50-329,83/05/13, 8305240353

8305240427 Requests work authorization for svc water pump structure underpinning program & replacement of svc water pipe Train A
MILLER,D B Consumers Power Co 83/05/13 HARRISON,J J Region 3, Office of Director 1p 18571 057 24X Fiche 50-329,83/05/13, 8305240427

8305310190 Submits list of acceptable activities for remedial soils work authorization
MILLER,D B Consumers Power Co 83/05/13 HARRISON,J J Region 3, Office of Director 1p 18651 001 24X Fiche 50-329,83/05/13, 8305310190

8305270057 Forwards Amend 113 to application for CPs & OLs,consisting of Rev 48 to FSAR containing site emergency plan
COOK,J W Consumers Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X Fiche 50-329,83/05/16,8305270057

--8305270063 Amend 113 to application for CPs & OLs,consisting of Rev 48 to FSAR containing site emergency plan
COOK,J W Consumers Power Co 83/05/16 1p 18640 064 24X Fiche 50-329,83/05/16,8305270057

8305200553 Forwards Rev 2 to engineering program plan & Rev 3 to project QA plan re independent design & const verification program
LEVIN,H TERA Corp 83/05/18 EISENHUT,D G Division of Licensing KEPPLER,J G Region 3, Office of Director COOK,J W Consumers Power Co 4pp 18514 284 24X Fiche 50-329,83/05/18, 8305200553

--8305200567 Rev 2 to "Engineering Program Plan Project Instruction PI-3201-009 Midland Independent Design & Const Verification Program,Project 3201 "
* TERA Corp 83/05/18 158pp 18514 288 24X
Fiche 50-329,83/05/18,8305200553

--8305200575 Rev 3 to "Project QA Plan for Midland Independent Design Const & Verification Program "
LEVIN,H A , LEMON,C E , BECK,J W TERA Corp 83/05/02 264pp 18515 086 24X Fiche 50-329,83/05/18,8305200553

8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & OLs,consisting of Rev 48 to FSAR - site emergency plan.
BUDZIK,D M Consumers Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18548 331 24X
Fiche 50-329,83/05/19,8305240137

8305240223 Forwards SB Baranow & J Chawla signed affidavits re potential conflict of interest in performing third-party const implementation overview
WILD,P A Stone & Webster, Inc 83/05/19 KEPPLER,J G Region 3, Office of Director 3pp 18548 012 24X Fiche 50-329,83/05/19, 8305240223

8305310143 Confirms 830720 meeting w/J Keppler to discuss various suppliers quality activities undertaken by Bechtel in support of nuclear projects,per 830520 discussion
SMITH,C F Bechtel Corp 83/05/20 WARNICK,R F Region 3, Office of Director 1p, 18658 073 24X Fiche 50-329,83/05/20,8305310143

8305270299 Enumerates new info matl & relevant to OM/OL proceeding,as presented before ASLB on 830427 Licensee identified & reported two cracks in svc water pump structure
WARNICK,R F Region 3, Office of Director 83/05/24 EISENHUT,D G Division of Licensing 2pp 18641 356 24X Fiche 50-329,83/05/24, 8305270299,

E NRC Safety Evaluation Report (SER), suppls & correspondence
---

8305020398 Forwards "B&W 177 Fuel Assembly Owners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup nozzles.
COOK,J W Consumers Power Co 83/04/13 DENTON,H R Office of Nuclear Reactor Regulation, Director, 3pp 18273 001 24X
Fiche 50-329,83/04/13,8305020398

--8305020404 "B&W 177 Fuel Assembly Owners Group Safe End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking "
* Babcock & Wilcox Co. 77-1141514-00. 83/04/13 61pp
18273 005. 24X Fiche 50-329,83/04/13,8305020398

8305040336 Notification of 830511 meeting w/util & B&W in Bethesda,MD to discuss SER Open Item 7 & Confirmatory Item 7 re natural circulation & reactor vessel head vent
HERNAN,R W Licensing Branch 4 83/04/27 ADENSAM,E G Licensing Branch 4 6pp 18326 335 24X Fiche 50-329,83/04/27,8305040336

8305110305 Suppls explanation of 820921 commitment to implement expanded cooling pond dike surveillance program,including visual insps of dike turf,to resolve NRC concern re dike erosion & performance identified in May 1982 SER
COOK,J W Consumers Power Co 83/05/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18393 229 24X
Fiche 50-329,83/05/03,8305110305

8305090594 Comments on Open Item 2 re turbine missiles in SER Sections 3 7 & 3 5 1 3 Probability of unacceptable damage to safety-related sys & components due to missiles acceptably low
NOVAK,T M Assistant Director for Licensing 83/05/04 COOK,J W Consumers Power Co 3pp 18367 344 24X Fiche 50-329,83/05/04, 8305090594

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305270057 Forwards Amend 113 to application for CPs & OLs,consisting of Rev 48 to FSAR containing site emergency plan
COOK,J W Consumers Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X
Fiche 50-329,83/05/16,8305270057

--8305270066 Rev 48 to FSAR containing site emergency plan
* Consumers Power Co 83/05/31 264pp 18640 067 24X
Fiche 50-329,83/05/16,8305270057

G Adjudicatory correspondence

8305040441 Notice of appearance in proceeding Certificate of Svc encl
PROVENZANO,V P Consumers Power Co 83/04/28 3pp 18322 128 24X Fiche 50-329,83/04/28,8305040441

8305040509 Renewed amended objections to interrogatories directed to util on ZACK issues & renewed motion for protective order Certificate of Svc encl Related correspondence
PROVENZANO,V P Consumers Power Co 83/04/28 Sinclair, M 7pp 18321 049 24X Fiche 50-329,83/04/28,8305040509

8305040449 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
BISHOP,L L Sinclair, M BISHOP,L L Harmon & Weiss 83/05/02 1p 18322 237 24X Fiche 50-329,83/05/02,8305040449

8305100341 Motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination at 830601 evidentiary hearings re reopened QA matters Certificate of Svc encl
STEPTOE,P Consumers Power Co STEPTOE,P Isham, Lincoln & Beale 83/05/04 Atomic Safety and Licensing Board Panel 88pp 18378 233 24X Fiche 50-329,83/05/04,8305100341

8305100264 Advises of svc of deposition subpoenas on deponents M Cioni & B Marello Svc list encl
PROCTOR,S D Isham, Lincoln & Beale PROCTOR,S D Consumers Power Co 83/05/06 Atomic Safety and Licensing Board Panel 2pp 18372,296 24X Fiche 50-329,83/05/06,8305100264

8305100418 Forwards unsigned subpoenas issued for L Clark,T Devine, B Garde & L Hallberg depositions,for signature Witnesses intend to file motion to quash Svc list encl
PROCTOR,S D. Isham, Lincoln & Beale 83/05/06 BECHHOEFER,C Atomic Safety and Licensing Board Panel 10pp 18378 081. 24X
Fiche 50-329,83/05/06,8305100418

8305120273 Revised motion to require submission of cross-examination plans,designation of lead intervenors & establishment of time limits on cross-examination Measures essential to timely development of complete record W/Certificate of Svc
MILLER,M I Consumers Power Co MILLER,M J Isham, Lincoln & Beale 83/05/09 Atomic Safety and Licensing Board Panel 48pp 18427 209 24X Fiche 50-329,83/05/09,8305120273

8305120295 Confirms 830418 telcon re disclosure of anonymous informants names Applicant counsel agreed not to disclose name if name discovered in documents
WILCOVE, M N Hearing Branch 2 83/05/10 STAHL, D Isham, Lincoln & Beale 2pp 18430 176 24X Fiche 50-329, 83/05/10, 8305120295

8305240373 Confirms telcon re continuation of deposition of L Clark & T Devine, scheduled for 830516 & 23, respectively B Garde deposition scheduled for 830606 may be continued provided reconvened QA hearings attended Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/05/13 MCCLAIN, W Karr & Lyons 1p 18574 015 24X Fiche 50-329, 83/05/13, 8305240373

8305190225 Forwards insp evaluation forms filed for IE Insp Repts 50-329/82-11 & 50-330/82-11, 50-329/82-17 & 50-330/82-17, 50-329/82-19 & 50-330/82-19 & 50-329/83-03 & 50-330/83-03
WILCOVE, M N Hearing Branch 2 83/05/17 BERNABEI, L Government Accountability Project 8pp 18500 204 24X Fiche 50-329, 83/05/17, 8305190225

8305190216 Motion for extension until 830524 to respond to util motion to limit cross-examination Counsel involved in 830519-24 hearing ASLB has adequate time to rule on motion before hearings resume Certificate of Svc encl
BERNABEI, L Stamiris, B. BERNABEI, L Government Accountability Project 83/05/18 Atomic Safety and Licensing Board Panel 4pp 18501 319 24X Fiche 50-329, 83/05/18, 8305190216

8305240322 Responds to 830510 ltr Areas of disagreement re documents still exist Conference call will be scheduled w/ASLB if util wishes to pursue matter
BRUNNER, J E Consumers Power Co 83/05/18 STAMIRIS, B Stamiris, B 10pp 18548 078 24X Fiche 50-329, 83/05/18, 8305240322

8305240491 Discusses schedule for appearances Deposition of S Marello will be rescheduled for June Deposition of C Grant scheduled for 830525 Proceedings will be instituted to enforce subpoena served on M Cioni
PROCTOR, S D Isham, Lincoln & Beale PROCTOR, S D Consumers Power Co 83/05/19 BECHOEFER, C Atomic Safety and Licensing Board Panel STUCKY, S W Docketing & Services Branch 2pp 18571 249 24X Fiche 50-329, 83/05/19, 8305240491

8305240059 Proposes schedule for presenting testimony during 830601-10 hearings Proposal is joint proposal of util & NRC Rept on investigation of alleged violation of ASLB order will not be available by 830601-10 hearings
WILCOVE, M N Hearing Branch 2 83/05/20 BECHHOEFER, C , COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18549 133 24X Fiche 50-329, 83/05/20, 8305240059

8305240065 Response to util 830509 revised motion revising 830504 motion re procedural limitations Commission does not favor singling out issue of discretionary referral of denied parts of motion during proceeding Certificate of Svc encl
WRIGHT, N A Hearing Branch 2 83/05/20 Atomic Safety and Licensing Board Panel 7pp 18549 055 24X Fiche 50-329, 83/05/20, 8305240065

8305240472 Order granting Stamiris motion for extension until 830524 to respond to applicant revised motion to establish limits on cross-examination
BECHHOEFER, C Atomic Safety and Licensing Board Panel, 83/05/20 Stamiris, B 1p 18549 278 24X Fiche 50-329, 83/05/20, 8305240472

8305250215 Telecopy response to util revised motion Extensive hearing record caused by const of safety-related bldgs on faulty soil, not by intervenor actions
SINCLAIR, M Sinclair, M 83/05/23 Docketing & Services Branch 2pp 18592 354 24X Fiche 50-329, 83/05/23, 8305250215

8305260169 Response to util revised motion to require submission of cross-examination plans, designation of lead intervenors & time limits on cross-examination Util apparent lack of concern for public safety justifies careful exam of issues
SINCLAIR, M Sinclair, M 83/05/23 Atomic Safety and Licensing Board Panel 2pp 18599 284 24X Fiche 50-329, 83/05/23, 8305260169

8305270547 Forwards "Seismic Margin Review," Vols I, V & VI W/o encl.
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P. Consumers Power Co 83/05/23 BECHHOEFER, C. , COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18646.127 24X Fiche 50-329, 83/05/23, 8305270547

8305260166 Response opposing util 830509 revised motion to require cross-examination plans, designation of lead intervenors & time limits on cross-examination Due process rights of full participation cannot be denied Certificate of Svc encl
BERNABEI, L. Stamiris, B BERNABEI, L Government Accountability Project 83/05/24 Atomic Safety and Licensing Board Panel 12pp 18599 290 24X Fiche 50-329, 83/05/24, 8305260166

8305260276 Transmittal of documents on encl list of submittals responsive to B Stamiris 830407 document request Submittals designated publicly available, already submitted, privileged under atty-client privilege/proprietary
WILCOVE, M N Hearing Branch 2 83/05/24 BERNABEI, L Government Accountability Project 2pp 18625 143 24X Fiche 50-329, 83/05/24, 8305260276

8305270606 Order granting Stamiris 820524 discovery request for documents re implementation of quality improvement program in soils area & denying addl discovery requests re NRC/util Sept 1982 meeting, containment cracks issue & audit repts
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/25 Stamiris, B 4pp 18644 248 24X Fiche 50-329, 83/05/25, 8305270606

H General correspondence

8305040549 Responds to 830324 ltr requesting independent plant audit & more public meetings Three independent audits in progress or planned for site Soils compaction problem & technical & QA concerns being addressed by current hearings
EISENHUT, D G Division of Licensing 83/04/22 ROMO, K B Affiliation Unknown 1p 18351 232. 24X Fiche 50-329, 83/04/22, 8305040549

8305040550 Responds to 830323 ltr requesting independent audit & further public meetings Three audits in progress or planned for site
EISENHUT, D G Division of Licensing 83/04/22 HAVERCAMP, M Affiliation Unknown 1p 18351 233 24X Fiche 50-329, 83/04/22, 8305040550

8305170392 Responds to 830421 ltr re reinsp & independent audits at facilities On 830503, TERA Corp approved to perform independent review of design & const of auxiliary feedwaters sys S&W will perform overview
KEPPLER, J. G Region 3, Office of Director 83/05/13 ROMO, L R Lone Tree Counsil 2pp 18471 202 24X Fiche 50-329, 83/05/13, 8305170392

--8305170395 Requests assurance of independent agent to perform facility audits, per NRC 830419 reinsp order
ROMO, L R Lone Tree Counsil 83/04/21 KEPPLER, J Region 3, Office of Director 1p 18471 204 24X Fiche 50-329, 83/05/13, 8305170392

X Utility Final Safety Analysis Report (FSAR) & amends

8305270057 Forwards Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
COOK, J W Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X Fiche 50-329, 83/05/16, 8305270057

--8305270063 Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
COOK, J W Consumers Power Co. 83/05/16 1p 18640 064 24X Fiche 50-329, 83/05/16, 8305270057

--8305270066 Rev 48 to FSAR containing site emergency plan
* Consumers Power Co 83/05/31 264pp 18640 067. 24X Fiche 50-329, 83/05/16, 8305270057

8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR - site emergency plan
BUDZIK, D M Consumers Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18548 331 24X Fiche 50-329, 83/05/19, 8305240137

Q Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11 PRENDERGAST, R Prendergast, R J 17pp 18506 057 24X Fiche: 50-000, 83/03/11, 8305190005

--8305190045 Requests vendor insp of facilities having contracts w/Zack Co due to QA/QC problems at Midland re HVAC activities Zack Co correspondence re LaSalle & related info encl
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 POTOPOUS, U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000, 83/03/11, 8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co,HVAC contractor at facilities,re potential allegations Zack Co planning to terminate several employees in document control section
HAYES,D W Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche 50-000,83/03/11, 8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co,HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE,T , GARDE,B Government Accountability Project 82/07/26 PALLADINO,N J Commissioners 11pp 18506 128 24X Fiche 50-000,83/03/11,8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
MARELLO,S L Affiliation Unknown 82/07/26 22pp 18506 139 24X Fiche 50-000,83/03/11,8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
HOWARD,A T Affiliation Unknown 82/07/26 55pp 18506 160 24X Fiche 50-000,83/03/11,8305190005

--8305190307 Discusses A Howard 820503 allegations re Zack Co tampering w/documents concerning HVAC activities at facilities Further investigation will be implemented if deemed appropriate by mgt
SHAFER,W.D Region 3, Office of Director 82/05/11 WARNICK,R F Region 3, Office of Director 3pp 18507 354 24X Fiche,50-000,83/03/11,8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
NORELIUS,C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000,83/03/11, 8305190005.

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319. 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381,291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl,
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp. 18382 165 24X Fiche:50-000,83/04/28,8303040027

8305110122 Forwards draft NRR SALP input for Jul 1981 - Mar 1983, based on info solicited from listed personnel.Comments received by 830505 will be considered in final rept
MILLER,M.A Licensing Branch 4 83/05/02. MATTSON,R Division of Systems Integration (post 811005). VOLLMER,R Division of Engineering. JORDAN,E Division of Emergency Preparedness & Engineering Response (Post 830103) 7pp 18421 316 24X Fiche.50-329,83/05/02,8305110122

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190298 Forwards changes in MPQP-1,Rev 5 re QA engineering,providing insp plan to QC & removing requirement for reviewing design documents NRC approval of activity requested
MILLER,D B Consumers Power Co 83/05/06 HARRISON,J J Region 3, Office of Director. 1p 18501 083 24X Fiche 50-329,83/05/06, 8305190298

--8305190300 Draft quality plan for underpinning activities
* Consumers Power Co MPQP-1 R06 DRFT 83/05/03 23pp 18501 084 24X Fiche 50-329,83/05/06,8305190298

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305130171 Ack receipt of 830329 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01
WARNICK,R F Region 3, Office of Director 83/05/11 COOK,J W Consumers Power Co 1p 18438 104 24X Fiche 50-329,83/05/11, 8305130171

--8305130182 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01 Corrective actions valve, serial 27855,placed back in Bechtel stock B&W revising QC procedure for receiving & insp
COOK,J W Consumers Power Co 83/03/29 KEPPLER,J G Region 3, Office of Director 6pp 18438 105 24X Fiche 50-329,83/05/11, 8305130171

8305200557 Advises that investigator file for IE Investigation Repts 50-329/82-13 & 50-330/82-13 reviewed,per ASLB order per intervenor request for discovery in QA hearings Proprietary & nonproprietary documents listed W/o stated encls
WARNICK,R F Region 3, Office of Director 83/05/17 PATON,W D NRC - No Detailed Affiliation Given 3pp 18515 350 24X Fiche 50-329,83/05/17,8305200557

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl,
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240006 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-03 & 50-330/83-03
WARNICK,R F Region 3, Office of Director 83/05/20 COOK,J W Consumers Power Co 1p 18549 039 24X Fiche 50-329,83/05/20, 8305240006

--8305240008 Responds to NRC 830407 ltr re violations noted in IE Insp Repts 50-329/83-03 & 50-330/83-03 Corrective actions,MPQAD Quality Action Request F-292 issued 830304 to review Bechtel procedures for proper quality classification
COOK,J W Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 11pp 18549 040 24X Fiche 50-329,83/05/20, 8305240006.

8305260310 Ack receipt of 830310 ltr informing NRC of steps taken to correct violations noted in 830208 notice of violation & proposed imposition of civil penalties Revised response re craft & engineering personnel training requested
KEPPLER,J.G Region 3, Office of Director 83/05/23 COOK,J W Consumers Power Co 2pp 18625 239 24X Fiche 50-329,83/05/23, 8305260310.

8305270076 Confirms 830624 SALP meeting in Midland,MI Meeting open to other interested parties
WARNICK,R F Region 3, Office of Director 83/05/24 COOK,J W Consumers Power Co 1p. 18638 301 24X Fiche 50-329,83/05/24, 8305270076

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305230270 "Active Mod Projects,Operating PWR,1982 "
* Consumers Power Co 82/12/31 4pp 18576 332 24X Fiche 50-000,82/12/31,8305230270

8305030111 Forwards Bechtel,B&W & util monthly nonconformance repts for Mar 1983,per 730323 Memorandum & Order ALAB-106 & Amend 1 to CPs
COOK,J W. Consumers Power Co 83/04/25 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1,139pp 18286 001 24X Fiche 50-329,83/04/25,8305030111

8305170373 Forwards "Work Activity List for May 1983," for remedial soil work per NRC-util work authorization procedure Authorization of specific work items requested
MILLER,D B Consumers Power Co 83/04/26 HARRISON,J J Region 3, Office of Director. 25pp 18466·031 24X Fiche.50-329,83/04/26, 8305170373

8305090052 Forwards addendum to "41st ALAB-106 Quarterly Rept,Apr-June 1983," consisting of resumes of recently hired employees
COOK,J W Consumers Power Co 83/04/29 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 18364 104 24X Fiche 50-329,83/04/29,8305090052

--8305090060 Addendum to "41st ALAB-106 Quarterly Rept,Apr-June 1983 "
* Consumers Power Co 83/04/29. 82pp 18364 105 24X Fiche 50-329,83/04/29,8305090052

8305310198 Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 1," covering period from project inception through 830527.
LEVIN,H A TERA Corp 83/05/27 KEPPLER,J G Region 3, Office of Director EISENHUT,D.G Division of Licensing COOK,J W Consumers Power Co 4pp 18659·047 24X Fiche 50-329,83/05/27, 8305310198

--8305310203 "Midland Independant Design & Const Verification Program Monthly Status Rept 1," covering period from project inception through 830527.
TULODIESKI,D , LEVIN,H A TERA Corp 83/05/27 62pp 18659 050 24X Fiche 50-329,83/05/27,8305310198

S Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents.Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506 059 24X Fiche 50-000,83/03/11,8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated,document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS,D E., EICHSTAEDT,C L , DEZUTEL,C Z Zack Co 81/10/23 310pp. 18506 215 24X Fiche 50-000,83/03/11,8305190005

8305170283 Ninth interim deficiency rept re improper thrust forces used in high energy line break analysis pipe whip restraint design Initially reported on 800919 Design drawings for 83 restraints revised Next rept will be submitted by 840220
COOK,J W Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 9pp 18465·345 24X Fiche 50-329,83/05/06, 8305170283

8305170391 Final deficiency rept re nonconforming Class IE radiation monitoring sys electronic modules mfg by Victoreen,Inc due to breakdown of QA program Initially reported on 820917 Vendor revised QA program reviewed & approved
COOK,J.W. Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 9pp 18471.211 24X Fiche:50-329,83/05/06, 8305170391.

8305170409 Interim deficiency rept re accident temp effects on containment level measurement Instrument string error exceeds allowable steam generator ECCS control setpoints Bechtel & B&W refining existing calculations
COOK,J W Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 2pp 18469 248 24X Fiche 50-329,83/05/06, 8305170409

8305170440 Interim deficiency rept re installation of B&W nonseismic transmitter mounting brackets forming part of RCPB Brackets will be replaced w/seismically qualified mounting brackets prior to initial fuel load Next rept expected by 830831
COOK,J W Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 2pp 18469 301 24X Fiche 50-329,83/05/06, 8305170440

8305170489 Final deficiency rept re underrated 460-volt motor control ctr control circuit transformers supplied by Gould-Brown Boveri Initially reported on 821013 Transformers to be replaced & installation supervised by Bechtel
COOK,J W Consumers Power Co 83/05/06 KEPPLER,J G Region 3, Office of Director 12pp 18470 055 24X Fiche 50-329,83/05/06, 8305170489

8305200680 Interim deficiency rept re procured safety-related electrical equipment not meeting project requirements Initially reported on 821230 Task force established to review purchase orders Next rept expected by 830629
COOK,J W Consumers Power Co 83/05/13 KEPPLER,J G Region 3, Office of Director 11pp 18519;108 24X Fiche 50-329,83/05/13, 8305200680

8305200349 Interim deficiency rept re improper installation design of Class IE electrical control cabinet/panels Initially reported on 830211 Drawings will be revised Next rept will be submitted by 830819 Bechtel rept encl
COOK,J W Consumers Power Co 83/05/16 KEPPLER,J.G Region 3, Office of Director 12pp 18516 235 24X Fiche 50-329,83/05/16, 8305200349

8305240010 Interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys Initially reported on 820625 Revs to Drawings 7220-M-560(Q) will be made by 830630 Safety-grade HVAC added to listed areas Next rept by 830915
COOK,J W Consumers Power Co 83/05/17 KEPPLER,J G Region 3, Office of Director 10pp 18549 028 24X Fiche 50-329,83/05/17, 8305240010

8305260218 Interim deficiency rept re design of embedments in concrete w/shear lugs located in tension zones Interim embedment design criterion being developed for use prior to testing completion Next rept expected by 831122
COOK,J.W Consumers Power Co 83/05/20 KEPPLER,J G Region 3, Office of Director 5pp 18599 317 24X Fiche 50-329,83/05/20, 8305260218

8305260235 Final deficiency rept re possible frazil ice formation in svc water intake structure Recirculation of svc water discharge flow near trash rack evaluated as best option to control ice at intake structure
COOK,J W Consumers Power Co 83/05/20 KEPPLER,J G Region 3, Office of Director 7pp 18599 340 24X Fiche 50-329,83/05/20, 8305260235

8305260324 Final deficiency rept re auxiliary feedwater (AFW) suction piping design Initially reported on 821214 Design change issued to install pressure relief valve on four AFW pump suction lines between pump & first isolation valve
COOK,J W Consumers Power Co 83/05/20 KEPPLER,J G Region 3, Office of Director 6pp. 18625 166 24X Fiche 50-329,83/05/20, 8305260324.

T Hearing transcripts on non-antitrust matters

8305100243 Forwards NRC testimony addressing Sinclair Contention 13 re assessment of severe accidents to be presented at 830328 hearing Testimony addressing Sinclair Contention 4 re steam generator tube integrity filed on 830131
WRIGHT,N A Office of the General Counsel 83/03/18
BECHHOEFER,C , COWAN,F P , HARBOUR,J Atomic Safety and Licensing Board Panel. 1p 18373 337 24X Fiche 50-329,83/03/18,8305100243

--8305100245 Testimony of F Rowsome re Sinclair Contention 13 on assessment of severe accidents.
ROWSOME,F Assistant Director for Technology Review 83/03/18 13pp. 18373 338 24X Fiche 50-329,83/03/18,8305100243

--8305100248 Testimony of LG Hulman & JA Mitchell re Sinclair Contention 13.
HULMAN,L G , MITCHELL,J A Accident Evaluation Branch 83/03/18 20pp 18373;351 24X Fiche 50-329,83/03/18,8305100243

8305100124 Supplemental testimony of JG Keppler re QA
KEPPLER, J G Region 3, Office of Director 83/03/25 6pp
18375 197 24X Fiche 50-000,83/03/25,8305100124

--8305100141 Responds to 811113 ltr re implications of recent seismic design errors at facility Due to design errors,util license suspended on 811119 pending completion of independent design review & receipt of schedule for completing mods
PALLADINO,N J Commissioners 82/02/01 DINGELL,J D House of Rep , Energy & Commerce 5pp 18375 228 24X
Fiche 50-000,83/03/25,8305100124

8305100147 Forwards supplemental testimonies of JG Keppler,RJ Cook,RN Gardner,RB Landsman,WD Shafer & JW Gilray re QA W/o encls
WILCOVE,M N Office of the Executive Legal Director 83/03/25
BECHHOEFFER,C , COWAN,F P , HARBOUR,J Atomic Safety and Licensing Board Panel 2pp 18374 217 24X Fiche 50-329,83/03/25,8305100147

8305100217 Supplemental testimony of RJ Cook,RN Gardner,RB Landsman & WD Shafer re QA
COOK,R J , GARDNER,R N , LANDSMAN,R B Region 3, Office of Director 83/03/25 6pp 18374 161 24X Fiche 50-329,83/03/25,8305100217

8305100261 Supplemental testimony of JW Gilray,RB Landsman & WD Shafer re QA program for underpinning activities of svc water pump structure & auxiliary bldg Supporting documentation encl
GILRAY,J W QA Branch LANDSMAN,R B , SHAFER,W D Region 3, Office of Director 83/03/25 38pp, 18372 258 24X Fiche 50-329, 83/03/25,8305100261

8305030457 Transcript of 830427 hearing in Midland,MI Pp 14,272-14,493 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/04/27 265pp
18294 184 24X Fiche 50-329,83/04/27,8305030457

8305040191 Transcript of 830428 hearing in Midland,MI Pp 14,495-14,750
* Atomic Safety and Licensing Board Panel 83/04/28 260pp
18324 037 24X Fiche 50-329,83/04/28,8305040191

8305050028 Transcript of 830429 hearing in Midland,MI Pp 14,751-14,977
* Atomic Safety and Licensing Board Panel 83/04/29 229pp
18342 262 24X Fiche 50-329,83/04/29,8305050028

8305050011 Transcript of 830430 hearing in Midland,MI Pp 14,978-15,096
* Atomic Safety and Licensing Board Panel 83/04/30 122pp
18338 155 24X Fiche 50-329,83/04/30,8305050011

8305060199 Transcript of 830502 hearing in Midland,MI Pp 15,097-15,393 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/02 616pp
18346 001 24X Fiche 50-329,83/05/02,8305060199

8305160033 Transcript of 830503 evidentiary hearing in Midland,MI Pp 15,394-15,692
* Atomic Safety and Licensing Board Panel 83/05/03 300pp
18455 116 24X Fiche 50-329,83/05/03,8305160033

8305110006 Transcript of 830504 evidentiary hearing in Midland,MI Pp 15,693-15,922
* Atomic Safety and Licensing Board Panel 83/05/04 232pp
18409 026 24X Fiche 50-329,83/05/04,8305110006

8305110092 Transcript of 830505 evidentiary hearing in Midland,MI Pp 15,923-16,219
* Atomic Safety and Licensing Board Panel 83/05/05 302pp
18410 007 24X Fiche 50-329,83/05/05,8305110092

8305110001 Transcript of 830506 evidentiary hearing in Midland,MI Pp 16,220-16,366
* Atomic Safety and Licensing Board Panel 83/05/06 150pp
18408 130 24X Fiche,50-329,83/05/06,8305110001

8305310163 Transcript of 830510 proceedings in Chicago,IL P 2 Subpoena directed to M Cioni encl
* Commissioners, 83/05/10 6pp, 18652 339 24X
Fiche 50-329,83/05/10,8305310163

DOCKET 50-330 MIDLAND PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305060379 Notification of contract execution,Mod 6 to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 " Contractor Geotechnical Engineers,Inc
FIELDS,J A Division of Contracts NRC-03-82-092 83/04/12
VOLLMER,R H Division of Engineering KANE,J NRC - No Detailed Affiliation Given 1p 18353 086 24X Fiche 50-329,83/04/12, 8305060379

--8305060384 Mod 6,modifying monthly business ltr reporting requirements, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 "
POULOS,S J Geotechnical Engineers, Inc GUSTAVE,R P Division of Contracts NRC-03-82-092 83/04/12 3pp 18353 087 24X
Fiche 50-329,83/04/12,8305060379

8304220515 Forwards revised affidavits for individuals previously employed by NRC now working on independent design & const verification program Clarification of "providing safety evaluation" also submitted
LEVIN,H A TERA Corp 83/04/21 KEPPLER,J G Region 3, Office of Director 15pp 18133 273 24X Fiche 50-329,83/04/21,8304220515

8305020565 Responds to 830325 ltr re TERA Corp QA & engineering plans for independent design & const verification program for facilities NRC comments on reporting requirements proposed by TERA Corp at 830413 meeting will be provided
REHM,T Office of the Executive Director for Operations 83/04/22
GORDE,B P Government Accountability Project 2pp 18284 238 24X
Fiche 50-329,83/04/22,8305020565

8305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Topical Rept CPC-1A, "QA Manual for Midland Nuclear Plant,Vol 1 "
MILLER,W O License Fee Management Branch 83/04/25 BYRD,W
Consumers Power Co 1p 18367 361 24X Fiche 50-329,83/04/25, 8305090551

8305170131 Informs of review completion for listed activities re remedial soils work Concurrence requested
MILLER,D B Consumers Power Co 83/04/28 HARRISON,J.J Region 3, Office of Director 2pp 18466 265 24X Fiche 50-329,83/04/28, 8305170131

8305170539 Forwards Vol 5 of "Seismic Margin Review'Diesel Generator Bldg."
COOK,J W Consumers Power Co 83/04/28 DENTON,H R, Office of Nuclear Reactor Regulation, Director 3pp 18469 036 24X
Fiche 50-329,83/04/28,8305170539

--8305170544 Vol 5 of "Seismic Margin Review Diesel Generator Bldg "
WESLEY,D A , KENNEDY,R P , KINCAID,R H Structural Mechanics Associates SMA 13701 05R003 V05 83/04/30 113pp 18469 040
24X Fiche 50-329,83/04/28,8305170539

8305170422 Forwards change specs for "Pier W11 - Load Recycling Procedure," for remedial soils work,per NRC-util work authorization procedure
MILLER,D B Consumers Power Co 83/04/29 HARRISON,J J Region 3, Office of Director 2pp 18469 286 24X Fiche 50-329,83/04/29, 8305170422

8305060483 Documents 830413 telcon,Util commitment to provide hogging air ejector radiation monitors deleted from FSAR Chapter 11 5 Potential relaxation of tritium sampling requirement discussion deferred pending effluent Tech Spec review
COOK,J W Consumers Power Co 83/05/02 DENTON,H R, Office of Nuclear Reactor Regulation, Director 3pp 18345 360 24X
Fiche 50-329,83/05/02,8305060483

8305170467 Requests concurrence w/proposed changes to approved work activity to perform load test at Pier 11W
MILLER,D B Consumers Power Co 83/05/02 HARRISON,J J. Region 3, Office of Director 2pp 18470 075 24X Fiche 50-329,83/05/02, 8305170467

8305110140 Accepts TERA Corp as independent third-party to perform review of design & const verification program re Unit 2 auxiliary feedwater sys
NOVAK,T M Assistant Director for Licensing 83/05/03 COOK,J W
Consumers Power Co, 7pp 18421 351 24X Fiche 50-329,83/05/03, 8305110140

8305170397 Requests authorization for remedial soils work to install Bulkheads E10 & W10 & to install,load & excavate Piers 8E, 8W,10E & 10W
MILLER,D B Consumers Power Co 83/05/03 HARRISON,J J Region 3, Office of Director 1p, 18469 231 24X Fiche,50-329,83/05/03, 8305170397

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D. G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305190065 Requests authorization to begin Remedial Soils Work Activities 407050400; shallow probing for Phase II & 202550104, SWPB-install & terminate cable
MILLER, D B Consumers Power Co 83/05/09 HARRISON, J J Region 3, Office of Director 1p 18502 067 24X Fiche 50-329, 83/05/09, 8305190065

8305200389 Confirms 830510 telcon authorizing minor soil excavation from buried pipes outside of valve pits
MILLER, D B. Consumers Power Co 83/05/10 HARRISON, J J. Region 3, Office of Director 1p 18518 174 24X Fiche 50-329, 83/05/10, 8305200389

8305170321 Forwards comments on review of TERA independent design const verification program from 830413 meeting Program scope omitted sys walk-down or turn-over & program interfaces
WARNICK, R F Region 3, Office of Director 83/05/11 NOVAK, T M Assistant Director for Licensing 3pp 18465 239 24X
Fiche: 50-329, 83/05/11, 8305170321

8305190280 Forwards "Evaluation of Pressures in Lines of Grouting Equipment - Crack Repair Borated Water Storage Tank Foundations," in response to unresolved item in 830118 ltr Mixing ratios for positive displacement pumps within specs
MILLER, D B Consumers Power Co 83/05/12 HARRISON, J J Region 3, Office of Director 1p 18501 148 24X Fiche 50-329, 83/05/12, 8305190280

--8305190284 "Evaluation of Pressures in Lines of Grouting Equipment - Crack Repair Borated Water Storage Tank Foundations."
MEISENHEIMER, J , WIELAND, R H Consumers Power Co 83/05/05 8pp 18501 149 24X Fiche 50-329, 83/05/12, 8305190280

8305240353 Documents 830512 discussion re remedial soils work authorization Three addl shallow holes on south side of diesel generator bldg constitute only minor change
MILLER, D B Consumers Power Co 83/05/13 HARRISON, J J Region 3, Office of Director 1p 18573 361 24X Fiche 50-329, 83/05/13, 8305240353

8305240427 Requests work authorization for svc water pump structure underpinning program & replacement of svc water pipe Train A.
MILLER, D B. Consumers Power Co 83/05/13 HARRISON, J J Region 3, Office of Director. 1p. 18571 057 24X Fiche 50-329, 83/05/13, 8305240427.

8305310190 Submits list of acceptable activities for remedial soils work authorization
MILLER, D B Consumers Power Co 83/05/13 HARRISON, J J Region 3, Office of Director. 1p 18651 001 24X Fiche 50-329, 83/05/13, 8305310190

8305270057 Forwards Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
COOK, J. W Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X
Fiche 50-329, 83/05/16, 8305270057

--8305270063 Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
COOK, J W. Consumers Power Co 83/05/16 1p 18640 064 24X
Fiche 50-329, 83/05/16, 8305270057

8305200553 Forwards Rev 2 to engineering program plan & Rev 3 to project QA plan re independent design & const verification program
LEVIN, H. TERA Corp 83/05/18 EISENHUT, D. G Division of Licensing. KEPPLER, J G Region 3, Office of Director COOK, J W Consumers Power Co 4pp 18514:284 24X Fiche 50-329, 83/05/18, 8305200553

--8305200567 Rev 2 to "Engineering Program Plan Project Instruction PI-3201-009 Midland Independent Design & Const Verification Program, Project 3201 "
* TERA Corp. 83/05/18 158pp 18514 288 24X
Fiche: 50-329, 83/05/18, 8305200553

--8305200575 Rev 3 to "Project QA Plan for Midland Independent Design Const & Verification Program "
LEVIN, H A , LEMON, C E , BECK, J W TERA Corp 83/05/02 264pp 18515 086 24X Fiche 50-329, 83/05/18, 8305200553

8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR - site emergency plan
BUDZIK, D M Consumers Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18548 331 24X
Fiche 50-329, 83/05/19, 8305240137

8305240223 Forwards SB Baranow & J Chawla signed affidavits re potential conflict of interest in performing third-party const implementation overview
WILD, P A Stone & Webster, Inc 83/05/19 KEPPLER, J G Region 3, Office of Director 3pp 18548 012 24X Fiche 50-329, 83/05/19, 8305240223

8305310143 Confirms 830720 meeting w/J Keppler to discuss various suppliers quality activities undertaken by Bechtel in support of nuclear projects, per 830520 discussion
SMITH, C F Bechtel Corp 83/05/20 WARNICK, R F Region 3, Office of Director 1p 18658 073 24X Fiche 50-329, 83/05/20, 8305310143

8305270299 Enumerates new info matl & relevant to OM/OL proceeding, as presented before ASLB on 830427 Licensee identified & reported two cracks in svc water pump structure
WARNICK, R F Region 3, Office of Director 83/05/24 EISENHUT, D G Division of Licensing 2pp 18641 356 24X Fiche 50-329, 83/05/24, 8305270299

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020398 Forwards "B&W 177 Fuel Assembly Owners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup nozzles
COOK, J W Consumers Power Co 83/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18273 001 24X
Fiche 50-329, 83/04/13, 8305020398

8305040336 Notification of 830511 meeting w/util & B&W in Bethesda, MD to discuss SER Open Item 7 & Confirmatory Item 7 re natural circulation & reactor vessel head vent
HERNAN, R W Licensing Branch 4 83/04/27 ADENSAM, E G Licensing Branch 4 6pp 18326 335 24X Fiche 50-329, 83/04/27, 8305040336

8305110305 Suppls explanation of 820921 commitment to implement expanded cooling pond dike surveillance program, including visual insps of dike turf, to resolve NRC concern re dike erosion & performance identified in May 1982 SER
COOK, J. W Consumers Power Co 83/05/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18393 229 24X
Fiche 50-329, 83/05/03, 8305110305

8305090594 Comments on Open Item 2 re turbine missiles in SER Sections 1 7 & 3 5 1 3 Probability of unacceptable damage to safety-related sys & components due to missiles acceptably low
NOVAK, T M Assistant Director for Licensing 83/05/04 COOK, J W Consumers Power Co 3pp 18367 344 24X Fiche 50-329, 83/05/04, 8305090594

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13. PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche. 50-000, 83/05/13, 8305240213

8305270057 Forwards Amend 113 to application for CPs & OLs, consisting of Rev 48 to FSAR containing site emergency plan
COOK, J W. Consumers Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X
Fiche 50-329, 83/05/16, 8305270057

--8305270066 Rev 48 to FSAR containing site emergency plan
* Consumers Power Co 83/05/31 264pp 18640 067 24X
Fiche 50-329, 83/05/16, 8305270057

G Adjudicatory correspondence

8305040441 Notice of appearance in proceeding Certificate of Svc encl
PROVENZANO, V P Consumers Power Co 83/04/28 3pp 18322 128
24X Fiche 50-329, 83/04/28, 8305040441

8305040509 Renewed amended objections to interrogatories directed to util on ZACK issues & renewed motion for protective order Certificate of Svc encl Related correspondence
PROVENZANO, V P Consumers Power Co 83/04/28 Sinclair, M 7pp
18321;045. 24X Fiche 50-329, 83/04/28, 8305040509

8305040449 Notice of withdrawal of appearance in proceeding Certificate of Svc encl.
BISHOP, L L Sinclair, M BISHOP, L L Harmon & Weiss 83/05/02
1p 18322 237 24X Fiche 50-329, 83/05/02, 8305040449

8305100341 Motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination at 830601 evidentiary hearings re reopened QA matters Certificate of Svc encl
STEPTOE, P. Consumers Power Co STEPTOE, P Isham, Lincoln & Beale
83/05/04 Atomic Safety and Licensing Board Panel 88pp
18378 233 24X Fiche 50-329, 83/05/04, 8305100341

8305100264 Advises of svc of deposition subpoenas on deponents M Cioni & S Marello Svc list encl
PROCTOR, S D Isham, Lincoln & Beale PROCTOR, S D Consumers Power Co 83/05/06 Atomic Safety and Licensing Board Panel 2pp
18372, 296 24X Fiche 50-329, 83/05/06, 8305100264

8305100418 Forwards unsigned subpoenas issued for L Clark, T Devine, B Garde & L Hallberg depositions, for signature Witnesses Intend to file motion to quash Svc list encl
PROCTOR, S. D Isham, Lincoln & Beale 83/05/06 BECHHOEFER, C
Atomic Safety and Licensing Board Panel 10pp 18378 081 24X
Fiche 50-329, 83/05/06, 8305100418

8305120273 Revised motion to require submission of cross-examination plans, designation of lead intervenors & establishment of time limits on cross-examination Measures essential to timely development of complete record W/Certificate of Svc
MILLER, M I Consumers Power Co MILLER, M J Isham, Lincoln & Beale 83/05/09 Atomic Safety and Licensing Board Panel. 48pp
18427 209 24X Fiche 50-329, 83/05/09, 8305120273

8305120295 Confirms 830418 telcon re disclosure of anonymous informants names Applicant counsel agreed not to disclose name if name discovered in documents.
WILCOVE, M. N Hearing Branch 2 83/05/10 STAHL, D Isham, Lincoln & Beale 2pp 18430 176 24X Fiche 50-329, 83/05/10, 8305120295

8305240373 Confirms telcon re continuation of deposition of L Clark & T Devine, scheduled for 830516 & 23, respectively B Garde deposition scheduled for 830606 may be continued provided reconvened QA hearings attended Related correspondence
PROCTOR, S D Isham, Lincoln & Beale 83/05/13 MCCLAIN, W Karr & Lyons. 1p 18574 015 24X Fiche 50-329, 83/05/13, 8305240373

8305190225 Forwards insp evaluation forms filed for IE Insp Repts 50-329/82-11 & 50-330/82-11, 50-329/82-17 & 50-330/82-17, 50-329/82-19 & 50-330/82-19 & 50-329/83-03 & 50-330/83-03
WILCOVE, M N Hearing Branch 2 83/05/17 BERNABEI, L Government Accountability Project. 6pp 18500 204 24X Fiche 50-329, 83/05/17, 8305190225

8305190216 Motion for extension until 830524 to respond to util motion to limit cross-examination Counsel involved in 830519-24 hearing ASLB has adequate time to rule on motion before hearings resume Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/05/18 Atomic Safety and Licensing Board Panel 4pp
18501;319 24X Fiche; 50-329, 83/05/18, 8305190216

8305240322 Responds to 830510 ltr Areas of disagreement re documents still exist Conference call will be scheduled w/ASLB if util wishes to pursue matter
BRUNNER, J E. Consumers Power Co 83/05/18. STAMIRIS, B Stamiris, B 10pp 18548 078 24X Fiche 50-329, 83/05/18, 8305240322

8305240491 Discusses schedule for appearances Deposition of S Marello will be rescheduled for June Deposition of C Grant scheduled for 830525. Proceedings will be instituted to enforce subpoena served on M Cioni
PROCTOR, S. D. Isham, Lincoln & Beale PROCTOR, S D Consumers Power Co 83/05/19. BECHOEFER, C Atomic Safety and Licensing Board Panel STUCKY, S W. Docketing & Services Branch 2pp 18571 269.
24X Fiche 50-329, 83/05/19, 8305240491

8305240059 Proposes schedule for presenting testimony during 830601-10 hearings Proposal is joint proposal of util & NRC Rept on investigation of alleged violation of ASLB order will not be available by 830601-10 hearings
WILCOVE, M N Hearing Branch 2 83/05/20 BECHHOEFER, C ,
COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel
2pp 18549 133 24X Fiche 50-329, 83/05/20, 8305240059

8305240065 Response to util 830509 revised motion revising 830504 motion re procedural limitations Commission does not favor singling out issue of discretionary referral of denied parts of motion during proceeding Certificate of Svc encl
WRIGHT, N A Hearing Branch 2 83/05/20 Atomic Safety and Licensing Board Panel 7pp 18549 055 24X Fiche 50-329, 83/05/20, 8305240065

8305240472 Order granting Stamiris motion for extension until 830524 to respond to applicant revised motion to establish limits on cross-examination
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/20
Stamiris, B 1p 18549 278 24X Fiche 50-329, 83/05/20, 8305240472

8305250215 Telecopy response to util revised motion Extensive hearing record caused by const of safety-related bldgs on faulty soil; not by intervenor actions
SINCLAIR, M Sinclair, M 83/05/23 Docketing & Services Branch
2pp 18592 354 24X Fiche 50-329, 83/05/23, 8305250215

8305260169 Response to util revised motion to require submission of cross-examination plans, designation of lead intervenors & time limits on cross-examination Util apparent lack of concern for public safety justifies careful exam of issues
SINCLAIR, M Sinclair, M 83/05/23 Atomic Safety and Licensing Board Panel 2pp 18599 284 24X Fiche 50-329, 83/05/23, 8305260169.

8305270547 Forwards "Seismic Margin Review," Vols I, V & VI W/o encl
STEPTOE, P P Isham, Lincoln & Beale STEPTOE, P P Consumers Power Co. 83/05/23 BECHHOEFER, C , COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18646 127 24X
Fiche 50-329, 83/05/23, 8305270547

8305260166 Response opposing util 830509 revised motion to require cross-examination plans, designation of lead intervenors & time limits on cross-examination Due process rights of full participation cannot be denied Certificate of Svc encl
BERNABEI, L Stamiris, B BERNABEI, L Government Accountability Project 83/05/24 Atomic Safety and Licensing Board Panel
12pp 18599 290 24X Fiche 50-329, 83/05/24, 8305260166

8305260276 Transmittal of documents on encl list of submittals responsive to B Stamiris 830407 document request Submittals designated publicly available, already submitted, privileged under atty-client privilege/proprietary
WILCOVE, M N Hearing Branch 2 83/05/24 BERNABEI, L. Government Accountability Project. 2pp 18625 143 `24X Fiche 50-329, 83/05/24, 8305260276

8305270606 Order granting Stamiris 820524 discovery request for documents re implementation of quality improvement program in soils area & denying add1 discovery requests re NRC/util Sept 1982 meeting, containment cracks issue & audit repts
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/25.
Stamiris, B 4pp 18644 248 24X Fiche 50-329, 83/05/25, 8305270606

H General correspondence

8305040549 Responds to 830324 ltr requesting independent plant audit & more public meetings Three independent audits in progress or planned for site Soils compaction problem & technical & QA concerns being addressed by current hearings
EISENHUT, D G Division of Licensing 83/04/22 ROMO, K. B
Affiliation Unknown 1p 18351 232 24X Fiche 50-329, 83/04/22,
8305040549

8305040550 Responds to 830323 ltr requesting independent audit & further public meetings. Three audits in progress or planned for site
EISENHUT, D G. Division of Licensing. 83/04/22 HAVERCAMP, M.
Affiliation Unknown 1p 18351 233 24X Fiche, 50-329, 83/04/22,
8305040550

8305170392 Responds to 830421 ltr re reinsp & independent audits at facilities On 830503, TERA Corp approved to perform independent review of design & const of auxiliary feedwaters sys S&W will perform overview
KEPPLER, J G Region 3, Office of Director 83/05/13. ROMO, L R
Lone Tree Counsil 2pp 18471 202. 24X Fiche 50-329, 83/05/13,
8305170392

--8305170376 Requests assurance of independent agent to perform Facility audits per NRC 830419 reinsp order
ROMO,L R Lone Tree Counsil 83/04/21 KEPPLER,J Region 3, Office of Director 1p 18471 204 24X Fiche 50-329,83/05/13, 8305170392

K Utility Final Safety Analysis Report (FSAR) & amends

8305270057 Forwards Amend 113 to application for CPs & OLs,consisting of Rev 49 to FSAR containing site emergency plan
COOK,J W Consumers Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18640 063 24X Fiche 50-329,83/05/16,8305270057

--8305270066 Rev 49 to FSAR containing site emergency plan
* Consumers Power Co 83/05/31 264pp 18640 067 24X Fiche 50-329,83/05/16 8305270057

8305240137 Forwards Affidavit of Svc for Amend 113 to application for CPs & OLs consisting of Rev 49 to FSAR - site emergency plan
BUDZIK,D M Consumers Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18548 331 24X Fiche 50-329,83/05/19,8305240137

Q Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON J M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506 057 24X Fiche 50-000,83/03/11,8305190005

--8305190045 Requestt vehdor insp of facilities having contracts w/Zack Co due to QA/QC problems at Midland re HVAC activities Zack Co correspondence re LaSalle & related info encl
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 POTOPOVS,U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000,83/03/11, 8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co,HVAC contractor at facilities,re potential allegations Zack Co planning to terminate several employees in document control section
HAYES,D W Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche 50-000,83/03/11, 8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co,HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE,T , GARDE,B Government Accountability Project 82/07/26
PALLADINO,N J Commissioners 11pp 18506 128 24X Fiche 50-000,83/03/11,8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
MARELLO,S L Affiliation Unknown 82/07/26 22pp 18506 139 24X Fiche 50-000,83/03/11,8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
HOWARD,A T Affiliation Unknown 82/07/26 55pp 18506 160 24X Fiche 50-000,83/03/11,8305190005

--8305190307 Discusses A Howard 820503 allegations re Zack Co tampering w/documents concerning HVAC activities at facilities Further investigation will be implemented if deemed appropriate by mgt
SHAFER,W D Region 3, Office of Director 82/05/11 WARNICK,R F Region 3, Office of Director 3pp 18507 354 24X Fiche 50-000,83/03/11,8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
MORELIUS,C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000,83/03/11, 8305190005

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche:50-000,83/04/25,8303040025.

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche:50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305110122 Forwards draft NRR SALP input for Jul 1981 - Mar 1983, based on info solicited from listed personnel Comments received by 830505 will be considered in final rept
MILLER,M A Licensing Branch 4 83/05/02 MATTSON,R. Division of Systems Integration (post B11005) VOLLMER,R Division of Engineering JORDAN,E Division of Emergency Preparedness & Engineering Response (Post 830103) 7pp 18421 316, 24X Fiche 50-329,83/05/02,8305110122

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche:50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche:50-000,83/05/06,8303040033

8305190298 Forwards changes in MPQP-1,Rev 5 re QA engineering,providing insp plan to QC & removing requirement for reviewing design documents NRC approval of activity requested
MILLER,D B Consumers Power Co. 83/05/06 HARRISON,J J. Region 3, Office of Director 1p 18501 083 24X Fiche:50-329,83/05/06, 8305190298

--8305190300 Draft quality plan for underpinning activities
* Consumers Power Co MPQP-1 R06 DRFT 83/05/03 23pp. 18501 084 24X Fiche 50-329,83/05/06,8305190298.

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche:50-000,83/05/11,8303040034

8305130171 Ack receipt of 830329 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01
WARNICK, R F. Region 3, Office of Director 83/05/11 COOK, J W Consumers Power Co 1p 18438 104 24X Fiche 50-329, 83/05/11, 8305130171

--8305130182 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-01 & 50-330/83-01 Corrective actions valve, serial 27855, placed back in Bechtel stock B&W revising QC procedure for receiving & insp
COOK, J W Consumers Power Co 83/03/29 KEPPLER, J G Region 3, Office of Director 6pp 18438 105 24X Fiche 50-329, 83/05/11, 8305130171

8305200557 Advises that investigator file for IE Investigation Repts 50-329/82-13 & 50-330/82-13 reviewed, per ASLB order per intervenor request for discovery in QA hearings Proprietary & nonproprietary documents listed W/o stated encls
WARNICK, R.F Region 3, Office of Director 83/05/17 PATON, W D NRC - No Detailed Affiliation Given 3pp 18519 350 24X Fiche 50-329, 83/05/17, 8305200557

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18497 009 24X Fiche 50-000, 83/05/19, 8303040040

8305240006 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-329/83-03 & 50-330/83-03
WARNICK, R F Region 3, Office of Director 83/05/20 COOK, J W Consumers Power Co 1p 18549 039 24X Fiche 50-329, 83/05/20, 8305240006

--8305240008 Responds to NRC 830407 ltr re violations noted in IE Insp Repts 50-329/83-03 & 50-330/83-03 Corrective actions MPQAD Quality Action Request F-292 issued 830304 to review Bechtel procedures for proper quality classification
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 11pp 18549 040 24X Fiche 50-329, 83/05/20, 8305240006

8305260310 Ack receipt of 830310 ltr informing NRC of steps taken to correct violations noted in 830208 notice of violation & proposed imposition of civil penalties Revised response re craft & engineering personnel training requested
KEPPLER, J G Region 3, Office of Director 83/05/23 COOK, J W Consumers Power Co 2pp 18625.239 24X Fiche 50-329, 83/05/23, 8305260310

8305270076 Confirms 830624 SALP meeting in Midland, MI Meeting open to other interested parties
WARNICK, R.F Region 3, Office of Director 83/05/24 COOK, J W Consumers Power Co 1p 18638 301 24X Fiche 50-329, 83/05/24, 8305270076

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305230270 "Active Mod Projects, Operating PWR, 1982 "
* Consumers Power Co 82/12/31 4pp 18576.332 24X Fiche 50-000, 82/12/31, 8305230270

8305030111 Forwards Bechtel, B&W & util monthly nonconformance repts for Mar 1983, per 730323 Memorandum & Order ALAB-106 & Amend 1 to CPs
COOK, J.W Consumers Power Co 83/04/25 DEYOUNG, R C Director's Office: Office of Inspection and Enforcement 1,139pp. 18286 001 24X Fiche 50-329, 83/04/25, 8305030111

8305170373 Forwards "Work Activity List for May 1983," for remedial soil work per NRC-util work authorization procedure Authorization of specific work items requested
MILLER, D B Consumers Power Co 83/04/26 HARRISON, J J Region 3, Office of Director 25pp. 18466 031. 24X Fiche 50-329, 83/04/26, 8305170373

8305090052 Forwards addendum to "41st ALAB-106 Quarterly Rept, Apr-June 1983," consisting of resumes of recently hired employees
COOK, J W Consumers Power Co 83/04/29 DEYOUNG, R C Director's Office: Office of Inspection and Enforcement 1p 18364.104. 24X Fiche: 50-329, 83/04/29, 8305090052

--8305090060 Addendum to "41st ALAB-106 Quarterly Rept, Apr-June 1983 "
* Consumers Power Co 83/04/29 82pp 18364 105 24X Fiche 50-329, 83/04/29, 8305090052

8305310198 Forwards "Midland Independent Design & Const Verification Program Monthly Status Rept 1," covering period from project inception through 830527
LEVIN, H A TERA Corp 83/05/27 KEPPLER, J G Region 3, Office of Director EISENHUT, D G Division of Licensing COOK, J W Consumers Power Co 4pp 18659 047 24X Fiche 50-329, 83/05/27, 8305310198

--8305310203 "Midland Independant Design & Const Verification Program Monthly Status Rept 1," covering period from project inception through 830527
YULODIESKI, D , LEVIN, H A TERA Corp 83/05/27 62pp 18659 050 24X Fiche 50-329, 83/05/27, 8305310198

S Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11
PRENDERGAST, R Prendergast, R J 17pp 18506 059 24X Fiche 50-000, 83/03/11, 8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS, D E , EICHSTAEDT, C L , DEZUTEL, C Z Zack Co 81/10/23 310pp 18506 215 24X Fiche 50-000, 83/03/11, 8305190005

8305170283 Ninth interim deficiency rept re improper thrust forces used in high energy line break analysis pipe whip restraint design Initially reported on 800919 Design drawings for 93 restraints revised Next rept will be submitted by 840220
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 9pp 18465 345 24X Fiche 50-329, 83/05/06, 8305170283

8305170391 Final deficiency rept re nonconforming Class IE radiation monitoring sys electronic modules mfg by Victoreen, Inc due to breakdown of QA program Initially reported on 820917 Vendor revised QA program reviewed & approved
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 9pp 18471 211 24X Fiche 50-329, 83/05/06, 8305170391

8305170409 Interim deficiency rept re accident temp effects on containment level measurement Instrument string error exceeds allowable steam generator ECCS control setpoints Bechtel & B&W refining existing calculations
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 2pp 18469 248 24X Fiche 50-329, 83/05/06, 8305170409

8305170440 Interim deficiency rept re installation of B&W nonseismic transmitter mounting brackets forming part of RCPB Brackets will be replaced w/seismically qualified mounting brackets prior to initial fuel load Next rept expected by 830831
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 2pp 18469 301 24X Fiche 50-329, 83/05/06, 8305170440

8305170489 Final deficiency rept re underrated 460-volt motor control ctr control circuit transformers supplied by Gould-Brown Boveri Initially reported on 821013 Transformers to be replaced & installation supervised by Bechtel
COOK, J W Consumers Power Co 83/05/06 KEPPLER, J G Region 3, Office of Director 12pp 18470 055 24X Fiche 50-329, 83/05/06, 8305170489

8305200680 Interim deficiency rept re procured safety-related electrical equipment not meeting project requirements Initially reported on 821230 Task force established to review purchase orders Next rept expected by 830429
COOK, J W Consumers Power Co 83/05/13 KEPPLER, J G Region 3, Office of Director 11pp 18519 108 24X Fiche 50-329, 83/05/13, 8305200680

8305200349 Interim deficiency rept re improper installation design of Class IE electrical control cabinet/panels Initially reported on 830211 Drawings will be revised Next rept will be submitted by 830819 Bechtel rept encl
COOK, J W Consumers Power Co 83/05/16 KEPPLER, J G Region 3, Office of Director 12pp 18516 235 24X Fiche 50-329, 83/05/16, 8305200349.

8305240010 Interim deficiency rept re Q-related equipment cooled by non-Q HVAC sys Initially reported on 820625 Revs to Drawings 7220-M-560(Q) will be made by 830630 Safety-grade HVAC added to listed areas Next rept by 830815
COOK, J W Consumers Power Co 83/05/17 KEPPLER, J G Region 3, Office of Director 10pp 18549 028 24X Fiche 50-329, 83/05/17, 8305240010

8305260309 Interim deficiency rept re core support structure bolting Initially reported on 830419 Evaluation of corrective action in progress Next rept will be sent by 831101
COOK, J W Consumers Power Co 83/05/19 KEPPLER, J G. Region 3, Office of Director 3pp 18625 200 24X Fiche 50-000, 83/05/19, 8305260309

--8305260311 Deficiency rept re ultrasonic test abnormal indications in upper barrel bolting of reactor internals Initially reported on 830328 Results of internal bolt insp discussed Addl info will be forwarded
TAYLOR, J H Babcock & Wilcox Co 83/04/11 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp, 18623 205 24X Fiche 50-000, 83/05/19, 8305260309

--8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
TAYLOR, J H Babcock & Wilcox Co 83/04/22 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement 3pp 18625 210 24X Fiche. 50-000, 83/05/19, 8305260309

8305260218 Interim deficiency rept re design of embedments in concrete w/shear lugs located in tension zones. Interim embedment design criterion being developed for use prior to testing completion Next rept expected by 831122
COOK, J W Consumers Power Co 83/05/20 KEPPLER, J G Region 3, Office of Director 5pp 18599 317 24X Fiche. 50-329, 83/05/20, 8305260218

8305260235 Final deficiency rept re possible frazil ice formation in svc water intake structure Recirculation of svc water discharge flow near trash rack evaluated as best option to control ice at intake structure
COOK, J W Consumers Power Co 83/05/20 KEPPLER, J G Region 3, Office of Director 7pp 18599 340 24X Fiche 50-329, 83/05/20, 8305260235.

8305260324 Final deficiency rept re auxiliary feedwater (AFW) suction piping design Initially reported on 821214 Design change issued to install pressure relief valve on four AFW pump suction lines between pump & first isolation valve
COOK, J W Consumers Power Co 83/05/20. KEPPLER, J G Region 3, Office of Director. 6pp 18625 166 24X Fiche 50-329, 83/05/20, 8305260324

T Hearing transcripts on non-antitrust matters

8305100243 Forwards NRC testimony addressing Sinclair Contention 13 re assessment of severe accidents to be presented at 830328 hearing Testimony addressing Sinclair Contention 4 re steam generator tube integrity filed on 830131
WRIGHT, N A Office of the General Counsel 83/03/18
BECHHOEFER, C , COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel 1p 18373.337 24X Fiche 50-329, 83/03/18, 8305100243

--8305100245 Testimony of F Rowsome re Sinclair Contention 13 on assessment of severe accidents
ROWSOME, F Assistant Director for Technology Review 83/03/18 13pp 18373 338 24X Fiche 50-329, 83/03/18, 8305100243.

--8305100248 Testimony of LG Hulman & JA Mitchell re Sinclair Contention 13
HULMAN, L G , MITCHELL, J A Accident Evaluation Branch 83/03/18 20pp. 18373 351 24X Fiche: 50-329, 83/03/18, 8305100243

8305100124 Supplemental testimony of JG Keppler re QA
KEPPLER, J G Region 3, Office of Director 83/03/25 6pp. 18375 197 24X Fiche 50-000, 83/03/25, 8305100124.

8305100147 Forwards supplemental testimonies of JG Keppler, RJ Cook, RN Gardner, RB Landsman, WD Shafer & JW Gilray re QA W/o encls.
WILCOVE, M N Office of the Executive Legal Director 83/03/25
BECHHOEFFER, C , COWAN, F P , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18374 217 24X Fiche 50-329, 83/03/25, 8305100147

8305100217 Supplemental testimony of RJ Cook, RN Gardner, RB Landsman & WD Shafer re QA
COOK, R J , GARDNER, R N., LANDSMAN, R. B Region 3, Office of Director 83/03/25 6pp 18374.161. 24X Fiche 50-329, 83/03/25, 8305100217

8305100261 Supplemental testimony of JW Gilray, RB Landsman & WD Shafer re QA program for underpinning activities of svc water pump structure & auxiliary bldg Supporting documentation encl
GILRAY, J W QA Branch LANDSMAN, R B , SHAFER, W D Region 3, Office of Director 83/03/25 38pp 18372 258 24X Fiche 50-329, 83/03/25, 8305100261

8305030457 Transcript of 830427 hearing in Midland, MI Pp 14,272-14,493 Supporting documentation encl.
* Atomic Safety and Licensing Board Panel 83/04/27 265pp. 18294 184 24X Fiche 50-329, 83/04/27, 8305030457

8305040191 Transcript of 830428 hearing in Midland, MI. Pp 14,495-14,750
* Atomic Safety and Licensing Board Panel 83/04/28 260pp 18324 037 24X Fiche 50-329, 83/04/28, 8305040191

8305050028 Transcript of 830429 hearing in Midland, MI Pp 14,751-14,977
* Atomic Safety and Licensing Board Panel 83/04/29 229pp 18342 262 24X Fiche 50-329, 83/04/29, 8305050028

8305050011 Transcript of 830430 hearing in Midland, MI Pp 14,978-15,096
* Atomic Safety and Licensing Board Panel. 83/04/30 122pp 18338 155 24X Fiche 50-329, 83/04/30, 8305050011

8305060199 Transcript of 830502 hearing in Midland, MI Pp 15,097-15,393 Supporting documentation encl
* Atomic Safety and Licensing Board Panel. 83/05/02 616pp 18346 001 24X Fiche 50-329, 83/05/02, 8305060199.

8305160033 Transcript of 830503 evidentiary hearing in Midland, MI Pp 15,394-15,692.
* Atomic Safety and Licensing Board Panel 83/05/03. 300pp. 18455 116 24X Fiche 50-329, 83/05/03, 8305160033

8305110006 Transcript of 830504 evidentiary hearing in Midland, MI. Pp 15,693-15,922
* Atomic Safety and Licensing Board Panel 83/05/04 232pp 18409 026. 24X Fiche: 50-329, 83/05/04, 8305110006

8305110092 Transcript of 830505 evidentiary hearing in Midland, MI Pp 15,923-16,219
* Atomic Safety and Licensing Board Panel 83/05/05 302pp 18410 007. 24X Fiche 50-329, 83/05/05, 8305110092

8305110001 Transcript of 830506 evidentiary hearing in Midland, MI Pp 16,220-16,366
* Atomic Safety and Licensing Board Panel. 83/05/06. 150pp 18408 130 24X Fiche 50-329, 83/05/06, 8305110001

8305310163 Transcript of 830510 proceedings in Chicago, IL P 2. Subpoena directed to M Cioni encl
* Commissioners 83/05/10. 6pp 18652 339. 24X Fiche 50-329, 83/05/10, 8305310163

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

8305090186 Forwards exemption from requirements of Section III G of App R to 10CFR50 per 820622 request re reactor bldg torus area & lower switchgear room Remaining areas for which exemptions requested will be addressed in future action
VASSALLO, D B Operating Reactors Branch 2 83/04/26 ARNOLD, A Iowa Electric Light & Power Co. 2pp 18367 256. 24X Fiche 50-331, 83/04/26, 8305090186

--8305090197 Exemption from requirements of Section III G of App R, 10CFR50 re reactor bldg torus area, north & south control rod drive module areas, reactor bldg RHR valve rooms, control, lower switchgear, battery & essential switchgear rooms
EISENHUT, D G Division of Licensing. 83/04/26 Iowa Electric Light & Power Co 8pp 18367 258. 24X Fiche 50-331, 83/04/26, 8305090186

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. G Division of Licensing. 83/05/11. Consolidated Edison Co of New York, Inc 16pp. 18540.095 24X Fiche: 50-000, 83/05/11, 8305110034

8305200172 Notifies of refund of Class II license amend fee re 800617 amend application Changes, per 10CFR50 54(p), do not decrease effectiveness of plan & do not require NRR approval
MILLER, W G License Fee Management Branch 83/05/12 ARNOLD, D. Iowa Electric Light & Power Co. 1p 18540 234. 24X Fiche 50-331, 83/05/12, 8305200172

8305310176 Forwards IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted
PAPERIELLO, C. J Region 3, Office of Director 83/05/16 LIU, L
Iowa Electric Light & Power Co 2pp 18659 118 24X
Fiche 50-331, 83/05/16, 8305310176

--8305310181 IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted. Major areas inspected actions taken in response to 810922 confirmatory action ltr & emergency preparedness appraisal improvement & training
PATTERSON, J P , SNELL, W G , AXELSON, W L Region 3, Office of Director 83/05/12 15pp 18659 120 24X Fiche 50-331, 83/05/16, 8305310176.

8305240564 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed.
VASSALLO, D B Operating Reactors Branch 2 83/05/18 LIU, L Iowa Electric Light & Power Co 3pp 18593 348 24X
Fiche 50-331, 83/05/18, 8305240564

P. Operating license stage documents & correspondence

8305040095 Forwards Amend 87 to License DPR-49 & notice of issuance & availability Amend incorporates revs to tables of safety-related snubbers to satisfy requirements of Mark I containment long-term 780228 order for mod
VASSALLO, D. B Operating Reactors Branch 2 83/04/18 ARNOLD, D
Iowa Electric Light & Power Co 3pp 18328 173 24X
Fiche 50-331, 83/04/18, 8305040095.

--8305040108 Amend 87 to License DPR-49, incorporating revs to tables of safety-related snubbers to satisfy requirements of Mark I containment long-term 780228 order for mod of license
VASSALLO, D B Operating Reactors Branch 2 83/04/18 9pp
18328 176 24X Fiche 50-331, 83/04/18, 8305040095

--8305040115 Notice of issuance & availability of Amend 87 to License DPR-49
VASSALLO, D B Operating Reactors Branch 2 83/04/18 2pp
18328 185. 24X Fiche 50-331, 83/04/18, 8305040095

8305160331 Responds to 830216 request for Tech Spec interpretation re component operability when diesel generator inoperable, stating NRR position
EISENHUT, D. G. Division of Licensing 83/04/20 NORELIUS, C E
Division of Project & Resident Programs 2pp. 18472 049 24X
Fiche. 50-331, 83/04/20, 8305160331

8305110549 Forwards Amend 88 to License DPR-49, safety evaluation & notice of issuance & availability Amend revises Tech Specs to incorporate limiting conditions for operation during Fuel Cycle 7.
APICELLA, F. L Operating Reactors Branch 2 83/04/25 ARNOLD, D
Iowa Electric Light & Power Co 2pp 18415.073 24X
Fiche 50-331, 83/04/25, 8305110549

--8305110556 Amend 88 to License DPR-49, revising Tech Specs to incorporate limiting conditions for operation during Fuel Cycle 7.
VASSALLO, D. B Operating Reactors Branch 2 83/04/25. 20pp
18415.075 24X Fiche 50-331, 83/04/25, 8305110549

--8305110560 Safety evaluation supporting Amend 88 to License DPR-49
* Office of Nuclear Reactor Regulation, Director. 83/04/25 7pp
18415:095. 24X Fiche 50-331, 83/04/25, 8305110549

--8305110566 Notice of issuance & availability of Amend 88 to License DPR-49.
VASSALLO, D. B. Operating Reactors Branch 2 83/04/25 2pp
18415 102. 24X Fiche. 50-331, 83/04/25, 8305110549.

8305180801 Forwards request for addl info re structural aspects of Mark I containment long-term program plant-unique analysis rept Response requested within 45 days of receipt of ltr
VASSALLO, D. B. Operating Reactors Branch 2 83/04/28 LIU, L Iowa Electric Light & Power Co 4pp 18505 346 24X
Fiche. 50-331, 83/04/28, 8305180801.

8305110100 Forwards Amend 89 to License DPR-49, safety evaluation & notice of issuance & availability. Amend revises Group I containment isolation signal, pressure setpoint & low-low set logic
APICELLA, F. L. Operating Reactors Branch 2. 83/04/29 LIU, L Iowa Electric Light & Power Co. 2pp 18434:315 24X
Fiche: 50-331, 83/04/29, 8305110100.

--8305110234 Amend 89 to License DPR-49, revising Group I containment isolation signal, pressure setpoint from 880 psig to 850 psig & low-low set logic
VASSALLO, D. B. Operating Reactors Branch 2. 83/04/29 10pp.
18434:317. 24X Fiche: 50-331, 83/04/29, 8305110100

--8305110242 Safety evaluation supporting Amend 89 to License DPR-49
* Office of Nuclear Reactor Regulation, Director 83/04/29 5pp
18434 327 24X Fiche 50-331, 83/04/29, 8305110100

--8305110243 Notice of issuance & availability of Amend 89 to License DPR-49
VASSALLO, D B Operating Reactors Branch 2 83/04/29 2pp
18434 332 24X Fiche 50-331, 83/04/29, 8305110100

8305100095 Informs of intended reporting mechanism for containment leak rate testing from Cycle 7 refueling outage, per 10CFR50, App J & Tech Spec App A LER reporting requirements do not apply Test results will be submitted in early Jul 1983
ROOT, L D Iowa Electric Light & Power Co 83/05/02 KEPPLER, J G
Region 3, Office of Director 2pp 18377 216 24X
Fiche 50-331, 83/05/02, 8305100095

8305110037 Forwards Amend 91 to License DPR-49, safety evaluation & notice of issuance & availability Amend modifies plan for integrated scheduling of mods
EISENHUT, D G Division of Licensing 83/05/03 LIU, L Iowa Electric Light & Power Co 3pp 18420 340 24X
Fiche 50-331, 83/05/03, 8305110037

--8305110039 Amend 91 to License DPR-49, revising plan for integrated scheduling of mods
VASSALLO, D B Operating Reactors Branch 2 83/05/03 2pp
18420 343 24X Fiche 50-331, 83/05/03, 8305110037

--8305110043 Safety evaluation supporting Amend 91 to License DPR-49
* Office of Nuclear Reactor Regulation, Director 83/05/03
15pp 18420 345 24X Fiche 50-331, 83/05/03, 8305110037

--8305110045 Notice of issuance & availability of Amend 91 to License DPR-49
ROONEY, V L Operating Reactors Branch 2 83/05/03 2pp
18420 360 24X Fiche 50-331, 83/05/03, 8305110037

8305180081 Forwards Amend 90 to License DPR-49 & notice of issuance & availability Amend deletes requirements for shift technical advisor to be on duty during refueling per TMI Action Item I A 1 1
VASSALLO, D B Operating Reactors Branch 2 83/05/03 ARNOLD, D
Iowa Electric Light & Power Co 3pp 18503 270 24X
Fiche 50-331, 83/05/03, 8305180081

--8305180091 Amend 90 to License DPR-49, deleting requirement for shift technical advisor to be on duty during refueling per TMI Action Item I A 1 1
VASSALLO, D B Operating Reactors Branch 2 83/05/03 4pp
18503 273 24X Fiche. 50-331, 83/05/03, 8305180081

--8305180093 Notice of issuance & availability of Amend 90 to License DPR-49
ROONEY, V L Operating Reactors Branch 2 83/05/03 2pp
18503 277 24X Fiche. 50-331, 83/05/03, 8305180081

8305060060 Application to amend License DPR-49, revising App A Tech Specs re max critical power ratio operating limits for 8x8 & 8x8R/P8x8R fuel types to allow implementation of turbine control valve mod
ROOT, L D Iowa Electric Light & Power Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18345 052 24X
Fiche 50-331, 83/05/04, 8305060060

--8305060066 Proposed App A Tech Specs revising max critical power ratio operating limits for 8x8 & 8x8R/P8x8R fuel types to allow implementation of turbine control valve mod
* Iowa Electric Light & Power Co 83/05/04 2pp 18345 053
24X Fiche 50-331, 83/05/04, 8305060060

--8305060076 Rev 1 to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr, Reload 6 "
WAGNER, R L , ZARBIS, W A , CHARNLEY, J S General Electric Co
Y1003J01A46 R01 83/03/31 20pp 18345 055 24X
Fiche 50-331, 83/05/04, 8305060060

8305180752 Provides clarification of SER re environ qualification of safety-related electrical equipment. All justifications for continued operation should be reviewed to ensure that all unqualified equipment covered Proprietary guidelines encl
VASSALLO, D. B Operating Reactors Branch 2 83/05/04 LIU, L Iowa Electric Light & Power Co 5pp 18506 048 24X
Fiche. 50-331, 83/05/04, 8305180752

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D. G Division of Licensing 83/05/09. Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170719 Advises that action required by 830209 Amend 81 to License DPR-49 & Generic Ltr 83-07 complete, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
VASSALLO, D B Operating Reactors Branch 2 83/05/09 LIU, L Iowa Electric Light & Power Co 2pp 18496 196 24X
Fiche 50-331, 83/05/09, 8305170719

8305260167 Forwards request for addl info re NUREG-0737, Item II K 3 28 on qualification of automatic depressurization sys accumulators Response within 45 days requested
VASSALLO, D B Operating Reactors Branch 2 83/05/11 LIU, L Iowa Electric Light & Power Co 3pp 18648 117 24X
Fiche 50-331, 83/05/11, 8305260167

8305230562 Informs that results of plant-unique calculations forming bases for mods to vacuum breakers will be submitted by 830731, in response to Generic Ltr 83-08 Required mods will be completed during Fall 1984 outage
ROOT, L D Iowa Electric Light & Power Co 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18537.330 24X
Fiche 50-331, 83/05/16, 8305230562

8305260192 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 LIU, L Iowa Electric Light & Power Co 2pp 18648 089 24X
Fiche 50-331, 83/05/18, 8305260192

8305240120 Forwards methodology used to address nonsafety-related equipment failures (IE Bulletin 79-01B), summary of environ qualification Action Items 40 & 41 & response for Category IV items, per 10CFR50 49 & 830504 request
ROOT, L D Iowa Electric Light & Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 18548 349 24X Fiche 50-331, 83/05/20, 8305240120.

Q Inspection reports, IE Bulletins & correspondence

8305040389 Advises that revised procedures covering adequate method to determine max permissible concentration-h from whole body counting data, per IE Insp Rept 50-331/82-06 will be delayed due to errors discovered in computer library
ROOT, L D Iowa Electric Light & Power Co 82/06/30 KEPPLER, J G Region 3, Office of Director 2pp 18323 205 24X
Fiche 50-331, 82/06/30, 8305040389

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305020358 Forwards IE Insp Rept 50-331/83-04 on 830216-19 & 0316-18 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/04/18 ARNOLD, D Iowa Electric Light & Power Co 2pp 18274 046 24X
Fiche 50-331, 83/04/18, 8305020358

--8305020360 IE Insp Rept 50-331/83-04 on 830216-19 & 0316-18 No noncompliance noted. Major areas inspected inservice insp program & procedures, insp documentation & recirculation sys & attached piping followup per IE Bulletin 82-03
KEY, W J , DANIELSON, D H Region 3, Office of Director 83/04/18 10pp 18274 048 24X Fiche 50-331, 83/04/18, 8305020358

8305100215 Forwards IE Insp Rept 50-331/83-01 on 830103-0225 & notice of violation
SHAFER, W D. Region 3, Office of Director 83/04/18 ARNOLD, D Iowa Electric Light & Power Co 2pp 18374 047 24X
Fiche 50-331, 83/04/18, 8305100215

--8305100216 Notice of violation from insp on 830103-0225
SHAFER, W D Region 3, Office of Director 83/04/18 2pp 18374 049 24X Fiche 50-331, 83/04/18, 8305100215

--8305100218 IE Insp Rept 50-331/83-01 on 830103-0225 Noncompliance noted failure to develop & adhere to detailed vessel head insulation removal procedures & to control measuring & testing equipment
CLARDY, L S , JORDAN, M J , WALKER, R D Region 3, Office of Director 83/04/18 8pp 18374 051 24X Fiche 50-331, 83/04/18, 8305100215

8305030317 Forwards finalized rept re followup insp at facility during wk of 830410 Areas included post-accident sampling, high-range containment monitors, high-range effluent monitors, training, dose assessment & in-plant survey procedures
STOETZEL, G A Battelle Memorial Institute, Pacific Northwest Laboratory 83/04/21 PATTERSON, J P Region 3, Office of Director 18pp 18297 051 24X Fiche 50-331, 83/04/21, 8305030317

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche. 50-000, 83/04/25, 8303040025

8305030131 Forwards addl response to IE Bulletin 82-03, Rev 1 re intergranular stress corrosion cracking Response suppls 821201 ltr Cycle 7 refueling outage exams revealed no indication of cracking
ROOT, L D Iowa Electric Light & Power Co 83/04/25 KEPPLER, J. G Region 3, Office of Director 9pp 18300 180 24X
Fiche 50-331, 83/04/25, 8305030131

8305100320 Responds to NRC ltr re violations noted in IE Insp Rept 50-331/83-02 Corrective actions, licensing personnel involved in development of Tech Spec changes cautioned re necessity for care & accuracy
ROOT, L D Iowa Electric Light & Power Co 83/04/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 3pp. 18370 094 24X Fiche 50-331, 83/04/25, 8305100320

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8305100364 Acl receipt of 830425 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-331/83-02
STREETER, J F Region 3, Office of Director 83/05/04 LIU, L Iowa Electric Light & Power Co 1p 18379 088 24X
Fiche 50-331, 83/05/04, 8305100364

--8305100372 Responds to NRC 830324 ltr re violation noted in IE Insp Rept 50-331/83-02 Corrective actions personnel cautioned re necessity for accuracy in development of Tech Spec changes
ROOT, L D Iowa Electric Light & Power Co 83/04/25 DEYOUNG, R. Director's Office, Office of Inspection and Enforcement 3pp 18379 089 24X Fiche 50-331, 83/05/04, 8305100364

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033.

8305190251 Forwards IE Insp Rept 50-331/83-06 on 830328-31 No noncompliance noted
STREETER, J F. Region 3, Office of Director. 83/05/06. LIU, L Iowa Electric Light & Power Co 2pp 18501:293. 24X
Fiche 50-331, 83/05/06, 8305190251

--8305190256 IE Insp Rept 50-331/83-06 on 830328-31 No noncompliance noted Major areas inspected general & nonlicensed training & licensed operator requalification training
SUTPHIN,R N , HAWKINS,F C Region 3, Office of Director
83/05/05 6pp 18501 295 24X Fiche 50-331,83/05/06,8305190251

8305240511 Documents results of visual insp of core spray sparger during 1983 refueling outage per IE Bulletin 80-13 Insp conducted w/remote actuated TV camera Equipment resolution capability verified using one mil wire
ROOT,L D Iowa Electric Light & Power Co 83/05/09 KEPPLER,J G
Region 3, Office of Director 1p 18571 273 24X
Fiche 50-331,83/05/09,8305240511

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305310176 Forwards IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/05/16 LIU,L
Iowa Electric Light & Power Co 2pp 18659 118 24X
Fiche,50-331,83/05/16,8305310176

--8305310181 IE Insp Rept 50-331/83-08 on 830411-15 No noncompliance noted,Major areas inspected actions taken in response to 810922 confirmatory action ltr & emergency preparedness appraisal improvement & training
PATTERSON,J P , SNELL,W G , AXELSON,W L Region 3, Office of Director 83/05/12 15pp 18659 120 24X Fiche 50-331,83/05/16, 8305310176

8305240284 Forwards IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/05/18 LIU,L
Iowa Electric Light & Power Co 2pp 18548 088 24X
Fiche,50-331,83/05/18,8305240284

--8305240292 IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted.Major areas inspected radiation protection program for operation & refueling,including organization & staffing, staff qualifications,training & outage planning
HUETER,L J., PAUL,R A , GREGER,L R Region 3, Office of Director
83/05/17 17pp, 18548.090 24X Fiche 50-331,83/05/18,8305240284

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697'009 24X Fiche 50-000,83/05/19,8303040040

8305240120 Forwards methodology used to address nonsafety-related equipment failures (IE Bulletin 79-01B),summary of environ qualification Action Items 40 & 41 & response for Category IV items,per 10CFR50 49 & 830504 request
ROOT,L D. Iowa Electric Light & Power Co 83/05/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 19pp 18548 349
24X Fiche 50-331,83/05/20,8305240120

8305260315 Confirms 830621 meeting between MJ Jordan & L Root in Cedar Rapids,IA re SALP Discussion to update regulatory improvement program will be held following meeting Outside observers must notify of attendance by 830617
NORELIUS,C E. Division of Project & Resident Programs. 83/05/23
LIU,L Iowa Electric Light & Power Co 1p 18626 006 24X
Fiche 50-331,83/05/23,8305260315

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc. 114pp 18647'007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305180346 Forwards monthly operating rept for Apr 1983
MINECK,D L Iowa Electric Light & Power Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18485 282 24X
Fiche 50-331,83/05/13,8305180346.

--8305180349 Monthly operating rept for Apr 1983
MILLER,W Iowa Electric Light & Power Co 83/05/13 8pp
18485 283 24X Fiche 50-331,83/05/13,8305180346

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305030394 Forwards LER 83-009/03L-0
MINECK,D L Iowa Electric Light & Power Co 83/04/25 KEPPLER,J G
Region 3, Office of Director 1p 18306 236 24X
Fiche 50-331,83/04/25,8305030394

--8305030396 LER 83-008/03L-0 on 830326,eight accessible hydraulic snubbers visually inspected & deficiencies noted Surveillance Procedure STP 46H002 revised to address mechanical aspects in addition to hydraulic mechanism
REIMERS,G A Iowa Electric Light & Power Co 83/04/25 Region 3, Office of Director 3pp 18306 237 24X Fiche 50-331, 83/04/25,8305030394

8305060472 RO while in cold shutdown,w/all rods inserted,reactor mode moved from refuel position to shutdown position & A logic did not trip Caused by failure of A sys shutdown scram reset interlock Unit maintained in cold shutdown
MINECK,D L Iowa Electric Light & Power Co 83/04/26 KEPPLER,J G
Region 3, Office of Director 1p 18351 174 24X
Fiche 50-331,83/04/26,8305060472

8305020511 PNO-III-83-032 on 830426,scram circuitry failed to operate properly when mode switch moved from refuel position to shutdown position Caused by three loose wires in rectifier bridge
JORDAN,M , SHAFER,W Region 3, Office of Director 83/04/27 1p
18281 253 24X Fiche 50-331,83/04/27,8305020511

8305040445 PNO-III-83-033 on 830428,contract health physics technician observed w/small vial containing white powdery substance Preliminary test identified substance as cocaine Individual denied access to site
CHRISTOFFER,G , CREED,J , MILLER,J Region 3, Office of Director
83/04/29 1p 18321 299 24X Fiche 50-331,83/04/29,8305040445

8305130094 RO on 830212,during Type C local leak rate testing,two MSIVs exceeded Tech Specs Valves repaired
MINECK,D L Iowa Electric Light & Power Co 83/05/06 KEPPLER,J G
Region 3, Office of Director 1p 18437 201 24X
Fiche 50-331,83/05/06,8305130094.

8305240221 LER 83-012/01T-0 on 830425,full scram should have been received when mode switch moved from refuel to shutdown, however,sys A did not trip Caused by faulty solder connection on rectifier Connections resoldered W/830510 ltr
KIBLER,D R , MINECK,D L Iowa Electric Light & Power Co 83/05/10
KEPPLER,J G Region 3, Office of Director 4pp 18575 262 24X
Fiche 50-331,83/05/10,8305240221

8305240236 LER 83-010/03L-0 on 830411,during refueling outage,one snubber found inoperable,one indeterminant,one had missing bushing & one w/bushing disengaged Caused by procedure error during previous maint W/830511 ltr
REIMERS,G A , MINECK,D L Iowa Electric Light & Power Co 83/05/10
KEPPLER,J G Region 3, Office of Director 6pp 18548 322 24X
Fiche 50-331,83/05/10,8305240236

8305270440 Forwards updated LERs 81-015/01T-1 & 81-016/01T-1
MINECK,D L Iowa Electric Light & Power Co 83/05/16 KEPPLER,J G
Region 3, Office of Director 1p 18642 259 24X
Fiche 50-331,83/05/16,8305270440

--8305270451 Updated LER 81-015/01T-1 on 810421,lower crankshaft 14 bearing found wiped on journal surface similar to problem identified on diesel 1G-31 Caused by high temp Bearing replaced & crankshaft relapped
DONNELLY,P M Iowa Electric Light & Power Co 83/05/16 Region 3, Office of Director 4pp 18642 253 24X Fiche 50-331, 83/05/16,8305270440

--8305270460 Updated LER 81-016/01T-1 on 810421,lower crankshaft thrust bearing 13 & adjacent bearing 12 found wiped on journal surface.Caused by high temp Crankshaft thrust bearings replaced & crankshaft relapped
DONNELLY,P M Iowa Electric Light & Power Co 83/05/16 Region 3, Office of Director 3pp 18642 256 24X Fiche 50-331, 83/05/16,8305270440

8305270429 LER 83-013/01T-0 on 830215, two MSIVs exceeded Tech Spec acceptance criteria Caused by wear on valve seats Valve seats reworked Reportability of event as LER established on 830505 W/830520 ltr
KIBLER, D R , MINECK, D L Iowa Electric Light & Power Co 83/05/20
KEPPLER, J G Region 3, Office of Director 2pp 18642 287 24X
Fiche 50-331, 83/05/20, 8305270429

DOCKET 50-332 BARNWELL REPROCESSING PLANT

G Inspection reports, IE Bulletins & correspondence

8305270288 Forwards IE Insp Rept 50-332/83-01 on 830301-04 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/03/23 BUCKHAM, J A Allied General Nuclear Services 2pp 18642 042 24X Fiche 50-332, 83/03/23, 8305270288

--8305270304 IE Insp Rept 50-332/83-01 on 830301-04 No noncompliance noted Major areas inspected preoperational tests, organization safety committees, internal review & independent effort
CORYELL, G P Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/03/22. 4pp 18642 044. 24X Fiche 50-332, 83/03/23, 8305270288

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

F Security, medical, emergency & fire protection plans

8305060548 Notifies that submittals re proposed alternate safe shutdown capability, mods & exemptions to meet Sections III G 3, III G & III L to 10CFR50 App R, acceptable
VASSALLO, D. B Operating Reactors Branch 2 83/04/26 BAYNE, J P Power Authority of the State of New York. 3pp 18359 213 24X Fiche. 50-333, 83/04/26, 8305060548

--8305060553 Exemption from provisions of Sections III G 2, III G & III L of 10CFR50 App R re alternate safe shutdown capability
EISENHUT, D G. Division of Licensing 83/04/26 Power Authority of the State of New York. 5pp 18359 216 24X
Fiche 50-333, 83/04/26, 8305060548

--8305060557 Safety evaluation supporting util request for exemption from Sections III G 3 & III L of 10CFR50 App R re alternate safe shutdown capability
* Office of Nuclear Reactor Regulation, Director 83/04/26 12pp. 18359 221 24X Fiche 50-333, 83/04/26, 8305060548

8305180572 Forwards exemption from requirements of 10CFR50, App E re annual schedule for emergency preparedness exercise Next exercise must be conducted no later than 831015
VASSALLO, D B Operating Reactors Branch 2 83/04/28 BAYNE, J P Power Authority of the State of New York 2pp 18505 298 24X
Fiche 50-333, 83/04/28, 8305180572

--8305180577 Exemption granting relief from requirements of 10CFR50, App E re schedule for conducting emergency preparedness exercise Next exercise must be conducted no later than 831015
EISENHUT, D. G Division of Licensing 83/04/28 Power Authority of the State of New York 3pp 18505 300 24X
Fiche 50-333, 83/04/28, 8305180572

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305250137 Informs that NUREG-0737 Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed
VASSALLO, D B Operating Reactors Branch 2 83/05/18 BAYNE, J P Power Authority of the State of New York 3pp. 18596 201 24X
Fiche 50-333, 83/05/18, 8305250137.

8305230375 Forwards amended exemption requests to NRC 830202 draft safety evaluation of App R, description of proposed water sprays & ltr from fire protection consultant providing info per 830511 request
BAYNE, J P. Power Authority of the State of New York. 83/05/19. DENTON, H R. Office of Nuclear Reactor Regulation, Director. 13pp 18538 243. 24X Fiche 50-333, 83/05/19, 8305230375.

J Insurance & indemnity information

8305120208 Forwards Endorsement 65 to NELIA Policy NF-208 & Endorsement 55 to MAELU Policy MF-77
GOLDEN, M P Marsh & McLennan, Inc 83/05/03 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18427 358 24X Fiche 50-000, 83/05/03, 8305120208

P Operating license stage documents & correspondence

8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Force effort, per 821221 ltr
DYSON, J S Power Authority of the State of New York 83/03/02. TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18541 338 24X
Fiche 50-000, 83/03/02, 8305230597

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305030135 Forwards safety evaluation based on review of util submittals re TMI Action Item II B 1, "RCS Vents " Licensee venting capability acceptable
VASSALLO, D B Operating Reactors Branch 2 83/04/18 BAYNE, J P Power Authority of the State of New York 4pp 18309 235. 24X
Fiche: 50-333, 83/04/18, 8305030135

--8303310020 "Selected Operating Reactor Issues Program II, RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept
HELB, J T Energy Incorporated HELD, J T Lawrence Livermore Laboratory. FIN A-0250 B14/TER-B-7 83/03/02 ALBERTHAL, G NRC - No Detailed Affiliation Given 4pp 18309 239 24X
Fiche: 50-333, 83/04/18, 8305030135

8305030066 Forwards safety evaluation & technical evaluation rept re environ qualification of safety-related electrical equipment Util should reaffirm justification for continued operation Technical evaluation withheld
VASSALLO, D. B Operating Reactors Branch 2 83/04/19 BAYNE, J. P Power Authority of the State of New York 3pp 18326 114 24X
Fiche 50-333, 83/04/19, 8305030066

--8305030070 Safety evaluation re environ qualification of safety-relatd electric equipment Four major qualification deficiencies listed
* Office of Nuclear Reactor Regulation, Director. 83/04/19. 7pp 18326 117 24X Fiche 50-333, 83/04/19, 8305030066

8305020209 Forwards response to NRC 830316 ltr re NUREG-0737, Item II K 3 13, "RCIC Automatic Restart," RCIC sys modified to relocate signal for high reactor vessel water level trip from RCIC turbine trip valve to steam supply valve
BAYNE, J P. Power Authority of the State of New York 83/04/28
VASSALLO, D B Operating Reactors Branch 2 2pp 18278 133. 24X
Fiche 50-333, 83/04/28, 8305020209

8305040424 Forwards application for amend to License DPR-59, requesting approval of proposed radiological effluent Tech Specs w/fixed implementation date of 840701
BAYNE, J P Power Authority of the State of New York 83/04/29
VASSALLO, D. B Operating Reactors Branch 2 2pp 18321 306 24X
Fiche 50-333, 83/04/29, 8305040424

--8305040434 Application for amend to License DPR-59, requesting approval of proposed radiological effluent Tech Specs w/fixed implementation date of 840701
BAYNE, J P Power Authority of the State of New York. 83/04/29 1p 18321 308 24X Fiche 50-333, 83/04/29, 8305040424

--8305040438 Proposed radiological effluent Tech Specs
* Power Authority of the State of New York 83/04/29. 76pp 18321. 309. 24X Fiche. 50-333, 83/04/29, 8305040424

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs. Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441. 120. 24X
Fiche 50-000, 83/05/02, 8305020455

8305040311 Forwards response to 830202 request for addl info re NUREG-0737, Item II F 1 6, "Containment Hydrogen Monitor." Info re water level monitors to be provided by 830615
BAYNE, J P Power Authority of the State of New York 83/05/02.
VASSALLO, D B Operating Reactors Branch 2 3pp, 18323 300. 24X
Fiche 50-333, 83/05/02, 8305040311

8305050026 Forwards NEDO-22209, "Analysis of Scram Discharge Vol Sys Piping Integrity " No further action planned re equipment qualification & sys design mods identified in generic SER (NUREG-0803)
BAYNE, J P. Power Authority of the State of New York 83/05/03
VASSALLO, D. B Operating Reactors Branch 2 2pp 18339 313 24X
Fiche. 50-333, 83/05/03, 8305050026

8305200246 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737, Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved
VASSALLO, D B Operating Reactors Branch 2 83/05/05 BAYNE, J P
Power Authority of the State of New York 5pp 18540 206 24X
Fiche. 50-333, 83/05/05, 8305200246

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305260209 Forwards request for addl info re 820401 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 45 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/05/11 BAYNE, J P
Power Authority of the State of New York 3pp 18629 354 24X
Fiche. 50-333, 83/05/11, 8305260209

8305160106 Forwards "Scram Instrument Vol Diverse Instrumentation for JA Fitzpatrick Nuclear Plant," supporting request that 801002 & 810109 orders re short-term mods of scram discharge vol sys be amended or lifted by 830630
BAYNE, J. P. Power Authority of the State of New York 83/05/12
DENTON, H R Office of Nuclear Reactor Regulation, Director
DEYOUNG, R Director's Office, Office of Inspection and Enforcement
2pp. 18450 096 24X Fiche 50-333, 83/05/12, 8305160106

--8305160112 "Scram Instrument Vol Diverse Instrumentation for JA Fitzpatrick Nuclear Plant "
* Power Authority of the State of New York 83/03/31 18pp
18450.098 24X Fiche 50-333, 83/05/12, 8305160106

8305200265 Forwards application to amend License DPR-59, revising Tech Spec Table 3 7-1 re process pipeline penetrating primary containment
BAYNE, J P Power Authority of the State of New York 83/05/13
VASSALLO, D B Operating Reactors Branch 2 2pp 18516 310 24X
Fiche 50-333, 83/05/13, 8305200265

--8305200268 Application to amend Tech Specs, revising Table 3 7-1 re process pipeline penetrating primary containment
BAYNE, J P Power Authority of the State of New York 83/05/13
1p 18516 312 24X Fiche 50-333, 83/05/13, 8305200265

--8305200272 Proposed Tech Spec changes re process piping penetrating primary containment
* Power Authority of the State of New York 83/05/13 4pp
18516 313 24X Fiche 50-333, 83/05/13, 8305200265

8305260297 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mod to plant design or operations required Action complete
VASSALLO, D. B Operating Reactors Branch 2 83/05/18 BAYNE, J P
Power Authority of the State of New York 2pp 18629 323 24X
Fiche 50-333, 83/05/18, 8305260297

8305240492 Forwards filing fee per 10CFR170 22 re Tech Spec changes to piping penetrating primary containment under protest pending final determination of legality of fee schedule
BAYNE, J P Power Authority of the State of New York 83/05/19
VASSALLO, D B Operating Reactors Branch 2, 1p 18572 069 24X
Fiche: 50-333, 83/05/19, 8305240492

8305240442 Forwards response to 10CR50 49 re equipment qualification Response to equipment qualification technical evaluation rept will be submitted separately since request from schedular exemption denied.
BAYNE, J P Power Authority of the State of New York. 83/05/20
VASSALLO, D. B Operating Reactors Branch 2 84pp 18573·036 24X
Fiche·50-333, 83/05/20, 8305240442

8305240463 Forwards response to Generic Ltr 83-08 re results of plant-unique calculations which form either bases for vacuum breaker mods or provide justification for as-built acceptability
BAYNE, J. P. Power Authority of the State of New York 83/05/20
VASSALLO, D B Operating Reactors Branch 2 2pp. 18573·173 24X
Fiche 50-333, 83/05/20, 8305240463

8305270340 Forwards application to amend License DPR-59 & "Supplemental Reload Licensing Submittal for JA Fitzpatrick Nuclear Power Plant, Reload 5 " Amend changes std reload licensing submittal for forthcoming Reload 5/Cycle 6 core
BAYNE, J P Power Authority of the State of New York 83/05/25
VASSALLO, D B Operating Reactors Branch 2 2pp 18643 071 24X
Fiche 50-333, 83/05/25, 8305270340

--8305270352 Application to amend License DPR-59, changing std reload licensing submittal for forthcoming Reload 5/Cycle 6 core
BAYNE, J P Power Authority of the State of New York 83/05/25
1p 18643 073 24X Fiche 50-333, 83/05/25, 8305270340

--8305270364 Proposed Tech Specs 3 1-1, 3 1-2, 4 1-1, 4 2-1, 3 4-1, 3 4-2, 3 5-6 to 3 5-10, 3 6-1, 4 6-1, 6 1-1 & 6 2-1 re Reload 5/Cycle 6
* Power Authority of the State of New York 83/05/25 38pp
18643 074 24X Fiche 50-333, 83/05/25, 8305270340

--8305270378 Rev 0 to "Supplemental Reload Licensing Submittal for JA Fitzpatrick Nuclear Power Plant, Reload 5 "
ZARBIS, W A , WAGNER, R L , CHARNLEY, J S General Electric Co
Y1003J01A56 R01 83/03/31 25pp 18643 103 24X
Fiche 50-333, 83/05/25, 8305270340

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305110501 Forwards IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/26
MCNEILL, C A Power Authority of the State of New York 2pp
18393 350 24X Fiche 50-333, 83/04/26, 8305110501

--8305110508 IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737, Item II B 2, "Design Review of Plant Shielding "
BRIGGS, L , HAVERKAMP, D , EAPEN, P Region 1, Office of Director
83/04/22 8pp 18393 352 24X Fiche 50-333, 83/04/26, 8305110501

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305110369 Forwards IE Insp Rept 50-333/83-06 on 830301-31 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/04/28
MCNEILL, C A Power Authority of the State of New York 2pp
18406·299 24X Fiche 50-333, 83/04/28, 8305110369

--8305110376 Notice of violation from insp on 830301-31
* Region 1, Office of Director 83/04/28 2pp 18406 301 24X
Fiche 50-333, 83/04/28, 8305110369

--8305110391 IE Insp Rept 50-333/83-06 on 830301-31 Noncompliance noted failure to implement radiation protection procedures, failure to implement biannual procedure review & failure to maintain special procedure re ac power failures
LINVILLE, J C , DOERFLEIN, L T , KISTER, H B Region 1, Office of Director 83/04/13 15pp 18406 303 24X Fiche 50-333, 83/04/28, 8305110369

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18392 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305250538 Notification of 830520 significant licensee meeting w/util in Buchanan, NY to present results of SALP repts
KISTER, H B Region 1, Office of Director 83/05/17 Region 1, Office of Director 2pp 18594 354 24X Fiche 50-000, 83/05/17, 8305250538

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305270392 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-11
MARTIN, T T Division of Engineering & Technical Programs 83/05/20, MCNEILL, C A Power Authority of the State of New York 2pp 18642 183 24X Fiche 50-333, 83/05/20, 8305270392

--8305270399 Responds to NRC 830413 ltr re violations noted in IE Insp Rept 50-333/83-11 Corrective actions burial ground personnel resealed open box & waste package & handling Procedure F-GP-488 revised on 830330
MCNEILL, C A Power Authority of the State of New York 83/05/11
MARTIN, T T Division of Engineering & Technical Programs 2pp 18642 185 24X Fiche 50-333, 83/05/20, 8305270392

8305270274 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-24 Required actions to improve QA program listed
MARTIN, T T Division of Engineering & Technical Programs 83/05/23 MCNEILL, C A Power Authority of the State of New York 2pp 18643 131 24X Fiche 50-333, 83/05/23, 8305270274

--8305270284 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-333/82-24 Corrective actions design verification by supervisors in Design & Analysis Procedure 3 11 & 3 18 revised per insp rept. Rev to be completed by Apr 1983
BAYNE, J P Power Authority of the State of New York 83/04/01
HAYNES, R C Region 1, Office of Director 15pp 18643 133 24X Fiche 50-333, 83/05/23, 8305270274

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007. 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305130132 Forwards monthly operating rept for Apr 1983
MCNEILL, C A Power Authority of the State of New York 83/05/09
Director's Office, Office of Inspection and Enforcement 1p 18437 206 24X Fiche 50-333, 83/05/09, 8305130132

--8305130134 Monthly operating rept for Apr 1983
COOK, J Power Authority of the State of New York 83/05/09 6p
18437 207 24X Fiche 50-333, 83/05/09, 8305130132

8305270189 "Annual Summary of Plant Mods, Changes & Experiments for 1982 "
MCNEILL, C A Power Authority of the State of New York 83/05/13
ALLAN, J M Region 1, Office of Director 23pp, 18638 001 24X Fiche 50-333, 83/05/13, 8305270189

S Reportable occurrences, LERs & related correspondence

8305050341 Forwards AEOD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR, RES & IE
BROWN, E J , ASHE, F S Reactor Operations Analysis Branch 83/04/13
SEYFRIT, K V Reactor Operations Analysis Branch 2pp 18352 031 24X Fiche 50-000, 83/04/13, 8305050341

--8305050353 "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment. " AEOD engineering evaluation rept
BROWN, E J , ASHE, F S Director's Office 83/04/13, 7pp 18352 053 24X Fiche 50-000, 83/04/13, 8305050341

8305110259 Forwards LER 83-016/03L-0
MCNEILL, C A Power Authority of the State of New York 83/04/21
ALLAN, J M Region 1, Office of Director 1p 18393, 291 24X Fiche 50-333, 83/04/21, 8305110259

--8305110264 LER 83-016/03L-0 on 830412, setpoint of high-high trip found less conservative than Tech Spec limit Caused by instrument drift Setpoint adjusted & test frequency increased for trend observation
KEITH, H N Power Authority of the State of New York 83/04/21, Region 1, Office of Director 1p, 18393 292 24X Fiche 50-333, 83/04/21, 8305110259

8305110405 Forwards LER 83-015/03L-0
MCNEILL, C A Power Authority of the State of New York 83/04/21
ALLAN, J M Region 1, Office of Director 1p 18392 016, 24X Fiche 50-333, 83/04/21, 8305110405

--8305110416 LER 83-015/03L-0 on 830408, while conducting Surveillance Test F-ST-1D, switch 2A-S12B found out of normal position in Test Mode D Caused by inadequacies in implementation of procedural controls
KEITH, H N Power Authority of the State of New York 83/04/21
Region 1, Office of Director 2pp 18392 017 24X Fiche 50-333, 83/04/21, 8305110405

8305110400 Forwards Updated LER 83-016/03L-1
MCNEILL, C A Power Authority of the State of New York 83/04/25
ALLAN, J M Region 1, Office of Director 1p 18392 012 24X Fiche 50-333, 83/04/25, 8305110400

--8305110408 Updated LER 83-016/03L-1 on 830412, during surveillance testing on D max stillwater level high radiation monitor, setpoint of high-high trip found below Tech Spec limit Caused by instrument drift Setpoint adjusted
KEITH, H N Power Authority of the State of New York 83/04/25
Region 1, Office of Director 1p 18392 013 24X Fiche 50-333, 83/04/25, 8305110400

8305110510 Forwards LER 83-017/03L-0
MCNEILL, C A Power Authority of the State of New York 83/04/27
ALLAN, J M Region 1, Office of Director 1p 18393 361 24X Fiche 50-333, 83/04/27, 8305110510

--8305110514 LER 83-017/03L-0: on 830414, Nine Mile Point-South Oswego 115kV Line 5 tripped & locked out, removing one reserve power supply from svc. Caused by line automatically isolating when tower hold down guy pulled out of ground
LISENO, R T Power Authority of the State of New York 83/04/27
Region 1, Office of Director 1p, 18393 362 24X Fiche 50-333, 83/04/27, 8305110510

8305230454 Forwards LER 83-014/03L-0
MCNEILL, C A Power Authority of the State of New York. 83/05/04
ALLAN, J M Region 1, Office of Director 1p 18537 342 24X Fiche 50-333, 83/05/04, 8305230454

--8305230459 LER 83-014/03L-0 on 830404, during normal plant operations, four cells of B side station battery found to have through wall cracks leaking electrolyte Caused by mishandling of cells during original installation Cells replaced
PETERS, R Power Authority of the State of New York 83/05/04
Region 1, Office of Director 2pp 18537 343 24X Fiche 50-333, 83/05/04, 8305230454

8305100360 Advises that discrepancy due to fuel pool wall irregularities & fact that new fuel racks at high end of allowable tolerance limit Not reportable per 10CFR21 Safety factor of two precludes wall-to-wall interaction
BAYNE, J P Power Authority of the State of New York 83/05/06
VASSALLO, D B Operating Reactors Branch 2 2pp 18378 216 24X
Fiche 50-333, 83/05/06, 8305100360

DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305200195 Supports util onsite emergency preparedness & upgraded plan per NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 " Item complete
VARGA, S A Operating Reactors Branch 1 83/05/11 CAREY, J J
Duquesne Light Co 3pp 18540 222 24X Fiche 50-334, 83/05/11, 8305200195

8305250426 Responds to 830209 & 0422 ltrs re changes to Revs 4 & 10 & correction of errors in Rev 9 to safeguards plan Changes consistent w/10CFR50 54(p) & acceptable for inclusion into safeguards plan
ALLAN, J M Region 1, Office of Director 83/05/18 CAREY, J J
Duquesne Light Co 3pp 18985 268 24X Fiche 50-334, 83/05/18, 8305250426

P Operating license stage documents & correspondence

8305230387 Responds to 830208 request for backfit info Total of $281 million spent on backfitting through Jul 1982 Addl $50 million required to complete work on NRC imposed backfits
ARTHUR, J M Duquesne Light Co 83/03/09 TOURTELOTTE, J
Regulatory Reform Task Force 17pp 18546 245 24X
Fiche 50-334, 83/03/09, 8305230387

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305020359 Forwards supplemental response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys" & NUREG-0737, Item II F 2 W/one oversize drawing Aperture card is available in PDR
CAREY, J J Duquesne Light Co 83/04/21 VARGA, S A Operating Reactors Branch 1 22pp 18273 198 24X Fiche 50-334, 83/04/21, 8305020359

8305040512 Discusses licensee action to initiate negotiations w/DOE re disposal of high level waste or spent nuclear fuel, per Amend 61 to License DPR-66 & Generic Ltr 83-07 re Nuclear Waste Policy Act of 1982 (Public Law 97-425), Section 302(b)
VARGA, S A Operating Reactors Branch 1 83/04/25 CAREY, J J
Duquesne Light Co 2pp 18336 229 24X Fiche 50-334, 83/04/25, 8305040512

8305040621 Forwards revised pages to 830328 Amend 66 to License DPR-66 incorporating radioactive effluent Tech Specs into license
TAM, P S Operating Reactors Branch 1 83/04/26 CAREY, J. J
Duquesne Light Co 2pp 18336 308 24X Fiche 50-334, 83/04/26, 8305040621

--8305040626 Revised pages to Amend 66 to License DPR-66 incorporating liquid effluent monitoring instrumentation into Tech Specs
* Operating Reactors Branch 1 83/04/26, 8pp 18336 311 24X
Fiche 50-334, 83/04/26, 8305040621

8305060604 Forwards rev to Tech Spec Change Request 84, in response to Generic Ltr 82-16 Rev required to reassign section numbers to conform w/format changes incorporated in Tech Spec Amend 66
CAREY, J J Duquesne Light Co 83/04/28 VARGA, S A Operating Reactors Branch 1 2pp 18349 014 24X Fiche 50-334, 83/04/28, 8305060604

--8305060609 Rev to application for amend to License DPR-66, consisting of Tech Spec Change Request 84, revising Tech Specs to conform w/change in format incorporated by Amend 66
CAREY, J J. Duquesne Light Co 83/04/28 1p 18349 016 24X
Fiche 50-334, 83/04/28, 8305060604

--8305060614 Proposed Tech Specs re administrative controls & power distribution limits
* Duquesne Light Co 83/04/28 5pp 18349 017 24X
Fiche 50-334, 83/04/28, 8305060604

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305100337 Forwards Franklin Research Ctr proprietary equipment environ qualification worksheets, in response to 830329 clarification of environ qualification SER Previous submittals justified continued operation Worksheets withheld (ref 10CFR2 790)
CAREY, J J Duquesne Light Co 83/05/02 VARGA, S A Operating Reactors Branch 1 2pp 18379 104 24X Fiche 50-334, 83/05/02, 8305100337

8305110360 Forwards WCAP-10252, nonproprietary version of WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel " Application for withholding WCAP-10196, submitted on 830202 encl
CAREY, J J Duquesne Light Co 83/05/02 VARGA, S A Operating Reactors Branch 1 1p 18392 146 24X Fiche 50-334, 83/05/02, 8305110360

--8305110377 Application for withholding proprietary WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel," per 10CFR2 790 Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp 83/04/20 VARGA, S A
Operating Reactors Branch 1 8pp 18392 147 24X
Fiche 50-334, 83/05/02, 8305110360

--8305110398 Nonproprietary version of, "Second Cycle Performance of Beaver Valley Unit 1 Fuel "
PRITCHETT, P A , KUNISHI, H , ROBERTS, E Westinghouse Electric Corp
WCAP-10252 83/05/02 66pp 18392 156 24X
Fiche 50-334, 83/05/02, 8305110360

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305230230 Advises that Tech Specs from Amends 47 & 36 re auxiliary feedwater sys surveillance satisfy open item noted in 820702 SER on NUREG-0737, Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication "
VARGA, S A Operating Reactors Branch 1 83/05/16 CAREY, J J
Duquesne Light Co 2pp 18543 152 24X Fiche 50-334, 83/05/16, 8305230230

8305240401 Forwards response to 10CFR50 49 rulemaking re environ qualification of electrical equipment When master list of equipment is coupled w/recent response to SER, more complete overview is presented
CAREY, J J Duquesne Light Co 83/05/19 VARGA, S A Operating Reactors Branch 1 40pp 18574 146 24X Fiche 50-334, 83/05/19, 8305240401

8305250516 Forwards addl info requested per 830512 telcon re util decision to replace existing control power transformers w/encapsulated-tube transformers per 10CFR50, App R Implementation planned during third refueling outage
CAREY, J J Duquesne Light Co 83/05/20 VARGA, S A Operating Reactors Branch 1 5pp 18588 273 24X Fiche 50-334, 83/05/20, 8305250516

8305270187 Forwards "Reload Safety Evaluation, Beaver Valley Nuclear Plant Unit 1, Cycle 4 " Requests that change to require 50% of in-core moveable detector thimbles for full core flux map be instituted for Cycle 4
CAREY, J J Duquesne Light Co 83/05/23 VARGA, S A Operating Reactors Branch 1 2pp 18638 107 24X Fiche 50-334, 83/05/23, 8305270187

--8305270190 "Reload Safety Evaluation, Beaver Valley Nuclear Plant Unit 1, Cycle 4 "
* Duquesne Light Co 83/02/28 19pp 18638 109 24X
Fiche 50-334, 83/05/23, 8305270187

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305050172 Forwards IE Insp Rept 50-334/83-07 on 830301-0404 & notice of violation
STAROSTECKI, R Division of Project & Resident Programs 83/04/20
CAREY, J J Duquesne Light Co 2pp 18341 013 24X
Fiche 50-334, 83/04/20, 8305050172

--8305050175 Notice of violation from insp on 830301-0404
* Region 1, Office of Director 83/04/20 2pp 18341 015 24X
Fiche 50-334, 83/04/20, 8305050172

--8305050180 IE Insp Rept 50-334/83-07 on 830301-0404 Noncompliance noted failure to provide supplemental LER info & failure to use approved procedure for refueling preparation
TROSKOSKI, W M., TRIPP, L E Region 1, Office of Director
83/04/18 20pp 18341 017 24X Fiche 50-334, 83/04/20, 8305050172

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305100337 Forwards Franklin Research Ctr proprietary equipment environ qualification worksheets, in response to 830329 clarification of environ qualification SER Previous submittals justified continued operation Worksheets withheld (ref 10CFR2 790).
CAREY, J J Duquesne Light Co 83/05/02 VARGA, S A. Operating Reactors Branch 1 2pp 18379 104 24X Fiche 50-334, 83/05/02, 8305100337

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441, 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305100268 Forwards Westinghouse Rev 1 to Procedure ISI-154, "Preservice & Inservice Insp of Reactor Vessels " Procedure meets intent of Reg Guide 1 150, Rev 1 as referenced in Generic Ltr 83-15
CAREY, J J Duquesne Light Co 83/05/06. VARGA, S A Operating Reactors Branch 1 1p 18371 160. 24X Fiche 50-334, 83/05/06, 8305100268

--8305100273 Rev 1 to Procedure ISI-154, "Preservice & Inservice Insp of Reactor Vessels "
ADAMONIS, D. C., LE FEBVRE, D. J , VANO, J. A Westinghouse Electric Corp 83/03/16 75pp. 18371 161 24X Fiche 50-334, 83/05/06, 8305100268

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200436 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/82-19 Violation withdrawn per 830420 verification that records of two maint/repair activities retained
MARTIN, T T Division of Engineering & Technical Programs 83/05/17
CAREY, J J Duquesne Light Co 2pp 18517 119 24X
Fiche 50-334, 83/05/17, 8305200436

--8305200439 Responds to NRC 820916 & 830324 ltrs re violations noted in IE Insp Rept 50-334/82-19 Requested documentation located in files at time of insp Violation C should be withdrawn.
CAREY, J J Duquesne Light Co 83/04/25 MARTIN, T T. Division of Engineering & Technical Programs 2pp 18517, 121 24X
Fiche 50-334, 83/05/17, 8305200436

8305240404 Forwards application for relief from inservice insp requirements re RHR HX nozzle Alternate exam requirements to be performed once per 40-month ASME Code period
CAREY, J J Duquesne Light Co 83/05/17 VARGA, S A Operating Reactors Branch 1 7pp 18571 045 24X Fiche 50-334, 83/05/17, 8305240404

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche: 50-000, 83/05/19, 8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8305060261 Forwards Vol 2 to "Annual Environ Rept, Radiological, 1982 "
SIEBER, J D Duquesne Light Co 83/04/25 WIGGINTON, D Operating Reactors Branch 1 1p 18344 193 24X Fiche 50-334, 83/04/25, 8305060261

--8305060269 Vol 2 to "Annual Environ Rept, Radiological, 1982 "
* Duquesne Light Co 83/04/25 126pp 18344 194 24X
Fiche 50-334, 83/04/25, 8305060261

8305110424 Forwards Vol 2 to "1982 Annual Environ Rept, Radiological. "
CAREY, J J Duquesne Light Co 83/04/25 HAYNES, R C Region 1, Office of Director 1p 18392 019 24X Fiche 50-334, 83/04/25, 8305110424

8305030593 Forwards NPDES discharge monitoring rept for Mar 1983
FEITKNECHT, C Duquesne Light Co 83/04/27 REID, R W Operating Reactors Branch 4 3pp 18303 271 24X Fiche 50-334, 83/04/27, 8305030593

--8305030595 NPDES discharge monitoring rept for Mar 1983
* Duquesne Light Co. 83/04/27 13pp 18303 273 24X
Fiche 50-334, 83/04/27, 8305030593

S Reportable occurrences, LERs & related correspondence

8305030311 Forwards updated LER 79-023/03X-1
LACEY, W S Duquesne Light Co 83/04/13 Region 1, Office of Director 2pp. 18297: 157 24X Fiche 50-334, 83/04/13, 8305030311

--8305030314 Updated LER 79-023/03X-1 on 790724, diesel generator output breaker 1 failed to close when control switch actuated & alarm indicated air start motor 1 failure to start generator Caused by sticking pinion Pinion assembly cleaned
DRUGA, R J Duquesne Light Co 83/04/11 Region 1, Office of Director 2pp 18297 159 24X Fiche 50-334, 83/04/13, 8305030311

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices, Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 5pp 18405. 095 24X Fiche 50-000, 83/04/21, 8305110427

8305110343 Forwards updated LER 83-008/03X-1
LACEY, W S Duquesne Light Co 83/04/25 ALLAN, J M Region 1, Office of Director 2pp 18406: 180 24X Fiche 50-334, 83/04/25, 8305110343

--8305110353 Updated LER 83-008/03X-1 on 830218,during testing of turbine driven auxiliary feedwater pump,excessive pump overheating at inboard packing follower observed Caused by packing failure (outer two rings found dry) Pump repacked
DRUGA,R J Duquesne Light Co 83/04/25 Region 1, Office of Director 2pp 18406 182 24X Fiche 50-334,83/04/25,8305110343

8305190185 Forwards updated LER 82-052/03X-1
LACEY,W S Duquesne Light Co 83/04/25 ALLAN,J M Region 1, Office of Director 2pp 18500 221 24X Fiche 50-334,83/04/25, 8305190185

--8305190309 Updated LER 82-052/03X-1 on 821105,while fire hydrant was being relocated due to interference w/Unit 2 activities,leak discovered in hydrant Caused by lack of awareness & inadequate research by Unit 2 crafts personnel
DRUGA,R J Duquesne Light Co 83/04/25 Region 1, Office of Director 2pp 18500 223 24X Fiche 50-334,83/04/25,8305190185

8305120402 Forwards LER 83-010/99X-0
LACEY,W S Duquesne Light Co 83/05/02 ALLAN,J M Region 1, Office of Director 2pp 18434 088 24X Fiche 50-334,83/05/02, 8305120402

--8305120411 LER 83-010/99X-0 on 830327,diesel driven fire pump failed operational surveillance test due to high coolant water temp Caused by casting defect in cylinder head Defective cylinder head & electrical components replaced
DRUGA,R J Duquesne Light Co 83/05/02 Region 1, Office of Director 2pp 18434 090 24X Fiche 50-334,83/05/02,8305120402

8305160058 Forwards LER 83-010/99X-0
LACEY,W S Duquesne Light Co 83/05/02 ALLAN,J M Region 1, Office of Director 2pp 18453 123 24X Fiche 50-334,83/05/02, 8305160058

--8305160064 LER 83-010/99X-0 on 830327,while performing weekly diesel engine driven fire pump operation test,water level in cooling sys expansion tank observed low Water added & high temp caused overflow Caused by defective cylinder head
DRUGA,R J Duquesne Light Co 83/05/02 Region 1, Office of Director 2pp 18453 125 24X Fiche 50-334,83/05/02,8305160058

8305230520 Forwards LER 83-011/03L-0
LACEY,W S, Duquesne Light Co 83/05/09 ALLAN,J M Region 1, Office of Director, 2pp 18536 323 24X Fiche 50-334,83/05/09, 8305230520

--8305230527 LER 83-011/03L-0 on 830409,motor thermal overload relay for containment sump to 1A low head safety injection pump suction valve (MOV-SI-860A) tripped,disabling motor Cause unknown.Event will be reevaluated
* Duquesne Light Co 83/05/09 Region 1, Office of Director 2pp. 18536:325 24X Fiche 50-334,83/05/09,8305230520

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

F. Security, medical, emergency & fire protection plans

8305040563 Forwards fire hazard analysis for facility
UHRIG,R E Florida Power & Light Co 83/04/12 EISENHUT,D G Division of Licensing 1p 18320 008 24X Fiche 50-335,83/04/12, 8305040563.

--8305040566 Fire hazard analysis for facility W/five oversize drawings Aperture cards are available in PDR
* Florida Power & Light Co 83/04/12 75pp 18320.009 24X Fiche:50-335,83/04/12,8305040563

8305200489 Forwards safeguards info re devitalization of certain equipment Info withheld (ref 10CFR73 21)
UHRIG,R.E. Florida Power & Light Co 83/04/22 O'REILLY,J P Region 2, Office of Director 1p 18513 007 24X Fiche,50-335,83/04/22,8305200489

8305170141 Summary of 830419-22 meetings w/util at site re physical security vital area analysis
NERBEB,V. Licensing Branch 3 83/05/03 Licensing Branch 3 4pp. 18495:325 24X Fiche 50-335,83/05/03,8305170141

8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09.No noncompliance noted.
DANCE,H C Division of Project & Resident Programs, 83/05/06 UHRIG,R.E. Florida Power & Light Co 2pp 18641 179 24X Fiche:50-335,83/05/06,8305270287.

--8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncomplience noted Major areas inspected emergency preparedness in technical support ctr
HUFFMAN,G N Region 2, Office of Director JENKINS,G R Division of Emergency Preparedness & Materials Safety 83/05/03 4pp 18641 181 24X Fiche 50-335,83/05/06,8305270287

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305200090 Notifies that NUREG-0737,Item III A 2 1. "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
CLARK,R A Operating Reactors Branch 3 83/05/11 UHRIG,R E Florida Power & Light Co 3pp 18541 001 24X Fiche 50-335,83/05/11,8305200090

8305200346 Forwards revised Chapters 5 & 6 to security plan Chapters withheld (ref 10CFR73 21)
UHRIG,R E Florida Power & Light Co 83/05/11 O'REILLY,J P Region 2, Office of Director 2pp 18516 251 24X Fiche 50-335,83/05/11,8305200346

J Insurance & indemnity information

8305040186 Forwards Endorsements 47 & 37 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively
DUCK,J R Marsh & McLennan, Inc 83/04/29 SALTZMAN,J Assistant Director for State & Licensee Relations 1p 18621 191 24X Fiche 50-335,83/04/29,8305040186

8305100182 Forwards executed Amends 8,9 & 10 to Indemnity Agreement B-76,adding Orlando Util Commission of City of Orlando,FL & Florida Municipal Power Agency & deleting Item 3 of attachment to indemnity agreement,respectively
UHRIG,R E Florida Power & Light Co 83/05/05 EISENHUT,D G Division of Licensing 4pp 18374 290 24X Fiche 50-335,83/05/05, 8305100182

P Operating license stage documents & correspondence

8305020602 Forwards safety evaluation for environ qualification of safety-related electrical equipment & proprietary technical evaluation rept Justification for continued operation on listed items requested W/o technical evaluation rept
CLARK,R A Operating Reactors Branch 3 83/04/21 UHRIG,R E Florida Power & Light Co 3pp 18284 204 24X Fiche 50-335,83/04/21,8305020602

--8305020603 Safety evaluation for environ qualification of safety-related electrical equipment Proprietary review guidelines encl
* Office of Nuclear Reactor Regulation, Director 83/04/21, 8pp 18284 207 24X Fiche 50-335,83/04/21,8305020602

8305060039 Ack receipt of 830419 ltr re resolution of thermal shield problems Schedule for submittal of repts to meet commitments submitted in ltr & discussed at 830425 meeting confirmed
CLARK,R.A Operating Reactors Branch 3 83/04/26 UHRIG,R E Florida Power & Light Co 2pp 18354 332 24X Fiche 50-335,83/04/26,8305060039

8305110128 Forwards safety evaluation of upper head voiding under natural circulation cooldown conditions Util analyses acceptable Program should be reviewed to assure that TMI Action Item I C 1 addressed within 60 days of ltr receipt
CLARK,R A Operating Reactors Branch 3 83/04/26 UHRIG,R E Florida Power & Light Co 4pp 18421 323 24X Fiche 50-335,83/04/26,8305110128

--8305110132 Safety evaluation re upper head voiding under natural circulation cooldown conditions Consequences of upper head voiding acceptable
* Office of Nuclear Reactor Regulation, Director 83/04/26 14pp. 18421.327 24X Fiche 50-335,83/04/26,8305110128

8305020168 Forwards plant recovery plan presented at 830425 meeting re reactor vessel internals & thermal shield,in response to Item C of 830419 ltr.Plan will be revised daily w/updates provided upon availability
UHRIG,R E Florida Power & Light Co 83/04/27 CLARK,R A Operating Reactors Branch 3 2pp 18284 062 24X Fiche 50-335,83/04/27,8305020168.

8305020345 Summarizes 830425 meeting w/NRC re reactor vessel internals & thermal shield plant recovery program concerning pressurized thermal shock Plant may safely operate w/o restriction from pressurized thermal shock considerations
UHRIG,R E Florida Power & Light Co 83/04/27 CLARK,R A
Operating Reactors Branch 3 13pp 18274 079 24X
Fiche 50-335,83/04/27,8305020345

8305020519 Forwards reactor vessel internals & thermal shield plant recovery program per 830419 commitment to provide safety assessment of possible effects on fuel performance due to loose parts No fuel problems indicated at facility
UHRIG,R E Florida Power & Light Co 83/04/27 CLARK,R A
Operating Reactors Branch 3 2pp 18281 254 24X
Fiche 50-335,83/04/27,8305020519

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to GLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc. 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305090476 Advises that 10-yr pressure-temp operating limits (P-T) for plant recovery program reactor vessel internals & thermal shield valid for upcoming Cycle 6 P-T limits will be reviewed & revised, if necessary, prior to exceeding 7 4 EFPY
UHRIG,R E Florida Power & Light Co 83/05/03 CLARK,R A
Operating Reactors Branch 3 1p 18362 271 24X
Fiche 50-335,83/05/03,8305090476

8305100236 Advises that vendor safety analysis to support installation of mods to auxiliary sys,per util 830103 ltr re main steam line break w/continued feedwater addition,is under review Response to core reactivity question expected by 830615
UHRIG,R E Florida Power & Light Co 83/05/03 CLARK,R A
Operating Reactors Branch 3 1p. 18374 127 24X
Fiche 50-335,83/05/03,8305100236

8305110105 Forwards Amend 57 to License DPR-67,safety evaluation & notice of issuance & availability Amend provides for removal of chlorine detectors from control room air intakes W/o encl
SELLS,D E Operating Reactors Branch 3 83/05/03 UHRIG,R E
Florida Power & Light Co 1p 18421 254 24X Fiche 50-335, 83/05/03,8305110105

8305120146 Forwards Amend 58 to License DPR-67,safety evaluation & notice of issuance & availability Amends change Tech Specs to clarify & modify surveillance requirements & limiting operating conditions for degraded grid voltage protection
SELLS,D E Operating Reactors Branch 3 83/05/03 UHRIG,R E
Florida Power & Light Co. 3pp 18435 312 24X
Fiche 50-335,83/05/03,8305120146

--8305120153 Amend 58 to License DPR-67,revising Tech Spec surveillance requirements & limiting operating conditions re grid voltage protection equipment & procedures
CLARK,R A Operating Reactors Branch 3 83/05/03 11pp
18435 315 24X Fiche 50-335,83/05/03,8305120146

--8305120160 Safety evaluation supporting Amend 58 to License DPR-67.
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp.
18435 326 24X Fiche 50-335,83/05/03,8305120146

--8209020602 "Technical Evaluation Rept on Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for St Lucie Nuclear Power Plant,Unit 1 "
SELAN,J.C Lawrence Livermore Laboratory FIN A-0250
UCID-19450 82/07/30 Office of Nuclear Reactor Regulation, Director 11pp. 18435 329 24X Fiche 50-335,83/05/03,8305120146

--8304060471 Rev 1,to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation," technical evaluation rept
SELAN,J C Lawrence Livermore Laboratory FIN A-0250 UCID-19450 R01. 83/03/23 Division of Licensing 10pp 18435 340 24X
Fiche 50-335,83/05/03,8305120146

--8305120171 Notice of issuance & availability of Amend 58 to License DPR-67.
TRAMMELL,C M Operating Reactors Branch 3 83/05/03 2pp
18435 351 24X Fiche 50-335,83/05/03,8305120146

8305120499 Summary of 830425 meeting w/util & C-E in Bethesda,MD re schedule for resolution of thermal shield damage Thermal shield chronological sequence encl
SELLS,D E. Operating Reactors Branch 3 83/05/03 Operating Reactors Branch 3 5pp. 18443 163 24X Fiche 50-335,83/05/03, 8305120499.

8305120520 Summary of 830425 meeting w/util & C-E in Bethesda,MD re thermal shock to reactor pressure vessel w/removal of thermal shield from facility Viewgraphs encl
SELLS,D E Operating Reactors Branch 3 83/05/03 Operating Reactors Branch 3 17pp 18441 341 24X Fiche 50-335,83/05/03, 8305120520

8305180567 Responds to 830425 ltr re decision to remove first reactor vessel matl irradiation surveillance specimen during current outage. Info resulting from exam & evaluation of specimen requested for review of thermal & shield analysis
CLARK,R A Operating Reactors Branch 3 83/05/04 UHRIG,R E
Florida Power & Light Co 2pp 18504 361 24X
Fiche 50-335,83/05/04,8305180567

8305100103 Forwards info justifying continued operation w/electrical equipment in Item 114 per 830421 ltr All other items listed in Category II B of Franklin Research Ctr technical evaluation rept replaced w/qualified transmitters
UHRIG,R E Florida Power & Light Co 83/05/05 CLARK,R A
Operating Reactors Branch 3 2pp 18377,249 24X
Fiche 50-335,83/05/05,8305100103

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130121 Responds to Generic Ltr 83-108, "Resolution of TMI Action Plan Item II K 3 5,'Automatic Trip of Coolant Pumps '" C-E Owners Group has chosen "trip two,leave two" strategy to resolve item Description of program expected by 830701
UHRIG,R E Florida Power & Light Co 83/05/10 EISENHUT,D G
Division of Licensing 2pp 18438 091 24X Fiche 50-335,83/05/10, 8305130121

8305170103 Notification of 830520 meeting w/util & C-E in Bethesda,MD to discuss loose parts monitoring sys & ex-core instrumentation Portions of meeting may be proprietary
SELLS,D E Operating Reactors Branch 3 83/05/12 CLARK,R A
Operating Reactors Branch 3 2pp 18495 340 24X
Fiche 50-335,83/05/12,8305170103

8305240599 Notification of cancellation of 830520 meeting w/util in Bethesda,MD to discuss loose parts monitoring sys & ex-core instrumentation
SELLS,D E Operating Reactors Branch 3 83/05/12 CLARK,R A
Operating Reactors Branch 3 2pp 18593 165 24X
Fiche 50-335,83/05/12,8305240599

8305170463 Forwards response to requests for addl info re Cycle 6 reload Performance of C-E fuel examined & Tech Spec change to remove augmentation factors supported
UHRIG,R E Florida Power & Light Co 83/05/13 EISENHUT,D G
Assistant Director for Licensing 19pp 18469 339 24X
Fiche 50-335,83/05/13,8305170463

8305270170 Forwards "St Lucie 1 & 2 & Turkey Point 3 & 4 Detailed Control Room Design Reviews Program Plan," fulfilling 830415 commitment per NUREG-0737,Suppl 1
UHRIG,R E Florida Power & Light Co. 83/05/14 EISENHUT,D G.
Division of Licensing 1p 18638 072 24X Fiche 50-335,83/05/14, 8305270170

8305230532 Forwards Class III fee for 830309 application for amend to Tech Specs for License DPR-67 re chlorine detection sys
UHRIG,R E Florida Power & Light Co 83/05/16 DIGGS,R.M License Fee Management Branch 1p 18537 059 24X Fiche 50-335,83/05/16, 8305230532

8305250397 Forwards Class III amend fee for 830309 request for proposed Tech Spec changed re chlorine detection sys
UHRIG,R E Florida Power & Light Co 83/05/16 DIGGS,R M License Fee Management Branch 2pp. 18592 082 24X Fiche 50-335,83/05/16, 8305250397

8305240372 Forwards responses to NRC 830118 request for info re accident monitoring,to aid in post-implementation review of NUREG-0737,Items II F 1 4,II F.1 5 & II F.1.6
UHRIG,R E Florida Power & Light Co 83/05/19 CLARK,R A
Operating Reactors Branch 3 17pp 18575 078 24X
Fiche 50-335,83/05/19,8305240372

8305250462 Reschedules 830520 meeting on plant recovery program - loose parts monitor & ex-core detector,for 830603,w/followup documentation to be provided by 830606
UHRIG,R E Florida Power & Light Co 83/05/19 CLARK,R A
Operating Reactors Branch 3 2pp 18589 033. 24X
Fiche 50-335,83/05/19,8305250462

8305250272 Responds to 830504 request for submittal date of exam & results for matl irradiation surveillance Final rept summarizing C-E test results expected in early Oct 1983 Rept will be submitted by 831101
UHRIG,R E Florida Power & Light Co 83/05/20 CLARK,R A
Operating Reactors Branch 3 1p 18592 301 24X
Fiche 50-335,83/05/20,8305250272

8305250395 Forwards schedule for qualification or replacement of equipment important to safety within scope of 10CFR50 49 Addl documentation to demonstate that equipment committed to be qualified meets specific requirements forthcoming
UHRIG,R E Florida Power & Light Co 83/05/20 CLARK,R A
Operating Reactors Branch 3 11pp 18585 319 24X
Fiche 50-335,83/05/20,8305250395

8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppl 1 to NUREG-0737
UHRIG,R E Florida Power & Light Co 83/05/20 EISENHUT,D G
Division of Licensing 1p 18588 333 24X Fiche 50-000,83/05/20,
8305250472

--8305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan "
* Florida Power & Light Co 83/04/30 34pp 18588 334 24X
Fiche 50-000,83/05/20,8305250472

8305250481 Forwards "Equipment Qualification Radiation Dose Map Development," in response to 830406 request Rept presents assumptions & methodology used in creating dose maps & two illustrative dose points
UHRIG,R E Florida Power & Light Co 83/05/20 EISENHUT,D G
Division of Licensing, 1p 18588 234 24X Fiche 50-335,83/05/20,
8305250481.

--8305250484 "Equipment Qualification Radiation Dose Map Development "
* Florida Power & Light Co 83/05/20 16pp 18588 235 24X
Fiche 50-335,83/05/20,8305250481

8305270168 Forwards responses to addl info requested in 830421 safety evaluation on environ qualification of safety-related electrical equipment
UHRIG,R E Florida Power & Light Co 83/05/25 CLARK,R A
Operating Reactors Branch 3 3pp 18638 056 24X
Fiche 50-335,83/05/25,8305270168

G Inspection reports, IE Bulletins & correspondence

8212040385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212040385

8305270561 Forwards IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/06
UHRIG,R E Florida Power & Light Co 2pp 18645 321 24X
Fiche 50-335,83/04/06,8305270561

--8305270576 IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted Major areas inspected Unit 1 plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items.
WRAY,J R , BARR,K P Region 2, Office of Director 83/04/05
8pp 18645:323 24X Fiche 50-335,83/04/06,8305270561.

8305270559 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-02 & 50-389/83-09
LEWIS,R C Division of Project & Resident Programs 83/04/14
UHRIG,R E Florida Power & Light Co 1p 18647 127 24X
Fiche 50-335,83/04/14,8305270559

--8305270572 Responds to NRC 830301 ltr re violations noted in IE Insp Rept 50-335/83-02 Corrective actions, licensed operator qualification program reviewed & will be revised by 830731 & exam date tracking sys established.
UHRIG,R.E. Florida Power & Light Co 83/03/31. O'REILLY,J P
Region 2, Office of Director, 4pp 18647,128 24X
Fiche 50-335,83/04/14,8305270559

--8305270579 Forwards IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/03/01
UHRIG,R.E. Florida Power & Light Co 2pp 18647 133 24X
Fiche 50-335,83/04/14,8305270559

--8305270584 Notice of violation from insp on 830124-28
* Region 2, Office of Director 83/03/01 2pp 18647 135 24X
Fiche 50-335,83/04/14,8305270559

--8305270594 IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 Noncompliance noted failure to follow procedures required by training programs & failure of licensed operators to be cognizant of facility design,procedures & license changes
BELISLE,G A , SKINNER,P H , UPRIGHT,C M Region 2, Office of Director 83/02/24 9pp 18647 137 24X Fiche 50-335,83/04/14,
8305270559

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020084 Withdraws 830405 relief request for performing inservice insp Relief will not be required
UHRIG,R E Florida Power & Light Co 83/04/26 EISENHUT,D G
Division of Licensing 1p 18279 278 24X Fiche 50-335,83/04/26,
8305020084

8305270359 Forwards IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/26
UHRIG,R E Florida Power & Light Co 2pp 18642 128 24X
Fiche 50-335,83/04/26,8305270359

--8305270367 IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted Major areas inspected local leak rate testing,snubber testing & review of Unit 1 procedures re refueling operations
WHITENER,H L , MATHIS,J , JAPE,F Region 2, Office of Director
83/04/21 6pp 18642 130 24X Fiche 50-335,83/04/26,8305270359

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305030340 Forwards three relief requests from certain Tech Spec 4 4 10 1 a & 10CFR50 55(g) inservice insp requirements Approval required during current outage
UHRIG,R E Florida Power & Light Co 83/04/29 EISENHUT,D G
Division of Licensing 9pp 18297 109 24X Fiche 50-335,83/04/29,
8305030340

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp. 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp. 18641 179 24X
Fiche 50-335, 83/05/06, 8305270287

--8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected emergency preparedness in technical support ctr
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/03. 4pp
18641 181 24X Fiche 50-335, 83/05/06, 8305270287

8305270329 Forwards IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp 18641 131 24X
Fiche 50-335, 83/05/06, 8305270329

--8305270339 IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted Major areas inspected inservice insp (Unit 1), core barrel/thermal shield damage (Unit 1), welding & NDE (Unit 1) & preservice insp (Unit 2)
CROWLEY, B R , BLAKE, J J Region 2, Office of Director 83/05/02
9pp 18641 133 24X Fiche 50-335, 83/05/06, 8305270329

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697.009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche. 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305030341 Forwards Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept, 1982 "
UHRIG, R E Florida Power & Light Co 83/04/28 MULLER, D R, NRC - No Detailed Affiliation Given 1p 18307 001 24X
Fiche 50-335, 83/04/28, 8305030341

--8305030347 Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept, 1982 "
* Applied Biology, Inc AB-442 83/03/31 406pp. 18307 004.
24X Fiche 50-335, 83/04/28, 8305030341

S Reportable occurrences, LERs & related correspondence

8305050127 Forwards LER 83-021/03L-0
WILLIAMS, J W Florida Power & Light Co 83/04/28. O'REILLY, J P.
Region 2, Office of Director 1p 18341 353 24X
Fiche 50-335, 83/04/28, 8305050127

--8305050138 LER 83-021/03L-0 on 830329, w/refueling cavity filled greater than 23 ft, two shutdown cooling hot leg suction valves closed, isolating flow to core Caused by shorting out of power supply to control circuit. Power restored
WALLING, G E Florida Power & Light Co 83/04/28 Region 2, Office of Director 1p 18341:334 24X Fiche: 50-335, 83/04/28, 8305050127

8305170527 Deficiency rept re potential significant safety hazard concerning defect in stainless steel tubing pressure boundary component Initially reported on 830504. Selected tubes returned to C-E Tubes for reinsp
SCHERER, A E Combustion Engineering, Inc 83/05/06 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement. 10pp
18468 017. 24X Fiche 50-335, 83/05/06, 8305170527.

8305170244 Forwards LER 83-025/03L-0
WILLIAMS, J. W. Florida Power & Light Co 83/05/09. O'REILLY, J P
Region 2, Office of Director 1p. 18466 124 24X
Fiche. 50-335, 83/05/09, 8305170244.

--8305170250 LER 83-025/03L-0 on 830419, 31-day fire station insp interval exceeded Caused by personnel oversight Personnel advised of importance of performing required insps.
BRANNIN, J P. Florida Power & Light Co 83/05/09. Region 2, Office of Director. 1p. 18466 125. 24X Fiche. 50-335, 83/05/09, 8305170244

8305200430 PND-II-83-040 on 830515, two util employees & one former employee arrested for cocaine & marijuana possession Arrest occurred offsite Employees not involved in licensed operator activities
LANDIS, K D , DANCE, H C Region 2, Office of Director. 83/05/17
1p 18517 150 24X Fiche 50-335, 83/05/17, 8305200430

8305250302 LER 83-026/09T-0 on 830513, 67 of 264 Bergen Paterson EA-3 clamps discovered oriented improperly Caused by vendor catalog interpreted improperly Clamps will be replaced during present outage W/830518 ltr
WILLIAMS, J. W , MCLAUGHLIN, L Florida Power & Light Co. 83/05/18
O'REILLY, J P Region 2, Office of Director 2pp 18592.154 24X
Fiche 50-335, 83/05/18, 8305250302

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305040022 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18330 065 24X Fiche 50-245, 83/04/25, 8305040022.

--8305040034 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate
COUNSIL, W. G Northeast Nuclear Energy Co (subs of Northeast Utilities). 83/04/12 EISENHUT, D G Division of Licensing 9pp
18330 066 24X Fiche 50-245, 83/04/25, 8305040022

--8305040039 Public version of revised emergency plan implementing procedures, including Procedures EPIP 4214 re Unit 1 reactor coolant & liquid waste post-accident sampling & EPIP 4222 re Unit 2 core damage estimate
* Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/03/31 300pp 18330 068 24X Fiche 50-245, 83/04/25, 8305040022.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180853 Authorizes refund for review of 821230 & 830408 requests from revised schedule for conducting emergency exercise
MILLER, W D License Fee Management Branch 83/05/11 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities). 1p
18506 030 24X Fiche 50-000, 83/05/11, 8305180853

8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III.A.2 1 Item complete
CRUTCHFIELD, D Operating Reactors Branch 5. 83/05/13 COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G. Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 18452.349. 24X
Fiche 50-000, 83/05/13, 8305160022

I Financial information

8305020093 Forwards "Annual Rept of Electric Utils, Licensees & Others (Class A & Class B), " FERC Form 1
BISHOP, R W Northeast Utilities 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279 109. 24X
Fiche 50-245, 83/04/26, 8305020093

J Insurance & indemnity information

8305120156 Forwards Endorsements 87 & 78 to NELIA Policy NF-173 & MAELU Policy MF-72, respectively
SINISI, J. M Marsh & McLennan, Inc 83/05/05 SALTZMAN, J D.
Assistant Director for State & Licensee Relations 3pp 18427 153
24X Fiche 50-245, 83/05/05, 8305120156.

P. Operating license stage documents & correspondence

8305230616 Forwards info in response to 830208 ltr requesting backfit cost data for operating nuclear units. Cost categorized according to NRC imposed, TMI & non-TMI backfits, util-initiated & hybrid backfits
COUNSIL, W G. Connecticut Yankee Atomic Power Co COUNSIL, W. G Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, W G. Northeast Utilities 83/03/21. TOURTELLOTTE, J. Regulatory Reform Task Force 25pp 18543 038 24X
Fiche 50-000, 83/03/21, 8305230616

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305160188 Advises that action required by 830126 Amends 88, 51 & 80 to Licenses DPR-21, DPR-61 & DPR-65, respectively & Generic Ltr 83-07 complete, based on util negotiations w/DOE re disposal of high level waste or spent nuclear fuel
CLARK, R A Operating Reactors Branch 3 83/04/20 COUNSIL, W G
Connecticut Yankee Atomic Power Co 2pp 18462 355 24X
Fiche. 50-000, 83/04/20, 8305160188

8305060058 Forwards SER supporting revs to radiological effluent Tech Specs Tech Specs acceptable
CLARK, R A Operating Reactors Branch 3 83/04/21 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp
18364 320 24X Fiche 50-336, 83/04/21, 8305060058

--8305060062 SER supporting revs to radiological effluent Tech Specs
* Office of Nuclear Reactor Regulation, Director 83/04/21 6pp
18364 322 24X Fiche 50-336, 83/04/21, 8305060058

--8209210332 "Radiological Effluent Tech Spec Implementation (A-2), Millstone Nuclear Power Station Unit 2," technical evaluation rept
FERNANDEZ, C , PANDEY, S., CARFAGNO, P Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-99 82/09/17 NRC - No Detailed Affiliation Given 26pp 18364 328 24X
Fiche: 50-336, 83/04/21, 8305060058.

8305040447 Provides info justifying continued operation in light of thermal shield concerns, per request made at 830412 meeting Visual insp, conducted during Fall 1980 outage, uncovered no evidence of thermal shield deterioration
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/04/26
CLARK, R A Operating Reactors Branch 3 2pp 18319 317 24X
Fiche 50-336, 83/04/26, 8305040447

8305050054 Forwards comments on Generic Ltr 82-32, "Potential Steam Generator Related Requirements " Vendor input should be sought, especially in areas of steam generator tube inservice insp & design considerations
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities)
COUNSIL, W G Northeast Utilities 83/04/29 EISENHUT, D G
Division of Licensing 6pp 18339 085 24X Fiche 50-000, 83/04/29, 8305050054

8305050229 Submits progress rept re TMI Items II F 1.1 & II F 1 2 re effluent monitor mods Vendor schedular uncertainties resolved. Remaining work consists of training operators, software changes & minor wiring change.
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL, W. G Northeast Utilities 83/04/29
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18338 062 24X
Fiche: 50-245, 83/04/29, 8305050229.

8305090465 Forwards revs to "Corporate Organization for Nuclear Incidents Procedure Manual," per 10CFR50, App E, Section V W/o encls.
COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities).
COUNSIL, W G. Northeast Utilities 83/04/29 EISENHUT, D G
Division of Licensing 2pp 18362 256 24X Fiche 50-000, 83/04/29, 8305090465

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing. 83/05/02 Consolidated Edison Co. of New York, Inc 50pp 18441.120 24X
Fiche: 50-000, 83/05/02, 8305020455.

8305120241 Forwards proprietary & nonproprietary responses to NRC 820819 request for addl info re measurement uncertainties & "Shape Annealing Factor Component of Axial Shape Index . " Proprietary response & rept withheld (ref 10CFR2 790)
COUNSIL, W. G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W. G Northeast Utilities 83/05/03.
CLARK, R A. Operating Reactors Branch 3 16pp 18429 151 24X
Fiche. 50-336, 83/05/03, 8305120241

--8305120252 "Shape Annealing Factor Component of Axial Shape Index Uncertainty."
* Combustion Engineering, Inc CEN-247(N)-NP. 83/03/31 48pp
18429: 167 24X Fiche: 50-336, 83/05/03, 8305120241

8305200081 Forwards SER supporting licensee 790625 & 810501 requests for relief from ASME Section XI inservice testing requirements, per 10CFR50 55(g) Relief from ASME Code requirements expires on 851225
CLARK, R A Operating Reactors Branch 3 83/05/04 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp
18541 006 24X Fiche 50-336, 83/05/04, 8305200081

--8305200085 Safety evaluation supporting licensee request for relief from ASME Section XI inservice testing requirements, per 10CFR50 55(g)
* Office of Nuclear Reactor Regulation, Director 83/05/04
26pp 18541 010 24X Fiche 50-336, 83/05/04, 8305200081

--8305200089 Notice of granting relief from ASME Section XI inservice testing requirements, per 10CFR50 55(g)
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp
18541 036 24X Fiche 50-336, 83/05/04, 8305200081

8305090426 Forwards Amends 91 & 86 to Licenses DPR-21 & DPR-65, respectively & notice of issuance & availability Amends change ownership interests in facilities
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities). 3pp
18360 236 24X Fiche 50-245, 83/05/05, 8305090426

--8305090460 Amend 86 to License DPR-65, reflecting merger of Connecticut Light & Power Co & Hartford Electric Light Co Pages 1 & 2 of Amend 4 to License DPR-21 encl
CLARK, R A Operating Reactors Branch 3 83/05/05 4pp
18360 246 24X Fiche 50-245, 83/05/05, 8305090426

--8305090463 Notice of issuance & availability of Amends 91 & 86 to Licenses DPR-21 & DPR-65, respectively
CRUTCHFIELD, D Operating Reactors Branch 5 83/05/05 2pp
18360 250 24X Fiche 50-245, 83/05/05, 8305090426

8305110219 Forwards Amend 85 to License DPR-65, safety evaluation & notice of issuance & availability Amend adds footnote to Tech Specs allowing use of temporary equipment hatch door
LEECH, R H Operating Reactors Branch 3 83/05/05 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp
18434 336 24X Fiche 50-336, 83/05/05, 8305110219

--8305110224 Amend 85 to License DPR-65, adding footnote to Tech Specs allowing use of temporary equipment hatch door to maintain containment integrity during fuel movement or core alterations
CLARK, R A Operating Reactors Branch 3 83/05/05 5pp
18434 340 24X Fiche 50-336, 83/05/05, 8305110219

--8305110228 Safety evaluation supporting Amend 85 to License DPR-65
* Office of Nuclear Reactor Regulation, Director 83/05/05 3pp
18434 345 24X Fiche 50-336, 83/05/05, 8305110219

--8305110230 Notice of issuance & availability of Amend 85 to License DPR-65
TRAMMELL, C M Operating Reactors Branch 3 83/05/05 2pp
18434 348 24X Fiche. 50-336, 83/05/05, 8305110219

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305230508 Discusses 830413 ltr re proposed revs to Tech Specs for Cycle 6 reload Current Tech Spec limits provide acceptable margin of safety
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/16
CLARK, R A Operating Reactors Branch 3 4pp 18537 326 24X
Fiche. 50-336, 83/05/16, 8305230508

8305250510 Application to amend Licenses DPR-61, DPR-21 & DPR-65 deleting 820630 deadline date for conformance w/final rule 10CFR50 49 removing requirement for central equipment qualification file
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co. 83/05/18 CLARK, R A Operating Reactors Branch 3
CRUTCHFIELD, D. Operating Reactors Branch 5 3pp 18588 278 24X
Fiche: 50-000, 83/05/18, 8305250510

--8305250518 Proposed Tech Spec changes deleting 820630 deadline for environ qualification of electrical equipment
* Northeast Nuclear Energy Co (subs of Northeast Utilities)
83/05/18 7pp 18588 281 24X Fiche 50-000, 83/05/18, 8305250510

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305060424 Responds to 830316 request for plans for Cycle 6 reload outage steam generator insp Tube defect assessment & supplementary steam generator testing program tables encl
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/04/29
CLARK, R A Operating Reactors Branch 3 5pp 18343 281 24X Fiche 50-336, 83/04/29, 8305060424

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 117pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EGP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305250459 Forwards IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted
STARDSTECKI, R Division of Project & Resident Programs 83/05/11
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588.096 24X Fiche 50-336, 83/05/11, 8305250459

--8305250465 IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted Major areas inspected: licensee actions taken to comply w/requirements discussed in NURG-0737, Item II B.2 re design review of plant shielding
LAZARUS, W. J , HAVERKAMP, D R , EAPEN, P K Region 1, Office of Director 83/05/09 6pp. 18588 098 24X Fiche 50-336, 83/05/11, 8305250459.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305270074 Forwards interim response to IE Bulletin 82-02 re degradation of threaded fasteners in RCPB No linear indications found in steam generator manway studs Five studs w/unacceptable mechanical damage replaced
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 83/05/19
MURLEY, T E Region 1, Office of Director 3pp 18638 285 24X Fiche 50-336, 83/05/19, 8305270074

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305170010 Forwards monthly operating rept for Apr 1983
MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E. J Northeast Utilities 83/05/12. Office of Resource Management, Director 1p 18466 150 24X
Fiche 50-336, 83/05/12, 8305170010

--8305170014 Monthly operating rept for Apr 1983
GIBSON, J Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/05/11. 5pp 18466 151 24X Fiche 50-336, 83/05/12, 8305170010

S Reportable occurrences, LERs & related correspondence

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573

8305270089 LER 83-015/03L-0 on 830421, control element assembly (CEA) 62 dropped fully into core Cause unknown Coil programmer power main & backup supplies tested & found satisfactory CEA withdrawn & power returned to 100% W/830520 ltr.
FOSTER, E R , MROCZKA, E J Northeast Nuclear Energy Co. (subs of Northeast Utilities) MROCZKA, E. J Northeast Utilities. 83/05/20
MURLEY, T Region 1, Office of Director 2pp 18638 193 24X
Fiche 50-336, 83/05/20, 8305270089

8305270239 LER 83-017/03L-0 on 830418, during routine power operation, valve 2-SI-616 taken out of svc to perform maint. Insp showed cracking in operator casing Cause under investigation by Limitorque Repairs will be made W/830520 ltr
BERGIN, J M , MROCZKA, E J Northeast Nuclear Energy Co (subs. of Northeast Utilities) MROCZKA, E J Northeast Utilities 83/05/20
MURLEY, T E Region 1, Office of Director 2pp 18637 184 24X
Fiche 50-336, 83/05/20, 8305270239

8305270454 LER 83-016/03L-0 on 830421, steam-driven auxiliary feedwater pump removed from svc for repacking Caused by natural end of life failure Pump repacked, tested & returned to svc W/830520 ltr
RESETAR, J , MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA, E. J Northeast Utilities 83/05/20
MURLEY, T E Region 1, Office of Director 2pp 18641 329 24X
Fiche 50-336, 83/05/20, 8305270454

8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520. Utils will measure vibration
HAISLER, R K. Litton Industries, Inc 83/05/20 KEPPLER, J G Region 3, Office of Director. 3pp 18646.212 24X Fiche 50-000, 83/05/20, 8305270625

DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs, as stated
STEWART, W L Virginia Electric & Power Co 83/03/24 MCGUIRE, D R
Division of Emergency Preparedness & Materials Safety 1p
18342 200 24X Fiche 50-000, 83/03/24, 8305050126

8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans
CLARK, R A Operating Reactors Branch 3 83/05/04 STEWART, W L
Virginia Electric & Power Co 4pp 18443 305 24X
Fiche 50-338, 83/05/04, 8305130010

--8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by QA dept at least once per 12 months
CLARK, R A Operating Reactors Branch 3 83/05/04 10pp
18443 309 24X Fiche 50-338, 83/05/04, 8305130010

--8305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp
18443 319 24X Fiche 50-338, 83/05/04, 8305130010

8305130058 Forwards revised submittal describing preliminary plan for emergency operations facilities (EOF) updating 820408 response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities
STEWART, W L Virginia Electric & Power Co 83/05/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 13pp 18436 215 24X Fiche 50-000, 83/05/06, 8305130058.

8305200094 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plants to App E, 10CFR50," completed Item closed
CLARK, R. A Operating Reactors Branch 3 83/05/10 STEWART, W L
Virginia Electric & Power Co 3pp 18540 355 24X
Fiche. 50-338, 83/05/10, 8305200094

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

O Adjudicatory correspondence

8305030555 First request for production of documents & first interrogatories Certificate of Svc encl
QELMAN, M R Virginia Electric & Power Co QELMAN, M R Hunton &
Williams 83/04/29 Louisa County, VA 6pp 18303 303 24X
Fiche 50-338, 83/04/29, 8305030555

8305190219 Response to request for production of documents Production will be permitted subj to encl stipulation of confidentiality Certificate of Svc encl
QELMAN, M R Virginia Electric & Power Co 83/05/16 Louisa
County, VA 8pp, 18502:180 24X Fiche 50-338, 83/05/16, 8305190219

8305200659 Response to interrogatories & request for documents Certificate of Svc encl Related correspondence
ALBRECHT, V S Louisa County, VA ALBRECHT, V S Beveridge,
Fairbanks & Diamond 83/05/16 Office of the Executive Legal
Director 18pp 18526 024 24X Fiche 50-338, 83/05/16, 8305200659

8305190223 Advises that info re operation of licensed nuclear reactors available in PDR
MCGURREN, H J. Hearing Branch 1 83/05/17 ALBRECHT, V S
Beveridge, Fairbanks & Diamond. 1p 18502 142 24X
Fiche: 50-338, 83/05/17, 8305190223

P Operating license stage documents & correspondence

8305090144 Summarizes review of completed Generic Item B-24 re containment purge & vent & TMI Action Plan Item II E 4 2 SER & "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," encl
CLARK, R. A Operating Reactors Branch 3 83/04/20 STEWART, W L
Virginia Electric & Power Co 3pp 18367 072 24X
Fiche 50-338, 83/04/20, 8305090144

--8305090149 Safety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purge isolation & other ESF sys
* Office of Nuclear Reactor Regulation, Director 83/04/20 6pp
18367 075 24X Fiche 50-338, 83/04/20, 8305090144

--8208060249 "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," technical evaluation rept
SARGENT, I , STONE, J Franklin Institute/Franklin Research Center
NRC-03-79-118 TER-C5257-207/208 82/08/04 CALVO, J NRC - No
Detailed Affiliation Given 31pp 18367 081 24X
Fiche 50-338, 83/04/20, 8305090144

8305060017 Forwards SER re util responses to NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor " Items resolved
CLARK, R A Operating Reactors Branch 3 83/04/21 STEWART, W L
Virginia Electric & Power Co 8pp 18354 314 24X
Fiche 50-338, 83/04/21, 8305060017

8305060065 Advises that adequate justification provided for continued operation w/Dresser safety valves on primary side, per TMI Action Item II D 1 Generic safety evaluation & plant-specific info encl
CLARK, R A Operating Reactors Branch 3 83/04/22 STEWART, W L
Virginia Electric & Power Co 14pp 18354 346 24X
Fiche 50-338, 83/04/22, 8305060065

8305060109 Forwards Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively, safety evaluation & notice of issuance & availability Amends revise partial power multiplier & delete Unit 2 Tech Spec 4 2 2 2 g 2
ENGLE, L B Operating Reactors Branch 3 83/04/22 STEWART, W L
Virginia Electric & Power Co 1p 18364 353 24X
Fiche 50-338, 83/04/22, 8305060109

--8305060120 Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively, revising partial power multiplier & deleting Unit 2 Tech Spec 4 2 2 2 g 2
CLARK, R A Operating Reactors Branch 3 83/04/22 26pp
18364 354 24X Fiche 50-338, 83/04/22, 8305060109

--8305060136 Safety evaluation supporting Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/22 3pp
18365 018 24X Fiche 50-338, 83/04/22, 8305060109

--8305060140 Notice of issuance & availability of Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 83/04/22 2pp
18365 021 24X Fiche 50-338, 83/04/22, 8305060109

8305040173 Forwards 30-day response to NRC 830324 SER for environ qualification of safety-related electrical equipment, reaffirming justification for continued operation & submitting info for items in NRC Categories I B, II A & IV
STEWART, W L Virginia Electric & Power Co 83/04/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 3,014pp 18311 001 24X
Fiche 50-338, 83/04/29, 8305040173

8305040409 Responds to 830324 request to review proprietary matl contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment One item identified as proprietary
STEWART, W L Virginia Electric & Power Co 83/04/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18323 209 24X
Fiche 50-338, 83/04/29, 8305040409

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans
CLARK, R A Operating Reactors Branch 3 83/05/04 STEWART, W L
Virginia Electric & Power Co 4pp 18443 305 24X
Fiche 50-338, 83/05/04, 8305130010

--8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by QA dept at least once per 12 months
CLARK, R A Operating Reactors Branch 3, 83/05/04 10pp
18443 309 24X Fiche 50-338, 83/05/04, 8305130010

--8305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp
18443 319 24X Fiche 50-338, 83/05/04, 8305130010

8305200709 Forwards Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, safety & technical evaluations & notice of issuance & availability Amends change RETS to establish new limiting conditions for quarterly & annual release rates
ENGLE, L B Operating Reactors Branch 3 83/05/05 STEWART, W L
Virginia Electric & Power Co 4pp 18539 199 24X
Fiche 50-338, 83/05/05, 8305200709

--8305200710 Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, changing RETS to establish new limiting conditions for operation for quarterly & annual average release rates
CLARK, R A Operating Reactors Branch 3 83/05/05 3pp
18539 203 24X Fiche 50-338, 83/05/05, 8305200709

--8305200717 Safety evaluation supporting Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively
e Office of Nuclear Reactor Regulation, Director 83/05/05 7pp
18540 051 24X Fiche 50-338, 83/05/05, 8305200709

--8305200720 "RETS Implementation (A-2)," technical evaluation rept
CASSELL, A , CHEN, S , PANDEY, S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-101/102 83/03/18
CONGEL, F , WILLIS, C NRC - No Detailed Affiliation Given 32pp
18540 058 24X Fiche 50-338, 83/05/05, 8305200709

--8305200724 Notice of issuance & availability of Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/05 2pp
18540 090 24X Fiche 50-338, 83/05/05, 8305200709

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
STEWART, W L Virginia Electric & Power Co 83/05/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director EISENHUT, D G
Division of Licensing 19pp 18513 182 24X Fiche 50-000, 83/05/12, 8305200499

8305260323 Responds to 10CFR50 49(g) & NRC 830324 ltr re electrical equipment important to safety Schedule for qualification or replacement submitted Master list of equipment encl
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 76pp 18626 007 24X
Fiche 50-338, 83/05/20, 8305260323

8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Westinghouse rept
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18637 325 24X
Fiche 50-338, 83/05/20, 8305270220

G Inspection reports, IE Bulletins & correspondence

8305270143 Corrects 821124 response to violation noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Item B Finding re RCS leakage removed as violation
STEWART, W L Virginia Electric & Power Co 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 18638 161 24X
Fiche 50-338, 83/02/25, 8305270143

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270517 Forwards IE Insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/29
STEWART, W L Virginia Electric & Power Co 2pp 18646 155 24X
Fiche: 50-338, 83/03/29, 8305270517

--8305270534 IE Insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted Major areas inspected internal & external exposures, surveys, plant tours, Unit 2 refueling outage preparation & offsite release records
WRAY, J R , BARR, K P Region 2, Office of Director 83/03/28
9pp 18646 157 24X Fiche 50-338, 83/03/29, 8305270517

8305270530 Forwards IE Insp Repts 50-338/83-05 & 50-339/83-05 on 830206-0305 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/01
STEWART, W L Virginia Electric & Power Co 2pp 18646 166 24X
Fiche 50-338, 83/04/01, 8305270530

--8305270544 IE Insp Repts 50-338/83-05 & 50-339/83-05 on 830206-0305 No noncompliance noted Major areas inspected outage activities, surveillance & maint activities, identified items, LERs & routine insps
SHYMLOCK, M B Region 2, Office of Director JULIAN, C. Division of Project & Resident Programs 83/03/31 7pp 18646, 168 24X
Fiche 50-338, 83/04/01, 8305270530

8305270394 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-01 & 50-339/83-01
LEWIS, R C Division of Project & Resident Programs 83/04/07.
STEWART, W L Virginia Electric & Power Co 1p. 18642.260 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270407 Responds to NRC 830204 ltr re violations noted in IE Insp Repts 50-338/83-01 & 50-339/83-01 Corrective actions' equipment failure trend analysis program will be described, implemented & controlled by administrative procedure
STEWART, W L Virginia Electric & Power Co 83/03/17
O'REILLY, J P Region 2, Office of Director. 4pp 18642:261. 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270416 Confirms NRC approval to extend response time to notice of violation contained in IE Insp Repts 50-338/83-01 & 50-339/83-01 to 830318
STEWART, W L Virginia Electric & Power Co 83/03/08.
O'REILLY, J P Region 2, Office of Director 1p. 18642 265 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270421 Forwards IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07 & notice of violation
LEWIS, R C Division of Project & Resident Programs. 83/02/04
STEWART, W L Virginia Electric & Power Co 2pp 18642 266. 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270430 Notice of violation from insp on 830103-07
* Region 2, Office of Director 83/02/04. 2pp 18642 268 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270442 IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07, Noncompliance noted, failure to perform all audits required by Tech Specs & to establish sys to evaluate equipment failures
BELISLE, G A , JACKSON, L H , SKINNER, P H Region 2, Office of Director 83/01/26 10pp. 18642.270. 24X Fiche 50-338, 83/04/07, 8305270394

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155. 24X Fiche: 50-000, 83/04/15, 8303040021

8305270238 Forwards IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/18.
STEWART, W. L Virginia Electric & Power Co 2pp 18637.173 24X
Fiche 50-338, 83/04/18, 8305270238

--8305270244 IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted Major areas inspected inservice testing pumps & valves, data evaluation & review, corrective LER action & calibr of inservice insp tool
ECONOMOS, N , BLAKE, J. J Region 2, Office of Director. 83/04/14
9pp 18637 175 24X Fiche 50-338, 83/04/18, 8305270238.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18303 089 24X Fiche 50-000, 83/04/22, 8303040023

8305270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety.
O'REILLY, J P Region 2, Office of Director 83/04/22. STEWART, W L
Virginia Electric & Power Co 2pp. 18646 001. 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270527 Forwards SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
LEWIS, R C Division of Project & Resident Programs 83/02/10
STEWART, W L Virginia Electric & Power Co 2pp 18646 003 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270541 SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
* Region 2, Office of Director 83/02/10 45pp 18646 005 24X
Fiche 50-000, 83/04/22, 8305270513

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche. 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441.170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001. 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270414 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-39 & 50-339/82-39
DANCE, H C Division of Project & Resident Programs 83/05/09
STEWART, W L Virginia Electric & Power Co 1p 18641 331 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270426 Responds to NRC 830311 ltr re violations noted in IE Insp Repts 50-338/82-39 & 50-339/82-39 Corrective actions emergency procedures revised to reflect Tech Spec 3 0 3 requirements
STEWART, W.L. Virginia Electric & Power Co 83/04/08
O'REILLY, J P Region 2, Office of Director 4pp 18641 332 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270437 Forwards IE Insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 & notice of violation
LEWIS, R. C. Division of Project & Resident Programs 83/03/11
STEWART, W L Virginia Electric & Power Co. 2pp 18641 336 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270448 Notice of violation from insp on 821106-1206
* Region 2, Office of Director 83/03/11 2pp. 18641 338 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270455 IE Insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 Noncompliance noted failure to have ESF actuation sys operable & failure to perform required surveillance.
SHYMLOCK, M. B Region 2, Office of Director. JULIAN, C. A Division of Project & Resident Programs 83/03/08 7pp. 18641.339 24X
Fiche 50-338, 83/05/09, 8305270414

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003. 24X Fiche. 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305230430 Forwards engineering evaluation rept, "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms " Aging factors not considered in implemented replacement criteria
ASHE, F Reactor Operations Analysis Branch 83/04/18 SEYFRIT, K V Reactor Operations Analysis Branch 2pp 18545 356 24X
Fiche 50-000, 83/04/18, 8305230430

--8305230441 "Degradation of Safety-Related Batteries Due to Cracking of Battery Cell Cases &/or Other Possible Aging-Related Mechanisms." engineering evaluation rept LERs re safety-related battery degradation reviewed
ASHE, F Reactor Operations Analysis Branch 83/04/18 5pp 18545 358 24X Fiche 50-000, 83/04/18, 8305230430

8305030158 Forwards LER 83-016/03L-0
HARRELL, E W Virginia Electric & Power Co 83/04/20 O'REILLY, J P Region 2, Office of Director 1p 18300 270 24X
Fiche 50-338, 83/04/20, 8305030158

--8305030165 LER 83-016/03L-0 on 830323, w/unit at 100% power, stiffener support not added to bus svc water auxiliary relay panel J per Design Change 80-845I Caused by personnel error Stiffener support added
HARRELL, E W Virginia Electric & Power Co 83/04/20 Region 2, Office of Director 3pp 18300 271 24X Fiche 50-338, 83/04/20, 8305030158

8305030611 Forwards LER 83-019/03L-0
HARRELL, E W Virginia Electric & Power Co 83/04/21 O'REILLY, J P Region 2, Office of Director 1p 18306 098 24X
Fiche. 50-338, 83/04/21, 8305030611

--8305030615 LER 83-019/03L-0 on 830405, individual rod position indication for control bank C, rod D-12, deviated from group demand position Caused by instrument drift Instrument recalibr
HARRELL, E W Virginia Electric & Power Co 83/04/21 Region 2, Office of Director. 1p 18306 099 24X Fiche 50-338, 83/04/21, 8305030611

8305050186 Forwards LER 83-008/03L-0
HARRELL, E W Virginia Electric & Power Co 83/04/27 O'REILLY, J P Region 2, Office of Director 1p 18341·062 24X
Fiche 50-338, 83/04/27, 8305050186

--8305050191 LER 83-008/03L-0 on 830410, review revealed that procedure used to restore boron injection tank concentration introduced potential unanalyzed injection flow diversions Caused by oversight Emergency procedures revised
HARRELL, E W Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 3pp 18341 063 24X Fiche 50-338, 83/04/27, 8305050186

8305110285 Forwards LER 83-020/03L-0
HARRELL, E. W Virginia Electric & Power Co 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18393.334 24X
Fiche 50-338, 83/05/05, 8305110285

--8305110288 LER 83-020/03L-0 on 830407, during surveillance testing, inside containment recirculation spray pump 1-RS-P-1B tripped Cause unknown Pump satisfactorily tested & returned to svc
HARRELL, E W Virginia Electric & Power Co 83/05/05 Region 2, Office of Director 3pp 18393 335 24X Fiche 50-338, 83/05/05, 8305110285

8305170406 Forwards LER 83-021/03L-0
HARRELL, E W Virginia Electric & Power Co 83/05/10 O'REILLY, J P Region 2, Office of Director 1p 18470·124 24X
Fiche 50-338, 83/05/10, 8305170406

--8305170412 LER 83-021/03L-0 on 830411,Fire Door S-71-7 between svc bldg health physics area & auxiliary bldg would not self close Caused by removal of reclosure device for maint of closure coupling Reclosure device reinstalled
HARRELL,E W Virginia Electric & Power Co 83/05/10 Region 2, Office of Director 3pp 18470 125 24X Fiche 50-338,83/05/10, 8305170406

8305200146 RO on 830509,w/unit at 100% power,severe hydrogen leak discovered on hydrogen inner-cooled turbine generator Unit rampdown ordered & hydrogen vented to atmosphere Emergency terminated when pressure reached less than 10 psig
HARRELL,E W Virginia Electric & Power Co 83/05/10 Region 2, Office of Director 2pp 18518 341 24X Fiche 50-338,83/05/10, 8305200146

8305200574 Forwards LER 83-022/03L-0
HARRELL,E W Virginia Electric & Power Co 83/05/13 O'REILLY,J P Region 2, Office of Director 1p 18514 139 24X
Fiche 50-338,83/05/13,8305200574

--8305200583 LER 83-022/03L-0 on 830412,review of ASME XI IWV program identified 192 valves not exercised &/or stroke timed,Caused by fragmented implementation of testing program Programs upgraded
HARRELL,E W Virginia Electric & Power Co 83/05/13 Region 2, Office of Director 3pp 18514 140 24X Fiche 50-338,83/05/13, 8305200574.

8305250288 LER 83-023/03L-0 on 830423,low head safety injection pump 1-SI-P-1B suction isolation valve failed to open.Caused by lack of lubrication on valve stem to operator nut area Stem lubricated & stroked W/830518 ltr
HARRELL,E W Virginia Electric & Power Co 83/05/18 O'REILLY,J P Region 2, Office of Director 3pp 18585 299 24X
Fiche 50-338,83/05/18,8305250288

8305250417 LER 83-025/03L-0 on 830429,while conducting surveillance test,conditioning module TC-MM-100A to meteorological 33-ft temp chart recorder drifted 1 6 F Caused by instrument drift Module recalbr W/830518 ltr
HARRELL,E W Virginia Electric & Power Co 83/05/18 O'REILLY,J P Region 2, Office of Director 2pp 18583 360 24X
Fiche 50-338,83/05/18,8305250417

8305270323 LER 83-026/03L-0 on 830426,calibr check of delta T/TAVG protection channel 1 revealed erratic TAVG lead lag derivative card Cause undetermined Card replaced & channel calibr W/830520 ltr
HARRELL,E W Virginia Electric & Power Co 83/05/20 O'REILLY,J P Region 2, Office of Director 3pp 18642 036 24X
Fiche 50-338,83/05/20,8305270323

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305050126 Informs that 830202 ltr provided changes to security plan, not personnel training & qualification programs,as stated
STEWART,W L Virginia Electric & Power Co 83/03/24 MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 1p 18342 200 24X Fiche 50-000,83/03/24,8305050126

8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans
CLARK,R A Operating Reactors Branch 3 83/05/04 STEWART,W L Virginia Electric & Power Co 4pp 18443 305 24X
Fiche 50-338,83/05/04,8305130010

--8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7,respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by QA dept at least once per 12 months
CLARK,R A Operating Reactors Branch 3 83/05/04, 10pp 18443 309 24X Fiche 50-338,83/05/04,8305130010

--8305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7,respectively
TRAMMELL,C M Operating Reactors Branch 3 83/05/04 2pp 18443 319 24X Fiche 50-338,83/05/04,8305130010.

8305130038 Forwards revised submittal describing preliminary plan for emergency operations facilities (EOF) updating 820408 response to Generic Ltr 82-33 Local EOF will be constructed adjacent or connected to existing training facilities
STEWART,W L Virginia Electric & Power Co 83/05/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 13pp 18436 215 24X Fiche 50-000,83/05/06,8305130038

8305200094 Notifies that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plants to App E,10CFR50," completed Item closed
CLARK,R A Operating Reactors Branch 3 83/05/10 STEWART,W.L Virginia Electric & Power Co 3pp 18540 355 24X
Fiche 50-338,83/05/10,8305200094

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co, of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

G Adjudicatory correspondence

8305030555 First request for production of documents & first interrogatories Certificate of Svc encl
GELMAN,M R Virginia Electric & Power Co GELMAN,M R Hunton & Williams 83/04/29 Louisa County, VA 6pp 18303:303 24X
Fiche 50-338,83/04/29,8305030555

8305190219 Response to request for production of documents Production will be permitted subj to encl stipulation of confidentiality,Certificate of Svc encl
GELMAN,M R Virginia Electric & Power Co 83/05/16, Louisa County, VA 8pp 18502,180 24X Fiche:50-338,83/05/16,8305190219

8305200659 Response to interrogatories & request for documents Certificate of Svc encl,Related correspondence
ALBRECHT,V S Louisa County, VA ALBRECHT,V S Beveridge, Fairbanks & Diamond 83/05/16 Office of the Executive Legal Director 18pp 18526,024 24X Fiche:50-338,83/05/16,8305200659

8305190223 Advises that info re operation of licensed nuclear reactors available in PDR
MCGURREN,H J Hearing Branch 1, 83/05/17, ALBRECHT,V S Beveridge, Fairbanks & Diamond 1p 18502,142, 24X
Fiche 50-338,83/05/17,8305190223

P Operating license stage documents & correspondence

8305090144 Summarizes review of completed Generic Item B-24 re containment purge & vent & TMI Action Plan Item II.E.4 2 SER & "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," encl.
CLARK,R A Operating Reactors Branch 3, 83/04/20, STEWART,W L Virginia Electric & Power Co 3pp 18367 072 24X
Fiche 50-338,83/04/20,8305090144

--8305090149 Safety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purge isolation & other ESF sys.
Office of Nuclear Reactor Regulation, Director 83/04/20 6pp 18367 075 24X Fiche,50-338,83/04/20,8305090144

--8208060249 "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," technical evaluation rept
SARGENT,I , STONE,J Franklin Institute/Franklin Research Center NRC-03-79-118 TER-C5257-207/208, 82/08/04, CALVO,J NRC - No Detailed Affiliation Given 3pp, 18367:081 24X
Fiche 50-338,83/04/20,8305090144.

8305060017 Forwards SER re util responses to NUREG-0737,Items II.F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F.1 6, "Containment Hydrogen Monitor " Items resolved
CLARK,R A Operating Reactors Branch 3, 83/04/21, STEWART,W L Virginia Electric & Power Co 8pp 18354:314 24X
Fiche 50-338,83/04/21,8305060017

8305060065 Advises that adequate justification provided for continued operation w/Dresser safety valves on primary side,per TMI Action Item II D 1 Generic safety evaluation & plant-specific info encl
CLARK,R.A Operating Reactors Branch 3 83/04/22, STEWART,W L Virginia Electric & Power Co 14pp, 18354,346 24X
Fiche 50-338,83/04/22,8305060065

8305060109 Forwards Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively,safety evaluation & notice of issuance & availability Amends revise partial power multiplier & delete Unit 2 Tech Spec 4.2 2 2 g 2
ENGLE,L B Operating Reactors Branch 3 83/04/22 STEWART,W L Virginia Electric & Power Co 1p, 18364 393, 24X
Fiche 50-338,83/04/22,8305060109

--8305060120 Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively, revising partial power multiplier & deleting Unit 2 Tech Spec 4 2 2 2.g 2
CLARK, R A Operating Reactors Branch 3 83/04/22 26pp
18364 354 24X Fiche 50-338, 83/04/22, 8305060109

--8305060136 Safety evaluation supporting Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/22 3pp
18365 018 24X Fiche 50-338, 83/04/22, 8305060109

--8305060140 Notice of issuance & availability of Amends 46 & 29 to Licenses NPF-4 & NPF-7, respectively
CLARK, R A Operating Reactors Branch 3 83/04/22 2pp
18365 021 24X Fiche 50-338, 83/04/22, 8305060109

8305040409 Responds to 830324 request to review proprietary matl contained in Franklin Research Ctr technical evaluation repts re environ qualification of safety-related electrical equipment One item identified as proprietary
STEWART, W L. Virginia Electric & Power Co 83/04/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18323 209 24X
Fiche 50-338, 83/04/29, 8305040409

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060283 Application for amend to License NPF-7, revising Tech Specs to support implementation of 2 5 F Tavg increase during current refueling outage Main steam line monoball support mods complete
STEWART, W L Virginia Electric & Power Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18345 022 24X
Fiche 50-339, 83/05/03, 8305060283

8305130010 Forwards Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively & notice of issuance & availability Amends revise audit frequencies of station emergency & security plans
CLARK, R A Operating Reactors Branch 3 83/05/04 STEWART, W L
Virginia Electric & Power Co 4pp 18443 305 24X
Fiche 50-338, 83/05/04, 8305130010

--8305130017 Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively, revising audit frequencies of station emergency & security plans & implementing procedures to provide for review by QA dept at least once per 12 months
CLARK, R A. Operating Reactors Branch 3 83/05/04 10pp
18443 309. 24X Fiche. 50-338, 83/05/04, 8305130010

--8305130023 Notice of issuance & availability of Amends 47 & 30 to Licenses NPF-4 & NPF-7, respectively
TRAMMELL, C M Operating Reactors Branch 3 83/05/04 2pp
18443 319. 24X Fiche 50-338, 83/05/04, 8305130010

8305200709 Forwards Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, safety & technical evaluations & notice of issuance & availability Amends change RETS to establish new limiting conditions for quarterly & annual release rates
ENGLE, L B Operating Reactors Branch 3 83/05/05 STEWART, W L
Virginia Electric & Power Co 4pp 18539 199 24X
Fiche. 50-338, 83/05/05, 8305200709

--8305200710 Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively, changing RETS to establish new limiting conditions for operation for quarterly & annual average release rates
CLARK, R A Operating Reactors Branch 3 83/05/05 3pp.
18539 203. 24X Fiche. 50-338, 83/05/05, 8305200709

--8305200717 Safety evaluation supporting Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/05 7pp
18540 051 24X Fiche. 50-338, 83/05/05, 8305200709.

--8305200720 "RETS Implementation (A-21)," technical evaluation rept
CASSELL, A , CHEN, S , PANDEY, S Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-101/102 83/03/18
CONGEL, F , WILLIS, C NRC - No Detailed Affiliation Given 32pp
18540 058 24X Fiche 50-338, 83/05/05, 8305200709

--8305200724 Notice of issuance & availablity of Amends 48 & 31 to Licenses NPF-4 & NPF-7, respectively
TRAMMELL, C M. Operating Reactors Branch 3 83/05/05 2pp
18540 090 24X Fiche 50-338, 83/05/05, 8305200709

8305120386 Submits status of License Condition 2 C(4)(c) Facility currently in second refueling outage New Rosemount resistance temp detector (RTD) Model 176KG will be installed until redesigned RTD available
STEWART, W L Virginia Electric & Power Co 83/05/06 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 18432 269 24X
Fiche 50-339, 83/05/06, 8305120386

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305190253 Informs of status of NUREG-0737, Item II F 1 3 re containment high-range radiation monitors Qualified in-containment electrical terminations will be made per IE Bulletin 79-01B & NUREG-0588 schedule
STEWART, W L Virginia Electric & Power Co 83/05/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18501 283 24X
Fiche 50-339, 83/05/12, 8305190253

8305200499 Forwards response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys," per 830310 ltr During upset conditions, alarm functions provided in conjunction w/ subcooling monitors
STEWART, W L Virginia Electric & Power Co 83/05/12 DENTON, H R
Office of Nuclear Reactor Regulation, Director 19pp 18513 182
24X Fiche 50-000, 83/05/12, 8305200499

8305270150 Informs that License Conditions 2 C(15)(h)(2) & 2 C(15)(h)(4)re diesel generator reliability satisfied Mods will be completed no later than second refueling outage
STEWART, W L Virginia Electric & Power Co 83/05/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 2pp 18638 201 24X
Fiche 50-339, 83/05/19, 8305270150

8305260323 Responds to 10CFR50 49(g) & NRC 830324 ltr re electrical equipment important to safety Schedule for qualification or replacement submitted Master list of equipment encl
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 76pp 18626 007 24X
Fiche 50-338, 83/05/20, 8305260323

8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Westinghouse rept
STEWART, W L Virginia Electric & Power Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18637 325 24X
Fiche 50-338, 83/05/20, 8305270220

8305310099 Advises that backup overcurrent protection sys for containment electrical penetrations installed during second refueling outage Seismic design verification program in progress for containment recirculation fans
STEWART, W L Virginia Electric & Power Co 83/05/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director CLARK, R A
Operating Reactors Branch 3 1p 18655 104 24X
Fiche 50-339, 83/05/24, 8305310099

Q Inspection reports, IE Bulletins & correspondence

8305270143 Corrects 821124 response to violation noted in IE Insp Repts 50-338/82-37 & 50-339/82-37 Item B finding re RCS leakage removed as violation
STEWART, W L Virginia Electric & Power Co 83/02/25 O'REILLY, J P
Region 2, Office of Director 2pp 18638 161 24X
Fiche 50-338, 83/02/25, 8305270143

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270517 Forwards IE Insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/29
STEWART, W L Virginia Electric & Power Co 2pp 18646 155 24X
Fiche 50-338, 83/03/29, 8305270517

--8305270534 IE Insp Repts 50-338/83-07 & 50-339/83-07 on 830228-0304 No noncompliance noted Major areas inspected internal & external exposures, surveys, plant tours, Unit 2 refueling outage preparation & offsite release records.
WRAY, J R , BARR, K P Region 2, Office of Director 83/03/28
9pp 18646 157 24X Fiche 50-338, 83/03/29, 8305270517

8305270530 Forwards IE Insp Repts 50-338/83-05 & 50-339/83-05 on 830206-0305 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/01
STEWART, W L Virginia Electric & Power Co 2pp 18646 166 24X
Fiche 50-338, 83/04/01, 8305270530

--8305270544 IE Insp Repts 50-338/83-05 & 50-339/83-05 on 830206-0305 No noncompliance noted Major areas inspected outage activities, surveillance & maint activities, identified items, LERs & routine insps
SHYMLOCK, M B Region 2, Office of Director JULIAN, C Division of Project & Resident Programs 83/03/31 7pp 18646 168 24X
Fiche 50-338, 83/04/01, 8305270530

8305270394 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-01 & 50-339/83-01
LEWIS, R C Division of Project & Resident Programs 83/04/07
STEWART, W L Virginia Electric & Power Co 1p 18642.260 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270407 Responds to NRC 830204 ltr re violations noted in IE Insp Repts 50-338/83-01 & 50-339/83-01 Corrective actions equipment failure trend analysis program will be described, implemented & controlled by administrative procedure
STEWART, W L Virginia Electric & Power Co 83/03/17
O'REILLY, J P Region 2, Office of Director 4pp 18642 261 24X
Fiche. 50-338, 83/04/07, 8305270394

--8305270416 Confirms NRC approval to extend response time to notice of violation contained in IE Insp Repts 50-338/83-01 & 50-339/83-01 to 830318
STEWART, W L Virginia Electric & Power Co. 83/03/08
O'REILLY, J P Region 2, Office of Director 1p 18642 265 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270421 Forwards IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/02/04
STEWART, W L Virginia Electric & Power Co 2pp 18642 266 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270430 Notice of violation from insp on 830103-07
* Region 2, Office of Director 83/02/04 2pp 18642 268 24X
Fiche 50-338, 83/04/07, 8305270394

--8305270442 IE Insp Repts 50-338/83-01 & 50-339/83-01 on 830103-07 Noncompliance noted failure to perform all audits required by Tech Specs & to establish sys to evaluate equipment failures
BELISLE, G A , JACKSON, L H , SKINNER, P H Region 2, Office of Director 83/01/26 10pp 18642 270 24X Fiche 50-338, 83/04/07, 8305270394

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 12&pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270238 Forwards IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/18
STEWART, W L Virginia Electric & Power Co 2pp 18637·173 24X
Fiche 50-338, 83/04/18, 8305270238

--8305270244 IE Insp Repts 50-338/83-09 & 50-339/83-09 on 830321-30 No noncompliance noted Major areas inspected inservice testing pumps & valves, data evaluation & review, corrective LER action & calibr of inservice insp tool
ECONOMOS, N , BLAKE, J J Region 2, Office of Director 83/04/14, 9pp 18637 175 24X Fiche 50-338, 83/04/18, 8305270238

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co. of New York, Inc 112pp. 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305270513 Advises that SALP Board assessment reviewed & issuance of rept approved Nuclear activities conducted w/proper concern for nuclear safety
O'REILLY, J P Region 2, Office of Director 83/04/22 STEWART, W L Virginia Electric & Power Co 2pp. 18646 001. 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270527 Forwards SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
LEWIS, R C Division of Project & Resident Programs 83/02/10
STEWART, W L Virginia Electric & Power Co 2pp. 18646·003 24X
Fiche 50-000, 83/04/22, 8305270513

--8305270541 SALP Repts 50-280/83-02, 50-281/83-02, 50-338/83-03 & 50-339/83-03 for Jul 1981 - Sept 1982
* Region 2, Office of Director 83/02/10 45pp 18646.005 24X
Fiche 50-000, 83/04/22, 8305270513

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382.282 24X Fiche. 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06. Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305120047 Advises that inservice insp of low pressure turbine, required by license condition, revealed cracks in discs at governor & generator end for low pressure turbine 1 & 2. Low pressure turbine rotors replaced Investigation underway
STEWART, W L Virginia Electric & Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R. A Operating Reactors Branch 3 2pp 18423 053 24X
Fiche 50-339, 83/05/06, 8305120047

8305270414 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/82-39 & 50-339/82-39
DANCE, H C Division of Project & Resident Programs 83/05/09
STEWART, W L Virginia Electric & Power Co 1p 18641·331 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270426 Responds to NRC 830311 ltr re violations noted in IE Insp Repts 50-338/82-39 & 50-339/82-39 Corrective actions' emergency procedures revised to reflect Tech Spec 3.0 3 requirements
STEWART, W L Virginia Electric & Power Co 83/04/08
O'REILLY, J P Region 2, Office of Director 4pp 18641·332. 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270437 Forwards IE Insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 & notice of violation
LEWIS, R C Division of Project & Resident Programs. 83/03/11
STEWART, W L Virginia Electric & Power Co 2pp 18641·336 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270448 Notice of violation from insp on 821106-1206
* Region 2, Office of Director 83/03/11. 2pp 18641 338. 24X
Fiche 50-338, 83/05/09, 8305270414

--8305270455 IE Insp Repts 50-338/82-39 & 50-339/82-39 on 821106-1206 Noncompliance noted: failure to have ESF actuation sys operable & failure to perform required surveillance
SHYMLOCK, M B Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs. 83/03/08 7pp 18641 339 24X
Fiche 50-338, 83/05/09, 8305270414

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030279 Forwards LER 83-025/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18300 056 24X
Fiche:50-339,83/04/20,8305030279

--8305030283 LER 83-025/03L-0,on 830331,w/unit in Mode 1,steam generator B water level channel 1 high-high turbine trip/feedwater isolation setpoint discovered greater than Tech Spec limit Caused by malfunctioning comparator card Card replaced
HARRELL,E.W Virginia Electric & Power Co 83/04/20 Region 2, Office of Director 1p 18300 057 24X Fiche 50-339,83/04/20, 8305030279

8305030357 Forwards LER 83-026/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/20 O'REILLY,J P
Region 2, Office of Director 1p 18291 340 24X
Fiche:50-339,83/04/20,8305030357

--8305030364 LER 83-026/03L-0 on 830402,Fire Doors 871-18 & 871-16 between 2H & 2J emergency diesel generator rooms & turbine bldg would not latch Caused by door strikes jammed open & bent Latches disassembled,cleaned,reassembled & tested
HARRELL,E.W. Virginia Electric & Power Co 83/04/02 Region 2, Office of Director 1p 18291 341 24X Fiche 50-339,83/04/20, 8305030357

8305030635 Forwards LER 83-027/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/21 O'REILLY,J P
Region 2, Office of Director 1p 18303 346 24X
Fiche 50-339,83/04/21,8305030635

--8305030640 LER 83-027/03L-0 on 830402,main steam safety valve pressure setpoints for valves SV-MS-201C,202C,203A & C,204A & 205A found low Caused by setpoint drift Setpoints adjusted
HARRELL,E W Virginia Electric & Power Co 83/04/21 Region 2, Office of Director 2pp 18303 347 24X Fiche 50-339,83/04/21, 8305030635

8305050210 Forwards LER 83-029/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/27 O'REILLY,J P
Region 2, Office of Director, 1p 18338 106 24X
Fiche:50-339,83/04/27,8305050210

--8305050215 LER 83-029/03L-0 on 830402,during Mode 4,automatic actuation of ECCS occurred Caused by maint personnel standing on conduit resulting in loss of lo-lo pressurizer pressure safety injection block.Maint personnel reinstructed
HARRELL,E W Virginia Electric & Power Co 83/04/27 Region 2, Office of Director 3pp 18338 107 24X Fiche 50-339,83/04/27, 8305050210

8305050271 Forwards updated LER 82-067/03X-1
HARRELL,E.W Virginia Electric & Power Co 83/04/27 O'REILLY,J P
Region 2, Office of Director 1p 18337,136 24X
Fiche:50-339,83/04/27,8305050271

--8305050276 Updated LER 82-067/03X-1 on 821017,steam generator C narrow range channel 2 indicated high Caused by failure of transmitter amplifier card Card replaced & loop recalibr.
HARRELL,E W. Virginia Electric & Power Co 83/04/27. Region 2, Office of Director 2pp 18337 137. 24X Fiche 50-339,83/04/27, 8305050271.

8305100023 Forwards LER 83-028/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/29, O'REILLY,J P
Region 2, Office of Director, 1p 18377 148 24X
Fiche:50-339,83/04/29,8305100023

--8305100029 LER 83-028/03L-0 on 830402,emergency diesel generator 2J tripped on high crankcase pressure after emergency start signal,initiated from ECCS actuation,reset Cause unknown Generator started & tested satisfactorily Switch calibr
HARRELL,E W Virginia Electric & Power Co 83/04/29 Region 2, Office of Director 2pp 18377 149 24X Fiche 50-339,83/04/29, 8305100023

8305100259 Forwards LER 83-030/03L-0
HARRELL,E W Virginia Electric & Power Co 83/04/29 O'REILLY,J P
Region 2, Office of Director 1p 18371 335 24X
Fiche 50-339,83/04/29,8305100259

--8305100265 LER 83-030/03L-0 on 830406,pressure in nitrogen supply tank B for pressurizer PORV PCV-2455C dropped below min to consider PORV operable Caused by leak in pressurizer PORV nitrogen supply sys Mod scheduled during current outage
HARRELL,E W Virginia Electric & Power Co 83/04/29 Region 2, Office of Director 2pp 18371 336 24X Fiche 50-339,83/04/29, 8305100259

8305110330 Forwards LER 83-023/03L-0
HARRELL,E W Virginia Electric & Power Co 83/05/05 O'REILLY,J P
Region 2, Office of Director 1p 18406 162 24X
Fiche 50-339,83/05/05,8305110330

--8305110336 LER 83-023/03L-0 on 830414,RHR flow temporarily lost when one of two in-series RHR suction valves closed Caused by open input breaker Breaker reclosed,vital bus restored,RHR suction valve reopened & flow restored
HARRELL,E W Virginia Electric & Power Co 83/05/05 Region 2, Office of Director 2pp 18406 163 24X Fiche 50-339,83/05/05, 8305110330

8305110453 Forwards LER 83-031/03L-0
HARRELL,E W Virginia Electric & Power Co 83/05/05 O'REILLY,J P
Region 2, Office of Director 1p 18405 054 24X
Fiche 50-339,83/05/05,8305110453

--8305110465 LER 83-031/03L-0 on 830408,w/unit in Mode 5,power lost to RHR subsystem A when 2H 4,160-volt emergency bus deenergized Caused by failure of fuses for 2H emergency bus undervoltage test circuit Fuses replaced
HARRELL,E.W Virginia Electric & Power Co 83/05/05 Region 2, Office of Director 3pp 18405 055 24X Fiche 50-339,83/05/05, 8305110453

8305200279 Forwards LER 83-032/03L-0
HARRELL,E.W Virginia Electric & Power Co 83/05/11 O'REILLY,J P
Region 2, Office of Director 1p 18516 260 24X
Fiche 50-339,83/05/11,8305200279

--8305200284 LER 83-032/03L-0,on 830412,during Mode 5,visual insp of hydraulic snubber 2-WGCB-HSS-38 revealed damaged reservoir w/o fluid Caused by personnel working in area Snubber replaced
HARRELL,E W Virginia Electric & Power Co 83/05/11 Region 2, Office of Director 2pp 18516 261 24X Fiche 50-339,83/05/11, 8305200279

8305250384 LER 83-036/03L-0 on 830429,while in Mode 6,loss of vital bus 2-1 resulted in loss of RHR flow for less than 1 minute when one of two RHR suction valves in series closed Caused by personnel shorting test lead Bus restored W/830518 ltr
HARRELL,E W Virginia Electric & Power Co 83/05/18 O'REILLY,J P
Region 2, Office of Director 4pp 18592 076 24X
Fiche 50-339,83/05/18,8305250384

8305270335 LER 83-035/03L-0 on 830423 & 24,86 lockout relay wiring omission detected while testing bus 2H charging high head safety injection pump breakers Caused by incorrect wiring Wiring properly installed W/830520 ltr
HARRELL,E W Virginia Electric & Power Co 83/05/20 O'REILLY,J P
Region 2, Office of Director 4pp 18644 359 24X
Fiche 50-339,83/05/20,8305270335

DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305020370 Responds to NRC 830316 ltr requesting schedule for addressing unqualified electrical components in safety-related sys Issue will be addressed in environ qualification update by 830701
TAUBER,H Detroit Edison Co 83/04/25 YOUNGBLOOD,B J Licensing Branch 1 1p 18276 342 24X Fiche 50-341,83/04/25,8305020370

8305030171 Forwards "Independent Design Verification Program,Final Rept," Vols 1,2 & 3 Rept presents results & conclusions of review conducted per 821216 independent design verification program plan
FERG,D A Cygna Energy Services 83/04/29 YOUNGBLOOD,B J Licensing Branch 1 COLBERT,W F Detroit Edison Co 1p 18289 060 24X Fiche 50-341,83/04/29,8305030171

--8305030178 "Independent Design Verification Program,Final Rept," Vols 1,2 & 3
FERG,D A Cygna Energy Services TR-83021-I R00 83/04/29 878pp 18289 061 24X Fiche 50-341,83/04/29,8305030171

8305050004 Forwards Pages 2 20-2 32 inadvertently omitted from "Independent Design Verification Program Final Rept "
FERG,D A Cygna Energy Services 83/05/03 YOUNGBLOOD,B J Licensing Branch 1 1p 18338 316 24X Fiche 50-341,83/05/03,8305050004

--8305050010 Pages 2 20-2 32 inadvertently omitted from "Independent Design Verification Program Final Rept "
* Cygna Energy Services TR-83021-1 R00 ERR 83/05/03 12pp 18338 317 24X Fiche 50-341,83/05/03,8305050004

8305100119 Forwards summary of post-accident sampling analytical procedures per 820707 ltr Info describes type of analysis, equipment,suitability,range & analytical method
TAUBER,H Detroit Edison Co 83/05/03 YOUNGBLOOD,B J Licensing Branch 1 2pp 18374 361 24X Fiche 50-341,83/05/03,8305100119

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305120231 Notification of 830513 meeting w/util in Bethesda,MD to discuss general procedures followed by NRC in responding to pending Section 2 206 petition
LYNCH,M D Licensing Branch 1 83/05/06 YOUNGBLOOD,B J. Licensing Branch 1 3pp 18435 263 24X Fiche 50-341,83/05/06, 8305120231

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305250207 Notification of Caseload Forecast Panel 830607-09 site visit to estimate const completion date Agenda encl
LYNCH,M D Licensing Branch 1 83/05/12 YOUNGBLOOD,B J Licensing Branch 1 6pp 18595 352 24X Fiche 50-341,83/05/12, 8305250207

8305230552 Summarizes 821207 conference call re current plan for conducting induction heating stress improvement (IHSI) program on appropriate welds in recirculation sys
TAUBER,H Detroit Edison Co 83/05/18 YOUNGBLOOD,B J Licensing Branch 1 2pp 18537 090 24X Fiche 50-341,83/05/18,8305230552

F Security, medical, emergency & fire protection plans

8305020264 Forwards IE Safeguards Insp Rept 50-341/83-05 on 830101-0228 & notice of violation
NORELIUS,C E Division of Project & Resident Programs 83/04/11
WELLS,D A Detroit Edison Co 2pp 18277 095 24X
Fiche 50-341,83/04/11,8305020264

--8305020274 Notice of violation from insp on 830101-0228
NORELIUS,C E Division of Project & Resident Programs 83/04/11 2pp 18277 097 24X Fiche 50-341,83/04/11,8305020264

---8305020285 IE Safeguards Insp Rept 50-341/83-05 on 830101-0228 Noncompliance noted failure to follow reactor vessel flow procedures & inadequate review of procedure changes & identification & control measures
LITTLE,B H , BYRON,P.M , WESCOTT,H M Region 3, Office of Director 83/04/04 13pp 18277 099 24X Fiche 50-341,83/04/11, 8305020264

8305090480 Forwards Michigan Emergency Preparedness Act MCLA 30 401, FEMA 830420 memo per ASLAP 830504 request on emergency preparedness issues,Michigan State Police 830408 ltr & Monroe County Ofc of Civil Preparedness 830318 ltr
LANDGRAF,L C. LeBoeuf, Lamb, Leiby & MacRae. LANDGRAF,L.C Detroit Edison Co 83/05/05. EILPERIN,B F , MOORE,T B , COTCHY,R L Atomic Safety and Licensing Appeal Panel 46pp 18362 279 24X
Fiche 50-341,83/05/05,8305090480.

8305110620 Notification of 830512 meeting w/util in Bethesda,MD to discuss fire protection of safety-related cables including adequacy of 3-h fire blankets fire stops & heat conduction
LYNCH,M D Licensing Branch 1 83/05/06 YOUNGBLOOD,B J Licensing Branch 1 3pp 18416 360 24X Fiche 50-341,83/05/06, 8305110620

8305250219 Notification of postponement of 830512 meeting w/util in Bethesda,MD to discuss fire protection of safety-related cables Meeting to be rescheduled
LYNCH,M D Licensing Branch 1 83/05/10 YOUNGBLOOD,B J Licensing Branch 1 3pp 18596 359 24X Fiche 50-341,83/05/10, 8305250219

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305020264 Forwards IE Safeguards Insp Rept 50-341/83-05 on 830101-0228 & notice of violation
NORELIUS,C E Division of Project & Resident Programs 83/04/11
WELLS,D A Detroit Edison Co 2pp 18277 095 24X
Fiche 50-341,83/04/11,8305020264

--8305020274 Notice of violation from insp on 830101-0228
NORELIUS,C E Division of Project & Resident Programs 83/04/11 2pp 18277 097 24X Fiche 50-341,83/04/11,8305020264

--8305020285 IE Safeguards Insp Rept 50-341/83-05 on 830101-0228 Noncompliance noted failure to follow reactor vessel flow procedures & inadequate review of procedure changes & identification & control measures
LITTLE,B H , BYRON,P M , WESCOTT,H M Region 3, Office of Director 83/04/04 13pp 18277 099 24X Fiche 50-341,83/04/11, 8305020264.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305170294 Forwards IE Insp Rept 50-341/83-04 on 830214-0317 & notice of violation.
SPESSARD,R L Division of Engineering 83/04/27 WELLS,D A Detroit Edison Co 2pp 18466 107 24X Fiche 50-341,83/04/27, 8305170294

--8305170298 Notice of violation from insp on 830214-0317
SPESSARD,R L Division of Engineering 83/04/27 3pp. 18466 109 24X Fiche 50-341,83/04/27,8305170294

--8305170304 IE Insp Rept 50-341/83-04 on 830214-0317 Noncompliance noted failure to identify & segregate nonconforming cables, adequately control temporary mod in test procedure & properly control & tag lifted leads
REIMANN,F W , REYES,L A Region 3, Office of Director 83/04/27 9pp 18466 112 24X Fiche 50-341,83/04/27,8305170294

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 11pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 11pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 12pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 12pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 11pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305100388 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/82-14
SPESSARD,R L Division of Engineering 83/05/04 WELLS,D A Detroit Edison Co 1p 18381 018 24X Fiche 50-341,83/05/04, 8305100388

--8305100393 Amends 830222 response to NRC 821203 ltr re violations noted in IE Insp Rept 50-341/82-14 Corrective actions QC mgt will follow Daniel Site Administrative Procedure AP-VII-02 re deviation disposition request
WELLS,D A Detroit Edison Co 83/03/31 LITTLE,W S Region 3, Office of Director 11pp 18381 019 24X Fiche 50-341,83/05/04, 8305100388

--8305100399 Responds to NRC 821203 ltr re violations noted in IE Insp Rept 50-341/82-14 Corrective actions Deviation Disposition Request (DDR) 1757 revised to require originator quality manager to provide copy of void DDR
WELLS,D A Detroit Edison Co 83/02/22 LITTLE,W S Region 3, Office of Director 10pp 18381 030 24X Fiche 50-341,83/05/04, 8305100388

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 11pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 11pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/19 Consolidated Edison Co of New York, Inc 11pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270261 Forwards IE Insp Rept 50-341/83-08 on 830411-13 No noncompliance noted
PAPERIELLO,C.J. Region 3, Office of Director 83/05/25. WELLS,D A. Detroit Edison Co 2pp 18642 016 24X Fiche 50-341,83/05/25, 8305270261

--8305270270 IE Insp Rept 50-341/83-08 on 830411-13 No noncompliance noted Major areas inspected preoperational radiological environ monitoring program,including mgt control,program implementation & results & QC
GEBTMANN,M J , ROZAK,S. , SCHUMACHER,M Region 3, Office of Director, 83/05/25 7pp 18642.018 24X Fiche 50-341,83/05/25, 8305270261

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 11pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030476 Interim deficiency rept re Fisher Control valve actuators not meeting seismic requirements Initially reported on 801231 New actuators ordered Engineering specs for Class 3 valves revised for future purchases
WELLS,D A Detroit Edison Co 83/04/15 KEPPLER,J G Region 3, Office of Director 2pp 18308 194 24X Fiche 50-341,83/04/15, 8305030476

8305030585 Final deficiency rept re defective Agastat relays Initially reported on 820205 One relay mfg by Amerace Corp shipped to facility Relay removed on 821001 & returned to manufacturer for insp & possible replacement
WELLS,D A Detroit Edison Co 83/04/15 KEPPLER,J G Region 3, Office of Director 2pp 18306 092 24X Fiche 50-341,83/04/15, 8305030585

8305030596 Interim deficiency rept re calibr of Rosemount Model 510 DU trip units Initially reported on 820720 Potentiometers replaced w/components containing gold contacts to prevent oxidation of trip setpoint
WELLS,D A Detroit Edison Co 83/04/15 KEPPLER,J G Region 3, Office of Director 2pp 18303 212 24X Fiche 50-341,83/04/15, 8305030596

8305030369 Interim deficiency rept re potential failure of ITE 4,160-volt circuit breakers due to cracks in puffer piston shafts Initially reported on 830321 One failure observed at linkage connecting pin on shaft
WELLS,R A Detroit Edison Co 83/04/18 KEPPLER,J G Region 3, Office of Director 1p 18306 216 24X Fiche 50-341,83/04/18, 8305030369

8305020085 Deficiency rept re questionable qualification of certain LK Comstock QC personnel Initially reported on 830311 Certification files updated to reflect prior work experience Const not adversely affected
WELLS,D A Detroit Edison Co 83/04/20 KEPPLER,J G Region 3, Office of Director 2pp 18278 248 24X Fiche 50-341,83/04/20, 8305020085

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305100015 Interim deficiency rept re loose nuts on drywell & steam tunnel beams of structural steel sliding connection 92 Initially reported on 830328 Deviation Disposition Request MP-11006 initiated on 830406
WELLS,D A Detroit Edison Co 83/04/28 KEPPLER,J G Region 3, Office of Director 1p 18377 153 24X Fiche 50-341,83/04/28, 8305100015

8305100118 Final Deficiency Rept 73 re reactor mode switch failure Initially reported on 820701 Switch handle replaced Documentation for replacement switch handle acceptable
WELLS,D A Detroit Edison Co 83/04/29 KEPPLER,J G Region 3, Office of Director 1p 18375 031 24X Fiche 50-341,83/04/29, 8305100118

8305100154 Final Deficiency Rept 83 re overpressurization of standby liquid control sys pump B Initially reported on 821206 Caused by disconnected terminal wire on relay No sys damage exists Item not reportable per 10CFR50 55(e)
WELLS,D A Detroit Edison Co 83/05/05 KEPPLER,J G Region 3, Office of Director 2pp 18374 219 24X Fiche 50-341,83/05/05, 8305100154

8305170207 Final deficiency rept (Item 81) re arc strikes on primary containment pipe penetration bellows Initially reported on 821123 Analysis of bellows repair revealed fatigue test met ASME requirements Item not reportable per 10CFR50 55(e)
WELLS,D A Detroit Edison Co 83/05/06 KEPPLER,J G, Region 3, Office of Director 2pp 18466 328 24X Fiche 50-341,83/05/06, 8305170207

8305170535 Interim deficiency rept (Item 93) re GE error in RHR HX flow calculations Initially reported on 830406 GE performed evaluation of flow deficiency & concluded lower baffle plates of HXs required mod & rework
WELLS,D A Detroit Edison Co 83/05/06 KEPPLER,J G Region 3, Office of Director 2pp 18467 356 24X Fiche 50-341,83/05/06, 8305170535

8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration
HAISLER,R K Litton Industries,Inc 83/05/20 KEPPLER,J G Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20, 8305270625

T Hearing transcripts on non-antitrust matters

8305060188 Transcript of 830504 oral argument in Bethesda,MD Pp 1-76
* Atomic Safety and Licensing Appeal Panel 83/05/04 78pp
18345 112 24X Fiche 50-341,83/05/04,8305060188

DOCKET 50-344 TROJAN NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

8305040417 Requests exemption from fire protection requirements of Section III G 2 of App R to 10CFR50 per 10CFR50 12 re 45-ft elevation of fuel & auxiliary bldg Proposed mods provide adequate level of protection
WITHERS,B D Portland General Electric Co 83/04/27 CLARK,R A
Operating Reactors Branch 3 5pp 18322 121 24X
Fiche 50-344,83/04/27,8305040417

8305060666 Forwards Amend 80 to License NPF-1 & notice of issuance & availability Amend adds License Condition 2 C (10) re implementation of IAEA safeguards at facility
CLARK,R A Operating Reactors Branch 3 83/04/27 WITHERS,B D
Portland General Electric Co 4pp 18357 335 24X
Fiche 50-344,83/04/27,8305060666

--8305060669 Amend 80 to License NPF-1,adding License Condition 2 C (10) (per 10CFR75 B) re implementation of IAEA safeguards at facility in response to 830323 ltr
CLARK,R A Operating Reactors Branch 3 83/04/27 7pp
18357 339 24X Fiche 50-344,83/04/27,8305060666

--8305060670 Notice of issuance & availability of Amend 80 to License NPF-1
CLARK,R A Operating Reactors Branch 3 83/04/27 2pp
18357 346 24X Fiche 50-344,83/04/27,8305060666

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing, 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 093 24X
Fiche 50-000,83/05/11,8305110034

8305200030 Notifies that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
CLARK,R A Operating Reactors Branch 3 83/05/12 WITHERS,B D
Portland General Electric Co 3pp 18540 120 24X
Fiche 50-344,83/05/12,8305200030.

P. Operating license stage documents & correspondence

8305230581 Forwards lists of NRC initiated & TMI-related backfit items, in response to 830208 ltr Backfitting costs resulting from utils own needs also provided.
WITHERS,B D Portland General Electric Co 83/03/24
TOURTELLOTTE,J Regulatory Reform Task Force 4pp 18541 314 24X
Fiche 50-344,83/03/24,8305230581

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305060666 Forwards Amend 80 to License NPF-1 & notice of issuance & availability Amend adds License Condition 2 C (10) re implementation of IAEA safeguards at facility
CLARK,R A Operating Reactors Branch 3 83/04/27 WITHERS,B D
Portland General Electric Co. 4pp 18357 335 24X
Fiche 50-344,83/04/27,8305060666

--8305060669 Amend 80 to License NPF-1,adding License Condition 2 C (10) (per 10CFR75 B) re implementation of IAEA safeguards at facility in response to 830323 ltr
CLARK,R A Operating Reactors Branch 3 83/04/27 7pp
18357 339 24X Fiche 50-344,83/04/27,8305060666

--8305060670 Notice of issuance & availability of Amend 80 to License NPF-1
CLARK,R A Operating Reactors Branch 3 83/04/27 2pp
18357 346 24X Fiche 50-344,83/04/27,8305060666

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305060600 Forwards application for amend to License NPF-1 to allow continued use of fuel assemblies modified w/stainless steel rods & partial grids Certificate of Svc for License Change Application 90 encl
WITHERS,B D. Portland General Electric Co 83/05/02 CLARK,R A
Operating Reactors Branch 3 1p 18348 358 24X
Fiche 50-344,83/05/02,8305060600

--8305060606 Application for amend to License NPF-1 to allow continued use of fuel assemblies modified w/stainless steel rods & partial grids
WITHERS,B D Portland General Electric Co 83/05/02 9pp.
18348 358 24X Fiche,50-344,83/05/02,8305060600

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130240 Advises that Cycle VI core physics data values & plot requested by Tech Spec 6 9 1 10 cannot be submitted on schedule due to design delay in design of core Approval of delayed submittal requested
WITHERS,B D Portland General Electric Co 83/05/09 MARTIN,J B
Region 5, Office of Director 2pp 18439 193 24X
Fiche:50-344,83/05/09,8305130240

8305200013 Advises that hydrogen vent valve replacement scheduled for 1983 refueling outage postponed until 1984 refueling outage or next permissible date per operating schedule Delay caused by late valve delivery from mfg
WITHERS,B D Portland General Electric Co 83/05/13 CLARK,R A
Operating Reactors Branch 3 1p 18519 083 24X
Fiche 50-344,83/05/13,8305200013

8305260275 Forwards lists identifying safety-related electric equipment subj to environ qualification,per 10CFR50 49(g) Hydrogen vent valves will not be replaced w/fully qualified valves until 1984 refueling outage
WITHERS,B D Portland General Electric Co 83/05/20 CLARK,R A
Operating Reactors Branch 3 21pp 18625 213 24X
Fiche 50-344,83/05/20,8305260275

8305270182 Forwards License Change Application 92 requesting amend to License NPF-1 Amend revises manipulator crane operability load testing requirements
WITHERS,B D Portland General Electric Co 83/05/24 CLARK,R A
Operating Reactors Branch 3 1p 18637 352 24X
Fiche 50-344,83/05/24,8305270182

--8305270186 License Change Application 92 revising manipulator crane operability load testing requirements
WITHERS,B D Portland General Electric Co 83/05/24 3pp
18637 353 24X Fiche 50-344,83/05/24,8305270182

--8305270188 Proposed Tech Specs revising manipulator crane operability load testing requirements
* Portland General Electric Co 83/05/24 2pp 18637 356 24X
Fiche 50-344,83/05/24,8305270182

8305270205 Forwards License Change Application 91 for amend to License NPF-1,revising MSIV & pressurized code safety valve surveillance requirements
WITHERS,B D Portland General Electric Co 83/05/24 CLARK,R A
Operating Reactors Branch 3 1p 18641.202 24X
Fiche 50-344,83/05/24,8305270205

--8305270211 License Change Application 91 for amend to License NPF-1, revising MSIV & pressurized code safety valve surveillance requirements
WITHERS,B D Portland General Electric Co 83/05/24 4pp
18641:203 24X Fiche 50-344,83/05/24,8305270205

--8305270282 Proposed Tech Spec revising MSIV & pressurized code safety valve surveillance requirements
* Portland General Electric Co 83/05/24 3pp 18641 207 24X Fiche 50-344,83/05/24,8305270205

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305170562 Forwards IE Insp Rept 50-344/83-08 on 830323-25 No noncompliance noted
BOOK,H E Region 5, Office of Director 83/04/08 WITHERS,B D Portland General Electric Co 2pp 18468 144 24X Fiche,50-344,83/04/08,8305170562

--8305170567 IE Insp Rept 50-344/83-08 on 830322-25 No noncompliance noted Major areas inspected radiation protection program, including procedures,surveys,general employee training, posting & labeling & external & internal exposure control
CILLIS,M , WENSLAWSKI,F A , BOOK,H E Region 5, Office of Director 83/04/07 11pp 18468 148 24X Fiche 50-344,83/04/08, 8305170562

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15. Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382;282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441,001 24X Fiche 50-000,83/05/04,8303040031,

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06. Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305130164 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves located in sys.Sys consists of closed cooling loop for each unit,which is cooled by svc water sys.
WITHERS,B D Portland General Electric Co 83/05/09 MARTIN,J B Region 5, Office of Director 2pp 18437 299 24X Fiche:50-344,83/05/09,8305130164

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305130224 Forwards updated LER 83-001/01X-1 Detailed event analysis encl
WITHERS,B D Portland General Electric Co 83/04/22 MARTIN,J B Region 5, Office of Director 3pp 18439 323 24X Fiche 50-344,83/04/22,8305130224

--8305130232 Updated LER 83-001/01X-1 on 830106,as-built conditions in masonry walls differed from conditions in previous seismic response analyses Cause not stated Further investigations in progress
BUSHNELL,T E Portland General Electric Co 83/04/21 Region 5, Office of Director 1p 18439 326 24X Fiche 50-344,83/04/22, 8305130224

8305130143 Forwards LER 83-003/03L-0 Detailed event analysis encl
YUNDT,C P Portland General Electric Co 83/04/27 MARTIN,J B Region 5, Office of Director 3pp 18438 127 24X Fiche 50-344,83/04/27,8305130143

--8305130152 LER 83-003/03L-0 on 830329,plant did not have emergency power source to boric acid transfer pump used in flowpath from boric acid storage tank during core alterations Caused by personnel error Procedure will be clarified
BAIR,G G Portland General Electric Co 83/04/27 Region 5, Office of Director 1p 18438 130 24X Fiche 50-344,83/04/27, 8305130143

DOCKET 50-346 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305100011 Forwards final rept of BNWL participants at 830413-14 emergency preparedness exercise Areas covered include technical support ctr,control room,operations support ctr & offsite monitoring teams
MARTIN,J B , THOMAS,W V Battelle Memorial Institute, Pacific Northwest Laboratory 83/04/22. PLOSKI,T Region 3, Office of Director 24pp 18377 157 24X Fiche 50-346,83/04/22,8305100011

8305100080 Forwards IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted Notices of deficiencies & deviations encl.
PAPERIELLO,C J Region 3, Office of Director 83/04/22 CROUSE,R P Toledo Edison Co 2pp. 18377 230 24X Fiche 50-346,83/04/22,8305100080

--8305100082 Notice of deficiencies from insp on 830315-18
* Region 3, Office of Director. 83/04/22 3pp 18377 232 24X Fiche 50-346,83/04/22,8305100080

--8305100084 Notice of deviation from insp on 830315-18
* Region 3, Office of Director 83/04/22 2pp 18377 235 24X Fiche 50-346,83/04/22,8305100080

--8305100090 IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted.Major areas inspected followup insp of items identified during emergency preparedness implementation appraisal on 830208-19.
PLOSKI,T J., AXELSON,W L Region 3, Office of Director 83/04/20 12pp 18377 237. 24X Fiche 50-346,83/04/22,8305100080

8305060595 Releases public version of temporary mod request to emergency plan implementing procedure
FELTON,J.M Division of Rules and Records 83/04/25 Document Management Branch 1p. 18359 185 24X Fiche 50-346,83/04/25, 8305060595

--8305060601 Forwards public version of Temporary Mod Request T-7104 to Emergency Plan Implementing Procedure EI 1300 07, "Technical Support Ctr Activation " Receipt form encl
* Toledo Edison Co 83/04/11 NRC - No Detailed Affiliation
Given 1p 18359 186 24X Fiche 50-346,83/04/25,8305060595

--8305060608 Public version of Temporary Mod Request T-7104 to Emergency Plan Implementing Procedure EI 1300 07, "Technical Support Ctr Activation " Rev 27 to index encl
DURDEL,R , FARIS,J A , MURRAY,T D Toledo Edison Co 83/04/05
3pp 18359 187 24X Fiche 50-346,83/04/25,8305060595

8305060692 Releases public version of rev to emergency plan implementing procedure
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18358 156 24X Fiche 50-346,83/04/25, 8305060692

--8305060699 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EI 1300 01, "Emergency Plan Activation "
* Toledo Edison Co 83/03/31 NRC - No Detailed Affiliation
Given 3pp 18358 157 24X Fiche 50-346,83/04/25,8305060692

--8305060702 Public version of Rev 5 to Emergency Plan Implementing Procedure EI 1300 01, "Emergency Plan Activation " Rev 26 to index encl
MURRAY,T D , BEYER,B R , BRIDEN,D W Toledo Edison Co 83/03/28
40pp 18358 160 24X Fiche 50-346,83/04/25,8305060692

8305030389 Ack receipt of 821206 proposed changes to industrial security plan Change B acceptable Comments on Change A,which decreases security plan effectiveness; encl Encls withheld (ref 10CFR73 21)
STOLZ,J F Operating Reactors Branch 4 83/04/26 CROUSE,R P
Toledo Edison Co 1p 18306 306 24X Fiche 50-346,83/04/26, 8305030389

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305270605 Forwards IE Insp Rept 50-346/83-07 on 830412-15 No violations or deviations identified Weaknesses w/emergency exercise identified which will require corrective action
PAPERIELLO,C J Region 3, Office of Director 83/05/12
CROUSE,R P Toledo Edison Co 3pp 18644 252 24X
Fiche 50-346,83/05/12,8305270605

--8305270614 IE Insp Rept 50-346/83-07 on 830412-15 Weaknesses identified in draft exercise scenario
PLOSKI,T J , PHILLIPS,M P , GLOERSEN,W B Region 3, Office of Director 83/05/12 13pp 18644 255 24X Fiche 50-346,83/05/12, 8305270605

8305240251 Advises that App B to industrial security plan,transmitted in Amend 56 to License NPF-3,contains no proprietary info
CROUSE,R P Toledo Edison Co 83/05/13 STOLZ,J F Operating Reactors Branch 4 1p 18548 308 24X Fiche 50-346,83/05/13, 8305240251

8305260241 Forwards application for amend to License NPF-3,reflecting change in audit frequency of security & emergency plans to 12 months
CROUSE,R P Toledo Edison Co 83/05/19 STOLZ,J F Operating Reactors Branch 4 1p 18599 332 24X Fiche 50-346,83/05/19, 8305260241

--8305260245 Application for amend to License NPF-3 reflecting change in audit frequency of security & emergency plans to 12 months
CROUSE,R P Toledo Edison Co 83/05/19 3pp 18599 333 24X
Fiche 50-346,83/05/19,8305260241

--8305260248 Marked-up proposed Tech Spec changes reflecting change in audit frequency of security & emergency plans to 12 months
* Toledo Edison Co 83/05/19 1p 18599 336 24X
Fiche 50-346,83/05/19,8305260241

8305260303 Responds to NRC 830422 ltr re deficiencies noted in IE Emergency Preparedness Appraisal Rept 50-346/83-03 Corrective actions,procedures revised,training conducted & sample lines shielded w/lead bricks & lead blankets
CROUSE,R P Toledo Edison Co 83/05/20 KEPPLER,J G Region 3, Office of Director 7pp 18625 344 24X Fiche 50-346,83/05/20, 8305260303

J Insurance & indemnity information

8305160105 Forwards Endorsement 44 to NELIA Policy NF-236 & Endorsement 34 to MAELU Policy MF-92
GOLDEN,M P Marsh & McLennan, Inc 83/05/02 SALTZMAN,J
Assistant Director for State & Licensee Relations 3pp 18451 053
24X Fiche 50-346,83/05/02,8305160105

P. Operating license stage documents & correspondence

8305230716 Responds to 830208 request for backfitting expenditures. Actual cost at OL date was $503 million Projected addl future cost for NRC imposed mods conservatively estimated at $26,500,000
CROUSE,R P Toledo Edison Co 83/02/18 TOURTELLOTTE,J
Regulatory Reform Task Force 10pp 18542 294 24X
Fiche 50-346,83/02/18,8305230716

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J. Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305040305 Responds to NRC 830325 ltr re safety-related electrical equipment Justification for continued operation exists for all equipment which may not be qualified Response submitted 830310 contains no changes or proprietary info
CROUSE,R P Toledo Edison Co 83/04/29 STOLZ,J F. Operating Reactors Branch 4 28pp 18323 260 24X Fiche 50-346,83/04/29, 8305040305

8305170462 Discusses results of analysis performed to determine probability of postulated tornado generated missile contacting gratings covering ventilation openings Probability acceptably small Condition not RO
CROUSE,R P Toledo Edison Co 83/04/29 KEPPLER,J G Region 3, Office of Director. 2pp 18470 136 24X Fiche 50-346,83/04/29, 8305170462

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche,50-000,83/05/02,8305020455

8305040472 Application to amend License NPF-3 revising App A to Tech Spec Tables 4 3-6 & 4 3-10 re extension of surveillance interval for steam generator outlet pressure instrumentation
CROUSE,R P Toledo Edison Co 83/05/02 STOLZ,J F Operating Reactors Branch 4 2pp 18322 157 24X Fiche 50-346,83/05/02, 8305040472.

--8305040480 Proposed changes to App A to Tech Specs revising Tables 4.3-6 & 4.3-10 re extension of surveillance interval for steam generator outlet pressure instrumentation
* Toledo Edison Co 83/05/02 4pp 18322 159 24X
Fiche 50-346,83/05/02,8305040472

8305040491 Forwards application for amend to License NPF-3 revising Tech Spec Section 4 8 1.2,Tables 4 3-11 & 3 6-2 re surveillance requirements for automatic load sequencer & monthly testing of auxiliary feedwater sys logic
CROUSE,R P Toledo Edison Co 83/05/02 STOLZ,J F Operating Reactors Branch 4 1p 18322 145 24X Fiche 50-346,83/05/02, 8305040491

--8305040497 Application for amend to License NPF-3 revising Tech Spec Section 4 8 1 2,Tables 4 3-11 & 3 6-2 re surveillance requirements for automatic load sequencer & monthly testing of auxiliary feedwater sys logic
CROUSE,R P. Toledo Edison Co 83/05/02. 3pp 18322 146 24X
Fiche 50-346,83/05/02,8305040491

--8305040503 Proposed changes to Tech Spec revising Section 4 8 1.2, Tables 4 3-11 & 3 6-2 re surveillance requirements for automatic load sequencer & monthly testing of auxiliary feedwater sys logic.
* Toledo Edison Co 83/05/03 8pp 18322.149 24X
Fiche 50-346,83/05/02,8305040491

8305060365 Notification of 830506 meeting w/B&W Owners Group in Bethesda,MD to discuss core barrel failure at Rancho Seco & Crystal River 3,future plans for resolving problem & justification for continued operation
MINER,B Operating Reactors Branch 4 83/05/02 STOLZ,J
Operating Reactors Branch 4. 2pp 18353 092 24X
Fiche,50-000,83/05/02,8305060365

8305060395 Forwards response to 820923 ltr re open items in NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants " Dynamic load effects, inservice insp & exam frequency reviewed Phase II results expected by 830601
CROUSE, R P Toledo Edison Co 83/05/02 STOLZ, J F Operating Reactors Branch 4 7pp 18343 167 24X Fiche 50-346, 83/05/02, 8305060395

8305170669 Forwards Amend 58 to License NPF-3, safety evaluation & notice of issuance & availability Amend modifies Tech Spec table to incorporate revised trip setpoints for borated water storage tank
DE AGAZIO, A W Operating Reactors Branch 4 83/05/05 CROUSE, R P Toledo Edison Co 3pp 18496 329 24X Fiche 50-346, 83/05/05, 8305170669

--8305170673 Amend 58 to License NPF-3, revising trip setpoints for borated water storage tank & bus feeder breaker trip delay
STOLZ, J F Operating Reactors Branch 4 83/05/05 9pp 18496 332 24X Fiche 50-346, 83/05/05, 8305170669

--8305170678 Safety evaluation supporting Amend 58 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 83/05/05 3pp 18496 341 24X Fiche 50-346, 83/05/05, 8305170669

--8305170682 Notice of issuance & availability of Amend 58 to License NPF-3
STOLZ, J F Operating Reactors Branch 4 83/05/05 2pp 18496 344 24X Fiche 50-346, 83/05/05, 8305170669

8305180102 Forwards Amend 57 to License NPF-3, safety evaluation & notice of issuance & availability Amend modifies specs to provide addl protection to minimize potential for low temp overpressure transients
STOLZ, J F. Operating Reactors Branch 4 83/05/05 CROUSE, R P Toledo Edison Co 4pp 18503 300 24X Fiche 50-346, 83/05/05, 8305180102.

--8305180114 Amend 57 to License NPF-3, modifying specs to provide addl protection to minimize potential for low temp overpressure transients
STOLZ, J F. Operating Reactors Branch 4 83/05/05 10pp 18503 304. 24X Fiche 50-346, 83/05/05, 8305180102

--8305180135 Safety evaluation supporting Amend 57 to License NPF-3
* Office of Nuclear Reactor Regulation, Director 83/05/05 4pp 18503 314 24X Fiche 50-346, 83/05/05, 8305180102

--8305180187 Notice of issuance & availability of Amend 57 to License NPF-3
STOLZ, J F. Operating Reactors Branch 4 83/05/05 2pp 18503 318. 24X Fiche 50-346, 83/05/05, 8305180102

8305110385 Forwards response to open item on safe load paths contained in NRC 820923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREG-0612)
CROUSE, R P. Toledo Edison Co 83/05/06 STOLZ, J F Operating Reactors Branch 4 11pp 18406 201 24X Fiche 50-346, 83/05/06, 8305110385

8305110437 Forwards "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits," per 830405 ltr
CROUSE, R. P Toledo Edison Co. 83/05/06 STOLZ, J F Operating Reactors Branch 4 1p 18404 320 24X Fiche 50-346, 83/05/06, 8305110437

--8305110443 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits "
* Babcock & Wilcox Co 77-1142162-00 83/05/06 28pp 18404 321. 24X Fiche 50-346, 83/05/06, 8305110437

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods, Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc 16pp. 18627 153 24X Fiche 50-000, 83/05/09, 8305090659.

8305130032 Responds to 830429 ltr re proposed changes to Tech Specs 3 0 3 & 4.0.3 Check in payment of fee transmitted
CROUSE, R P. Toledo Edison Co 83/05/09. MILLER, W D License Fee Management Branch. 1p 18437 101 24X Fiche 50-346, 83/05/09, 8305130032

8305180411 Provides status rept on implementation of integrated living schedule program, per 830412 ltr Internal task force & standing committees, charged w/various living schedule activities, created & utilized
CROUSE, R. P. Toledo Edison Co 83/05/10 STOLZ, J. F Operating Reactors Branch 4. 6pp. 18485 356 24X Fiche 50-346, 83/05/10, 8305180411

8305200592 Advises that due to difficulties w/rev. license amend request re DHR capability redundancy will be submitted by 830615
CROUSE, R P Toledo Edison Co 83/05/13 STOLZ, J F Operating Reactors Branch 4 1p 18514 120 24X Fiche 50-346, 83/05/13, 8305200592

8305240351 Forwards response to 830411 request for addl info re deletion of surveillance requirements for auxiliary feedwater pump turbine speed switches Water level in steam generator controlled at 35 inches
CROUSE, R P Toledo Edison Co 83/05/17 STOLZ, J F Operating Reactors Branch 4 4pp 18574 075 24X Fiche 50-346, 83/05/17, 8305240351

8305260241 Forwards application for amend to License NPF-3, reflecting change in audit frequency of security & emergency plans to 12 months
CROUSE, R P Toledo Edison Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18599 332 24X Fiche 50-346, 83/05/19, 8305260241

--8305260245 Application for amend to License NPF-3 reflecting change in audit frequency of security & emergency plans to 12 months
CROUSE, R P Toledo Edison Co 83/05/19 3pp 18599 333 24X Fiche 50-346, 83/05/19, 8305260241

--8305260248 Marked-up proposed Tech Spec changes reflecting change in audit frequency of security & emergency plans to 12 months
* Toledo Edison Co 83/05/19 1p 18599 336 24X Fiche 50-346, 83/05/19, 8305260241

8305240423 Forwards info re environ qualification of electrical equipment important to safety, per 10CFR50 49 List of activities to resolve technical evaluation rept open items encl Namco limit switches scheduled for replacement listed
CROUSE, R P Toledo Edison Co 83/05/20 STOLZ, J F Operating Reactors Branch 4 29pp 18573 006 24X Fiche 50-346, 83/05/20, 8305240423

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305100080 Forwards IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted Notices of deficiencies & deviations encl
PAPERIELLO, C J Region 3, Office of Director 83/04/22
CROUSE, R P Toledo Edison Co 2pp 18377 230 24X Fiche 50-346, 83/04/22, 8305100080

--8305100082 Notice of deficiencies from insp on 830315-18
* Region 3, Office of Director 83/04/22 3pp 18377 232 24X Fiche 50-346, 83/04/22, 8305100080

--8305100084 Notice of deviation from insp on 830315-18
* Region 3, Office of Director 83/04/22 2pp 18377 235 24X Fiche 50-346, 83/04/22, 8305100080

--8305100090 IE Insp Rept 50-346/83-03 on 830315-18 No noncompliance noted Major areas inspected followup insp of items identified during emergency preparedness implementation appraisal on 830208-19.
PLOSKI, T J , AXELSON, W L Region 3, Office of Director 83/04/20 12pp 18377 237 24X Fiche 50-346, 83/04/22, 8305100080

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170303 Forwards IE Insp Rept 50-346/83-04 on 830301-04 & 09-11 & notice of violation
STREETER, J F Region 3, Office of Director 83/04/27 CROUSE, R P. Toledo Edison Co 2pp 18466 015 24X Fiche 50-346, 83/04/27, 8305170303

--8305170308 Notice of violation from insp on 830301-04 & 09-11
STREETER, J F Region 3, Office of Director 83/04/27 1p 18466 017 24X Fiche 50-346, 83/04/27, 8305170303

--8305170315 IE Insp Rept 50-346/83-04 on 830301-04 & 09-11 Noncompliance noted waivers not prepared & exams not given to two individuals not attending required radiological control requalification training
SUTPHIN, R N , HAWKINS, F C Region 3, Office of Director 83/04/27 6pp 18466 018 24X Fiche 50-346, 83/04/27, 8305170303

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305060519 Forwards revised "Inservice Insp Pump & Valve Program, " reflecting results discussed at 830329 meeting
CROUSE, R P Toledo Edison Co 83/04/29 STOLZ, J F Operating Reactors Branch 4 2pp 18351 113 24X Fiche 50-346, 83/04/29, 8305060519

--8305060523 "Inservice Insp Pump & Valve Program "
* Toledo Edison Co 83/04/29 23pp 18351 115 24X Fiche 50-346, 83/04/29, 8305060519

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche: 50-000, 83/05/04, 8303040031.

8305100096 Confirms 830627 meeting in Glen Ellyn, IL to discuss SALP
NORELIUS, C E Division of Project & Resident Programs 83/05/04 CROUSE, R P Toledo Edison Co 1p 18377 274 24X Fiche 50-346, 83/05/04, 8305100096

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523.248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305270605 Forwards IE Insp Rept 50-346/83-07 on 830412-15 No violations or deviations identified Weaknesses w/emergency exercise identified which will require corrective action
PAPERIELLO, C J Region 3, Office of Director 83/05/12 CROUSE, R P Toledo Edison Co 3pp 18644 252 24X Fiche, 50-346, 83/05/12, 8305270605

--8305270614 IE Insp Rept 50-346/83-07 on 830412-15 Weaknesses identified in draft exercise scenario.
PLOSKI, T J , PHILLIPS, M P., GLOERSEN, W B Region 3, Office of Director 83/05/12 13pp. 18644 255. 24X Fiche 50-346, 83/05/12, 8305270605

8305200509 Ack receipt of 830118 & 0203 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/82-25
SPESSARD, R L Division of Engineering 83/05/17 CROUSE, R P Toledo Edison Co 1p 18516 075 24X Fiche 50-346, 83/05/17, 8305200509

--8305200514 Responds to NRC 821221 ltr re violations noted in IE Insp Rept 50-346/82-25 Advises that response will be submitted by 830301 Delay due to number of organizations involved in preparation of response
CROUSE, R P Toledo Edison Co 83/01/18 NORELIUS, C E Division of Engineering 1p 18516 076 24X Fiche 50-346, 83/05/17, 8305200509

--8305200520 Responds to NRC 821221 ltr re violations noted in IE Insp Rept 50-346/82-25 Reload pattern did not entail unreviewed safety questions for reason stated
CROUSE, R P Toledo Edison Co 83/02/03 NORELIUS, C E Division of Engineering 2pp 18516 077 24X Fiche 50-346, 83/05/17, 8305200509

--8305200527 Responds to NRC 821221 ltr re violations noted in IE Insp Rept 50-346/82-25 Corrective actions cross-shuffle appropriately considered & proper safety evaluation performed Retraction of notice of violation requested
CROUSE, R P Toledo Edison Co 83/04/13 NORELIUS, C E Division of Engineering 1p 18516 079 24X Fiche 50-346, 83/05/17, 8305200509

8305240067 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-01 Responsibilities to promptly determine, evaluate & rept causes of malfunctions of safety-related equipment stressed
SHAFER, W D Region 3, Office of Director 83/05/17 CROUSE, R P Toledo Edison Co 1p 18549 062 24X Fiche, 50-346, 83/05/17, 8305240067

--8305240072 Responds to NRC 830308 ltr re violations noted in IE Insp Rept 50-346/83-01 Corrective actions statusing of facility change requests initiated to assure that drawings reflect as-built condition Radwaste panel drawing stick updated
CROUSE, R P Toledo Edison Co 83/04/29 NORELIUS, C E Division of Engineering 15pp 18549 063 24X Fiche 50-346, 83/05/17, 8305240067

8305200330 Ack receipt of 830429 ltr Concurs w/decision to extend completion of first 10-yr inservice insp interval to end of scheduled Spring 1989 refueling outage
SPESSARD, R L Division of Engineering 83/05/18 CROUSE, R P Toledo Edison Co 1p 18516 218 24X Fiche 50-346, 83/05/18, 8305200330

--8305200337 Informs of intention to extend completion of first 10-yr inservice insp interval to end of scheduled Spring 1989 refueling outage to coincide w/other planned outages
CROUSE, R P Toledo Edison Co 83/04/29 KEPPLER, J G Region 3, Office of Director 1p 18516 219 24X Fiche 50-346, 83/05/18, 8305200330

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305260303 Responds to NRC 830422 ltr re deficiencies noted in IE Emergency Preparedness Appraisal Rept 50-346/83-03 Corrective actions procedures revised, training conducted & sample lines shielded w/lead bricks & lead blankets
CROUSE, R P Toledo Edison Co 83/05/20 KEPPLER, J G Region 3, Office of Director 7pp 18625 344 24X Fiche 50-346, 83/05/20, 8305260303

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305190149 Forwards "Effluent & Waste Disposal Semiannual Rept, Solid Waste & Irradiated Fuel Shipments, Jul-Dec 1980 "
MURRAY, T D Toledo Edison Co 83/05/11 KEPPLER, J G Region 3, Office of Director 1p 18502 071 24X Fiche 50-346, 83/05/11, 8305190149

--8305190154 "Effluent & Waste Disposal Semiannual Rept, Solid Waste & Irradiated Fuel Shipments, Jul-Dec 1980 "
* Toledo Edison Co 83/05/11 2pp 18502, 072 24X Fiche, 50-346, 83/05/11, 8305190149

B Reportable occurrences, LERs & related correspondence

8305130093 Forwards revised LER 83-012/01X-2
MURRAY, T D Toledo Edison Co 83/05/05 KEPPLER, J G Region 3, Office of Director 1p 18437 193 24X Fiche 50-346, 83/05/05, 8305130093

--8305130095 Revised LER 83-012/01X-2 on 830303, operating practice of requiring one ECCS room cooler to be valved into svc in each ECCS room less conservative than updated FSAR assumptions Caused by lack of procedural control FSAR reviewed
RICHTER, L Toledo Edison Co 83/05/05 Region 3, Office of Director 5pp 18437 196 24X Fiche 50-346, 83/05/05, 8305130093

8305130190 Forwards revised LERs 82-020/03X-2, 81-032/03X-1 & 81-058/01X-1. Previous LER forms should be replaced & respective supplemental info sheets retained
MURRAY, T D Toledo Edison Co 83/05/05 KEPPLER, J G Region 3, Office of Director 1p 18439 348 24X Fiche 50-346, 83/05/05, 8305130190

--8305130195 Revised LER 82-020/03X-2 on 820409, loss of 120 volt alternating current Distribution Panel Y2 experienced while in Mode 6 Safety feature actuation signal Channel 2 actuated Caused by blown YV2 inverter fuse Fuse replaced
MATHENY, D. C , STOTZ, J Toledo Edison Co 83/05/05 Region 3, Office of Director 1p 18439 349 24X Fiche 50-346, 83/05/05, 8305130190

--8305130201 Revised LER 81-032/03X-1 on 810604, relay status lamp 302A did not change when trip signal applied, rendering trip output to AF 599 from steam & feedwater rupture control sys Channel 2 inoperable. Caused by failed relay driver card
TRAUTMAN, D J, Toledo Edison Co 83/05/05 Region 3, Office of Director. 1p. 18439 350 24X Fiche 50-346, 83/05/05, 8305130190

--8305130205 Revised LER 81-058/01X-1 on 811001, very little air flow through chlorine detectors AE5358A & B observed On 811009, detectors declared inoperable Caused by design error Detector discharge routed back to ventilation duct
IBLEY, T Toledo Edison Co. 83/05/05 Region 3, Office of Director, 1p. 18439 351 24X Fiche 50-346, 83/05/05, 8305130190

8305170162 Forwards revised LER 83-002/03X-1.
MURRAY, T D Toledo Edison Co 83/05/05. KEPPLER, J G Region 3, Office of Director 1p. 18466.299 24X Fiche 50-346, 83/05/05, 8305170162

--8305170171 Revised LER 83-002/03X-1 on 830115, RCS dose equivalent I-131 exceeded Tech Spec limit of 1.0 uCi/gm Caused by leakage of fission products through fuel cladding I-131 monitored until level dropped
RICHTER, L Toledo Edison Co 83/05/05. Region 3, Office of Director 8pp 18466 300 24X Fiche 50-346, 83/05/05, 8305170162

8305170201 Forwards LER 83-016/03L-0
MURRAY, T D. Toledo Edison Co 83/05/05 KEPPLER, J G Region 3, Office of Director 1p. 18466 351 24X Fiche 50-346, 83/05/05, 8305170201

--8305170205 LER 83-016/03L-0 on 830407, determined that amplifier of startup level transmitter LT-SP9A3 for steam generator 1-2 failed. Caused by component failure within amplifier Amplifier replaced
YARGER, K Toledo Edison Co. 83/05/05 Region 3, Office of Director 3pp 18466.352 24X Fiche 50-346, 83/05/05, 8305170201

8305240219 LER 83-017/03L-0 on 830411, spent fuel pool (SFP) level verification surveillance test ordered later than Tech Spec requirement Caused by personnel error SFP level verified Memo on schedules planned W/830509 ltr
MURRAY, T. D Toledo Edison Co 83/05/09 KEPPLER, J G Region 3, Office of Director 3pp. 18548 019 24X Fiche 50-346, 83/05/09, 8305240219

8305240341 LER 83-018/03L-0, on 830417, safety features actuation sys channel 4 radiation monitor RE2007 found reading below normal Caused by equipment failure Detector replaced & failed detector sent to vendor for repair W/830516 ltr
IBLEY, T , MURRAY, T D. Toledo Edison Co 83/05/16 KEPPLER, J. G Region 3, Office of Director 3pp 18571 356 24X Fiche: 50-346, 83/05/16, 8305240341.

8305260293 Revised LER 83-016/03X-1, on 830407, amplifier of startup level transmitter LT-SP9A3 for steam generator 1-2 failed Caused by component failure within amplifier. Amplifier replaced W/830517 ltr.
YARGER, K , MURRAY, T D Toledo Edison Co 83/05/17 KEPPLER, J. G Region 3, Office of Director 2pp. 18625 318 24X Fiche: 50-346, 83/05/17, 8305260293

8305310038 LER 83-019/03L-0 on 830421, steam & feedwater rupture control sys Channel 3 tripped Caused by failed +15-volt dc power supply. On 830427, Channel 3 tripped Power supply returned to vendor Failed supplies replaced W/830520 ltr
YARGER, K , STOTZ, J , MURRAY, T D Toledo Edison Co 83/05/20
KEPPLER, J G Region 3, Office of Director 4pp 18653 131 24X Fiche 50-346, 83/05/20, 8305310038

DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305060616 Releases public version of revised svc bldg telephone directory
FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18359 116 24X Fiche 50-348, 83/04/26, 8305060616

--8305060621 Forwards public version of revised svc bldg telephone directory to be filed w/Administrative Procedure FNP-0-EIP-8
HUDSPETH, J B Alabama Power Co 83/04/05 Office of Nuclear Reactor Regulation, Director 2pp 18359 117 24X Fiche 50-348, 83/04/26, 8305060616

--8305060626 Public version of revised svc bldg telephone directory
* Alabama Power Co 83/03/17 66pp 18359 119 24X Fiche 50-348, 83/04/26, 8305060616

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240191 Forwards Rev 6 to security plan Rev establishes upper limit of 120 days on interim clearance, per Varga 830105 ltr Rev withheld (ref 10CFR2 790)
CLAYTON, F L Alabama Power Co 83/05/12 O'REILLY, J P Region 2, Office of Director 1p 18548 031 24X Fiche 50-348, 83/05/12, 8305240191

8305250285 Forwards response to 830204 SERs & NRC 830412 ltr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included
CLAYTON, F L Alabama Power Co 83/05/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 118 p 18696 251 24X Fiche 50-348, 83/05/20, 8305250285

8305250391 Responds to NRC request to evaluate adding RCS cold leg temp indication & source range neutron monitor to hot shutdown panels per 10CFR50, App R Addition of RCS appropriate mod Source range neutron monitor too costly
CLAYTON, F L Alabama Power Co 83/05/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 18585.337. 24X Fiche 50-348, 83/05/20, 8305250391

I Financial information

8305240481 Forwards Annual Financial Rept 1982 & related financial info to satisfy retrospective premium guarantee required under Price-Anderson Act
BOWDEN, T J Alabama Power Co 83/05/20 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 16pp 18572 113 24X Fiche 50-348, 83/05/20, 8305240481

--8305240484 Annual Financial Rept 1982
FARLEY, J M Alabama Power Co 83/03/04 40pp 18572 129 24X Fiche 50-348, 83/05/20, 8305240481

J Insurance & indemnity information

8305040180 Forwards Endorsements 52 & 43 to NELIA Policy NF-238 & MAELU Policy MF-93, respectively
DUCK, J. R Marsh & McLennan, Inc. 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 18324 034 24X Fiche 50-348, 83/04/28, 8305040180

P Operating license stage documents & correspondence

8305090016 Forwards Amend 31 to License NPF-2, safety evaluation & notice of issuance & availability Amend allows increase in storage capacity of spent fuel pool from 675 to 1,407 storage locations
REEVES, E. A Operating Reactors Branch 1 83/04/15 CLAYTON, F. L Alabama Power Co 2pp 18369 288 24X Fiche 50-348, 83/04/15, 8305090016.

--8305090019 Amend 31 to License NPF-2, revising Tech Specs to increase storage capacity of spent fuel pool from 675 to 1,407 storage locations
VARGA, S A Operating Reactors Branch 1 83/04/15 4pp,
18369 290 24X Fiche 50-348, 83/04/15, 8305090016

--8305090023 Safety evaluation supporting Amend 31 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 83/04/15
15pp 18369 294 24X Fiche 50-348, 83/04/15, 8305090016

--8305090027 EIA supporting Amend 31 to License NPF-2
* Office of Nuclear Reactor Regulation, Director 83/04/15
11pp 18369 309 24X Fiche 50-348, 83/04/15, 8305090016

--8305090032 Notice of issuance & availability of Amend 31 to License NPF-2
VARGA, S A Operating Reactors Branch 1 83/04/15 2pp
18369 320 24X Fiche 50-348, 83/04/15, 8305090016

8305020456 Advises of active negotiation w/DOE on agreement for disposal of spent nuclear fuel &/or high level radwaste per Generic Ltr 83-07 Comments on draft std disposal contract & proposed disposal rulemaking encl
CLAYTON, F L Alabama Power Co 83/04/25 VARGA, S A Office of Nuclear Reactor Regulation, Director 12pp 18282 347 24X
Fiche 50-348, 83/04/25, 8305020456

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305180712 Forwards safety evaluation re requests for relief from ASME Code Section XI inservice testing requirements Some relief granted & some alternate testing authorized.
VARGA, S A Operating Reactors Branch 1 83/05/02 CLAYTON, F L Alabama Power Co 4pp 18504 172 24X Fiche 50-348, 83/05/02, 8305180712

--8305180721 Safety evaluation re requests for relief from ASME Code Section XI inservice testing requirements Relief from exercising requirements for svc water check valves denied per IE Bulletin 83-03
* Office of Nuclear Reactor Regulation, Director 83/05/02
14pp 18504 176 24X Fiche 50-348, 83/05/02, 8305180712

--8305180725 Supplementary safety evaluation of inservice testing program
* NRC - No Detailed Affiliation Given 83/05/02 13pp
18504 287 24X Fiche 50-348, 83/05/02, 8305180712

--8305180731 Notice of granting of relief to util from ASME Section XI inservice testing requirements
VARGA, S A Operating Reactors Branch 1 83/05/02 2pp
18504 300 24X Fiche 50-348, 83/05/02, 8305180712

8305110308 Application for amend to OLs revising Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions
CLAYTON, F L Alabama Power Co 83/05/03 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 18393 198 24X
Fiche 50-348, 83/05/03, 8305110308

--8305110311 Proposed changes to Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 increasing confidence of battery operability & providing time to correct certain battery conditions w/o undue plant shutdown
* Alabama Power Co 83/05/03 19pp 18393 203 24X
Fiche 50-348, 83/05/03, 8305110308

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305240440 Advises that operator training program procedures re natural circulation cooldown (Generic Ltr 81-21), based on Westinghouse Owners Group guidelines, will be incorporated by 830615 Training will be completed by 830519
CLAYTON, F L Alabama Power Co 83/05/18 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 18573 131 24X
Fiche 50-348, 83/05/18, 8305240440

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270358 Forwards IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/30
MCDONALD, R P Alabama Power Co 2pp 18642 096 24X
Fiche 50-348, 83/03/30, 8305270358

--8305270370 IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No noncompliance noted Major areas inspected monthly maint & surveillance, operational safety, independent insp effort, refueling & IE Bulletin 82-04 followup
BRADFORD, W H , RULAND, W H Region 2, Office of Director
CANTRELL, F. S Division of Project & Resident Programs 83/03/29
8pp 18642 098 24X Fiche 50-348, 83/03/30, 8305270358

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co, of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305160094 Discusses actions taken to identify & resolve potential DS-416 reactor trip breaker problems per IE Bulletin 83-01 Schedule, w/finalized implementation dates, to be submitted by 830531. Emergency operating procedures encl
CLAYTON, F L Alabama Power Co 83/05/10 VARGA, S A Office of Nuclear Reactor Regulation, Director 7pp 18450 206 24X
Fiche 50-348, 83/05/10, 8305160094

--8305160100 Rev 6 to Emergency Operating Procedure FNP-1-EOP-5 O, "Reactor Trip "
* Alabama Power Co 83/05/09 6pp 18450 213, 24X
Fiche 50-348, 83/05/10, 8305160094

--8305160107 Rev 6 to Emergency Operating Procedure FNP-1-EOP-15 0, "Anticipated Transients W/o Trip (ATWT) "
* Alabama Power Co 83/05/10 5pp 18450 219 24X
Fiche 50-348, 83/05/10, 8305160094

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305200306 Forwards monthly operating rept for Apr 1983
CLAYTON, F L Alabama Power Co 83/05/12 Office of Resource Management, Director 1p 18516 274 24X Fiche 50-348, 83/05/12, 8305200306

--8305200327 Monthly operating rept for Apr 1983
HAIRSTON, W. G Alabama Power Co 83/05/02, 5pp 18516 275 24X Fiche 50-348, 83/05/12, 8305200306

8305200579 Forwards monthly status of licensing items, requiring NRC approval, identified in 830113 ltr
CLAYTON, F L. Alabama Power Co 83/05/13 VARGA, S A Office of Nuclear Reactor Regulation, Director 6pp 18514 114 24X
Fiche 50-348, 83/05/13, 8305200579

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices Initially reported on 830420
Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P. Westinghouse Electric Corp 83/04/21 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427

8305050148 Forwards LERs 83-012/03L-0 & 83-015/03L-0
CLAYTON, F L. Alabama Power Co 83/04/27 O'REILLY, J P Region 2, Office of Director 1p 18341 355 24X Fiche 50-348, 83/04/27, 8305050148

--8305050154 LER 83-015/03L-0 on 830328, instrumentation channel associated w/steam generator 1C flow transmitter FT-497 declared inoperable due to erroneous high indication Caused by obstruction of low pressure sensing line Line cleared
HAIRSTON, W. G Alabama Power Co 83/04/27 Region 2, Office of Director 1p 18341 356 24X Fiche 50-348, 83/04/27, 8305050148

--8305050158 LER 83-012/03L-0 on 830402, overtemp-delta temp loop 2 Channel II declared inoperable when bistables 422C1-2 tripped Caused by power supply failure of comparator card Card replaced & loop calibr
HAIRSTON, W. G Alabama Power Co 83/04/27 Region 2, Office of Director 1p 18341 357 24X Fiche 50-348, 83/04/27, 8305050148

8305050195 Forwards LER 83-014/03L-0
CLAYTON, F L Alabama Power Co 83/04/29 Region 2, Office of Director. 1p 18338, 149 24X Fiche 50-348, 83/04/29, 8305050195

--8305050203 LER 83-014/03L-0, on 830330, during surveillance test of main feedwater pump turbine 1A, RCS Tavg decreased below 541 F. Caused by overfeeding of steam generators due to excessive leak past main feedwater pump discharge valve
HAIRSTON, W G. Alabama Power Co. 83/04/29 Region 2, Office of Director. 1p 18338, 150 24X Fiche 50-348, 83/04/29, 8305050195

8305230540 Forwards LERs 83-018/03L-0 & 83-019/03L-0
CLAYTON, F L. Alabama Power Co 83/05/13 Region 2, Office of Director. 1p 18537 079. 24X Fiche 50-348, 83/05/13, 8305230540

--8305230544 LER 83-018/03L-0, on 830413, RCS temp average fell below Tech Spec limit. Caused by excessive leakby on 1A main feedwater regulating bypass valve Stroke on 1A main feedwater regulating bypass valve adjusted & verified
HAIRSTON, W G Alabama Power Co 83/05/13 Region 2, Office of Director. 1p. 18537 080. 24X Fiche 50-348, 83/05/13, 8305230540

--8305230550 LER 83-017/03L-0 on 830415, pressurizer pressure fell below Tech Spec limits during performance of FNP-1-STP-201 1B Caused by personnel failure to verify instrumentation channel selector switches prior to initiating test
HAIRSTON, W G Alabama Power Co 83/05/13 Region 2, Office of Director 2pp 18537 081 24X Fiche 50-348, 83/05/13, 8305230540

8305250353 LER 83-017/03L-0 on 830417, specific gravity of train A svc water battery bank cells 34 & 43 less than 1 190 Cause undetermined Cells replaced & battery bank returned to svc W/830517 ltr
HAIRSTON, W G , CLAYTON, F L Alabama Power Co 83/05/17 Region 2, Office of Director 2pp 18592 080 24X Fiche 50-348, 83/05/17, 8305250353

8305250581 LER 83-020/03L-0 on 830420, overtemp Delta temp instrumentation loop B associated w/TI422C declared inoperable due to reading out of tolerance w/other channels Caused by drift of summing amplified card W/830520 ltr
HAIRSTON, W G , CLAYTON, F L Alabama Power Co 83/05/20 Region 2, Office of Director 2pp 18588 205 24X Fiche 50-348, 83/05/20, 8305250581

8305310201 Comments on adequacy of current facility DB-416 reactor trip breakers Breaker configuration modified based on dimensional alignment & extensive testing Safe operation not adversely impacted by breakers
CLAYTON, F L Alabama Power Co 83/05/26 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 18658 197 24X
Fiche 50-348, 83/05/26, 8305310201

DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1

A Application/construction stage documents & correspondence

8305060507 Responds to concerns expressed in Encl 1 to NRC 820812 ltr re dynamic qualification of safety-related equipment for seismic & hydrodynamic loads Qualification program revs will be completed by Fourth Quarter 1983
KEMPER, J S Philadelphia Electric Co 83/03/31 SCHWENCER, A
Licensing Branch 2 7pp 18351 147 24X Fiche 50-352, 83/03/31, 8305060507

8305040527 Forwards request for addl info needed for review of auxiliary sys issues
SCHWENCER, A Licensing Branch 2 83/04/22 BAUER, E G
Philadelphia Electric Co 4pp 18351 227 24X
Fiche 50-352, 83/04/22, 8305040527

8305060529 Forwards "Environ Assessment Rept & Findings, Point Pleasant Water Supply Project," per NRC request
WESTON, R T Pennsylvania, Commonwealth of, 83/04/26 LEHR, J C
Environmental & Hydrologic Engineering Branch 1p 18347 309 24X
Fiche 50-352, 83/04/26, 8305060529

--8305060536 "Environ Assessment Rept & Findings, Point Pleasant Water Supply Project "
MIDDENDORF, W D , WESTON, R T , DUNCAN, P S Pennsylvania, Commonwealth of, 82/08/31 118pp 18347 310 24X
Fiche 50-352, 83/04/26, 8305060529

8305020335 Responds to 820405 request for addl info re control rod drive sys hydrodynamic loads Loads caused by operation of scram valves incorporated into sys support design
KEMPER, J S Philadelphia Electric Co 83/04/29 SCHWENCER, A
Licensing Branch 2 5pp 18277 135 24X Fiche 50-352, 83/04/29, 8305020335

8305030299 Forwards application for Amend 48 to OL application, revising FSAR & design assessment rept
BRADLEY, E J Philadelphia Electric Co 83/04/29 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18297 147
24X Fiche 50-352, 83/04/29, 8305030299

--8305030307 Application for Amend 48 to OL application, revising FSAR & design assessment rept Certificate of Svc encl
BAUER, E G , BRADLEY, E J Philadelphia Electric Co 83/04/29
7pp 18297 150 24X Fiche 50-352, 83/04/29, 8305030299

8305060457 Forwards draft responses to NUREG-0737, Items I C 1, I C 6, I D 1, 1 D 2, I G 1 & III, A 1 2 Responses will be incorporated into FSAR by June 1983.
BRADLEY, E J Philadelphia Electric Co 83/05/04 SCHWENCER, A
Licensing Branch 2 9pp 18351 160 24X Fiche 50-352, 83/05/04, 8305060457

8305100275 Forwards Rev 0 to "Study Calculation for E-Sys Clamp on Elbows."
KEMPER, J S Philadelphia Electric Co 83/05/04 PURPLE, R A
Division of Licensing 2pp 18370 175 24X Fiche 50-352, 83/05/04, 8305100275

--8305100281 Rev 0 to "Study Calculation For E-Sys Clamp on Elbows " One oversize drawing encl Aperture card available in PDR
HU,C K , HUANG,A Y , KHLAFALLAH,M Z Bechtel Corp SR 8031-S910 R00 83/04/18 76pp 18370 177 24X Fiche 50-352,83/05/04, 8305100275

8305110079 Summary of 830322-24 meetings w/util,Bechtel & GE in San Jose,CA re applicant response to NRC requests for addl info re mechanical engineering review
MARTIN,R E Licensing Branch 2 83/05/05 Licensing Branch 2 16pp 18419 337 24X Fiche 50-352,83/05/05,8305110079

8305190012 Notification of 830517 & 18 meetings w/util in Bethesda,MD to discuss resolution of remaining outstanding issues
MARTIN,R E Licensing Branch 2 83/05/06 SCHWENCER,A Licensing Branch 2 4pp 18523 209 24X Fiche 50-352,83/05/06,8305190012

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche:50-000,83/05/09,8305090659

8305130026 Notification of 830511 meeting w/util in Bethesda,MD to discuss requirements for resolution of geotechnical issues identified in NRC 830311 ltr
MARTIN,R E Licensing Branch 2 83/05/09 SCHWENCER,A Licensing Branch 2 4pp 18457 175 24X Fiche 50-352,83/05/09,8305130026

8305120320 Forwards draft proposed changes in response to 830407 discussions re Items 1,3a,3b,4,7,8,10-13,15-16 & 18 Draft changes will be incorporated into FSAR rev scheduled for June 1983 & into design assessment rept
BRADLEY,E J Philadelphia Electric Co 83/05/10 SCHWENCER,A Licensing Branch 2 138pp 18431 170 24X Fiche 50-352,83/05/10, 8305120320

8305200170 Notification of cancellation of 830511 meeting w/util in Bethesda,MD to discuss requirements for resolution of geotechnical issues
MARTIN,R E Licensing Branch 2 83/05/10 SCHWENCER,A Licensing Branch 2 4pp 18540 235 24X Fiche 50-352,83/05/10,8305200170

8305170187 Forwards draft responses & FSAR page changes re Instrumentation & Control Sys Branch Requests for Addl Info 421 5,421 6,421 7,421 16,421 30 & 421 50 in NRC 820825 ltr W/seven oversize drawings Aperture cards in PDR
BRADLEY,E J Philadelphia Electric Co 83/05/12 SCHWENCER,A Licensing Branch 2 150pp 18463 017 24X Fiche 50-352,83/05/12, 8305170187

8305180343 Forwards draft responses & FSAR page changes in response to Mechanical Engineering Branch 830411 request for addl info re non-straight main steam line & independent design verification program
BRADLEY,E J Philadelphia Electric Co 83/05/13. SCHWENCER,A Licensing Branch 2 42pp 18485 171 24X Fiche 50-352,83/05/13, 8305180343

8305180402 Forwards draft change to FSAR Section 9 2 6.4 2 2 re spray pond natural evaporation per 830420 telcon Change to be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A Licensing Branch 2. 3pp. 18486 009. 24X Fiche 50-352,83/05/13, 8305180402

8305180419 Forwards draft revs to responses to Questions 430.68,430 72, 430 75 & 430 114 re diesel generator auxiliary sys Changes will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A Licensing Branch 2 21pp. 18485 332. 24X Fiche 50-352,83/05/13, 8305180419

8305180432 Forwards draft responses to Radiological Assessment Branch request for addl info & draft FSAR changes resulting from 830428 telcon w/NRC Schedule for formally incorporating changes into future FSAR revs noted
BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER,A Licensing Branch 2 55pp 18486 126 24X Fiche 50-352,83/05/16, 8305180432

8305230496 Forwards draft revs to QA Branch Questions 260.1 through 260 55 & related FSAR changes per 830329 meeting Info will be incorporated into FSAR in June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/19 SCHWENCER,A Licensing Branch 2 315pp. 18535 358 24X Fiche 50-352,83/05/19, 8305230496

8305250133 Forwards Amend 50 to OL application,substituting revised version of physical security plan Rev withheld (ref 10CFR2 790)
BRADLEY,E J Philadelphia Electric Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18584 065 24X Fiche 50-352,83/05/20,8305250133

--8305250135 Amend 50 to OL application,substituting revised version of physical security plan W/Certificate of Svc
KEUPER,J S Philadelphia Electric Co 83/05/20 7pp 18584.069 24X Fiche 50-352,83/05/20,8305250133

8305270375 Forwards revised draft change to Hydrologic & Geotechnical Engineering Branch open item re FSAR Section 9 2 6 4 2 2 Change will be formally incorporated into FSAR rev in June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/25 SCHWENCER,A Licensing Branch 2 3pp 18644 296 24X Fiche 50-352,83/05/25, 8305270375

C Utility Environmental Report (ER), amends & correspondence

8305160001 Rev 12 to environ rept - OL stage One oversize drawing encl Aperture card available in PDR
* Philadelphia Electric Co 83/04/30 72pp 18448.030 24X Fiche 50-352,83/04/30,8305160001

8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept,per DG Eisenhut 810706 ltr
BRADLEY,E J Philadelphia Electric Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18500.027. 24X Fiche 50-352,83/05/13,8305190359

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020255 Forwards draft responses to Questions 440 3,440 4,440 5 & 440 32 Responses also address Item 1 of draft SER Series 440 Reactor Sys Branch, "ODYN Analysis of Pressurization Transients" & Item 3 of 820716 ltr re SER Section 4 4
BRADLEY,E J Philadelphia Electric Co 83/04/27 SCHWENCER,A Licensing Branch 2 15pp 18277 080 24X Fiche 50-352,83/04/27, 8305020255

8305020454 Forwards draft responses to Reactor Sys Branch draft SER re TMI Items II K 3 13,II K 3 15,II K.3 16,II K 3 18,II K 3 21, II K 3 22,II K 3 24,II K 3.25,II.K 3 30,II K 3 31 & II K 3 45 Response will be incorporated into FSAR revs
BRADLEY,E J Philadelphia Electric Co 83/04/27 SCHWENCER,A Licensing Branch 2 13pp 18283 287 24X Fiche 50-352,83/04/27, 8305020454

8305170228 Forwards draft responses to Reactor Sys Branch draft SER, Items 4 & 5 re TMI Action Items II K 1 5 & II K 1 10 Responses will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J. Philadelphia Electric Co 83/05/11 SCHWENCER,A Licensing Branch 2 4pp 18466 342 24X Fiche 50-352,83/05/11, 8305170228

8305180389 Forwards draft FSAR page changes re open items for Chemical Technology Section draft SER re reactor coolant & suppression pool & secondary containment atmosphere Changes to be incorporated into Rev 20 to FSAR in May 1983
BRADLEY,E.J Philadelphia Electric Co 83/05/13 SCHWENCER,A Licensing Branch 2 10pp 18486 347 24X Fiche 50-352,83/05/13, 8305180389.

8305180451 Forwards draft responses to SER open items re draft fire protection section,per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A Licensing Branch 2 67pp 18486 201 24X Fiche 50-352,83/05/13, 8305180451

8305180414 Forwards Peach Bottom procedures supplementing util 830516 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick
BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER,A Licensing Branch 2 2pp 18482.007 24X Fiche,50-000,83/05/16, 8305180414

--8305180426 Procedure HPO/CO-3, "Airborne Activity Survey Techniques," including techniques for constant air monitors,portable fixed filter samplers & charcoal cartridges
* Philadelphia Electric Co 83/05/16 15pp 18482.009. 24X Fiche 50-000,83/05/16,8305180414

--8305180431 Procedure HPO/CD-65, "Field Use of Low Vol Portable Air Sampler "
* Philadelphia Electric Co 83/05/16 2pp 18482 024 24X
Fiche 50-000,83/05/16,8305180414

--8305180438 Procedure HPA-63d, "Calibr of Ventilation Sys Radiation Monitors "
* Philadelphia Electric Co 83/05/16 8pp 18482 026 24X
Fiche 50-000,83/05/16,8305180414

--8305180443 Procedure HPA-77, "Determination of Max Permissible Concentration Hours "
* Philadelphia Electric Co 83/05/16 5pp 18482 034 24X
Fiche 50-000,83/05/16,8305180414

8305200615 Forwards FSAR page changes & draft responses prepared per Procedures & Test Review Branch draft SER open items
Responses & FSAR page changes will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/18 SCHWENCER,A Licensing Branch 2 26pp 18520 095 24X Fiche 50-352,83/05/18,8305200615

8305310009 Forwards draft responses to personnel qualification SER Items 1-3, mgt technology Items 1 & 2 & draft rev to FSAR Section 13 2 2 1 7 re performance review program Changes will be incorporated into June 1983 FSAR rev
BRADLEY,E J Philadelphia Electric Co 83/05/25 SCHWENCER,A Licensing Branch 2 20pp 18653 243 24X Fiche 50-352,83/05/25,8305310009

8305310045 Forwards draft responses to Core Performance Branch draft SER Items 1 through 4 & 6 through 11 FSAR Chapters 4,5,6 & 15 will be revised to incorporate latest approved revs to GESTAR II in June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/25 SCHWENCER,A Licensing Branch 2 16pp 18653 288 24X Fiche 50-352,83/05/25,8305310045

F. Security, medical, emergency & fire protection plans

8304290013 Forwards draft fire protection section of SER based on review of util 830128 submittal of fire protection program through Amend 45 of OL application Thirty-four open items require resolution.
SCHWENCER,A Licensing Branch 2 83/04/19, BAUER,E G Philadelphia Electric Co 31pp 18266 053 24X
Fiche:50-352,83/04/19,8304290013

8305110072 Notification of 830518-19 meetings w/util in Bethesda,MD to discuss fire protection issues
MARTIN,R E Licensing Branch 2, 83/05/05 SCHWENCER,A Licensing Branch 2 3pp 18419 360 24X Fiche 50-352,83/05/05,8305110072

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11, Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche:50-000,83/05/11,8305110034

8305180451 Forwards draft responses to SER open items re draft fire protection section,per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A Licensing Branch 2 67pp 18486 201 24X Fiche 50-352,83/05/13,8305180451.

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J. Office of the Executive Director for Operations, 83/05/13 PALLADINO,N.J. Commissioners 5pp 18593 322 24X
Fiche:50-000,83/05/13,8305240213

8305250133 Forwards Amend 50 to OL application,substituting revised version of physical security plan Rev withheld (ref 10CFR2 790).
BRADLEY,E J Philadelphia Electric Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18584 065. 24X Fiche:50-352,83/05/20,8305250133

--8305250135 Amend 50 to OL application,substituting revised version of physical security plan.W/Certificate of Svc
KEUPER,J.S. Philadelphia Electric Co 83/05/20 7pp 18584.068. 24X Fiche 50-352,83/05/20,8305250133

G Adjudicatory correspondence

8305020441 Answer opposing Limerick Ecology Action,F Romano & M Lewis further particularization of conditionally admitted contentions Neither specificity nor bases provided for contentions Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn 83/04/27 Atomic Safety and Licensing Board Panel 48pp 18283 092 24X Fiche 50-352,83/04/27,8305020441

8305040470 New info contention re inadequate util mgt Repeated carelessness,malfunctioning safety-related equipment & util response adversely reflect on mgt capability
ROMANO,F R Air and Water Pollution Patrol 83/04/27 Commissioners 1p 18322 236 24X Fiche 50-352,83/04/27, 8305040470

8305020405 Notice of ASLAB reconstitution CN Kohl,chairman & OJ Edles & RL Gotchy,members
TOMPKINS,G A Atomic Safety and Licensing Appeal Panel 83/04/28 1p 18273 066 24X Fiche 50-352,83/04/28,8305020405

8305030563 Forwards joint repts on status of emergency planning reviews & schedule re onsite & offsite emergency planning contentions,status of discovery & suggested items for discussion at 830509 prehearing conference
WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co 83/04/29 BRENNER,L , MORRIS,P A , COLE,R F Atomic Safety and Licensing Board Panel 7pp 18306 118 24X
Fiche 50-352,83/04/29,8305030563

8305030550 Memorandum & order ALAB-726,reversing ASLB 830427 Decision LBP-83-25 & remanding Del-Aware 830308 request for late-filed Contention V-26 to ASLB for disposition on merits
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 83/05/02 Atomic Safety and Licensing Board Panel 7pp 18306 140 24X
Fiche 50-352,83/05/02,8305030550

8305060478 Provides update of status of conditionally admitted non-PRA contentions
WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co 83/05/03 BRENNER,L , COLE,R F , COLE,R F Atomic Safety and Licensing Board Panel 7pp 18348 238 24X
Fiche 50-352,83/05/03,8305060478

8305060339 Response to Limerick Ecology Action/Air & Water Pollution Patrol spec of conditionally admitted contentions
Contentions I-8,I-15 & I-30 admissible PRA contentions should be denied Certificate of Svc encl
HODGDON,A P Hearing Branch 2 83/05/04 Atomic Safety and Licensing Board Panel 23pp 18344 085 24X Fiche 50-352,83/05/04, 8305060339

8305090478 Advises of change of address Svc list should be amended accordingly
ELLIOTT,C W Brose & Poswistillo 83/05/06 NRC - No Detailed Affiliation Given 1p 18360 235 24X Fiche 50-352,83/05/06, 8305090478

8305120278 Forwards status rept on draft emergency plan preparation
AU,T Y Pennsylvania, Commonwealth of, 83/05/09 BRENNER,L , COLE,R F , MORRIS,P A Atomic Safety and Licensing Board Panel 1p 18427 257 24X Fiche 50-352,83/05/09,8305120278

--8305120280 Status rept re preparation of draft emergency plans Certificate of Svc encl
AU,T.Y Pennsylvania, Commonwealth of, 83/05/09 4pp 18427 258 24X Fiche 50-352,83/05/09,8305120278

8305120296 Forwards JI Ruttenberg notice of appearance & AJ Nogee notice of withdrawal of appearance Certificate of Svc encl
RUTTENBERG,J I Keystone Alliance 83/05/09 BRENNER,L , MORRIS,P A , COLE,R F Atomic Safety and Licensing Board Panel 5pp 18430 171 24X Fiche 50-352,83/05/09,8305120296

8305160174 Notice of appearance in proceeding Certificate of Svc encl
BUSH,M.W Philadelphia, PA 83/05/09 5pp 18446 068 24X
Fiche 50-352,83/05/09,8305160174

8305160177 Notice of appearance in proceeding
LEWIS,K S Philadelphia, PA 83/05/09 2pp 18444 034 24X
Fiche 50-352,83/05/09,8305160177.

8305170533 Response to ASLB 830321 order advising that Commonwealth of PA,Ofc of Consumer Advocate intends to participate in proceeding
WERBAN,D Pennsylvania, Commonwealth of, 83/05/10 BRENNER,L Atomic Safety and Licensing Board Panel 1p 18467 355 24X
Fiche 50-352,83/05/10,8305170533

8305170538 Order directing util,NRC & Air & Water Pollution Patrol to jointly supply ASLB w/IE Insp Rept 50-353/76-06,notice of violation,util response & other documents re scope of reexam of welds by particular inspector
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/13
Philadelphia Electric Co 3pp 18469 025 24X
Fiche 50-352,83/05/13,8305170538

8305180136 Memorandum & order confirming schedules established at 830509-11 special prehearing conference NRC ordered to rept on FEMA schedule for reviewing plans & NRC schedule for issuing SER,first SER suppl,PRA,DES & FES
BRENNER,L Atomic Safety and Licensing Board Panel 83/05/16
10pp 18490 012 24X Fiche 50-352,83/05/16,8305180136

8305240516 First set of interrogatories on pressurized thermal shock contention Certificate of Svc encl Related correspondence
LEWIS,M I Lewis, M 83/05/19 Office of the Executive Legal Director 1p 18571 175 24X Fiche 50-352,83/05/19,8305240516

8305260181 Forwards IE Insp Rept 50-353/76-06,notice of violation & util response,per ASLB 830513 order re QA documents Comments on insp repts,notices of violation & interrogatories received on 830518 W/o encl
ROMANO,F R Air and Water Pollution Patrol 83/05/19 BRENNER,L
Atomic Safety and Licensing Board Panel 1p 18599 261 24X
Fiche 50-352,83/05/19,8305260181

8305230239 Advises that FEMA is discussing time needed to review Pennsylvania Emergency Mgt Agency emergency plan w/FEMA regional ofc NRC schedules for issuance of SER,SER suppl, PRA,DES & FES unchanged
VOGLER,B H Hearing Branch 2 83/05/20 BRENNER,L , MORRIS,P A ,
COLE,R F Atomic Safety and Licensing Board Panel 2pp 18539:004
24X Fiche 50-352,83/05/20,8305230239

8305240489 Forwards,in response to ASLB 830513 order for QA documents, IE Insp Rept 50-353/76-06 & related documents
WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co 83/05/20 BRENNER,L , MORRIS,P A , COLE,R.F Atomic Safety and Licensing Board Panel 87pp 18572 166 24X
Fiche 50-352,83/05/20,8305240489

8305260322 Response to ASLB 830516 scheduling order Addl statement re NRC use of PRA & rept on NUREG-0737,Item II K 3 18 encl Schedules for NRC issuance of documents discussed at second special prehearing conference valid W/Certificate of Svc
HODGDON,A P Hearing Branch 2 83/05/24 9pp 18625 019. 24X
Fiche 50-352,83/05/24,8305260322

--8305260327 Forwards evaluation of BWR Owners Group generic response to NUREG-0737,Item II K 3 18, "Mod of Automatic Depressurization Sys Logic - Feasibility for Increased Diversity of Some Event Sequences " Response requested
SCHWENCER,A Licensing Branch 2 83/05/23 BAUER,E G
Philadelphia Electric Co 9pp 18625 028 24X
Fiche 50-352,83/05/24,8305260322

--8304140161 Forwards safety evaluation of mods proposed by BWR Owners Group re NUREG-0737,Item II K 3 18, "Mod of ADS Logic " Two options proposed acceptable W/o encl
HOUSTON,R W Assistant Director for Reactor Safety 83/04/01
LAINAS,G C Assistant Director for Safety Assessment 2pp
18625 037 24X Fiche 50-352,83/05/24,8305260322

8305310013 Supplemental motion to reopen &/or to admit new Contentions V-27 & V-28 re feasibility of providing water to plant by startup Certificate of Svc encl
SUGARMAN,R J Del-Aware Unlimited, Inc SUGARMAN,R J Sugarman, R J 83/05/24 Atomic Safety and Licensing Board Panel 17pp
18653 263 24X Fiche 50-352,83/05/24,8305310013

H General correspondence

8305240316 Requests MW Bush & K Lewis be added to OL proceeding svc list for City of Philadelphia Svc will replace former managing director,W Goode
BUSH,M W Philadelphia, PA 83/05/19 BRENNER,L , COLE,R F ,
MORRIS,P A Atomic Safety and Licensing Board Panel, 4pp
18548 197 24X Fiche 50-352,83/05/19,8305240316

K Utility Final Safety Analysis Report (FSAR) & amends

8301310260 Forwards Rev 16 to FSAR
BRADLEY,E J Philadelphia Electric Co 83/01/28 DENTON,H R,
Office of Nuclear Reactor Regulation, Director. 2pp 16967 246
24X Fiche 50-352,83/01/28,8301310260

--8301310274 Rev 16 to Limerick Generating Station,Units 1 & 2 FSAR
* Philadelphia Electric Co 83/01/31 442pp. 16967-333 24X
Fiche 50-352,83/01/28,8301310260

8305160117 Rev 19 to FSAR
* Philadelphia Electric Co 83/04/30 626pp 18448 187 24X
Fiche 50-352,83/04/30,8305160117

8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept,per DG Eisenhut B10706 ltr
BRADLEY,E J Philadelphia Electric Co 83/05/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 18500 027
24X Fiche 50-352,83/05/13,8305190359

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp. 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305050202 Informs that changes to Rosemount transmitters will be completed by 840701 for Unit 1 & prior to fuel load for Unit 2 Info completes response to IE Bulletin 80-16
KEMPER,J S Philadelphia Electric Co 83/04/25 HAYNES,R C
Region 1, Office of Director 3pp 18341 078 24X
Fiche 50-352,83/04/25,8305050202

8305060057 Notification of significant licensee 830502 meeting in Philadelphia,PA to discuss results of SALP
TRIPP,L E Region 1, Office of Director 83/04/27 Division of Project & Resident Programs. 1p 18354 362 24X
Fiche 50-352,83/04/27,8305060057

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Stndby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240489 Forwards, in response to ASLB 830513 order for QA documents, IE Insp Rept 50-353/76-06 & related documents
WETTERHAHN,M J Conner & Wetterhahn WETTERHAHN,M J Philadelphia Electric Co 83/05/20 BRENNER,L , MORRIS,P A , COLE,R F Atomic Safety and Licensing Board Panel 87pp 18572 166 24X Fiche,50-352,83/05/20,8305240489

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

T Hearing transcripts on non-antitrust matters

8305160035 Transcript of 830509 prehearing conference in Philadelphia, PA Pp 4,039-4,167
* Atomic Safety and Licensing Board Panel 83/05/09 132pp 18456 094 24X Fiche 50-352,83/05/09,8305160035

8305160173 Transcript of 830510 hearing in Philadelphia,PA Pp 4,168-4,395
* Atomic Safety and Licensing Board Panel 83/05/10 228pp 18445 180 24X Fiche 50-352,83/05/10,8305160173

8305160016 Transcript of 830511 prehearing conference in Philadelphia,PA Pp 4,396-4,529
* Atomic Safety and Licensing Board Panel 83/05/11 135pp 18453 165 24X Fiche 50-352,83/05/11,8305160016

DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

A. Application/construction stage documents & correspondence

8305060507 Responds to concerns expressed in Encl 1 to NRC 820812 ltr re dynamic qualification of safety-related equipment for seismic & hydrodynamic loads Qualification program revs will be completed by Fourth Quarter 1983
KEMPER,J S Philadelphia Electric Co 83/03/31 SCHWENCER,A
Licensing Branch 2 7pp 18351 147 24X Fiche 50-352,83/03/31,8305060507

8305040527 Forwards request for addl info needed for review of auxiliary sys issues
SCHWENCER,A. Licensing Branch 2 83/04/22 BAUER,E Q
Philadelphia Electric Co 4pp 18351 227 24X
Fiche 50-352,83/04/22,8305040527

8305060529 Forwards "Environ Assessment Rept & Findings,Point Pleasant Water Supply Project," per NRC request
WESTON,R T Pennsylvania, Commonwealth of, 83/04/26 LEHR,J C
Environmental & Hydrologic Engineering Branch 1p 18347 309 24X
Fiche 50-352,83/04/26,8305060529

--8305060536 "Environ Assessment Rept & Findings,Point Pleasant Water Supply Project "
HIDDENDORF,W B , WESTON,R T , DUNCAN,P S Pennsylvania, Commonwealth of,. 82/08/31 118pp 18347 310 24X
Fiche 50-352,83/04/26,8305060529

8305020335 Responds to 820405 request for addl info re control rod drive sys hydrodynamic loads Loads caused by operation of scram valves incorporated into sys support design
KEMPER,J S Philadelphia Electric Co. 83/04/29 SCHWENCER,A
Licensing Branch 2 5pp 18277 135 24X Fiche 50-352,83/04/29,8305020335

8305030299 Forwards application for Amend 48 to OL application,revising FSAR & design assessment rept
BRADLEY,E J. Philadelphia Electric Co 83/04/29 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp. 18297 147 24X Fiche 50-352,83/04/29,8305030299

8305030307 Application for Amend 48 to OL application,revising FSAR & design assessment rept Certificate of Svc encl
BAUER,E Q , BRADLEY,E J Philadelphia Electric Co 83/04/29
7pp 18297 150. 24X Fiche 50-352,83/04/29,8305030299

8305060457 Forwards draft responses to NUREG-0737,Items I C 1,I C 6, I D 1.1 D 2,I G 1 & III A 1 2 Responses will be incorporated into FSAR by June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/04 SCHWENCER,A
Licensing Branch 2 9pp 18351 160 24X Fiche 50-352,83/05/04,8305060457

8305100275 Forwards Rev 0 to "Study Calculation for E-Sys Clamp on Elbows "
KEMPER,J S Philadelphia Electric Co. 83/05/04 PURPLE,R A
Division of Licensing 2pp 18370 175 24X Fiche 50-352,83/05/04,8305100275

--8305100281 Rev 0 to "Study Calculation for E-Sys Clamp on Elbows " One oversize drawing encl Aperture card available in PDR
HU,C K , HUANG,A Y , KHLAFALLAH,M Z Bechtel Corp SR 6031-5910 R00 83/04/18 76pp 18370 177 24X Fiche 50-352,83/05/04,8305100275

8305110079 Summary of 830322-24 meetings w/util,Bechtel & GE in San Jose,CA re applicant response to NRC requests for addl info re mechanical engineering review
MARTIN,R E Licensing Branch 2 83/05/05 Licensing Branch 2
16pp 18419 337 24X Fiche 50-352,83/05/05,8305110079

8305190012 Notification of 830517 & 18 meetings w/util in Bethesda,MD to discuss resolution of remaining outstanding issues
MARTIN,R E Licensing Branch 2 83/05/06 SCHWENCER,A Licensing Branch 2 4pp 18523 209 24X Fiche 50-352,83/05/06,8305190012

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130026 Notification of 830511 meeting w/util in Bethesda,MD to discuss requirements for resolution of geotechnical issues identified in NRC 830311 ltr
MARTIN,R E Licensing Branch 2 83/05/09 SCHWENCER,A Licensing Branch 2 4pp 18457 175 24X Fiche 50-352,83/05/09,8305130026

8305130096 Forwards draft responses to Auxiliary Sys Branch Questions 410 00 - 410 104 Info discusses Rev 14 to FSAR re detection of leakage through spent fuel pool liner & continuous occupational exposure during normal operations
BRADLEY,E J Philadelphia Electric Co 83/05/09 SCHWENCER,A
Licensing Branch 2 12pp 18438 045 24X Fiche 50-353,83/05/09,8305130096

8305120320 Forwards draft proposed changes in response to 830407 discussions re Items 1,3a,3b,4,7,8,10-13,15-16 & 18 Draft changes will be incorporated into FSAR rev scheduled for June 1983 & into design assessment rept
BRADLEY,E J Philadelphia Electric Co 83/05/10 SCHWENCER,A
Licensing Branch 2 138pp 18431 170 24X Fiche 50-352,83/05/10,8305120320

8305200170 Notification of cancellation of 830511 meeting w/util in Bethesda,MD to discuss requirements for resolution of geotechnical issues
MARTIN,R E Licensing Branch 2 83/05/10 SCHWENCER,A Licensing Branch 2 4pp 18540 235 24X Fiche 50-352,83/05/10,8305200170

8305170187 Forwards draft responses & FSAR page changes re Instrumentation & Control Sys Branch Requests for Addl Info 421 5,421 6,421 7,421 16,421 30 & 421 50 in NRC 820825 ltr W/seven oversize drawings Aperture cards in PDR
BRADLEY,E J Philadelphia Electric Co 83/05/12 SCHWENCER,A
Licensing Branch 2 150pp 18463 017 24X Fiche 50-352,83/05/12,8305170187

8305180343 Forwards draft responses & FSAR page changes in response to Mechanical Engineering Branch 830411 request for addl info re non-straight main steam line & independent design verification program
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 42pp 18485,171 24X Fiche 50-352,83/05/13,8305180343

8305180402 Forwards draft change to FSAR Section 9 2 6 4 2 2 re spray pond natural evaporation per 830420 telcon Change to be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 3pp 18486 009 24X Fiche 50-352,83/05/13,8305180402

8305180419 Forwards draft revs to responses to Questions 430 68,430 72, 430 73 & 430 114 re diesel generator auxiliary sys Changes will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 21pp 18485 332 24X Fiche 50-352,83/05/13, 8305180419

8305180432 Forwards draft responses to Radiological Assessment Branch request for addl info & draft FSAR changes resulting from 830428 telcon w/NRC Schedule for formally incorporating changes into future FSAR revs noted
BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER,A
Licensing Branch 2 55pp 18486 126 24X Fiche 50-352,83/05/16, 8305180432

8305230496 Forwards draft revs to QA Branch Questions 260 1 through 260 55 & related FSAR changes per 830329 meeting Info will be incorporated into FSAR in June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/19 SCHWENCER,A
Licensing Branch 2 315pp 18535 358 24X Fiche 50-352,83/05/19, 8305230496

8305250133 Forwards Amend 50 to OL application,substituting revised version of physical security plan Rev withheld (ref 10CFR2 790)
BRADLEY,E J Philadelphia Electric Co 83/05/20 DENTON,H R
Office of Nuclear Reactor Regulation, Director 3pp 18584 065
24X Fiche 50-352,83/05/20,8305250133

--8305250135 Amend 50 to OL application,substituting revised version of physical security plan W/Certificate of Svc
KEUPER,J S Philadelphia Electric Co 83/05/20 7pp 18584 068
24X Fiche 50-352,83/05/20,8305250133

8305270375 Forwards revised draft change to Hydrologic & Geotechnical Engineering Branch open item re FSAR Section 9 2 6 4 2 2 Change will be formally incorporated into FSAR rev in June 1983
BRADLEY,E J Philadelphia Electric Co. 83/05/25 SCHWENCER,A
Licensing Branch 2 3pp 18644 296 24X Fiche 50-352,83/05/25, 8305270375

C Utility Environmental Report (ER), amends & correspondence

8305160001 Rev 12 to environ rept - OL stage One oversize drawing encl. Aperture card available in PDR
* Philadelphia Electric Co 83/04/30 72pp 18448 030 24X
Fiche 50-352,83/04/30,8305160001

8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept,per DG Eisenhut 810706 ltr
BRADLEY,E J Philadelphia Electric Co 83/05/13 DENTON,H R
Office of Nuclear Reactor Regulation, Director 5pp 18500 027
24X Fiche 50-352,83/05/13,8305190359

E NRC Safety Evaluation Report (SER), suppls & correspondence

8304290013 Forwards draft fire protection section of SER based on review of util 830128 submittal of fire protection program through Amend 45 of OL application Thirty-four open items require resolution
SCHWENCER,A Licensing Branch 2 83/04/19 BAUER,E G
Philadelphia Electric Co 31pp 18266-053 24X
Fiche 50-352,83/04/19,8304290013

8305020255 Forwards draft responses to Questions 440 3,440 4,440 5 & 440 32 Responses also address Item 1 of draft SER Series 440 Reactor Sys Branch, "ODYN Analysis of Pressurization Transients" & Item 3 of 820716 ltr re SER Section 4 4
BRADLEY,E J Philadelphia Electric Co 83/04/27 SCHWENCER,A
Licensing Branch 2. 15pp 18277 080 24X Fiche.50-352,83/04/27, 8305020255

8305020454 Forwards draft responses to Reactor Sys Branch draft SER re TMI Items II K 3 13,II.K 3 15,II K 3 16,II K 3 18,II K 3 21, II K 3 22,II K 3 24,II K 3 25,II K 3 30,II K 3 31 & II K.3.45 Response will be Incorporated into FSAR revs
BRADLEY,E J Philadelphia Electric Co 83/04/27 SCHWENCER,A
Licensing Branch 2 13pp 18283 287 24X Fiche 50-352,83/04/27, 8305020454

8305170228 Forwards draft responses to Reactor Sys Branch draft SER, Items 4 & 5 re TMI Action Items II K 1 5 & II.K 1.10 Responses will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E.J Philadelphia Electric Co 83/05/11. SCHWENCER,A
Licensing Branch 2 4pp 18466 342 24X Fiche 50-352,83/05/11, 8305170228

8305180389 Forwards draft FSAR page changes re open items for Chemical Technology Section draft SER re reactor coolant & suppression pool & secondary containment atmosphere Changes to be incorporated into Rev 20 to FSAR in May 1983
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 10pp 18486 347 24X Fiche 50-352,83/05/13, 8305180389

8305180451 Forwards draft responses to SER open items re draft fire protection section,per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 67pp 18486 201 24X Fiche 50-352,83/05/13, 8305180451

8305180414 Forwards Peach Bottom procedures supplementing util 830316 response to Item 5 of Radiological Assessment Branch draft SER Similar or improved procedures will be developed for Limerick.
BRADLEY,E J Philadelphia Electric Co 83/05/16 SCHWENCER,A
Licensing Branch 2 2pp 18482 007 24X Fiche:50-000,83/05/16, 8305180414

8305200615 Forwards FSAR page changes & draft responses prepared per Procedures & Test Review Branch draft SER open items. Responses & FSAR page changes will be formally incorporated into FSAR rev scheduled for June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/18 SCHWENCER,A
Licensing Branch 2 26pp 18520 095 24X Fiche 50-352,83/05/18, 8305200615

8305310009 Forwards draft responses to personnel qualification SER Items 1-3, mgt technology Items 1 & 2 & draft rev to FSAR Section 13 2 2 1 7 re performance review program Changes will be incorporated into June 1983 FSAR rev
BRADLEY,E J Philadelphia Electric Co 83/05/25. SCHWENCER,A
Licensing Branch 2 20pp 18653 243 24X Fiche:50-352,83/05/25, 8305310009.

8305310045 Forwards draft responses to Core Performance Branch draft SER Items 1 through 4 & 6 through 11 FSAR Chapters 4,5,6 & 15 will be revised to incorporate latest approved revs to GESTAR II in June 1983.
BRADLEY,E J Philadelphia Electric Co 83/05/25. SCHWENCER,A
Licensing Branch 2. 16pp 18653 298. 24X Fiche. 50-352,83/05/25, 8305310045

F. Security, medical, emergency & fire protection plans

8305110072 Notification of 830518-19 meetings w/util in Bethesda,MD to discuss fire protection issues
MARTIN,R E Licensing Branch 2 83/05/05 SCHWENCER,A. Licensing Branch 2 3pp 18419 360 24X Fiche.50-352,83/05/05,8305110072

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305180451 Forwards draft responses to SER open items re draft fire protection section,per 830419 ltr Final responses & related page changes will be submitted subsequent to 830518 & 19 meetings
BRADLEY,E J Philadelphia Electric Co 83/05/13 SCHWENCER,A
Licensing Branch 2 67pp 18486 201 24X Fiche.50-352,83/05/13, 8305180451

8305250133 Forwards Amend 50 to OL application,substituting revised version of physical security plan Rev withheld (ref 10CFR2 790)
BRADLEY,E J Philadelphia Electric Co. 83/05/20 DENTON,H.R
Office of Nuclear Reactor Regulation, Director. 3pp. 18584-065
24X Fiche 50-352,83/05/20,8305250133

--8305250135 Amend 50 to OL application,substituting revised version of physical security plan W/Certificate of Svc
KEUPER,J S Philadelphia Electric Co. 83/05/20 7pp 18584 068
24X Fiche 50-352,83/05/20,8305250133

O Adjudicatory correspondence

8305020441 Answer opposing Limerick Ecology Action,F Romano & M Lewis further particularization of conditionally admitted contentions Neither specificity nor bases provided for contentions Certificate of Svc encl
WETTERHAHN,M J Philadelphia Electric Co WETTERHAHN,M.J Conner & Wetterhahn 83/04/27 Atomic Safety and Licensing Board Panel. 40pp 18283.092. 24X Fiche 50-352,83/04/27,8305020441

8305040470 New info contention re inadequate util mgt Repeated carelessness, malfunctioning safety-related equipment & util response adversely reflect on mgt capability
ROMANO, F R Air and Water Pollution Patrol 83/04/27
Commissioners 1p 18322 236 24X Fiche 50-352, 83/04/27, 8305040470

8305020405 Notice of ASLAB reconstitution CN Kohl, chairman & OJ Edles & RL Gotchy, members
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/04/28
1p 18273 066 24X Fiche 50-352, 83/04/28, 8305020405

8305030563 Forwards joint repts on status of emergency planning reviews & schedule re onsite & offsite emergency planning contentions, status of discovery & suggested items for discussion at 830509 prehearing conference
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/04/29 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 7pp 18306 118 24X
Fiche: 50-352, 83/04/29, 8305030563

8305030550 Memorandum & order ALAB-726, reversing ASLB 830427 Decision LBP-83-25 & remanding Del-Aware 830308 request for late-filed Contention V-26 to ASLB for disposition on merits.
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/05/02
Atomic Safety and Licensing Board Panel 7pp 18306 140 24X
Fiche 50-352, 83/05/02, 8305030550

8305060478 Provides update of status of conditionally admitted non-PRA contentions
WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co 83/05/03 BRENNER, L , COLE, R F , COLE, R F Atomic Safety and Licensing Board Panel 7pp 18348 238 24X
Fiche 50-352, 83/05/03, 8305060478

8305060339 Response to Limerick Ecology Action/Air & Water Pollution Patrol spec of conditionally admitted contentions Contentions I-8, I-15 & I-30 admissible PRA contentions should be denied Certificate of Svc encl
HODGDON, A P Hearing Branch 2 83/05/04 Atomic Safety and Licensing Board Panel 23pp 18344 085 24X Fiche 50-352, 83/05/04, 8305060339

8305090478 Advises of change of address Svc list should be amended accordingly
ELLIOTT, C. W Brose & Poswistillo 83/05/06 NRC - No Detailed Affiliation Given 1p 18360 235 24X Fiche 50-352, 83/05/06, 8305090478

8305120278 Forwards status rept on draft emergency plan preparation
AU, T Y Pennsylvania, Commonwealth of, 83/05/09 BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 1p 18427 257. 24X Fiche. 50-352, 83/05/09, 8305120278

--8305120280 Status rept re preparation of draft emergency plans Certificate of Svc encl
AU, T Y Pennsylvania, Commonwealth of, 83/05/09 4pp. 18427 258 24X Fiche 50-352, 83/05/09, 8305120278

8305120296 Forwards JI Ruttenberg notice of appearance & AJ Nogee notice of withdrawal of appearance Certificate of Svc encl
RUTTENBERG, J I Keystone Alliance 83/05/09 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 3pp 18430 171 24X Fiche 50-352, 83/05/09, 8305120296

8305160174 Notice of appearance in proceeding Certificate of Svc encl
BUSH, M W Philadelphia, PA 83/05/09 5pp 18446 068 24X
Fiche. 50-352, 83/05/09, 8305160174

8305160177 Notice of appearance in proceeding
LEWIS, K S Philadelphia, PA 83/05/09 2pp 18444 034 24X
Fiche 50-352, 83/05/09, 8305160177.

8305170533 Response to ASLB 830321 order advising that Commonwealth of PA, Ofc of Consumer Advocate intends to participate in proceeding
WERSAN, D. Pennsylvania, Commonwealth of, 83/05/10 BRENNER, L
Atomic Safety and Licensing Board Panel 1p 18467 355 24X
Fiche 50-352, 83/05/10, 8305170533

8305170538 Order directing util, NRC & Air & Water Pollution Patrol to jointly supply ASLB w/IE Insp Rept 50-353/76-06, notice of violation, util response & other documents re scope of reexam of welds by particular inspector
BRENNER, L. Atomic Safety and Licensing Board Panel, 83/05/13
Philadelphia Electric Co 3pp 18469 025 24X
Fiche: 50-352, 83/05/13, 8305170538

8305180136 Memorandum & order confirming schedules established at 830509-11 special prehearing conference NRC ordered to rept on FEMA schedule for reviewing plans & NRC schedule for issuing SER, first SER suppl, PRA, DES & FES
BRENNER, L Atomic Safety and Licensing Board Panel 83/05/16
10pp 18490 012 24X Fiche 50-352, 83/05/16, 8305180136

8305240516 First set of interrogatories on pressurized thermal shock contention Certificate of Svc encl Related correspondence
LEWIS, M I Lewis, M 83/05/19 Office of the Executive Legal Director 1p 18571 175 24X Fiche 50-352, 83/05/19, 8305240516

8305260181 Forwards IE Insp Rept 50-353/76-06, notice of violation & util response, per ASLB 830513 order re QA documents Comments on insp repts, notices of violation & interrogatories received on 830518 W/o encl
ROMANO, F R Air and Water Pollution Patrol 83/05/19 BRENNER, L
Atomic Safety and Licensing Board Panel 1p 18599 261 24X
Fiche 50-352, 83/05/19, 8305260181

8305230239 Advises that FEMA is discussing time needed to review Pennsylvania Emergency Mgt Agency emergency plan w/FEMA regional ofc NRC schedules for issuance of SER, SER suppl, PRA, DES & FES unchanged
VOGLER, B H Hearing Branch 2 83/05/20 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 18539 004
24X Fiche 50-352, 83/05/20, 8305230239

8305240489 Forwards, in response to ASLB 830513 order for QA documents, IE Insp Rept 50-353/76-06 & related documents
WETTERHAHN, M J Conner & Wetterhahn, WETTERHAHN, M J Philadelphia Electric Co 83/05/20 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 87pp 18572 166 24X
Fiche 50-352, 83/05/20, 8305240489

8305260322 Response to ASLB 830516 scheduling order Addl statement re NRC use of PRA & rept on NUREG-0737, Item II K 3 18 encl Schedules for NRC issuance of documents discussed at second special prehearing conference valid W/Certificate of Svc
HODGDON, A P Hearing Branch 2 83/05/24 9pp 18625 019 24X
Fiche 50-352, 83/05/24, 8305260322

--8305260327 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic - Feasibility for Increased Diversity of Some Event Sequences " Response requested
SCHWENCER, A Licensing Branch 2 83/05/23 BAUER, E G
Philadelphia Electric Co 9pp 18625 028 24X
Fiche 50-352, 83/05/24, 8305260322

--8304140161 Forwards safety evaluation of mods proposed by BWR Owners Group re NUREG-0737, Item II K 3 18, "Mod of ADS Logic " Two options proposed acceptable W/o encl
HOUSTON, R W Assistant Director for Reactor Safety 83/04/01
LAINAS, G C Assistant Director for Safety Assessment 2pp
18625 037 24X Fiche 50-352, 83/05/24, 8305260322

8305310013 Supplemental motion to reopen &/or to admit new Contentions V-27 & V-28 re feasibility of providing water to plant by startup Certificate of Svc encl
SUGARMAN, R J Del-Aware Unlimited, Inc SUGARMAN, R J Sugarman, R J. 83/05/24 Atomic Safety and Licensing Board Panel 17pp
18653 263 24X Fiche 50-352, 83/05/24, 8305310013

H General correspondence

8305240316 Requests MW Bush & K Lewis be added to OL proceeding svc list for City of Philadelphia Svc will replace former managing director, W Goode
BUSH, M W Philadelphia, PA 83/05/19 BRENNER, L , COLE, R F , MORRIS, P A Atomic Safety and Licensing Board Panel 4pp
18548 197 24X Fiche 50-352, 83/05/19, 8305240316

K Utility Final Safety Analysis Report (FSAR) & amends

8301310260 Forwards Rev 16 to FSAR
BRADLEY, E J Philadelphia Electric Co 83/01/28 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 16967 246
24X Fiche, 50-352, 83/01/28, 8301310260

--8301310274 Rev 16 to Limerick Generating Station, Units 1 & 2 FSAR.
* Philadelphia Electric Co 83/01/31 442pp 16967 333 24X
Fiche 50-352, 83/01/28, 8301310260

8305160117 Rev 19 to FSAR
* Philadelphia Electric Co 83/04/30 626pp 18448 187 24X
Fiche, 50-352, 83/04/30, 8305160117

8305190359 Forwards Affidavit of Svc re distribution of Rev 19 to FSAR & Rev 12 to environ rept, per DG Eisenhut 810706 ltr
BRADLEY, E J Philadelphia Electric Co 83/05/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 5pp 18500 027
24X Fiche 50-352, 83/05/13, 8305190359

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305050202 Informs that changes to Rosemount transmitters will be completed by 840701 for Unit 1 & prior to fuel load for Unit 2 Info completes response to IE Bulletin 80-16
KEMPER, J S Philadelphia Electric Co 83/04/25 HAYNES, R C
Region 1, Office of Director 3pp 18341 078 24X
Fiche, 50-352, 83/04/25, 8305050202

8305060057 Notification of significant licensee 830502 meeting in Philadelphia, PA to discuss results of SALP
TRIPP, L E Region 1, Office of Director 83/04/27 Division of
Project & Resident Programs 1p 18354 362 24X
Fiche 50-352, 83/04/27, 8305060057

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/03 Consolidated Edison Co of New York, Inc 122pp. 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 117pp 18441.001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche: 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305240489 Forwards, in response to ASLB 830513 order for QA documents, IE Insp Rept 50-353/76-06 & related documents
WETTERHAHN, M J Conner & Wetterhahn 83/05/20 BRENNER, L Atomic
Safety and Licensing Board Panel 87pp 18572 166 24X
Fiche 50-352, 83/05/20, 8305240489

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

T Hearing transcripts on non-antitrust matters

8305160035 Transcript of 830509 prehearing conference in Philadelphia, PA Pp 4,039-4,167
* Atomic Safety and Licensing Board Panel 83/05/09, 132pp,
18456 094 24X Fiche 50-352, 83/05/09, 8305160035

8305160173 Transcript of 830510 hearing in Philadelphia, PA
Pp 4,168-4,395
* Atomic Safety and Licensing Board Panel 83/05/10 228pp
18445 180 24X Fiche 50-352, 83/05/10, 8305160173

8305160016 Transcript of 830511 prehearing conference in Philadelphia, PA Pp 4,396-4,529
* Atomic Safety and Licensing Board Panel 83/05/11 135pp
18453 165 24X Fiche 50-352, 83/05/11, 8305160016

DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305130096 Forwards draft responses to Auxiliary Sys Branch Questions 410 00 - 410 104 Info discusses Rev 14 to FSAR re detection of leakage through spent fuel pool liner & continuous occupational exposure during normal operations.
BRADLEY, E J Philadelphia Electric Co 83/05/09 SCHWENCER, A
Licensing Branch 2 12pp 18438 045 24X Fiche 50-353, 83/05/09,
8305130096

O Adjudicatory correspondence

8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl.
CHILK, S J Office of the Secretary of the Commission 83/03/31
Commissioners 3pp 17807 049 24X Fiche 50-000, 83/03/31,
8304040470

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE, J C Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 196 24X Fiche 50-000, 83/05/05,
8305060250

8305130060 Response opposing intervenor motion for recusation. Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO, N J Commissioners 83/05/11 2pp 18436 228 24X
Fiche 50-000, 83/05/11, 8305130060

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/05/12
Commissioners 1p 18437 033 24X Fiche 50-000, 83/05/12,
8305130061

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK, S J Office of the Secretary of the Commission 83/05/19,
Commissioners 1p 18514 283 24X Fiche, 50-000, 83/05/19,
8305200560,

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl.
CHILK, S J Office of the Secretary of the Commission 83/05/27
14pp 18653 311 24X Fiche 50-000, 83/05/27, 8305310017

I Financial information

8305200067 Forwards Annual Financial Repts for 1982
FRYLING,R Public Service Electric & Gas Co of New Jersey
83/05/17 Office of Nuclear Reactor Regulation, Director 1p
18516,198 24X Fiche 50-000,83/05/17,8305200067

Q Inspection reports, IE Bulletins & correspondence

8305160083 Forwards IE Insp Rept 50-354/83-05 on 830301-0417 & notice of violation
STAROSTECKI,R Division of Project & Resident Programs 83/05/02
MARTIN,T J Public Service Electric & Gas Co of New Jersey 2pp
18451 007 24X Fiche 50-354,83/05/02,8305160083

--8305160087 Notice of violation from insp on 830301-0417
* Division of Project & Resident Programs 83/05/02 1p
18451 009 24X Fiche 50-354,83/05/02,8305160083

--8305160091 IE Insp Rept 50-354/83-05 on 830301-0417 Noncompliance noted failure of QC insp to identify HVAC ductwork support discrepancies
BATEMAN,W H , TRIPP,L E Region 1, Office of Director 83/04/26
14pp. 18451 010 24X Fiche 50-354,83/05/02,8305160083

8305170487 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/83-02
STAROSTECKI,R Division of Project & Resident Programs 83/05/11
MARTIN,T J Public Service Electric & Gas Co of New Jersey 1p
18469,358 24X Fiche 50-354,83/05/11,8305170487

--8305170490 Responds to NRC 830311 ltr re violations noted in IE Insp Rept 50-354/83-02 Corrective actions concrete placements in question covered w/moistened burlap Curing period extended addl 4 days
MARTIN,T J Public Service Electric & Gas Co of New Jersey
83/04/08 HAYNES,R C Region 1, Office of Director 2pp
18469 359. 24X Fiche 50-354,83/05/11,8305170487

R. Periodic operating reports & related correspondence

8305250387 "Monthly Status Completion Rept for Apr 1983 " Fuel load scheduled for Jan 1986 Const progress approx 67 85% complete at end of Apr 1983
LANDRIEU,P R H Public Service Electric & Gas Co of New Jersey
83/05/19 TRIPP,L E Region 1, Office of Director 1p 18585 351
24X Fiche 50-354,83/05/19,8305250387

S Reportable occurrences, LERs & related correspondence

8305030459 PNS-I-83-010 on 830427,Bechtel safety representative received telephone call that bomb located in reactor Search of reactor bldg conducted w/negative results Police notified No press release planned
MCKEOWN,L , KUSHNER,W , JOYNER,J Region 1, Office of Director
83/04/28 1p 18294 150 24X Fiche 50-354,83/04/28,8305030459

8305060470 Deficiency rept re scribed lines on small bore piping resulting in sharp discontinuities Initially reported on 830124 Repairs will involve replacing pipe,blending out scribe line or welding Completion expected by 830530
MARTIN,T J Public Service Electric & Gas Co of New Jersey
83/04/28 ALLAN,J M Region 1, Office of Director 3pp
18348 080 24X Fiche,50-354,83/04/28,8305060470

8305110255 Significant const deficiency rept re weld defects in Class IE cabinets. Initially reported on 830125.Bailey Controls Co reworked all affected cabinets.
MARTIN,T J. Public Service Electric & Gas Co of New Jersey
83/05/02 ALLAN,J M Region 1, Office of Director 2pp
18393.175. 24X Fiche 50-354,83/05/02,8305110255

8305120384 Interim significant const deficiency rept re mechanical shock arrest or brackets supplied by ITT Grinnell w/ potential interference problems Initially reported on 830413 Affected parts returned to ITT Grinnell for rework
MARTIN Public Service Electric & Gas Co of New Jersey 83/05/05
ALLAN,J M. Region 1, Office of Director 2pp. 18433 079. 24X
Fiche:50-354,83/05/05,8305120384

V Operator Examinations

8305310185 Informs that initial licensing exams will be given to 28 senior reactor operators & 20 reactor operator candidates in Nov 1983,per Generic Ltr 83-01 Instructor certification exams scheduled for Jul 1985 for eight candidates
MITTL,R L. Public Service Electric & Gas Co. of New Jersey
83/05/13 SCHWENCER,A. Licensing Branch 2 1p. 18658 150 24X
Fiche:50-354,83/05/13,8305310185.

DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2

Q Adjudicatory correspondence

8304040470 Order extending time until 830428 for Commission to act to review ALAB-701 Commissioner Ahearne dissenting views encl
CHILK,S J Office of the Secretary of the Commission 83/03/31
Commissioners 3pp 17807 049 24X Fiche 50-000,83/03/31,
8304040470

8305060250 Order extending time until 830513 for Commission to act to review ALAB-701
HOYLE,J C Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 196 24X Fiche 50-000,83/05/05,
8305060250

8305130060 Response opposing intervenor motion for recusation Motion does not specifically discuss reasons why prior activities may constitute conflict of interest
PALLADINO,N J Commissioners 83/05/11 2pp 18436 228 24X
Fiche 50-000,83/05/11,8305130060

8305130061 Order extending time until 830520 for Commission to act to review petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/12
Commissioners 1p 18437 033 24X Fiche 50-000,83/05/12,
8305130061

8305200560 Order extending time until 830527 for Commission to act to review intervenor 821227 petition for review of ALAB-701
CHILK,S J Office of the Secretary of the Commission 83/05/19
Commissioners 1p 18514 283 24X Fiche 50-000,83/05/19,
8305200560

8305310017 Memorandum & order to hold decision in ALAB-701 in abeyance until Commission completes review of U mill tailings pile requirements & of rulemakings to conform Commission requirements to EPA stds Separate J Ahearne statement encl
CHILK,S J Office of the Secretary of the Commission 83/05/27
14pp 18653 311 24X Fiche 50-000,83/05/27,8305310017

S Reportable occurrences, LERs & related correspondence

8305060470 Deficiency rept re scribed lines on small bore piping resulting in sharp discontinuities Initially reported on 830124.Repairs will involve replacing pipe,blending out scribe line or welding Completion expected by 830530
MARTIN,T J Public Service Electric & Gas Co of New Jersey
83/04/28 ALLAN,J M Region 1, Office of Director 3pp
18348 080 24X Fiche 50-354,83/04/28,8305060470

8305110255 Significant const deficiency rept re weld defects in Class IE cabinets Initially reported on 830125 Bailey Controls Co reworked all affected cabinets
MARTIN,T J Public Service Electric & Gas Co of New Jersey
83/05/02 ALLAN,J M Region 1, Office of Director 2pp
18393 175 24X Fiche 50-354,83/05/02,8305110255

8305120384 Interim significant const deficiency rept re mechanical shock arrest or brackets supplied by ITT Grinnell w/ potential interference problems Initially reported on 830413 Affected parts returned to ITT Grinnell for rework
MARTIN Public Service Electric & Gas Co of New Jersey. 83/05/05
ALLAN,J M Region 1, Office of Director 2pp 18433 079 24X
Fiche 50-354,83/05/05,8305120384

DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305190168 Forwards draft rev to organization (Criterion I) section of FSAR Chapter 17 1, "QA Program for Design & Const Phase " Draft reflects current commitments for remainder of ZPS-1 Guidance written per SRP,Rev 2
BORGMANN,E A Cincinnati Gas & Electric Co 82/10/15
KEPPLER,J G , HUNTER,D Region 3, Office of Director 16pp
18502 219 24X Fiche 50-358,82/10/15,8305190168

8305190190 Responds to 821228 ltr requesting supplemental info to 821126 ltr requesting approval for Bechtel to conduct independent review of plant mgt Assessment program includes issues covered in 821112 order to show cause
DICKHONER,W H Cincinnati Gas & Electric Co 83/01/03
KEPPLER,J G Region 3, Office of Director 67pp 18502 074 24X
Fiche 50-358,83/01/03,8305190190

8305090542 Partial response to FOIA request for transcript of Commission meetings discussing 821112 order & documents supporting NRC recommendations to Commission re issuance of order Forwards App B documents App A documents in PDR
FELTON, J M Division of Rules and Records 83/03/17 SAMP, R A Shaw, Pittman, Potts & Trowbridge 4pp 18365 136 24X Fiche 50-358, 83/03/17, 8305090542

--8305090545 Submits interim rept of Natl Board Notification ASME Code related const at facility, per State of OH, Div of Boiler Insp
MCDONALD, D G Ohio, State of 82/05/12 MILAN, D M Ohio, State of 76pp 18365 140 24X Fiche 50-358, 83/03/17, 8305090542

--8305090561 Submits Natl Board Audit Interim Rept 3 re ASME Code related const at facility, per State of OH Div of Boiler Insp Rept covers activities from 820807-0930
MCDONALD, D J , ALLISON, C W , SULLIVAN, M F Ohio, State of 82/09/30 MILAN, D M Ohio, State of 18pp 18365 361 24X Fiche 50-358, 83/03/17, 8305090542

8305260397 Addl response to FOIA request for transcripts of Commission 821028, 1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/03/28 SAMP, R A Shaw, Pittman, Potts & Trowbridge 4pp 18647 294 24X Fiche 50-358, 83/03/28, 8305260397

--8305260401 Forwards press release, witness list & J Keppler final testimony for 820914 hearing on status of NRC review of const activities at facility
KAMMERER, C Office of Congressional Affairs 82/09/13 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 1p 18647 298 24X Fiche 50-358, 83/03/28, 8305260397

8305190278 Amend 147 to application for OL, consisting of Rev 93 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 83/03/31 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 18501 157 24X Fiche 50-358, 83/03/31, 8305190278

--8305190281 Rev 93 to FSAR
* Cincinnati Gas & Electric Co 83/03/31 79pp 18501 159 24X Fiche 50-358, 83/03/31, 8305190278

8305020432 Responds to questions raised in NRC 830404 ltr re contacts w/Bechtel on Zimmer project List of Bechtel revenues to GA Technologies encl
NEYLAN, A J Torrey Pines Technology 83/04/05 DICKHONER, W H Cincinnati Gas & Electric Co 4pp 18281 218 24X Fiche 50-358, 83/04/05, 8305020432

8305020435 Requests ltrs & documents referenced in NRC transcript of 830328 public meeting
NEYLAN, A J GA Technologies, Inc /General Atomic Co 83/04/15 DICKHONER, W H Cincinnati Gas & Electric Co 1p 18281 252 24X Fiche 50-358, 83/04/15, 8305020435

8305020367 Forwards advance copy of "Program Plan for Independent Review of Zimmer Project Mgt " Plan will be discussed at 830425 public meeting in Cincinnati, OH
NEYLAN, A J Torrey Pines Technology 83/04/21 DICKHONER, W H Cincinnati Gas & Electric Co 1p 18276 250 24X Fiche 50-358, 83/04/21, 8305020367

--8305020368 GA-C17044, "Program Plan for Indegendent Review of Zimmer Project Mgt "
* Torrey Pines Technology 83/03/31 39pp 18276 251 24X Fiche 50-358, 83/04/21, 8305020367

8305030528 Application for Amend 148 to OL application, consisting of Rev 94 to FSAR
BORGMANN, E A Cincinnati Gas & Electric Co 83/04/29 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 18292 356 24X Fiche 50-358, 83/04/29, 8305030528

8305110118 REPORT OF THE EVALUATION TEAM ON THE QUALITY OF CONSTRUCTION AT THE ZIMMER NUCLEAR POWER STATION
* NRC - No Detailed Affiliation Given NUREG-0969 83/04/30 391pp 18418 001 24X Fiche 50-358, 83/04/30, 8305110118

8305120022 Notification of 830601-03 meetings w/util in Moscow, OH for site audit of environ qualification of safety-related electrical equipment
KINTNER, L L Licensing Branch 1 83/05/03 YOUNGBLOOD, B J Licensing Branch 1 4pp 18443 278 24X Fiche 50-358, 83/05/03, 8305120022

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G. Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305170550 Responds to 830107 ltr requesting concurrence in performing addl work activities not in violation of 821112 show cause order & order immediately suspending const Listed activities not safety-related & may be undertaken
WARNICK, R F Region 3, Office of Director 83/05/06 BORGMANN, E A Cincinnati Gas & Electric Co 5pp 18469 153 24X Fiche 50-358, 83/05/06, 8305170550

--8305170553 Requests that work activities not in violation of 821112 order to show cause & order to immediately suspend essential const be allowed to continue Activities to be performed listed
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/07 KEPPLER, J G Region 3, Office of Director 5pp. 18469, 158 24X Fiche, 50-358, 83/05/06, 8305170550

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659.

8305130111 Forwards Certificate of Svc for License Amend 148 in form of Rev 94 to FSAR
WILLIAMS, J Cincinnati Gas & Electric Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18438 089 24X Fiche 50-358, 83/05/09, 8305130111

8305170093 Board Notification 83-62 forwards NRC evaluation team independent assessment of installed safety-related equipment W/o rept
NOVAK, T M Division of Licensing 83/05/10 Atomic Safety and Licensing Appeal Panel 7pp 18495 317 24X Fiche 50-358, 83/05/10, 8305170093

--8305170098 Forwards NRC evaluation team rept (NUREG-0969) re onsite hardware evaluation conducted 830124-0304 W/o encl
DIRCKS, W J Office of the Executive Director for Operations 83/05/04 PALLADINO, N , GILINSKY, V , AHEARNE, J Commissioners 1p 18495 323 24X Fiche 50-358, 83/05/10, 8305170093

8305230630 Requests rev of QA program description in FSAR Section 17 1 to incorporate changes resulting from util response to 821112 order suspending const of safety-related equipment
YOUNGBLOOD, B J Licensing Branch 1 83/05/11 WILLIAMS, J Cincinnati Gas & Electric Co 4pp 18543 025 24X Fiche 50-358, 83/05/11, 8305230630

8305230658 Forwards Containment Sys Branch request for addl info re performance of wetwell-to-drywell vacuum breakers during LOCA pool swell phase for Mark II containments OL application should be amended by ref NEDE-22178(P)
YOUNGBLOOD, B J Licensing Branch 1 83/05/13 WILLIAMS, J Cincinnati Gas & Electric Co 4pp 18542 339 24X Fiche 50-358, 83/05/13, 8305230658

8305190312 Ack receipt of 820830 ltr re understanding of 801224 immediate action ltr & associated stop work order concerning Reactor Controls, Inc Work performance will be examined following lifting of Commission 821112 order
WARNICK, R F Region 3, Office of Director 83/05/16 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 18501 062 24X Fiche, 50-358, 83/05/16, 8305190312

--8305190314 Documents 820818 telcon re Stop Work Order 82-01. Immediate action ltr issued on 801224 Stop Work Order 80-14 applies only to matl, equipment & labor supplied by Reactor Controls, Inc Catalytic, Inc released to perform new work
BORGMANN, E. A Cincinnati Gas & Electric Co 82/08/30, KEPPLER, J G. Region 3, Office of Director 2pp 18501 064, 24X Fiche 50-358, 83/05/16, 8305190312

8305200454 Requests addl info re time required to recertify welders employed at plant from Jul-Nov 1982 during special welder qualification program Detailed accounting of time for each individual welder should be provided
KEPPLER, J G Region 3, Office of Director 83/05/17 WILLIAMS, J Cincinnati Gas & Electric Co 3pp 18513 011 24X Fiche 50-358, 83/05/17, 8305200454.

8305200558 Confirms followup 830526 meeting in Cincinnati,OH to discuss details of planned independent mgt review,including QA & quality verification programs Meeting will be open to public.
KEPPLER,J G Region 3, Office of Director 83/05/17 NEYLAN,A J Torrey Pines Technology 2pp 18515 353 24X Fiche 50-358, 83/05/17,8305200558

8305260336 Responds to 830506 request for NRC review & acceptance of results & conclusions of quality confirmation program,Task V (radiography) Review & disposition of identified nonconforming conditions will be performed during next insp
WARNICK,R F Region 3, Office of Director 83/05/23 WILLIAMS,J Cincinnati Gas & Electric Co 2pp 18625 044 24X Fiche 50-358,83/05/23,8305260336

--8305260337 Forwards Rev 1 to "Task V Radiographic Confirmation Rept," demonstrating adequacy of AW Kellogg Co,radiograph technique for piping subassembly shop welds
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/06 KEPPLER,J G Region 3, Office of Director 2pp 18625 046 24X Fiche 50-358,83/05/23,8305260336

--8305260338 Rev 1 to "Task V Radiographic Confirmation Rept "
* Cincinnati Gas & Electric Co 83/03/24 10pp 18625 048 24X Fiche 50-358,83/05/23,8305260336

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305090486 Forwards response to Suppl 3 of SER (NUREG-0528), Section 3 10, "Seismic & Dynamic Qualification of Seismic Category 1 Mechanical & Electrical Equipment "
FLYNN,J D Cincinnati Gas & Electric Co 83/05/05 DENTON,H Office of Nuclear Reactor Regulation, Director 4pp 18360 223 24X Fiche 50-358,83/05/05,8305090486

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EIGENHUT,D.G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche,50-000,83/05/11,8305110034

8305180458 Forwards "Ohio River Valley Wind Field Characterization Within WH Zimmer Nuclear Power Station Emergency Planning Zone," in response to NRC Question 322 18
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18482 163 24X Fiche 50-358,83/05/13,8305180458

--8305180463 "Ohio River Valley Wind Field Characterization Within WH Zimmer Nuclear Power Station Emergency Planning Zone "
* Stone & Webster Engineering Corp 83/04/30 281pp 18482 165 24X Fiche,50-358,83/05/13,8305180458

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W.J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J. Commissioners 5pp 18593 322 24X Fiche 50-000,83/05/13,8305240213.

G Adjudicatory correspondence

8305110290 Clarifies Contention 5 re ion exchange resin reactor coolant polishing sys,per 10CFR2.206
GILLMAN,D. Affiliation Unknown 83/04/28 Office of Nuclear Reactor Regulation, Director 3pp 18393 304 24X Fiche:50-358,83/04/28,8305110290

8305040436 Order extending time until 830520 for Commission to act to review Director's decision
CHILK,S J. Office of the Secretary of the Commission 83/05/02 Commissioners 1p. 18321.305 24X Fiche 50-358,83/05/02, 8305040436.

8305040504 Decision ALAB-727,modifying ASLB 820621 decision As modified,decision is affirmed Emergency response plans need not be final when OL application noticed for hearing.
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel. 83/05/02 28pp. 18319:236. 24X Fiche 50-358,83/05/02,8305040504

8305110350 Memorandum & order dismissing D Gillman 830319 & 0408 appeals re ASLB denial of intervention.Content of appeals appears to constitute challenge to ASLB application of factors governing late filed intervention petitions
SHOEMAKER,C J. Atomic Safety and Licensing Appeal Panel 83/05/10 GILLMAN,D. Affiliation Unknown. 8pp 18406 132 24X Fiche 50-358,83/05/10,8305110350.

8305200525 Order extending time until 830527 for Commission to act to review Director's decision dtd 830210
CHILK,S J Office of the Secretary of the Commission 83/05/19 Commissioners 1p 18516 074 24X Fiche 50-358,83/05/19, 8305200525

8305260171 Requests recommendations on proceeding w/remaining offsite emergency planning issues in light of ALAB-727
FRYE,J H Atomic Safety and Licensing Board Panel 83/05/25 BARTH,C A Hearing Branch I CONNER,T B , WETTERHAHN,M J Conner & Wetterhahn 1p 18599 289 24X Fiche 50-358,83/05/25,8305260171

8305310018 Order extending time until 830606 for Commission to act to review 830210 Director's decision
CHILK,S J Office of the Secretary of the Commission 83/05/27 Commissioners 1p 18653 125 24X Fiche 50-358,83/05/27, 8305310018

H General correspondence

8305160202 Ack receipt of 830413 ltr re selection of Torrey Pines Technology (TPT) to conduct mgt review of facility TPT to meet w/NRC to consider final review plan
MENCZER,W B Region 3, Office of Director 83/05/02 WESTBROOK,J Cleveland, OH 2pp 18462 359 24X Fiche 50-358,83/05/02, 8305160202

J Insurance & indemnity information

8305270539 Responds to 830422 ltr re American Nuclear Insurers activity at facility No ASME Code work in process due to stop work order HJ Kaiser continuing to resolve existing nonconformances & verification of resolutions
DOBEL,H F Hartford Insurance Group 83/05/19 HARRISON,S F National Board of Boiler & Pressure Vessel Inspectors 2pp 18446 137 24X Fiche 50-358,83/05/19,8305270539

K Utility Final Safety Analysis Report (FSAR) & amends

8305190278 Amend 147 to application for OL,consisting of Rev 93 to FSAR
BORGMANN,E A Cincinnati Gas & Electric Co 83/03/31 DENTON,H Office of Nuclear Reactor Regulation, Director 2pp 18501 157 24X Fiche 50-358,83/03/31,8305190278

--8305190281 Rev 93 to FSAR
* Cincinnati Gas & Electric Co 83/03/31 79pp 18501 159 24X Fiche 50-358,83/03/31,8305190278

8305030528 Application for Amend 148 to OL application,consisting of Rev 94 to FSAR
BORGMANN,E A Cincinnati Gas & Electric Co 83/04/29 DENTON,H Office of Nuclear Reactor Regulation, Director 2pp 18292 356 24X Fiche 50-358,83/04/29,8305030528

--8305030533 Rev 94 to FSAR
* Cincinnati Gas & Electric Co 83/04/30 228pp 18292 358 24X Fiche 50-358,83/04/29,8305030528

8305130111 Forwards Certificate of Svc for License Amend 148 in form of Rev 94 to FSAR
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/09 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18438 089 24X Fiche 50-358,83/05/09,8305130111

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305120070 Addl response to FOIA request for IE Insp Rept 50-358/81-13 Portions of documents listed on app withheld (ref FOIA Exemption 4)
FELTON,J M Division of Rules and Records 83/03/21 DEVINE,T , ROSENTHAL Government Accountability Project 3pp 18443 193 24X Fiche 50-358,83/03/21,8305120070

--8305120074 Forwards Electrical Drafting Std EDSB-126 revised on 791005, Pages 2-43 through 2-48 of Electrical Installation Spec H-2173 & Pages 8 3-29,8 3-30 & 8 3-65 of FSAR,per request re tray loading criteria.Related info encl
COTTA,R E Sargent & Lundy, Inc. 81/02/18 BARRETT,P Region 3, Chicago, Office of the Director 36pp 18443 196 24X Fiche 50-358,83/03/21,8305120070

8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All NRC ofcs will comply w/FOIA request Request Requests will be coordinated w/Ofc of General Counsel
PALLADINO, N J Commissioners 83/04/14 UDALL, M K House of Rep , Interior & Insular Affairs 7pp 18594 131 24X
Fiche 50-358, 83/04/14, 8305240252

--8305240256 Responds to 830302 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All FOIA requests will be coordinated w/Ofc of General Counsel Commissioners views encl
PALLADINO, N J Commissioners 83/04/14 SEIBERLING, J F House of Rep , Interior & Insular Affairs 12pp 18594 138 24X
Fiche 50-358, 83/04/14, 8305240252

--8305240263 Discusses investigation of Applegate allegations, "Adequacy of IE Investigation 50-358/80-09 at WH Zimmer Nuclear Power Station," per Udall 821207 ltr IE investigation found unsatisfactory in Aug 1981 T Harpster interview encl
CUMMINGS, J J Office of Inspector & Auditor 83/01/05
BICKWIT, L Office of the General Counsel 8pp 18594 153 24X
Fiche 50-358, 83/04/14, 8305240252

--8305240267 Forwards addl info re NRC withholding of T Harpster interview w/Govt Accountability Project 811123 FOIA request, per Commission 830207 instructions
CUMMINGS, J Office of Inspector & Auditor 83/02/16 MALSCH, M G Office of the General Counsel 4pp 18594 163 24X
Fiche 50-358, 83/04/14, 8305240252

--8305240272 Requests info re Ofc of Inspector & Auditor (OIA) inquiry into Zimmer matter Reasons for removal of documents from OIA ofcs questioned Withholding of documents contributed to delay in public recognition of true status of project
UDALL, M K House of Rep , Interior & Insular Affairs 82/12/07
PALLADINO, N J Commissioners 1p 18594 169 24X
Fiche 50-358, 83/04/14, 8305240252

--8305240275 Requests addl info re 821207 ltr seeking explanation of circumstances surrounding compliance w/FOIA request for documents pertaining to facility Adequacy of Cummings reply questioned
UDALL, M , SIEBERLING, J House of Rep , Interior & Insular Affairs 83/03/02 PALLADINO, N Commissioners 2pp 18594 170 24X
Fiche 50-358, 83/04/14, 8305240252

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 163 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305170447 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-10 Request for extension until 830609 for response to noncompliance granted
WARNICK, R F Region 3, Office of Director 83/05/13 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 18471 224 24X
Fiche 50-358, 83/05/13, 8305170447

--8305170454 Responds to NRC 830325 ltr re noncompliances noted in IE Insp Rept 50-358/82-10 Extension to 830609 for responding to noncompliances due to extensiveness of rept requested
BORGMANN, E A Cincinnati Gas & Electric Co 83/04/20
KEPPLER, J G Region 3, Office of Director 2pp 18471 226 24X
Fiche 50-358, 83/05/13, 8305170447

8305260223 Forwards IE Insp Rept 50-358/82-11 on 820505 & 0726-0930 & notice of violation
WARNICK, R F Region 3, Office of Director 83/05/13 WILLIAMS, J
Cincinnati Gas & Electric Co 2pp 18622 087 24X
Fiche 50-358, 83/05/13, 8305260223

--8305260225 Notice of violation from insp on 820505 & 0726-0930
WARNICK, R F Region 3, Office of Director 83/05/13 4pp 18622 089 24X Fiche 50-358, 83/05/13, 8305260223

--8305260231 IE Insp Rept 50-358/82-11 on 820505 & 0726-0930 Noncompliance noted failure to follow procedures, to document nonconforming welds on piping matl & to provide adequate design control measures
CHRISTIANSON, W , GWYNN, T P , NIGHTINGALE, E Region 3, Office of Director 83/04/14 27pp 18622 093 24X Fiche 50-358, 83/05/13, 8305260223

8305190269 Ack receipt of 821115 ltr in response to NRC 821027 request for info re allegations concerning welder qualification NRC will examine matters during subsequent insps
KEPPLER, J G Region 3, Office of Director 83/05/16 WILLIAMS, J
Cincinnati Gas & Electric Co 1p 18501 238 24X
Fiche 50-358, 83/05/16, 8305190269

--8305190273 Responds to 821027 ltr re allegations concerning withholding of relevant documentation on welders from 820709 meeting w/NRC List of documents used at 820708 mgt meeting w/HJ Kaiser &/or 820709 meeting provided
SYLVIA, B R Cincinnati Gas & Electric Co 82/11/15 KEPPLER, J G Region 3, Office of Director 3pp. 18501 239 24X
Fiche 50-358, 83/05/16, 8305190269

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305240001 Ack receipt of 830125 & 0223 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-358/82-01
WARNICK, R F Region 3, Office of Director 83/05/20 WILLIAMS, J
Cincinnati Gas & Electric Co 1p 18549 135 24X
Fiche 50-358, 83/05/20, 8305240001

--8305240012 Suppls 820804 & 830104 ltrs in response to NRC 820624 ltr re violations noted in IE Insp Rept 50-358/82-01, Cable grip installation will be verified for cable installed on vertical risers
BORGMANN, E A Cincinnati Gas & Electric Co 83/01/25
KEPPLER, J G Region 3, Office of Director 1p 18549 136 24X
Fiche 50-358, 83/05/20, 8305240001

--8305240016 Suppls 830125 response to violations noted in IE Insp Rept 50-358/82-01 Design changes require mods to as-built condition Const work authorization request prepared Followup rept will be sent by 830506
BORGMANN,E A Cincinnati Gas & Electric Co 83/02/23
KEPPLER,J G Region 3, Office of Director 1p 18549 137 24X
Fiche 50-358,83/05/20,8305240001

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305250162 Monthly status rept for Apr 1983 W/830519 ltr
* Region 3, Office of Director DIRCKS,W J Office of the Executive Director for Operations 83/04/30 PALLADINO,N
Commissioners 69pp 18596 071 24X Fiche 50-358,83/04/30,
8305250162

S Reportable occurrences, LERs & related correspondence

8305120342 Interim deficiency rept re masking of radiography by inadequate surface preparation Initially reported on 820520 Const work authorization request processed to blend grind & reradiograph welds Next rept expected by 830815
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 2pp 18432 267 24X
Fiche 50-358,83/04/29,8305120342

8305120410 Interim deficiency rept re Item M-72 on lack of QA program for fire protection sys installation Sargent & Lundy developing sampling program to assure as-designed sys installed & functional Next rept to be submitted by 830801
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 2pp 18434 092 24X
Fiche:50-358,83/04/29,8305120410

8305120429 Interim deficiency rept re Brown Boveri 125-volt dc control device failure on 6 9 kV & 4 16 kV switchgear Initially reported on 830202 All Brown Boveri circuit breakers will be inspected & adjusted Followup rept by 830815
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 5pp 18431 161 24X
Fiche 50-358,83/04/29,8305120429

--8305120437 "Instructions for Inspecting,Adjusting &/or Replacement of Parts for Obtaining Limit Switch Adjustments on Brown Boveri 7 5 kV Through 15 kV,500 Through 750 MVA;5HK350,3000; All HKV Breakers "
* Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/29
4pp. 18431 166 24X Fiche 50-358,83/04/29,8305120429

8305120432 Interim deficiency rept re failure of essential HVAC turning vanes (Item M-46) Initially reported on 820510 Scheduling & implementation of test procedure clarifying design adequacy contingent upon release of NRC 821112 order to show cause
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 2pp 18431 154 24X
Fiche 50-358,83/04/29,8305120432

8305120446 Interim deficiency rept re Item M-29 concerning lack of weld procedure qualification & Item M-73 concerning possibly altered welding procedures Initially reported on 811103 & 821217,respectively
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 2pp 18431 078 24X
Fiche 50-358,83/04/29,8305120446

8305120487 Interim deficiency rept re inadequate cable tray hanger insp (Item E-20) Initially reported on 820503 Alternate method for cable tray hanger reinsp developed for galvanized cables Next rept will be submitted by 830620
WILLIAMS,J Cincinnati Gas & Electric Co 83/04/29 KEPPLER,J G
Region 3, Office of Director 2pp 18431 055 24X
Fiche 50-358,83/04/29,8305120487

8305170524 Interim deficiency rept re Item Q-3 concerning lack of insp personnel qualifications Review of work packages to identify any insp personnel whose qualifications & certifications not documented continuing Next rept expected by 830808
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/06 KEPPLER,J G
Region 3, Office of Director 2pp 18467 249 24X
Fiche 50-358,83/05/06,8305170524

8305190228 Deficiency rept re Item M-84 concerning spent fuel rack spacing Initially reported on 830415 GE evaluation determined condition not reportable per 10CFR50 55(e)
WILLIAMS,J. Cincinnati Gas & Electric Co 83/05/10 KEPPLER,J G
Region 3, Office of Director 2pp 18500 200 24X
Fiche 50-358,83/05/10,8305190228

8305200536 Interim deficiency rept re seismic qualification of 13 essential damper operator mounting brackets Initially reported on 801014 Vendor approved American Warming & Ventilating Co design mods Next rept by 830810
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/13 KEPPLER,J G
Region 3, Office of Director 2pp 18516 019 24X
Fiche 50-358,83/05/13,8305200536

8305190316 Ack receipt of 820929 ltr informing NRC of exception to correction notice to document deficiencies during document review & use of generic nonconformance repts to document deficiencies to comply w/previous commitments
WARNICK,R F Region 3, Office of Director 83/05/16 WILLIAMS,J
Cincinnati Gas & Electric Co 2pp 18501 059 24X
Fiche 50-358,83/05/16,8305190316

8305260227 Final deficiency rept re essential instruments attached to nonessential/nonseismic piping Initially reported on 830420 Condition determined not reportable per 10CFR50 55(e)
WILLIAMS,J Cincinnati Gas & Electric Co 83/05/19 KEPPLER,J G
Region 3, Office of Director 2pp 18599 330 24X
Fiche 50-358,83/05/19,8305260227

T Hearing transcripts on non-antitrust matters

8305090537 FOIA request for transcript of Commission meetings discussing 821112 order CLI-82-33 & documents supporting NRC recommendation to Commission re issuance of order
SAMP,R A Shaw, Pittman, Potts & Trowbridge 83/02/09
GRIMSLEY,D H Division of Rules and Records 2pp 18365 134 24X
Fiche 50-358,83/02/09,8305090537

8305090542 Partial response to FOIA request for transcript of Commission meetings discussing 821112 order & documents supporting NRC recommendations to Commission re issuance of order Forwards App B documents App A documents in PDR
FELTON,J M Division of Rules and Records 83/03/17 SAMP,R A
Shaw, Pittman, Potts & Trowbridge 4pp 18365 136 24X
Fiche 50-358,83/03/17,8305090542

--8305090549 Testimony of JG Keppler before US House of Representatives, Committee on Interior & Insular Affairs,Subcommittee on Energy & Environ on 820610 re QA problems & related activites at facility Pp 1-12
KEPPLER,J G NRC - No Detailed Affiliation Given 82/06/10
12pp 18365 216 24X Fiche 50-358,83/03/17,8305090542

8305260397 Addl response to FOIA request for transcripts of Commission 821028,1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/03/28 SAMP,R A
Shaw, Pittman, Potts & Trowbridge 4pp 18647 294 24X
Fiche 50-358,83/03/28,8305260397

--8305260405 Testimony of JG Keppler (Region III) before Subcommittee on Energy & Environ of Committee on Interior & Insular Affairs on 830914 re quality confirmation program in Washington,DC
KEPPLER,J G Region 2, Office of Director 82/09/14 62pp
18647 302 24X Fiche 50-358,83/03/28,8305260397

U Congressional/Executive Correspondence

8305260397 Addl response to FOIA request for transcripts of Commission 821028,1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/03/28 SAMP,R A
Shaw, Pittman, Potts & Trowbridge 4pp 18647 294 24X
Fiche 50-358,83/03/28,8305260397

8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All NRC ofcs will comply w/FOIA request Request Requests will be coordinated w/Ofc of General Counsel
PALLADINO,N J Commissioners 83/04/14 UDALL,M K House of Rep
Interior & Insular Affairs 7pp 18594 131 24X
Fiche 50-358,83/04/14,8305240252

--8305240256 Responds to 830302 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All FOIA requests will be coordinated w/Ofc of General Counsel Commissioners views encl
PALLADINO,N J Commissioners 83/04/14 SEIBERLING,J F House of Rep , Interior & Insular Affairs 12pp 18594 138 24X
Fiche 50-358,83/04/14,8305240252

--8305240272 Requests info re Ofc of Inspector & Auditor (OIA) inquiry into Zimmer matter Reasons for removal of documents from OIA ofcs questioned Withholding of documents contributed to delay in public recognition of true status of project
UDALL,M K House of Rep , Interior & Insular Affairs 82/12/07
PALLADINO,N J Commissioners 1p 18594 169 24X
Fiche 50-358,83/04/14,8305240252

--8305240275 Requests addl info re 821207 ltr seeking explanation of circumstances surrounding compliance w/FOIA request for documents pertaining to facility Adequacy of Cummings reply questioned
UDALL,M , SIEBERLING,J House of Rep , Interior & Insular Affairs 83/03/02 PALLADINO,N Commissioners 2pp 18594 170 24X
Fiche 50-358,83/04/14,8305240252

DOCKET 50-361 SAN ONOFRE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

8305060683 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision
KNIGHTON,G W Licensing Branch 3 83/04/27 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co 5pp. 18357 314 24X Fiche 50-361,83/04/27,8305060683

--8305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ASLAB 830304 decision
EISENHUT,D G Division of Licensing 83/04/27 4pp 18357 318 24X Fiche 50-361,83/04/27,8305060683

--8305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively
* NRC - No Detailed Affiliation Given, 83/04/27 1p 18357 322 24X Fiche 50-361,83/04/27,8305060683

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
Fiche:50-000,83/05/11,8305110034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21).
NORDERHAUG,L R Region 5, Office of Director 83/05/12 PAPAY,L T Southern California Edison Co. 2pp 18599 322 24X
Fiche 50-206,83/05/12,8305260242

8305170471 Responds to Generic Ltr 82-33 (NUREG-0737,Suppl 1) re emergency response capability requirements Progress in areas of safety parameter display sys,detailed control room design reviews & emergency response facilities summarized
BASKIN,K P Southern California Edison Co. 83/05/13 EISENHUT,D G Office of Nuclear Reactor Regulation, Director 8pp 18470 077 24X Fiche 50-361,83/05/13,8305170471

G Adjudicatory correspondence

8305100199 Discusses Memorandum & Order CLI-83-10 re arrangements required under regulations for medical svc for contaminated-injured individuals No further evidentiary hearing required
CHANDLER,L J Office of the Executive Legal Director 83/04/25
BROWN,R F California, Univ. of, San Francisco 1p 18374 199 24X Fiche:50-361,83/04/25,8305100199.

8305100220 Advises that no further evidentiary hearing required to determine compliance w/Commission regulations re medical svcs for contaminated injured individuals Issue can be resolved on basis of written submission
CHANDLER,L J. Hearings Division 83/04/25. NESBITT,W Affiliation Unknown 1p 18373 319. 24X Fiche 50-361,83/04/25,8305100220

8305190195 Proposed findings of fact & conclusions of law Declaration of Svc encl
PIGOTT,D R Southern California Edison Co PIGOTT,D R Orrick, Herrington & Sutcliffe. 83/05/16 5pp 18500 001 24X
Fiche 50-361,83/05/16,8305190195.

8305190212 Motion to augment record to include various revised county emergency plans & other documents re emergency planning. Decisions should reflect current info Declaration of Svc encl
PIGOTT,D.R Southern California Edison Co PIGOTT,D R. Orrick, Herrington & Sutcliffe. 83/05/16 Atomic Safety and Licensing Board Panel 33pp, 18502 146 24X Fiche 50-361,83/05/16, 8305190212

8305190232 Position re Commission 830405 Memorandum & Order CLI-83-10 on offsite medical svcs Util provided necessary level of medical svcs for general public Declaration of Svc encl.
PIGOTT,D R Southern California Edison Co 83/05/16 9pp 18501 284 24X Fiche 50-361,83/05/16,8305190232

8305240522 Order extending time until 830607 for Commission to act to review petitions for review of ALAB-717
CHILK,S J Office of the Secretary of the Commission 83/05/20
Commissioners 1p 18571 118 24X Fiche 50-361,83/05/20, 8305240522

H General correspondence

8305090024 Addl response to FOIA request for documents re 821130 special insp rept Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6) Documents 3 & 4 withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/21 GARDE,B Government Accountability Project 4pp 18381 198 24X
Fiche 50-206,83/03/21,8305090024

8305120178 Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcombe replaces GD Cotton as representative authorized to sign NRC licensing documents
HOLCOMBE,J C San Diego Gas & Electric Co 83/05/06 EISENHUT,D G Division of Licensing 1p. 18427 156 24X Fiche 50-206,83/05/06, 8305120178

P Operating license stage documents & correspondence

8305110179 Forwards Amend 16 to License NPF-10, safety evaluation & notice of issuance & availability Amend updates Unit 2 Tech Specs for consistency w/Unit 3 Tech Specs
KNIGHTON,G W Licensing Branch 3 83/04/25 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co. 4pp 18434 357 24X Fiche 50-361,83/04/25,8305110179

--8305110182 Amend 16 to License NPF-10, updating Tech Specs for consistency w/Unit 3 Tech Specs
KNIGHTON,G W Licensing Branch 3 83/04/25 81pp 18434 361. 24X Fiche 50-361,83/04/25,8305110179

--8305110186 Safety evaluation supporting Amend 16 to License NPF-10
* Office of Nuclear Reactor Regulation, Director 83/04/25 1p 18435 152 24X Fiche 50-361,83/04/25,8305110179

--8305110188 Notice of issuance & availability of Amend 16 to License NPF-10
KNIGHTON,G.W. Licensing Branch 3. 83/04/25 2pp. 18435 153 24X Fiche 50-361,83/04/25,8305110179.

8305060683 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision
KNIGHTON,G W Licensing Branch 3 83/04/27 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co 5pp 18357 314 24X Fiche 50-361,83/04/27,8305060683

--8305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ASLAB 830304 decision
EISENHUT,D G Division of Licensing. 83/04/27 4pp. 18357 318 24X Fiche 50-361,83/04/27,8305060683.

--8305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively.
* NRC - No Detailed Affiliation Given 83/04/27. 1p 18357 322 24X Fiche 50-361,83/04/27,8305060683.

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
EISENHUT,D.G Division of Licensing. 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120. 24X
Fiche 50-000,83/05/02,8305020455

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification. Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D.G. Division of Licensing 83/05/04. PALLADINO,N. Commissioners. 22pp 18337 139 24X Fiche. 50-000,83/05/04, 8305040323.

8305170229 Forwards Amends 19 & 7 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability Amends modify Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation
KNIGHTON, G W Licensing Branch 3 83/05/04 DIETCH, R Southern California Edison Co CATTON, G D , BERNATH, L San Diego Gas & Electric Co 3pp 18476 349 24X Fiche 50-361, 83/05/04, 8305170229

--8305170233 Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation to add steam generator blowdown pass line as alternative release path
EISENHUT, D G Division of Licensing 83/04/29 10pp 18476 352 24X Fiche 50-361, 83/05/04, 8305170229

--8305170234 Safety evaluation supporting Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively
e Office of Nuclear Reactor Regulation, Director 83/04/29 8pp 18476 362 24X Fiche 50-361, 83/05/04, 8305170229

--8305170236 Notice of issuance & availability of Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively
KNIGHTON, G W Licensing Branch 3 83/04/29 2pp 18477 008 24X Fiche 50-361, 83/05/04, 8305170229

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc 16pp 18627 153 24X Fiche: 50-000, 83/05/09, 8305090659

8305260122 Comments on 830106 proposal to delete integral test of core protection calculator functional capability from natural circulation test Alternate demonstration of functional capability requested
NOVAK, T. M Assistant Director for Licensing 83/05/12 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co. 6pp 18649 059 24X Fiche 50-361, 83/05/12, 8305260122

8305190028 Responds to Generic Ltr 83-10A re resolution of TMI Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Util, as member of C-E Owners Group, has chosen "trip two, leave two" strategy to resolve item
BASKIN, K P Southern California Edison Co 83/05/13. KNIGHTON, G W Licensing Branch 3 2pp 18502.039 24X Fiche 50-361, 83/05/13, 8305190028

8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs
NOVAK, T. M Assistant Director for Licensing 83/05/18. Atomic Safety and Licensing Board Panel. 7pp 18627 107 24X Fiche: 50-000, 83/05/18, 8305250209

--8305250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ASLAB
MATTSON, R. J. Division of Systems Integration (post 811005) 83/04/28. EISENHUT, D. G Division of Licensing 1p 18627 113 24X Fiche 50-000, 83/05/18, 8305250209

--8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630.
DIRCKS, W J. Office of the Executive Director for Operations 83/04/25. CHILK, S. J Office of the Secretary of the Commission. 1p. 18627.115. 24X Fiche 50-000, 83/05/18, 8305250209

8305240458 Forwards status of environ qualification of electrical equipment per 10CFR50 49(g). All equipment, except auxiliary feedwater pump motors, meets NUREG-0588 guidelines for Category II plant
BASKIN, K. P. Southern California Edison Co 83/05/20. KNIGHTON, G. W. Licensing Branch 3 3pp 18549:286 24X Fiche 50-361, 83/05/20, 8305240458.

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308.319 24X Fiche 50-000, 83/03/21, 8212060385

8305030075 Comments on Mgt Analysis Co 830404 visit to Region V re recent licensee regulatory performance & circumstances which led to proposed issuance of civil penalties against util
CREWS, J L Division of Resident, Reactor Project & Engineering Programs 83/04/13 Division of Resident, Reactor Project & Engineering Programs 1p 18300 178 24X Fiche 50-361, 83/04/13, 8305030075

8305170417 Forwards IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 & notice of violation
BISHOP, T W Region 5, Office of Director 83/04/14 PAPAY, L T Southern California Edison Co 2pp 18469 253 24X Fiche 50-361, 83/04/14, 8305170417

--8305170420 Notice of violation from insp on 830312-25
KIRSCH, D F Region 5, Office of Director 83/04/14 3pp 18469 255 24X Fiche 50-361, 83/04/14, 8305170417

--8305170421 IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 Noncompliance noted failure to rept reactor trip breaker inoperability & to implement vendor svc bulletin info
STERNBERG, D M , KIRSCH, D F , CHAFFEE, A E Region 5, Office of Director 83/04/13 28pp 18469 259 24X Fiche 50-361, 83/04/14, 8305170417

8305170474 Forwards IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No noncompliance noted
BISHOP, T. W Region 5, Office of Director 83/04/14 PAPAY, L T Southern California Edison Co 2pp 18470:086 24X Fiche. 50-361, 83/04/14, 8305170474

--8305170480 IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No noncompliance noted Major areas inspected operational safety verification, monthly surveillance, LER review & independent insp effort
PATE, R. J , MENDONCA, M M , O'BRIEN, J P Region 5, Office of Director. 83/04/14 4pp. 18470 088 24X Fiche 50-361, 83/04/14, 8305170474.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15. Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305170515 Forwards IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 & notice of violation
SCARANO, R A. Division of Radiological Safety & Safeguards Program 83/04/18. PAPAY, L T. Southern California Edison Co 2pp 18467.260 24X Fiche 50-361, 83/04/18, 8305170515

--8305170521 Notice of violation from insp on 830321-30
WENSLAWSKI, F A Region 5, Office of Director 83/04/18 2pp 18467 262 24X Fiche 50-361, 83/04/18, 8305170515

--8305170530 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 Noncompliance noted failure to perform surveys, inform workers & properly monitor liquid radioactive effluent release
YUHAS, G P , WENSLAWSKI, F A , BOOK, H E Region 5, Office of Director 83/04/14 10pp 18467 264 24X Fiche 50-361, 83/04/18, 8305170515

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383.089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170359 Forwards IE Insp Repts 50-361/83-16 & 50-362/83-16 on 830404-08. No noncompliance noted
BISHOP, T. W. Region 5, Office of Director 83/04/26 PAPAY, L T Southern California Edison Co 2pp 18466 098 24X Fiche. 50-361, 83/04/26, 8305170359

--8305170361 IE Insp Repts 50-361/83-16 & 50-362/83-16 on 830404-08 No noncompliance noted. Major areas inspected: corrective & preventative maint programs
ECKHARDT, J H , KIRSCH, D F Region 5, Office of Director 83/04/22 4pp. 18466 100. 24X Fiche 50-361, 83/04/26, 8305170359

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28. Consolidated Edison Co of New York, Inc. 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 11Spp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305090278 Forwards response to notice of violation & proposed imposition of civil penalties based on IE Insp Repts 50-361/83-06 & 50-361/83-08 Generic procedure will be revised by 830430 to detail key plant sys Payment encl
PAPAY,L T Southern California Edison Co 83/05/02 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 18364 002 24X Fiche 50-361,83/05/02,8305090278

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21)
NORDERHAUG,L R Region 5, Office of Director 83/05/12 PAPAY,L T Southern California Edison Co 2pp 18599 322 24X
Fiche 50-206,83/05/12,8305260242

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009. 24X Fiche 50-000,83/05/19,8303040040

8305260264 Advises that util 830502 response to notice of violation & proposed imposition of civil penalties acceptable w/one exception re interim measures for analysis of radioactive iodines
MARTIN,J B Region 5, Office of Director 83/05/20 PAPAY,L T Southern California Edison Co 2pp 18626 001 24X
Fiche,50-361,83/05/20,8305260264

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8304150372 Monthly operating repts for Feb 1983
MAYWEATHER,L Southern California Edison Co 83/03/15 11pp
17981 359 24X Fiche 50-361,83/03/15,8304150348

S. Reportable occurrences, LERs & related correspondence

8305030432 RO 50-361/82-176 on 830329,review of nonconformance repts revealed less than conservative limiting conditions for operation Caused by failure to verify undervoltage trip mechanism operability following 820710 maint
RAY,H.B Southern California Edison Co 83/03/30 ENGELKEN,R H Region 5, Office of Director 2pp 18306 274 24X
Fiche 50-361,83/03/30,8305030432

8305060505 Forwards LER 83-036/01T-0
RAY,H B Southern California Edison Co 83/04/08 MARTIN,J B Region 5, Office of Director 2pp 18351 143 24X
Fiche 50-361,83/04/08,8305060505

--8305060514 LER 83-036/01T-0 on 830321,discharge isolation valve on common liquid radwaste effluent radiation monitor 2/3 RT-7813 discovered shut Caused by personnel error Valve left shut during quarterly channel functional test
RAY,H B Southern California Edison Co 83/04/08 Region 5, Office of Director 2pp 18351 145 24X Fiche 50-361,83/04/08, 8305060505

8305050341 Forwards AEOD/E305, "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment " Rept should be forwarded to NRR,RES & IE
BROWN,E J Reactor Operations Analysis Branch 83/04/13
SEYFRIT,K V Reactor Operations Analysis Branch 2pp 18352:051
24X Fiche 50-000,83/04/13,8305050341

--8305050353 "Inoperable Motor Operated Valve Assemblies Due to Premature Degradation of Motors &/or Improper Limit Switch/Torque Switch Adjustment," AEOD engineering evaluation rept
BROWN,E J Director's Office 83/04/13 7pp 18352 053 24X
Fiche 50-000,83/04/13,8305050341

8305030356 Forwards LER 83-026/01T-0 Detailed event analysis submitted
RAY,H B Southern California Edison Co 83/04/18 MARTIN,J B Region 5, Office of Director 3pp 18306 219 24X
Fiche 50-361,83/04/18,8305030356

--8305030359 LER 83-026/01T-0 on 830404,containment isolation valve 2HV8248 indicated mid-position following both open & closed signals Caused by faulty magnetic reed switch assembly Assembly replaced Valve declared operable
RAY,H B Southern California Edison Co 83/04/18 Region 5, Office of Director 2pp 18306 222 24X Fiche 50-361,83/04/18, 8305030356

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573

8305030360 RO high steam generator differential pressure trip function operability requirements exceeded for Modes 1,2 & 3 Setpoints will be corrected before reentry into Mode 3 & will be reported in LER by 830505
RAY,H B Southern California Edison Co 83/04/22 MARTIN,J B, Region 5, Office of Director 2pp 18291 361 24X
Fiche 50-361,83/04/22,8305030360

8305020183 PND-V-83-018 on 830421,util received ltr from C-E informing of error in equivalent voltages corresponding to setpoints associated w/steam generator high delta pressure trip function Corrective action being developed
BISHOP,T W Region 5, Office of Director 83/04/25 1p
18277 295 24X Fiche 50-361,83/04/25,8305020183

8305060467 RO 83-038 on 830426,motor operated valves 2HV8150,2HV8152 & 2HV8153 could not be opened during testing in preparation to proceed to Mode 3 operation Investigation continuing Followup rept to be submitted by 830512
RAY,H B Southern California Edison Co 83/04/27 MARTIN,J B Region 5, Office of Director 2pp 18351 190 24X
Fiche 50-361,83/04/27,8305060467

8305180790 Forwards SER on reactor trip breakers Licensee proposed actions provide acceptable basis for restart & operation
EISENHUT,D G Division of Licensing 83/05/02 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co 3pp 18505 001 24X Fiche 50-361,83/05/02,8305180790

--8305180804 SER lifting restrictions on exceeding power documented in confirmation of action ltrs dtd 830311 & 0429 based on corrective actions re reactor trip breaker failure.
* Office of Nuclear Reactor Regulation, Director 83/04/30
58pp 18505 004 24X Fiche 50-361,83/05/02,8305180790

8305160011 Forwards LER 83-035/03L-0
RAY,H B Southern California Edison Co 83/05/05, MARTIN,J,B Region 5, Office of Director 1p 18456 083 24X
Fiche 50-361,83/05/05,8305160011

--8305160014 LER 83-035/03L-0 on 830405,pin hole leaks discovered in mini flow line for auxiliary feedwater pump P141,downstream from flow orifice FO-4711 P141 delcared inoperable Caused by cavitation downstream of flow orifice Pipe section replaced
RAY,H B Southern California Edison Co 83/05/05 Region 5, Office of Director 1p 18456 084 24X Fiche 50-361,83/05/05, 8305160011

8305160055 Forwards LERs 83-037/01T-0 for Units 1 & 2
RAY,H B Southern California Edison Co 83/05/05 MARTIN,J B Region 5, Office of Director 2pp 18451 047 24X
Fiche 50-361,83/05/05,8305160055

--8305160069 LER 83-037/01T-0 on 830421,high steam generator differential pressure setpoint used in PPS emergency feedwater sys logic circuitry resulted in actual trip setpoint of 300 psid, higher than assumed in FSAR Caused by conversion error
RAY,H B. Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 049 24X Fiche 50-361,83/05/05, 8305160055

--8305160101 LER 83-037/01T-0 on 830421,high steam generator differential pressure setpoint used in PPS emergency feedwater sys logic circuitry resulted in actual trip setpoint 300 psid higher than assumed in FSAR Caused by voltage conversion error
RAY,H B Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 051 24X Fiche 50-361,83/05/05, 8305160055

8305270321 RO 83-040 on 830426,while filling safety injection tank T-007,valves 2HV9334 & MU-099 inadvertently left open Procedure SO23-3-2 7 revised to include positive steps to close valves.Followup rept will be submitted by 830523
RAY,H B Southern California Edison Co 83/05/09 MARTIN,J B Region 5, Office of Director 3pp 18641 164 24X
Fiche 50-361,83/05/09,8305270321

8305270243 LER 83-038/03L-0 on 830426,shutdown cooling sys HX isolation valves 2HV8150,52 & 53 could not be remotely opened from control room Mode 3 restraint imposed Caused by incorrect sequence torque setting W/830512 ltr
RAY,H B Southern California Edison Co. 83/05/12 MARTIN,J B Region 5, Office of Director 4pp 18637 157 24X
Fiche 50-361,83/05/12,8305270243

8305170278 Confirms no safety-related applications of integral undervoltage trip devices exist other than in reactor trip switchgear,in response to NRC request for info re 830415 reactor trip breaker rept
BASKIN,K P Southern California Edison Co 83/05/13 KNIGHTON,G W Licensing Branch 3 1p 18465,326, 24X Fiche 50-361,83/05/13, 8305170278

8305270408 LER 83-039/03L-0 on 830419,diesel generator starting time exceeded surveillance requirement Caused by relay K-8 not reset Relay manually cycled W/830519 ltr
RAY,H B Southern California Edison Co 83/05/19 MARTIN,J B Region 5, Office of Director 4pp 18642 317 24X
Fiche 50-361,83/05/19,8305270408

8305270131 LER 83-042/03L-0 on 830422,during operability testing, emergency chiller E-335 (train B) stalled Caused by valve closed on surge line due to low compressor suction pressure Valve opened.W/830520 ltr
RAY,H B Southern California Edison Co 83/05/20 MARTIN,J B Region 5, Office of Director 4pp 18638 210 24X
Fiche 50-361,83/05/20,8305270131

DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

8305060683 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision
KNIGHTON,G W Licensing Branch 3 83/04/27 DIETCH,R Southern California Edison Co 5pp 18357 314 24X Fiche 50-361,83/04/27, 8305060683

--8305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15,respectively, modifying emergency preparedness license conditions imposed by ASLAB 830304 decision.
EISENHUT,D G Division of Licensing 83/04/27 4pp 18357 318 24X Fiche 50-361,83/04/27,8305060683

--8305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15,respectively.
* NRC - No Detailed Affiliation Given 83/04/27 1p 18357 322 24X Fiche 50-361,83/04/27,8305060683

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21)
NORDERHAUG,L R Region 5, Office of Director 83/05/12 PAPAY,L T Southern California Edison Co 2pp 18599 322 24X
Fiche 50-206,83/05/12,8305260242

8305170471 Responds to Generic Ltr 82-33 (NUREG-0737,Suppl 1) re emergency response capability requirements Progress in areas of safety parameter display sys,detailed control room design reviews & emergency response facilities summarized
BASKIN,K P Southern California Edison Co 83/05/13 EISENHUT,D G Office of Nuclear Reactor Regulation, Director 8pp 18470 077 24X Fiche 50-361,83/05/13,8305170471

G Adjudicatory correspondence

8305100199 Discusses Memorandum & Order CLI-83-10 re arrangements required under regulations for medical svc for contaminated-injured individuals No further evidentiary hearing required
CHANDLER,L J Office of the Executive Legal Director 83/04/25 BROWN,R F California, Univ of, San Francisco 1p 18374 199 24X Fiche 50-361,83/04/25,8305100199

8305100220 Advises that no further evidentiary hearing required to determine compliance w/Commission regulations re medical svcs for contaminated injured individuals Issue can be resolved on basis of written submission
CHANDLER,L J Hearings Division 83/04/25 NEBBITT,W Affiliation Unknown 1p 18373 319 24X Fiche 50-361,83/04/25,8305100220

8305190195 Proposed findings of fact & conclusions of law Declaration of Svc encl
PIGOTT,D R Southern California Edison Co PIGOTT,D R Orrick, Herrington & Sutcliffe 83/05/16 5pp 18500 001 24X
Fiche 50-361,83/05/16,8305190195

8305190212 Motion to augment record to include various revised county emergency plans & other documents re emergency planning Decisions should reflect current info Declaration of Svc encl
PIGOTT,D R Southern California Edison Co PIGOTT,D R Orrick, Herrington & Sutcliffe 83/05/16 Atomic Safety and Licensing Board Panel 33pp 18502 146 24X Fiche 50-361,83/05/16, 8305190212

8305190252 Position re Commission 830405 Memorandum & Order CLI-83-10 on offsite medical svcs Util provided necessary level of medical svcs for general public Declaration of Svc encl
PIGOTT,D R Southern California Edison Co 83/05/16 9pp 18501 284 24X Fiche 50-361,83/05/16,8305190252

8305240522 Order extending time until 830607 for Commission to act to review petitions for review of ALAB-717
CHILK,S J Office of the Secretary of the Commission 83/05/20 Commissioners 1p 18571 118 24X Fiche 50-361,83/05/20, 8305240522

H General correspondence

8305090024 Addl response to FOIA request for documents re 821130 special insp rept Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6). Documents 3 & 4 withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/21 GARDE,B Government Accountability Project 4pp 18381 158 24X
Fiche 50-206,83/03/21,8305090024

8305120178 Advises that organizational change shifted responsibility for nuclear matters from engineering div to power supply div JC Holcomba replaces GD Cotton as representative authorized to sign NRC licensing documents
HOLCOMBE,J C. San Diego Gas & Electric Co 83/05/06 EISENHUT,D G Division of Licensing 1p 18427 156 24X Fiche 50-206,83/05/06, 8305120178

P Operating license stage documents & correspondence

8305060683 Forwards Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively & notice of issuance & availability Amends modify emergency preparedness license conditions imposed by ASLAB 830304 decision
KNIGHTON, G W Licensing Branch 3 83/04/27 DIETCH, R Southern California Edison Co COTTON, G D , BERNATH, L San Diego Gas & Electric Co 5pp 18357 314 24X Fiche 50-361, 83/04/27, 8305060683

--8305060694 Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively, modifying emergency preparedness license conditions imposed by ASLAB 830304 decision
EISENHUT, D G Division of Licensing 83/04/27 4pp 18357 318 24X Fiche 50-361, 83/04/27, 8305060683

--8305060703 Notice of issuance & availability of Amends 18 & 6 to Licenses NPF-10 & NPF-15, respectively
* NRC - No Detailed Affiliation Given 83/04/27 1p 18357 322 24X Fiche 50-361, 83/04/27, 8305060683

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000, 83/05/02, 8305020455

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing. 83/05/04 PALLADINO, N Commissioners 22pp. 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305170229 Forwards Amends 19 & 7 to Licenses NPF-10 & NPF-15, respectively, safety evaluation & notice of issuance & availability. Amends modify Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation
KNIGHTON, G W Licensing Branch 3, 83/05/04 DIETCH, R. Southern California Edison Co CATTON, G D , BERNATH, L San Diego Gas & Electric Co 3pp 18476 349 24X Fiche 50-361, 83/05/04, 8305170229

--8305170233 Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively, modifying Tech Specs re radioactive liquid effluents & effluent monitoring instrumentation to add steam generator blowdown pass line as alternative release path
EISENHUT, D G Division of Licensing 83/04/29 10pp 18476 352 24X Fiche 50-361, 83/05/04, 8305170229

--8305170234 Safety evaluation supporting Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/29 8pp 18476 362 24X Fiche 50-361, 83/05/04, 8305170229

--8305170236 Notice of issuance & availability of Amends 17 & 5 to Licenses NPF-10 & NPF-15, respectively
KNIGHTON, G. W Licensing Branch 3 83/04/29 2pp 18477 008 24X Fiche 50-361, 83/05/04, 8305170229

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp. 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305260122 Comments on 830106 proposal to delete integral test of core protection calculator functional capability from natural circulation test Alternate demonstration of functional capability requested.
NOVAK, T M Assistant Director for Licensing 83/05/12 DIETCH, R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 6pp 18649 059 24X Fiche 50-361, 83/05/12, 8305260122

8305190028 Responds to Generic Ltr 83-10A re resolution of TMI Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps " Util, as member of C-E Owners Group, has chosen "trip two, leave two" strategy to resolve item
BASKIN, K. P Southern California Edison Co. 83/05/13 KNIGHTON, G W Licensing Branch 3 2pp 18502.039 24X Fiche 50-361, 83/05/13, 8305190028

8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs.
NOVAK, T M Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X Fiche 50-000, 83/05/18, 8305250209

--8305250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ASLAB
MATTSON, R. J Division of Systems Integration (post 811005) 83/04/28 EISENHUT, D G Division of Licensing 1p 18627 113 24X Fiche 50-000, 83/05/18, 8305250209

--8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630
DIRCKS, W J. Office of the Executive Director for Operations 83/04/25 CHILK, S J Office of the Secretary of the Commission 1p. 18627. 115 24X Fiche 50-000, 83/05/18, 8305250209

8305240458 Forwards status of environ qualification of electrical equipment per 10CFR50 49(g) All equipment, except auxiliary feedwater pump motors, meets NUREG-0588 guidelines for Category II plant
BASKIN, K P Southern California Edison Co 83/05/20 KNIGHTON, G W Licensing Branch 3 5pp 18549 286 24X Fiche. 50-361, 83/05/20, 8305240458

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305030075 Comments on Mgt Analysis Co 830404 visit to Region V re recent licensee regulatory performance & circumstances which led to proposed issuance of civil penalties against util
CREWS, J L Division of Resident/Reactor Project & Engineering Programs 83/04/13 Division of Resident/Reactor Project & Engineering Programs 1p 18300 178 24X Fiche. 50-361, 83/04/13, 8305030075

8305170417 Forwards IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 & notice of violation
BISHOP, T W Region 5, Office of Director 83/04/14. PAPAY, L T Southern California Edison Co 2pp 18469 253 24X Fiche 50-361, 83/04/14, 8305170417.

--8305170421 IE Insp Repts 50-361/83-13 & 50-362/83-12 on 830312-25 Noncompliance noted: failure to rept reactor trip breaker inoperability & to implement vendor svc bulletin info.
STERNBERG, D M , KIRSCH, D. F , CHAFFEE, A E Region 5, Office of Director 83/04/13 28pp 18469. 258 24X Fiche 50-361, 83/04/14, 8305170417.

8305170474 Forwards IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No noncompliance noted
BISHOP, T W Region 5, Office of Director 83/04/14 PAPAY, L T. Southern California Edison Co 2pp 18470 086 24X Fiche 50-361, 83/04/14, 8305170474

--8305170480 IE Insp Repts 50-361/83-12 & 50-362/83-11 on 830221-0325 No noncompliance noted. Major areas inspected operational safety verification, monthly surveillance, LER review & independent insp effort
PATE, R J , MENDONCA, M M , O'BRIEN, J P. Region 5, Office of Director 83/04/14 4pp 18470 088 24X Fiche. 50-361, 83/04/14, 8305170474

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305170515 Forwards IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 & notice of violation.
SCARANO, R A. Division of Radiological Safety & Safeguards Program 83/04/18 PAPAY, L T. Southern California Edison Co 2pp 18467 260 24X Fiche 50-361, 83/04/18, 8305170515

--8305170521 Notice of violation from insp on 830321-30
WENSLAWSKI, F A Region 5, Office of Director. 83/04/18. 2pp 18467 262 24X Fiche 50-361, 83/04/18, 8305170515

--8305170530 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 Noncompliance noted failure to perform surveys, inform workers & properly monitor liquid radioactive effluent release
YUHAS, G. P , WENSLAWSKI, F A , BOOK, H. E. Region 5, Office of Director 83/04/14 10pp 18467 264 24X Fiche 50-361, 83/04/18, 8305170515

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305170359 Forwards IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08.No noncompliance noted
BISHOP,T W Region 5, Office of Director 83/04/26 PAPAY,L T
Southern California Edison Co 2pp 18466 098 24X
Fiche 50-361,83/04/26,8305170359

--8305170361 IE Insp Repts 50-361/83-18 & 50-362/83-16 on 830404-08 No noncompliance noted.Major areas inspected corrective & preventative maint programs.
ECKHARDT,J H , KIRSCH,D F Region 5, Office of Director
83/04/22 4pp. 18466·100 24X Fiche 50-361,83/04/26,8305170359

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche.50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp. 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305260242 Forwards IE Safeguards Insp Repts 50-206/83-11,50-361/83-20 & 50-362/83-18 on 830425-29 No noncompliance noted Details withheld (ref 10CFR73 21).
NORDERHAUG,L R. Region 5, Office of Director 83/05/12 PAPAY,L T
Southern California Edison Co 2pp 18599.322. 24X
Fiche·50-206,83/05/12,8305260242.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697·009. 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647·007 24X Fiche.50-000,83/05/26,8303040046.

R Periodic operating reports & related correspondence

8304150372 Monthly operating repts for Feb 1983.
MAYWEATHER,L Southern California Edison Co 83/03/15. 11pp
17981 359 24X Fiche.50-361,83/03/15,8304150368

S Reportable occurrences, LERs & related correspondence

8305060448 Forwards revised LER 83-005/01X-1
RAY,H B Southern California Edison Co 83/03/31 ENGELKEN,R H
Region 5, Office of Director 2pp 18343 135 24X
Fiche 50-362,83/03/31,8305060448

--8305060450 Revised LER 83-005/01X-1 on 830222,observed loose snubbers & hangers associated w/two sampling valves (3HV508 & 3HV517) of RCS Caused by removal for maint performed on associated components Snubbers reconnected
RAY,H B Southern California Edison Co 83/03/31 Region 5, Office of Director 3pp 18343 137 24X Fiche 50-362,83/03/31, 8305060448

8305030360 RO high steam generator differential pressure trip function operability requirements exceeded for Modes 1,2 & 3 Setpoints will be corrected before reentry into Mode 3 & will be reported in LER by 830505
RAY,H B Southern California Edison Co 83/04/22 MARTIN,J B
Region 5, Office of Director 2pp 18291 361 24X
Fiche 50-361,83/04/22,8305030360.

8305020183 PNO-V-83-018 on 830421,util received ltr from C-E informing of error in equivalent voltages corresponding to setpoints associated w/steam generator high delta pressure trip function Corrective action being developed
BISHOP,T W Region 5, Office of Director 83/04/25 1p
18277 295 24X Fiche 50-361,83/04/25,8305020183

8305180790 Forwards SER on reactor trip breakers Licensee proposed actions provide acceptable basis for restart & operation
EISENHUT,D G Division of Licensing 83/05/02 DIETCH,R Southern California Edison Co COTTON,G D , BERNATH,L San Diego Gas & Electric Co 3pp 18505 001 24X Fiche 50-361,83/05/02,8305180790

--8305180804 SER lifting restrictions on exceeding power documented in confirmation of action ltrs dtd 830311 & 0429 based on corrective actions re reactor trip breaker failure
* Office of Nuclear Reactor Regulation, Director 83/04/30
58pp 18505 004 24X Fiche 50-361,83/05/02,8305180790

8305160047 Forwards LER 83-035/03L-0
RAY,H B Southern California Edison Co 83/05/03 MARTIN,J B
Region 5, Office of Director 2pp 18453 020 24X
Fiche 50-362,83/05/03,8305160047

--8305160051 LER 83-035/03L-0 on 830404,fire spray sys spuriously actuated Fire detectors inoperable Cause unknown Compensatory measures remained in place until fire spray sys returned to svc on 830416.
RAY,H B Southern California Edison Co 83/05/03 Region 5, Office of Director 1p 18453 022 24X Fiche 50-362,83/05/03, 8305160047

8305160110 Forwards LER 83-033/03L-0
RAY,H B. Southern California Edison Co 83/05/03 MARTIN,J B
Region 5, Office of Director 2pp 18450 093 24X
Fiche 50-362,83/05/03,8305160110

--8305160115 LER 83-033/03L-0 on 830331,fire spray sys that protects control bldg cable riser elevator 30 ft spuriously activated Cause unidentified Corrective action re proper resetting technique to be provided to personnel
RAY,H B Southern California Edison Co 83/05/03 Region 5, Office of Director 1p 18450 095 24X Fiche 50-362,83/05/03, 8305160110

8305160120 Forwards LER 83-036/03L-0
RAY,H B Southern California Edison Co 83/05/03 MARTIN,J B
Region 5, Office of Director 2pp 18448 143 24X
Fiche 50-362,83/05/03,8305160120

--8305160125 LER 83-036/03L-0 on 830308 & 0401,early warning fire detectors in zones 41 & 6,respectively,found inoperable Cause unknown.Detector inoperability under evaluation
RAY,H B Southern California Edison Co 83/05/03 Region 5, Office of Director 1p 18448 145 24X Fiche 50-362,83/05/03, 8305160120

8305160055 Forwards LERs 83-037/01T-0 for Units 1 & 2
RAY,H B Southern California Edison Co 83/05/05. MARTIN,J B.
Region 5, Office of Director 2pp 18451 047 24X
Fiche 50-361,83/05/05,8305160055

--8305160101 LER 83-037/01T-0 on 830421,high steam generator differential pressure setpoint used in PPS emergency feedwater sys logic circuitry resulted in actual trip setpoint 300 psid higher than assumed in FSAR Caused by voltage conversion error
RAY,H B Southern California Edison Co 83/05/05 Region 5, Office of Director 2pp 18451 051 24X Fiche 50-361,83/05/05, 8305160055

8305170278 Confirms no safety-related applications of integral undervoltage trip devices exist other than in reactor trip switchgear, in response to NRC request for info re 830415 reactor trip breaker rept
BASKIN, K P Southern California Edison Co 83/05/13 KNIGHTON, G W Licensing Branch 3 1p 18465 326 24X Fiche 50-361, 83/05/13, 8305170278

8305270157 LER 83-036/03L-0 on 830420, possible problems in source insp, mfg & configuration control of reactor trip circuit breaker supplier identified in QA audit Caused by inadequate supplier QA program for subcontractors W/830520 ltr
RAY, H B Southern California Edison Co 83/05/20 MARTIN, J B Region 5, Office of Director 3pp 18638 067 24X
Fiche 50-362, 83/05/20, 8305270157

DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305060616 Releases public version of revised svc bldg telephone directory
FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18359 116 24X Fiche 50-348, 83/04/26, 8305060616

--8305060621 Forwards public version of revised svc bldg telephone directory to be filed w/Administrative Procedure
FNP-0-EIP-8
HUDSPETH, J B Alabama Power Co 83/04/05 Office of Nuclear Reactor Regulation, Director 2pp 18359 117 24X
Fiche 50-348, 83/04/26, 8305060616

--8305060626 Public version of revised svc bldg telephone directory
* Alabama Power Co 83/03/17 66pp 18359 119 24X
Fiche 50-348, 83/04/26, 8305060616

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240191 Forwards Rev 6 to security plan Rev establishes upper limit of 120 days on interim clearance, per Varga 830105 ltr Rev withheld (ref 10CFR2 790)
CLAYTON, F L Alabama Power Co 83/05/12 O'REILLY, J P Region 2, Office of Director 1p 18548 031 24X Fiche 50-348, 83/05/12, 8305240191

8305250285 Forwards response to 830204 SERs & NRC 830412 ltr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included
CLAYTON, F L Alabama Power Co 83/05/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 118 p 18696 251 24X
Fiche 50-348, 83/05/20, 8305250285

8305250391 Responds to NRC request to evaluate adding RCS cold leg temp indication & source range neutron monitor to hot shutdown panels per 10CFR50, App R Addition of RCS appropriate mod Source range neutron monitor too costly
CLAYTON, F L Alabama Power Co 83/05/20 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 18585 337 24X
Fiche 50-348, 83/05/20, 8305250391

I Financial information

8305240481 Forwards Annual Financial Rept 1982 & related financial info to satisfy retrospective premium guarantee required under Price-Andersen Act
BOWDEN, T J Alabama Power Co 83/05/20 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 16pp 18572 113 24X
Fiche 50-348, 83/05/20, 8305240481

--8305240484 Annual Financial Rept 1982
FARLEY, J M Alabama Power Co 83/03/04 40pp 18572 129 24X
Fiche 50-348, 83/05/20, 8305240481

J Insurance & indemnity information

8305040180 Forwards Endorsements 52 & 43 to NELIA Policy NF-238 & MAELU Policy MF-93, respectively
DUCK, J R Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18324 034 24X
Fiche 50-348, 83/04/28, 8305040180.

P Operating license stage documents & correspondence

8305020456 Advises of active negotiation w/DOE on agreement for disposal of spent nuclear fuel &/or high level radwaste per Generic Ltr 83-07 Comments on draft std disposal contract & proposed disposal rulemaking encl
CLAYTON, F L Alabama Power Co 83/04/25 VARGA, S A Office of Nuclear Reactor Regulation, Director 12pp 18282 347 24X
Fiche 50-348, 83/04/25, 8305020456

8305170659 Forwards supplemental BER input re turbine valve testing Interval between periodic turbine valve tests can be increased from weekly to monthly on interim basis, pending establishment of new probabilistic turbine missile position
VARGA, S A Operating Reactors Branch 1 83/04/29 CLAYTON, F L Alabama Power Co 9pp 18481 063 24X Fiche 50-364, 83/04/29, 8305170659

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 30pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305110308 Application for amend to OLs revising Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions
CLAYTON, F L Alabama Power Co 83/05/03 VARGA, S A Office of Nuclear Reactor Regulation, Director 5pp 18393 198 24X
Fiche 50-348, 83/05/03, 8305110308

--8305110311 Proposed changes to Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 increasing confidence of battery operability & providing time to correct certain battery conditions w/o undue plant shutdown
* Alabama Power Co 83/05/03 19pp 18393 203 24X
Fiche 50-348, 83/05/03, 8305110308

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305240440 Advises that operator training program procedures re natural circulation cooldown (Generic Ltr 81-21), based on Westinghouse Owners Group guidelines, will be incorporated by 830615 Training will be completed by 830519
CLAYTON, F L Alabama Power Co 83/05/18 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 18573 131 24X
Fiche 50-348, 83/05/18, 8305240440

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270358 Forwards IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/30
MCDONALD, R P Alabama Power Co 2pp 18642 096 24X
Fiche, 50-348, 83/03/30, 8305270358

--8305270370 IE Insp Repts 50-348/83-10 & 50-364/83-08 on 830216-0305 No noncompliance noted Major areas inspected monthly maint & surveillance, operational safety, independent insp effort, refueling & IE Bulletin 82-04 followup
BRADFORD, W H , RULAND, W H Region 2, Office of Director
CANTRELL, F S Division of Project & Resident Programs 83/03/29 8pp 18642 098 24X Fiche, 50-348, 83/03/30, 8305270358

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp, 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp, 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/06 Consolidated Edison Co, of New York, Inc 115pp, 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160094 Discusses actions taken to identify & resolve potential DS-416 reactor trip breaker problems per IE Bulletin 83-01 Schedule,w/finalized implementation dates,to be submitted by 830531 Emergency operating procedures encl
CLAYTON,F L Alabama Power Co 83/05/10 VARGA,S A Office of Nuclear Reactor Regulation, Director 7pp 18450 206 24X Fiche 50-348,83/05/10,8305160094

--8305160100 Rev 6 to Emergency Operating Procedure FNP-1-EOP-5 0, "Reactor Trip."
* Alabama Power Co 83/05/09 6pp 18450 213 24X Fiche 50-348,83/05/10,8305160094

--8305160107 Rev 6 to Emergency Operating Procedure FNP-1-EOP-15 0, "Anticipated Transients W/o Trip (ATWT) "
* Alabama Power Co 83/05/10 5pp 18450 219 24X Fiche.50-348,83/05/10,8305160094

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007 24X Fiche.50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305200357 Forwards monthly operating rept for Apr 1983
CLAYTON,F.L Alabama Power Co. 83/05/12 Division of Data Automation & Management Information 2pp 18518.096, 24X Fiche:50-364,83/05/12,8305200357

--8305200362 Monthly operating rept for Apr 1983
HAIRSTON,W G. Alabama Power Co, 83/05/02 4pp 18518 098 24X Fiche 50-364,83/05/12,8305200357

8305200579 Forwards monthly status of licensing items,requiring NRC approval,identified in 830113 ltr
CLAYTON,F L Alabama Power Co 83/05/13 VARGA,S A Office of Nuclear Reactor Regulation, Director 6pp 18514 114 24X Fiche 50-348,83/05/13,8305200579

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030580 Forwards LER 83-018/03L-0
CLAYTON,F L Alabama Power Co 83/04/22 Region 2, Office of Director 1p 18305 358 24X Fiche 50-364,83/04/22,8305030580

--8305030589 LER 83-018/03L-0 on 830326,pressurizer heater group 2A declared inoperable when heaters failed to energize Caused by discharge breaker closing springs & out of adjustment microswitch Switch adjusted & breaker cycled
HAIRSTON,W G Alabama Power Co 83/04/22 Region 2, Office of Director 1p 18305 359 24X Fiche 50-364,83/04/22,8305030580

8305100132 Forwards LER 83-019/03L-0
CLAYTON,F L Alabama Power Co 83/05/03 Region 2, Office of Director 1p 18374 358 24X Fiche 50-364,83/05/03,8305100132

--8305100139 LER 83-019/03L-0 on 830404 & 19,rod control sys declared inoperable upon receipt of failure alarm on power cabinet 2AC Following second occurrence,phase control card B2 replaced
HAIRSTON,W G Alabama Power Co 83/05/03 Region 2, Office of Director 2pp 18374 359 24X Fiche 50-364,83/05/03,8305100132

8305110257 Forwards LER 83-021/03L-0
CLAYTON,F L Alabama Power Co 83/05/05 Region 2, Office of Director 1p 18393 179 24X Fiche 50-364,83/05/05,8305110257

--8305110260 LER 83-021/03L-0 on 830411,instrumentation channel associated w/refueling water storage tank water level indicator LI-4075A declared inoperable due to low indication Cause not determined
HAIRSTON,W G Alabama Power Co 83/05/05 Region 2, Office of Director 1p 18393 180 24X Fiche 50-364,83/05/05,8305110257

8305310201 Comments on adequacy of current facility DS-416 reactor trip breakers Breaker configuration modified based on dimensional alignment & extensive testing Safe operation not adversely impacted by breakers
CLAYTON,F L Alabama Power Co 83/05/26 VARGA,S A Office of Nuclear Reactor Regulation, Director 2pp 18658 157 24X Fiche 50-348,83/05/26,8305310201

DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

8305030685 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p. 18309 141 24X Fiche 50-321,83/04/25, 8305030685

--8305030687 Forwards public version of revised emergency plan implementing procedures,including Procedures HNP-4734 re general emergency - Savannah River Operations Ofc & HNP-4527 re alert - security force
NIX,H C Georgia Power Co 83/04/07 Office of Nuclear Reactor Regulation, Director 1p 18309 142 24X Fiche 50-321,83/04/25, 8305030685

--8305030690 Public version of revised emergency plan implementing procedures,including Procedures HNP-4734 re general emergency - Savannah River Operations & HNP-4527 re alert - security force
ROGERS,W H , NIX,H Georgia Power Co 83/04/04 50pp 18309 143 24X Fiche 50-321,83/04/25,8305030685

8305040648 Releases public version of revised pages to emergency plan
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18336 275 24X Fiche 50-321,83/04/25, 8305040648

--8305040654 Forwards public version of revised Pages C-3 & P-1 to emergency plan
OLLINGER, W H Georgia Power Co 83/03/31 NRC - No Detailed Affiliation Given 1p 18336 276 24X Fiche 50-321, 83/04/25, 8305040648

--8305040659 Public version of revised Pages C-3 & P-1 to emergency plan
* Georgia Power Co 83/02/28 2pp 18336 277 24X Fiche 50-321, 83/04/25, 8305040648

8305060469 Clarifies requests for exemptions from 10CFR50 48 & App R requirements in response to NRC request at 830330 meeting Rev to 820701 response to be submitted by 830530
GUCWA, L T Georgia Power Co 83/04/28 STOLZ, J F Operating Reactors Branch 4 11pp. 18351 179 24X Fiche 50-321, 83/04/28, 8305060469

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034.

8305250530 Submits info on compliance w/Branch Technical Position 9 5-1 re qualification of fire protection engineers Qualification requirements met through maint of staff at affiliated svc company, Southern Co Svcs, Inc
GUCWA, L T Georgia Power Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18588 229 24X Fiche 50-321, 83/05/19, 8305250530

H General correspondence

8305030261 Requests changes in correspondence routines due to recent mgt changes
GUCWA, L T Georgia Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18300 046 24X Fiche 50-000, 83/04/28, 8305030261

J Insurance & indemnity information

8305040202 Forwards Endorsement 78 to NELIA Policy NF-215 & Endorsement 63 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc 83/04/28 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 18324 028 24X Fiche 50-321, 83/04/28, 8305040202

8305200270 Forwards Endorsement 79 to NELIA Policy NF-215 & Endorsement 64 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc. 83/05/16 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18516 256 24X Fiche, 50-321, 83/05/16, 8305200270

8305230027 Forwards Endorsement 80 to NELIA Policy NF-215 & Endorsement 66 to MAELU Policy MF-78
DUCK, J R Marsh & McLennan, Inc 83/05/16 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp. 18539 180 24X Fiche: 50-321, 83/05/16, 8305230027

P. Operating license stage documents & correspondence

8304120027 Forwards revised order confirming licensee commitments on post-TMI-related issues, correcting info re implementation schedule for Item II B 3, "Post-Accident Sampling "
STOLZ, J F Operating Reactors Branch 4. 83/03/30 BECKHAM, J T Georgia Power Co 4pp. 17957 320 24X Fiche 50-321, 83/03/30, 8304120027

--8304120042 Order revising schedule for submittal of info re Item II.B 3, "Post-Accident Sampling," from 830401 to 830701
PURPLE, R A Division of Licensing 83/03/30 Georgia Power Co 10pp 17957.324 24X Fiche 50-321, 83/03/30, 8304120027.

technical evaluation rept re
tor Operator & Senior
aining for Mitigating
737 requirements.
83/04/20 BECKHAM, J T
* 50-321, 83/04/20,

on Programs as
chnical

07/01 NRC -
X

8305030634 Application to amend Licenses DPR-57 & NPF-5, revising Tech Specs re TMI Action Plan Items I A 1 1 3, I A 1 3, II E 4.1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4
BECKHAM, J T Georgia Power Co 83/04/22 STOLZ, J F Operating Reactors Branch 4. 8pp 18305 285 24X Fiche 50-321, 83/04/22, 8305030634

--8305030665 Revised Tech Specs re TMI Action Plan Items I A.1 1.3, I A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II.K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4
* Georgia Power Co 83/04/22 31pp 18305 293 24X Fiche 50-321, 83/04/22, 8305030634

8305040748 Summary of 830223-24 meetings w/util & EG&G in Atlanta, GA re proposed radiological effluent Tech Specs
RIVENBARK, G W Operating Reactors Branch 4 83/04/22. STOLZ, J F. Operating Reactors Branch 4 15pp 18327 179 24X Fiche, 50-321, 83/04/22, 8305040748

8305060671 Forwards EG&G 830404 ltr transmitting list of NRC comments on unresolved items from proposed radiological effluent Tech Specs Earlier scheduled date for final submittal requested
STOLZ, J F Operating Reactors Branch 4 83/04/22 BECKHAM, J T. Georgia Power Co 2pp 18358 001 24X Fiche 50-321, 83/04/22, 8305060671

--8304220257 Forwards list of major radiological effluent Tech Spec items from licensee proposal that were not resolved at Atlanta meeting Differences between Unit 1 & Unit 2 proposals are minor Commitment date for next submittal not identified.
SERRANO, W EG&G, Inc 83/04/04 WILLIS, C A NRC - No Detailed Affiliation Given 3pp 18358.003 24X Fiche 50-321, 83/04/22, 8305060671

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02. Consolidated Edison Co of New York, Inc 50pp 18441·120 24X Fiche, 50-000, 83/05/02, 8305020455

8305060306 Requests that portion of 830422 response to Generic Ltr 83-02 be withdrawn Portion re Item II F 1, "Addl Accident Monitoring Instrumentation," will be reevaluated upon receipt of NRC guidance.
GUCWA, L T Georgia Power Co 83/05/02 STOLZ, J F Operating Reactors Branch 4 1p 18344 323 24X Fiche 50-321, 83/05/02, 8305060306

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT, D G Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305160159 Amends 830330 submittal re extension of MALPHGR limits. ECCS analysis results justify operation of all facility fuel types at exposures greater than 30,000 MWd/st
GUCWA, L T Georgia Power Co 83/05/10 STOLZ, J F Operating Reactors Branch 4 2pp. 18446;083 24X Fiche, 50-366, 83/05/10, 8305160159

8305200453 Commits to submit results of plant-unique calculations re acceptability of mod to torus vacuum breakers by 830615, in response to Generic Ltr 83-08
GUCWA, L T Georgia Power Co 83/05/16 STOLZ, J F Operating Reactors Branch 4. 1p 18519 085 24X Fiche 50-321, 83/05/16, 8305200453

8305240250 Advises that startup expected to occur between 830607-14 assuming resolution of outstanding licensing issues. Unknowns still exist in schedule due to existence of pipe flaw indications Draft rept on weld repairs expected by 830530.
GUCWA, L T Georgia Power Co. 83/05/19. STOLZ, J F. Operating Reactors Branch 4 1p 18548·307 24X Fiche·50-366, 83/05/19, 8305240250.

8305260298 Submits QE info assuring that crud-induced local corrosion failures will not occur during Cycle 4, in response to NRC 830519 request
GUCWA, L T Georgia Power Co 83/05/20. STOLZ, J F. Operating Reactors Branch 4 1p. 18626 264. 24X Fiche 50-366, 83/05/20, 8305260298

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270491 Ack receipt of 830328 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-02
DANCE, H C Division of Project & Resident Programs 83/04/07
KELLY, R J Georgia Power Co 1p 18646 072 24X
Fiche 50-366,83/04/07,8305270491

--8305270508 Responds to NRC 830225 ltr re violations noted in IE Insp Rept 50-366/83-02 Corrective actions personnel to evaluate actions taken for both units if event affects shared equipment & shift
HEAD, G F Georgia Power Co 83/03/28 O'REILLY, J P Region 2, Office of Director. 2pp 18646 073 24X Fiche 50-366,83/04/07, 8305270491

--8305270523 Forwards IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/02/25
KELLY, R J Georgia Power Co 2pp 18646 075 24X
Fiche 50-366,83/04/07,8305270491

--8305270536 Notice of violation from insp on 821220-830121
* Region 2, Office of Director 83/02/25, 1p 18646 077 24X
Fiche: 50-366,83/04/07,8305270491

--8305270550 IE Insp Repts 50-321/83-02 & 50-366/83-02 on 821220-830121 Noncompliance noted failure to make 24-h telephone rept within required time limit
CRLENJAK, R V , HOLMES-RAY, P Region 2, Office of Director
BROWNLEE, V L Division of Project & Resident Programs 83/02/23
4pp 18646 078 24X Fiche 50-366,83/04/07,8305270491

8305270570 Requests that docket number in 830322 IE Insp Rept 50-336/83-05 be changed to 50-366/83-05 due to administrative error
DANCE, H C Division of Project & Resident Programs 83/04/08
KELLY, R J Georgia Power Co 1p 18646 113 24X
Fiche. 50-321,83/04/08,8305270570

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089. 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270332 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04.
DANCE, H C. Division of Project & Resident Programs 83/04/27
KELLY, R. J Georgia Power Co 1p 18642.066 24X
Fiche: 50-321,83/04/27,8305270332

--8305270336 Responds to NRC 830318 ltr re violations noted in IE Insp Repts 50-321/83-04 & 50-366/83-04 Corrective actions training directive issued to appropriate personnel stressing prompt notification of unusual event
BECKHAM, J. T. Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director. 2pp 18642 067 24X Fiche 50-321, 83/04/27,8305270332.

--8305270343 Forwards IE Insp Repts 50-321/83-04 & 50-366/83-04 on 830207-11 & notice of violation.
DANCE, H. C. Division of Project & Resident Programs 83/03/18
KELLY, R. J. Georgia Power Co. 2pp 18642:069 24X
Fiche: 50-321,83/04/27,8305270332.

--8305270351 Notice of violation from insp on 830207-11
* Region 2, Office of Director. 83/03/18, 1p 18642 071. 24X
Fiche: 50-321,83/04/27,8305270332

--8305270357 IE Insp Repts 50-321/83-04 & 50-366/83-04 on 830207-11 Noncompliance noted failure to make proper notification to NRC following liquid radwaste release on 821209
WRAY, J R Region 2, Office of Director BARR, K P Division of Emergency Preparedness & Materials Safety 83/03/10 7pp
18642 072 24X Fiche 50-321,83/04/27,8305270332

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 113pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305040711 Notification of 830429 meeting w/util in Atlanta, GA to discuss results of ongoing ultrasonic insp of pipes, details of crack length & depth determinations, proposed repairs & bases for repairs
RIVENBARK, G W Operating Reactors Branch 4 83/04/28. STOLZ, J F Operating Reactors Branch 4 2pp 18328 109 24X
Fiche 50-366,83/04/28,8305040711

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 113pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160144 Submits 30-day response to SER & technical evaluation rept re environ qualification of Class IE equipment (IE Bulletin 79-01B) Final plans for resolving qualification of items in Categories I D, II A & II B will be transmitted by 830520
GUCWA, L T Georgia Power Co 83/05/06 STOLZ, J F Operating Reactors Branch 4 394pp 18444 044 24X Fiche 50-321,83/05/06, 8305160144

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305270350 Forwards IE Insp Repts 50-321/83-11 & 50-366/83-11 on 830411-15 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/11
KELLY, R J Georgia Power Co 2pp 18644 323 24X
Fiche 50-321,83/05/11,8305270350

--8305270356 IE Insp Repts 50-321/83-11 & 50-366/83-11 on 830411-15 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, QA program, design mods, test & experiments program & procurement program
BELISLE, Q A , DEBBAGE, A G , UPRIGHT, C M Region 2, Office of Director 83/05/11 14pp 18644 325 24X Fiche 50-321,83/05/11, 8305270350

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18497 009 24X Fiche 50-000,83/05/19,8303040040

8305270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program
GUCWA, L T Georgia Power Co 83/05/19 STOLZ, J F Operating Reactors Branch 4 1p 18638 217 24X Fiche 50-321,83/05/19, 8305270128

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

8305310073 Submits info re analyses & repairs of large-diameter stainless steel piping welds per inservice insp conducted during 1983 maint/refueling outage identifying unacceptable ultrasonic indications in recirculation & RHR sys
BECKHAM, J T Georgia Power Co 83/05/26 STOLZ, J F Operating Reactors Branch 4 9pp 18655 345 24X Fiche 50-366, 83/05/26, 8305310073

--8305310084 Provides response to IE Bulletin 83-02 re stress corrosion cracking in large-diameter stainless steel recirculation sys piping at BWR plants
BECKHAM, J T Georgia Power Co 83/05/26 O'REILLY, J P Region 2, Office of Director 39pp 18655 354 24X
Fiche 50-366, 83/05/26, 8305310073

--8305310092 Discusses possible imposition of augmented leak detection requirements for RCS due to discovery of unacceptable pipe flaw indications in recirculation & RHR sys Util commitments to incorporate NUREG-0313, Rev 1, Section IV B 1 a 2
BECKHAM, J T Georgia Power Co 83/05/25 STOLZ, J F Operating Reactors Branch 4 2pp 18656 032 24X Fiche 50-366, 83/05/26, 8305310073

--8305310097 Draft Rev A to "Design Rept for Weld Overlay Repairs & Flaw Evaluation in Recirculation & RHR Sys," preliminary rept
GUSTIN, H L NUTECH Engineers, Inc GPC-07-102 RA DRFT 83/05/31 91pp 18656 034 24X Fiche, 50-366, 83/05/26, 8305310073

R Periodic operating reports & related correspondence

8305180279 Forwards monthly operating repts for Apr 1983
NIX, H C Georgia Power Co 83/05/06 Director's Office, Office of Inspection and Enforcement 1p 18490 282 24X
Fiche 50-321, 83/05/06, 8305180279

--8305180284 Monthly operating repts for Apr 1983
REDWANZ, F J Georgia Power Co 83/05/06 12pp 18490 295 24X
Fiche 50-321, 83/05/06, 8305180279

S Reportable occurrences, LERs & related correspondence

8305110375 Forwards revised LER 82-100/03X-1
NIX, H C Georgia Power Co 83/04/26 O'REILLY, J P Region 2, Office of Director 1p 18406 226 24X Fiche 50-366, 83/04/26, 8305110375

--8305110389 Revised LER 82-100/03X-1 on 820828, RCIC sys declared inoperable upon discovery of inoperative switches Caused by failure of switch components due to corrosion & water damage Switches replaced
TIPPS, S B Georgia Power Co 83/04/26 Region 2, Office of Director 3pp 18406:227 24X Fiche 50-366, 83/04/26, 8305110375

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO, S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000, 83/04/26, 8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T, Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000, 83/04/26, 8305120392

8305110410 Forwards LER 83-023/01T-0
NIX, H. C Georgia Power Co 83/04/28 O'REILLY, J P Region 2, Office of Director 1p 18392 004 24X Fiche 50-366, 83/04/28, 8305110410

--8305110417 LER 83-023/01T-0 on 830418, cracklike indications noted on recirculation sys 2B31 endcap-to-manifold weld heat affected zone of weld 2B31-228M-4 Caused undetermined Followup rept to be submitted upon completion of repair
TIPPS, S B Georgia Power Co 83/04/28 Region 2, Office of Director 3pp 18392 005 24X Fiche 50-366, 83/04/28, 8305110410

8305110429 Forwards LER 83-007/03L-0
NIX, H. C Georgia Power Co 83/04/28 O'REILLY, J P Region 2, Office of Director 1p 18404 352 24X Fiche 50-366, 83/04/28, 8305110429

--8305110436 LER 83-007/03L-0 on 830401, RHR flow indicator 2CB2-R004 on remote shutdown panel found to be reading inaccurately, rendering instrument loop inoperable Caused by component failure Defective amplifier card replaced
TIPPS, S B Georgia Power Co 83/04/28 Region 2, Office of Director 3pp 18404 353 24X Fiche 50-366, 83/04/28, 8305110429

8305130235 Forwards LER 83-019/03L-0
NIX, H C Georgia Power Co 83/04/28 O'REILLY, J P Region 2, Office of Director 1p 18440 094 24X Fiche 50-366, 83/04/28, 8305130235

--8305130242 LER 83-019/03L-0 on 830127, during fire protection isolation valve position & lube check Procedure HNP-2-3358, lube oil room deluge sys isolation valve 2U43-F101 found locked closed Cause unknown Valve locked open
TIPPS, S B Georgia Power Co 83/04/28 Region 2, Office of Director 3pp 18440 095 24X Fiche 50-366, 83/04/28, 8305130235

8305170276 Forwards LER 83-027/03L-0
NIX, H C Georgia Power Co 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18465 290 24X Fiche 50-366, 83/05/05, 8305170276

--8305170284 LER 83-027/03L-0 on 830420, during performance of Procedure HNP-2-3752, primary containment RHR valves found leaking in excess of Tech Spec limit Cause under investigation Corrective maint to be performed
TIPPS, S B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp 18465 291 24X Fiche, 50-366, 83/05/05, 8305170276

8305170389 Forwards LER 83-017/03L-0
NIX, H C. Georgia Power Co 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18469 227 24X Fiche 50-366, 83/05/05, 8305170389

--8305170394 LER 83-017/03L-0 on 830406, during HNP-2-3322, w/unit in cold shutdown, HPCI pump discharge valve 2E41-F006 failed to open Caused by loose wire on terminal block inside valve operator Wire tightened Valve cycled
TIPPS, S B Georgia Power Co 83/05/05 Region 2, Office of Director 3pp. 18469.228 24X Fiche 50-366, 83/05/05, 8305170389

8305170481 Forwards LER 83-016/03L-0
NIX, H C Georgia Power Co. 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18470.001 24X Fiche 50-366, 83/05/05, 8305170481

--8305170499 LER 83-016/03L-0 on 830405, MSIV drain valve 2B21-F016 would not close, Caused by dirty torque switch contacts Contacts disconnected, cleaned & retightened Valve cycled properly
SUMNER, H L Georgia Power Co 83/05/05 Region 2, Office of Director 3pp 18470 002 24X Fiche 50-366, 83/05/05, 8305170481.

8305170502 Forwards LER 83-018/03L-0
NIX, H C Georgia Power Co 83/05/05 O'REILLY, J P Region 2, Office of Director 1p 18470 018 24X Fiche 50-366, 83/05/05, 8305170502

--8305170506 LER 83-018/03L-0 on 830406, while performing quarterly core spray pump operability Procedure HNP-2-3201, core spray pump min flow bypass valve 2E21-F013B would not close automatically Caused by bent fingers on torque switch.
TIPPS, S B Georgia Power Co 83/05/05 Region 2, Office of Director. 3pp 18470 019 24X Fiche, 50-366, 83/05/05, 8305170502

8305110364 RO 50-366/83-01 on 830125 & 0314, Units 2 & 1, respectively, had spray/sprinkler sys taken out of svc for mods & could not be restored to operable status within 14 days per Tech Specs. Continuous fire watches maintained
NIX, H C Georgia Power Co 83/05/06 O'REILLY, J P. Region 2, Office of Director 3pp 18406.262 24X Fiche 50-321, 83/05/06, 8305110364

8305230463 Forwards LER 83-015/01T-0
NIX, H C Georgia Power Co 83/05/09 O'REILLY, J P Region 2, Office of Director 1p 18537 345 24X Fiche, 50-366, 83/05/09, 8305230463

--8305230468 LER 83-015/01T-0 on 830427, during visual exam, damaged pipe supports found on HPCI pump discharge line Cause not determined Discharge pipe & pipe supports being analyzed Pipe supports will be repaired
TIPPS, S B Georgia Power Co 83/05/09 Region 2, Office of Director 3pp 18537 346 24X Fiche, 50-366, 83/05/09, 8305230463

8305230486 Forwards LER 83-022/03L-0
NIX, H. C Georgia Power Co 83/05/09 O'REILLY, J P Region 2, Office of Director 1p 18537:145 24X Fiche 50-366, 83/05/09, 8305230486

--8305230490 LER 83-022/03L-0 on 830413,MSIV leakage bleed valve 2E32-F007 failed to close as required Caused by dirty torque switch inside valve operator 2E32-F007 Torque switch cleaned & valve stroked during maint
TIPPS,S.B Georgia Power Co 83/05/09 Region 2, Office of Director 3pp 18537 146 24X Fiche 50-366,83/05/09,8305230486

8305230495 Forwards LER 83-025/03L-0
NIX,H C. Georgia Power Co 83/05/09 O'REILLY,J P Region 2, Office of Director 1p 18537 179 24X Fiche 50-366,83/05/09, 8305230495

--8305230498 LER 83-025/03L-0 on 830414,during turbine bldg area temp functional test & calibr,monitor 2U61-R002 found out of calibr Caused by setpoint drift of five temp switches & inoperability of one switch Monitor replaced
TIPPS,S.B Georgia Power Co 83/05/09 Region 2, Office of Director, 3pp 18537 180 24X Fiche 50-366,83/05/09,8305230495

8305310124 LER 83-020/03L-0 on 830423,discovered main bearing 11 on upper crank shaft wiped,Caused by lack of lubricating oil at upper crankshaft main bearing 11 Design change (DCR-82-259) completed to improve oil supply W/830517 ltr
TIPPS,S.B , NIX,H C Georgia Power Co 83/05/17 O'REILLY,J P Region 2, Office of Director 4pp 18658 078 24X
Fiche 50-366,83/05/17,8305310124

8305310206 LER 83-030/01T-0 on 830503,during performance of main steam relief valve maint by Wyle Lab,10 steam relief valves found unacceptable Caused by setpoint drift,pilot tube leakage & long delay time W/830517 ltr
TIPPS,S.B , NIX,H C Georgia Power Co 83/05/17 O'REILLY,J P Region 2, Office of Director 4pp 18651 010 24X
Fiche 50-366,83/05/17,8305310206

8305270123 LER 83-029/03L-0 on 830428,safety/relief valve position primary indicators 2B21-N301A & C found to actuate at 91 & 90 5 psig,respectively,contrary to Tech Specs Caused by setpoint drift,Indicators will be replaced W/830519 ltr
TIPPS,S.B , NIX,H C Georgia Power Co 83/05/19 O'REILLY,J P Region 2, Office of Director 4pp 18638 221 24X
Fiche 50-366,83/05/19,8305270123

8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration
HAEBLER,R K. Litton Industries,Inc 83/05/20 KEPPLER,J G Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20, 8305270625

DOCKET 50-367 BAILLY GENERATING STATION

A Application/construction stage documents & correspondence

8305160318 Notification of contract execution,Mod 1 to "Div of Engineering Review Support on Bailly Nuclear Plant I "
Contractor'MT Davisson
FIELDS,J A Technical Assistance Contracts Branch FIN B-7505 83/05/06 VOLLMER,R.H Division of Engineering LEAR,G NRC - No Detailed Affiliation Given, 1p 18472 051 24X
Fiche: 50-367,83/05/06,8305160318

--8305160332 Mod 1,terminating contract & deobligating funds,to "Div of Engineering Review Support on Bailly Nuclear Plant I "
DAVISSON,M T. Darisson, M,T GUSTAVE,R P Division of Contracts FIN B-7505 83/05/06 2pp 18472 052 24X
Fiche 50-367,83/05/06,8305160318

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

8305200326 Forwards list of emergency response open items for which no written response required,Open items resulting from recent emergency exercise will be reflected in future rept
MARSHALL,J R Arkansas Power & Light Co 83/04/08 COLLINS,J T Region 4, Office of Director 2pp. 18516 308 24X
Fiche: 50-313,83/04/08,8305200326

8304270424 Releases public version of revised emergency plan implementing procedures.
FELTON,J.M. Division of Rules and Records. 83/04/22 Document Management Branch 1p. 18244 027 24X Fiche: 50-313,83/04/22, 8304270424

--8304270426 Forwards public version of revised emergency plan implementing procedures,including Procedures 1,2 & 6 re assignment of personnel to emergency response organization, notifications & emergency response ctrs,respectively
MARSHALL,J R Arkansas Power & Light Co 83/04/05 COLLINS,J T Region 4, Office of Director 1p 18244 028 24X
Fiche 50-313,83/04/22,8304270424

--8304270427 Public version of revised emergency plan implementing procedures,including Procedures 1,2 & 6 re assignment of personnel to emergency response organization,notifications & emergency response ctrs,respectively
* Arkansas Power & Light Co 83/03/07 86pp 18244 029 24X
Fiche 50-313,83/04/22,8304270424

8305060575 Releases public version of revised emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18359 190 24X Fiche 50-313,83/04/25, 8305060575

--8305060583 Forwards public version of revised Emergency Plan Implementing Procedures 1904 06 re radiological plume tracking & dose integration & 1904 06 re protective action recommendations
* Arkansas Power & Light Co 83/04/14 NRC - No Detailed Affiliation Given 1p 18359 191 24X Fiche 50-313,83/04/25, 8305060575

--8305060591 Public version of revised Emergency Plan Implementing Procedures 1904 06 re radiological plume tracking & dose integration & 1904 07 re protective action recommendations
LEVINE,J M Arkansas Power & Light Co 83/04/14 8pp 18359 192 24X Fiche 50-313,83/04/25,8305060575

8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months
CLARK,R A Operating Reactors Branch 3 83/04/29 GRIFFIN,J
Arkansas Power & Light Co 4pp 18434 262 24X
Fiche 50-313,83/04/29,8305110193

--8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6,respectively, changing Tech Specs to require annual audits of emergency programs & security plan
CLARK,R A Operating Reactors Branch 3 83/04/29 9pp 18434 266 24X Fiche 50-313,83/04/29,8305110193

--8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6,respectively
CLARK,R A Operating Reactors Branch 3 83/04/29 2pp 18434 275 24X Fiche 50-313,83/04/29,8305110193

8305160288 Releases public version of revised nuclear contingency plan procedures
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18462 334 24X Fiche 50-313,83/05/02, 8305160288

--8305160290 Forwards public version of revised Nuclear Contingency Plan Procedures 1,2,3,5,6,7,8,9,12,13,14 & 15 W/o encl
MARSHALL,J R. Arkansas Power & Light Co 83/04/05 COLLINS,J T Region 4, Office of Director. 1p 18462 335 24X
Fiche 50-313,83/05/02,8305160288

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305180161 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," complete
STOLZ,J F Operating Reactors Branch 4 CLARK,R A Operating Reactors Branch 3 83/05/11 GRIFFIN,J M Arkansas Power & Light Co 3pp 18502 349 24X Fiche 50-313,83/05/11,8305180161

H General correspondence

8305240139 Advises that correspondence distribution to Region IV will be modified to original plus three copies,per B Johnson request
MARSHALL,J R Arkansas Power & Light Co 83/04/22 SEIDLE,W C Region 4, Office of Director 1p 18548 334 24X
Fiche 50-313,83/04/22,8305240139

J Insurance & indemnity information

8305090421 Forwards NELIA & MAELU Certificates of Insurance to comply w/10CFR50 54w Submittals from 830331 & 0422 misinterpreted to comply w/10CFR140 & 140 15a
MARSHALL, J R Arkansas Power & Light Co 83/05/03 STOLZ, J F Operating Reactors Branch 4 COLLINS, J T Region 4, Office of Director DINITZ, I NRC - No Detailed Affiliation Given 6pp 18363 065 24X Fiche 50-313, 83/05/03, 8305090421

8305190363 Forwards NELIA & MAELU secondary financial protection Certificates of Insurance 48 & 68, respectively, for CY83, per 10CFR140 15(a)
MARSHALL, J R Arkansas Power & Light Co 83/05/11 DINITZ, I Antitrust & Economic analysis Branch (Utility Finance) 4pp 18500 032 24X Fiche 50-313, 83/05/11, 8305190363

P Operating license stage documents & correspondence

8305230364 Forwards cost info associated w/backfitting nuclear units, per JL Maulden 830224 commitment
MARSHALL, J R Arkansas Power & Light Co 83/03/11, TOURTELLOTTE, J Regulatory Reform Task Force 11pp 18546 234 24X
Fiche 50-313, 83/03/11, 8305230364

8303240480 Forwards "Structural Evaluation of AR Nuclear One-Unit 1 & Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
MARSHALL, J R Arkansas Power & Light Co 83/03/22 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 17678 109, 24X Fiche 50-313, 83/03/22, 8303240480

--8303240495 "Structural Evaluation of Arkansas Nuclear One-Unit 2 Spent Fuel Storage Facility for Consolidated Fuel Storage "
STURKEY, J J , BALLARD, T. A Structural Dynamics Research Corp APL-02-013 82/11/24 75pp 17678 191 24X
Fiche 50-313, 83/03/22, 8303240480

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11 PALLADINO, N J , GILINSKY, V , AHEARNE, J F Commissioners 2pp 18542 272 24X Fiche 50-000, 83/04/11, 8305230720

8305200580 Forwards list of addl procedures controlling QA measures for threaded fastener lubricants to minimize fastener susceptibility to stress corrosion cracking
MARSHALL, J R Arkansas Power & Light Co 83/04/21 SEIDLE, W. C Region 4, Office of Director 3pp 18514 250 24X
Fiche 50-368, 83/04/21, 8305200580

8305200541 Forwards revised schedule for completion of licensing procedures upgrade, per regulatory response & commitment control program Delay due to continuing support requirements for Unit 1 outage Upgrade to be completed by 830527
MARSHALL, J R Arkansas Power & Light Co 83/04/25 COLLINS, J T Region 4, Office of Director 2pp 18514.264 24X
Fiche 50-313, 83/04/25, 8305200541

8305110625 Forwards corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 83/04/27 GRIFFIN, J M Arkansas Power & Light Co 2pp 18417 357. 24X Fiche 50-313, 83/04/27, 8305110625

--8305110626 Corrected Pages 8 & 15 to safety evaluation supporting Amends 76 & 43 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 83/04/27 2pp 18417 359 24X Fiche 50-313, 83/04/27, 8305110625

8305050125 Ack receipt of 830427 ltr w/corrections to safety evaluation for proposed spent fuel pool storage expansion Statement 15 corrected to indicate divers will not be permitted to exceed 1 rem whole body, per 830428 discussion w/G Vissing
MARSHALL, J R Arkansas Power & Light Co 83/04/28 STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3 1p 18341 347 24X Fiche: 50-313, 83/04/28, 8305050125

8305020416 Acks receipt of 830415 SER & technical evaluation rept re environ qualification of safety-related electrical equipment Category II E items acceptable
MARSHALL, J R. Arkansas Power & Light Co 83/04/29 CLARK, R A Operating Reactors Branch 3 2pp 18273 190 24X
Fiche. 50-368, 83/04/29, 8305020416

8305110193 Forwards Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively & notice of issuance & availability Amends change Tech Specs to require audit of emergency programs & security plan at frequency of at least once per 12 months
CLARK, R A Operating Reactors Branch 3 83/04/29 GRIFFIN, J Arkansas Power & Light Co 4pp 18434 262 24X
Fiche 50-313, 83/04/29, 8305110193

--8305110199 Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively, changing Tech Specs to require annual audits of emergency programs & security plan
CLARK, R A Operating Reactors Branch 3 83/04/29 9pp 18434 266 24X Fiche 50-313, 83/04/29, 8305110193

--8305110205 Notice of issuance & availability of Amends 78 & 44 to Licenses DPR-51 & NPF-6, respectively
CLARK, R A Operating Reactors Branch 3 83/04/29 2pp 18434 275 24X Fiche 50-313, 83/04/29, 8305110193

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441.120 24X
Fiche 50-000, 83/05/02, 8305020455

8305110165 Forwards Amend 45 to License NPF-6, safety evaluation & notice of issuance & availability Amend clarifies & modifies emergency diesel generator load block application timing criteria
TOURIGNY, E G Operating Reactors Branch 3 83/05/03 GRIFFIN, J Arkansas Power & Light Co 3pp 18434 244 24X
Fiche 50-368, 83/05/03, 8305110165

--8305110169 Amend 45 to License NPF-6, revising Tech Specs for emergency diesel generator load block application timing criteria
CLARK, R A Operating Reactors Branch 3 83/05/03 5pp 18434 247 24X Fiche 50-368, 83/05/03, 8305110165

--8305110173 Safety evaluation supporting Amend 45 to License NPF-6
* Office of Nuclear Reactor Regulation, Director. 83/05/03 3pp 18434 252 24X Fiche 50-368, 83/05/03, 8305110165

--8305110176 Notice of issuance & availability of Amend 45 to License NPF-6
TRAMMELL, C. M Operating Reactors Branch 3 83/05/03 2pp 18434 255 24X Fiche 50-368, 83/05/03, 8305110165

8305120504 Forwards Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, safety evaluation & notice of issuance & availability Amends revise Tech Specs to require verification of leak testing of purge valves
CLARK, R A Operating Reactors Branch 3 STOLZ, J. F. Operating Reactors Branch 4 83/05/03 GRIFFIN, J Arkansas Power & Light Co 3pp 18443 141 24X Fiche 50-313, 83/05/03, 8305120504

--8305120506 Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively, revising Tech Specs to require verification of leak rate testing of purge valves
STOLZ, J F Operating Reactors Branch 4 CLARK, R A. Operating Reactors Branch 3 83/05/03 9pp 18443 144 24X
Fiche 50-313, 83/05/03, 8305120504

--8305120508 Safety evaluation supporting Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively
* Office of Nuclear Reactor Regulation, Director 83/05/03 3pp 18443 153 24X Fiche 50-313, 83/05/03, 8305120504

--8305120512 Notice of issuance & availability of Amends 79 & 46 to Licenses DPR-51 & NPF-6, respectively
TRAMMELL, C. M Operating Reactors Branch 3 83/05/03 2pp 18443 156. 24X Fiche 50-313, 83/05/03, 8305120504

8305090333 Forwards responses to NRC 830406 request for addl info re use of RADCAL gamma thermometer (RGT) for inadequate core cooling instrumentation RGT consists of sheathed thermocouples, heater rod, core tube & jacket tube
MARSHALL, J. R Arkansas Power & Light Co 83/05/04 EISENHUT, D G Division of Licensing 8pp 18363:341 24X Fiche 50-313, 83/05/04, 8305090333.

8305100351 Corrects statement in 830328 response to NRC questions re precautions taken to minimize personnel exposure to radiation during spent fuel storage expansion Self-reading dosimeters will be worn outside diving suits, not inside
MARSHALL, J. R Arkansas Power & Light Co 83/05/04 STOLZ, J F Operating Reactors Branch 4 CLARK, R A. Operating Reactors Branch 3. 1p 18379 058 24X Fiche 50-313, 83/05/04, 8305100351.

8305180030 Forwards Amend 47 to License NPF-6, EIA & notice of issuance & negative declaration Amend deletes requirements for remote aerial surveillance monitoring & bird impaction event studies.
LYNCH, D. D Operating Reactors Branch 3 83/05/05 GRIFFIN, J
Arkansas Power & Light Co 4pp 18497 203 24X
Fiche 50-368, 83/05/05, 8305180030

--8305180036 Amend 47 to License NPF-6, deleting Tech Specs for remote aerial surveillance monitoring & bird impaction event studies
CLARK, R A Operating Reactors Branch 3 83/05/05 7pp
18497 207 24X Fiche, 50-368, 83/05/05, 8305180030

--8305180041 EIA supporting Amend 47 to License NPF-6
LYNCH, D D Office of Nuclear Reactor Regulation, Director
83/05/05 3pp 18497 214 24X Fiche 50-368, 83/05/05, 8305180030

--8305180049 Notice of issuance & negative declaration re Amend 47 to License NPF-6
TRAMMELL, C. M. Operating Reactors Branch 3 83/05/05 2pp
18497 217 24X Fiche 50-368, 83/05/05, 8305180030

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implamentation of plant mods. Svc list encl.
EISENHUT, D. G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180849 Notifies of unacceptability of delay of proposed Tech Specs re snubber surveillance in order to include ANSI Std, ANSI/ASME OM4-1982, "Exam & Performance Testing of Nuclear Power Plant Dynamics Restraints (Snubbers) " Std not adopted
STOLZ, J F Operating Reactors Branch 4 CLARK, R A Operating Reactors Branch 3. 83/05/09 GRIFFIN, J M Arkansas Power & Light Co. 2pp. 18506.024. 24X Fiche 50-313, 83/05/09, 8305180849

8305170622 Forwards list of current unresolved issues for radiological effluent Tech Specs remaining as result of 820622-24 meetings Final submittal requested within 30 days
CLARK, R. A Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4 83/05/10 GRIFFIN, J M Arkansas Power & Light Co 7pp. 18497 001 24X Fiche 50-313, 83/05/10, 8305170622

8305230128 Forwards SER supporting licensee compliance w/NUREG-0737, Item II B 2 2, "Required Plant Mods, " & design review of plant shielding requirements for access to vital areas
CLARK, R A. Operating Reactors Branch 3 STOLZ, J F Operating Reactors Branch 4. 83/05/11. GRIFFIN, J. M Arkansas Power & Light Co. 2pp. 18546.349. 24X Fiche 50-313, 83/05/11, 8305230128

--8305230145 Safety evaluation supporting licensee compliance w/NUREG-0737, Item II. B. 2. "Design Review of Plant Shielding Access to Vital Areas "
* Office of Nuclear Reactor Regulation, Director 83/05/11 2pp
18546.351. 24X Fiche: 50-313, 83/05/11, 8305230128

8305180467 Forwards 15 revised oversize drawings Aperture cards are available in PDR. Drawing transmittal list encl
SHIVELY, C Arkansas Power & Light Co 83/05/12 NRC - No Detailed Affiliation Given. 2pp 18482 129. 24X
Fiche: 50-368, 83/05/12, 8305180467

8305230723 Forwards "Arkansas Nuclear 1 Steam Electric Station, Unit 2, Cycle Three Startup Rept, " summarizing precritical, low power & power escalation testing for period ending 830104
MARSHALL, J. R. Arkansas Power & Light Co 83/05/12 CLARK, R A Operating Reactors Branch 3 1p 18541 096 24X
Fiche: 50-368, 83/05/12, 8305230723

--8305230723 "Arkansas Nuclear 1 Steam Electric Station, Unit 2, Cycle Three Startup Rept, " for period ending 830104
* Arkansas Power & Light Co WP-0676 83/05/12 34pp
18541 097 24X Fiche, 50-368, 83/05/12, 8305230723

8305240360 Informs that response to NUREG-0737, Item II E 1 2, "Emergency Feedwater Sys Automatic Initiation & Flow Indication, " per 830411 request, will be provided by 830614 Change discussed w/E Tourigny
MARSHALL, J R. Arkansas Power & Light Co. 83/05/17 CLARK, R A Operating Reactors Branch 3. 1p 18574 002 24X
Fiche: 50-368, 83/05/17, 8305240360

8305270065 Forwards list of electrical equipment important to safety & schedule for qualification provisions or replacement of remaining equipment, per 10CFR50 49, Aging-related maint/surveillance requirements will be addressed by NRC deadline
MARSHALL, J R. Arkansas Power & Light Co. 83/05/20 STOLZ, J F. Operating Reactors Branch 4 CLARK, R. A Operating Reactors Branch 3 27pp. 18638 252. 24X Fiche, 50-313, 83/05/20, 8305270065

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8304150143 Forwards IE Insp Repts 50-313/83-03 & 50-368/83-03 on 830201-28 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/03/30 GRIFFIN, J M Arkansas Power & Light Co 2pp 17983 226 24X
Fiche 50-313, 83/03/30, 8304150143

--8304150154 IE Insp Repts 50-313/83-03 & 50-368/83-03 on 830201-28 Noncompliance noted failure to adhere to requirements of refueling shuffle procedure, use of unapproved info sources & required verification signatures missing
CALLAN, L J , CUMMINS, J E , JOHNSON, W D Region 4, Office of Director 83/03/24 10pp 17983 231 24X Fiche 50-313, 83/03/30, 8304150143

8305100348 Forwards IE Insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18 & notice of violation
SEIDLE, W C Region 4, Office of Director 83/04/14 GRIFFIN, J M Arkansas Power & Light Co 2pp 18379 019 24X
Fiche 50-313, 83/04/14, 8305100348

--8305100353 Notice of violation from insp on 830314-18
* Region 4, Office of Director 83/04/14 2pp 18379 021 24X
Fiche 50-313, 83/04/14, 8305100348

--8305100361 IE Insp Repts 50-313/83-04 & 50-368/83-04 on 830314-18 Noncompliance noted failure to conduct design change reviews by offsite engineering group & failure to follow procedure re forms used in closeout of design change packages
JAUDON, J P , MURPHY, M E , JOHNSON, W D Region 4, Office of Director 83/04/12 10pp 18379 023 24X Fiche 50-313, 83/04/14, 8305100348

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025.

8305030325 Ack receipt of 830324 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-01 & 50-368/83-01
SEIDLE, W C Region 4, Office of Director 83/04/27 GRIFFIN, J M Arkansas Power & Light Co 1p. 18297 044 24X
Fiche 50-313, 83/04/27, 8305030325

--8305030331 Responds to NRC 830217 ltr re violations noted in IE Insp Repts 50-313/83-01 & 50-368/83-01 Corrective actions revised procedure incorporating three sample requirements into Step 7 2 4 & provided proper training for applicable personnel
MARSHALL, J R Arkansas Power & Light Co 83/03/24 SEIDLE, W C Region 4, Office of Director 3pp 18297.045 24X
Fiche 50-313, 83/04/27, 8305030325

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020436 Forwards IE Insp Rept 50-313/83-06 on 830301-31 & notice of violation.
KELLY, J A Region 4, Office of Director 83/04/28 Region 4, Office of Director 1p 18284 031 24X Fiche 50-313, 83/04/28, 8305020436

--8305020445 Forwards IE Insp Repts 50-313/83-06 & 50-368/83-06 on 830301-31 & notice of violation Notice of violation withheld (ref 10CFR2 790)
SEIDLE,W C Region 4, Office of Director 83/04/18 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18284 032 24X
Fiche 50-313,83/04/28,8305020436

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305120445 Ack receipt of 830406 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/82-36 & 50-368/82-37
SEIDLE,W C Region 4, Office of Director 83/05/06 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18431 072 24X
Fiche 50-313,83/05/06,8305120445

--8305120451 Responds to NRC 830309 ltr re violations noted in IE Insp Repts 50-313/82-36 & 50-368/82-37 Corrective actions Form 1609 010A re calculation of max permissible concentration revised to require health physics supervisor signature
MARSHALL,J R Arkansas Power & Light Co 83/04/06 SEIDLE,W C
Region 4, Office of Director 4pp 18431 074 24X
Fiche 50-313,83/05/06,8305120445

8305230337 Forwards IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No noncompliance noted
SEIDLE,W C Region 4, Office of Director 83/05/06 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18538 256 24X
Fiche 50-313,83/05/06,8305230337

--8305230348 IE Insp Repts 50-313/83-07 & 50-368/83-07 on 830418-22 No noncompliance noted Major areas inspected test & experiment & procurement programs & receipt,storage & handling of equipment & matls program
JAUDON,J P , JOHNSON,W D Region 4, Office of Director 83/05/03
6pp 18538 258 24X Fiche 50-313,83/05/06,8305230337

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305200313 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-02 & 50-368/83-02
SEIDLE,W C Region 4, Office of Director 83/05/13 GRIFFIN,J M
Arkansas Power & Light Co 2pp, 18517 056 24X
Fiche 50-313,83/05/13,8305200313

--8305200319 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-313/83-02 & 50-368/83-02 Corrective actions administrative controls implemented to provide adequate procedural controls re safety-related equipment
MARSHALL,J R Arkansas Power & Light Co 83,04/27 SEIDLE,W C
Region 4, Office of Director 4pp 18517 058 24X
Fiche 50-313,83/05/13,8305200313

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240049 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-03 & 50-368/83-03 Addl info re order/sequence & temporary placement of fuel assemblies requested
SEIDLE,W C Region 4, Office of Director 83/05/19 GRIFFIN,J M
Arkansas Power & Light Co 2pp 18549 125 24X
Fiche 50-313,83/05/19,8305240049

--8305240054 Responds to NRC 830330 ltr re violations noted in IE Insp Repts 50-313/83-03 & 50-368/83-03 Corrective actions: Procedure 1000 36, "Control of Miscellaneous Info Sources," reviewed w/personnel by dept heads to establish compliance
MARSHALL,J R Arkansas Power & Light Co 83/05/02 SEIDLE,W C
Region 4, Office of Director 6pp 18549 127 24X
Fiche 50-313,83/05/19,8305240049

8305310194 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-04 & 50-368/83-04
SEIDLE,W C Region 4, Office of Director 83/05/25 GRIFFIN,J M
Arkansas Power & Light Co 1p 18658 152 24X
Fiche 50-313,83/05/25,8305310194

--8305310199 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-313/83-04 & 50-368/83-04 Corrective actions Rev 5 to QA topical rept,reflecting design activity changes,will be submitted for approval by 830610
MARSHALL,J R Arkansas Power & Light Co 83/05/12 SEIDLE,W C
Region 4, Office of Director 3pp 18658 153 24X
Fiche 50-313,83/05/25,8305310194

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R. Periodic operating reports & related correspondence

8305200573 Submits third monthly status rept re regulatory response & commitment control program Info consists of progress made in areas of verification of implementation of commitments since 790101 & procedure rev tracking
MARSHALL,J R Arkansas Power & Light Co 83/04/14 COLLINS,J T
Region 4, Office of Director 3pp 18514.274 24X
Fiche 50-368,83/04/14,8305200573

S Reportable occurrences, LERs & related correspondence

8305200445 Forwards NPDES noncompliance rept,per Permit AR0001392
MARSHALL,J R Arkansas Power & Light Co 83/04/04. COLLINS,J T
Region 4, Office of Director 1p 18516 109 24X
Fiche 50-313,83/04/04,8305200445

--8305200451 NPDES noncompliance rept on 830323,discovered oil & grease concentrations from Outfall 003 exceeded Permit AR0001392 limits Caused by startup activities on Unit 1 Rev of operating procedures being considered to prevent recurrence
CAVANAUGH,W Arkansas Power & Light Co 83/03/30 WHITTINGTON,D
Region 4, Office of Director 2pp 18516 110 24X
Fiche 50-313,83/04/04,8305200445

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch, 83/04/19,
SEYFRIT,K V Reactor Operations Analysis Branch 1p 18541:342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343 24X Fiche 50-000,83/04/19,8305230573.

8305260260 NPDES noncompliance notification on 830413,routine analysis revealed average oil & grease concentration of 25 mg/l & pollutant load of 27 9 lb per day Caused by bearing failure on turbine Bearing repaired W/830426 ltr
GRIFFIN,J , MARSHALL,J R Arkansas Power & Light Co 83/04/20
COLLINS,J T Region 4, Office of Director WHITTINGTON,D
Environmental Protection Agency 3pp 18629 074 24X
Fiche 50-313,83/04/20,8305260260

8305020373 Forwards LER 83-014/01T-0
MARSHALL,J R Arkansas Power & Light Co 83/04/25 SEIDLE,W C
Region 4, Office of Director, 1p 18276 309 24X
Fiche:50-368,83/04/25,8305020373

--8305020378 LER 83-014/01T-0 on 830411, response times of two RCS resistance temp detectors found badly degraded Caused by degradation of couplant (Never-Seer) used in mating resistance temp detectors into thermowells
ROGERS, P Arkansas Power & Light Co 83/04/25 Region 4, Office of Director 2pp 18276 310 24X Fiche 50-368, 83/04/25, 8305020373

8305200490 NPDES noncompliance notification on 830413, sample from Outfall 003, oily water separator, revealed average oil & grease concentration of 25 mg/l & pollutant load at 27 9 lbs per day Caused by bearing failure on Unit 1 turbine
MARSHALL, J R Arkansas Power & Light Co 83/04/26 COLLINS, J T Region 4, Office of Director 3pp 18514 036 24X
Fiche 50-313, 83/04/26, 8305200490

8305260249 Telecopy LER 83-020/01T-0 on 830519, fire watch posted in wrong location for period exceeding Tech Spec limit Further details will be provided
LEVINE, J. M Arkansas Power & Light Co 83/05/19 COLLINS, J Region 4, Office of Director 1p 18626 323 24X
Fiche 50-368, 83/05/19, 8305260249

DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8305040584 Releases public version of rev to emergency plan implementing procedures
FELTON, J. M Division of Rules and Records 83/04/26 Document Management Branch 1p 18336 139 24X Fiche 50-369, 83/04/26, 8305040584

--8305040597 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general emergency
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18336 140 24X Fiche 50-369, 83/04/26, 8305040584

--8305040606 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general emergency
GLOVER, M B Duke Power Co 83/02/24 77pp 18336 142 24X
Fiche 50-369, 83/04/26, 8305040584

8305050135 Forwards Rev 15 to security plan, including implementation of Unit 2 vital access, safe shutdown facility & deletion of interim vital areas Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/04/26 O'REILLY, J P Region 2, Office of Director 1p. 18342 239 24X Fiche 50-369, 83/04/26, 8305050135

8305160283 Releases public version of revised emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18472 079 24X Fiche 50-369, 83/05/02, 8305160283

--8305160285 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/03 re site area emergency
TUCKER, H B. Duke Power Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18472·080 24X Fiche 50-369, 83/05/02, 8305160283

--8305160286 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/03 re site area emergency
LEONARD, J R., MCCONNELL, T Duke Power Co 83/02/04 159pp 18472.082 24X Fiche·50-369, 83/05/02, 8305160283

8305130192 Advises of plan to use public address sys for local fire alarms in reactor bldg. Plan meets intent of NFPA 72D-1975 as committed in Section E 1(a) of fire protection review plan NRC approval requested by 830701
TUCKER, H B Duke Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4. 2pp 18439·358. 24X Fiche 50-369, 83/05/06, 8305130192

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G. Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X
Fiche. 50-000, 83/05/11, 8305110034

8305200556 Forwards IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/17
TUCKER, H B Duke Power Co 2pp 18514 266 24X
Fiche 50-369, 83/05/17, 8305200556

--8305200565 IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation, review of security organization & security program audit Details withheld (ref 10CFR73 21)
TILLMAN, A , URYC, B Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/05/17
1p 18514 268 24X Fiche 50-369, 83/05/17, 8305200556

8305250278 Forwards Rev 7 to spent fuel transportation plan Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/05/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18592 362 24X
Fiche 50-369, 83/05/18, 8305250278

J Insurance & indemnity information

8305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101, respectively, for McGuire
LAWSON, L T Duke Power Co 83/05/20 SALTZMAN, J Office of Resource Management, Director 19pp 18626 120 24X
Fiche 50-000, 83/05/20, 8305260261

P Operating license stage documents & correspondence

8303300370 Notification of 830329 meeting w/util in Bethesda, MD to discuss equipment qualification
BIRKEL, R A Licensing Branch 4 83/03/22 ADENSAM, E G Licensing Branch 4 3pp 17754 286 24X Fiche 50-369, 83/03/22, 8303300370

8305050283 Forwards proprietary & nonproprietary versions of attachment to 830314 ltr re Tech Spec change to reduce measurement uncertainty for RCS flow rate Proprietary version withheld (ref 10CFR2 790)
TUCKER, H B Duke Power Co 83/04/26 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 28pp 18337 261 24X Fiche 50-369, 83/04/26, 8305050283

--8305050288 Application for withholding proprietary info re Westinghouse reactor protection sys/ESF actuation sys setpoint methodology (ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp 83/04/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 8pp 18337 289 24X Fiche 50-369, 83/04/26, 8305050283

8305060224 Application for amend to License NPF-9 revising 821123 application re reduced measurement uncertainty for RCS flow rate Amend should also be applied to Unit 2 Tech Specs withheld (ref 10CFR2 790) Class I amend fee encl
TUCKER, H B Duke Power Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 18345 024 24X Fiche 50-369, 83/04/27, 8305060224

8305060413 Forwards addl info re monitoring & testing program for steam generators concerning preheater mod Installation of mod on Unit 2 currently scheduled to begin in mid-June Date tentative depending on Westinghouse schedule
TUCKER, H B Duke Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 18343 259 24X Fiche 50-369, 83/04/28, 8305060413

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305100383 Requests that 830418 proposed amend to Tech Specs to revise setpoint for upper head injection accumulator automatic isolation be changed to incorporate revised setpoint calculation
TUCKER, H B Duke Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4. 2pp 18377 323 24X Fiche 50-369, 83/05/04, 8305100383

--8305100390 Revised proposed Tech Specs changing upper head injection accumulator automatic isolation setpoints to incorporate revised setpoint calculation
* Duke Power Co 83/05/04 1p 18377 325 24X
Fiche 50-369, 83/05/04, 8305100383.

8305100007 Requests approval of revised test method & acceptance criteria for dynamic rod drop test Reply requested by 830511, scheduled date of test
TUCKER, H B Duke Power Co 83/05/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18377 257 24X Fiche 50-369, 83/05/05, 8305100007

8305100347 Forwards addl justification supporting adequacy of test of electrical load to satisfy License Condition 2 C & WCAP-8921, "Setpoint Study, Duke Power, William B McGuire Nuclear Plant, Units 1 & 2 " Rept withheld (ref 10CFR2 790)
TUCKER, H B Duke Power Co 83/05/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18378 325 24X Fiche 50-369, 83/05/05, 8305100347

8305180053 Forwards Amend 21 to License NPF-9, safety evaluation & notice of issuance & availability Amend adds condition for verifying acceptability of Model D2 steam generator mods
ADENSAM, E G Licensing Branch 4 83/05/05 TUCKER, H B Duke Power Co 3pp 18499 307 24X Fiche 50-369, 83/05/05, 8305180053

--8305180058 Amend 21 to License NPF-9, adding condition for verifying acceptability of Model D2 steam generator design mods
EISENHUT, D G Division of Licensing 83/05/05 4pp 18499 309 24X Fiche 50-369, 83/05/05, 8305180053

--8305180066 Safety evaluation supporting Amend 21 to License NPF-9
* Office of Nuclear Reactor Regulation, Director 83/05/05 13pp 18499 313 24X Fiche 50-369, 83/05/05, 8305180053

--8305180072 Notice of issuance & availability of Amend 21 to License NPF-9
ADENSAM, E G Licensing Branch 4 83/05/05 3pp 18499 326 24X Fiche 50-369, 83/05/05, 8305180053

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305170723 Responds to 830311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mods by welding on both units associated w/steam generator D Approach acceptable
NOVAK, T M Assistant Director for Licensing 83/05/09 TUCKER, H B Duke Power Co 4pp 18496 186 24X Fiche 50-369, 83/05/09, 8305170723

--8305170726 SER supporting 830311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mods by welding on both units associated w/steam generator D
* Division of Licensing 83/05/09 3pp 18496 190 24X Fiche 50-369, 83/05/09, 8305170723

--8305170730 Notice of granting of relief from certain requirements of ASME Code Section XI inservice testing requirements
ADENSAM, E G Licensing Branch 4 83/05/10 2pp 18496 193 24X Fiche 50-369, 83/05/09, 8305170723

8305170277 Forwards response to open items identified in Franklin Research Ctr technical evaluation rept re environ qualification of electrical equipment
TUCKER, H B Duke Power Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 29pp 18465 297 24X Fiche 50-369, 83/05/11, 8305170277

8305180791 Requests addl Class I fee for 830311 application for relief from ASME Code Section XI requirements Requirements impractical
DIGGS, R M License Fee Management Branch. 83/05/11 TUCKER, H B Duke Power Co 1p 18505 345 24X Fiche 50-369, 83/05/11, 8305180791

8305200438 Forwards Rev 1 to "Offsite Dose Calculation Manual "
TUCKER, H B Duke Power Co 83/05/17 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p, 18517-124 24X Fiche 50-369, 83/05/17, 8305200438

--8305200440 Rev 1 to "Offsite Dose Calculation Manual "
BIRCH, M L , MCINTOSH, M D , STEWART, J M Duke Power Co 83/04/15 8pp 18517 125 24X Fiche 50-369, 83/05/17, 8305200438

8305240097 Informs that License Condition 2 C (11)g on NUREG-0737, Item II K 3 10, "Anticipatory Reactor Trip," satisfied Safety evaluation encl.
NOVAK, T M Assistant Director for Licensing 83/05/17 TUCKER, H B Duke Power Co 6pp 18594 125 24X Fiche 50-369, 83/05/17, 8305240097

8305250267 Approves util 830505 requested changes to dynamic rod drop test purpose, method & acceptance criteria Change alters test to record data on dynamic reactor response to simultaneous drop of two rods into core
NOVAK, T M Assistant Director for Licensing 83/05/17. TUCKER, H B Duke Power Co 3pp 18595 333 24X Fiche 50-369, 83/05/17, 8305250267

8305250281 Clarifies commitment to modify automatic shunt trip design per Salem Task Force generic study Implementation schedule for independent fusing scheme for breaker closing circuits & auxiliary relays will be submitted
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 18592 361 24X Fiche 50-369, 83/05/20, 8305250281

8305250287 Informs of control scheme reevaluation for hydrogen mitigation sys Switches allowing manual actuation will be added during first refueling shutdown
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 18592 075 24X Fiche 50-369, 83/05/20, 8305250287

8305250442 Advises that info submitted 830223 & 0512 re environ qualification of electric equipment in Unit 2 applies equally to Unit 1
TUCKER, H B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 18588 095 24X Fiche 50-369, 83/05/20, 8305250442.

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270146 Forwards IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted
DANCE, H C Division of Project & Resident Programs. 83/03/25
TUCKER, H B Duke Power Co 2pp 18638 195 24X Fiche 50-369, 83/03/25, 8305270146

--8305270151 IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted Major areas inspected Unit 2 initial fuel loading, preoperational test results review & followup on previous inspector-identified items
THOMAS, M Region 2, Office of Director JAPE, F Division of Emergency Preparedness & Materials Safety 83/03/24. 4pp 18638 197 24X Fiche 50-369, 83/03/25, 8305270146

8305270154 Forwards IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/27
TUCKER, H B Duke Power Co 2pp 18638 034 24X Fiche 50-369, 83/03/29, 8305270154

--8305270160 IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 No noncompliance noted Major areas inspected operations, surveillance testing, maint, procedures review, TMI requirement verification & previous outstanding items
ORDERS, W , ROGGE, J Region 2, Office of Director IGNATONIS, A Division of Project & Resident Programs 83/03/28 19pp 18638 036 24X Fiche 50-369, 83/03/29, 8305270154

8305270385 Forwards IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/03/29
TUCKER, H B Duke Power Co 2pp 18643 037 24X Fiche 50-369, 83/03/29, 8305270385

--8305270402 IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted Major areas inspected steam generator mod, NDE & preservice insp, observation of work & work activities
KLEINSORGE, W P , BLAKE, J J Region 2, Office of Director 83/03/28 11pp 18643 039 24X Fiche 50-369, 83/03/29, 8305270385

8305270327 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08
DANCE, H C Division of Project & Resident Programs 83/04/04
TUCKER, H B Duke Power Co 1p 18642, 224 24X
Fiche 50-369, 83/04/04, 8305270327

--8305270366 Responds to NRC 830224 ltr re violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08 Corrective actions procedures will be modified by 830401 to verify quantity of radioactive matl per App C & 10CFR20 203
TUCKER,H B Duke Power Co 83/03/25 O'REILLY, J P Region 2, Office of Director 2pp 18642 225 24X Fiche 50-369,83/04/04, 8305270327

--8305270382 Forwards IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204 & notice of violation
DANCE,H C Division of Project & Resident Programs 83/02/24
TUCKER,H B Duke Power Co 2pp 18642 227 24X
Fiche 50-369,83/04/04,8305270327

--8305270405 Notice of violation from insp on 830131-0204
Region 2, Office of Director 83/02/24 1p 18642 229 24X
Fiche 50-369,83/04/04,8305270327

--8305270428 IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204
Noncompliance noted trailer containing more than 10 times
App C quantity of Co-60 not posted per 10CFR20 203e
ALBRIGHT,R H , COLLINS,T R Region 2, Office of Director
BARR,K P Division of Engineering & Radiological Safety Programs
83/02/22 3pp 18642 230 24X Fiche 50-369,83/04/04,8305270327

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp. 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270511 Forwards IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/27
TUCKER,H B. Duke Power Co 2pp 18645 248 24X
Fiche 50-369,83/04/27,8305270511

--8305270521 IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted Major areas inspected startup programs & closeout of outstanding items
BURNETT,P.T., JAPE,F Region 2, Office of Director 83/04/25
6pp 18645 250 24X Fiche 50-369,83/04/27,8305270511

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 110pp. 18382 165, 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp. 18382.282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc 119pp 18441 001. 24X Fiche 50-000,83/05/04,8303040031

8305100148 Forwards revised info re steam generator insp program following preheater mod installation Attachment replaces Page 2 of encl to 830428 ltr
TUCKER,H B. Duke Power Co 83/05/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4. 2pp 18374:221. 24X Fiche 50-369,83/05/05,8305100148

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305190462 Discusses NDE support to Task Order 4-83,which L Frank requested CV Dodd to undertake Meeting of eddy-current specialists to discuss exam of preheater tube wear defects will be scheduled
FRANK,L Materials Engineering Branch FIN B-0779-3 83/05/13
MCCLUNG,R W Oak Ridge National Laboratory 1p 18523 166 24X
Fiche 50-369,83/05/13,8305190462

8305200556 Forwards IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/17
TUCKER,H B Duke Power Co 2pp 18514 266 24X
Fiche 50-369,83/05/17,8305200556

--8305200565 IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation,review of security organization & security program audit Details withheld (ref 10CFR73 21)
TILLMAN,A , URYC,B Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 83/05/17
1p 18514 268 24X Fiche 50-369,83/05/17,8305200556

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170536 Forwards monthly operating repts for Apr 1983
TUCKER,H B Duke Power Co 83/05/13 Director's Office, Office of Inspection and Enforcement 1p 18469 028 24X
Fiche 50-369,83/05/13,8305170536

--8305170540 Monthly operating repts for Apr 1983
REAVIS,J A Duke Power Co 83/05/13 7pp 18469 029 24X
Fiche 50-369,83/05/13,8305170536

S Reportable occurrences, LERs & related correspondence

8305310052 Updated LER 83-014/03X-1 on 830303,conventional waste water sys radiation monitor 1EMF-31 channel found out of tolerance Caused by cracking detector crystal due to excessive temp change Crystal replaced W/830518 ltr
NARDOCI,P.B , TUCKER,H B Duke Power Co 83/04/15 O'REILLY,J P
Region 2, Office of Director 2pp 18453 164 24X
Fiche 50-369,83/04/15,8305310052

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN,E J Reactor Operations Analysis Branch, 83/04/19
SEYFRIT,K V. Reactor Operations Analysis Branch 1p 18541 342
24X Fiche 50-000,83/04/19,8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping.
BROWN,E J Reactor Operations Analysis Branch 83/04/19 9pp
18541 343. 24X Fiche 50-000,83/04/19,8305230573

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices.Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030675 Summary of 830419 meeting w/util,Bechtel & Westinghouse in Bethesda,MD re failures of undervoltage trip devices in reactor trip breakers (Westinghouse Model DS-416)
BIRKEL,R A Licensing Branch 4 83/04/25 Licensing Branch 4 36pp 18309 195 24X Fiche 50-369,83/04/25,8305030675

8305100002 Forwards LER 83-016/03L-0
TUCKER,H B Duke Power Co 83/04/26 O'REILLY,J P Region 2, Office of Director 1p 18377 213 24X Fiche 50-369,83/04/26, 8305100002

--8305100003 LER 83-016/03L-0 on 830327,hanger 1MCA-ND-H260 discovered pulled loose from wall anchors & snubbers 1MCA-ND-H177 & H317 found locked up during subsequent full-stroking Caused by water hammer event resulting in void formation
NARDOCI,P B Duke Power Co 83/04/26 Region 2, Office of Director 1p 18377 214 24X Fiche 50-369,83/04/26,8305100002

8305040273 Clarifies info re reactor trip breakers reported in 830228, 0301 & 22 ltrs Five consecutive failures to trip reactor trip breakers via undervoltage attachment considered single failure
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director NOVAK,T H NRC - No Detailed Affiliation Given 2pp 18323 242 24X Fiche 50-369,83/04/28, 8305040273

8305060403 Submits addl info requested by 830426-27 telcons re problems w/DB-416 breaker undervoltage devices Undervoltage devices replaced w/new corrected devices & installation checks to verify proper alignment initiated
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 10pp 18343 177 24X Fiche 50-369,83/04/28,8305060403

8305100366 Forwards radial peaking factor limit rept,in response to RO 369/83-11 re removal of burnable poison rod assemblies Requirement to submit rept 60 days prior to effective date of limits does not apply
TUCKER,H B Duke Power Co 83/04/28 O'REILLY,J P Region 2, Office of Director 3pp 18379 101 24X Fiche 50-369,83/04/28, 8305100366

8305110281 Forwards LER 83-013/03L-0.Detailed event analysis encl
TUCKER,H B Duke Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 4pp 18393 243 24X Fiche 50-369,83/04/29, 8305110281

--8305110283 LER 83-013/03L-0 on 830315,during upperhead injection level switch calibr,switches found out of tolerance Caused by design deficiency Rev to Tech Specs changing switch setpoint submitted
NARDOCI,P B Duke Power Co 83/04/29 Region 2, Office of Director 1p 18393 247 24X Fiche 50-369,83/04/29,8305110281

8305040229 Forwards "Investigation of Unit Trips," "Unit Fast Recovery," "Actions Required for ATWS Event," "Reactor Trip," & evaluation re mod to provide automatic reactor trip breaker actuation,per NRC request
TUCKER,H B Duke Power Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp, 18323 219 24X Fiche 50-369,83/05/02,8305040229

--8305040240 Procedure OP/1/A/6100/05, "Unit Fast Recovery "
* Duke Power Co 83/05/02 9pp 18323 222 24X Fiche 50-369,83/05/02,8305040229

--8305040246 Procedure AP/0/A/5500/34, "Actions Required for ATWS Event "
FIREBAUGH,L , REESIDE,W O Duke Power Co 82/04/22 3pp 18323 231 24X Fiche 50-369,83/05/02,8305040229

--8305040260 Change 0 to Procedure AP/1/A/5500/01, "Reactor Trip "
REESIDE,B , FIREBAUGH,L Duke Power Co 82/06/29 8pp 18323 234 24X Fiche.50-369,83/05/02,8305040229

8305090472 Discusses 830418 rept re reactor trip breakers (RTB) for facility RTB found w/no gap between undervoltage device trip arm & breaker trip shaft pin on 830331 Problem inadvertently omitted in 830418 rept Proper gaps verified
TUCKER,H B Duke Power Co 83/05/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p, 18362 341, 24X Fiche 50-369,83/05/03,8305090472

8305110085 Submits addl info requested in 830427 telcon re failure of DB-416 breaker undervoltage devices Westinghouse recommendations implemented Addl testing will be performed & amend to Tech Spec will be added.
TUCKER,H B Duke Power Co 83/05/03 DENTON,H R, Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 18398 062 24X Fiche 50-369,83/05/03,8305110085

8305100327 Clarifies 830331 incident involving problem w/train B reactor trip breaker Problem resulted in failure of breaker to trip upon undervoltage
TUCKER,H B Duke Power Co 83/05/05 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18378 321 24X Fiche 50-369,83/05/05,8305100327

8305170355 Forwards LER 83-017/03L-0
TUCKER,H B Duke Power Co 83/05/05 O'REILLY,J P Region 2, Office of Director 1p 18466 105 24X Fiche 50-369,83/05/05, 8305170355

--8305170358 LER 83-017/03L-0 on 830405,during draining of refueling cavity RHR (ND) pumps began to cavitate & eventually both ND pumps stopped Caused by level gauge isolation Cavity refilled ND sys vented Procedures revised
NARDOCI,P B Duke Power Co 83/05/05 Region 2, Office of Director 1p 18466 106 24X Fiche 50-369,83/05/05,8305170355

8305170507 Advises that all info re RO 369/83-18 on 830407 on snubber operability unavailable Complete rept will be submitted by 830520
TUCKER,H B Duke Power Co 83/05/06 O'REILLY,J P Region 2, Office of Director 1p 18470 014 24X Fiche 50-369,83/05/06, 8305170507

8305170649 Ack receipt of 830428 response to NRC concerns re reactor trip breakers Facility may be returned to operation Detailed schematic diagrams,describing approved reactor protection sys shunt mod,requested
EISENHUT,D G Division of Licensing 83/05/06 TUCKER,H B Duke Power Co 2pp 18496 244 24X Fiche 50-369,83/05/06,8305170649

8305130158 Provides addl info updating 830428 & 0503 ltrs re recent problems w/DB-416 breaker undervoltage devices,per NRC request Actions & commitments provide sufficient basis for operation Util intends to proceed w/startup per schedule
TUCKER,H B Duke Power Co 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 18437 172 24X Fiche 50-369,83/05/10,8305130158.

8305250404 LER 83-019/03L-0 on 830413,representative fuel pool ventilation sys carbon filter sample analysis indicated sample failed to meet methyl iodide penetration criteria Sample analyses made to determine cause W/830512 ltr
NARDOCI,P B , TUCKER,H B Duke Power Co 83/05/12 O'REILLY,J P, Region 2, Office of Director 2pp 18592 091 24X Fiche 50-369,83/05/12,8305250404

8305230717 Forwards SER of util actions in response to DB-416 reactor trip breaker failures Unit may be returned to svc
NOVAK,T M Assistant Director for Licensing 83/05/18 TUCKER,H B Duke Power Co 2pp 18542 274 24X Fiche 50-369,83/05/18, 8305230717

--8305230719 Safety evaluation re util actions taken in response to reactor trip breaker failures Unit may be returned to svc
* Assistant Director for Licensing 83/05/18 18pp 18542 276 24X Fiche 50-369,83/05/18,8305230717.

8305250549 Submits list of procedures changed to require independant engineering analysis on reactor trips Analysis will use reactor trip checklist to ensure appropriate parameters considered Performance engineer to document review
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 18588 224 24X Fiche 50-369,83/05/20,8305250549

8305310174 PNO-II-83-042 on 830521,employee injured while pressurizing inflatable,bladder-like pipe plug Rupture of bladder caused employee left hand to hit adjacent piping resulting in cuts & broken bones Hand decontaminated
IGNATONIS,A , GIBSON,A F, Region 2, Office of Director 83/05/23 2pp 18652 297 24X Fiche 50-369,83/05/23,8305310174

DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305190032 Forwards response to outstanding environ qualification items identified in Section 7 8 of Suppl 6 to SER & technical evaluation rept Info supports full power licensing
TUCKER,H B Duke Power Co 83/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 5pp 18502 058 24X Fiche 50-370,83/05/12,8305190032

F Security, medical, emergency & fire protection plans

8305040584 Releases public version of rev to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/26 Document Management Branch 1p 18336 139 24X Fiche 50-369, 83/04/26, 8305040584

--8305040597 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general emergency
TUCKER, H B Duke Power Co 83/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18336 140 24X Fiche 50-369, 83/04/26, 8305040584

--8305040606 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/04 re general emergency
GLOVER, M S Duke Power Co 83/02/24 77pp 18336 142 24X Fiche 50-369, 83/04/26, 8305040584

8305050135 Forwards Rev 15 to security plan, including implementation of Unit 2 vital access, safe shutdown facility & deletion of interim vital areas Rev withheld (ref 10CFR73 21)
TUCKER, H B. Duke Power Co 83/04/26 O'REILLY, J P Region 2, Office of Director 1p. 18342 239 24X Fiche 50-369, 83/04/26, 8305050135

8305160283 Releases public version of revised emergency plan *implementing procedures*
FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18472 079 24X Fiche 50-369, 83/05/02, 8305160283

--8305160285 Forwards public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/03 re site area emergency
TUCKER, H B Duke Power Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18472 080 24X Fiche 50-369, 83/05/02, 8305160283

--8305160286 Public version of revised emergency plan implementing procedures, including Procedures RP/0/A/5700/01 re notification of unusual event, RP/0/A/5700/02 re alert & RP/0/A/5700/03 re site area emergency
LEONARD, J R , MCCONNELL, T Duke Power Co 83/02/04 159pp 18472 082 24X Fiche 50-369, 83/05/02, 8305160283

8305130192 Advises of plan to use public address sys for local fire alarms in reactor bldg Plan meets intent of NFPA 72D-1975 as committed in Section E 1(a) of fire protection review plan *NRC approval requested by 830701*
TUCKER, H B. Duke Power Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18439:358 24X Fiche 50-369, 83/05/06, 8305130192

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305190020 Submits schedule for installation of RCS cold leg temp monitors as integral part of standby shutdown sys Mod will be implemented no later than startup following second refueling outage Exemption may be needed
TUCKER, H B. Duke Power Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 4pp 18502 017 24X Fiche 50-370, 83/05/13, 8305190020

8305200556 Forwards IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/17
TUCKER, H B Duke Power Co 2pp 18514 266 24X
Fiche: 50-369, 83/05/17, 8305200556

--8305200565 IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation, review of security organization & security program audit Details withheld (ref 10CFR73 21)
TILLMAN, A Region 2, Office of Director 83/05/17 1p 18514 268 24X Fiche 50-369, 83/05/17, 8305200556

8305250278 Forwards Rev 7 to spent fuel transportation plan Rev withheld (ref 10CFR73 21)
TUCKER, H B Duke Power Co 83/05/18. DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18592 362 24X
Fiche: 50-369, 83/05/18, 8305250278

J Insurance & indemnity information

8305260261 Forwards Endorsements 55 & 56 to MAELU Policy MF-61 & Endorsement 72 to NELIA Policy NF-182 for Oconee Nuclear Station & Endorsements 25 & 20 to NELIA Policy NF-248 & MAELU Policy MF-101, respectively, for McGuire
LAWSON, L T Duke Power Co 83/05/20 SALTZMAN, J Office of Resource Management, Director 19pp 18626 120 24X
Fiche 50-000, 83/05/20, 8305260261

P Operating license stage documents & correspondence

8303300370 Notification of 830329 meeting w/util in Bethesda, MD to discuss equipment qualification
BIRKEL, R A Licensing Branch 4 83/03/22 ADENSAM, E G Licensing Branch 4 3pp 17754 286 24X Fiche 50-369, 83/03/22, 8303300370

8305060224 Application for amend to License NPF-9 revising 821123 application re reduced measurement uncertainty for RCS flow rate Amend should also be applied to Unit 2 Tech Specs withheld (ref 10CFR2 790) Class I amend fee encl
TUCKER, H B Duke Power Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 3pp 18345 024 24X Fiche 50-369, 83/04/27, 8305060224

8305040469 Discusses util intentions re performance of requirements placed on Westinghouse for physics testing & surveillance of hybrid control rods Estimated critical positions will be used thoughout Cycle 1
TUCKER, H B Duke Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18321 297 24X Fiche 50-370, 83/04/28, 8305040469

8305060413 Forwards addl info re monitoring & testing program for steam generators concerning preheater mod Installation of mod on Unit 2 currently scheduled to begin in mid-June Date tentative depending on Westinghouse schedule
TUCKER, H B Duke Power Co 83/04/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 5pp 18343 259 24X Fiche 50-369, 83/04/28, 8305060413

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305100383 Requests that 830418 proposed amend to Tech Specs to revise setpoint for upper head injection accumulator automatic isolation be changed to incorporate revised setpoint *calculation*
TUCKER, H B Duke Power Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 18377 323 24X Fiche 50-369, 83/05/04, 8305100383

--8305100390 Revised proposed Tech Specs changing upper head injection accumulator automatic isolation setpoints to incorporate revised setpoint calculation
* *Duke Power Co* 83/05/04 1p 18377 325 24X
Fiche 50-369, 83/05/04, 8305100383

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D. G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170723 Responds to 830311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mods by welding on both units associated w/steam generator D Approach acceptable
NOVAK, T M Assistant Director for Licensing 83/05/09 TUCKER, H B Duke Power Co 4pp 18496 186 24X Fiche 50-369, 83/05/09, *8305170723*

--8305170726 SER supporting 830311 request for relief from ASME Code Section XI requirements re performing hydrostatic tests after mods by welding on both units associated w/steam generator D
* Division of Licensing 83/05/09 3pp 18496 190 24X
Fiche 50-369, 83/05/09, 8305170723

--8305170730 Notice of granting of relief from certain requirements of ASME Code Section XI inservice testing requirements
ADENSAM,E G Licensing Branch 4 83/05/10 2pp 18496 193 24X
Fiche 50-369,83/05/09,8305170723

8305170277 Forwards response to open items identified in Franklin Research Ctr technical evaluation rept re environ qualification of electrical equipment
TUCKER,H B Duke Power Co. 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 29pp 18465 297 24X Fiche 50-369,83/05/11,8305170277

8305180791 Requests addl Class I fee for 830311 application for relief from ASME Code Section XI requirements Requirements impractical.
DIGGS,R M License Fee Management Branch 83/05/11 TUCKER,H B Duke Power Co 1p 18505 345 24X Fiche 50-369,83/05/11, 8305180791

8303040044 Board Notification 83-66 forwards review of WCAP-10297(P), "Dropped Rod Methodology for Negative Flux Rate Trip Plants " Rod issue resolved by analysis in rept Plants beyond first cycle must perform analysis Comments encl
EISENHUT,D G Division of Licensing 83/05/13 PALLADINO,N , GILINSKY,V , AHEARNE,J Commissioners 21pp 18541:068 24X
Fiche 50-000,83/05/13,8303040044

8305230499 Notification of 830608 meeting w/util in Bethesda,MD to discuss forthcoming appeal meeting re staff positions for standby shutdown facility Process monitoring instruments & source range flux monitors to be addressed
SUERMANN,J F Operating Reactors Branch 4 83/05/16 STOLZ,J F Operating Reactors Branch 4 2pp 18541 274 24X
Fiche.50-000,83/05/16,8305230499

8305200438 Forwards Rev 1 to "Offsite Dose Calculation Manual "
TUCKER,H B, Duke Power Co 83/05/17 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p. 18517 124 24X Fiche 50-369,83/05/17,8305200438.

--8305200440 Rev 1 to "Offsite Dose Calculation Manual "
BIRCH,M L , MCINTOSH,M D , STEWART,J M Duke Power Co 83/04/15 8pp 18517 125 24X Fiche.50-369,83/05/17,8305200438

8305250281 Clarifies commitment to modify automatic shunt trip design per Salem Task Force generic study Implementation schedule for independent fusing scheme for breaker closing circuits & auxiliary relays will be submitted
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 18592 361 24X Fiche 50-369,83/05/20,8305250281

8305250287 Informs of control scheme reevaluation for hydrogen mitigation sys Switches allowing manual actuation will be added during first refueling shutdown
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4. 1p. 18592 075 24X Fiche 50-369,83/05/20,8305250287

8305250290 Clarifies statements made in 830511 & 12 ltrs re environ qualification of electrical equipment All outstanding items will be resolved & will be consistent w/10CR50 49(g) requirements
TUCKER,H B Duke Power Co. 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G. Licensing Branch 4 2pp 18592 136 24X Fiche 50-370,83/05/20,8305250290

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270146 Forwards IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/25
TUCKER,H B Duke Power Co. 2pp 18638 195 24X
Fiche 50-369,83/03/25,8305270146

--8305270151 IE Insp Repts 50-369/83-14 & 50-370/83-21 on 830307-10 No noncompliance noted Major areas inspected Unit 2 initial fuel loading,preoperational test results review & followup on previous inspector-identified items
THOMAS,M Region 2, Office of Director JAPE,F Division of Emergency Preparedness & Materials Safety. 83/03/24. 4pp 18638 197 24X Fiche 50-369,83/03/25,8305270146.

8305270154 Forwards IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/27
TUCKER,H B Duke Power Co 2pp 18638 034 24X
Fiche 50-369,83/03/29,8305270154

--8305270160 IE Insp Repts 50-369/83-13 & 50-370/83-19 on 830120-0302 noncompliance noted Major areas inspected operations, surveillance testing,maint,procedures review,TMI requirement verification & previous outstanding items
ORDERS,W , ROGGE,J Region 2, Office of Director IGNATONIS,A Division of Project & Resident Programs. 83/03/28 19pp 18638 036 24X Fiche.50-369,83/03/29,8305270154

8305270385 Forwards IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/29
TUCKER,H B Duke Power Co 2pp 18643 037 24X
Fiche 50-369,83/03/29,8305270385

--8305270402 IE Insp Repts 50-369/83-11 & 50-370/83-14 on 830216-18 & 0301-04 No noncompliance noted Major areas inspected steam generator mod,NDE & preservice insp,observation of work & work activities
KLEINSORGE,W P , BLAKE,J J Region 2, Office of Director 83/03/28 11pp 18643 039 24X Fiche 50-369,83/03/29,8305270385

8305270327 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08
DANCE,H C Division of Project & Resident Programs. 83/04/04
TUCKER,H B Duke Power Co 1p 18642.224 24X
Fiche 50-369,83/04/04,8305270327

--8305270366 Responds to NRC 830224 ltr re violations noted in IE Insp Repts 50-369/83-05 & 50-370/83-08 Corrective actions procedures will be modified by 830401 to verify quantity of radioactive matl per App C & 10CFR20 203
TUCKER,H B Duke Power Co 83/03/25 O'REILLY, J P Region 2, Office of Director, 2pp 18642.225 24X Fiche 50-369,83/04/04, 8305270327

--8305270382 Forwards IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204 & notice of violation.
DANCE,H C Division of Project & Resident Programs. 83/02/24
TUCKER,H B Duke Power Co 2pp. 18642.227 24X
Fiche 50-369,83/04/04,8305270327

--8305270428 IE Insp Repts 50-369/83-05 & 50-370/83-08 on 830131-0204 Noncompliance noted trailer containing more than 10 times App C quantity of Co-60 not posted per 10CFR20 203e
ALBRIGHT,R.H , COLLINS,T R Region 2, Office of Director
BARR,K P Division of Engineering & Radiological Safety Program 83/02/22 5pp 18642 230 24X Fiche 50-369,83/04/04,8305270327

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383.089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270511 Forwards IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/27
TUCKER,H B Duke Power Co. 2pp 18645.248 24X
Fiche 50-369,83/04/27,8305270511

--8305270521 IE Insp Repts 50-369/83-15 & 50-370/83-22 on 830404-08 No noncompliance noted Major areas inspected startup programs & closeout of outstanding items
BURNETT,P T , JAPE,F Region 2, Office of Director. 83/04/25 6pp 18645 250 24X Fiche 50-369,83/04/27,8305270511

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382.047. 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 112pp. 18382.282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441·001 24X Fiche 50-000,83/05/04,8303040031

8305100148 Forwards revised info re steam generator insp program following preheater mod installation Attachment replaces Page 2 of encl to 830428 ltr
TUCKER,H B. Duke Power Co 83/05/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp. 18374 221 24X Fiche 50-369,83/05/05,8305100148.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co of New York, Inc. 115pp. 18523.248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp. 18524:003 24X Fiche 50-000,83/05/11,8303040034

8305200556 Forwards IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22.No noncompliance noted
DANCE,H C Division of Project & Resident Programs, 83/05/17
TUCKER,H B Duke Power Co 2pp 18514 266 24X
Fiche·50-369,83/05/17,8305200556

--8305200565 IE Safeguards Insp Repts 50-369/83-18 & 50-370/83-25 on 830418-22 No noncompliance noted Major areas inspected site orientation,review of security organization & security program audit.Details withheld (ref 10CFR73 21)
TILLMAN,A., URYC,B Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 83/05/17 1p. 18514:268 24X Fiche 50-369,83/05/17,8305200556

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp. 18697:009. 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305170536 Forwards monthly operating repts for Apr 1983
TUCKER,H.B. Duke Power Co. 83/05/13 Director's Office, Office of Inspection and Enforcement 1p. 18469·028 24X
Fiche:50-369,83/05/13,8305170536

--8305170540 Monthly operating repts for Apr 1983.
REAVIS,J.A. Duke Power Co 83/05/13 7pp 18469 029 24X
Fiche·50-369,83/05/13,8305170536

S. Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices.Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21, DEYOUNG,R.C. Director's Office, Office of Inspection and Enforcement. 5pp 18405·095. 24X Fiche:50-000,83/04/21,8305110427

8305030675 Summary of 830419 meeting w/util,Bechtel & Westinghouse in Bethesda,MD re failures of undervoltage trip devices in reactor trip breakers (Westinghouse Model DS-416)
BIRKEL,R A Licensing Branch 4 83/04/25 Licensing Branch 4 36pp 18309 195 24X Fiche 50-369,83/04/25,8305030675

8305040273 Clarifies info re reactor trip breakers reported in 830228, 0301 & 22 ltrs Five consecutive failures to trip reactor trip breakers via undervoltage attachment considered single failure
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director NOVAK,T H NRC - No Detailed Affiliation Given 2pp 18323:242 24X Fiche 50-369,83/04/28,8305040273

8305050153 Interim deficiency rept re ITT Barton Class IE transmitters exhibiting thermal nonrepeatability Initially reported on 821210 Since errors within safety analysis limits,no setpoint changes required
TUCKER,H B Duke Power Co 83/04/28 O'REILLY,J P Region 2, Office of Director 2pp 18341 358 24X Fiche 50-370,83/04/28,8305050153

8305060403 Submits addl info requested by 830426-27 telcons re problems w/DB-416 breaker undervoltage devices Undervoltage devices replaced w/new corrected devices & installation checks to verify proper alignment initiated
TUCKER,H B Duke Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4. 10pp 18343 177 24X Fiche·50-369,83/04/28,8305060403

8305040229 Forwards "Investigation of Unit Trips," "Unit Fast Recovery," "Actions Required for ATWS Event," "Reactor Trip," & evaluation re mod to provide automatic reactor trip breaker actuation,per NRC request
TUCKER,H B Duke Power Co 83/05/02 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 3pp 18323 219 24X Fiche 50-369,83/05/02,8305040229

--8305040240 Procedure OP/1/A/6100/05, "Unit Fast Recovery "
* Duke Power Co 83/05/02 9pp 18323 222 24X
Fiche 50-369,83/05/02,8305040229

--8305040246 Procedure AP/0/A/5500/34, "Actions Required for ATWS Event "
FIREBAUGH,L , REESIDE,W O Duke Power Co 82/04/22 3pp
18323 231 24X Fiche 50-369,83/05/02,8305040229

--8305040260 Change 0 to Procedure AP/1/A/5500/01, "Reactor Trip "
REESIDE,B , FIREBAUGH,L Duke Power Co 82/06/29 8pp
18323 234 24X Fiche 50-369,83/05/02,8305040229

8305130186 PNO-II-83-033 on 830501,inadvertent safety injection occurred Caused by spurious signal during tests of steam generator D Low power DL received on 830303 & initial criticality planned during wk
NEJFELT,G , IGNATONIS,A. Region 2, Office of Director 83/05/02
1p 18440 049 24X Fiche 50-370,83/05/02,8305130186

8305090472 Discusses 830418 rept re reactor trip breakers (RTB) for facility RTB found w/no gap between undervoltage device trip arm & breaker trip shaft pin on 830331 Problem inadvertently omitted in 830418 rept.Proper gaps verified
TUCKER,H B Duke Power Co 83/05/05 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 18362 341 24X Fiche 50-369,83/05/03,8305090472

8305110085 Submits addl info requested in 830427 telcon re failure of DB-416 breaker undervoltage devices Westinghouse recommendations implemented Addl testing will be performed & amend to Tech Spec will be added
TUCKER,H B Duke Power Co 83/05/03. DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 18398 062 24X Fiche·50-369,83/05/03,8305110085

8305170258 Forwards LER 83-004/03L-0
TUCKER,H B Duke Power Co 83/05/06 O'REILLY,J P Region 2, Office of Director. 1p 18465 068 24X Fiche 50-370,83/05/06, 8305170258

--8305170269 LER 83-004/03L-0 on 830406,ventilation unit condensate drain tank released while composite sampler inoperable for more than 30 days Caused by personnel error Tank red tagged, sampler installed & operation procedure will be modified
NARDOCI,P B Duke Power Co 83/05/06 Region 2, Office of Director 1p 18465 069 24X Fiche 50-370,83/05/06,8305170258

8305110262 PNO-II-83-036,on 830508,unit achieved initial criticality w/o incident Actual parameters in close agreement w/ predicted conditions
NEJFELT,G M , IGNATONIS,A Region 2, Office of Director 83/05/09.
1p 18393 158 24X Fiche:50-370,83/05/09,8305110262

8305130158 Provides addl info updating 830428 & 0503 ltrs re recent problems w/DS-416 breaker undervoltage devices,per NRC request Actions & commitments provide sufficient basis for operation Util intends to proceed w/startup per schedule
TUCKER,H B Duke Power Co 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 18437 172 24X Fiche 50-369,83/05/10,8305130158

8305250439 LER 83-005/03L-0 on 830413,procedure review revealed that area temp monitoring surveillance not performed within 12 h limit Caused by revs to Tech Specs Surveillance interval not recorded Procedures revised W/830512 ltr
NARDOCI,P B , TUCKER,H B Duke Power Co 83/05/12 O'REILLY,J P Region 2, Office of Director 2pp 18585 289 24X
Fiche 50-370,83/05/12,8305250439

8305250499 LER 83-006/03L-0 on 830413,while in Mode 5,control room wide range reactor coolant loop D pressure indicator found low & declared inoperable Caused by air trapped in pressure transmitter Transmitter bled & loop recalibr W/830512 ltr
NARDOCI,P B , TUCKER,H B Duke Power Co 83/05/12 O'REILLY,J P Region 2, Office of Director 2pp 18588 266 24X
Fiche 50-370,83/05/12,8305250499

8305250525 Interim deficiency rept re Tech Spec 3 & 1 3 concerning operability of containment air lock Investigation continuing Complete rept will be provided by 830603
TUCKER,H B Duke Power Co 83/05/18 O'REILLY,J P Region 2, Office of Director 1p 18583 340 24X Fiche 50-370,83/05/18, 8305250525

8305250507 Notifies that commitment to limit operation of Unit 2 to zero power physics testing as result of recent problems w/DS-416 reactor trip breakers met w/issuance of safety evaluation for Unit 1 breakers
TUCKER,H B Duke Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 18588 254 24X Fiche 50-370,83/05/19,8305250507

8305250549 Submits list of procedures changed to require independent engineering analysis on reactor trips Analysis will use reactor trip checklist to ensure appropriate parameters considered Performance engineer to document review
TUCKER,H B Duke Power Co 83/05/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 18588 224 24X Fiche 50-369,83/05/20,8305250549

DOCKET 50-373 LASALLE COUNTY STATION, UNIT 1

F Security, medical, emergency & fire protection plans

8305240087 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
FELTON,J M Division of Rules and Records 83/03/31 GARDE,B Government Accountability Project 2pp 18593 015 24X
Fiche 50-373,83/03/31,8305240087

--8305250144 Recommends unsorted access to protected areas for R Lipinski & S Chan Rapifac sheet transmitting evaluation of technical rept, "Assessment of Effects of Nicked Reinforcing Steel," encl
KEPPLER,J G Region 3, Office of Director 82/06/14 REED,C Commonwealth Edison Co 7pp 18593 056 24X
Fiche 50-373,83/03/31,8305240087

8305050402 Forwards request for addl info re fire protection for safe shutdown,based on review of Amend 62 to FSAR
SCHWENCER,A Licensing Branch 2 83/04/28 FARRAR,D L Commonwealth Edison Co. 3pp 18392 046 24X Fiche 50-373,83/04/28, 8305050402

8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29,1201,14 & 830414 & notice of violation
SPESSARD,R L Division of Engineering 83/04/28 REED,C Commonwealth Edison Co 2pp 18431 107 24X Fiche 50-373,83/04/28, 8305120438

--8305120443 Notice of violation from insp on 821124,26,29,1201,14 & 830414
SPESSARD,R L. Division of Engineering 83/04/28 3pp 18431 109 24X Fiche 50-373,83/04/28,8305120438

--8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29, 1201,14 & 830414 Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices
RAMSEY,C , ULIE,J , HASSE,R Region 3, Office of Director 83/04/27 19pp 18431 112 24X Fiche 50-373,83/04/28,8305120438

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305130149 Ack receipt of 830419 ltr informing NRC of objectives & providing scenario outline for 830712 exercise
PAPERIELLO,C J Region 3, Office of Director 83/05/11 REED,C Commonwealth Edison Co 1p 18437 156 24X Fiche 50-373,83/05/11, 8305130149

--8305130155 Forwards list of objectives,scope of participation,scenario outline & narrative summary for emergency exercise scheduled for 830712
BLACKMON,T G Commonwealth Edison Co 83/04/19 HIND,J Division of Emergency Preparedness & Operational Support 15pp 18437 157 24X Fiche 50-373,83/05/11,8305130149

8305170423 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-373/83-03
MILLER,J R Region 3, Office of Director 83/05/12 REED,C Commonwealth Edison Co 1p 18469 290 24X Fiche 50-373,83/05/12, 8305170423

--8305170425 Responds to NRC 830329 ltr re violations noted in IE Safeguards Insp Rept 50-373/83-03 Corrective actions. procedures used to test metal detectors & proposed change in description of metal detectors addressed Details withheld
FARRAR,D L Commonwealth Edison Co 83/04/19 KEPPLER,J G. Region 3, Office of Director 1p 18469 291 24X
Fiche 50-373,83/05/12,8305170423

Q Adjudicatory correspondence

8305200481 Advises that time for Commission to review Director's Decision DD-83-1 expired Commission declined review Decision became final agency action on 830506
CHILK,S J Office of the Secretary of the Commission 83/05/19 HARTIGAN,N Illinois, State of ROREM,B L Friends of the Earth GOOOL,E M Citizens Against Nuclear Power 1p 18513 014 24X
Fiche 50-373,83/05/19,8305200481

P Operating license stage documents & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11, PRENDERGAST,R Prendergast, R J. 17pp 18506 059 24X
Fiche 50-000,83/03/11,8305190005

--8208250506 Trip rept of 820802 audit,reviewing seismic & qualification file for Zack Co equipment,at Sargent & Lundy Engineers ofc in Chicago,IL
ROSZTOCZY,Z R Equipment Qualification Branch, 82/08/06 SCHWENCER,A Licensing Branch 2 8pp 18507 201 24X
Fiche 50-000,83/03/11,8305190005

--8305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removal welds Certain welds on Unit 2,Div II switchgear heat removal sys may not meet applicable code requirements
HOLYOAK,R H Commonwealth Edison Co 82/08/06 Region 3, Office of Director 1p 18507 200 24X Fiche 50-000,83/03/11, 8305190005

--8305190302 Forwards Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const,LaSalle County Station Units 1 & 2," QC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired.
POLLOCK,R H Sargent & Lundy, Inc 82/08/27 SHELTON,B.R Commonwealth Edison Co 1p 18507 317 24X Fiche 50-000, 83/03/11,8305190005

--8305190303 Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const,LaSalle County Station Units 1 & 2 "
CHO,F L , KISISEL,I T , MELIGI,A V Sargent & Lundy, Inc CQD-003490 R00 82/08/27 27pp 18507 318 24X
Fiche 50-000,83/03/11,8305190005

--8305190332 Forwards "LaSalle County Station Independent HVAC Review," interim rept Rept also sent to JG Keppler
KEMPIAK,A J C F Braun & Co 82/09/15 SHELTON,B R Commonwealth Edison Co 1p 18507 359 24X Fiche 50-000, 83/03/11,8305190005

--8305190333 Forwards TE Watts 821019 & 29 memos to CW Schroeder responding to R Lanksbury questions re HVAC ductwork design & transmitting Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station "
SCHROEDER,C W Commonwealth Edison Co 82/10/27 KEPPLER,J G Region 3, Office of Director 9pp 18508 093 24X Fiche 50-000,83/03/11,8305190005.

--8305190357 Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station Units 1 & 2 "
* Sargent & Lundy, Inc 82/10/21 9pp 18508 102 24X Fiche:50-000,83/03/11,8305190005

--8305190365 Forwards Vols 1-4 to "Independent HVAC Review,LaSalle County Nuclear Plant," final rept
KEMPFAK,A J C F Braun & Co 82/10/27 SHELTON,G R Commonwealth Edison Co 1p 18508 111 24X Fiche 50-000, 83/03/11,8305190005

--8305190367 Ack receipt of CF Braun final rept of independent HVAC review at facilities
PHILLIPS,R.W Region 3, Office of Director 82/10/27 Region 3, Office of Director 1p 18508 112 24X Fiche 50-000,83/03/11, 8305190005

--8305190379 Requests list of results of detailed calculations on rebar damage for 647 concrete elements affecting Unit 1 operation & approved CF Braun proposal for independent HVAC review Zack Co chronology encl.
GOODIE,J S Illinois, State of 82/09/07 KEPPLER,J G Region 3, Office of Director 5pp 18511 278 24X Fiche 50-000, 83/03/11,8305190005

--8305190390 P Donahue show Transcript 08302 re nuclear power safety info re facilities & Zack Co encl
* Multimedia Program Production, Inc 83/03/11 128pp 18512 189 24X Fiche 50-000,83/03/11,8305190005

8304290034 Requests documented acceptance of General Motors Electro-Motive Div (EMD) MI 9644 mod as acceptable alternative to diesel generator prelube oil pump EMD clarification of prelube requirements encl
SCHROEDER,C W Commonwealth Edison Co 83/04/26 SCHWENCER,A Licensing Branch 2 3pp 18265 274 24X Fiche 50-373,83/04/26, 8304290034

8305030161 Confirms discussion w/A Bournia changing effective date for proposed Tech Spec re radiation chemistry technician qualification requirements to 830505
SCHROEDER,C W Commonwealth Edison Co 83/04/27 SCHWENCER,A Licensing Branch 2 1p 18300 269 24X Fiche 50-373,83/04/27, 8305030161.

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X Fiche 50-000,83/05/02,8305020455

8305110082 Forwards "Test Rept on Verification Testing of Separation Between Class IE & Non-Class IE Power Cables in Raceways " Written confirmation of closure of License Condition 2 C (24) requested
SCHROEDER,C W Commonwealth Edison Co 83/05/03 SCHWENCER,A Licensing Branch 2 2pp 18397 239 24X Fiche 50-373,83/05/03, 8305110082.

--8305110089 "Test Rept on Verification Testing of Separation Between Class IE & Non-Class IE Power Cables in Raceways "
HAZELTINE,J , JOHNSON,F , ROBERTS,W Wyle Laboratories 46511-3 83/03/28 181pp 18397 241 24X Fiche 50-373,83/05/03, 8305110082

8305110171 Forwards safety evaluation on drywell to wetwell vacuum breaker valve mods to withstand suppression pool swell phase of LOCA Mods acceptable
SCHWENCER,A Licensing Branch 2 83/05/03 FARRAR,D L Commonwealth Edison Co 2pp 18434 236 24X Fiche 50-373,83/05/03, 8305110171

--8305110175 Safety evaluation on drywell to wetwell vacuum breaker valve mods to withstand suppression pool swell phase of LOCA Mods acceptable
* NRC - No Detailed Affiliation Given 83/05/03 3pp 18434 238 24X Fiche:50-373,83/05/03,8305110171

8305120580 Forwards Amend 14 to License NPF-11, safety evaluation & notice of issuance & availability Amend deletes License Condition 2 C (26) & incorporates licensee approved alternative to Rad/Chem technical qualifications
SCHWENCER,A Licensing Branch 2 83/05/05 FARRAR,D L Commonwealth Edison Co 3pp 18441 319 24X Fiche 50-373,83/05/05, 8305120580

--8305120585 Amend 14 to License NPF-11,deleting License Condition 2 C (26) & changing Tech Specs to incorporate licensee approved alternative to Rad/Chem technical qualifications
EISENHUT,D G Division of Licensing 83/05/05 6pp 18441 322 24X Fiche 50-373,83/05/05,8305120580

--8305120589 Safety evaluation supporting Amend 14 to License NPF-11
* Office of Nuclear Reactor Regulation, Director 83/05/05 2pp 18441 328 24X Fiche 50-373,83/05/05,8305120580

--8305120593 Notice of issuance & availability of Amend 14 to License NPF-11
SCHWENCER,A Licensing Branch 2 83/05/05 3pp 18441 330 24X Fiche 50-373,83/05/05,8305120580

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp. 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305170477 Confirms 830512 enforcement conference in Glen Ellyn, IL w/util to discuss programmatic deficiencies identified in surveillance testing program
NORELIUS,C E Division of Project & Resident Programs 83/05/09 REED,C Commonwealth Edison Co 1p 18470 085 24X Fiche 50-373,83/05/09,8305170477

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED,C Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche 50-000,83/05/11,8305200621

--8305200637 "Energy,Inc/Ferguson,Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN,R N , HARRIS,R J Energy Incorporated FERGUSON,R N Ferguson, Inc 82/07/06 65pp 18521 095 24X Fiche 50-000,83/05/11,8305200621

--8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects "
* Commonwealth Edison Co 82/11/17 350pp 18521 160 24X Fiche 50-000,83/05/11,8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment
MARCUS,G F Commonwealth Edison Co 81/10/06 6pp 18522 150 24X Fiche 50-000,83/05/11,8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD,T , MARCUS,G F Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fiche 50-000,83/05/11,8305200621

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
MARCUS,G F Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche 50-000,83/05/11,8305200621

--8305200681 Rev 3 to "Interface Control Agreement,Westinghouse Piping & Structural Evaluation Program for Byron Station Unit 1 "
* Westinghouse Electric Corp * Commonwealth Edison Co * Sargent & Lundy, Inc 82/10/29 19pp 18522 221 24X Fiche 50-000,83/05/11,8305200621

--8305200683 Rev C to Procedure 3 Q 4, "Design Control - New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl
WHITAKER,W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fiche 50-000,83/05/11,8305200621

--8305200684 Advises that Westinghouse QA program implementation described in WCAP-8370,Rev 9A,satisfactory
SEYFRIT,K V Region 4, Dallas, Office of the Director (81/03/01) 81/04/30 SLEMDER,R J Westinghouse Electric Corp 2pp 18522 259 24X Fiche 50-373,83/05/11,8305200621

DOCKETED ITEMS

--8305200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util QA statement re verification of adequacy of design & const of Byron Unit 1 encl
WATTELET,P L , MEISTER,J R , BRAEGER,C B Sargent & Lundy, Inc
DRR-AF-001-BB R00 80/07/16 84pp 18522 303 24X
Fiche 50-000,83/05/11,8305200621.

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed "
BIGBEE,D , CURRAN,R N , FARMAN,R F Energy Incorporated.
83/04/04 127pp 18523 027 24X Fiche 50-000,83/05/11,
8305200621

8305200015 Responds to util 830407 request to change Tech Specs allowing dilution flow blowdown determination by position of regulating valve Request unacceptable Flow rate estimate still vulnerable to uncertainties
NOVAK,T M Division of Licensing 83/05/17 FARRAR,D L
Commonwealth Edison Co 3pp 18528 360 24X Fiche 50-373,83/05/17,
8305200015

8305230584 Submits editorial rev to Specific Action 10 per 821228 response to Generic Ltr 81-04 re measures to minimize intergranular stress corrosion cracking General & specific corrective actions discussed NUREG-0313 compliance achieved
SCHROEDER,C W Commonwealth Edison Co 83/05/19 LAINAS,G C
Licensing Branch 2 4pp 18537,313 24X Fiche 50-373,83/05/19,
8305230584

8305240110 Forwards Tables 3 9 4 & 3 9-4A comparing NRC fuel assembly load combinations in horizontal plane,vertical plane & design basis loads Encl tables will be included in FSAR Amend 63 to be submitted by 830630
SCHROEDER,C W Commonwealth Edison Co 83/05/19 SCHWENCER,A
Licensing Branch 2 4pp 18548 343 24X Fiche 50-373,83/05/19,
8305240110

8305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing matl tests.
SPESSARD,R L Division of Engineering. 83/05/24 REED,C
Commonwealth Edison Co 1p 18644 087 24X Fiche 50-000,83/05/24,
8305270476

--8305270501 Rev 1 to "Evaluation of Three Legged Pipe Whip Restraint Sys "
MA,J S , YANG,M S , AMIN,M Sargent & Lundy, Inc S 15 1-0 R01
82/09/21 47pp 18644 099 24X Fiche 50-000,83/05/24,8305270476

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util BCRDR program plan
GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D
Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000,83/05/26,8305310086.

Q Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR. App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506 059 24X
Fiche. 50-000,83/03/11,8305190005

--8305190045 Requests vendor insp of facilities having contracts w/Zack Co due to QA/QC problems at Midland re HVAC activities
Zack Co correspondence re LaSalle & related info encl
FIORELLI,G Region 3, Chicago, Reactor Construction & Engineering Support Branch. 80/04/21 POTOPOUS,U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000,83/03/11,
8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co,HVAC contractor at facilities,re potential allegations,Zack Co planning to terminate several employees in document control section
HAYES,D W Region 3, Office of Director 82/05/12 Region 3,
Office of Director. 1p 18506,089 24X Fiche 50-000,83/03/11,
8305190005

-8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24. NRC - No Detailed
Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11,
8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co,HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE,T Government Accountability Project 82/07/26
PALLADINO,N J, Commissioners 11pp 18506 128 24X
Fiche 50-000,83/03/11,8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
MARELLO,S L Affiliation Unknown 82/07/26 22pp 18506 139
24X Fiche 50-000,83/03/11,8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
HOWARD,A T Affiliation Unknown 82/07/26 55pp 18506,160
24X Fiche:50-000,83/03/11,8305190005.

--8305190119 Repts investigation re possible flawed equipment at facilities,per Eyewitness News broadcast
* Radio TV Reports, Inc 82/07/26 NRC - No Detailed
Affiliation Given 2pp 18507 165 24X Fiche 50-000,83/03/11,
8305190005

--8305190124 Offers assistance & cooperation in investigating Zack Co Suggestions discussed
DEVINE,T , GARDE,D P Government Accountability Project
82/07/27. PALLADINO,N J Commissioners 2pp 18507 167 24X
Fiche 50-000,83/03/11,8305190005

--8305190128 Forwards outline of investigation rept re Zack documentation concerning HVAC activities Discussion of matl spec & mechanical properties for galvanized sheet steel & stiffener hanger & support steel & L DelGeorge handwritten notes encl
NORELIUS,C E Region 3, Office of Director 82/07/28.
KEPPLER,J G , DAVIS,A B , FOSTER,J Region 3, Office of Director,
25pp 18507 169 24X Fiche 50-000,83/03/11,8305190005

--8305190151 Informs of atty general of State of IL intention to attend NRC 820811 meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations
VAN VRANKEN,J Illinois, State of 82/08/09. KEPPLER,J G
Region 3, Office of Director 1p. 18507,209 24X
Fiche 50-000,83/03/11,8305190005

--8305190162 Introduction of 820811 public meeting to discuss util plans re employment of third party contractor to conduct independent review of HVAC sys at facilities.
* NRC - No Detailed Affiliation Given. 82/08/11 2pp
18507 214 24X Fiche 50-000,83/03/11,8305190005.

--8305190167 Requests that all interested parties be furnished proposed contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized
VAN VRANKEN,J. Illinois, State of 82/08/12. KEPPLER,J.G
Region 3, Office of Director 2pp 18507,215. 24X
Fiche 50-000,83/03/11,8305190005

--8305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & S Marello experience & knowledge be utilized in review process Util 820813 ltr to CF Braun & Co encl
HOWARD,A.T Affiliation Unknown. 82/08/13 KEPPLER,J.G. Region 3, Office of Director 11pp 18507,216 24X
Fiche 50-000,83/03/11,8305190005

--8305190184 Confirms 820812 telcon re telephone call from M Cherry concerning Zack investigation & circumstances surrounding termination of Zack employees
DAVIS,A B Region 3, Office of Director 82/08/16 FITZGERALD,J
Office of Investigation 2pp 18507 230 24X
Fiche 50-000,83/03/11,8305190005

--8305190189 Notification of 820824 meeting w/util in Glen Ellyn,IL to discuss status of licensee independent HVAC review
* Region 3, Office of Director 82/08/18. Region 3, Office of Director 1p 18507 231 24X Fiche 50-000,83/03/11,8305190005

--8305190283 Introduction of 820824 public meeting to discuss util preliminary plans re independent review of HVAC sys at facilities Meeting will focus on CF Braun technical proposals.
* NRC - No Detailed Affiliation Given 83/08/24. 1p 18507 266
24X Fiche. 50-000,83/03/11,8305190005

--8305190289 Forwards T Devine 820813 ltr, AT Howard 820813 ltr & SS Marello 820816 ltr for NRR consideration in assessment of util proposal on third party review of HVAC sys at facilities
SPESSARD, R L Division of Project & Resident Programs 82/08/25
EISENHUT, D G Division of Licensing 1p 18507 293 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190292 Advises that AT Howard & SS Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co, subj to listed conditions Related info encl.
DEVINE, T. Government Accountability Project 82/08/13
KEPPLER, J. Region 3, Office of Director 16pp 18507 294 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities CF Braun should rept directly to NRC & should audit all critical areas at facilities
MARELLO, S L. Affiliation Unknown 82/08/16 KEPPLER, J Region 3, Office of Director 3pp 18507 313 24X Fiche 50-000, 83/03/11, 8305190005.

--8305190304 Discusses concerns on behalf of AT Howard & S Marello, for NRC consideration in review of CF Braun final proposal to conduct independent review of HVAC sys at facilities, per 820824 meeting.
DEVINE, T. Government Accountability Project 82/09/04
KEPPLER, J. G Region 3, Office of Director 6pp 18507 345 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190329 Responds to 820904 ltr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taken into consideration in NRR review of proposal
KEPPLER, J G Region 3, Office of Director 82/09/13 DEVINE, T
Government Accountability Project 1p 18507 357 24X
Fiche: 50-000, 83/03/11, 8305190005.

--8305190384 Advises that field insp of HVAC sys at facility completed, including review of Govt Accountability Project allegations against Zack Co No technical basis exists for further restriction of facility power level. W/related info
KEPPLER, J G Region 3, Office of Director 82/12/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 11pp 18512 038
24X Fiche 50-000, 83/03/11, 8305190005

--8305190387 Rev 1 to "LaSalle County Station Technical Proposal," including scope of work, work plan to accomplish independent HVAC review, organization chart & resumes of personnel assigned to project. List of matl specs for HVAC const encl
* C F Braun & Co 82/08/25. 34pp. 18512 155 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities. Personally identifiable info deleted
NORELIUS, C. E Division of Engineering 82/07/12 Division of Engineering. 1p 18512 323 24X Fiche 50-000, 83/03/11, 8305190005

--8305190399 Handwritten notes re meeting w/util on allegations concerning Zack Co activities at facilities.
DAVIS, A. B. NRC - No Detailed Affiliation Given 82/07/16. 9pp
18512.335. 24X Fiche 50-000, 83/03/11, 8305190005

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co of New York, Inc
112pp 18308, 319 24X Fiche, 50-000, 83/03/21, 8212060385

8305090306 Addl response to FOIA request for all records prepared at Region III, all investigators involved in investigation of T Howard & S Morella allegations & all internal records re problems discovered at facility Forwards App B documents
FELTON, J M. Division of Rules and Records 83/03/22 GARDE, B
Government Accountability Project. 2pp 18381 216 24X
Fiche 50-373, 83/03/22, 8305090306

--8305090313 IE Investigation Repts 50-373/82-51 & 50-374/82-15 on 820721-1001. No noncompliance noted Major areas investigated followup on allegations re matl procurement & QA deficiencies of HVAC sys installed by Zach Co
LANKSBURY, R. D. WESTCOTT, H. M. Region 3, Office of Director
82/08/16 4pp. 18381 219. 24X Fiche 50-373, 83/03/22, 8305090306.

8304120409 Forwards IE Insp Rept 50-373/83-07 on 830215-0311. No noncompliance noted
LITTLE, W. S. Region 3, Office of Director. 83/03/23 REED, C.
Commonwealth Edison Co. 2pp. 17932.150. 24X Fiche 50-373, 83/03/23, 8304120409.

--8304120412 IE Insp Rept 50-373/83-07 on 830215-0311 No noncompliance noted Major areas inspected startup test results & previously opened items
MAURA, F A , REYES, L A Region 3, Office of Director 83/03/23
4pp 17932 152 24X Fiche 50-373, 83/03/23, 8304120409

8305240087 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
FELTON, J M Division of Rules and Records 83/03/31 GARDE, B
Government Accountability Project 2pp 18593 015 24X
Fiche 50-373, 83/03/31, 8305240087

--8305240098 Five draft summaries of affidavits & statements, draft comments on followup of allegations, minutes of Region III 820329, 0419, 0503 & 0706 staff meetings & draft investigation schedule Personally identifiable info deleted
* NRC - No Detailed Affiliation Given 83/03/25 36pp
18593 018 24X Fiche 50-373, 83/03/31, 8305240087

--8305240125 Discusses actions planned during addl insp to resolve concerns re adequacy of workmanship during const of masonry walls R Lipinski assistance requested to resolve issues starting wk of 820815
SPESSARD, R L Division of Project & Resident Programs 82/08/17
EISENHUT, D G Division of Licensing 2pp 18593 054 24X
Fiche 50-373, 83/03/31, 8305240087

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020094 Confirms 830513 enforcement conference at Region III ofc in Glen Ellyn, IL to discuss programmatic deficiencies identified in surveillance testing program, per 830414 telcon
NORELIUS, C E Division of Project & Resident Programs 83/04/25
REED, C Commonwealth Edison Co 1p 18278 247 24X
Fiche 50-373, 83/04/25, 8305020094

8305120415 Forwards IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/04/27 REED, C
Commonwealth Edison Co 2pp 18434.080 24X Fiche 50-373, 83/04/27, 8305120415

--8305120420 IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncompliance noted Major areas inspected as-built walkdown & review of procedures for structural steel items & socket weld cracks in main steam drain lines
KEATING, D E , CILIMBERG, R L , DANIELSON, D H Region 3, Office of Director 83/04/27. 6pp. 18434 082 24X Fiche 50-373, 83/04/27, 8305120415

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124, 26, 29, 1201, 14 & 830414 & notice of violation
SPESSARD, R L Division of Engineering 83/04/28 REED, C
Commonwealth Edison Co 2pp 18431 107 24X Fiche 50-373, 83/04/28, 8305120438

--8305120443 Notice of violation from insp on 821124, 26, 29, 1201, 14 & 830414
SPESSARD, R L Division of Engineering. 83/04/28 3pp
18431 109 24X Fiche 50-373, 83/04/28, 8305120438.

--8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29, 1201,14 & 830414 Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices
RAMSEY,C , ULIE,J , HASSE,R Region 3, Office of Director 83/04/27 19pp 18431 112 24X Fiche 50-373,83/04/28,8305120438

8305170398 Forwards IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 & notice of violation
STREETER,J F Region 3, Office of Director 83/04/28 REED,C Commonwealth Edison Co 2pp 18469 232 24X Fiche 50-373,83/04/28, 8305170398

--8305170400 Notice of violation from insp on 830307-0408.
STREETER,J F Region 3, Office of Director 83/04/28 1p 18469 234 24X Fiche 50-373,83/04/28,8305170398

--8305170403 IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 Noncompliance noted failure to have adequate preoperational test procedure to determine end-of-cycle recirculation pump trip sys response time
LANKSBURY,R D , DUPONT,S O , REYES,L A Region 3, Office of Director 83/04/28. 5pp 18469 235 24X Fiche 50-373,83/04/28, 8305170398

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305060542 Ack receipt of 830404 & 08 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10
SPESSARD,R L Division of Engineering 83/05/03 REED,C. Commonwealth Edison Co 1p 18348 306 24X Fiche 50-373,83/05/03, 8305060542

--8305060554 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10 Corrective actions meetings & discussions held between GA general mgt & dept lead auditors General ofcs audited
REED,C Commonwealth Edison Co 83/04/04 KEPPLER,J G Region 3, Office of Director. 17pp 18348 307 24X Fiche 50-373,83/05/03,8305060542

--8305060569 Forwards revised Page 2 to response to noncompliance noted in IE Insp Repts 50-373/82-40 & 50-374/82-10,per NRC 830214 ltr
SCHROEDER,C W Commonwealth Edison Co 83/04/08 KEPPLER,J G Region 3, Office of Director 2pp 18348 325 24X Fiche 50-373,83/05/03,8305060542

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche.50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche,50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp. 18523 248. 24X Fiche 50-000,83/05/06,8303040033

8305240241 Forwards IE Insp Rept 50-373/83-14 on 830329-0415 & notice of violation
NORELIUS,C.E Division of Project & Resident Programs 83/05/06 REED,C Commonwealth Edison Co. 2pp 18548 287 24X Fiche 50-373,83/05/06,8305240241

-8305240244 Notice of violation from insp on 830329-0415
NORELIUS,C E Division of Project & Resident Programs 83/05/06 2pp. 18548 289 24X Fiche 50-373,83/05/06,8305240241

-8305240247 IE Insp Rept 50-373/83-14 on 830329-0415 Noncompliance noted failure to have adequate surveillance procedures & failure to perform required surveillance test within periodic time interval
LANKSBURY,R D , GULDEMOND,W G , WALKER,R.D Region 3, Office of Director 83/05/06. 7pp. 18548 291. 24X Fiche 50-373,83/05/06, 8305240241.

8305130139 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/82-47 Based on info supplied,second item of noncompliance remains violation
SPESSARD,R L Region 3, Office of Director 83/05/10 REED,C Commonwealth Edison Co 1p 18436 001 24X Fiche.50-373,83/05/13, 8305130139

--8305130144 Responds to NRC 830401 ltr re violations noted in IE Insp Rept 50-373/82-47 Corrective actions instruction/review session by site project const superintendent stressed importance of procedure adherence
FARRAR,D L Commonwealth Edison Co 83/05/04 KEPPLER,J G Region 3, Office of Director 9pp 18436 002 24X Fiche 50-373,83/05/10,8305130139

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp, 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305170423 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Rept 50-373/83-03
MILLER,J R Region 3, Office of Director 83/05/12 REED,C Commonwealth Edison Co 1p 18469 290 24X Fiche 50-373,83/05/12, 8305170423

--8305170425 Responds to NRC 830329 ltr re violations noted in IE Safeguards Insp Rept 50-373/83-03 Corrective actions procedures used to test metal detectors & proposed change in description of metal detectors addressed Details withheld.
FARRAR,D L Commonwealth Edison Co 83/04/19 KEPPLER,J G Region 3, Office of Director 1p 18469 291 24X Fiche 50-373,83/05/12,8305170423

8305260329 Forwards IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 & notice of violation
STREETER,J.F Region 3, Office of Director 83/05/12 REED,C Commonwealth Edison Co 2pp 18625 120 24X Fiche 50-373,83/05/12, 8305260329

--8305260331 Notice of violation from insp on 830309-30.
STREETER,J F Region 3, Office of Director 83/05/12 1p 18625 122 24X Fiche 50-373,83/05/12,8305260329

--8305260334 IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 Noncompliance noted failure to follow mod package procedures
HASSE,R A , CHOULES,N C , FARRELL,R E Region 3, Office of Director 83/05/11 16pp 18625 123 24X Fiche 50-373,83/05/12, 8305260329

8305240301 Ack receipt of 830404 & 26 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-55 & 50-378/82-33 Due to improvement of internal communications, smoother communication w/resident inspector expected
NORELIUS,C E Division of Project & Resident Programs 83/05/17 REED,C Commonwealth Edison Co 1p 18548 115 24X Fiche 50-373,83/05/17,8305240301

--8305240308 Responds to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions onsite review conducted on 830316 & included discussion of possible broad implications of noncompliance
FARRAR,D L Commonwealth Edison Co 83/04/04 KEPPLER,J G Region 3, Office of Director 8pp 18548 116 24X Fiche 50-373,83/05/17,8305240301

--8305240315 Suppls response to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions:dept heads to prepare memo to station superintendent summarizing any potential noncompliance
FARRAR,D L Commonwealth Edison Co. 83/04/26 KEPPLER,J G Region 3, Office of Director 2pp 18548 124 24X Fiche 50-373,83/05/17,8305240301

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche.50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305040365 Forwards errata to Part 2 of "Operating Rept of Radioactive Effluents for Jul-Dec 1982 "
DIEDERICH, G J Commonwealth Edison Co 83/04/19 KEPPLER, J G
Region 3, Office of Director 1p 18323 198 24X
Fiche 50-373, 83/04/19, 8305040365

--8305040371 Errata to Part 2 of "Operating Rept of Radioactive Effluents for Jul-Dec 1982 "
* Commonwealth Edison Co 83/04/19 6pp 18323 199 24X
Fiche 50-373, 83/04/19, 8305040365

8305110447 Forwards monthly operating rept for Apr 1983
DIEDERICH, G J Commonwealth Edison Co 83/05/05 Office of Resource Management, Director 1p 18405 073 24X
Fiche 50-373, 83/05/05, 8305110447

--8305110452 Monthly operating rept for Apr 1983
LIN, D L Commonwealth Edison Co 83/05/05 13pp 18405 074 24X Fiche 50-373, 83/05/05, 8305110447

S Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11
PRENDERGAST, R Prendergast, R J 17pp 18506 059 24X
Fiche, 50-000, 83/03/11, 8305190005

--8305190084 RO fire dampers supplied by American Warming & Ventilation, Inc declared inoperative Caused by discrepancy in fuse link assembly size Fuse assemblies will be replaced JV Winkle ltr re news telecast & J Dierbeck note encl
HOLYOAK, R H. Commonwealth Edison Co 82/07/01 KEPPLER, J G
Region 3, Office of Director 33pp 18506 091 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS, D. E Zack Co 81/10/23 310pp 18506 215 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190393 Discusses Zack Co Part 21 rept re dual traveler record sys for fabrication of duct work & hangers at facility, per 820729 telcon w/L DelGeorge & C Reed AT Howard resume encl
WILLIAMS, C. C NRC - No Detailed Affiliation Given 83/03/11
LANKSBURY, R D NRC - No Detailed Affiliation Given 6pp 18512 317 24X Fiche 50-000, 83/03/11, 8305190005

8305020351 Forwards LER 83-026/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/04/13 KEPPLER, J G
Region 3, Office of Director 1p 18274 120 24X
Fiche 50-373, 83/04/13, 8305020351.

--8305020353 LER 83-026/03L-0 on 830321, radwaste discharge process radiation monitor declared inoperable. Caused by high fixed level of background radiation Task force formed to resolve problems Equipment design under investigation
ARAND, J J Commonwealth Edison Co. 83/04/13 Region 3, Office of Director 2pp 18274 121 24X Fiche 50-373, 83/04/13, 8305020351.

8305020205 Forwards LER 83-027/03L-0
DIEDERICH, G. J. Commonwealth Edison Co 83/04/15 KEPPLER, J G
Region 3, Office of Director 1p. 18278 189 24X
Fiche 50-373, 83/04/15, 8305020205

--8305020236 LER 83-027/03L-0 on 830320, steam leak on main turbine control valve 1 stem seal leakoff line ITD20AA 1-/2 inches discovered Caused by overlap of weldments Welds repaired.
SPENCER, D. Commonwealth Edison Co 83/04/15 Region 3, Office of Director 2pp 18278 190 24X Fiche. 50-373, 83/04/15, 8305020205

8305020241 Forwards LER 83-028/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/04/15 KEPPLER, J G
Region 3, Office of Director 1p 18277. 274 24X
Fiche: 50-373, 83/04/15, 8305020241

--8305020251 LER 83-028/03L-0 on 830320, steam leak discovered on offgas steam jet air ejector 1A drain line to turbine bldg equipment drains Caused by defective weldment Work Request L23380 generated to repair weldment
SPENCER, D. Commonwealth Edison Co 83/04/15 Region 3, Office of Director. 2pp 18277 275 24X Fiche: 50-373, 83/04/15, 8305020241.

8305230573 Forwards engineering evaluation rept, "Cracks & Leaks in Small Diameter Piping "
BROWN, E J Reactor Operations Analysis Branch 83/04/19
SEYFRIT, K V Reactor Operations Analysis Branch 1p 18541 342 24X Fiche 50-000, 83/04/19, 8305230573

--8305230619 "Cracks & Leaks in Small Diameter Piping," engineering evaluation rept Small pipe leaks associated w/unanticipated vibration problems require addl supports or rerouting of piping
BROWN, E J Reactor Operations Analysis Branch 83/04/19 9pp 18541 343 24X Fiche 50-000, 83/04/19, 8305230573

83050200B6 Forwards LER 83-030/03L-0
DIEDERICH, G J. Commonwealth Edison Co 83/04/21 KEPPLER, J G
Region 3, Office of Director 1p 18279 106 24X
Fiche 50-373, 83/04/21, 8305020086

--8305020090 LER 83-030/03L-0 on 830324, local leak rate test on CRD removal hatch double gasket seals incorrectly performed prior to startup Caused by personnel error Leak rate test reperformed & new Procedure LTS 100-8 initiated
HOUSTON, R W Commonwealth Edison Co 83/04/21 Region 3, Office of Director 2pp 18279 107 24X Fiche 50-373, 83/04/21, 8305020086

8305020109 Forwards LER 83-031/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/04/21 KEPPLER, J G
Region 3, Office of Director 1p 18278 199 24X
Fiche 50-373, 83/04/21, 8305020109

--8305020114 LER 83-031/03L-0 on 830324, Validyne P232 flow transmitters installed near standby gas treatment failed environ qualification testing Caused by inappropriate location near high radiation levels Instruments will be relocated
MARTINOVICH, M Commonwealth Edison Co 83/04/21 Region 3, Office of Director 3pp 18278 200 24X Fiche 50-373, 83/04/21, 8305020109

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO, S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000, 83/04/26, 8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T
Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000, 83/04/26, 8305120392

8305060493 Forwards LER 83-031/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/04/27 KEPPLER, J G
Region 3, Office of Director 1p 18348 096 24X
Fiche 50-373, 83/04/27, 8305060493

--8305060509 LER 83-031/03L-0 on 830331, turbine stop valve limit switch for reactor protection sys found out of spec Caused by improper alignment on initial installation Limit switch repositioned & new adjustable actuating arm installed
MASTERSON, V V Commonwealth Edison Co 83/04/27 Region 3, Office of Director 4pp 18348 097 24X Fiche 50-373, 83/04/27, 8305060493

8305060398 Forwards LER 83-033/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/04/28 KEPPLER, J G
Region 3, Office of Director 1p 18343 160 24X
Fiche 50-373, 83/04/28, 8305060398

--8305060401 LER 83-033/03L-0, on 830402, during hot shutdown, radwaste effluent monitor declared inoperable Caused by high fixed level of background radiation Liquid radwaste PRM inner chamber coated w/acrylic resin to prevent radiation buildup
ARAND, J Commonwealth Edison Co 83/04/28 Region 3, Office of Director 2pp 18343 161 24X Fiche 50-373, 83/04/28, 8305060398

8305170374 Forwards LER 83-034/03L-0
DIEDERICH, G J. Commonwealth Edison Co 83/05/03 KEPPLER, J G
Region 3, Office of Director 1p 18469 208 24X
Fiche 50-373, 83/05/03, 8305170374

--8305170378 LER 83-034/03L-0 on 830408, during LIS-HP-10, level indicating switch 1B21-N100A as-found setpoint exceeded Tech Spec value Caused by setpoint drift Switch setpoint recalibr
HOUSTON, R W Commonwealth Edison Co 83/05/03 Region 3, Office of Director 2pp 18469 209 24X Fiche 50-373, 83/05/03, 8305170374

8305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attached hold tags to 13 HVAC control panels w/defect Evaluation being conducted
HALL, D P Illinois Power Co 83/05/04 KEPPLER, J G Region 3, Office of Director 2pp 18431 049 24X Fiche 50-000, 83/05/04, 8305120475

--8305120484 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformance rept will be issued for applicable sites
FAUCONNEAU, G Mark Controls Corp. 83/04/18 Director's Office, Office of Inspection and Enforcement 2pp 18431 051 24X Fiche 50-000, 83/05/04, 8305120475

8305170383 Forwards LER 83-035/03L-0
DIEDERICH, G J Commonwealth Edison Co 83/05/04 KEPPLER, J G Region 3, Office of Director 1p 18469 213 24X Fiche 50-373, 83/05/04, 8305170383

--8305170388 LER 83-035/03L-0 on 830406, offgas hydrogen analyzer 1A not maintaining proper vacuum & analyzer 1B not wired properly. Caused by dirty flame arrestor on analyzer A Flame arrestor cleaned Analyzer B rewired
HOUSTON, R W Commonwealth Edison Co 83/05/04 Region 3, Office of Director. 2pp 18469 214 24X Fiche 50-373, 83/05/04, 8305170383

8305240229 LER 83-038/03L-0 on 830207, during performance of LIS-HP-09, head correction omitted from calibr test pressure, leaving instrument 1E22-N013 out of tolerance Caused by misunderstanding of procedures W/830504 ltr
TAYLOR, R , DIEDERICH, G. J. Commonwealth Edison Co 83/05/04. KEPPLER, J G Region 3, Office of Director 4pp 18548 311. 24X Fiche. 50-373, 83/05/04, 8305240229

8305240007 RO on 820715, ultraviolet fire detectors taken out of svc Due to continued const work, fire detectors to be out of svc until Fall 1983 fuel load
DIEDERICH, G J Commonwealth Edison Co. 83/05/10 KEPPLER, J G Region 3, Office of Director 1p 18549 038 24X Fiche: 50-373, 83/05/10, 8305240007

8305240318 LER 83-036/03L-0 on 830414, welding Procedures WPS 1-5-A & 5-5-A discovered in conflict w/ASME Code. Repairs to main steam drain line welds made using subj procedures Evaluation of procedures in process W/830504 ltr
SPENCER, D A , DIEDERICH, G. J Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 3pp 18548 075 24X Fiche 50-373, 83/05/10, 8305240318

8305240354 LER 83-037/03L-0 on 830421, while in cold shutdown, liquid radwaste effluent process radiation monitor declared inoperable Caused by not performing acceptable source check due to high level of internal contamination W/830510 ltr.
ARAND, J J , DIEDERICH, G. J Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 3pp. 18575: 104 24X Fiche: 50-373, 83/05/10, 8305240354

8305240381 LER 83-040/03L-0 on 830412, stack wide-range gas monitor mid-range noble gas recorder 0D18-R521 produced unusual readings Caused by electronic noise Original power supply reinstalled in mid-range recorder W/830511 ltr
MASTERSON, V , DIEDERICH, G J Commonwealth Edison Co 83/05/10 KEPPLER, J. G. Region 3, Office of Director 4pp 18549 341 24X Fiche 50-373, 83/05/10, 8305240381

8305240025 LER 83-041/03L-0 on 830414, steam leak in weld fittings on instrument line 1MS798A-1 inch discovered Caused by insufficient weld matl Weld ground out & connections rewelded W/830511 ltr
WATFORD, P G , DIEDERICH, G. J Commonwealth Edison Co 83/05/11 KEPPLER, J G Region 3, Office of Director 2pp 18549 052 24X Fiche 50-373, 83/05/11, 8305240025.

8305240334 NPDES noncompliance notification between 830411-17, composite sample & analysis not performed Caused by personnel error Personnel to be instructed on proper setup of composite sampler W/830512 ltr
DIEDERICH, G J Commonwealth Edison Co 83/05/12 KEPPLER, J G Region 3, Office of Director 3pp. 18549 358 24X Fiche: 50-373, 83/05/12, 8305240334

8305240073 RO on 830424, during surveillance, smoke observed coming out of diesel fire pump OA valve covers Pump shipped to manufacturer to determine cause of failure New diesel pump installed & tested
DIEDERICH, G J Commonwealth Edison Co. 83/05/13 KEPPLER, J G. Region 3, Office of Director. 1p. 18549 093. 24X Fiche 50-373, 83/05/13, 8305240073

8305240425 LER 83-039/03L-0 on 830418, during visual insp, mechanical snubbers found locked between hot & cold settings Caused by movement in excess of snubber travel range or defective snubber Snubber replaced. W/830517 ltr
SPENCER, D A , DIEDERICH, G J Commonwealth Edison Co 83/05/17 KEPPLER, J G Region 3, Office of Director 3pp 18571 058 24X Fiche 50-373, 83/05/17, 8305240425

8305270237 RO on 830322, scram occurred on low reactor water level. HPCS & RCIC sys auto initiated due to low reactor water level Caused by receiving rept of B flow control valve ramping open on spurious signal
DIEDERICH, G J Commonwealth Edison Co 83/05/17 KEPPLER, J G Region 3, Office of Director 1p 18637 156 24X Fiche 50-373, 83/05/17, 8305270237

8305270195 LER 83-042/03L-0 on 830423, during MSIV local leak rate test, inboard MSIV found exceeding allowable leak rate of 25 SCFH Caused by less than perfect seating of disc & seat surfaces. Inboard MSIVs, discs & seats lapped & machined W/830520 ltr
MASTERSON, V , DIEDERICH, G J Commonwealth Edison Co 83/05/20 KEPPLER, J G Region 3, Office of Director 4pp 18637: 339 24X Fiche 50-373, 83/05/20, 8305270195

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

8305190005 Final response to FOIA request for documents re Zack Co w/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11. PRENDERGAST, R Prendergast, R J 17pp 18506 059. 24X Fiche 50-000, 83/03/11, 8305190005

--8208250506 Trip rept of 820802 audit, reviewing seismic & qualification file for Zack Co equipment, at Sargent & Lundy Engineers ofc in Chicago, IL
ROSZTOCZY, Z R Equipment Qualification Branch 82/08/06 SCHWENCER, A Licensing Branch 2 8pp 18507. 201. 24X Fiche 50-000, 83/03/11, 8305190005

--8305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removal welds Certain welds on Unit 2, Div II switchgear heat removal sys may not meet applicable code requirements
HOLYOAK, R H Commonwealth Edison Co. 82/09/06. Region 3, Office of Director 1p 18507 200 24X Fiche 50-000, 83/03/11, 8305190005

--8305190302 Forwards Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const, LaSalle County Station Units 1 & 2 " QC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired
POLLOCK, R H Sargent & Lundy, Inc 82/08/27 SHELTON, B R Commonwealth Edison Co 1p 18507 317 24X Fiche 50-000, 83/03/11, 8305190005

--8305190303 Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const, LaSalle County Station Units 1 & 2 "
CHO, F. L , KISISEL, I T , MELIGI, A V Sargent & Lundy, Inc CQD-003490 R00 82/08/27 27pp 18507 318 24X Fiche 50-000, 83/03/11, 8305190005

--8305190332 Forwards "LaSalle County Station Independent HVAC Review," interim rept Rept also sent to JG Keppler
KEMPIAK, A J, C F Braun & Co 82/09/15 SHELTON, B R Commonwealth Edison Co 1p 18507 359 24X Fiche 50-000, 83/03/11, 8305190005

--8305190353 Forwards TE Watts 821019 & 25 memos to CW Schroeder responding to R Lanksbury questions re HVAC ductwork design & transmitting Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station."
SCHROEDER, C W Commonwealth Edison Co 82/10/27 KEPPLER, J G Region 3, Office of Director 9pp 18508 093 24X Fiche 50-000, 83/03/11, 8305190005

--8305190357 Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station Units 1 & 2 "
* Sargent & Lundy, Inc 82/10/21 9pp 18508 102 24X Fiche 50-000, 83/03/11, 8305190005

--8305190365 Forwards Vols 1-4 to "Independent HVAC Review, LaSalle County Nuclear Plant," final rept
KEMPIAK, A J C F. Braun & Co 82/10/27 SHELTON, B R Commonwealth Edison Co 1p 18508 111 24X Fiche. 50-000, 83/03/11, 8305190005

--8305190367 Ack receipt of CF Braun final rept of independent HVAC review at facilities
PHILLIPS,R W Region 3, Office of Director 82/10/27 Region 3, Office of Director 1p 18508 112 24X Fiche 50-000,83/03/11, 8305190005

--8305190379 Requests list of results of detailed calculations on rebar damage for 647 concrete elements affecting Unit 1 operation & approved CF Braun proposal for independent HVAC review
Zack Co chronology encl
GOODIE,J S Illinois, State of 82/09/07 KEPPLER,J G Region 3, Office of Director 5pp 18511 278 24X Fiche 50-000, 83/03/11,8305190005

--8305190390 P Donahue show Transcript 08302 re nuclear power safety Info re facilities & Zack Co encl
* Multimedia Program Production, Inc 83/03/11 128pp 18512.189 24X Fiche 50-000,83/03/11,8305190005

8304290034 Requests documented acceptance of General Motors Electro-Motive Div (EMD) MI 9644 mod as acceptable alternative to diesel generator prelube oil pump EMD clarification of prelube requirements encl
SCHROEDER,C W Commonwealth Edison Co 83/04/26 SCHWENCER,A Licensing Branch 2 3pp 18265 274 24X Fiche 50-373,83/04/26, 8304290034

8305110082 Forwards "Test Rept on Verification Testing of Separation Between Class IE & Non-Class IE Power Cables in Raceways " Written confirmation of closure of License Condition 2 C (24) requested.
SCHROEDER,C W Commonwealth Edison Co 83/05/03 SCHWENCER,A Licensing Branch 2 2pp 18397 239 24X Fiche 50-373,83/05/03, 8305110082.

--8305110089 "Test Rept on Verification Testing of Separation Between Class IE & Non-Class IE Power Cables in Raceways "
HAZELTINE,J., JOHNSON,F., ROBERTS,W Wyle Laboratories 46511-3 83/03/28. 181pp. 18397:241 24X Fiche 50-373,83/05/03, 8305110082

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D.G. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche.50-000,83/05/09,8305090659

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876). Supporting documentation encl
REED,C. Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche.50-000,83/05/11,8305200621

--8305200637 "Energy,Inc/Ferguson,Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN,R N , HARRIS,R.J Energy Incorporated FERGUSON,R.N Ferguson, Inc. 82/07/06 63pp 18521 095 24X Fiche.50-000,83/05/11,8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD,T., MARCUS,Q F Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fiche 50-000,83/05/11,8305200621.

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl.
MARCUS,Q F. Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche:50-000,83/05/11,8305200621

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed."
BIGBEE,D., CURRAN,R.N , FARMAN,R F Energy Incorporated. 83/04/04 127pp. 18523.027 24X Fiche 50-000,83/05/11, 8305200621

8305230584 Submits editorial rev to Specific Action 10 per 821228 response to Generic Ltr 81-04 re measures to minimize intergranular stress corrosion cracking General & specific corrective actions discussed NUREG-0313 compliance achieved.
SCHROEDER,C.W. Commonwealth Edison Co 83/05/19. LAINAS,G.C. Licensing Branch 2 4pp. 18537:313 24X Fiche:50-373,83/05/19, 8305230584.

8305240110 Forwards Tables 3 9 4 & 3 9-4A comparing NRC fuel assembly load combinations in horizontal plane,vertical plane & design basis loads Encl tables will be included in FSAR Amend 63 to be submitted by 830630
SCHROEDER,C W Commonwealth Edison Co 83/05/19 SCHWENCER,A Licensing Branch 2 4pp 18548 343 24X Fiche 50-373,83/05/19, 8305240110

8305240111 Confirms 830513 telcon re schedule for installation of instrumentation for automatic scram to shut down reactor in event of low pressure scram in control rod drive sys
SCHROEDER,C W Commonwealth Edison Co 83/05/19 SCHWENCER,A Licensing Branch 2 2pp 18548 347 24X Fiche 50-374,83/05/19, 8305240111

8305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing matl tests
SPESSARD,R L Division of Engineering 83/05/24 REED,C Commonwealth Edison Co. 1p 18644 087 24X Fiche.50-000,83/05/24, 8305270476

--8305270501 Rev 1 to "Evaluation of Three Legged Pipe Whip Restraint Sys "
MA,J S , YANG,M S , AMIN,M Sargent & Lundy, Inc S 15 1-0 R01 82/09/21 47pp 18644 099 24X Fiche 50-000,83/05/24,8305270476

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan
GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000,83/05/26,8305310086

F Security, medical, emergency & fire protection plans

83052400B7 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
FELTON,J M Division of Rules and Records 83/03/31 GARDE,B Government Accountability Project 2pp 18593 015 24X Fiche 50-373,83/03/31,8305240087

--8305230144 Recommends unsorted access to protected areas for R Lipinski & S Chan Rapifac sheet transmitting evaluation of technical rept, "Assessment of Effects of Nicked Reinforcing Steel," encl
KEPPLER,J G. Region 3, Office of Director 82/06/14 REED,C Commonwealth Edison Co 7pp 18593 056 24X Fiche 50-373,83/03/31,8305240087

8305050402 Forwards request for addl info re fire protection for safe shutdown,based on review of Amend 62 to FSAR
SCHWENCER,A Licensing Branch 2 83/04/28 FARRAR,D L Commonwealth Edison Co 3pp 18352 046 24X Fiche.50-373,83/04/28, 8305050402

8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29,1201,14 & 830414 & notice of violation
SPESSARD,R L Division of Engineering 83/04/28 REED,C Commonwealth Edison Co 2pp 18431.107 24X Fiche 50-373,83/04/28, 8305120438

--8305120443 Notice of violation from insp on 821124,26,29,1201,14 & 830414
SPESSARD,R L. Division of Engineering 83/04/28 3pp 18431 109 24X Fiche 50-373,83/04/28,8305120438

--8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29, 1201,14 & 830414. Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices
RAMSEY,C , WILLIAMS,C.C Region 3, Office of Director 83/04/27 19pp 18431.112 24X Fiche 50-373,83/04/28,8305120438

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034.

8305130149 Ack receipt of 830419 ltr informing NRC of objectives & providing scenario outline for 830712 exercise
PAPERIELLO,C.J Region 3, Office of Director, 83/05/11 REED,C Commonwealth Edison Co 1p 18437:136 24X Fiche 50-373,83/05/11, 8305130149

8305130155 Forwards list of objectives, scope of participation, scenario outline & narrative summary for emergency exercise scheduled for 830712
BLACKMON, T G Commonwealth Edison Co 83/04/19 HIND, J
Division of Emergency Preparedness & Operational Support 15pp
18437 157 24X Fiche 50-373, 83/05/11, 8305130149

Adjudicatory correspondence

8052004B1 Advises that time for Commission to review Director's Decision DD-83-1 expired Commission declined review Decision became final agency action on 830506
CHILK, S J Office of the Secretary of the Commission 83/05/19
HARTIGAN, N Illinois, State of AOREM, B L Friends of the Earth
GOGOL, E M Citizens Against Nuclear Power 1p 18513 014 24X
Fiche 50-373, 83/05/19, 8305200481

Inspection reports, IE Bulletins & correspondence

305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11
PRENDERGAST, R Prendergast, R J 17pp 18506 059 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190045 Requests vendor insp of facilities having contracts w/Zack Co due to QA/QC problems at Midland re HVAC activities Zack Co correspondence re LaSalle & related info encl
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 POTOPOVS, U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000, 83/03/11, 8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co, HVAC contractor at facilities, re potential allegations Zack Co planning to terminate several employees in document control section
HAYES, D W Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche 50-000, 83/03/11, 8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000, 83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co, HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE, T Government Accountability Project 82/07/26
PALLADINO, N J Commissioners 11pp 18506 128 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co, HVAC contractor at facilities
MARELLO, S L Affiliation Unknown 82/07/26 22pp 18506 139.
24X Fiche 50-000, 83/03/11, 8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co, HVAC contractor at facilities
HOWARD, A T Affiliation Unknown 82/07/26 55pp 18506 160
24X Fiche 50-000, 83/03/11, 8305190005

--8305190119 Repts investigation re possible flawed equipment at facilities, per Eyewitness News broadcast
* Radio TV Reports, Inc 82/07/26 NRC - No Detailed Affiliation Given 2pp 18507 165 24X Fiche 50-000, 83/03/11, 8305190005

--8305190128 Forwards outline of investigation rept re Zack documentation concerning HVAC activities Discussion of matl spec & mechanical properties for galvanized sheet steel & stiffener hanger & support steel & L DelGeorge handwritten notes encl
NORELIUS, C E Region 3, Office of Director 82/07/28
KEPPLER, J G , DAVIS, A B , FOSTER, J Region 3, Office of Director
25pp 18507 149 24X Fiche 50-000, 83/03/11, 8305190005

--8305190151 Informs of atty general of State of IL intention to attend NRC 820811 meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations
VAN VRANKEN, J Illinois, State of 82/08/09 KEPPLER, J G
Region 3, Office of Director 1p 18507 209 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190162 Introduction of 820811 public meeting to discuss util plans re employment of third party contractor to conduct independent review of HVAC sys at facilities
* NRC - No Detailed Affiliation Given 82/08/11 2pp
18507 214 24X Fiche 50-000, 83/03/11, 8305190005

--8305190167 Requests that all interested parties be furnished proposed contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized
VAN VRANKEN, J Illinois, State of 82/08/12 KEPPLER, J G
Region 3, Office of Director 2pp 18507 215 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & S Marello experience & knowledge be utilized in review process Util 820813 ltr to CF Braun & Co encl
HOWARD, A T Affiliation Unknown 82/08/13 KEPPLER, J G Region 3, Office of Director 11pp 18507 216 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190184 Confirms 820812 telcon re telephone call from M Cherry concerning Zack investigation & circumstances surrounding termination of Zack employees
DAVIS, A B Region 3, Office of Director 82/08/16 FITZGERALD, J Office of Investigation 2pp 18507 230 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190283 Introduction of 820824 public meeting to discuss util preliminary plans re independent review of HVAC sys at facilities Meeting will focus on CF Braun technical proposals
* NRC - No Detailed Affiliation Given 83/08/24 1p 18507 266.
24X Fiche 50-000, 83/03/11, 8305190005

--8305190289 Forwards T Devine 820813 ltr, AT Howard 820813 ltr & SB Marello 820816 ltr for NRR consideration in assessment of util proposal on third party review of HVAC sys at facilities
SPESSARD, R L Division of Project & Resident Programs 82/08/25
EISENHUT, D G Division of Licensing 1p 18507 293 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190292 Advises that AT Howard & SB Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co, subj to listed conditions Related info encl
DEVINE, T Government Accountability Project 82/08/13
KEPPLER, J Region 3, Office of Director 16pp 18507 294 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities CF Braun should rept directly to NRC & should audit all critical areas at facilities
MARELLO, S L Affiliation Unknown 82/08/16 KEPPLER, J Region 3, Office of Director 3pp 18507 313 24X Fiche 50-000, 83/03/11, 8305190005

--8305190304 Discusses concerns on behalf of AT Howard & S Marello, for NRC consideration in review of CF Braun final proposal to conduct independent review of HVAC sys at facilities, per 820824 meeting
DEVINE, T Government Accountability Project 82/09/04
KEPPLER, J G Region 3, Office of Director 6pp 18507 345 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190329 Responds to 820904 ltr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taken into consideration in NRR review of proposal
KEPPLER, J G Region 3, Office of Director 82/09/13 DEVINE, T
Government Accountability Project 1p. 18507 357 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190387 Rev 1 to "LaSalle County Station Technical Proposal," including scope of work, work plan to accomplish independent HVAC review, organization chart & resumes of personnel assigned to project List of matl specs for HVAC const encl.
* C F Braun & Co. 82/08/25 34pp 18512 155 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
NORELIUS, C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000, 83/03/11, 8305190005

--8305190399 Handwritten notes re meeting w/util on allegations concerning Zack Co activities at facilities
DAVIS, A B NRC - No Detailed Affiliation Given 82/07/16 9pp.
18512 335 24X Fiche 50-000, 83/03/11, 8305190005

8305120346 Forwards IE Insp Rept 50-374/83-07 on 830224-25 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/03/16 REED,C Commonwealth Edison Co 2pp 18433 064 24X Fiche 50-374,83/03/16, 8305120346

--8305120353 IE Insp Rept 50-374/83-07 on 830224-25 No noncompliance noted Major areas inspected organization,radiation protection procedures,facilities,instruments & equipment & progress of certain sys demonstrations & tests
MILLER,D E , GREGER,L R. Region 3, Office of Director 83/03/14 5pp. 18433 066 24X Fiche 50-374,83/03/16,8305120346

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305090306 Addl response to FOIA request for all records prepared at Region III,all investigators involved in investigation of T Howard & S Morella allegations & all internal records re problems discovered at facility Forwards App B documents.
FELTON,J M Division of Rules and Records 83/03/22 GARDE,B Government Accountability Project 2pp 18381 216 24X Fiche 50-373,83/03/22,8305090306

--8305090313 IE Investigation Repts 50-373/82-51 & 50-374/82-15 on 820721-1001 No noncompliance noted Major areas investigated followup on allegations re matl procurement & QA deficiencies of HVAC sys installed by Zach Co
LANKSBURY,R D , WESTCOTT,H M Region 3, Office of Director 82/08/16 4pp 18381 219 24X Fiche 50-373,83/03/22,8305090306

8305240087 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of facility during May-Jul 1982 Forwards App C documents
FELTON,J M Division of Rules and Records 83/03/31 GARDE,B Government Accountability Project 2pp 18593 015 24X Fiche 50-373,83/03/31,8305240087

--8305240098 Five draft summaries of affidavits & statements,draft comments on followup of allegations,minutes of Region III 820329,0419,0503 & 0706 staff meetings & draft investigation schedule Personally identifiable info deleted
* NRC - No Detailed Affiliation Given 83/03/25 36pp 18593 018 24X Fiche 50-373,83/03/31,8305240087.

--8305240125 Discusses actions planned during addl insp to resolve concerns re adequacy of workmanship during const of masonry walls R Lipinski assistance requested to resolve issues starting wk of 820815
SPESSARD,R L Division of Project & Resident Programs 82/08/17 EISENHUT,D G Division of Licensing 2pp. 18593 054 24X Fiche. 50-373,83/03/31,8305240087

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435.155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc 119pp. , 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305120361 Forwards IE Insp Rept 50-374/83-11 on 830322-25 & 29 & 30 & notice of violation.
LITTLE,W.S Region 3, Office of Director 83/04/26 REED,C Commonwealth Edison Co 2pp 18431 136. 24X Fiche 50-374,83/04/26, 8305120361

--8305120364 Notice of violation from insp on 830322-25 & 29 & 30
LITTLE,W.S Region 3, Office of Director 83/04/26 1p 18431.138 24X Fiche.50-374,83/04/26,8305120361.

--8305120368 IE Insp Rept 50-374/83-11 on 830322-25 & 29 & 30 Noncompliance noted.failure to translate FSAR requirements into instructions & procedures to establish separation of cables belonging to different reactor protection sys.
NAIDU,K R., AHMED,I., WILLIAMS,C.C. Region 3, Office of Director 83/04/22. 7pp 18431 139. 24X Fiche.50-374,83/04/26,8305120361

8305120415 Forwards IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncompliance noted
LITTLE,W S Region 3, Office of Director 83/04/27 REED,C Commonwealth Edison Co 2pp 18434 080 24X Fiche 50-373,83/04/27, 8305120415

--8305120420 IE Insp Repts 50-373/83-13 & 50-374/83-03 on 830131-0421 No noncompliance noted Major areas inspected as-built walkdown & review of procedures for structural steel items & socket weld cracks in main steam drain lines
KEATING,D E , CILIMBERG,R L , DANIELSON,D H Region 3, Office of Director 83/04/27 6pp 18434 082 24X Fiche 50-373,83/04/27, 8305120415

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305120438 Forwards IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29,1201,14 & 830414 & notice of violation
SPESSARD,R L Division of Engineering 83/04/28 REED,C Commonwealth Edison Co 2pp 18431 107 24X Fiche 50-373,83/04/28, 8305120438

--8305120443 Notice of violation from insp on 821124,26,29,1201,14 & 830414
SPESSARD,R L Division of Engineering 83/04/28 3pp 18431 109 24X Fiche 50-373,83/04/28,8305120438

--8305120447 IE Insp Repts 50-373/82-54 & 50-374/82-22 on 821124,26,29, 1201,14 & 830414 Noncompliance noted failure to write nonconformance repts & failure to comply w/10CFR50,App B, Criterion II re housekeeping practices
RAMSEY,C , ULIE,J , HASSE,R Region 3, Office of Director 83/04/27 19pp 18431 112 24X Fiche 50-373,83/04/28,8305120438

8305170398 Forwards IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 & notice of violation
STREETER,J F Region 3, Office of Director 83/04/28 REED,C Commonwealth Edison Co 2pp 18469 232 24X Fiche 50-373,83/04/28, 8305170398

--8305170403 IE Insp Repts 50-373/83-11 & 50-374/83-06 on 830307-0408 Noncompliance noted failure to have adequate preoparational test procedure to determine end-of-cycle recirculation pump trip sys response time
LANKSBURY,R D , DUPONT,S G , REYES,L A Region 3, Office of Director 83/04/28 5pp 18469 239 24X Fiche 50-373,83/04/28, 8305170398

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305060542 Ack receipt of 830404 & 08 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10
SPESSARD,R L Division of Engineering 83/05/03 REED,C Commonwealth Edison Co 1p 18348 306 24X Fiche 50-373,83/05/03, 8305060542

--8305060554 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-373/82-40 & 50-374/82-10 Corrective actions meetings & discussions held between QA general mgt & dept lead auditors General ofcs audited
REED,C Commonwealth Edison Co 83/04/04 KEPPLER,J G Region 3, Office of Director 17pp 18348 307 24X
Fiche 50-373,83/05/03,8305060542

--8305060569 Forwards revised Page 2 to response to noncompliance noted in IE Insp Repts 50-373/82-40 & 50-374/82-10,per NRC 830214 ltr
SCHROEDER,C W Commonwealth Edison Co 83/04/08 KEPPLER,J G Region 3, Office of Director 2pp 18348 325 24X
Fiche 50-373,83/05/03,8305060542

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305170322 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-374/83-05
SPESSARD, R L Division of Engineering 83/05/11 REED, C Commonwealth Edison Co 1p 18465 232 24X Fiche 50-374, 83/05/11, 8305170322

--8305170331 Responds to NRC 830405 ltr re violations noted in IE Insp Rept 50-374/83-05. Corrective actions requirement for testing LPCS sys excess flow check valve incorporated into nuclear boiler Preoperational Test PT-NB-201.
FARRAR, D L Commonwealth Edison Co 83/05/04 KEPPLER, J G Region 3, Office of Director 6pp 18465 233 24X
Fiche 50-374, 83/05/11, 8305170322

8305260329 Forwards IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 & notice of violation
STREETER, J F Region 3, Office of Director 83/05/12 REED, C Commonwealth Edison Co 2pp 18625 120 24X Fiche 50-373, 83/05/12, 8305260329

--8305260334 IE Insp Repts 50-373/83-15 & 50-374/83-13 on 830309-30 Noncompliance noted failure to follow mod package procedures
HASSE, R A , CHOULES, N C , FARRELL, R E Region 3, Office of Director. 83/05/11 16pp 18625 123 24X Fiche, 50-373, 83/05/12, 8305260329

8305240301 Ack receipt of 830404 & 26 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Due to improvement of internal communications, smoother communication w/resident inspector expected
NORELIUS, C E Division of Project & Resident Programs. 83/05/17 REED, C Commonwealth Edison Co 1p 18548 115 24X
Fiche 50-373, 83/05/17, 8305240301

--8305240308 Responds to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions onsite review conducted on 830316 & included discussion of possible broad implications of noncompliance
FARRAR, D L Commonwealth Edison Co 83/04/04 KEPPLER, J G Region 3, Office of Director 8pp 18548 116 24X
Fiche 50-373, 83/05/17, 8305240301

--8305240315 Suppls response to NRC 830223 ltr re violations noted in IE Insp Repts 50-373/82-55 & 50-374/82-33 Corrective actions dept heads to prepare memo to station superintendent summarizing any potential noncompliance
FARRAR, D L Commonwealth Edison Co 83/04/26 KEPPLER, J G Region 3, Office of Director 2pp 18548 124 24X
Fiche, 50-373, 83/05/17, 8305240301

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

B Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records. 83/03/11 PRENDERGAST, R Prendergast, R J 17pp. 18506 059 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS, D E Zack Co 81/10/23 310pp 18506 215 24X
Fiche 50-000, 83/03/11, 8305190005

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328. Matter under investigation Final rept by 830808 Reported per Part 21
MANNO, S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000, 83/04/26, 8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T. Region 4, Office of Director 3pp 18433 074 24X
Fiche 50-000, 83/04/26, 8305120392

8305100018 Interim Deficiency Rept 83-01 re temp offset problems experienced w/Riley temp switches installed in leak detection sys Calibr procedure modified & switches recalibr Final rept will be submitted by 830601.
* Commonwealth Edison Co 83/05/02 KEPPLER, J G. Region 3, Office of Director 1p 18377 152 24X Fiche 50-374, 83/05/02, 8305100018

8305100352 Updated interim deficiency rept re offset & module problems of Riley temp indicating switches in leak detection sys Calibr procedure modified Final resolution of module problem (hardware mod) in progress Final rept expected by 830601
SCHROEDER, C W Commonwealth Edison Co 83/05/03 KEPPLER, J G. Region 3, Office of Director 1p 18379 092 24X
Fiche 50-374, 83/05/03, 8305100352

8305240007 RO on 820715, ultraviolet fire detectors taken out of svc Due to continued const work; fire detectors to be out of svc until Fall 1983 fuel load
DIEDERICH, G J Commonwealth Edison Co 83/05/10 KEPPLER, J G Region 3, Office of Director 1p 18549 038 24X
Fiche 50-373, 83/05/10, 8305240007

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

8305020502 Forwards comments on C-E Owners Group calculations re depressurization & DHR capability of C-E plants w/o pressurizer PORVs, discussed at 830112 meeting w/C-E Owners Group in Bethesda, MD
NOVAK, T M Assistant Director for Licensing 83/04/19 MAURIN, L V Louisiana Power & Light Co 4pp. 18284 333 24X
Fiche 50-382, 83/04/19, 8305020502

8305020341 Requests extension of commitment re athropometric concern w/highest row of meters on remote shutdown panel LCP-43 by providing permanent metal deck in front panel per human factors audit findings
MAURIN, L V Louisiana Power & Light Co. 83/04/25 KNIGHTON, G Licensing Branch 3 2pp 18277 115 24X Fiche 50-382, 83/04/25, 8305020341

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing. 83/05/04. PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G. Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659.

8305130343 Forwards Board Notification 83-64 re issuance of 40-yr OL
EISENHUT, D G Division of Licensing 83/05/10. NOVAK, T. M. Assistant Director for Licensing. 2pp 18456 227 24X
Fiche 50-382, 83/05/10, 8305130343

--8305130344 Board Notification 83-64 forwards util 830318 request for 40-yr OL
NOVAK, T M Assistant Director for Licensing. 83/05/10 Atomic Safety and Licensing Board Panel. 8pp. 18456 228 24X
Fiche 50-382, 83/05/10, 8305130343

8305240258 Notification of 830523 site visit to conduct control room audit & discuss revs to emergency operating procedures
WILSON, J H Licensing Branch 3 83/05/10 KNIGHTON, G W Licensing Branch 3 3pp 18593 297 24X Fiche 50-382, 83/05/10, 8305240258

8305180468 Forwards responses to NRC concerns raised at 830218 meeting w/util to close out open items re emergency feedwater control sys, per NUREG-0787, Suppl 1 W/23 oversize drawings
Aperture cards are available in PDR
MAURIN, L V Louisiana Power & Light Co 83/05/13 KNIGHTON, G W Licensing Branch 3 31pp 18482 131 24X Fiche 50-382, 83/05/13, 8305180468

8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs.
NOVAK, T M Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X Fiche 50-000, 83/05/18, 8305250209

--8305250221 Requests that encl documents on status of DHR studies for C-E plants, w/emphasis on need for PORVs in current C-E designs, be provided to ASLB & ASLAB.
MATTSON, R. J Division of Systems Integration (post 811005) 83/04/28 EISENHUT, D G Division of Licensing 1p 18627 113. 24X Fiche 50-000, 83/05/18, 8305250209

--8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630
DIRCKS, W J. Office of the Executive Director for Operations 83/04/25 CHILK, S J. Office of the Secretary of the Commission 1p. 18627 115 24X Fiche 50-000, 83/05/18, 8305250209

8305310094 Forwards revised description of NUREG-0737, Item II F 2, "Inadequate Core Cooling Instrumentation," providing sufficient info to close item & corresponding requirement in SER.
DRUMMOND, F J Louisiana Power & Light Co 83/05/23 KNIGHTON, G W Licensing Branch 3 34pp. 18655 039 24X Fiche 50-382, 83/05/23, 8305310094

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8305310094 Forwards revised description of NUREG-0737, Item II. F 2, "Inadequate Core Cooling Instrumentation," providing sufficient info to close item & corresponding requirement in SER
DRUMMOND, F. J Louisiana Power & Light Co 83/05/23 KNIGHTON, G W Licensing Branch 3. 34pp 18655:039 24X Fiche 50-382, 83/05/23, 8305310094

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl.
EISENHUT, D G. Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X Fiche: 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W. J Office of the Executive Director for Operations. 83/05/13. PALLADINO, N J. Commissioners 5pp 18593 322. 24X Fiche 50-000, 83/05/13, 8305240213.

8305200285 Forwards list of NRC emergency preparedness insp team personnel requiring unescorted & unrestricted access to facility on 830523-27. Site orientation on issuance of badges, escort duties & emergency evacuation requested
COLLINS, J. T Region 4, Office of Director 83/05/16 MAURIN, L V Louisiana Power & Light Co 2pp. 18517.065 24X Fiche: 50-382, 83/05/16, 8305200285

G. Adjudicatory correspondence

8305120322 Order granting NRC 830415 motion to correct 830208-11 hearing transcript.
WOLFE, B J. Atomic Safety and Licensing Board Panel 83/05/11 Office of the Executive Legal Director 1p 18432 266 24X Fiche: 50-382, 83/05/11, 8305120322.

8305180429 Advises that all sirens within emergency planning zone will be tested by parish officials for rotational function, output & audibility at perimeter of each siren effective range Svc list encl.
RIDGWAY, D. A Shaw, Pittman, Potts & Trowbridge. RIDGWAY, D. A Louisiana Power & Light Co 83/05/16 TURK, S E Hearing Branch 1 4pp. 18485:294 24X Fiche. 50-382, 83/05/16, 8305180429

8305200642 Corrects statements made at 830419 oral argument Neither NRC nor FEMA will independently verify accuracy of siren measurements NRC method for verifying siren coverage adequacy delineated
TURK, S E Hearing Branch 1 83/05/18 EILPERIN, S F, KOHL, C N, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 6pp 18520 129 24X Fiche 50-382, 83/05/18, 8305200642

8305270634 Second partial initial decision in OL hearing Requests that NRC ascertain that changes &/or mods to preemergency public info brochure implemented
JORDAN, W H, FOREMAN, H, WOLFE, S J Atomic Safety and Licensing Board Panel 83/05/26 34pp 18646 264 24X Fiche 50-382, 83/05/26, 8305270634

H. General correspondence

8305170290 Informs that correspondence signed by FJ Drummond, RP Barkhurst & TF Gerrets should be accepted as valid submittals
CAVANAUGH, W Louisiana Power & Light Co 83/05/13 KNIGHTON, G W Licensing Branch 3 1p 18465 358 24X Fiche 50-382, 83/05/13, 8305170290

O. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction" Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308.319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305200190 Informs that 830316 order imposing civil penalty & accompanying info should be transmitted to ASLB & parties, per Ofc Ltr 19 procedures
EISENHUT, D G Division of Licensing 83/04/19 NOVAK, T Assistant Director for Licensing 1p 18576 133 24X Fiche 50-382, 83/04/19, 8305200190

--8305200199 Board Notification 83-52 notifies that order imposing civil penalty issued to util on 830316 resulting from breakdown in QA/QC program
NOVAK, T M Assistant Director for Licensing 83/04/19. Atomic Safety and Licensing Board Panel. 4pp 18576 134 24X Fiche 50-382, 83/04/19, 8305200190

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383.089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 113pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment" Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305170004 Forwards IE Insp Rept 50-382/83-16 on 830328-31 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/04/29 MAURIN, L V Louisiana Power & Light Co 2pp 18466 242 24X Fiche 50-382, 83/04/29, 8305170004

--8305170009 IE Insp Rept 50-382/83-16 on 830328-31 No noncompliance noted. Major areas inspected safety-related records, site-related design activities & potential const deficiency re emergency feedwater turbine-driven pump
OBERG, C R, CROSSMAN, W A Region 4, Office of Director. 83/04/25. 9pp 18466 244. 24X Fiche 50-382, 83/04/29, 8305170004

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305200251 Forwards IE Investigation Rept 50-382/82-09 on 820329-0516 & notice of violation
MADSEN, G L Region 4, Office of Director 83/05/04 MAURIN, L V
Louisiana Power & Light Co 2pp 18517 067 24X
Fiche 50-382, 83/05/04, 8305200251

--8305200253 Notice of violation from investigation on 820329-0516
* Region 4, Office of Director 83/05/04 1p 18517 069 24X
Fiche 50-382, 83/05/04, 8305200251

--8305200256 IE Investigation Rept 50-382/82-09 on 820329-0516 Noncompliance noted individual in plant metrology lab performed equipment calibr w/o being properly qualified
DRISKILL, D D , JOHNSON, E H Region 4, Office of Director
83/03/10 12pp 18517 070 24X Fiche 50-382, 83/05/04, 8305200251

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305200285 Forwards list of NRC emergency preparedness insp team personnel requiring unescorted & unrestricted access to facility on 830523-27 Site orientation on issuance of badges, escort duties & emergency evacuation requested
COLLINS, J T Region 4, Office of Director 83/05/16 MAURIN, L V
Louisiana Power & Light Co 2pp 18517.065 24X
Fiche 50-382, 83/05/16, 8305200285

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 007 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305050017 Forwards nuclear organization staffing status rept as of 830415 & status rept of personnel commitments contained in 810420 ltr
MAURIN, L V Louisiana Power & Light Co 83/04/20 WILSON, J NRC -
No Detailed Affiliation Given 3pp 18338 331 24X
Fiche 50-382, 83/04/20, 8305050017

S Reportable occurrences, LERs & related correspondence

8305060008 Board Notification 83-40 notifies of applicant commitment to periodically survey industrial & transportation activities in plant area to maintain awareness of significant product changes, per preliminary notification dtd 830322
NOVAK, T M Assistant Director for Licensing 83/04/22 Atomic Safety and Licensing Board Panel 4pp 18354 292 24X
Fiche 50-382, 83/04/22, 8305060008

8305020411 Final Significant Const Deficiency 64 re low safety injection tanks, discharge flow rates during preoperational testing C-E analysis performed per Nonconformance Rept W3-4636 Flow rates acceptable
MAURIN, L V Louisiana Power & Light Co 83/04/25 COLLINS, J. T.
Region 4, Office of Director 3pp 18273 097 24X
Fiche 50-382, 83/04/25, 8305020411

8305020450 Final Significant Const Deficiency Rept 69 re failure of Crosby Valve & Gauge Co Stellite Alloy 6B discs to meet ASME requirements Solid Stellite 6B valve discs meet all ASME Code Section 3 requirements
MAURIN, L V Louisiana Power & Light Co 83/04/25 COLLINS, J T
Region 4, Office of Director 1p 18281 249 24X
Fiche 50-382, 83/04/25, 8305020450

8305020479 First interim rept of Significant Const Deficiency 76 re damage to pressurizer heaters during precore hot functional testing Initially reported on 830311 Unacceptable heaters will be replaced/reworked Next rept expected by 830715
MAURIN, L V Louisiana Power & Light Co 83/04/25 COLLINS, J T
Region 4, Office of Director 2pp 18283 268 24X
Fiche 50-382, 83/04/25, 8305020479

8305060425 Forwards rev to seismic qualification completion schedule.
MAURIN, L V Louisiana Power & Light Co 83/04/27, KNIGHTON, G W
Licensing Branch 3 32pp 18343 193 24X Fiche 50-382, 83/04/27, 8305060425

8305060566 Final Deficiency Rept 110 re damage to main steam piping supports Initially reported on 830325 Evaluation completed Condition determined not reportable Hydraulic transient attributed to improper operation of sys
MAURIN, L V. Louisiana Power & Light Co 83/04/27 COLLINS, J T
Region 4, Office of Director 2pp, 18349 053 24X
Fiche 50-382, 83/04/27, 8305060566

8305060367 First Interim Significant Deficiency Rept 78 re insufficien documentation from American Bridge for reactor auxiliary & fuel handling bldgs bolting & welding Nonconformance repts issued Next rept by 830630
MAURIN, L V Louisiana Power & Light Co 83/04/28, COLLINS, J T
Region 4, Office of Director 3pp. 18344 148 24X
Fiche 50-382, 83/04/28, 8305060367

8305060587 Third Interim Significant Const Deficiency Rept 53 re possible failure of GE Type HFA relays. Submittal of final rept delayed until 830615 due to plant testing
MAURIN, L V Louisiana Power & Light Co 83/04/29 COLLINS, J T
Region 4, Office of Director. 1p 18349 010 24X
Fiche 50-382, 83/04/29, 8305060587

8305130019 NPDES noncompliance notification on 830317-19, approx 200,000 gallons of condenser hotwell water released from NPDES outfall Number 002 Caused by necessity to drain secondary sys & Units 1 & 2 waste treatment ponds full.
MAURIN, L V Louisiana Power & Light Co 83/05/06 KNIGHTON, G W
Licensing Branch 3 4pp 18437 149 24X Fiche 50-382, 83/05/06, 8305130019

8305170223 Second Intgrim Const Deficiency Rept 72 re radiation monitoring sys RM-23 control modules Initially reported on 830321 Corrective action scheduled for completion by 830615 Final rept will be submitted by 830630.
MAURIN, L V Louisiana Power & Light Co 83/05/11 COLLINS, J T
Region 4, Office of Director 1p 18466 340 24X
Fiche 50-382, 83/05/11, 8305170223

8305170265 Second interim Significant Const Deficiency Rept SCD 71 re failure to properly review condition identification & work authorization for reportability Initially reported on 830211 Forms being reviewed Final rept expected by 830815
MAURIN, L V Louisiana Power & Light Co 83/05/11 COLLINS, J. T
Region 4, Office of Director 2pp 18465 018 24X
Fiche 50-382, 83/05/11, 8305170265.

8305170327 First Interim Const Deficiency Rept 79 re unqualified components in hydrogen analyzers Initially reported on 830415 Field insp by Ebasco determined that pump bearings contained grease qualified for LOCA environ
MAURIN, L V Louisiana Power & Light Co 83/05/11. COLLINS, J T
Region 4, Office of Director . 4pp 18465 169. 24X
Fiche 50-382, 83/05/11, 8305170327.

8305170351 Sixth interim rept of Significant Const Deficiency Rept 35 re matl properties of tube track & welding fittings JC White fittings tested by Lucious Pitkins, Inc Corrective actions will be completed 830630. Final rept by 830720
MAURIN, L V Louisiana Power & Light Co 83/05/11. COLLINS, J. T.
Region 4, Office of Director 1p 18465 266. 24X
Fiche 50-382, 83/05/11, 8305170351

8305170484 Third Interim Const Deficiency Rept 60 re turnover documentation & inadequate hanger weld problems Initially reported on 830214 Corrective actions 95% complete Final rept will be submitted by 830715
MAURIN,L V Louisiana Power & Light Co 83/05/11 O'REILLY,J P
Region 2, Office of Director 1p 18470 067 24X
Fiche 50-382,83/05/11,8305170484

8305170492 Second Interim Const Deficiency Rept 70 re GE 480-volt trip coils not dropping out after tripping Initially reported on 830321 Corrective actions scheduled for completion by 830601,Final rept will be submitted by 830622
MAURIN,L V Louisiana Power & Light Co 83/05/11 COLLINS,J T
Region 4, Office of Director 1p 18470 054 24X
Fiche:50-382,83/05/11,8305170492

8305170500 Sixth Interim Const Deficiency Rept 33 re chilled water piping supports Initially reported on 830307 Hardware mods complete Review of supporting documentation underway Final rept will be submitted by 830630
MAURIN,L V. Louisiana Power & Light Co 83/05/11 COLLINS,J T
Region 4, Office of Director 1p 18470 035 24X
Fiche 50-382,83/05/11,8305170500

8305200542 Sixth interim rept re Significant Const Deficiency Rept 54 on tube steel (HT-166) lamination Corrective action completed by replacing 240 ft of tube steel installed in safety-related sys Final rept delayed until 830623
DRUMMOND,F.J Louisiana Power & Light Co 83/05/16 COLLINS,J T.
Region 4, Office of Director 1p 18515 355 24X
Fiche,50-382,83/05/16,8305200542

8305270138 Interim Significant Deficiency Rept 80 re unsatisfactory stroking of emergency feedwater pump turbine steam shutoff valves Initially reported on 830420 Vendor rept submitted on 830429 & springs replaced Next rept by 830729
DRUMMOND,F.J Louisiana Power & Light Co 83/05/20 COLLINS,J T
Region 4, Office of Director 2pp 18638 163 24X
Fiche 50-382,83/05/20,8305270138

8305270147 Sixth interim deficiency rept re incorrect structural calculations for holdup & boric acid make up tanks Corrective action scheduled for completion by 830531 Final rept will be delayed until 830621
DRUMMOND,F J Louisiana Power & Light Co 83/05/20 COLLINS,J T'
Region 4, Office of Director 1p 18638 160 24X
Fiche:50-382,83/05/20,8305270147

8305270194 Second interim Significant Const Deficiency Rept 77 re inadequate containment purge valve closure time & flow rate.Hardware corrective action complete Final rept will be submitted by 830630.
DRUMMOND,F J Louisiana Power & Light Co 83/05/20 COLLINS,J.T
Region 4, Office of Director 1p. 18637,343 24X
Fiche 50-382,83/05/20,8305270194.

8305270373 Significant Const Deficiency Rept 73 re American Bridge reactor containment bldg structural steel welding defects.Reinsp scheduled Corrective action rework will be completed.Next rept will be provided by 830815.
DRUMMOND,F J. Louisiana Power & Light Co 83/05/20 COLLINS,J T
Region 4, Office of Director 1p, 18642 336 24X
Fiche:50-382,83/05/20,8305270373

DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8305050285 Releases public version of temporary change to emergency plan procedure
FELTON,J.M Division of Rules and Records 83/04/25 Document Management Branch. 1p. 18352:070 24X Fiche 50-387,83/04/25, 8305050285

--8305050289 Forwards public version of Temporary Change 83-575 to Emergency Plan Procedure EP-IP-044, "Emergency Environ Sampling." Receipt form encl
* Pennsylvania Power & Light Co. 83/04/14 SCHWENCER,A NRC -
No Detailed Affiliation Given 3pp 18352:071 24X
Fiche:50-387,83/04/25,8305050285

8305030144 Forwards application for proposed Amend 23 to License NPF-14,changing License Condition 2.C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737,Item III.A.1.2 (Generic Ltr 82-33).
CURTIS,N.W Pennsylvania Power & Light Co 83/04/29 SCHWENCER,A.
Licensing Branch 2. 1p 18306 328 24X Fiche 50-387,83/04/29, 8305030144.

--8305030153 Application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737,Item III A 1 2
CURTIS,N W Pennsylvania Power & Light Co 83/04/29 2pp
18306 329 24X Fiche 50-387,83/04/29,8305030144

8305130310 Releases public version of rev to emergency plan implementing procedure
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18456 237 24X Fiche 50-387,83/05/02, 8305130310

--8305130311 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr "
* Pennsylvania Power & Light Co 83/04/20 SCHWENCER,A NRC -
No Detailed Affiliation Given 1p 18456 238 24X
Fiche,50-387,83/05/02,8305130310

--8305130314 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr "
* Pennsylvania Power & Light Co. 83/04/20 96pp 18456 239
24X Fiche 50-387,83/05/02,8305130310

8305200091 Forwards request for addl info re Rev 6 to emergency plan, needed to complete review Info requested by 830520
SCHWENCER,A Licensing Branch 2 83/05/09 CURTIS,N W
Pennsylvania Power & Light Co 5pp 18540 358 24X
Fiche 50-387,83/05/09,8305200091

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095. 24X
Fiche 50-000,83/05/11,8305110034

K Utility Final Safety Analysis Report (FSAR) & amends

8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FSAR
CURTIS,N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER,A
Licensing Branch 2 6pp 18405 100 24X Fiche 50-387,83/05/05, 8305110097

--8305110104 Application for Amend 54 to OLs containing Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/05/05 1p 18405 107 24X
Fiche 50-387,83/05/05,8305110097

--8305110108 Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/04/30 323pp 18405 108
24X Fiche 50-387,83/05/05,8305110097

P Operating license stage documents & correspondence

8303300772 Forwards addl guidance re reporting offsite radiation doses to public
SCHWENCER,A Licensing Branch 2 83/03/24 CURTIS,N W
Pennsylvania Power & Light Co 4pp 17765 244 24X
Fiche 50-387,83/03/24,8303300772

8305040669 Forwards SER on BWR Owners Group generic response to NUREG-0737,Item II K 3 18, "Mod of Automatic Depressurization Sys (ADS) Logic " Response acceptable w/ stipulated conditions Response requested expediently
SCHWENCER,A Licensing Branch 2 83/04/25 CURTIS,N W
Pennsylvania Power & Light Co 10pp 18336 338 24X
Fiche 50-387,83/04/25,8305040669

8305110160 Forwards 467 oversize drawings,per Reg Guide 1.70 Drawing transmittal list encl Aperture cards are available in PDR
MOLCHANY,W J Pennsylvania Power & Light Co 83/04/25.
SCHWENCER,A Licensing Branch 2 20pp 18406 318 24X
Fiche 50-387,83/04/25,8305110160

8305040546 Requests remittance of Class III fee for 821110 application re nonconformance w/NUREG-0737,Item II E 4 2 on containment isolation dependability
DIGGS,R M License Fee Management Branch 83/04/27 CURTIS,N,W
Pennsylvania Power & Light Co 1p, 18351 230 24X
Fiche 50-387,83/04/27,8305040546

8305020387 Responds to NRC 830203 & 0330 questions re proposed SRP Amend 19 No need exists to arbitrarily increase initial power to account for uncertainty in power level Errata sheet & transient summary of feedwater controller failure encl.
CURTIS, N W Pennsylvania Power & Light Co 83/04/28 SCHWENCER, A Licensing Branch 2 4pp 18276 314 24X Fiche 50-387, 83/04/28, 8305020387.

8305030144 Forwards application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737, Item III A 1.2 (Generic Ltr 82-33)
CURTIS, N W Pennsylvania Power & Light Co 83/04/29 SCHWENCER, A Licensing Branch 2 1p 18306 328 24X Fiche 50-387, 83/04/29, 8305030144

--8305030153 Application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (28)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737, Item III A 1 2
CURTIS, N W Pennsylvania Power & Light Co 83/04/29 2pp 18306 329 24X Fiche 50-387, 83/04/29, 8305030144

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G. Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp. 18441.120 24X Fiche 50-000, 83/05/02, 8305020455

8305040616 Ack completion of action required by Amend 7 to License NPF-14, Paragraph 3 by initiating DOE negotiations concerning disposal of high level waste or spent nuclear fuel.
SCHWENCER, A Licensing Branch 2 83/05/02 CURTIS, N W Pennsylvania Power & Light Co 2pp 18351 225 24X Fiche. 50-387, 83/05/02, 8305040616

8305100016 Forwards proposed Amend 24 to License NPF-14, changing App A Tech Specs re circuit breaker location, gaseous release type, bypass damper leakage & reactor vessel level instrumentation
KENYON, B D Pennsylvania Power & Light Co 83/05/04 SCHWENCER, A Licensing Branch 2 4pp 18377 126 24X Fiche 50-387, 83/05/04, 8305100016

--8305100019 Proposed Amend 24 to License NPF-14, changing App A Tech Specs re circuit breaker location, gaseous release type, bypass damper leakage & reactor vessel level instrumentation
KENYON, B D. Pennsylvania Power & Light Co 83/05/04 1p 18377 130 24X Fiche 50-387, 83/05/04, 8305100016

--8305100021 Proposed changes to App A Tech Specs, including Tables 4 11 2 1 2-1, 4 4, 6 1 3-1 & 3.3 9-2, Spec 4.7 2 b 1 & Section 8 0
* Pennsylvania Power & Light Co 83/05/04 13pp 18377 131 24X Fiche 50-387, 83/05/04, 8305100016

8305100308 Forwards "Offsite Dose Calculation Manual."
CURTIS, N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER, A Licensing Branch 2 1p 18370 004 24X Fiche 50-387, 83/05/05, 8305100308

--8305100317 "Offsite Dose Calculation Manual "
* Pennsylvania Power & Light Co 83/04/27 76pp. 18370:005 24X Fiche 50-387, 83/05/05, 8305100308

8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FSAR
CURTIS, N W Pennsylvania Power & Light Co 83/05/05. SCHWENCER, A Licensing Branch 2 4pp. 18405 100 24X Fiche 50-387, 83/05/05, 8305110097

--8305110104 Application for Amend 54 to OLs containing Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/05/05 1p 18405 107 24X Fiche 50-387, 83/05/05, 8305110097

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT, D G. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18427.153 24X Fiche 50-000, 83/05/09, 8305090659

8305130114 Forwards responses to questions re ultimate heat sink test plan Calibr temp measuring device will be used to measure temp in main stilling well in pumphouse Tests will be performed during Jul or Aug 1983.
CURTIS, N W Pennsylvania Power & Light Co 83/05/10. SCHWENCER, A Licensing Branch 2. 7pp. 18438 082 24X Fiche 50-387, 83/05/10, 8305130114

8305200176 Approves licensee 830225 submittal w/description of permanent mods to 12-inch gas pipeline near facility, limiting flow & precluding flammable mixture at facility air intakes
SCHWENCER, A Licensing Branch 2 83/05/10 CURTIS, N W Pennsylvania Power & Light Co 2pp 18540 232 24X Fiche 50-387, 83/05/10, 8305200176

8305190285 Advises that util participating in BWR Owners Group Committee to address fast scram issues Due to delays caused by addl testing, BWR rept will not be received in time for response in Second Quarter 1983
CURTIS, N W Pennsylvania Power & Light Co 83/05/16 SCHWENCER, A. Licensing Branch 2 1p 18501 147 24X Fiche 50-387, 83/05/16, 8305190285

8305190295 Forwards drawing of mod to resolve essential svc water single failure issue Mod allows manual shutoff valves in RHR room & corrects loss of both RHR pumps in one div
CURTIS, N W Pennsylvania Power & Light Co 83/05/16 SCHWENCER, A. Licensing Branch 2. 3pp 18500 218 24X Fiche: 50-387, 83/05/16, 8305190295

8305230541 Advises that util endorses BWR Owners Group rept NEDO-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity " Proposed amend to License NPF-14 will be submitted to reflect position.
CURTIS, N W Pennsylvania Power & Light Co 83/05/19 SCHWENCER, A. Licensing Branch 2. 2pp 18537 335 24X Fiche 50-387, 83/05/19, 8305230541

8305270064 Forwards equipment qualification summary rept Summary info submitted complete for Unit 1 but only partially complete for Unit 2 Next rev of rept will contain complete info for Unit 2.
CURTIS, N W Pennsylvania Power & Light Co 83/05/20 SCHWENCER, A. Licensing Branch 2 766pp. 18635 095. 24X Fiche. 50-387, 83/05/20, 8305270064.

8305310208 Fowards check in payment of review re nonconformance w/ NUREG-0737, Item II E. 4 2, per 830427 request
CURTIS, N. W Pennsylvania Power & Light Co 83/05/25 SCHWENCER, A Licensing Branch 2. 1p. 18658 133 24X Fiche 50-387, 83/05/25, 8305310208

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptability to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche. 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp. 18381.291 24X Fiche. 50-000, 83/04/25, 8303040025

8305050366 Grants util 830303 preservice insp relief requests. Encl technical evaluation will be incorporated into future suppl to SER
SCHWENCER, A Licensing Branch 2 83/04/25 CURTIS, N W Pennsylvania Power & Light Co 2pp 18352 026. 24X Fiche. 50-387, 83/04/25, 8305050366.

--8305050373 Supplemental SER, supporting preservice insp relief request
* NRC - No Detailed Affiliation Given 83/04/25. 17pp 18352 028. 24X Fiche 50-387, 83/04/25, 8305050366

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28. Consolidated Edison Co. of New York, Inc 115pp. 18382 047. 24X Fiche. 50-000, 83/04/28, 8303040026.

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305110149 Notification of 830517 meeting w/util onsite to discuss results of SALP
MCCABE, E C Region 1, Office of Director 83/04/29 Region 1, Office of Director, 1p 18421 346 24X Fiche: 50-387, 83/04/29, 8305110149

8305060543 Submits addl info re IE Bulletin 82-01, Rev 1, Suppl 1, "Alterations of Radiographs of Welds in Piping Subassemblies," per 830330 request Three radiographs dispositioned per PSI ultrasonic exam, ASME Code Section XI
CURTIS, N W. Pennsylvania Power & Light Co 83/05/02 ALLAN, J M Region 1, Office of Director 3pp 18347 306 24X Fiche 50-387, 83/05/02, 8305060543

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03, Consolidated Edison Co of New York, Inc 122pp. 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp. 18382:282. 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 119pp. 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06. Consolidated Edison Co. of New York, Inc 119pp. 18523 248 24X Fiche. 50-000, 83/05/06, 8303040033.

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11. Consolidated Edison Co of New York, Inc. 114pp. 18524 003. 24X Fiche 50-000, 83/05/11, 8303040034.

8305250571 Forwards IE Insp Rept 50-387/83-10 on 830314-15 No noncompliance noted.
MARTIN, T T. Division of Engineering & Technical Programs 83/05/13
KENYON, B.D Pennsylvania Power & Light Co. 2pp 18588.211 24X Fiche: 50-387, 83/05/13, 8305250571.

--8305250575 IE Insp Rept 50-387/83-10 on 830314-15 No noncompliance noted. Major areas inspected, open items from IE Insp Rept 50-387/82-36 re radiographic documentation & NDE.
KERCH, H Region 1, Office of Director. 83/04/20 3pp. 18588:213 24X Fiche: 50-387, 83/05/13, 8305250571

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/19. Consolidated Edison Co. of New York, Inc. 114pp. 18697:009. 24X Fiche 50-000, 83/05/19, 8303040040.

8305270255 Forwards response to Enforcement Action 83-26 & payment of civil penalty. Supervisor of operations conducted training sessions w/each shift to ensure all significant aspects of event understood
KENYON, B.D. Pennsylvania Power & Light Co. 83/05/20. DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 8pp. 18637:141. 24X Fiche: 50-387, 83/05/20, 8305270255

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl.
JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 114pp. 18647:007. 24X Fiche: 50-000, 83/05/26, 8303040046.

B. Reportable occurrences, LERs & related correspondence

8305030334 Forwards LER 83-051/03L-0.
KEISER, H. W. Pennsylvania Power & Light Co. 83/04/21 ALLAN, J. M Region 1, Office of Director. 1p. 18297:141. 24X Fiche: 50-387, 83/04/21, 8305030334.

--8305030338 LER 83-051/03L-0 on 830322, RCIC turbine tripped on electrical overspeed signal Caused by slow operation of governor valve RCIC quick testing frequency increased to monthly
KUCZYNSKI, L A Pennsylvania Power & Light Co 83/04/21. Region 1, Office of Director 2pp 18297 142 24X Fiche 50-387, 83/04/21, 8305030334

8305120422 Forwards updated LER 82-001/01X-1
KEISER, H W Pennsylvania Power & Light Co 83/04/21 ALLAN, J M Region 1, Office of Director 1p 18433 238 24X Fiche 50-387, 83/04/21, 8305120422

--8305120430 Updated LER 82-001/01X-1 on 820718, linear indications found on recirculation riser weld A-11M Caused by slag inclusion in A-11M weld & partial cold lap on 1/4 inch A-13 weld Weld areas excavated & repaired
TODD, J T Pennsylvania Power & Light Co 83/04/21 Region 1, Office of Director 2pp 18433 239 24X Fiche 50-387, 83/04/21, 8305120422.

8305110241 Forwards LER 83-052/03L-0
KEISER, H W Pennsylvania Power & Light Co 83/04/22 ALLAN, J M Region 1, Office of Director. 1p 18406 340 24X Fiche: 50-387, 83/04/22, 8305110241

--8305110247 LER 83-052/03L-0: on 830325, during surveillance test, CREOASS train A tripped Caused by fan belts coming off fan pulley Belts replaced & bearings & fan pulley realigned
KUCZYNSKI, L A Pennsylvania Power & Light Co 83/04/22 Region 1, Office of Director 1p. 18406:341 24X Fiche 50-387, 83/04/22, 8305110241

8305110348 Forwards LER 83-053/03L-0
KEISER, H W Pennsylvania Power & Light Co. 83/04/25 ALLAN, J M. Region 1, Office of Director. 1p. 18404.349 24X Fiche 50-387, 83/04/25, 8305110348

--8305110358 LER 83-053/03L-0 on 830326 & 30, containment hydrogen & oxygen analyzer B declared inoperable due to erratic readings Investigation underway. Air in-leakage suspected
KUCZYNSKI, L A Pennsylvania Power & Light Co. 83/04/25 Region 1, Office of Director 2pp 18404 350 24X Fiche 50-387, 83/04/25, 8305110348

8305110421 Forwards LER 83-054/03L-0
KEISER, H W Pennsylvania Power & Light Co 83/04/28 ALLAN, J. M. Region 1, Office of Director 1p 18404 356. 24X Fiche: 50-387, 83/04/28, 8305110421

--8305110430 LER 83-054/03L-0 on 830401, one hydraulic control unit found w/pressure below allowable limit. Caused by leaking connections Procedural changes instituted to recharge any accumulator w/low pressure, but above alarm point
PIEMONTESE, A P Pennsylvania Power & Light Co. 83/04/28 Region 1, Office of Director 1p. 18404 357 24X Fiche 50-387, 83/04/28, 8305110421

8305060442 LER 83-057/01P-0 confirms 830428 telcon re incident concerning bypass leakage calculations for feedwater following DBA LOCA
KEISER, H W Pennsylvania Power & Light Co 83/04/29. ALLAN, J. M Region 1, Office of Director 1p. 18343 146 24X Fiche. 50-387, 83/04/29, 8305060442

8305060592 Forwards LER 83-055/03L-0.
KEISER, H W Pennsylvania Power & Light Co. 83/04/29. ALLAN, J. M Region 1, Office of Director 1p 18349 008 24X Fiche 50-387, 83/04/29, 8305060592

--8305060598 LER 83-055/03L-0 on 830405, while calibr safety relief valve acoustic monitoring sys, one monitor did not indicate that respective valve open Faulty indication caused by broken pin on accelerometer connector Connector replaced.
KUCZYNSKI, L A Pennsylvania Power & Light Co 83/04/29. Region 1, Office of Director 1p 18349:009. 24X Fiche 50-387, 83/04/29, 8305060592

8305160140 Corrected RO on 821221, actual total activity released was 14 uCi at concentration of 1 37E-5 uCi/ml instead of 4 82 uCi at concentration of 4.7E-6 uCi/ml Release figures well below required reporting limits.
KEISER, H W. Pennsylvania Power & Light Co. 83/04/29. ALLAN, J. M Region 1, Office of Director. 1p. 18446:104 24X Fiche. 50-387, 83/04/29, 8305160140

8305160132 RO. on 830212, ECCS actuated, resulting in reactor scram on main turbine control valve fast closure Event occurred again on 830322 when reactor scrammed due to main steam line high radiation Planned HPCI injections initiated 821229-830404.
KEISER, H W. Pennsylvania Power & Light Co 83/05/04. ALLAN, J. M Region 1, Office of Director 2pp 18446.188 24X Fiche 50-387, 83/05/04, 8305160132

8305230471 Forwards LER 83-059/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/05/04 ALLAN,J M
Region 1, Office of Director 1p 18537 194 24X
Fiche 50-387,83/05/04,8305230471

--8305230477 LER 83-059/03L-0 on 830404,following full MSIV isolation, test data showed Level 1 acceptance criteria for one valve not met Event under investigation Updated LER to be forwarded shortly
PIEMONTESE,A P Pennsylvania Power & Light Co 83/05/04
Region 1, Office of Director 2pp 18537 195 24X
Fiche 50-387,83/05/04,8305230471

8305160124 Forwards LER 83-058/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/05/06 ALLAN,J M
Region 1, Office of Director 1p 18448 183 24X
Fiche 50-387,83/05/06,8305160124

--8305160151 LER 83-058/03L-0 on 830409,during scheduled surveillance tests,two reactor pressure vessel water level switches found out of tolerance Caused by setpoint drift Engineering evaluation re use of analog transmitters underway
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/05/06 Region 1, Office of Director 1p 18448 184 24X Fiche 50-387,83/05/06, 8305160124

8305190319 Interim deficiency rept re failure of GE reactor mode switch to actuate reactor protection sys channel Initially reported on 830407 Franklin Inst test & analysis rept on 830322 switch failure encl Final rept for Unit 2 by 831001
CURTIS,N W Pennsylvania Power & Light Co 83/05/06 ALLAN,J M
Region 1, Office of Director 2pp 18501 025 24X
Fiche 50-387,83/05/06,8305190319

--8305190322 "Susquehanna Unit 1 Reactor Mode Switch Failure Modes & Mechanisms," final rept
* Franklin Institute/Franklin Research Center F-A5818-1
83/04/29 30pp 18501 027 24X Fiche 50-387,83/05/06,8305190319

8305200555 Forwards LER 83-063/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/05/11 ALLAN,J M
Region 1, Office of Director 1p 18514 257 24X
Fiche 50-387,83/05/11,8305200555

--8305200561 LER 83-063/03L-0 on 830411,main steam line drain valve leakage exceeded Tech Spec limit Cause not stated Seal ring replaced,outboard valve lapped & valves reassembled
TODD,J T Pennsylvania Power & Light Co 83/05/11 Region 1, Office of Director 1p 18514 258 24X Fiche 50-387,83/05/11, 8305200555

8305200640 Forwards LER 83-060/03L-0
KEISER,H W Pennsylvania Power & Light Co 83/05/11 ALLAN,J M
Region 1, Office of Director 1p 18520 150 24X
Fiche 50-387,83/05/11,8305200640

--8305200646 LER 83-060/03L-0 on 830411,reactor protection sys actuation caused Div II of RHR to isolate while in shutdown cooling mode Caused by const worker bumping breaker handle for 4kV safeguard LC X-fmr Cause unknown LER will be updated
KUCZYNSKI,L A Pennsylvania Power & Light Co 83/05/11 Region 1, Office of Director 1p 18520 151 24X Fiche 50-387,83/05/11, 8305200640

DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

A Application/construction stage documents & correspondence

8305040669 Forwards SER on BWR Owners Group generic response to NUREG-0737,Item II K 3.18, "Mod of Automatic Depressurization Sys (ADS) Logic " Response acceptable w/ stipulated conditions Response requested expediently
SCHWENCER,A Licensing Branch 2 83/04/25 CURTIS,N W
Pennsylvania Power & Light Co 10pp 18336 338 24X
Fiche 50-387,83/04/25,8305040669

8305110160 Forwards 467 oversize drawings,per Reg Guide 1 70 Drawing transmittal list encl Aperture cards are available in PDR
MOLCHANY,W J Pennsylvania Power & Light Co 83/04/25
SCHWENCER,A Licensing Branch 2 20pp 18406 318 24X
Fiche 50-387,83/04/25,8305110160

8305100426 Notification of 830525-27 meetings w/util in Luzerne County, PA to assess status of const & completion schedules Meeting on 830525 open to public Agenda encl
PERCH,R Licensing Branch 2 83/05/05 SCHWENCER,A Licensing Branch 2 1p 18621 194. 24X Fiche 50-388,83/05/05,8305100426

8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FSAR
CURTIS,N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER,A
Licensing Branch 2. 6pp 18405 100 24X Fiche 50-387,83/05/05, 8305110097.

--8305110104 Application for Amend 54 to OLs containing Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/05/05 1p 18405 107 24X
Fiche 50-387,83/05/05,8305110097

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing, 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130114 Forwards responses to questions re ultimate heat sink test plan Calibr temp measuring device will be used to measure temp in main stilling well in pumphouse Tests will be performed during Jul or Aug 1983
CURTIS,N W Pennsylvania Power & Light Co 83/05/10 SCHWENCER,A, Licensing Branch 2 7pp, 18438 082 24X Fiche 50-387,83/05/10, 8305130114

8305190285 Advises that util participating in BWR Owners Group Committee to address fast scram issues Due to delays caused by addl testing,BWR rept will not be received in time for response in Second Quarter 1983
CURTIS,N W Pennsylvania Power & Light Co 83/05/16 SCHWENCER,A
Licensing Branch 2 1p 18501 147 24X Fiche 50-387,83/05/16, 8305190285

8305230541 Advises that util endorses BWR Owners Group rept NEDO-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity " Proposed amend to License NPF-14 will be submitted to reflect position.
CURTIS,N W Pennsylvania Power & Light Co 83/05/19 SCHWENCER,A
Licensing Branch 2 2pp 18537 335 24X Fiche 50-387,83/05/19, 8305230541

8305270064 Forwards equipment qualification summary rept Summary info submitted complete for Unit 1 but only partially complete for Unit 2 Next rev of rept will contain complete info for Unit 2
CURTIS,N W Pennsylvania Power & Light Co 83/05/20 SCHWENCER,A
Licensing Branch 2 766pp 18635,095 24X Fiche 50-387,83/05/20, 8305270064

F Security, medical, emergency & fire protection plans

8305050285 Releases public version of temporary change to emergency plan procedure.
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch, 1p. 18352 070 24X Fiche 50-387,83/04/25, 8305050285

--8305050289 Forwards public version of Temporary Change 83-575 to Emergency Plan Procedure EP-IP-044, "Emergency Environ Sampling." Receipt form encl
* Pennsylvania Power & Light Co 83/04/14 SCHWENCER,A NRC - No Detailed Affiliation Given 3pp 18352 071 24X
Fiche 50-387,83/04/25,8305050285

8305130310 Releases public version of rev to emergency plan implementing procedure
FELTON,J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18456 237 24X Fiche 50-387,83/05/02, 8305130310

--8305130311 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr "
* Pennsylvania Power & Light Co 83/04/20 SCHWENCER,A NRC - No Detailed Affiliation Given 1p 18456 238 24X
Fiche 50-387,83/05/02,8305130310

--8305130314 Public version of Rev 1 to Emergency Plan Implementing Procedure EP-IP-030, "Activation & Functional Operation of Emergency Operations Facility & Transfer of Control From Technical Support Ctr "
* Pennsylvania Power & Light Co 83/04/20 96pp. 18456 239 24X Fiche 50-387,83/05/02,8305130310

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D.G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095. 24X
Fiche.50-000,83/05/11,8305110034

K Utility Final Safety Analysis Report (FSAR) & amends

8305110097 Forwards application for Amend 54 to OLs containing Rev 33 to FSAR
CURTIS,N W Pennsylvania Power & Light Co 83/05/05 SCHWENCER,A Licensing Branch 2 6pp 18405 100 24X Fiche 50-387,83/05/05, 8305110097

--8305110104 Application for Amend 54 to OLs containing Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/05/05 1p 18405 107 24X Fiche 50-387,83/05/05,8305110097

--8305110108 Rev 33 to FSAR
* Pennsylvania Power & Light Co 83/04/30 323pp 18405 108 24X Fiche 50-387,83/05/05,8305110097

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptability to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J.M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308·319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047. 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 118pp 18382,165. 24X Fiche 50-000,83/04/28,8303040027

8305110149 Notification of 830517 meeting w/util onsite to discuss results of SALP
MCCABE,E C Region 1, Office of Director 83/04/29 Region 1, Office of Director 1p 18421 346 24X Fiche 50-387,83/04/29, 8305110149

8305060543 Submits addl info re IE Bulletin 82-01,Rev 1,Suppl 1, "Alterations of Radiographs of Welds in Piping Subassemblies," per 830330 request Three radiographs dispositioned per PSI ultrasonic exam,ASME Code Section XI
CURTIS,N W Pennsylvania Power & Light Co 83/05/02 ALLAN,J M Region 1, Office of Director 3pp 18347 306 24X Fiche:50-387,83/05/02,8305060543

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp 18382·282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp. 18441:001. 24X Fiche.50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305160140 Corrected RO on 821221,actual total activity released was 14 uCi at concentration of 1 37E-5 uCi/ml instead of 4 82 uCi at concentration of 4 7E-6 uCi/ml Release figures well below required reporting limits
KEISER,H W Pennsylvania Power & Light Co 83/04/29 ALLAN,J M Region 1, Office of Director 1p 18446 104 24X Fiche 50-387,83/04/29,8305160140

8305110258 PNO-I-83-047 on 830504,contractor employee entered roped-off area for radiographic exams of pipe welds & received approx 40 mrem dose No overexposure identified Industrial radiography suspended pending completion of evaluation
MCCANN, MCCABE Region 1, Office of Director 83/05/05 1p 18393 290 24X Fiche 50-388,83/05/05,8305110258

DOCKET 50-389 ST LUCIE PLANT, UNIT 2

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020590 Forwards Suppl 3 to SER W/o encl
KNIGHTON,G W Licensing Branch 3 83/04/20 UHRIG,R E Florida Power & Light Co 2pp 18284 230 24X Fiche 50-389,83/04/20, 8305020590

F Security, medical, emergency & fire protection plans

8305270289 Forwards IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/29 UHRIG,R E Florida Power & Light Co 2pp 18638 352 24X Fiche 50-389,83/03/29,8305270289

--8305270293 IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted Major areas inspected fire protection
MILLER,W H , CONLON,T E Region 2, Office of Director 83/03/28 7pp 18638 354 24X Fiche 50-389,83/03/29,8305270289

8305270098 Forwards IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted.
DANCE,H C Division of Project & Resident Programs 83/04/19 UHRIG,R E Florida Power & Light Co 2pp 18662 125 24X Fiche.50-389,83/04/19,8305270098

--8305270101 IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted Major areas inspected cable fire stops,radiation monitors,relay coordination study,IE bulletins & QA audits
HUNT,M.D Region 2, Office of Director CONLON,T E Division of Engineering & Radiological Safety Programs 83/04/15 5pp 18662 127 24X Fiche 50-389,83/04/19,8305270098

8305030231 Releases public version of revised offnormal & emergency operating procedures
FELTON,J M Division of Rules and Records 83/04/22 Document Management Branch 1p. 18310 077. 24X Fiche 50-389,83/04/22, 8305030231

--8305030240 Forwards public version of revised offnormal & emergency operating procedures,including Procedures 2-0120035 re pressurizer pressure & level & 2-0760030 re dc ground isolation
WETHY,C M Florida Power & Light Co 83/04/06 Director's Office, Office of Inspection and Enforcement. 1p. 18310:078 24X Fiche 50-389,83/04/22,8305030231

--8305030244 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0120035 re pressurizer pressure & level & 2-0960030 re dc ground isolation
* Florida Power & Light Co 83/04/05 78pp 18310 079 24X
Fiche 50-389, 83/04/22, 8305030231

8305200489 Forwards safeguards info re devitalization of certain equipment Info withheld (ref 10CFR73 21)
UHRIG, R E Florida Power & Light Co 83/04/22. O'REILLY, J P.
Region 2, Office of Director 1p 18513 007 24X
Fiche 50-335, 83/04/22, 8305200489

8305160279 Releases public version of revised emergency plan implementing procedures
FELTON, J.M Division of Rules and Records 83/05/02 Document Management Branch 1p 18475.011 24X Fiche 50-389, 83/05/02, 8305160279

--8305160282 Forwards public version of Rev 1 to Emergency Plan Implementing Procedure 2-0030143, "Total Loss of AC Power" & Rev 1 to 2-0120037, "Reactor Coolant Gas Vent Sys Off-Normal Operation."
WETHY, C M Florida Power & Light Co 83/04/19 Director's Office, Office of Inspection and Enforcement 1p 18475 012 24X
Fiche 50-389, 83/05/02, 8305160279

--8305160284 Public version of Rev 1 to Emergency Plan Implementing Procedure 2-0030143, "Total Loss of AC Power" & Rev 1 to 2-0120037, "Reactor Coolant Gas Vent Sys Off-Normal Operation "
* Florida Power & Light Co 83/04/14 25pp 18475 013 24X
Fiche 50-389, 83/05/02, 8305160279.

8305170141 Summary of 830419-22 meetings w/util at site re physical security vital area analysis
NERSES, V Licensing Branch 3 83/05/03 Licensing Branch 3
6pp 18495.325 24X Fiche 50-335, 83/05/03, 8305170141

8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp. 18641 179 24X
Fiche 50-335, 83/05/06, 8305270287

--8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected, emergency preparedness in technical support ctr.
HUFFMAN, G. N Region 2, Office of Director. 83/05/03 4pp
18641 181 24X Fiche 50-335, 83/05/06, 8305270287

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D. G Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp 18540·095. 24X
Fiche·50-000, 83/05/11, 8305110034.

8305170356 Informs that changes to security plan, per 830405 & 06 ltrs & 830418-22 security meeting commitments, transmitted on 830511 Reevaluation of vital areas for safety-safeguards interface performed.
UHRIG, R E Florida Power & Light Co 83/05/11 EISENHUT, D G
Division of Licensing 1p 18466·104 24X Fiche 50-389, 83/05/11, 8305170356

8305200346 Forwards revised Chapters 5 & 6 to security plan Chapters withheld (ref 10CFR73 21)
UHRIG, R E Florida Power & Light Co 83/05/11 O'REILLY, J P
Region 2, Office of Director. 2pp 18516 251. 24X
Fiche 50-335, 83/05/11, 8305200346

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations, 83/05/13 PALLADINO, N J. Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

J Insurance & indemnity information

8305030016 Forwards License NPF-16 authorizing operation at 5% power, FR notice, Amends 8, 9 & 10 to Indemnity Agreement B-76 & assessment of license duration
EISENHUT, D G Division of Licensing 83/04/06 UHRIG, R. E Florida Power & Light Co. 5pp. 18310 290 24X Fiche 50-389, 83/04/06, 8305030016

8305030379 Forwards Endorsement 1 to NELIA Certificate N-89 & MAELU Certificate M-89
DUCK, J.R Marsh & McLennan, Inc. 83/04/25 SALTZMAN, J Assistant Director for State & Licensee Relations 16pp 18308 200. 24X
Fiche. 50-389, 83/04/25, 8305030379

8305040186 Forwards Endorsements 47 & 37 to NELIA Policy NF-227 & MAELU Policy MF-88, respectively
DUCK, J R Marsh & McLennan, Inc 83/04/29 BALTZMAN, J Assistant Director for State & Licensee Relations 1p 18621 191. 24X
Fiche 50-335, 83/04/29, 8305040186

8305100182 Forwards executed Amends 8, 9 & 10 to Indemnity Agreement B-76, adding Orlando Util Commission of City of Orlando, FL & Florida Municipal Power Agency & deleting Item 3 of attachment to indemnity agreement, respectively
UHRIG, R E Florida Power & Light Co 83/05/05 EISENHUT, D G.
Division of Licensing 4pp 18374 290 24X Fiche 50-335, 83/05/05, 8305100182

P Operating license stage documents & correspondence

8305030016 Forwards License NPF-16 authorizing operation at 5% power, FR notice, Amends 8, 9 & 10 to Indemnity Agreement B-76 & assessment of license duration
EISENHUT, D G Division of Licensing 83/04/06 UHRIG, R. E Florida Power & Light Co 5pp 18310·290 24X Fiche·50-389, 83/04/06, 8305030016

--8305030019 License NPF-16, authorizing operation at 5% power
DENTON, H R Office of Nuclear Reactor Regulation, Director
83/04/06 45pp 18310 295 24X Fiche 50-389, 83/04/06, 8305030016

--8305030022 Notice of issuance of License NPF-16
KNIGHTON, G W Licensing Branch 3 83/04/06 3pp. 18310·340
24X Fiche. 50-389, 83/04/06, 8305030016

8305060298 Forwards Amend 1 to License NPF-16, safety evaluation & notice of issuance & availability. Amend changes channel functional test surveillance requirements for wide-range logarithmic neutron flux monitor
KNIGHTON, G. W Licensing Branch 3 83/04/22 UHRIG, R E Florida Power & Light Co. 2pp 18353 068 24X Fiche 50-389, 83/04/22, 8305060298

--8305060303 Amend 1 to License NPF-16, changing channel functional test surveillance requirements for wide-range logarithmic neutron flux monitor
KNIGHTON, G W Licensing Branch 3 83/04/22. 7pp 18353.070.
24X Fiche 50-389, 83/04/22, 8305060298

--8305060308 Safety evaluation supporting Amend 1 to License NPF-16.
* Office of Nuclear Reactor Regulation, Director. 83/04/22. 1p
18353 077 24X Fiche·50-389, 83/04/22, 8305060298

--8305060312 Notice of issuance & availability of Amend 1 to License NPF-16
BUCKLEY, B. Licensing Branch 3. 83/04/22 3pp. 18353·078 24X
Fiche 50-389, 83/04/22, 8305060298.

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
EISENHUT, D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441.120 24X
Fiche 50-000, 83/05/02, 8305020455

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17.
EISENHUT, D G Division of Licensing. 83/05/04 PALLADINO, N. Commissioners 22pp 18337.139 24X Fiche·50-000, 83/05/04, 8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153. 24X
Fiche: 50-000, 83/05/09, 8305090659

8305130118 Advises that mods to purge sys not required. Sufficient margin exists to allow check valve to perform intended safety function Item closes out 5% of rated thermal power portion of License Condition 2 C 8
UHRIG, R E. Florida Power & Light Co 83/05/10 EISENHUT, D G
Division of Licensing 2pp. 18438.057. 24X Fiche·50-389, 83/05/10, 8305130118

8305270251 Forwards revised FSAR Table 7.3-9 indicating effects ESF actuation sys devices have on plant operation Table will be incorporated into Amend 14 to FSAR scheduled for 830808.
UHRIG, R E Florida Power & Light Co 83/05/14. EISENHUT, D. G
Division of Licensing. 3pp. 18637.149 24X Fiche·50-389, 83/05/14, 8305270251

8305250455 Confirms that GE AK-2 scram breakers used at San Onofre also in use at facility
UHRIG,R E Florida Power & Light Co 83/05/20 EISENHUT,D G
Division of Licensing 1p 18588 210 24X Fiche 50-389,83/05/20,
8305250455

8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppl 1 to NUREG-0737
UHRIG,R E Florida Power & Light Co 83/05/20 EISENHUT,D G
Division of Licensing 1p 18588 333 24X Fiche 50-000,83/05/20,
8305250472

--8305250491 "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan "
* Florida Power & Light Co 83/04/30 34pp 18588:334 24X
Fiche 50-000,83/05/20,8305250472

8305260381 Requests remittance of two Class III fees for review of 830422 application to amend License NPF-16,changing requirements for primary & secondary coolants & requirements for wide-range logarithmic neutron flux monitor
DIGGS,R M License Fee Management Branch 83/05/20 UHRIG,R F
Florida Power & Light Co. 1p 18647 249 24X Fiche 50-389,
83/05/20,8305260381

8305270104 Forwards summary of calculations performed to determine flood level inside containment,in response to NRC request for addl info re util 830510 ltr
UHRIG,R E Florida Power & Light Co 83/05/25 EISENHUT,D G
Division of Licensing 6pp 18638 244 24X Fiche 50-389,83/05/25,
8305270104.

8305270125 Forwards resolution of Item I C re remote shutdown demonstration prior to initial criticality,per Region II request Item closed Requests Region II be notified of concurrence following review
UHRIG,R E. Florida Power & Light Co. 83/05/25 EISENHUT,D G
Division of Licensing 3pp 18638:218 24X Fiche 50-389,83/05/25,
8305270125

8305270153 Forwards addl info re turbine trip circuitry at facility Turbine manual trip initiated in control room by depressing pushbutton PB/170 located on RTG board 201
UHRIG,R E Florida Power & Light Co 83/05/25 EISENHUT,D G
Division of Licensing. 3pp 18638.156 24X Fiche 50-389,83/05/25,
8305270153

8305310184 Forwards list of resolved license conditions for initial criticality Post-fuel load initial test program initiated, including criticality & low power testing described in Chapter 14 to FSAR
UHRIG,R E Florida Power & Light Co 83/05/26 EISENHUT,D.G.
Division of Licensing 6pp 18658 162 24X Fiche 50-389,83/05/26,
8305310184

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J.M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche:50-000,83/03/21,8212060385

8305270289 Forwards IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/29
UHRIG,R E Florida Power & Light Co 2pp 18638 352 24X
Fiche.50-389,83/03/29,8305270289

--8305270293 IE Insp Rept 50-389/83-17 on 830301-04 No noncompliance noted Major areas inspected:fire protection.
MILLER,W.H., CONLON,T.E Region 2, Office of Director 83/03/28
7pp. 18638.354 24X Fiche:50-389,83/03/29,8305270289.

8305270310 Forwards IE Insp Rept 50-389/83-18 on 830308-11 No noncompliance noted
DANCE,H.C. Division of Project & Resident Programs 83/03/30
UHRIG,R E. Florida Power & Light Co 2pp 18641:167 24X
Fiche:50-389,83/03/30,8305270310

--8305270315 IE Insp Rept 50-389/83-18 on 830308-11 No noncompliance noted Major areas inspected:seismic analysis for as-built safety-related piping sys.
ANG,W P.; BLAKE,J J Region 2, Office of Director. 83/03/29
4pp. 18641:169 24X Fiche 50-389,83/03/30,8305270310

8305270447 Forwards IE Insp Rept 50-389/83-19 on 830307-11 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/04
UHRIG,R E Florida Power & Light Co 2pp 18642 245 24X
Fiche 50-389,83/04/04,8305270447

--8305270453 IE Insp Rept 50-389/83-19 on 830307-11 No noncompliance noted Major areas inspected plant & maint procedure review, evaluation of integrated hot functional test results & reactor protection sys test results evaluation
TAYLOR,P A Region 2, Office of Director JAPE,F Division of Engineering & Radiological Safety Programs 83/03/30 6pp
18642 247 24X Fiche 50-389,83/04/04,8305270447

8305270561 Forwards IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/06
UHRIG,R E Florida Power & Light Co 2pp 18645 321 24X
Fiche:50-335,83/04/06,8305270561

--8305270576 IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted Major areas inspected Unit 1 plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items
WRAY,J R ; BARR,K P Region 2, Office of Director 83/04/05
8pp 18645 323 24X Fiche 50-335,83/04/06,8305270561

8305270559 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-02 & 50-389/83-09
LEWIS,R C Division of Project & Resident Programs 83/04/14
UHRIG,R E Florida Power & Light Co 1p 18647 127 24X
Fiche 50-335,83/04/14,8305270559.

--8305270579 Forwards IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 & notice of violation
LEWIS,R C Division of Project & Resident Programs 83/03/01.
UHRIG,R E Florida Power & Light Co 2pp 18647 133 24X
Fiche 50-335,83/04/14,8305270559

--8305270594 IE Insp Repts 50-335/83-02 & 50-389/83-09 on 830124-28 Noncompliance noted failure to follow procedures required by training programs & failure of licensed operators to be cognizant of facility design,procedures & license changes
BELISLE,G A ; BKINNER,P H ; UPRIGHT,C M Region 2, Office of Director 83/02/24 9pp 18647 137 24X Fiche 50-335,83/04/14,
8305270559

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche:50-000,83/04/15,8303040021

8305270240 Forwards IE Insp Rept 50-389/83-24 on 830321-24 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/15
UHRIG,R E Florida Power & Light Co 2pp 18637 162 24X
Fiche.50-389,83/04/15,8305270240

--8305270245 IE Insp Rept 50-389/83-24 on 830321-24 No noncompliance noted Major areas inspected test results for integrated ESF test,RCS leakage monitoring test & plant tour
TAYLOR,P A Region 2, Office of Director JAPE,F Division of Project & Resident Programs 83/04/15 3pp 18637 164 24X
Fiche 50-389,83/04/15,8305270240

8305270098 Forwards IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/19
UHRIG,R E Florida Power & Light Co 2pp 18662 125 24X
Fiche 50-389,83/04/19,8305270098

--8305270101 IE Insp Rept 50-389/83-30 on 830329-0402 No noncompliance noted Major areas inspected,cable fire stops,radiation monitors,relay coordination study,IE bulletins & QA audits
HUNT,M D Region 2, Office of Director CONLON,T.E. Division of Engineering & Radiological Safety Programs 83/04/15 5pp
18662 127 24X Fiche.50-389,83/04/19,8305270098

8305270349 Ack receipt of 830330 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/83-06
LEWIS,R C. Division of Project & Resident Programs 83/04/19
UHRIG,R E Florida Power & Light Co 1p 18642 113 24X
Fiche.50-389,83/04/19,8305270349

--8305270360 Responds to NRC 830301 ltr re violations noted in IE Insp Rept 50-389/83-06 Corrective actions bolting repts from inception of const completion group to 830218 being reviewed & civil const activity QA insps reviewed
UHRIG,R E. Florida Power & Light Co 83/03/30 O'REILLY,J.P
Region 2, Office of Director. 4pp 18642:114 24X
Fiche:50-389,83/04/19,8305270349

--8305270365 Forwards IE Insp Rept 50-389/83-06 on 830110-27 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/01
UHRIG, R E Florida Power & Light Co 3pp 18642 118 24X
Fiche 50-389, 83/04/19, 8305270349

--8305270371 Notice of violation from insp on 830110-27
* Region 2, Office of Director 83/03/01 2pp. 18642 120 24X
Fiche 50-389, 83/04/19, 8305270349

--8305270379 IE Insp Rept 50-389/83-06 on 830110-27 Noncompliance noted inadequate procedure for accomplishing final civil structural turnover & failure to follow procedures for insp of structural steel.
LENAHAN, J J , CONLON, T E Region 2, Office of Director 83/02/18
6pp 18642 122 24X Fiche 50-389, 83/04/19, 8305270349

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp. 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305270359 Forwards IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/26
UHRIG, R E Florida Power & Light Co 2pp 18642 128 24X
Fiche 50-335, 83/04/26, 8305270359

--8305270367 IE Insp Repts 50-335/83-07 & 50-389/83-21 on 830314-18 No noncompliance noted Major areas inspected local leak rate testing, snubber testing & review of Unit 1 procedures re refueling operations
WHITENER, H L , MATHIS, J , JAPE, F Region 2, Office of Director 83/04/21 6pp 18642 130 24X Fiche 50-335, 83/04/26, 8305270359

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305270507 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-389/83-13
LEWIS, R C Division of Project & Resident Programs 83/05/02.
UHRIG, R E Florida Power & Light Co 1p 18645 256 24X
Fiche 50-389, 83/05/02, 8305270507

--8305270520 Responds to violations noted in IE Insp Rept 50-389/83-13 Corrective actions QC inspector given verbal & written reprimand & need for strict compliance discussed at weekly electrical inspectors meeting
UHRIG, R E Florida Power & Light Co 83/04/08 O'REILLY, J P
Region 2, Office of Director 2pp 18645 257 24X
Fiche 50-389, 83/05/02, 8305270507

--8305270529 Forwards IE Insp Rept 50-389/83-13 on 830201-04 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/08
UHRIG, R E Florida Power & Light Co 2pp 18645 259 24X
Fiche 50-389, 83/05/02, 8305270507

--8305270535 Notice of violation from insp on 830201-04
* Region 2, Office of Director 83/03/08 1p 18645 261 24X
Fiche 50-389, 83/05/02, 8305270507

--8305270542 IE Insp Rept 50-389/83-13 on 830201-04 Noncompliance noted failure to follow procedures for insp of safety-related cables
MERRIWEATHER, N , GIBBONS, T D Region 2, Office of Director
CONLON, T E Division of Project & Resident Programs 83/03/03
-- 18645 262 24X Fiche 50-389, 83/05/02, 8305270507

E Info Notice 83-26, "Failure of Safety/Relief Valve
.ine Vacuum Breakers " Svc list encl
Division of Emergency Preparedness & Engineering
'ost 830103). 83/05/03 Consolidated Edison Co. of New
122pp 18441.170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305270176 Forwards IE Insp Rept 50-389/83-28 on 830405-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs. 83/05/05
UHRIG, R E Florida Power & Light Co 2pp 18638 024 24X
Fiche 50-389, 83/05/05, 8305270176

--8305270179 IE Insp Rept 50-389/83-28 on 830405-08 No noncompliance noted Major areas inspected nonconformance control sys & review of as-built drawings
COLEY, J L , WRIGHT, R W , HERDT, A R Region 2, Office of Director, 83/05/02 5pp 18638 026 24X Fiche 50-389, 83/05/05, 8305270176

8305270232 Forwards IE Insp Rept 50-389/83-31 on 830309-10 & 0402 & 07 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/05
UHRIG, R E Florida Power & Light Co 2pp 18637, 200 24X
Fiche 50-389, 83/05/05, 8305270232

--8305270236 IE Insp Rept 50-389/83-31 on 830309-10 & 0402 & 07. No noncompliance noted Major areas inspected civil turnover program, piping analysis & cable tray bolting requirements
LENAHAN, J J , CONLON, T E. Region 2, Office of Director 83/05/02.
4pp 18637 202 24X Fiche 50-389, 83/05/05, 8305270232.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305270287 Forwards IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp 18641 179 24X
Fiche 50-335, 83/05/06, 8305270287

--8305270297 IE Insp Repts 50-335/83-11 & 50-389/83-27 on 830407-09 No noncompliance noted Major areas inspected emergency preparedness in technical support ctr
HUFFMAN, G N Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/05/03. 4pp.
18641 181 24X Fiche 50-335, 83/05/06, 8305270287

8305270329 Forwards IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp 18641 131. 24X
Fiche 50-335, 83/05/06, 8305270329

--8305270339 IE Insp Repts 50-335/83-13 & 50-389/83-33 on 830412-15 No noncompliance noted Major areas inspected inservice insp (Unit 1), core barrel/thermal shield damage (Unit 1), welding & NDE (Unit 1) & preservice insp (Unit 2)
CROWLEY, B R , BLAKE, J J Region 2, Office of Director 83/05/02
9pp 18641 133 24X Fiche 50-335, 83/05/06, 8305270329

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche. 50-000, 83/05/26, 8303040046

DOCKETED ITEMS

R Periodic operating reports & related correspondence

8305030341 Forwards Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept,1982 "
UHRIG,R E Florida Power & Light Co 83/04/28 MULLER,D R NRC - No Detailed Affiliation Given 1p 18307 001 24X
Fiche 50-335,83/04/28,8305030341

--8305030347 Vols 1 & 2 to "Annual Nonradiological Aquatic Monitoring Rept,1982 "
* Applied Biology, Inc AB-442 83/03/31 406pp 18307 004
24X Fiche 50-335,83/04/28,8305030341

S Reportable occurrences, LERs & related correspondence

8305030306 Final Deficiency Rept 83-009 re condensate storage tank damage Initially reported on 830322 Caused by condensation of steam creating local vacuum conditions Double butt welded plates installed,cracks sealed & designs improved
UHRIG,R E Florida Power & Light Co 83/04/21 O'REILLY,J P
Region 2, Office of Director 4pp 18296 194 24X
Fiche 50-389,83/04/21,8305030306.

8305030604 Interim deficiency rept re Westinghouse gate valve premature indication of valve closure Initially reported on 830223.Util evaluating condition & will submit final rept by 830304
UHRIG,R E Florida Power & Light Co 83/04/25 O'REILLY,J P
Region 2, Office of Director 1p 18303 342 24X
Fiche 50-389,83/04/25,8305030604

8305100088 Interim deficiency rept re failure of two safety-related Agastat relays to time out properly & installation of incorrect Agastat relay on diesel generator Initially reported on 830330 Investigation ongoing
UHRIG,R E Florida Power & Light Co 83/04/29 O'REILLY,J P
Region 2, Office of Director 2pp 18377 223 24X
Fiche 50-389,83/04/29,8305100088

8305100227 Final deficiency rept re loss of continuity on mineral insulated cable assemblies Initially reported on 830330 Twenty-three cable assemblies w/defective connectors repaired Deficiencies not reportable per 10CFR50 55(e)
UHRIG,R E Florida Power & Light Co 83/04/29 O'REILLY,J P
Region 2, Office of Director 2pp 18373 286 24X
Fiche 50-389,83/04/29,8305100227

8305100269 Forwards LER 83-001/01T-0
WILLIAMS,J W. Florida Power & Light Co 83/05/02 O'REILLY,J P
Region 2, Office of Director 1p 18371 331 24X
Fiche 50-389,83/05/02,8305100269

--8305100278 LER 83-001/01T-0 on 830416,during fuel movement,both emergency generators discovered out-of-svc Caused by personnel error in establishing out of svc log Logs reviewed & periodic surveillance procedure revised
WALLING,G E. Florida Power Corp 83/05/02 Region 2, Office of Director 3pp. 18371 332 24X Fiche 50-389,83/05/02,8305100269

8305170191 Forwards LER 83-003/03L-0
WILLIAMS,J W. Florida Power & Light Co 83/05/09 O'REILLY,J P
Region 2, Office of Director 1p 18466 326 24X
Fiche 50-389,83/05/09,8305170191

--8305170197 LER 83-003/03L-0 on 830412,following initial core load,low pressure safety injection pump A tripped off Condition resulted in loss of operation of shutdown cooling loop A Caused by personnel error Technician reinstructed
VALDES,S A Florida Power & Light Co 83/05/09. Region 2, Office of Director 1p 18466 327 24X Fiche.50-389,83/05/09, 8305170191

8305170310 RO 389-83-005 on 830507,safety injection tank isolation valves closed w/plant in Mode 4 above 276 psia Caused by personnel error.Procedural step overlooked during plant heatup Valves immediately opened
WETHY,C.M Florida Power & Light Co 83/05/09. O'REILLY,J P
Region 2, Office of Director 1p 18463 187 24X
Fiche:50-389,83/05/09,8305170310

8305200181 Final deficiency rept re premature indication of valve closure of Westinghouse gate valves Initially reported on 830223.Configuration represents normal design condition Condition not reportable per 10CFR50 55(e)
UHRIG,R.E Florida Power & Light Co. 83/05/11 O'REILLY,J P
Region 2, Office of Director 3pp 18519 064 24X
Fiche:50-389,83/05/11,8305200181

8305200430 PNO-II-83-040 on 830515,two util employees & one former employee arrested for cocaine & marijuana possession Arrest occurred offsite Employees not involved in licensed operator activities
LANDIS,K D , DANCE,H C Region 2, Office of Director 83/05/17
1p 18517 150 24X Fiche 50-335,83/05/17,8305200430

8305250416 Clarifies 830418 final deficiency rept re diesel generator start relay defect Addl indication provided to indicate to control room when master control switch,located in diesel generator bldg,is in stop position
UHRIG,R E Florida Power & Light Co 83/05/19 O'REILLY,J P
Region 2, Office of Director 1p 18583 359 24X
Fiche 50-389,83/05/19,8305250416

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305030121 Forwards three oversize flow diagrams illustrating mods to chemical feed lines,in response to NRC request
MILLS,L M Tennessee Valley Authority 83/04/22 ADENSAM,E
Licensing Branch 4 2pp 18298 138 24X Fiche 50-390,83/04/22, 8305030121

8305030606 Forwards response to Generic Ltr 83-10C re program for resolution of NUREG-0737,Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Pump trip can be achieved safely & reliably by operator,when required
MILLS,L M Tennessee Valley Authority 83/04/22 ADENSAM,E
Licensing Branch 4 8pp 18303 172 24X Fiche 50-390,83/04/22, 8305030606

8305030041 Forwards responses to 821201 request for addl info re Items 1 b,1 g,5 a & 5 c of Branch Technical Position CSB 6-4.Info includes opening supply & exhaust lines & seismic design category of debris screens
MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM,E
Licensing Branch 4 4pp 18300 352 24X Fiche 50-390,83/04/26, 8305030041

8305030434 Forwards comments on LLL preliminary sys interaction results from diagram matrix analysis of safety injection sys Terminology used in rept not common to industry & should be defined at first ref
MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM,E
Licensing Branch 4 3pp 18292 151 24X Fiche 50-390,83/04/26, 8305030434

8305040253 Informs that consequences of unmitigated boron dilution event meets acceptance criteria for postulated accidents. Control room contains adequate audible & discrete info to determine boron dilution event
MILLS,L M Tennessee Valley Authority 83/04/29 ADENSAM,E
Licensing Branch 4 2pp 18323 247 24X Fiche 50-390,83/04/29, 8305040253

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305200325 Forwards evaluation results re potential for liquefaction of soils beneath essential raw cooling water pipelines Site-specific ground motion & modified seed & Idriss (1981) procedure discussed Proposed 830520 meeting agenda encl
MILLS,L M Tennessee Valley Authority 83/05/17 ADENSAM,E
Licensing Branch 4 3pp 18517 043 24X Fiche 50-390,83/05/17, 8305200325

8305240660 Notification of 830519 meeting w/util in Silver Spring,MD to discuss proposed application of watch tower power block concept
KENYON,T J Licensing Branch 4 83/05/17 ADENSAM,E G Licensing Branch 4 4pp. 18593 174 24X Fiche 50-390,83/05/17,8305240660

8305230624 Recommends meeting,within 30 days receipt of ltr,to discuss util plans for completing environ qualification program
NOVAK,T M. Assistant Director for Licensing 83/05/18 PARRIS,H G Tennessee Valley Authority 3pp 18543 035 24X
Fiche 50-390,83/05/18,8305230624

8305250425 Responds to 830401 ltr re environ qualification of safety-related mechanical equipment located in harsh environ areas.Schedule proposed by NRC for list of mechanical equipment 1 month prior to site audit,cannot be supported
MILLS,L M Tennessee Valley Authority 83/05/19 ADENSAM,E
Licensing Branch 4 3pp 18585 265 24X Fiche 50-390,83/05/19, 8305250425

DOCKETED ITEMS

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305030543 Forwards list of safety-related electrical components, respective functions & summary of data used to establish setpoints for balance-of-plant equipment, per SER Section 7 1 3 1 Info completes action per SER Confirmatory Item 21
KAMMER, D S Tennessee Valley Authority 83/04/25 ADENSAM, E
Operating Reactors Branch 4 326pp 18302 001 24X
Fiche: 50-390, 83/04/25, 8305030543

8305130020 Forwards addl justification required by SER (NUREG-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities
MILLS, L M Tennessee Valley Authority 83/05/10 ADENSAM, E
Licensing Branch 4 4pp 18437.129 24X Fiche 50-390, 83/05/10, 8305130020

8305310039 Forwards info re schedule for steam generator mods, per SER (NUREG-0847) design changes.
MILLS, L M Tennessee Valley Authority 83/05/27 ADENSAM, E
Licensing Branch 4 2pp 18653 307 24X Fiche 50-390, 83/05/27, 8305310039

F Security, medical, emergency & fire protection plans

8305090409 Forwards IE Safeguards Insp Rept 50-390/83-12 on 830418-22 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/05/06
PARRIS, H G Tennessee Valley Authority 2pp 18363 062 24X
Fiche 50-390, 83/05/06, 8305090409

--8305090418 IE Safeguards Insp Rept 50-390/83-12 on 830418-22 No noncompliance noted. Major areas inspected. security plan requirements re barrier between facilities & proposed watchtowers Details withheld (ref 10CFR73 21)
MOORE, D E. Region 2, Office of Director. MCGUIRE, D R Division of Emergency Preparedness & Materials Safety. 83/05/06 1p 18363 064. 24X Fiche 50-390, 83/05/06, 8305090409.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G. Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W. J Office of the Executive Director for Operations
83/05/13. PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI, D M Division of Project & Resident Programs. 83/05/19
PARRIS, H G Tennessee Valley Authority 1p 18637 193 24X
Fiche: 50-390, 83/05/19, 8305270228

--8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance
KAMMER, D S. Tennessee Valley Authority. 83/05/09 O'REILLY, J. P
Region 2, Office of Director 2pp 18637 196 24X
Fiche 50-390, 83/05/19, 8305270228

8305310187 Forwards physical security plan Plan withheld (ref 10CFR73 21) Revs requested within 40 days of ltr receipt
ADENSAM, E G Licensing Branch 4 83/05/24 PARRIS, H G Tennessee Valley Authority. 2pp. 18651·002. 24X Fiche·50-390, 83/05/24, 8305310187

O. Advisory Committee on Reactor Safeguards reports & correspondence

8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/05
ACRS - Advisory Committee on Reactor Safeguards. 529pp. 18458, 225
24X Fiche·50-000, 83/05/05, 8305130290

Q Inspection reports, IE Bulletins & correspondence

8305270133 Suppls 830117 response to notice of violation contained in IE Insp Repts 50-390/82-35 & 50-391/82-32 Corrective actions any necessary revs to operating div instructions will be made as appropriate
MILLS, L M Tennessee Valley Authority 83/03/18 O'REILLY, J P
Region 2, Office of Director 2pp 18638 208 24X
Fiche 50-390, 83/03/18, 8305270133

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270290 Forwards IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/23
PARRIS, H G Tennessee Valley Authority 2pp 18645 344 24X
Fiche 50-390, 83/03/23, 8305270290

--8305270303 IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted Major areas inspected followup on licensee identified items, licensee action on previous enforcement matters & independent insp effort
HEATHERLY, T L , SWAN, W Region 2, Office of Director. QUICK, D
Division of Project & Resident Programs 83/03/22 9pp
18645 346 24X Fiche 50-390, 83/03/23, 8305270290

8305270651 Forwards IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs. 83/04/11
PARRIS, H G Tennessee Valley Authority 2pp 18646:344 24X
Fiche 50-390, 83/04/11, 8305270651

--8305270659 IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent insp efforts, preservice insp & safety-related structures
COLEY, J L. , BLAKE, J J Region 2, Office of Director 83/04/06
12pp 18646·346 24X Fiche 50-390, 83/04/11, 8305270651

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270540 Forwards IE Insp Rept 50-390/83-09 on 830329-0401 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/15
PARRIS, H G Tennessee Valley Authority 2pp 18646 332 24X
Fiche 50-390, 83/04/15, 8305270540

--8305270562 IE Insp Rept 50-390/83-09 on 830329-0401 No noncompliance noted Major areas inspected. preoperational test procedure review, preoperational test witnessing & followup on previous enforcement matter
THOMAS, M , MATHIS, J L , JAPE, F Region 2, Office of Director
83/04/14 4pp 18646 334 24X Fiche 50-390, 83/04/15, 8305270540

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc. 115pp. 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28. Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche·50-000, 83/04/28, 8303040027

8305270557 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI, D M Division of Project & Resident Programs 83/05/02
PARRIS, H G Tennessee Valley Authority 1p 18646 116 24X
Fiche 50-390, 83/05/02, 8305270557

--8305270567 Second supplemental response to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions drawings will be revised to reflect mark numbers of as-installed dampers by 830430
MILLS, L M Tennessee Valley Authority 83/04/11 O'REILLY, J P
Region 2, Office of Director 1p 18646 117 24X
Fiche 50-390, 83/05/02, 8305270557

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305090409 Forwards IE Safeguards Insp Rept 50-390/83-12 on 830418-22 No noncompliance noted
VERRELLI, D Division of Project & Resident Programs 83/05/06
PARRIS, H G Tennessee Valley Authority 2pp 18363 062 24X
Fiche. 50-390, 83/05/06, 8305090409

--8305090418 IE Safeguards Insp Rept 50-390/83-12 on 830418-22 No noncompliance noted. Major areas inspected security plan requirements re barrier between facilities & proposed watchtowers Details withheld (ref 10CFR73 21)
MOORE, D E Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 83/05/06 1p
18363. 064 24X Fiche. 50-390, 83/05/06, 8305090409.

8305270413 Forwards IE Insp Repts 50-390/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted.
VERRELLI, D M Division of Project & Resident Programs 83/05/09.
PARRIS, H G. Tennessee Valley Authority. 2pp. 18642. 299 24X
Fiche 50-390, 83/05/09, 8305270413

--8305270420 IE Insp Repts 50-390/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, licensee identified items, inspector followup items & independent insp effort
GIBBONS, T. D., CONLON, T. E. Region 2, Office of Director 83/05/06.
4pp 18642. 301 24X Fiche. 50-390, 83/05/09, 8305270413

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/11 Consolidated Edison Co of New York, Inc. 114pp. 18524. 003 24X Fiche. 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009. 24X Fiche: 50-000, 83/05/19, 8303040040.

8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI, D. M. Division of Project & Resident Programs. 83/05/19.
PARRIS, H G. Tennessee Valley Authority 1p 18637. 195. 24X
Fiche: 50-390, 83/05/19, 8305270228.

--8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20. Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance
KAMMER, D. B Tennessee Valley Authority 83/05/09 O'REILLY, J. P
Region 2, Office of Director 2pp 18637. 196. 24X
Fiche. 50-390, 83/05/19, 8305270228

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000, 83/04/21, 8305110427

8305030072 First interim deficiency rept re loose matl in steam generator Initially reported on 830325 All loose items & matl determined detrimental removed from generators Next rept expected by 830808
MILLS, L M Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 2pp 18300 349 24X
Fiche 50-390, 83/04/25, 8305030072

8305030082 Second interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 QA documents being prepared to substantiate insulation data Next rept expected by 830921
MILLS, L M Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 2pp 18397 239 24X
Fiche 50-390, 83/04/25, 8305030082

8305030578 First interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830329 Program being modified to automatically calculate direction cosines Next rept to be submitted by 830923
MILLS, L M Tennessee Valley Authority 83/04/26 O'REILLY, J P
Region 2, Office of Director 2pp 18303 309 24X
Fiche 50-390, 83/04/26, 8305030578

8305050067 Ninth interim deficiency rept re seismic qualification for chillers/coolers & deficient piping of HVAC sys & improper classification of ERCW sys piping & components Initially reported on 810324 & 0507, respectively Next rept due 830829
MILLS, L M Tennessee Valley Authority 83/04/27 O'REILLY, J P
Region 2, Office of Director 4pp 18342 062 24X
Fiche 50-390, 83/04/27, 8305050067

8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
MILLS, L M Tennessee Valley Authority 83/04/27 O'REILLY, J P.
Region 2, Office of Director 3pp 18341 083 24X
Fiche 50-000, 83/04/27, 8305050152

8305050232 Second combined interim deficiency rept re alternate analysis piping program Significant breakdown of program requires reverification of alternate analysis Full review program underway Next rept expected by 830930
MILLS, L. M Tennessee Valley Authority 83/04/27 O'REILLY, J P
Region 2, Office of Director 5pp 18337 329 24X
Fiche 50-390, 83/04/27, 8305050232

8305050078 First interim deficiency rept re spacing & clearance in high pressure fire protection sprinkler sys in auxiliary bldg Initially reported on 830331 Evaluation in progress Next rept will be sent by 830624
MILLS, L. M Tennessee Valley Authority 83/04/28 O'REILLY, J. P
Region 2, Office of Director 2pp 18342. 150 24X
Fiche: 50-390, 83/04/28, 8305050078

8305050188 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per QA program Initially reported on 830329 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706
MILLS, L M Tennessee Valley Authority 83/04/28 O'REILLY, J P
Region 2, Office of Director 2pp 18341 076 24X
Fiche. 50-000, 83/04/28, 8305050188

8305050243 Third interim deficiency rept re high point venting in ERCW sys Initially reported on 820930 Performance evaluation ongoing. Next rept will be submitted by 830729
MILLS, L M Tennessee Valley Authority 83/04/28 O'REILLY, J P
Region 2, Office of Director 1p 18338 056 24X
Fiche. 50-390, 83/04/28, 8305050243

8305050047 Fourth interim deficiency rept re questionable patches of plastic cement mortar. Initially reported on 820429 Three of 50 supports determined to be in violation of Const Spec G-32. Next rept will be submitted by 830805
MILLS, L M Tennessee Valley Authority 83/04/29 O'REILLY, J P
Region 2, Office of Director 1p 18338 330 24X
Fiche: 50-390, 83/04/29, 8305050047.

8305110317 Seventh interim deficiency rept re lack of documentation for rock supported structures for 1-inch differential settlement. Initially reported on 810707 Design criteria being prepared Next rept by 830922
MILLS,L M, Tennessee Valley Authority 83/05/04 O'REILLY,J P
Region 2, Office of Director 3pp 18393 183 24X
Fiche 50-390,83/05/04,8305110317

8305110319 First interim rept re Deficiencies 1,2 & 3 QA program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc Written instructions & procedures not provided to contractor in performing/documenting piping analysis Review underway
MILLS,L M Tennessee Valley Authority 83/05/05 O'REILLY,J P
Region 2, Office of Director 3pp 18393 181 24X
Fiche 50-000,83/05/05,8305110319

8305130133 Supplemental info to final deficiency rept re insufficient documentation for protective devices Initially reported on 810313 Completion date for corrective actions delayed until 830531 One field change request remains
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18437 279 24X
Fiche 50-390,83/05/06,8305130133

8305130217 Addl info to final deficiency rept re nonconservative calculation method for general Const Spec G-32 Initially reported on 820528 Rev to Design Std DS-C6 1 will be issued by 830630
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J.P
Region 2, Office of Director 1p 18440 089 24X
Fiche 50-390,83/05/06,8305130217

8305170288 Second interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 Scope of investigation expanded to include generic implications Next rept expected by 830922
MILLS,L M Tennessee Valley Authority 83/05/09 O'REILLY,J P
Region 2, Office of Director 2pp 18465 071 24X
Fiche 50-390,83/05/09,8305170288

8305170299 Final deficiency rept re lack of support for reactor bldg annulus floor drain sump Initially reported on 821207 Pipes analyzed & appropriate seismic supports designed under Engineering Change Notice ECN 3234
MILLS,L M Tennessee Valley Authority 83/05/09 O'REILLY,J P.
Region 2, Office of Director 2pp. 18465 066 24X
Fiche 50-390,83/05/09,8305170299

8305200274 Revised final deficiency rept re unqualified control equipment Initially reported on 800922 Control equipment seismic qualification test requirements will be reviewed
MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P.
Region 2, Office of Director 2pp 18518 094 24X
Fiche.50-390,83/05/11,8305200274

8305200275 Eighth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 New Engineering Procedure SWP-EP 43 22 written Drawings containing reviewed & updated quality issued.
MILLS,L.M Tennessee Valley Authority 83/05/11 O'REILLY,J P.
Region 2, Office of Director 1p 18516 318 24X
Fiche 50-390,83/05/11,8305200275

8305200343 Suppl to final deficiency repts re Class IE electrical components for ERCW traveling screens Initially reported on 810518 Qualified motor search continues Corrections to be completed by 831001
MILLS,L M Tennessee Valley Authority. 83/05/11 O'REILLY,J P.
Region 2, Office of Director 1p 18516 232 24X
Fiche-50-390,83/05/11,8305200343

8305230575 Final deficiency rept re missing seismic design documentation for auxiliary bldg platform. Initially reported on 820426 Required drawing revs completed. Field mods will be completed by 830801 & 840214 for Units 1 & 2, respectively
MILLS,L M Tennessee Valley Authority 83/05/13 O'REILLY,J P.
Region 2, Office of Director 2pp 18537 309 24X
Fiche:50-390,83/05/13,8305230575.

8305200387 Second revised final deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Previous decision re nonapplicability of 10CFR50 55(e) sustained
MILLS,L M Tennessee Valley Authority 83/05/16 O'REILLY,J P.
Region 2, Office of Director. 2pp 18519,086. 24X
Fiche.50-390,83/05/16,8305200387

8305230482 Third interim deficiency rept re incorrect supports in analysis of 3-inch chemical vol & control sys line Initially reported on 830505 Addl problems identified Field mods required. Next rept will be submitted by 830922
MILLS,L.M Tennessee Valley Authority 83/05/17 O'REILLY,J.P
Region 2, Office of Director 2pp 18537 149 24X
Fiche-50-390,83/05/17,8305230482

8305230433 Final deficiency rept re inadequate freeze protection Initially reported on 810413 Piping to ERCW pump motor cooler redesigned to be self-draining
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J P
Region 2, Office of Director 2pp 18538 212 24X
Fiche 50-390,83/05/18,8305230433

8305230447 Second interim deficiency rept re auxiliary instrument room fire door failure Initially reported on 821229 Lower flush bolt not engaged in strike plate at floor Acceptance criteria established for max room pressures
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J P.
Region 2, Office of Director 2pp 18538 194 24X
Fiche 50-390,83/05/18,8305230447

8305230569 Fifth interim deficiency rept re excessive movement of containment penetration bellows Initially reported on 811204 Analysis Problems N3-63-7A & N3-74-1A reanalyzed Support mods required Next rept due by 830930
MILLS,L.M Tennessee Valley Authority 83/05/18. O'REILLY,J.P
Region 2, Office of Director 1p 18536 318 24X
Fiche 50-390,83/05/18,8305230569

8305250421 First interim deficiency rept re qualification of nozzle loads in reactor coolant loop Initially reported on 830421. Review of analysis problems in progress. Next rept by 830921.
MILLS,L M Tennessee Valley Authority 83/05/19 O'REILLY,J P.
Region 2, Office of Director 2pp 18585 263 24X
Fiche 50-390,83/05/19,8305250421.

8305250435 Final rept re deficiencies in Ameron cement mortar lining. Initially reported on 820521 Corrections to each deviation listed Also reportable per 10CFR21.
MILLS,L.M Tennessee Valley Authority 83/05/20 O'REILLY,J P
Region 2, Office of Director 4pp 18585 293 24X
Fiche-50-390,83/05/20,8305250435

8305310172 Second interim deficiency rept re failure of curtain-type fire dampers to close Initially reported on 821025 Engineering change notice issued to add negator closure springs & positive latches
MILLS,L M Tennessee Valley Authority. 83/05/23 O'REILLY,J.P
Region 3, Office of Director 1p. 18658-149 24X
Fiche 50-390,83/05/23,8305310172

DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondance

8305030121 Forwards three oversize flow diagrams illustrating mods to chemical feed lines,in response to NRC request.
MILLS,L M Tennessee Valley Authority 83/04/22. ADENSAM,E
Licensing Branch 4 2pp. 18298-138 24X Fiche-50-390,83/04/22,
8305030121.

8305030606 Forwards response to Generic Ltr 83-10C re program for resolution of NUREG-0737,Item II K 3.5, "Automatic Trip of Reactor Coolant Pumps." Pump trip can be achieved safely & reliably by operator,when required.
MILLS,L M Tennessee Valley Authority 83/04/22 ADENSAM,E.
Licensing Branch 4. 8pp 18303:172 24X Fiche.50-390,83/04/22,
8305030606

8305030041 Forwards responses to 821201 request for addl info re Items 1.b.1 g.5 a & 5 c of Branch Technical Position CSB 6-4 Info includes opening supply & exhaust lines & seismic design category of debris screens
MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM,E.
Licensing Branch 4. 4pp 18300.352. 24X Fiche.50-390,83/04/26,
8305030041

8305030434 Forwards comments on LLL preliminary sys interaction results from diagram matrix analysis of safety injection sys. Terminology used in rept not common to industry & should be defined at first ref
MILLS,L M Tennessee Valley Authority. 83/04/26. ADENSAM,E.
Licensing Branch 4 3pp 18292:151 24X Fiche:50-390,83/04/26,
8305030434

8305040253 Informs that consequences of unmitigated boron dilution event meets acceptance criteria for postulated accidents. Control room contains adequate audible & discrete info to determine boron dilution event
MILLS,L M. Tennessee Valley Authority 83/04/29. ADENSAM,E
Licensing Branch 4. 2pp 18323 247. 24X Fiche.50-390,83/04/29,
8305040253

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D.G Division of Licensing. 83/05/09 Consolidated Edison Co. of New York, Inc. 16pp. 18627 153. 24X
Fiche-50-000,83/05/09,8305090659

8305200325 Forwards evaluation results re potential for liquefaction of soils beneath essential raw cooling water pipelines Site-specific ground motion & modified seed & Idriss (1981) procedure discussed Proposed 830520 meeting agenda encl
MILLS, L M Tennessee Valley Authority 83/05/17 ADENSAM, E Licensing Branch 4 3pp 18517 043 24X Fiche 50-390, 83/05/17, 8305200325

8305240660 Notification of 830519 meeting w/util in Silver Spring, MD to discuss proposed application of watch tower power block concept
KENYON, T J Licensing Branch 4 83/05/17 ADENSAM, E G Licensing Branch 4 4pp 18593 174 24X Fiche 50-390, 83/05/17, 8305240660

8305230624 Recommends meeting, within 30 days receipt of ltr, to discuss util plans for completing environ qualification program
NOVAK, T M 'Assistant Director for Licensing 83/05/18 PARRIS, H G Tennessee Valley Authority 3pp 18543:035 24X
Fiche 50-390, 83/05/18, 8305230624

8305250425 Responds to 830401 ltr re environ qualification of safety-related mechanical equipment located in harsh environ areas. Schedule proposed by NRC for list of mechanical equipment 1 month prior to site audit, cannot be supported
MILLS, L M Tennessee Valley Authority 83/05/19 ADENSAM, E Licensing Branch 4. 3pp 18585 265 24X Fiche 50-390, 83/05/19, 8305250425

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8305030543 Forwards list of safety-related electrical components, respective functions & summary of data used to establish setpoints for balance-of-plant equipment, per SER Section 7 1.3 1. Info completes action per SER Confirmatory Item 21
KAMMER, D S Tennessee Valley Authority 83/04/25 ADENSAM, E Operating Reactors Branch 4 326pp 18302 001 24X
Fiche 50-390, 83/04/25, 8305030543

8305130020 Forwards addl justification required by SER (NUREG-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities
MILLS, L M Tennessee Valley Authority 83/05/10 ADENSAM, E Licensing Branch 4 4pp 18437 129 24X Fiche 50-390, 83/05/10, 8305130020

8305310039 Forwards info re schedule for steam generator mods, per SER (NUREG-0847) design changes
MILLS, L.M Tennessee Valley Authority 83/05/27 ADENSAM, E Licensing Branch 4 2pp 18653 307 24X Fiche 50-390, 83/05/27, 8305310039.

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D. G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI, D M Division of Project & Resident Programs 83/05/19
PARRIS, H G Tennessee Valley Authority 1p. 18637·195. 24X
Fiche 50-390, 83/05/19, 8305270228

--8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adequate. Two dampers not in compliance
KAMMER, D S Tennessee Valley Authority 83/05/09 O'REILLY, J. P. Region 2, Office of Director 2pp. 18637·196 24X
Fiche 50-390, 83/05/19, 8305270228

8305310187 Forwards physical security plan. Plan withheld (ref 10CFR73 21) Revs requested within 40 days of ltr receipt.
ADENSAM, E G Licensing Branch 4 83/05/24. PARRIS, H. G Tennessee Valley Authority 2pp 18651 002 24X Fiche 50-390, 83/05/24, 8305310187

G. Advisory Committee on Reactor Safeguards reports & correspondence

8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards 83/05/05
ACRS - Advisory Committee on Reactor Safeguards. 529pp. 18458:225
24X Fiche: 50-000, 83/05/05, 8305130290.

G Inspection reports, IE Bulletins & correspondence

8305270133 Suppls 830117 response to notice of violation contained in IE Insp Repts 50-390/82-35 & 50-391/82-32 Corrective actions any necessary revs to operating div instructions will be made as appropriate
MILLS, L M Tennessee Valley Authority 83/03/18 O'REILLY, J P Region 2, Office of Director 2pp 18638 208 24X
Fiche 50-390, 83/03/18, 8305270133

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270290 Forwards IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/03/23
PARRIS, H G Tennessee Valley Authority 2pp 18645 344 24X
Fiche 50-390, 83/03/23, 8305270290

--8305270303 IE Insp Repts 50-390/83-06 & 50-391/83-05 on 830122-0222 No noncompliance noted Major areas inspected followup on licensee identified items, licensee action on previous enforcement matters & independent insp effort
HEATHERLY, T L , SWAN, W Region 2, Office of Director QUICK, D Division of Project & Resident Programs 83/03/22 9pp 18645 346 24X Fiche 50-390, 83/03/23, 8305270290

8305270651 Forwards IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/11
PARRIS, H G Tennessee Valley Authority 2pp 18646 344 24X
Fiche 50-390, 83/04/11, 8305270651

--8305270659 IE Insp Repts 50-390/83-05 & 50-391/83-04 on 830228-0304 & 15-18 No noncompliance noted Major areas inspected licensee action on previous enforcement matters, independent insp efforts, preservice insp & safety-related structures
COLEY, J L , BLAKE, J J Region 2, Office of Director 83/04/06 12pp 18646 346 24X Fiche 50-390, 83/04/11, 8305270651

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305270557 Ack receipt of 830411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI, D M Division of Project & Resident Programs. 83/05/02
PARRIS, H G Tennessee Valley Authority 1p. 18646·114 24X
Fiche 50-390, 83/05/02, 8305270557

--8305270567 Second supplemental response to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions drawings will be revised to reflect mark numbers of as-installed dampers by 830430.
MILLS, L M Tennessee Valley Authority 83/04/11 O'REILLY, J P Region 2, Office of Director 1p 18646:117 24X
Fiche 50-390, 83/05/02, 8305270557

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270413 Forwards IE Insp Repts 50-390/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/05/09
PARRIS,H G Tennessee Valley Authority 2pp 18642 299 24X
Fiche 50-390,83/05/09,8305270413

--8305270420 IE Insp Repts 50-390/83-10 & 50-391/83-08 on 830411-15 No noncompliance noted Major areas inspected licensee action on previous enforcement matters,licensee identified items, inspector followup items & independent insp effort
GIBBONS,T D , CONLON,T E Region 2, Office of Director 83/05/06
4pp 18642 301 24X Fiche 50-390,83/05/09,8305270413

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270228 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20
VERRELLI,D M Division of Project & Resident Programs 83/05/19
PARRIS,H G Tennessee Valley Authority 1p 18637,195 24X
Fiche 50-390,83/05/19,8305270228

--8305270233 Responds to NRC 821216 ltr re violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions deficient fire dampers replaced or determined to be adequate Two dampers not in compliance
KAMMER,D S Tennessee Valley Authority 83/05/09 O'REILLY,J P
Region 2, Office of Director 2pp 18637 196 24X
Fiche 50-390,83/05/19,8305270228

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E.P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement, 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030072 First interim deficiency rept re loose matl in steam generator Initially reported on 830325 All loose items & matl determined detrimental removed from generators Next rept expected by 830808
MILLS,L M Tennessee Valley Authority, 83/04/25 O'REILLY,J P
Region 2, Office of Director 2pp 18300,349 24X
Fiche 50-390,83/04/25,8305030072

8305030082 Second interim deficiency rept re incorrect insulation weights used in piping analysis Initially reported on 820825 QA documents being prepared to substantiate insulation data Next rept expected by 830921
MILLS,L M Tennessee Valley Authority 83/04/25 O'REILLY,J P
Region 2, Office of Director 2pp 18397 239 24X
Fiche 50-390,83/04/25,8305030082

8305030578 First interim deficiency rept re inaccurate results from ANCHORS computer program Initially reported on 830329 Program being modified to automatically calculate direction cosines Next rept to be submitted by 830923
MILLS,L M Tennessee Valley Authority 83/04/26 O'REILLY,J P.
Region 2, Office of Director 2pp 18303 309 24X
Fiche 50-390,83/04/26,8305030578

8305050067 Ninth interim deficiency rept re seismic qualification for chillers/coolers & deficient piping of HVAC sys & improper classification of ERCW sys piping & components Initially reported on 810324 & 0507,respectively Next rept due 830829.
MILLS,L M Tennessee Valley Authority 83/04/27 O'REILLY,J P
Region 2, Office of Director 4pp 18342 062 24X
Fiche 50-390,83/04/27,8305050067

8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
MILLS,L M Tennessee Valley Authority 83/04/27 O'REILLY,J P
Region 2, Office of Director. 3pp 18341 083 24X
Fiche 50-000,83/04/27,8305050152

8305050232 Second combined interim deficiency rept re alternate analysis piping program Significant breakdown of program requires reverification of alternate analysis.Full review program underway Next rept expected by 830930.
MILLS,L M Tennessee Valley Authority 83/04/27 O'REILLY,J.P.
Region 2, Office of Director 5pp 18337 329 24X
Fiche 50-390,83/04/27,8305050232

8305050078 First interim deficiency rept re spacing & clearance in high pressure fire protection sprinkler sys in auxiliary bldg. Initially reported on 830331 Evaluation in progress Next rept will be sent by 830624
MILLS,L M Tennessee Valley Authority 83/04/28. O'REILLY,J.P.
Region 2, Office of Director 2pp 18342 150 24X
Fiche 50-390,83/04/28,8305050078

8305050188 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per QA program Initially reported on 830329 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706.
MILLS,L M Tennessee Valley Authority 83/04/28 O'REILLY,J.P.
Region 2, Office of Director 2pp. 18341 076 24X
Fiche 50-000,83/04/28,8305050188

8305050243 Third interim deficiency rept re high point venting in ERCW sys. Initially reported on 820930 Performance evaluation ongoing Next rept will be submitted by 830729.
MILLS,L M Tennessee Valley Authority 83/04/28 O'REILLY,J P
Region 2, Office of Director 1p 18338 056 24X
Fiche 50-390,83/04/28,8305050243.

8305050047 Fourth interim deficiency rept re questionable patches of plastic cement mortar Initially reported on 820429 Three of 50 supports determined to be in violation of Const Spec G-32 Next rept will be submitted by 830805.
MILLS,L M. Tennessee Valley Authority. 83/04/29. O'REILLY,J P.
Region 2, Office of Director. 1p 18338,330 24X
Fiche 50-390,83/04/29,8305050047.

8305110505 Final deficiency rept re incorrectly wired ERCW flow control valves.Initially reported on 830405 Event determined isolated condition caused by misinterpretation of conduit drawings Operators rewired & personnel reinstructed
MILLS,L M Tennessee Valley Authority 83/05/03 O'REILLY,J.P.
Region 2, Office of Director 2pp 18405,046 24X
Fiche 50-391,83/05/03,8305110505

8305110317 Seventh interim deficiency rept re lack of documentation for rock supported structures for 1-inch differential settlement Initially reported on 810707.Design criteria being prepared Next rept by 830922
MILLS,L M Tennessee Valley Authority 83/05/04. O'REILLY,J P
Region 2, Office of Director 3pp 18393 183 24X
Fiche 50-390,83/05/04,8305110317.

8305110319 First interim rept re Deficiencies 1,2 & 3 QA program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc.Written instructions & procedures not provided to contractor in performing/documenting piping analysis.Review underway
MILLS,L M Tennessee Valley Authority 83/05/05 O'REILLY,J P
Region 2, Office of Director. 3pp 18393 181. 24X
Fiche 50-000,83/05/05,8305110319.

8305130133 Supplemental info to final deficiency rept re insufficient documentation for protective devices Initially reported on 810313 Completion date for corrective actions delayed until 830531 One field change request remains
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18437 279 24X
Fiche 50-390,83/05/06,8305130133

8305130217 Addl info to final deficiency rept re nonconservative calculation method for general Const Spec G-32 Initially reported on 820528 Rev to Design Std DS-C6 1 will be issued by 830630
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J P
Region 2, Office of Director 1p 18440 089 24X
Fiche 50-390,83/05/06,8305130217

8305170288 Second interim deficiency rept re incorrect use of Category I(L) supports on pipes near water chillers Initially reported on 830117 Scope of investigation expanded to include generic implications Next rept expected by 830922
MILLS,L M Tennessee Valley Authority 83/05/09 O'REILLY,J P
Region 2, Office of Director 2pp 18465 071 24X
Fiche 50-390,83/05/09,8305170288

8305170299 Final deficiency rept re lack of support for reactor bldg annulus floor drain sump Initially reported on 821207 Pipes analyzed & appropriate seismic supports designed under Engineering Change Notice ECN 3234
MILLS,L M Tennessee Valley Authority 83/05/09 O'REILLY,J P
Region 2, Office of Director 2pp 18465 066 24X
Fiche 50-390,83/05/09,8305170299

8305200274 Revised final deficiency rept re unqualified control equipment Initially reported on 800922 Control equipment seismic qualification test requirements will be reviewed
MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P
Region 2, Office of Director 2pp 18518 094 24X
Fiche 50-390,83/05/11,8305200274

8305200275 Eighth interim deficiency rept re retrievable info used in piping analysis Initially reported on 810316 New Engineering Procedure BWP-EP 43 22 written Drawings containing reviewed & updated quality issued
MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P
Region 2, Office of Director 1p 18516 318 24X
Fiche 50-390,83/05/11,8305200275

8305200343 Suppl to final deficiency repts re Class IE electrical components for ERCW traveling screens Initially reported on 810518 Qualified motor search continues Corrections to be completed by 831001
MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P
Region 2, Office of Director 1p 18516 232 24X
Fiche 50-390,83/05/11,8305200343

8305230575 Final deficiency rept re missing seismic design documentation for auxiliary bldg platform Initially reported on 820426 Required drawing revs completed Field mods will be completed by 830801 & 840214 for Units 1 & 2,respectively
MILLS,L M Tennessee Valley Authority 83/05/13 O'REILLY,J P
Region 2, Office of Director 2pp 18537 309 24X
Fiche 50-390,83/05/13,8305230575.

8305200387 Second revised final deficiency rept re attachment of conduit & piping supports to cable tray supports Initially reported on 820607 Previous decision re nonapplicability of 10CFR50 55(e) sustained
MILLS,L M Tennessee Valley Authority 83/05/16 O'REILLY,J P
Region 2, Office of Director. 2pp 18519 086 24X
Fiche 50-390,83/05/16,8305200387

8305230482 Third interim deficiency rept re incorrect supports in analysis of 3-inch chemical vol & control sys line Initially reported on 830505 Addl problems identified Field mods required.Next rept will be submitted by 830922
MILLS,L M Tennessee Valley Authority. 83/05/17 O'REILLY,J P
Region 2, Office of Director 2pp. 18537 149 24X
Fiche.50-390,83/05/17,8305230482

8305230433 Final deficiency rept re inadequate freeze protection Initially reported on 810413 Piping to ERCW pump motor cooler redesigned to be self-draining
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J.P.
Region 2, Office of Director 2pp 18538 212 24X
Fiche.50-390,83/05/18,8305230433

8305230447 Second interim deficiency rept re auxiliary instrument room fire door failure Initially reported on 821229 Lower flush bolt not engaged in strike plate at floor Acceptance criteria established for max room pressures
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J.P
Region 2, Office of Director 2pp 18538 194. 24X
Fiche 50-390,83/05/18,8305230447

8305230569 Fifth interim deficiency rept re excessive movement of containment penetration bellows Initially reported on 811204 Analysis Problems N3-63-7A & N3-74-1A reanalyzed Support mods required Next rept due by 830930
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J P
Region 2, Office of Director 1p 18536 318 24X
Fiche 50-390,83/05/18,8305230569

8305250421 First interim deficiency rept re qualification of nozzle loads in reactor coolant loop Initially reported on 830421 Review of analysis problems in progress Next rept by 830921
MILLS,L M Tennessee Valley Authority 83/05/19 O'REILLY,J P
Region 2, Office of Director 2pp 18585 263 24X
Fiche 50-390,83/05/19,8305250421

8305250435 Final rept re deficiencies in Ameron cement mortar lining Initially reported on 820521 Corrections to each deviation listed Also reportable per 10CFR21
MILLS,L M Tennessee Valley Authority 83/05/20 O'REILLY,J P
Region 2, Office of Director 6pp 18585 293 24X
Fiche 50-390,83/05/20,8305250435

8305310172 Second interim deficiency rept re failure of curtain-type fire dampers to close Initially reported on 821025 Engineering change notice issued to add negator closure springs & positive latches
MILLS,L M Tennessee Valley Authority 83/05/23 O'REILLY,J P
Region 3, Office of Director 1p 18658 149 24X
Fiche 50-390,83/05/23,8305310172

DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305200513 Summarizes 830510 telcon,clarifying SER description of feedwater mod isolation logic Reverse flush valves provided w/Class IE Trains A & B closure signals
DIXON,O W South Carolina Electric & Gas Co 83/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18516 086 24X Fiche 50-395,83/05/12,8305200513

F Security, medical, emergency & fire protection plans

8305030010 Advises that position concerning nonestablishment of backup emergency operations facility (EOF) unacceptable Plans to establish EOF by 830601 must be submitted & must meet NUREG-0737,Suppl 1 (Generic Ltr 82-33) criteria
EISENHUT,D G Division of Licensing 83/04/25 DIXON,O W South Carolina Electric & Gas Co 3pp 18310 353 24X
Fiche 50-395,83/04/25,8305030010

8305050311 Releases public version of rev to emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/25 Document Management Branch 1p 18352 185 24X Fiche 50-395,83/04/25, 8305050311

--8305050317 Forwards public version of Rev 5 to Emergency Plan Implementing Procedure EPP-002, "Communication & Notification" & Change 1 to Rev 1 of EPP-020, "Emergency Personnel Exposure Control "
DIXON,O W South Carolina Electric & Gas Co 83/03/25
DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 18352 186 24X Fiche 50-395,83/04/25,8305050311

--8305050321 Public version of Rev 5 to Emergency Plan Implementing Procedure EPP-002, "Communication & Notification" & Change 1 to Rev 1 of EPP-020, "Emergency Personnel Exposure Control "
COUNTS,M , BRADHAM,A S South Carolina Electric & Gas Co 83/03/15. 40pp 18352 188 24X Fiche 50-395,83/04/25,8305050311

8305270436 Forwards IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/25
DIXON,O W South Carolina Electric & Gas Co 2pp 18662 115 24X
Fiche 50-395,83/04/25,8305270436

--8305270446 IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted Major areas inspected coordinated emergency response exercise
CLINE,W E , STANSBERRY,W W Region 2, Office of Director
JENKINS,G R Division of Emergency Preparedness & Materials Safety 83/04/14. 8pp 18662 117 24X Fiche 50-395,83/04/25, 8305270436

8305060130 Forwards Amend 15 to License NPF-12,safety evaluation & notice of issuance & availability Amend changes Tech Spec to reflect addl fire protection equipment installed & actual location & number of fire detectors.
ADENSAM,E G Licensing Branch 4 83/04/27 DIXON,O W South Carolina Electric & Gas Co 2pp 18359 310 24X
Fiche 50-395,83/04/27,8305060130

--8305060282 Amend 15 to License NPF-12, changing Tech Spec to reflect addl fire protection equipment installed, actual location & number of fire detectors & location of water spray & sprinkler sys
ADENSAM, E G Licensing Branch 4 83/04/27 15pp 18359 312
24X Fiche 50-395, 83/04/27, 8305060130

--8305060288 Safety evaluation supporting Amend 15 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/04/27 2pp
18359 327 24X Fiche 50-395, 83/04/27, 8305060130

--8305060295 Notice of issuance & availability of Amend 15 to License NPF-12
ADENSAM, E G Licensing Branch 4 83/04/27 3pp 18359 329 24X
Fiche 50-395, 83/04/27, 8305060130

8305090454 Forwards IE Safeguards Insp Rept 50-395/83-13 on 820903-830406 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/05/06 DIXON, O W
South Carolina Electric & Gas Co. 2pp 18362 261 24X
Fiche: 50-395, 83/05/06, 8305090454

--8305090461 IE Safeguards Insp Rept 50-395/83-13 on 820903-830406. No noncompliance noted Major areas inspected licensee revalidation of preemployment screening records Details withheld (ref 10CFR73 21)
TOBIN, W J , FERNY, C , LANKFORD, J Region 2, Office of Director
83/05/04 1p 18362 263 24X Fiche 50-395, 83/05/06, 8305090454

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305180373 Requests exemption from Generic Ltr 82-33 requiring backup emergency operations facility to be located within 10 to 20 miles of plant site Approval requested to have backup emergency operations facility at corporate ofc
DIXON, O W South Carolina Electric & Gas Co 83/05/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18486 357
24X Fiche 50-395, 83/05/16, 8305180373

P Operating license stage documents & correspondence

8305040010 Informs that relief from preservice hydrostatic tests required by ASME Code Section IX justifiable Alternative program incorporating NRC evaluation will provide acceptable level of structural integrity SER & FR notice forwarded
NOVAK, T M Assistant Director for Licensing 83/04/22 DIXON, O W
South Carolina Electric & Gas Co 2pp 18351 216 24X
Fiche 50-395, 83/04/22, 8305040010

--8305040016 Safety evaluation supporting util request for relief from preservice hydrostatic test required by ASME Code Section IX
* NRC - No Detailed Affiliation Given 83/04/22 4pp
18351 218 24X Fiche 50-395, 83/04/22, 8305040010

--8305040021 Notice of granting of relief from certain requirements of ASME Code Section IX inservice (testing) requirements
ADENSAM, E G Licensing Branch 4 83/04/22. 3pp 18351:222 24X
Fiche 50-395, 83/04/22, 8305040010

8305030014 Requests remittance of Class III fees for 830127 & 0218 applications requesting relief from requirements of ASME Code Section XI re hydrostatic testing of feedwater sys
DIGGS, R M License Fee Management Branch 83/04/26 DIXON, O W
South Carolina Electric & Gas Co 1p 18310:348 24X
Fiche 50-395, 83/04/26, 8305030014

8305060130 Forwards Amend 15 to License NPF-12, safety evaluation & notice of issuance & availability Amend changes Tech Spec to reflect addl fire protection equipment installed & actual location & number of fire detectors
ADENSAM, E G Licensing Branch 4 83/04/27 DIXON, O W South
Carolina Electric & Gas Co 2pp 18359 310 24X
Fiche 50-395, 83/04/27, 8305060130

--8305060282 Amend 15 to License NPF-12, changing Tech Spec to reflect addl fire protection equipment installed, actual location & number of fire detectors & location of water spray & sprinkler sys
ADENSAM, E G Licensing Branch 4 83/04/27 15pp 18359 312
24X Fiche 50-395, 83/04/27, 8305060130

--8305060288 Safety evaluation supporting Amend 15 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/04/27 2pp
18359 327. 24X Fiche 50-395, 83/04/27, 8305060130

--8305060295 Notice of issuance & availability of Amend 15 to License NPF-12
ADENSAM, E G Licensing Branch 4 83/04/27 3pp 18359 329 24X
Fiche 50-395, 83/04/27, 8305060130

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT, D G Division of Licensing 83/05/02 Consolidated
Edison Co of New York, Inc 30pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305060619 Discusses steam generator mod to OL Conditions 2 C(14) & 2 C(32) Loose parts monitoring program & monitoring of feedwater inlet pressure oscillations clarified, per 830413 & 0214 ltrs, respectively
DIXON, O W South Carolina Electric & Gas Co 83/05/03 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18348 355.
24X Fiche 50-395, 83/05/03, 8305060619

8305110136 Advises that action required by 830203 on Amend 9, Paragraph 3, to License NPF-12 & Generic Ltr 83-07 completed, based on util negotiating w/DOE re disposal of high level waste or spent nuclear fuel
ADENSAM, E G Licensing Branch 4 83/05/03 DIXON, O W South
Carolina Electric & Gas Co . 2pp 18421 255 24X
Fiche 50-395, 83/05/03, 8305110136

8305100301 Informs of completion of evaluation of piping associated w/ feedwater mod, piping break blowdown, pipe whip, jet impingement & reactive forces to assure FSAR commitments unchanged
DIXON, O W South Carolina Electric & Gas Co. 83/05/04 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 2pp 18371.249
24X Fiche 50-395, 83/05/04, 8305100301

8305200113 Forwards request for addl info on util rept, "Seismic Confirmatory Program for Equipment & Components for VC Summer Nuclear Station - Feb 1983," submitted in response to OL Condition 2 C(25)
ADENSAM, E G Licensing Branch 4 83/05/04. DIXON, O W South
Carolina Electric & Gas Co 3pp 18540 318 24X
Fiche 50-395, 83/05/04, 8305200113

8305180012 Forwards Amend 16 to License NPF-12, safety evaluation & notice of issuance & availability Amend permits operation of modified Model D-3 steam generators
ADENSAM, E G. Licensing Branch 4 83/05/05 DIXON, O W South
Carolina Electric & Gas Co 4pp 18497.138 24X
Fiche 50-395, 83/05/05, 8305180012

--8305180015 Amend 16 to License NPF-12, permitting operation of modified Model D-3 steam generators
EISENHUT, D G Division of Licensing 83/05/05 5pp. 18497 142.
24X Fiche 50-395, 83/05/05, 8305180012

--8305180020 Safety evaluation supporting Amend 16 to License NPF-12
* Office of Nuclear Reactor Regulation, Director 83/05/05
10pp 18497 147 24X Fiche 50-395, 83/05/05, 8305180012

--8305180023 Notice of issuance & availability of Amend 16 to License NPF-12
ADENSAM, E G. Licensing Branch 4 83/05/05 3pp 18497 157. 24X
Fiche 50-395, 83/05/05, 8305180012

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods. Svc list encl
EISENHUT, D G Division of Licensing. 83/05/09. Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180442 Forwards fees for reviews of two separate requests for relief from ASME Code Section XI requirements
DIXON, O W South Carolina Electric & Gas Co 83/05/12 DIGGS, R W
License Fee Management Branch 2pp 18486 181 24X
Fiche 50-395, 83/05/12, 8305180442

8305250492 Forwards list of Class IE electric equipment important to safety, per 10CFR50. 49. Schedule for environ qualification of remaining equipment encl
DIXON, O W South Carolina Electric & Gas Co 83/05/17 DENTON, H R
Office of Nuclear Reactor Regulation, Director 30pp. 18588.303.
24X Fiche 50-395, 83/05/17, 8305250492

8305310224 Requests addl fee based on Class III determination for Amend 16 to License NPF-12, permitting operation of modified Model D-3 steam generators.
DIGGS, R M License Fee Management Branch 83/05/24 DIXON, D. W
South Carolina Electric & Gas Co 1p 18662 260 24X
Fiche: 50-395, 83/05/24, 8305310224.

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305270412 Ack receipt of 830329 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-01
LEWIS, R C Region 2, Office of Director 83/04/11 DIXON, O W South Carolina Electric & Gas Co 1p 18642 001 24X Fiche 50-395, 83/04/11, 8305270412

--8305270422 Responds to NRC 830301 ltr re violations noted in IE Insp Rept 50-395/83-01 Corrective actions cross-ref table being prepared identifying reactor trip & ESF actuation sys instrumentation test procedures
DIXON, O W South Carolina Electric & Gas Co 83/03/29
O'REILLY, J P. Region 2, Office of Director 3pp 18642 002 24X Fiche 50-395, 83/04/11, 8305270412

--8305270433 Forwards IE Insp Rept 50-395/83-01 on 830105-31 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/03/01
DIXON, O W South Carolina Electric & Gas Co 2pp 18642 005 24X Fiche 50-395, 83/04/11, 8305270412

--8305270443 Notice of violation from insp on 830105-31
* Region 2, Office of Director 83/03/01 1p 18642 007 24X Fiche 50-395, 83/04/11, 8305270412

--8305270462 IE Insp Rept 50-395/83-01 on 830105-31 Noncompliance noted failure to comply w/action statement for ESF actuation
SKOLDS, J L Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/02/18 8pp 18642 008 24X Fiche 50-395, 83/04/11, 8305270412

8305270431 Ack receipt of 830314 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-04
VERRELLI, D M Division of Project & Resident Programs 83/04/13
DIXON, O W South Carolina Electric & Gas Co 1p 18641 346 24X Fiche. 50-395, 83/04/13, 8305270431

--8305270441 Responds to NRC 830214 violations noted in IE Insp Rept 50-395/83-04 Corrective actions containment equipment hatch area will be posted w/rigid sign
DIXON, O W South Carolina Electric & Gas Co 83/03/14
O'REILLY, J P Region 2, Office of Director 2pp 18641 347 24X Fiche 50-395, 83/04/13, 8305270431

--8305270449 Forwards IE Insp Rept 50-395/83-04 on 830118-20 & notice of violation
DANCE, H C Division of Project & Resident Programs 83/02/14
DIXON, O W South Carolina Electric & Gas Co 2pp 18641 349 24X Fiche. 50-395, 83/04/13, 8305270431

--8305270452 Notice of violation from insp on 830118-20
* Region 2, Office of Director 83/02/14 1p 18641 351 24X Fiche 50-395, 83/04/13, 8305270431

--8305270458 IE Insp Rept 50-395/83-04 on 830118-20 Noncompliance noted failure to properly post radiation area
PEERY, W W , BARR, K P Region 2, Office of Director 83/02/09 4pp 18641 352 24X Fiche 50-395, 83/04/13, 8305270431

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305270091 Forwards IE Insp Rept 50-395/83-12 on 830322-25 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/18
DIXON, O W. South Carolina Electric & Gas Co 2pp 18638 186. 24X Fiche. 50-395, 83/04/18, 8305270091

--8305270094 IE Insp Rept 50-395/83-12 on 830322-25 No noncompliance noted Major areas inspected seismic analysis for as-built safety-related piping sys (IE Bulletin 79-14) & Tech Spec compliance.
ANG, W P Region 2, Office of Director BLAKE, J J Division of Emergency Preparedness & Materials Safety 83/04/14 5pp. 18638 188 24X Fiche 50-395, 83/04/18, 8305270091

8305270093 Forwards IE Insp Rept 50-395/83-11 on 830329-31 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/20
DIXON, W O South Carolina Electric & Gas Co 2pp 18638 171 24X Fiche 50-395, 83/04/20, 8305270083

--8305270086 IE Insp Rept 50-395/83-11 on 830329-31 No noncompliance noted Major areas inspected radiochemical instrument calibr, QC program & records & capability tests for measurement of radioactive effluents
EVANS, C D Region 2, Office of Director MONTGOMERY, D Division of Emergency Preparedness & Materials Safety 83/04/19 8pp 18638 173 24X Fiche 50-395, 83/04/20, 8305270083

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305270436 Forwards IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted
VERRELLI, D M Division of Project & Resident Programs 83/04/25
DIXON, O W South Carolina Electric & Gas Co 2pp 18662 115 24X Fiche 50-395, 83/04/25, 8305270436

--8305270446 IE Insp Rept 50-395/83-07 on 830314-17 No noncompliance noted Major areas inspected coordinated emergency response exercise
CLINE, W E , STANSBERRY, W W Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/04/14 8pp 18662 117 24X Fiche 50-395, 83/04/25, 8305270436

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305270464 Forwards IE Insp Rept 50-395/83-14 on 830412-15 No noncompliance noted
VERRELLI, D M Region 2, Office of Director 83/05/05 DIXON, O W South Carolina Electric & Gas Co 2pp 18644 057 24X Fiche 50-395, 83/05/05, 8305270464

--8305270478 IE Insp Rept 50-395/83-14 on 830412-15 No noncompliance noted Major areas inspected steam generator mod, welding program & NDE program
KLEINSORGE, W P Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/04 15pp 18644 059 24X Fiche 50-395, 83/05/05, 8305270464

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305090454 Forwards IE Safeguards Insp Rept 50-395/83-13 on 820903-830406 No noncompliance noted
O'REILLY, J P Region 2, Office of Director 83/05/06 DIXON, O W South Carolina Electric & Gas Co 2pp 18362 261 24X
Fiche 50-395, 83/05/06, 8305090454

--8305090461 IE Safeguards Insp Rept 50-395/83-13 on 820903-830406 No noncompliance noted Major areas inspected licensee revalidation of preemployment screening records Details withheld (ref 10CFR73 21)
TOBIN, W J., PERNY, C , LANKFORD, J Region 2, Office of Director 83/05/04 1p 18362 263 24X Fiche 50-395, 83/05/06, 8305090454

8305270512 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-395/83-05
LEWIS, R C Division of Project & Resident Programs 83/05/10
DIXON, O W South Carolina Electric & Gas Co 1p 18646 050 24X
Fiche 50-395, 83/05/10, 8305270512

--8305270519 Forwards IE Insp Rept 50-395/83-05 on 830201-0304 & notice of violation
LEWIS, R C Division of Project & Resident Programs 83/04/04
DIXON, O W South Carolina Electric & Gas Co 2pp 18646 051
24X Fiche: 50-395, 83/05/10, 8305270512

--8305270522 Notice of violation from insp on 830201-0304
* Region 2, Office of Director 83/04/04 2pp 18646·053 24X
Fiche 50-395, 83/05/10, 8305270512

--8305270532 IE Insp Rept 50-395/83-05 on 830201-0304 Noncompliance noted failure to follow procedures for waste monitor tank by not flushing discharge line & control room fan inoperable
SKOLDS, J L Region 2, Office of Director CANTRELL, F S, Division of Project & Resident Programs 83/03/30 10pp 18646 055 24X
Fiche 50-395, 83/05/10, 8305270512

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/03/11. Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034.

8305180465 Forwards 830117 divers rept on svc water intake structure & Gilbert Commonwealth Assocs engineering evaluation of divers insp, in response to NRC 830324 ltr Svc water intake structure essentially stabilized
DIXON, O W South Carolina Electric & Gas Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18483 086
24X Fiche 50-395, 83/05/11, 8305180465

--8305180466 "Divers Rept Svc Water Intake Tunnel Insp "
EASON, T D. Eason Diving & Marine Contractors, Inc 83/01/17
11pp 18483 090 24X Fiche 50-395, 83/05/11, 8305180465

8305200311 Forwards Rev 5 to Emergency Operating Procedure EOP-5, "Recovery From Reactor Trip," in response to IE Bulletins 83-01 & 83-04 Procedure revised to require manual reactor trip upon automatic reactor trip condition
DIXON, O W South Carolina Electric & Gas Co 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18516 199
24X Fiche 50-395, 83/05/12, 8305200311

--8305200352 Rev 5 to Emergency Operating Procedure EOP-5, "Recovery From Reactor Trip "
POOLE, J W South Carolina Electric & Gas Co 83/04/27 14pp
18516 204 24X Fiche, 50-395, 83/05/12, 8305200311

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046.

B. Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P Westinghouse Electric Corp 83/04/21. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 5pp 18405:095. 24X Fiche 50-000, 83/04/21, 8305110427

8305030627 Forwards LER 83-031/03L-0 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/04/22
O'REILLY, J P Region 2, Office of Director 3pp 18303, 328 24X
Fiche 50-395, 83/04/22, 8305030627

--8305030637 LER 83-031/03L-0 on 830325, ECCS mechanical water chiller XHX-001B tripped Caused by intermittently failing valve control switch Switch repaired
FIELDS, H C South Carolina Electric & Gas Co 83/04/22. Region 2, Office of Director 1p 18303 331 24X Fiche 50-395, 83/04/22, 8305030627

8305050057 Forwards LER 83-033/03L-0 Detailed event analysis encl
DIXON, O W South Carolina Electric & Gas Co 83/04/29
O'REILLY, J P Region 2, Office of Director 2pp 18342 066 24X
Fiche 50-395, 83/04/29, 8305050057

--8305050061 LER 83-033/03L-0, on 830331, while in Mode 5, source range detectors N-31 & N-32 lost for approx 5 minutes Caused by maint personnel error in placing trains of solid state protection sys in wrong position Personnel cautioned
FIELDS, H C South Carolina Electric & Gas Co 83/04/29. Region 2, Office of Director 1p 18342 068 24X Fiche 50-395, 83/04/29, 8305050057

8305050233 Forwards LER 83-032/03L-0, Detailed event analysis encl.
DIXON, O W South Carolina Electric & Gas Co. 83/04/29
O'REILLY, J P. Region 2, Office of Director 2pp 18338·057. 24X
Fiche 50-395, 83/04/29, 8305050233

--8305050239 LER 83-032/03L-0 on 830331, detection Zone NNN in control bldg failed to respond to simulated smoke condition during investigation of alarm Alarm previously received on 830329 Caused by short in smoke detector Dectector reinstalled.
MCKINNEY, C J. South Carolina Electric & Gas Co 83/04/29.
Region 2, Office of Director. 1p. 18338·059. 24X
Fiche 50-395, 83/04/29, 8305050233

8305100089 Forwards LER 83-034/03L-0 Detailed event analysis encl.
DIXON, O W South Carolina Electric & Gas Co 83/05/02
O'REILLY, J. P. Region 2, Office of Director 2pp 18377:220 24X
Fiche 50-395, 83/05/02, 8305100089.

--8305100091 LER 83-034/03L-0, on 830409, motor junction box cover on RHR pump B found w/burned area, Caused by electrical short to ground resulting from insulation failure Termination retaped & pump returned to operable status
MCKINNEY, C J South Carolina Electric & Gas Co. 83/05/02.
Region 2, Office of Director 1p 18377·222. 24X
Fiche 50-395, 83/05/02, 8305100089.

8305110313 Part 21 rept re blow-out panel in east & west penetration areas. Initially reported on 830506. Structural framing sys designed to protect flow transmitter & related instrument tubing.
BARKER, N. R Gilbert/Commonwealth Cos 83/05/09. DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement 2pp
18393 196 24X Fiche. 50-395, 83/05/09, 8305110313

8305110322 Part 21 rept re ring duct stiffener failure Initially reported on 830506. Design change to eliminate airflow-induced vibration & redesign of ring stiffener submitted to util.
BARKER, N R Gilbert/Commonwealth Cos 83/05/09 DEYOUNG, R. C. Director's Office, Office of Inspection and Enforcement. 2pp.
18393. 177. 24X Fiche· 50-395, 83/05/09, 8305110322.

8305110399 PNO-II-83-035 on 830507, fire detected in circuitry of one of three component cooling water pumps. Licensee declared alert Caused by faulty relay. Relay replaced & pump restored to operability
BUTCHER, R C , CANTRELL, F. S. Region 2, Office of Director. 83/05/09.
1p. 18406, 189 24X Fiche· 50-395, 83/05/09, 8305110399.

8305200626 Forwards LER 83-038/03L-0 Detailed event analysis encl.
DIXON, O W. South Carolina Electric & Gas Co. 83/05/12.
O'REILLY, J. P Region 2, Office of Director. 2pp. 18519:326 24X
Fiche 50-395, 83/05/12, 8305200626.

--8305200633 LER 83-038/03L-0, on 830415, pressurizer pressure transmitter IPT-457 found out of tolerance Caused by zero & span shift of test instrument used in calibr of transmitter. Transmitter recalibr
BOUKNIGHT, R. J. South Carolina Electric & Gas Co 83/05/12.
Region 2, Office of Director 1p 18519 328. 24X
Fiche. 50-395, 83/05/12, 8305200626

8305200510 Forwards LER 83-036/03L-0 Detailed event analysis encl.
DIXON, O. W South Carolina Electric & Gas Co 83/05/13.
O'REILLY, J. P. Region 2, Office of Director 3pp. 18513:078. 24X
Fiche· 50-395, 83/05/13, 8305200510.

--8305200515 LER 83-036/03L-0 on 830414, during performance of channel calibr, pressurizer safety valve position indication on valves failed to function properly Caused by excessive current flow during contact closure Switch assembly changed
MCKINNEY, C J South Carolina Electric & Gas Co 83/05/13
Region 2, Office of Director 1p 18513 081 24X
Fiche 50-395, 83/05/13, 8305200515

8305250349 LER 83-035/03L-0 on 830420, horizontal fire barrier above svc water booster pump A found damaged Caused by maint activities in immediate area of fire barrier Damaged barrier replaced W/830520 ltr
DIXON, D W , BOUKNIGHT, R J South Carolina Electric & Gas Co
83/05/20 O'REILLY, J P Region 2, Office of Director 2pp
18592 102 24X Fiche 50-395, 83/05/20, 8305250349

DOCKET 50-396 UNIV OF VIRGINIA CAVALIER REACTOR

P Operating license stage documents & correspondence

8305230548 Application for amend to License R-123, changing Tech Specs to remove Item 3 2 b re subcriticality w/single rod inserted & to modify Section 5 1 re fuel elements
BRENIZER, J S Virginia, Univ of, Charlottesville, VA 83/05/10
THOMAS, C. O Standardization & Special Projects Branch 2pp
18537 083 24X Fiche 50-396, 83/05/10, 8305230548

DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8305130262 Notification of 830524 meeting w/util in Walnut Creek, CA to review program status of engineering, licensing, const, startup, quality verification, equipment qualification (environ & seismic) & emergency planning
* Region 5, Office of Director 83/04/09 Region 5, Office of Director 2pp 18439 242 24X Fiche 50-397, 83/04/09, 8305130262

8305030324 Forwards summary review of actions taken to assure quality of safety-related const & to meet commitments made to Commission in 800717 ltr, per 10CFR50 54(f) Actions included in restart & quality verification programs
CARLISLE, C S Washington Public Power Supply System 83/04/18
MARTIN, J B Region 5, Office of Director 20pp 18297 163 24X
Fiche 50-397, 83/04/18, 8305030324

8305040289 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK, T M Assistant Director for Licensing 83/04/26
HOLTZSCHER, D L Illinois Power Co 2pp 18326 343 24X
Fiche: 50-000, 83/04/26, 8305040289

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche: 50-000, 83/05/03, 8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D. G Division of Licensing. 83/05/03. HALE, D P
Illinois Power Co. 2pp 18523 200 24X Fiche 50-000, 83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D. G Division of Licensing. 83/05/03 FERGUSON, M R
Washington Public Power Supply System 2pp 18523, 202 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing. 83/05/03. MCGAUGHY, J P.
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants.
EISENHUT, D G. Division of Licensing. 83/05/03 CAHILL, J Gulf States Utilities Co. 2pp 18523 206 24X Fiche 50-000, 83/05/03, 8305190046.

8305100110 Responds to 830413 ltr re TMI Action Item II K 3 18, "Mods to ADS Sys Logic " One of two options (2 or 4) will be implemented Choice based on benefit to design impact on schedule, availability of hardware & analysis & total cost
BOUCHEY, G D Washington Public Power Supply System 83/05/04
SCHWENCER, A Licensing Branch 2 1p 18375 032 24X
Fiche 50-397, 83/05/04, 8305100110

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305170156 Forwards Burns & Roe Drawing H501 defining jurisdictional boundary between NF & AISC for supports W/o encl
BOUCHEY, G D Washington Public Power Supply System 83/05/11
SCHWENCER, A Licensing Branch 2 1p 18466 341 24X
Fiche 50-397, 83/05/11, 8305170156

8305250261 Notification of 830606-09 meetings w/util & LASL onsite to discuss control room human factors reviews
AULUCK, R Licensing Branch 2 83/05/18 SCHWENCER, A Licensing Branch 2 5pp 18595 338 24X Fiche 50-397, 83/05/18, 8305250261

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 HOLTZSCHER, D L
Illinois Power Co 2pp 18443 173 24X Fiche 50-000, 83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 POWELL, P Washington Public Power Supply System 1p 18443 174 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 REED, W J Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000, 83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 RICHARDSON, J D
Mississippi Power & Light Co 1p 18443 176 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs. Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J. Licensing Branch 1 83/05/02 BUZZELLI, E M
Cleveland Electric Illuminating Co 1p 18443 177 24X
Fiche 50-000, 83/05/02, 8305120460

8305160041 Forwards marked-up FSAR pages describing equipment for sampling & monitoring process & effluent streams during postulated accidents Submittal closes out commitment in Section 11 5 2 (Page 11-14) of SER, NUREG-0892
BOUCHEY, G D Washington Public Power Supply System 83/05/10
SCHWENCER, A Licensing Branch 2, 20pp. 18444 009 24X
Fiche 50-397, 83/05/10, 8305160041

8305250082 Forwards Suppl 3 to SER (NUREG-0892) W/o encl
SCHWENCER, A Licensing Branch 2 83/05/19 FERGUSON, R L
Washington Public Power Supply System 2pp 18596 307 24X
Fiche 50-397, 83/05/19, 8305250082

F Security, medical, emergency & fire protection plans

8305130262 Notification of 830524 meeting w/util in Walnut Creek, CA to review program status of engineering, licensing, const, startup, quality verification, equipment qualification (environ & seismic) & emergency planning
* Region 5, Office of Director 83/04/09 Region 5, Office of Director 2pp. 18439 242 24X Fiche 50-397, 83/04/09, 8305130262.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

G Adjudicatory correspondence

8303290382 Brief in opposition to Coalition for Safe Power appeal from ASLB 830222 memorandum & order dismissing 820223 petition to intervene Petitioner failed to particularize & support contentions Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/03/25 Atomic Safety and Licensing Appeal Panel 25pp 17724 021 24X Fiche 50-397, 83/03/25, 8303290382

8305260174 Advises that time for Commission to review ALAB-722 expired Commission declined review Decision became final agency action on 830523.
CHILK, S J Office of the Secretary of the Commission 83/05/25 Atomic Safety and Licensing Board Panel 1p 18599 272 24X
Fiche 50-397, 83/05/25, 8305260174

K Utility Final Safety Analysis Report (FSAR) & amends

8305120233 Forwards Amend 29 to FSAR
BOUCHEY, G D Washington Public Power Supply System 83/03/15
SCHWENCER, A Licensing Branch 2 2pp 18424 226 24X
Fiche 50-397, 83/03/15, 8305120233

--8305120236 Amend 29 to FSAR
* Washington Public Power Supply System 83/03/31 952pp
18424 228 24X Fiche 50-397, 83/03/15, 8305120233

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp. 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305170375 Forwards IE Insp Rept 50-397/83-10 on 830301-31 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/04/18.
CARLISLE, C S Washington Public Power Supply System 2pp
18469 191 24X Fiche 50-397, 83/04/18, 8305170375

--8305170381 IE Insp Rept 50-397/83-10 on 830301-31 No noncompliance noted Major areas inspected pipe support records, const quality reverification activities & const mgt topics
TOTH, A D , DODDS, R T Region 5, Office of Director 83/04/15
14pp 18469 193 24X Fiche 50-397, 83/04/18, 8305170375.

8305170346 Forwards IE Insp Rept 50-397/83-13 on 830404-08 No noncompliance noted.
STERNBERG, D M Region 5, Office of Director 83/04/19
CARLISLE, C S Washington Public Power Supply System 2pp
18465 268 24X Fiche 50-397, 83/04/19, 8305170346

--8305170349 IE Insp Rept 50-397/83-13 on 830404-08. No noncompliance noted Major areas inspected preoperational test program, open items, IE bulletin/circular response, TMI (NUREG-0737) activities & independent insp
WILLETT, D J , DODDS, R T Region 5, Office of Director 83/04/19.
3pp 18465 270 24X Fiche: 50-397, 83/04/19, 8305170346

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305130245 Forwards "WNP-2 Project Review of Completed Safety-Related Work," fourteenth progress rept for Jan-Mar 1983, per util 800717 commitments in response to notice of violation & addl info in accordance w/10CFR50.54(f)
CARLISLE, C S Washington Public Power Supply System 83/04/26.
MARTIN, J D Region 5, Office of Director 17pp 18439 195 24X
Fiche 50-397, 83/04/26, 8305130245

8305170436 Forwards IE Insp Rept 50-397/83-12 on 830301-31 No noncompliance noted
STERNBERG, D M Region 5, Office of Director. 83/04/26
CARLISLE, C S Washington Public Power Supply System 2pp
18469 177 24X Fiche 50-397, 83/04/26, 8305170436

--8305170439 IE Insp Rept 50-397/83-12 on 830301-31 No noncompliance noted Major areas inspected preoperational test procedure review, witnessing & independent insp effort
FEIL, R A , TOTH, A D , DODDS, R T Region 5, Office of Director
83/04/24 7pp 18469 179 24X Fiche 50-397, 83/04/26, 8305170436

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028.

8305050159 Forwards Vol 4 to "WPPSS Nuclear Project 2 Preservice Insp Program Plan, Summary Rept," documenting completion of approx 98% of volumetric & surface exams, repairs & replacements & including Request for Relief PSI-2-001
BOUCHEY, G D Washington Public Power Supply System 83/05/03
SCHWENCER, A Licensing Branch 2 2pp 18341, 121. 24X
Fiche 50-397, 83/05/03, 8305050159

--8305050164 Vol 4 to "WPPSS Nuclear Project 2 Preservice Insp Program Plan, Summary Rept "
PORTER, D W , MARTIN, J Washington Public Power Supply System
83/04/27 196pp 18341 123 24X Fiche 50-397, 83/05/03, 8305050159

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8305170335 Forwards IE Insp Rept 50-397/83-16 on 830418-22 No noncompliance noted
BOOK, H E Region 5, Office of Director. 83/05/05. CARLISLE, C S Washington Public Power Supply System 2pp 18465, 126 24X
Fiche 50-397, 83/05/05, 8305170335

--8305170343 IE Insp Rept 50-397/83-16 on 830418-22. No noncompliance noted Major areas inspected radwaste mgt sys, including review of preoperational test program & status of gas, liquid & solid waste treatment sys
YUHAS, G P , WENSLAWSKI, F A , BOOK, H E Region 5, Office of Director 83/05/04 5pp 18465 128 24X Fiche 50-397, 83/05/05, 8305170335

8305260252 Requests unrestricted access for team members to site during NRC const assessment team insp scheduled for 830516-27 & 0606-16
STERNBERG, D. M Region 5, Office of Director. 83/05/05.
CARLISLE, C S Washington Public Power Supply System. 2pp
18626 108 24X Fiche 50-397, 83/05/05, 8305260252

--8305260255 Lists team members & areas of assignment for NRC const assessment insp scheduled for 830516-27 & 0606-16
HEIBHMAN, R F Reactor Construction Branch 83/04/26 Reactor Construction Branch 1p 18626 110 24X Fiche 50-397, 83/05/05, 8305260252

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8305130245 Forwards "WNP-2 Project Review of Completed Safety-Related Work," fourteenth progress rept for Jan-Mar 1983, per util 800717 commitments in response to notice of violation & addl info in accordance w/10CFR50 54(f)
CARLISLE, C S Washington Public Power Supply System 83/04/26
MARTIN, J D Region 5, Office of Director 17pp 18439 195 24X
Fiche 50-397, 83/04/26, 8305130245

S Reportable occurrences, LERs & related correspondence

8305030300 Part 21 rept re linear indications identified in SA 106 grade pipe Initially reported on 830413 Caused by mfg process error & ultrasonic exam inadequacies All seamless pipe put on hold & magnetic particle examined
CARLISLE, C S Washington Public Power Supply System 83/04/15
MARTIN, J B Region 5, Office of Director 18pp 18297 070 24X
Fiche: 50-397, 83/04/15, 8305030300

8305030507 Final & interim deficiency repts re Class IE cables in Seismic Category 1 raceways & standby gas treatment sys damper Next rept by 830718
CARLISLE, C S Washington Public Power Supply System 83/04/18
MARTIN, J B Region 5, Office of Director 11pp 18295 098 24X
Fiche 50-397, 83/04/18, 8305030507

8305030500 Interim deficiency repts re IE Circular 81-05, "Sway Strut/ Snubber End Bushings" & Anaconda flexible conduit Initially reported on 821202 & 830321, respectively Quarterly updates will continue to be provided Next rept expected by 830720
CARLISLE, C. S Washington Public Power Supply System 83/04/20
MARTIN, J. B. Region 5, Office of Director 5pp 18306 345 24X
Fiche 50-397, 83/04/20, 8305030500

8305130106 Interim deficiency repts on Condition 221 re NAMCO EA-180 & EA-740 limit switches & Condition 226 re 125-volt dc motor operator connected to 250-volt dc power source Next rept by 830726
CARLISLE, C. S Washington Public Power Supply System 83/04/26
MARTIN, J. B Region 5, Office of Director 4pp 18438, 093 24X
Fiche: 50-397, 83/04/26, 8305130106.

DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
SMITH, S H Carolina Power & Light Co 83/03/22 TOURTELLOTTE, J Regulatory Reform Task Force 13pp 18543 277 24X
Fiche: 50-000, 83/03/22, 8305230283.

8305020506 Forwards request for addl info re personnel training to aid in review performed by Licensee Qualifications Branch.
KNIGHTON, G. W Licensing Branch 3 83/04/11 UTLEY, E E Carolina Power & Light Co 4pp 18284 325 24X Fiche 50-400, 83/04/11, 8305020506

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305170577 Forwards request for design documents to continue NRC review
KNIGHTON, G W Licensing Branch 3 83/04/21 UTLEY, E E Carolina Power & Light Co 3pp 18496 117 24X Fiche 50-400, 83/04/21, 8305170577

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120467 Forwards "Conformance W/Title 10 of CFR Parts 20, 50 & 100," per 811125 request & 820630 schedule Requirements of applicable regulations met Addl verification provided by independent NRC review
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 18431 058 24X Fiche 50-400, 83/05/09, 8305120467

8305170282 Forwards changes to corporate QA program, currently provided in Section 1 8 of PSAR
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 18465 329 24X
Fiche 50-400, 83/05/09, 8305170282

--8305170285 Changes to Section 1 8 (QA program) of PSAR
* Carolina Power & Light Co 83/05/09 14pp 18465 330 24X
Fiche 50-400, 83/05/09, 8305170282

D NRC Draft/Final Environmental Statements, suppls & correspondence

8305170149 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1 AND 2 Docket Nos STN 50-400 And STN 50-401 (Carolina Power And Light Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0972
83/04/30 220pp 18477 216 24X Fiche 50-400, 83/04/30, 8305170149

8305200122 Forwards DES & FR notice W/o DES
KNIGHTON, G W Licensing Branch 3 83/05/12 UTLEY, E E Carolina Power & Light Co 2pp 18528 346 24X Fiche 50-400, 83/05/12, 8305200122

--8305200125 Notice of availability of DES
KNIGHTON, G W Licensing Branch 3 83/05/12 2pp 18528 348
24X Fiche 50-400, 83/05/12, 8305200122

8305200197 Forwards draft EIS & FR notice W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 Butzel & Kass
EBERT, P Affiliation Unknown 3pp 18576 151 24X
Fiche 50-400, 83/05/12, 8305200197

8305200205 Forwards, for comments, DES & notice of availability W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 WILSON, K Environmental Protection Agency 2pp 18540 215 24X
Fiche 50-400, 83/05/12, 8305200205

8305200209 Forwards, for review & comment, DES Comments due within 45 days after FR publication W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 4pp 18540 211 24X Fiche 50-400, 83/05/12, 8305200209

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020124 Forwards responses to draft SER Open Items 8 & 9 for Meteorological & Effluent Treatment Branch Wind loads for winds faster than 117 mph considered in svc load combinations for containment design (FSAR Table 3.8 1-2)
MCDUFFIE, M. A Carolina Power & Light Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp. 18278 231 24X Fiche 50-400, 83/04/27, 8305020124.

8305230296 Forwards QA Branch & Matls Engineering Branch requests for addl info not addressed in Feb 1983 draft SER Info requested by 830701
KNIGHTON, G W Licensing Branch 3 83/05/03 UTLEY, E E. Carolina Power & Light Co 7pp 18543 292 24X Fiche 50-400, 83/05/03, 8305230296

8305060555 Forwards responses to draft SER Open Items 34,35,40,42 & 44
MCDUFFIE,M A Carolina Power & Light Co 83/05/04 DENTON,H R
Office of Nuclear Reactor Regulation, Director 9pp 18348 293
24X Fiche 50-400,83/05/04,8305060555

8305110248 Informs that draft SER Open Item 67 re design of normal containment purge sys closed Sys adequate Issue of time sys allowed to operate to be addressed during Tech Spec preparation
MCDUFFIE,M A Carolina Power & Light Co 83/05/09 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18406 339 24X
Fiche 50-400,83/05/09,8305110248

8305110294 Confirms 830428 telcon closing out draft SER Open Items 298 & 299 per Generic Ltr 82-14 Responses to other open items will be submitted shortly
MCDUFFIE,M A Carolina Power & Light Co 83/05/09 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18393 307 24X
Fiche 50-400,83/05/09,8305110294.

8305160017 Forwards response to draft SER Open Item 59 re containment sys Reactor cavity subcompartment analysis conservative
MCDUFFIE,M A Carolina Power & Light Co 83/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 18453 163
24X Fiche 50-400,83/05/11,8305160017

8305160021 Forwards response to draft SER Open Item 294 concerning refueling water storage tank (RWST) Two RWST vent lines are protected from freezing by redundant ambient sensing heat tracing on each vent line
MCDUFFIE,M A Carolina Power & Light Co 83/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 2pp 18452 347.
24X Fiche 50-400,83/05/11,8305160021

8305160109 Advises that draft SER Open Items 48 & 74 closed per Generic Ltr 82-14 No anticipatory reactor trip mod proposed
MCDUFFIE,M A Carolina Power & Light Co 83/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18444 029 24X
Fiche 50-400,83/05/11,8305160109

8305180400 Forwards response to draft SER Open Item 191 re closing of cooling water surge tank vent valve upon radiation alarm annunciation Vent valve automatically closes upon receipt of signal from cooling water monitor
MCDUFFIE,M A Carolina Power & Light Co 83/05/16 DENTON,H R.
Office of Nuclear Reactor Regulation, Director 2pp 18486 012
24X Fiche 50-400,83/05/16,8305180400

8305200442 Advises that draft SER Open Item 128 closed per 830329 telcon Description of new fuel pool antisiphon svcs will be provided in response to Open Item 130
MCDUFFIE,M A Carolina Power & Light Co. 83/05/16 DENTON,H R.
Office of Nuclear Reactor Regulation, Director 1p 18517 123 24X
Fiche 50-400,83/05/16,8305200442

8305200329 Forwards responses to Procedures & Sys Review Branch draft SER on Open Items 200,205 & 206 re proposed method for measuring process-to-sensor response time
MCDUFFIE,M A Carolina Power & Light Co 83/05/18 DENTON,H.R
Office of Nuclear Reactor Regulation, Director 9pp 18517 046.
24X Fiche 50-400,83/05/18,8305200329

8305200384 Forwards response to draft SER Open Items 32 & 33 re irradiation-strengthened Zircaloy yield strengths & predicted cladding collapse time exceeding lifetime of fuel, respectively
MCDUFFIE,M A Carolina Power & Light Co 83/05/18 DENTON,H,R
Office of Nuclear Reactor Regulation, Director 3pp 18518 160
24X Fiche 50-400,83/05/18,8305200384

8305250494 Documents 830421 telcon re draft SER Open Items 12,15 & 16 concerning environ & hydrologic engineering;per Generic Ltr 82-14 Items considered closed as result of info submitted in 821104 ltr
MCDUFFIE,M A Carolina Power & Light Co 83/05/22 DENTON,H.R.
Office of Nuclear Reactor Regulation, Director 1p. 18583 354 24X
Fiche.50-400,83/05/22,8305250494

8305270023 Forwards responses to draft Chemical Engineering Branch SER Open Items 145 & 148 re TMI Item II.B 3, "Post-Accident Sampling Sys" & operator training requirements for post-accident sampling sys,respectively.
MUDUFFIE,M A Carolina Power & Light Co. 83/05/23 DENTON,H.R.
Office of Nuclear Reactor Regulation, Director 3pp. 18633 349.
24X Fiche 50-400,83/05/23,8305270023.

8305260234 Informs that draft Radiological Assessment Branch SER Open Item 168 closed per 830510 telcon on FSAR Question 471 21. Responses to other open items in draft SER expected shortly
MCDUFFIE,M A Carolina Power & Light Co 83/05/24 DENTON,H.R.
Office of Nuclear Reactor Regulation, Director 1p 18599 339 24X
Fiche:50-400,83/05/24,8305260234.

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing. 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations
83/05/13 PALLADINO,N J. Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

Q Adjudicatory correspondence

8305040479 Requests extension by 1-wk of deadline re briefs on proposed security plan experts Time needed due to large number of depositions & late scheduling of depositions Related correspondence
CARROW,H Carolina Power & Light Co 83/04/28 KELLEY,J L.,
BRIGHT,G O , CARPENTER,J H Atomic Safety and Licensing Board Panel.
2pp 18322 163 24X Fiche 50-400,83/04/28,8305040479

--8305040485 Answers to general interrogatories & interrogatories on Contentions 22A,22B,75,80,83,84 & 132,first set Related correspondence.
CARROW,H Carolina Power & Light Co 83/04/28 EDDLEMAN,W
Eddleman, W. 63pp 18322 165 24X Fiche 50-400,83/04/28,
8305040479

--8305040492 Response to request for production of documents Certificate of Svc encl
CARROW,H Carolina Power & Light Co 83/04/28 EDDLEMAN,W
Eddleman, W 4pp 18322 228 24X Fiche 50-400,83/04/28,
8305040479

--8305040498 Response to first request for admission re Eddleman Contention 22-B Certificate of Svc encl
CARROW,H Carolina Power & Light Co 83/04/28 Eddleman, W
4pp. 18322 232 24X Fiche 50-400,83/04/28,8305040479

8305060471 Forwards LI Loflin affidavit to be included in util 830428 answers to W Eddleman first set of interrogatories on Contentions 22A,22B,75,80,83,84 & 132 Svc list encl.
CARROW,H Carolina Power & Light Co 83/05/02 KELLEY,J L.,
BRIGHT,G O , CARPENTER,J H Atomic Safety and Licensing Board Panel.
4pp. 18351 175 24X Fiche 50-400,83/05/02,8305060471.

8305060485 Contentions based on util site emergency plan Certificate of Svc encl
EDDLEMAN,W Eddleman, W 83/05/02 Atomic Safety and Licensing Board Panel 4pp 18348 135 24X Fiche:50-400,83/05/02,8305060485.

8305060532 Answer to NRC 830420 motion to compel Conservation Council of North Carolina to respond to discovery Council is willing to negotiate Council unable to answer all NRC discovery requests W/Certificate of Svc Related correspondence
RUNKLE,J Conservation Council of North Carolina RUNKLE,J
Runkle, J D 83/05/02. 10pp 18347 293 24X
Fiche 50-400,83/05/02,8305060532

8305040412 Memorandum & order confirming withdrawal of Citizens Against Nuclear Power as formal party
KELLEY,J.L Atomic Safety and Licensing Board Panel 83/05/03
Citizens Against Nuclear Power 1p 18319.358 24X
Fiche.50-400,83/05/03,8305040412.

--8305040421 Advises of Citizens Against Nuclear Power withdrawal as formal party
NEWMAN,P T , NEWMAN,S.E Citizens Against Nuclear Power.
83/04/28. KELLEY,J L Atomic Safety and Licensing Board Panel
1p 18319 359. 24X Fiche:50-400,83/05/03,8305040412

8305090475 Motion to compel applicant to respond to Conservation Council of North Carolina Interrogatories 4-1 through 4-5 & 4-14 (first set) re Contention 4 concerning cumulative effects of transshipments Certificate of Svc encl.
RUNKLE,J Conservation Council of North Carolina 83/05/03. 6pp.
18360:229 24X Fiche 50-400,83/05/03,8305090475.

8305110145 Affidavit of W Eddleman certifying negotations w/NRC re response to NRC first set of interrogatories.
EDDLEMAN,W Eddleman, W 83/05/06. 2pp. 18393.342 24X
Fiche:50-400,83/05/06,8305110145.

DOCKETED ITEMS

8305110222 Responds to NRC first set of interrogatories Related correspondence
EDDLEMAN,W Eddleman, W 83/05/06 Atomic Safety and Licensing Board Panel 19pp 18407 076 24X Fiche 50-400,83/05/06, 8305110222

8305110361 Response to applicant third set of first round interrogatories Certificate of Svc encl Related correspondence
EDDLEMAN,W Eddleman, W 83/05/06 Carolina Power & Light Co 12pp. 18406 287 24X Fiche 50-400,83/05/06,8305110361

8305110366 First set of interrogatories Reply requested before 830529 Related correspondence
EDDLEMAN,W Eddleman, W 83/05/06 Office of the Executive Legal Director 10pp 18406 265 24X Fiche 50-400,83/05/06,8305110366

8305120288 Submission of Contention 161 re DB-416 circuit breakers for safe shutdown defects & possible malfunction Documents from which basis derived unavailable until 830420 Certificate of Svc encl
EDDLEMAN,W Eddleman, W 83/05/07 Atomic Safety and Licensing Board Panel 2pp 18424 120 24X Fiche 50-400,83/05/07,8305120288

8305130075 Responds to R Wilson interrogatories Certificate of Svc & affidavit encl Related correspondence
CARROW,H Carolina Power & Light Co 83/05/10 Wilson, R 19pp 18436:279 24X Fiche 50-400,83/05/10,8305130075

8305130088 Response to R Wilson request for production of documents as contained in interrogatories to applicant Documents will be made available at mutually agreeable time Certificate of Svc encl Related correspondence
CARROW,H Carolina Power & Light Co 83/05/10 WILSON,R Wilson, R 4pp 18437 090 24X Fiche 50-400,83/05/10,8305130088

8305170497 Responses to first set of general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc encl.Related correspondence
BAXTER,T A Carolina Power & Light Co. BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/12 EDDLEMAN,W Eddleman, W 56pp 18467 295 24X Fiche 50-400,83/05/12,8305170497.

8305170450 Response to first set of requests for production of documents on Contentions 41 & 65
BAXTER,T.A Carolina Power & Light Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge. 83/05/13 EDDLEMAN,W Eddleman, W. 3pp 18469:315 24X Fiche 50-400,83/05/13,8305170450.

8305170456 Response to 830318 interrogatories Related correspondence
WILSON,R. Wilson, R 83/05/13 Office of the Executive Legal Director 5pp 18467:285 24X Fiche 50-400,83/05/13,8305170456

8305170486 Clarification & supplementation of 830303 responses to 830131 interrogatories & request for production of documents Certificate of Svc encl Related correspondence
WILSON,R Wilson, R. 83/05/13 Carolina Power & Light Co 4pp 18470:069 24X Fiche 50-400,83/05/13,8305170486

8305170491 Second set of interrogatories Related correspondence.
WILSON,R Wilson, R 83/05/13 Carolina Power & Light Co 2pp. 18470,006. 24X Fiche 50-400,83/05/13,8305170491

8305170528 Suppl to Contentions 150 - 161 re five factors for late filing of contentions Balancing of factors not required since contentions based on previously unavailable info Certificate of Svc encl
EDDLEMAN,W Eddleman, W 83/05/14 Atomic Safety and Licensing Board Panel 3pp 18467 352 24X Fiche 50-400,83/05/14,8305170528

8305240500 Response to first set of interrogatories on Joint Contention II,Certificate of Svc encl.Related correspondence
PAYNE,M T. Kudzu Alliance. PAYNE,M.T Edelstein & Payne. 83/05/16. Carolina Power & Light Co 21pp 18575 208 24X Fiche 50-400,83/05/16,8305240500

8305240507 First set of interrogatories on Contentions III,IV & V. Certificate of Svc encl.Related correspondence
PAYNE,M T Kudzu Alliance PAYNE,M.T. Edelstein & Payne. 83/05/16. Carolina Power & Light Co. 15pp. 18571 244. 24X Fiche.50-400,83/05/16,8305240507.

8305190231 Brief on qualifications of witnesses proffered as expert in security planning;10CFR73.Parts of plans re expertise of BJ Tuggle,JR Maples,LW Stevens & ER Bleacher should be made available to experts W/Certificate of Svc.
BARTH,C.A Hearing Branch 1 83/05/17. 13pp 18500 187. 24X Fiche:50-400,83/05/17,8305190231

8305200630 Request for extension until 830603 to respond to W Eddl 830502 contentions on util site emergency plan Counsel has numerous conflicting obligations Certificate of Svc encl
O'NEILL,J H Carolina Power & Light Co O'NEILL,J H Shaw, Pittman, Potts & Trowbridge 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18520 153 24X Fiche 50-400,83/05, 8305200630

8305240446 Brief re qualifications of persons proffered by interver as experts to evaluate facility security plan All five intervenor witnesses fail to display sufficient expertise & should be withdrawn Certificate of Svc encl
FLYNN,S F , CARROW,H Carolina Power & Light Co 83/05/17 29p 18574 091 24X Fiche 50-400,83/05/17,8305240446

8305240551 Motion requesting J Mackie be withdrawn as proposed exps witness Applicant deprived of right to depose Mackie Benefit of having conducted cross-examination not afforded Certificate of Svc encl Related correspondence
FLYNN,S F , CARROW,H Carolina Power & Light Co 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18575 276 24X Fiche 50-400,83/05/17,8305240551

8305240550 Response opposing Conservation Council of North Carolina 830503 motion to compel applicant to respond to discovery Contention 4 does not encompass cumulative effects of fuel shipment W/Certification of Counsel & Certificate of Svc.
O'NEIL,J H Carolina Power & Light Co O'NEIL,J H Shaw, Pittm Potts & Trowbridge 83/05/18 Atomic Safety and Licensing Boa Panel 12pp 18575 284 24X Fiche 50-400,83/05/18,8305240550

K Utility Final Safety Analysis Report (FSAR) & amends

8305200676 Forwards Amend 6 to FSAR Amend revises positions re reg guides in Section 1 8 & QA organization & responsibility revs in Sections 13 1 & 17 2,per 830311 final rule
MCDUFFIE,M A Carolina Power & Light Co 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18519:119 24X Fiche 50-400,83/05/13,8305200676

--8305200679 Amend 6 to FSAR
* Carolina Power & Light Co 83/05/13 23pp 18519 121 24) Fiche 50-400,83/05/13,8305200676

8305240417 Forwards revised distribution list,reflecting changes in title;name & address of persons receiving copies of Amend 6 to FSAR,per request
ZIMMERMAN,S R Carolina Power & Light Co 83/05/20 EISENHUT,D Division of Licensing 4pp. 18571 032 24X Fiche 50-400,83/05/2 8305240417

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319. 24X Fiche 50-000,83/03/21,8212060385

8305270341 Forwards IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/31
UTLEY,E E Carolina Power & Light Co 1p 18641:358 24X Fiche 50-400,83/03/31,8305270341

--8305270348 IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 noncompliance noted Major areas inspected structural design activities & IE Bulletin 79-02 & 79-14 followup
LENAHAN,J J Region 2, Office of Director CONLON,T E. Divisi of Engineering & Radiological Safety Programs 83/03/30. 4pp 18641 359 24X Fiche 50-400,83/03/31,8305270341

8305270546 Forwards IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 No noncompliance noted
VERRELLI,D.M Division of Project & Resident Programs 83/04/05
UTLEY,E.E Carolina Power & Light Co 2pp 18645 276 24X Fiche:50-400,83/04/05,8305270546

--8305270551 IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 N noncompliance noted Major areas inspected structural concrete & steel
HARRIS,J R , CONLON,T.E. Region 2, Office of Director. 83/04/04 5pp 18645 278. 24X Fiche 50-400,83/04/05,8305270546.

8305270377 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-03 & 50-401/83-03
VERRELLI,D M Division of Project & Resident Programs. 83/04/14
UTLEY,E E Carolina Power & Light Co 1p 18642 187 24X Fiche 50-400,83/04/14,8305270377

--8305270383 Responds to NRC 830302 ltr re violations noted in IE Insp Rept 50-400/83-03 Corrective actions preservice insp Procedure NES-80A5035 revised to include surface magnetic particle insp for Weld 1-SH-RV-018
PARSONS,R M Carolina Power & Light Co 83/03/31 O'REILLY,J P Region 2, Office of Director 2pp 18642 188 24X Fiche 50-400,83/04/14,8305270377

--8305270391 Forwards IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/03/02 UTLEY,E E Carolina Power & Light Co 2pp 18642 190 24X Fiche 50-400,83/04/14,8305270377

--8305270397 Notice of violation from insp on 830124-27
* Region 2, Office of Director 83/03/02 1p 18642 192 24X Fiche 50-400,83/04/14,8305270377

--8305270406 IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 Noncompliance noted failure to establish adequate measures to control purchased svcs
KLEINSORGE,W P , BLAKE,J J Region 2, Office of Director 83/02/28 11pp 18642 193 24X Fiche 50-400,83/04/14,8305270377

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305270623 Forwards IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted.
VERRELLI,D M Division of Project & Resident Programs. 83/05/03
UTLEY,E E Carolina Power & Light Co 2pp 18645 269. 24X
Fiche 50-400,83/05/03,8305270623

--8305270632 IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted Major areas inspected geotechnical design activities,lakes,dams & canals,quality records & safety-related dam/dike operational insp program
LENAHAN,J J , CONLON,T E Region 2, Office of Director 83/04/29 4pp 18645:271. 24X Fiche 50-400,83/05/03,8305270623

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc. 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001. 24X Fiche.50-000,83/05/04,8303040031

8305270484 Forwards IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/05/04.
UTLEY,E E Carolina Power & Light Co 2pp 18644·024 24X
Fiche·50-400,83/05/04,8305270484

--8305270492 IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15. No noncompliance noted Major areas inspected containment steel, reactor vessel & safety-related structures
YORK,J W , LIU,W C Region 2, Office of Director. BLAKE,J J Division of Engineering & Radiological Safety Programs 83/05/03. 6pp 18644 026 24X Fiche 50-400,83/05/04,8305270484

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270609 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-06 & 50-401/83-06
VERRELLI,D M Division of Project & Resident Programs 83/05/10.
UTLEY,E E Carolina Power & Light Co 1p 18647 146 24X
Fiche 50-400,83/05/10,8305270609

--8305270615 Responds to NRC 830401 ltr re violations noted in IE Insp Rept 50-400/83-06 Corrective actions addl supports added to two svc water piping spool pieces to comply w/procedural requirements,WP-102,App A
PARSONS,R M Carolina Power & Light Co 83/04/26 O'REILLY,J.P. Region 2, Office of Director 2pp 18647 147 24X
Fiche 50-400,83/05/10,8305270609

--8305270620 Forwards IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/04/01
UTLEY,E E Carolina Power & Light Co 2pp 18647·149 24X
Fiche 50-400,83/05/10,8305270609

--8305270626 Notice of violation from insp on 830120-0220
* Region 2, Office of Director 83/04/01 2pp 18647.151 24X
Fiche 50-400,83/05/10,8305270609

--8305270631 IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220. Noncompliance noted·failure to support piping per procedural requirements
MAXWELL,G F Region 2, Office of Director BEMIS,P. Division of Project & Resident Programs 83/04/01 6pp 18647 153 24X
Fiche 50-400,83/05/10,8305270609

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc. 114pp 18524 003. 24X Fiche 50-000,83/05/11,8303040034

8305270271 Ack receipt of 830503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12
VERRELLI,D M Division of Project & Resident Programs. 83/05/16.
UTLEY,E E Carolina Power & Light Co 1p 18641.313 24X
Fiche 50-400,83/05/16,8305270271.

--8305270281 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12.Corrective actions· Procedure CGC-2 re nonconformance control revised on 830329 to provide guidelines for deficiency rept issuance
PARSONS,R M Carolina Power & Light Co 83/05/03. O'REILLY,J P Region 2, Office of Director 2pp. 18641 314 24X
Fiche·50-400,83/05/16,8305270271

--8305270292 Forwards IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 & notice of violation
VERRELLI,D M Division of Project & Resident Programs. 83/04/04.
UTLEY,E.E. Carolina Power & Light Co 2pp 18641:316 24X
Fiche 50-400,83/05/16,8305270271

--8305270301 Notice of violation from insp on 830220-0320
* Region 2, Office of Director. 83/04/04 1p 18641:318. 24X
Fiche 50-400,83/05/16,8305270271

--8305270308 IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320. Noncompliance noted·Deficiency Disposition Rept 1301 not evaluated during 14-day period
MAXWELL,G F Region 2, Office of Director BEMIS,P. Division of Project & Resident Programs 83/04/04. 7pp 18641·319 24X
Fiche.50-400,83/05/16,8305270271.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/19 Consolidated Edison Co. of New York, Inc. 114pp 18697.009 24X Fiche 50-000,83/05/19,8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8305020165 Forwards "Quarterly Seismic Monitoring Rept for Jan-Mar 1983 "
ZIMMERMAN, B R Carolina Power & Light Co 83/04/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18284 060 24X
Fiche 50-400, 83/04/27, 8305020165

--8305020172 "Seismic Monitoring Program Quarterly Data Rept Jan-Mar 1983 "
* Carolina Power & Light Co 83/04/27 1p 18284 061 24X
Fiche 50-400, 83/04/27, 8305020165

Reportable occurrences, LERs & related correspondence

8304280299 PNB-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified.
HALL, B L , MCGUIRE, D Region 2, Atlanta, Office of the Director
80/11/04 1p 18255 330 24X Fiche 50-400, 80/11/04, 8304280299

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P. Westinghouse Electric Corp 83/04/21 DEYOUNG, R C
Director's Office, Office of Inspection and Enforcement 5pp
18403, 095 24X Fiche, 50-000, 83/04/21, 8305110427

8305030601 Final deficiency rept re weld deficiencies in Class IE transfer panels Initially reported on 830401 Deficiency not reportable per 10CFR50 55(e)
CHIANGI, N J Carolina Power & Light Co 83/04/25 O'REILLY, J P
Region 2, Office of Director 1p 18306 088 24X
Fiche, 50-400, 83/04/25, 8305030601.

8305050124 Final deficiency & Part 21 repts re pressure boundary matl supplied by Tube Line Corp failing to meet Tech Specs, Item 123 Initially reported on 830330 Items returned to vendor. New fittings purchased
PARSONS, R M Carolina Power & Light Co 83/04/28 O'REILLY, J P
Region 2, Office of Director 4pp 18341, 343 24X
Fiche 50-400, 83/04/28, 8305050124

8305050185 Interim deficiency & Part 21 repts re base metal defect in spool piece supplied by Southwest Fabricating & Welding Co Initially reported on 830126 Vendor directed to show preventive measures Final rept by 830801
PARSONS, R M. Carolina Power & Light Co 83/04/29 O'REILLY, J P
Region 2, Office of Director 4pp 18342 240. 24X
Fiche, 50-400, 83/04/29, 8305050185

8305050259 Final deficiency & Part 21 repts re 480-volt switchgear design defect in secondary disconnects Initially reported on 821102. Brown-Boveri completed change-out of all old style stationary secondary disconnects
PARSONS, R M Carolina Power & Light Co 83/04/29 O'REILLY, J P
Region 2, Office of Director 4pp 18338 016 24X
Fiche 50-400, 83/04/29, 8305050259

8305130027 Part 21 & final deficiency repts (Item 106) re incorrect design of 480-volt switchgear on secondary disconnects Disconnects installed in breaker cradle will be replaced
PARSONS, R. M. Carolina Power & Light Co 83/04/29. O'REILLY, J P
Region 2, Office of Director 4pp 18437 125 24X
Fiche: 50-400, 83/04/29, 8305130027

05110252 Interim deficiency rept re conduit installed in structural concrete not in accordance w/ACI-318 Initially reported on 830401. Evaluation determined item not reportable per 10CFR50. 55(e).
CHIANGI, N. J Carolina Power & Light Co 83/05/03 O'REILLY, J. P
Region 2, Office of Director 1p. 18406 338 24X
Fiche: 50-400, 83/05/03, 8305110252

05130080 Deficiency rept re Class IE motor control ctrs from ITT Gould containing weld defects Initially reported on 830408. Vendor evaluation to be completed by Jul 1983. Extension until 830713 requested. Also reported per Part 21
PARSONS, R. M. Carolina Power & Light Co. 83/05/06 O'REILLY, J. P
Region 2, Office of Director. 1p. 18436 264. 24X
Fiche: 50-400, 83/05/06, 8305130080.

8305130216 Interim rept re deficient welds on emergency svc water self-cleaning strainers Initially reported on 830408 Evaluation of pressure boundary welds not expected to be completed until June 1983 Next rept will be submitted by 830617
PARSONS, R M Carolina Power & Light Co 83/05/06 O'REILLY, J P
Region 2, Office of Director 1p 18439 329 24X
Fiche 50-400, 83/05/06, 8305130216

8305130113 Part 21 rept re low natural frequency of counterbalance assembly, resulting in unacceptable stresses on backdraft damper counterbalance arm Seismic qualification criteria not fully met Investigation & testing underway
HILL, T D Ruskin Manufacturing Co 83/05/10 Director's Office, Office of Inspection and Enforcement 7pp 18438 001 24X
Fiche 50-400, 83/05/10, 8305130113

8305230442 Final deficiency rept, Item 67, re omission of protective coating behind pad attachment inside containment dome liner Initially reported on 811228 Work on weepholes completed using Keeler & Long 6548-S epoxy surfacer
PARSONS, R M Carolina Power & Light Co 83/05/13 O'REILLY, J. P
Region 2, Office of Director 4pp 18538 196 24X
Fiche 50-400, 83/05/13, 8305230442

T Hearing transcripts on non-antitrust matters

8305240077 Forwards transcript of Tuggle, Maples, Mackie, Bleacher & Stevens depositions as experts of W Eddleman on security, per 830520 telcon W/o encl
BARTH, C A Hearing Branch 1 83/05/20 EDDLEMAN, W Eddleman, W.
1p 18549 094 24X Fiche 50-400, 83/05/20, 8305240077

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305020506 Forwards request for addl info re personnel training to aid in review performed by Licensee Qualifications Branch.
KNIGHTON, G W Licensing Branch 3 83/04/11. UTLEY, E E Carolina Power & Light Co 4pp 18284 325 24X Fiche 50-400, 83/04/11, 8305020506

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11.
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305170577 Forwards request for design documents to continue NRC review
KNIGHTON, G W Licensing Branch 3 83/04/21 UTLEY, E E Carolina Power & Light Co. 3pp 18496 117 24X Fiche 50-400, 83/04/21, 8305170577

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EIBENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305120467 Forwards "Conformance W/Title 10 of CFR Parts 20, 50 & 100," per 811125 request & 820630 schedule Requirements of applicable regulations met Addl verification provided by independent NRC review
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 13pp 18431 058
24X Fiche 50-400, 83/05/09, 8305120467.

8305170282 Forwards changes to corporate QA program, currently provided in Section 1 B of PSAR
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18465 329 24X
Fiche 50-400, 83/05/09, 8305170282

--8305170285 Changes to Section 1 B (QA program) of PSAR
* Carolina Power & Light Co 83/05/09 14pp 18465 330 24X
Fiche 50-400, 83/05/09, 8305170282

D NRC Draft/Final Environmental Statements, suppls & correspondence

8305170149 DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1 AND 2. Docket Nos STN 50-400 And STN 50-401 (Carolina Power And Light Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0972.
83/04/30 220pp 18477 216 24X Fiche 50-400, 83/04/30, 8305170149.

8305200122 Forwards DES & FR notice W/o DES
KNIGHTON, G W Licensing Branch 3 83/05/12 UTLEY, E E Carolina Power & Light Co 2pp 18528 346 24X Fiche 50-400, 83/05/12, 8305200122

--8305200125 Notice of availability of DES
KNIGHTON, G W Licensing Branch 3 83/05/12 2pp 18528 348 24X Fiche 50-400, 83/05/12, 8305200122

8305200197 Forwards draft EIS & FR notice W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 Butzel & Kass
EBERT, P Affiliation Unknown 3pp 18576 151 24X
Fiche 50-400, 83/05/12, 8305200197

8305200205 Forwards, for comments, DES & notice of availability W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 WILSON, K
Environmental Protection Agency 2pp 18540 215 24X
Fiche. 50-400, 83/05/12, 8305200205

8305200209 Forwards, for review & comment, DES Comments due within 45 days after FR publication W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 WOOD, J M Commerce, Dept of, Natl Oceanographic & Atmospheric Administration 4pp 18540:211 24X Fiche 50-400, 83/05/12, 8305200209

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020124 Forwards responses to draft SER Open Items 8 & 9 for Meteorological & Effluent Treatment Branch Wind loads for winds faster than 117 mph considered in svc load combinations for containment design (FSAR Table 3 8 1-2)
MCDUFFIE, M. A Carolina Power & Light Co. 83/04/27. DENTON, H R
Office of Nuclear Reactor Regulation, Director 4pp. 18278 231.
24X Fiche 50-400, 83/04/27, 8305020124

8305230296 Forwards GA Branch & Matls Engineering Branch requests for addl info not addressed in Feb 1983 draft SER Info requested by 830701
KNIGHTON, G W Licensing Branch 3 83/05/03 UTLEY, E. E. Carolina Power & Light Co 7pp 18543·292 24X Fiche 50-400, 83/05/03, 8305230296.

8305060555 Forwards responses to draft SER Open Items 34, 35, 40, 42 & 44
MCDUFFIE, M. A Carolina Power & Light Co 83/05/04 DENTON, H R
Office of Nuclear Reactor Regulation, Director 9pp 18348·293
24X Fiche 50-400, 83/05/04, 8305060555.

8305110248 Informs that draft SER Open Item 67 re design of normal containment purge sys closed Sys adequate Issue of time sys allowed to operate to be addressed during Tech Spec preparation
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director. 1p 18406, 339 24X
Fiche 50-400, 83/05/09, 8305110248

8305110294 Confirms 830428 telcon closing out draft SER Open Items 298 & 299 per Generic Ltr 82-14 Responses to other open items will be submitted shortly
MCDUFFIE, M A Carolina Power & Light Co 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18393 307 24X
Fiche 50-400, 83/05/09, 8305110294.

8305160017 Forwards response to draft SER Open Item 59 re containment sys Reactor cavity subcompartment analysis conservative
MCDUFFIE, M A. Carolina Power & Light Co 83/05/11. DENTON, H R
Office of Nuclear Reactor Regulation, Director. 2pp. 18453:163
24X Fiche·50-400, 83/05/11, 8305160017.

8305160021 Forwards response to draft SER Open Item 274 concerning refueling water storage tank (RWST). Two RWST vent lines are protected from freezing by redundant ambient sensing heat tracing on each vent line
MCDUFFIE, M A Carolina Power & Light Co. 83/05/11. DENTON, H. R
Office of Nuclear Reactor Regulation, Director 2pp. 18432, 347.
24X Fiche: 50-400, 83/05/11, 8305160021

8305160109 Advises that draft SER Open Items 48 & 74 closed per Generic Ltr 82-14. No anticipatory reactor trip mod proposed
MCDUFFIE, M A Carolina Power & Light Co. 83/05/11. DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p. 18444:029. 24X
Fiche·50-400, 83/05/11, 8305160109

8305180400 Forwards response to draft SER Open Item 191 re closing of cooling water surge tank vent valve upon radiation alarm annunciation Vent valve automatically closes upon receipt of signal from cooling water monitor.
MCDUFFIE, M A. Carolina Power & Light Co. 83/05/16. DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp. 18486, 012.
24X Fiche. 50-400, 83/05/16, 8305180400

8305200442 Advises that draft SER Open Item 128 closed per 830329 telcon Description of new fuel pool antisiphon svcs will be provided in response to Open Item 130
MCDUFFIE, M A Carolina Power & Light Co 83/05/16 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18517, 123 24X
Fiche 50-400, 83/05/16, 8305200442

8305200329 Forwards responses to Procedures & Sys Review Branch draft SER on Open Items 200, 205 & 206 re proposed method for measuring process-to-sensor response time
MCDUFFIE, M A Carolina Power & Light Co 83/05/18 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 9pp 18517, 046
24X Fiche 50-400, 83/05/18, 8305200329

8305200384 Forwards response to draft SER Open Items 32 & 33 re irradiation-strengthened Zircaloy yield strengths & predicted cladding collapse time exceeding lifetime of fuel, respectively
MCDUFFIE, M A Carolina Power & Light Co 83/05/18 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 3pp 18518 160
24X Fiche 50-400, 83/05/18, 8305200384

8305250494 Documents 830421 telcon re draft SER Open Items 12, 15 & 16 concerning environ & hydrologic engineering, per Generic Ltr 82-14 Items considered closed as result of info submitted in 821104 ltr.
MCDUFFIE, M A Carolina Power & Light Co 83/05/22. DENTON, H R.
Office of Nuclear Reactor Regulation, Director 1p. 18583·354. 24X
Fiche: 50-400, 83/05/22, 8305250494

8305270023 Forwards responses to draft Chemical Engineering Branch SER Open Items 145 & 148 re TMI Item II B 3, "Post-Accident Sampling Sys" & operator training requirements for post-accident sampling sys, respectively.
MUDUFFIE, M. A Carolina Power & Light Co 83/05/23 DENTON, H R.
Office of Nuclear Reactor Regulation, Director 3pp. 18633, 349.
24X Fiche 50-400, 83/05/23, 8305270023

8305260234 Informs that draft Radiological Assessment Branch SER Open Item 168 closed per 830510 telcon on FSAR Question 471 21. Responses to other open items in draft SER expected shortly.
MCDUFFIE, M. A Carolina Power & Light Co 83/05/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p. 18599 339. 24X
Fiche 50-400, 83/05/24, 8305260234

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X
Fiche·50-000, 83/05/11, 8305110034

Q. Adjudicatory correspondence

8305040479 Requests extension by 1-wk of deadline re briefs on proposed security plan experts Time needed due to large number of depositions & late scheduling of depositions Related correspondence
CARROW, H Carolina Power & Light Co 83/04/29 KELLEY, J. L.,
BRIGHT, G O., CARPENTER, J. H Atomic Safety and Licensing Board Panel.
2pp 18322·163 24X Fiche. 50-400, 83/04/28, 8305040479.

--8305040485 Answers to general interrogatories & interrogatories on Contentions 22A, 22B, 75, 80, 83, 84 & 132, first set Related correspondence.
CARROW, H Carolina Power & Light Co 83/04/28. EDDLEMAN, W.
Eddleman, W 63pp 18322·165 24X Fiche. 50-400, 83/04/28,
8305040479

--8305040492 Response to request for production of documents. Certificate of Svc encl.
CARROW, H. Carolina Power & Light Co 83/04/28. EDDLEMAN, W
Eddleman, W 4pp 18322.228 24X Fiche·50-400, 83/04/28,
8305040479.

--8305040498 Response to first request for admission re Eddleman Contention 22-B Certificate of Svc encl.
CARROW, H Carolina Power & Light Co 83/04/28. Eddleman, W.
4pp 18322·232. 24X Fiche. 50-400, 83/04/28, 8305040479.

8305060471 Forwards LI Loflin affidavit to be included in util 830428 answers to W Eddleman first set of interrogatories on Contentions 22A, 22B, 75, 80, 83, 84 & 132. Svc list encl
CARROW, H. Carolina Power & Light Co 83/05/02. KELLEY, J. L.,
BRIGHT, G. O., CARPENTER, J H Atomic Safety and Licensing Board Panel.
4pp. 18351, 175. 24X Fiche. 50-400, 83/05/02, 8305060471.

8305060485 Contentions based on util site emergency plan Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/05/02 Atomic Safety and Licensing Board Panel 4pp 18348 135 24X Fiche 50-400, 83/05/02, 8305060485

8305060532 Answer to NRC 830420 motion to compel Conservation Council of North Carolina to respond to discovery Council is willing to negotiate Council unable to answer all NRC discovery requests W/Certificate of Svc Related correspondence
RUNKLE, J Conservation Council of North Carolina. RUNKLE, J Runkle, J D 83/05/02 10pp 18347 293 24X
Fiche: 50-400, 83/05/02, 8305060532

8305040412 Memorandum & order confirming withdrawal of Citizens Against Nuclear Power as formal party
KELLEY, J L Atomic Safety and Licensing Board Panel 83/05/03 Citizens Against Nuclear Power 1p 18319:358 24X
Fiche 50-400, 83/05/03, 8305040412

--8305040421 Advises of Citizens Against Nuclear Power withdrawal as formal party
NEWMAN, P T , NEWMAN, S E Citizens Against Nuclear Power 83/04/28 KELLEY, J L Atomic Safety and Licensing Board Panel 1p 18319:359 24X Fiche 50-400, 83/05/03, 8305040412

8305090475 Motion to compel applicant to respond to Conservation Council of North Carolina Interrogatories 4-1 through 4-5 & 4-14 (first set) re Contention 4 concerning cumulative effects of transshipments Certificate of Svc encl
RUNKLE, J Conservation Council of North Carolina 83/05/03. 6pp 18360:229 24X Fiche 50-400, 83/05/03, 8305090475

8305110145 Affidavit of W Eddleman certifying negotations w/NRC re response to NRC first set of interrogatories
EDDLEMAN, W Eddleman, W 83/05/06 2pp 18393.342 24X
Fiche: 50-400, 83/05/06, 8305110145

8305110222 Responds to NRC first set of interrogatories Related correspondence
EDDLEMAN, W Eddleman, W 83/05/06 Atomic Safety and Licensing Board Panel 19pp. 18407 076 24X Fiche 50-400, 83/05/06, 8305110222

8305110361 Response to applicant third set of first round interrogatories Certificate of Svc encl Related correspondence
EDDLEMAN, W Eddleman, W 83/05/06. Carolina Power & Light Co 12pp 18406 287 24X Fiche 50-400, 83/05/06, 8305110361.

8305110366 First set of interrogatories. Reply requested before 830525 Related correspondence
EDDLEMAN, W Eddleman, W 83/05/06 Office of the Executive Legal Director 10pp 18406:265 24X Fiche: 50-400, 83/05/06, 8305110366

8305120288 Submission of Contention 161 re DS-416 circuit breakers for safe shutdown defects & possible malfunction. Documents from which basis derived unavailable until 830420 Certificate of Svc encl.
EDDLEMAN, W Eddleman, W 83/05/07 Atomic Safety and Licensing Board Panel. 2pp 18424 120 24X Fiche 50-400, 83/05/07, 8305120288

8305130075 Responds to R Wilson interrogatories Certificate of Svc & affidavit encl Related correspondence
CARROW, H Carolina Power & Light Co. 83/05/10. Wilson, R 19pp 18436:279 24X Fiche 50-400, 83/05/10, 8305130075

8305130088 Response to R Wilson request for production of documents as contained in interrogatories to applicant Documents will be made available at mutually agreeable time Certificate of Svc encl Related correspondence
CARROW, H Carolina Power & Light Co 83/05/10 WILSON, R Wilson, R. 4pp. 18437.090. 24X Fiche 50-400, 83/05/10, 8305130088

8305170497 Responses to first set of general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc encl Related correspondence
BAXTER, T. A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/12. EDDLEMAN, W. Eddleman, W 56pp 18467 295. 24X Fiche: 50-400, 83/05/12, 8305170497

8305170450 Response to first set of requests for production of documents on Contentions 41 & 65
BAXTER, T A. Carolina Power & Light Co. BAXTER, T A. Shaw, Pittman, Potts & Trowbridge 83/05/13. EDDLEMAN, W Eddleman, W. 3pp 18469:315 24X Fiche: 50-400, 83/05/13, 8305170450

8305170454 Response to 830318 interrogatories. Related correspondence.
WILSON, R. Wilson, R 83/05/13 Office of the Executive Legal Director 5pp 18467:285. 24X Fiche. 50-400, 83/05/13, 8305170454

8305170486 Clarification & supplementation of 830303 responses to 830131 interrogatories & request for production of documents Certificate of Svc encl Related correspondence
WILSON, R Wilson, R 83/05/13 Carolina Power & Light Co 4pp 18470 069 24X Fiche. 50-400, 83/05/13, 8305170486

8305170491 Second set of interrogatories Related correspondence
WILSON, R Wilson, R 83/05/13 Carolina Power & Light Co 2pp 18470 006 24X Fiche 50-400, 83/05/13, 8305170491

8305190209 Package of seven requests to make limited appearance statement at OL hearings
GAGE, J , HUBBARD, K S , GREENBAUM, R L Affiliation Unknown 83/05/13 NRC - No Detailed Affiliation Given 7pp 18502 188 24X Fiche 50-440, 83/05/13, 8305190209

8305170528 Suppl to Contentions 150 - 161 re five factors for late filing of contentions Balancing of factors not required since contentions based on previously unavailable info Certificate of Svc encl
EDDLEMAN, W Eddleman, W 83/05/14 Atomic Safety and Licensing Board Panel 3pp 18467 352 24X Fiche 50-400, 83/05/14, 8305170528

8305240500 Response to first set of interrogatories on Joint Contention II Certificate of Svc encl Related correspondence.
PAYNE, M T Kudzu Alliance PAYNE, M T. Edelstein & Payne 83/05/16 Carolina Power & Light Co. 21pp 18575 208 24X
Fiche 50-400, 83/05/16, 8305240500

8305240507 First set of interrogatories on Contentions III, IV & V Certificate of Svc encl. Related correspondence.
PAYNE, M T Kudzu Alliance PAYNE, M T Edelstein & Payne 83/05/16 Carolina Power & Light Co. 15pp 18571 244 24X
Fiche 50-400, 83/05/16, 8305240507

8305190231 Brief on qualifications of witnesses proffered as expert in security planning. 10CFR73 Parts of plans re expertise of BJ Tuggle, JR Maples, LW Stevens & ER Bleacher should be made available to experts W/Certificate of Svc
BARTH, C A Hearing Branch 1 83/05/17 13pp 18500 187 24X
Fiche 50-400, 83/05/17, 8305190231

8305200630 Request for extension until 830603 to respond to W Eddleman 830502 contentions on util site emergency plan Counsel has numerous conflicting obligations Certificate of Svc encl
O'NEILL, J H Carolina Power & Light Co. O'NEILL, J H Shaw, Pittman, Potts & Trowbridge. 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18520.153 24X Fiche 50-400, 83/05/17, 8305200630

8305240446 Brief re qualifications of persons proffered by intervenors as experts to evaluate facility security plan All five intervenor witnesses fail to display sufficient expertise & should be withdrawn Certificate of Svc encl
FLYNN, S F , CARROW, H Carolina Power & Light Co. 83/05/17 29pp 18574 091 24X Fiche 50-400, 83/05/17, 8305240446

8305240551 Motion requesting J Mackie be withdrawn as proposed expert witness. Applicant deprived of right to depose Mackie Benefit of having conducted cross-examination not afforded Certificate of Svc encl. Related correspondence
FLYNN, S F , CARROW, H Carolina Power & Light Co 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18575 276 24X
Fiche 50-400, 83/05/17, 8305240551.

8305240550 Response opposing Conservation Council of North Carolina 830503 motion to compel applicant to respond to discovery Contention 4 does not encompass cumulative effects of fuel shipment W/Certification of Counsel & Certificate of Svc
O'NEIL, J H Carolina Power & Light Co O'NEIL, J. H Shaw, Pittman, Potts & Trowbridge 83/05/18 Atomic Safety and Licensing Board Panel 12pp 18575 284 24X Fiche 50-400, 83/05/18, 8305240550

K Utility Final Safety Analysis Report (FSAR) & amends

8305200676 Forwards Amend 6 to FSAR. Amend revises positions re reg guides in Section 1, 8 & QA organization & responsibility revs in Sections 13, 1 & 17 2, per 830311 final rule
MCDUFFIE, M A. Carolina Power & Light Co 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18519:119 24X Fiche 50-400, 83/05/13, 8305200676

--8305200679 Amend 6 to FSAR
* Carolina Power & Light Co 83/05/13 23pp 18519 121 24X
Fiche 50-400, 83/05/13, 8305200676

8305240417 Forwards revised distribution list,reflecting changes in title,name & address of persons receiving copies of Amend 6 to FSAR,per request
ZIMMERMAN,S R Carolina Power & Light Co 83/05/20 EISENHUT,D G Division of Licensing 4pp 18571 052 24X Fiche 50-400,83/05/20, 8305240417

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308-319 24X Fiche 50-000,83/03/21,8212060385

8305270341 Forwards IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/31
UTLEY,E E Carolina Power & Light Co 1p 18641 358 24X
Fiche 50-400,83/03/31,8305270341

--8305270348 IE Insp Repts 50-400/83-11 & 50-401/83-11 on 830308-11 No noncompliance noted Major areas inspected structural design activities & IE Bulletin 79-02 & 79-14 followup
LENAHAN,J J Region 2, Office of Director CONLON,T E Division of Engineering & Radiological Safety Programs 83/03/30 4pp 18641 359 24X Fiche 50-400,83/03/31,8305270341

8305270546 Forwards IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/05
UTLEY,E E Carolina Power & Light Co 2pp 18643 276 24X
Fiche 50-400,83/04/05,8305270546

--8305270551 IE Insp Repts 50-400/83-09 & 50-401/83-09 on 830314-18 No noncompliance noted Major areas inspected structural concrete & steel
HARRIS,J R , CONLON,T E Region 2, Office of Director 83/04/04 5pp 18643 278 24X Fiche 50-400,83/04/05,8305270546

8305270377 Ack receipt of 830331 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-03 & 50-401/83-03
VERRELLI,D M Division of Project & Resident Programs 83/04/14
UTLEY,E E Carolina Power & Light Co 1p 18642 187 24X
Fiche 50-400,83/04/14,8305270377

--8305270391 Forwards IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/03/02
UTLEY,E E Carolina Power & Light Co 2pp 18642 190 24X
Fiche 50-400,83/04/14,8305270377

--8305270406 IE Insp Repts 50-400/83-03 & 50-401/83-03 on 830124-27 Noncompliance noted failure to establish adequate measures to control purchased svcs
KLEINSORGE,W P., BLAKE,J J Region 2, Office of Director 83/02/28 11pp. 18642 193 24X Fiche 50-400,83/04/14,8305270377

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 124pp. 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp. 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp. 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 115pp. 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.

8305270623 Forwards IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs. 83/05/03
UTLEY,E E Carolina Power & Light Co 2pp 18645 269 24X
Fiche 50-400,83/05/03,8305270623

--8305270632 IE Insp Repts 50-400/83-14 & 50-401/83-14 on 830413-15 No noncompliance noted Major areas inspected geotechnical design activities,lakes,dams & canals,quality records & safety-related dam/dike operational insp program
LENAHAN,J J , CONLON,T E Region 2, Office of Director. 83/04/29. 4pp 18645 271 24X Fiche 50-400,83/05/03,8305270623

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8305270484 Forwards IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/05/04
UTLEY,E E Carolina Power & Light Co 2pp 18644 024 24X
Fiche 50-400,83/05/04,8305270484

--8305270492 IE Insp Repts 50-400/83-13 & 50-401/83-13 on 830411-15 No noncompliance noted Major areas inspected containment steel, reactor vessel & safety-related structures
YORK,J W , LIU,W C Region 2, Office of Director. BLAKE,J J Division of Engineering & Radiological Safety Programs 83/05/03 6pp 18644 026 24X Fiche 50-400,83/05/04,8305270484

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270609 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-06 & 50-401/83-06
VERRELLI,D M Division of Project & Resident Programs 83/05/10
UTLEY,E E Carolina Power & Light Co. 1p 18647 146 24X
Fiche 50-400,83/05/10,8305270609

--8305270620 Forwards IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/04/01
UTLEY,E E Carolina Power & Light Co 2pp 18647 149 24X
Fiche 50-400,83/05/10,8305270609

--8305270631 IE Insp Repts 50-400/83-06 & 50-401/83-06 on 830120-0220 Noncompliance noted failure to support piping per procedural requirements
MAXWELL,G F Region 2, Office of Director BEMIS,P. Division of Project & Resident Programs 83/04/01. 6pp 18647 153 24X
Fiche 50-400,83/05/10,8305270609

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003. 24X Fiche 50-000,83/05/11,8303040034

8305270271 Ack receipt of 830503 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12
VERRELLI,D M. Division of Project & Resident Programs. 83/05/16
UTLEY,E E Carolina Power & Light Co 1p 18641 313 24X
Fiche 50-400,83/05/16,8305270271

--8305270281 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-400/83-12 & 50-401/83-12 Corrective actions Procedure CQC-2 re nonconformance control revised on 830329 to provide guidelines for deficiency rept issuance.
PARSONS,R M Carolina Power & Light Co 83/05/03 O'REILLY,J P Region 2, Office of Director 2pp. 18641 314 24X
Fiche 50-400,83/05/16,8305270271

--8305270292 Forwards IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/04/04
UTLEY, E E Carolina Power & Light Co 2pp 18641 316 24X
Fiche 50-400, 83/05/16, 8305270271

--8305270308 IE Insp Repts 50-400/83-12 & 50-401/83-12 on 830220-0320 Noncompliance noted Deficiency Disposition Rept 1301 not evaluated during 14-day period
MAXWELL, G F Region 2, Office of Director BEMIB, P Division of Project & Resident Programs 83/04/04 7pp 18641 319 24X
Fiche 50-400, 83/05/16, 8305270271

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8305020165 Forwards "Quarterly Seismic Monitoring Rept for Jan-Mar 1983 "
ZIMMERMAN, S R Carolina Power & Light Co 83/04/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18284 060 24X
Fiche 50-400, 83/04/27, 8305020165

--8305020172 "Seismic Monitoring Program Quarterly Data Rept Jan-Mar 1983 "
* Carolina Power & Light Co 83/04/27 1p 18284 061 24X
Fiche 50-400, 83/04/27, 8305020165

S Reportable occurrences, LERs & related correspondence

8304280299 PNS-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified
HALL, B L , MCQUIRE, D Region 2, Atlanta, Office of the Director 80/11/04 1p, 18255 330 24X Fiche 50-400, 80/11/04, 8304280299

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427

8305030601 Final deficiency rept re weld deficiencies in Class IE transfer panels Initially reported on 830401. Deficiency not reportable per 10CFR50 55(e)
CHIANGI, N J Carolina Power & Light Co 83/04/25 O'REILLY, J P Region 2, Office of Director 1p 18306 088 24X
Fiche 50-400, 83/04/25, 8305030601

8305110252 Interim deficiency rept re conduit installed in structural concrete not in accordance w/ACI-318 Initially reported on 830401. Evaluation determined item not reportable per 10CFR50 55(e)
CHIANGI, N. J Carolina Power & Light Co 83/05/03, O'REILLY, J. P Region 2, Office of Director 1p, 18406 338 24X
Fiche 50-400, 83/05/03, 8305110252

8305130080 Deficiency rept re Class IE motor control ctrs from ITT Gould containing weld defects Initially reported on 830408 Vendor evaluation to be completed by Jul 1983 Extension until 830713 requested Also reported per Part 21
PARSONS, R M Carolina Power & Light Co 83/05/06 O'REILLY, J P Region 2, Office of Director, 1p, 18436 264 24X
Fiche: 50-400, 83/05/06, 8305130080

8305130216 Interim rept re deficient welds on emergency svc water self-cleaning strainers. Initially reported on 830408 Evaluation of pressure boundary welds not expected to be completed until June 1983. Next rept will be submitted by 830617
PARSONS, R M Carolina Power & Light Co 83/05/06 O'REILLY, J. P Region 2, Office of Director, 1p 18439 329, 24X
Fiche: 50-400, 83/05/06, 8305130216

8305130113 Part 21 rept re low natural frequency of counterbalance assembly, resulting in unacceptable stresses on backdraft damper counterbalance arm Seismic qualification criteria not fully met Investigation & testing underway
HILL, T. D Ruskin Manufacturing Co 83/05/10, Director's Office, Office of Inspection and Enforcement, 7pp 18438 001 24X
Fiche 50-400, 83/05/10, 8305130113

T Hearing transcripts on non-antitrust matters

8305240077 Forwards transcript of Tuggle, Maples, Mackie, Bleacher & Stevens depositions as experts of W Eddleman on security, per 830520 telcon W/o encl
BARTH, C A Hearing Branch 1 83/05/20 EDDLEMAN, W Eddleman, W 1p 18549 094 24X Fiche 50-400, 83/05/20, 8305240077

DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 3

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

S Reportable occurrences, LERs & related correspondence

8304280299 PNS-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified
HALL, B L Region 2, Atlanta, Office of the Director 80/11/04 1p 24X Fiche 50-400, 80/11/04, 8304280299

DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4

S Reportable occurrences, LERs & related correspondence

8304280299 PNS-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified
HALL, B L Region 2, Atlanta, Office of the Director 80/11/04 1p 24X Fiche 50-400, 80/11/04, 8304280299

DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR

C Utility Environmental Report (ER), amends & correspondence

8305190349 Application for renewal of License R-126 including financial info, revised Tech Specs, environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail
BROPHY, J J Utah, Univ of 83/05/12 Office of Nuclear Reactor Regulation, Director 20pp 18500 321 24X Fiche 50-407, 83/05/12, 8305190349

--8305190369 Environ rept
* Utah, Univ of 83/03/07 4pp 18501 015 24X
Fiche 50-407, 83/05/12, 8305190349

I Financial information

8305190349 Application for renewal of License R-126 including financial info, revised Tech Specs, environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail
BROPHY, J J Utah, Univ of 83/05/12 Office of Nuclear Reactor Regulation, Director 20pp 18500 321 24X Fiche 50-407, 83/05/12, 8305190349

P Operating license stage documents & correspondence

8305060660 Advises that License R-126 for TRIGA reactor not considered expired, as renewal application dtd 830308 apparently lost in mails
EISENHUT, D G Division of Licensing 83/05/03 BROPHY, J J Utah, Univ of 1p 18357 356 24X Fiche 50-407, 83/05/03, 8305060660

8305190349 Application for renewal of License R-126 including financial info, revised Tech Specs, environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail
BROPHY, J J Utah, Univ. of 83/05/12 Office of Nuclear Reactor Regulation, Director, 20pp 18500 321, 24X Fiche. 50-407, 83/05/12, 8305190349

--8305190360 Proposed Tech Specs & bases for TRIGA reactor
* Utah, Univ of 83/05/12 37pp 18500 341 24X
Fiche 50-407, 83/05/12, 8305190349

--8305190369 Environ rept
* Utah, Univ of 83/03/07 4pp 18501 015 24X
Fiche 50-407, 83/05/12, 8305190349

--8305190380 Revised reactor operator requalification program
SANDQUIST,G M Utah, Univ of 83/01/31 4pp 18501 019 24X
Fiche 50-407,83/05/12,8305190349

V Operator Examinations

8305190349 Application for renewal of License R-126 including financial info,revised Tech Specs,environ data operator requalification program & revised emergency plan Application resubmission of 830308 application apparently lost in mail
BROPHY,J J Utah, Univ of 83/05/12 Office of Nuclear Reactor Regulation, Director 20pp 18500 321 24X Fiche.50-407,83/05/12, 8305190349

--8305190380 Revised reactor operator requalification program
SANDQUIST,G M Utah, Univ of 83/01/31 4pp 18501 019. 24X
Fiche 50-407,83/05/12,8305190349

DOCKET 50-409 LA CROSSE BOILING WATER REACTOR

F Security, medical, emergency & fire protection plans

8305110298 Forwards LACBWR onsite meteorological data from Mar 1982 - Feb 1983
WEISS,D Dairyland Power Cooperative 83/05/02 FAIRBENT,J.
Division of Systems Integration (post 811005) 159pp 18392 343
24X Fiche 50-409,83/05/02,8305110298

8305160050 Responds to 830428 telcon requesting written confirmation of 830419 verbal agreement to install free-standing metal barrier between HPSW/fire protection diesel driven pumps in cribhouse,to act as radiant shield
LINDER,F Dairyland Power Cooperative 83/05/05 CRUTCHFIELD,D
Operating Reactors Branch 5 2pp 18453 018 24X
Fiche 50-409,83/05/05,8305160050

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D.G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240327 Forwards response to unresolved item identified during 820920-24 insp Response withheld (ref 10CFR73 21)
LINDER,F Dairyland Power Cooperative 83/05/13 CRUTCHFIELD,D
Operating Reactors Branch 5 1p 18573 172 24X
Fiche 50-409,83/05/13,8305240327

8305170416 Notifies that onsite & offsite emergency preparedness adequate NUREG-0737,Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E,10CFR50," complete.
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/16 LINDER,F
Dairyland Power Cooperative 3pp. 18469,250. 24X
Fiche.50-409,83/05/16,8305170416

8305190016 Responds to 821020 ltr re changes to physical security, safeguards contingency & guard training & qualification plans Certain proposed changes unacceptable Encl comments withheld (ref 10CFR73 21)
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/17 LINDER,F
Dairyland Power Cooperative 1p. 18501-358. 24X
Fiche.50-409,83/05/17,8305190016

8305310169 Forwards listed changes to EPP-2,Issue 9, "Organization & Operations During Emergencies " Ack of receipt requested.W/o encl.
LINDER,F Dairyland Power Cooperative 83/05/23 Region 3, Office of Director 1p. 18652-296 24X Fiche 50-409,83/05/23, 8305310169

Q Adjudicatory correspondence

8305100214 Discusses ASLB 830421 initial decision,deciding show cause proceeding re liquefaction potential at facility.SSE of 0 12 g adequate & conservative description.Dewatering sys need not be installed to preclude liquefaction
CUNNINGHAM,G H Office of the Executive Legal Director 83/04/28.
DENTON,H R Office of Nuclear Reactor Regulation, Director
DEYOUNG,R. Director's Office, Office of Inspection and Enforcement.
3pp 18374;185 24X Fiche 50-409,83/04/28,8305100214

8305200452 Forwards ASLP Initial Decision 80-445-01 SC re liquefaction potential at LACBWR Util neither required to submit detailed design proposal for,nor make operational,site dewatering sys.
CRUTCHFIELD,D Operating Reactors Branch 5, 83/05/19 LINDER,F.
Dairyland Power Cooperative. 3pp 18513.023. 24X
Fiche 50-409,83/05/19,8305200452

J Insurance & indemnity information

8305230029 Forwards Endorsements 50 & 51 to NELIA Policy NF-217
DEVINE,H F Dairyland Power Cooperative 83/05/16 DINITZ,I
Office of Nuclear Reactor Regulation, Director 2pp 18539:197.
24X Fiche 50-409,83/05/16,8305230029

P. Operating license stage documents & correspondence

8305040682 INTEGRATED PLANT SAFETY ASSESSMENT REPORT,SYSTEMATIC EVALUATION PROGRAM - LACROSSE BOILING WATER REACTOR Docket No. 50-409 (Dairyland Power Cooperative)
* Division of Licensing NUREG-0827 83/04/30 494pp 18334-142
24X Fiche 50-409,83/04/30,8305040682

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl
EISENHUT,D G Division of Licensing 83/05/02 Consolidated Edison Co of New York, Inc 50pp 18441 120 24X
Fiche 50-000,83/05/02,8305020455

8305100025 Forwards Class II fee for 820609 application to amend License DPR-45,in response to NRC 830118,0314 & 0412 ltrs Util maintains that fee not appropriate,as described in util 830315 ltr
LINDER,F Dairyland Power Cooperative 83/05/02 MILLER,W G
License Fee Management Branch. 1p 18377 115 24X
Fiche 50-409,83/05/02,8305100025.

8305120066 Confirms pumping time/fuel consumption of emergency svc water supply sys pumps using flooding bases similar to alternate core spray sys,per Dudley 830420 telcon Specific cases discussed
LINDER,F Dairyland Power Cooperative. 83/05/02 CRUTCHFIELD,D
Operating Reactors Branch 5 3pp 18431.024 24X
Fiche 50-409,83/05/02,8305120066

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT,D G Division of Licensing. 83/05/09 Consolidated Edison Co. of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305230398 Forwards response to 830330 request for clarification of items identified in SER on environ qualification of safety-related electrical equipment Request for extension to 1984 refueling outage schedule repeated per 830311 ltr
LINDER,F Dairyland Power Cooperative. 83/05/16 CRUTCHFIELD,D.
Operating Reactors Branch 5 4pp. 18538 228. 24X
Fiche 50-409,83/05/16,8305230398

8305260082 Advises that facility design acceptable TMI Action Item II K.3 28, "Qualification of Accumulators on Automatic Depressurization Sys Valves," resolved Safety evaluation encl.
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/24 LINDER,F
Dairyland Power Cooperative 5pp 18599.302 24X
Fiche 50-409,83/05/24,8305260082.

8305270002 Forwards SER accepting licensee actions in response to TMI Action Plan Item II K 3 25, "Effect of Loss of AC Power on Pump Seals " Seal injection will continue even if offsite power lost
CRUTCHFIELD,D Operating Reactors Branch 5 83/05/25 LINDER,F.
Dairyland Power Cooperative. 3pp. 18633 346 24X
Fiche 50-409,83/05/25,8305270002

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl.
TAYLOR,J M. Division of Safeguards & Inspection Programs (Post 830103) 83/03/21. Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc. 126pp 18435-155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22. Consolidated Edison Co. of New York, Inc 112pp. 18383-089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305130258 Informs that draft "Regulatory Improvement Program," submitted w/util 830404 ltr, responsive to NRC concerns Program implementation will be monitored Info re changes to program milestones requested
KEPPLER, J G Region 3, Office of Director 83/05/05 LINDER, F W
Dairyland Power Cooperative 1p 18439 220 24X
Fiche 50-409, 83/05/05, 8305130258

--8305130267 Forwards draft "Regulatory Improvement Program " Draft derived from meetings w/Region III & reviewed by M Brach, resident inspector
TAYLOR, J W Dairyland Power Cooperative 83/04/04 KEPPLER, J G
Region 3, Office of Director 1p 18439 222 24X
Fiche. 50-409, 83/05/05, 8305130258

--8305130271 Draft Procedure 032483JWT, "Regulatory Improvement Program " * Dairyland Power Cooperative. 83/04/04 15pp 18439 223 24X
Fiche 50-409, 83/05/05, 8305130258

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523, 248 24X Fiche 50-000, 83/05/06, 8303040033

8305130109 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-02
BHAFER, W. D Region 3, Office of Director 83/05/10. LINDER, F W.
Dairyland Power Cooperative 1p. 18437 360 24X
Fiche. 50-409, 83/05/10, 8305130109.

--8305130112 Responds to NRC 830330 ltr re violations noted in IE Insp Rept 50-409/83-02. Corrective actions: contract issued to Nuclear Energy Svcs, Inc for svcs including applicable 10CFR50, App B & Part 21 requirements
LINDER, F Dairyland Power Cooperative 83/04/19 STREETER, J. E
Region 3, Office of Director 2pp 18437: 361 24X
Fiche 50-409, 83/05/10, 8305130109

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11. Consolidated Edison Co. of New York, Inc. 114pp. 18524·003 24X Fiche. 50-000, 83/05/11, 8303040034

8305260256 Forwards IE Insp Rept 50-409/83-04 on 830411-15 No noncompliance noted
STREETER, J. F Region 3, Office of Director. 83/05/12 LINDER, F W
Dairyland Power Cooperative 2pp 18626: 111 24X
Fiche· 50-409, 83/05/12, 8305260256.

--8305260258 IE Insp Rept 50-409/83-04 on 830411-15 No noncompliance noted Major areas inspected licensed & unlicensed employee training, licensed operator requalification training & QA audits of training program
SUTPHIN, R N , HAWKINS, F C Region 3, Office of Director
83/05/12 7pp 18626 113 24X Fiche 50-409, 83/05/12, 8305260256

8305240327 Forwards response to unresolved item identified during 820920-24 insp Response withheld (ref 10CFR73 21)
LINDER, F Dairyland Power Cooperative 83/05/13 CRUTCHFIELD, D
Operating Reactors Branch 5 1p 18573 172 24X
Fiche 50-409, 83/05/13, 8305240327

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R Periodic operating reports & related correspondence

8305110298 Forwards LACBWR onsite meteorological data from Mar 1982 - Feb 1983
WEISS, D Dairyland Power Cooperative 83/05/02 FAIROBENT, J
Division of Systems Integration (post 811005) 189pp 18392 343
24X Fiche 50-409, 83/05/02, 8305110298

8305310154 Forwards annual environ radioactivity monitoring repts for 1982 W/o encl
MCDONNELL, L J Wisconsin, State of NRC-05-80-275 83/05/23
KEPPLER, J G Region 3, Office of Director 1p 18659 140 24X
Fiche 50-000, 83/05/23, 8305310154

S Reportable occurrences; LERs & related correspondence

8305020146 Forwards LER 83-001/03L-0 & updated LER 82-020/03X-1 Detailed event analysis encl
LINDER, F Dairyland Power Cooperative 83/04/21 KEPPLER, J G
Region 3, Office of Director 3pp 18278 194 24X
Fiche 50-409, 83/04/21, 8305020146

--8305020170 LER 83-001/03L-0 on 830325, following low reactor water level scram, 1B HPCS pump observed not running. Caused by backward installation of current transformer in HPCS pump breaker ground fault trip device
GOODMAN, L S Dairyland Power Cooperative 83/04/21 Region 3, Office of Director 1p 18278 197 24X Fiche 50-409, 83/04/21, 8305020146

--8305020182 Updated LER 82-020/03X-1 on 821119-20, on three occasions vacuum pump which maintains isokinetic flow rate to stack activity monitors tripped Caused by pump & motor overheating Motor thermal overload fuses upgraded
GOODMAN, L S Dairyland Power Cooperative 83/04/21 Region 3, Office of Director 1p 18278 198 24X Fiche 50-409, 83/04/21, 8305020146

T Hearing transcripts on non-antitrust matters

8305100164 Transcript of ACRS LACBWR SEP Subcommittee 830506 hearing in Washington, DC Pp 1-166 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/06
229pp 18370 265 24X Fiche 50-409, 83/05/06, 8305100164

DOCKET 50-410 NINE MILE POINT NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305090633 Forwards FR notices of receipt of OL application, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER, A Licensing Branch 2 83/05/02 RHODE, G K Niagara Mohawk Power Corp 4pp 18367 307 24X Fiche 50-410, 83/05/02, 8305090633

--8305090648 Notice of receipt of application for OL, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER, A Licensing Branch 2 83/05/02 7pp 18367 311 24X
Fiche. 50-410, 83/05/02, 8305090633

--8305090652 Notice of opportunity for public participation in proposed NRC licensing application by Niagara Mohawk Power Corp, et al, for Nine Mile Point Station, Unit 2
* NRC - No Detailed Affiliation Given 83/05/02 4pp
18367 318 24X Fiche 50-410, 83/05/02, 8305090633

8305110315 Application for Amend 2 to OL application (filed in PDR Category A), consisting of Amend 2 to FSAR (filed in PDR Category K) & Suppl 1 to environ rept - OL stage (filed in PDR Category C) Affidavit of Svc encl.
MANGAN, C V Niagara Mohawk Power Corp 83/05/05 EISENHUT, D G
Division of Licensing 6pp 18394 001 24X Fiche 50-410, 83/05/05, 8305110315

8305180054 Summary of 830428 meeting w/util, GE & AE in Bethesda, MD re licensing review of OL application & specific review issues
HAUGHEY, M F Licensing Branch 2 83/05/05 Licensing Branch 2
19pp 18499 330 24X Fiche 50-410, 83/05/05, 8305180054.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305230574 Forwards repts in response to FSAR & environ rept - OL stage acceptance review questions per NRC request for addl info to 830419 submittal re OL application List of repts submitted encl
MANGAN, C V Niagara Mohawk Power Corp 83/05/13 EISENHUT, D G
Division of Licensing 3pp 18600 001 24X Fiche 50-410, 83/05/13, 8305230574

--8305230582 Forwards addl info re FSAR & environ rept - OL stage per NRC 830329 request List of repts submitted encl
RHODE, G K Niagara Mohawk Power Corp 83/04/19 EISENHUT, D G
Division of Licensing 3pp 18600 004 24X Fiche 50-410, 83/05/13, 8305230574

--8305230585 "316(a) Demonstration Submission, NPDES Permit NY 0001015 "
* Niagara Mohawk Power Corp 83/05/13 224pp 18600 007 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6," interim rept
* Lawler, Matusky & Skelly Engineers LMSE-82/0091&191-058
82/04/30 82pp 18600 231 24X Fiche 50-410, 83/05/13, 8305230574

--8305230592 "316(a) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 217pp
18600 308 24X Fiche 50-410, 83/05/13, 8305230574

--8305230599 "316(b) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 325pp
18601 165 24X Fiche: 50-410, 83/05/13, 8305230574

--8305230603 "Fish Tag Rept Summary 1972-76 "
STORR, J F Storr, J F 76/12/31 93pp 18602 130 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies, Summary Plankton, Benthos, Fish, 1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 591pp
18602 225 24X Fiche 50-410, 83/05/13, 8305230574

--8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies, Fish Impingement, Water Quality, 1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 268pp
18604 096 24X Fiche 50-410, 83/05/13, 8305230574

--8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 1, Apps I-III (a-d) Methods & Matls, Statistical Procedures, Plankton, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 508pp,
18605 001 24X Fiche 50-410, 83/05/13, 8305230574

--8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 2, App III (m-p), Plankton, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 577pp
18606 149 24X Fiche 50-410, 83/05/13, 8305230574

--8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 3, Apps IV, V, VI Benthos, Fish, Fish Impingement, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 396pp,
18608: 006 24X Fiche: 50-410, 83/05/13, 8305230574.

--8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies, Part 4, App VII Water Quality, 1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 291pp
18610 015 24X Fiche 50-410, 83/05/13, 8305230574

--8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies, Chapters I-IV, 1974 "
* Lawler, Matusky & Skelly Engineers 75/12/31 333pp
18609 042 24X Fiche 50-410, 83/05/13, 8305230574

--8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies, (Chapters VII-X), 1974 "
* Lawler, Matusky & Skelly Engineers 75/12/31 280pp
18610 306 24X Fiche 50-410, 83/05/13, 8305230574

--8305230661 "Nine Mile Point Aquatic Ecology Studies, 1975, "
* Lawler, Matusky & Skelly Engineers LMSE-76/0081&191-033
76/05/31 497pp 18611 226 24X Fiche 50-410, 83/05/13,
8305230574

--8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies, 1976 "
* Lawler, Matusky & Skelly Engineers 77/05/31 489pp
18613 001 24X Fiche 50-410, 83/05/13, 8305230574

--8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies, App I-IX, 1976 "
* Lawler, Matusky & Skelly Engineers. 77/05/31 651pp
18614 130 24X Fiche 50-410, 83/05/13, 8305230574

--8305230680 "Nine Mile Point Aquatic Ecology Studies, 1977 "
* Texas Instruments, Inc 78/05/31 875pp 18616 061. 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230681 "316(a) Demonstration Submission, NPDES Permit 070 OX2 2 000632 NY (0003212) "
* Niagara Mohawk Power Corp 83/05/13 150pp 18618 216 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230684 "Intake Considerations, NPDES Permit 070 OX2 2 00632 NY (0003212) "
* Niagara Mohawk Power Corp 83/05/13 50pp 18619.006. 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230687 "316(a) Demonstration Submission NPDES Permit 070 OX2 2 000633 NY (0003221) "
* Niagara Mohawk Power Corp LMSE-75/0363&191/029, 83/05/13
152pp 18619 053 24X Fiche 50-410, 83/05/13, 8305230574

--8305230691 "Intake Considerations NPDES Permit 070 OX2 2 000633 NY (0003221) "
* Niagara Mohawk Power Corp 83/05/13 50pp 18619 205. 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230696 "316(A) Demonstration Submission NPDES Permit NY 0002186."
* Niagara Mohawk Power Corp 83/05/13 460pp 18619 249 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230699 "Intake Considerations NPDES Permit NY 0002186 "
* Niagara Mohawk Power Corp 83/05/13 149pp 18620 349 24X
Fiche 50-410, 83/05/13, 8305230574

--8305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 6 - Oswego Steam Station "
* Stone & Webster Engineering Corp 77/05/31. 52pp 18621 138
24X Fiche 50-410, 83/05/13, 8305230574

8305240498 Responds to 830419 Generic Ltr 83-18 requesting addl info re review of BWR Owners Group control room survey program Info addressed in 830414 ltr to NRC.
MANGAN, C V Niagara Mohawk Power Corp 83/05/18 EISENHUT, D.G.
Division of Licensing 1p 18572 068 24X Fiche 50-410, 83/05/18, 8305240498

C Utility Environmental Report (ER), amends & correspondence

8305090633 Forwards FR notices of receipt of OL application, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER, A Licensing Branch 2 83/05/02. RHODE, G K Niagara Mohawk Power Corp 4pp 18367 307 24X Fiche 50-410, 83/05/02, 8305090633

--8305090648 Notice of receipt of application for OL, notice of availability of environ rept, notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER, A. Licensing Branch 2 83/05/02 7pp 18367: 311. 24X
Fiche 50-410, 83/05/02, 8305090633

8305110315 Forwards Suppl 1 to environ rept - OL stage (filed in PDR Category C)
MANGAN,C V Niagara Mohawk Power Corp 83/05/05 EISENHUT,D G Division of Licensing 6pp 18394 001 24X Fiche 50-410,83/05/05, 8305110315

--8305110359 Suppl 1 to environ rept - OL stage
* Niagara Mohawk Power Corp 83/05/31 79pp 18394 007 24X Fiche 50-410,83/05/05,8305110315

8305230574 Forwards repts in response to FSAR & environ rept - OL stage acceptance review questions per NRC request for addl info to 830419 submittal re OL application List of repts submitted encl
MANGAN,C V Niagara Mohawk Power Corp 83/05/13 EISENHUT,D G Division of Licensing 3pp 18600 001 24X Fiche 50-410,83/05/13, 8305230574

--8305230585 "316(a) Demonstration Submission,NPDES Permit NY 0001015 "
* Niagara Mohawk Power Corp 83/05/13 224pp 18600 007 24X Fiche 50-410,83/05/13,8305230574

--8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6," interim rept
* Lawler,Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 82pp 18600 231 24X Fiche 50-410,83/05/13,8305230574

--8305230592 "316(a) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 217pp 18600 308 24X Fiche 50-410,83/05/13,8305230574

--8305230599 "316(b) Demonstration Submission Permit NY 0020109 "
* Power Authority of the State of New York 83/05/13 325pp 18601 165 24X Fiche 50-410,83/05/13,8305230574

--8305230603 "Fish Tag Rept Summary 1972-76 "
STORR,J F Storr, J F 76/12/31 95pp 18602 130 24X Fiche:50-410,83/05/13,8305230574

--8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies,Summary Plankton,Benthos,Fish,1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 591pp 18602 225 24X Fiche 50-410,83/05/13,8305230574

--8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies,Fish Impingement,Water Quality,1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 268pp 18604:096 24X Fiche 50-410,83/05/13,8305230574

--8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 1, Apps I-III (a-d) Methods & Matls,Statistical Procedures, Plankton,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 508pp 18605:001 24X Fiche 50-410,83/05/13,8305230574

--8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 2, App III (e-p) Plankton,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24X Fiche 50-410,83/05/13,8305230574

--8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 3, Apps IV,V,VI Benthos,Fish,Fish Impingement,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 396pp 18608 006 24X Fiche 50-410,83/05/13,8305230574

-8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 4, App VII,Water Quality,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 291pp 18610:015 24X Fiche 50-410,83/05/13,8305230574

--8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies,Chapters I-IV,1974 "
* Lawler,Matusky & Skelly Engineers 75/12/31, 333pp, 18609:042 24X Fiche 50-410,83/05/13,8305230574,

--8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies,(Chapters VII-X),1974 "
* Lawler,Matusky & Skelly Engineers, 75/12/31 280pp 18610:306 24X Fiche 50-410,83/05/13,8305230574

--8305230661 "Nine Mile Point Aquatic Ecology Studies,1975 "
* Lawler,Matusky & Skelly Engineers, LMSE-76/0081&191-033 76/05/31 497pp 18611 226 24X Fiche 50-410,83/05/13, 8305230574,

--8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies,1976 "
* Lawler,Matusky & Skelly Engineers, 77/05/31 489pp 18613 001 24X Fiche,50-410,83/05/13,8305230574

--8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies,App I-IX, 1976 "
* Lawler,Matusky & Skelly Engineers 77/05/31 651pp 18614 130 24X Fiche 50-410,83/05/13,8305230574

--8305230680 "Nine Mile Point Aquatic Ecology Studies,1977 "
* Texas Instruments, Inc 78/05/31 875pp 18616 061 24X Fiche 50-410,83/05/13,8305230574

--8305230681 "316(a) Demonstration Submission,NPDES Permit 070 OX2 2 000632 NY (0003212) "
* Niagara Mohawk Power Corp 83/05/13 150pp 18618 216 24X Fiche 50-410,83/05/13,8305230574

--8305230684 "Intake Considerations,NPDES Permit 070 OX2 2 00632 NY (0003212) "
* Niagara Mohawk Power Corp 83/05/13 50pp 18619 006 24X Fiche 50-410,83/05/13,8305230574

--8305230687 "316(a) Demonstration Submission NPDES Permit 070 OX2 2 000633 NY (0003221) "
* Niagara Mohawk Power Corp LMSE-75/0363&191/029 83/05/13 152pp 18619 053 24X Fiche 50-410,83/05/13,8305230574

--8305230691 "Intake Considerations NPDES Permit 070 OX2 2 000633 NY (0003221) "
* Niagara Mohawk Power Corp 83/05/13 50pp 18619 205 24X Fiche 50-410,83/05/13,8305230574

--8305230696 "316(A) Demonstration Submission NPDES Permit NY 0002186 "
* Niagara Mohawk Power Corp 83/05/13 460pp 18619 249 24X Fiche 50-410,83/05/13,8305230574

--8305230699 "Intake Considerations NPDES Permit NY 0002186 "
* Niagara Mohawk Power Corp 83/05/13 149pp 18620 349 24X Fiche 50-410,83/05/13,8305230574

--8305230701 "Studies to Alleviate Potential Fish Entrapment at Unit 6 - Oswego Steam Station "
* Stone & Webster Engineering Corp 77/05/31 52pp 18621 138 24X Fiche 50-410,83/05/13,8305230574

8305260086 Forwards Affidavit of Svc indicating that Amend 2 to FSAR & Suppl 1 to environ rept - OL stage,provided to appropriate parties delineated in 830329 ltr Distribution lists encl
MANGAN,C V Niagara Mohawk Power Corp 83/05/23 EISENHUT,D G Division of Licensing 5pp 18599 309 24X Fiche 50-410,83/05/23, 8305260086

D NRC Draft/Final Environmental Statements, suppls & correspondence

8305110296 Discusses draft EIS received on 830415 which indicated no known historic significant sites will be directly affected by plant operation Council must be afforded opportunity to comment prior to granting license or permit
KLIMA,D L Advisory Council on Historic Preservation 83/05/09 BYKOSKI,L Siting Analysis Branch 17pp 18393 256 24X Fiche 50-410,83/05/09,8305110296

F Security, medical, emergency & fire protection plans

8305030515 Forwards revised meteorological data tape for facility Physical specs of data tape unchanged from previous submittal Tape will be included in next FSAR amend W/o encl
MANGAN,C V Niagara Mohawk Power Corp 83/04/29 SCHWENCER,A Licensing Branch 2 1p 18300.339 24X Fiche 50-410,83/04/29, 8305030515

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

G. Adjudicatory correspondence

8305090633 Forwards FR notices of receipt of OL application,notice of availability of environ rept,notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER,A Licensing Branch 2 83/05/02 RHODE,G K Niagara Mohawk Power Corp 4pp 18367 307 24X Fiche.50-410,83/05/02, 8305090633,

--8305090648 Notice of receipt of application for OL,notice of availability of environ rept,notice of consideration of issuance of OL & notice of opportunity for hearing
SCHWENCER,A Licensing Branch 2 83/05/02 7pp 18367 311 24X Fiche 50-410,83/05/02,8305090633

K Utility Final Safety Analysis Report (FSAR) & amends

8304210238 Forwards Amend 1 to FSAR,consisting of SRP deviation statements,page changes & 1,470 oversize drawings
MANGAN,C V Niagara Mohawk Power Corp 83/04/13 EISENHUT,D G Division of Licensing 2pp 18090 272 24X Fiche 50-410,83/04/13, 8304210238

--8304210240 Amend 1 to FSAR W/1,216 oversize drawings & 254 oversize figures Aperture cards are available in PDR
* Niagara Mohawk Power Corp 83/04/30 387pp 18090,274 24X Fiche 50-410,83/04/13,8304210238

8305110315 Forwards Amend 2 to FSAR (filed in PDR Category K) W/21 oversize drawings Aperture cards are available in PDR
MANGAN,C V Niagara Mohawk Power Corp. 83/05/03 EISENHUT,D G Division of Licensing 6pp 18394 001 24X Fiche 50-410,83/05/05, 8305110315

--8305110372 Amend 2 to FSAR W/21 oversize drawings Aperture cards are available in PDR
* Niagara Mohawk Power Corp 83/05/31 136pp 18394 085 24X Fiche 50-410,83/05/05,8305110315

8305260086 Forwards Affidavit of Svc indicating that Amend 2 to FSAR & Suppl 1 to environ rept - OL stage,provided to appropriate parties delineated in 830329 ltr Distribution lists encl
MANGAN,C V Niagara Mohawk Power Corp. 83/05/23 EISENHUT,D G Division of Licensing 5pp 18599 309 24X Fiche 50-410,83/05/23, 8305260086

M Antitrust correspondence

8305130028 Forwards addl info requested on 830321 re antitrust review of OL application
MANGAN,C V Niagara Mohawk Power Corp. 83/05/09 REGAN,W H Site Analysis Branch 21pp 18437 104 24X Fiche 50-410,83/05/09, 8305130028

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305230529 Forwards expurgated statements not previously submitted w/IE Investigation Rept 50-410/82-076 re improper use of QC inspector trainees by S&W
STAROSTECKI,R Division of Project & Resident Programs. 83/03/24
RHODE,O K Niagara Mohawk Power Corp 26pp. 18537:029. 24X Fiche 50-410,83/03/24,8305230529

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co of New York, Inc 126pp. 18435:155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche:50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382:047 24X Fiche:50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282. 24X Fiche 50-000,83/05/04,8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441,001 24X Fiche 50-000,83/05/04,8303040031

8305160093 Responds to request for addl info re IE Bulletin 82-01,Rev 1,Suppl 1.Three welds inaccessible for reradiography currently under evaluation Two addl welds w/enhanced radiographs found satisfactory
MANNO,S F Niagara Mohawk Power Corp 83/05/04 STAROSTECKI,R Division of Project & Resident Programs 2pp 18452 013 24X Fiche:50-410,83/05/04,8305160093.

8305190331 Forwards IE Insp Rept 50-410/83-04 on 830314-0415.No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/04
RHODE,O.K Niagara Mohawk Power Corp 2pp 18500:305. 24X Fiche 50-410,83/05/04,8305190331

--8305190334 IE Insp Rept 50-410/83-04 on 830314-0415 No noncompliance noted Major areas inspected.safety-related piping,licensee surveillance,contractor audits,instrumentation tubing supports & structural steel
SCHULZ,R D , KISTER,H.B. Region 1, Office of Director. 83/05/02 11pp. 18500:307 24X Fiche:50-410,83/05/04,8305190331

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06. Consolidated Edison Co. of New York, Inc 115pp. 18523 248 24X Fiche.50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines." Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11. Consolidated Edison Co of New York, Inc 114pp 18524:003 24X Fiche.50-000,83/05/11,8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp. 18697.009 24X Fiche 50-000,83/05/19,8303040040.

8305270638 Ack receipt of 830426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/83-02
STAROSTECKI,R. Division of Project & Resident Programs 83/05/19
RHODE,O K Niagara Mohawk Power Corp 1p 18646:207. 24X Fiche:50-410,83/05/19,8305270638

--8305270645 Responds to NRC 830328 ltr re violations noted in IE Insp Rept 50-410/83-02 Corrective actions correct process planner was obtained before restarting work & foremen & superintendent retrained
MANNO,S.F Niagara Mohawk Power Corp. 83/04/26 STAROSTECKI,R Region 1, Office of Director 3pp 18646.208 24X Fiche 50-410,83/05/19,8305270638.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc 114pp. 18647:007 24X Fiche.50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305230574 Forwards repts in response to FSAR & environ rept - OL stage acceptance review questions per NRC request for addl info to 830419 submittal re OL application List of repts submitted encl.
MANGAN,C V Niagara Mohawk Power Corp 83/05/13 EISENHUT,D G Division of Licensing 3pp 18600 001 24X Fiche 50-410,83/05/13, 8305230574

--8305230587 "Evaluation of Angeled Screen Fish Divers Sys at Oswego Steam Station Unit 6," interim rept
* Lawler,Matusky & Skelly Engineers LMSE-82/0091&191-058 82/04/30 82pp 18600 231 24X Fiche 50-410,83/05/13,8305230574

--8305230603 "Fish Tag Rept Summary 1972-76 "
STORR,J F Storr, J F 76/12/31 95pp 18602 130 24X Fiche.50-410,83/05/13,8305230574

--8305230607 Vol I to "Nine Mile Point Aquatic Ecology Studies,Summary Plankton,Benthos,Fish;1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 591pp 18602.225 24X Fiche 50-410,83/05/13,8305230574

--8305230614 Vol II to "Nine Mile Point Aquatic Ecology Studies,Fish Impingement,Water Quality,1973 "
* Quirk, Lawler & Matusky Engineers 74/08/31 268pp 18604 096 24X Fiche.50-410,83/05/13,8305230574

--8305230622 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 1, Apps I-III (a-d),Methods & Matls,Statistical Procedures, Plankton,1973,"
* Quirk, Lawler & Matusky Engineers 83/05/13 508pp 18605:001 24X Fiche 50-410,83/05/13,8305230574

--8305230628 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 2, App III (e-p) Plankton,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 577pp 18606 149 24X Fiche 50-410,83/05/13,8305230574

--8305230637 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 3, Apps IV,V,VI Benthos,Fish,Fish Impingement,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 396pp 18608:006 24X Fiche 50-410,83/05/13,8305230574

--8305230644 Vol III to "Nine Mile Point Aquatic Ecology Studies,Part 4, App VII'Water Quality,1973 "
* Quirk, Lawler & Matusky Engineers 83/05/13 291pp 18610'015. 24X Fiche.50-410,83/05/13,8305230574

--8305230650 Vol I to "Nine Mile Point Aquatic Ecology Studies,Chapters I-IV,1974 "
* Lawler,Matusky & Skelly Engineers 75/12/31 333pp 18609.042. 24X Fiche'50-410,83/05/13,8305230574.

--8305230656 Vol II to "Nine Mile Point Aquatic Ecology Studies,(Chapters VII-X),1974 "
* Lawler,Matusky & Skelly Engineers 75/12/31 280pp 18610'306 24X Fiche'50-410,83/05/13,8305230574

--8305230661 "Nine Mile Point Aquatic Ecology Studies,1975,"
* Lawler,Matusky & Skelly Engineers LMSE-76/0081&191-033. 76/05/31. 497pp 18611.226 24X Fiche.50-410,83/05/13, 8305230574.

--8305230666 Vol I to "Nine Mile Point Aquatic Ecology Studies,1976 "
* Lawler,Matusky & Skelly Engineers 77/05/31 489pp 18613.001 24X Fiche:50-410,83/05/13,8305230574

--8305230678 Vol II to "Nine Mile Point Aquatic Ecology Studies,App I-IX, 1976,"
* Lawler,Matusky & Skelly Engineers. 77/05/31. 651pp. 18614:130. 24X Fiche:50-410,83/05/13,8305230574

--8305230680 "Nine Mile Point Aquatic Ecology Studies,1977 "
* Texas Instruments, Inc. 78/05/31. 875pp 18616.061 24X Fiche:50-410,83/05/13,8305230574

S. Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328.Matter under investigation Final rept by 830808 Reported per Part 21.
MANNO,S.F. Niagara Mohawk Power Corp 83/04/26. STAROSTECKI,R Region 1, Office of Director. 2pp 18433:072. 24X Fiche:50-000,83/04/26,8305120392.

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305120334 Interim deficiency rept re GE control rod drive sys clamps Initially reported on 830405 Clamps not ASME qualified Final rept will be submitted by 830829
MANNO,S F Niagara Mohawk Power Corp 83/05/04 STAROSTECKI,R Division of Project & Resident Programs 2pp 18432 292 24X Fiche 50-410,83/05/04,8305120334

8305250430 Suppls 820402 final deficiency rept re Power Strut spring nuts Corrective actions completed Nuts from Field Purchase Order 12113 returned to vendor S&W QA Insp Plan N20E061AFA008 revised to ensure use of proper spring nut
MANNO,S F Niagara Mohawk Power Corp 83/05/16 STAROSTECKI,R Division of Project & Resident Programs 1p 18585 286 24X Fiche 50-410,83/05/16,8305250430

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11 PALLADINO,N J Commissioners 2pp 18542 272 24X Fiche:50-000,83/04/11,8305230720

8305230263 Informs of NRC determination that probability of unacceptable damage due to turbine missiles acceptably low, provided turbine missile generation probability maintained as specified
KNIGHTON,G W Licensing Branch 3 83/04/28 WOOLEVER,E J Duquesne Light Co 3pp 18543 258 24X Fiche 50-412,83/04/28, 8305230263

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

C Utility Environmental Report (ER), amends & correspondence

8305170199 Summary of 830322 meeting w/util & S&W in Bethesda,MD re environ rept OL stage
LAZO,L Licensing Branch 3 83/05/10 Licensing Branch 3 24pp 18496'144 24X Fiche'50-412,83/05/10,8305170199

8305180559 Forwards environ rept for Beaver Valley Power Station,Unit 2.
WOOLEVER,E J Duquesne Light Co 83/05/16. DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18550 001 24X Fiche 50-412,83/05/16,8305180559

--8305180576 Environ rept - OL Stage for Beaver Valley Power Station, Unit 2 Errata encl
* Duquesne Light Co 83/05/16 781pp 18568 119 24X Fiche 50-412,83/05/16,8305180559

F Security, medical, emergency & fire protection plans

8305020426 Informs of mod to Unit 1 emergency preparedness plan to include Unit 2 Units will have one emergency plan & separate sets of implementing procedures
WOOLEVER,E J Duquesne Light Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp. 18273 192 24X Fiche 50-412,83/04/28,8305020426

8305170186 Summary of 830317 meeting w/util in Bethesda,MD re physical security plan Plan required by 830731
LAZO,L Licensing Branch 3. 83/05/10 Licensing Branch 3 4pp 18496 140 24X Fiche 50-412,83/05/10,8305170186

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D.G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540:095. 24X Fiche 50-000,83/05/11,8305110034

8305310234 Summary of 830411 meeting w/util in Bethesda,MD re schedule for completing items in Generic Ltr 82-33,Suppl 1 to NUREG-0737 requirements for emergency response capability
LAZO,L Licensing Branch 3 83/05/11 Licensing Branch 3 12pp
18662 234 24X Fiche 50-412,83/05/11,8305310234

8305180256 Forwards "Beaver Valley Power Station Unit 2 Fire Protection Evaluation Rept " Ack of receipt requested
WOOLEVER,E J Duquesne Light Co 83/05/16 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 18490 355 24X
Fiche 50-412,83/05/16,8305180256

--8305180259 "Beaver Valley Power Station Unit 2 Fire Protection Evaluation Rept "
* Duquesne Light Co 83/05/16 576pp 18490 357 24X
Fiche 50-412,83/05/16,8305180256

K Utility Final Safety Analysis Report (FSAR) & amends

8305180283 Forwards Amend 1 to FSAR
WOOLEVER,E J Duquesne Light Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18487 225 24X
Fiche 50-412,83/05/16,8305180283

--8305180287 Amend 1 to FSAR W/seven oversize figures Aperture cards are available in PDR
* Duquesne Light Co 83/05/31 862pp 18487 230 24X
Fiche 50-412,83/05/16,8305180283

8305180559 Forwards FSAR & environ rept (filed in PDR Category C) for Beaver Valley Power Station,Unit 2
WOOLEVER,E J Duquesne Light Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director. 2pp 18550 001 24X
Fiche 50-412,83/05/16,8305180559

--8305180569 FSAR for Beaver Valley Power Station,Unit 2 Errata encl
* Duquesne Light Co. 83/05/16 2,879pp 18550 003. 24X
Fiche 50-412,83/05/16,8305180559

--8305180585 Chapter 1 to Beaver Valley Unit 2 FSAR, "Introduction & General Description of Plant "
* Duquesne Light Co 83/05/16 269pp 18550 014 24X
Fiche 50-412,83/05/16,8305180559

--8305180592 Chapter 2 to Beaver Valley Unit 2 FSAR, "Site Characteristics "
* Duquesne Light Co. 83/05/16 230pp 18550 283 24X
Fiche 50-412,83/05/16,8305180559

--8305180598 App 2.3A to Beaver Valley Unit 2 FSAR, "Salt & Water Drift "
* Duquesne Light Co 83/05/16 15pp 18551 153. 24X
Fiche 50-412,83/05/16,8305180559

--8305180606 App 2 3B to Beaver Valley Unit 2 FSAR, "Visible Plume Model "
* Duquesne Light Co. 83/05/16 8pp. 18551 167. 24X
Fiche 50-412,83/05/16,8305180559

--8305180613 App 2 3C to Beaver Valley Unit 2 FSAR, "Beaver Valley Power Station Joint Frequency Distribution at 35-Ft Level (Jan 1976 - Dec 1980) "
* Duquesne Light Co. 83/05/16 117pp 18551 174 24X
Fiche 50-412,83/05/16,8305180559

--8305180625 App 2 3D to Beaver Valley Unit 2 FSAR, "Beaver Valley Power Station Joint Frequency Distribution at 500-Ft Level (Jan 1976 - Dec 1980). "
* Duquesne Light Co. 83/05/16 183pp 18551 291 24X
Fiche 50-412,83/05/16,8305180559

--8305180634 App 2 4A to Beaver Valley Unit 2 FSAR, "Analysis of Flood Heights,Ohio River at Shippingport,PA Hydrologic Engineering Investigation " Aperture card available in PDR.
* Duquesne Light Co 83/05/16 185pp 18552 114 24X
Fiche 50-412,83/05/16,8305180559

--8305180641 App 2 5A to Beaver Valley Unit 2 FSAR, "Ohio River Elevations & Piezometer Data "
* Duquesne Light Co 83/05/16 44pp 18552 299 24X
Fiche 50-412,83/05/16,8305180559

--8305180650 App 2.5B to Beaver Valley Unit 2 FSAR, "Boring Logs." Aperture cards available in PDR
* Duquesne Light Co 83/05/16 48pp. 18552 347. 24X
Fiche 50-412,83/05/16,8305180559

--8305180655 App 2 5C to Beaver Valley Unit 2 FSAR, "Relative Density Plots for Verification Borings,Terra Probe Densification Main Intake Structure "
* Duquesne Light Co 83/05/16 51pp. 18553 035 24X
Fiche 50-412,83/05/16,8305180559

--8305180661 App 2 5D to Beaver Valley Unit 2 FSAR, "Lab Test Data In Situ Soils "
* Duquesne Light Co 83/05/16 138pp 18553 085 24X
Fiche 50-412,83/05/16,8305180559

--8305180666 Chapter 3 to Beaver Valley Unit 2 FSAR, "Design of Structures,Components,Equipment & Sys "
* Duquesne Light Co 83/05/16 1,147pp 18553 223. 24X
Fiche 50-412,83/05/16,8305180559

--8305180673 App 3A to Beaver Valley Unit 2 FSAR, "Computer Program for Dynamic & Static Analysis of Seismic Category I Structures, Equipment & Components "
* Duquesne Light Co 83/05/16 157pp 18556 290. 24X
Fiche. 50-412,83/05/16,8305180559

--8305180681 App 3B to Beaver Valley Unit 2 FSAR, "Study of Probability of Aircraft Collision W/Beaver Valley Power Station - Unit 2 "
* Duquesne Light Co. 83/05/16 65pp 18557.087 24X
Fiche. 50-412,83/05/16,8305180559

--8305180685 Chapter 4 to Beaver Valley Unit 2 FSAR, "Reactor "
* Duquesne Light Co 83/05/16 231pp 18557 170 24X
Fiche 50-412,83/05/16,8305180559

--8305180693 Chapter 5 to Beaver Valley Unit 2 FSAR, "RCS & Connected Sys " Four aperture cards available in PDR
* Duquesne Light Co 83/05/16 252pp. 18558 041 24X
Fiche 50-412,83/05/16,8305180559

--8305180695 App 5A to Beaver Valley Unit 2 FSAR, "Cold Shutdown Capability "
* Duquesne Light Co 83/05/16 12pp 18558 293 24X
Fiche 50-412,83/05/16,8305180559

--8305180697 Chapter 6 to Beaver Valley Unit 2 FSAR, "ESF." Aperture cards available in PDR.
* Duquesne Light Co 83/05/16 460pp 18558 332 24X
Fiche 50-412,83/05/16,8305180559

--8305180705 Chapter 7 to Beaver Valley Unit 2 FSAR, "Instrumentation & Controls."
* Duquesne Light Co 83/05/16 682pp 18560 072. 24X
Fiche 50-412,83/05/16,8305180559

--8305180708 Chapter 8 to Beaver Valley Unit 2 FSAR, "Electric Power "
* Duquesne Light Co. 83/05/16 180pp 18562:034. 24X
Fiche. 50-412,83/05/16,8305180559

--8305180715 Chapter 9 to Beaver Valley Unit 2 FSAR, "Auxiliary Sys " Aperture cards available in PDR.
* Duquesne Light Co 83/05/16 480pp 18562:214 24X
Fiche 50-412,83/05/16,8305180559

--8305180720 Chapter 10 to Beaver Valley Unit 2 FSAR, "Steam & Power Conversion Sys." Aperture cards available in PDR
* Duquesne Light Co 83/05/16 114pp 18563:334. 24X
Fiche 50-412,83/05/16,8305180559

--8305180728 App 10A to Beaver Valley Unit 2 FSAR, "Auxiliary Feedwater Sys Simplified Reliability Analysis "
* Duquesne Light Co. 83/05/16. 77pp 18564.088. 24X
Fiche 50-412,83/05/16,8305180559

--8305180735 Chapter 11 to Beaver Valley Unit 2 FSAR, "Radwaste Mgt." Aperture cards available in PDR
* Duquesne Light Co 83/05/16 143pp 18564 176 24X
Fiche 50-412,83/05/16,8305180559

--8305180740 App 11A to Beaver Valley Unit 2 FSAR, "Summary of Annual Radiation Doses."
* Duquesne Light Co. 83/05/16. 26pp 18564:319. 24X
Fiche 50-412,83/05/16,8305180559.

--8305180746 Chapter 12 to Beaver Valley Unit 2 FSAR, "Radiation Protection "
* Duquesne Light Co. 83/05/16 192pp. 18564.352. 24X
Fiche 50-412,83/05/16,8305180559

--8305180749 Chapter 13 to Beaver Valley Unit 2 FSAR, "Conduct of Operations "
* Duquesne Light Co 83/05/16 117pp 18565 184 24X
Fiche 50-412,83/05/16,8305180559

--8305180755 Chapter 14 to Beaver Valley Unit 2 FSAR, "Initial Test Program " Four aperture cards available in PDR
* Duquesne Light Co 83/05/16 183pp 18565 301 24X
Fiche 50-412,83/05/16,8305180559

--8305180760 Chapter 15 to Beaver Valley Unit 2 FSAR, "Accident Analyses "
* Duquesne Light Co 83/05/16 461pp 18566 124 24X
Fiche 50-412,83/05/16,8305180559

--8305180764 App 15A to Beaver Valley Unit 2 FSAR, "Dose Methodology "
* Duquesne Light Co 83/05/16 8pp 18567 225 24X
Fiche 50-412,83/05/16,8305180559

--8305180767 Chapter 16 to Beaver Valley Unit 2 FSAR, "Tech Specs "
* Duquesne Light Co 83/05/16 7pp 18567 234 24X
Fiche 50-412,83/05/16,8305180559

--8305180769 Chapter 17 to Beaver Valley Unit 2 FSAR, "QA " Errata encl
* Duquesne Light Co. 83/05/16 31pp 18567 240 24X
Fiche.50-412,83/05/16,8305180559

8305240248 Forwards affidavit certifying distribution of FSAR Amend 1
WOOLEVER,E J. Duquesne Light Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 18548 304 24X
Fiche:50-412,83/05/19,8305240248

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381.291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382:047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co, of New York, Inc. 118pp. 18382.165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03. Consolidated Edison Co, of New York, Inc. 122pp 18441.170. 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382·282. 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441.001. 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New-York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305250488 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-01
MARTIN,T T Division of Engineering & Technical Programs 83/05/20
WOOLEVER,E J Duquesne Light Co 1p 18589 035 24X
Fiche 50-412,83/05/20,8305250488

--8305250498 Responds to NRC 830210 ltr re violations noted in IE Insp Rept 50-412/83-01 Corrective actions three steam generator cold leg nozzle welds will be repaired by end of Dec 1983 Steam generator technical manual will be revised
WOOLEVER,E J Duquesne Light Co 83/05/04 STAROSTECKI,R Division of Project & Resident Programs 6pp 18589 036 24X
Fiche 50-412,83/05/20,8305250488

8305270656 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/81-09
STAROSTECKI,R Division of Project & Resident Programs 83/05/24
WOOLEVER,E J Duquesne Light Co 1p 18646 358 24X
Fiche 50-412,83/05/24,8305270656

--8305270662 Revises 820310 response to NRC 820209 ltr re violations noted in IE Insp Rept 50-412/81-09 Corrective actions nuts & bolts in duct connection will be replaced w/new nuts,bolts & flat washers to ensure proper bearing surface area
WOOLEVER,E J Duquesne Light Co 83/04/04 STAROSTECKI,R Division of Project & Resident Programs 3pp 18646 359 24X
Fiche 50-412,83/05/24,8305270656

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305100104 Interim Significant Deficiency Rept 83-02 re QC acceptance of conditions in nonconformance w/insp plan attributes Initially reported on 830318 QC supervisor & lead inspectors reinstructed Next rept will be submitted by 830801
WOOLEVER,E J Duquesne Light Co 83/04/29 HAYNES,R C Region 1, Office of Director 4pp 18374 350 24X Fiche 50-412,83/04/29,8305100104

8305110295 Interim Significant Deficiency Rept 83-01 re incorrect Westinghouse EMD gate valve position indication Initially reported on 830112,Rept of results of evaluation will be submitted by 830531
,WOOLEVER,E J Duquesne Light Co 83/04/29 HAYNES,R C Region 1, Office of Director 5pp 18393 273 24X Fiche 50-412,83/04/29,8305110295

8305200429 Final Significant Deficiency Rept 82-06 re failed sheared pinion keys in Limitorque motor operators supplied by Westinghouse All deficient keys replaced Also reportable per Part 21
WOOLEVER,E J Duquesne Light Co 83/05/10 ALLAN,J Region 1, Office of Director 5pp 18517 145 24X Fiche 50-412,83/05/10,8305200429

DOCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305020326 Forwards addl info re containment pressure boundary fracture toughness,in response to NRC 820504 ltr W/four oversize drawings Aperture cards are available in PDR
PARKER,W O Duke Power Co 82/06/03 DENTON,H R. Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 18276.220 24X Fiche 50-413,82/06/03,8305020326

8305050008 Forwards "Const Project Evaluation for Catawba Nuclear Station "
OWEN, W H Duke Power Co 82/12/30 O'REILLY, J P Region 2, Office of Director. 1p 18339 110 24X Fiche 50-413, 82/12/30, 8305050008

--8305050014 "Const Project Evaluation for Catawba Nuclear Station "
* Duke Power Co 82/10/31 202pp 18339 111 24X
Fiche 50-413, 82/12/30, 8305050008

8305020556 Approves request to withhold "Reactor Cavity Asymmetric Loads" from public disclosure per 10CFR2 790
ADENSAM, E G Licensing Branch 4 83/04/26 TUCKER, H B Duke Power Co 2pp 18284, 247 24X Fiche 50-413, 83/04/26, 8305020556

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305270005 Forwards proposed Tech Specs in form of marked-up Rev 4 to NUREG-0452, "STS for Westinghouse PWRs "
TUCKER, H B Duke Power Co 83/05/20. DENTON, H. R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 741pp 18630 001 24X Fiche 50-413, 83/05/20, 8305270005

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020020 Forwards comments on SER Section 9.5 1 re fire protection program, issued by NRC on 830222. W/four oversize drawings. List of room descriptions also encl. Aperture cards are available in PDR.
TUCKER, H B. Duke Power Co 83/04/14. DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 14pp. 18276 222 24X Fiche 50-413, 83/04/14, 8305020020

8305020028 Notification of 830504 meeting w/util in Bethesda, MD to discuss SER Confirmatory Item 17 re Type C leak rate testing of certain isolation valves.
JABBOUR, K N Licensing Branch 4 83/04/25 ADENSAM, E. G Licensing Branch 4. 3pp 18308 302 24X Fiche: 50-413, 83/04/25, 8305020028

8305170712 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION, UNITS 1 AND 2 Docket Nos 50-413 And 50-414 (Duke Power Company, et al)
* Division of Licensing NUREG-0954 S01 83/04/30. 36pp.
Available at NRC $4 75 18481, 126 24X Fiche 50-413, 83/04/30, 8305170712

8305160196 Forwards Hydrologic Engineering Section request for addl info re SER Confirmatory Item 1 on local flooding analysis Response requested by 830610
ADENSAM, E G Licensing Branch 4 83/05/06 TUCKER, H B Duke Power Co 4pp. 18471 335. 24X Fiche 50-413, 83/05/06, 8305160196

8305170615 Forwards Suppl 1 to SER. W/o encl.
NOVAK, T M Division of Licensing 83/05/13 TUCKER, H B Duke Power Co. 3pp 18497 017. 24X Fiche 50-413, 83/05/13, 8305170615.

8305240021 Notification of 830525 meeting w/util & Westinghouse in Bethesda, MD to discuss resolution of SER Open Item 9 re conformance to RSB 5-1 & steam generator tube rupture.
JABBOUR, K N Licensing Branch 4 83/05/13 ADENSAM, E G Licensing Branch 4 3pp 18577 311. 24X Fiche 50-413, 83/05/13, 8305240021

8305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion
TUCKER, H B Duke Power Co 83/05/16. DENTON, H. R Office of Nuclear Reactor Regulation, Director. ADENSAM, E G Licensing Branch 4 4pp 18517 297. 24X Fiche. 50-413, 83/05/16, 8305200401.

8305200476 Forwards revised pages to FSAR addressing Open Item 15, Confirmatory Items 2, 5 & 10 & License Condition 4, per SER. Revised pages will be included in Rev 8.
TUCKER, H B Duke Power Co 83/05/16 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. G Licensing Branch 4 11pp 18512 347 24X Fiche: 50-413, 83/05/16, 8305200476

8305310200 Informs of plans to perform mods to Westinghouse Model D2/D3 steam generators per SER (NURE-0966) issued on 830316. Plant-specific mod details encl
TUCKER, H B. Duke Power Co. 83/05/18 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. ADENSAM, E. G. Licensing Branch 4 7pp. 18651 014 24X Fiche: 50-413, 83/05/18, 8305310200.

F Security, medical, emergency & fire protection plans

8305020020 Forwards comments on SER Section 9 5 1 re fire protection program, issued by NRC on 830222 W/four oversize drawings List of room descriptions also encl Aperture cards are available in PDR
TUCKER, H B Duke Power Co 83/04/14 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4. 14pp 18276 222 24X Fiche 50-413, 83/04/14, 8305020020

8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/21
TUCKER, H B Duke Power Co 2pp 18642 175 24X
Fiche 50-413, 83/04/21, 8305270393

--8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08. No noncompliance noted Major area inspected: fire protection.
MILLER, W H., CONLON, T E Region 2, Office of Director 83/04/19 6pp 18642 177 24X Fiche 50-413, 83/04/21, 8305270393.

8305160292 Releases public version of evacuation time estimates.
FELTON, J M Division of Rules and Records 83/05/02 Document Management Branch 1p 18462 238 24X Fiche 50-413, 83/05/02, 8305160292.

--8305160293 Forwards public version of "Evacuation Time Estimates "
TUCKER, H B Duke Power Co 83/04/20 DENTON, H. R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 1p 18462, 239 24X Fiche. 50-413, 83/05/02, 8305160292.

--8305160295 Public version of "Evacuation Time Estimates "
* Planning Research Corp 83/04/30. 94pp 18462: 240 24X
Fiche 50-413, 83/05/02, 8305160292

8305170296 Forwards storage & in-transit security plan for SNM of low strategic significance Plan withheld (ref 10CFR73 80).
TUCKER, H. B Duke Power Co 83/05/10 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p 18465 078. 24X
Fiche 50-413, 83/05/10, 8305170296

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N. J. Commissioners 5pp 18593: 322. 24X
Fiche: 50-000, 83/05/13, 8305240213

8305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion
TUCKER, H B Duke Power Co. 83/05/16 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E G. Licensing Branch 4 4pp 18517 297. 24X Fiche 50-413, 83/05/16, 8305200401

G. Adjudicatory correspondence

8305030504 Advises that NRC will not serve responsive pleading to Palmetto Alliance 830411 motion to compel discovery from applicants. NRC is not party to discovery dispute.
JOHNSON, G E Hearing Branch 4 83/04/29. KELLEY, J. L , FOSTER, R. F., CALLIHAN, D Atomic Safety and Licensing Board Panel. 1p
18295: 304 24X Fiche 50-413, 83/04/29, 8305030504.

8305040538 Motion to compel Palmetto Alliance response to util interrogatories & requests to produce re Palmetto Alliance Contentions 6, 7, 8, 16 & 44. Responses inadequate to date. Certificate of Svc encl. Related correspondence.
MCGARRY, J M. Duke Power Co. MCGARRY, J M. Debevoise & Liberman 83/04/29 Atomic Safety and Licensing Board Panel. 65pp.
18321: 152 24X Fiche 50-413, 83/04/29, 8305040538

8305030576 Followup interrogatories & related document requests on Contentions 6, 8, 16, 27 & 44. Certificate of Svc encl.
JOHNSON, G. E. Hearing Branch 4. 83/05/02 Palmetto Alliance. 10pp 18306, 100. 24X Fiche: 50-413, 83/05/02, 8305030576

8305060252 Responses to 830418 interrogatories & requests to produce re DEB Contentions 11, 17 & 19. Related correspondence.
QUILD, R Palmetto Alliance. RILEY, J L. Carolina Environmental Study Group. QUILD, R. Quild, R 83/05/02 Duke Power Co 21pp
18345, 197. 24X Fiche: 50-413, 83/05/02, 8305060252.

8305050080 Renewed motion to compel Palmetto Alliance full answers to interrogatories on Contention 7 Answers & supplemental answers evasive Certificate of Svc encl
JOHNSON,O E Hearing Branch 4 83/05/04 Atomic Safety and Licensing Board Panel 13pp 18342 135 24X Fiche 50-413,83/05/04, 8305050080

8305090468 Advises that emergency operating procedures mailed to intervenors per ASLB 820305 & 1201 orders Thirty-day period for filing contentions should start on 830509
CARR,A V Duke Power Co 83/05/04 KELLEY,J L , CALLIHAN,A D , FOSTER,R F Atomic Safety and Licensing Board Panel 1p 18362 258 24X Fiche 50-413,83/05/04,8305090468

8305100282 Forwards notices of deposition for W McAfee,NR Hoopingarner & M Lowe re Palmetto Alliance contentions Related correspondence
CARR,A V Duke Power Co 83/05/04 GUILD,R Guild, R 1p 18371 261 24X Fiche 50-413,83/05/04,8305100282

--8305100289 Notice of W McAfee deposition in Columbia,SC re Palmetto Alliance Contention 6 & 810722 affidavit
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371 262 24X Fiche 50-413,83/05/04,8305100282

--8305100297 Notice of NR Hoopingarner deposition in Columbia,SC re Palmetto Alliance Contention 6 & 810722 affidavit
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371,263 24X Fiche 50-413,83/05/04,8305100282

--8305100305 Notice of M Lowe deposition in Columbia,SC re Palmetto Alliance Contentions 6,7,8,16,27 & 44.
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371 264 24X Fiche 50-413,83/05/04,8305100282

8305100342 Followup interrogatories to Palmetto Alliance Contentions 6, 7,8,16 & 27 Answer must be filed by 830520 Certificate of Svc encl Related correspondence
CARR,A.V. Duke Power Co 83/05/04 Atomic Safety and Licensing Board Panel 16pp 18378 196 24X Fiche 50-413,83/05/04, 8305100342

8305100415 Advises of filing of followup interrogatories on Palmetto Alliance Contentions 6,7,8,16 & 27 Applicant has received no answers from Palmetto Alliance to interrogatories on Contention 44,so no followup available at present time
CARR,A V Duke Power Co 83/05/04 KELLEY,J L Atomic Safety and Licensing Board Panel CALLIHAN,A D Union Carbide Corp FOSTER,R F Affiliation Unknown 1p 18378 080 24X Fiche,50-413,83/05/04,8305100415

8305090511 Discusses 830502 telcon re recording of applicant & Palmetto Alliance depositions on Contentions 27,16,8,44,6 & 7 Draft stipulation encl
MCGARRY,J M Debevoise & Liberman 83/05/05 GUILD,R Guild, R. 7pp. 18362 146 24X Fiche 50-413,83/05/05,8305090511

8305100232 Responds to Duke Power Co motion to establish deadline for control room design review contentions NRC does not oppose motion to extent contentions filed by 830531 Certificate of Svc encl
JOHNSON,O E Office of the Executive Legal Director 83/05/09, Atomic Safety and Licensing Board Panel 3pp 18374 122 24X Fiche 50-413,83/05/09,8305100232

8305110462 Response to Carolina Environ Study Group (CESG) Contention 18 & DES Contention 17 Interrogatory 10 of Contention 17 irrelevant,Affidavits,Certificate of Counsel & Certificate of Svc encl
JOHNSON,O E. Hearing Branch 4 83/05/10 Atomic Safety and Licensing Board Panel 29pp 18405,017 24X Fiche 50-413,83/05/10, 8305110462

8305130056 Advises that NRC will make NRC technical staff members available for deposition on 830516-18 in Bethesda,MD No written notice of deposition received
JOHNSON,O E Hearing Branch 4 83/05/11 GUILD,R. Guild, R GUILD,R. Palmetto Alliance. 2pp 18436,333 24X Fiche 50-413,83/05/11,8305130056

8305170472 Memorandum & order ruling on util 830429 motion to compel Palmetto Alliance further responses to util interrogatories & requests to produce re Palmetto Contentions 6,7,8,16 & 44 Listed requests granted
KELLEY,J L Atomic Safety and Licensing Board Panel 83/05/13, Duke Power Co 13pp 18470 099 24X Fiche 50-413,83/05/13, 8305170472.

8305170556 Forwards SER Suppl 1 (NUREG-0954) W/o encl
JOHNSON,O E. Hearing Branch 4 83/05/16, KELLEY,J L , FOSTER,R F., CALLIHAN,D Atomic Safety and Licensing Board Panel 1p 18468,160. 24X Fiche 50-413,83/05/16,8305170556

8305240485 Followup interrogatories re DES Contentions 11,17 & 19 Certificate of Svc encl Related correspondence
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/18 Palmetto Alliance 16pp 18572 317 24X Fiche 50-413,83/05/18,8305240485

8305230055 Forwards addl documentation re util welding insp task force rept Documents may fall within scope of General Interrogatory 4 (First set) Documents identified in response to FOIA request W/o encl
JOHNSON,O E Hearing Branch 4 83/05/19 GUILD,R Palmetto Alliance GUILD,R Guild, R 1p 18539 176 24X Fiche 50-413,83/05/19,8305230055

8305310025 Forwards 830517 & 20 ltrs from HB Tucker to JO Davis & HR Denton,respectively,per request W/o encl
CARR,A V Duke Power Co 83/05/24 GUILD,R Guild, R 1p 18653 310 24X Fiche 50-413,83/05/24,8305310025

8305310035 Lists post-discovery administrative matters requiring resolution Remaining documents should be identified in response to ASLB 830513 order,by 830531
GIBSON,R L Duke Power Co 83/05/24 GUILD,R Palmetto Alliance GUILD,R Guild, R 2pp 18653 211 24X Fiche 50-413,83/05/24, 8305310035

8305310155 Motion to establish discovery schedule on QA Contention 9 Certificate of Svc encl
GUILD,R Palmetto Alliance 83/05/25 Atomic Safety and Licensing Board Panel 21pp 18653 015 24X Fiche 50-413,83/05/25, 8305310155

H General correspondence

8305040455 Forwards documents identified in 830414 ltr per 830428 telcon W/o encls Related correspondence
GIBSON,R L Consumers Power Co 83/04/29 GUILD,R Palmetto Alliance 1p 18322 143 24X Fiche 50-413,83/04/29,8305040455

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270324 Forwards IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/25
TUCKER,H B Duke Power Co 2pp 18642 059 24X
Fiche 50-413,83/03/25,8305270324

--8305270334 IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No noncompliance noted Major areas inspected IE Bulletin 82-04 followup,electrical component & sys nonconformance items, pipe welding & electrical cables & terminations
VANDOORN,P.K Region 2, Office of Director IGNATONIS,A J Division of Project & Resident Programs 83/03/22 5pp. 18642 061 24X Fiche 50-413,83/03/25,8305270324

8305270590 Forwards IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/13
TUCKER,H.B Duke Power Co 2pp 18646 103 24X
Fiche 50-413,83/04/13,8305270590

--8305270602 IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted Major areas inspected reviews of licensee QA surveillance repts & authorized nuclear inspector problem repts
VANDOORN,P.K , IGNATONIS,A J Region 2, Office of Director 83/04/12 5pp 18646 105 24X Fiche 50-413,83/04/13,8305270590

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/21
TUCKER,H B. Duke Power Co 2pp 18642 175. 24X
Fiche:50-413,83/04/21,8305270393

--8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted.Major area inspected,fire protection
MILLER,W H , CONLON,T E Region 2, Office of Director 83/04/19 6pp 18642 177 24X Fiche 50-413,83/04/21,8305270393

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291. 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250211 Requests comments on encl draft NRR SALP input for June 1982 - Apr 1983 Comments received by 830523 will be considered in final rept
JABBOUR,K N Licensing Branch 4 83/05/18 EISENHUT,D G Division of Licensing MATTSON,R Division of Systems Integration (post 811005) VOLLMER,R Division of Engineering 6pp. 18627 117 24X Fiche 50-413,83/05/18,8305250211

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305170292 Final Significant Deficiency Rept SD 413-414/82-23 re violation of const procedures for mixing & placing SikaTop 122 during drill hole repair Initially reported on 821208 Test program concluded SikaTop 122 acceptable
TUCKER,H B Duke Power Co 83/05/06 O'REILLY,J.P Region 2, Office of Director 3pp 18465 359, 24X Fiche 50-413,83/05/06, 8305170292

8305250282 Significant Deficiency Rept SD 413/83-07 re vent valve LND105 not installed in accordance w/design & const criteria Initially reported on 830414 Valve will be corrected to conform w/drawing in June 1983
TUCKER,H B Duke Power Co 83/05/13 O'REILLY,J P Region 2, Office of Director 2pp 18592 359 24X Fiche 50-413,83/05/13, 8305250282

8305270069 Final Significant Deficiency Rept SD 413-414/82-27 re cracks in cell containers of nickel cadmium batteries mfg by Transamerica Delaval Initially reported on 821220 Caused by contact w/unknown solvent used for cleaning
TUCKER,H B Duke Power Co 83/05/17 O'REILLY,J P Region 2, Office of Director 3pp 18638 279 24X Fiche 50-413,83/05/17, 8305270069

DOCKET 50-414 CATAWBA NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305020326 Forwards addl info re containment pressure boundary fracture toughness, in response to NRC 820504 ltr W/four oversize drawings Aperture cards are available in PDR
PARKER,W O Duke Power Co 82/06/03 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 18276 220 24X Fiche 50-413,82/06/03,8305020326.

8305050008 Forwards "Const Project Evaluation for Catawba Nuclear Station "
OWEN,W H Duke Power Co 82/12/30 O'REILLY,J P Region 2, Office of Director 1p 18339.110 24X Fiche 50-413,82/12/30,8305050008.

--8305050014 "Const Project Evaluation for Catawba Nuclear Station. "
* Duke Power Co 82/10/31 202pp 18339·111 24X Fiche 50-413,82/12/30,8305050008

8305020556 Approves request to withhold "Reactor Cavity Asymmetric Loads" from public disclosure per 10CFR2 790
ADENSAM,E G Licensing Branch 4 83/04/26 TUCKER,H B, Duke Power Co. 2pp 18284 247 24X Fiche 50-413,83/04/26,8305020556.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09. Consolidated Edison Co of New York, Inc 16pp 18627.153 24X Fiche 50-000,83/05/09,8305090659

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020020 Forwards comments on SER Section 9.5 1 re fire protection program, issued by NRC on 830222 W/four oversize drawings. List of room descriptions also encl Aperture cards are available in PDR
TUCKER,H B Duke Power Co 83/04/14 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 14pp 18276 222 24X Fiche 50-413,83/04/14,8305020020.

8305020028 Notification of 830504 meeting w/util in Bethesda,MD to discuss SER Confirmatory Item 17 re Type C leak rate testing of certain isolation valves
JABBOUR,K N Licensing Branch 4 83/04/25. ADENSAM,E.G Licensing Branch 4 3pp 18308 302 24X Fiche·50-413,83/04/25,8305020028

8305170712 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION, UNITS 1 AND 2 Docket Nos. 50-413 And 50-414 (Duke Power Company,et al)
* Division of Licensing NUREG-0954 S01 83/04/30 56pp. Available at NRC #4 75 18481 126 24X Fiche.50-413,83/04/30, 8305170712

8305160196 Forwards Hydrologic Engineering Section request for addl info re SER Confirmatory Item 1 on local flooding analysis Response requested by 830610
ADENSAM,E G Licensing Branch 4 83/05/06. TUCKER,H.B Duke Power Co 4pp 18471·335 24X Fiche 50-413,83/05/06,8305160196

8305170615 Forwards Suppl 1 to SER W/o encl.
NOVAK,T M Division of Licensing 83/05/13 TUCKER,H.B Duke Power Co. 3pp 18497 017 24X Fiche:50-413,83/05/13,8305170615.

8305240021 Notification of 830525 meeting w/util & Westinghouse in Bethesda,MD to discuss resolution of SER Open Item 9 re conformance to RSB 5-1 & steam generator tube rupture
JABBOUR,K.N Licensing Branch 4 83/05/13 ADENSAM,E G Licensing Branch 4 3pp 18577 311 24X Fiche 50-413,83/05/13,8305240021

8305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion
TUCKER,H B Duke Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 4pp 18517 297 24X Fiche 50-413,83/05/16,8305200401

8305200476 Forwards revised pages to FSAR addressing Open Item 15, Confirmatory Items 2,5 & 10 & License Condition 4,per SER Revised pages will be included in Rev 8
TUCKER,H B Duke Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 11pp 18512 347 24X Fiche 50-413,83/05/16,8305200476

8305310200 Informs of plans to perform mods to Westinghouse Model D2/D3 steam generators per SER (NURE-0966) issued on 830316 Plant-specific mod details encl
TUCKER,H B Duke Power Co 83/05/18 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 7pp 18651 014 24X Fiche 50-413,83/05/18,8305310200

F Security, medical, emergency & fire protection plans

8305020020 Forwards comments on SER Section 9 5 1 re fire protection program,issued by NRC on 830222 W/four oversize drawings List of room descriptions also encl Aperture cards are available in PDR
TUCKER,H B Duke Power Co 83/04/14 DENTON,H R Office of Nuclear Reactor Regulation, Director 14pp 18276 222 24X Fiche 50-413,83/04/14,8305020020

8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/21
TUCKER,H B Duke Power Co 2pp 18642 175 24X Fiche 50-413,83/04/21,8305270393

--8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted Major area inspected fire protection.
MILLER,W H Region 2, Office of Director 83/04/19 6pp 18642 177 24X Fiche 50-413,83/04/21,8305270393

8305160292 Releases public version of evacuation time estimates
FELTON,J.M Division of Rules and Records 83/05/02 Document Management Branch 1p 18462 238 24X Fiche 50-413,83/05/02, 8305160292

--8305160293 Forwards public version of "Evacuation Time Estimates "
TUCKER,H B. Duke Power Co 83/04/20 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 1p 18462 239 24X Fiche 50-413,83/05/02,8305160292

--8305160295 Public version of "Evacuation Time Estimates "
* Planning Research Corp 83/04/30 94pp 18462 240 24X Fiche 50-413,83/05/02,8305160292

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EIBENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 093 24X Fiche:50-000,83/05/11,8305110034

8305200401 Requests SER Section 9 5 3 be revised to accurately reflect design of emergency lighting sys at facility Emergency lighting portion of Open Item 15 should be closed based on encl discussion
TUCKER,H B Duke Power Co 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18517 297 24X Fiche:50-413,83/05/16,8305200401

Q Adjudicatory correspondence

8305030504 Advises that NRC will not serve responsive pleading to Palmetto Alliance 830411 motion to compel discovery from applicants NRC is not party to discovery dispute
JOHNSON,G.E. Hearing Branch 4 83/04/29 KELLEY,J L , FOSTER,R F , CALLIHAN,D Atomic Safety and Licensing Board Panel 1p 18295 304 24X Fiche 50-413,83/04/29,8305030504

8305040538 Motion to compel Palmetto Alliance response to util interrogatories & requests to produce re Palmetto Alliance Contentions 6,7,8,16 & 44 Responses inadequate to date Certificate of Svc encl Related correspondence
MCGARRY,J M Duke Power Co. MCGARRY,J M Debevoise & Liberman 83/04/29 Atomic Safety and Licensing Board Panel 65pp. 18321.152 24X Fiche 50-413,83/04/29,8305040538

8305030576 Followup interrogatories & related document requests on Contentions 6,8,16,27 & 44 Certificate of Svc encl
JOHNSON,G E Hearing Branch 4 83/05/02 Palmetto Alliance 10pp 18306 100 24X Fiche 50-413,83/05/02,8305030576

8305060252 Responses to 830418 interrogatories & requests to produce re DES Contentions 11,17 & 19 Related correspondence
QUILD,R Palmetto Alliance RILEY,J L Carolina Environmental Study Group QUILD,R Guild, R 83/05/02 Duke Power Co 21pp 18345 197 24X Fiche 50-413,83/05/02,8305060252

8305050080 Renewed motion to compel Palmetto Alliance full answers to interrogatories on Contention 7 Answers & supplemental answers evasive Certificate of Svc encl
JOHNSON,G E Hearing Branch 4 83/05/04 Atomic Safety and Licensing Board Panel 13pp 18342 135 24X Fiche 50-413,83/05/04, 8305050080

8305090468 Advises that emergency operating procedures mailed to intervenors per ASLB 820305 & 1201 orders Thirty-day period for filing contentions should start on 830509
CARR,A V Duke Power Co 83/05/04 KELLEY,J L , CALLIHAN,A D , FOSTER,R F Atomic Safety and Licensing Board Panel 1p 18362 258 24X Fiche 50-413,83/05/04,8305090468

8305100282 Forwards notices of deposition for W McAfee,NR Hoopingarner & M Lowe re Palmetto Alliance contentions Related correspondence
CARR,A V Duke Power Co 83/05/04 GUILD,R Guild, R 1p 18371 261 24X Fiche 50-413,83/05/04,8305100282

--8305100289 Notice of W McAfee deposition in Columbia,SC re Palmetto Alliance Contention 6 & 810722 affidavit
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371 262 24X Fiche 50-413,83/05/04,8305100282

--8305100297 Notice of NR Hoopingarner deposition in Columbia,SC re Palmetto Alliance Contention 6 & 810722 affidavit
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371 263 24X Fiche 50-413,83/05/04,8305100282

--8305100305 Notice of M Lowe deposition in Columbia,SC re Palmetto Alliance Contentions 6,7,8,16,27 & 44
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman 83/05/04 1p 18371 264 24X Fiche 50-413,83/05/04,8305100282

8305100342 Followup interrogatories to Palmetto Alliance Contentions 6, 7,8,16 & 27 Answer must be filed by 830520 Certificate of Svc encl Related correspondence
CARR,A V Duke Power Co 83/05/04 Atomic Safety and Licensing Board Panel 16pp 18378 196 24X Fiche 50-413,83/05/04, 8305100342

8305100415 Advises of filing of followup interrogatories on Palmetto Alliance Contentions 6,7,8,16 & 27 Applicant has received no answers from Palmetto Alliance to interrogatories on Contention 44,so no followup available at present time
CARR,A V Duke Power Co 83/05/04 KELLEY,J L Atomic Safety and Licensing Board Panel CALLIHAN,A D Union Carbide Corp FOSTER,R F Affiliation Unknown 1p 18378 080 24X Fiche 50-413,83/05/04,8305100415

8305090511 Discusses 830502 telcon re recording of applicant & Palmetto Alliance depositions on Contentions 27,16,8,44,6 & 7 Draft stipulation encl
MCGARRY,J M Debevoise & Liberman 83/05/05 GUILD,R Guild, R 7pp 18362 146 24X Fiche 50-413,83/05/05,8305090511

8305100232 Responds to Duke Power Co motion to establish deadline for control room design review contentions NRC does not oppose motion to extent contentions filed by 830531 Certificate of Svc encl
JOHNSON,G E Office of the Executive Legal Director 83/05/09 Atomic Safety and Licensing Board Panel 5pp 18374 122 24X Fiche 50-413,83/05/09,8305100232

8305110462 Response to Carolina Environ Study Group (CESG) Contention 18 & DES Contention 17 Interrogatory 10 of Contention 17 irrelevant Affidavits,Certificate of Counsel & Certificate of Svc encl
JOHNSON,G E Hearing Branch 4 83/05/10 Atomic Safety and Licensing Board Panel 29pp 18405 017 24X Fiche 50-413,83/05/10, 8305110462

8305130056 Advises that NRC will make NRC technical staff members available for deposition on 830516-18 in Bethesda,MD No written notice of deposition received
JOHNSON,G E Hearing Branch 4 83/05/11 QUILD,R Guild, R QUILD,R Palmetto Alliance 2pp 18436 333 24X Fiche 50-413,83/05/11,8305130056

8305170472 Memorandum & order ruling on util 830429 motion to compel Palmetto Alliance further responses to util interrogatories & requests to produce re Palmetto Contentions 4,7,8,16 & 44 Listed requests granted
KELLEY,J L Atomic Safety and Licensing Board Panel 83/05/13
Duke Power Co 13pp 18470 099 24X Fiche 50-413,83/05/13, 8305170472

8305170556 Forwards SER Suppl 1 (NUREG-0954) W/o encl
JOHNSON,G E Hearing Branch 4 83/05/16 KELLEY,J L , FOSTER,R F , CALLIHAN,D Atomic Safety and Licensing Board Panel 1p
18468 160 24X Fiche 50-413,83/05/16,8305170556

8305240485 Followup interrogatories re DES Contentions 11,17 & 19 Certificate of Svc encl Related correspondence
MCGARRY,J M Duke Power Co MCGARRY,J M Debevoise & Liberman
83/05/18 Palmetto Alliance 16pp 18572 317 24X
Fiche 50-413,83/05/18,8305240485

8305230055 Forwards addl documentation re util welding insp task force rept Documents may fall within scope of General Interrogatory 4 (first set) Documents identified in response to FOIA request W/o encl
JOHNSON,G E Hearing Branch 4 83/05/19 GUILD,R Palmetto Alliance GUILD,R Guild, R 1p 18539 176 24X
Fiche 50-413,83/05/19,8305230055

8305310025 Forwards 830517 & 20 ltrs from HB Tucker to JO Davis & HR Denton,respectively,per request W/o encl
CARR,A V Duke Power Co 83/05/24 GUILD,R Guild, R 1p
18653 310 24X Fiche 50-413,83/05/24,8305310025

8305310035 Lists post-discovery administrative matters requiring resolution Remaining documents should be identified in response to ASLB 830513 order,by 830531
GIBSON,R L Duke Power Co 83/05/24 GUILD,R Palmetto Alliance GUILD,R Guild, R 2pp 18653 211. 24X Fiche 50-413,83/05/24, 8305310035

8305310155 Motion to establish discovery schedule on GA Contention G Certificate of Svc encl
GUILD,R Palmetto Alliance 83/05/25 Atomic Safety and Licensing Board Panel. 21pp 18653 015 24X Fiche 50-413,83/05/25, 8305310155

H General correspondence

8305040455 Forwards documents identified in 830414 ltr per 830428 telcon W/o encls Related correspondence
GIBSON,R L Consumers Power Co 83/04/29. GUILD,R Palmetto Alliance 1p 18322 143 24X Fiche 50-413,83/04/29,8305040455

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc.
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270324 Forwards IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/25
TUCKER,H B. Duke Power Co 2pp 18642.059 24X
Fiche 50-413,83/03/25,8305270324

--8305270334 IE Insp Repts 50-413/83-03 & 50-414/83-03 on 830126-0225 No noncompliance noted Major areas inspected IE Bulletin 82-04 followup,electrical component & sys nonconformance items, pipe welding & electrical cables & terminations
VANDOORN,P K Region 2, Office of Director IGNATONIS,A J Division of Project & Resident Programs. 83/03/22 5pp
18642 061 24X Fiche 50-413,83/03/25,8305270324.

8305270590 Forwards IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/13,
TUCKER,H B. Duke Power Co 2pp 18646 103 24X
Fiche 50-413,83/04/13,8305270590

--8305270602 IE Insp Repts 50-413/83-05 & 50-414/83-05 on 830226-0326 No noncompliance noted Major areas inspected reviews of licensee QA surveillance repts & authorized nuclear inspector problem repts
VANDOORN,P.K , IGNATONIS,A J. Region 2, Office of Director
83/04/12 5pp 18646 105. 24X Fiche. 50-413,83/04/13,8305270590.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8305270393 Forwards IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/04/21,
TUCKER,H B Duke Power Co 2pp 18642 175 24X
Fiche 50-413,83/04/21,8305270393

--8305270404 IE Insp Repts 50-413/83-06 & 50-414/83-06 on 830405-08.No noncompliance noted Major area inspected fire protection
MILLER,W H , CONLON,T E Region 2, Office of Director 83/04/19, 6pp 18642 177 24X Fiche 50-413,83/04/21,8305270393

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383.089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche. 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs," Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp. 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.

8303040029 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441.170. 24X Fiche 50-000,83/05/03,8303040029

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/04. Consolidated Edison Co. of New York, Inc 112pp. 18382:282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp. 18523 248 24X Fiche 50-000,83/05/06,8303040033.

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305250211 Requests comments on encl draft NRR SALP input for June 1982 - Apr 1983. Comments received by 830523 will be considered in final rept.
JABBOUR,K N Licensing Branch 4. 83/05/18 EISENHUT,D.G. Division of Licensing MATTSON,R Division of Systems Integration (post 811005). VOLLMER,R Division of Engineering 6pp. 18627:117. 24X
Fiche 50-413,83/05/18,8305250211.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/19. Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche: 50-000,83/05/19,8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

B Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305170292 Final Significant Deficiency Rept SD 413-414/82-23 re violation of const procedures for mixing & placing SikaTop 122 during drill hole repair Initially reported on 821208 Test program concluded SikaTop 122 acceptable
TUCKER,H B Duke Power Co 83/05/06 O'REILLY,J P Region 2, Office of Director 3pp 18465 359 24X Fiche 50-413,83/05/06, 8305170292

8305250449 Significant Deficiency Rept SD 414/83-08 re tack weld found on shaft/rotor assembly of Limitorque operator motor Initially reported on 830415 Shaft rotor/assembly to be repaired or replaced Final rept expected by 830603
TUCKER,H B Duke Power Co 83/05/13 O'REILLY,J P Region 2, Office of Director 2pp 18585 284 24X Fiche 50-414,83/05/13, 8305250449

8305270069 Final Significant Deficiency Rept SD 413-414/82-27 re cracks in cell containers of nickel cadmium batteries mfg by Transamerica Delaval Initially reported on 821220 Caused by contact w/unknown solvent used for cleaning
TUCKER,H B Duke Power Co 83/05/17 O'REILLY,J P Region 2, Office of Director, 3pp 18638 279 24X Fiche 50-413,83/05/17, 8305270069

DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON,J M Division of Rules and Records 83/03/31 SHOLLY,S C Union of Concerned Scientists 2pp 18593 179 24X Fiche 50-000,83/03/31,8305240254.

--8103300276 Comments on draft "Reactor Safety Study Methodology Applications Program Results for Grand Gulf 1 BWR Power Plant " Omissions & simplifications overstate risk of facility operation.
HODGES,W Reactor Systems Branch 81/03/24 CURRY,J Office of Nuclear Regulatory Research, Director 3pp 18593,252 24X Fiche 50-000,83/03/31,8305240254

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 HOLTZSCHER,D.L. Illinois Power Co. 2pp 18443 173 24X Fiche 50-000,83/05/02, 8305120460.

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs, Info needed to document evaluation on each Licensing Review Group II generic issue.
STEFANO,J J Licensing Branch 1 83/05/02 POWELL,P Washington Public Power Supply System. 1p 18443 174 24X
Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs, Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 REED,W.J. Gulf States Utilities Co 1p. 18443,175 24X Fiche 50-000,83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue.
STEFANO,J J Licensing Branch 1 83/05/02 RICHARDSON,J.D. Mississippi Power & Light Co 1p 18443 176. 24X
Fiche 50-000,83/05/02,8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 BUZZELLI,E M Cleveland Electric Illuminating Co 1p 18443 177 24X
Fiche 50-000,83/05/02,8305120460

F Security, medical, emergency & fire protection plans

8305050075 Forwards Rev 6 to physical security plan Rev withheld (ref 10CFR2 790)
MCGAUGHY,J P Mississippi Power & Light Co 83/02/21 O'REILLY,J P Region 2, Office of Director 2pp 18342 052 24X Fiche 50-416,83/02/21,8305050075

8305050077 Forwards revised pages & response to NRC comments re physical security plan,Revs 7 & 5,respectively Encls withheld (ref 10CFR2 790)
MCGAUGHY,J P Mississippi Power & Light Co 83/03/15 O'REILLY,J P Region 2, Office of Director 2pp 18342 148 24X Fiche 50-416,83/03/15,8305050077

8305270409 Notifies that IE Insp Rept 50-416/83-03 was inadvertently assigned wrong number Correct number is 50-416/83-07 Reissued IE Insp Rept 50-416/83-07 encl
VERRELLI,D M Division of Project & Resident Programs 83/03/28 RICHARD,J B. Mississippi Power & Light Co 1p 18642 305 24X Fiche 50-416,83/03/28,8305270409

--8305270417 Forwards IE Insp Rept 50-416/83-07 on 830124-27 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/28 RICHARD,J B Mississippi Power & Light Co 2pp 18642 306. 24X Fiche 50-416,83/03/28,8305270409

--8305270427 Corrected IE Insp Rept 50-416/83-07 on 830124-27. No noncompliance noted Major areas inspected emergency preparedness exercise
CLINE,W E. Region 2, Office of Director JENKINS,G R Division of Emergency Preparedness & Materials Safety 83/03/25 9pp 18642 308 24X Fiche 50-416,83/03/28,8305270409

8304280037 Application for amend to License NPF-13 re sealed source contamination,reporting,fire protection & trip setpoints
MCGAUGHY,J P Mississippi Power & Light Co 83/04/25 DENTON,H R Office of Nuclear Reactor Regulation, Director 9pp 18251 152 24X Fiche 50-416,83/04/25,8304280037

--8304280049 Proposed Tech Specs re sealed source contamination, reporting,fire protection & trip setpoints
* Mississippi Power & Light Co 83/04/25 14pp 18251 161 24X
Fiche 50-416,83/04/25,8304280037

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

8305270028 Confirms NRC position re use of manually-entered codes & anti-passback features for control of access to vital areas Devices may unduly restrict movement during safety-related emergencies Response requested by 830630
SCHWENCER,A. Licensing Branch 2 83/05/23 MCGAUGHY,J P Mississippi Power & Light Co 2pp 18662 105 24X
Fiche 50-416,83/05/23,8305270028

J. Insurance & indemnity information

8305190015 Forwards ANI Certificate N-79 & MAELU Certificate M-79 for secondary financial coverage
DALE,L F. Mississippi Power & Light Co 83/05/11 KERR,G W Office of State Programs, Director 18pp 18501,340 24X
Fiche 50-416,83/05/11,8305190015

O Advisory Committee on Reactor Safeguards reports & correspondence

8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington,DC.
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/05
ACRS - Advisory Committee on Reactor Safeguards 529pp 18458:225 24X Fiche 50-000,83/05/05,8305130290

P Operating license stage documents & correspondence

8305230608 Provides lump sum number representing direct cost impact of regulatory proliferation during approx period from NRC CP to low-power OL, in response to 830208 request re backfitting costs
LUTKEN, D C Mississippi Power & Light Co 83/03/04
TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18541 340 24X
Fiche 50-416, 83/03/04, 8305230608

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M
Division of Rules and Records 1p 18593 178 24X
Fiche 50-000, 83/03/11, 8305240249

8305240260 Forwards util comments on Reactor Safety Study Methodology Applications Program results Risks associated w/BWR/6 plant design misrepresented
CESARE, G NRC - No Detailed Affiliation Given 81/02/17 CURRY, J
NRC - No Detailed Affiliation Given 5pp 18593 195 24X
Fiche 50-000, 83/03/31, 8305240254

--8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RSSMAP) evaluation conducted by Sandia Natl Labs Excessively conservative calculations used Related correspondence encl
DALE, L F Mississippi Power & Light Co 81/01/23 BERNERD, R M
Office of Nuclear Regulatory Research, Director 49pp, 18593 200
24X Fiche 50-000, 83/03/31, 8305240254

8304110321 Forwards application to amend License NPF-13 Amend revises surveillance procedure review - Package 2 & miscellaneous Tech Specs re responsibility for auditing station activities
MCGAUGHY, J P Mississippi Power & Light Co 83/04/07 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 17911 031
24X Fiche 50-416, 83/04/07, 8304110321

--8304110328 Application for amend to License NPF-13, revising surveillance procedure review - Package 2 & miscellaneous Tech Specs re responsibility for auditing station activities
MCGAUGHY, J P Mississippi Power & Light Co 83/04/07 12pp
17911 033 24X Fiche 50-416, 83/04/07, 8304110321.

--8304110335 Proposed Tech Specs re prompt notification w/written followup, reactor protection sys instrumentation & RCS surveillance requirements, reactor vessel matl surveillance program-withdrawal schedule & area temp monitoring
* Mississippi Power & Light Co 83/04/07 34pp 17911 045 24X
Fiche 50-416, 83/04/07, 8304110321

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force, 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8304190378 Forwards corrected 830413 ltr providing update to 830128 & 820610 ltrs re Category I masonry walls & temp monitoring in HPCS diesel generator room
DALE, L F Mississippi Power & Light Co 83/04/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 6pp 18056 063
24X Fiche, 50-416, 83/04/13, 8304190378

8304280037 Application for amend to License NPF-13 re sealed source contamination, reporting, fire protection & trip setpoints
MCGAUGHY, J. P Mississippi Power & Light Co 83/04/25 DENTON, H. R
Office of Nuclear Reactor Regulation, Director 9pp 18251 152
24X Fiche 50-416, 83/04/25, 8304280037

--8304280049 Proposed Tech Specs re sealed source contamination, reporting, fire protection & trip setpoints
* Mississippi Power & Light Co 83/04/25 14pp 18251 161 24X
Fiche 50-416, 83/04/25, 8304280037.

8305040289 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK, T. M Assistant Director for Licensing 83/04/26
HOLTZSCHER, D L Illinois Power Co 2pp 18326-343 24X
Fiche 50-000, 83/04/26, 8305040289

8305020455 Generic Ltr 83-19 to all power reactor & testing licensees re new procedures for providing public notice concerning issuance of amends to OLs Svc list encl.
EISENHUT, D G Division of Licensing. 83/05/02 Consolidated
Edison Co of New York, Inc 30pp 18441 120 24X
Fiche 50-000, 83/05/02, 8305020455

8305240496 Forwards "Safety Relief Valve Discharge Test," final rept for Kuosheng Nuclear Power Station, including Apps A-T Rept withheld (ref 10CFR2 790) Info submitted per OL Condition 2 C(45)
DALE, L F Mississippi Power & Light Co 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 96189-286
24X Fiche 50-000, 83/05/02, 8305240496

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 HALE, D P
Illinois Power Co 2pp 18523 200 24X Fiche 50-000, 83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 FERGUSON, M. R
Washington Public Power Supply System 2pp, 18523 202 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants.
EISENHUT, D G Division of Licensing 83/05/03 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing. 83/05/03 CAHILL, J Gulf
States Utilities Co 2pp 18523 206 24X Fiche 50-000, 83/05/03, 8305190046

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT, D G Division of Licensing 83/05/09. Consolidated
Edison Co. of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659.

8305130126 Forwards response to questions included in 830203 ltr re Hydrogen Control Owners Group program Questions 8 & 9 must be addressed on plant-specific basis Tentative arrangements made for meeting w/Containment Sys Branch on 830602
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III
RICHARDSON, J D Mississippi Power & Light Co 83/05/11
HOUSTON, R W Division of Systems Integration (post 811005), 25pp
18437 231 24X Fiche 50-416, 83/05/11, 8305130126

8305250150 Notification of 830603 meeting w/BWR-Hydrogen Control Owners Group in Bethesda, MD to discuss hydrogen control program & emergency procedure guidelines
HOUSTON, D Licensing Branch 2, 83/05/17 SCHWENCER, A Licensing
Branch 2, 4pp 18596.191, 24X Fiche, 50-416, 83/05/17, 8305250150

8305240143 Forwards qualification status & compliance summary per 10CFR50 49 re environ qualification of electrical equipment important to safety. Updated equipment list & qualification status for relevant components encl.
DALE, L F Mississippi Power & Light Co 83/05/20. DENTON, H R
Office of Nuclear Reactor Regulation, Director. 61pp 18549:176.
24X Fiche 50-416, 83/05/20, 8305240143

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl.
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/03/21 Consolidated Edison Co. of New York, Inc
112pp. 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385

8305270409 Notifies that IE Insp Rept 50-416/83-03 was inadvertently assigned wrong number. Correct number is 50-416/83-07. Reissued IE Insp Rept 50-416/83-07 encl.
VERRELLI, D. M Division of Project & Resident Programs 83/03/28.
RICHARD, J B. Mississippi Power & Light Co. 1p 18642.305 24X
Fiche 50-416, 83/03/28, 8305270409.

--8305270417 Forwards IE Insp Rept 50-416/83-07 on 830124-27 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/28
RICHARD,J B Mississippi Power & Light Co 2pp 18642 306 24X
Fiche 50-416,83/03/28,8305270409

--8305270427 Corrected IE Insp Rept 50-416/83-07 on 830124-27 No noncompliance noted Major areas inspected emergency preparedness exercise
CLINE,W E Region 2, Office of Director JENKINS,O R Division of Emergency Preparedness & Materials Safety 83/03/25 9pp
18642 308 24X Fiche 50-416,83/03/28,8305270409

8305270300 Forwards IE Insp Rept 50-416/83-11 on 830310-13 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/30
RICHARD,J B Mississippi Power & Light Co 2pp 18641 173 24X
Fiche 50-416,83/03/30,8305270300

--8305270306 IE Insp Rept 50-416/83-11 on 830310-13 No noncompliance noted Major area inspected drywell suppression pool bypass leakage testing
BROOKS,E H , JAPE,F Region 2, Office of Director 83/03/28
4pp 18641 175 24X Fiche 50-416,83/03/30,8305270300

8305270463 Forwards IE Insp Rept 50-416/83-09 on 830314-18 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/05
RICHARD,J B Mississippi Power & Light Co 2pp 18644 074 24X
Fiche 50-416,83/04/05,8305270463

--8305270470 IE Insp Rept 50-416/83-09 on 830314-18 No noncompliance noted. Major areas inspected review of startup procedures & acceptable test packages
BURNETT,P T , JAPE,F. Region 2, Office of Director 83/03/30
5pp. 18644 076 24X Fiche 50-416,83/04/05,8305270463

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New
York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New
York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/25 Consolidated Edison Co of New
York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305270585 Approves issuance of SALP Rept 50-416/82-45 for Jul 1981 - Aug 1982 Discussion of comment submitted in util 830302 ltr provided.
O'REILLY,J P Region 2, Office of Director 83/04/25 LUTKIN,D C
Mississippi Power & Light Co 3pp 18644 187 24X
Fiche:50-416,83/04/25,8305270585.

--8305270593 Comments on SALP Board Assessment 50-416/82-45 for Jul 1981 - Aug 1982. Plans to upgrade performance will be submitted in Mar 1983
MCGAUGHY,J P Mississippi Power & Light Co 83/03/02
O'REILLY,J P Region 2, Office of Director. 8pp. 18644 190 24X
Fiche 50-416,83/04/25,8305270585

--8305270596 Forwards SALP Board Assessment 50-416/82-45 for Jul 1981 - Aug 1982.
LEWIS,R C Division of Project & Resident Programs 83/02/03
STAMPLEY,N L Mississippi Power & Light Co 2pp 18644.198 24X
Fiche 50-416,83/04/25,8305270585

--8305270639 SALP Board Assessment 50-416/82-45 for Jul 1981 - Aug 1982
* Region 2, Office of Director 83/04/25 25pp 18644.200 24X
Fiche 50-416,83/04/25,8305270585

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New
York, Inc 115pp. 18382:047 24X Fiche:50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN,E. L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/28 Consolidated Edison Co. of New
York, Inc 118pp 18382 165 24X Fiche.50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK,T M Assistant Director for Licensing 83/05/03
HOLTZSCHER,D L Licensing Review Group II HOLTZSCHER,D L
Illinois Power Co 6pp 18440 356 24X Fiche 50-000,83/05/03,
8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 117pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New
York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305270275 Forwards IE Enforcement Conference Rept 50-416/83-15 on 830420
O'REILLY,J P Region 2, Office of Director 83/05/12 RICHARD,J B
Mississippi Power & Light Co 2pp 18644 299 24X
Fiche 50-416,83/05/12,8305270275

--8305270283 IE Enforcement Conference Rept 50-416/83-15 on 830420 Major areas discussed enforcement issues resulting from inadequate control of mods & maint & inadequate corrective actions
VERRELLI,D M Division of Project & Resident Programs 83/05/12
4pp 18644 301 24X Fiche 50-416,83/05/12,8305270275

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New
York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270388 Ack receipt of 830401 & 0510 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-416/83-04
VERRELLI,D M Division of Project & Resident Programs 83/05/19
RICHARD,J B Mississippi Power & Light Co 1p 18643 023 24X
Fiche 50-416,83/05/19,8305270388

--8305270400 Responds to NRC 830304 ltr re violations noted in IE Insp Rept 50-416/83-04 Corrective actions personnel informed of significance of correct positioning of handswitches
MCGAUGHY,J P Mississippi Power & Light Co 83/05/10
O'REILLY,J P Region 2, Office of Director 2pp 96207 303 24X
Fiche 50-416,83/05/19,8305270388

--8305270410 Responds to NRC 830304 ltr re violations noted in IE Insp Rept 50-416/83-04 Corrective actions DOT label covered & correct label posted, addl training seminar on posting held on 830128 & handswitches moved to standby
MCGAUGHY,J P Mississippi Power & Light Co 83/04/01
O'REILLY,J.P Region 2, Office of Director 3pp 18643 026 24X
Fiche 50-416,83/05/19,8305270388

--8305270418 Forwards IE Insp Rept 50-416/83-04 on 830117-0215 & notice of violation
VERRELLI,D.M Division of Project & Resident Programs 83/03/04
STAMPLEY,N L Mississippi Power & Light Co 2pp 18643 029. 24X
Fiche 50-416,83/05/19,8305270388

--8305270424 Notice of violation from insp on 830117-0215
* Region 2, Office of Director 83/03/04 1p 18643 031 24X
Fiche 50-416,83/05/19,8305270388

--8305270438 IE Insp Rept 50-416/83-04 on 830117-0215 Noncompliance noted failure to make Part 20 posting & to follow procedure re handswitches
WAGNER,A G , SCOTT,D E , CANTRELL,F S Region 2, Office of Director 83/03/02 5pp 18643 032 24X Fiche 50-416,83/05/19, 8305270388

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

R Periodic operating reports & related correspondence

8305250072 Monthly operating rept for Apr 1983 W/830513 ltr
RICHARDSON,J D , MCGAUGHY,J P Mississippi Power & Light Co. 83/05/13 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 7pp 18585 103 24X Fiche 50-416,83/05/13,8305250072

S Reportable occurrences, LERs & related correspondence

8305270515 Interim deficiency rept re defective contact button in Liberty Control telephone relays. Initially reported on 830217 Investigation of applicability to Unit 2 underway Deficiency not reportable for Unit 1 Final rept by 830418
MCGAUGHY,J P Mississippi Power & Light Co. 83/03/18.
O'REILLY,J P Region 2, Office of Director. 6pp. 18646.121 24X Fiche 50-416,83/03/18,8305270515

8305030553 RO 83-024/0 on 830319 & 30, several smoke detectors in control room Zones 1-18 & auxiliary bldg corridors, elevation 139 ft, respectively, covered to prevent actuation during welding Fire watches established
MCGAUGHY,J P Mississippi Power & Light Co 83/04/25
O'REILLY,J P. Region 2, Office of Director 2pp. 18303·337 24X Fiche 50-416,83/04/25,8305030553

8305030562 RO 83-023/0, on 830312, two smoke detectors in standby gas treatment filter train room, Zone 2-19 covered during welding activities to prevent actuation. Similar event occurred on 830315. Detector operability to be restored by 830315.
MCGAUGHY,J P Mississippi Power & Light Co 83/04/25
O'REILLY,J P Region 2, Office of Director. 1p. 18306·125. 24X Fiche 50-416,83/04/25,8305030562

8305050256 Forwards LER 83-061/03L-0
RICHARDS,J Mississippi Power & Light Co 83/04/27. O'REILLY,J P Region 2, Office of Director 1p 18338 020 24X Fiche.50-416,83/04/27,8305050256

--8305050261 LER 83-061/03L-0 on 830328, one solenoid operated Freon valve found w/blown gasket. Caused by defective ALCO Controls solenoid operated gasket Valve reworked w/valve repair kit & new gasket installed
ROHRER,M V., SHINGLETON,E.B Mississippi Power & Light Co 83/04/27 Region 2, Office of Director 1p 18338:021 24X Fiche.50-416,83/04/27,8305050256

8305050131 RO 83-026/0 on 830327, security access card reader to fire door 1A318, Elevation 166 ft, in auxiliary bldg malfunctioned Caused by fire door blocked to allow personnel access. Card reader reworked & returned to svc 830405
MCGAUGHY,J P Mississippi Power & Light Co 83/04/28
O'REILLY,J P Region 2, Office of Director. 1p 18342.201. 24X Fiche 50-416,83/04/28,8305050131

8305050167 Forwards LER 83-060/03L-0
MCGAUGHY,J P Mississippi Power & Light Co 83/04/28.
O'REILLY,J P Region 2, Office of Director 1p 18341.086 24X Fiche:50-416,83/04/28,8305050167.

--8305050178 LER 83-060/03L-0 on 830329, during cold shutdown, load shedding & Div I LSS sequencing panel failure alarm actuated Caused by failure of 15-volt dc power supply used to power solid state electronics for sys logic.
BYRD,R. Mississippi Power & Light Co. 83/04/28. Region 2, Office of Director 2pp. 18341.087. 24X Fiche:50-416,83/04/28, 8305050167

8305050227 RO 83-025/0 on 830322, fire rated penetrations opened to implement design change packages Hourly fire watches established within 1 h & will be maintained for duration of planned maint activities. Work to be completed by 830610
MCGAUGHY,J P. Mississippi Power & Light Co 83/04/28
O'REILLY,J.P Region 2, Office of Director 2pp. 18338:094. 24X Fiche 50-416,83/04/28,8305050227.

8305110275 Forwards LER 83-051/03L-0
DALE,L F Mississippi Power & Light Co. 83/04/29. O'REILLY,J.P. Region 2, Office of Director. 1p 18393:148 24X Fiche:50-416,83/04/29,8305110275.

--8305110279 LER 83-051/03L-0 on 830401, control room emergency filtration subsystem taken out of svc to allow performance of corrective maint Task completed & subsystem energized on 830404
ROHRER,M V , SHINGLETON,E B Mississippi Power & Light Co 83/04/29 Region 2, Office of Director 2pp 18393 149 24X Fiche 50-416,83/04/29,8305110275

8305110418 RO 83-027/0 on 830321, during performance of seismic monitoring sys functional test, operation of chart recorders & spectrum analyzer determined unacceptable Cause not stated Investigation underway Next rept expected by 830615
DALE,L F Mississippi Power & Light Co 83/04/29. O'REILLY,J P Region 2, Office of Director 1p 18392 001 24X Fiche 50-416,83/04/29,8305110418

8305110291 Special Rept 83-028/0 on 830329, fire penetrations opened to implement design change packages Fire watches established, Work tasks expected to be completed by 830701
MCGAUGHY,J Mississippi Power & Light Co 83/05/04 O'REILLY,J.P Region 2, Office of Director 3pp 18393 142 24X Fiche 50-416,83/05/04,8305110291

8305130194 Forwards updated LER 82-175/99X-1
MCGAUGHY,J P Mississippi Power & Light Co 83/05/06
O'REILLY,J P Region 2, Office of Director. 1p 18440:071. 24X Fiche 50-416,83/05/06,8305130194

--8305130200 Updated LER 82-175/99X-1 on 821213, fire barriers in control room panel discovered open Caused by breaking fire barriers to accomodate design change in panel Barriers restored on 830412
BYRD,R. Mississippi Power & Light Co 83/05/06 Region 2, Office of Director 1p 18440.072 24X Fiche 50-416,83/05/06, 8305130194

8305170424 Forwards LER 83-048/01T-0
MCGAUGHY,J P Mississippi Power & Light Co 83/05/09.
O'REILLY,J P Region 2, Office of Director 1p. 18469.295 24X Fiche 50-416,83/05/09,8305170424

--8305170426 LER 83-048/01T-0 on 830423, suppression pool level instrumentation discovered not functionally tested since 830409 Cause under investigation Instrumentation tested satisfactorily within 8 h
ROHRER,M V , SHINGLETON,E B Mississippi Power & Light Co. 83/05/09 Region 2, Office of Director. 1p. 18469 296 24X Fiche.50-416,83/05/09,8305170424

8305170427 Forwards updated LER 83-031/99X-1.
MCGAUGHY,J.P Mississippi Power & Light Co. 83/05/09.
O'REILLY,J P Region 2, Office of Director. 2pp. 18469:292. 24X Fiche·50-416,83/05/09,8305170427

--8305170431 Updated LER 83-031/99X-1, on 830113, fire rated Door DC104 blocked open to route temporary discharge hose from hot machine shop sump to turbine bldg floor drain sys Caused by inadequacy of present sys Mod to be completed by Sept 1983.
BYRD,R Mississippi Power & Light Co 83/05/09 Region 2, Office of Director 1p. 18469 294. 24X Fiche.50-416,83/05/09, 8305170427

8305170430 Forwards updated LER 83-004/01T-0.
MCGAUGHY,J P Mississippi Power & Light Co. 83/05/09.
O'REILLY,J P Region 2, Office of Director. 2pp 18467:291. 24X Fiche 50-416,83/05/09,8305170430.

--8305170433 Updated LER 83-004/01T-1 on 830110, penetration AP-728 found open & had been open since 821213 Caused by planned maint work & personnel error Hourly fire watch established. Penetration to be resealed by 830630.
BYRD,R. Mississippi Power & Light Co. 83/05/09 Region 2, Office of Director. 2pp 18467·293 24X Fiche:50-416,83/05/09, 8305170430.

8305200280 Forwards LER 83-049/03L-0.
MCGAUGHY,J.P Mississippi Power & Light Co. 83/05/09.
O'REILLY,J.P Region 2, Office of Director. 1p. 18516·263. 24X Fiche:50-416,83/05/09,8305200280

--8305200286 LER 83-049/03L-0 on 830409, during cold shutdown, diesel generator 12 auto start not available when alarm actuated. Caused by condensate drain valve downstream of tank C not fully closed. Compressors reworked.
BYRD,R Mississippi Power & Light Co. 83/05/09 Region 2, Office of Director 3pp 18516.264 24X Fiche.50-416,83/05/09, 8305200280

8305200604 RO 83-029/0 on 830422,50-meter wind direction reading did not agree w/10-meter reading Caused by incorrectly wired new sensors located in Design Change Package 82-502 Wiring diagram corrected
MCGAUGHY,J P Mississippi Power & Light Co 83/05/09
O'REILLY,J P Region 2, Office of Director 1p 18514 089 24X
Fiche 50-416,83/05/09,8305200604

8305200523 Forwards LER 83-052/03L-0
MCGAUGHY,J P Mississippi Power & Light Co 83/05/11
O'REILLY,J P Region 2, Office of Director 1p 18516 043 24X
Fiche 50-416,83/05/11,8305200523

--8305200532 LER 83-052/03L-0 on 830411,while reviewing vessel head installation work package,discovered head flange/vessel flange thermocouples not physically reinstalled during insulation installation Cause under evaluation
ROHRER,M V Mississippi Power & Light Co 83/05/11 Region 2, Office of Director 1p 18516 044 24X Fiche 50-416,83/05/11, 8305200523

8305200484 Forwards LER 83-046/03L-0
MCGAUGHY,J P Mississippi Power & Light Co 83/05/12
O'REILLY,J P Region 2, Office of Director 1p 18513 008 24X
Fiche 50-416,83/05/12,8305200484

--8305200493 LER 83-046/03L-0 on 830412,monthly functional surveillance for Div I chlorine detection sys not performed by 830410 Caused by personnel error
ROHRER,M V Mississippi Power & Light Co 83/05/12 Region 2, Office of Director 2pp 18513 009 24X Fiche 50-416,83/05/12, 8305200484

8305250365 RO 83-032/0 on 830415,smoke detectors in control room covered to prevent alarm condition while welding performed Detectors uncovered on 830501 & sys returned to normal operation
MCGAUGHY,J P Mississippi Power & Light Co 83/05/17
O'REILLY,J P Region 2, Office of Director 1p 18585 350 24X
Fiche 50-416,83/05/17,8305250365

8305250405 Final RO 83-002/1 on 830201,smoke detectors on Elevation 119 ft of auxiliary bldg covered to perform planned maint Hourly fire watch established Detectors restored to svc on 830509.
MCGAUGHY,J P. Mississippi Power & Light Co 83/05/17
O'REILLY,J P Region 2, Office of Director 1p 18585 332 24X
Fiche. 50-416,83/05/17,8305250405

8305250434 RO 83-031/0 on 830415,fire doors blocked open for 21 days, exceeding 7-day time limit Doors closed & restored to operation
MCGAUGHY,J P Mississippi Power & Light Co 83/05/17
O'REILLY,J P Region 2, Office of Director 2pp 18585 291 24X
Fiche: 50-416,83/05/17,8305250434

8305250513 RO 83-033/0 on 830411,fire-rated penetrations opened to implement design change packages Hourly fire watches established within 1 h & will be maintained for duration of planned maint activities
MCGAUGHY,J P Mississippi Power & Light Co 83/05/17
O'REILLY,J P. Region 2, Office of Director 2pp 18583 352 24X
Fiche 50-416,83/05/17,8305250513

8305310146 Updated RO 83-006/1 on 830210,fire penetrations AE-382C & AE-384C opened to permit planned maint work Initially reported on 830318 Maint work order not completed Restoration date estimated for 830614
MCGAUGHY,J P Mississippi Power & Light Co 83/05/17
O'REILLY,J P. Region 2, Office of Director 1p 18651 208, 24X
Fiche 50-416,83/05/17,8305310146

8305310207 Updated LER 82-027/99X-3 on 820727,seal AV-8D discovered not installed in spare HVAC penetration to containment exhaust filter train room due to current drawings not requiring penetrations to be sealed W/830517 ltr
ROHRER,M V., SHINGLETON,E B , MCGAUGHY,J P Mississippi Power & Light Co 83/05/17 O'REILLY,J P Region 2, Office of Director 2pp 18651 008 24X Fiche 50-416,83/05/17,8305310207

8305250487 Updated LER 83-048/01X-1 on 830425,surveillance coordinator found that suppression pool level instrumentation not functionally tested before exceeding Tech Spec late date Caused by personnel error W/830518 ltr
ROHRER,M.V., MCGAUGHY,J P Mississippi Power & Light Co. 83/05/18
O'REILLY,J.P Region 2, Office of Director 3pp 18588.288. 24X
Fiche: 50-416,83/05/18,8305250487

8305250579 Updated LER 83-001/01X-1 on 830107,two wall penetrations (auxiliary bldg to turbine bldg) not previously opened Caused by personnel error Hourly fire watch established & personnel reinstructed re Tech Specs W/830518 ltr
BYRD,R , MCGAUGHY,J P Mississippi Power & Light Co 83/05/18
O'REILLY,J P Region 2, Office of Director 4pp 18588 207 24X
Fiche 50-416,83/05/18,8305250579

8305270473 RO on 830418,smoke detectors N604 A,B & C at elevation 139 ft in auxiliary bldg covered to prevent continuous alarm condition from welding performed for planned maint activity Detectors uncovered & returned to svc on 830509
MCGAUGHY,J P Mississippi Power & Light Co 83/05/18
O'REILLY,J P Region 3, Office of Director 1p 18644 146 24X
Fiche 50-416,83/05/18,8305270473

8305310065 Updated LER 82-080/01X-2 on 821004,cap screw,securing rear crankcase cover to engine block,found cracked & breaking during torque check Caused by fatigue during engine operation W/830518 ltr
ROHRER,M V , SHINGLETON,E B , MCGAUGHY,J P Mississippi Power & Light Co 83/04/18 O'REILLY,J P Region 2, Office of Director 5pp 18653 206 24X Fiche 50-416,83/05/18,8305310065

8305310204 Updated LER 82-138/99X-1 on 821112,several duct covers could not be installed while performing approved maint work on control room floor grid seals & duct covers Caused by cables extending through ducts W/830518 ltr
BYRD,R , MCGAUGHY,J P Mississippi Power & Light Co 83/05/18
O'REILLY,J P Region 2, Office of Director 2pp 18651 006 24X
Fiche 50-416,83/05/18,8305310204

8305310069 Updated RO 83-015/1 on 830311,during special insp of fire-rated assemblies,three open penetrations identified Correct matl nonconformance rept numbers should be 00162-83, 00163-83 & 00165-83 Restoration set for 830530
MCGAUGHY,J P Mississippi Power & Light Co 83/05/19.
O'REILLY,J P Region 2, Office of Director 2pp 18653 204 24X
Fiche 50-416,83/05/19,8305310069

8305310196 RO 83-034/0 on 830413,Fire Door 1A312 alarmed & would not reset Cause unknown Door functionally tested & returned to svc
MCGAUGHY,J P Mississippi Power & Light Co 83/05/20
O'REILLY,J P Region 2, Office of Director 2pp 18658 160 24X
Fiche 50-416,83/05/20,8305310196

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON,J M Division of Rules and Records 83/03/31 SHOLLY,S C Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000,83/03/31,8305240254

--8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RSSMAP) evaluation conducted by Sandia Natl Labs Excessively conservative calculations used Related correspondence encl
DALE,L F Mississippi Power & Light Co 81/01/23 BERNERO,R M Office of Nuclear Regulatory Research, Director 49pp 18593 200 24X Fiche 50-000,83/03/31,8305240254

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8304190378 Forwards corrected 830413 ltr providing update to 830128 & 820610 ltrs re Category I masonry walls & temp monitoring in HPCS diesel generator room
DALE,L F Mississippi Power & Light Co 83/04/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18054 063 24X Fiche 50-416,83/04/13,8304190378

8305040289 Advises that effective 830418,JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK,T M Assistant Director for Licensing 83/04/26
HOLTZSCHER,D L Illinois Power Co 2pp 18326 343 24X
Fiche 50-000,83/04/26,8305040289

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 HALE, D P
Illinois Power Co 2pp 18523 200 24X Fiche: 50-000, 83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 FERGUSON, M R
Washington Public Power Supply System 2pp 18523 202 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing. 83/05/03 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing. 83/05/03 CAHILL, J Gulf
States Utilities Co 2pp 18523 206 24X Fiche 50-000, 83/05/03, 8305190046

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche: 50-000, 83/05/09, 8305090659

8305130126 Forwards response to questions included in 830203 ltr re Hydrogen Control Owners Group program Questions 8 & 9 must be addressed on plant-specific basis. Tentative arrangements made for meeting w/Containment Sys Branch on 830602
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III
RICHARDSON, J D Mississippi Power & Light Co. 83/05/11.
HOUSTON, R W Division of Systems Integration (post 811005). 25pp
18437 231 24X Fiche. 50-416, 83/05/11, 8305130126

8305240143 Forwards qualification status & compliance summary per 10CFR50 49 re environ qualification of electrical equipment important to safety Updated equipment list & qualification status for relevant components encl
DALE, L F Mississippi Power & Light Co 83/05/20 DENTON, H R
Office of Nuclear Reactor Regulation, Director 61pp 18549 176
24X Fiche 50-416, 83/05/20, 8305240143

E NRC Safety Evaluation Report (SER), suppls & correspondence
---

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02. HOLTZSCHER, D L
Illinois Power Co 2pp 18443 173 24X Fiche. 50-000, 83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 POWELL, P Washington
Public Power Supply System 1p. 18443 174 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 REED, W J Gulf
States Utilities Co 1p 18443 175 24X Fiche 50-000, 83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 RICHARDSON, J D
Mississippi Power & Light Co 1p 18443 176 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 BUZZELLI, E M.
Cleveland Electric Illuminating Co 1p 18443 177. 24X
Fiche 50-000, 83/05/02, 8305120460

F Security, medical, emergency & fire protection plans

8305050075 Forwards Rev 6 to physical security plan Rev withheld (ref 10CFR2 790)
MCGAUGHY, J P Mississippi Power & Light Co 83/02/21
O'REILLY, J P Region 2, Office of Director 2pp 18342 052 24X
Fiche 50-416, 83/02/21, 8305050075

8305050077 Forwards revised pages & response to NRC comments re physical security plan, Revs 7 & 5, respectively Encls withheld (ref 10CFR2 790)
MCGAUGHY, J P Mississippi Power & Light Co 83/03/15
O'REILLY, J P Region 2, Office of Director 2pp 18342 148. 24X
Fiche 50-416, 83/03/15, 8305050077

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305270028 Confirms NRC position re use of manually-entered codes & anti-passback features for control of access to vital areas Devices may unduly restrict movement during safety-related emergencies Response requested by 830630
SCHWENCER, A Licensing Branch 2 83/05/23 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 18662 105 24X
Fiche 50-416, 83/05/23, 8305270028

J Insurance & indemnity information

8305190015 Forwards ANI Certificate N-79 & MAELU Certificate M-79 for secondary financial coverage
DALE, L F Mississippi Power & Light Co 83/05/11 KERR, O.W
Office of State Programs, Director 18pp 18501.340 24X
Fiche 50-416, 83/05/11, 8305190015

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post
830103) 83/03/21 Consolidated Edison Co. of New York, Inc
112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/15 Consolidated Edison Co. of New
York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co. of New
York, Inc 112pp 18383 089. 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co. of New
York, Inc 119pp 18381.291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New
York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New
York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/03. Consolidated Edison Co. of New
York, Inc. 122pp. 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK, T M Assistant Director for Licensing 83/05/03
HOLTZSCHER, D L Licensing Review Group II HOLTZSCHER, D L
Illinois Power Co 6pp 18440 356 24X Fiche 50-000, 83/05/03, 8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co, of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305270515 Interim deficiency rept re defective contact button in Liberty Control telephone relays Initially reported on 830217 Investigation of applicability to Unit 2 underway Deficiency not reportable for Unit 1 Final rept by 830418
MCGAUGHY, J P Mississippi Power & Light Co 83/03/18
O'REILLY, J P Region 2, Office of Director 6pp 18646 121 24X Fiche 50-416, 83/03/18, 8305270515

DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8305060648 Forwards request for addl info to complete evaluation of application for OL FSAR should be amended to include info requested Response requested by 830801
YOUNGBLOOD, B J Licensing Branch 1 83/05/03 COUNSIL, W G
Northeast Nuclear Energy Co (subs of Northeast Utilities) 31pp 18358 006 24X Fiche 50-423, 83/05/03, 8305060648

--8303170135 Forwards Div of Engineering proposed program to address USGS clarification re seismic design earthquakes on eastern US seaboard. Proposed program will complete ongoing FRA reviews
VOLLMER, R. H Division of Engineering 83/03/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 91pp 18358 037 24X Fiche 50-423, 83/05/03, 8305060648.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305250185 Summary of 830412 meeting w/util & Day, Berry & Howard in Bethesda, MD re licensing review items Viewgraphs encl
DOOLITTLE, E L Licensing Branch 1 83/05/12 Licensing Branch 1
7pp 18626 348. 24X Fiche 50-423, 83/05/12, 8305250185

8305200587 Requests info re NRC contingencies built into current OL application review schedule to support fuel load date, per 830412 meeting
COUNSIL, W G Northeast Utilities 83/05/13 YOUNGBLOOD, B J
Licensing Branch 1 1p 18514 246 24X Fiche 50-423, 83/05/13, 8305200587

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations
83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

I Financial information

8305020093 Forwards "Annual Rept of Electric Utils, Licensees & Others (Class A & Class B)," FERC Form 1
BISHOP, R W Northeast Utilities 83/04/26 Office of Nuclear Reactor Regulation, Director 132pp 18279 109 24X
Fiche 50-245, 83/04/26, 8305020093

K Utility Final Safety Analysis Report (FSAR) & amends

8305050069 Forwards receipt ack form & corrected pages inadvertently omitted from FSAR Amend 2 package
EMERSON, W Stone & Webster Engineering Corp 83/04/20 NRC - No Detailed Affiliation Given 8pp 18342 054 24X
Fiche 50-423, 83/04/20, 8305050069

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche, 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305270033 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-423/83-04
MARTIN,T T Division of Engineering & Technical Programs 83/05/20
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 18638 341 24X Fiche 50-423,83/05/20,8305270033

---8305270037 Responds to NRC 830328 ltr re violations noted in IE Insp Rept 50-423/83-04 Corrective actions equipment storage history cards updated to reflect vendor requirements on spraying electrical contacts w/CRC 2-26 every 2 yrs
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 83/04/27 MARTIN,T T Division of Engineering & Technical Programs 3pp 18638 342 24X Fiche 50-423,83/05/20,8305270033

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305060455 Interim deficiency rept re inadvertent uncoupling of pull-apart terminal blocks in Gould motor control ctrs Initially reported on 830329 Development of prototype brackets underway Final rept expected by 830701
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 83/04/28
ALLAN,J M Region 1, Office of Director 1p 18351 198 24X Fiche:50-423,83/04/28,8305060455

8305200533 Interim Significant Deficiency Rept SD-36 re design & const in main control board welds Initially reported on 830413 Meeting w/util & engineer scheduled for 830517 to discuss necessary corrective actions
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities. 83/05/13
ALLAN,J M Region 1, Office of Director 2pp 18516 025 24X Fiche 50-423,83/05/13,8305200533

8305270036 Final Deficiency Rept SD-37 re possible misoperation of Westinghouse DS-416 reactor trip switchgear undervoltage attachments Initially reported on 830420 Undervoltage attachments will be replaced w/new design
COUNSIL,W G , SEARS,C F Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL,W G Northeast Utilities 83/05/20
ALLAN,J M Region 1, Office of Director 2pp 18638 308 24X Fiche 50-423,83/05/20,8305270036

DOCKET 50-424 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305050086 Notifies that update to PSAR Chapter 17 outlining QA organizational change will be provided by June 1983 per 10CFR50 54
DUTTON,D E Georgia Power Co 83/04/21 EISENHUT,D G Office of Nuclear Reactor Regulation, Director 1p 18342 026, 24X Fiche 50-424,83/04/21,8305050086

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

H General correspondence

8305030261 Requests changes in correspondence routines due to recent mgt changes
GUCWA,L T Georgia Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18300 046 24X Fiche 50-000,83/04/28,8305030261

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270330 Forwards IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/28
KELLY,R J Georgia Power Co 2pp 18641 112 24X Fiche 50-424,83/03/28,8305270330

--8305270337 IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted Major areas inspected lifting & installation of NSSS components, automatic welding of pipe & electrical control terminations
SANDERS,W F Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/03/28. 6pp 18641 114 24X Fiche 50-424,83/03/28,8305270330

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381:291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382.047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441.170 24X Fiche 50-000,83/05/03,8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl.
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co. of New York, Inc 112pp. 18382.282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270320 Forwards IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/10
KELLY,R J Georgia Power Co 2pp 18642 217 24X
Fiche 50-424,83/05/10,8305270320

--8305270328 IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted Major areas inspected general observations of work in progress,observations of primary pipe welding & preparations for heavy lifts
SANDERS,W F Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/05/09 4pp 18642 219 24X Fiche 50-424,83/05/10,8305270320

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil, " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

B. Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RANE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C, Director's Office, Office of Inspection and Enforcement 5pp 18405:095 24X Fiche 50-000,83/04/21,8305110427

8305100161 Interim deficiency rept re pipe support design calculations Initially reported on 830325 Engineering evaluation will not be completed until end of yr Schedule for completion of evaluation expected by 831201
FOSTER,D O Georgia Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 1p 18374 271 24X Fiche 50-424,83/04/29, 8305100161

8305250452 Advises that final rept re sheared pinion keys in Limitorque motor operators will be submitted by 830610
FOSTER,D O. Georgia Power Co 83/05/16 O'REILLY,J P. Region 2, Office of Director 1p 18585 211 24X Fiche 50-424,83/05/16, 8305250452

DOCKET 50-425 ALVIN W VOGTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305050086 Notifies that update to PBAR Chapter 17 outlining QA organizational change will be provided by June 1983 per 10CFR50 54.
DUTTON,D E. Georgia Power Co. 83/04/21 EISENHUT,D G. Office of Nuclear Reactor Regulation, Director. 1p 18342 026 24X
Fiche 50-424,83/04/21,8305050086

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

H General correspondence

8305030261 Requests changes in correspondence routines due to recent mgt changes
GUCHA,L T Georgia Power Co 83/04/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18300 046 24X
Fiche 50-000,83/04/28,8305030261

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270330 Forwards IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/03/28
KELLY,R J Georgia Power Co 2pp 18641 112 24X
Fiche 50-424,83/03/28,8305270330

--8305270337 IE Insp Repts 50-424/83-07 & 50-425/83-07 on 830115-0308 No noncompliance noted Major areas inspected lifting & installation of NSSS components,automatic welding of pipe & electrical control terminations
SANDERS,W F Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/03/28 6pp 18641 114 24X Fiche 50-424,83/03/28,8305270330

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382,282 24X Fiche:50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche:50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270320 Forwards IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted
DANCE,H C Division of Project & Resident Programs 83/05/10
KELLY,R J Georgia Power Co 2pp 18642 217 24X
Fiche 50-424,83/05/10,8305270320

--8305270328 IE Insp Repts 50-424/83-08 & 50-425/83-08 on 830309-0412 No noncompliance noted Major areas inspected general observations of work in progress,observations of primary pipe welding & preparations for heavy lifts
SANDERS,W F Region 2, Office of Director BROWNLEE,V L
Division of Project & Resident Programs 83/05/09 4pp
18642 219 24X Fiche 50-424,83/05/10,8305270320

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/09/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000,83/04/21,8305110427

8305100161 Interim deficiency rept re pipe support design calculations Initially reported on 830325 Engineering evaluation will not be completed until end of yr Schedule for completion of evaluation expected by 831201
FOSTER,D D Georgia Power Co 83/04/29 O'REILLY,J P Region 2, Office of Director 1p 18374 271 24X Fiche 50-424,83/04/29,8305100161

8305250452 Advises that final rept re sheared pinion keys in Limitorque motor operators will be submitted by 830610
FOSTER,D D Georgia Power Co 83/05/16 O'REILLY,J P Region 2, Office of Director 1p 18595 211 24X Fiche 50-424,83/05/16,8305250452

DOCKET STN-50-437 FLOATING NUCLEAR PLANT

A Application/construction stage documents & correspondence

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N
Commissioners 22pp 18537 139 24X Fiche 50-000,83/05/04,8305040323

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305030598 Advises that applicable recommendations contained in B&W Topical Rept BAW-1564, "Integrated Control Sys Reliability Analysis," will be implemented prior to fuel loading to fulfill requirements of NUREG-0737,Item II K 2 9
MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM,E
Licensing Branch 4 1p 18303 299 24X Fiche 50-438,83/04/26,8305030598

8305100358 Forwards addl documentation re Code Case N-192 for use of flexible metal instrumentation hose W/one oversize proprietary drawing Drawing withheld (may contain company sensitive info) Aperture card in Central Files
MILLS,L M Tennessee Valley Authority 83/05/04 ADENSAM,E
Licensing Branch 4 1p 18377 275 24X Fiche 50-438,83/05/04,8305100358

--8305100369 "Design Spec BNP-DS-1940-4809-R0 Flexible Metal Instrumentation Hoses for Instrumentation & Control Sys "
BELTZ,I L Tennessee Valley Authority 80/09/03 7pp
18377 277 24X Fiche 50-438,83/05/04,8305100358

--8305100382 Rev A to "Documentation of Compliance for MBC Part 78153 to Requirements of ASME Section III NC-3649 & Code Case N-92 & N-198-1 "
NYSTROM,R H Metal Bellows Corp CR 730 RA 80/10/17 8pp
18377 284 24X Fiche 50-438,83/05/04,8305100358

--8305100395 Rev A to "Design Rept for Hose Assembly Flexible Metal Per ASME Boiler & Pressure Vessel Code Section III,Subsection NC,Class 2 "
NYSTROM,R H Metal Bellows Corp CR 729 RA 80/10/17 31pp
18377 292 24X Fiche 50-438,83/05/04,8305100358

8305100240 Forwards response to Unresolved Safety Issues A-1,A-5,A-11, A-12,A-17,A-40,A-43,A-44,A-45,A-46,A-47,A-48 & A-49 Responses support position that plant can be operated safely until resolution of open items
MILLS,L M Tennessee Valley Authority 83/05/05 ADENSAM,E
Licensing Branch 4 26pp 18372 298 24X Fiche 50-438,83/05/05,8305100240

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153, 24X
Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations
83/05/13 PALLADINO,N J, Commissioners 5pp 18593 322. 24X
Fiche 50-000,83/05/13,8305240213

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J.M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18309 319 24X Fiche 50-000,83/03/21,8212060385

8305270524 Forwards IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/04/11,
PARRIS,H G, Tennessee Valley Authority, 2pp, 18646 175, 24X
Fiche 50-438,83/04/11,8305270524

--8305270537 IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17 No noncompliance noted Major areas inspected item reported by licensee under 10CFR50 55(e) re excessive vibration of ERCW pump/motor
LIU,W C , BLAKE,J.J Region 2, Office of Director 83/04/07
3pp 18646 177 24X Fiche 50-438,83/04/11,8305270524.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 12App 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305270589 Ack receipt of 830331 & 0418 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02
VERRELLI, D M Division of Project & Resident Programs 83/04/29
PARRIS, H G Tennessee Valley Authority 2pp 18646 215 24X
Fiche 50-438,83/04/29,8305270589

--8305270597 Addl response to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Item B of noncompliance in area of flushing & hydrostatic testing & related procedures disputed
MILLS, L M Tennessee Valley Authority 83/04/18 O'REILLY, J P
Region 2, Office of Director 3pp 18646 217 24X
Fiche 50-438,83/04/29,8305270589

--8305270608 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Corrective actions document control unit performing review of craft drawings & will resolve discrepancies
MILLS, L M Tennessee Valley Authority 83/03/31 O'REILLY, J P
Region 2, Office of Director 4pp 18646 220 24X
Fiche 50-438,83/04/29,8305270589

--8305270616 Forwards IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/02/25
PARRIS, H G Tennessee Valley Authority 2pp 18646 224 24X
Fiche 50-438,83/04/29,8305270589

--8305270619 Notice of violation from insp on 830101-31
* Region 2, Office of Director 83/02/25 2pp 18646 226 24X
Fiche 50-438,83/04/29,8305270589

--8305270629 IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 Noncompliance noted failure to control installation of supports for remote valve operators, inadequate drawing control & inadequate const operating instructions
WILCOX, J D Region 2, Office of Director FREDRICKSON, P
Division of Project & Resident Programs 83/02/25 14pp.
18646 228. 24X Fiche 50-438,83/04/29,8305270589

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl.
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc. 112pp. 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305270372 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03
VERRELLI, D M Division of Project & Resident Programs 83/05/04
PARRIS, H G Tennessee Valley Authority 1p 18642 337 24X
Fiche 50-438,83/05/04,8305270372

--8305270386 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03 Corrective actions inspector reinstructed to verify concrete patch curing record completion
MILLS, L M Tennessee Valley Authority 83/04/22 O'REILLY, J P
Region 2, Office of Director 5pp 18642 338 24X
Fiche 50-438,83/05/04,8305270372

--8305270396 Forwards IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/03/25
PARRIS, H G Tennessee Valley Authority 2pp 18642 343 24X
Fiche 50-438,83/05/04,8305270372

--8305270398 Notice of violation from insp on 830207-18
* Region 2, Office of Director 83/03/25 2pp 18642 345 24X
Fiche 50-438,83/05/04,8305270372

--8305270415 IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 Noncompliance noted failure to properly cure concrete repair patch & failure to train electrical craft foremen in procedure for structural steel installations
HARRIS, J R Region 2, Office of Director CONLON, T E Division of Project & Resident Programs 83/03/23 11pp 18642 347 24X
Fiche 50-438,83/05/04,8305270372

8305270582 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04
VERRELLI, D M Division of Project & Resident Programs 83/05/05
PARRIS, H G Tennessee Valley Authority 1p 18646 301 24X
Fiche 50-438,83/05/05,8305270582

--8305270592 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04 Corrective actions cable reconfigured to produce acceptable bend radius & proper torque values for side bolting obtained from vendor
KAMMER, D B Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 5pp 18646 302 24X
Fiche 50-438,83/05/05,8305270582

--8305270601 Forwards IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/03/25
PARRIS, H G Tennessee Valley Authority 2pp 18646 307. 24X
Fiche 50-438,83/05/05,8305270582

--8305270607 Notice of violation from insp on 830207-18
* Region 2, Office of Director 83/03/25 1p 18646 309 24X
Fiche 50-438,83/05/05,8305270582

--8305270618 IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18 Noncompliance noted bend at trays TY5-A649-A, TY5A561-B & TY4AA91-A exceeded General Const Spec 0-38 min radius
BUFF, A B Region 2, Office of Director CONLON, T E Division of Project & Resident Programs 83/03/23 14pp 18646 310 24X
Fiche 50-438,83/05/05,8305270582

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp. 18523 248 24X Fiche: 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030252 Final Deficiency Rept NCR 1690 re nonconforming seismic support lugs on 2-inch or less steel pipe Initially reported on 811225 Designs & procedures modified & fabrication techniques changed to reduce welding
MILLS,L M Tennessee Valley Authority 83/04/25 O'REILLY,J P
Region 2, Office of Director 3pp 18300 051 24X
Fiche 50-438,83/04/25,8305030252

8305030370 Seventh interim deficiency rept re failure of bolts & nuts to meet ASTM specs Initially reported on 810924 Results of analysis of bolting matl will be evaluated Next rept will be submitted by 830707 Also reported per 10CFR21
MILLS,L M Tennessee Valley Authority 83/04/25 O'REILLY,J P
Region 2, Office of Director 2pp 18306 217 24X
Fiche 50-438,83/04/25,8305030370

8305050120 Second interim deficiency rept re improperly qualified nozzle loads Initially reported on 830124 Fifty-five problems identified & 62 problems remain to be investigated Next rept expected by 831017
MILLS,L M Tennessee Valley Authority 83/04/27 O'REILLY,J P
Region 2, Office of Director 2pp 18337 133 24X
Fiche 50-438,83/04/27,8305050120

8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
MILLS,L M Tennessee Valley Authority 83/04/27 O'REILLY,J P
Region 2, Office of Director 3pp 18341 083 24X
Fiche 50-000,83/04/27,8305050152

8305050122 Second interim deficiency rept re unqualified flex-hose connections Initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 83/04/28 O'REILLY,J P
Region 2, Office of Director 2pp 18342 198 24X
Fiche 50-438,83/04/28,8305050122

8305050189 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per QA program Initially reported on 830329 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706
MILLS,L M Tennessee Valley Authority 83/04/28 O'REILLY,J P
Region 2, Office of Director 2pp 18341 076 24X
Fiche 50-000,83/04/28,8305050189

8305110304 First interim deficiency rept re outdated design criteria for DHR & core flooding sys Initially reported on 830405 Latest approved B&W descriptions reviewed to determine adequacy of latest util design Next rept by 831123
MILLS,L M Tennessee Valley Authority 83/05/02 O'REILLY,J P
Region 2, Office of Director 2pp 18393 235 24X
Fiche 50-438,83/05/02,8305110304

8305110406 Third interim deficiency rept re undersized fillet welds made before mid-1980 Initially reported on 820722 Craftsmen & inspectors not in possession of fillet gauges to determine proper weld size Insp continuing Next rept by 831205
MILLS,L M Tennessee Valley Authority 83/05/02 O'REILLY,J P
Region 2, Office of Director 2pp 18406 187 24X
Fiche 50-438,83/05/02,8305110406

8305110319 First interim rept re Deficiencies 1,2 & 3 QA program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc Written instructions & procedures not provided to contractor in performing/documenting piping analysis Review underway
MILLS,L M Tennessee Valley Authority 83/05/05 O'REILLY,J P
Region 2, Office of Director 3pp 18393 181 24X
Fiche 50-000,83/05/05,8305110319

8305130147 Second interim deficiency rept re backflow not considered for ERCW booster pump shutoff Initially reported on 821230 Design criteria diagram for ERCW modified to include check valves Next rept will be submitted by 840719
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J P.
Region 2, Office of Director 2pp 18438 122 24X
Fiche 50-438,83/05/06,8305130147

8305130154 First interim deficiency rept re defects in pipe clamps mfg by ITT Grinnell Initially reported on 830406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 83/05/06 O'REILLY,J P
Region 2, Office of Director 3pp. 18437 182 24X
Fiche 50-438,83/05/06,8305130154

8305200569 Fourth interim deficiency rept re implementation of QA test documentation on radiation monitoring equipment Initially reported on 820824 QA Technologies will field test monitor & rewrite test travelers Next rept by 831228
MILLS,L M Tennessee Valley Authority 83/05/11 O'REILLY,J P
Region 2, Office of Director 1p 18514 277 24X
Fiche 50-438,83/05/11,8305200569

8305200187 Final deficiency rept re unauthorized use of QC stamp Initially reported on 821216 Identification markings on items cited by rept have been obliterated & items scrapped QC personnel trained on proper use & security
MILLS,L M Tennessee Valley Authority 83/05/16 O'REILLY,J P
Region 2, Office of Director 2pp 18519 001 24X
Fiche 50-438,83/05/16,8305200187

8305200519 First interim deficiency rept re inadequate Calculation TI-ECS-47, "Common Zone & Fuel Handling Area Tornado Depressurization Analysis " Initially reported on 830414 Initial review indicated walls & floors maintain integrity
MILLS,L M Tennessee Valley Authority 83/05/16 O'REILLY,J P
Region 2, Office of Director 2pp. 18516 083 24X
Fiche 50-438,83/05/16,8305200519

8305230545 Second interim rept re generic deficiencies at Consolidated Controls Corp Initially reported on 820916 Evaluation indicates QC problems corrected & equipment failures random Also reported per Part 21 Next rept by 831117
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J P.
Region 2, Office of Director 2pp 18537 085 24X
Fiche 50-438,83/05/18,8305230545

8305230551 Third interim deficiency rept re lack of environ qualification for equipment in auxiliary bldg due to potential failure of startup & rcirculation sys Initially reported on 820422 Design work ongoing Next rept by 840217
MILLS,L M Tennessee Valley Authority 83/05/18 O'REILLY,J P
Region 2, Office of Director 2pp 18537 333 24X
Fiche,50-438,83/05/18,8305230551

8305230565 Final deficiency rept re use of unqualified TVA-designed fillet welds on piping lugs Initially reported on 820819. Calculation package for lugs complete Procedures for designing fillet-welded lugs incorporated
MILLS,L M Tennessee Valley Authority 83/05/18, O'REILLY,J.P
Region 2, Office of Director 2pp 18537 092 24X
Fiche 50-438,83/05/18,8305230565

8305310138 Seventh interim deficiency rept re inconsistency between assumptions for pipe break in LOCA & structural analyses for connecting pipes in affected loop Initially reported on 801121 Next rept by 831118 Also reported per Part 21.
MILLS,L M Tennessee Valley Authority 83/05/23 O'REILLY,J.P
Region 2, Office of Director 2pp 18656 125 24X
Fiche 50-438,83/05/23,8305310138

8305310193 First interim deficiency rept re power cable bend radii in vertical to horizontal trays Initially reported on 830422 Vendor assistance will be requested to determine min acceptable bend radius
MILLS,L M Tennessee Valley Authority 83/05/23 O'REILLY,J P
Region 2, Office of Director 2pp 18651.004 24X
Fiche 50-438,83/05/23,8305310193

8305310214 Eighth interim deficiency rept re B&W nonconservative analysis of neutron flux. Initially reported on 801105. Also reportable per Part 21 Util awaiting results of B&W analysis Next rept will be submitted by 831024
MILLS,L.M Tennessee Valley Authority 83/05/23 O'REILLY,J.P
Region 2, Office of Director 2pp 18658 146 24X
Fiche 50-438,83/05/23,8305310214

DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305030558 Advises that applicable recommendations contained in B&W Topical Rept BAW-1564, "Integrated Control Sys Reliability Analysis," will be implemented prior to fuel loading to fulfill requirements of NUREG-0737, Item II K 2.9.
MILLS,L M Tennessee Valley Authority 83/04/26 ADENSAM,E
Licensing Branch 4 1p. 18303 299 24X Fiche,50-438,83/04/26,
8305030558

8305100358 Forwards addl documentation re Code Case N-192 for use of flexible metal instrumentation hose W/one oversize proprietary drawing Drawing withheld (may contain company sensitive info) Aperture card in Central Files
MILLS,L M Tennessee Valley Authority 83/05/04 ADENSAM,E
Licensing Branch 4 1p 18377 275 24X Fiche,50-438,83/05/04,
8305100358

--8305100369 "Design Spec BNP-DS-1940-4809-R0 Flexible Metal Instrumentation Hoses for Instrumentation & Control Sys "
BELTZ, I L Tennessee Valley Authority 80/09/03 7pp
18377 277 24X Fiche 50-438,83/05/04,8305100358

--8305100382 Rev A to "Documentation of Compliance for MBC Part 78153 to Requirements of ASME Section III NC-3649 & Code Case N-92 & N-188-1 "
NYSTROM,R H Metal Bellows Corp CR 730 RA 80/10/17 8pp
18377 284 24X Fiche 50-438,83/05/04,8305100358

--8305100395 Rev A to "Design Rept for Hose Assembly Flexible Metal Per ASME Boiler & Pressure Vessel Code Section III,Subsection NC,Class 2 "
NYSTROM,R H Metal Bellows Corp CR 729 RA 80/10/17 31pp
18377 292 24X Fiche 50-438,83/05/04,8305100358

8305100240 Forwards response to Unresolved Safety Issues A-1,A-5,A-11, A-12,A-17,A-40,A-43,A-44,A-45,A-46,A-47,A-48 & A-49 Responses support position that plant can be operated safely until resolution of open items
MILLS,L M Tennessee Valley Authority 83/05/05 ADENSAM,E Licensing Branch 4 26pp 18372 298 24X Fiche 50-438,83/05/05, 8305100240

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT,D G. Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche:50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc. 16pp 18540 095 24X
Fiche.50-000,83/05/11,8305110034

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305270524 Forwards IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17.No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs. 83/04/11.
PARRIS,H G Tennessee Valley Authority 2pp 18646:175 24X
Fiche.50-438,83/04/11,8305270524

--8305270537 IE Insp Repts 50-438/83-09 & 50-439/83-09 on 830316-17 No noncompliance noted Major areas inspected item reported by licensee under 10CFR50 55(e) re excessive vibration of ERCW pump/motor
LIU,W.C., BLAKE,J J Region 2, Office of Director. 83/04/07
5pp. 18646 177. 24X Fiche 50-438,83/04/11,8305270524

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383 089 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E.L. -Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/25 Consolidated Edison Co. of New York, Inc 119pp. 18381 291. 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305270589 Ack receipt of 830331 & 0418 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02
VERRELLI,D M Division of Project & Resident Programs 83/04/29
PARRIS,H G Tennessee Valley Authority 2pp 18646 215 24X
Fiche 50-438,83/04/29,8305270589

--8305270597 Addl response to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Item B of noncompliance in area of flushing & hydrostatic testing & related procedures disputed
MILLS,L M Tennessee Valley Authority 83/04/18 O'REILLY,J P
Region 2, Office of Director 3pp 18646 217 24X
Fiche 50-438,83/04/29,8305270589

--8305270608 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-438/83-02 & 50-439/83-02 Corrective actions document control unit performing review of craft drawings & will resolve discrepancies
MILLS,L M Tennessee Valley Authority 83/03/31 O'REILLY,J P
Region 2, Office of Director 4pp 18646 220 24X
Fiche 50-438,83/04/29,8305270589

--8305270616 Forwards IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 & notice of violation
VERRELLI,D M Division of Project & Resident Programs 83/02/25.
PARRIS,H G Tennessee Valley Authority 2pp 18646 224 24X
Fiche 50-438,83/04/29,8305270589

--8305270619 Notice of violation from insp on 830101-31
* Region 2, Office of Director 83/02/25 2pp 18646 226 24X
Fiche 50-438,83/04/29,8305270589

--8305270629 IE Insp Repts 50-438/83-02 & 50-439/83-02 on 830101-31 Noncompliance noted failure to control installation of supports for remote valve operators,inadequate drawing control & inadequate const operating instructions
WILCOX,J D Region 2, Office of Director FREDRICKSON,P
Division of Project & Resident Programs 83/02/25 14pp.
18646 228 24X Fiche 50-438,83/04/29,8305270589

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305270372 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03
VERRELLI,D M Division of Project & Resident Programs. 83/05/04
PARRIS,H G Tennessee Valley Authority 1p 18642 337. 24X
Fiche 50-438,83/05/04,8305270372

--8305270386 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-03 & 50-439/83-03 Corrective actions inspector reinstructed to verify concrete patch curing record completion
MILLS,L M. Tennessee Valley Authority 83/04/22 O'REILLY,J P
Region 2, Office of Director 5pp 18642 338 24X
Fiche 50-438,83/05/04,8305270372

--8305270396 Forwards IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18 & notice of violation.
VERRELLI,D.M Division of Project & Resident Programs 83/03/25
PARRIS,H G. Tennessee Valley Authority 2pp 18642·343 24X
Fiche·50-438,83/05/04,8305270372.

--8305270398 Notice of violation from insp on 830207-18
* Region 2, Office of Director 83/03/25 2pp 18642·345 24X
Fiche 50-438,83/05/04,8305270372.

--8305270415 IE Insp Repts 50-438/83-03 & 50-439/83-03 on 830207-18
Noncompliance noted failure to properly cure concrete repair patch & failure to train electrical craft foremen in procedure for structural steel installations
HARRIS, J R Region 2, Office of Director CONLON, T E Division of Project & Resident Programs 83/03/23 11pp 18649 347 24X
Fiche 50-438, 83/05/04, 8305270372

8305270582 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04
VERRELLI, D M Division of Project & Resident Programs 83/05/05
PARRIS, H G Tennessee Valley Authority 1p 18646 301 24X
Fiche 50-438, 83/05/05, 8305270582

--8305270592 Responds to NRC 830325 ltr re violations noted in IE Insp Repts 50-438/83-04 & 50-439/83-04 Corrective actions cable reconfigured to produce acceptable bend radius & proper torque values for side bolting obtained from vendor
KAMMER, D S Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 5pp 18646 302 24X
Fiche 50-438, 83/05/05, 8305270582

--8305270601 Forwards IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18 & notice of violation
VERRELLI, D M Division of Project & Resident Programs 83/03/25
PARRIS, H G Tennessee Valley Authority 2pp 18646 307 24X
Fiche 50-438, 83/05/05, 8305270582

--8305270607 Notice of violation from insp on 830207-18
* Region 2, Office of Director 83/03/25 1p 18646 309 24X
Fiche 50-438, 83/05/05, 8305270582

--8305270618 IE Insp Repts 50-438/83-04 & 50-439/83-04 on 830207-18
Noncompliance noted bend at trays TY5-A649-A, TY5A561-B & TY4AA91-A exceeded General Const Spec G-38 min radius
RUFF, A B Region 2, Office of Director CONLON, T E Division of Project & Resident Programs 83/03/23 14pp 18646 310 24X
Fiche 50-438, 83/05/05, 8305270582

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007. 24X Fiche 50-000, 83/05/26, 8303040046

B Reportable occurrences, LERs & related correspondence

8305030252 Final Deficiency Rept NCR 1690 re nonconforming seismic support lugs on 2-inch or less steel pipe Initially reported on 811225 Designs & procedures modified & fabrication techniques changed to reduce welding
MILLS, L M Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 3pp 18300 051 24X
Fiche 50-438, 83/04/25, 8305030252

8305030370 Seventh interim deficiency rept re failure of bolts & nuts to meet ASTM specs. Initially reported on 810924 Results of analysis of bolting matl will be evaluated Next rept will be submitted by 830707 Also reported per 10CFR21
MILLS, L M Tennessee Valley Authority 83/04/25 O'REILLY, J P
Region 2, Office of Director 2pp 18306 217 24X
Fiche 50-438, 83/04/25, 8305030370

8305050120 Second interim deficiency rept re improperly qualified nozzle loads Initially reported on 830124 Fifty-five problems identified & 62 problems remain to be investigated. Next rept expected by 831017
MILLS, L M Tennessee Valley Authority 83/04/27 O'REILLY, J P
Region 2, Office of Director 2pp 18337 133 24X
Fiche 50-438, 83/04/27, 8305050120

8305050152 Final rept for Deficiencies A & D re procurement control activities which could lead to shipment of defective equipment & adversely affect plant safety Initially reported on 810316
MILLS, L M Tennessee Valley Authority 83/04/27 O'REILLY, J P.
Region 2, Office of Director 3pp 18341 083 24X
Fiche 50-000, 83/04/27, 8305050152

8305050122 Second interim deficiency rept re unqualified flex-hose connections Initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21
MILLS, L M Tennessee Valley Authority 83/04/28 O'REILLY, J P
Region 2, Office of Director 2pp 18342 198 24X
Fiche 50-438, 83/04/28, 8305050122

8305050188 First interim deficiency rept re tubeline matls supplied by Capital Pipe not mfg per QA program Initially reported on 830329 Investigation of involved carbon steel fittings & flanges continuing Next rept expected by 830706
MILLS, L M Tennessee Valley Authority 83/04/28 O'REILLY, J P
Region 2, Office of Director 2pp 18341 076 24X
Fiche 50-000, 83/04/28, 8305050188

8305110292 Third interim deficiency rept re linear indications in Natl Valve & Mfg Co spool pieces Initially reported on 820924. Vendor requested to supply list of spool pieces w/Heat Code L63687 Util awaiting reply Also reportable per Part 21.
MILLS, L M Tennessee Valley Authority 83/05/02. O'REILLY, J. P.
Region 2, Office of Director 2pp 18393 254 24X
Fiche 50-439, 83/05/02, 8305110292

8305110304 First interim deficiency rept re outdated design criteria for DHR & core flooding sys Initially reported on 830405. Latest approved B&W descriptions reviewed to determine adequacy of latest util design Next rept by 831123.
MILLS, L M Tennessee Valley Authority 83/05/02 O'REILLY, J.P
Region 2, Office of Director 2pp 18393 235 24X
Fiche 50-438, 83/05/02, 8305110304

8305110406 Third interim deficiency rept re undersized fillet welds made before mid-1980 Initially reported on 820722 Craftsmen & inspectors not in possession of fillet gauges to determine proper weld size Insp continuing Next rept by 831205
MILLS, L M Tennessee Valley Authority 83/05/02 O'REILLY, J P.
Region 2, Office of Director 2pp 18406 187. 24X
Fiche 50-438, 83/05/02, 8305110406

8305110441 Final deficiency rept re faulty relays mfg by Brown Boveri Electric in auxiliary power distribution sys Initially reported on 820528 Four relays returned to vendor for repair & reinstalled at facility Also reported per 10CFR21.
MILLS, L M Tennessee Valley Authority. 83/05/02. O'REILLY, J.P
Region 2, Office of Director 2pp 18393 348 24X
Fiche 50-439, 83/05/02, 8305110441

8305130089 First interim deficiency rept re drawing discrepancy for in-core monitor tank sleeves Initially reported on 830405 Use of tank sleeves in present configuration under investigation Next rept will be submitted by 831222
MILLS, L M Tennessee Valley Authority 83/05/04. O'REILLY, J P
Region 2, Office of Director 2pp 18437 256 24X
Fiche 50-439, 83/05/04, 8305130089

8305110319 First interim rept re Deficiencies 1, 2 & 3. QA program per TVA Personal Svcs Contract TV-49510A w/Gilbert Assoc Written instructions & procedures not provided to contractor in performing/documenting piping analysis Review underway
MILLS, L M Tennessee Valley Authority 83/05/05. O'REILLY, J P
Region 2, Office of Director 3pp 18393 181 24X
Fiche 50-000, 83/05/05, 8305110319

8305130147 Second interim deficiency rept re backflow not considered for ERCW booster pump shutoff Initially reported on 821230. Design criteria diagram for ERCW modified to include check valves Next rept will be submitted by 840719
MILLS, L M Tennessee Valley Authority 83/05/06 O'REILLY, J P
Region 2, Office of Director. 2pp 18438 122. 24X
Fiche 50-438, 83/05/06, 8305130147

8305130154 First interim deficiency rept re defects in pipe clamps mfg by ITT Grinnell Initially reported on 830406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21
MILLS, L M Tennessee Valley Authority 83/05/06. O'REILLY, J P
Region 2, Office of Director 3pp. 18437 182 24X
Fiche 50-438, 83/05/06, 8305130154

8305200569 Fourth interim deficiency rept re implementation of QA test documentation on radiation monitoring equipment Initially reported on 820824. QA Technologies will field test monitor & rewrite test travelers Next rept by 831228.
MILLS, L M Tennessee Valley Authority 83/05/11. O'REILLY, J.P.
Region 2, Office of Director 1p 18514 277 24X
Fiche 50-438, 83/05/11, 8305200569

8305200187 Final deficiency rept re unauthorized use of QC stamp
Initially reported on 821216 Identification markings on
items cited by rept have been obliterated & items scrapped
QC personnel trained on proper use & security
MILLS, L M Tennessee Valley Authority 83/05/16 O'REILLY, J P
Region 2, Office of Director 2pp 18519 001 24X
Fiche 50-438, 83/05/16, 8305200187

8305200519 First interim deficiency rept re inadequate Calculation
TI-ECS-47, "Common Zone & Fuel Handling Area Tornado
Depressurization Analysis " Initially reported on 830414
Initial review indicated walls & floors maintain integrity
MILLS, L M Tennessee Valley Authority 83/05/16 O'REILLY, J P
Region 2, Office of Director 2pp 18516 083 24X
Fiche 50-438, 83/05/16, 8305200519

8305230545 Second interim rept re generic deficiencies at Consolidated
Controls Corp Initially reported on 820916 Evaluation
indicates QC problems corrected & equipment failures random
Also reported per Part 21 Next rept by 831117
MILLS, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director 2pp 18537 085 24X
Fiche 50-438, 83/05/18, 8305230545

8305230551 Third interim deficiency rept re lack of environ
qualification for equipment in auxiliary bldg due to
potential failure of startup & recirculation sys Initially
reported on 820422 Design work ongoing Next rept by 840217
MILLS, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director 2pp 18537 333 24X
Fiche 50-438, 83/05/18, 8305230551

8305230565 Final deficiency rept re use of unqualified TVA-designed
fillet welds on piping lugs Initially reported on 820819
Calculation package for lugs complete Procedures for
designing fillet-welded lugs incorporated
MILLS, L M Tennessee Valley Authority 83/05/18 O'REILLY, J P
Region 2, Office of Director 2pp 18537 092 24X
Fiche 50-438, 83/05/18, 8305230565

8305310138 Seventh interim deficiency rept re inconsistency between
assumptions for pipe break in LOCA & structural analyses
for connecting pipes in affected loop Initially reported on
801121, Next rept by 831118 Also reported per Part 21
MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
Region 2, Office of Director 2pp 18656 125 24X
Fiche 50-438, 83/05/23, 8305310138

8305310193 First interim deficiency rept re power cable bend radii in
vertical to horizontal trays Initially reported on 830422
Vendor assistance will be requested to determine min
acceptable bend radius
MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
Region 2, Office of Director 2pp 18651 004 24X
Fiche: 50-438, 83/05/23, 8305310193

8305310214 Eighth interim deficiency rept re B&W nonconservative
analysis of neutron flux Initially reported on 801105 Also
reportable per Part 21 Util awaiting results of B&W
analysis. Next rept will be submitted by 831024
MILLS, L M Tennessee Valley Authority 83/05/23 O'REILLY, J P
Region 2, Office of Director 2pp 18658 146 24X
Fiche, 50-438, 83/05/23, 8305310214

DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

A Application/construction stage documents & correspondence

8303280059 Forwards seismic qualification & pump valve operability
info, per 830203 request Repts on floor response spectra,
seismic summary listing, revised PVORT & seismic
qualification review team forms included
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/16
YOUNGBLOOD, B J Licensing Branch 1 1,704pp 17701 001 24X
Fiche: 50-440, 83/03/16, 8303280059

8305040289 Advises that effective 830418, JJ Stefano designated
Licensing Review Group II program project manager Change
will help expedite reviews on disposition of remaining
generic issues
NOVAK, T M Assistant Director for Licensing, 83/04/26,
HOLTZSCHER, D L, Illinois Power Co 2pp 18326 343 24X
Fiche: 50-000, 83/04/26, 8305040289

8305190096 Advises of NRC evaluation findings of automatic
depressurization sys logic mod options in response to TMI
Action Item II K.3 18 Util should advise NRC of which action
will be implemented & furnish necessary design & info
YOUNGBLOOD, B J. Licensing Branch 1 83/04/27 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18523 194 24X
Fiche 50-440, 83/04/27, 8305190096

8305090277 Forwards Board Notification (BN) 83-58 previously
transmitted as BN 83-13, forwarding EG&G draft rept,
"Identification & Ranking of Nuclear Plant Structures, Sys &
Components & Graded QA Guidelines " W/o BN 83-58
NOVAK, T M Assistant Director for Licensing 83/05/02 Atomic
Safety and Licensing Board Panel 6pp 18366 275 24X
Fiche 50-440, 83/05/02, 8305090277

8305190046 Commends representatives of BWR/6 utils participating in
Licensing Review Group II for efforts in resolving issues
generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190054 Commends representatives of BWR/6 utils participating in
Licensing Review Group II for efforts in resolving issues
generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 HALE, D P
Illinois Power Co 2pp 18523 200 24X Fiche 50-000, 83/05/03,
8305190046

--8305190060 Commends representatives of BWR/6 utils participating in
Licensing Review Group II for efforts in resolving issues
generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 FERGUSON, M R
Washington Public Power Supply System 2pp 18523 202 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190068 Commends representatives of BWR/6 utils participating in
Licensing Review Group II for efforts in resolving issues
generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 MCGAUGHY, J P
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190077 Commends representatives of BWR/6 utils participating in
Licensing Review Group II for efforts in resolving issues
generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 CAHILL, J Gulf
States Utilities Co 2pp 18523 206 24X Fiche 50-000, 83/05/03,
8305190046

8305040323 Board Notification 83-057 forwards differing prof opinions
re sys interaction & safety classification Info relates to
Board Notifications 83-17 & 83-44 re Unresolved Safety Issue
A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N
Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04,
8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees &
holders of CPs re integrated scheduling for implementation
of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated
Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305230143 Responds to 821214 & 830401 requests for addl info re safety
relief valve piping & quencher device & safety-related
piping supports Info will be provided 830630 for Questions
210 10 & 210 11 & 840630 for Question 210 9
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/16
YOUNGBLOOD, B J Licensing Branch 1 1p 18539 187 24X
Fiche 50-440, 83/05/16, 8305230143

8305250189 Notification of 830526 meeting w/util & Gilbert Assocs in
Bethesda, MD to discuss design for containment purge
STEFANO, J J Licensing Branch 1 83/05/16 YOUNGBLOOD, B J
Licensing Branch 1 3pp 18595 359 24X Fiche 50-440, 83/05/16,
8305250189

8305230290 Forwards addl info re environ equipment qualification
program & plant readiness for audit, in response to 830323
Questions 270 1-270 13 Safety-related equipment, per TMI
Items II D.3 & II F 1, will be added prior to fuel load
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/17,
YOUNGBLOOD, B J Licensing Branch 1 238pp 18529 001 24X
Fiche 50-440, 83/05/17, 8305230290

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8304060126 NUS-4336, "Description of Perry Nuclear Power Plant
Emergency Offsite Dose Calculations "
WILKENSON NUS Corp 83/04/30 44pp 17858 021 24X
Fiche 50-440, 83/04/04, 8304060118,

8305040664 Forwards Suppl 3 to SER (NUREG-0887), W/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/04/27 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18336 266 24X
Fiche 50-440, 83/04/27, 8305040664

8305170096 SAFETY EVALUATION REPORT RELATED TO OPERATION OF THE PERRY NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0887 S03 83/04/30 75pp 18492 303 24X Fiche 50-440,83/04/30,8305170096

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 HOLTZSCHER,D L Illinois Power Co 2pp 18443 173 24X Fiche 50-000,83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs. Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 POWELL,P Washington Public Power Supply System 1p. 18443 174 24X
Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 REED,W J Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000,83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 RICHARDSON,J D. Mississippi Power & Light Co 1p 18443 176. 24X
Fiche 50-000,83/05/02,8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J, Licensing Branch 1 83/05/02 BUZZELLI,E M Cleveland Electric Illuminating Co 1p 18443 177 24X
Fiche 50-000,83/05/02,8305120460

8305110300 Forwards response to Human Factors 821112 in-progress audit rept re SER Outstanding Issue 7,control room design review
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/04
YOUNGBLOOD,B.J Licensing Branch 1 21pp 18393 312 24X
Fiche 50-440,83/05/04,8305110300

8305230649 Forwards request for addl info re SER Section 13 5 2 2, "Reanalysis of Transients & Accidents Development of Emergency Operating Procedures " Schedule requested within 7 days of receipt of ltr.
YOUNGBLOOD,B J. Licensing Branch 1 83/05/06 EDELMAN,M.R Cleveland Electric Illuminating Co 6pp 18542:354 24X
Fiche 50-440,83/05/06,8305230649

8305230645 Forwards NUREG-0887,Suppl 3 to SER W/o encl
YOUNGBLOOD,B J Licensing Branch 1 83/05/09. EDELMAN,M R Cleveland Electric Illuminating Co 3pp 18542 360. 24X
Fiche 50-440,83/05/09,8305230645

8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re SER Outstanding Issue 19 Curves dependent on amount of fuel inventory released Revised response to Round 2 Question I 2 submitted on 830404.
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/13
YOUNGBLOOD,B J, Licensing Branch 1 4pp 18539 188. 24X
Fiche 50-440,83/05/13,8305230106.

8305260267 Forwards response to 830307 request for clarifications & addl info re FSAR Table 3 2-1 Suppl 3 to SER issued in Apr referenced same questions as outstanding Issue 23. Info should resolve Outstanding Issue 23 in next SER suppl.
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/19.
YOUNGBLOOD,B J Licensing Branch 1. 11pp 18626 200 24X
Fiche 50-440,83/05/19,8305260267

F. Security, medical, emergency & fire protection plans

8305230649 Forwards request for addl info re SER Section 13.5 2.2, "Reanalysis of Transients & Accidents.Development of Emergency Operating Procedures." Schedule requested within 7 days of receipt of ltr
YOUNGBLOOD,B.J Licensing Branch 1 83/05/06 EDELMAN,M R. Cleveland Electric Illuminating Co. 6pp 18542-354. 24X
Fiche.50-440,83/05/06,8305230649

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re SER Outstanding Issue 19 Curves dependent on amount of fuel inventory released Revised response to Round 2 Question I 2 submitted on 830404
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/13
YOUNGBLOOD,B.J Licensing Branch 1 4pp 18539 188 24X
Fiche 50-440,83/05/13,8305230106

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations, 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

G Adjudicatory correspondence

8305020470 Answer opposing Ohio Citizens for Responsible Energy 830418 motion to hold record open on QA issue Motion based on mere speculation that intervenor witnesses may become available Certificate of Svc encl
SILBERG,J E Commonwealth Edison Co SILBERG,J E Shaw, Pittman, Potts & Trowbridge 83/04/27 Atomic Safety and Licensing Board Panel 7pp 18283 300 24X Fiche 50-440,83/04/27,8305020470

8305040528 Motion for summary disposition of OL application on grounds of matl false statement in amend to environ rept Certificate of Svc encl Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28, Atomic Safety and Licensing Board Panel 18pp 18321.217 24X
Fiche 50-440,83/04/28,8305040528

8305040541 Motion to stay proceeding pending ruling on OH Citizens for Responsible Energy 830428 motion for summary disposition of OL application Certificate of Svc encl Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28, Atomic Safety and Licensing Board Panel. 3pp 18321.276 24X
Fiche.50-440,83/04/28,8305040541

8305040544 Response opposing unmeritable motion for reconsideration & clarification of ASLB 830330 memorandum & order granting NRC motion for summary disposition of Issue 9 on polymer degradation W/Certificate of Svc Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28
Atomic Safety and Licensing Board Panel 4pp 18321·272 24X
Fiche 50-440,83/04/28,8305040544

8305020477 Answer opposing Ohio Citizens for Responsible Energy 830418 motion to hold record open on QA issue Motion premature & grounded on sheer speculation Certificate of Svc encl
CUTCHIN,J M Hearing Branch 4 83/04/29 Atomic Safety and Licensing Board Panel 4pp 18282 359 24X Fiche.50-440,83/04/29, 8305020477

8305040325 Brief supporting Ohio Citizens for Responsible Energy motion to hold record open on QA issue Applicant is moving back const completion date of own volition
WILT,D D Sunflower Alliance 83/04/29 Atomic Safety and Licensing Board Panel. 2pp 18323·293 24X Fiche·50-440,83/04/29, 8305040325

8305040487 Application for subpoenas directed to CM Shuster,of util & to J Keppler,NRC Region III administrator Proof of Svc encl.
WILT,D D. Sunflower Alliance WILT,D D Wilt, D.D 83/04/29. Atomic Safety and Licensing Board Panel 3pp 18319.270 24X
Fiche.50-440,83/04/29,8305040487

8305040548 Request for NRC & util to stipulate to authenticity of documents to be identified by 830518 & request to admit documents as evidence Proof of Svc encl
WILT,D D Sunflower Alliance WILT,D D Wilt, D D 83/04/29. Atomic Safety and Licensing Board Panel. 1p 18321 271 24X
Fiche 50-440,83/04/29,8305040548

8305040307 Response opposing Sunflower Alliance,Inc,et al 830429 motion which requests applicant to stipulate to authenticity of unidentified documents & requests admission of documents as evidence Certificate of Svc encl
SILBERG,J E Cleveland Electric Illuminating Co SILBERG,J E. Shaw, Pittman, Potts & Trowbridge 83/05/02. Atomic Safety and Licensing Board Panel 3pp. 18323.303. 24X Fiche:50-440,83/05/02, 8305040307

8305090487 Informs ASLB that requested documents re matters mentioned in NRC prefiled testimony on Issue 3 will be provided CE Norelius 820910 ltr re special const insp forwarded GA insp rept forthcoming Evaluation encl
CUTCHIN, J M Hearing Branch 4 83/05/06 BLOCH, P B , BRIGHT, G O , KLINE, J R Atomic Safety and Licensing Board Panel 2pp
18361 153 24X Fiche 50-440, 83/05/06, 8305090487

--8305090490 Forwards "Self-Initiated Evaluation," assessing project & committing to maintaining highest quality stds
EDELMAN, M R Cleveland Electric Illuminating Co 82/12/07
KEPPLER, J G Region 3, Office of Director 1p 18361 156 24X
Fiche 50-440, 83/05/06, 8305090487

--8305090493 "Self-Initiated Evaluation "
* Cleveland Electric Illuminating Co 82/10/31 213pp
18361 157 24X Fiche 50-440, 83/05/06, 8305090487

8305100294 Amended application for subpoena directing attendance of CM Shuster & JG Keppler at 830503 hearings on Issue 3 re nonconformance trend analysis sys Proof of Svc encl
WILT, D. D Sunflower Alliance WILT, D D Wilt, D D 83/05/06
SHUSTER, C M Cleveland Electric Illuminating Co KEPPLER, J G Region 3, Office of Director 3pp 18370 139 24X
Fiche 50-440, 83/05/06, 8305100294

8305100367 Brief in support of Ohio Citizens for Responsible Energy 830428 motion for summary disposition of OL application & motion for stay of proceedings Appropriate sanctions should be imposed on applicant Proof of Svc encl
WILT, D D Sunflower Alliance WILT, D D Wilt, D D 83/05/06
Atomic Safety and Licensing Board Panel 7pp 18379 042 24X
Fiche 50-440, 83/05/06, 8305100367

8305160156 Requests to make limited appearance statement at OL hearings
MCCLUSKEY, G Affiliation Unknown 83/05/08 NRC - No Detailed Affiliation Given 1p 18446 086 24X Fiche 50-440, 83/05/08, 8305160156

8305100168 Forwards SER, Suppl 3 (NUREG-0887) W/o encl
CUTCHIN, J M Hearing Branch 4 83/05/08 BLOCH, P B , BRIGHT, G D., KLINE, J R. Atomic Safety and Licensing Board Panel 1p 18374 273 24X Fiche 50-440, 83/05/09, 8305100168

8305120304 Requests to make limited appearance statement at 830523 OL hearings
RENNER, A E Affiliation Unknown 83/05/09 NRC - No Detailed Affiliation Given 1p 18424 206 24X Fiche 50-440, 83/05/09, 8305120304

8305160122 Requests to make limited appearance statement at OL hearings
COOK, G S Affiliation Unknown 83/05/10 NRC - No Detailed Affiliation Given 1p 18450 130 24X Fiche 50-440, 83/05/10, 8305160122,

8305160153 Requests to make limited appearance statement at OL hearings.
GLEISSEN, A Affiliation Unknown 83/05/10 NRC - No Detailed Affiliation Given 1p. 18446 087 24X Fiche 50-440, 83/05/10, 8305160153

8305170305 Objects to characterization of Ohio Citizens for Responsible Energy members as persons advocating disruption, demonstration & disrespect for law, as stated in Sunflower Alliance 830506 brief in support of motion
HIATT, S L Ohio Citizens for Responsible Energy 83/05/10
WILT, D D Wilt, D.D 1p 18465 075. 24X Fiche 50-440, 83/05/10, 8305170305

8305170341 Motion to file contentions, objecting to SNM license issuance unless & until OL granted & facility ready to load fuel Certificate of Svc encl.
HIATT, S. L. Ohio Citizens for Responsible Energy 83/05/10
Atomic Safety and Licensing Board Panel. 21pp 18465 096. 24X
Fiche: 50-440, 83/05/10, 8305170341.

8305170457 Requests opportunity for staff member to make limited appearance statement at 830523 hearing
ECKART, D. E. House of Rep 83/05/11 STUCKY, S Office of the Secretary of the Commission 1p. 18470 141. 24X
Fiche. 50-440, 83/05/11, 8305170457.

8305170461 Requests to make limited appearance statement at 830523 & 31 hearings in Painesville
WALDORF, E. J Affiliation Unknown. 83/05/11 Office of the Secretary of the Commission 1p 18469 318 24X
Fiche 50-440, 83/05/11, 8305170461

8305170464 Requests to make limited appearance statement at OL hearings
BIMBER, R M Affiliation Unknown 83/05/12 NRC - No Detailed Affiliation Given 1p 18469 361 24X Fiche 50-440, 83/05/12, 8305170464

8305170452 Requests to make limited appearance statement at OL hearings
RAJKI, S Affiliation Unknown 83/05/13 Docketing & Services Branch 1p 18469 207 24X Fiche 50-440, 83/05/13, 8305170452

8305190209 Package of seven requests to make limited appearance statement at OL hearings
GAGE, J , HUBBARD, K S , GREENBAUM, R L Affiliation Unknown 83/05/13 NRC - No Detailed Affiliation Given 7pp 18502 188 24X Fiche 50-440, 83/05/13, 8305190209

8305190214 Requests to make limited appearance statement at OL hearings
RUDD, C C Affiliation Unknown 83/05/14 NRC - No Detailed Affiliation Given 1p 18502 237 24X Fiche 50-440, 83/05/14, 8305190214

8305240512 Requests to make limited appearance statement at OL hearings
O'NEILL, K Affiliation Unknown 83/05/15 NRC - No Detailed Affiliation Given 1p 18571 109 24X Fiche 50-440, 83/05/15, 8305240512

8305200656 Requests to make limited appearance statement at OL hearings
ZIVKOVICH, E A , HANDBOY, L , WARCLOUD, J Affiliation Unknown 83/05/17 Office of the Secretary of the Commission 6pp 18519 312 24X Fiche 50-440, 83/05/17, 8305200656

8305200598 Requests to make limited appearance statement at OL hearings
DEVINE, A , THOMPSON, D , MAST, L Affiliation Unknown 83/05/19 Docketing & Services Branch 2pp 18514 104 24X
Fiche 50-440, 83/05/19, 8305200598

8305240515 Update to util 830205 answer to Interrogatory 3 of Sunflower Alliance 811202 first set of interrogatories All three counties have submitted draft plans to Ohio Disaster Svcs Agency Svc list encl Related correspondence
SWIGER, M A Shaw, Pittman, Potts & Trowbridge SWIGER, M A Cleveland Electric Illuminating Co 83/05/19 WILT, D. D Sunflower Alliance WILT, D D Wilt, D D 7pp 18571 125 24X
Fiche 50-440, 83/05/19, 8305240515

8305240544 Requests to make limited appearance statement at OL hearings
FLAGG, D M , FINK, J , REED, J R Affiliation Unknown 83/05/19, Office of the Secretary of the Commission 3pp 18576 040 24X
Fiche 50-440, 83/05/19, 8305240544

H General correspondence

8305310031 Notifies that DD Wilt no longer represents Sunflower Alliance, Inc due to irreconcilable differences & prof responsibility
WILT, D D Wilt, D D 83/05/23 BLOCH, P , KLINE, J R., BRIGHT, G O Atomic Safety and Licensing Board Panel 1p 18653 130 24X
Fiche 50-440, 83/05/23, 8305310031

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8304150362 Forwards IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/04/01 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 17982 129. 24X
Fiche 50-440, 83/04/01, 8304150362

--8304150364 IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted Major areas inspected licensee actions on 10CFR50 55(e) items
WARD, K D , CILIMBERG, R. L , DANIELSON, D H Region 3, Office of Director 83/04/01 9pp. 17982 131 24X Fiche. 50-440, 83/04/01, 8304150362

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl.
NOVAK, T M Assistant Director for Licensing 83/05/03
HOLTZSCHER, D L Licensing Review Group II. HOLTZSCHER, D L
Illinois Power Co 6pp. 18440 356 24X Fiche 50-000,83/05/03,
8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8305120130 Summary of 830426 meeting w/util in Perry,OH re containment weld deficiencies addressed in IE insp reps Acceptability study ongoing
STEFANO, J J Licensing Branch 1 83/05/04 YOUNGBLOOD, B J
Licensing Branch 1 5pp 18435 353 24X Fiche 50-440,83/05/04,
8305120130

8305170203 Advises that liquid penetrant testing utilized as alternative to magnetic testing on containment vessel penetration welds per IE Bulletin 80-08 response
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/05
KEPPLER, J G Region 3, Office of Director 1p 18466 350 24X
Fiche 50-440,83/05/05,8305170203

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E.L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033.

8305260236 Forwards IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 & notice of violation
LITTLE, W S Region 3, Office of Director 83/05/09 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp. 18599 347 24X
Fiche 50-440,83/05/09,8305260236

--8305260239 Notice of violation from insp on 830328-0401
LITTLE, W S Region 3, Office of Director. 83/05/10 1p
18599 349. 24X Fiche 50-440,83/05/09,8305260236.

--8305260243 IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 Noncompliance noted turnover reviews of purchase orders & installation/fabrication packages performed w/o controlling procedure
MERRIWEATHER, N , CONLON, T E Region 2, Office of Director
83/04/18 5pp 18599 350 24X Fiche 50-440,83/05/09,8305260236

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305260221 Forwards IE Insp Rept 50-440/83-07 on 830215-18 & 0414-15 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/05/12 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18622 120 24X
Fiche 50-440,83/05/12,8305260221

--8305260224 IE Insp Rept 50-440/83-07 on 830215-18 & 0414-15. No noncompliance noted Major areas inspected procedures for control of preoperational testing, turnover controls & jurisdictional control of equipment
REIMANN, F W , LANKSBURY, R D , REYES, L A Region 3, Office of Director 83/05/12 5pp 18622 122 24X Fiche 50-440,83/05/12,
8305260221

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305020500 Second interim deficiency rept re linear indications on pipe whip restraint bracket welds for B21/B33 sys Initially reported on 821228. Brackets will be removed & structural steel brackets reworked Next rept by 830701
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/15.
KEPPLER, J G Region 3, Office of Director 2pp 18281 245 24X
Fiche 50-440,83/04/15,8305020500

8305130222 Part 21 rept re potential ASME Section III & V violation Initially reported on 830412 Scope & condition of nonconformance under investigation
WHEATON, W R Borg-Warner Corp 83/04/15 MARTIN, J B Region 5,
Office of Director 4pp 18439 336 24X Fiche 50-440,83/04/15,
8305130222

8305020308 Revised final deficiency rept re incomplete fill detected in biological shield wall concrete of reactor bldgs Due to const scheduling, Unit 1 & 2 repairs will be completed by 830831 & 1231, respectively
EDELMAN, M R Cleveland Electric Illuminating Co. 83/04/19.
KEPPLER, J G Region 3, Office of Director 1p 18277.175. 24X
Fiche 50-440,83/04/19,8305020308

8305040486 Interim deficiency rept re nonconforming condition on Class IE low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222 Welding fix planned for cubicle EF2C05 Final rept will be submitted by 831130
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/27.
KEPPLER, J G Region 3, Office of Director 2pp 18319 353 24X
Fiche 50-440,83/04/27,8305040486

8305040496 Final deficiency rept re potential breach of seal integrity of hydrogen igniter Model 6043 glow plug component supplied by Power Sys Initially reported on 830207 Igniters repaired. Also reportable per Part 21
EDELMAN, M R. Cleveland Electric Illuminating Co 83/04/27
KEPPLER, J G. Region 3, Office of Director 2pp 18319.356 24X
Fiche 50-440,83/04/27,8305040496.

8305100394 Interim deficiency rept re failure of Johnson Controls, Inc to adequately verify acceptability of Unistrut Corp QA program implementation Initially reported on 830329. Corrective action request & nonconformance rept issued.
EDELMAN, M R Cleveland Electric Illuminating Co. 83/04/28.
KEPPLER, J.G Region 3, Office of Director 2pp 18377 357. 24X
Fiche 50-440,83/04/28,8305100394

8305040465 Interim deficiency rept re incorrectly sized reactor pressure vessel water level transmitters Replacement of transmitters expected by 830501 Final rept will be submitted upon work completion
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/29
KEPPLER, J G Region 3, Office of Director 1p 18319 355 24X
Fiche 50-440, 83/04/29, 8305040465

8305100013 Second interim deficiency rept re defective Bailey 720 util station devices installed in GE supplied balance-of-plant panels. Initially reported 810626 Seventy of 71 devices returned to GE for rework Final rept due by 831201
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/29
KEPPLER, J G Region 3, Office of Director 2pp 18421 244 24X
Fiche 50-440, 83/04/29, 8305100013

8305100333 Second interim deficiency rept re ASME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc w/o matl certification Initially reported on 830325 Supports reanalyzed Next rept by 830701
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/29
KEPPLER, J G Region 3, Office of Director 2pp 18379 005 24X
Fiche 50-440, 83/04/29, 8305100333

8305130236 Final Deficiency Rept RDC 71(83) re breakdown in QA program of Carboline, Co Initially reported on 830408 Program inadequate to meet requirement of 10CFR50, App B Carboline Co initiated new changes to QA program
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/06
KEPPLER, J G Region 3, Office of Director 2pp 18439 318 24X
Fiche 50-440, 83/05/06, 8305130236

8305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LOCA Initially reported on 830407 Final rept expected by 830815 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/06
KEPPLER, J G Region 3, Office of Director 2pp 18439 212 24X
Fiche 50-440, 83/05/06, 8305130248

T Hearing transcripts on non-antitrust matters

8305030526 Forwards Region III testimony re QA issues of fact contained in ASLB 821222 order
CUTCHIN, J, M Hearing Branch 4 83/05/02 BLOCH, P B , BRIGHT, G O , KLINE, J R Atomic Safety and Licensing Board Panel 1p 18292 117 24X Fiche 50-440, 83/05/02, 8305030526

--8305030537 Testimony of Region III panel consisting of JE Konklin, CC Williams, GF Maxwell & ML Gildner re QA issues of fact contained in ASLB 821222 order. Discusses const activities & implementation of QA program W/prof qualifications
KONKLIN, J. E , WILLIAMS, C. C , MAXWELL, G F Region 3, Office of Director 83/05/02 33pp 18292 118 24X Fiche 50-440, 83/05/02, 8305030526

8305040506 Forwards testimony of MR Edelman & GR Leidich re QA program for control of safety-related contractors (Issue 3)
SILBERG, J E , GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge 83/05/02 BLOCH, P B , KLINE, J R , BRIGHT, G O Atomic Safety and Licensing Board Panel 2pp 18322 069 24X Fiche 50-440, 83/05/02, 8305040506

--8305040516 Testimony of MR Edelman & GR Leidich re util QA program for control of safety-related contractors (Issue 3).
EDELMAN, M R , LEIDICH, G R Cleveland Electric Illuminating Co 83/05/02 38pp 18322.071 24X Fiche 50-440, 83/05/02, 8305040506

8305110004 Transcript of 830509 telephone conference in Bethesda, MD Pp 805-883
* Atomic Safety and Licensing Board Panel 83/05/09 78pp 18408 289 24X Fiche 50-440, 83/05/09, 8305110004

8305260093 Transcript of 830523 hearing in Painesville, OH. Pp 884-994 Supporting documentation encl
* Atomic Safety and Licensing Board Panel. 83/05/23 128pp. 18622.192 24X Fiche 50-440, 83/05/23, 8305260093

8305310137 Transcript of 830524 hearing in Painesville, OH Pp 996-1,226 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/24 272pp 18657 128 24X Fiche 50-440, 83/05/24, 8305310137

DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8303280059 Forwards seismic qualification & pump valve operability info, per 830203 request Repts on floor response spectra, seismic summary listing, revised PVQRT & seismic qualification review team forms included
EDELMAN, M R Cleveland Electric Illuminating Co 83/03/16
YOUNGBLOOD, B J Licensing Branch 1 1,704pp 17701 001 24X
Fiche 50-440, 83/03/16, 8303280059

8305040289 Advises that effective 830418, JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK, T M Assistant Director for Licensing 83/04/26
HOLTZSCHER, D L Illinois Power Co 2pp 18326 343 24X
Fiche 50-000, 83/04/26, 8305040289

8305190096 Advises of NRC evaluation findings of automatic depressurization sys logic mod options in response to TMI Action Item II K 3 18 Util should advise NRC of which action will be implemented & furnish necessary design & info
YOUNGBLOOD, B J Licensing Branch 1 83/04/27 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 194 24X
Fiche 50-440, 83/04/27, 8305190096

8305090277 Forwards Board Notification (BN) 83-58 previously transmitted as BN 83-13, forwarding EG&G draft rept, "Identification & Ranking of Nuclear Plant Structures, Sys & Components & Graded QA Guidelines " W/o BN 83-58
NOVAK, T M Assistant Director for Licensing 83/05/02 Atomic Safety and Licensing Board Panel 6pp 18366 275 24X
Fiche 50-440, 83/05/02, 8305090277

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 HALE, D P Illinois Power Co 2pp 18523 200 24X Fiche 50-000, 83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 FERGUSON, M R Washington Public Power Supply System 2pp 18523 202 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 MCGAUGHY, J P Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000, 83/05/03, 8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT, D G Division of Licensing 83/05/03 CAHILL, J Gulf States Utilities Co 2pp 18523 206 24X Fiche. 50-000, 83/05/03, 8305190046

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche. 50-000, 83/05/09, 8305090659

8305230143 Responds to 821214 & 830401 requests for addl info re safety relief valve piping & quencher device & safety-related piping supports Info will be provided 830630 for Questions 210 10 & 210 11 & 840630 for Question 210 9
EDELMAN, M R Cleveland Electric Illuminating Co. 83/05/16
YOUNGBLOOD, B J Licensing Branch 1 1p 18539 187 24X
Fiche 50-440, 83/05/16, 8305230143

8305250189 Notification of 830526 meeting w/util & Gilbert Assocs in Bethesda,MD to discuss design for containment purge
STEFANO,J J Licensing Branch 1 83/05/16 YOUNGBLOOD,B J
Licensing Branch 1 3pp 18595 359 24X Fiche 50-440,83/05/16,
8305250189

8305230290 Forwards addl info re environ equipment qualification program & plant readiness for audit,in response to 830323 Questions 270 1-270 13 Safety-related equipment,per TMI Items II D 3 & II F 1,will be added prior to fuel load
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/17
YOUNGBLOOD,B J Licensing Branch 1 238pp 18529 001 24X
Fiche 50-440,83/05/17,8305230290

E NRC Safety Evaluation Report (SER), suppls & correspondence
---

8305040664 Forwards Suppl 3 to SER (NUREG-0887) W/o encl
YOUNGBLOOD,B J Licensing Branch 1 83/04/27 EDELMAN,M R
Cleveland Electric Illuminating Co 2pp 18336 266 24X
Fiche 50-440,83/04/27,8305040664

8305170096 SAFETY EVALUATION REPORT RELATED TO OPERATION OF THE PERRY NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)
* Office of Nuclear Reactor Regulation, Director NUREG-0887 803.
83/04/30 75pp 18492 303 24X Fiche 50-440,83/04/30,8305170096

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 HOLTZSCHER,D L
Illinois Power Co 2pp 18443 173 24X Fiche 50-000,83/05/02,
8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 POWELL,P Washington
Public Power Supply System 1p 18443 174 24X
Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 REED,W J Gulf
States Utilities Co 1p 18443 175 24X Fiche 50-000,83/05/02,
8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 RICHARDSON,J D
Mississippi Power & Light Co 1p 18443 176 24X
Fiche 50-000,83/05/02,8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 BUZZELLI,E M
Cleveland Electric Illuminating Co 1p 18443 177. 24X
Fiche 50-000,83/05/02,8305120460

8305110300 Forwards response to Human Factors 821112 in-progress audit rept re SER Outstanding Issue 7,control room design review
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/04
YOUNGBLOOD,B J Licensing Branch 1 21pp 18393 312. 24X
Fiche 50-440,83/05/04,8305110300

8305230649 Forwards request for addl info re SER Section 13 5 2 2, "Reanalysis of Transients & Accidents Development of Emergency Operating Procedures " Schedule requested within 7 days of receipt of ltr
YOUNGBLOOD,B J Licensing Branch 1 83/05/06 EDELMAN,M R.
Cleveland Electric Illuminating Co 4pp 18542 354 24X
Fiche 50-440,83/05/06,8305230649

8305230645 Forwards NUREG-0887,Suppl 3 to SER W/o encl
YOUNGBLOOD,B J Licensing Branch 1 83/05/09 EDELMAN,M.R
Cleveland Electric Illuminating Co 3pp 18542 360 24X
Fiche:50-440,83/05/09,8305230645

8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re SER Outstanding Issue 19 Curves dependent on amount of fuel inventory released.Revised response to Round 2 Question I 2 submitted on 830404
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/13
YOUNGBLOOD,B J Licensing Branch 1. 4pp 18539 188 24X
Fiche 50-440,83/05/13,8305230106

8305260267 Forwards response to 830307 request for clarifications & addl info re FSAR Table 3 2-1 Suppl 3 to SER issued in Apr referenced same questions as outstanding Issue 23 Info should resolve Outstanding Issue 23 in next SER suppl
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/19.
YOUNGBLOOD,B J Licensing Branch 1 11pp 18626 200 24X
Fiche 50-440,83/05/19,8305260267

F Security, medical, emergency & fire protection plans

8304060126 NUS-4336, "Description of Perry Nuclear Power Plant Emergency Offsite Dose Calculations "
WILKENSON NUS Corp 83/04/30 44pp 17858;021 24X
Fiche 50-440,83/04/04,8304060118.

8305230649 Forwards request for addl info re SER Section 13.5 2 2, "Reanalysis of Transients & Accidents Development of Emergency Operating Procedures " Schedule requested within 7 days of receipt of ltr
YOUNGBLOOD,B J Licensing Branch 1. 83/05/06 EDELMAN,M R.
Cleveland Electric Illuminating Co 4pp 18542 354 24X
Fiche 50-440,83/05/06,8305230649

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl.
EISENHUT,D G Division of Licensing. 83/05/11. Consolidated
Edison Co of New York, Inc 16pp. 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305230106 Forwards curves showing gamma dose rate vs time & instructions for use re SER Outstanding Issue 19.Curves dependent on amount of fuel inventory released Revised response to Round 2 Question I 2 submitted on 830404
EDELMAN,M R Cleveland Electric Illuminating Co. 83/05/13
YOUNGBLOOD,B J Licensing Branch 1 4pp 18539 188. 24X
Fiche 50-440,83/05/13,8305230106

G Adjudicatory correspondence

8305020470 Answer opposing Ohio Citizens for Responsible Energy 830418 motion to hold record open on GA issue Motion based on mere speculation that intervenor witnesses may become available. Certificate of Svc encl
SILBERG,J E. Commonwealth Edison Co SILBERG,J.E Shaw, Pittman,
Potts & Trowbridge 83/04/27. Atomic Safety and Licensing Board
Panel 7pp 18283 300. 24X Fiche 50-440,83/04/27,8305020470.

8305040528 Motion for summary disposition of OL application on grounds of matl false statement in amend to environ rept Certificate of Svc encl Related correspondence.
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28
Atomic Safety and Licensing Board Panel 18pp. 18321 217 24X
Fiche 50-440,83/04/28,8305040528

8305040541 Motion to stay proceeding pending ruling on OH Citizens for Responsible Energy 830428 motion for summary disposition of OL application Certificate of Svc encl Related correspondence
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28.
Atomic Safety and Licensing Board Panel 3pp 18321 276 24X
Fiche 50-440,83/04/28,8305040541

8305040544 Response opposing unmeritable motion for reconsideration & clarification of ASLB 830330 memorandum & order granting NRC motion for summary disposition of issue 9 on polymer degradation W/Certificate of Svc Related correspondence.
HIATT,S L Ohio Citizens for Responsible Energy 83/04/28.
Atomic Safety and Licensing Board Panel 4pp. 18321 272 24X
Fiche 50-440,83/04/28,8305040544

8305020477 Answer opposing Ohio Citizens for Responsible Energy 830418 motion to hold record open on GA issue Motion premature & grounded on sheer speculation Certificate of Svc encl.
CUTCHIN,J.M Hearing Branch 4 83/04/29 Atomic Safety and
Licensing Board Panel. 4pp 18282 359. 24X Fiche 50-440,83/04/29,
8305020477

8305040325 Brief supporting Ohio Citizens for Responsible Energy motion to hold record open on GA issue.Applicant is moving back const completion date of own volition
WILT,D.D Sunflower Alliance. 83/04/29. Atomic Safety and
Licensing Board Panel 2pp. 18323 293 24X Fiche 50-440,83/04/29,
8305040325

8305040487 Application for subpoenas directed to CM Shuster,of util & to J Keppler,NRC Region III administrator Proof of Svc encl
WILT,D.D Sunflower Alliance WILT,D D Wilt, D D. 83/04/29.
Atomic Safety and Licensing Board Panel 3pp. 18319;270 24X
Fiche 50-440,83/04/29,8305040487

8305040548 Request for NRC & util to stipulate to authenticity of documents to be identified by 830518 & request to admit documents as evidence Proof of Svc encl
WILT, D D Sunflower Alliance WILT, D D Wilt, D D 83/04/29
Atomic Safety and Licensing Board Panel 1p 18321 271 24X
Fiche 50-440, 83/04/29, 8305040548

8305040307 Response opposing Sunflower Alliance, Inc, et al 830429 motion which requests applicant to stipulate to authenticity of unidentified documents & requests admission of documents as evidence. Certificate of Svc encl
SILBERG, J E. Cleveland Electric Illuminating Co SILBERG, J E
Shaw, Pittman, Potts & Trowbridge 83/05/02 Atomic Safety and Licensing Board Panel 3pp 18323 303 24X Fiche 50-440, 83/05/02, 8305040307

8305090487 Informs ASLB that requested documents re matters mentioned in NRC prefiled testimony on Issue 3 will be provided CE Norelius 820910 ltr re special const insp forwarded QA insp rept forthcoming Evaluation encl
CUTCHIN, J M Hearing Branch 4 83/05/06 BLOCH, P B , BRIGHT, G O , KLINE, J R Atomic Safety and Licensing Board Panel 2pp.
18361.153 24X Fiche 50-440, 83/05/06, 8305090487

--8305090490 Forwards "Self-Initiated Evaluation," assessing project & committing to maintaining highest quality stds
EDELMAN, M. R Cleveland Electric Illuminating Co 82/12/07
KEPPLER, J G Region 3, Office of Director 1p 18361.156 24X
Fiche 50-440, 83/05/06, 8305090487

--8305090493 "Self-Initiated Evaluation "
Cleveland Electric Illuminating Co 82/10/31. 213pp.
18361 157. 24X Fiche 50-440, 83/05/06, 8305090487

8305100294 Amended application for subpoena directing attendance of CM Shuster & JG Keppler at 830503 hearings on Issue 3 re nonconformance trend analysis sys Proof of Svc encl
WILT, D D. Sunflower Alliance WILT, D D Wilt, D D 83/05/06
SHUSTER, C M Cleveland Electric Illuminating Co KEPPLER, J G
Region 3, Office of Director 3pp 18370 139 24X
Fiche: 50-440, 83/05/06, 8305100294

8305100367 Brief in support of Ohio Citizens for Responsible Energy 830428 motion for summary disposition of OL application & motion for stay of proceedings Appropriate sanctions should be imposed on applicant. Proof of Svc encl
WILT, D D Sunflower Alliance. WILT, D D Wilt, D D 83/05/06.
Atomic Safety and Licensing Board Panel. 7pp 18379.042 24X
Fiche. 50-440, 83/05/06, 8305100367

8305160156 Requests to make limited appearance statement at OL hearings
MCCLUSKEY, G Affiliation Unknown 83/05/08. NRC - No Detailed
Affiliation Given 1p 18446.086 24X Fiche: 50-440, 83/05/08, 8305160156

8305100168 Forwards SER, Suppl 3 (NUREG-0887). W/o encl
CUTCHIN, J M Hearing Branch 4 83/05/09 BLOCH, P B., BRIGHT, G D., KLINE, J R Atomic Safety and Licensing Board Panel. 1p 18374 273
24X Fiche 50-440, 83/05/09, 8305100168

8305120304 Requests to make limited appearance statement at 830523 OL hearings
RENNER, A E Affiliation Unknown 83/05/09 NRC - No Detailed
Affiliation Given 1p 18424 206 24X Fiche 50-440, 83/05/09, 8305120304

8305160122 Requests to make limited appearance statement at OL hearings
COOK, G S Affiliation Unknown 83/05/10 NRC - No Detailed
Affiliation Given 1p 18450 130. 24X Fiche 50-440, 83/05/10, 8305160122

8305160153 Requests to make limited appearance statement at OL hearings
GLEIBSEN, A. Affiliation Unknown 83/05/10. NRC - No Detailed
Affiliation Given. 1p. 18446 087 24X Fiche 50-440, 83/05/10, 8305160153

8305170305 Objects to characterization of Ohio Citizens for Responsible Energy members as persons advocating disruption, demonstration & disrespect for law, as stated in Sunflower Alliance 830506 brief in support of motion.
HIATT, B L. Ohio Citizens for Responsible Energy 83/05/10.
WILT, D D Wilt, D.D 1p. 18465.075 24X Fiche 50-440, 83/05/10, 8305170305

8305170341 Motion to file contentions, objecting to SNM license issuance unless & until OL granted & facility ready to load fuel Certificate of Svc encl
HIATT, B. L. Ohio Citizens for Responsible Energy. 83/05/10.
Atomic Safety and Licensing Board Panel. 21pp 18465.096 24X
Fiche 50-440, 83/05/10, 8305170341.

8305170457 Requests opportunity for staff member to make limited appearance statement at 830523 hearing
ECKART, D E House of Rep 83/05/11 STUCKY, S Office of the Secretary of the Commission 1p 18470 141 24X
Fiche 50-440, 83/05/11, 8305170457

8305170461 Requests to make limited appearance statement at 830523 & 31 hearings in Painesville
WALDORF, E J Affiliation Unknown 83/05/11 Office of the Secretary of the Commission 1p 18469 318 24X
Fiche 50-440, 83/05/11, 8305170461

8305170464 Requests to make limited appearance statement at OL hearings
BIMBER, R M Affiliation Unknown 83/05/12 NRC - No Detailed
Affiliation Given 1p 18469 361 24X Fiche 50-440, 83/05/12, 8305170464

8305170452 Requests to make limited appearance statement at OL hearings
RAUKI, S Affiliation Unknown 83/05/13 Docketing & Services Branch 1p 18469 207 24X Fiche 50-440, 83/05/13, 8305170452

8305190214 Requests to make limited appearance statement at OL hearings
RUDD, C C Affiliation Unknown 83/05/14 NRC - No Detailed
Affiliation Given 1p 18502 237 24X Fiche 50-440, 83/05/14, 8305190214

8305240512 Requests to make limited appearance statement at OL hearings
O'NEILL, K Affiliation Unknown 83/05/15 NRC - No Detailed
Affiliation Given 1p 18571 109 24X Fiche. 50-440, 83/05/15, 8305240512

8305200656 Requests to make limited appearance statement at OL hearings
ZIVKOVICH, E A , HANDBOY, L , WARCLOUD, J Affiliation Unknown
83/05/17 Office of the Secretary of the Commission 6pp
18519 312 24X Fiche 50-440, 83/05/17, 8305200656

8305200598 Requests to make limited appearance statement at OL hearings
DEVINE, A , THOMPSON, D , MAST, L Affiliation Unknown 83/05/19
Docketing & Services Branch 2pp 18514 104 24X
Fiche 50-440, 83/05/19, 8305200598

8305240515 Update to util 830205 answer to Interrogatory 3 of Sunflower Alliance 811202 first set of interrogatories All three counties have submitted draft plans to Ohio Disaster Svcs Agency Svc list encl Related correspondence
SWIGER, M A Shaw, Pittman, Potts & Trowbridge SWIGER, M A
Cleveland Electric Illuminating Co 83/05/19 WILT, D D Sunflower Alliance WILT, D D Wilt, D D 7pp 18571 125 24X
Fiche 50-440, 83/05/19, 8305240515

8305240544 Requests to make limited appearance statement at OL hearings
FLAGG, D M , FINK, J. , REED, J R Affiliation Unknown 83/05/19
Office of the Secretary of the Commission 3pp 18576.040 24X
Fiche 50-440, 83/05/19, 8305240544.

H General correspondence

8305310031 Notifies that DD Wilt no longer represents Sunflower Alliance, Inc due to irreconcilable differences & prof responsibility
WILT, D D Wilt, D D 83/05/23 BLOCH, P , KLINE, J R , BRIGHT, G O
Atomic Safety and Licensing Board Panel 1p 18653 130 24X
Fiche 50-440, 83/05/23, 8305310031

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18309 319. 24X Fiche 50-000, 83/03/21, 8212060385

8304150362 Forwards IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted
LITTLE, W S Region 3, Office of Director 83/04/01 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 17982 129 24X
Fiche 50-440, 83/04/01, 8304150362

--8304150364 IE Insp Repts 50-440/83-09 & 50-441/83-08 on 830314-17 No noncompliance noted Major areas inspected licensee actions on 10CFR50 55(e) items
WARD,K D , CILIMBERG,R L , DANIELSON,D H Region 3, Office of Director 83/04/01 9pp 17982 131 24X Fiche 50-440,83/04/01, 8304150362

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK,T M Assistant Director for Licensing 83/05/03
HOLTZSCHER,D L Licensing Review Group II 6pp 18440 356 24X Fiche 50-000,83/05/03,8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305120130 Summary of 830426 meeting w/util in Perry,OH re containment weld deficiencies addressed in IE insp reps Acceptability study ongoing
STEFANO,J J Licensing Branch 1 83/05/04 YOUNGBLOOD,B J Licensing Branch 1 5pp 18435 353 24X Fiche 50-440,83/05/04, 8305120130

8305170203 Advises that liquid penetrant testing utilized as alternative to magnetic testing on containment vessel penetration welds per IE Bulletin 80-08 response
EDELMAN,M R Cleveland Electric Illuminating Co 83/05/05
KEPPLER,J G Region 3, Office of Director 1p 18466 350 24X Fiche 50-440,83/05/05,8305170203

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033.

8305260236 Forwards IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 & notice of violation
LITTLE,W S Region 3, Office of Director 83/05/09 EDELMAN,M R. Cleveland Electric Illuminating Co 2pp 18599 347 24X Fiche 50-440,83/05/09,8305260236

--8305260243 IE Insp Repts 50-440/83-11 & 50-441/83-10 on 830328-0401 Noncompliance noted turnover reviews of purchase orders & installation/fabrication packages performed w/o controlling procedure
MERRIWEATHER,N , CONLON,T E Region 2, Office of Director 83/04/18 5pp 18599 350 24X Fiche 50-440,83/05/09,8305260243

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program" Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305020500 Second interim deficiency rept re linear indications exist whip restraint bracket welds for B21/B33 sys Initially reported on 821228 Brackets will be removed & structural steel brackets reworked Next rept by 830701
EDELMAN,M R Cleveland Electric Illuminating Co 83/04/15
KEPPLER,J G Region 3, Office of Director 2pp 18281 243 24X Fiche 50-440,83/04/15,8305020500

8305130222 Part 21 rept re potential ASME Section III & V violations Initially reported on 830412 Scope & condition of nonconformance under investigation
WHEATON,W R Borg-Warner Corp 83/04/15 MARTIN,J B Region 3, Office of Director 4pp 18439 336 24X Fiche 50-440,83/04/15, 8305130222

8305020308 Revised final deficiency rept re incomplete fill (shrinkage) biological shield wall concrete of reactor bldgs Due to const scheduling,Unit 1 & 2 repairs will be completed by 830831 & 1231,respectively
EDELMAN,M R. Cleveland Electric Illuminating Co 83/04/19.
KEPPLER,J G Region 3, Office of Director 1p 18277 175 24X Fiche 50-440,83/04/19,8305020308

8305040486 Interim deficiency rept re nonconforming condition on Class 1E low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222.Welding fix planned for cubicle EF2C05 Final rept will be submitted by 831130
EDELMAN,M R Cleveland Electric Illuminating Co 83/04/27.
KEPPLER,J G Region 3, Office of Director 2pp 18319 350 24X Fiche 50-440,83/04/27,8305040486.

8305040496 Final deficiency rept re potential breach of seal integrity of hydrogen igniter Model 6043 glow plug component supplied by Power Sys Initially reported on 830207 Igniters repaired Also reportable per Part 21
EDELMAN,M R Cleveland Electric Illuminating Co 83/04/27
KEPPLER,J G Region 3, Office of Director 2pp 18319.356 24X Fiche 50-440,83/04/27,8305040496

8305100394 Interim deficiency rept re failure of Johnson Controls,Inc to adequately verify acceptability of Unistrut Corp QA program implementation Initially reported on 830329 Corrective action request & nonconformance rept issued
EDELMAN,M R Cleveland Electric Illuminating Co 83/04/28.
KEPPLER,J G Region 3, Office of Director 2pp 18377 357 24X Fiche 50-440,83/04/28,8305100394

8305040465 Interim deficiency rept re incorrectly sized reactor pressure vessel water level transmitters Replacement of transmitters expected by 830501 Final rept will be submitted upon work completion
EDELMAN,M R Cleveland Electric Illuminating Co 83/04/29
KEPPLER,J G Region 3, Office of Director 1p 18319:355 24X Fiche 50-440,83/04/29,8305040465.

8305100013 Second interim deficiency rept re defective Bailey 720 unit station devices installed in GE supplied balance-of-plant panels Initially reported 810626.Seventy of 71 devices returned to GE for rework.Final rept due by 831201
EDELMAN,M R Cleveland Electric Illuminating Co. 83/04/29.
KEPPLER,J.G Region 3, Office of Director. 2pp 18421:244 24X Fiche 50-440,83/04/29,8305100013.

8305100333 Second interim deficiency rept re ASME Code Section III, Class 3 piping supports supplied by Transamerica Delaval, Inc w/o matl certification Initially reported on 830325 Supports reanalyzed Next rept by 830701
EDELMAN, M R Cleveland Electric Illuminating Co 83/04/29
KEPPLER, J G Region 3, Office of Director 2pp 18379 005 24X
Fiche 50-440, 83/04/29, 8305100333

8305130236 Final Deficiency Rept RDC 71(83) re breakdown in QA program of Carboline, Co Initially reported on 830408 Program inadequate to meet requirement of 10CFR50, App B Carboline Co initiated new changes to QA program
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/06
KEPPLER, J G Region 3, Office of Director 2pp 18439 318 24X
Fiche 50-440, 83/05/06, 8305130236

8305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LOCA Initially reported on 830407 Final rept expected by 830815 Also reported per Part 21
EDELMAN, M R Cleveland Electric Illuminating Co 83/05/06
KEPPLER, J G Region 3, Office of Director 2pp 18439 212 24X
Fiche 50-440, 83/05/06, 8305130248

T Hearing transcripts on non-antitrust matters

8305030526 Forwards Region III testimony re QA issues of fact contained in ASLB 821222 order
CUTCHIN, J. M Hearing Branch 4 83/05/02 BLOCH, P. B , BRIGHT, G O , KLINE, J R. Atomic Safety and Licensing Board Panel 1p 18292 117 24X Fiche 50-440, 83/05/02, 8305030526

--8305030537 Testimony of Region III panel consisting of JE Konklin, CC Williams, GF Maxwell & ML Gildner re QA issues of fact contained in ASLB 821222 order Discusses const activities & implementation of QA program W/prof qualifications
KONKLIN, J E , WILLIAMS, C. C , MAXWELL, G. F Region 3, Office of Director 83/05/02 33pp 18292 118. 24X Fiche 50-440, 83/05/02, 8305030526

8305040506 Forwards testimony of MR Edelman & GR Leidich re QA program for control of safety-related contractors (Issue 3)
SILBERG, J. E , GLASSPIEGEL, H Shaw, Pittman, Potts & Trowbridge 83/05/02 BLOCH, P B , KLINE, J R , BRIGHT, G D Atomic Safety and Licensing Board Panel 2pp 18322 069 24X Fiche 50-440, 83/05/02, 8305040506

--8305040516 Testimony of MR Edelman & GR Leidich re util QA program for control of safety-related contractors (Issue 3)
EDELMAN, M R , LEIDICH, G R Cleveland Electric Illuminating Co 83/05/02 38pp, 18322 071 24X Fiche 50-440, 83/05/02, 8305040506

8305110004 Transcript of 830509 telephone conference in Bethesda, MD Pp 883-883
* Atomic Safety and Licensing Board Panel 83/05/09 78pp 18408 289. 24X Fiche 50-440, 83/05/09, 8305110004

8305260093 Transcript of 830523 hearing in Painesville, OH. Pp 884-994 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/23 128pp 18622. 182. 24X Fiche 50-440, 83/05/23, 8305260093

8305310137 Transcript of 830524 hearing in Painesville, OH Pp 996-1, 226 Supporting documentation encl
* Atomic Safety and Licensing Board Panel. 83/05/24 272pp 18657. 128. 24X Fiche 50-440, 83/05/24, 8305310137

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305130335 Forwards ACRS 830419 ltr re review of application for OL, reporting on low power operation
KNIGHTON, G W Licensing Branch 3 83/04/25 HARRISON, R. J. Public Service Co. of New Hampshire 3pp 18457. 328 24X
Fiche. 50-443, 83/04/25, 8305130335

--8305130339 Comments on lower power operation review of OL application Operation reasonably assured at core power levels up to 5% full power w/o undue risk to public health & safety
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/04/19. PALLADINO, N J Commissioners 3pp. 18457. 331 24X
Fiche. 50-443, 83/04/25, 8305130335.

8305110016 Notification of 830511 meeting w/util in Bethesda, MD to discuss projected const completion date.
WHEELER, L. L Licensing Branch 3. 83/04/28 KNIGHTON, G W Licensing Branch 3 4pp 18421: 238 24X Fiche. 50-443, 83/04/28, 8305110016.

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305130332 Requests description of environ qualification program including listed items Scope of submittal to include all electrical equipment important to safety located in harsh environ
KNIGHTON, G W Licensing Branch 3 83/05/05 HARRISON, R J Public Service Co of New Hampshire 4pp 18457 334 24X
Fiche 50-443, 83/05/05, 8305130332

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305270019 Requests extension of CP completion dates for Units 1 & 2 to June 1986 & Oct 1988, respectively, per Amend 40 to CPPR-135 & CPPR-136
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18662 107 24X
Fiche 50-443, 83/05/16, 8305270019

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305170668 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos 50-443 And 50-444 (Public Service Company of New Hampshire, et al)
* Division of Licensing NUREG-0896 S01 83/04/30 32pp
Available at NRC #4 50 18481 332 24X Fiche 50-443, 83/04/30, 8305170668

8305260038 Forwards Suppl 1 to SER re application for OL W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 HARRISON, R J Public Service Co of New Hampshire 4pp. 18649 088 24X
Fiche 50-443, 83/05/12, 8305260038

F Security, medical, emergency & fire protection plans

8305090523 FOIA request for addl info re earlier request on Pilgrim dtd 821105 concerning similar documentation for Seabrook facilities
SHOTWELL, J A Massachusetts, Commonwealth of, 83/01/05.
FELTON, J M Division of Rules and Records 2pp 18368 001 24X
Fiche 50-443, 83/01/05, 8305090523

8305090529 Partial response to FOIA request for addl info re 821105 request pertaining to facility. Forwards App A documents Documents also available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records. 83/03/10 SHOTWELL, J A Massachusetts, Commonwealth of, 5pp 18368 003 24X
Fiche 50-443, 83/03/10, 8305090529

--8203150093 Forwards branch review comments of facility emergency plan, performed against NUREG-0654 criteria Addl info & commitments required prior to acceptance
PAGANO, F G EP Licensing Branch 82/03/03 MIRAGLIA, F J Licensing Branch 3 20pp 18368 014 24X Fiche 50-443, 83/03/10, 8305090529

--8208190078 Requests findings on prompt protective action decisionmaking in States of VT, NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 encl
GRIMES, B K Division of Emergency Preparedness (Pre 830103) 82/04/27 KRIMM, R M Federal Emergency Management Agency 6pp 18368 034 24X Fiche 50-443, 83/03/10, 8305090529

--8305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station "
* JHM Associates, Inc 83/03/10 56pp 18368 155 24X
Fiche 50-443, 83/03/10, 8305090529

8305050006 Forwards United Engineers & Constructors General Arrangement Drawing 9736-F-805062 re fire protection of primary component cooling water pumps, per util 830121 ltr W/o encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/02 KNIGHTON, G W. Licensing Branch 3 2pp 18339 083 24X Fiche 50-443, 83/05/02, 8305050006

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X Fiche 50-000, 83/05/13, 8305240213

Q Adjudicatory correspondence

8305100356 Forwards responses to New England Coalition on Nuclear Pollution fourth, sixth, eighth, twelfth, fourteenth & fifteenth motions for summary disposition
LESSY, R P Hearing Branch 3 83/03/21. HOYT, H , LUEBKE, E A , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18411 001 24X Fiche 50-443, 83/03/21, 8305100356

--8305100375 Response to twelfth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 1 NRC cannot agree or disagree w/statement of matl fact until receipt of preservice & inservice insp programs
LESSY, R P , PERLIS, R G Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 28pp. 18411 003 24X Fiche 50-443, 83/03/21, 8305100356

--8305100392 Response to fourteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R P. Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 5pp 18411 032 24X Fiche 50-443, 83/03/21, 8305100356

--8305100400 Affidavit of RK Anand on New England Coalition on Nuclear Pollution Contention I.D 3 Requirements of QDC 30 satisfied.
ANAND, R K. Auxiliary Systems Branch. 83/03/18 6pp 18411 037 24X Fiche 50-443, 83/03/21, 8305100356.

--8305100411 Response to fifteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I G No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W, F , LESSY, R P Hearing Branch 3 83/03/18. Atomic Safety and Licensing Board Panel 4pp 18411 043. 24X Fiche 50-443, 83/03/21, 8305100356

--8305100419 Affidavit of RO LaGrange on util commitment to qualify wide-range pressure transmitters per NUREG-0588 requirements Commitment acceptable
LAGRANGE, R O Equipment Qualification Branch 83/03/18 3pp 18411 047 24X Fiche 50-443, 83/03/21, 8305100356

--8305100425 Response to fourth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I 1 Requirement to qualify path to cold shutdown not needed. Contention must be dismissed
PERLIS, R G , LESSY, R P. Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 2pp 18411 050 24X Fiche 50-443, 83/03/21, 8305100356

--8305100430 Response to sixth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention NH-13 No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R.P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 5pp. 18411 052. 24X Fiche 50-443, 83/03/21, 8305100356

--8305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREG-0737, Item I A 1 1 requirements re shift technical advisor position Proposal acceptable
WIGGINS, J T Division of Project & Resident Programs 83/03/17. 2pp 18411 057 24X Fiche 50-443, 83/03/21, 8305100356.

--8305100432 Response to eighth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I A 2 No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R P. Hearing Branch 3 83/03/18. Atomic Safety and Licensing Board Panel. 4pp 18411:059 24X Fiche 50-443, 83/03/21, 8305100356

--8305100424 Affidavit of RO LaGrange on qualification of Class IE electric valve operators installed inside containment. Util committed to qualification per NUREG-0588
LAGRANGE, R O Equipment Qualification Branch 83/03/18. 3pp. 18411 064 24X Fiche 50-443, 83/03/21, 8305100356

8305100158 Forwards CY Liang, WT LeFave & SS Kirslis joint affidavit reviewing & commenting on Table I A 2-3 which includes listing of all electric valve operators inside containment, per ASLB request
LESSY, R P Hearings Division PATTERSON, W F Office of the Executive Legal Director 83/04/20 HOYT, H , LUEBKE, E A , HARBOUR, J Atomic Safety and Licensing Board Panel 3pp 18374 252 24X Fiche 50-443, 83/04/20, 8305100158

--8305100166 Affidavit of CY Liang, WT LeFave & SS Kirslis providing results of NRC review of Table I A 2-3 concerning environ qualification of electric valve operators installed inside containment Prof qualifications encl
LIANG, C Y Reactor Systems Branch LEFAVE, W T Auxiliary Systems Branch KIRSLIS, S S Chemical Engineering Branch 83/04/19 16pp. 18374·255 24X Fiche 50-443, 83/04/20, 8305100158.

8305100219 Forwards supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I A. 2 in NRC 821228 response to first set of interrogatories W/affidavits re review of Table I A 2-3
LESSY, R P. Office of the Executive Legal Director 83/04/20. CURRAN, D Harmon & Weiss 2pp 18374 145 24X Fiche 50-443, 83/04/20, 8305100219

--8305100221 Supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I. A 2 in NRC 821228 response to first set of interrogatories Affidavits re Table I A. 2-3 encl
LESSY, R P , PATTERSON, W. F Office of the Executive Legal Director 83/04/20 Atomic Safety and Licensing Board Panel. 14pp. 18374 147 24X Fiche 50-443, 83/04/20, 8305100219

8305020425 Forwards Town of Seabrook request to participate as interested municipality Interests lie in areas of emergency planning, insurance & accidents & precautionary evacuation.
FELCH, F B , RANDALL, W I., FALCONER, J C Seabrook, NH. 83/04/22 HOYT, H F Atomic Safety and Licensing Board Panel 1p 18273 196 24X Fiche 50-443, 83/04/22, 8305020425

--8305020429 Request to participate as interested municipality per 10CFR2. 715(c)
FELCH, F B , RANDALL, W I , FALCONER, J C Seabrook, NH. 83/04/22 Atomic Safety and Licensing Board Panel 1p 18273 197. 24X Fiche. 50-443, 83/04/22, 8305020425

8305020492 Forwards Town of Exeter request to participate as interested municipality
CHICK, D E Exeter, NH 83/04/26 HOYT, H F Atomic Safety and Licensing Board Panel 1p 18282·298 24X Fiche: 50-443, 83/04/26, 8305020482.

--8305020486 Request to participate as interested municipality per 10CFR2 715(c)
CHICK, D E Exeter, NH. 83/04/26 Atomic Safety and Licensing Board Panel 1p 18282 299. 24X Fiche 50-443, 83/04/26, 8305020482

8305030541 Motion to reconsider ASLB 830425 memorandum & order in response to New England Coalition on Nuclear Pollution objection to 830414 conference call Complexity of issue justifies 20-day response period Certificate of Svc encl.
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution BISHOP, L L Harmon & Weiss. 83/04/29. Atomic Safety and Licensing Board Panel 5pp 18301.357. 24X Fiche. 50-443, 83/04/29, 8305030541

8305030570 Order admitting Town of Exeter, NH as interested municipality Exeter must observe procedural requirements & take proceeding as found
HOYT, H. F Atomic Safety and Licensing Board Panel. 83/04/29. Exeter, NH 7pp 18306:110 24X Fiche 50-443, 83/04/29, 8305030570

8305040300 Response to New England Coalition on Nuclear Pollution motion to amend petition to intervene. Addl contention should be denied on grounds of timeliness or partially denied on grounds of vagueness Certificate of Svc encl
DIGNAN, T G , QAD, R. K. Public Service Co of New Hampshire. DIGNAN, T G Ropes & Gray 83/04/29 Atomic Safety and Licensing Board Panel 16pp 18324 001 24X Fiche 50-443, 83/04/29, 8305040300.

8305040316 Response to Town of Seabrook,NH request to participate as interested municipality Emergency planning exercise & public insurance coverage issues may not be litigated in present proceeding Certificate of Svc encl
DIGNAN,T G , DIGNAN,T G Public Service Co of New Hampshire
GAD,R K Ropes & Gray 83/04/29 5pp 18323 295 24X
Fiche.50-443,83/04/29,8305040316

8305090501 Forwards request to participate as interested municipality in proceedings
SARGENT,A V Salisbury,MA 83/05/02 HOYT,H F Atomic Safety and Licensing Board Panel 2pp 18362 138 24X Fiche 50-443,83/05/02, 8305090501

--8305090502 Request to participate as interested municipality in proceedings
SARGENT,A V Salisbury,MA 83/05/02 Atomic Safety and Licensing Board Panel 1p 18362 139 24X Fiche 50-443,83/05/02, 8305090501

8305060329 Responds to New England Coalition on Nuclear Pollution & State of NH submittals subsequent to 830407-08 prehearing conference Objects to word "omission" in reworded Coalition Contention I D 2.
LESSY,R P. Hearing Branch 3 83/05/04 HOYT,H , LUEBKE,E A , HARBOUR,J. Atomic Safety and Licensing Board Panel 4pp 18344 081. 24X Fiche 50-443,83/05/04,8305060329

8305060463 Order denying New England Coalition on Nuclear Pollution 830429 motion for reconsideration of ASLB 830425 memorandum & order No basis exists to reconsider order
HOYT,H F Atomic Safety and Licensing Board Panel 82/05/04 New England Coalition on Nuclear Pollution 3pp 18348 072 24X
Fiche 50-443,83/05/04,8305060463

8305090508 Order admitting Town of Seabrook,NH as interested municipality All procedural requirements must be observed
HOYT,H F Atomic Safety and Licensing Board Panel 83/05/06 6pp 18362.140 24X Fiche 50-443,83/05/06,8305090508

8305100200 Order admitting Town of Salisbury,MA as interested municipality List of Seabrook contentions remaining as of 830414 encl.
HOYT,H.F Atomic Safety and Licensing Board Panel 83/05/06
Atomic Safety and Licensing Board Panel 6pp 18374 023. 24X
Fiche:50-443,83/05/06,8305100200

8305270573 Requests inclusion as intervenor in upcoming hearings re evacuation planning for facility
NOWLES,S W Northampton County, PA 83/05/07 Atomic Safety and Licensing Board Panel. 3pp 18646 112 24X Fiche 50-443,83/05/07, 8305270573

8305100334 Response opposing New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene Motion should be rejected as untimely filed Certificate of Svc encl
PERLIS,R.Q , LESSY,R P Hearing Branch 3 83/05/09. Atomic Safety and Licensing Board Panel 8pp 18378.329 24X
Fiche 50-443,83/05/09,8305100334

8305130087 Informs that Strafford County Superior Court will be available for ASLB hearings during part of Jul & all of Aug 1983, in response to request for hearing
D'AMOURS,N E House of Rep 83/05/09 HOYT,H F Atomic Safety and Licensing Board Panel 1p 18440 044 24X Fiche 50-443,83/05/09, 8305130087.

8305130181 Memorandum & order memorializing 830407-08 prehearing conference in Boston,MA Rulings made on filing of contentions re Newburyport,MA emergency plan & re motions for summary disposition
HOYT,H F. Atomic Safety and Licensing Board Panel 83/05/11. Public Service Co of New Hampshire 36pp 18440.001 24X
Fiche:50-443,83/05/11,8305130181

8305160068 Affidavit of QC Minor responding to NRC 830420 affidavit on qualification of electric valve operators at plant Operators must be considered important to safety & environmentally qualified Certificate of Svc encl.Related correspondence
MINOR,Q C. New England Coalition on Nuclear Pollution 83/05/11. 13pp 18453 105 24X Fiche 50-443,83/05/11,8305160068

8305160002 Motion to file out-of-time answer to NRC affidavit re Contention I.A.2 concerning environ qualification of electric valve operators inside containment Intervenor unable to complete review within 10-day period set by ASLB
CURRAN,D , JORDAN,W S New England Coalition on Nuclear Pollution
CURRAN,D. Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel 3pp. 18456 056 24X Fiche 50-443,83/05/12,8305160002

8305160019 Response opposing NRC 830420 affidavit supporting assertion that none of unqualified electric valve operators inside containment are important to safety Failure to operate could prevent successful cooling of reactor
CURRAN,D , JORDAN,W S New England Coalition on Nuclear Pollution
CURRAN,D Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel 4pp 18452 341 24X Fiche 50-443,83/05/12,8305160019

8305170478 Memorandum & order denying New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene to admit new Contention NECNP VII on environ qualification of electrical equipment important to safety
HOYT,H F Atomic Safety and Licensing Board Panel 83/05/13 New England Coalition on Nuclear Pollution 6pp 18470 092 24X
Fiche 50-443,83/05/13,8305170478

8305190346 Requests public meeting be held to receive public input for preparation of Town of Hampton radiological emergency mgt plan
WALKER,J R Hampton, NH 83/05/13 Affiliation Unknown 1p 18500 022 24X Fiche 50-443,83/05/13,8305190346

8305190199 Motion to amend petition to intervene by adding Contention SAPL Suppl 7, "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate of Svc encl
BACKUS,R A Seacoast Anti-Pollution League BACKUS,R A Backus, Shea & Meyer 83/05/16 Atomic Safety and Licensing Board Panel 5pp 18502 205 24X Fiche 50-443,83/05/16,8305190199

8305250327 Requests MB Pearson be placed on svc list as Town of Amesbury,MA representative,per ASLB 830328 ltr
STUART,D L Amesbury, MA 83/05/16 HOYT,H F Atomic Safety and Licensing Board Panel 1p 18585 361 24X Fiche 50-443,83/05/16, 8305250327

8305240451 Order promulgating schedules for proceeding,including schedules for technical safety & onsite & offsite emergency planning contentions
HOYT,H F Atomic Safety and Licensing Board Panel 83/05/23 4pp 18574 120 24X Fiche 50-443,83/05/23,8305240451

8305310147 Response to SAPL motion to amend petition to intervene re SER open items Motion should be denied on grounds of timeliness Certificate of Svc encl
DIGNAN,T G Public Service Co of New Hampshire DIGNAN,T G Ropes & Gray 83/05/24 Atomic Safety and Licensing Board Panel 8pp 18651 209 24X Fiche 50-443,83/05/24,8305310147

8305270598 Order granting Town of North Hampton,NH 830507 petition to intervene re evacuation planning & admitting town as interested municipality in proceeding per 10CFR2 715(c)
HOYT,H F Atomic Safety and Licensing Board Panel 83/05/25
Public Service Co of New Hampshire 2pp 18645 361 24X
Fiche 50-443,83/05/25,8305270598

H General correspondence

8305250331 Offers use of junior high school auditorium for Aug 1983 licensing hearings Auditorium seats 500 people & has adjacent nurses room & bathroom for personal use
NADEAU,J P , YOUNG,M L , HOLWAY,F I Rye, NH 83/05/20 HOYT,H F Atomic Safety and Licensing Board Panel 1p 18592 104 24X
Fiche 50-443,83/05/20,8305250331

O Advisory Committee on Reactor Safeguards reports & correspondence

8305130352 Informs of uneasiness on selection of 1755 Cape Ann earthquake as facility std for design response spectra Critical safety-related components should be designed to withstand larger Charleston event
POMEROY,P W Rondout Associates POMEROY,P W ACRS - Advisory Committee on Reactor Safeguards 83/04/05 KERR,W ACRS - Advisory Committee on Reactor Safeguards 2pp 18443 333 24X
Fiche 50-443,83/04/05,8305130352

8305130335 Forwards ACRS 830419 ltr re review of application for OL, reporting on low power operation
KNIGHTON,G W Licensing Branch 3 83/04/25 HARRISON,R J Public Service Co of New Hampshire 3pp 18457 328 24X
Fiche 50-443,83/04/25,8305130335

--8305130339 Comments on lower power operation review of OL application Operation reasonably assured at core power levels up to 5% full power w/o undue risk to public health & safety
EBERSOLE,J.C ACRS - Advisory Committee on Reactor Safeguards 83/04/19 PALLADINO,N J Commissioners 3pp 18457 331. 24X
Fiche 50-443,83/04/25,8305130335

8305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities Supporting documentation encl
MAXWELL, J C Maxwell, J C MAXWELL, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/05 KERR, W ACRS - Advisory Committee on Reactor Safeguards 5pp 18443 335 24X Fiche 50-443, 83/05/05, 8305130347

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305050116 Forwards IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/01
HARRISON, R J Public Service Co of New Hampshire 2pp 18342 244 24X Fiche 50-443, 83/04/01, 8305050116

--8305050119 IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted Major areas inspected work activities, procedures & records re sys & component installation & structural steel erection
CERNE, A C , GRAMM, R A , NARROW, L M Region 1, Office of Director 83/04/20 12pp 18342 246 24X Fiche 50-443, 83/04/01, 8305050116

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524·003 24X Fiche 50-000, 83/05/11, 8303040034.

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046.

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices. Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P. Westinghouse Electric Corp 83/04/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427.

8305200495 Supplementary Part 21 rept re adequacy of svc water cooling tower structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630
SARBTEN, G.E United Engineers & Constructors, Inc. (subs of Raytheon Co) 83/04/29 Region 1, Office of Director 3pp 18514 033 24X Fiche 50-443, 83/04/29, 8305200495

8305160039 Final deficiency rept re sheared pinion keys on six Limitorque motor operators Initially reported on 820805 Westinghouse will replace pinion keys on all SB-0 motor operators for Westinghouse valves
DEVINCENTIS, J Public Service Co of New Hampshire 83/05/04
STAROSTECKI, R Division of Project & Resident Programs 3pp 18453 127 24X Fiche 50-443, 83/05/04, 8305160039.

8305110299 PND-1-83-048 on 830429, potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds, involving procedural violations during magnetic particle exam.
CERNE, A , GALLO, R. Region 1, Office of Director 83/05/06. 1p. 18393 333 24X Fiche 50-443, 83/05/06, 8305110299

8305190164 Second interim deficiency rept re Westinghouse EMD gate valve position indication Initially reported on 830110 Investigation continuing Detailed description, analysis of safety implications & corrective actions expected by 830610.
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/09 STAROSTECKI, R Division of Project & Resident Programs 2pp 18502 235 24X Fiche 50-443, 83/05/09, 8305190164

8305200353 Final deficiency rept re DB-416 reactor trip switchgear malfunction Initially reported on 830422 Caused by deviations from breaker internal recommended clearances. Manufacturer drawings modified.
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 STAROSTECKI, R Division of Project & Resident Programs 3pp 18518·091 24X Fiche 50-443, 83/05/16, 8305200353

8305200402 Interim deficiency rept re svc water & circulating water pump house structural inadequacy Initially reported on 830419 Detailed engineering evaluation scheduled for completion by 830722
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 STAROSTECKI, R. Division of Project & Resident Programs 2pp 18517 295. 24X Fiche. 50-443, 83/05/16, 8305200402

8305250244 Second interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 Series process instrumentation & control sys cabinets Initially reported on 830318 Evaluation rept expected by 830630
DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/20 STAROSTECKI, R Division of Project & Resident Programs. 1p 18592 297. 24X Fiche. 50-443, 83/05/20, 8305250244

U Congressional/Executive Correspondence

8304250241 Requests suggestions for appropriate facility to accommodate licensing proceeding in reasonable space & comfort & w/o unnecessary handicaps
HOYT, H.F Atomic Safety and Licensing Board Panel. 83/04/20.
D'AMOURS, N E. House of Rep 1p 18178 111. 24X
Fiche 50-443, 83/04/20, 8304250241.

DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305130335 Forwards ACRS 830419 ltr re review of application for OL, reporting on low power operation
KNIGHTON, G W Licensing Branch 3 83/04/25 HARRISON, R J Public Service Co of New Hampshire. 3pp 18457 328 24X
Fiche 50-443, 83/04/25, 8305130335

8305110016 Notification of 830511 meeting w/util in Bethesda, MD to discuss projected const completion date
WHEELER, L L Licensing Branch 3 83/04/28 KNIGHTON, G W Licensing Branch 3 4pp 18421 238 24X Fiche 50-443, 83/04/28, 8305110016

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305130332 Requests description of environ qualification program including listed items Scope of submittal to include all electrical equipment important to safety located in harsh environ
KNIGHTON, G W Licensing Branch 3 83/05/05 HARRISON, R J Public Service Co of New Hampshire 4pp 18457 334 24X
Fiche 50-443, 83/05/05, 8305130332

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305270019 Requests extension of CP completion dates for Units 1 & 2 to June 1986 & Oct 1988, respectively, per Amend 40 to CPPR-135 & CPPR-136
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18662 107 24X
Fiche 50-443, 83/05/16, 8305270019

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305170668 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos 50-443 And 50-444 (Public Service Company of New Hampshire, et al)
* Division of Licensing NUREG-0896 S01 83/04/30 32pp
Available at NRC $4 50. 18481:332 24X Fiche 50-443, 83/04/30, 8305170668

8305260038 Forwards Suppl 1 to SER re application for OL W/o encl
KNIGHTON, G W Licensing Branch 3 83/05/12 HARRISON, R. J Public Service Co of New Hampshire 4pp 18649 088 24X
Fiche: 50-443, 83/05/12, 8305260038

F Security, medical, emergency & fire protection plans

8305090523 FOIA request for addl info re earlier request on Pilgrim dtd 821105 concerning similar documentation for Seabrook facilities
SHOTWELL, J A Massachusetts, Commonwealth of, 83/01/05,
FELTON, J. M Division of Rules and Records 2pp 18368 001 24X
Fiche 50-443, 83/01/05, 8305090523

8305090529 Partial response to FOIA request for addl info re 821105 request pertaining to facility Forwards App A documents Documents also available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FELTON, J. M Division of Rules and Records 83/03/10 SHOTWELL, J. A. Massachusetts, Commonwealth of, 5pp 18368 003 24X
Fiche 50-443, 83/03/10, 8305090529

--8203150093 Forwards branch review comments of facility emergency plan, performed against NUREG-0654 criteria Addl info & commitments required prior to acceptance.
PAGANO, F Q. EP Licensing Branch 82/03/03. MIRAGLIA, F J Licensing Branch 3 20pp. 18368 014 24X Fiche. 50-443, 83/03/10, 8305090529

--8208190078 Requests findings on prompt protective action decisionmaking in States of VT, NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 encl
GRIMES, B K Division of Emergency Preparedness (Pre 830103) 82/04/27 KRIMM, R M Federal Emergency Management Agency 6pp 18368 034 24X Fiche 50-443, 83/03/10, 8305090529

--8305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station "
* HMM Associates, Inc 83/03/10 56pp 18368 155 24X
Fiche 50-443, 83/03/10, 8305090529

8305050006 Forwards United Engineers & Constructors General Arrangement Drawing 9736-F-805062 re fire protection of primary component cooling water pumps, per util 830121 ltr W/o encl
DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/02 KNIGHTON, G W Licensing Branch 3 2pp 18339 083 24X Fiche 50-443, 83/05/02, 8305050006

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18340 095 24X
Fiche 50-000, 83/05/11, 8305110034

G Adjudicatory correspondence

8305100356 Forwards responses to New England Coalition on Nuclear Pollution fourth, sixth, eighth, twelfth, fourteenth & fifteenth motions for summary disposition
LESSY, R P Hearing Branch 3 83/03/21 HOYT, H , LUEBKE, E A , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18411 001 24X Fiche 50-443, 83/03/21, 8305100356

--8305100375 Response to twelfth motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 1 NRC cannot agree or disagree w/statement of matl fact until receipt of preservice & inservice insp programs
LESSY, R P , PERLIS, R G Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 28pp 18411 003 24X
Fiche 50-443, 83/03/21, 8305100356

--8305100392 Response to fourteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 5pp 18411 032 24X
Fiche 50-443, 83/03/21, 8305100356

---8305100400 Affidavit of RK Anand on New England Coalition on Nuclear Pollution Contention I D 3 Requirements of GDC 30 satisfied
ANAND, R K Auxiliary Systems Branch 83/03/18 6pp 18411 037 24X Fiche 50-443, 83/03/21, 8305100356

--8305100411 Response to fifteenth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I G No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 4pp 18411 043 24X
Fiche 50-443, 83/03/21, 8305100356

---8305100419 Affidavit of RG LaGrange on util commitment to qualify wide-range pressure transmitters per NUREG-0588 requirements Commitment acceptable
LAGRANGE, R. G Equipment Qualification Branch 83/03/18 3pp 18411 047 24X Fiche 50-443, 83/03/21, 8305100356

--8305100425 Response to fourth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I 1 Requirement to qualify path to cold shutdown not needed Contention must be dismissed.
PERLIS, R G , LESSY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 2pp 18411 050 24X
Fiche 50-443, 83/03/21, 8305100356

--8305100430 Response to sixth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention NH-13 No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W. F , LESSY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 5pp 18411 052 24X
Fiche 50-443, 83/03/21, 8305100356

--8305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREG-0737, Item I A 1 1 requirements re shift technical advisor position Proposal acceptable
WIGGINS, J T Division of Project & Resident Programs 83/03/17 2pp 18411 057 24X Fiche 50-443, 83/03/21, 8305100356

--8305100432 Response to eighth motion for summary disposition of New England Coalition on Nuclear Pollution (NECNP) Contention I A 2 No genuine issue of matl fact exists & NECNP entitled to favorable decision
PATTERSON, W F , LESSY, R P Hearing Branch 3 83/03/18 Atomic Safety and Licensing Board Panel 4pp 18411 059 24X Fiche 50-443, 83/03/21, 8305100356

--8305100424 Affidavit of RG LaGrange on qualification of Class IE electric valve operators installed inside containment. Util committed to qualification per NUREG-0588
LAGRANGE, R G Equipment Qualification Branch 83/03/18 3pp 18411 064 24X Fiche 50-443, 83/03/21, 8305100356.

8305100158 Forwards CY Liang, WT LeFave & SS Kirslis joint affidavit reviewing & commenting on Table I A 2-3 which includes listing of all electric valve operators inside containment, per ASLB request
LESSY, R P Hearings Division PATTERSON, W F Office of the Executive Legal Director 83/04/20 HOYT, H , LUEBKE, E A , HARBOUR, J Atomic Safety and Licensing Board Panel. 3pp 18374 252 24X Fiche 50-443, 83/04/20, 8305100158

--8305100166 Affidavit of CY Liang, WT LeFave & SS Kirslis providing results of NRC review of Table I A 2-3 concerning environ qualification of electric valve operators installed inside containment Prof qualifications encl
LIANG, C Y Reactor Systems Branch LEFAVE, W T Auxiliary Systems Branch KIRSLIS, S S Chemical Engineering Branch 83/04/19 16pp 18374 255 24X Fiche 50-443, 83/04/20, 8305100158

8305100219 Forwards supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I A 2 in NRC 82122B response to first set of interrogatories W/affidavits re review of Table I A 2-3
LESSY, R P Office of the Executive Legal Director 83/04/20
CURRAN, D Harmon & Weiss 2pp 18374 145 24X
Fiche 50-443, 83/04/20, 8305100219

--8305100221 Supplemental responses to New England Coalition on Nuclear Pollution Interrogatories 4-8 re Contention I A 2 in NRC 82122B response to first set of interrogatories Affidavits re Table I A 2-3 encl
LESSY, R P , PATTERSON, W F Office of the Executive Legal Director 83/04/20 Atomic Safety and Licensing Board Panel 14pp 18374 147 24X Fiche. 50-443, 83/04/20, 8305100219

8305020425 Forwards Town of Seabrook request to participate as interested municipality Interests lie in areas of emergency planning, insurance & accidents & precautionary evacuation.
FELCH, F B , RANDALL, W I , FALCONER, J C Seabrook, NH 83/04/22
HOYT, H F. Atomic Safety and Licensing Board Panel 6p. 18273 196 24X Fiche 50-443, 83/04/22, 8305020425

--8305020429 Request to participate as interested municipality per 10CFR2 715(c)
FELCH, F B , RANDALL, W I , FALCONER, J. C. Seabrook, NH 83/04/22 Atomic Safety and Licensing Board Panel. 1p 18273-197 24X Fiche 50-443, 83/04/22, 8305020425

8305020482 Forwards Town of Exeter request to participate as interested municipality
CHICK, D E Exeter, NH 83/04/26 HOYT, H F Atomic Safety and Licensing Board Panel 1p. 18282-298. 24X Fiche 50-443, 83/04/26, 8305020482

--8305020486 Request to participate as interested municipality per 10CFR2 715(c)
CHICK, D E Exeter, NH 83/04/26 Atomic Safety and Licensing Board Panel 1p 18282 299 24X Fiche 50-443, 83/04/26, 8305020482

8305030541 Motion to reconsider ASLB 830425 memorandum & order in response to New England Coalition on Nuclear Pollution objection to 830414 conference call Complexity of issue justifies 20-day response period Certificate of Svc encl
CURRAN, D , BISHOP, L L New England Coalition on Nuclear Pollution
BISHOP, L L Harmon & Weiss 83/04/29 Atomic Safety and Licensing Board Panel 5pp 18301.357 24X Fiche. 50-443, 83/04/29, 8305030541

8305030570 Order admitting Town of Exeter, NH as interested municipality Exeter must observe procedural requirements & take proceeding as found.
HOYT, H F. Atomic Safety and Licensing Board Panel 83/04/29. Exeter, NH 7pp 18306-110 24X Fiche 50-443, 83/04/29, 8305030570

8305040300 Response to New England Coalition on Nuclear Pollution motion to amend petition to intervene Addl contention should be denied on grounds of timeliness or partially denied on grounds of vagueness Certificate of Svc encl
DIGNAN, T G , GAD, R K Public Service Co of New Hampshire
DIGNAN, T G Ropes & Gray 83/04/29 Atomic Safety and Licensing Board Panel 16pp 18324 001 24X Fiche 50-443, 83/04/29, 8305040300

8305040316 Response to Town of Seabrook, NH request to participate as interested municipality Emergency planning exercise & public insurance coverage issues may not be litigated in present proceeding Certificate of Svc encl
DIGNAN, T G , DIGNAN, T G Public Service Co of New Hampshire
GAD, R K Ropes & Gray 83/04/29 5pp 18323 295 24X
Fiche 50-443, 83/04/29, 8305040316

8305090501 Forwards request to participate as interested municipality in proceedings
SARGENT, A V Salisbury, MA 83/05/02 HOYT, H F Atomic Safety and Licensing Board Panel 2pp 18362 138 24X Fiche 50-443, 83/05/02, 8305090501

--8305090502 Request to participate as interested municipality in proceedings
SARGENT, A V Salisbury, MA 83/05/02 Atomic Safety and Licensing Board Panel 1p 18362.139 24X Fiche 50-443, 83/05/02, 8305090501.

8305060329 Responds to New England Coalition on Nuclear Pollution & State of NH submittals subsequent to 830407-08 prehearing conference Objects to word "omission" in reworded Coalition Contention I.D 2
LESSY, R P Hearing Branch 3 83/05/04 HOYT, H. , LUEBKE, E A. , HARBOUR, J Atomic Safety and Licensing Board Panel. 4pp 18344.081 24X Fiche 50-443, 83/05/04, 8305060329

8305060463 Order denying New England Coalition on Nuclear Pollution 830429 motion for reconsideration of ASLB 830425 memorandum & order. No basis exists to reconsider order.
HOYT, H F Atomic Safety and Licensing Board Panel 82/05/04. New England Coalition on Nuclear Pollution 3pp 18348.072. 24X Fiche 50-443, 83/05/04, 8305060463.

8305090508 Order admitting Town of Seabrook, NH as interested municipality All procedural requirements must be observed.
HOYT, H F Atomic Safety and Licensing Board Panel. 83/05/06. 6pp. 18362 140 24X Fiche 50-443, 83/05/06, 8305090508

8305100200 Order admitting Town of Salisbury, MA as interested municipality List of Seabrook contentions remaining as of 830414 encl
HOYT, H F. Atomic Safety and Licensing Board Panel. 83/05/06. Atomic Safety and Licensing Board Panel 6pp 18374 023. 24X Fiche. 50-443, 83/05/06, 8305100200

8305270573 Requests inclusion as intervenor in upcoming hearings re evacuation planning for facility
NOWLES, S W. Northampton County, PA 83/05/07 Atomic Safety and Licensing Board Panel 3pp. 18646 112 24X Fiche. 50-443, 83/05/07, 8305270573

8305100334 Response opposing New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene Motion should be rejected as untimely filed. Certificate of Svc encl.
PERLIS, R G. , LESSY, R P Hearing Branch 3 83/05/09 Atomic Safety and Licensing Board Panel 8pp 18378-329. 24X Fiche 50-443, 83/05/09, 8305100334.

8305130087 Informs that Strafford County Superior Court will be available for ASLB hearings during part of Jul & all of Aug 1983, in response to request for hearing
D'AMOURS, N.E. House of Rep 83/05/09. HOYT, H.F. Atomic Safety and Licensing Board Panel 1p. 18440 044 24X Fiche: 50-443, 83/05/09, 8305130087

8305130181 Memorandum & order memorializing 830407-08 prehearing conference in Boston, MA Rulings made on filing of contentions re Newburyport, MA emergency plan & re motions for summary disposition
HOYT, H F Atomic Safety and Licensing Board Panel 83/05/11. Public Service Co of New Hampshire 36pp. 18440 001 24X Fiche: 50-443, 83/05/11, 8305130181

8305160068 Affidavit of GC Minor responding to NRC 830420 affidavit on qualification of electric valve operators at plant Operators must be considered important to safety & environmentally qualified. Certificate of Svc encl. Related correspondence.
MINOR, G C. New England Coalition on Nuclear Pollution. 83/05/11 13pp. 18453 105. 24X Fiche: 50-443, 83/05/11, 8305160068

8305160002 Motion to file out-of-time answer to NRC affidavit re Contention I A 2 concerning environ qualification of electric valve operators inside containment Intervenor unable to complete review within 10-day period set by ASLB
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel 3pp 18456 056 24X Fiche 50-443, 83/05/12, 8305160002

8305160019 Response opposing NRC 830420 affidavit supporting assertion that none of unqualified electric valve operators inside containment are important to safety Failure to operate could prevent successful cooling of reactor
CURRAN, D , JORDAN, W S New England Coalition on Nuclear Pollution
CURRAN, D Harmon & Weiss 83/05/12 Atomic Safety and Licensing Board Panel 4pp 18452 341 24X Fiche 50-443, 83/05/12, 8305160019

8305170478 Memorandum & order denying New England Coalition on Nuclear Pollution 830421 motion to amend petition to intervene to admit new Contention NECNP VII on environ qualification of electrical equipment important to safety
HOYT, H F Atomic Safety and Licensing Board Panel 83/05/13 New England Coalition on Nuclear Pollution 6pp 18470 092 24X Fiche. 50-443, 83/05/13, 8305170478

8305190346 Requests public meeting be held to receive public input for preparation of Town of Hampton radiological emergency mgt plan
WALKER, J. R Hampton, NH 83/05/13 Affiliation Unknown 1p 18500 022 24X Fiche 50-443, 83/05/13, 8305190346

8305190199 Motion to amend petition to intervene by adding Contention SAPL Suppl 7, "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer 83/05/16 Atomic Safety and Licensing Board Panel 5pp. 18502.205 24X Fiche 50-443, 83/05/16, 8305190199

8305250327 Requests MB Pearson be placed on svc list as Town of Amesbury, MA representative, per ASLB 830328 ltr
STUART, D L Amesbury, MA 83/05/16 HOYT, H F Atomic Safety and Licensing Board Panel 1p 18585 361 24X Fiche 50-443, 83/05/16, 8305250327

8305240451 Order promulgating schedules for proceeding, including schedules for technical safety & onsite & offsite emergency planning contentions
HOYT, H F Atomic Safety and Licensing Board Panel 83/05/23 4pp 18574:120 24X Fiche 50-443, 83/05/23, 8305240451

8305310147 Response to SAPL motion to amend petition to intervene re SER open items Motion should be denied on grounds of timeliness Certificate of Svc encl
DIGNAN, T G Public Service Co of New Hampshire DIGNAN, T. G. Ropes & Gray. 83/05/24 Atomic Safety and Licensing Board Panel 8pp 18651 209. 24X Fiche 50-443, 83/05/24, 8305310147

8305270598 Order granting Town of North Hampton, NH 830507 petition to intervene re evacuation planning & admitting town as interested municipality in proceeding per 10CFR2 715(c)
HOYT, H F Atomic Safety and Licensing Board Panel. 83/05/25
Public Service Co of New Hampshire 2pp 18645·361 24X
Fiche: 50-443, 83/05/25, 8305270598

H General correspondence

8305250331 Offers use of junior high school auditorium for Aug 1983 licensing hearings. Auditorium seats 500 people & has adjacent nurses room & bathroom for personal use
NADEAU, J P , YOUNG, M L , HOLWAY, F. I Rye, NH 83/05/20 HOYT, H F
Atomic Safety and Licensing Board Panel 1p 18592 104 24X
Fiche· 50-443, 83/05/20, 8305250331

O Advisory Committee on Reactor Safeguards reports & correspondence

8305130352 Informs of uneasiness on selection of 1755 Cape Ann earthquake as facility std for design response spectra Critical safety-related components should be designed to withstand larger Charleston event
POMEROY, P W. Rondout Associates. POMEROY, P W ACRS - Advisory Committee on Reactor Safeguards 83/04/05 KERR, W ACRS - Advisory Committee on Reactor Safeguards 2pp 18443 333 24X
Fiche· 50-443, 83/04/05, 8305130352

8305130335 Forwards ACRS 830419 ltr re review of application for OL, reporting on low power operation
KNIGHTON, G. W Licensing Branch 3. 83/04/25. HARRISON, R J Public Service Co. of New Hampshire 3pp 18457 328 24X
Fiche: 50-443, 83/04/25, 8305130335

--8305130339 Comments on lower power operation review of OL application Operation reasonably assured at core power levels up to 5% full power w/o undue risk to public health & safety
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/04/19 PALLADINO, N J Commissioners 3pp 18457 331 24X Fiche 50-443, 83/04/25, 8305130335

8305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities Supporting documentation encl
MAXWELL, J C Maxwell, J C MAXWELL, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/05 KERR, W ACRS - Advisory Committee on Reactor Safeguards 5pp 18443 335 24X Fiche 50-443, 83/05/05, 8305130347

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305050116 Forwards IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/04/01
HARRISON, R J Public Service Co of New Hampshire 2pp 18342 244
24X Fiche: 50-443, 83/04/01, 8305050116

--8305050119 IE Insp Repts 50-443/83-05 & 50-444/83-05 on 830301-0408 No noncompliance noted Major areas inspected work activities, procedures & records re sys & component installation & structural steel erection
CERNE, A C , GRAMM, R A , NARROW, L M Region 1, Office of Director 83/04/20 12pp 18342 246 24X Fiche 50-443, 83/04/01, 8305050116

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25, Consolidated Edison Co of New York, Inc 119pp. 18381.291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382.047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382.282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc. 119pp 18441.001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305200495 Supplementary Part 21 rept re adequacy of svc water cooling tower structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630
BARSTEN,G E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/04/29 Region 1, Office of Director 3pp 18514 033 24X Fiche 50-443,83/04/29,8305200495

8305160039 Final deficiency rept re sheared pinion keys on six Limitorque motor operators Initially reported on 820805 Westinghouse will replace pinion keys on all SB-0 motor operators for Westinghouse valves
DEVINCENTIS,J Public Service Co of New Hampshire 83/05/04 STAROSTECKI,R Division of Project & Resident Programs 3pp 18453:127 24X Fiche 50-443,83/05/04,8305160039.

8305110299 PNO-1-83-048 on 830429,potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds,involving procedural violations during magnetic particle exam
CERNE,A , GALLO,R Region I, Office of Director 83/05/06 1p 18393 333 24X Fiche 50-443,83/05/06,8305110299

8305190164 Second interim deficiency rept re Westinghouse EMD gate valve position indication Initially reported on 830110 Investigation continuing Detailed description,analysis of safety implications & corrective actions expected by 830610.
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 83/05/09 STAROSTECKI,R Division of Project & Resident Programs 2pp 18502 235 24X
Fiche 50-443,83/05/09,8305190164

8305200353 Final deficiency rept re DS-416 reactor trip switchgear malfunction Initially reported on 830422 Caused by deviations from breaker internal recommended clearances Manufacturer drawings modified
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 83/05/16 STAROSTECKI,R Division of Project & Resident Programs 3pp 18518 091. 24X
Fiche 50-443,83/05/16,8305200353

8305200402 Interim deficiency rept re svc water & circulating water pump house structural inadequacy Initially reported on 830419 Detailed engineering evaluation scheduled for completion by 830722
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 83/05/16 STAROSTECKI,R Division of Project & Resident Programs 2pp 18517 295 24X
Fiche 50-443,83/05/16,8305200402

8305250244 Second interim deficiency rept re power transistor heat sink separation from transistors in Westinghouse 7300 Series process instrumentation & control sys cabinets. Initially reported on 830318 Evaluation rept expected by 830630
DEVINCENTIS,J Yankee Atomic Electric Co DEVINCENTIS,J Public Service Co of New Hampshire 83/05/20 STAROSTECKI,R Division of Project & Resident Programs 1p 18592 297 24X
Fiche 50-443,83/05/20,8305250244

U Congressional/Executive Correspondence

8304250241 Requests suggestions for appropriate facility to accommodate licensing proceeding in reasonable space & comfort & w/o unnecessary handicaps
HOYT,H F Atomic Safety and Licensing Board Panel 83/04/20
D'AMOURS,N E House of Rep 1p 18178 111 24X
Fiche 50-443,83/04/20,8304250241

DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA ,UNIT 1

A Application/construction stage documents & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root,Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000,83/03/09,8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE,J F Commissioners 5pp
18497 228 24X Fiche 50-000,83/03/09,8305180001

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE,J Regulatory Reform Task Force 83/04/11
PALLADINO,N J Commissioners 2pp 18542 272. 24X
Fiche,50-000,83/04/11,8305230720

8305090722 Board Notification 83-12 forwards rept, "Design & Const - Self-Initiated Evaluation," to facilitate general upgrading of plant & industry
NOVAK,T M Assistant Director for Licensing AS BN83-12 83/05/02, Atomic Safety and Licensing Board Panel 3pp 18368 291 24X
Fiche 50-445,83/05/02,8305090722

--8305090726 "Design & Const - Self-Initiated Evaluation,Comanche Peak Steam Electric Station "
* Texas Utilities Generating Co 82/10/31 354pp 18368 294
24X Fiche 50-445,83/05/02,8305090722

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305120109 Summary of 830413 meeting w/util in Bethesda,MD re added assurance program to assure independent verification program requirements met
BURWELL,S B Licensing Branch 1 83/05/04 Licensing Branch 1, 7pp 18443 179 24X Fiche 50-445,83/05/04,8305120109

8305100125 Forwards comments on environ qualification correlation between installed & qualified components as followup to 821014 audit trip rept on Item II.a, "Auxiliary Bldg Modular Train Filter "
SCHMIDT,H C Texas Utilities Services, Inc 83/05/05,
YOUNGBLOOD,B J Licensing Branch 1 2pp 18375 029. 24X
Fiche 50-445,83/05/05,8305100125

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305230627 Forwards request for procedures generation package needed to complete OL application evaluation
YOUNGBLOOD,B J Licensing Branch 1 83/05/12 GARY,R J Texas Utilities Generating Co 4pp 18543 029 24X Fiche 50-445, 83/05/12,8305230627.

8305310151 Comments on alternate shutdown reactor heat removal Direct readings of process variables necessary to perform & control reactor heat removal provided at hot shutdown panel as part of alternate shutdown design
SCHMIDT,H C Texas Utilities Services, Inc 83/05/20,
YOUNGBLOOD,B J Licensing Branch 1 3pp 18651.221 24X
Fiche 50-445,83/05/20,8305310151

F Security, medical, emergency & fire protection plans

8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness
MIZUNO,G S Hearing Branch 1 83/04/29 BLOCH,P B , JORDAN,W H ,
MCCOLLOM,K A Atomic Safety and Licensing Board Panel 3pp
18292 163 24X Fiche 50-445,83/04/29,8305030464

8305240213 Forwards monthly status rept on offsite emergency
preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations
83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

Q Adjudicatory correspondence

8212300009 Brief in opposition to NRC exceptions to ASLB 820930 order
denying reconsideration of orders to produce info Affidavit
& Certificate of Svc encl
ELLIS,J Citizens Association for Sound Energy 82/12/21 Atomic
Safety and Licensing Appeal Panel 175pp 16599 036 24X
Fiche 50-445,82/12/21,8212300009

8305020422 Motion to allow Citizens Assoc for Sound Energy to file
written argument on issue in lieu of presenting oral
argument at 830119 hearing Citizens do not have finances to
come to Bethesda,MD for 40-minute argument
ELLIS,J Citizens Association for Sound Energy 83/01/11 Atomic
Safety and Licensing Appeal Panel 2pp 18283 001 24X
Fiche 50-445,83/01/11,8305020422

--8305020430 Written argument on issues to be argued orally on 830119 in
Bethesda,MD Citizens Assoc for Sound Energy unable to attend
or find representative Whistleblower protection discussed
ELLIS,J Citizens Association for Sound Energy 83/01/11
Atomic Safety and Licensing Appeal Panel 65pp 18283 003 24X
Fiche 50-445,83/01/11,8305020422

--8305020437 Forwards Citizens Assoc for Sound Energy witness J Doyle
affidavit re blacklisting due to testimony at hearings
ELLIS,J Citizens Association for Sound Energy 83/01/18
ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel 1p
18283 068 24X Fiche 50-445,83/01/11,8305020422

--8305020444 Affidavit of J Doyle re blacklisting due to testimony at
hearings NRC should take immediate & stringent measures to
stop insidious practice NRC current protection for
whistleblowers is farce & charade Certificate of Svc encl
DOYLE,J Affiliation Unknown 83/01/17 4pp 18283 069 24X
Fiche 50-445,83/01/11,8305020422

8305040529 Affidavit of MA Walsh re computer program in J Doyle 830426
surrebuttal testimony STRUDL program utilized w/sufficient
similarities to assure results will be accurate
WALSH,M A Citizens Association for Sound Energy 83/04/26 1p
18320 001 24X Fiche 50-445,83/04/26,8305040529

8305040296 Motion for discovery re applicant & NRC interrogatories on
const appraisal team Insp Repts 50-445/83-18 & 50-446/83-12
Related correspondence
ELLIS,J. Citizens Association for Sound Energy 83/04/28. Atomic
Safety and Licensing Board Panel 3pp 18324.025 24X
Fiche 50-445,83/04/28,8305040296

8305040499 Fourteenth set of interrogatories & requests to produce.
Related correspondence
ELLIS,J Citizens Association for Sound Energy 83/04/28 Texas
Utilities Generating Co 10pp 18322 111 24X
Fiche.50-445,83/04/28,8305040499

8305040513 Fourth set of interrogatories & requests to produce Related
correspondence
ELLIS,J Citizens Association for Sound Energy 83/04/28. Office
of the Executive Legal Director 7pp. 18321 249 24X
Fiche·50-445,83/04/28,8305040513

8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness
MIZUNO,G S Hearing Branch 1 83/04/29 BLOCH,P B , JORDAN,W H. ,
MCCOLLOM,K A. Atomic Safety and Licensing Board Panel 3pp
18292 163 24X Fiche 50-445,83/04/29,8305030464

8305030514 Motion for protective order that discovery not be had re
draft notice of violation on calculation of deflection of
rigid support CC-1-107-008-E23R Draft is not final NRC
document Certificate of Svc encl
ROTHSCHILD,M U Hearing Branch 1 83/04/29 Atomic Safety and
Licensing Board Panel 7pp 18306 350 24X Fiche 50-445,83/04/29,
8305030514

8305030522 Order extending time until 830503 for Commission to act to
review ALAB-714
CHILK,S J Office of the Secretary of the Commission 83/04/29
Commissioners 1p 18306 357 24X Fiche 50-445,83/04/29,
8305030522

8305040531 Advises of NRC agreement to voluntarily release one
paragraph designated by Judge Bloch as containing factual
info possibly relevant to litigation,from draft 821229
notice of violation Paragraph set forth
TREBY,S A Hearing Branch 1 83/05/03 CASE,J Citizens
Association for Sound Energy 1p 18321 241 24X
Fiche 50-445,83/05/03,8305040531

8305040557 Reply to State of TX brief on collateral estoppel State of
TX erred in concluding Dept of Labor decision should be
given collateral estoppel effect Decision not sufficiently
firm to be accorded preclusive effect
ROTHSCHILD,M U Hearing Branch 1 83/05/03 4pp 18321 282 24X
Fiche 50-445,83/05/03,8305040557

--8305040560 Reply to Citizens Assoc for Sound Energy brief re
consideration of LOCA in design criteria for pipe supports
Operability of pipe supports not necessary to assure
safety-related component operability W/Certificate of Svc
MIZUNO,G S Hearing Branch 1 83/05/03 9pp 18321 286 24X
Fiche 50-445,83/05/03,8305040557

8305050015 Order extending time until 830520 for Commission to act to
review ALAB-714
CHILK,S J Office of the Secretary of the Commission 83/05/03
Commissioners 1p 18339 055 24X Fiche 50-445,83/05/03,
8305050015

830505001B Reply brief to Citizens Assoc for Sound Energy 830420 brief
re consideration of effects of LOCA on pipe support design
Citizens erroneously applied provisions of ASME Code not
applicable to design Certificate of Svc encl
REYNOLDS,N S , HORIN,W A Texas Utilities Generating Co
REYNOLDS,N S Debevoise & Liberman 83/05/03 21pp 18338 334
24X Fiche 50-445,83/05/03,8305050018

8305090443 Response in opposition to NRC 830420 response to ASLB
question re LOCA-induced thermal expansion in linear
supports & applicant 830421 brief on consideration of pipe
support design thermal stresses W/Certificate of Svc
ELLIS,J Citizens Association for Sound Energy 83/05/03 Atomic
Safety and Licensing Board Panel 25pp 18363 001 24X
Fiche 50-445,83/05/03,8305090443

8305110137 Responds to 830504 request to review proposed protective
agreement between Citizens Assoc for Sound Energy & ITT-
Grinnel re design criteria for pipe supports Wording too
restrictive Revised proposal encl for review
ELLIS,J Citizens Association for Sound Energy 83/05/04 HORIN,W
Debevoise & Liberman 4pp 18393 344 24X Fiche 50-445,83/05/04,
8305110137

8305110347 Certifies svc of J Doyle 830504 supplemental surrebuttal
testimony
ELLIS,J Citizens Association for Sound Energy 83/05/04 2pp
18406·158 24X Fiche 50-445,83/05/04,8305110347

8305090507 Forwards testimony of LJ Skiles,AB Armstrong & CL Born re
emergency planning recommendations,A Vega testimony re const
appraisal team rept & JS Marshall,DH Wade,JC Finneran &
DR Woodlan affidavits Related correspondence
REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Texas Utilities
Generating Co 83/05/05 BLOCH,P B , MCCOLLOM,K A , JORDAN,W H
Atomic Safety and Licensing Board Panel 2pp 18362 014 24X
Fiche 50-445,83/05/05,8305090507

--8305090517 Affidavit of JS Marshall in response to ASLB inquiry re
classification of equipment for application of 10CFR50,App B
requirements & relationship of Board Notification 83-13 to
HR Denton 811120 memo on classification
MARSHALL,J S Texas Utilities Generating Co 83/05/05 7pp
18362 026 24X Fiche 50-445,83/05/05,8305090507

--8305090521 Affidavit of DH Wade re Midland-Ross superstrut matl
(Board Notifications 83-02 & 83-14) & welds in main control
board panels (Board Notifications 82-90,90A & 116)
WADE,D H Texas Utilities Generating Co 83/05/05 90pp
18362 033 24X Fiche 50-445,83/05/05,8305090507

--8305090525 Affidavit of JC Finneran on applicant response to Board
Notification 82-105 re pipe clamps employed on ASME Code
Class I piping
FINNERAN,J C Texas Utilities Generating Co 83/05/05 3pp
18362 123 24X Fiche 50-445,83/05/05,8305090507

--8305090530 Affidavit of DR Woodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl
WOODLAN,D R Texas Utilities Generating Co 83/05/05 12pp 18362 126 24X Fiche 50-445,83/05/05,8305090507

8305090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon
TREBY,S A , ROTHSCHILD,M U , MIZUNO,G S Hearing Branch 1 83/05/05 BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445,83/05/05, 8305090568

--8305090578 Supplemental testimony of S Burwell,WP Chen,JI Tapia,J Rajan & RG Taylor re concerns raised by MA Walsh & J Doyle & NRC const appraisal insp rept Prof qualifications encl
BURWELL,S Division of Licensing CHEN,W P Energy, Dept of. TAPIA,J I Division of Resident, Reactor Project & Engineering Programs 83/05/05 14pp 18360 004 24X Fiche 50-445,83/05/05, 8305090568

--8305090586 Supplemental testimony of DM Rohrer & T Urbanik re emergency preparedness
ROHRER,D M Emergency Preparedness Branch URBANIK,T Texas A&M Univ , College Station, TX 83/05/05 20pp 18360 018 24X Fiche 50-445,83/05/05,8305090568

--8305090592 Supplemental testimony of A Lookabaugh & J Benton re emergency preparedness
LOOKABAUGH,A , BENTON,J Federal Emergency Management Agency 83/05/05 15pp 18360 038 24X Fiche 50-445,83/05/05,8305090568

--8305090600 Affidavit of SB Burwell re questions posed during ASLB 830407 telcon on implemented procedures concerning maint of scram breakers as result of Board Notifications 83-26 & 83-38 Prof qualifications encl
BURWELL,S B Licensing Branch 1 83/05/05 5pp 18360 053 24X Fiche 50-445,83/05/05,8305090568

--8305090607 Affidavit of FD Coffman on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants," per ASLB 830407 telcon request Prof qualifications encl
COFFMAN,F D Reliability & Risk Assessment Branch 83/05/05 9pp 18360 058 24X Fiche 50-445,83/05/05,8305090568

--8305090618 Affidavit of S Diab re semiscale feed & bleed Experiment S-SR-2 & related subsequent RELAP-5 analyses,per ASLB 830407 telcon request Prof qualifications encl
DIAB,S Reactor Systems Branch 83/05/05 5pp 18360 067 24X Fiche 50-445,83/05/05,8305090568

--8305090625 Affidavit of TG Dunning re ASLB 830407 telcon question on reactor trip (scram) sys & conformance w/IEEE-279 Prof qualifications encl
DUNNING,T G Instrumentation & Control Systems Branch 83/05/05 6pp 18360 072 24X Fiche 50-445,83/05/05,8305090568

--8305090632 Affidavit of WP Haass re ASLB 830407 telcon questions on NRC interpretation of 10CFR50,App B Prof qualifications encl
HAASS,W P QA Branch. 83/05/05 5pp 18360 078 24X Fiche 50-445,83/05/05,8305090568

--8305090640 Affidavit of CE Rossi re ASLB 830407 telcon questions concerning status of NRC position on Unresolved Safety Issue A-9, "ATWS " Prof qualifications encl
ROSSI,C E Instrumentation & Control Systems Branch 83/05/05 5pp 18360 083 24X Fiche 50-445,83/05/05,8305090568

--8305090646 Affidavit of AJ Szukiewicz & TG Dunning re ASLB 830407 questions on Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Prof qualifications encl
SZUKIEWICZ,A J Generic Issues Branch DUNNING,T G Instrumentation & Control Systems Branch 83/05/05 9pp 18360 093 24X Fiche 50-445,83/05/05,8305090568

--8305090650 Affidavit of RG Taylor re ASLB 830407 telcon questions on use of superstrut matl
TAYLOR,R.G Region 4, Office of Director 83/05/05 2pp 18360 102 24X Fiche 50-445,83/05/05,8305090568

ac re ASLB 830407 telcon questions on "Alleged Design Deficiency "

,eering Branch 83/05/05 5pp
15,83/05/05,8305090568

--8305090660 Testimony of AB Beach re const appraisal team insp concerning pipe support const & pipe support design interfaces w/const Prof qualifications encl
BEACH,A B Director's Office, Office of Inspection and Enforcement 83/05/05 4pp 18360 109 24X Fiche 50-445,83/05/05,8305090568

8305090560 Notice of 830612-17 evidentiary hearings re const appraisal team QA study Limited appearance statements will be disallowed
BLOCH,P B Atomic Safety and Licensing Board Panel 83/05/06 1p 18360 153 24X Fiche 50-445,83/05/06,8305090560

8305100270 Confirms ASLB response to util question re delegation of authority to county judges to make decisions concerning radiological emergency protective action notification & recommendations
REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Texas Utilities Generating Co 83/05/06 BLOCH,P B Atomic Safety and Licensing Board Panel 1p 18371 338 24X Fiche 50-445,83/05/06,8305100270

8305100321 Forwards drawing of upper lateral restraint ref in J Doyle 830426 rebuttal testimony
REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Texas Utilities Generating Co 83/05/06 BLOCH,P B Atomic Safety and Licensing Board Panel 2pp 18370 091 24X Fiche 50-445,83/05/06,8305100321

8305110332 Requests info re introduction into evidence of const & appraisal team insp & investigation repts by NRC
ELLIS,J Citizens Association for Sound Energy 83/05/06 ROTHSCHILD,M U Office of the Executive Legal Director 1p. 18406 147 24X Fiche 50-445,83/05/06,8305110332

8305110368 Discusses proposed stipulation re listed Citizens Assoc for Sound Energy discovery matters
ELLIS,J Citizens Association for Sound Energy 83/05/06 ROTHSCHILD,M U Office of the Executive Legal Director. 2pp 18406 077 24X Fiche 50-445,83/05/06,8305110368

8305110397 Submits list of stipulations re Citizens Assoc for Sound Energy exhibits for verification of authenticity & possible admission into evidence
ELLIS,J Citizens Association for Sound Energy 83/05/06. HORIN,N Debevoise & Liberman 2pp 18406 195 24X Fiche 50-445,83/05/06, 8305110397

8305110357 Response opposing NRC 830505 motion to withdraw Sept 1982 prefiled testimony Certificate of Svc encl.
ELLIS,J Citizens Association for Sound Energy 83/05/07. Atomic Safety and Licensing Board Panel 4pp 18406 082 24X Fiche 50-445,83/05/07,8305110357

8305100267 Forwards original signed pages to JS Marshall,DH Wade,JC Finneran & DR Woolan affidavits filed on 830505.
HORIN,W A Debevoise & Liberman HORIN,W A Texas Utilities Generating Co 83/05/09 STUCKY,S W Docketing & Services Branch 5pp 18371 236 24X Fiche 50-445,83/05/09,8305100267.

8305100295 Answer opposing Citizens Assoc for Sound Energy motion for discovery re const appraisal team rept Discovery requests unnecessary,cumulative,unduly burdensome & untimely. Certificate of Svc encl.
REYNOLDS,N S Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 83/05/09 Atomic Safety and Licensing Board Panel. 6pp 18371 255 24X Fiche 50-445,83/05/09,8305100295.

8305130064 Motion to allow addl supplementary surrebuttal testimony of J Doyle,witness for intervenor Receipt of drawing creates need to revise previous testimony
ELLIS,J Citizens Association for Sound Energy 83/05/09. Atomic Safety and Licensing Board Panel 2pp 18436.331 24X Fiche 50-445,83/05/09,8305130064

8305130175 Response to ASLB 830506 request for discussion of interrelationship of ASME App XVII,Section 2271 3,to rest of ASME Code App is mandatory & integral part of ASME Code & is applicable to pipe supports Certificate of Svc encl
ELLIS,J Citizens Association for Sound Energy 83/05/09 34pp. 18437 303 24X Fiche 50-445,83/05/09,8305130175.

8305130013 Answer to Citizens Assoc for Sound Energy 830428 motion for discovery Answers to interrogatories filed as limited discovery on IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 relevant
ROTHSCHILD,M U Hearing Branch 1 83/05/11 Atomic Safety and Licensing Board Panel 3pp 18437 133 24X Fiche 50-445,83/05/11, 8305130013

--8305130021 Answers to fourth set of interrogatories & requests to produce
BEACH,A B Director's Office, Office of Inspection and Enforcement 83/05/11 Citizens Association for Sound Energy. 12pp. 18437 136 24X Fiche 50-445,83/05/11,8305130013

8305130033 Response to ASLB inquiry re ASME Boiler & Pressure Vessel Code App XVII App delineates requirements & stress limits for analysis of linear pipe supports
MIZUNO,G S Hearing Branch 1 83/05/11 3pp 18437 094 24X Fiche 50-445,83/05/11,8305130033

--8305130040 Affidavit of RJ Bosnak re App XVII-2000 requirements & stress limits for linear elastic analysis of linear pipe supports Article XVII-2271 3 requires appropriate design consideration be given Certificate of Svc encl
BOSNAK,R J Office of Nuclear Reactor Regulation, Director 83/05/11 4pp 18437 097 24X Fiche 50-445,83/05/11,8305130033

8305130260 Supplemental reply brief re pipe support design Consideration of thermal expansion of supports not required in design of linear-type pipe supports Certificate of Svc encl
REYNOLDS,N S , HORIN,W A Texas Utilities Generating Co REYNOLDS,N S Debevoise & Liberman 83/05/11 Atomic Safety and Licensing Board Panel 7pp 18439 244 24X Fiche 50-445,83/05/11, 8305130260

8305170287 Forwards improved drawing received from applicant in response to request re Citizens Assoc for Sound Energy Exhibit 763 (J Doyle 830504 supplemental surrebuttal testimony)
ELLIS,J Citizens Association for Sound Energy 83/05/11 BLOCH,P B , MCCOLLOM,K A , JORDAN,W H Atomic Safety and Licensing Board Panel 3pp 18465 354 24X Fiche 50-445,83/05/11,8305170287

8305170513 Forwards addl exhibits to assist in reaching stipulations prior to hearings W/o encl
ELLIS,J Citizens Association for Sound Energy 83/05/11 ROTHSCHILD,M U Hearing Branch 1 REYNOLDS,N S Debevoise & Liberman 2pp 18470 009 24X Fiche 50-445,83/05/11,8305170513

8305160147 Forwards AB Beach 830511 signed affidavit & prof qualifications to NRC 830511 answers to Citizens Assoc for Sound Energy fourth set of interrogatories
ROTHSCHILD,M U Hearing Branch 1 83/05/12 ELLIS,J Citizens Association for Sound Energy 3pp 18446 101 24X Fiche 50-445,83/05/12,8305160147

8305200504 Forwards 830513 ltr transmitted to Region IV & util in response to ASLB directive re cross-examination document delivery.
ELLIS,J. Citizens Association for Sound Energy 83/05/16 BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 1p 18514 086 24X Fiche 50-445,83/05/16,8305200504

8305200554 Order extending time until 830527 for Commission to act to review ALAB-714
CHILK,S J Office of the Secretary of the Commission 83/05/19 Commissioners 1p 18519 091 24X Fiche 50-445,83/05/19, 8305200554

8305270015 Forwards NB Le,DC Ford,P Keshishian,RM Compton,GC Gower, HW Phillips & WA Hansen prof qualifications Individuals listed in NRC answer to Interrogatory 1 (fourth set) & requests to produce
ROTHSCHILD,M.U Hearing Branch 1 83/05/26 ELLIS,J Citizens Association for Sound Energy 10pp 18633 352 24X Fiche: 50-445,83/05/26,8305270015

8305310011 Order extending time until 830606 for Commission to act to review ALAB-714
CHILK,S J. Office of the Secretary of the Commission 83/05/27 Commissioners 1p 18653 239 24X Fiche 50-445,83/05/27, 8305310011

K. Utility Final Safety Analysis Report (FSAR) & amends

8305160138 Forwards Amend 40 to FSAR
GARY,R J Texas Utilities Generating Co 83/05/09 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18446,190 24X Fiche,50-445,83/05/09,8305160138

--8305160141 Amend 40 to FSAR
* Texas Utilities Generating Co 83/05/09 397pp 18446 194 24X Fiche,50-445,83/05/09,8305160138

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc, 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385.

8305100093 Confirms plan to perform independent verification insp on 830425-0506 Addl info re required documentation packages for 47 welds selected for independent verification requested by 830411
GAGLIARDO,J E Division of Resident, Reactor Project & Engineering Programs 83/04/11 GARY,R J Texas Utilities Generating Co 8pp 18377 266 24X Fiche 50-445,83/04/11,8305100093

8305120145 Forwards IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Executive summary of results & list of potential enforcement actions encl
Region IV will address findings at later date
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/04/11 GARY,R J Texas Utilities Generating Co 10pp 18427 262 24X Fiche 50-445,83/04/11,8305120145

--8305120155 IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Major areas inspected electrical & instrumentation const,mechanical const,welding & NDE & civil & structural const
BEACH,A B , KESHISHIAN,P I , GOWER,G C Reactor Construction Branch 83/04/08 89pp 18427 270 24X Fiche 50-445,83/04/11, 8305120145

8305100247 Forwards IE Insp Rept 50-445/83-13 on 830307-11 No noncompliance noted
MADSEN,G L Region 4, Office of Director 83/04/13 GARY,R J Texas Utilities Generating Co 2pp 18373 279 24X Fiche 50-445,83/04/13,8305100247

--8305100249 IE Insp Rept 50-445/83-13 on 830307-11 No noncompliance noted Major areas inspected review of electrical instrumentation cable quality records & review of QA audits of electrical instrumentation & cables
MULKIKIN,R P , HUNNICUTT,D M , WESTERMAN,T F Region 4, Office of Director 83/04/07 5pp 18373 281 24X Fiche 50-445,83/04/13, 8305100247

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305120610 Informs that commitments re extent & method of exam of preservice insp program consistent w/inservice exams,based on Reg Guide 1 150 Preservice exam plan described in 830301 ltr acceptable provided plan completed before 840115
YOUNGBLOOD,B J Licensing Branch 1 83/04/27 GARY,R J Texas Utilities Generating Co 2pp 18440 354 24X Fiche 50-445, 83/04/27,8305120610

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047, 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305170309 Forwards IE Insp Rept 50-445/83-08 on 830301-31 & notice of violation
MADSEN,G L Region 4, Office of Director 83/04/29 GARY,R J Texas Utilities Generating Co 2pp 18466 001 24X Fiche 50-445,83/04/29,8305170309

--8305170313 Notice of violation from insp on 830301-31
* Region 4, Office of Director 83/04/29 1p 18466 003 24X Fiche 50-445,83/04/29,8305170309

--8305170318 IE Insp Rept 50-445/83-08 on 830301-31 Noncompliance noted failure to review change to Rev 0 to Procedure IPO-001A, "Plant Startup from Cold Shutdown "
KELLEY,D L , MCCRORY,S L , WESTERMAN,T F Region 4, Office of Director 83/04/28 11pp 18466 004 24X Fiche 50-445,83/04/29, 8305170309

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305160240 Board Notification 83-29C provides 830413 meeting summary describing continuing discussion between NRC & util on need for program to assure adequate plant design & const, as result of const appraisal team insp
NOVAK, T M Assistant Director for Licensing 83/05/04 Atomic Safety and Licensing Board Panel 4pp 18471 351 24X Fiche 50-445, 83/05/04, 8305160240

--8305160244 Summary of 830413 meeting w/util in Bethesda, MD re misunderstanding between util & NRC on need for added assurance that plant designed & contructed in accordance w/ application Results of const appraisal team insp discussed
BURWELL, S B Licensing Branch 1 83/05/04 Licensing Branch 1 6pp 18471 354 24X Fiche 50-445, 83/05/04, 8305160240

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305120373 Informs that IE Insp Rept 50-455/83-05 canceled No rept will be issued under subj number
MADSEN, G L Region 4, Office of Director 83/05/09 GARY, R J Texas Utilities Generating Co 1p 18432 280 24X Fiche 50-445, 83/05/09, 8305120373

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305230445 Forwards IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/05/13 GARY, R J Texas Utilities Generating Co 2pp 18538 178 24X Fiche 50-445, 83/05/13, 8305230445

--8305230449 IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted Major areas inspected- followup of unresolved items in IE Insp Repts 50-445/82-26, 50-446/82-14 & 50-445/82-22
TAPIA, J I , CHEN, W P , HUNNICUTT, D M Region 4, Office of Director 83/05/03 8pp 18538 180 24X Fiche 50-445, 83/05/13, 8305230445

8305200416 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-03 & 50-446/83-01
MADSEN, G L Region 4, Office of Director 83/05/18 GARY, R J Texas Utilities Generating Co 1p 18518 124 24X Fiche 50-445, 83/05/18, 8305200416

--8305200419 Responds to NRC 830328 ltr re violations noted in IE Insp Repts 50-445/83-03 & 50-446/83-01 Corrective actions light poles will be inspected & items designated non-nuclear safety-related reviewed & upgraded
GARY, R J Texas Utilities Generating Co 83/04/25. MADSEN, Region 4, Office of Director 3pp 18518 125 24X Fiche 50-445, 83/05/18, 8305200416

8305200666 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04
MADSEN, G L Region 4, Office of Director 83/05/18 GARY, R J Texas Utilities Generating Co 1p 18519 095 24X Fiche 50-445, 83/05/18, 8305200666

--8305200674 Responds to NRC 830314 ltr re violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 Corrective actions const personnel will be reinstructed in necessity for rigid compliance w/design & procedural requirements
GARY, R J Texas Utilities Generating Co 83/04/15 MADSEN, G L Region 4, Office of Director 3pp 18519 096 24X Fiche 50-445, 83/05/18, 8305200666

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305240003 Forwards IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/05/20 GARY, R J Texas Utilities Generating Co 2pp 18549 139 24X Fiche 50-445, 83/05/20, 8305240003

--8305240005 IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted Major areas inspected radwaste program & transportation activities, including organization, training, radwaste sys mgt, effluent release controls & procedures
BAER, R E , MURRAY, B , WESTERMAN, T F Region 4, Office of Director, 83/05/19 34pp 18549 141 24X Fiche 50-445, 83/05/20, 8305240003

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

R. Periodic operating reports & related correspondence

8305100130 Forwards "Reactor Containment Bldg Unit 1 Preoperational Integrated Leak Rate Test, 1983 " Electrical penetrations leaked excessively during testing Further testing to determine cause of leakage in progress
SCHMIDT, H C Texas Utilities Services, Inc 83/05/06. DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18370:145 24X Fiche 50-445, 83/05/06, 8305100130

--8305100135 "Reactor Containment Bldg Unit 1 Preoperational Integrated Leak Test, 1983 "
* Texas Utilities Services, Inc 83/12/31 33pp. 18370 146. 24X Fiche 50-445, 83/05/06, 8305100130

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised.
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000, 83/04/21, 8305110427.

8305200298 Interim Deficiency Rept SDAR-106 re HVAC hangers fabricated at variance w/design Initially reported on 830301. Completion of evaluation anticipated by 830705
GARY, R J Texas Utilities Generating Co 83/05/11 MADSEN, G L. Region 4, Office of Director 1p 18516.273. 24X Fiche 50-445, 83/05/11, 8305200298

8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513. Bolting parts greater than 2-inch size not examined
HOVI, L NPB Industries, Inc 83/05/16 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 18574 001 24X Fiche 50-000, 83/05/16, 8305240356

T Hearing transcripts on non-antitrust matters

8305020156 Corrected transcript of 830407 telephone conference in Bethesda, MD Pp 1-132
* Atomic Safety and Licensing Board Panel 83/04/07. 135pp 18272 228 24X Fiche 50-445, 83/04/07, 8305020156

8305040507 Forwards J Doyle surrebuttal testimony.
ELLIS, J Citizens Association for Sound Energy. 83/04/26 BLOCH, P B , JORDAN, W. H , MCCOLLOM, K. A Atomic Safety and Licensing Board Panel 1p 18319 146 24X Fiche 50-445, 83/04/26, 8305040507

DOCKETED ITEMS

--8305040515 Surrebuttal testimony of J Doyle re consideration of LOCA in design criteria for pipe supports Results of hand calculations supported by computer analysis indicate gross error in fundamental approach Certificate of Svc encl
DOYLE, J Citizens Association for Sound Energy 83/04/26 89pp
18319 147 24X Fiche 50-445, 83/04/26, 8305040507

8305040535 Supplemental surrebuttal testimony of J Doyle re severe minor & offsetting errors in computer analysis Certificate of Svc encl
DOYLE, J Citizens Association for Sound Energy 83/04/28 8pp
18321 263 24X Fiche 50-445, 83/04/28, 8305040535

8305110157 Surrebuttal testimony of MA Walsh Certificate of Svc encl Related correspondence
WALSH, M A Citizens Association for Sound Energy 83/05/04 9pp
18407 112 24X Fiche 50-445, 83/05/04, 8305110157

8305110354 Supplemental surrebuttal testimony of J Doyle re special insp team Insp Repts 50-445/82-26 & 50-446/82-14 Related correspondence
DOYLE, J Citizens Association for Sound Energy 83/05/04 42pp
18406 086 24X Fiche 50-445, 83/05/04, 8305110354

8305090507 Forwards testimony of LJ Skiles, AB Armstrong & CL Born re emergency planning recommendations, A Vega testimony re const appraisal team rept & JS Marshall, DH Wade, JC Finneran & DR Woodlan affidavits Related correspondence
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/05/05 BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 2pp 18362 014 24X Fiche, 50-445, 83/05/05, 8305090507

--8305090510 Testimony of LJ Skiles, AB Armstrong & CL Born on ASLB 830425 telcon questions re adequacy of county judge as emergency plan coordinator
SKILES, L J , ARMSTRONG, A B , BORN, C L Texas, State of 83/05/05
7pp 18362 016 24X Fiche 50-445, 83/05/05, 8305090507

--8305090513 Testimony of A Vega re applicant response to 830411 Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12
VEGA, A Texas Utilities Generating Co 83/05/05 3pp
18362 023 24X Fiche 50-445, 83/05/05, 8305090507

--8305090517 Affidavit of JS Marshall in response to ASLB inquiry re classification of equipment for application of 10CFR50, App B requirements & relationship of Board Notification 83-13 to HR Denton 811120 memo on classification
MARSHALL, J S Texas Utilities Generating Co 83/05/05 7pp
18362 026 24X Fiche 50-445, 83/05/05, 8305090507

--8305090521 Affidavit of DH Wade re Midland-Ross superstrut matl (Board Notifications 83-02 & 83-14) & welds in main control board panels (Board Notifications 82-90, 90A & 116)
WADE, D H Texas Utilities Generating Co 83/05/05 90pp
18362 033 24X Fiche 50-445, 83/05/05, 8305090507

--8305090525 Affidavit of JC Finneran on applicant response to Board Notification 82-105 re pipe clamps employed on ASME Code Class I piping.
FINNERAN, J C Texas Utilities Generating Co 83/05/05 3pp
18362 123 24X Fiche 50-445, 83/05/05, 8305090507

--8305090530 Affidavit of DR Woodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl
WOODLAN, D R Texas Utilities Generating Co. 83/05/05, 12pp
18362 126 24X Fiche 50-445, 83/05/05, 8305090507

8305090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon
TREBY, S A , ROTHSCHILD, M.U , MIZUNO, G S Hearing Branch 1
83/05/05 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445, 83/05/05, 8305090568

--8305090578 Supplemental testimony of S Burwell, WP Chen, JI Tapia, J Rajan & RG Taylor re concerns raised by MA Walsh & J Doyle & NRC const appraisal insp rept Prof qualifications encl
BURWELL, S Division of Licensing CHEN, W P Energy, Dept of
TAPIA, J. I. Division of Resident, Reactor Project & Engineering Programs, 83/05/05 14pp 18360 004 24X Fiche 50-445, 83/05/05, 8305090568

--8305090586 Supplemental testimony of DM Rohrer & T Urbanik re emergency preparedness
ROHRER, D M Emergency Preparedness Branch URBANIK, T Texas A&M Univ., College Station, TX 83/05/05 20pp 18360 018 24X Fiche 50-445, 83/05/05, 8305090568

--8305090592 Supplemental testimony of A Lookabaugh & J Denton re emergency preparedness
LOOKABAUGH, A , DENTON, J Federal Emergency Management Agency
83/05/05 15pp 18360 038 24X Fiche 50-445, 83/05/05, 8305090568

--8305090660 Testimony of AB Beach re const appraisal team insp concerning pipe support const & pipe support design interfaces w/const Prof qualifications encl
BEACH, A B Director's Office, Office of Inspection and Enforcement 83/05/05 4pp 18360 109 24X
Fiche 50-445, 83/05/05, 8305090568

8305130157 Supplementary surrebuttal testimony of J Doyle Error in fundamentals used in calculations for upper lateral restraint compounded by errors in stiffness used in Gibbs & Hill calculations Related correspondence
DOYLE, J Citizens Association for Sound Energy 83/05/09 2pp
18437 269 24X Fiche 50-445, 83/05/09, 8305130157

8305230138 Transcript of 830516 hearing in Fort Worth, TX re OL application Pp 5,855-6,169 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/16 408pp
18530 215 24X Fiche 50-445, 83/05/16, 8305230138

8305230100 Transcript of 830517 hearing in Fort Worth, TX Pp 6,170-6,286 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/17 268pp
18534 282 24X Fiche 50-445, 83/05/17, 8305230100

8305230147 Transcript of 830517 hearing in Fort Worth, TX Pp 6,287-6,471 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/17 336pp
18529 239 24X Fiche, 50-445, 83/05/17, 8305230147

8305250010 Transcript of 830518 hearing in Fort Worth, TX Pp 6,472-6,817 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/18 388pp
18584 075 24X Fiche 50-445, 83/05/18, 8305250010

8305260099 Transcript of 830519 hearing in Fort Worth, TX Pp 6,818-7,272 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/19 743pp
18597 001 24X Fiche 50-445, 83/05/19, 8305260099

8305260079 Transcript of 830520 hearing in Fort Worth, TX Pp 7,273-7,485 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/20 319pp
18624 046 24X Fiche 50-445, 83/05/20, 8305260079

DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA ,UNIT 2

A Application/construction stage documents & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON, J M Division of Rules and Records 83/03/09 LINDEMAN, H N
Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000, 83/03/09, 8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE, J F Commissioners 5pp
18497 228 24X Fiche 50-000, 83/03/09, 8305180001

8305230720 Forwards list of utils responding to requests for cost figures on backfitting.
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305090722 Board Notification 83-12 forwards rept, "Design & Const - Self-Initiated Evaluation," to facilitate general upgrading of plant & industry
NOVAK, T M Assistant Director for Licensing, AS BN83-12 83/05/02
Atomic Safety and Licensing Board Panel 3pp 18368 291 24X
Fiche 50-445, 83/05/02, 8305090722

--8305090726 "Design & Const - Self-Initiated Evaluation, Comanche Peak Steam Electric Station "
* Texas Utilities Generating Co 82/10/31 354pp 18368 294
24X Fiche 50-445, 83/05/02, 8305090722

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305120109 Summary of 830413 meeting w/util in Bethesda,MD re added assurance program to assure independent verification program requirements met
BURWELL,S B Licensing Branch 1 83/05/04 Licensing Branch 1 7pp 18443 179 24X Fiche 50-445,83/05/04,8305120109

8305100125 Forwards comments on environ qualification correlation between installed & qualified components as followup to 821014 audit trip rept on Item II a, "Auxiliary Bldg Modular Train Filter "
SCHMIDT,H C Texas Utilities Services, Inc 83/05/05
YOUNGBLOOD,B J Licensing Branch 1 2pp 18375-029 24X
Fiche 50-445,83/05/05,8305100125

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305230627 Forwards request for procedures generation package needed to complete OL application evaluation
YOUNGBLOOD,B J Licensing Branch 1 83/05/12 GARY,R J Texas Utilities Generating Co 6pp 18543,029 24X Fiche 50-445, 83/05/12,8305230627

8305310151 Comments on alternate shutdown reactor heat removal Direct readings of process variables necessary to perform & control reactor heat removal provided at hot shutdown panel as part of alternate shutdown design
SCHMIDT,H C Texas Utilities Services, Inc 83/05/20
YOUNGBLOOD,B J Licensing Branch 1 3pp 18651 221. 24X
Fiche 50-445,83/05/20,8305310151

F Security, medical, emergency & fire protection plans

8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness.
MIZUNO,G S Hearing Branch 1 83/04/29 BLOCH,P B Atomic Safety and Licensing Board Panel 3pp. 18292 163 24X
Fiche 50-445,83/04/29,8305030464

G Adjudicatory correspondence

8305020422 Motion to allow Citizens Assoc for Sound Energy to file written argument on issue in lieu of presenting oral argument at 830119 hearing Citizens do not have finances to come to Bethesda,MD for 40-minute argument
ELLIS,J Citizens Association for Sound Energy 83/01/11. Atomic Safety and Licensing Appeal Panel 2pp 18283 001 24X
Fiche 50-445,83/01/11,8305020422

--8305020430 Written argument on issues to be argued orally on 830119 in Bethesda,MD Citizens Assoc for Sound Energy unable to attend or find representative Whistleblower protection discussed
ELLIS,J Citizens Association for Sound Energy 83/01/11
Atomic Safety and Licensing Appeal Panel 65pp 18283 003 24X
Fiche 50-445,83/01/11,8305020422

--8305020437 Forwards Citizens Assoc for Sound Energy witness J Doyle affidavit re blacklisting due to testimony at hearings.
ELLIS,J Citizens Association for Sound Energy 83/01/18
ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel 1p 18283 068 24X Fiche:50-445,83/01/11,8305020422

--8305020444 Affidavit of J Doyle re blacklisting due to testimony at hearings NRC should take immediate & stringent measures to stop insidious practice NRC current protection for whistleblowers is farce & charade Certificate of Svc encl
DOYLE,J Affiliation Unknown 83/01/17 4pp 18283-069. 24X
Fiche 50-445,83/01/11,8305020422

8305040529 Affidavit of MA Walsh re computer program in J Doyle 830426 surrebuttal testimony STRUDL program utilized w/sufficient similarities to assure results will be accurate
WALSH,M A Citizens Association for Sound Energy 83/04/26 1p 18320 001 24X Fiche 50-445,83/04/26,8305040529

8305040296 Motion for discovery re applicant & NRC interrogatories on const appraisal team Insp Repts 50-445/83-18 & 50-446/83-12. Related correspondence
ELLIS,J Citizens Association for Sound Energy 83/04/28. Atomic Safety and Licensing Board Panel 3pp 18324 025 24X
Fiche:50-445,83/04/28,8305040296

8305040499 Fourteenth set of interrogatories & requests to produce Related correspondence
ELLIS,J Citizens Association for Sound Energy 83/04/28 Texas Utilities Generating Co 10pp 18322 111 24X
Fiche 50-445,83/04/28,8305040499

8305040513 Fourth set of interrogatories & requests to produce,Related correspondence
ELLIS,J Citizens Association for Sound Energy 83/04/28 Office of the Executive Legal Director 7pp 18321 249 24X
Fiche 50-445,83/04/28,8305040513

8305030464 Forwards FEMA 830322 memo to NRC re emergency preparedness.
MIZUNO,G S Hearing Branch 1 83/04/29 BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 3pp.
18292 163 24X Fiche 50-445,83/04/29,8305030464

8305030514 Motion for protective order that discovery not be had re draft notice of violation on calculation of deflection of rigid support CC-1-107-008-E23R Draft is not final NRC document Certificate of Svc encl
ROTHSCHILD,M U Hearing Branch 1 83/04/29 Atomic Safety and Licensing Board Panel 7pp 18306 350 24X Fiche.50-445,83/04/29, 8305030514

8305030522 Order extending time until 830503 for Commission to act to review ALAB-714
CHILK,S J Office of the Secretary of the Commission. 83/04/29
Commissioners 1p 18306 357 24X Fiche:50-445,83/04/29, 8305030522

8305040531 Advises of NRC agreement to voluntarily release one paragraph designated by Judge Bloch as containing factual info possibly relevant to litigation,from draft 821229 notice of violation Paragraph set forth
TREBY,S A Hearing Branch 1 83/05/03 CASE,J Citizens Association for Sound Energy 1p. 18321 241. 24X
Fiche 50-445,83/05/03,8305040531

8305040557 Reply to State of TX brief on collateral estoppel State of TX erred in concluding Dept of Labor decision should be given collateral estoppel effect Decision not sufficiently firm to be accorded preclusive effect
ROTHSCHILD,M U Hearing Branch 1 83/05/03 4pp. 18321 282. 24X
Fiche 50-445,83/05/03,8305040557

--8305040560 Reply to Citizens Assoc for Sound Energy brief re consideration of LOCA in design criteria for pipe supports Operability of pipe supports not necessary to assure safety-related component operability W/Certificate of Svc.
MIZUNO,G S Hearing Branch 1 83/05/03 9pp. 18321 286. 24X
Fiche 50-445,83/05/03,8305040557

8305050015 Order extending time until 830520 for Commission to act to review ALAB-714
CHILK,S J. Office of the Secretary of the Commission. 83/05/03
Commissioners. 1p 18339 055 24X Fiche 50-445,83/05/03, 8305050015

8305050018 Reply brief to Citizens Assoc for Sound Energy 830420 brief re consideration of effects of LOCA on pipe support design. Citizens erroneously applied provisions of ASME Code not applicable to design Certificate of Svc encl.
REYNOLDS,N S , HORIN,W A Texas Utilities Generating Co.
REYNOLDS,N S Debevoise & Liberman. 83/05/03 21pp. 18338 334.
24X Fiche:50-445,83/05/03,8305050018.

8305090443 Response in opposition to NRC 830420 response to ASLB question re LOCA-induced thermal expansion in linear supports & applicant 830421 brief on consideration of pipe support design thermal stresses W/Certificate of Svc.
ELLIS,J Citizens Association for Sound Energy. 83/05/03. Atomic Safety and Licensing Board Panel. 25pp. 18363-001 24X
Fiche 50-445,83/05/03,8305090443.

8305110137 Responds to 830504 request to review proposed protective agreement between Citizens Assoc for Sound Energy & ITT-Grinnel re design criteria for pipe supports Wording too restrictive.Revised proposal encl for review.
ELLIS,J Citizens Association for Sound Energy 83/05/04. HORIN,W Debevoise & Liberman. 4pp 18393-344 24X Fiche-50-445,83/05/04, 8305110137

8305110347 Certifies svc of J Doyle 830504 supplemental surrebuttal testimony.
ELLIS,J. Citizens Association for Sound Energy. 83/05/04 2pp. 18404.158 24X Fiche 50-445,83/05/04,8305110347

8305090507 Forwards testimony of LJ Skiles, AB Armstrong & CL Born re emergency planning recommendations, A Vega testimony re const appraisal team rept & JS Marshall, DH Wade, JC Finneran & DR Woodlan affidavits Related correspondence
REYNOLDS, N S Debevoise & Liberman 83/05/05 BLOCH, P B Atomic Safety and Licensing Board Panel 2pp 18362 014 24X Fiche 50-445, 83/05/05, 8305090507

--8305090517 Affidavit of JS Marshall in response to ASLB inquiry re classification of equipment for application of 10CFR50, App B requirements & relationship of Board Notification 83-13 to HR Denton 811120 memo on classification
MARSHALL, J S Texas Utilities Generating Co 83/05/05 7pp 18362 026 24X Fiche 50-445, 83/05/05, 8305090507

--8305090521 Affidavit of DH Wade re Midland-Ross superstrut matl (Board Notifications 83-02 & 83-14) & welds in main control board panels (Board Notifications 82-90, 90A & 116)
WADE, D H Texas Utilities Generating Co 83/05/05 90pp 18362 033 24X Fiche 50-445, 83/05/05, 8305090507

--8305090525 Affidavit of JC Finneran on applicant response to Board Notification 82-105 re pipe clamps employed on ASME Code Class I piping
FINNERAN, J C Texas Utilities Generating Co 83/05/05 3pp 18362 123 24X Fiche 50-445, 83/05/05, 8305090507

--8305090530 Affidavit of DR Woodlan providing responses to ASLB inquiries re Board Notifications 83-26 & 83-38 concerning failure of certain reactor trip breakers to perform as designed Prof qualifications encl
WOODLAN, D R Texas Utilities Generating Co 83/05/05 12pp 18362 126 24X Fiche 50-445, 83/05/05, 8305090507

8305090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon
TREBY, S A , ROTHSCHILD, M U , MIZUNO, G S Hearing Branch 1 83/05/05 BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445, 83/05/05, 8305090568

--8305090600 Affidavit of SB Burwell re questions posed during ASLB 830407 telcon on implemented procedures concerning maint of scram breakers as result of Board Notifications 83-26 & 83-38 Prof qualifications encl
BURWELL, S B Licensing Branch 1 83/05/05 5pp 18360 053 24X Fiche 50-445, 83/05/05, 8305090568

--8305090607 Affidavit of FD Coffman on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants," per ASLB 830407 telcon request Prof qualifications encl
COFFMAN, F D Reliability & Risk Assessment Branch 83/05/05 9pp 18360 058 24X Fiche 50-445, 83/05/05, 8305090568

--8305090618 Affidavit of S Diab re semiscale feed & bleed Experiment S-SR-2 & related subsequent RELAP-5 analyses, per ASLB 830407 telcon request Prof qualifications encl
DIAB, S. Reactor Systems Branch 83/05/05 5pp. 18360 067 24X Fiche 50-445, 83/05/05, 8305090568

--8305090625 Affidavit of TQ Dunning re ASLB 830407 telcon question on reactor trip (scram) sys & conformance w/IEEE-279 Prof qualifications encl
DUNNING, T Q Instrumentation & Control Systems Branch 83/05/05 6pp 18360 072 24X Fiche 50-445, 83/05/05, 8305090568

--8305090632 Affidavit of WP Haass re ASLB 830407 telcon questions on NRC interpretation of 10CFR50, App B Prof qualifications encl
HAASS, W P QA Branch 83/05/05 5pp 18360 078 24X Fiche 50-445, 83/05/05, 8305090568

--8305090640 Affidavit of CE Rossi re ASLB 830407 telcon questions concerning status of NRC position on Unresolved Safety Issue A-9, "ATWS " Prof qualifications encl
ROSSI, C E Instrumentation & Control Systems Branch. 83/05/05 5pp 18360 083. 24X Fiche 50-445, 83/05/05, 8305090568

--8305090646 Affidavit of AJ Szukiewicz & TQ Dunning re ASLB 830407 questions on Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Prof qualifications encl
SZUKIEWICZ, A J Generic Issues Branch DUNNING, T Q Instrumentation & Control Systems Branch 83/05/05. 9pp 18360 093 24X Fiche 50-445, 83/05/05, 8305090568

--8305090650 Affidavit of RQ Taylor re ASLB 830407 telcon questions on use of superstrut matl
TAYLOR, R Q Region 4, Office of Director 83/05/05 2pp 18360 102 24X Fiche 50-445, 83/05/05, 8305090568

--8305090654 Affidavit of D Terao re ASLB 830407 telcon questions on Board Notification 82-105, "Alleged Design Deficiency " Prof qualifications encl
TERAO, D Mechanical Engineering Branch 83/05/05 5pp 18360 104 24X Fiche 50-445, 83/05/05, 8305090568

8305090560 Notice of 830612-17 evidentiary hearings re const appraisal team QA study Limited appearance statements will be disallowed
BLOCH, P B Atomic Safety and Licensing Board Panel 83/05/06 1p 18360 153 24X Fiche 50-445, 83/05/06, 8305090560

8305100270 Confirms ASLB response to util question re delegation of authority to county judges to make decisions concerning radiological emergency protective action notification & recommendations
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/05/06 BLOCH, P B Atomic Safety and Licensing Board Panel 1p 18371 338 24X Fiche 50-445, 83/05/06, 8305100270

8305100321 Forwards drawing of upper lateral restraint ref in J Doyle 830426 rebuttal testimony
REYNOLDS, N S Debevoise & Liberman REYNOLDS, N S Texas Utilities Generating Co 83/05/06 BLOCH, P B Atomic Safety and Licensing Board Panel 2pp 18370 091 24X Fiche 50-445, 83/05/06, 8305100321

8305110332 Requests info re introduction into evidence of const & appraisal team insp & investigation repts by NRC
ELLIS, J Citizens Association for Sound Energy 83/05/06
ROTHSCHILD, M U Office of the Executive Legal Director 1p 18406 147 24X Fiche 50-445, 83/05/06, 8305110332

8305110368 Discusses proposed stipulation re listed Citizens Assoc for Sound Energy discovery matters
ELLIS, J Citizens Association for Sound Energy 83/05/06
ROTHSCHILD, M U Office of the Executive Legal Director 2pp 18406 077 24X Fiche 50-445, 83/05/06, 8305110368

8305110397 Submits list of stipulations re Citizens Assoc for Sound Energy exhibits for verification of authenticity & possible admission into evidence
ELLIS, J Citizens Association for Sound Energy 83/05/06 HORIN, N Debevoise & Liberman 2pp 18406 195 24X Fiche 50-445, 83/05/06, 8305110397

8305110357 Response opposing NRC 830505 motion to withdraw Sept 1982 prefiled testimony Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/05/07 Atomic Safety and Licensing Board Panel 4pp 18406 082 24X Fiche 50-445, 83/05/07, 8305110357

8305100267 Forwards original signed pages to JS Marshall, DH Wade, JC Finneran & DR Woolan affidavits filed on 830505
HORIN, W A Debevoise & Liberman HORIN, W A Texas Utilities Generating Co 83/05/09 STUCKY, S W Docketing & Services Branch 5pp 18371 236 24X Fiche 50-445, 83/05/09, 8305100267

8305100295 Answer opposing Citizens Assoc for Sound Energy motion for discovery re const appraisal team rept Discovery requests unnecessary, cumulative, unduly burdensome & untimely Certificate of Svc encl
REYNOLDS, N S Texas Utilities Generating Co REYNOLDS, N S Debevoise & Liberman 83/05/09 Atomic Safety and Licensing Board Panel 6pp 18371 255 24X Fiche 50-445, 83/05/09, 8305100295

8305130066 Motion to allow addl supplementary surrebuttal testimony of J Doyle, witness for intervenor Receipt of drawing creates need to revise previous testimony
ELLIS, J Citizens Association for Sound Energy 83/05/09. Atomic Safety and Licensing Board Panel 2pp 18436 331 24X Fiche 50-445, 83/05/09, 8305130066

8305130175 Response to ASLB 830506 request for discussion of interrelationship of ASME App XVII, Section 2271 3, to rest of ASME Code App is mandatory & integral part of ASME Code & is applicable to pipe supports Certificate of Svc encl
ELLIS, J Citizens Association for Sound Energy 83/05/09 34pp 18437 303 24X Fiche 50-445, 83/05/09, 8305130175

8305130013 Answer to Citizens Assoc for Sound Energy 830428 motion for discovery Answers to interrogatories filed as limited discovery on IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 relevant
ROTHSCHILD, M U Hearing Branch 1 83/05/11 Atomic Safety and Licensing Board Panel 3pp 18437 133 24X Fiche 50-445, 83/05/11, 8305130013

--8305130021 Answers to fourth set of interrogatories & requests to produce
BEACH, A B Director's Office, Office of Inspection and Enforcement 83/05/11 Citizens Association for Sound Energy 12pp 18437 136 24X Fiche 50-445, 83/05/11, 8305130013

8305130033 Response to ASLB inquiry re ASME Boiler & Pressure Vessel Code App XVII App delineates requirements & stress limits for analysis of linear pipe supports
MIZUNO, G S Hearing Branch 1 83/05/11 3pp 18437 094 24X Fiche 50-445, 83/05/11, 8305130033

--8305130040 Affidavit of RJ Bosnak re App XVII-2000 requirements & stress limits for linear elastic analysis of linear pipe supports Article XVII-2271 3 requires appropriate design consideration be given Certificate of Svc encl
BOSNAK, R J Office of Nuclear Reactor Regulation, Director 83/05/11 4pp 18437 097 24X Fiche 50-445, 83/05/11, 8305130033

8305130260 Supplemental reply brief re pipe support design. Consideration of thermal expansion of supports not required in design of linear-type pipe supports Certificate of Svc encl
REYNOLDS, N S , HORIN, W A Texas Utilities Generating Co
REYNOLDS, N S Debevoise & Liberman 83/05/11. Atomic Safety and Licensing Board Panel 7pp 18439 244 24X Fiche 50-445, 83/05/11, 8305130260

8305170287 Forwards improved drawing received from applicant in response to request re Citizens Assoc for Sound Energy Exhibit 763 (J Doyle 830504 supplemental surrebuttal testimony)
ELLIS, J Citizens Association for Sound Energy 83/05/11
BLOCH, P B , MCCOLLOM, K A , JORDAN, W H Atomic Safety and Licensing Board Panel 3pp 18465 354 24X Fiche 50-445, 83/05/11, 8305170287

8305170513 Forwards addl exhibits to assist in reaching stipulations prior to hearings W/o encl.
ELLIS, J Citizens Association for Sound Energy 83/05/11
ROTHSCHILD, M U Hearing Branch 1 REYNOLDS, N S Debevoise & Liberman 2pp 18470 009 24X Fiche 50-445, 83/05/11, 8305170513

8305160147 Forwards AB Beach 830511 signed affidavit & prof qualifications to NRC 830511 answers to Citizens Assoc for Sound Energy fourth set of interrogatories
ROTHSCHILD, M U Hearing Branch 1 83/05/12 ELLIS, J Citizens Association for Sound Energy 3pp 18446 101 24X Fiche: 50-445, 83/05/12, 8305160147

8305200504 Forwards 830513 ltr transmitted to Region IV & util in response to ASLB directive re cross-examination document delivery
ELLIS, J Citizens Association for Sound Energy 83/05/16
BLOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 1p 18514 086 24X Fiche 50-445, 83/05/16, 8305200504

8305200554 Order extending time until 830527 for Commission to act to review ALAB-714
CHILK, S J Office of the Secretary of the Commission 83/05/19
Commissioners 1p 18519 091 24X Fiche 50-445, 83/05/19, 8305200554

8305270015 Forwards NB Le, DC Ford, P Keshishian, RM Compton, GC Gower, HW Phillips & WA Hansen prof qualifications Individuals listed in NRC answer to Interrogatory 1 (fourth set) & requests to produce
ROTHSCHILD, M U Hearing Branch 1 83/05/26 ELLIS, J Citizens Association for Sound Energy 10pp 18633 352 24X Fiche 50-445, 83/05/26, 8305270015

8305310011 Order extending time until 830606 for Commission to act to review ALAB-714
CHILK, S J Office of the Secretary of the Commission 83/05/27
Commissioners 1p 18653 239 24X Fiche 50-445, 83/05/27, 8305310011

K Utility Final Safety Analysis Report (FSAR) & amends

8305160138 Forwards Amend 40 to FSAR
GARY, R J Texas Utilities Generating Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18446 190 24X Fiche 50-445, 83/05/09, 8305160138

--8305160141 Amend 40 to FSAR
* Texas Utilities Generating Co 83/05/09 397pp. 18446 194 24X Fiche 50-445, 83/05/09, 8305160138

Q. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co. of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305100093 Confirms plan to perform independent verification insp on 830425-0506 Addl info re required documentation packages for 47 welds selected for independent verification requested by 830411
GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 83/04/11 GARY, R J Texas Utilities Generating Co 8pp 18377 266 24X Fiche 50-445, 83/04/11, 8305100093

8305120145 Forwards IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Executive summary of results & list of potential enforcement actions encl
Region IV will address findings at later date
DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 83/04/11 GARY, R J Texas Utilities Generating Co 10pp 18427 262 24X Fiche 50-445, 83/04/11, 8305120145

--8305120155 IE Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & 0214-0303 Major areas inspected electrical & instrumentation const, mechanical const, welding & NDE & civil & structural const
BEACH, A B , KESHISHIAN, P I , GOWER, G C Reactor Construction Branch 83/04/08 89pp 18427 270 24X Fiche 50-445, 83/04/11, 8305120145

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025.

8305120610 Informs that commitments re extent & method of exam of preservice insp program consistent w/inservice exams, based on Reg Guide 1 150. Preservice exam plan described in 830301 ltr acceptable provided plan completed before 840115
YOUNGBLOOD, B J Licensing Branch 1 83/04/27 GARY, R. J. Texas Utilities Generating Co 2pp 18440 354 24X Fiche 50-445, 83/04/27, 8305120610

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282. 24X Fiche. 50-000, 83/05/04, 8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 119pp 18441 001. 24X Fiche 50-000, 83/05/04, 8303040031

8305160240 Board Notification 83-29C provides 830413 meeting summary describing continuing discussion between NRC & util on need for program to assure adequate plant design & const, as result of const appraisal team insp
NOVAK, T M. Assistant Director for Licensing. 83/05/04. Atomic Safety and Licensing Board Panel 4pp 18471 351 24X Fiche 50-445, 83/05/04, 8305160240

--8305160244 Summary of 830413 meeting w/util in Bethesda,MD re misunderstanding between util & NRC on need for added assurance that plant designed & contructed in accordance w/ application Results of const appraisal team insp discussed
BURWELL,S B Licensing Branch 1 83/05/04 Licensing Branch 1
6pp 18471 354 24X Fiche 50-445,83/05/04,8305160240

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305230445 Forwards IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted
MADSEN,G L Region 4, Office of Director 83/05/13 GARY,R J
Texas Utilities Generating Co 2pp 18538 178 24X
Fiche:50-445,83/05/13,8305230445

--8305230449 IE Insp Repts 50-445/83-12 & 50-446/83-07 on 830222-0308 & 0322-23 No noncompliance noted Major areas inspected followup of unresolved items in IE Insp Repts 50-445/82-26, 50-446/82-14 & 50-445/82-22
TAPIA,J I , CHEN,W P , HUNNICUTT,D M Region 4, Office of Director 83/05/03 8pp 18538 180 24X Fiche 50-445,83/05/13, 8305230445

8305200416 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-03 & 50-446/83-01
MADSEN,G L Region 4, Office of Director 83/05/18 GARY,R J
Texas Utilities Generating Co 1p 18518 124 24X
Fiche 50-445,83/05/18,8305200416

--8305200419 Responds to NRC 830328 ltr re violations noted in IE Insp Repts 50-445/83-03 & 50-446/83-01 Corrective actions light poles will be inspected & items designated non-nuclear safety-related reviewed & upgraded
GARY,R J Texas Utilities Generating Co 83/04/25 MADSEN, Region 4, Office of Director 3pp 18518 125 24X
Fiche 50-445,83/05/18,8305200416

8305200666 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04
MADSEN,G L Region 4, Office of Director 83/05/18 GARY,R J
Texas Utilities Generating Co 1p 18519 095 24X
Fiche,50-445,83/05/18,8305200666

--8305200674 Responds to NRC 830314 ltr re violations noted in IE Insp Repts 50-445/83-07 & 50-446/83-04 Corrective actions const personnel will be reinstructed in necessity for rigid compliance w/design & procedural requirements
GARY,R J Texas Utilities Generating Co 83/04/15 MADSEN,G L
Region 4, Office of Director 3pp 18519 096 24X
Fiche 50-445,83/05/18,8305200666

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305240003 Forwards IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted
MADSEN,G L Region 4, Office of Director 83/05/20 GARY,R J
Texas Utilities Generating Co 2pp 18549 139 24X
Fiche 50-445,83/05/20,8305240003

--8305240005 IE Insp Repts 50-445/83-14 & 50-446/83-08 on 830328-31 No noncompliance noted Major areas inspected radwaste program & transportation activities,including organization,training, radwaste sys mgt,effluent release controls & procedures
BAER,R.E , MURRAY,B , WESTERMAN,T F Region 4, Office of Director 83/05/19 34pp 18549 141 24X Fiche 50-445,83/05/20, 8305240003

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000,83/04/21,8305110427

8305200298 Interim Deficiency Rept SDAR-106 re HVAC hangers fabricated at variance w/design Initially reported on 830301 Completion of evaluation anticipated by 830705
GARY,R J Texas Utilities Generating Co 83/05/11 MADSEN,G L
Region 4, Office of Director 1p 18516 273 24X
Fiche 50-445,83/05/11,8305200298

8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513 Bolting parts greater than 2-inch size not examined
HOVI,L NPS Industries, Inc 83/05/16 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 18574 001 24X
Fiche 50-000,83/05/16,8305240356

T Hearing transcripts on non-antitrust matters

8305020156 Corrected transcript of 830407 telephone conference in Bethesda,MD Pp 1-132
* Atomic Safety and Licensing Board Panel 83/04/07 135pp
18272 228 24X Fiche 50-445,83/04/07,8305020156

8305040507 Forwards J Doyle surrebuttal testimony
ELLIS,J Citizens Association for Sound Energy 83/04/26
BLOCH,P B , JORDAN,W H , MCCOLLOM,K A Atomic Safety and Licensing Board Panel 1p 18319 146 24X Fiche 50-445,83/04/26,8305040507

--8305040515 Surrebuttal testimony of J Doyle re consideration of LOCA in design criteria for pipe supports Results of hand calculations supported by computer analysis indicate gross error in fundamental approach Certificate of Svc encl
DOYLE,J Citizens Association for Sound Energy 83/04/26 89pp
18319 147 24X Fiche 50-445,83/04/26,8305040507

8305040535 Supplemental surrebuttal testimony of J Doyle re severe minor & offsetting errors in computer analysis Certificate of Svc encl
DOYLE,J Citizens Association for Sound Energy 83/04/28 8pp
18321 263 24X Fiche 50-445,83/04/28,8305040535

8305110157 Surrebuttal testimony of MA Walsh Certificate of Svc encl Related correspondence
WALSH,M A Citizens Association for Sound Energy 83/05/04 9pp
18407 112 24X Fiche 50-445,83/05/04,8305110157

8305110354 Supplemental surrebuttal testimony of J Doyle re special insp team Insp Repts 50-445/82-26 & 50-446/82-14 Related correspondence
DOYLE,J Citizens Association for Sound Energy 83/05/04 42pp
18406 086 24X Fiche 50-445,83/05/04,8305110354

8305090507 Forwards testimony of LJ Skiles,AB Armstrong & CL Born re emergency planning recommendations,A Vega testimony re const appraisal team rept & JS Marshall,DH Wade,JC Finneran & DR Woodlan affidavits Related correspondence
REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Texas Utilities Generating Co 83/05/05 BLOCH,P B , MCCOLLOM,K A , JORDAN,W H
Atomic Safety and Licensing Board Panel 2pp 18362 014 24X
Fiche 50-445,83/05/05,8305090507

--8305090510 Testimony of LJ Skiles,AB Armstrong & CL Born on ASLB 830425 telcon questions re adequacy of county judge as emergency plan coordinator
SKILES,L J , ARMSTRONG,A B , BORN,C L Texas, State of 83/05/05
7pp 18362 016 24X Fiche 50-445,83/05/05,8305090507

--8305090513 Testimony of A Vega re applicant response to 830411 Const Appraisal Team Insp Repts 50-445/83-19 & 50-446/83-12
VEGA,A Texas Utilities Generating Co 83/05/05 3pp
18362 023 24X Fiche 50-445,83/05/05,8305090507

8305090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon
TREBY,S A Hearing Branch 1 83/05/05 BLOCH,P B Atomic Safety and Licensing Board Panel 2pp 18360 001 24X
Fiche 50-445,83/05/05,8305090568

--8305090578 Supplemental testimony of S Burwell, WP Chen, JI Tapia, J Rajan & RG Taylor re concerns raised by MA Walsh & J Doyle & NRC const appraisal insp rept Prof qualifications encl
BURWELL, S Division of Licensing CHEN, W P Energy, Dept of TAPIA, J I Division of Resident, Reactor Project & Engineering Programs 83/05/05 14pp 18360 004 24X Fiche 50-445, 83/05/05, 8305090568

--8305090586 Supplemental testimony of DM Rohrer & T Urbanik re emergency preparedness
ROHRER, D M Emergency Preparedness Branch URBANIK, T Texas A&M Univ, College Station, TX 83/05/05 20pp 18360 018 24X Fiche 50-445, 83/05/05, 8305090568

--8305090592 Supplemental testimony of A Lookabaugh & J Benton re emergency preparedness
LOOKABAUGH, A, BENTON, J Federal Emergency Management Agency 83/05/05 15pp 18360 038 24X Fiche 50-445, 83/05/05, 8305090568

--8305090660 Testimony of AB Beach re const appraisal team insp concerning pipe support const & pipe support design interfaces w/const Prof qualifications encl
BEACH, A B Director's Office, Office of Inspection and Enforcement 83/05/05 4pp 18360 109 24X
Fiche 50-445, 83/05/05, 8305090568

8305130157 Supplementary surrebuttal testimony of J Doyle Error in fundamentals used in calculations for upper lateral restraint compounded by errors in stiffness used in Gibbs & Hill calculations Related correspondence
DOYLE, J Citizens Association for Sound Energy 83/05/09 2pp 18437 269 24X Fiche 50-445, 83/05/09, 8305130157

8305230138 Transcript of 830516 hearing in Fort Worth, TX re OL application Pp 5,855-6,169 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/16 408pp 18530 215 24X Fiche 50-445, 83/05/16, 8305230138

8305230100 Transcript of 830517 hearing in Fort Worth, TX Pp 6,170-6,286 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/17. 268pp 18534 282 24X Fiche 50-445, 83/05/17, 8305230100

8305230147 Transcript of 830517 hearing in Fort Worth, TX Pp 6,287-6,471 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/17 336pp 18529 239 24X Fiche 50-445, 83/05/17, 8305230147

8305250010 Transcript of 830518 hearing in Fort Worth, TX Pp 6,472-6,817 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/18 388pp 18584 075 24X Fiche 50-445, 83/05/18, 8305250010

8305260099 Transcript of 830519 hearing in Fort Worth, TX Pp 6,818-7,272 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/19 743pp 18597 001 24X Fiche 50-445, 83/05/19, 8305260099

8305260079 Transcript of 830520 hearing in Fort Worth, TX Pp 7,273-7,485 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/20 319pp 18624 046 24X Fiche 50-445, 83/05/20, 8305260079

DOCKET STN-50-447 GESSAR-238

A Application/construction stage documents & correspondence

8303240338 Forwards revised draft responses to discussion items & questions from NRC Power Sys Branch, Containment Sys Branch, Instrumentation & Control Sys Branch & GA Sys Branch re GESSAR-II
SHERWOOD, G G General Electric Co 83/03/23 EISENHUT, D G Division of Licensing 59pp 17681 251 24X Fiche 50-447, 83/03/23, 8303240338

8305020573 Responds to 821001, 830309, 0414 & 19 ltrs re GE request for final design approval for GESSAR-II nuclear island design Approval can be granted if listed requirements met
DENTON, H R Office of Nuclear Reactor Regulation, Director 83/04/21 SHERWOOD, G G General Electric Co 3pp 18284 233 24X Fiche 50-447, 83/04/21, 8305020573

8305030403 Provides statement of GE objectives for final design approval in light of current Commission proposed policy statement on severe accidents ACRS review of GESSAR II SER (NUREG-0979) recommended
SHERWOOD, G G General Electric Co 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp. 18306 240 24X
Fiche 50-447, 83/04/29, 8305030403

8305180060 Notification of ACRS 830513 meeting w/GE in Washington, DC to discuss GESSAR-II BWR/6 nuclear island design Marked-up agenda encl
THOMAS, C O Standardization & Special Projects Branch 83/05/09
KNIGHT, J P Assistant Director for Comp & Structures Engineering (Post 830201) JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) HOUSTON, R W Assistant Director for Reactor Safety 3pp 18499 345 24X Fiche 50-447, 83/05/09, 8305180060

8305200157 Forwards marked-up revised response to Question 460 09 of NRC 820825 request re GESSAR-II std SAR
SHERWOOD, G G General Electric Co 83/05/18 EISENHUT, D G Division of Licensing 6pp 18519 071 24X Fiche 50-447, 83/05/18, 8305200157

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020355 Forwards proposed resolution to GESSAR-II SER outstanding issue re post-accident monitoring instrumentation
SHERWOOD, G G General Electric Co 83/04/28 EISENHUT, D G Division of Licensing 48pp 18277 003 24X Fiche 50-447, 83/04/28, 8305020355

8305050379 Forwards SER for GESSAR-II BWR/6 Nuclear Island Design Outstanding issues identified in Section 1 8 expected to be resolved prior to May 1983 ACRS meeting W/o encl
THOMAS, C O Standardization & Special Projects Branch 83/04/28
RAY, J J ACRS - Advisory Committee on Reactor Safeguards 1p 18352 045 24X Fiche 50-447, 83/04/28, 8305050379

8305060562 Forwards SER (NUREG-0979) re application for final design approval for GESSAR II & FR notice W/o NUREG
THOMAS, C O Standardization & Special Projects Branch 83/04/28
SHERWOOD, G G General Electric Co 2pp 18359 210 24X
Fiche 50-447, 83/04/28, 8305060562

--8305060568 Notice of availability of SER (NUREG-0979) on proposed final design approval for GESSAR II
BRINKMAN, D S Standardization & Special Projects Branch 83/04/28 1p 18359 212 24X Fiche 50-447, 83/04/28, 8305060562

8305030403 Provides statement of GE objectives for final design approval in light of current Commission proposed policy statement on severe accidents. ACRS review of GESSAR II SER (NUREG-0979) recommended
SHERWOOD, G G General Electric Co 83/04/29. DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18306 240 24X
Fiche 50-447, 83/04/29, 8305030403

8305100298 Forwards proposed resolution of Containment Sys & Instrumentation & Control Sys Branches outstanding SER issues re GESSAR II
SHERWOOD, G G General Electric Co 83/05/05. EISENHUT, D. G Division of Licensing 6pp 18370 085 24X Fiche 50-447, 83/05/05, 8305100298

8305260037 Forwards supplemental responses to Power Sys Branch questions re GESSAR-II ac/dc power sys/balance-of-plant interfaces Responses will be included w/Amend 15 to SER
SHERWOOD, G G General Electric Co 83/05/24 EISENHUT, D G Division of Licensing 10pp 18622 310 24X Fiche. 50-447, 83/05/24, 8305260037

--8305260048 Forwards draft Amend 15 to GESSAR-II Amend resolves selected outstanding & confirmatory issues identified in SER (NUREG-0979) & completes Subsection 1 9 1 on GESSAR-II/FSAR interfaces
SHERWOOD, G G General Electric Co 83/05/24 EISENHUT, D. G. Division of Licensing 446pp 18622. 320 24X
Fiche 50-447, 83/05/24, 8305260037

T Hearing transcripts on non-antitrust matters

8305020174 Transcript of ACRS Subcommittee on GE Water Reactors, GESSAR-II 830422 meeting in Santa Monica, CA, Pp 361-609. Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/04/22 357pp 18281 299 24X Fiche 50-447, 83/04/22, 8305020174

DOCKET STN-50-454 BYRON STATION, UNIT 1

A Application/construction stage documents & correspondence

8305120552 Informs that ASME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III, Div 1, Classes 1, 2, MC & CS," not acceptable for generic use & not listed in reg guide series, per 830302 submittal.
YOUNGBLOOD, B J Licensing Branch 1. 83/05/03 FARRAR, D. L. Commonwealth Edison Co 2pp 18443 120. 24X Fiche 50-000, 83/05/03, 8305120552

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N Commissioners 22pp 18337 139 24X Fiche 50-000, 83/05/04, 8305040323

8305100237 Forwards response to FSAR question re crushable pipe whip restraint matl, per 830330 request for addl info Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FSAR amend
SWARTZ, E D Commonwealth Edison Co 83/05/04 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18373 269 24X Fiche 50-000, 83/05/04, 8305100237

8305110216 Notification of 830513 meeting w/C-E & Westinghouse in Bethesda, MD to discuss seismic & qualification review team results & pump & valve operability
OLSHAN, L N Licensing Branch 1 83/05/05 YOUNGBLOOD, B J Licensing Branch 1 3pp 18434 354 24X Fiche 50-454, 83/05/05, 8305110216

8305130051 Forwards revised response to Question 270 9, Part C re environ qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev
SWARTZ, E D Commonwealth Edison Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18436 313 24X Fiche 50-000, 83/05/06, 8305130051

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc. 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review," Suppls I & II
SWARTZ, E D Commonwealth Edison Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18487 001 24X Fiche 50-000, 83/05/09, 8305180385

--8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review," Suppls I & II
* Commonwealth Edison Co 83/04/30 221pp 18487 002 24X Fiche 50-000, 83/05/09, 8305180385

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED, C Commonwealth Edison Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche 50-000, 83/05/11, 8305200621

--8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN, R N , HARRIS, R J Energy Incorporated FERGUSON, R N Ferguson, Inc 82/07/06 65pp 18521 095 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects "
* Commonwealth Edison Co 82/11/17. 350pp 18521 160 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment
MARCUS, G F Commonwealth Edison Co 81/10/06 6pp 18522 150 24X Fiche 50-000, 83/05/11, 8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD, T , MARCUS, G F Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fiche 50-000, 83/05/11, 8305200621.

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
MARCUS, G F Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche. 50-000, 83/05/11, 8305200621

--8305200681 Rev 3 to "Interface Control Agreement, Westinghouse Piping & Structural Evaluation Program for Byron Station Unit 1 "
* Westinghouse Electric Corp * Commonwealth Edison Co * Sargent & Lundy, Inc. 82/10/29 19pp 18522 221 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200683 Rev C to Procedure 3 0 4, "Design Control - New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl
WHITAKER, W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fiche 50-000, 83/05/11, 8305200621

--8305200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util QA statement re verification of adequacy of design & const of Byron Unit 1 encl
WATTELET, P L , MEISTER, J R , BRAEGER, C B Sargent & Lundy, Inc DRR-AF-001-BB R00 80/07/16 84pp 18522 303 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed "
BIGBEE, D , CURRAN, R N , FARMAN, R F Energy Incorporated 83/04/04 127pp 18523 027 24X Fiche 50-000, 83/05/11, 8305200621

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305160059 Clarifies commitments re timing for completion of preoperational testing of auxiliary bldg ventilation sys Review of SER, NUREG-0876, indicates misunderstanding may exist
TRAMM, T R Commonwealth Edison Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18453 118 24X
Fiche 50-454, 83/05/11, 8305160059

F Security, medical, emergency & fire protection plans

8305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability
YOUNGBLOOD, B J Licensing Branch 1 83/04/11 FARRAR, D L Commonwealth Edison Co 3pp 18336 219 24X Fiche 50-000, 83/04/11, 8305040062

--8304150458 Forwards revised position accepting use of exit core thermocouples as alternative to use of hot leg temp resistance temp detectors Use of thermocouples will comply w/10CFR50, App R
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 83/03/18 MATTSON, R J Division of Systems Integration (post 811005) 4pp 18336 224 24X Fiche 50-454, 83/04/11, 8305040062

8305040069 Releases public version of rev to emergency plan implementing procedures
FELTON, J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18329 092 24X Fiche 50-454, 83/04/22, 8305040069

--8305040074 Forwards public version of rev to emergency plan implementing procedures, including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel
TRAMM, T R Commonwealth Edison Co 83/02/25 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18329 093 24X
Fiche 50-454, 83/04/22, 8305040069

--8305040080 Public version of rev to emergency plan implementing procedures, including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel
* Commonwealth Edison Co 83/02/10 331pp 18329 094 24X
Fiche 50-454, 83/04/22, 8305040069

8305060184 Forwards Rev 8 to security plan Rev withheld (ref 10CFR73 21)
FARRAR, D L Commonwealth Edison Co 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18345 090 24X
Fiche 50-454, 83/04/29, 8305060184

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations, 83/05/13 PALLADINO, N J Commissioners 5pp 18593, 322 24X
Fiche 50-000, 83/05/13, 8305240213

G Adjudicatory correspondence

8305040405 Memorandum & order denying intervenor 830428 oral motion to keep record open on steam tube integrity subissues Record contains sufficient info to make decision re Unresolved Safety Issue A-3
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/03
League of Women Voters of Rockford, IL 2pp 18323 208 24X
Fiche 50-454,83/05/03,8305040405

8305100286 Application for issuance of encl unsigned subpoenas directing attendance & testimony of I Souders & J Ogsbury at ASLB 830523 session in Rockford,IL Certificate of Svc encl
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M
DeKalb Area Alliance for Responsible Energy WHICHER, J M
Sinnissippi Alliance for the Environment (SAFE) 83/05/06
SOUDERS, I , OGSBURY, J Affiliation Unknown 7pp 18371 134 24X
Fiche 50-454,83/05/06,8305100286

8305100172 NRC response to joint intervenor motion to reopen record raised under Contention 1A concerning J Hughes testimony on QC/QA Staff opposes further hearing on subj matters
YOUNG, M A Atomic Safety and Licensing Board Panel 83/05/09 7pp
18374 323 24X Fiche 50-454,83/05/09,8305100172

--8305100176 Affidavit of DW Hayes & KA Connaughton re statement by J Hughes supporting intervenor motion to reopen record
HAYES, D W , CONNAUGHTON, K Region 3, Office of Director
83/05/09 15pp 18374 330 24X Fiche 50-454,83/05/09,8305100172

8305110215 Response in opposition to Rockford League of Women Voters & Dekalb Area Alliance for Responsible Energy/Safe Alternatives for Future Energy motion to allow testimony of J Hughes on QA/QC Certificate of Svc encl
BECKER, B D Commonwealth Edison Co BECKER, B D Isham, Lincoln & Beale 83/05/09 Atomic Safety and Licensing Board Panel 13pp
18407 039 24X Fiche 50-454,83/05/09,8305110215

8305120299 Discusses order of witness presentation for hearings resuming on 830523 NRC will present witnesses on liquid pathway contention first,followed by util,Rockford League of Women Voters & util rebuttal witnesses
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co
83/05/10 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18430 169 24X Fiche 50-454,83/05/10,
8305120299

8305160060 Affidavit of RP Tuetken on J Hughes allegations re welding Welding of brace to pressure pipe proper,if performed per design spcs Util conducting reinsp of work performed by contractor QC inspectors
TUETKEN, R P Commonwealth Edison Co 83/05/11 3pp 18453 120
24X Fiche 50-454,83/05/11,8305160060

8305170314 Confirms mailing of proprietary version of Pages 4691,4692 & 4699 from 830415 transcript,per terms of Westinghouse nondisclosure agreement Method for circulating nonproprietary portion to PDRs being worked out
DAVIS, F X Westinghouse Electric Corp 83/05/11 THOMAS, D
Affiliation Unknown 2pp 18465 076 24X Fiche 50-454,83/05/11,
8305170314

8305170319 Forwards nondisclosure agreement signed on 830427 Terms of agreement should be used to handle Westinghouse proprietary info contained in 830415 transcript Method for circulating nonproprietary portion to PDRs being worked out W/o encl
DAVIS, F X Westinghouse Electric Corp 83/05/11 CHAVEZ, D DeKalb Area Alliance for Responsible Energy CHAVEZ, D Sinnissippi Alliance for the Environment (SAFE) 1p 18465 362 24X
Fiche 50-454,83/05/11,8305170319

8305170334 Forwards application for withholding from public disclosure Westinghouse proprietary info discussed in 830415 meeting Method for circulating nonproprietary portions of 830415 transcript to PDRs being worked out W/o encl
DAVIS, F X Westinghouse Electric Corp 83/05/11 SMITH, I W ,
COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel
2pp 18469 006 24X Fiche 50-454,83/05/11,8305170334

8305170522 Forwards nondisclosure agreement signed on 830426 & proprietary version of Pages 4691,4692 & 4699 from 830415 transcript W/o proprietary pages
DAVIS, F X Westinghouse Electric Corp 83/05/11. BRIDENBAUGH, D ,
JOHNSON, B , BUNCH, R League of Women Voters of Rockford, IL 1p
18467 251 24X Fiche 50-454,83/05/11,8305170522

8305160162 Memorandum & order scheduling special deposition session for 830526 in Rockford,IL to take deposition of J Hughes & possibly of Souders & Ogsbury
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/12 8pp
18444 036 24X Fiche,50-454,83/05/12,8305160162

8305170297 Forwards stipulation w/affidavits & ambulance survey re admission of certain evidence offered by intervenors on emergency planning issues Upon admission of evidence,hearing record should be closed Svc list encl W/o stated encl
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/05/12 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18465 063 24X
Fiche 50-454,83/05/12,8305170297

8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unexecuted stipulation
BIELAWSKI, A P Commonwealth Edison Co BIELAWSKI, A P Isham, Lincoln & Beale 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18468 168 24X Fiche 50-454,83/05/12,8305170565

--8305170569 Testimony of P Holmbeck re investigation into adequacy of emergency plans re emergency planning contentions Util made no attempt to study protective value of sheltering populations around plant
HOLMBECK, P DeKalb Area Alliance for Responsible Energy
HOLMBECK, P Sinnissippi Alliance for the Environment (SAFE)
HOLMBECK, P League of Women Voters of Rockford, IL 83/05/12
73pp 18468 170 24X Fiche 50-454,83/05/12,8305170565

--8305170572 Testimony of Q Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable
MONTEL, Q DeKalb Area Alliance for Responsible Energy MONTEL, Q,
Sinnissippi Alliance for the Environment (SAFE) MONTEL, Q League of Women Voters of Rockford, IL 83/02/16 12pp 18468 245 24X
Fiche 50-454,83/05/12,8305170565

--8305170576 Testimony of JM Maloney on emergency preparedness contentions Util emergency plan cannot be implemented until questions on notification,transportation,communication & liability answered
MALONEY, J M DeKalb Area Alliance for Responsible Energy
MALONEY, J M Sinnissippi Alliance for the Environment (SAFE).
MALONEY, J M League of Women Voters of Rockford, IL 83/02/17.
12pp 18468 257 24X Fiche 50-454,83/05/12,8305170565

--8305170581 Testimony of C Lamb re emergency preparedness contentions
LAMB, C DeKalb Area Alliance for Responsible Energy LAMB, C.
Sinnissippi Alliance for the Environment (SAFE) LAMB, C. League of Women Voters of Rockford, IL 83/02/16 11pp 18468 271 24X
Fiche 50-454,83/05/12,8305170565

--8305170588 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications,transportation difficulties & school liability
TURNER, D DeKalb Area Alliance for Responsible Energy TURNER, D
Sinnissippi Alliance for the Environment (SAFE) TURNER, D. League of Women Voters of Rockford, IL 83/02/10. 12pp 18468 282 24X
Fiche 50-454,83/05/12,8305170565

--8305170590 Testimony of D Miller re emergency preparedness contentions Concerns include procedures for & modes of emergency communications,transportation difficulties & school liability
MILLER, D DeKalb Area Alliance for Responsible Energy MILLER, D
Sinnissippi Alliance for the Environment (SAFE) MILLER, D League of Women Voters of Rockford, IL 83/02/28 12pp. 18468 295. 24X
Fiche 50-454,83/05/12,8305170565

--8305170593 Testimony of JL Murphy on Contentions 3 & 13 Listed problems inherent in any radiological accident & should be resolved to provide reasonable degree of safety to citizens
MURPHY, J L DeKalb Area Alliance for Responsible Energy
MURPHY, J L Sinnissippi Alliance for the Environment (SAFE).
MURPHY, J L League of Women Voters of Rockford, IL. 83/02/28
16pp 18468 307 24X Fiche 50-454,83/05/12,8305170565

8305200521 Memorandum & order approving stipulation to offer into evidence Joint Intervenors Exhibits 13 - 20 Stipulation will be bound into 830523 transcript Proposed findings & conclusions on emergency planning issues due 830620
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/19
Office of the Executive Legal Director 1p 18516 085 24X
Fiche,50-454,83/05/19,8305200521

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305170238 Forwards IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 & 31 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/04/26 REED,C
Commonwealth Edison Co 2pp 18465.087 24X Fiche 50-454,83/04/26, 8305170238

--8305170248 IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 & 31 No noncompliance noted Major areas inspected,environ protection,including preoperational radiological environ monitoring implementation & results & mgt controls
OESTMANN,M J , SCHUMACHER,M C Region 3, Office of Director 83/04/25 7pp 18465 089 24X Fiche 50-454,83/04/26,8305170238

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190019 Forwards IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted
LITTLE,W G Region 3, Office of Director 83/05/06 REED,C
Commonwealth Edison Co 2pp. 18502 004 24X Fiche,50-454,83/05/06, 8305190019

--8305190027 IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted Major areas inspected evaluation of NDE results for pool liner welds & review of quality records
WARD,K O , DANIELSON,D H Region 3, Office of Director 83/04/29 11pp 18502 006 24X Fiche 50-454,83/05/06,8305190019

8305130129 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
SPESSARD,R L Region 3, Office of Director 83/05/10 REED,C
Commonwealth Edison Co 1p 18437 280 24X Fiche 50-454,83/05/10, 8305130129

--8305130135 Responds to NRC 820624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Welding procedures & instructions need not be at each location where actual welding performed,per ASME Code
STIEDE,W L Commonwealth Edison Co 83/01/03 KEPPLER,J G
Region 3, Office of Director 3pp 18437 281 24X
Fiche 50-454,83/05/10,8305130129

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305170458 Confirmatory action ltr re insp of pipe whip restraints in safety-related high energy piping sys on 830503-04 & 09-10 Restarting installation of whip restraints contingent upon transmittal of as-built drawings to Sargent & Lundy
KEPPLER,J G Region 3, Office of Director 83/05/13 REED,C
Commonwealth Edison Co 2pp 18469 319 24X Fiche 50-454,83/05/13, 8305170458

8305200508 Ack receipt of 830210 & 0504 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12
SPESSARD,R L Region 3, Office of Director 83/05/17 REED,C
Commonwealth Edison Co 1p 18516 060 24X Fiche 50-454,83/05/17, 8305200508

--8305200522 Responds to 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions contractor placed hold tags on 50 panels & notified electrical const dept per Procedure 6
FARRAR,D L Commonwealth Edison Co 83/05/04 KEPPLER,J G
Region 3, Office of Director 6pp 18516 061 24X
Fiche 50-454,83/05/17,8305200508

--8305200540 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions contractor instructed to identify panels which contained cable separation problems & hold tags placed on panels
FARRAR,D L Commonwealth Edison Co 83/02/10 KEPPLER,J G
Region 3, Office of Director 7pp 18516 067 24X
Fiche 50-454,83/05/17,8305200508

8305200586 Confirms enforcement conference on 830523 in Chicago,IL per 830516 telcon Conference concerns deficiencies identified in preoperational test program
SPESSARD,R L Division of Engineering 83/05/18 REED,C
Commonwealth Edison Co 1p 18514 121 24X Fiche 50-454,83/05/18, 8305200586.

8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers
NORELIUS,C E Division of Project & Resident Programs 83/05/18
REED,C Commonwealth Edison Co 1p 18571 181 24X
Fiche 50-000,83/05/18,8305240524

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260278 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Finding only 10 rejectable welds out of 1,067 not proper indication of inspector performance
NORELIUS,C E. Division of Project & Resident Programs 83/05/20
REED,C Commonwealth Edison Co 1p 18625 156 24X
Fiche 50-454,83/05/20,8305260278

--8305260282 Responds to NRC 830324 ltr re violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Corrective actions,welds reinspected New onsite contractor QA/QC qualification procedures implemented
FARRAR,D L Commonwealth Edison Co 83/04/19 KEPPLER,J G
Region 3, Office of Director 3pp 18625 157 24X
Fiche 50-454,83/05/20,8305260278

8305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing matl tests
SPESSARD,R L Division of Engineering 83/05/24 REED,C
Commonwealth Edison Co 1p. 18644 087 24X Fiche 50-000,83/05/24, 8305270476

--8305270489 Responds to NRC 830331 ltr re violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Corrective actions site design procedures compiled into manual by Westinghouse & issued to facility for site use on 830415
FARRAR,D L Commonwealth Edison Co 83/04/29 KEPPLER,J G Region 3, Office of Director 11pp 18644 088 24X Fiche 50-000,83/05/24,8305270476

--8305270501 Rev 1 to "Evaluation of Three Legged Pipe Whip Restraint Sys "
MA,J S , YANG,M S , AMIN,M Sargent & Lundy, Inc S 15 I-Q R01 82/09/21 47pp 18644 099 24X Fiche 50-000,83/05/24,8305270476

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030270 Final deficiency rept re reactor coolant pump & steam generator support columns not installed within tolerances specified on Sargent & Lundy Design Drawing S-1105 Initially reported on 830325 Revised tolerances will be verified
SWARTZ,E D Commonwealth Edison Co 83/04/25 KEPPLER,J G Region 3, Office of Director 3pp 18300 027 24X Fiche 50-454,83/04/25, 8305030270

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STARDSTECKI,R. Region 1, Office of Director. 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305190233 PNO-III-83-035 on 830511, licensee stopped work on new installation of pipe-whip restraints on safety-related piping per 830513 confirmatory action ltr Restraints installed w/o adequate procedures or QC insp program
DANIELSON,D H , LITTLE,W S Region 3, Office of Director 83/05/13 1p 18501 318 24X Fiche 50-454,83/05/13,8305190233

T Hearing transcripts on non-antitrust matters

8305040349 Transcript of 830415 hearing in Rockford, IL Pp 4,671-4,830 Supporting documentation encl
* NRC - No Detailed Affiliation Given 83/04/15 163pp 18323 031 24X Fiche 50-454,83/04/15,8305040349

8305020163 Transcript of 830426 hearing in Rockford, IL Pp 5,964-6,156
* NRC - No Detailed Affiliation Given 83/04/26 192pp. 18277 301 24X Fiche 50-454,83/04/26,8305020163

8305170408 Forwards proprietary & nonproprietary versions of statements made by NRC witness re Westinghouse Model D4/D5 steam generators Proprietary info withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp 83/04/26 EISENHUT,D G Division of Licensing 1p 18469 326 24X Fiche 50-454,83/04/26, 8305170408

--8305170411 Forwards application for withholding proprietary version of statements made by NRC witness re Westinghouse Model D4/D5 steam generators per 10CFR2 790
WIESEMANN,R A Westinghouse Electric Corp 83/04/26
EISENHUT,D G Division of Licensing 9pp 18469.327 24X Fiche 50-454,83/04/26,8305170408

Nonproprietary version of statements made by Rajan re
use Model D4/D5 steam generators.Pp 4,691-4,692 &

RC - No Detailed Affiliation Given 83/04/26 3pp
36 24X Fiche 50-454,83/04/26,8305170408

8305030305 Transcript of 830427 hearing in Rockford, IL Pp 6,157-6,400
* NRC - No Detailed Affiliation Given 83/04/27 204pp
18296 200 24X Fiche 50-454,83/04/27,8305030305

8305030508 Motion to permit J Hughes testimony re QA/QC at facility & to shorten time for responses by util & NRC Matters of testing documentation & welding constitute significant safety issues
WHICHER,J M League of Women Voters of Rockford, IL WHICHER,J M DeKalb Area Alliance for Responsible Energy WHICHER,J,M Safe Energy for New Haven 83/04/27 Atomic Safety and Licensing Board Panel 4pp 18295 091 24X Fiche 50-454,83/04/27,8305030508

--8305030516 Handwritten testimony of J Hughes re QA/QC at facility
HUGHES,J League of Women Voters of Rockford, IL HUGHES,J DeKalb Area Alliance for Responsible Energy HUGHES,J Safe Energy for New Haven 83/04/25 3pp 18295 095 24X Fiche 50-454,83/04/27,8305030508

8305030391 Transcript of 830428 hearing in Rockford, IL Pp 6,401-6,540 Supporting documentation encl
* NRC - No Detailed Affiliation Given 83/04/28 221pp 18295 329 24X Fiche 50-454,83/04/28,8305030391

8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unexecuted stipulation
BIELAWSKI,A P Commonwealth Edison Co BIELAWSKI,A P Isham, Lincoln & Beale 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18468 168 24X Fiche 50-454,83/05/12,8305170565

--8305170569 Testimony of P Holmbeck re investigation into adequacy of emergency plans re emergency planning contentions.Util made no attempt to study protective value of sheltering populations around plant
HOLMBECK,P DeKalb Area Alliance for Responsible Energy
HOLMBECK,P Sinnissippi Alliance for the Environment (SAFE)
HOLMBECK,P League of Women Voters of Rockford, IL 83/05/12, 73pp 18468 170 24X Fiche 50-454,83/05/12,8305170565

--8305170572 Testimony of Q Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable
MONTEL,Q. DeKalb Area Alliance for Responsible Energy. MONTEL,Q. Sinnissippi Alliance for the Environment (SAFE) MONTEL,Q. League of Women Voters of Rockford, IL 83/02/16 12pp 18468 245 24X Fiche 50-454,83/05/12,8305170565

--8305170576 Testimony of JM Maloney on emergency preparedness contentions Util emergency plan cannot be implemented until questions on notification, transportation, communication & liability answered
MALONEY,J M DeKalb Area Alliance for Responsible Energy.
MALONEY,J M Sinnissippi Alliance for the Environment (SAFE)
MALONEY,J M League of Women Voters of Rockford, IL. 83/02/17, 12pp 18468 257 24X Fiche 50-454,83/05/12,8305170565.

--8305170581 Testimony of C Lamb re emergency preparedness contentions
LAMB,C DeKalb Area Alliance for Responsible Energy LAMB,C. Sinnissippi Alliance for the Environment (SAFE) LAMB,C. League of Women Voters of Rockford, IL 83/02/16 11pp 18468.271. 24X Fiche 50-454,83/05/12,8305170565

--8305170588 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications, transportation difficulties & school liability
TURNER,D DeKalb Area Alliance for Responsible Energy. TURNER,D Sinnissippi Alliance for the Environment (SAFE). TURNER,D. League of Women Voters of Rockford, IL 83/02/10 12pp 18468·282 24X Fiche 50-454,83/05/12,8305170565

--8305170590 Testimony of D Miller re emergency preparedness contentions Concerns include procedures for & modes of emergency communications, transportation difficulties & school liability
MILLER,D DeKalb Area Alliance for Responsible Energy MILLER,D. Sinnissippi Alliance for the Environment (SAFE) MILLER,D League of Women Voters of Rockford, IL 83/02/28. 12pp 18468 295. 24X Fiche.50-454,83/05/12,8305170565.

--8305170593 Testimony of JL Murphy on Contentions 3 & 13.Listed problems inherent in any radiological accident & should be resolved to provide reasonable degree of safety to citizens
MURPHY,J L DeKalb Area Alliance for Responsible Energy.
MURPHY,J L. Sinnissippi Alliance for the Environment (SAFE)
MURPHY,J L League of Women Voters of Rockford, IL 83/02/28 16pp. 18468 307 24X Fiche·50-454,83/05/12,8305170565.

8305310093 Transcript of 830523 hearing in Rockford, IL Pp 6,541-6,675
* Atomic Safety and Licensing Board Panel 83/05/23 167pp
18655 129 24X Fiche 50-454,83/05/23,8305310093

8305310116 Transcript of 830524 hearing in Rockford, IL Pp 6,676-6,951 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/24 359pp
18656 129 24X Fiche 50-454,83/05/24,8305310116

DOCKET STN-50-455 BYRON STATION, UNIT 2

A Application/construction stage documents & correspondence

8305120552 Informs that ASME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III,Div 1,Classes 1,2,MC & CS," not acceptable for generic use & not listed in reg guide series,per 830302 submittal
YOUNGBLOOD,B J Licensing Branch 1 83/05/03 FARRAR,D L Commonwealth Edison Co 2pp 18443 120. 24X Fiche 50-000,83/05/03, 8305120552

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305100237 Forwards response to FSAR question re crushable pipe whip restraint matl,per 830330 request for addl info Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FSAR amend
SWARTZ,E D Commonwealth Edison Co 83/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18373 269 24X Fiche 50-000,83/05/04,8305100237

8305110216 Notification of 830513 meeting w/C-E & Westinghouse in Bethesda,MD to discuss seismic & qualification review team results & pump & valve operability
OLSHAN,L N Licensing Branch 1 83/05/05 YOUNGBLOOD,B J Licensing Branch 1 3pp 18434 354 24X Fiche 50-454,83/05/05, 8305110216

8305130051 Forwards revised response to Question 270 9,Part C re environ qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev
SWARTZ,E D Commonwealth Edison Co 83/05/06 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18436 313 24X Fiche 50-000,83/05/06,8305130051

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review," Suppls I & II
SWARTZ,E D Commonwealth Edison Co 83/05/09 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18487 001 24X Fiche. 50-000,83/05/09,8305180385

--8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review," Supplis 1 & II
* Commonwealth Edison Co 83/04/30 221pp 18487 002 24X Fiche. 50-000,83/05/09,8305180385

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED,C Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp. 18521 085. 24X Fiche 50-000,83/05/11,8305200621.

--8305200637 "Energy,Inc/Ferguson,Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN,R N Energy Incorporated 82/07/06 65pp 18521 095 24X Fiche:50-000,83/05/11,8305200621

--8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects "
* Commonwealth Edison Co 82/11/17. 350pp. 18521 160 24X Fiche. 50-000,83/05/11,8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment
MARCUS,G F Commonwealth Edison Co 81/10/06 6pp 18522 150 24X Fiche 50-000,83/05/11,8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD,T Commonwealth Edison Co 83/03/23 18pp 18522 156 24X Fiche 50-000,83/05/11,8305200621

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
MARCUS,G F Commonwealth Edison Co 82/06/17 48pp 18522 174 24X Fiche 50-000,83/05/11,8305200621

--8305200683 Rev C to Procedure 3 0 4, "Design Control - New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl
WHITAKER,W A Nuclear Power Services, Inc 82/11/23 18pp 18522 241 24X Fiche 50-000,83/05/11,8305200621

--8305200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util QA statement re verification of adequacy of design & const of Byron Unit 1 encl
WATTELET,P L , MEISTER,J R , BRAEGER,C B Sargent & Lundy, Inc DRR-AF-001-BB R00 80/07/16 84pp 18522 303 24X Fiche 50-000,83/05/11,8305200621

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed "
BIGBEE,D Energy Incorporated 83/04/04 127pp 18523 027 24X Fiche 50-000,83/05/11,8305200621

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan
GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D Operating Reactors Branch 5 2pp 18658 063 24X Fiche 50-000,83/05/26,8305310086

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305160059 Clarifies commitments re timing for completion of preoperational testing of auxiliary bldg ventilation sys Review of SER,NUREG-0876,indicates misunderstanding may exist
TRAMM,T R Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18453 118 24X Fiche 50-454,83/05/11,8305160059

F Security, medical, emergency & fire protection plans

8305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability
YOUNGBLOOD,B J Licensing Branch 1 83/04/11 FARRAR,D L Commonwealth Edison Co 3pp 18336 219 24X Fiche 50-000,83/04/11, 8305040062

8305040069 Releases public version of rev to emergency plan implementing procedures
FELTON,J M Division of Rules and Records 83/04/22 Document Management Branch 1p 18329 092 24X Fiche 50-454,83/04/22, 8305040069

--8305040074 Forwards public version of rev to emergency plan implementing procedures,including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel
TRAMM,T R Commonwealth Edison Co 83/02/25 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18329.093 24X Fiche 50-454,83/04/22,8305040069

--8305040080 Public version of rev to emergency plan implementing procedures,including Procedures BZP 100-1 re station manager & BZP 310-4 re assembly & evacuation of personnel
* Commonwealth Edison Co 83/02/10 331pp 18329 094 24X Fiche 50-454,83/04/22,8305040069

8305060184 Forwards Rev 8 to security plan Rev withheld (ref 10CFR73 21)
FARRAR,D L Commonwealth Edison Co 83/04/29 Office of Nuclear Reactor Regulation, Director 1p 18345 090 24X Fiche. 50-454,83/04/29,8305060184

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

Q Adjudicatory correspondence

8305040405 Memorandum & order denying intervenor 830428 oral motion to keep record open on steam tube integrity subissues Record contains sufficient info to make decision re Unresolved Safety Issue A-3
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/03 League of Women Voters of Rockford, IL 2pp 18323 208 24X Fiche 50-454, 83/05/03, 8305040405

8305100286 Application for issuance of encl unsigned subpoenas directing attendance & testimony of I Souders & J Ogsbury at ASLB 830523 session in Rockford, IL Certificate of Svc encl
WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M DeKalb Area Alliance for Responsible Energy WHICHER, J M Sinnissippi Alliance for the Environment (SAFE) 83/05/06
SOUDERS, I , OGSBURY, J Affiliation Unknown 7pp 18371 134 24X Fiche 50-454, 83/05/06, 8305100286

8305100172 NRC response to joint intervenor motion to reopen record raised under Contention 1A concerning J Hughes testimony on QC/QA Staff opposes further hearing on subj matters
YOUNG, M A Atomic Safety and Licensing Board Panel 83/05/09. 7pp 18374.323 24X Fiche 50-454, 83/05/09, 8305100172

--8305100176 Affidavit of DW Hayes & KA Connaughton re statement by J Hughes supporting intervenor motion to reopen record
HAYES, D W , CONNAUGHTON, K Region 3, Office of Director 83/05/09 15pp 18374 330 24X Fiche 50-454, 83/05/09, 8305100172

8305110215 Response in opposition to Rockford League of Women Voters & Dekalb Area Alliance for Responsible Energy/Safe Alternatives for Future Energy motion to allow testimony of J Hughes on QA/QC Certificate of Svc encl
BECKER, B D Commonwealth Edison Co BECKER, B D Isham, Lincoln & Beale 83/05/09 Atomic Safety and Licensing Board Panel 13pp 18407.039 24X Fiche 50-454, 83/05/09, 8305110215

8305120299 Discusses order of witness presentation for hearings resuming on 830523 NRC will present witnesses on liquid pathway contention first, followed by util, Rockford League of Women Voters & util rebuttal witnesses
GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co. 83/05/10 SMITH, I W , COLE, R F , CALLIHAN, A D. Atomic Safety and Licensing Board Panel. 2pp 18430 169 24X Fiche 50-454, 83/05/10, 8305120299

8305160060 Affidavit of RP Tuetken on J Hughes allegations re welding Welding of brace to pressure pipe proper if performed per design specs Util conducting reinsp of work performed by contractor QC inspectors
TUETKEN, R P Commonwealth Edison Co 83/05/11 3pp 18453 120 24X Fiche 50-454, 83/05/11, 8305160060

8305170314 Confirms mailing of proprietary version of Pages 4691, 4692 & 4699 from 830415 transcript, per terms of Westinghouse nondisclosure agreement Method for circulating nonproprietary portion to PDRs being worked out.
DAVIS, F X Westinghouse Electric Corp 83/05/11 THOMAS, D Affiliation Unknown 2pp 18465 076 24X Fiche 50-454, 83/05/11, 8305170314

8305170319 Forwards nondisclosure agreement signed on 830427 Terms of agreement should be used to handle Westinghouse proprietary info contained in 830415 transcript Method for circulating nonproprietary portion to PDRs being worked out W/o encl
DAVIS, F X Westinghouse Electric Corp 83/05/11 CHAVEZ, D DeKalb Area Alliance for Responsible Energy CHAVEZ, D Sinnissippi Alliance for the Environment (SAFE) 1p. 18465 362. 24X Fiche 50-454, 83/05/11, 8305170319.

8305170334 Forwards application for withholding from public disclosure Westinghouse proprietary info discussed in 830415 meeting. Method for circulating nonproprietary portions of 830415 transcript to PDRs being worked out W/o encl
DAVIS, F X Westinghouse Electric Corp 83/05/11 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 2pp 18469 006 24X Fiche, 50-454, 83/05/11, 8305170334

8305170522 Forwards nondisclosure agreement signed on 830426 & proprietary version of Pages 4691, 4692 & 4699 from 830415 transcript W/o proprietary pages
DAVIS, F X Westinghouse Electric Corp 83/05/11 BRIDENBAUGH, D JOHNSON, B , BUNCH, R. League of Women Voters of Rockford, IL 1p 18467 251 24X Fiche 50-454, 83/05/11, 8305170522

8305160162 Memorandum & order scheduling special deposition session for 830526 in Rockford, IL to take deposition of J Hughes & possibly of Souders & Ogsbury
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/12 8pp 18444 036 24X Fiche 50-454, 83/05/12, 8305160162

8305170297 Forwards stipulation w/affidavits & ambulance survey re admission of certain evidence offered by intervenors on emergency planning issues Upon admission of evidence, hearing record should be closed Svc list encl W/o stated encl
BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/05/12 SMITH, I W , COLE, R F , CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18465 063 24X Fiche 50-454, 83/05/12, 8305170297

8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unexecuted stipulation
BIELAWSKI, A P Commonwealth Edison Co BIELAWSKI, A P. Isham, Lincoln & Beale 83/05/12. Atomic Safety and Licensing Board Panel 2pp 18468: 168 24X Fiche 50-454, 83/05/12, 8305170565

8305200521 Memorandum & order approving stipulation to offer into evidence Joint Intervenors Exhibits 13 - 20 Stipulation will be bound into 830523 transcript Proposed findings & conclusions on emergency planning issues due 830620
SMITH, I W Atomic Safety and Licensing Board Panel 83/05/19 Office of the Executive Legal Director. 1p. 18516 085. 24X Fiche 50-454, 83/05/19, 8305200521

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435: 155 24X Fiche, 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc. 112pp. 18383: 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys," Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/25 Consolidated Edison Co of New York, Inc. 119pp 18381 291. 24X Fiche, 50-000, 83/04/25, 8303040025

8305170238 Forwards IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 & 31, No noncompliance noted.
PAPERIELLO, C. J. Region 3, Office of Director. 83/04/26. REED, C Commonwealth Edison Co. 2pp. 18465.087 24X Fiche: 50-454, 83/04/26, 8305170238.

--8305170249 IE Insp Repts 50-454/83-14 & 50-455/83-12 on 830316-18 & 31 No noncompliance noted Major areas inspected: environ protection, including preoperational radiological environ monitoring implementation & results & mgt controls.
OEBTMANN, M. J , SCHUMACHER, M C Region 3, Office of Director. 83/04/25 7pp. 18465.089. 24X Fiche: 50-454, 83/04/26, 8305170238

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs," Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 115pp. 18382·047. 24X Fiche. 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382·165 24X Fiche: 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/03. Consolidated Edison Co of New York, Inc 122pp 18441.170. 24X Fiche· 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305190019 Forwards IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted
LITTLE,W.S Region 3, Office of Director 83/05/06 REED,C Commonwealth Edison Co 2pp 18502 004 24X Fiche 50-454,83/05/06, 8305190019

--8305190027 IE Insp Repts 50-454/83-15 & 50-455/83-13 on 830321 & 28-31 No noncompliance noted Major areas inspected evaluation of NDE results for pool liner welds & review of quality records
WARD,K O , DANIELSON,D H Region 3, Office of Director 83/04/29, 11pp 18502 006 24X Fiche 50-454,83/05/06,8305190019

8305130129 Ack receipt of 830103 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04
SPESSARD,R L Region 3, Office of Director 83/05/10 REED,C Commonwealth Edison Co. 1p 18437 280 24X Fiche 50-454,83/05/10, 8305130129

--8305130135 Responds to NRC 820624 ltr re violations noted in IE Insp Repts 50-454/82-05 & 50-455/82-04 Welding procedures & instructions need not be at each location where actual welding performed,per ASME Code
STIEDE,W L Commonwealth Edison Co 83/01/03 KEPPLER,J G Region 3, Office of Director 3pp 18437 281 24X Fiche 50-454,83/05/10,8305130129

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp. 18524 003. 24X Fiche 50-000,83/05/11,8303040034

8305170458 Confirmatory action ltr re insp of pipe whip restraints in safety-related high energy piping sys on 830503-04 & 09-10. Restarting installation of whip restraints contingent upon transmittal of as-built drawings to Sargent & Lundy
KEPPLER,J G Region 3, Office of Director 83/05/13 REED,C Commonwealth Edison Co. 2pp 18469 319 24X Fiche 50-454,83/05/13, 8305170458.

8305200508 Ack receipt of 830210 & 0504 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12.
SPESSARD,R L Region 3, Office of Director 83/05/17 REED,C Commonwealth Edison Co 1p 18516:060 24X Fiche.50-454,83/05/17, 8305200508

--8305200522 Responds to 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions contractor placed hold tags on 30 panels & notified electrical const dept per Procedure 6
FARRAR,D L Commonwealth Edison Co 83/05/04 KEPPLER,J.G Region 3, Office of Director 6pp 18516.061 24X Fiche 50-454,83/05/17,8305200508

--8305200540 Responds to NRC 830111 ltr re violations noted in IE Insp Repts 50-454/82-17 & 50-455/82-12 Corrective actions contractor instructed to identify panels which contained cable separation problems & hold tags placed on panels
FARRAR,D.L. Commonwealth Edison Co. 83/02/10. KEPPLER,J G Region 3, Office of Director. 7pp 18516 067 24X Fiche 50-454,83/05/17,8305200508

8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP For facilities Meeting will be opened to other interested parties as observers
NORELIUS,C E Division of Project & Resident Programs 83/05/18 REED,C. Commonwealth Edison Co. 1p 18571 181 24X Fiche: 50-000,83/05/18,8305240524

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305260278 Ack receipt of 830419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Finding only 10 rejectable welds out of 1,067 not proper indication of inspector performance
NORELIUS,C E Division of Project & Resident Programs 83/05/20 REED,C Commonwealth Edison Co 1p 18625 156 24X Fiche 50-454,83/05/20,8305260278

--8305260282 Responds to NRC 830324 ltr re violations noted in IE Insp Repts 50-454/83-07 & 50-455/83-03 Corrective actions welds reinspected New onsite contractor QA/QC qualification procedures implemented
FARRAR,D L Commonwealth Edison Co 83/04/19 KEPPLER,J G Region 3, Office of Director 3pp 18625 157 24X Fiche 50-454,83/05/20,8305260278

8305270476 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Actions will be decided during pipe whip restraint energy absorbing matl tests
SPESSARD,R L Division of Engineering 83/05/24 REED,C Commonwealth Edison Co 1p 18644 087 24X Fiche 50-000,83/05/24, 8305270476

--8305270489 Responds to NRC 830331 ltr re violations noted in IE Insp Repts 50-454/83-06 & 50-455/83-05 Corrective actions site design procedures compiled into manual by Westinghouse & issued to facility for site use on 830415
FARRAR,D L Commonwealth Edison Co 83/04/29 KEPPLER,J G Region 3, Office of Director 11pp 18644 088 24X Fiche 50-000,83/05/24,8305270476

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030270 Final deficiency rept re reactor coolant pump & steam generator support columns not installed within tolerances specified on Sargent & Lundy Design Drawing S-1105 Initially reported on 830325 Revised tolerances will be verified
SWARTZ,E D Commonwealth Edison Co 83/04/25 KEPPLER,J G. Region 3, Office of Director 3pp 18300 027 24X Fiche 50-454,83/04/25, 8305030270

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072. 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11. COLLINS,J T. Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305190233 PNO-III-83-035 on 830511, licensee stopped work on new installation of pipe-whip restraints on safety-related piping per 830513 confirmatory action ltr Restraints installed w/o adequate procedures or QC insp program
DANIELSON,D.H , LITTLE,W S Region 3, Office of Director 83/05/13 1p. 18501·318 24X Fiche 50-454,83/05/13,8305190233.

T. Hearing transcripts on non-antitrust matters

8305040349 Transcript of 830415 hearing in Rockford,IL Pp 4,67 Supporting documentation encl
* NRC - No Detailed Affiliation Given 83/04/15 163pp 18323.031 24X Fiche 50-454,83/04/15,8305040349

8305020163 Transcript of 830426 hearing in Rockford, IL Pp 5,964-6,156
* NRC - No Detailed Affiliation Given 83/04/26 192pp
18277 301 24X Fiche 50-454,83/04/26,8305020163

8305170408 Forwards proprietary & nonproprietary versions of statements made by NRC witness re Westinghouse Model D4/D5 steam generators Proprietary info withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp 83/04/26 EISENHUT,D G Division of Licensing 1p 18469 326 24X Fiche 50-454,83/04/26, 8305170408

--8305170411 Forwards application for withholding proprietary version of statements made by NRC witness re Westinghouse Model D4/D5 steam generators per 10CFR2 790
WIESEMANN,R A Westinghouse Electric Corp 83/04/26
EISENHUT,D G Division of Licensing 9pp 18469 327 24X
Fiche 50-454,83/04/26,8305170408

--8305170413 Nonproprietary version of statements made by Rajan re Westinghouse Model D4/D5 steam generators Pp 4,691-4,692 & 4,699
RAJAN NRC - No Detailed Affiliation Given 83/04/26 3pp
18469 336 24X Fiche 50-454,83/04/26,8305170408

8305030305 Transcript of 830427 hearing in Rockford, IL Pp 6,157-6,400
* NRC - No Detailed Affiliation Given 83/04/27 204pp
18296 200 24X Fiche 50-454,83/04/27,8305030305

8305030508 Motion to permit J Hughes testimony re QA/QC at facility & to shorten time for responses by util & NRC Matters of testing documentation & welding constitute significant safety issues
WHICHER,J M League of Women Voters of Rockford, IL WHICHER,J M DeKalb Area Alliance for Responsible Energy WHICHER,J.M Safe Energy for New Haven 83/04/27 Atomic Safety and Licensing Board Panel 4pp 18295 091 24X Fiche 50-454,83/04/27,8305030508

--8305030516 Handwritten testimony of J Hughes re QA/QC at facility
HUGHES,J League of Women Voters of Rockford, IL HUGHES,J DeKalb Area Alliance for Responsible Energy HUGHES,J Safe Energy for New Haven 83/04/25 3pp 18295 095 24X
Fiche 50-454,83/04/27,8305030508

8305030391 Transcript of 830428 hearing in Rockford, IL Pp 6,401-6,540 Supporting documentation encl
* NRC - No Detailed Affiliation Given 83/04/28 221pp
18295 329 24X Fiche 50-454,83/04/28,8305030391

8305170565 Motion to receive into evidence stipulation & portions of prefiled testimony Stipulation covers admissibility of affidavits & exhibits bearing on emergency planning matters W/unexecuted stipulation
BIELAWSKI,A P Commonwealth Edison Co 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18468 168 24X
Fiche 50-454,83/05/12,8305170565

--8305170569 Testimony of P Holmbeck re investigation into adequacy of emergency plans re emergency planning contentions Util made no attempt to study protective value of sheltering populations around plant
HOLMBECK,P DeKalb Area Alliance for Responsible Energy
HOLMBECK,P Sinnissippi Alliance for the Environment (SAFE)
HOLMBECK,P League of Women Voters of Rockford, IL 83/05/12
73pp 18468 170 24X Fiche 50-454,83/05/12,8305170565

--8305170572 Testimony of Q Montel on emergency preparedness contentions Notification & verification procedures not developed for Pinecrest Home for Aged Vehicles & support personnel to evacuate home unavailable
MONTEL,Q DeKalb Area Alliance for Responsible Energy MONTEL,Q Sinnissippi Alliance for the Environment (SAFE). MONTEL,Q League of Women Voters of Rockford, IL 83/02/16 12pp 18468 245 24X
Fiche 50-454,83/05/12,8305170565

--8305170576 Testimony of JM Maloney on emergency preparedness contentions Util emergency plan cannot be implemented until questions on notification,transportation,communication & liability answered
MALONEY,J M DeKalb Area Alliance for Responsible Energy
MALONEY,J M Sinnissippi Alliance for the Environment (SAFE)
MALONEY,J M League of Women Voters of Rockford, IL 83/02/17.
12pp 18468 257 24X Fiche 50-454,83/05/12,8305170565

--8305170581 Testimony of C Lamb re emergency preparedness contentions
LAMB,C DeKalb Area Alliance for Responsible Energy LAMB,C Sinnissippi Alliance for the Environment (SAFE) LAMB,C League of Women Voters of Rockford, IL 83/02/16 11pp. 18468 271 24X
Fiche 50-454,83/05/12,8305170565

--8305170588 Testimony of D Turner re emergency preparedness contentions Concerns include procedures for & modes of carrying on emergency communications,transportation difficulties & school liability
TURNER,D DeKalb Area Alliance for Responsible Energy TURNER,D Sinnissippi Alliance for the Environment (SAFE) TURNER,D League of Women Voters of Rockford, IL 83/02/10 12pp 18468 282 24X
Fiche 50-454,83/05/12,8305170565

--8305170590 Testimony of D Miller re emergency preparedness contentions Concerns include procedures for & modes of emergency communications,transportation difficulties & school liability
MILLER,D DeKalb Area Alliance for Responsible Energy MILLER,D, Sinnissippi Alliance for the Environment (SAFE) MILLER,D League of Women Voters of Rockford, IL 83/02/28 12pp 18468 295 24X
Fiche 50-454,83/05/12,8305170565

--8305170593 Testimony of JL Murphy on Contentions 3 & 13 Listed problems inherent in ang radiological accident & should be resolved to provide reasonable degree of safety to citizens
MURPHY,J L DeKalb Area Alliance for Responsible Energy
MURPHY,J L Sinnissippi Alliance for the Environment (SAFE).
MURPHY,J L League of Women Voters of Rockford, IL 83/02/28
16pp. 18468 307 24X Fiche 50-454,83/05/12,8305170565

8305310093 Transcript of 830523 hearing in Rockford, IL Pp 6,541-6,675
* Atomic Safety and Licensing Board Panel 83/05/23 167pp
18655 129 24X Fiche 50-454,83/05/23,8305310093

8305310116 Transcript of 830524 hearing in Rockford, IL Pp 6,676-6,931 Supporting documentation encl
* Atomic Safety and Licensing Board Panel 83/05/24 359pp
18656 129 24X Fiche 50-454,83/05/24,8305310116

DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1

A Application/construction stage documents & correspondence

8305120552 Informs that ASME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III,Div 1,Classes 1,2,MC & CS," not acceptable for generic use & not listed in reg guide series,per 830302 submittal
YOUNGBLOOD,B J Licensing Branch 1 83/05/03 FARRAR,D,L Commonwealth Edison Co 2pp 18443 120 24X Fiche 50-000,83/05/03, 8305120552

8305100237 Forwards response to FSAR question re crushable pipe whip restraint matl,per 830330 request for addl info Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FSAR amend
SWARTZ,E D Commonwealth Edison Co 83/05/04 DENTON,H.R Office of Nuclear Reactor Regulation, Director 2pp 18373 269, 24X
Fiche 50-000,83/05/04,8305100237

8305130001 Forwards addl FSAR info,responding to Questions 241 1,241 2, 241 7 & rev to 241.6-3 in NRC 830114 & 0201 ltrs FSAR will be amended to include info
SWARTZ,E D Commonwealth Edison Co 83/05/06 DENTON,H.R Office of Nuclear Reactor Regulation, Director 24pp 18436 344 24X
Fiche 50-456,83/05/06,8305130001

8305130051 Forwards revised response to Question 270 9,Part C re environ qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev
SWARTZ,E D Commonwealth Edison Co 83/05/06 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 18436 313 24X
Fiche 50-000,83/05/06,8305130051

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review," Supplis I & II.
SWARTZ,E D. Commonwealth Edison Co 83/05/09 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 1p 18487 001 24X
Fiche 50-000,83/05/09,8305180385

--8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review." Suppls I & II
* Commonwealth Edison Co 83/04/30 221pp 18487 002. 24X
Fiche 50-000,83/05/09,8305180385

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED,C Commonwealth Edison Co 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X
Fiche 50-000,83/05/11,8305200621

--8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN,R N Energy Incorporated 82/07/06 65pp 18521 095
24X Fiche 50-000,83/05/11,8305200621

--8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects "
* Commonwealth Edison Co 82/11/17 350pp 18521 160 24X
Fiche 50-000,83/05/11,8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment
MARCUS,G F Commonwealth Edison Co 81/10/06 6pp 18522 150
24X Fiche 50-000,83/05/11,8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD,T Commonwealth Edison Co 83/03/23 18pp
18522 156 24X Fiche 50-000,83/05/11,8305200621

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
MARCUS,G F Commonwealth Edison Co 82/06/17 48pp 18522 174
24X Fiche 50-000,83/05/11,8305200621

--8305200683 Rev C to Procedure 3 Q 4, "Design Control - New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl
WHITAKER,W A Nuclear Power Services, Inc 82/11/23 18pp
18522 241 24X Fiche 50-000,83/05/11,8305200621

--8305200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept "-Util QA statement re verification of adequacy of design & const of Byron Unit 1 encl
WATTELET,P L Sargent & Lundy, Inc DRR-AF-001-88 R00 80/07/16
26pp 18523 001 24X Fiche 50-000,83/05/11,8305200621

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed."
HIGBEE,D Energy Incorporated 83/04/04 127pp 18523 027 24X
Fiche 50-000,83/05/11,8305200621

8305260287 Forwards addl FSAR info on Questions 241 3 & 330 1 re lean concrete & toxic matl shipments, respectively & revised response to Questions 241 5 & 241 7 per 830114 ltr Info will be included in FSAR amend
SWARTZ,E D Commonwealth Edison Co 83/05/23 DENTON,H R. Office of Nuclear Reactor Regulation, Director 11pp 18625 145 24X
Fiche 50-456,83/05/23,8305260287

8305310086 Notification of 830614 meeting w/util in Bethesda,MD to discuss util DCRDR program plan
GILBERT,R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD,D
Operating Reactors Branch 5 2pp 18658 063 24X
Fiche. 50-000,83/05/26,8305310086

F Security, medical, emergency & fire protection plans

8305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability
YOUNGBLOOD,B,J Licensing Branch 1 83/04/11 FARRAR,D L.
Commonwealth Edison Co 3pp 18336 219 24X Fiche 50-000,83/04/11,
8305040062

8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted
KNOP,R C. Region 3, Office of Director 83/05/04 REED,C
Commonwealth Edison Co 2pp 18548 212 24X Fiche 50-456,83/05/04,
8305240264

--8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted. Major areas inspected licensee response file for IE circulars & bulletins, action on previously identified items & fire protection requirements
HINDS,J,M , HAYES,D W Region 3, Office of Director 83/05/03
7pp. 18548 214 24X Fiche 50-456,83/05/04,8305240264

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated
Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations
83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

8305270079 Forwards expanded resume for station health physicist & proposed training program FSAR will be amended to reflect changes
SWARTZ,E D Commonwealth Edison Co 83/05/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 18638 293 24X
Fiche 50-456,83/05/23,8305270079

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305020110 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Request to withdraw Violation 3 denied Audit revealed 196 drawings missing
NORELIUS,C E Division of Project & Resident Programs 83/04/25
REED,C Commonwealth Edison Co 2pp 18278 203 24X
Fiche 50-456,83/04/25,8305020110

--8305020115 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Corrective actions grounding connection removed, floor drains cleaned & foreign matl removed from cable pans
FARRAR,D L Commonwealth Edison Co 83/03/16 KEPPLER,J G
Region 3, Office of Director 9pp 18278 205 24X
Fiche 50-456,83/04/25,8305020110

8305020224 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations & 830202 proposed imposition of civil penalties noted in IE Insp Repts 50-456/82-05 & 50-457/82-05
NORELIUS,C E Division of Project & Resident Programs 83/04/26
REED,C Commonwealth Edison Co 1p 18278 144 24X
Fiche 50-456,83/04/26,8305020224

--8305020234 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-456/82-05 & 50-457/82-05 Corrective actions full-time project manager assigned to site & improvements in organization & procedures of site contractors made
REED,C Commonwealth Edison Co 83/04/04 KEPPLER,J G Region 3, Office of Director 22pp 18278 145 24X
Fiche 50-456,83/04/26,8305020224

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305060547 Ack receipt of 830308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/81-14 & 50-457/81-14
SPESSARD, R L Division of Engineering 82/05/02 REED, C
Commonwealth Edison Co 1p 18348 245 24X Fiche 50-456, 83/05/02, 8305060547

--8305060559 Responds to NRC 830105 ltr re violations noted in IE Insp Repts 50-456/81-14 & 50-457/81-14 Corrective actions restressing of eight dome tendons w/liftoff values below predicated level began 830307
SWARTZ, E D Commonwealth Edison Co 83/03/08 KEPPLER, J G
Region 3, Office of Director 1p 18348 246 24X
Fiche 50-456, 83/05/02, 8305060547

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/05/04 REED, C
Commonwealth Edison Co 2pp 18548 212 24X Fiche 50-456, 83/05/04, 8305240264

--8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins, action on previously identified items & fire protection requirements
HINDS, J M , HAYES, D W Region 3, Office of Director 83/05/03
7pp 18548.214 24X Fiche 50-456, 83/05/04, 8305240264

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc. 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers
NORELIUS, C E Division of Project & Resident Programs 83/05/18
REED, C Commonwealth Edison Co 1p 18571 181 24X
Fiche 50-000, 83/05/18, 8305240524

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8305270191 Ack receipt of 830331 ltr in response to items of noncompliance noted in IE Insp Rept 50-456/82-06 Items 1 a 3 & 4.a incomplete Item 4 a re nonconforming cable reels deleted, per Region III 830510 meeting
SPESSARD, R L Region 3, Office of Director 83/05/23 REED, C
Commonwealth Edison Co 2pp 18637 344 24X Fiche 50-456, 83/05/23, 8305270191.

--8305270193 Responds to notice of violation noted in IE Insp Rept 50-456/82-06 Corrective actions: field walkdown of cable tray sys will be performed to identify pulled cables installed w/separation less than required
FARRAR, D L Commonwealth Edison Co 83/03/31 KEPPLER, J G
Region 3, Office of Director 6pp 18637 346 24X
Fiche 50-456, 83/05/23, 8305270191

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046.

S Reportable occurrences, LERs & related correspondence#

8305110427 Part 21 & deficiency repts re misoperation of DB-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E F Westinghouse Electric Corp 83/04/21 DEYOUNG, R, C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000, 83/04/21, 8305110427

DOCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

A Application/construction stage documents & correspondence

8305120552 Informs that ASME Code Case N-340, "Alternate Rules for Exam of Weld Edge Preparation Section III, Div 1, Classes 1, 2, MC & CS, " not acceptable for generic use & not listed in reg guide series, per 830302 submittal
YOUNGBLOOD, B J Licensing Branch 1 83/05/03 FARRAR, D L
Commonwealth Edison Co 2pp 18443 120 24X Fiche 50-000, 83/05/03, 8305120552

8305100237 Forwards response to FSAR question re crushable pipe whip restraint matl, per 830330 request for addl info. Confirmation test to verify angularity of load results will be completed by 830801 Info will be included in FSAR amend
SWARTZ, E D Commonwealth Edison Co 83/05/04. DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18373 269 24X
Fiche 50-000, 83/05/04, 8305100237

8305130001 Forwards addl FSAR info, responding to Questions 241 1, 241.2, 241 7 & rev to 241 6-3 in NRC 830114 & 0201 ltrs FSAR will be amended to include info
SWARTZ, E D Commonwealth Edison Co 83/05/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 18436 344. 24X
Fiche 50-456, 83/05/06, 8305130001

8305130051 Forwards revised response to Question 270.7, Part C re environ qualification program Representative sample of active mechanical equipment in harsh environ qualified FSAR will be amended to include rev.
SWARTZ, E D Commonwealth Edison Co 83/05/06 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 18436 313. 24X
Fiche 50-000, 83/05/06, 8305130051

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09. Consolidated Edison Co of New York, Inc 16pp 18627.153 24X
Fiche 50-000, 83/05/09, 8305090659

8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review, " Suppls I & II.
SWARTZ, E D Commonwealth Edison Co 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p 18487 001 24X
Fiche 50-000, 83/05/09, 8305180385

--8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review, " Suppls I & II
* Commonwealth Edison Co 83/04/30 221pp. 18487 002 24X
Fiche 50-000, 83/05/09, 8305180385

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl.
REED, C Commonwealth Edison Co 83/05/11 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200637 "Energy, Inc/Ferguson, Inc Audit Rept of Sargent & Lundy for Comm Ed "
CURRAN, R N Energy Incorporated 82/07/06 65pp 18521 095
24X Fiche, 50-000, 83/05/11, 8305200621

--8305200647 "Rept on INPO Self-Initiated Evaluation for Byron & Braidwood Nuclear Station Const Projects, "
* Commonwealth Edison Co 82/11/17 350pp 18521.160 24X
Fiche 50-000, 83/05/11, 8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment
MARCUS, G F Commonwealth Edison Co 81/10/06 6pp 18522:150
24X Fiche, 50-000, 83/05/11, 8305200621

--8305200665 Rept of 830307-15 audit to evaluate Sargent & Lundy QA program implementation & adequacy of facility design
SUMMERFIELD, T Commonwealth Edison Co 83/03/23 18pp
18522 156 24X Fiche 50-000, 83/05/11, 8305200621

--8305200675 Rept of 820607-11 audit re Sargent & Lundy QA program implementation & evaluation of adequacy of mechanical, electrical & structural design of facilities Related info encl
MARCUS, G F Commonwealth Edison Co 82/06/17 48pp 18522 174
24X Fiche 50-000, 83/05/11, 8305200621

--8305200683 Rev C to Procedure 3 0 4, "Design Control - New Design, Byron Station " Description of Westinghouse design assurance controls for Byron/Braidwood encl
WHITAKER, W A Nuclear Power Services, Inc 82/11/23 18pp
18522 241 24X Fiche 50-000, 83/05/11, 8305200621

--8305200688 Rev 0 to "Auxiliary Feedwater Sys Design Review Rept " Util QA statement re verification of adequacy of design & const of Byron Unit 1 encl
WATTELET, P L Sargent & Lundy, Inc DRR-AF-001-88 R00 80/07/16
26pp 18523 001 24X Fiche 50-000, 83/05/11, 8305200621.

--8305200691 "Design Evaluation (Audit) Rept of Sargent & Lundy for Comm Ed "
BIGBEE, D Energy Incorporated 83/04/04 127pp 18523 027 24X
Fiche 50-000, 83/05/11, 8305200621

8305260287 Forwards addl FSAR info on Questions 241 3 & 330 1 re lean concrete & toxic matl shipments, respectively & revised response to Questions 241 5 & 241 7 per 830114 ltr Info will be included in FSAR amend
SWARTZ, E D Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 18625 145 24X
Fiche 50-456, 83/05/23, 8305260287

8305310086 Notification of 830614 meeting w/util in Bethesda, MD to discuss util DCRDR program plan
GILBERT, R A Operating Reactors Branch 5 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18658 063 24X
Fiche 50-000, 83/05/26, 8305310086

F Security, medical, emergency & fire protection plans

8305040062 Requests that response to NRC position re source range neutron flux monitoring be expedited to allow completion of review of remaining open items re App R criteria for post-fire safe shutdown capability
YOUNGBLOOD, B. J Licensing Branch 1 83/04/11 FARRAR, D L
Commonwealth Edison Co 3pp 18336 221 24X Fiche 50-000, 83/04/11, 8305040062

8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted
KNOP, R C Region 3, Office of Director 83/05/04 REED, C
Commonwealth Edison Co 2pp 18548 212 24X Fiche 50-456, 83/05/04, 8305240264

--8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins, action on previously identified items & fire protection requirements
HINDS, J M Region 3, Office of Director 83/05/03 7pp
18548 214 24X Fiche 50-456, 83/05/04, 8305240264

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095. 24X
Fiche: 50-000, 83/05/11, 8305110034

8305270079 Forwards expanded resume for station health physicist & proposed training program FSAR will be amended to reflect changes
SWARTZ, E D Commonwealth Edison Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18638 293 24X
Fiche: 50-456, 83/05/23, 8305270079

G. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305020110 Ack receipt of 830316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Request to withdraw Violation 3 denied Audit revealed 196 drawings missing
NORELIUS, C E Division of Project & Resident Programs 83/04/25
REED, C Commonwealth Edison Co 2pp 18278 203 24X
Fiche 50-456, 83/04/25, 8305020110

--8305020115 Responds to NRC 830214 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Corrective actions grounding connection removed, floor drains cleaned & foreign matl removed from cable pans
FARRAR, D L Commonwealth Edison Co 83/03/16 KEPPLER, J G
Region 3, Office of Director 9pp 18278 205 24X
Fiche 50-456, 83/04/25, 8305020110

8305020224 Ack receipt of 830404 ltr informing NRC of steps taken to correct violations & 830202 proposed imposition of civil penalties noted in IE Insp Repts 50-456/82-05 & 50-457/82-05
NORELIUS, C E Division of Project & Resident Programs 83/04/26
REED, C Commonwealth Edison Co 1p 18278 144 24X
Fiche 50-456, 83/04/26, 8305020224

--8305020234 Responds to NRC 830225 ltr re violations noted in IE Insp Repts 50-456/82-05 & 50-457/82-05 Corrective actions full-time project manager assigned to site & improvements in organization & procedures of site contractors made
REED, C Commonwealth Edison Co 83/04/04 KEPPLER, J G Region 3, Office of Director 22pp 18278 145 24X
Fiche 50-456, 83/04/26, 8305020224

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305060547 Ack receipt of 830308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/81-14 & 50-457/81-14
SPESSARD, R L Division of Engineering 82/05/02 REED, C
Commonwealth Edison Co 1p 18348 245 24X Fiche 50-456, 83/05/02, 8305060547

--8305060559 Responds to NRC 830105 ltr re violations noted in IE Insp Repts 50-456/81-14 & 50-457/81-14 Corrective actions restressing of eight dome tendons w/liftoff values below predicated level began 830307
SWARTZ, E D Commonwealth Edison Co 83/03/08 KEPPLER, J G
Region 3, Office of Director 1p 18348 246 24X
Fiche 50-456, 83/05/02, 8305060547

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305240264 Forwards IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted
KNOP,R C Region 3, Office of Director 83/05/04 REED,C Commonwealth Edison Co 2pp. 18548 212 24X Fiche 50-456,83/05/04, 8305240264

--8305240268 IE Insp Repts 50-456/83-05 & 50-457/83-05 on 830405-08 & 14 No noncompliance noted Major areas inspected licensee response file for IE circulars & bulletins,action on previously identified items & fire protection requirements
HINDS,J M , HAYES,D W Region 3, Office of Director 83/05/03 7pp 18548 214 24X Fiche 50-456,83/05/04,8305240264

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 113pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305240524 Confirms arrangements for 830613 meeting between NRC & util in Region III ofcs to discuss SALP for facilities Meeting will be opened to other interested parties as observers
NORELIUS,C E Division of Project & Resident Programs 83/05/18
REED,C Commonwealth Edison Co 1p 18571 181 24X
Fiche 50-000,83/05/18,8305240524

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

DOCKET 50-458 RIVER BEND STATION, UNIT 1

A Application/construction stage documents & correspondence

8305040289 Advises that effective 830418,JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues.
NOVAK,T M Assistant Director for Licensing 83/04/26
HOLTZSCHER,D L Illinois Power Co 2pp 18326 343 24X
Fiche 50-000,83/04/26,8305040289

8305100198 Forwards containment issues cross ref & action plan to address addl containment issues,per util 821209 ltr W/four oversize drawings Aperture cards are available in PDR
BOOKER,J E Gulf States Utilities Co 83/04/29 SCHWENCER,A Licensing Branch 2 170pp 18380 106 24X Fiche,50-458,83/04/29, 8305100198

8305040677 Responds to 830112 request to withhold from public disclosure info re seismic reflection lines depicted in FSAR Figure 2 5-18 Request acceptable
SCHWENCER,A Licensing Branch 2 83/05/02 CAHILL,W J Gulf States Utilities Co 3pp 18336 253 24X Fiche 50-458,83/05/02, 8305040677

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000,83/05/03,8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 HALE,D P, Illinois Power Co 2pp 18523 200 24X Fiche 50-000,83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 FERGUSON,M R Washington Public Power Supply System 2pp 18523 202 24X
Fiche 50-000,83/05/03,8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 MCGAUGHY,J P Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000,83/05/03,8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 CAHILL,J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03, 8305190046

8305090602 Forwards NRC position re turbine maint Commitment to meet position classifying turbine missile issue as confirmatory required
SCHWENCER,A Licensing Branch 2 83/05/04 CAHILL,W J Gulf States Utilities Co 3pp 18367 338 24X Fiche 50-458,83/05/04, 8305090602

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305270039 Forwards request for addl info re personnel training as part of NRC review of application for OL
SCHWENCER,A Licensing Branch 2 83/05/23 CAHILL,W J Gulf States Utilities Co 5pp 18662 097 24X Fiche,50-458,83/05/23, 8305270039

C Utility Environmental Report (ER), amends & correspondence

8305260305 Summary of 830428 meeting w/util in Bethesda,MD re various environ rept - OL stage topics Topic 4 re summary cost-benefit analysis not discussed Meeting notice & agenda encl
WEINKAM,E J Licensing Branch 2 83/05/18 Licensing Branch 2 5pp 18629 296 24X Fiche:50-458,83/05/18,8305260305

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305030106 Forwards draft SER on reactor sys open items,Addl questions encl Meeting will be arranged & schedule established to resolve open items
SCHWENCER,A Licensing Branch 2, 83/04/21 CAHILL,W J. Gulf States Utilities Co, 46pp 18310 031 24X Fiche,50-458,83/04/21, 8305030106.

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02. HOLTZSCHER,D L. Illinois Power Co 2pp 18443 173 24X Fiche,50-000,83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J.J Licensing Branch 1 83/05/02 POWELL,P Washington Public Power Supply System 1p 18443 174. 24X
Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 REED, W J Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000, 83/05/02, 8305120460

--8305120483 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 RICHARDSON, J D Mississippi Power & Light Co 1p 18443 176 24X Fiche 50-000, 83/05/02, 8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 BUZZELLI, E M Cleveland Electric Illuminating Co 1p 18443 177 24X Fiche 50-000, 83/05/02, 8305120460

8305110616 Forwards structural engineering input for draft SER Encl provides summary of open items & scope of review
SCHWENCER, A Licensing Branch 2 83/05/04 CAHILL, W J, BOOKER, J E Gulf States Utilities Co 28pp 18419 309, 24X Fiche 50-458, 83/05/04, 8305110616

8305260348 Forwards draft SER input re auxiliary sys Difficulty encountered in performing review due to illegibility of some drawings
SCHWENCER, A Licensing Branch 2 83/05/18 CAHILL, W J Gulf States Utilities Co 211pp 18629, 077 24X Fiche 50-458, 83/05/18, 8305260348

8305260306 Forwards revised safeguards SER & Tech Specs in response to 830502 request for review & comments on draft SER.
MIRAGLIA, F J Assistant Director for Safety Assessment 83/05/20 NOVAK, T M Assistant Director for Licensing 4pp 18629 292 24X Fiche 50-458, 83/05/20, 8305260306

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305170468 Forwards Amend 8 to FSAR, providing responses & text changes to Section 13 3 re emergency planning
CAHILL, W J. Gulf States Utilities Co 83/05/13 EISENHUT, D G Division of Licensing 4pp 18470 167 24X Fiche 50-458, 83/05/13, 8305170468

8305190492 Notification of 830525 meeting w/util & S&W in Bethesda, MD to discuss fire protection/safe shutdown open items
WEINKAM, E J Licensing Branch 2 83/05/13 SCHWENCER, A Licensing Branch 2 3pp 18523 163 24X Fiche 50-458, 83/05/13, 8305190492

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp. 18593 322 24X Fiche: 50-000, 83/05/13, 8305240213

8305230007 Releases public version of applicant responses to NRC questions re emergency plan
FELTON, J M. Division of Rules and Records 83/05/20 Document Management Branch 1p. 18535 190. 24X Fiche 50-458, 83/05/20, 8305230007.

--8305230009 Forwards public version of responses to NRC 821216 questions re emergency plan Responses prepared per 830203 discussion w/NRC
BOOKER, J E Gulf States Utilities Co 83/03/01 SCHWENCER, A Licensing Branch 2. 89pp 18535 191 24X Fiche 50-458, 83/05/20, 8305230007

8305260306 Forwards revised safeguards SER & Tech Specs in response to 830502 request for review & comments on draft SER.
MIRAGLIA, F. J. Assistant Director for Safety Assessment. 83/05/20 NOVAK, T. M. Assistant Director for Licensing 4pp 18629 292 24X Fiche: 50-458, 83/05/20, 8305260306

Q Adjudicatory correspondence

8305030548 Order scheduling 830614 prehearing conference in Baton Rouge, LA
COTTER, B P Atomic Safety and Licensing Board Panel 83/04/29 2pp 18303 319 24X Fiche 50-458, 83/04/29, 8305030548

8305100328 Response to NRC answer to State of LA Contentions 1-6 Reasonable specificity requirements of 10CFR2 714(b) satisfied Contentions 2 & 5 premature & should be accepted conditionally Certificate of Svc encl
LINDSAY, I D Louisiana, State of 83/05/03 Atomic Safety and Licensing Board Panel 11pp 18379 007 24X Fiche 50-458, 83/05/03, 8305100328

I Financial information

8305310102 Annual Financial Rept 1982 W/830407 ltr
LEE, N R, MURRILL, P W, BOOKER, J E Gulf States Utilities Co 83/04/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 46pp 18655 296 24X Fiche 50-458, 83/04/07, 8305310102

K Utility Final Safety Analysis Report (FSAR) & amends

8305170468 Forwards Amend 8 to FSAR, providing responses & text changes to Section 13 3 re emergency planning
CAHILL, W J Gulf States Utilities Co 83/05/13 EISENHUT, D G Division of Licensing 4pp 18470 167 24X Fiche 50-458, 83/05/13, 8305170468

--8305170473 Amend 8 to FSAR
* Gulf States Utilities Co 83/05/31 390pp 18470 171 24X Fiche 50-458, 83/05/13, 8305170468

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305100137 Forwards IE Insp Rept 50-458/83-07 on 830307-11 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/04/11 CAHILL, W J Gulf States Utilities Co 2pp 18375 010 24X Fiche 50-458, 83/04/11, 8305100137

--8305100142 IE Insp Rept 50-458/83-07 on 830307-11 No noncompliance noted Major areas inspected action on previous insp findings, review of QA program for safety-related pipe supports & observation of work activities
JOHNSON, C E, CROSSMAN, W A, HUNNICUTT, D M Region 4, Office of Director. 83/04/07 6pp 18375 012 24X Fiche 50-458, 83/04/11, 8305100137

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305050157 Forwards IE Insp Rept 50-458/83-09 on 830305-0406 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/04/21 CAHILL, W J Gulf States Utilities Co 2pp 18342 001 24X Fiche 50-458, 83/04/21, 8305050157

--8305050163 IE Insp Rept 50-458/83-09 on 830305-0406 No noncompliance noted. Major areas inspected containment, structural concrete, storage of safety-related pipe & valves, structural steel installation, reactor vessel & internals storage
BROWN, R L, CROSSMAN, W A Region 4, Office of Director 83/04/20 8pp 18342 003 24X Fiche 50-458, 83/04/21, 8305050157

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/22 Consolidated Edison Co of New York, Inc. 112pp 18383, 089. 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305230305 Forwards IE Insp Rept 50-458/83-08 on 830328-31 No noncompliance noted
MADSEN,G L Region 4, Office of Director 83/04/29 CAHILL,W J
Gulf States Utilities Co 2pp 18539 135 24X
Fiche 50-458,83/04/29,8305230305

--8305230314 IE Insp Rept 50-458/83-08 on 830328-31 No noncompliance noted Major areas inspected site tour,observation of work & review of records for welding & NDE of safety-related piping & review of procedures for protective coatings
GILBERT,L D , JOHNSON,C E , DESS,J E Region 4, Office of Director 83/04/25 8pp 18539 137 24X Fiche 50-458,83/04/29, 8305230305

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8305120343 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount,Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Pressure transmitters not employed in safety-related applications
BOOKER,J E Gulf States Utilities Co 83/05/03 COLLINS,J T
Region 4, Office of Director 1p 18432 319 24X
Fiche 50-458,83/05/03,8305120343

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK,T M Assistant Director for Licensing 83/05/03
HOLTZSCHER,D L Licensing Review Group II 6pp 18440 356 24X
Fiche 50-000,83/05/03,8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co, of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp, 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030422 Interim Deficiency Rept DR-72 re improper installation (torquing),testing & insp of concrete drilled-in expansion-type anchors Evaluation in progress Interim or final rept will be sent by 830610
BOOKER,J E Gulf States Utilities Co 83/04/25 COLLINS,J T
Region 4, Office of Director 1p 18306 248 24X
Fiche 50-458,83/04/25,8305030422

8305110324 Part 21 rept re Type 8A-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd)
83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000,83/04/27,8305110324

8305060435 Interim Deficiency Rept DR-105 re electrical separation of reactor protection sys wiring from NSSS shutoff wiring. Initially reported on 830329 Investigation incomplete Next rept expected by 830701
BOOKER,J E Gulf States Utilities Co 83/04/28 COLLINS,J T
Region 4, Office of Director 1p 18343 148 24X
Fiche 50-458,83/04/28,8305060435

8305060475 Interim Deficiency Rept DR-104 re overturning of Transilift crane that was lifting reactor shield bldg dome Initially reported on 830328 Investigation incomplete Next rept expected by 830624
BOOKER,J E Gulf States Utilities Co 83/04/28 COLLINS,J T.
Region 4, Office of Director 1p 18348 166 24X
Fiche 50-458,83/04/28,8305060475

8305120367 Final Deficiency Rept DR-23 re HPCS diesel generator radiative heat loss value used in sizing of HPCS room cooling fans Initially reported on 820212 GE committed to change heat load data in manuals for diesel engines
BOOKER,J E Gulf States Utilities Co 83/04/29 COLLINS,J T
Region 4, Office of Director 2pp 18433 118 24X
Fiche 50-458,83/04/29,8305120367

8305120321 Interim Deficiency Rept DR-107 re Category I air circuit breakers w/trip coils of higher range than shown on bill of matls Initially reported on 830404 Investigation incomplete Next rept will be submitted by 830614
BOOKER,J E Gulf States Utilities Co 83/05/04 COLLINS,J.T
Region 4, Office of Director 1p 18431 080 24X
Fiche 50-458,83/05/04,8305120321

8305120409 Interim Deficiency Rept DR-106 re Interstate Steel,Hub Inc, Regal & Welded Tube of America documentation for Class 1, A-500,Grade B tube steel Initially reported on 830404. Investigation ongoing Next rept by 830707
BOOKER,J E Gulf States Utilities Co 83/05/04 COLLINS,J.T.
Region 4, Office of Director 1p 18431 152. 24X
Fiche 50-458,83/05/04,8305120409

8305120413 Interim Deficiency Rept DR-108 re Bergen-Paterson pipe support std components nonconformance w/design drawings Initially reported on 830406 Investigation ongoing Interim or final rept will be submitted by 830621
BOOKER,J E Gulf States Utilities Co. 83/05/06 COLLINS,J T
Region 4, Office of Director 1p 18434 094 24X
Fiche 50-458,83/05/06,8305120413

8305120424 Final Deficiency Rept DR-91 re misapplication of Bethlehem Steel load indicating washer in structural steel slip connection in reactor bldg.Initially reported on 830111 Condition determined not reportable per 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co 83/05/06 COLLINS,J T
Region 4, Office of Director 1p 18431 160 24X
Fiche 50-458,83/05/06,8305120424

8305170281 Final Deficiency Rept DR-86 re 821213 notification of possible misinterpretation of electrical equipment hold down weld detail Detail adequate for design considerations Item not reportable under 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co. 83/05/09. COLLINS,J T.
Region 4, Office of Director 1p. 18465.070. 24X
Fiche 50-458,83/05/09,8305170281.

8305170385 Interim Deficiency Rept DR-109 re Velan 3/4-inch,600 lb, socket-welded globe valves w/counterbores not concentric to valve ctr Initially reported on 830408 Nonconcentric counterbores may cause weld problems Next rept by 830613.
BOOKER,J E Gulf States Utilities Co 83/05/09 COLLINS,J.T.
Region 4, Office of Director 1p 18471 201 24X
Fiche 50-458,83/05/09,8305170385

8305170479 Interim Deficiency Rept DR-110 re possible contamination of stainless steel w/ultrasonic couplant failing to meet chemical analysis requirements Initially reported on 830408 Next rept to be submitted by 830615
BOOKER,J E Gulf States Utilities Co 83/05/09 COLLINS,J T
Region 4, Office of Director 1p 18467 290 24X
Fiche 50-458,83/05/09,8305170479

8305200151 Interim Deficiency Rept DR-100 re Category I motor control ctr motor operated valve feed breaker settings supplied by Gould-Brown Boveri Initially reported on 830222 Util awaiting addl info from AE Next rept expected by 830620
BOOKER,J E Gulf States Utilities Co 83/05/12 COLLINS,J T
Region 4, Office of Director 1p 18519 003 24X
Fiche 50-458,83/05/12,8305200151

8305200390 Interim Deficiency Rept DR-111 re dimensional discrepancy on two small bore pipe support design drawings Initially reported on 830412 Design drawings reflect longer dimension than justified Next rept expected by 830608
BOOKER,J E Gulf States Utilities Co 83/05/12 COLLINS,J T.
Region 4, Office of Director 1p 18518 109 24X
Fiche 50-458,83/05/12,8305200390

8305200264 Interim Deficiency Rept DR-92 re FYCO, Inc & subsupplier ASME III documentation for Category I stainless steel thermowells Initially reported on 830114 Addl info from AE pending Next will be provided by 830627
BOOKER,J E. Gulf States Utilities Co. 83/05/13 COLLINS,J T
Region 4, Office of Director 1p 18517 092 24X
Fiche 50-458,83/05/13,8305200264

8305230462 Interim Deficiency Rept DR-85 re incorrect taper at welds between outside diameter of heavy wall pipe fittings & std wall pipe on 30-inch svc water piping sys Initially reported on 821208 AE will submit addl info Next rept by 830728
BOOKER,J E Gulf States Utilities Co 83/05/16 COLLINS,J T
Region 4, Office of Director. 1p 18537 197 24X
Fiche.50-458,83/05/16,8305230462

8305230438 Final Deficiency Rept DR-87 re enlarged connection bolt holes in electrical tray supports & overtorqued connecting bolts Initially reported on 821217 Support sys structurally tested Condition not reportable per 10CFR50 55(e)
BOOKER,J E Gulf States Utilities Co 83/05/17 COLLINS,J T
Region 4, Office of Director. 1p 18538 204 24X
Fiche 50-458,83/05/17,8305230438

8305240468 Interim Deficiency Rept DR-30 re interpretation of radiographs performed by DF Shaw Co AE evaluation of defective welds will be completed by 830603 Next rept will be submitted by 830624.
BOOKER,J.E. Gulf States Utilities Co 83/05/18 COLLINS,J T
Region 4, Office of Director 1p 18549 295 24X
Fiche 50-458,83/05/18,8305240468

8305260268 Interim Deficiency Rept DR-112 re oversized power cable lugs supplied by Power Conversion Products. Initially reported on 830419 Investigation continuing Interim or final status rept will be submitted by 830628
BOOKER,J E Gulf States Utilities Co 83/05/14 COLLINS,J.T.
Region 4, Office of Director. 1p 18625 043. 24X
Fiche.50-458,83/05/19,8305260268

8305260299 Interim Deficiency Rept DR-113 re misapplication of matls used for in-line cable splices on electrical connections for hydrogen igniter assemblies Initially reported on 830419. Investigation continuing Next rept by 830629.
BOOKER,J.E Gulf States Utilities Co 83/05/19, COLLINS,J.T
Region 4, Office of Director. 1p 18625 018 24X
Fiche 50-458,83/05/19,8305260299

8305260318 Interim Deficiency Rept DR-114 re weld defects in radial rebar anchor ring for shield bldg roof Initially reported on 830419 Investigation continuing. Interim or final status rept will be submitted by 830630
BOOKER,J E. Gulf States Utilities Co 83/05/14 COLLINS,J T
Region 4, Office of Director 1p. 18625.199. 24X
Fiche 50-458,83/05/19,8305260318.

8305310042 Interim Deficiency Rept DR-96 re linear indication in section of tube steel supplied by Bergen-Patterson. Initially reported on 830217. Investigation continuing Next rept will be submitted by 830701.
BOOKER,J E Gulf States Utilities Co 83/05/20 COLLINS,J.T
Region 4, Office of Director. 1p 18653 306. 24X
Fiche 50-458,83/05/20,8305310042

DOCKET 50-459 RIVER BEND STATION, UNIT 2

A Application/construction stage documents & correspondence

8305040289 Advises that effective 830418,JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK,T M Assistant Director for Licensing 83/04/26
HOLTZSCHER,D L Illinois Power Co 2pp 18326 343 24X
Fiche 50-000,83/04/26,8305040289

8305100198 Forwards containment issues cross ref & action plan to address addl containment issues,per util 821209 ltr W/four oversize drawings Aperture cards are available in PDR
BOOKER,J E Gulf States Utilities Co 83/04/29 SCHWENCER,A
Licensing Branch 2 170pp 18380 106 24X Fiche 50-458,83/04/29,8305100198

8305040677 Responds to 830112 request to withhold from public disclosure info re seismic reflection lines depicted in FSAR Figure 2 5-18 Request acceptable
SCHWENCER,A Licensing Branch 2 83/05/02 CAHILL,W J Gulf States Utilities Co 3pp 18336 253 24X Fiche 50-458,83/05/02,8305040677

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D.G Division of Licensing 83/05/03 EDELMAN,M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000,83/05/03,8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 HALE,D P
Illinois Power Co. 2pp 18523 200 24X Fiche:50-000,83/05/03,8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 FERGUSON,M R
Washington Public Power Supply System 2pp 18523 202 24X
Fiche 50-000,83/05/03,8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 MCGAUGHY,J P
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000,83/05/03,8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 CAHILL,J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03,8305190046

8305090602 Forwards NRC position re turbine maint Commitment to meet position classifying turbine missile issue as confirmatory required
SCHWENCER,A Licensing Branch 2 83/05/04 CAHILL,W J Gulf States Utilities Co. 3pp 18367 338. 24X Fiche:50-458,83/05/04,8305090602.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D.G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305270039 Forwards request for addl info re personnel training as part of NRC review of application for OL
SCHWENCER,A Licensing Branch 2 83/05/23. CAHILL,W J Gulf States Utilities Co 5pp 18662 097 24X Fiche:50-458,83/05/23,8305270039.

C Utility Environmental Report (ER), amends & correspondence

8305260305 Summary of 830428 meeting w/util in Bethesda,MD re various environ rept - OL stage topics Topic 4 re summary cost-benefit analysis not discussed Meeting notice & agenda encl
WEINKAM,E J Licensing Branch 2 83/05/18. Licensing Branch 2. 5pp 18629 296 24X Fiche:50-458,83/05/18,8305260305

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305030106 Forwards draft SER on reactor sys open items Addl questions encl Meeting will be arranged & schedule established to resolve open items
SCHWENCER,A Licensing Branch 2 83/04/21 CAHILL,W J Gulf States Utilities Co 46pp 18310 031 24X Fiche 50-458,83/04/21, 8305030106

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 HOLTZSCHER,D L Illinois Power Co 2pp 18443 173 24X Fiche 50-000,83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 POWELL,P Washington Public Power Supply System 1p 18443 174. 24X Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02. REED,W J Gulf States Utilities Co 1p 18443 175 24X Fiche.50-000,83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 RICHARDSON,J.D Mississippi Power & Light Co 1p 18443 176 24X Fiche 50-000,83/05/02,8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 BUZZELLI,E M. Cleveland Electric Illuminating Co 1p 18443 177 24X Fiche 50-000,83/05/02,8305120460

8305110616 Forwards structural engineering input for draft SER Encl provides summary of open items & scope of review
SCHWENCER,A Licensing Branch 2 83/05/04 CAHILL,W J , BOOKER,J E Gulf States Utilities Co 28pp 18419 309 24X Fiche 50-458,83/05/04,8305110616

8305170604 Forwards site analysis sections for draft SER Open items re population data & barge transportation of toxic gases highlighted
SCHWENCER,A Licensing Branch 2 83/05/05 CAHILL,W.J Gulf States Utilities Co 17pp 18497 027. 24X Fiche 50-459,83/05/05, 8305170604

8305260348 Forwards draft SER input re auxiliary sys Difficulty encountered in performing review due to illegibility of some drawings
SCHWENCER,A Licensing Branch 2 83/05/18 CAHILL,W J. Gulf States Utilities Co. 21ipp. 18629 077 24X Fiche 50-458,83/05/18, 8305260348

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11. Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

8305170468 Forwards Amend 8 to FSAR,providing responses & text changes to Section 13 3 re emergency planning
CAHILL,W J Gulf States Utilities Co 83/05/13 EISENHUT,D.G Division of Licensing 4pp. 18470 167. 24X Fiche 50-458,83/05/13, 8305170468

8305230007 Releases public version of applicant responses to NRC questions re emergency plan
FELTON,J M Division of Rules and Records. 83/05/20 Document Management Branch 1p 18535·190 24X Fiche 50-458,83/05/20, 8305230007

--8305230009 Forwards public version of responses to NRC 821216 questions re emergency plan Responses prepared per 830203 discussion w/NRC
BOOKER,J E Gulf States Utilities Co 83/03/01 SCHWENCER,A. Licensing Branch 2 89pp 18535 191 24X Fiche 50-458,83/05/20, 8305230007

G Adjudicatory correspondence

8305030548 Order scheduling 830614 prehearing conference in Baton Rouge,LA
COTTER,D P Atomic Safety and Licensing Board Panel 83/04/29, 2pp 18303 319 24X Fiche 50-458,83/04/29,8305030548

8305100328 Response to NRC answer to State of LA Contentions 1-6 Reasonable specificity requirements of 10CFR2 714(b) satisfied Contentions 2 & 5 premature & should be accepted conditionally Certificate of Svc encl
LINDSAY,I D Louisiana, State of 83/05/03 Atomic Safety and Licensing Board Panel 11pp 18379 007 24X Fiche 50-458,83/05/03, 8305100328

I Financial information

8305310102 Annual Financial Rept 1982 W/830407 ltr
LEE,N R , MURRILL,P W , BOOKER,J E Gulf States Utilities Co 83/04/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 46pp 18655 296 24X Fiche.50-458,83/04/07,8305310102

K Utility Final Safety Analysis Report (FSAR) & amends

8305170468 Forwards Amend 8 to FSAR,providing responses & text changes to Section 13 3 re emergency planning
CAHILL,W J Gulf States Utilities Co 83/05/13 EISENHUT,D.G Division of Licensing 4pp 18470 167. 24X Fiche·50-458,83/05/13, 8305170468

--8305170473 Amend 8 to FSAR
* Gulf States Utilities Co 83/05/31 390pp 18470 171. 24X Fiche 50-458,83/05/13,8305170468

O. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385.

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435:155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383·089. 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25. Consolidated Edison Co. of New York, Inc 119pp 18381·291 24X Fiche·50-000,83/04/25,8303040025.

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc 115pp. 18382,047 24X Fiche 50-000,83/04/28,8303040026.

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co. of New York, Inc. 118pp 18382:165. 24X Fiche 50-000,83/04/28,8303040027.

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441:170 24X Fiche 50-000,83/05/03,8303040028

8305120343 Responds to IE Bulletin 80-16, "Potential Misapplication of Rosemount, Inc Models 1151 & 1152 Pressure Transmitters W/ Either A or D Output Codes " Pressure transmitters not employed in safety-related applications
BOOKER, J E Gulf States Utilities Co 83/05/03 COLLINS, J T Region 4, Office of Director 1p 18432 319 24X Fiche 50-458, 83/05/03, 8305120343

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK, T M Assistant Director for Licensing 83/05/03 HOLTZSCHER, D L Licensing Review Group II 6pp 18440 356 24X Fiche 50-000, 83/05/03, 8305120569

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046.

S Reportable occurrences, LERs & related correspondence

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/27 STELLO, V Director's Office, Office of Inspection and Enforcement 5pp, 18393 278 24X Fiche 50-000, 83/04/27, 8305110324

DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1

A. Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G. Division of Licensing. 83/05/09 Consolidated Edison Co of New York, Inc 14pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305170721 Notifies that use of ASME Code Cases N-19 & N-19-2 for application in const of diesel exhaust sys components acceptable, based on review of 830401 request
NOVAK, T. M Assistant Director for Licensing 83/05/11. FERGUSON, R. L. Washington Public Power Supply System 1p. 18496 175 24X Fiche 50-460, 83/05/11, 8305170721

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT, D G Division of Licensing 83/05/11. Consolidated Edison Co. of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

G Adjudicatory correspondence

8305020473 Motion to strike Wall Street Journal 830404 article appended to petitioner response to applicant motion for reconsideration &/or certification Article of insufficient probative value Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/04/28 Atomic Safety and Licensing Board Panel 6pp 18283 281 24X Fiche 50-460, 83/04/28, 8305020473

8305050009 Response to 830414 first set of interrogatories Certificate of Svc encl Related correspondence
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/05/03 Coalition for Safe Power 10pp 18339 018 24X Fiche 50-460, 83/05/03, 8305050009

8305050019 First set of interrogatories & requests to produce Certificate of Svc encl Related correspondence
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/05/03 Coalition for Safe Power 9pp 18338 355 24X Fiche 50-460, 83/05/03, 8305050019

8305050082 First set of interrogatories & document production requests Certificate of Svc encl
WAGNER, M E Hearing Branch 4 83/05/04 Coalition for Safe Power 8pp 18342 044 24X Fiche 50-460, 83/05/04, 8305050082

8305100263 Advises that 830404 memo re PORV environ & safety qualification not received Failure to receive notifications prejudices future involvement in case Assurance of future full notification requested
BELL, N Coalition for Safe Power 83/05/04 GROSSMAN, H , HARBOUR, J , BRIGHT, G D Atomic Safety and Licensing Board Panel 1p 18372 295 24X Fiche 50-460, 83/05/04, 8305100263

8305310076 Motion to be admitted as interested state in proceedings Certificate of Svc encl
LEWIS, N D Washington, State of 83/05/09 Atomic Safety and Licensing Board Panel 3pp 18655 119 24X Fiche 50-460, 83/05/09, 8305310076

8305170516 Opposes petitioner 830504 request for ASLB action to ensure petitioner fully notified of issues re OL Petitioner should not be treated as party since intervention status not granted
REYNOLDS, N S Debevoise & Liberman. REYNOLDS, N S Washington Public Power Supply System 83/05/12 GROSSMAN, H , BRIGHT, G D , HARBOUR, J Atomic Safety and Licensing Board Panel 2pp 18467 247 24X Fiche 50-460, 83/05/12, 8305170516

8305200576 Response opposing applicant 830428 motion to strike Wall Street Journal article appended to petitioner response to applicant motion for reconsideration Argument re probative value & admissibility misplaced W/Certificate of Svc
WAGNER, M E Hearing Branch 4 83/05/18 Atomic Safety and Licensing Board Panel 4pp 18514 122 24X Fiche 50-460, 83/05/18, 8305200576

8305200582 Advises that no communication received from Coalition for Safe Power in response to ASLB 830426 order to disclose names & addresses of individuals needed to meet standing requirements Deadline was 830506
WAGNER, M E Hearing Branch 4 83/05/18 BELL, N Coalition for Safe Power 1p 18514 249 24X Fiche 50-460, 83/05/18, 8305200582

8305240347 Motion to compel responses to 830414 first set of interrogatories to applicant re const delay Licensee objected to request Claim w/o basis Util should be ordered to respond Certificate of Svc encl
BELL, N Coalition for Safe Power 83/05/18 Atomic Safety and Licensing Board Panel 5pp 18573 001 24X Fiche 50-460, 83/05/18, 8305240347

8305240465 Memorandum opposing petitioner intervention Petitioner failed to respond to protective order, so standing can no longer be based on undisclosed individuals Certificate of Svc encl
HARTMAN, S L Washington Public Power Supply System HARTMAN, S L Debevoise & Liberman 83/05/20 Atomic Safety and Licensing Board Panel 6pp 18573 175 24X Fiche 50-460, 83/05/20, 8305240465

8305310005 Response to Interrogatories 1 through 22 (first set) Certificate of Svc encl Related correspondence
BELL, N Coalition for Safe Power 83/05/23 Washington Public Power Supply System. 7pp 18653 231 24X Fiche 50-460, 83/05/23, 8305310005

8305260172 Memorandum & order setting new time limits for responding to petitioner disclosure of individual members needed to establish standing Applicant,NRC & petitioner responses due 830608,16 & 27,respectively
GROSSMAN,H Atomic Safety and Licensing Board Panel 83/05/25
Washington Public Power Supply System 3pp 18599 286 24X
Fiche 50-460,83/05/25,8305260172

K Utility Final Safety Analysis Report (FSAR) & amends

8305030166 Forwards Amend 2 to FSAR
BOUCHEY,G D Washington Public Power Supply System 83/04/18
ADENSAM,E G Licensing Branch 4 2pp 18298 140 24X
Fiche 50-460,83/04/18,8305030166

--8305030172 Amend 2 to FSAR W/33 oversize figures Aperture cards are available in PDR
* Washington Public Power Supply System 83/04/30 600pp
18298 142 24X Fiche 50-460,83/04/18,8305030166

8305100246 Forwards Certificate of Svc for FSAR Amend 2 Atty General ofc returned FSAR & Amend 1 Ofc will no longer be provided w/documents
BOUCHEY,G D Washington Public Power Supply System 83/05/05
ADENSAM,E G Licensing Branch 4 3pp 18374,105 24X
Fiche 50-460,83/05/05,8305100246

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18433 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

Info Notice 83-29, "Fuel Binding Caused by Fuel Rack " Svc list encl
Division of Emergency Preparedness & Engineering
,st 830103) 83/05/06, Consolidated Edison Co of New
115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 007 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8303240346 Forwards responses to addl concerns of J Humphrey re containment,consisting of Action Plans 15,18,19,22,25,28,31 & 32
WULLER,G E Illinois Power Co 83/03/17 SCHWENCER,A Licensing Branch 2 46pp 17681 310 24X Fiche 50-461,83/03/17,8303240346

8305040289 Advises that effective 830418,JJ Stefano designated Licensing Review Group II program project manager Change will help expedite reviews on disposition of remaining generic issues
NOVAK,T M Assistant Director for Licensing 83/04/26
HOLTZSCHER,D L. Illinois Power Co 2pp 18326 343. 24X
Fiche 50-000,83/04/26,8305040289

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 EDELMAN,M R
Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000,83/05/03,8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 HALE,D P
Illinois Power Co 2pp 18523 200 24X Fiche,50-000,83/05/03,
8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03. FERGUSON,M R
Washington Public Power Supply System 2pp 18523 202. 24X
Fiche 50-000,83/05/03,8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G. Division of Licensing 83/05/03 MCGAUGHY,J P
Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000,83/05/03,8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 CAHILL,J. Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03,
8305190046

8305170701 Requests applicant latest presentation & summary of Caseload Forecast Panel evaluation of facility
BUDWANI,R N Affiliation Unknown 83/05/06 NRC - No Detailed
Affiliation Given 2pp 18496 258 24X Fiche 50-461,83/05/06,
8305170701

--8305170705 Forwards most recent (B01112-14) Caseload Forcast Panel meeting summary re const status
SCHWENCER,A Licensing Branch 2. 83/05/06 BUDWANI,R.
Affiliation Unknown 1p 18496 260 24X Fiche 50-461,83/05/06,
8305170701

8305200667 Submits updated info to 820924 response to 820326 request for addl info re fast scram loads on control rod drive sys. Test data revealed that 45-ms valve opening parameter more appropriately models valve hydraulic response
WULLER,G E Illinois Power Co 83/05/18 SCHWENCER,A Licensing Branch 2 1p 18519 094 24X Fiche 50-461,83/05/18,8305200667.

8305240406 Concurs in NRC recovery plan for procurement of spare & replacement parts & in lifting of stop work order
KEPPLER, J G. Region 3, Office of Director 83/05/19 GERSTNER, W C
Illinois Power Co 1p 18571 044 24X Fiche 50-461, 83/05/19, 8305240406

8305240407 Ack receipt of 830408 & 0502 requests for concurrence in lifting Stop Work Orders 017, 018 & 010 on electrical equipment, instrumentation installation & drywell refueling bellows, respectively Concurrence granted
KEPPLER, J G Region 3, Office of Director 83/05/19 GERSTNER, W C
Illinois Power Co 2pp 18574 287 24X Fiche 50-461, 83/05/19, 8305240407

--8305240413 Requests concurrence in lifting 820623 Stop Work Orders 017 re electrical equipment installation & 018 re electrical instrumentation installation Recovery plan, correcting deficiencies in traveler control procedure, encl
HALL, D P Illinois Power Co 83/04/09 KEPPLER, J G Region 3, Office of Director 34pp 18574 289 24X Fiche 50-461, 83/05/19, 8305240407.

--8305240421 Requests evaluation of completed refueling bellows recovery program to permit lifting of 820226 Stop Work Order 010 to continue bellows installation
HALL, D P Illinois Power Co 83/05/02 KEPPLER, J G Region 3, Office of Director 2pp 18574 323 24X Fiche 50-461, 83/05/19, 8305240407

8305260246 Ack receipt of 830505 ltr requesting NRC review & concurrence w/HVAC recovery plan for Stop Work Orders 014, 015 & 020 Concurs w/plan intent
KEPPLER, J G Region 3, Office of Director 83/05/19. GERSTNER, W C
Illinois Power Co 1p 18626 139 24X Fiche. 50-461, 83/05/19, 8305260246

--8305260247 Forwards Rev 1 to "HVAC Recovery Plan" for review & concurrence Rev divides actions under Phases II & III resulting in addl Phases IV & V.
HALL, D P Illinois Power Co 83/05/05 KEPPLER, J G Region 3, Office of Director 2pp 18626 140 24X Fiche 50-461, 83/05/19, 8305260246

--8305260253 Rev 1 to "HVAC Recovery Plan " W/one oversize encl Aperture card is available in PDR
* Illinois Power Co 83/05/03 38pp 18626 142 24X
Fiche 50-461, 83/05/19, 8305260246

8305240142 Forwards response to Equipment Qualification Branch review comments on FSAR Section 3 11, "Environ Qualification of Electrical Equipment "
WULLER, G E Illinois Power Co 83/05/20 SCHWENCER, A Licensing Branch 2 369pp 18547 001 24X Fiche 50-461, 83/05/20, 8305240142

8305270017 Advises that fuel load date revised from Jan 1984 to Jan 1986. Const schedule updates will continue to be submitted quarterly Next update planned for Jul 1983
HALL, D P Illinois Power Co 83/05/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18638 317 24X
Fiche 50-461, 83/05/24, 8305270017

E. NRC Safety Evaluation Report (SER), suppls & correspondence

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue.
STEFANO, J J Licensing Branch 1. 83/05/02 HOLTZSCHER, D L.
Illinois Power Co 2pp 18443 173 24X Fiche 50-000, 83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 POWELL, P Washington Public Power Supply System 1p 18443 174 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue.
STEFANO, J. J. Licensing Branch 1. 83/05/02 REED, W J. Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000, 83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 RICHARDSON, J D
Mississippi Power & Light Co 1p 18443 176 24X
Fiche 50-000, 83/05/02, 8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO, J J Licensing Branch 1 83/05/02 BUZZELLI, E M
Cleveland Electric Illuminating Co 1p 18443 177 24X
Fiche 50-000, 83/05/02, 8305120460

8305130146 Lists documentation to be provided re SER Outstanding Issue 3 (NUREG-0853), "Seismic Analysis," per NRC request at 830428 meeting W/Sargent & Lundy in Bethesda, MD, satisfying site-specific spectrum concerns
WULLER, G E Illinois Power Co 83/05/10 SCHWENCER, A Licensing Branch 2 3pp 18438 124 24X Fiche 50-461, 83/05/10, 8305130146

F Security, medical, emergency & fire protection plans

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations
83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

G Adjudicatory correspondence

8305120336 Memorializes 830509 conversation w/Judge Paris ASLB will participate in 830602 site visit All parties may attend
GODDARD, R J Hearing Branch 3 83/05/11 FOY, J Prairie Alliance
NEUMAN, R Illinois, State of ZABEL, S A Schiff, Hardin & Waite
1p 18432 294 24X Fiche 50-461, 83/05/11, 8305120336

K Utility Final Safety Analysis Report (FSAR) & amends

8304050243 Forwards Amend 24 to FSAR, consisting of Tables 3 10-1 & -2 re dynamic qualifications of BOP & NSSS electrical equipment & revs to jet impingement evaluation & froth impingement loads
HALL, D P Illinois Power Co 83/03/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 17831 252 24X
Fiche 50-461, 83/03/28, 8304050243

8304050254 Amend 24 to FSAR
* Illinois Power Co 83/03/31 773pp 17831 253 24X
Fiche 50-461, 83/03/28, 8304060243

Q Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11
PRENDERGAST, R Prendergast, R J 17pp 18506 059 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co, HVAC contractor at facilities, re potential allegations Zack Co planning to terminate several employees in document control section
HAYES, D W Region 3, Office of Director 82/05/12 Region 3, Office of Director. 1p. 18506 089 24X Fiche 50-000, 83/03/11, 8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000, 83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co, HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE, T Government Accountability Project 82/07/26
PALLADINO, N, J Commissioners 11pp 18506 128 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co, HVAC contractor at facilities
MARELLO, S L Affiliation Unknown 82/07/26 22pp 18506 139
24X Fiche 50-000, 83/03/11, 8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
HOWARD,A T Affiliation Unknown 82/07/26 55pp 18506 160
24X Fiche 50-000,83/03/11,8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
NORELIUS,C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000,83/03/11,
8305190005

8305020336 Forwards IE Mgt Meeting Rept 50-461/83-06 on 830317
KEPPLER,J G Region 3, Office of Director 83/04/08 GERSTNER,W C
Illinois Power Co 1p 18277 068 24X Fiche 50-461,83/04/08,
8305020336

--8305020339 IE Mgt Meeting Rept 50-461/83-06 on 830317 Major areas discussed status of stop work recovery & overinsp & improvement programs
KEPPLER,J G , KNOP,R C , HAYES,D W Region 3, Office of Director
83/04/07 3pp 18277 069 24X Fiche 50-461,83/04/08,8305020336

8305060576 Forwards revised overinsp & record verification program Procedures BQA 185,BQA 190-BQA 194 & BQA 196,for review W/o encl
HALL,D P Illinois Power Co 83/04/13 KEPPLER,J G Region 3,
Office of Director 1p 18349 052 24X Fiche 50-461,83/04/13,
8305060576

8305020111 Informs of withdrawal of 830413 request for review & concurrence of revs to overinsp & record verification program procedures
HALL,D P Illinois Power Co 83/04/20 KEPPLER,J G Region 3,
Office of Director 1p 18278 216 24X Fiche 50-461,83/04/20,
8305020111

8305120345 Forwards IE Insp Rept 50-461/82-25 on 820914-830325 No noncompliance noted
LITTLE,W S Region 3, Office of Director 83/04/27 GERSTNER,W C
Illinois Power Co 2pp 18432 271 24X Fiche 50-461,83/04/27,
8305120345

--8305120348 IE Insp Rept 50-461/82-25 on 820914-830325,No noncompliance noted Major areas inspected procedures & records for reinsp of structural steel bolting
KEATING,D E , DANIELSON,D H Region 3, Office of Director
83/04/27 7pp 18432 273 24X Fiche 50-461,83/04/27,8305120345

8305170013 Forwards IE Insp Rept 50-461/83-04 on 830106-0317 No noncompliance noted
KNOP,R C Region 3, Office of Director 83/04/27 GERSTNER,W C
Illinois Power Co 2pp 18466 156 24X Fiche 50-461,83/04/27,
8305170013

--8305170022 IE Insp Rept 50-461/83-04 on 830106-0317 No noncompliance noted Major areas inspected matl laydown & storage areas, program control,general welding activities & stop work recovery activities
LIVERMORE,H H , HAYES,D W Region 3, Office of Director
83/04/26 5pp 18466 158. 24X Fiche 50-461,83/04/27,8305170013

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK,T M Assistant Director for Licensing. 83/05/03.
HOLTZSCHER,D L Licensing Review Group II 6pp 18440.356 24X
Fiche,50-000,83/05/03,8305120569

8305260244 Forwards IE Insp Rept 50-461/83-01 on 830420 & 21 No noncompliance noted
STREETER,J F Region 3, Office of Director 83/05/12
GERSTNER,W C Illinois Power Co 2pp 18599 324 24X
Fiche 50-461,83/05/12,8305260244

--8305260250 IE Insp Rept 50-461/83-01 on 830420 & 21 No noncompliance noted Major areas inspected licensee action on spare replacement part procurement sys inadequacies
HASSE,R A , HAWKINS,F C Region 3, Office of Director 83/05/12
4pp 18599 326 24X Fiche,50-461,83/05/12,8305260244

R Periodic operating reports & related correspondence

8305030559 Forwards "Preoperational Environ Radiological Monitoring Program,Clinton Power Station,1982 "
WULLER,G E Illinois Power Co 83/04/26 SCHWENCER,A Licensing Branch 2 1p 18305 150 24X Fiche 50-461,83/04/26,8305030559

--8305030592 "Preoperational Environ Radiological Monitoring Program Clinton Power Station,1982 "
MARUCUT,C R , HUEBNER,L G Harleton Laboratories America, Inc
83/04/07 78pp 18305 151 24X Fiche 50-461,83/04/26,8305030559

S Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co & or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506 059 24X
Fiche 50-000,83/03/11,8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated,document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS,D E Zack Co 81/10/23 310pp 18506 215 24X
Fiche 50-000,83/03/11,8305190005

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T
Region 4, Office of Director 5pp. 18433 074 24X
Fiche 50-000,83/04/26,8305120392

8305040298 Interim Dficiency Rept 82-11 re incorrect identification of base matl & weld procedures on piping hanger travelers Initially reported on 821020 Further traveler review necessary Investigation to be completed in 90 days
HALL,D P Illinois Power Co 83/04/27 KEPPLER,J G Region 3,
Office of Director 5pp 18324 020 24X Fiche 50-461,83/04/27,
8305040298

8305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attached hold tags to 13 HVAC control panels w/defect. Evaluation being conducted
HALL,D P Illinois Power Co 83/05/04 KEPPLER,J G Region 3,
Office of Director 2pp. 18431 049 24X Fiche 50-000,83/05/04,
8305120475

--8305120484 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformance rept will be issued for applicable sites
FAUCONNEAU,G Mark Controls Corp 83/04/18 Director's Office
Office of Inspection and Enforcement 2pp 18431 051 24X
Fiche 50-000,83/05/04,8305120475

8305310129 Interim Deficiency Rept 83-05 re failure of 1/4 inch 20 Hex head cap screws Initially reported on 830412 Conduit straps will be installed w/higher strength cap screws & torque instructions will be issued.
HALL,D P Illinois Power Co 83/05/23 KEPPLER,J G Region 3,
Office of Director 4pp 18655 035 24X Fiche 50-461,83/05/23,
8305310129

8305310183 Interim Deficiency Rept 81-04 re inconsistencies in certifications of HVAC matls Initially reported on 811002 Zack Co revised corporate & site QA manuals to enhance controls & describe programs
HALL,D P Illinois Power Co 83/05/23 KEPPLER,J G Region 3,
Office of Director 4pp 18658 129 24X Fiche 50-461,83/05/23,
8305310183

DOCKET 50-462 CLINTON POWER STATION, UNIT 2

G Inspection reports, IE Bulletins & correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR,App B,C,D & E documents withheld (ref FOIA Exemption 7).
FELTON,J.M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506.059 24X
Fiche 50-000,83/03/11,8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co,HVAC contractor at facilities,re potential allegations Zack Co lanning to terminate several employees in document control action
HAYES,D W Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche 50-000,83/03/11, 8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co,HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE,T Government Accountability Project 82/07/26
PALLADINO,N J Commissioners 11pp 18506 128 24X Fiche 50-000,83/03/11,8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
MARELLO,S L Affiliation Unknown 82/07/26 22pp 18506 139 24X Fiche 50-000,83/03/11,8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co,HVAC contractor at facilities
HOWARD,A T Affiliation Unknown 82/07/26 55pp 18506 160 24X Fiche 50-000,83/03/11,8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
NORELIUS,C E Division of Engineering 82/07/12 Division of Engineering 1p 18512 323 24X Fiche 50-000,83/03/11, 8305190005

B Reportable occurrences, LERs & related correspondence

8305190005 Final response to FOIA request for documents re Zack Co &/pr work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11
PRENDERGAST,R Prendergast, R J 17pp 18506 059 24X Fiche: 50-000,83/03/11,8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated,document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS,D E Zack Co 81/10/23 310pp 18506 215 24X Fiche 50-000,83/03/11,8305190005

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,B F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 3pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

DOCKET 50-447 KUOSHENG POWER STATION, UNIT 1

P. Operating license stage documents & correspondence

8305240496 Forwards "Safety Relief Valve Discharge Test," final rept for Kuosheng Nuclear Power Station,including Apps A-T Rept withheld (ref 10CFR2 790) Info submitted per OL Condition 2.C(45).
DALE,L.F Mississippi Power & Light Co 83/05/02 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp. 96189 286 24X Fiche: 50-000,83/05/02,8305240496

DOCKET STN-50-470 CESSAR SYSTEM 80

A Application/construction stage documents & correspondence

8305170326 Forwards revised CESSAR-F Section 3 11 re environ design of mechanical & electrical equipment Rev will be incorporated into amend to CESSAR-F
SCHERER,A E Combustion Engineering, Inc 83/05/10 EISENHUT,D G Division of Licensing 52pp 18465 173 24X Fiche 50-470,83/05/10, 8305170326

8305230704 Responds to ACRS 811215 recommendation re C-E evaluation of interface requirements for applications ref CESSAR ACRS recommendations could have antitrust implications Outlined response to be included in CESSAR SER
EISENHUT,D G Division of Licensing 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18542 304 24X Fiche 50-470,83/05/16,8305230704

--8302250480 Expresses concern that requiring C-E NSSS applicants to select C-E to make CESSAR interface requirements determination may have antitrust implications
VOLLMER,R H Division of Engineering 83/02/17 EISENHUT,D G Division of Licensing 3pp 18542 315 24X Fiche 50-470, 83/05/16,8305230704

B Utility Preliminary Safety Analysis Report, amends

8305120120 Forwards Amend 8 to CESSAR-F List of rev topics encl
SCHERER,A E Combustion Engineering, Inc 83/05/10 THOMAS,C Standardization & Special Projects Branch 5pp 18428 260 24X Fiche 50-470,83/05/10,8305120120

--8305120124 Amend 8 to CESSAR-F
* Combustion Engineering, Inc 83/05/10 246pp 18428 265 24X Fiche 50-470,83/05/10,8305120120

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305020400 Forwards "Sys 80 CESSAR FSAR,Responses to Questions on Steam Line Break Method," per SER Confirmatory Item 14 Proprietary responses withheld (ref 10CFR2 790)
SCHERER,A E Combustion Engineering, Inc 83/04/26 THOMAS,C O Standardization & Special Projects Branch 6pp 18284 034 24X Fiche 50-470,83/04/26,8305020400

--8305020406 "Sys 80 CESSAR FSAR,Responses to Questions on Steam Line Break Method "
* Combustion Engineering, Inc 83/04/30 16pp 18284 040 24X Fiche 50-470,83/04/26,8305020400

8305090338 Forwards proprietary & nonproprietary "Response to NRC Questions on CESSAR-F Statistical Combination of Uncertainties in Thermal Margin Analysis for Sys 80," (SER Item 7) Proprietary response withheld (ref 10CFR2 790)
SCHERER,A E Combustion Engineering, Inc 83/05/03 EISENHUT,D G Division of Licensing 6pp 18363 074 24X Fiche 50-470,83/05/03, 8305090338

--8305090372 Nonproprietary "Response to NRC Questions on CESSAR-F Statistical Combination of Uncertainties in Thermal Margin Analysis for Sys 80," (SER Item 7)
* Combustion Engineering, Inc 83/04/30 39pp 18363 080 24X Fiche 50-470,83/05/03,8305090338

8305120185 Forwards nonproprietary & proprietary responses to Questions 440 5,10,11 & 12 on steam line break method,resolving SER Confirmatory Items 14 & 15 Proprietary responses withheld (ref 10CFR2.790) Affidavit encl
SCHERER,A E Combustion Engineering, Inc 83/05/10 THOMAS,C O Standardization & Special Projects Branch 19pp 18424 208 24X Fiche 50-470,83/05/10,8305120185

8305130081 Notifies that steam generator tube rupture analysis addressed in 830426 ltr will be performed,per SER Confirmatory Item 18 & will be submitted by 830715
SCHERER,A E Combustion Engineering, Inc 83/05/10 EISENHUT,D G Division of Licensing 2pp 18437 088 24X Fiche 50-470,83/05/10, 8305130081

8305180017 Requests current schedule to respond to SER Suppl 1 open item re finalization of generic statistical combination of uncertainty analysis
THOMAS,C O Standardization & Special Projects Branch 83/05/13
BERLINGER,C Core Performance Branch 2pp 18497 198 24X Fiche 50-470,83/05/13,8305180017

8305200568 Forwards amended Table 3-1 of Section II F 2, App B reflecting clarification of addressing TMI Action Item II F 2 re inadequate core cooling detection instrumentation, Open Item 4 of CESSAR-F SER
SCHERER, A E Combustion Engineering, Inc 83/05/13 EISENHUT, D G Division of Licensing 4pp 18514 279 24X Fiche 50-470, 83/05/13, 8305200568

M Antitrust correspondence

8305230704 Responds to ACRS 811215 recommendation re C-E evaluation of interface requirements for applications ref CESSAR ACRS recommendations could have antitrust implications Outlined response to be included in CESSAR SER
EISENHUT, D G Division of Licensing 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18542 304 24X Fiche 50-470, 83/05/16, 8305230704

--8302250480 Expresses concern that requiring C-E NSSS applicants to select C-E to make CESSAR interface requirements determination may have antitrust implications
VOLLMER, R H Division of Engineering 83/02/17 EISENHUT, D G Division of Licensing 3pp 18542 315 24X Fiche 50-470, 83/05/16, 8305230704

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8305040006 Forwards request for addl info to complete evaluation of 830310 environ qualification plan Info should be provided within 30 days or NRC licensing project managers notified within 7 days of ltr receipt if schedule cannot be met
YOUNGBLOOD, B J Licensing Branch 1 83/04/20 SCHNELL, D F Union Electric Co 6pp 18331 248 24X Fiche 50-000, 83/04/20, 8305040006

8305020229 Discusses inaccuracies in util 830121 response to NRC questions re SNM application No enforcement action planned Complete candor between NRC & licensee emphasized
GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 83/04/28 KOESTER, G L Kansas Gas & Electric Co 2pp 18278 142 24X Fiche 50-482, 83/04/28, 8305020229

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305110014 Forwards response to 820907 request for addl info re pump & valve operability & purge valve operability, consisting of master listing of seismic & dynamic qualification for facilities Proposed audit schedule encl
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 233pp 18621 203 24X Fiche 50-000, 83/05/09, 8305110014

8305130007 Requests permission to use Paragraph NX-4427 of Winter 1982 Addenda to ASME Boiler & Pressure Vessel Code, Section III allowing undersizing of fillet welds
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18437 148 24X Fiche 50-000, 83/05/09, 8305130007

8305250193 Notification of 830615 public meeting w/util in Burlington, KS & Caseload Forecast Panel 830616 & 17 site visit to assess status of const & completion schedules
HOLONICH, J J Licensing Branch 1 83/05/09 YOUNGBLOOD, B J Licensing Branch 1 6pp 18626 324 24X Fiche 50-482, 83/05/09, 8305250193

8305270058 Advises that fuel load scheduled for 840815 & commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltr 82-33) requirements re emergency plans will be met
CADMAN, W K Kansas Gas & Electric Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18638 250 24X Fiche 50-482, 83/05/23, 8305270058

8305310175 Forward Rev 1 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0588 "
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/27 DENTON, H R, Office of Nuclear Reactor Regulation, Director 344pp 18659 144 24X Fiche 50-000, 83/05/27, 8305310175

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305110047 Forwards test summary rept demonstrating acceptability of using regulating-type transformer as isolation device in IE circuit per SER Confirmatory Issue 19
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18409 017 24X Fiche 50-000, 83/05/09, 8305110047

8305250231 Summary of Power Sys Branch 830409-09 site audit re power supply for auxiliary feedwater sys per SER Confirmatory Issues 15, 17 & 23 (Section 1 7 of NUREG-0830)
EDISON, G E , HOLONICH, J J Licensing Branch 1 83/05/12 YOUNGBLOOD, B J Licensing Branch 1 7pp 18627 100 24X Fiche 50-000, 83/05/12, 8305250231

8305180393 Informs that results of tests on isolating regulating transformer, in conjunction w/change in 830509 ltr re SER Confirmatory Issue 19, assure that faults postulated on secondary circuits will not adversely affect Class IE bus
PETRICK, N A Standardized Nuclear Unit Power Plant System 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18486 346 24X Fiche 50-000, 83/05/13, 8305180393

8305270210 Forwards div input to emergency planning for suppl to SER Matl updates info contained in Section 13 3, "Emergency Planning of Wolf Creek Generating Station SER," (NUREG-0881, Apr 1982)
PAGANO, F G Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/25 YOUNGBLOOD, B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482, 83/05/25, 8305270210

F Security, medical, emergency & fire protection plans

8305060338 Releases public version of addl info for review of emergency plan
FELTON, J M Division of Rules and Records 83/04/25 Document Management Branch, 1p 18353 026 24X Fiche 50-482, 83/04/25, 8305060338

--8305060346 Forwards public version of addl info re review of emergency plan, consisting of revised response to NRC questions & of revised emergency plan pages
KOESTER, G L Kansas Gas & Electric Co 83/04/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18353 027 24X Fiche 50-482, 83/04/25, 8305060338

--8305060354 Public version of revised pages to emergency plan, including revised response to NRC questions & of revised emergency plan pages
* Kansas Gas & Electric Co 83/04/30 6pp 18353 029, 24X Fiche 50-482, 83/04/25, 8305060338

8305020421 Forwards addl info re emergency plan per 821206 request Info addresses Question B.4 concerning plant personnel response capability during emergency situation per staffing goals in Suppl 1 to NUREG-0737
KOESTER, G L Kansas Gas & Electric Co. 83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18273, 100 24X Fiche 50-482, 83/04/29, 8305020421

8305120088 Requests review schedule for applicant response to Generic Ltr 82-33 re NUREG-0737, Suppl 1 concerning emergency response capability W/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/04/29, MOORE, V Human Engineering Section ROBA, F Instrumentation & Control Branch PAGANO, F Emergency Preparedness Licensing Br (after 801119 see I&E) 2pp 18443 191 24X Fiche 50-000, 83/04/29, 8305120088

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT, D G Division of Licensing, 83/05/11 Consolidated Edison Co of New York, Inc 16pp, 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322, 24X Fiche 50-000, 83/05/13, 8305240213

8305270058 Advises that fuel load scheduled for 840815 & commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltr 82-33) requirements re emergency plans will be met
CADMAN, W K Kansas Gas & Electric Co 83/05/23 DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 18638 250 24X Fiche 50-482, 83/05/23, 8305270058

8305270210 Forwards div input to emergency planning for suppl to SER Matl updates info contained in Section 13 3, "Emergency Planning of Wolf Creek Generating Station SER." (NUREG-0881, Apr 1982)
PAGANO,F O Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/25 YOUNGBLOOD,B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482,83/05/25,8305270210

Q Adjudicatory correspondence

8305060488 Objections to proposed issues & motion for adoption of interrogatory responses as statement of issues for litigation Proposed stipulation lacks specificity Certificate of Svc encl Related correspondence
RIDGWAY,D A Kansas Gas & Electric Co 83/05/03 Atomic Safety and Licensing Board Panel 24pp 18348 214 24X
Fiche 50-482,83/05/03,8305060488

8305090496 Order denying objection to ASLB prehearing order re amend of contention/stipulation by intervenor & granting request to add Kansas Dept of Transportation & Highway Patrol employees to witness list
LAURENSON,J A Atomic Safety and Licensing Board Panel 83/05/05 5pp 18361 148 24X Fiche 50-482,83/05/05,8305090496

8305090503 Order of expedited briefing schedule re applicant objection & motion for adoption of interrogatory responses as statement of issues for litigation Responses due by 830516
LAURENSON,J A Atomic Safety and Licensing Board Panel 83/05/05 Kansas Gas & Electric Co 2pp 18362 010 24X
Fiche 50-482,83/05/05,8305090503

8305120391 Attachment A,alternative evacuation plan contention,to response in opposition to intervenors W Christy & ME Salava 830330 objections to ASLB 830318 prehearing conference order Related correspondence
RIDGWAY,D Kansas Gas & Electric Co RIDGWAY,D Shaw, Pittman, Potts & Trowbridge 83/05/05 34pp 18433 081 24X
Fiche 50-482,83/05/05,8305120391

8305180288 Response opposing util 830503 objections to issues & motion for adoption of interrogatory responses as statement of issues for litigation ASLB should adopt intervenor second stipulation of contentions W/Certificate of Svc
SIMPSON,J M Christy, W , Intervenor SIMPSON,J M Salava, M E Intervenor 83/05/12 Atomic Safety and Licensing Board Panel 28pp 18490 305 24X Fiche 50-482,83/05/12,8305180288

8305170002 Response to util 830503 objections to intervenor proposed issues & motion for adoption Util correct in limiting scope of inquiry to plume emergency planning zone,per Commission regulations.Certificate of Svc encl
KARMAN,M Hearing Branch 1 83/05/13 6pp 18466 225 24X
Fiche.50-482.83/05/13,8305170002.

8305240313 Informs of agreement to develop acceptable statement of contentions & resolution of all but one objection to proposed issues for litigation,per applicant 830503 objections.
SILBERG,J E. Shaw, Pittman, Potts & Trowbridge SILBERG,J E Kansas Gas & Electric Co 83/05/19 LAURENSON,J A , ANDERSON,O C , PAXTON,H C Atomic Safety and Licensing Board Panel 5pp 18548 188 24X Fiche.50-482,83/05/19,8305240313

I. Financial information

8305230567 Forwards Annual Financial Repts for 1982 for Kansas Gas & Electric Co,Kansas City Power & Light Co & audited financial statements for 1982 from Kansas Electric Power Cooperative, Inc.
KOESTER,G L Kansas Gas & Electric Co 83/05/18 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p. 18535 280 24X
Fiche.50-482.83/05/18,8305230567.

--8305230570 Annual Financial Rept 1982.
CADMAN,W K Kansas Gas & Electric Co. 83/02/04 32pp.
18535 281. 24X Fiche 50-482,83/05/18,8305230567

--8305230572 Annual Financial Rept 1982 Audited statements from Kansas Electric Power Cooperative,Inc for 1982 encl.
DOYLE,A J Kansas City Power & Light 83/03/01 46pp
18535 313. 24X Fiche.50-482,83/05/18,8305230567

O. Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J.M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308,319 24X Fiche 50-000,83/03/21,8212060385.

8305100303 Forwards 830315 IE investigation rept re activities under CPPR-147 No violations identified
COLLINS,J T Region 4, Office of Director 83/04/05 KOESTER,G L Kansas Gas & Electric Co 4pp 18370 081 24X
Fiche 50-482,83/04/05,8305100303

--8305100307 Rept of investigation on 820802-830110 re allegations concerning activities authorized by CPPR-147 No violations observed
GRIFFIN,H B , HERR,R K , WARD,W J Region 4, Office of Director 83/03/15 3pp 18370 082 24X Fiche 50-482,83/04/05,8305100303

8305100112 Forwards IE Insp Rept 50-482/83-06 on 830221-0315 No noncompliance noted
SEIDLE,W C Region 4, Office of Director 83/04/12 KOESTER,G L Kansas Gas & Electric Co 2pp 18375 036 24X
Fiche 50-482,83/04/12,8305100112

--8305100116 IE Insp Rept 50-482/83-06 on 830221-0315 No noncompliance noted Major areas inspected action on previous insp findings,const deficiency repts,observations of safety-related pipe hangers & supports & general plant tours
ROBERDS,H W , JOHNSON,W D Region 4, Office of Director 83/04/04 5pp 18375 038 24X Fiche 50-482,83/04/12,8305100112

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305100151 Forwards IE Insp Rept 50-482/83-07 on 830301-31 & notice of violation
SEIDLE,W C Region 4, Office of Director, 83/04/22 KOESTER,G L Kansas Gas & Electric Co 2pp 18374 223 24X
Fiche 50-482,83/04/22,8305100151

--8305100155 Notice of violation from insp on 830301-31
* Region 4, Office of Director 83/04/22 1p 18374 225 24X
Fiche 50-482,83/04/22,8305100151

--8305100160 IE Insp Rept 50-482/83-07 on 830301-31 Noncompliance noted failure to implement QA program requirements for constructor test program
SCHUM,W B , JOHNSON,W D Region 4, Office of Director 83/04/21 9pp 18374 226 24X Fiche 50-482,83/04/22,8305100151

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305030617 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/82-22
SEIDLE,W C Region 4, Office of Director 83/04/27 KOESTER,G L Kansas Gas & Electric Co 2pp 18303 321 24X
Fiche 50-482,83/04/27,8305030617

--8305030622 Responds to NRC 830223 ltr re violations noted in IE Insp Rept 50-482/82-22 Corrective actions maint forms revised, vendor contact documented & maint records for Westinghouse supplied items will be reviewed
KOESTER,G L Kansas Gas & Electric Co 83/03/25 SEIDLE,W C Region 4, Office of Director 5pp 18303 323 24X
Fiche 50-482,83/04/27,8305030617

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp. 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305230473 Forwards IE Insp Rept 50-482/83-10 on 830316-0415 & notice of violation
SEIDLE,W C Region 4, Office of Director 83/05/06 KOESTER,G L Kansas Gas & Electric Co 2pp 18537 186 24X
Fiche 50-482,83/05/06,8305230473

--8305230476 Notice of violation from insp on 830316-0415
* Region 4, Office of Director 83/05/06 1p 18537 188 24X
Fiche 50-482,83/05/06,8305230473

--8305230480 IE Insp Rept 50-482/83-10 on 830316-0415 Noncompliance noted failure to prescribe activities affecting quality by procedure for welding of electrical raceway supports
ROBERDS,H W , JOHNSON,W D Region 4, Office of Director 83/05/03 5pp 18537 189 24X Fiche 50-482,83/05/06,8305230473

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305230485 Ack receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-04 Addl info requested re measures to assure that all equipment opened prior to rev had necessary controls applied
SEIDLE,W C Region 4, Office of Director 83/05/18 KOESTER,G L Kansas Gas & Electric Co 1p 18537 183 24X Fiche 50-482, 83/05/18,8305230485

--8305230489 Responds to NRC 830325 ltr re violations noted in IE Insp Rept 50-482/83-04 Corrective actions vol control tank cleaned & procedures for maintaining cleanliness revised
KOESTER,G L Kansas Gas & Electric Co 83/04/21 SEIDLE,W C Region 4, Office of Director 2pp 18537 184 24X
Fiche 50-482,83/05/18,8305230485

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8305310104 Ack receipt of 830511 ltr discussing educational qualification of util QC inspector Results of verification process for personnel educational level requested.
SEIDLE,W C Region 4, Office of Director 83/05/25 KOESTER,G L Kansas Gas & Electric Co 1p 18658 067 24X Fiche 50-482, 83/05/25,8305310104

--8305310110 Advises that incident re educational qualification of QC inspector under investigation Completion of high school not verified if completion of higher level of educ verified. High school educ verification continuing
KOESTER,G L Kansas Gas & Electric Co 83/05/11 SEIDLE,W C Region 4, Office of Director 2pp 18658 068 24X
Fiche 50-482,83/05/25,8305310104

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S. Reportable occurrences, LERs & related correspondence

8304150354 Part 21 Rept U-48 & interim deficiency rept re GE ARR-30 & AKR-50 circuit breakers. Initially reported on 830211. Assessment of safety implications & corrective actions requested of AE Final rept expected by 830429
SCHNELL,D.F Union Electric Co. 83/04/07 SPESSARD,R.L. Division of Project & Resident Programs. 1p 17982 128 24X
Fiche 50-000,83/04/07,8304150354

8305020073 Final Deficiency Rept SDR 83-06 re Anchor/Darling check valves failing to close Initially reported on 830323 Caused by improper design Hinge pins replaced & Stellite 6 bushings to be installed
SEIKEN,S J Standardized Nuclear Unit Power Plant System 83/04/20 KEPPLER,J G Region 3, Office of Director COLLINS,J T Region 4, Office of Director 2pp 18279 100 24X Fiche 50-000,83/04/20, 8305020073

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030354 Interim deficiency rept re restricted movement of nonstationary pipe supports Initially reported on 821014, AE evaluation in progress Next rept will be sent by 830729
KOESTER,G L Kansas Gas & Electric Co 83/04/25 SEIDLE,W C. Region 4, Office of Director 1p 18300 022 24X
Fiche 50-482,83/04/25,8305030354

8305030378 Interim deficiency rept re compromised welding inspector exams Initially reported on 820712 Number of inspectors under investigation reduced to four & reinsp of welds accepted by four inspectors in progress Next rept by 830826.
KOESTER,G L Kansas Gas & Electric Co 83/04/25 SEIDLE,W C. Region 4, Office of Director 1p 18306 258 24X
Fiche 50-482,83/04/25,8305030378

8305030492 Second interim deficiency rept re documentation & hardware discrepancies in borated refueling water sys Initially reported on 830121 Status rept of evaluation will be submitted by 830624
KOESTER,G L Kansas Gas & Electric Co 83/04/25 SEIDLE,W.C Region 4, Office of Director 2pp 18306 181. 24X
Fiche 50-482,83/04/25,8305030492

8305040430 Final Significant Deficiency Rept 83-05 re GE AKR 30 & 50 electrically operated low voltage circuit breakers. Initially reported on 830211 Field rework plan will be issued to effect necessary breaker repairs
SEIKEN,S Standardized Nuclear Unit Power Plant System 83/04/28, KEPPLER,J G Region 3, Office of Director COLLINS,T T. Region 4, Office of Director 8pp 18319.319 24X Fiche 50-000,83/04/28, 8305040430

8305200335 Supplemental final deficiency rept re suspect modules mfg by Foxboro Co Eight addl suspect modules identified & will be replaced
KOESTER,G L Kansas Gas & Electric Co 83/05/12. SEIDLE,W C. Region 4, Office of Director 1p 18516 228 24X
Fiche 50-482,83/05/12,8305200335

8305310148 Final deficiency rept re matl traceability of U-bolts & bulk bolting matls Initially reported on 830204 Marking requirements established to assure proper matl identification.
KOESTER,G.L Kansas Gas & Electric Co 83/05/23 SEIDLE,W.C. Region 4, Office of Director 5pp. 18653.055 24X
Fiche 50-482,83/05/23,8305310148.

DOCKET STN-50-483 CALLAWAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

8303240307 Forwards "Offsite Dose Calculation Manual "
SCHNELL,D F Union Electric Co 83/03/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp. 17682:049 24X
Fiche 50-483,83/03/21,8303240307

--8303240311 "Offsite Dose Calculation Manual "
* Union Electric Co. 83/03/21 66pp 17682 052. 24X
Fiche 50-483,83/03/21,8303240307

8305040006 Forwards request for addl info to complete evaluation of 830310 environ qualification plan Info should be provided within 30 days or NRC licensing project managers notified within 7 days of ltr receipt if schedule cannot be met.
YOUNGBLOOD,B J Licensing Branch 1 83/04/20 SCHNELL,D.F. Union Electric Co 6pp 18331 248 24X Fiche 50-000,83/04/20,8305040006

8305040323 Board Notification 83-057, forwards differing prof opinions re sys interaction & safety classification. Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17.
EISENHUT,D G Division of Licensing 83/05/04. PALLADINO,N Commissioners. 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305110014 Forwards response to 820907 request for addl info re pump & valve operability & purge valve operability, consisting of master listing of seismic & dynamic qualification for facilities Proposed audit schedule encl
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 233pp 18621 203 24X Fiche 50-000, 83/05/09, 8305110014

8305130007 Requests permission to use Paragraph NX-4427 of Winter 1982 Addenda to ASME Boiler & Pressure Vessel Code, Section III allowing undersizing of fillet welds
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18437 148 24X Fiche 50-000, 83/05/09, 8305130007

8305310175 Forward Rev 1 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0588 "
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 344pp 18659 144 24X Fiche 50-000, 83/05/27, 8305310175

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305110047 Forwards test summary rept demonstrating acceptability of using regulating-type transformer as isolation device in IE circuit per SER Confirmatory Issue 19
PETRICK, N A Standardized Nuclear Unit Power Plant System
83/05/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 18409 017 24X Fiche 50-000, 83/05/09, 8305110047.

8305250231 Summary of Power Sys Branch 830405-09 site audit re power supply for auxiliary feedwater sys per SER Confirmatory Issues 15, 17 & 23 (Section 1 7 of NUREG-0830)
EDISON, G. E., HOLONICH, J. J Licensing Branch 1 83/05/12, YOUNGBLOOD, B J Licensing Branch 1 7pp 18627 100 24X Fiche: 50-000, 83/05/12, 8305250231

8305180393 Informs that results of tests on isolating regulating transformer, in conjunction w/change in 830509 ltr re SER Confirmatory Issue 19, assure that faults postulated on secondary circuits will not adversely affect Class IE bus
PETRICK, N A. Standardized Nuclear Unit Power Plant System
83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 18486 346 24X Fiche 50-000, 83/05/13, 8305180393

F Security, medical, emergency & fire protection plans

8305120088 Requests review schedule for applicant response to Generic Ltr 82-33 re NUREG-0737, Suppl 1 concerning emergency response capability W/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/04/29, MOORE, V Human Engineering Section, ROSA, F Instrumentation & Control Branch PAGANO, F. Emergency Preparedness Licensing Br (after 801119 see I&E). 2pp 18443, 191 24X Fiche 50-000, 83/04/29, 83051200BB

8305170222 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-14.
SPESSARD, R L Division of Engineering 83/05/09 SCHNELL, D F Union Electric Co 1p 18466 346 24X Fiche. 50-483, 83/05/09, 8305170222.

--8305170227 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-483/82-14 Corrective actions complete walkdown performed on all outside area bldgs, fuel bldg & other fire-rated openings
SCHNELL, D F Union Electric Co 83/04/27 LITTLE, W B Region 3, Office of Director 3pp 18466 347 24X Fiche 50-483, 83/05/09, 8305170222.

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc 16pp 18540 095. 24X
Fiche: 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J. Office of the Executive Director for Operations, 83/05/13 PALLADINO, N J Commissioners 5pp. 18593 322 24X Fiche 50-000, 83/05/13, 8305240213.

G Adjudicatory correspondence

8305030467 Forwards Daniel Const Co summary of relevant events & corrective actions re potential reportable deficiency in testing of candidates for QC inspector certification Certificate of Svc encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union Electric Co 83/04/28 ROSENTHAL, A S , EDLES, G J , COTCHY, R L Atomic Safety and Licensing Appeal Panel 8pp 18292 166 24X Fiche 50-483, 83/04/28, 8305030467

8305020394 Order scheduling 830614 oral argument in Bethesda, MD re Joint Intervenors appeal from ASLB partial initial decision
TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/04/29 2pp 18276 327 24X Fiche 50-483, 83/04/29, 8305020394

8305100257 Requests rescheduling of 830614 oral argument on appeal of Joint Intervenors from partial initial decision Certificate of Svc encl
CHACKES, K M Chackes & Hoare 83/05/06 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 2pp 18374 062 24X
Fiche 50-483, 83/05/06, 8305100257

8305110266 Confirms svc of Callaway County/Fulton County radiological emergency response plan on 830506 Plans for Osage Gasconade & Montgomery Counties & state plan forthcoming Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/09 REED, J G Missouri, State of 2pp 18393 155 24X Fiche 50-483, 83/05/09, 8305110266

8305120314 Order rescheduling oral argument for 830622 per Joint Intervenors request
SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel 83/05/10 Joint Intervenors-Callaway 1p 18424 105 24X
Fiche 50-483, 83/05/10, 8305120314

8305130083 Notice of rescheduling of 830614 oral argument for 830622 in Bethesda, MD
SHOEMAKER, C J Atomic Safety and Licensing Board Panel 83/05/11 1p 18436 265 24X Fiche 50-483, 83/05/11, 8305130083

8305190249 Confirms util delivery of State of MO accident plan for plant & Osage County radiological emergency response plan Svc list encl
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union Electric Co 83/05/17 REED, J G Reed, J G 2pp 18501 301 24X
Fiche 50-483, 83/05/17, 8305190249

8305250205 Confirms delivery of Gasconade & Montgomery County radiological emergency response plans on 830519 Svc list encl W/o encl ltrs
BAXTER, T A Shaw, Pittman, Potts & Trowbridge BAXTER, T A Union Electric Co 83/05/20 REED, J G Reed, J G 2pp 18592 356 24X
Fiche 50-483, 83/05/20, 8305250205

8305250294 Memorandum of law supporting motions for summary disposition of emergency planning issues Hearing time should not be spent on baseless allegations Notice of appearance encl
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 14pp 18585 001 24X Fiche 50-483, 83/05/20, 8305250294

--8305250297 Motion for summary disposition of Reed Contention 1 re staffing of Montgomery County sheriff ofc No genuine issue of matl fact exists & applicant entitled to favorable decision.
BAXTER, T A Union Electric Co. BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 25pp 18586 015 24X Fiche: 50-483, 83/05/20, 8305250294

--8305250300 Statement of matl facts as to which there is no genuine issue re Reed Contention 1 staffing of Montgomery County sheriff ofc
BAXTER, T A Union Electric Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge. 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 040 24X Fiche 50-483, 83/05/20, 8305250294

--8305250304 Affidavit of WM Clark re Reed Contention 1 on staffing of sheriff ofcs Adequate personnel available w/law enforcement training to provide emergency law enforcement svcs for Callaway County & City of Fulton
CLARK, W M. Union Electric Co CLARK, W M Callaway County, MO
CLARK, W M Fulton, MO 83/05/16 16pp 18586 042 24X
Fiche. 50-483, 83/05/20, 8305250294

--8305250341 Affidavit of GW Stanfill re Reed Contention 1 on staffing of sheriffs ofc. Sufficient personnel available per shift to fulfill law enforcement functions assigned to Montgomery, Gasconade & Osage Counties
STANFILL, G W Union Electric Co STANFILL, G W Missouri, State of. 83/05/12 12pp 18586 058 24X Fiche 50-483, 83/05/20, 8305250294

--8305250346 Motion for summary disposition of Reed Contention 2 re staffing of county clerk ofcs No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 18pp 18586 070 24X Fiche 50-483,83/05/20,8305250294

--8305250351 Statement of matl facts as to which there is no genuine issue re Reed Contention 2 on staffing of county clerk ofcs
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 088 24X Fiche 50-483,83/05/20,8305250294

--8305250354 Affidavit of WM Clark re Reed Contention 2 on staffing of Callaway County & City of Fulton clerk ofcs No addl clerical personnel needed to provide assistance during emergency shifts Prof qualifications encl
CLARK,W M Union Electric Co CLARK,W M Callaway County, MO
CLARK,W M Fulton,MO 83/05/16 9pp 18586 090 24X
Fiche 50-483,83/05/20,8305250294

--8305250356 Affidavit of GW Stanfill re Reed Contention 2 on staffing of clerk ofcs Emergency-related clerical functions described in county plans will be properly incorporated in Montgomery, Gasconade & Osage Counties Prof qualifications encl
STANFILL,G W Union Electric Co STANFILL,G W Missouri, State of 83/05/12 4pp 18586 099 24X Fiche 50-483,83/05/20, 8305250294

--8305250358 Motion for summary disposition of Reed Contention 3 re emergency mgt director staffing No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18586 103 24X Fiche 50-483,83/05/20,8305250294

--8305250359 Statement of matl facts as to which there is no genuine issue re Reed Contention 3 on emergency mgt director staffing
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 118 24X Fiche 50-483,83/05/20,8305250294

--8305250360 Affidavit of T Mitchell re Reed Contention 3 on emergency mgt director staffing Full-time emergency mgt director in Montgomery County unnecessary VB Eldringhoff is alternate director
MITCHELL,J Union Electric Co MITCHELL,J Affiliation Unknown 83/05/17 4pp 18586 120 24X Fiche 50-483,83/05/20,8305250294

--8305250363 Affidavit of H Lalk re Reed Contention 3 on emergency mgt director staffing Full-time emergency mgt director for Gasconade County unnecessary
LALK,H Union Electric Co LALK,H Gasconade County, MO 83/05/16 4pp 18586 124 24X Fiche 50-483,83/05/20,8305250294

--8305250372 Affidavit of J Crowe re Reed Contention 3 on emergency mgt director staffing Full-time emergency mgt director for Osage County unnecessary
CROWE,J Union Electric Co CROWE,J Osage County, MO 83/05/09 4pp 18586 128 24X Fiche 50-483,83/05/20,8305250294

--8305250383 Motion for summary disposition of Reed Contention 4 re emergency action level scheme/worker notification No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18586 132 24X Fiche 50-483,83/05/20,8305250294

--8305250388 Statement of matl facts as to which there is no genuine issue re Reed Contention 4 on emergency action level scheme/ worker notification
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 147 24X Fiche 50-483,83/05/20,8305250294

--8305250394 Affidavit of JW Baer re Reed Contention 4 on emergency action level scheme/worker notification Emergency classification sys & worker notification provisions reflect sound operational concepts Prof qualifications encl
BAER,J W Union Electric Co BAER,J W Energy Consultants, Inc 83/05/13 12pp 18586 149 24X Fiche 50-483,83/05/20,8305250294

--8305250401 Motion for summary disposition of Reed Contention 5,Parts B & C re radio communications No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 5pp 18586 161 24X Fiche 50-483,83/05/20,8305250294

--8305250403 Statement of matl facts as to which there is no genuine issue re Reed Contention 5,Parts B & C on radio communications
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 166 24X Fiche 50-483,83/05/20,8305250294

--8305250408 Affidavit of MA Stiller re Reed Contention 5,Parts B & C on radio communications Commitment to supply addl transceivers for designated patrol & rescue vehicles provides sufficient communication for patrol & rescue
STILLER,M A Union Electric Co 83/05/18 4pp 18586 168 24X Fiche 50-483,83/05/20,8305250294

--8305250412 Motion for summary disposition of Reed Contentions 6 & 16 re protective actions against radioiodines & messages for long-term sheltering No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 50pp 18586 172 24X Fiche 50-483,83/05/20,8305250294

--8305250419 Statement of matl facts as to which there is no genuine issue re Reed Contentions 6 & 16 on protective actions against radioiodines & messages w/instructions for long-term sheltering
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 3pp 18586 222 24X Fiche 50-483,83/05/20,8305250294

--8305250424 Affidavit of KV Miller re Reed Contention 6 on protective actions against radioiodines State of MO will not administer potassium iodine to general public in event of accident,but drug will be available to state emergency workers
MILLER,K V Union Electric Co MILLER,K V Missouri, State of 83/05/11 7pp 18586 225 24X Fiche 50-483,83/05/20,8305250294

--8305250428 Affidavit of RE Linneman re Reed Contention 6 on protective actions against radioiodines Describes risks & benefits associated w/ingestion of potassium iodine & endorses State of MO policy re distribution of potassium iodine
LINNEMANN,R E Union Electric Co LINNEMANN,R E Radiation Management Corp 83/04/28 14pp 18586 232 24X
Fiche 50-483,83/05/20,8305250294

--8305250432 Affidavit of NO Slaten re Reed Contentions 6 & 16 on protective actions against radioiodines & messages w/ instructions for long-term sheltering Explains effectiveness of sheltering as protective action
SLATEN,N O Union Electric Co. 83/05/16 8pp 18586,246 24X
Fiche 50-483,83/05/20,8305250294

--8305250436 Affidavit of S Harris re Reed Contentions 6 & 16 on protective actions against radioiodines & messages w/ instructions for long-term sheltering Explains effectiveness of ad hoc respiratory protection
HARRIS,S Union Electric Co 83/05/16 14pp 18586·254 24X
Fiche 50-483,83/05/20,8305250294

--8305250440 Motion for summary disposition of Reed Contention 7 re presited decontamination facilities No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T.A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 6pp 18586 268 24X Fiche 50-483,83/05/20,8305250294

--8305250444 Statement of matl facts as to which there is no genuine issue re Reed Contention 7 on presited decontamination facilities
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 274. 24X Fiche 50-483,83/05/20,8305250294

--8305250448 Motion for summary disposition of Reed Contention 8 re radiation detection equipment.No genuine issue of matl fact exists & applicant entitled to favorable decision
BAUSER,D B Union Electric Co BAUSER,D.B. Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 11pp 18586 276 24X Fiche 50-483,83/05/20,8305250294

--8305250451 Statement of matl facts as to which there is no genuine issue re Reed Contention 8 on radiation detection equipment
BAUSER,D B Union Electric Co BAUSER,D.B. Shaw, Pittman, Potts & Trowbridge 83/05/20. Atomic Safety and Licensing Board Panel 2pp 18586 287 24X Fiche 50-483,83/05/20,8305250294

--8305250458 Affidavit of RE Linnemann re Reed Contention 8 on radiation detection equipment State of MO & local govts have sufficient equipment,lab facilities & expertise to evaluate external & internal radiation exposures
LINNEMANN,R E Union Electric Co LINNEMANN,R E. Radiation Management Corp. 83/04/28. 13pp 18586·289 24X
Fiche 50-483,83/05/20,8305250294

--8305250461 Motion for summary disposition of Reed Contention 9 on radiological exposures No genuine issue of matl fact exists & applicant entitled to favorable decision
BAUSER,D B Union Electric Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18586 302 24X Fiche 50-483,83/05/20,8305250294

--8305250463 Statement of matl fact as to which there is no genuine issue re Reed Contention 9 on radiological exposures
BAUSER,D B Union Electric Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 317 24X Fiche 50-483,83/05/20,8305250294

--8305250468 Affidavit of RE Linnemann re Reed Contention 9 on radiological exposure Means for controlling radiological exposure of local emergency workers during accident established per 10CFR50 47(b)(11)
LINNEMANN,R E Union Electric Co LINNEMANN,R E Radiation Management Corp 83/04/28 17pp 18586 319 24X Fiche 50-483,83/05/20,8305250294

--8305250474 Motion for summary disposition of Reed Contention 10 re medical treatment No genuine issue of matl fact exists & applicant entitled to favorable decision
BAUSER,D B Union Electric Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 22pp 18586,336, 24X Fiche 50-483,83/05/20,8305250294

--8305250477 Statement of matl fact as to which there is no genuine issue re Reed Contention 10 on medical treatment
BAUSER,D B Union Electric Co BAUSER,D B Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18586 358 24X Fiche 50-483,83/05/20,8305250294

--8305250482 Affidavit of RE Linnemann re Reed Contention 10 on medical treatment Upon completion of training program,Callaway Memorial Hosp will provide adequate local medical resources to handle all types of radiation injuries
LINNEMANN,R E Union Electric Co LINNEMANN,R E Radiation Management Corp 83/04/28 26pp 18586 360 24X Fiche 50-483,83/05/20,8305250294

--8305250486 Motion for summary disposition of Reed Contention 11 re reentry/recovery radiation stds No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 13pp 18587,024 24X Fiche 50-483,83/05/20,8305250294

--8305250490 Statement of matl fact as to which there is no genuine issue re Reed Contention 11 on recovery & reentry radiation stds
BAXTER,T A Union Electric Co. BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 037 24X Fiche 50-483,83/05/20,8305250294

--8305250496 Affidavit of JW Baer re Reed Contention 11 on reentry/recovery radiation stds Offsite emergency plans reentry decision process description complies w/planning criteria Prof qualifications encl
BAER,J W Union Electric Co BAER,J W. Energy Consultants, Inc 83/05/13 9pp 18587 039 24X Fiche 50-483,83/05/20,8305250294

--8305250502 Motion for summary disposition of Reed Contention 13 re organizations requiring SOPs No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T.A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18587·049, 24X Fiche 50-483,83/05/20,8305250294

--8305250506 Statement of matl fact as to which there is no genuine issue re Reed Contention 13 on organizations requiring SOPs
BAXTER,T.A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20. Atomic Safety and Licensing Board Panel 2pp. 18587 063 24X Fiche 50-483,83/05/20,8305250294

--8305250511 Affidavit of JW Baer re Reed Contention 13 on organizations requiring SOPs Functional procedures will provide adequate instructions to organizations assigned emergency response role
BAER,J W. Union Electric Co BAER,J W Energy Consultants, Inc 83/05/13, 13pp 18587 065 24X Fiche 50-483,83/05/20,8305250294

--8305250515 Motion for summary disposition of Reed Contention 14 on incorporated cities,towns & villages No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge. 83/05/20. Atomic Safety and Licensing Board Panel 17pp. 18587 078 24X Fiche 50-483,83/05/20,8305250294

--8305250521 Statement of matl fact as to which there is no genuine issue re Contention 14 on incorporated cities,towns & villages
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 097 24X Fiche 50-483,83/05/20,8305250294

--8305250524 Motion for summary disposition of Reed Contention 15 re ltrs of agreement No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 14pp 18587 099 24X Fiche 50-483,83/05/20,8305250294

--8305250531 Statement of matl fact as to which there is no genuine issue re Contention 15 on ltrs of agreement
BAXTER,T A Union Electric Co 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 113 24X Fiche 50-483, 83/05/20,8305250294

--8305250536 Affidavit of WM Clark re Reed Contention 15 on ltrs of agreement Sufficient ltrs of agreement exist or will exist prior to plant operation to ensure necessary emergency support & resources to implement util/Fulton plan
CLARK,W M Union Electric Co CLARK,W M Callaway County, MO
CLARK,W M Fulton,MO 83/05/16 17pp 18587 115 24X Fiche 50-483,83/05/20,8305250294

--8305250540 Motion for summary disposition of Reed Contention 17 re radiological monitoring No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20. Atomic Safety and Licensing Board Panel 21pp 18587 132 24X Fiche 50-483,83/05/20,8305250294

--8305250542 Statement of matl fact as to whcih there is no genuine issue re Reed Contention 17 on radiological monitoring
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 3pp 18587 133 24X Fiche 50-483,83/05/20,8305250294

--8305250544 Affidavit of KV Miller re Reed Contention 17 on radiological monitoring State resources in trained personnel & radiation monitoring equipment adequate Prof qualifications encl
MILLER,K V Union Electric Co MILLER,K V Missouri, State of 83/05/17 12pp 18587 156 24X Fiche 50-483,83/05/20,8305250294

--8305250548 Affidavit of WK Johnson re Reed Contention 17 on radiological monitoring State resources in trained personnel & radiation monitoring equipment adequate Prof qualifications encl
JOHNSON,W K Union Electric Co JOHNSON,W K Missouri, State of 83/05/13 6pp 18587 168 24X Fiche 50-483,83/05/20,8305250294

--8305250552 Affidavit of NG Slaten re Reed Contention 17 on radiological monitoring Util radiological emergency organization includes extensive radiological monitoring capability & resources Prof qualifications encl
SLATEN,N G Union Electric Co 83/05/16 23pp 18587 174 24X Fiche 50-483,83/05/20,8305250294

--8305250553 Motion for summary disposition of Reed Contention 18 re human food & animal feeds No genuine issue of matl fact exists & applicant entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 15pp 18587 197 24X Fiche 50-483,83/05/20,8305250294

--8305250557 Statement of matl fact as to which there is no genuine issue re Reed Contention 18 on human food & animal feeds
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 212 24X Fiche 50-483,83/05/20,8305250294

--8305250559 Motion for summary disposition of Reed Contention 19 re impediments to use of evacuation routes No genuine issue of matl fact exists & util entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 22pp 18587 214 24X Fiche 50-483,83/05/20,8305250294

--8305250562 Statement of matl fact as to which there is no genuine issue re Reed Contention 19 on impediments to use of evacuation routes
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 236 24X Fiche 50-483,83/05/20,8305250294

--8305250566 Affidavit of RG Wright re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments
WRIGHT,R G Union Electric Co WRIGHT,R A Callaway County, MO 83/05/17 7pp 18587 238 24X Fiche 50-483,83/05/20,8305250294

--8305250573 Affidavit of G Epple re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments
EPPLE,G Union Electric Co EPPLE,G Gasconade County, MO
83/05/16 4pp 18587 245 24X Fiche 50-483,83/05/20,8305250294

--8305250576 Affidavit of VB Eldringhoff re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments
ELDRINGHOFF,V Union Electric Co ELDRINGHOFF,V Montgomery County, MD 83/05/14 7pp 18587 249 24X Fiche 50-483, 83/05/20,8305250294

--8305250580 Affidavit of H Matthews re Reed Contention 19 on impediments to use of evacuation routes Resources & planning efforts available to overcome impediments
MATTHEWS,H Union Electric Co MATTHEWS,H Affiliation Unknown
83/05/16 3pp 18587 256 24X Fiche 50-483,83/05/20,8305250294

--8305250583 Motion for summary disposition of Reed Contention 20 re authorization of excess radiological worker exposures & spec of decontamination action levels No genuine issue of matl fact exists & util entitled to favorable decision
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 12pp 18587 259 24X Fiche 50-483,83/05/20,8305250294

--8305250584 Statement of matl fact as to which there is no genuine issue re Reed Contention 20 on authorization of excess radiological worker exposures & spec of decontamination action levels
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge 83/05/20 Atomic Safety and Licensing Board Panel 2pp 18587 271 24X Fiche 50-483,83/05/20,8305250294

--8305250587 Affidavit of WM Clark re Reed Contention 20 on authorization of excess exposures to workers & spec of decontamination action levels Planning need for authorization per NUREG-0654,Section III E 3,met Prof qualifications encl
CLARK,W M Union Electric Co CLARK,W M Callaway County, MO
83/05/18 7pp 18587 273 24X Fiche 50-483,83/05/20,8305250294

--8305250589 Affidavit of JW Baer re Reed Contention 20 on authorization of excess radiological worker exposures & spec of decontamination action levels Certificate of Svc & prof qualifications encl
BAER,J W Union Electric Co BAER,J W Energy Consultants, Inc
83/05/18 67pp 18587 280 24X Fiche 50-483,83/05/20,8305250294

8305260168 Forwards corrected Certificate of Svc certifying svc of documents on 830520 Original certificate date incorrect
BAXTER,T A Shaw, Pittman, Potts & Trowbridge BAXTER,T A Union Electric Co 83/05/23 GLEASON,J P , BRIGHT,G O , KLINE,J R Atomic Safety and Licensing Board Panel 1p 18599 273 24X Fiche 50-483,83/05/23,8305260168

--8305260173 Corrected Certificate of Svc certifying svc of documents on 830520
BAXTER,T A Union Electric Co 83/05/20 9pp 18599 274 24X Fiche 50-483,83/05/23,8305260168

8305260164 Advises that TA Baxter will represent util at 830622 oral argument in response to Joint Intervenors appeal
BAXTER,T A Shaw, Pittman, Potts & Trowbridge. BAXTER,T A Union Electric Co 83/05/24 TOMPKINS,B A Atomic Safety and Licensing Appeal Panel 1p 18599 283 24X Fiche 50-483,83/05/24,8305260164

8305310170 Advises that table of contents & table of cross-refs to NUREG-0654 planning stds/evaluation criteria adequate to locate portions relevant to contentions Referenced portions of plans listed
BAXTER T A Shaw, Pittman, Potts & Trowbridge 83/05/26 REED,J.G Affiliation Unknown 7pp 18652 326 24X Fiche 50-483,83/05/26, 8305310170

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc.
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8305030469 Forwards IE Integrated Designed Insp Rept 50-483/82-22 on 821110-19 & 29-1214
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 83/04/04 SCHNELL,D F Union Electric Co 5pp.
18295,183 24X Fiche 50-483,83/04/04,8305030469

--8305030474 IE Integrated Design Insp Rept 50-483/82-22 on 821110-19 & 29-1214 Noncompliance noted no formal control over Bechtel plant design newsletters & ability of motor controllers to withstand fault currents not considered
ALLISON,D P , NORKIN,D P , FAIR,J R Director's Office, Office of Inspection and Enforcement 83/03/31 114pp 18295 189 24X Fiche 50-483,83/04/04,8305030469

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021.

8305020350 Forwards IE Insp Rept 50-483/83-02 on 830223-24 to 0314-17 & notice of violation
SPESSARD,R L Division of Engineering 83/04/18 SCHNELL,D F Union Electric Co 2pp 18274 107 24X Fiche 50-483,83/04/18, 8305020350

--8305020354 Notice of violation from insp on 830223-24 to 0314-17
SPESSARD,R L Division of Engineering 83/04/18 1p. 18274:109 24X Fiche 50-483,83/04/18,8305020350

--8305020357 IE Insp Rept 50-483/83-02 on 830223-24 to 0314-17. Noncompliance noted failure to include design document limits & precautions in Safety Injection Accumulator Preoperational Test Procedure CS-03EP01
WOHLD,P R , RING,M A , REYES,L A Region 3, Office of Director
83/04/18 5pp 18274 110 24X Fiche 50-483,83/04/18,8305020350.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs." Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28. Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305030258 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-21.
SPESSARD,R L Region 3, Office of Director 83/04/28 SCHNELL,D F Union Electric Co 1p 18300 034 24X Fiche 50-483,83/04/28, 8305030258

--8305030263 Responds to NRC 830308 ltr re violations noted in IE Insp Rept 50-483/82-21 Corrective actions:scaffolding immediately removed from load ctrs Visual insp of load ctrs after scaffolding removed revealed no damage
SCHNELL,D F. Union Electric Co 83/04/08 LITTLE,W S Region 3, Office of Director 3pp 18300 035 24X Fiche 50-483,83/04/28, 8305030258

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03. Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche.50-000,83/05/03,8303040028.

8305060284 Ack receipt of 830413 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-20
SPESSARD,R L Division of Engineering 83/05/03 SCHNELL,D F. Union Electric Co 1p 18344 325 24X Fiche 50-483,83/05/03, 8305060284

--8305060293 Responds to NRC 830315 ltr re violations noted in IE Insp Rept 50-483/82-20 Corrective actions component support checklist revised,hanger insp underway,revised insp procedures implemented & training sessions will be held.
SCHNELL,D F Union Electric Co 83/04/13. LITTLE,W S. Region 3, Office of Director 6pp 18344 326 24X Fiche 50-483,83/05/03, 8305060284

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305170130 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-21
SPESSARD,R L Division of Engineering 83/05/09 SCHNELL,D F Union Electric Co 1p 18466 261 24X Fiche 50-483,83/05/09, 8305170130

--8305170136 Responds to NRC 830308 ltr re violations noted in IE Insp Rept 50-483/82-21 Corrective actions test program to confirm max sidewall pressure values & contact w/vendor to verify validity of max values in progress
SCHNELL,D F Union Electric Co 83/05/04 LITTLE,W S Region 3, Office of Director 3pp 18466 262 24X Fiche 50-483,83/05/09, 8305170130

8305170182 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-09 Extension of compliance date to 830801 acceptable
SPESSARD,R L Division of Engineering 83/05/09 SCHNELL,D F Union Electric Co 1p 18466 324 24X Fiche 50-483,83/05/09, 8305170182

--8305170188 Responds to NRC 820917 ltr re violations noted in IE Insp Rept 50-483/82-09 Extension to 830801 to complete rebar scanning activities requested
SCHNELL,D F Union Electric Co 83/04/29 NORELIUS,C E Division of Engineering 1p 18466 325 24X Fiche 50-483,83/05/09,8305170182

8305170222 Ack receipt of 830427 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/82-14
SPESSARD,R L Division of Engineering 83/05/09 SCHNELL,D F Union Electric Co 1p 18466 346 24X Fiche 50-483,83/05/09, 8305170222

--8305170227 Responds to NRC 830329 ltr re violations noted in IE Insp Rept 50-483/82-14 Corrective actions complete walkdown performed on all outside area bldgs,fuel bldg & other fire-rated openings
SCHNELL,D F Union Electric Co 83/04/27 LITTLE,W S Region 3, Office of Director 3pp 18466 347 24X Fiche 50-483,83/05/09, 8305170222

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8305200512 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-483/83-03
NORELIUS,C E Division of Project & Resident Programs 83/05/13
SCHNELL,D F Union Electric Co 1p. 18516 088 24X
Fiche 50-483,83/05/13,8305200512

--8305200518 Responds to NRC 830331 ltr re violations noted in IE Insp Rept 50-483/83-03 Corrective actions damaged & missing matl replaced & cable 1SBY09CA pulled out & replaced w/new cable per approved Disposition 28D-9973-E
SCHNELL,D F Union Electric Co 83/04/29 NORELIUS,C E Division of Project & Resident Programs 3pp. 18516,089 24X Fiche 50-483,83/05/13,8305200512

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8304150354 Part 21 Rept U-48 & interim deficiency rept re GE ARR-30 & AKR-50 circuit breakers Initially reported on 830211 Assessment of safety implications & corrective actions requested of AE Final rept expected by 830429
SCHNELL,D F Union Electric Co 83/04/07 SPESSARD,R L Division of Project & Resident Programs 1p 17982 128 24X
Fiche 50-000,83/04/07,8304150354

8305020073 Final Deficiency Rept SDR 83-06 re Anchor/Darling check valves failing to close Initially reported on 830323 Caused by improper design Hinge pins replaced & Stellite 6 bushings to be installed
SEIKEN,S J Standardized Nuclear Unit Power Plant System 83/04/20 KEPPLER,J G Region 3, Office of Director COLLINS,J T Region 4, Office of Director 2pp 18279 100 24X Fiche 50-000,83/04/20, 8305020073

8305020133 Supplemental Part 21 Rept 6 re possible thermostatic valve malfunction fail-safe to full cooling position Lower overrun assemblies in Robertshaw valves on diesel generator sets replaced w/assemblies using cotter pins
MORIARTY,J M Colt Industries, Inc 83/04/21 KEPPLER,J G Region 3, Office of Director 1p 18278 219 24X Fiche 50-483,83/04/21, 8305020133

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305030467 Forwards Daniel Const Co summary of relevant events & corrective actions re potential respnsible deficiency in testing of candidates for QC inspector certification Certificate of Svc encl
BAXTER,T A Shaw, Pittman, Potts & Trowbridge BAXTER,T A Union Electric Co 83/04/28 ROSENTHAL,A S , EDLES,G J , GOTCHY,R L Atomic Safety and Licensing Appeal Panel 8pp 18292 166 24X
Fiche 50-483,83/04/28,8305030467

8305040430 Final Significant Deficiency Rept 83-05 re GE AKR 30 & 50 electrically operated low voltage circuit breakers Initially reported on 830211 Field rework plan will be issued to effect necessary breaker repairs
SEIKEN,S Standardized Nuclear Unit Power Plant System 83/04/28 KEPPLER,J G Region 3, Office of Director COLLINS,T T Region 4, Office of Director 8pp 18319 319 24X Fiche 50-000,83/04/28, 8305040430

DOCKET STN-50-491 CHEROKEE NUCLEAR STATION, UNIT 1

S Reportable occurrences, LERs & related correspondence

8305030374 PNO-II-83-031 on 830429,Unit 1 cancellation announced Caused by lower than anticipated growth in customer demand for power
IGNATONIS,A , DANCE,H C Region 2, Office of Director 83/04/29
2pp 18306 302 24X Fiche 50-491,83/04/29,8305030374

DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18427 153 24X
Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026.

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18497 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON, J M Division of Rules and Records 83/03/09 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X Fiche 50-000, 83/03/09, 8305180001

--8005140296 Responds to 800418 memo re concrete voiding Discusses status of problems & repairs
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/25 BRADFORD, P A Commissioners 3pp 18499 139 24X Fiche 50-000, 83/03/09, 8305180001

--8006090443 Forwards WA Post article re harassment of QC personnel Lack of enforcement action questioned
BRADFORD, P A Commissioners 79/10/10 STELLO, V Office of Inspection & Enforcement, Office of the Director 2pp 18497 237 24X Fiche 50-000, 83/03/09, 8305180001

--8008120773 Forwards outlines of JF Ahearne & V Stello proposed testimony re facility before House Subcommittee on Oversight & Investigation
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/11 AHEARNE, J F , GILINSKY, V , HENDRIE, J Commissioners 6pp 18499 163 24X Fiche 50-000, 83/03/09, 8305180001

--8010090450 Forwards draft Commission info paper re plan for resumption of const Comments or concurrences needed by 800912 W/o encl
THORNBURG, H D Division of Reactor Construction Inspection 80/09/11 DENTON, H R Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director
STELLO, V Office of Inspection & Enforcement, Office of the Director 9pp 18499 222 24X Fiche 50-000, 83/03/09, 8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE, J F Commissioners 5pp 18497 228 24X Fiche 50-000, 83/03/09, 8305180001

--8010280581 Assigns questions resulting from 800923 Eckhardt hearing
AHEARNE, J F Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193 24X Fiche 50-000, 83/03/09, 8305180001

--8305180121 Requests info re scope & significance of voids in concrete at site Response requested by 800423
BRADFORD, P A Commissioners. 80/04/18 DIRCKS, W J Office of the Executive Director for Operations 1p 18499 138 24X Fiche 50-000, 83/03/09, 8305180001

--8305180148 Advises that staff should notify Commission in advance of proposed actions re facility investigation, per Commissioner Bradford 800418 memo
CHILK, S J Office of the Secretary of the Commission 80/04/28
DIRCKS, W J Office of the Executive Director for Operations 1p 18499 142. 24X Fiche 50-000, 83/03/09, 8305180001.

--8305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility
KAMMERER, C Office of Congressional Affairs 80/07/09
AHEARNE, J F , GILINSKY, V , HENDRIE, J M Commissioners 2pp 18499 157 24X Fiche 50-000, 83/03/09, 8305180001

--8305180236 Submits schedule of Congressional hearings re waste bill H R 7418, West Valley Bill H R 6865 & South Texas project Related info encl
REHM, T A Office of the Executive Director for Operations 80/07/07 STELLO, V Office of Inspection & Enforcement, Office of the Director DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 4pp 18499 159 24X Fiche 50-000, 83/03/09, 8305180001

--8305180250 Forwards Chairman Ahearne & V Stello testimony prepared for House Subcommittee on Oversight & Investigation hearing re facility
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/25 AHEARNE, J F GILINSKY, V , HENDRIE, J M Commissioners 2pp 18499 169 24X Fiche 50-000, 83/03/09, 8305180001

--8305180315 Forwards Part 2 of Commission regulations re practice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl
BURNS, S G Office of the Executive Legal Director 80/05/29
CORTEZ, B Communities Organized for Public Service 1p 18499 218 24X Fiche 50-000, 83/03/09, 8305180001

--8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickwit, general counsel
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS, W J Office of the Executive Director for Operations 11pp 18499 231 24X Fiche 50-000, 83/03/09, 8305180001

--8305180337 Discusses importance of NASLAP decision re protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants
THOMPSON, D Enforcement & Investigation Staff (Pre 820201) 81/05/14 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 1p 18499 244 24X Fiche 50-000, 83/03/09, 8305180001

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305310177 Forwards licensing review schedule Submittal of first comprehensive update of FSAR scheduled for 830701 Review of updated issues requested
GOLDBERG, J H Houston Lighting & Power Co 83/05/17 EISENHUT, D G Division of Licensing 6pp 18659 037 24X Fiche 50-498, 83/05/17, 8305310177

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X Fiche 50-000, 83/05/13, 8305240213

G Adjudicatory correspondence

8305020434 Motion to compel Citizens Concerned About Nuclear Power answers to applicant 830328 seventh set of interrogatories & requests for production of documents No response received Certificate of Svc encl
NEWMAN, J R Joint Applicants-South Texas Project NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 83/04/27 Atomic Safety and Licensing Board Panel 5pp 18281 213 24X Fiche 50-498, 83/04/27, 8305020434

8305060499 Response to State of TX atty general 830421 request for extension of discovery schedule for 90 days Applicants do not object to extension for TX but object to extension for other parties Certificate of Svc encl
NEWMAN, J R Joint Applicants-South Texas Project 83/05/03 Atomic Safety and Licensing Board Panel 4pp 18348 108 24X Fiche 50-498, 83/05/03, 8305060499

8305060274 Order extending time until 830523 for Commission to act to review 830303 Director's decision
CHILK,S J Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 023 24X Fiche 50-498,83/05/05,
8305060274

8305110225 Response in opposition to Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension of deadlines until 830617 CCANP has failed to show good cause for requested deferrals W/Certificate of Svc
NEWMAN,J R Houston Lighting & Power Co NEWMAN,J R Lowenstein, Newman, Reis, Axelrad & Toll 83/05/05 Atomic Safety and Licensing Board Panel 8pp 18407 068 24X Fiche 50-498,83/05/05,
8305110225

8305090143 Response opposing Atty General of TX 830421 motion for 90-day extension of discovery until 830725 State of TX failed to take full advantage of available discovery period Certificate of Svc encl
PERLIS,R G Hearing Branch 3 83/05/06 Atomic Safety and Licensing Board Panel 5pp 18364 044 24X Fiche 50-498,83/05/06,
8305090143

8305110339 Response opposing Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension until 830617 Time to reply to applicant interrogatories may be extended until 830522 Certificate of Svc encl
PERLIS,R G Hearing Branch 3 83/05/10 Atomic Safety and Licensing Board Panel 6pp 18406 148 24X Fiche 50-498,83/05/10,
8305110339

8305130045 Memorandum & order ruling on Citizens Concerned About Nuclear Power 830420 motions Extensions granted until 830531 to respond to various filings
BECHHOEFER,C Atomic Safety and Licensing Board Panel 83/05/11
Citizens Concerned About Nuclear Power, Inc 4pp 18436 335 24X Fiche 50-498,83/05/11,8305130045

8305200511 Memorandum & order granting Atty General of State of TX 830421 motion for extension of discovery deadline until 90 days from svc of order Effective participation by State in resolution of Quadrex Rept issues warrants addl time.
BECHHOEFER,C Atomic Safety and Licensing Board Panel 83/05/18
Texas, State of 5pp 18516 103 24X Fiche 50-498,83/05/18,
8305200511

8305260176 Order extending time until 830530 for Commission to act to review 830303 Director's decision
CHILK,S J Office of the Secretary of the Commission. 83/05/23
Commissioners 1p 18599 271 24X Fiche 50-498,83/05/23,
8305260176

8305310015 Order extending time until 830606 for Commission to act to review 830303 Director's decision
CHILK,S J Office of the Secretary of the Commission 83/05/27
Commissioners 1p 18653 220 24X Fiche 50-498,83/05/27,
8305310015

K Utility Final Safety Analysis Report (FSAR) & amends

8305250056 Forwards Amend 31 to FSAR Amend reflects changes to HVAC design
GOLDBERG,J H Houston Lighting & Power Co 83/05/20 DENTON,H Office of Nuclear Reactor Regulation, Director 3pp 18591 168 24X Fiche 50-498,83/05/20,8305250056

--8305250058 Amend 31 to FSAR
GOLDBERG,J H Houston Lighting & Power Co 83/05/20. 221pp 18591 171 24X Fiche 50-498,83/05/20,8305250056

G Inspection reports, IE Bulletins & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root,Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497·219 24X Fiche:50-000,83/03/09,8305180001

--7908080036 Forwards matl re allegations of harassment & intimidation per 790524 request
THOMPSON,D Executive Officer for Operations Support. 79/06/12
FORTUNA,R A Office of Inspector & Auditor 8pp. 18499 196 24X Fiche 50-000,83/03/09,8305180001

--8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is awaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/11 AHEARNE,J , GILINSKY,V , KENNEDY,R Commissioners 175pp 18498 304 24X Fiche 50-000,83/03/09,
8305180001

--8006090238 Responds to 800421 request that IE interview former site QC inspectors Of 69 persons identified,23 contacted
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/13 BRADFORD,P A Commissioners 3pp 18499 149 24X Fiche 50-000,83/03/09,8305180001

--8006090440 Responds to 791010 memo re enforcement action against Brown & Root Enforcement package complete No enforcement action taken previously since earlier insps did not substantiate allegations
STELLO,V. Office of Inspection & Enforcement, Office of the Director, 80/05/15 BRADFORD,P A Commissioners 2pp. 18499 155 24X Fiche 50-000,83/03/09,8305180001

--8009120352 Advises that Region 4 should assume responsibility for review & verification of corrective actions by licensee as followup action associated w/South Texas problems Headquarters will be responsible for monitoring reviews.
THORNBURG,H D Division of Reactor Construction Inspection
80/06/24 SEYFRIT,K V Region 4, Dallas, Office of the Director 3pp 18499 219. 24X Fiche·50-000,83/03/09,8305180001.

--8103250385 Summarizes events re 810317 telcon w/L Sinkin concerning allegations at facility Improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged
WILBER,H A Reactor Projects Sections (Regions 2,4 & 5).
81/03/17 SEYFRIT,K.V Region 4, Dallas, Office of the Director. 2pp 18499 242 24X Fiche 50-000,83/03/09,8305180001

--8305180064 Responds to Gossick request to reply to inquiry re adequacy of QA/QC program Licensee continuing to look for addl voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners
STELLO,V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY,R T. Commissioners 3pp 18497·234 24X Fiche.50-000,83/03/09,8305180001

--8305180075 Responds to Commissioner Bradford 791019 inquiry re newspaper article concerning facility insps "Surprise insp" announced IE insp of facility QA program Allegations re beating of QC inspector could not be substantiated
HUBACEK,W G Region 4, Dallas, Office of the Director 79/10/26
REINMUTH,G N Division of Reactor Construction Inspection. 2pp. 18497 239 24X Fiche 50-000,83/03/09,8305180001

--8305180083 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barber/Thompson
REINMUTH,G W Division of Reactor Construction Inspection.
79/11/02 SEIDLE,W.C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 18497 241. 24X
Fiche 50-000,83/03/09,8305180001

--8305180094 Discusses recommendations for further IE investigation & insp efforts at facilities Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established Related info encl
HAYES,D W Region 3, Chicago, Office of the Director 80/03/11.
THORNBURG,H D. Division of Reactor Construction Inspection
421pp 18497 243 24X Fiche 50-000,83/03/09,8305180001.

--8305180157 Forwards enforcement package including enforcement notice, draft press release, forwarding ltr, notice of violation, proposed imposition of civil penalty & show cause order. W/o encls
STELLO,V. Office of Inspection & Enforcement, Office of the Director 80/04/28 AHEARNE,J.F , GILINSKY,V., KENNEDY,R T Commissioners 1p 18499 143 24X Fiche.50-000,83/03/09,
8305180001.

--8305180167 Informs that Commission concensus not in favor of recommendations contained in 800418 memo re facility investigation.Modified version of Suggestion 1 further modified by Commissioner Kennedy Responses encl.W/o encls.
CHILK,S J Office of the Secretary of the Commission. 80/04/28.
BRADFORD,P A. Commissioners. 1p 18499·144. 24X
Fiche 50-000,83/03/09,8305180001

--8305180175 Recommends that IE address Ofc of General Counsel Questions 1-7 prior to enforcement action IE will take action on 800501
BRADFORD,P A Commissioners 80/04/30. AHEARNE,J.F.
Commissioners 1p 18499;145 24X Fiche·50-000,83/03/09,
8305180001.

--8305180181 Discusses results of followup inquires by Region IV re terminated Brown & Root,Inc QC civil engineer inspectors
SEYFRIT,R V Region 4, Dallas, Office of the Director 80/04/30
DEYOUNG,R C Office of Inspection & Enforcement, Office of the Director 2pp 18499 146 24X Fiche 50-000,83/03/09,8305180001

--8305180189 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Questions 1-7 prior to time of enforcement action
CHILK,S J Office of the Secretary of the Commission 80/05/02
BRADFORD,P A Commissioners 1p 18499 148 24X
Fiche 50-000,83/03/09,8305180001

--8305180202 Informs of new allegations concerning possible intimidation of QC inspectors received while preparing response to 791010 memo Investigation will be conducted to verify facts Appropriate enforcement action will be taken
STELLO,V Office of Inspection & Enforcement, Office of the Director 83/03/09 BRADFORD,P A Commissioners 1p
18499 152 24X Fiche 50-000,83/03/09,8305180001

--8305180211 Responds to 791010 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of alleged beating of Brown & Root QC inspector Allegation could not be substantiated
STELLO,V Office of Inspection & Enforcement, Office of the Director 83/03/09 BRADFORD,P A Commissioners 2pp
18499 153 24X Fiche 50-000,83/03/09,8305180001

--8305180276 Forwards draft Commission info paper intended for presentation during wk of 800414 re investigation & proposed enforcement action Comments needed by 800409
THORNBURG,H D Division of Reactor Construction Inspection 80/04/03 DENTON,H R Office of Nuclear Reactor Regulation, Director BHAPAR,H K Office of the Executive Legal Director
STELLO,V Office of Inspection & Enforcement, Office of the Director 11pp 18499 204 24X Fiche 50-000,83/03/09,8305180001

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
112pp. 18308,319, 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp, 18382 165 24X Fiche 50-000,83/04/28,8303040027,

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030,

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305170212 Forwards IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1983 No noncompliance noted
MADSEN,G L Region 4, Office of Director 83/05/04 OPREA,G W
Houston Lighting & Power Co 2pp 18467 001 24X
Fiche 50-498,83/05/04,8305170212

--8305170224 IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1983 No noncompliance noted Major areas inspected storage & maint of equipment,IE bulletins & notices,const deficiency repts,electrical sys,structural concrete & QA/QC procedures
HILL,W H , CROSSMAN,W A Region 4, Office of Director 83/05/03
18pp 18467 003 24X Fiche 50-498,83/05/04,8305170212

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

B Reportable occurrences, LERs & related correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root,Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N
Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000,83/03/09,8305180001

--7909180214 Requests views re adequacy of QA/QC program in light of PNO-79-179, "Voids in Reactor Containment Wall "
KENNEDY,R T. Commissioners 79/06/25 GOSSICK,L V Office of the Executive Director for Operations 1p 18497 233 24X
Fiche 50-000,83/03/09,8305180001

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000,83/04/21,8305110427

8305060456 Final deficiency rept re incorrect motor operator weights used in stress analyses of valves supplied by Anchor Darling Valve Co.Initially reported on 820629 Stress analysis for valve MS-143 will be reperformed using actual weight
OPREA,G W Houston Lighting & Power Co 83/04/27 COLLINS,J T.
Region 4, Office of Director 4pp 18351 156 24X
Fiche 50-498,83/04/27,8305060456

8305170510 Sixth interim deficiency rept re nonconforming welds in vendor fabricated Category I structural steel Initially reported on 810108 Review & evaluation program in progress Next rept will be submitted by Sept 1983
OPREA,G W Houston Lighting & Power Co 83/05/10 COLLINS,J T
Region 4, Office of Director 3pp 18470 015 24X
Fiche: 50-498,83/05/10,8305170510

8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513 Bolting parts greater than 2-inch size not examined
HOVI,L NPB Industries, Inc 83/05/16 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 18574 001 24X
Fiche 50-000,83/05/16,8305240356

8305230416 Interim deficiency rept re voltage regulation problem for large motors on 480-volt Class IE load ctrs Initially reported on 830419.Bechtel evaluating corrective actions. Next rept will be submitted by 830630
OPREA,G W Houston Lighting & Power Co 83/05/18 COLLINS,J T
Region 4, Office of Director 3pp 18538,232 24X
Fiche: 50-498,83/05/18,8305230416

8305230525 Final deficiency rept re Westinghouse reactor trip switchgear undervoltage attachments w/design discrepancy Initially reported on 830422 Attachments replaced Mfg drawings & QC procedures modified Also reported per Part 21
OPREA, G W Houston Lighting & Power Co 83/05/18 COLLINS, J T Region 4, Office of Director 4pp 18936 319 24X Fiche 50-498, 83/05/18, 8305230525

T Hearing transcripts on non-antitrust matters

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON, J M Division of Rules and Records 83/03/09 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X Fiche 50-000, 83/03/09, 8305180001

--8305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5
AHEARNE, J F Commissioners 80/07/29 6pp 18499 171 24X Fiche 50-000, 83/03/09, 8305180001

--8305180257 Statement of V Stello before House Subcommittee on Oversight & Investigations 800729 hearing Pp 1-15
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 18499 177 24X Fiche 50-000, 83/03/09, 8305180001

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON, J M Division of Rules and Records 83/03/09 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X Fiche 50-000, 83/03/09, 8305180001

--8005140296 Responds to 80041B memo re concrete voiding Discusses status of problems & repairs
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/25 BRADFORD, P A Commissioners 3pp 18499 139 24X Fiche 50-000, 83/03/09, 8305180001

--8006090443 Forwards WA Post article re harassment of QC personnel Lack of enforcement action questioned
BRADFORD, P A Commissioners 79/10/10 STELLO, V Office of Inspection & Enforcement, Office of the Director 2pp 18497 237 24X Fiche 50-000, 83/03/09, 8305180001

--8008120773 Forwards outlines of JF Ahearne & V Stello proposed testimony re facility before House Subcommittee on Oversight & Investigation
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/11 AHEARNE, J F, GILINSKY, V, HENDRIE, J Commissioners 6pp 18499 163 24X Fiche 50-000, 83/03/09, 8305180001

--8010090450 Forwards draft Commission info paper re plan for resumption of const Comments or concurrences needed by 800912 W/o encl
THORNBURG, H D Division of Reactor Construction Inspection, 80/09/11 DENTON, H R Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director STELLO, V Office of Inspection & Enforcement, Office of the Director 9pp 18499 222 24X Fiche 50-000, 83/03/09, 8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE, J F Commissioners, 5pp, 18497 228 24X Fiche 50-000, 83/03/09, 8305180001

--8010280581 Assigns questions resulting from 800923 Eckhardt hearing
AHEARNE, J F Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193 24X Fiche 50-000, 83/03/09, 8305180001.

--8305180121 Requests info re scope & significance of voids in concrete at site Response requested by 800423
BRADFORD, P A Commissioners. 80/04/18 DIRCKS, W J Office of the Executive Director for Operations 1p 18499 138 24X Fiche 50-000, 83/03/09, 8305180001

--8305180148 Advises that staff should notify Commission in advance of proposed actions re facility investigation, per Commissioner Bradford 800418 memo
CHILK, S J Office of the Secretary of the Commission 80/04/28 DIRCKS, W J Office of the Executive Director for Operations. 1p 18499 142 24X Fiche 50-000, 83/03/09, 8305180001

--8305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility
KAMMERER, C Office of Congressional Affairs 80/07/09 AHEARNE, J F, GILINSKY, V, HENDRIE, J M Commissioners 2pp 18499 157 24X Fiche 50-000, 83/03/09, 8305180001

--8305180236 Submits schedule of Congressional hearings re waste bill H R 7418, West Valley Bill H R 6865 & South Texas project Related info encl
REHM, T A Office of the Executive Director for Operations 80/07/07 STELLO, V Office of Inspection & Enforcement, Office of the Director DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 4pp 18499 159 24X Fiche 50-000, 83/03/09, 8305180001

--8305180250 Forwards Chairman Ahearne & V Stello testimony prepared for House Subcommittee on Oversight & Investigation hearing re facility
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/25 AHEARNE, J F, GILINSKY, V, HENDRIE, J M Commissioners 2pp 18499 169 24X Fiche 50-000, 83/03/09, 8305180001

--8305180315 Forwards Part 2 of Commission regulations re practice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl
BURNS, S G Office of the Executive Legal Director 80/05/29 CORTEZ, B Communities Organized for Public Service 1p 18499 218 24X Fiche 50-000, 83/03/09, 8305180001

--8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickwit, general counsel.
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS, W J. Office of the Executive Director for Operations 11pp. 18499 231 24X Fiche 50-000, 83/03/09, 8305180001

--8305180337 Discusses importance of NASLAP decision re protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants
THOMPSON, D Enforcement & Investigation Staff (Pre 820201) 81/05/14 GRIER, B H Region 1, Philadelphia, Office of the Director (81/03/01) O'REILLY, J P Region 2, Atlanta, Office of the Director (81/03/01). KEPPLER, J G Region 3, Chicago, Office of the Director (81/03/01) 1p 18499 244 24X Fiche 50-000, 83/03/09, 8305180001

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305310177 Forwards licensing review schedule Submittal of first comprehensive update of FSAR scheduled for 830701. Review of updated issues requested.
GOLDBERG, J H Houston Lighting & Power Co 83/05/17. EISENHUT, D. G Division of Licensing 6pp 18659 037. 24X Fiche 50-498, 83/05/17, 8305310177

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits, Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp. 18540 095. 24X Fiche 50-000, 83/05/11, 8305110034

Q Adjudicatory correspondence

8305020434 Motion to compel Citizens Concerned About Nuclear Power answers to applicant 830328 seventh set of interrogatories & requests for production of documents No response received. Certificate of Svc encl.
NEWMAN, J R Joint Applicants-South Texas Project NEWMAN, J. R Lowenstein, Newman, Reis, Axelrad & Toll, 83/04/27 Atomic Safety and Licensing Board Panel 5pp 18281 213 24X Fiche 50-498, 83/04/27, 8305020434

8305060499 Response to State of TX atty general 830421 request for extension of discovery schedule for 90 days Applicants do not object to extension for TX but object to extension for other parties Certificate of Svc encl
NEWMAN, J R Joint Applicants-South Texas Project 83/05/03
Atomic Safety and Licensing Board Panel 4pp 18348 108 24X
Fiche 50-498, 83/05/03, 8305060499

8305060274 Order extending time until 830523 for Commission to act to review 830303 Director's decision
CHILK, S J Office of the Secretary of the Commission 83/05/05
Commissioners 1p 18345 023 24X Fiche 50-498, 83/05/05,
8305060274

8305110225 Response in opposition to Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension of deadlines until 830617 CCANP has failed to show good cause for requested deferrals W/Certificate of Svc
NEWMAN, J R Houston Lighting & Power Co NEWMAN, J R Lowenstein, Newman, Reis, Axelrad & Toll 83/05/05 Atomic Safety and Licensing Board Panel 8pp 18407 068 24X Fiche 50-498, 83/05/05,
8305110225

8305090143 Response opposing Atty General of TX 830421 motion for 90-day extension of discovery until 830725 State of TX failed to take full advantage of available discovery period Certificate of Svc encl
PERLIS, R G Hearing Branch 3 83/05/06 Atomic Safety and Licensing Board Panel 5pp 18364 044 24X Fiche 50-498, 83/05/06,
8305090143

8305110339 Response opposing Citizens Concerned About Nuclear Power (CCANP) 830420 motion for deferral of rulings & extension until 830617 Time to reply to applicant interrogatories may be extended until 830522 Certificate of Svc encl
PERLIS, R G Hearing Branch 3 83/05/10 Atomic Safety and Licensing Board Panel 6pp 18406 148 24X Fiche 50-498, 83/05/10,
8305110339.

8305130045 Memorandum & order ruling on Citizens Concerned About Nuclear Power 830420 motions Extensions granted until 830531 to respond to various filings
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/11
Citizens Concerned About Nuclear Power, Inc 4pp 18436:335 24X
Fiche 50-498, 83/05/11, 8305130045

8305200511 Memorandum & order granting Atty General of State of TX 830421 motion for extension of discovery deadline until 90 days from svc of order Effective participation by State in resolution of Quadrex Rept issues warrants addl time
BECHHOEFER, C Atomic Safety and Licensing Board Panel 83/05/18
Texas, State of 5pp 18516 103 24X Fiche 50-498, 83/05/18,
8305200511

8305260176 Order extending time until 830530 for Commission to act to review 830303 Director's decision
CHILK, S J Office of the Secretary of the Commission 83/05/23
Commissioners. 1p. 18599 271 24X Fiche 50-498, 83/05/23,
8305260176.

8305310015 Order extending time until 830606 for Commission to act to review 830303 Director's decision
CHILK, S J Office of the Secretary of the Commission 83/05/27
Commissioners 1p 18653 220 24X Fiche, 50-498, 83/05/27,
8305310015

K. Utility Final Safety Analysis Report (FSAR) & amends

8305250056 Forwards Amend 31 to FSAR Amend reflects changes to HVAC design
GOLDBERG, J H Houston Lighting & Power Co 83/05/20 DENTON, H
Office of Nuclear Reactor Regulation, Director 3pp 18591 168
24X Fiche 50-498, 83/05/20, 8305250056

--8305250058 Amend 31 to FSAR
GOLDBERG, J H Houston Lighting & Power Co 83/05/20. 221pp.
18591 171 24X Fiche 50-498, 83/05/20, 8305250056

O Inspection reports, IE Bulletins & correspondence

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project. Forwards App B documents Documents also available in PDR Addl documents undergoing review.
FELTON, J M. Division of Rules and Records 83/03/09 LINDEMAN, H N
Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497:219. 24X
Fiche 50-000, 83/03/09, 8305180001

--7908080036 Forwards matl re allegations of harassment & intimidation per 790524 request
THOMPSON, D Executive Officer for Operations Support 79/06/12
FORTUNA, R A Office of Inspector & Auditor 8pp 18499 196 24X
Fiche 50-000, 83/03/09, 8305180001

--8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is awaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/11 AHEARNE, J , GILINSKY, V , KENNEDY, R
Commissioners 175pp 18498 304 24X Fiche 50-000, 83/03/09,
8305180001

--8006090238 Responds to 800421 request that IE interview former site QC inspectors Of 69 persons identified, 23 contacted
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/13 BRADFORD, P A Commissioners 3pp
18499 149 24X Fiche 50-000, 83/03/09, 8305180001

--8006090440 Responds to 791010 memo re enforcement action against Brown & Root Enforcement package complete No enforcement action taken previously since earlier insps did not substantiate allegations
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/05/15. BRADFORD, P A Commissioners 2pp
18499 155 24X Fiche 50-000, 83/03/09, 8305180001

--8103250385 Summarizes events re 810317 telcon w/L Sinkin concerning allegations at facility Improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged
WILBER, H A Reactor Projects Sections (Regions 2, 4 & 5)
81/03/17 SEYFRIT, K V Region 4, Dallas, Office of the Director
2pp 18499 242 24X Fiche 50-000, 83/03/09, 8305180001

--8305180064 Responds to Gossick request to reply to inquiry re adequacy of QA/QC program Licensee continuing to look for addl voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners
STELLO, V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY, R T Commissioners 3pp
18497 234 24X Fiche 50-000, 83/03/09, 8305180001

--8305180075 Responds to Commissioner Bradford 791019 inquiry re newspaper article concerning facility insps "Surprise insp" announced IE insp of facility QA program Allegations re beating of QC inspector could not be substantiated
HUBACEK, W G Region 4, Dallas, Office of the Director 79/10/26
REINMUTH, G N Division of Reactor Construction Inspection 2pp
18497 239. 24X Fiche 50-000, 83/03/09, 8305180001

--8305180083 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barber/Thompson
REINMUTH, G W Division of Reactor Construction Inspection
79/11/02 SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 18497 241 24X
Fiche 50-000, 83/03/09, 8305180001

--8305180094 Discusses recommendations for further IE investigation & insp efforts at facilities. Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established Related info encl
HAYES, D W Region 3, Chicago, Office of the Director 80/03/11
THORNBURG, H D Division of Reactor Construction Inspection
421pp 18497 243 24X Fiche 50-000, 83/03/09, 8305180001

--8305180157 Forwards enforcement package including enforcement notice, draft press release, forwarding ltr, notice of violation, proposed imposition of civil penalty & show cause order W/o encls
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/04/28 AHEARNE, J. F , GILINSKY, V , KENNEDY, R T
Commissioners 1p 18499 143 24X Fiche 50-000, 83/03/09,
8305180001

--8305180167 Informs that Commission concensus not in favor of recommendations contained in 800418 memo re facility investigation Modified version of Suggestion 1 further modified by Commissioner Kennedy Responses encl W/o encls
CHILK, S J Office of the Secretary of the Commission 80/04/28
BRADFORD, P A Commissioners 1p 18499 144 24X
Fiche 50-000, 83/03/09, 8305180001

--8305180175 Recommends that IE address Ofc of General Counsel Questions 1-7 prior to enforcement action IE will take action on 800501
BRADFORD, P. A Commissioners 80/04/30 AHEARNE, J F
Commissioners 1p 18499 145 24X Fiche 50-000, 83/03/09,
8305180001

--8305180181 Discusses results of followup inquires by Region IV re terminated Brown & Root, Inc QC civil engineer inspectors
SEYFRIT, K V Region 4, Dallas, Office of the Director 80/04/30
DEYOUNG, R C Office of Inspection & Enforcement, Office of the Director 2pp 18499 146 24X Fiche 50-000, 83/03/09, 8305180001

--8305180189 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Questions 1-7 prior to time of enforcement action
CHILK, S J Office of the Secretary of the Commission 80/05/02
BRADFORD, P A Commissioners 1p 18499.148 24X
Fiche 50-000, 83/03/09, 8305180001

--8305180202 Informs of new allegations concerning possible intimidation of QC inspectors received while preparing response to 791010 memo Investigation will be conducted to verify facts Appropriate enforcement action will be taken
STELLO, V Office of Inspection & Enforcement, Office of the Director 83/03/09 BRADFORD, P A Commissioners 1p 18499 152 24X Fiche 50-000, 83/03/09, 8305180001

--8305180211 Responds to 791010 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of alleged beating of Brown & Root QC inspector Allegation could not be substantiated
STELLO, V Office of Inspection & Enforcement, Office of the Director 83/03/09 BRADFORD, P A Commissioners 2pp 18499 153 24X Fiche, 50-000, 83/03/09, 8305180001

--8305180276 Forwards draft Commission info paper intended for presentation during wk of 800414 re investigation & proposed enforcement action Comments needed by 800409
THORNBURG, H D Division of Reactor Construction Inspection 80/04/03 DENTON, H R Office of Nuclear Reactor Regulation, Director SHAPAR, H K Office of the Executive Legal Director
STELLO, V Office of Inspection & Enforcement, Office of the Director 11pp 18499 204, 24X Fiche 50-000, 83/03/09, 8305180001

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21, Consolidated Edison Co of New York, Inc.
112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co, of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 112pp 18383.089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382 282, 24X Fiche, 50-000, 83/05/04, 8303040030.

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8305170212 Forwards IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1983 No noncompliance noted
MADSEN, G L Region 4, Office of Director 83/05/04 OPREA, G.W
Houston Lighting & Power Co 2pp 18467 001 24X
Fiche 50-498, 83/05/04, 8305170212

--8305170224 IE Insp Repts 50-498/83-06 & 50-499/83-06 during Mar 1983 No noncompliance noted. Major areas inspected storage & maint of equipment, IE bulletins & notices, const deficiency repts, electrical sys, structural concrete & QA/QC procedures.
HILL, W H ; CROSSMAN, W A Region 4, Office of Director 83/05/03
18pp 18467 003 24X Fiche 50-498, 83/05/04, 8305170212

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche, 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co. of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised.
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R C.
Director's Office, Office of Inspection and Enforcement 5pp
18405·095 24X Fiche, 50-000, 83/04/21, 8305110427

8305060456 Final deficiency rept re incorrect motor operator weights used in stress analyses of valves supplied by Anchor Darling Valve Co Initially reported on 820629 Stress analysis for valve MS-143 will be reperformed using actual weight
OPREA, G W Houston Lighting & Power Co. 83/04/27 COLLINS, J. T.
Region 4, Office of Director 4pp 18351 156 24X
Fiche 50-498, 83/04/27, 8305060456

8305170510 Sixth interim deficiency rept re nonconforming welds in vendor fabricated Category I structural steel. Initially reported on 810108 Review & evaluation program in progress Next rept will be submitted by Sept 1983
OPREA, G W Houston Lighting & Power Co 83/05/10 COLLINS, J T
Region 4, Office of Director 3pp 18470 015 24X
Fiche 50-498, 83/05/10, 8305170510.

8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513. Bolting parts greater than 2-inch size not examined.
HOVI, L NPS Industries, Inc 83/05/16 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 1p 18574:001. 24X
Fiche 50-000, 83/05/16, 8305240356

8305230416 Interim deficiency rept re voltage regulation problem for large motors on 480-volt Class IE load ctrs Initially reported on 830419. Bechtel evaluating corrective actions Next rept will be submitted by 830630
OPREA, G W. Houston Lighting & Power Co 83/05/18 COLLINS, J T.
Region 4, Office of Director. 3pp 18538 232 24X
Fiche 50-498, 83/05/18, 8305230416.

8305230525 Final deficiency rept re Westinghouse reactor trip switchgear undervoltage attachments w/design discrepancy Initially reported on 830422 Attachments replaced. Mfg drawings & QC procedures modified Also reported per Part 21.
OPREA, G W Houston Lighting & Power Co 83/05/18 COLLINS, J T
Region 4, Office of Director 4pp. 18536 319 24X
Fiche, 50-498, 83/05/18, 8305230525.

T Hearing transcripts on non-antitrust matters

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root, Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON, J M Division of Rules and Records 83/03/09 LINDEMAN, H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X
Fiche 50-000, 83/03/09, 8305180001

--8305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5
AHEARNE, J F Commissioners 80/07/29 6pp 18499 171 24X
Fiche 50-000, 83/03/09, 8305180001

--8305180257 Statement of V Stello before House Subcommittee on Oversight & Investigations 800729 hearing Pp 1-15
STELLO, V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 18499 177 24X Fiche 50-000, 83/03/09, 8305180001

DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J. Commissioners 2pp 18542 272 24X
Fiche: 50-000, 83/04/11, 8305230720

DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche: 50-000, 83/04/11, 8305230720

DOCKET STN-50-502 HAVEN NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

A Application/construction stage documents & correspondence

8305100097 Forwards responses to NRC acceptance review questions for Mar 1983, Marked-up FSAR pages which show changes to be included in subsequent amend also encl W/two oversize figures Aperture cards are available in PDR
BOUCHEY, G D Washington Public Power Supply System 83/04/20
KNIGHTON, G W Licensing Branch 3 6pp 18371 339 24X
Fiche, 50-508, 83/04/20, 8305100097

8305110018 Summary of 830419 meeting w/util in Bethesda, MD re discussion on program plan for control room design review
WHEELER, L Licensing Branch 3 83/04/20 Licensing Branch 3
3pp. 18415 059 24X Fiche 50-508, 83/04/20, 8305110018

8305230155 Forwards second set of requests for addl info re safety review Responses should be forwarded no later than 830712 Draft SER will be prepared to provide basis for series of meetings designed to close out open items.
NOVAK, T M Assistant Director for Licensing 83/05/03
FERGUSON, R L Washington Public Power Supply System 42pp
18577 207 24X Fiche 50-508, 83/05/03, 8305230155

8305100304 Discusses responses to NRC 820625 & 0730 questions re usage of ITT Grinnell pipe clamps Response to 820914 questions delayed pending minor clamp mods & retesting program Meeting suggested to insure closure of issue
BOUCHEY, G D Washington Public Power Supply System 83/05/05
KNIGHTON, G W Licensing Branch 3 2pp 18371 251 24X
Fiche 50-508, 83/05/05, 8305100304

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305230155 Forwards second set of requests for addl info re safety review Responses should be forwarded no later than 830712 Draft SER will be prepared to provide basis for series of meetings designed to close out open items
NOVAK, T M Assistant Director for Licensing 83/05/03
FERGUSON, R L Washington Public Power Supply System 42pp
18577 207 24X Fiche 50-508, 83/05/03, 8305230155

8305260205 Forwards request for addl info re safety review Response requested by 830712 Draft SER will be prepared to close out open items
NOVAK, T M Assistant Director for Licensing 83/05/11
FERGUSON, R L Washington Public Power Supply System 17pp
18648 048 24X Fiche 50-508, 83/05/11, 8305260205

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations
83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X
Fiche 50-000, 83/05/13, 8305240213

G Adjudicatory correspondence

8305060491 Joint util, NRC & Coalition for Safe Power recommended schedule for submission of proposed contentions & subsequent responsive filings & for time & place for holding prehearing conference Certificate of Svc encl
REYNOLDS, N S Washington Public Power Supply System REYNOLDS, N S Debevoise & Liberman 83/05/05 5pp 18348 144 24X
Fiche 50-508, 83/05/05, 8305060491

8305130110 Notice of ASLB reconstitution MB Margulies, chairman & FJ Shon & JH Carpenter, members
COTTER, D P Atomic Safety and Licensing Board Panel 83/05/11
2pp 18437 358 24X Fiche 50-508, 83/05/11, 8305130110

8305170483 Memorandum & order scheduling 830803-04 special prehearing conference in Montesano, WA Addl schedule dates listed
MARGULIES, M B Atomic Safety and Licensing Board Panel 83/05/16
2pp 18470 073 24X Fiche 50-508, 83/05/16, 8305170483

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc
11Pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8305130116 Notification of 830523 significant licensee meeting w/util in Walnut Creek, CA to discuss licensee efforts to increase owner involvement in quality issues, actions taken to improve design control & status of sys completion
* Region 5, Office of Director 83/04/05 Region 5, Office of Director 1p 18438 008 24X Fiche 50-508, 83/04/05, 8305130116

8305170384 Forwards IE Insp Rept 50-508/83-03 on 830314-17 & notice of deviation
STERNBERG, D M Region 5, Office of Director 83/04/08
LEDDICK, R S Washington Public Power Supply System 2pp
18469 216 24X Fiche 50-508, 83/04/08, 8305170384

--8305170387 Notice of deviation from insp on 830314-17
DODDS,R T Region 5, Office of Director 83/04/08 1p
18469 218 24X Fiche 50-508,83/04/08,8305170384

--8305170390 IE Insp Rept 50-508/83-03 on 830314-17 Noncompliance noted failure to qualify weld procedure in accordance w/AWS D 1 1 requirements
HAIST,D P , BURDOIN,J F , DODDS,R T Region 5, Office of Director 83/04/07 8pp 18469 219 24X Fiche 50-508,83/04/08,8305170384

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305170494 Forwards IE Insp Rept 50-508/83-05 on 830328-0427 No noncompliance noted
STERNBERG,D M Region 5, Office of Director 83/05/04
LEDDICK,R S Washington Public Power Supply System 1p 18470 025 24X Fiche 50-508,83/05/04,8305170494

--8305170498 IE Insp Rept 50-508/83-05 on 830328-0427 No noncompliance noted Major areas inspected const activities,including exam of welding for safety-related pipe supports & restraints & installation of core internals
ALBERT,W G , DODDS,R T Region 5, Office of Director 83/05/04
9pp 18470 026 24X Fiche 50-508,83/05/04,8305170494

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009. 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305160049 Supplemental final deficiency rept re safety injection tank safe-end indications (D/N 23) Safe-end-to-nozzle-welds for injection tanks reradiographed,approved & accepted per spec & ASME Code requirements
LEDDICK,R S Washington Public Power Supply System 83/04/06
STERNBERG,D M Region 5, Office of Director 2pp 18453 130. 24X Fiche 50-508,83/04/06,8305160049

8305030489 Final deficiency rept re Rockbestos insulated cable Type D60-1 Initially reported on 821203 Dented cable to be reworked to restore cable to original specified thickness Deficiency determined not reportable under 10CFR50.55(e)
LEDDICK,R S Washington Public Power Supply System 83/04/20
STERNBERG,D M Region 5, Office of Director 3pp 18294 147 24X Fiche 50-508,83/04/20,8305030489

DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4

S Reportable occurrences, LERs & related correspondence

8305100094 PNB-V-83-006 on 830504,article in Tri-City Herald erroneously quoted util spokesman J Britton as saying 1,700 or 1,800 craft workers will be asked to take vacations during 830705-15 or be laid off Util will clarify
MORTENSEN,W P , NORDERHAUG,L R Region 5, Office of Director. 83/05/05 1p 18377 261 24X Fiche 50-513,83/05/05,8305100094

DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095. 24X Fiche 50-000,83/05/11,8305110034

P Operating license stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153. 24X Fiche 50-000,83/05/09,8305090659

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155. 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche.50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche.50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095. 24X Fiche 50-000,83/05/11,8305110034

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction." Svc list encl
TAYLOR,J.M Division of Safeguards & Inspection Programs (Post 830103). 83/03/21 Consolidated Edison Co of New York, Inc 112pp. 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co. of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305100189 Forwards "Details of Deferral Plans for Hartsville Nuclear Plant A " Yellow Creek plan submittal delayed until 830513
MILLS,L M Tennessee Valley Authority 83/05/05. DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18374.294. 24X Fiche 50-518,83/05/05,8305100189

--8305100193 "Details of Deferral Plans for Hartsville Nuclear Plant A "
* Tennessee Valley Authority 83/05/31 9pp 18374 295 24X Fiche 50-518,83/05/05,8305100189

G. Inspection reports, IE Bulletins & correspondence

8305270468 Forwards IE Insp Repts 50-518/83-01,50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/25. PARRIS,H G. Tennessee Valley Authority 2pp 18644 147 24X Fiche 50-518,83/03/25,8305270468

--8305270496 IE Insp Repts 50-518/83-01,50-519/83-01,50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units),independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2)
SCHAPKER,J F , CANTRELL,F S Region 2, Office of Director 83/03/24 5pp 18644 149 24X Fiche 50-518,83/03/25,8305270468

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T
Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

Q Inspection reports, IE Bulletins & correspondence

8305270468 Forwards IE Insp Repts 50-518/83-01,50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/25
PARRIS,H G Tennessee Valley Authority 2pp 18644 147 24X
Fiche 50-518,83/03/25,8305270468

--8305270496 IE Insp Repts 50-518/83-01,50-519/83-01,50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units),independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2)
SCHAPKER,J F , CANTRELL,F S Region 2, Office of Director,
83/03/24 5pp 18644 149 24X Fiche 50-518,83/03/25,8305270468

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T
Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

A Application/construction stage documents & correspondence

8305100189 Forwards "Details of Deferral Plans for Hartsville Nuclear Plant A " Yellow Creek plan submittal delayed until 830513
MILLS,L M Tennessee Valley Authority 83/05/05 DENTON,H R
Office of Nuclear Reactor Regulation, Director 1p 18374 294. 24X
Fiche 50-518,83/05/05,8305100189

--8305100193 "Details of Deferral Plans for Hartsville Nuclear Plant A "
* Tennessee Valley Authority 83/05/31 9pp 18374 295. 24X
Fiche 50-518,83/05/05,8305100189

Q Inspection reports, IE Bulletins & correspondence

8305270468 Forwards IE Insp Repts 50-518/83-01,50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/25.
PARRIS,H G Tennessee Valley Authority 2pp 18644 147. 24X
Fiche 50-518,83/03/25,8305270468

--8305270496 IE Insp Repts 50-518/83-01,50-519/83-01,50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units),independent insp effort (A-1 & A-2) & site deferral preparation (A-1 & A-2)
SCHAPKER,J F , CANTRELL,F S Region 2, Office of Director
83/03/24 5pp 18644 149 24X Fiche:50-518,83/03/25,8305270468

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T
Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

Q Inspection reports, IE Bulletins & correspondence

8305270468 Forwards IE Insp Repts 50-518/83-01,50-519/83-01, 50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted
VERRELLI,D M Division of Project & Resident Programs 83/03/25
PARRIS,H G Tennessee Valley Authority 2pp 18644 147 24X
Fiche 50-518,83/03/25,8305270468

--8305270496 IE Insp Repts 50-518/83-01,50-519/83-01,50-520/83-01 & 50-521/83-01 on 821120-830218 No noncompliance noted Major areas inspected open items (all units),independent insp effort (A-1 & A-2),& site deferral preparation (A-1 & A-2).
SCHAPKER,J F Region 2, Office of Director 83/03/24 5pp.
18644 149 24X Fiche 50-518,83/03/25,8305270468

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl. Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R.
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C. Rockwell International Corp 83/03/11 COLLINS,J.T.
Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

DOCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl.
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co. of New York, Inc. 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

O Adjudicatory correspondence

8305170272 Motion for summary disposition of Contention 1 re calculation of demand for electrical energy negating need for plant,No genuine issue of matl fact exists
CAVANAGH,R Natural Resources Defense Council CAVANAGH,R.
Coalition for Safe Power CAVANAGH,R Columbia River Inter-Tribal Fish Commission 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 061. 24X Fiche:50-522,83/05/12,8305170272

8305170279 Statement of matl facts as to which there is no genuine issue re Contention 1
CAVANAGH,R Natural Resources Defense Council 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 327 24X Fiche 50-522,83/05/12,8305170279

8305170347 Memorandum of points & authorities supporting intervenor motion for summary disposition since Contention 1 no longer controversial issue Certificate of Svc encl
CAVANAGH,R Natural Resources Defense Council 83/05/12 Atomic Safety and Licensing Board Panel 14pp 18469 008 24X Fiche 50-522,83/05/12,8305170347

8305170557 Affidavit of DB Goldstein supporting NRDC motion for summary disposition of Contention 1 re need for power Four forecasts for energy needs refute need for power justification developed by util Prof qualifications encl
GOLDSTEIN,D B Natural Resources Defense Council 83/05/12 81pp 18468 040 24X Fiche 50-522,83/05/12,8305170557

8305310029 Requests current suspension of federal & state licensing proceedings continue until mid-Sept 1983 to consider licensing alternatives
THOMSEN,F T Perkins, Coie, Stone, Olsen & Williams THOMSEN,F T Puget Sound Power & Light Co 83/05/25 WOLF,J F , LEWIS,N D Atomic Safety and Licensing Board Panel 3pp 18653 127 24X Fiche 50-522,83/05/25,8305310029

8305310082 Request for extension until 830930 to answer NRDC motion for summary disposition of Contention 1 Time needed to consider implications of final northwest conservation electric power, plan & licensing alternatives Certificates of Svc encl
THOMSEN,F T. Puget Sound Power & Light Co THOMSEN,F T Perkins, Coie, Stone, Olsen & Williams 83/05/25 Atomic Safety and Licensing Board Panel 8pp 18658 040 24X Fiche 50-522,83/05/25, 8305310082

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/04/28 Consolidated Edison Co of New York, Inc. 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche,50-000,83/04/28,8303040027,

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co. of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co. of New York, Inc 112pp 18382,282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

O Adjudicatory correspondence

8305170272 Motion for summary disposition of Contention 1 re calculation of demand for electrical energy negating need for plant No genuine issue of matl fact exists
CAVANAGH,R Natural Resources Defense Council CAVANAGH,R Coalition for Safe Power CAVANAGH,R Columbia River Inter-Tribal Fish Commission 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 041 24X Fiche 50-522,83/05/12,8305170272

8305170279 Statement of matl facts as to which there is no genuine issue re Contention 1
CAVANAGH,R Natural Resources Defense Council 83/05/12 Atomic Safety and Licensing Board Panel 2pp 18465 327 24X Fiche 50-522,83/05/12,8305170279

8305170347 Memorandum of points & authorities supporting intervenor motion for summary disposition since Contention 1 no longer controversial issue Certificate of Svc encl
CAVANAGH,R Natural Resources Defense Council 83/05/12 Atomic Safety and Licensing Board Panel 14pp 18469 008 24X Fiche 50-522,83/05/12,8305170347

8305170557 Affidavit of DB Goldstein supporting NRDC motion for summary disposition of Contention 1 re need for power Four forecasts for energy needs refute need for power justification developed by util Prof qualifications encl
GOLDSTEIN,D.B Natural Resources Defense Council 83/05/12 81pp 18468 040 24X Fiche 50-522,83/05/12,8305170557

8305310029 Requests current suspension of federal & state licensing proceedings continue until mid-Sept 1983 to consider licensing alternatives
THOMSEN,F T Perkins, Coie, Stone, Olsen & Williams. THOMSEN,F T Puget Sound Power & Light Co 83/05/25 WOLF,J F , LEWIS,N D Atomic Safety and Licensing Board Panel 3pp 18653 127 24X Fiche 50-522,83/05/25,8305310029

8305310082 Request for extension until 830930 to answer NRDC motion for summary disposition of Contention 1 Time needed to consider implications of final northwest conservation electric power plan & licensing alternatives Certificates of Svc encl
THOMSEN, F T Puget Sound Power & Light Co THOMSEN, F T Perkins, Coie, Stone, Olsen & Williams 83/05/25 Atomic Safety and Licensing Board Panel 8pp 18658 040 24X Fiche 50-522, 83/05/25, 8305310082

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptability to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305030013 Forwards NRC comments on C-E Owners Group study re depressurization & DHR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision
NOVAK, T M Assistant Director for Licensing 83/04/20 VAN BRUNT, E E Arizona Public Service Co 4pp 18310 349 24X Fiche 50-528, 83/04/20, 8305030013

8305110022 Summary of 830406-07 meetings w/util & Bechtel at site re NRC power sys site audit findings Agenda encl
LICITRA, E A Licensing Branch 3 83/05/03 Licensing Branch 3 7pp 18415 066 24X Fiche 50-528, 83/05/03, 8305110022

8305230003 Forwards request for addl info re 830322 proposed rev to Table 3 2-1 of FSAR Rev deleting commitment to apply QA program to certain items during operations phase w/o justification
KNIGHTON, G W Licensing Branch 3 83/05/03 VAN BRUNT, E E Arizona Public Service Co 4pp 18541 352 24X Fiche 50-528, 83/05/03, 8305230003

--8305230004 Suggests that encl request for addl info be transmitted to applicant Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 QA program during operations phase
HAASS, W P QA Branch 83/04/26 KNIGHTON, G W Licensing Branch 3 6pp 18541 356 24X Fiche 50-528, 83/05/03, 8305230003

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT, D G Division of Licensing 83/05/04 PALLADINO, N , GILINSKY, V , ROBERTS, T M Commissioners 22pp 18337 139. 24X Fiche 50-000, 83/05/04, 8305040323

8305170219 Forwards summary of 830407 meeting w/util in Bethesda, MD re draft procedures generation package for emergency procedures
LICITRA, E A Licensing Branch 3 83/05/06 Licensing Branch 3 2pp 18476 343 24X Fiche 50-528, 83/05/06, 8305170219

--8305170225 Summary of 830428 meeting w/util in Bethesda, MD re draft procedures generation package for emergency procedures
GOODMAN, M J Procedures & Systems Review Branch 83/04/28, CLAYTON, H B Procedures & Systems Review Branch 4pp 18476 345 24X Fiche 50-528, 83/05/06, 8305170219

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000, 83/05/09, 8305090659

8305240038 Requests schedule for submittal of addl info needed in order to resolve remaining FSAR items prior to decision on OL issuance Response requested within 2 wks of receipt of ltr
KNIGHTON, G W Licensing Branch 3 83/05/09 VAN BRUNT, E E Arizona Public Service Co 7pp 18594 294 24X Fiche 50-528, 83/05/09, 8305240038

8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda, MD to present results of independent QA evaluation & discuss status of corrective actions
LICITRA, E A Licensing Branch 3 83/05/10 KNIGHTON, G W Licensing Branch 3 3pp 18593 300 24X Fiche 50-528, 83/05/10, 8305240253

8305160071 Forwards application for amend to CPPR-141, requesting extension of const completion date from 830831 to 1231 Class II fee encl
VAN BRUNT, E E Arizona Public Service Co 83/05/12 Office of Nuclear Reactor Regulation, Director 2pp 18453 029 24X Fiche 50-528, 83/05/12, 8305160071

--8305160072 Application for amend to CPPR-141, requesting extension of const completion date from 830831 to 1231
VAN BRUNT, E E Arizona Public Service Co 83/05/12 4pp 18453 031 24X Fiche 50-528, 83/05/12, 8305160071

8305200417 Justifies rev to FSAR Section 1 8 re exception to Reg Guide 1 38 storage requirements for fission chamber detectors & sealed sources, in response to Jan 1983 request
VAN BRUNT, E E Arizona Public Service Co 83/05/18 KNIGHTON, G Licensing Branch 3 2pp 18517 162 24X Fiche 50-528, 83/05/18, 8305200417

8305310161 Notifies that util will provide plant-specific info re depressurization & DHR capabilities by 830731, instead of previous schedule date of 830930
VAN BRUNT, E E Arizona Public Service Co 83/05/24 KNIGHTON, G Licensing Branch 3 2pp 18652 345 24X Fiche 50-528, 83/05/24, 8305310161

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305230273 Confirms requests for info identified in discussions w/util re analysis of Sys 80 fuel design under combined seismic & LOCA loads & protection against low temp overpressure event per SER open item
KNIGHTON, G W Licensing Branch 3 83/05/04 VAN BRUNT, E E Arizona Public Service Co 3pp 18543 265 24X Fiche 50-528, 83/05/04, 8305230273

8305120385 Forwards RCS pressure temp (P-T) curves requested in Section 5 3 2 of SER (NUREG-0857) P-T curves will be submitted as part of final Tech Spec submission Submittal resolves issue
VAN BRUNT, E E Arizona Public Service Co 83/05/09 KNIGHTON, G Licensing Branch 3 4pp 18433 120 24X Fiche 50-528, 83/05/09, 8305120385

F. Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X Fiche 50-000, 83/05/13, 8305240213

8305200322 Advises that installation of source range neutron flux monitor, per 10CFR50, App R, Section III L, will be accomplished by end of first refueling outage
VAN BRUNT, E E Arizona Public Service Co 83/05/17 KNIGHTON, G Licensing Branch 3 6pp 18516 294 24X Fiche 50-528, 83/05/17, 8305200322

G Adjudicatory correspondence

8305200488 Advises that time for Commission to review ALAB-713 expired Commission declined review Decision became final agency action on 830427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners
CHILK, S J Office of the Secretary of the Commission 83/05/19, Office of the Executive Legal Director 1p 18514 039 24X Fiche 50-528, 83/05/19, 8305200488

8305310215 Requests opportunity to respond to West Valley Agricultural Protection Council 830506 supplemental motion re FES - OL stage & to argue relevancy if ASLB determines that consideration should be given
GEHR, A C Snell & Wilmer GEHR, A C Arizona Public Service Co 83/05/23 LAZO, R M , CALLIHAN, D , COLE, R F Atomic Safety and Licensing Board Panel 5pp 18658 137 24X Fiche 50-528, 83/05/23, 8305310215

K Utility Final Safety Analysis Report (FSAR) & amends

8305020089 Forwards Amend 11 to FSAR
VAN BRUNT, E E Arizona Public Service Co 83/04/28, Office of Nuclear Reactor Regulation, Director 2pp 18274 123 24X Fiche 50-528, 83/04/28, 8305020089

--8305020092 Amend 11 to FSAR W/47 oversize figures Aperture cards are available in PDR
* Arizona Public Service Co. 83/04/30 806pp. 18274 125 24X Fiche 50-528, 83/04/28, 8305020089

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptability to Exothermic Chemical Reaction," Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8305030302 Notification of 830502 enforcement conference w/util in Walnut Creek, CA
* Region 5, Office of Director 83/04/20 Region 5, Office of Director 1p 18301 352 24X Fiche 50-528, 83/04/20, 8305030302

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305170531 Forwards IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance noted
CREWS, J L Division of Resident, Reactor Project & Engineering Programs 83/04/22 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 001 24X Fiche 50-528, 83/04/22, 8305170531

--8305170537 IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 Noncompliance noted improper documentation of cable termination records
ECKHARDT, J H , VORDERBRUEGGEN, ELIN, J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-528, 83/04/22, 8305170531

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170560 Forwards IE Insp Repts 50-528/83-09, 50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/04/25 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 128 24X Fiche 50-528, 83/04/25, 8305170560

--8305170564 IE Insp Repts 50-528/83-09, 50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted Major areas inspected allegations made by R Gunderson & W Royce in affidavits before ASLB on 830108 & 0225
VORDERBRUEGGEN, FIORELLI, G , BURDOIN, J Region 5, Office of Director 83/04/22 14pp 18468 130 24X Fiche 50-528, 83/04/25, 8305170560

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8305260319 Ack receipt of 830404 & 22 ltrs informing NRC of steps taken to correct violations noted in IE insp on 830104-07 & 17-21
STERNBERG, D M Region 5, Office of Director 83/05/03 VAN BRUNT, E E Arizona Public Service Co 1p 18625 007 24X Fiche 50-528, 83/05/03, 8305260319

--8305260321 Responds to NRC 830302 ltr re violations noted in IE insp on 830104-07 & 17-21. Corrective actions 6-inches of pipe & weld replaced Listed supports installed on 830323 per Design Change Package 1-SS-RD-013
VAN BRUNT, E E Arizona Public Service Co 83/04/04
STERNBERG, D M Region 5, Office of Director 6pp 18625 008 24X Fiche 50-528, 83/05/03, 8305260319

--8305260326 Revises 830404 response to IE insp re unauthorized undocumented weld Alleger did not claim to have knowledge of any other incidents
VAN BRUNT, E E Arizona Public Service Co 83/04/22
STERNBERG, D M Region 5, Office of Director 4pp 18625 014 24X Fiche 50-528, 83/05/03, 8305260319

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl.
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8305170377 Forwards IE Insp Rept 50-528/83-13 on 830321-0429 No noncompliance noted
STERNBERG,D M Region 5, Office of Director 83/05/04
ANDOGNINI,G C Arizona Public Service Co 2pp 18470 128 24X
Fiche 50-528,83/05/04,8305170377

--8305170382 IE Insp Rept 50-528/83-13 on 830321-0429 No noncompliance noted Major areas inspected startup testing,maint,fuel receipt & reactor coolant pump repairs
FIORELLI,G , JOHNSTON,G , YOUNG,T. Region 5, Office of Director 83/05/04 6pp 18470 130 24X Fiche 50-528,83/05/04,8305170377

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160008 Notification of 830525 meeting w/util & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/05/10 Region 5, Office of Director 2pp 18456 079 24X Fiche 50-528,83/05/10,8305160008

8305160089 Confirms 830525 meeting w/applicant at Deer Valley Project ofc to discuss SALP for Jul 1981 - Feb 1983
CREWS,J L Division of Resident,Reactor Project & Engineering Programs 83/05/10 VAN BRUNT,E E Arizona Public Service Co 3pp. 18448 146 24X Fiche 50-528,83/05/10,8305160089

--8305160179 SALP rept for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528,83/05/10,8305160089

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl.
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040.

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030626 Interim Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power. Initially reported on 830318 Final rept by 830519
VAN BRUNT,E E Arizona Public Service Co 83/04/15 STERNBERG,D M Region 5, Office of Director 3pp 18303 339 24X
Fiche 50-528,83/04/15,8305030626

8305030285 Final Deficiency Rept DER 82-84 re internal damage to Class IE load ctrs by space heaters Initially reported on 830127 Deficiency not reportable under 10CFR50 55(e) Space heaters being supplied w/correct voltage
VAN BRUNT,E E Arizona Public Service Co 83/04/19. STERNBERG,D M Region 5, Office of Director 4pp 18300 080 24X
Fiche 50-528,83/04/19,8305030285

8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection switches failure to meet requirements of TMI Task 18A Initially reported on 830304 Info will not be finalized until 830519,due to extensive investigation.
VAN BRUNT,E.E Arizona Public Service Co 83/04/21. STERNBERG,D M Region 5, Office of Director 1p 18440,093 24X
Fiche 50-528,83/04/21,8305130229

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11. COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

8305130183 Interim Deficiency Rept DER 82-51 re Pullman-Kellogg pipe line failure in essential cooling water sys Initially reported on 820910 Submittal of final rept delayed until 830531 due to extensive evaluation required
VAN BRUNT,E E Arizona Public Service Co 83/04/26 STERNBERG,D M. Region 5, Office of Director 2pp 18439 345 24X
Fiche 50-528,83/04/26,8305130183

8305130127 Final Deficiency Rept DER 83-4 re failure of Waldinger test procedures for air handling units to meet ANSI N510 requirements Initially reported on 830126 Condition determined not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/27 STERNBERG,D M Region 5, Office of Director 6pp 18437 271 24X
Fiche 50-528,83/04/27,8305130127

8305130169 Interim Deficiency Rept DER 82-53 re failure of Joy fan blade causing 2-inch penetration of containment liner plate. Initially reported on 820924 Submittal of final rept delayed until 830628 due to extensive investigation required
VAN BRUNT,E E Arizona Public Service Co 83/04/27 STERNBERG,D M Region 5, Office of Director 2pp. 18438 111 24X
Fiche 50-528,83/04/27,8305130169

8305130124 Deficiency Evaluation Rept 83-18 re installation of pipe supports which do not meet Seismic IX requirements Initially reported on 830329 Deficiency determined not reportable per 10CFR50 55(e) Documentation will be maintained in files
VAN BRUNT,E E Arizona Public Service Co 83/04/28. STERNBERG,D M. Region 5, Office of Director 2pp 18438.059 24X
Fiche 50-528,83/04/28,8305130124

8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 830406. Deficiency determined not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/29. STERNBERG,D M Region 5, Office of Director 2pp. 18437 185 24X
Fiche 50-528,83/04/29,8305130159

8305130210 Advises that Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co. 83/04/29 STERNBERG,D M Region 5, Office of Director 1p 18440 090 24X
Fiche 50-528,83/04/29,8305130210

8305130082 Final Deficiency Rept DER 82-62 re ESF actuation sys dc power supply ground detectors failing preoperational tests Initially reported on 821021. Item determined not reportable under 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 6pp 18436.273. 24X
Fiche 50-528,83/05/03,8305130082

8305130107 Final Deficiency Rept DER 83-2 re valve operators accidentally interchanged by Posi-Seal on inside & outside containment valves. Initially reported on 830125 Operators to be replaced Also reported per Part 21 by Posi-Seal
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M. Region 5, Office of Director 4pp. 18437 219. 24X
Fiche 50-528,83/05/03,8305130107

8305130148 Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements. Initially reported on 821124 Revised test plan reviewed by Bechtel Final rept expected by 830823. Also reported per Part 21.
VAN BRUNT,E E Arizona Public Service Co 83/05/03. STERNBERG,D M Region 5, Office of Director 4pp 18438.117 24X
Fiche 50-528,83/05/03,8305130148

8305130168 Interim Deficiency Rept DER 83-19 re Pacific Scientific safety injection sys snubber failure to function properly. Info will be finalized by 830801 Delay due to extensive investigation & evaluation.
VAN BRUNT,E E Arizona Public Service Co. 83/05/03 STERNBERG,D.M Region 5, Office of Director. 3pp 18438 101. 24X
Fiche 50-528,83/05/03,8305130168.

8305130189 Final Deficiency Rept DER 83-12 re malfunction of GE add-on electric interlocks used w/Class IE,Size 2,starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 5pp 18439 340 24X
Fiche 50-528,83/05/03,8305130189

8305130226 Rev 1 to Interim Deficiency Rept DER 82-80 re failure of Conax electrical penetration low level insulation resistance to meet qualification tests Initially reported on 821217 Testing in progress Next rept by 830914
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 3pp 18439 188 24X
Fiche 50-528,83/05/03,8305130226

8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Also reportable per 10CFR21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18439 238 24X
Fiche.50-528,83/05/03,8305130264

8305230517 Final Deficiency Rept DER 83-21 re operation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)
VAN BRUNT,E E. Arizona Public Service Co 83/05/06 STERNBERG,D M Region 5, Office of Director 2pp 18536 313 24X
Fiche 50-528,83/05/06,8305230517

DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305030013 Forwards NRC comments on C-E Owners Group study re depressurization & DHR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision
NOVAK,T M Assistant Director for Licensing 83/04/20 VAN BRUNT,E E Arizona Public Service Co 4pp 18310 349 24X
Fiche:50-528,83/04/20,8305030013

8305110022 Summary of 830406-07 meetings w/util & Bechtel at ..te re NRC power sys site audit findings Agenda encl
LICITRA,E A Licensing Branch 3 83/05/03 Licensing Branch 3
7pp 18415,066 24X Fiche 50-528,83/05/03,8305110022

8305230003 Forwards request for addl info re 830322 proposed rev to Table 3.2-1 of FSAR Rev deleting commitment to apply QA program to certain items during operations phase w/o justification
KNIGHTON,G W. Licensing Branch 3 83/05/03 VAN BRUNT,E.E.
Arizona Public Service Co 4pp 18541 352 24X
Fiche·50-528,83/05/03,8305230003

--8305230004 Suggests that encl request for addl info be transmitted to applicant.Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 QA program during operations phase
HAASS,W P QA Branch 83/04/26 KNIGHTON,G W Licensing Branch 3 6pp 18541·356 24X Fiche:50-528,83/05/03,8305230003

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17.
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N ,
GILINSKY,V , ROBERTS,T,M Commissioners 22pp 18337 139 24X
Fiche 50-000,83/05/04,8305040323

8305170219 Forwards summary of 830407 meeting w/util in Bethesda,MD re draft procedures generation package for emergency procedures
LICITRA,E A. Licensing Branch 3 83/05/06. Licensing Branch 3
2pp. 18476·343 24X Fiche·50-528,83/05/06,8305170219

--8305170225 Summary of 830428 meeting w/util in Bethesda,MD re draft procedures generation package for emergency procedures.
GOODMAN,M J Procedures & Systems Review Branch 83/04/28.
CLAYTON,H B Procedures & Systems Review Branch 4pp 18476:345
24X Fiche 50-528,83/05/06,8305170219

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods,Svc list encl
EISENHUT,D.G Division of Licensing 83/05/09 Consolidated Edison Co. of New York, Inc 16pp 18627 153 24X
Fiche:50-000,83/05/09,8305090659

8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda,MD to present results of independent QA evaluation & discuss status of corrective actions
LICITRA,E A Licensing Branch 3 83/05/10 KNIGHTON,G W
Licensing Branch 3 3pp 18593 300 24X Fiche 50-528,83/05/10,
8305240253

8305200417 Justifies rev to FSAR Section 1 8 re exception to Reg Guide 1 38 storage requirements for fission chamber detectors & sealed sources,in response to Jan 1983 request
VAN BRUNT,E E Arizona Public Service Co 83/05/18 KNIGHTON,G
Licensing Branch 3 2pp 18517 162 24X Fiche 50-528,83/05/18,
8305200417

8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants,w/emphasis on need for PORVs in current C-E designs
NOVAK,T M Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X
Fiche 50-000,83/05/18,8305250209

--8305250221 Requests that encl documents on status of DHR studies for C-E plants,w/emphasis on need for PORVs in current C-E designs,be provided to ASLB & ASLAB
MATTSON,R J Division of Systems Integration (post 811005)
83/04/28 EISENHUT,D G Division of Licensing 1p 18627 113
24X Fiche 50-000,83/05/18,8305250209

--8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630
DIRCKS,W J Office of the Executive Director for Operations
83/04/25 CHILK,S J Office of the Secretary of the Commission
1p 18627 115 24X Fiche 50-000,83/05/18,8305250209

8305310161 Notifies that util will provide plant-specific info re depressurization & DHR capabilities by 830731,instead of previous schedule date of 830930
VAN BRUNT,E E Arizona Public Service Co 83/05/24 KNIGHTON,G
Licensing Branch 3 2pp 18652 345 24X Fiche 50-528,83/05/24,
8305310161

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305230273 Confirms requests for info identified in discussions w/util re analysis of Sys 80 fuel design under combined seismic & LOCA loads & protection against low temp overpressure event per SER open item
KNIGHTON,G W Licensing Branch 3 83/05/04 VAN BRUNT,E E
Arizona Public Service Co 3pp 18543 265 24X
Fiche 50-528,83/05/04,8305230273

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305200322 Advises that installation of source range neutron flux monitor,per 10CFR50,App R,Section III L,will be accomplished by end of first refueling outage
VAN BRUNT,E E Arizona Public Service Co 83/05/17 KNIGHTON,G
Licensing Branch 3 6pp 18516 294 24X Fiche 50-528,83/05/17,
8305200322

G Adjudicatory correspondence

8305030594 Second set of nonuniform interrogatories Certificate of Svc encl Related correspondence
CRAWFORD,V A. Joint Applicants-Palo Verde CRAWFORD,V A Snell & Wilmer 83/04/27 West Valley Agricultural Protection Council, Inc. 56pp 18303 215 24X Fiche 50-529,83/04/27,8305030594

8305030498 Second set of interrogatories Certificate of Svc encl
DEWEY,L S Hearing Branch 3 83/04/29 West Valley Agricultural Protection Council, Inc 9pp 18295 109 24X Fiche 50-529,
83/04/29,8305030498

8305160080 Memorandum supporting West Valley Agricultural Protection Council,Inc supplemental motion for declaration that NEPA analysis inadequate & for continuance No attempt made to identify/analyze salt drifts W/Cetificate of Svc
BERLIN,K West Valley Agricultural Protection Council, Inc
BERLIN,K. Berlin, Roisman, Kessler & Cashdan 83/05/06 Atomic Safety and Licensing Board Panel 6pp 18450 120 24X
Fiche 50-529,83/05/06,8305160080

8305110268 Comments on format of Univ of Arizona agricultural productivity study methodology Methodology adequate for evaluating impacts of salt drift on representative agricultural crops
DEWEY, L S Hearing Branch 3 83/05/10 PLATT, W E Snell & Wilmer 3pp 18393 293 24X Fiche 50-529, 83/05/10, 8305110268

8305160032 Supplemental motion to 830202 motion for declaration that NEPA analysis inadequate & for continuance of proceedings Joint applicant responses to interrogatories lacked meaningful data on salt deposition
BERLIN, K West Valley Agricultural Protection Council, Inc 83/05/13 Atomic Safety and Licensing Board Panel 13pp 18453 149 24X Fiche 50-529, 83/05/13, 8305160032

8305160034 Motion for mod of ASLB 830323 discovery schedule, per 830309 stipulation on discovery Depositions scheduled for 830718 should be rescheduled for 830829 Discovery on Univ of Arizona crop study should begin on 831220
BERLIN, K West Valley Agricultural Protection Council, Inc 83/05/13 Atomic Safety and Licensing Board Panel 3pp 18456 089 24X Fiche 50-529, 83/05/13, 8305160034

8305160086 Memorandum supporting West Valley Agricultural Protection Council, Inc motion for discovery schedule Projected date for crop study completion 6 wks later than original date
BERLIN, K West Valley Agricultural Protection Council, Inc BERLIN, K Berlin, Roisman, Kessler & Cashdan 83/05/16 Atomic Safety and Licensing Board Panel 3pp 18451 024 24X Fiche 50-529, 83/05/16, 8305160086

8305240482 Joint Applicants response to West Valley Agricultural Protection Council second set of interrogatories
GEHR, A C , PLATT, W E , BISCHOFF, C A Snell & Wilmer 83/05/18 Atomic Safety and Licensing Board Panel 61pp 18572 252 24X Fiche 50-529, 83/05/18, 8305240482

8305200488 Advises that time for Commission to review ALAB-713 expired Commission declined review Decision became final agency action on 830427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners
CHILK, S J Office of the Secretary of the Commission 83/05/19 Office of the Executive Legal Director 1p 18514 039 24X Fiche 50-528, 83/05/19, 8305200488

8305310215 Requests opportunity to respond to West Valley Agricultural Protection Council 830506 supplemental motion re FES - OL stage & to argue relevancy if ASLB determines that consideration should be given
GEHR, A C Snell & Wilmer GEHR, A C Arizona Public Service Co 83/05/23 LAZO, R M , CALLIHAN, D , COLE, R F Atomic Safety and Licensing Board Panel 5pp 18658 137 24X Fiche 50-528, 83/05/23, 8305310215

8305270024 Response to West Valley Agricultural Protection Council 830306 motion for mod of discovery schedule Requests 10-day extension to answer motion since Joint Applicants & Council stipulation not received Certificate of Svc encl
DEWEY, L S Hearing Branch 1 83/05/26 Atomic Safety and Licensing Board Panel 4pp 18640 059 24X Fiche 50-529, 83/05/26, 8305270024

8305310074 Response to West Valley Agricultural Protection Council, Inc supplemental motion for declaration that NEPA analysis inadequate for continuance of proceedings Request for new EIS & continuance should be denied W/Certificate of Svc
DEWEY, L S Hearing Branch 3 83/05/26 Atomic Safety and Licensing Board Panel 14pp 18655 103 24X Fiche 50-529, 83/05/26, 8305310074

K Utility Final Safety Analysis Report (FSAR) & amends

8305020089 Forwards Amend 11 to FSAR
VAN BRUNT, E E Arizona Public Service Co 83/04/28 Office of Nuclear Reactor Regulation, Director 2pp 18274 123 24X Fiche 50-528, 83/04/28, 8305020089

--8305020092 Amend 11 to FSAR W/47 oversize figures Aperture cards are available in PDR
* Arizona Public Service Co 83/04/30 806pp 18274 125 24X Fiche 50-528, 83/04/28, 8305020089

O Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction," Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021.

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8305170531 Forwards IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance noted
CREWS, J L Division of Resident, Reactor Project & Engineering Programs 83/04/22 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 001 24X Fiche 50-528, 83/04/22, 8305170531

--8305170537 IE Insp Repts 50-528/83-10, 50-529/83-07 & 50-530/83-05 on 820601-830311 Noncompliance noted improper documentation of cable termination records
ECKHARDT, J H , VORDERBRUEGGEN, ELIN, J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-528, 83/04/22, 8305170531

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8305170560 Forwards IE Insp Repts 50-528/83-09, 50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted
STERNBERG, D M Region 5, Office of Director 83/04/25 VAN BRUNT, E E Arizona Public Service Co 2pp 18468 128 24X Fiche 50-528, 83/04/25, 8305170560

--8305170564 IE Insp Repts 50-528/83-09, 50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted Major areas inspected allegations made by R Gunderson & W Royce in affidavits before ASLB on 830108 & 0225
VORDERBRUEGGEN, FIORELLI, G , BURDOIN, J Region 5, Office of Director 83/04/22 14pp 18468 130 24X Fiche 50-528, 83/04/25, 8305170560

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8305020466 Informs that insp of facility not warranted unless significant safety deficiency identified re elongated roof truss bolts VITS item closed & matl placed in vendor reactive file
CONWAY, J T Region 4, Office of Director 83/04/28 BARNES, I. Region 4, Office of Director 1p 18283 307 24X Fiche 50-529, 83/04/28, 8305020466

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co. of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8305160008 Notification of 830525 meeting w/util & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/05/10 Region 5, Office of Director 2pp 18456 079 24X Fiche 50-528,83/05/10,8305160008

8305160089 Confirms 830525 meeting w/applicant at Deer Valley Project ofc to discuss SALP for Jul 1981 - Feb 1983
CREWS, J L Division of Resident,Reactor Project & Engineering Programs 83/05/10 VAN BRUNT,E E Arizona Public Service Co 3pp 18448 146 24X Fiche 50-528,83/05/10,8305160089

--8305160179 SALP rept for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528,83/05/10,8305160089

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030346 Interim Deficiency Rept DER 83-15 re Marathon A354 anchor bolt breaking after overtorquing during test acceptance Initially reported on 830318 Due to extensive investigation & evaluation,final rept expected by 830519
VAN BRUNT,E E Arizona Public Service Co 83/04/15 STERNBERG,D M Region 5, Office of Director 3pp 18297 134 24X Fiche 50-529,83/04/15,8305030346

8305030626 Interim Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Final rept by 830519
VAN BRUNT,E E Arizona Public Service Co 83/04/15 STERNBERG,D M Region 5, Office of Director 3pp 18303 339 24X Fiche 50-528,83/04/15,8305030626

8305130161 Interim Deficiency Rept DER 82-72 re concrete void in containment exterior wall Initially reported on 821124 Grouting procedure implemented Apr 1983 per Bechtel investigation Final rept will be submitted by 830629
VAN BRUNT,E E Arizona Public Service Co 83/04/21 STERNBERG,D M Region 5, Office of Director 3pp 18437 296 24X Fiche 50-529,83/04/21,8305130161

8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection switches failure to meet requirements of TMI Task 18A Initially reported on 830304 Info will not be finalized until 830519,due to extensive investigation
VAN BRUNT,E E Arizona Public Service Co 83/04/21 STERNBERG,D M Region 5, Office of Director 1p 18440 093 24X Fiche 50-528,83/04/21,8305130229

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X Fiche,50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application.Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 3pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305130124 Deficiency Evaluation Rept 83-18 re installation of pipe supports which do not meet Seismic IX requirements Initially reported on 830329 Deficiency determined not reportable per 10CFR50 55(e) Documentation will be maintained in files.
VAN BRUNT,E E Arizona Public Service Co 83/04/28 STERNBERG,D M Region 5, Office of Director 2pp 18438 059 24X Fiche 50-528,83/04/28,8305130124

8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 830406 Deficiency determined not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/29 STERNBERG,D M Region 5, Office of Director 2pp 18437 185 24X Fiche 50-528,83/04/29,8305130159

8305130210 Advises that Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/29 STERNBERG,D M Region 5, Office of Director 1p 18440 090 24X Fiche 50-528,83/04/29,8305130210

8305130148 Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements Initially reported on 821124 Revised test plan reviewed by Bechtel Final rept expected by 830823 Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18438 117 24X Fiche 50-528,83/05/03,8305130148

8305130226 Rev 1 to Interim Deficiency Rept DER 82-80 re failure of Conax electrical penetration low level insulation resistance to meet qualification tests Initially reported on 821217 Testing in progress Next rept by 830914
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 3pp 18439 188 24X Fiche 50-528,83/05/03,8305130226

8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Also reportable per 10CFR21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18439 238 24X Fiche 50-528,83/05/03,8305130264

8305230517 Final Deficiency Rept DER 83-21 re operation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/05/06 STERNBERG,D M Region 5, Office of Director 2pp 18536 313 24X Fiche 50-528,83/05/06,8305230517

DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

A Application/construction stage documents & correspondence

8305030013 Forwards NRC comments on C-E Owners Group study re depressurization & DHR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision
NOVAK,T M Assistant Director for Licensing 83/04/20 VAN BRUNT,E E Arizona Public Service Co 4pp 18310 349 24X Fiche 50-528,83/04/20,8305030013

8305110022 Summary of 830406-07 meetings w/util & Bechtel at site re NRC power sys site audit findings Agenda encl
LICITRA,E A Licensing Branch 3 83/05/03 Licensing Branch 3 7pp 18415 066 24X Fiche 50-528,83/05/03,8305110022

8305230003 Forwards request for addl info re 830322 proposed rev to Table 3 2-1 of FSAR Rev deleting commitment to apply QA program to certain items during operations phase w/o justification
KNIGHTON,G W Licensing Branch 3 83/05/03 VAN BRUNT,E E Arizona Public Service Co 4pp 18541 352 24X Fiche 50-528,83/05/03,8305230003

--8305230004 Suggests that encl request for addl info be transmitted to applicant Proposed revs unacceptable w/o justification for deleting commitment to apply FSAR Chapter 17 QA program during operations phase
HAASS,W P QA Branch 83/04/26 KNIGHTON,G W Licensing Branch 3 6pp 18541 356 24X Fiche 50-528,83/05/03,8305230003

8305040323 Board Notification 83-057 forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305170219 Forwards summary of 830407 meeting w/util in Bethesda,MD re draft procedures generation package for emergency procedures
LICITRA,E A Licensing Branch 3 83/05/06 Licensing Branch 3 2pp 18476 343 24X Fiche 50-528,83/05/06,8305170219

--8305170225 Summary of 830428 meeting w/util in Bethesda,MD re draft procedures generation package for emergency procedures
GOODMAN,M J Procedures & Systems Review Branch 83/04/28
CLAYTON,H B Procedures & Systems Review Branch 4pp 18476 345
24X Fiche 50-528,83/05/06,8305170219

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305240253 Notification of 830602 meeting w/util & Torrey Pines Technology in Bethesda,MD to present results of independent QA evaluation & discuss status of corrective actions
LICITRA,E A Licensing Branch 3 83/05/10 KNIGHTON,G W
Licensing Branch 3 3pp 18593 300 24X Fiche 50-528,83/05/10,
8305240253

8305200417 Justifies rev to FSAR Section 1 8 re exception to Reg Guide 1 38 storage requirements for fission chamber detectors & sealed sources,in response to Jan 1983 request
VAN BRUNT,E E Arizona Public Service Co 83/05/18 KNIGHTON,G
Licensing Branch 3 2pp 18517 162 24X Fiche 50-528,83/05/18,
8305200417

8305250209 Board Notification 83-063 transmits memos re status of DHR studies for C-E plants,w/emphasis on need for PORVs in current C-E designs
NOVAK,T M Assistant Director for Licensing 83/05/18 Atomic Safety and Licensing Board Panel 7pp 18627 107 24X
Fiche 50-000,83/05/18,8305250209

--8305250221 Requests that encl documents on status of DHR studies for C-E plants,w/emphasis on need for PORVs in current C-E designs,be provided to ASLB & ASLAB
MATTSON,R J Division of Systems Integration (post 811005)
83/04/28 EISENHUT,D G Division of Licensing 1p. 18627·113
24X Fiche 50-000,83/05/18,8305250209

--8305250228 Responds to Commission 830404 request that study of need for controlled depressurization capability in C-E plants be accelerated & that ACRS views be solicited on issue prior to reporting back to Commission Study to be concluded 830630
DIRCKS,W J Office of the Executive Director for Operations
83/04/25 CHILK,S J Office of the Secretary of the Commission
1p 18627 115 24X Fiche 50-000,83/05/18,8305250209

8305310161 Notifies that util will provide plant-specific info re depressurization & DHR capabilities by 830731,instead of previous schedule date of 830930
VAN BRUNT,E E Arizona Public Service Co 83/05/24 KNIGHTON,G
Licensing Branch 3 2pp 18652 345 24X Fiche 50-528,83/05/24,
8305310161

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305230273 Confirms requests for info identified in discussions w/util re analysis of Sys 80 fuel design under combined seismic & LOCA loads & protection against low temp overpressure event per SER open item
KNIGHTON,G W Licensing Branch 3 83/05/04 VAN BRUNT,E E.
Arizona Public Service Co 3pp 18543 265 24X
Fiche 50-528,83/05/04,8305230273

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits
Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305200322 Advises that installation of source range neutron flux monitor,per 10CFR50,App R,Section III L,will be accomplished by end of first refueling outage
VAN BRUNT,E E Arizona Public Service Co. 83/05/17 KNIGHTON,G
Licensing Branch 3 6pp 18516 294. 24X Fiche 50-528,83/05/17,
8305200322

G Adjudicatory correspondence

8305030594 Second set of nonuniform interrogatories Certificate of Svc encl,Related correspondence
CRAWFORD,V A Joint Applicants-Palo Verde. CRAWFORD,V.A Snell & Wilmer 83/04/27 West Valley Agricultural Protection Council, Inc. 56pp 18303 215 24X Fiche.50-529,83/04/27,8305030594

8305030498 Second set of interrogatories Certificate of Svc encl
DEWEY,L S Hearing Branch 3 83/04/29 West Valley Agricultural Protection Council, Inc 9pp 18295 109 24X Fiche 50-529,
83/04/29,8305030498

8305160080 Memorandum supporting West Valley Agricultural Protection Council,Inc supplemental motion for declaration that NEPA analysis inadequate & for continuance No attempt made to identify/analyze salt drifts W/Cetificate of Svc
BERLIN,K West Valley Agricultural Protection Council, Inc.
BERLIN,K Berlin, Roisman, Kessler & Cashdan 83/05/06 Atomic Safety and Licensing Board Panel 6pp 18450 120 24X
Fiche 50-529,83/05/06,8305160080

8305110268 Comments on format of Univ of Arizona agricultural productivity study methodology Methodology adequate for evaluating impacts of salt drift on representative agricultural crops
DEWEY,L S Hearing Branch 3 83/05/10 PLATT,W E. Snell & Wilmer
3pp 18393 293 24X Fiche 50-529,83/05/10,8305110268

8305160032 Supplemental motion to 830202 motion for declaration that NEPA analysis inadequate & for continuance of proceedings Joint applicant responses to interrogatories lacked meaningful data on salt deposition
BERLIN,K West Valley Agricultural Protection Council, Inc.
83/05/13 Atomic Safety and Licensing Board Panel 13pp
18453 149 24X Fiche·50-529,83/05/13,8305160032

8305160034 Motion for mod of ASLB 830323 discovery schedule,per 830309 stipulation on discovery Depositions scheduled for 830718 should be rescheduled for 830829 Discovery on Univ of Arizona crop study should begin on 831220
BERLIN,K West Valley Agricultural Protection Council, Inc
83/05/13 Atomic Safety and Licensing Board Panel 5pp
18456 089 24X Fiche 50-529,83/05/13,8305160034

8305160086 Memorandum supporting West Valley Agricultural Protection Council,Inc motion for discovery schedule Projected date for crop study completion 6 wks later than original date
BERLIN,K West Valley Agricultural Protection Council, Inc.
BERLIN,K Berlin, Roisman, Kessler & Cashdan 83/05/16. Atomic Safety and Licensing Board Panel 3pp 18451 024 24X
Fiche 50-529,83/05/16,8305160086

8305240482 Joint Applicants response to West Valley Agricultural Protection Council second set of interrogatories
QEHR,A C ; PLATT,W E ; BISCHOFF,C A Snell & Wilmer 83/05/18.
Atomic Safety and Licensing Board Panel 61pp 18572;252. 24X
Fiche 50-529,83/05/18,8305240482

8305200488 Advises that time for Commission to review ALAB-713 expired Commission declined review Decision became final agency action on 830427 Action does not deal w/uncontested issues considered separately by NRC & Commissioners
CHILK,S J Office of the Secretary of the Commission. 83/05/19.
Office of the Executive Legal Director 1p 18514 039. 24X
Fiche 50-528,83/05/19,8305200488

8305310215 Requests opportunity to respond to West Valley Agricultural Protection Council 830506 supplemental motion re FES - OL stage & to argue relevancy if ASLB determines that consideration should be given
QEHR,A C Snell & Wilmer. QEHR,A C Arizona Public Service Co.
83/05/23. LAZO,R.M., CALLIHAN,D ; COLE,R F. Atomic Safety and Licensing Board Panel 5pp 18658·137 24X Fiche.50-528,83/05/23,
8305310215

8305270024 Response to West Valley Agricultural Protection Council 830306 motion for mod of discovery schedule Requests 10-day extension to answer motion since Joint Applicants & Council stipulation not received.Certificate of Svc encl
DEWEY,L S Hearing Branch 1 83/05/26 Atomic Safety and Licensing Board Panel 4pp. 18640 059 24X Fiche.50-529,83/05/26,
8305270024

8305310074 Response to West Valley Agricultural Protection Council,Inc supplemental motion for declaration that NEPA analysis inadequate for continuance of proceedings Request for new EIS & continuance should be denied W/Certificate of Svc.
DEWEY,L S Hearing Branch 3 83/05/26 Atomic Safety and Licensing Board Panel. 14pp 18655 105 24X Fiche 50-529,83/05/26,
8305310074

K Utility Final Safety Analysis Report (FSAR) & amends

8305020089 Forwards Amend 11 to FSAR
VAN BRUNT,E E Arizona Public Service Co 83/04/28. Office of Nuclear Reactor Regulation, Director 2pp 18274,123. 24X
Fiche 50-528,83/04/28,8305020089

--8305020092 Amend 11 to FSAR W/47 oversize figures Aperture cards are available in PDR
* Arizona Public Service Co 83/04/30 806pp 18274 125 24X Fiche 50-528,83/04/28,8305020089

G Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8305170531 Forwards IE Insp Repts 50-528/83-10,50-529/83-07 & 50-530/83-05 on 820601-830311 One item of noncompliance noted
CREWS,J L Division of Resident,Reactor Project & Engineering Programs, 83/04/22 VAN BRUNT,E E Arizona Public Service Co 2pp 18468 001 24X Fiche 50-528,83/04/22,8305170531

--8305170537 IE Insp Repts 50-528/83-10,50-529/83-07 & 50-530/83-05 on 820601-830311 Noncompliance noted improper documentation of cable termination records
ECKHARDT,J H, VORDERBRUEGGEN, ELIN,J O Region 5, Office of Director 83/04/21 15pp 18468 003 24X Fiche 50-528,83/04/22, 8305170531.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305170560 Forwards IE Insp Repts 50-528/83-09,50-529/83-06 & 50-530/83-04 on 830404-07.No noncompliance noted
STERNBERG,D M Region 5, Office of Director 83/04/25 VAN BRUNT,E E Arizona Public Service Co 2pp 18468 128 24X Fiche 50-528,83/04/25,8305170560

--8305170564 IE Insp Repts 50-528/83-09,50-529/83-06 & 50-530/83-04 on 830404-07 No noncompliance noted Major areas inspected allegations made by R Gunderson & W Royce in affidavits before ASLB on 830108 & 0225
VORDERBRUEGGEN, FIORELLI,G , BURDOIN,J Region 5, Office of Director 83/04/22 14pp 18468 130 24X Fiche 50-528,83/04/25, 8305170560.

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs," Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment," Svc list encl
JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co. of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl,
JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/04 Consolidated Edison Co of New York, Inc 112pp, 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441.001. 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305160008 Notification of 830525 meeting w/util & Bechtel in Deer Valley project ofc to discuss SALP for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/05/10 Region 5, Office of Director 2pp 18456 079 24X Fiche 50-528,83/05/10,8305160008

8305160089 Confirms 830525 meeting w/applicant at Deer Valley Project ofc to discuss SALP for Jul 1981 - Feb 1983
CREWS,J L Division of Resident,Reactor Project & Engineering Programs 83/05/10 VAN BRUNT,E E Arizona Public Service Co 3pp 18448 146 24X Fiche 50-528,83/05/10,8305160089

--8305160179 SALP rept for Jul 1981 - Feb 1983
* Region 5, Office of Director 83/04/30 31pp 18448 152 24X Fiche 50-528,83/05/10,8305160089

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305030626 Interim Deficiency Rept DER 83-16 re potential failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Final rept by 830519
VAN BRUNT,E E Arizona Public Service Co 83/04/15, STERNBERG,D M Region 5, Office of Director 3pp 18303 339 24X Fiche 50-528,83/04/15,8305030626

8305130229 Corrected Interim Deficiency Rept DER 83-17 re ITE fire protection switches failure to meet requirements of TMI Task 18A Initially reported on 830304 Info will not be finalized until 830519,due to extensive investigation
VAN BRUNT,E E Arizona Public Service Co 83/04/21 STERNBERG,D M Region 5, Office of Director 1p 18440 093 24X Fiche 50-528,83/04/21,8305130229

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,B J Niagara Mohawk Power Corp 83/04/26. STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 3pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

8305130124 Deficiency Evaluation Rept 83-18 re installation of pipe supports which do not meet Seismic IX requirements Initially reported on 830329 Deficiency determined not reportable per 10CFR50 55(e) Documentation will be maintained in files
VAN BRUNT,E E Arizona Public Service Co 83/04/28 STERNBERG,D M Region 5, Office of Director 2pp 18438 059 24X Fiche 50-528,83/04/28,8305130124

8305130159 Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications Initially reported on 830406 Deficiency determined not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/29 STERNBERG,D M Region 5, Office of Director 2pp 18437 185 24X Fiche 50-528,83/04/29,8305130159.

8305130210 Advises that Deficiency Evaluation Rept DER 83-20 re startup test personnel qualifications not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/04/29 STERNBERG,D M Region 5, Office of Director 1p 18440 090 24X Fiche 50-528,83/04/29,8305130210

8305130148 Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements Initially reported on 821124 Revised test plan reviewed by Bechtel Final rept expected by 830823 Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18438 117 24X Fiche 50-528,83/05/03,8305130148

8305130189 Final Deficiency Rept DER 83-12 re malfunction of GE add-on electric interlocks used w/Class IF,Size 2,starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 5pp 18439 340 24X Fiche 50-528,83/05/03,8305130189

8305130226 Rev 1 to Interim Deficiency Rept DER 82-80 re failure of Conax electrical penetration low level insulation resistance to meet qualification tests Initially reported on 821217 Testing in progress Next rept by 830914
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 3pp 18439 188 24X Fiche 50-528,83/05/03,8305130226

8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Also reportable per 10CFR21
VAN BRUNT,E E Arizona Public Service Co 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18439 238 24X Fiche 50-528,83/05/03,8305130264

8305230517 Final Deficiency Rept DER 83-21 re operation of low pressure safety injection pump in violation of procedures Deficiency not reportable per 10CFR50 55(e)
VAN BRUNT,E E Arizona Public Service Co 83/05/06 STERNBERG,D M Region 5, Office of Director 2pp 18536 313 24X Fiche 50-528,83/05/06,8305230517

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

A Application/construction stage documents & correspondence

8305170086 COMPARISON OF CRBR DESIGN BASIS EVENTS WITH THOSE OF FOREIGN LMFBR PLANTS
AGRAWAL,A K Brookhaven National Laboratory FIN A-3364 NUREG/CR-3240 83/04/30 Clinch River Breeder Reactor Program Office 85pp Available at NRC $5 00 18493 193 24X Fiche 50-537,83/04/30,8305170086

8305110590 Notification of 830524 meeting w/DOE,Project Mgt Corp & TVA in Bethesda,MD to review status of applicant PRA
STARK,R M Clinch River Breeder Reactor Program Office 83/05/04 GRACE,J N Clinch River Breeder Reactor Program Office 3pp 18417 361 24X Fiche 50-537,83/05/04,8305110590

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D,G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X Fiche 50-000,83/05/09,8305090659

8305170449 Submits supplemental info to 830401 ltr re cable separation by confirming that approx 75 ft of DHR svc & steam generator auxiliary heat removal sys cable will be run in separate conduits or encl raceways
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 83/05/16 GRACE,J,N Clinch River Breeder Reactor Program Office 1p 18471 220 24X Fiche 50-537,83/05/16,8305170449

8305230113 Forwards Rev 5 to Vol 2 to "Thermal Margin Beyond Design Base." Rev incorporates isotopic inventory for heterogeneous core,current meteorology,addl organ doses & more realistic Pu sparging calculations
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 83/05/17 GRACE,J N Clinch River Breeder Reactor Program Office 1p 18696 200 24X Fiche 50-537,83/05/17,8305230113

--8305310003 Rev 5 to "Hypothetical Core Disruptive Accident Considerations in CRBRP," Vol 2, "Assessment of Thermal Margin Beyond Design Base "
* Energy, Dept of CRBRP-3 V02 R05 83/03/31 52pp 18696 201 24X Fiche 50-537,83/05/17,8305230113

8305230285 Forwards Rev 1 to "CRBR Project Heat Transport Sys In-Containment Piping Reserve Seismic Margins" & rept re consequences of leaks from small diameter primary heat transport sys piping
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 83/05/19 GRACE,J N Clinch River Breeder Reactor Program Office 2pp 18539 043 24X Fiche 50-537,83/05/19,8305230285

--8305230292 Rev 1 to "CRBR Project Heat Transport Sys In-Containment Piping Reserve Seismic Margins "
MELLO,R M , CHANDRA,U , MALLETT,R H Energy, Dept of, Clinch River Breeder Reactor Plant ES-LPD-83-001 R01, 83/05/31 75pp 18539 045 24X Fiche 50-537,83/05/19,8305230285

B Utility Preliminary Safety Analysis Report, amends

8305200459 Forwards Amend 77 to PSAR
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 83/05/20 GRACE,J N Clinch River Breeder Reactor Program Office 4pp 18513 201 24X Fiche 50-537,83/05/20,8305200459

--8305200463 Amend 77 to PSAR
* Energy, Dept of, Clinch River Breeder Reactor Plant 83/05/31, 166pp 18513 209 24X Fiche 50-537,83/05/20,8305200459,

E NRC Safety Evaluation Report (SER), suppls & correspondence

8305090013 Forwards SER (NUREG-0968,Suppl 1) including addl info received from applicant & ACRS comments
GRACE,J N Clinch River Breeder Reactor Program Office 83/05/02, LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 32pp 18369 322 24X Fiche 50-537,83/05/02,8305090013,

8305060524 Forwards revised responses to SER Item 6 re QA,including info to complete identification of safety-related structures,sys & components controlled by CRBR QA program for PSAR Marked-up Tech Specs encl
LONGENECKER,J Energy, Dept of 83/05/05 GRACE,J N Clinch River Breeder Reactor Program Office 18pp 18351 095 24X Fiche 50-537,83/05/05,8305060524

8305250166 Forwards Suppl 1 to SER (NUREG-0968) re evaluation of addl info on previously identified as outstanding review items since preparation of SER Response to comments for ACRS 830419 rept to Commission also encl W/o encls
GRACE,J N Clinch River Breeder Reactor Program Office 83/05/19 LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 2pp 18596 140 24X Fiche 50-537,83/05/19,8305250166

8305240022 Forwards Suppl 2 to SER (NUREG-0968) re evaluation of addl info on previously identified outstanding review items
GRACE,J N Clinch River Breeder Reactor Program Office, 83/05/20 LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 16pp 18577 314 24X Fiche 50-537,83/05/20,8305240022

8305170057 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No 50-537 (U S Department of Energy,Tennessee Valley Authority And Project Management Corporation)
* Clinch River Breeder Reactor Program Office NUREG-0968 S01 83/05/31 36pp 18493 199 24X Fiche 50-537,83/05/31,8305170057

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11, Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000,83/05/11,8305110034

G Adjudicatory correspondence

8303240390 Suppl to 830307 schedule motion Parties need definite milestones to work toward commencement of hearings
EDGAR,G L Project Management Corp. LUCK,W.D Energy, Dept of, 83/03/23 Atomic Safety and Licensing Board Panel 4pp 17679 117 24X Fiche 50-537,83/03/23,8303240390,

--8303240394 Forwards draft statement of scope & schedule for forthcoming CP hearings & requests telcon to discuss schedule Certificate of Svc encl
EDGAR,G L, Morgan, Lewis & Bockius, 83/03/02 TURK,S E, Hearing Branch 1 FINAMORE,B.A Natural Resources Defense Council. 6pp 17679 121 24X Fiche 50-537,83/03/23,8303240390

8305030572 Requests to make limited appearance statement at 830718 CP hearings re regional socioeconomic impacts
PATE,D S Affiliation Unknown 83/04/27 CHILK,S J Office of the Secretary of the Commission 1p 18306 117 24X
Fiche 50-537,83/04/27,8305030572

8305030490 Advises that NRC will not file separate response to util 830427 motion to dismiss intervenor Contention 10 NRC position agreeing contention is no longer in issue was accurately represented in util motion
MIZUNO,G S Hearing Branch 1 83/04/29 MILLER,M , LINENBERGER,G
HAND,C H Atomic Safety and Licensing Board Panel 1p 18292 175
24X Fiche 50-537,83/04/29,8305030490

8305030502 Motion for extension of time for discovery permitted by 830329 CP scheduling order,to provide opportunity to prepare questions & responses to documentation supporting CP contentions W/Certificate of Svc
FINAMORE,B A , WEISS,E R Natural Resources Defense Council
WEISS,E R Sierra Club 83/04/29 MILLER,M E , LINENBERGER,G ,
HAND,C H Atomic Safety and Licensing Board Panel 9pp 18306 185
24X Fiche 50-537,83/04/29,8305030502

8305030483 Notice of T Cochran 830509 deposition in Washington,DC re Contentions 1a-b,3a-c,9c & 9f-g Certificate of Svc encl
MIZUNO,G S Hearing Branch 1 83/05/02 3pp 18308 247. 24X
Fiche 50-537,83/05/02,8305030483

8305030542 Suppl to updated response to intervenor interrogatories transmitting A Schwallie,RE Hottel,EK Sliger & HP Planchon statements of prof qualifications Certificate of Svc encl
* Joint Applicants-Clinch River Breeder Reactor 83/05/02
Natural Resources Defense Council 12pp 18305 266 24X
Fiche 50-537,83/05/02,8305030542

8305060317 Advises that NRC will not file formal response to applicant 830427 motion to dismiss intervenor Contentions 2(f),(g) & (h) NRC position agreeing that contentions no longer in issue is correct
TURK,S E Hearing Branch 1 83/05/05 MILLER,M , LINENBERGER,G ,
HAND,C H Atomic Safety and Licensing Board Panel 1p 18344 151
24X Fiche 50-537,83/05/05,8305060317

8305090499 Order concurring w/ALAB-721 denying stay of effectiveness of partial initial decision authorizing issuance of LWA Statements of Commissioners Palladino,Ahearne & Gilinsky encl
HOYLE,J C Commissioners 83/05/05 Energy, Dept of 7pp
18361 141 24X Fiche 50-537,83/05/05,8305090499

8305100022 Confirms that 830509 Cochran deposition re Contentions 1(a)-(h),3(a)-(c) & 9(c),(f) & (g) rescheduled for 830512 in Washington,DC
TURK,S E Hearing Branch 1 83/05/06 FINAMORE,B A Natural Resources Defense Council FINAMORE,B A Finamore, B A 1p
18377 151 24X Fiche 50-537,83/05/06,8305100022

8305100210 Response to applicant 830421 tenth set of interrogatories Related correspondence
FINAMORE,B A Natural Resources Defense Council 83/05/06 10pp
18374 037 24X Fiche 50-537,83/05/06,8305100210

8305100276 Affidavit of TB Cochran re answers to interrogatories Related correspondence
COCHRAN,T B Natural Resources Defense Council 83/05/06 Atomic Safety and Licensing Board Panel 1p 18371 242 24X
Fiche 50-537,83/05/06,8305100276

8305100350 Supplementary response to eighth & ninth set of interrogatories dtd 830401 & 08 Review of SER & related documentation incomplete,hindering response to certain interrogatories Related correspondence
FINAMORE,B.A Natural Resources Defense Council FINAMORE,B A
Sierra Club 83/05/06 MILLER,M E , LINENBERGER,G , HAND,C H
Atomic Safety and Licensing Board Panel 15pp 18410 321. 24X
Fiche. 50-537,83/05/06,8305100350

8305120291 Certifies svc on 830506 of intervenor supplementary response to applicant eighth & ninth set of interrogatories dtd 830401 & 08 & intervenor response to applicant tenth set of interrogatories dtd 830421
FINAMORE,B A Natural Resources Defense Council FINAMORE,B A.
Sierra Club 83/05/06 3pp. 18424 122 24X Fiche 50-537,83/05/06,
8305120291

8305110220 Response opposing intervenor 830429 motion for extension of time.Good cause not demonstrated
EDGAR,G L Project Management Corp LUCK,W D Energy, Dept of
83/05/09 Atomic Safety and Licensing Board Panel 11pp
18407 052 24X Fiche 50-537,83/05/09,8305110220

8305110337 Notice of 830513 conference w/parties in proceeding & respective counsel in Bethesda,MD to discuss pending motions & requests
MILLER,M E Atomic Safety and Licensing Board Panel 83/05/09 1p
18406 179 24X Fiche 50-537,83/05/09,8305110337

8305110438 Response to first set of CP interrogatories & request to produce Requested documents will be made available for insp & copying Related correspondence
* Energy, Dept of * Project Management Corp * Tennessee Valley Authority 83/05/09 Natural Resources Defense Council
2pp 18405 008 24X Fiche 50-537,83/05/09,8305110438

8305110448 Responds to second set of CP interrogatories Aerosol plateout & fallout calculations discussed Affidavit encl Related correspondence
* Energy, Dept of * Project Management Corp * Tennessee Valley Authority 83/05/09 Natural Resources Defense Council
7pp 18405 010 24X Fiche 50-537,83/05/09,8305110448

8305120313 Certifies svc on 830509
EDGAR,G L Project Management Corp 83/05/09 3pp 18424 102
24X Fiche 50-537,83/05/09,8305120313

8305110445 Forwards corrected 830509 response to NRDC & Sierra Club first set of interrogatories & request to produce directed to applicant Original document not identified as response
SCHMUTZ,T A Morgan, Lewis & Bockius 83/05/10 Docketing & Services Branch 1p 18405 048 24X Fiche 50-537,83/05/10,
8305110445

--8305110449 Corrected response to first set of interrogatories & request to produce Requested documents will be made available for insp & copying
* Energy, Dept of * Project Management Corp * Tennessee Valley Authority 83/05/09 Natural Resources Defense Council
2pp 18405 049 24X Fiche 50-537,83/05/10,8305110445

8305110450 Amended response to NRDC & Sierra Club 830407 first set of CP interrogatories & request to produce Discusses NRC best estimate of containment failure pressure Affidavit encl
TURK,S E Hearing Branch 1 83/05/10 Natural Resources Defense Council 3pp 18405 058 24X Fiche 50-537,83/05/10,8305110450

--8305110455 Response to NRDC & Sierra Club 830426 second set of CP interrogatories & request to produce Affidavits & Certificate of Svc encl
TURK,S E Hearing Branch 1 83/05/10 Natural Resources Defense Council 12pp 18405 061 24X Fiche 50-537,83/05/10,
8305110450

8305130063 Submission of encl to NRC 830510 response to second set of CP interrogatories Certificate of Svc encl
TURK,S E Hearing Branch 1 83/05/11 Natural Resources Defense Council 9pp 18436 304 24X Fiche 50-537,83/05/11,8305130063

8305160128 Response opposing NRDC & Sierra Club 830429 motion for extension until 830708 to complete discovery Delay in hearing schedule to permit further discovery unreasonable Two Certificates of Svc encl
TURK,S E Hearing Branch 1 83/05/13 Atomic Safety and Licensing Board Panel 9pp 18446 105 24X Fiche 50-537,83/05/13,
8305160128

8305160149 Response to 830427 second set of CP interrogatories & request for admissions Related correspondence
FINAMORE,B A , WEISS,E R Natural Resources Defense Council
WEISS,E R Sierra Club 83/05/13 Office of the Executive Legal Director 13pp 18446 088 24X Fiche 50-537,83/05/13,8305160149

8305160181 Response to 830425 eleventh set of interrogatories & request for admissions Certificate of Svc encl Related correspondence
FINAMORE,B A , WEISS,E R Natural Resources Defense Council
WEISS,E R Sierra Club 83/05/13 Joint Applicants-Clinch River Breeder Reactor 36pp 18445 092 24X Fiche 50-537,83/05/13,
8305160181

8305190204 Order following 830513 conference w/parties Remaining contentions are Contentions 1 re envelope of DBA not including core disruptive accidents,3 re core disruptive accidents & 9(c),(f) & (g) re emergency planning
MILLER,M E Atomic Safety and Licensing Board Panel 83/05/17
10pp 18502 195 24X Fiche 50-537,83/05/17,8305190204

8305190221 Third set of CP interrogatories & request to produce Certificate of Svc encl Related correspondence
FINAMORE,B A , WEISS,E R Natural Resources Defense Council
WEISS,E R Sierra Club. 83/05/17 Office of the Executive Legal Director 7pp 18501 323 24X Fiche 50-537,83/05/17,8305190221

8305190339 Notification re PRA status rept Encl Phase I PRA rept not submitted to NRC for review Results of rept insignificant to proceeding W/o Phase 1 rept Certificate of Svc encl
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/18 6pp 18500-212 24X Fiche 50-537, 83/05/18, 8305190339

8305240553 Brief supporting exceptions to ASLB 830228 partial initial decision re LWA
FINAMORE, B A , WEISS, E R Natural Resources Defense Council, WEISS, E R Sierra Club 83/05/18 Atomic Safety and Licensing Board Panel 89pp 18575 296 24X Fiche 50-537, 83/05/18, 8305240553

8305200636 Motion for summary disposition of Contention 9(g) re emergency plans No genuine issue of matl fact exists
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/19 Atomic Safety and Licensing Board Panel 4pp 18519 329 24X Fiche 50-537, 83/05/19, 8305200636

--8305200648 Statement of matl facts as to which there is no genuine issue re Contention 9(g) on emergency planning Certificate of Svc encl
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/19 Atomic Safety and Licensing Board Panel 5pp 18519 333 24X Fiche 50-537, 83/05/19, 8305200636

8305240070 Response to 830517 third set of CP interrogatories & request to produce Certificate of Svc encl
TURK, S E Hearing Branch 1 83/05/20 Natural Resources Defense Council 15pp 18549 078 24X Fiche 50-537, 83/05/20, 8305240070

8305240475 Motion for summary disposition of intervenor Contentions 9(c) & 9(f) re adequacy of evacuation time analysis in PSAR. No genuine issue of matl fact exists & applicant entitled to favorable decision Certificate of Svc encl
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of. 83/05/23 Atomic Safety and Licensing Board Panel 10pp 18549 345 24X Fiche 50-537, 83/05/23, 8305240475

8305240480 Statement of matl facts as to which there is no genuine issue re Contentions 9(c) & (f) on emergency plans
EDGAR, G L Project Management Corp. LUCK, W D Energy, Dept of 83/05/23 Atomic Safety and Licensing Board Panel 3pp 18571 266 24X Fiche 50-537, 83/05/23, 8305240480

8305240503 Motion for extension until 830722 to file response to intervenors 830518 brief in support of exceptions Certificate of Svc encl
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/23 Atomic Safety and Licensing Appeal Panel 6pp 18571 238 24X Fiche 50-537, 83/05/23, 8305240503

8305310188 Notification of pending litigation re NRDC 821001 motion to expedite consideration of emergency motion to amend US District Court of Appeals remand & to review EPA regulations. Certificate of Svc encl
EDGAR, G L Project Management Corp LUCK, W D Energy, Dept of 83/05/27 11pp 18652.271 24X Fiche 50-537, 83/05/27, 8305310188

L Limited work authorization & related correspondence

8305260001 Forwards notice of issuance of LWA-1 constituting authorization to conduct activities described in 770401 request & revised site preparation activities rept dtd June 1982
GRACE, J N Clinch River Breeder Reactor Program Office. 83/05/19 LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant. 4pp 18649 105 24X Fiche 50-537, 83/05/19, 8305260001

--8305260002 Notice of issuance of LWA-1, authorizing util, DOE & Project Mgt Corp to conduct certain site activities prior to decision on issuance of CP
GRACE, J N Clinch River Breeder Reactor Program Office 83/05/19. 3pp 18649.109 24X Fiche 50-537, 83/05/19, 8305260001

O Advisory Committee on Reactor Safeguards reports & correspondence

8304140158 Summary of ACRS CRBR Subcommittee meeting on 821027 in Washington, DC re plant design criteria, rationale of selection of DBA spectrum & associated prevention/mitigation sys & plant safeguards & security.
* ACRS - Advisory Committee on Reactor Safeguards 82/10/29. ACRS - Advisory Committee on Reactor Safeguards. 21pp 18541-047. 24X Fiche 50-537, 82/10/29, 8304140158

8305160299 Forwards rept summarizing review of TMBDB presentation at ACRS 830310-11 meetings Review confined to thermomechanics, engineering design & finite element analysis Review will be summarized at 830414 meeting
ANDERSON, C A Los Alamos Scientific Laboratory ANDERSON, C A ACRS - Advisory Committee on Reactor Safeguards 83/03/29. CARBON, M. ACRS - Advisory Committee on Reactor Safeguards 6pp 18472 069. 24X Fiche 50-537, 83/03/29, 8305160299

8305130359 Telecopy of comments on CRBR re pressure boundary Design of reactor pressure vessel meets & usually exceeds requirements of ASME III & relevant code cases
BUSH, S H Battelle Memorial Institute, Pacific Northwest Laboratory BUSH, S H ACRS - Advisory Committee on Reactor Safeguards. 83/03/30 CARBON, M ACRS - Advisory Committee on Reactor Safeguards 2pp 18443 324 24X Fiche 50-537, 83/03/30, 8305130359.

8305130349 Submits comments on core disruptive accidents & seismic margins per request made at ACRS 830316-17 meetings Applicant energetic source term acceptable Seismic margin calculations not acceptable
LIPINSKI, W C Argonne National Laboratory LIPINSKI, W. C ACRS - Advisory Committee on Reactor Safeguards 83/03/31. CARBON, M W. ACRS - Advisory Committee on Reactor Safeguards 3pp. 18457-340. 24X Fiche 50-537, 83/03/31, 8305130349

8305130350 Comments on seismic design safety margin for facility Add1 comments to be made at ACRS 830414 meeting
SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS - Advisory Committee on Reactor Safeguards 83/03/31. BOEHNERT, P. ACRS - Advisory Committee on Reactor Safeguards. 3pp 18443:357 24X Fiche 50-537, 83/03/31, 8305130350.

8305130355 Provides input re seismic safety margins for CRBR, based on ongoing seismic safety margins research program at lab
BOHM, M P Lawrence Livermore Laboratory BOHM, M. P. ACRS - Advisory Committee on Reactor Safeguards 83/04/08 CARBON, M ACRS - Advisory Committee on Reactor Safeguards 6pp 18443-326. 24X Fiche 50-537, 83/04/08, 8305130355.

8305180637 Expresses appreciation for opportunity to participate in CRBR project review Seismic safety margin estimates probably conservative Failure of small diameter pipes will be discussed
SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS - Advisory Committee on Reactor Safeguards 83/04/15. CARBON, M ACRS - Advisory Committee on Reactor Safeguards 1p. 18505.329. 24X Fiche 50-537, 83/04/15, 8305180637.

8305120556 "Consultant Rept for ACRS Review of CRBR Thermal Margin Beyond Design Basis "
POWERS, D A. Sandia Laboratories POWERS, D A ACRS - Advisory Committee on Reactor Safeguards 83/05/10. 30pp 18443:090. 24X Fiche. 50-537, 83/05/10, 8305120556

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319. 24X Fiche 50-000, 83/03/21, 8212060385.

8305270472 Forwards IE Insp Rept 50-537/83-01 on 830315. No noncompliance noted
DANCE, H C. Division of Project & Resident Programs 83/04/06. BREWINGTON, P Energy, Dept. of, Clinch River Breeder Reactor Plant 2pp 18644-081. 24X Fiche 50-537, 83/04/06, 8305270472.

--8305270482 IE Insp Rept 50-537/83-01 on 830315 No noncompliance noted Project mgt meeting, warehouse tours & site tour conducted.
IGNATONIS, A J Region 2, Office of Director BROWNLEE, V. L Division of Project & Resident Programs. 83/04/06. 4pp 18644.083 24X Fiche 50-537, 83/04/06, 8305270472

8305270314 Forwards IE Insp Rept 50-537/83-02 on 830328-0401 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs. 83/04/14. BREWINGTON, P Energy, Dept of, Clinch River Breeder Reactor Plant 2pp. 18642 204 24X Fiche: 50-537, 83/04/14, 8305270314.

--8305270319 IE Insp Rept 50-537/83-02 on 830328-0401. No noncompliance noted Major areas inspected: pre-CP QA activities
MCFARLAND, C. R Region 2, Office of Director. WRIGHT, C. M. Division of Engineering & Radiological Safety Programs. 83/04/13. 4pp. 18642 206 24X Fiche 50-537, 83/04/14, 8305270314

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15. Consolidated Edison Co. of New York, Inc 126pp. 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8305270197 Forwards IE Insp Rept 50-537/83-03 on 830404-06 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/02
BREWINGTON, P. Energy, Dept of, Clinch River Breeder Reactor Plant
2pp 18637 237 24X Fiche 50-537,83/05/02,8305270197.

--8305270200 IE Insp Rept 50-537/83-03 on 830404-06 No noncompliance noted Major areas inspected site preparation
HARRIS, J R , CONLON, T E. Region 2, Office of Director 83/04/25
2pp. 18637 239. 24X Fiche 50-537,83/05/02,8305270197

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers." Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382.282 24X Fiche,50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04. Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8305270273 Forwards IE Insp Rept 50-537/83-04 on 830411-15 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/05/06
BREWINGTON, P Energy, Dept of, Clinch River Breeder Reactor Plant
2pp 18644 268. 24X Fiche 50-537,83/05/06,8305270273

--8305270278 IE Insp Rept 50-537/83-04 on 830411-15 No noncompliance noted Major areas inspected preconst QA activities
JACKSON, L. , UPRIGHT, C. M Region 2, Office of Director 83/05/02
4pp. 18644.270 24X Fiche 50-537,83/05/06,8305270273

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines." Svc list encl.
JORDAN, E L. Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11. Consolidated Edison Co. of New York, Inc 114pp. 18524.003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl.
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc. 114pp. 18697.009. 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/26. Consolidated Edison Co of New York, Inc. 114pp. 18647 007 24X Fiche 50-000,83/05/26,8303040046

T Hearing transcripts on non-antitrust matters

8305170293 Transcript of 830513 conference in Bethesda, MD Pp 7,106-7,279
* Atomic Safety and Licensing Board Panel 83/05/13 184pp
18464 149 24X Fiche 50-537,83/05/13,8305170293

U Congressional/Executive Correspondence

8305240019 Responds to 830418 ltr recommending retention of technical cadre of experts to review CRBR & overall DOE breeder program Maint of CRBR Program Ofc at adequate level planned Decision on issuance of CP expected by June 1984
DIRCKS, W J Office of the Executive Director For Operations
83/05/10 LLOYD, M House of Rep , Science & Technology 3pp
18577 308 24X Fiche 50-537,83/05/10,8305240019

--8305240023 Recommends that Commission retain technical cadre of experts to review CRBR & overall DOE breeder program
LLOYD, M House of Rep , Science & Technology 83/04/18
PALLADINO, N J Commissioners 1p 18577 310 24X
Fiche 50-537,83/05/10,8305240019

DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

8305230654 Ack receipt of ltr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron increases
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/10
TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18542 352 24X
Fiche 50-546,83/03/10,8305230654

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000,83/04/11,8305230720

8305120457 Confirms 830414 commitment re electrical cable tray hanger installation under conditions outlined in 830203 confirmatory action ltr Request to restart installation of hangers renewed
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/15
KEPPLER, J G Region 3, Office of Director 3pp 18434 036 24X
Fiche. 50-546,83/04/15,8305120457

8304250167 Application for amend of CPPR-170 & CPPR-171 (filed in PDR Category A), consisting of Amend 24 to FSAR (filed in PDR Category K) & Suppl 1 to environ rept - OL stage (Filed in PDR Category C)
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/21
DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp
18212 083 24X Fiche 50-546,83/04/21,8304250167

8305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984
YOUNGBLOOD, B J Licensing Branch 1 83/04/28 YOST, F E Utility Data Institute 1p 18434 279 24X Fiche 50-546,83/04/28,8305110185.

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130119 Forwards response to Generic Ltr 83-10C re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Response to Items I 1e,I 3a & I 3c will be addressed in FSAR,App E,scheduled for submittal by 840331
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/09
EISENHUT, D G Division of Licensing 5pp 18437 353 24X
Fiche 50-546,83/05/09,8305130119

8305230635 Forwards request for addl info re environ qualification of electrical & mechanical equipment Schedular commitment for submittal of program should be provided within 30 days
YOUNGBLOOD, B J Licensing Branch 1 83/05/10 SHIELDS, S W Public Service Co. of Indiana, Inc 4pp 18543 021 24X
Fiche 50-546,83/05/10,8305230635

8305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ rept - OL stage Affidavit of Distribution encl
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18466 024 24X Fiche 50-546, 83/05/13, 8305170306

--8305170312 Revised Suppl 1 to environ rept - OL stage
* Public Service Co of Indiana, Inc 83/05/31 1p 18466 030 24X Fiche 50-546, 83/05/13, 8305170306

8305200289 Forwards Amend 25 to CP & OL applications, including revs to security plan Amend withheld (ref 10CFR2 790)
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/05/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18516 319 24X Fiche 50-546, 83/05/16, 8305200289

C Utility Environmental Report (ER), amends & correspondence

8304250167 Forwards Suppl 1 to environ rept - OL stage (filed in PDR Category C) Supporting repts encl
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 18212 083 24X Fiche 50-546, 83/04/21, 8304250167

8305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984
YOUNGBLOOD, B J Licensing Branch 1 83/04/28 VOST, F E Utility Data Institute 1p 18434 279 24X Fiche 50-546, 83/04/28, 8305110185

8305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ rept - OL stage Affidavit of Distribution encl
SHIELDS, S W Public Service Co of Indiana, Inc SHIELDS, S W Wabash Valley Power Association, Inc 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 18466 024 24X Fiche 50-546, 83/05/13, 8305170306

--8305170312 Revised Suppl 1 to environ rept - OL stage
* Public Service Co of Indiana, Inc 83/05/31 1p 18466 030 24X Fiche 50-546, 83/05/13, 8305170306

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X Fiche 50-000, 83/05/11, 8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS, W J Office of the Executive Director for Operations 83/05/13 PALLADINO, N J Commissioners 5pp 18593 322 24X Fiche 50-000, 83/05/13, 8305240213

8305260233 Advises of 830527 prompt notification sys development meeting in Clarksville, IN to discuss objectives & design of emergency planning zone
KNIGHT, M R Public Service Co of Indiana, Inc 83/05/18 AXELSON, W L Region 3, Office of Director 1p 18599 338 24X Fiche 50-546, 83/05/18, 8305260233

G Adjudicatory correspondence

8305130073 Answer to Indiana Sassafras Audubon Society (ISAS) petition for leave to intervene ISAS fails to establish right to intervene Certificate of Svc encl
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc * LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 11pp 18436 251 24X Fiche 50-546, 83/05/12, 8305130073

8305130098 Response w/o objection to Save the Valley petition for leave to intervene, provided applicant may object to contentions & right to hearing after petition suppl filed Certificate of Svc encl
VOIGT, H H Public Service Co of Indiana, Inc VOIGT, H H Wabash Valley Power Association, Inc VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 4pp 18438 097 24X Fiche 50-546, 83/05/12, 8305130098

8305130244 Response opposing Valley Watch, Inc 820427 petition for leave to intervene in proceeding Petitioner fails to establish sufficient interest in proceeding to establish standing as matter of right or discretion W/Certificate of Svc
VOIGT, H H Public Service Co of Indiana, Inc VOIGT, H H. Wabash Valley Power Association, Inc VOIGT, H H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 11pp 18439 174 24X Fiche 50-546, 83/05/12, 8305130244

8305160146 Response in opposition to Valley Watch, Inc 830419 petition for intervention & request for public hearing re OL application Petition has not established requisite standing to intervene Certificate of Svc encl
CHAN, E I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 078 24X Fiche 50-546, 83/05/12, 8305160146

8305160158 Response to Save the Valley petition to intervene Requisite standing to intervene established Aspects of proceeding to be addressed by intervenor identified Certificate of Svc encl
CHAN, E I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 141 24X Fiche 50-546, 83/05/12, 8305160158

8305170003 Response to Sassafras Audubon Soc of South Central Indiana 830416 petition to intervene Requisite standing to intervene not established Specific aspects appropriate for consideration identified by Soc Certificate of Svc encl
CHAN, E I Hearing Branch 2 83/05/13 Atomic Safety and Licensing Board Panel 11pp 18466 231 24X Fiche 50-546, 83/05/13, 8305170003

K Utility Final Safety Analysis Report (FSAR) & amends

8304250167 Forwards Amend 24 to FSAR (filed in PDR Category K) W/277 oversize drawings Aperture cards are available in PDR
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 18212 083 24X Fiche, 50-546, 83/04/21, 8304250167

--8304250190 Amend 24 to FSAR W/277 oversize drawings Aperture cards are available in PDR
* Public Service Co of Indiana, Inc 83/04/30 138pp 18212 099 24X Fiche 50-546, 83/04/21, 8304250167

Q Inspection reports, IE Bulletins & correspondence

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040.

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co, of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche: 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys. " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291, 24X Fiche 50-000, 83/04/25, 8303040025

8305120419 Forwards IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 & notice of violation
SPESSARD, R L Division of Engineering 83/04/25 SHIELDS, S W
Public Service Co of Indiana, Inc 2pp 18434 051 24X
Fiche 50-546, 83/04/25, 8305120419

--8305120423 Notice of violation from insp on 830124-28 & 0224-25
SPESSARD, R L Division of Engineering 83/04/25 4pp
18434 053 24X Fiche 50-546, 83/04/25, 8305120419

--8305120428 IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 Noncompliance noted Failure to assure that applicable requirements translated into instructions, procedures or drawings Nonconforming items not tagged
LOVE, R S , MENDEZ, R , WILLIAMS, C C Region 3, Office of Director
83/04/20 23pp 18434 057 24X Fiche 50-546, 83/04/25, 8305120419

8305170148 Forwards IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted
STREETER, J F Region 3, Office of Director 83/04/27 SHIELDS, S W
Public Service Co of Indiana, Inc 2pp 18466 285 24X
Fiche 50-546, 83/04/27, 8305170148

--8305170153 IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted Major areas inspected electrical contractors QA program, implementing procedures & training
VANDEL, T E , KISH, J N , HAWKINS, F C Region 3, Office of Director
83/04/27 4pp 18466 287 24X Fiche 50-546, 83/04/27, 8305170148

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

S Reportable occurrences, LERs & related correspondence

8305020291 Final deficiency rept re potential for inaccurate indication of Westinghouse mfg gate valve position Initially reported on 821222 Westinghouse issued field change notice documenting corrective actions
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/21
KEPPLER, J G Region 3, Office of Director 2pp 18281 296 24X
Fiche 50-546, 83/04/21, 8305020291

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE, E P Westinghouse Electric Corp 83/04/21 DEYOUNG, R C
Director s Office, Office of Inspection and Enforcement 5pp
18405 095 24X Fiche 50-000, 83/04/21, 8305110427

8305020118 Final deficiency rept re interference between rear attachment brackets & mechanical snubber pivot mount brackets Initially reported on 830325 Rear brackets will be returned to ITT Grinnel for reworking
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/22
KEPPLER, J G Region 3, Office of Director 1p 18278 217 24X
Fiche 50-546, 83/04/22, 8305020118

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL, D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd)
83/04/27 STELLO, V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000, 83/04/27, 8305110324

8305040494 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on 800509 Westinghouse & util working to refine equipment mod to mutual satisfaction Next rept by 831028
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/28
KEPPLER, J G Region 3, Office of Director 2pp 18319 264 24X
Fiche 50-546, 83/04/28, 8305040494

8305130207 Interim deficiency rept re problem involving embedded plates in primary shield wall w/deformed wire anchors missing or welds between plate & anchor being cracked Initially reported on 820818 Caused by axial tensile stresses
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/09
KEPPLER, J G Region 3, Office of Director 2pp 18439 355 24X
Fiche 50-546, 83/05/09, 8305130207

8305240408 Final deficiency rept re potential for improper operation of DS-416 reactor trip switchgear undervoltage attachments Initially reported on 830421 Attachments to be replaced w/ attachments having modified grooves
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/16
KEPPLER, J G Region 3, Office of Director 2pp 18574 277 24X
Fiche 50-546, 83/05/16, 8305240408

8305260332 Interim deficiency rept re Commonwealth-Lord Joint Venture failure to adequately implement QA program Initially reported on 830211 Nonconformance repts for items not previously audited written Next rept by 830805
SHIELDS, S W Public Service Co of Indiana, Inc 83/05/18
KEPPLER, J G Region 3, Office of Director 2pp 18625 005 24X
Fiche 50-546, 83/05/18, 8305260332

DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

8305230654 Ack receipt of ltr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron increases
SHIELDS, S W Public Service Co of Indiana, Inc 83/03/10
TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18542 352 24X
Fiche 50-546, 83/03/10, 8305230654

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J Commissioners 2pp 18542 272 24X
Fiche 50-000, 83/04/11, 8305230720

8305120457 Confirms 830414 commitment re electrical cable tray hanger installation under conditions outlined in 830203 confirmatory action ltr Request to restart installation of hangers renewed
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/15
KEPPLER, J G Region 3, Office of Director 3pp 18434 036 24X.
Fiche 50-546, 83/04/15, 8305120457

8304250167 Application for amend of CPPR-170 & CPPR-171 (filed in PDR Category A), consisting of Amend 24 to FSAR (filed in PDR Category K) & Suppl 1 to environ rept - OL stage (filed in PDR Category C)
SHIELDS, S W Public Service Co of Indiana, Inc 83/04/21
DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp
18212 083 24X Fiche 50-546, 83/04/21, 8304250167.

8305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984
YOUNGBLOOD,B J Licensing Branch 1 83/04/28 YOST,F E Utility Data Institute 1p 18434 279 24X Fiche 50-546,83/04/28, 8305110185

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT,D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000,83/05/09,8305090659

8305130119 Forwards response to Generic Ltr 83-10C re resolution of TMI Action Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps " Response to Items I 1e,I 3a & I 3c will be addressed in FSAR,App E,scheduled for submittal by 840331
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/09
EISENHUT,D G Division of Licensing 5pp 18437 353 24X
Fiche 50-546,83/05/09,8305130119

8305230635 Forwards request for addl info re environ qualification of electrical & mechanical equipment Schedular commitment for submittal of program should be provided within 30 days
YOUNGBLOOD,B J Licensing Branch 1 83/05/10 SHIELDS,S W Public Service Co of Indiana, Inc 4pp 18543 021 24X
Fiche 50-546,83/05/10,8305230635

8305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ rept - OL stage Affidavit of Distribution encl
SHIELDS,S W Public Service Co of Indiana, Inc SHIELDS,S W Wabash Valley Power Association, Inc 83/05/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18466 024 24X
Fiche 50-546,83/05/13,8305170306

8305200289 Forwards Amend 25 to CP & OL applications,including revs to security plan Amend withheld (ref 10CFR2 790)
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/16
DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18516 319 24X Fiche 50-546,83/05/16,8305200289

C Utility Environmental Report (ER), amends & correspondence

8304250167 Forwards Suppl 1 to environ rept - OL stage (filed in PDR Category C) Supporting repts encl
SHIELDS,S W Public Service Co of Indiana, Inc 83/04/21
DENTON,H R Office of Nuclear Reactor Regulation, Director 16pp 18212 083 24X Fiche 50-546,83/04/21,8304250167

8305110185 Responds to 830413 ltr re 830325 FR notice of NRC receipt of application for OLs & environ rept Environ rept available in PDR & is scheduled for issuance in June 1984
YOUNGBLOOD,B J Licensing Branch 1 83/04/28 YOST,F E Utility Data Institute 1p 18434 279 24X Fiche 50-546,83/04/28, 8305110185

8305170306 Application to amend CPPR-170 & CPPR-171 w/submittal of revised Suppl 1 to environ rept - OL stage Affidavit of Distribution encl
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/13
DENTON,H R Office of Nuclear Reactor Regulation, Director 6pp 18466 024 24X Fiche 50-546,83/05/13,8305170306

--8305170312 Revised Suppl 1 to environ rept - OL stage
* Public Service Co of Indiana, Inc 83/05/31 1p 18466 030 24X Fiche 50-546,83/05/13,8305170306

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT,D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000,83/05/11,8305110034

8305240213 Forwards monthly status rept on offsite emergency preparedness for OL reviews for Apr 1983
DIRCKS,W J Office of the Executive Director for Operations 83/05/13 PALLADINO,N J Commissioners 5pp 18593 322 24X
Fiche 50-000,83/05/13,8305240213

8305200289 Forwards Amend 25 to CP & OL applications,including revs to security plan Amend withheld (ref 10CFR2 790)
SHIELDS,S W Public Service Co, of Indiana, Inc SHIELDS,S.W. Wabash Valley Power Association, Inc 83/05/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18516 319 24X
Fiche 50-546,83/05/16,8305200289

8305260233 Advises of 830527 prompt notification sys development meeting in Clarksville,IN to discuss objectives & design of emergency planning zone
KNIGHT,M R Public Service Co of Indiana, Inc 83/05/18
AXELSON,W L Region 3, Office of Director 1p 18599 338 24X
Fiche 50-546,83/05/18,8305260233

G Adjudicatory correspondence

8305130073 Answer to Indiana Sassafras Audubon Society (ISAS) petition for leave to intervene ISAS fails to establish right to intervene Certificate of Svc encl
* Public Service Co of Indiana, Inc * Wabash Valley Power Association, Inc * LeBoeuf, Lamb, Leiby & MacRae 83/05/12, Commissioners 11pp 18436 251 24X Fiche 50-546,83/05/12, 8305130073

8305130098 Response w/o objection to Save the Valley petition for leave to intervene,provided applicant may object to contentions & right to hearing after petition suppl filed. Certificate of Svc encl
VOIGT,H H Public Service Co of Indiana, Inc VOIGT,H H Wabash Valley Power Association, Inc VOIGT,H H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 4pp 18438 097 24X
Fiche 50-546,83/05/12,8305130098

8305130244 Response opposing Valley Watch,Inc 820427 petition for leave to intervene in proceeding,Petitioner fails to establish sufficient interest in proceeding to establish standing as matter of right or discretion W/Certificate of Svc
VOIGT,H H Public Service Co of Indiana, Inc VOIGT,H H Wabash Valley Power Association, Inc VOIGT,H H LeBoeuf, Lamb, Leiby & MacRae 83/05/12 Commissioners 11pp 18439 174 24X
Fiche 50-546,83/05/12,8305130244

8305160146 Response in opposition to Valley Watch,Inc 830419 petition for intervention & request for public hearing re OL application Petition has not established requisite standing to intervene Certificate of Svc encl
CHAN,E I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 078 24X Fiche 50-546,83/05/12, 8305160146

8305160158 Response to Save the Valley petition to intervene Requisite standing to intervene established Aspects of proceeding to be addressed by intervenor identified Certificate of Svc encl
CHAN,E I Hearing Branch 2 83/05/12 Atomic Safety and Licensing Board Panel 11pp 18445 141 24X Fiche 50-546,83/05/12, 8305160158

8305170003 Response to Sassafras Audubon Soc of South Central Indiana 830416 petition to intervene Requisite standing to intervene not established Specific aspects appropriate for consideration identified by Soc Certificate of Svc encl
CHAN,E I Hearing Branch 2 83/05/13 Atomic Safety and Licensing Board Panel 11pp 18466 231 24X Fiche 50-546,83/05/13, 8305170003

K Utility Final Safety Analysis Report (FSAR) & amends

8304250167 Forwards Amend 24 to FSAR (filed in PDR Category K) W/277 oversize drawings Aperture cards are available in PDR
SHIELDS,S W Public Service Co of Indiana, Inc 83/04/21
DENTON,H R Office of Nuclear Reactor Regulation, Director. 16pp 18212 083 24X Fiche 50-546,83/04/21,8304250167

--8304250190 Amend 24 to FSAR W/277 oversize drawings Aperture cards are available in PDR
* Public Service Co of Indiana, Inc 83/04/30 138pp 18212 099 24X Fiche 50-546,83/04/21,8304250167

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp 18308 319, 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche,50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8305120419 Forwards IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 & notice of violation
SPESSARD,R L Division of Engineering 83/04/25 SHIELDS,S W Public Service Co of Indiana, Inc 2pp 18434 051 24X Fiche,50-546,83/04/25,8305120419

--8305120423 Notice of violation from insp on 830124-28 & 0224-25
SPESSARD,R L Division of Engineering 83/04/25 4pp 18434 053 24X Fiche 50-546,83/04/25,8305120419

--8305120428 IE Insp Repts 50-546/83-01 & 50-547/83-01 on 830124-28 & 0224-25 Noncompliance noted failure to assure that applicable requirements translated into instructions, procedures or drawings Nonconforming items not tagged
LOVE,R S , MENDEZ,R , WILLIAMS,C C Region 3, Office of Director 83/04/20 23pp 18434 057 24X Fiche 50-546,83/04/25,8305120419

8305170148 Forwards IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted
STREETER,J F Region 3, Office of Director 83/04/27 SHIELDS,S W Public Service Co of Indiana, Inc 2pp 18466 285 24X Fiche 50-546,83/04/27,8305170148

--8305170153 IE Insp Repts 50-546/83-04 & 50-547/83-04 on 830309-18 No noncompliance noted Major areas inspected electrical contractors QA program,implementing procedures & training
VANDEL,T E , KISH,J N , HAWKINS,F C Region 3, Office of Director 83/04/27 4pp 18466 287 24X Fiche 50-546,83/04/27,8305170148

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines," Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

S Reportable occurrences, LERs & related correspondence

8305020291 Final deficiency rept re potential for inaccurate indication of Westinghouse mfg gate valve position Initially reported on 821228 Westinghouse issued field change notice documenting corrective actions
SHIELDS,S W Public Service Co of Indiana, Inc 83/04/21
KEPPLER,J G Region 3, Office of Director 2pp 18281 296 24X Fiche 50-546,83/04/21,8305020291

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E P Westinghouse Electric Corp 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18405 095 24X Fiche 50-000 83/04/21,8305110427

8305020118 Final deficiency rept re interference between rear attachment brackets & mechanical snubber pivot mount brackets Initially reported on 830325 Rear brackets will be returned to ITT Grinnel for reworking
SHIELDS,S W Public Service Co of Indiana, Inc 83/04/22
KEPPLER,J G Region 3, Office of Director 1p 18278 217 24X Fiche 50-546,83/04/22,8305020118

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X Fiche 50-000,83/04/27,8305110324

8305040494 Interim deficiency rept re operation of centrifugal charging pumps during high energy line rupture Initially reported on 800509 Westinghouse & util working to refine equipment mod to mutual satisfaction Next rept by 831028
SHIELDS,S W Public Service Co of Indiana, Inc 83/04/28
KEPPLER,J G Region 3, Office of Director 2pp 18319 264 24X Fiche 50-546,83/04/28,8305040494

8305130207 Interim deficiency rept re problem involving embedded plates in primary shield wall w/deformed wire anchors missing or welds between plate & anchor being cracked Initially reported on 820818 Caused by axial tensile stresses
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/09
KEPPLER,J G Region 3, Office of Director 2pp 18439 355 24X Fiche 50-546,83/05/09,8305130207

8305240408 Final deficiency rept re potential for improper operation of DS-416 reactor trip switchgear undervoltage attachments Initially reported on 830421 Attachments to be replaced w/ attachments having modified grooves
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/16
KEPPLER,J G Region 3, Office of Director 2pp 18574 277 24X Fiche 50-546,83/05/16,8305240408

8305260332 Interim deficiency rept re Commonwealth-Lord Joint Venture failure to adequately implement QA program Initially reported on 830211 Nonconformance repts for items not previously audited written Next rept by 830805
SHIELDS,S W Public Service Co of Indiana, Inc 83/05/18
KEPPLER,J G Region 3, Office of Director 2pp 18625 005 24X Fiche 50-546,83/05/18,8305260332

DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X Fiche 50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83/03/11 COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X Fiche 50-000,83/04/26,8305120392

DOCKET STN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

S Reportable occurrences, LERs & related correspondence

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO, S F Niagara Mohawk Power Corp 83/04/26 STAROSTECKI, R
Region 1, Office of Director 2pp 18433 072 24X
Fiche 50-000, 83/04/26, 8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY, D C Rockwell International Corp 83/03/11 COLLINS, J T
Region 4, Office of Director 3pp 18433 074 24X
Fiche 50-000, 83/04/26, 8305120392

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

Q Adjudicatory correspondence

8305260178 Advises that time for Commission to review ALAB-723 expired Commission declined review Decision became final agency action on 830524
CHILK, S J Office of the Secretary of the Commission 83/05/25
Atomic Safety and Licensing Board Panel 1p 18599 270 24X
Fiche 50-556, 83/05/25, 8305260178

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089 24X Fiche 50-000, 83/04/22, 8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 271 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000, 83/04/28, 8303040027

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co, of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing 83/05/09 Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

F Security, medical, emergency & fire protection plans

8305110034 Generic Ltr 83-21 to all licensees of operating reactors, applicants for OLs & holders of CPs re clarification of access to control procedures for law enforcement visits. Svc list encl
EISENHUT, D G Division of Licensing 83/05/11 Consolidated Edison Co of New York, Inc 16pp 18540 095 24X
Fiche 50-000, 83/05/11, 8305110034

Q Adjudicatory correspondence

8305260178 Advises that time for Commission to review ALAB-723 expired Commission declined review Decision became final agency action on 830524
CHILK, S J Office of the Secretary of the Commission 83/05/25
Atomic Safety and Licensing Board Panel 1p 18599 270 24X
Fiche 50-556, 83/05/25, 8305260178

Q Inspection reports, IE Bulletins & correspondence

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc 112pp 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp 18383 089, 24X Fiche: 50-000, 83/04/22, 8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New York, Inc 119pp 18381 291 24X Fiche 50-000,83/04/25,8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047 24X Fiche 50-000,83/04/28,8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 118pp 18382 165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc. 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028.

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation." Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc. 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN,E.L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp. 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil." Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

8305090285 FOIA request for all documents re decision to terminate const of facility.
DEVIENCE,A Devience & O'Meara, Ltd 83/02/24 Office of Administration 1p 18381 225 24X Fiche:50-566,83/02/24, 8305090285

8305090292 Responds to FOIA request for all documents re decision to terminate const of facility Forwards documents listed in App A
FELTON,J M Division of Rules and Records 83/03/21 DEVIENCE,A Devience & O'Meara, Ltd. 2pp 18381 226 24X Fiche 50-566, 83/03/21,8305090292.

8305170237 Forwards "Details of Deferral Plans for Yellow Creek Nuclear Plant "
MILLS,L M Tennessee Valley Authority 83/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18465 079 24X Fiche 50-566,83/05/12,8305170237

--8305170240 "Details of Deferral Plans for Yellow Creek Nuclear Plant."
* Tennessee Valley Authority 83/05/31 7pp 18465 080 24X Fiche 50-566,83/05/12,8305170237

G Inspection reports, IE Bulletins & correspondence

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

8305090285 FOIA request for all documents re decision to terminate const of facility
DEVIENCE,A Devience & O'Meara, Ltd 83/02/24 Office of Administration 1p 18381 225 24X Fiche 50-566,83/02/24, 8305090285

8305090292 Responds to FOIA request for all documents re decision to terminate const of facility Forwards documents listed in App A
FELTON,J M Division of Rules and Records 83/03/21 DEVIENCE,A Devience & O'Meara, Ltd 2pp 18381 226 24X Fiche 50-566, 83/03/21,8305090292

8305170237 Forwards "Details of Deferral Plans for Yellow Creek Nuclear Plant "
MILLS,L M Tennessee Valley Authority 83/05/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18465 079 24X Fiche 50-566,83/05/12,8305170237

--8305170240 "Details of Deferral Plans for Yellow Creek Nuclear Plant "
* Tennessee Valley Authority 83/05/31 7pp 18465 080 24X Fiche 50-566,83/05/12,8305170237

DOCKET STN-50-599 CARROLL FACILITY I

G Adjudicatory correspondence

8305060461 Provides quarterly status rept on developments Projected inservice dates revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001
BIELAWSKI,A P Isham, Lincoln & Beale BIELAWSKI,A P Consolidated Edison Co of New York, Inc 83/05/02 WOLF,J F , HOLTON,R L , BRIGHT,G O Atomic Safety and Licensing Board Panel 2pp 18348 070 24X Fiche 50-599,83/05/02,8305060461

DOCKET STN-50-600 CARROLL FACILITY II

G Adjudicatory correspondence

8305060461 Provides quarterly status rept on developments Projected inservice dates revised for Unit 1 from 1999 to 2000 & for Unit 2 from 2000 to 2001
BIELAWSKI,A P Isham, Lincoln & Beale BIELAWSKI,A P Consolidated Edison Co of New York, Inc 83/05/02 WOLF,J F , HOLTON,R L , BRIGHT,G O Atomic Safety and Licensing Board Panel 2pp 18348 070 24X Fiche 50-599,83/05/02,8305060461

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-0008 BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

8305170568 Forwards renewed License SNM-7,consolidating activities authorized by License SNM-7 & Byproduct Matls License 34-6854-05 Byproduct Matls License 34-6854-05 terminated
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 83/04/29
TOY,H L Battelle Memorial Institute, Columbus Laboratories 2pp 18496 126

--8305170570 Renewed License SNM-7,consolidating activities authorized by License SNM-7 & Byproduct Matls License 34-6854-05
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 83/04/29 12pp 18496 128

--8305170571 Forwards question & answer fact sheet & 821227 FR notice re final rulemaking on land disposal of low level radwaste (10CFR61) New provisions include waste classification, manifest preparation & missing shipment investigation
HAWKINS,E F Low Level Waste Licensing Branch 83/02/11 Affiliation Unknown 43pp 18494 338

8305060623 Forwards IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401 No noncompliance noted
PAPERIELLO,C J Region 3, Office of Director 83/05/03 UNGAR,E W Battelle Memorial Institute, Columbus Laboratories 2pp 18348 251

--8305060634 IE Insp Repts 70-0008/83-01 & 40-8202/83-01 on 830330-0401 No noncompliance noted Major areas inspected radiation protection,radwaste mgt,facility changes & safety committees
PECK,C C , GREGER,L R Region 3, Office of Director 83/04/29 6pp 18348 253

8305190161 PND-III-83-036 bioassays & in vivo count of licensee worker indicated potential thorium uptake Cause unknown No potential exposure sources identified Addl medical tests scheduled for 830516
GREGER,L R , MILLER,D E , PAPERIELLO,C J Region 3, Office of Director 83/05/13 1p 18502 238

DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA

8305200338 Recommends that item of noncompliance re License SNM-21 be classified as Severity Level IV violation & handled per guidance in Item 2 of encl 820719 telcon memo W/o encl
AXELRAD,J A Director's Office, Office of Inspection and Enforcement 82/10/18 JOHNSON,A Region 5, Office of Director 1p 18516 229

8303240506 Forwards IE Safeguards Insp Rept 70-0025/83-02 on 830307-11 No noncompliance noted Rept withheld (ref 10CFR2 790)
NORDERHAUG,L R Region 5, Office of Director 83/03/21
FEILER,F W Rockwell International Corp 2pp 17678 106

8305310219 Forwards "Radiation Survey for Phase I Release for Unrestricted Use of ESG Headquarters,Bldg 001 " Document describes efforts to assure elimination of any residual contamination,scope of survey & procedures followed
REMLEY,M E Rockwell International Corp 83/05/05 THOMAS,R D Region 5, Office of Director 2pp 18662 269

--8305310220 "Radiation Survey for Phase I Release for Unrestricted Use of ESG Headquarters,Bldg 001 "
REMLEY,M E Rockwell International Corp 83/05/06 38pp 18662 271

DOCKET 70-0027 BABCOCK & WILCOX CO , LYNCHBURG, VA

8305270548 Forwards IE Insp Rept 70-0027/83-04 on 830314-18 No noncompliance noted
STOHR,J P Division of Emergency Preparedness & Materials Safety 83/04/20 ECKERT,J P Babcock & Wilcox Co 2pp 18647.165

--8305270556 IE Insp Rept 70-0027/83-04 on 830314-18 No noncompliance noted Major areas inspected operations,10CFR21 implementation,internal reviews & audit,safety committees, training & nonroutine events
CORYELL,G P Region 2, Office of Director MCALPINE,E J Division of Emergency Preparedness & Materials Safety 83/04/20 5pp. 18647 167

8305030368 Forwards IE Safeguards Insp Rept 70-0027/83-06 on 830404-08 No noncompliance noted.
STOHR,J P Division of Emergency Preparedness & Materials Safety 83/04/28 ECKERT,J P Babcock & Wilcox Co 2pp 18292 176

--8305030371 IE Safeguards Insp Rept 70-0027/83-06 on 830404-08 No noncompliance noted Major areas inspected site organization, review of security organization-mgt & security organization-personnel Details withheld (ref 10CFR73 21)
TILLMAN,A , URYC,B Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 83/04/28 1p 18292 178

8305160178 Issues Amend 19 to License SNM-42 incorporating radiological contingency plan Amend supersedes Amend 15 dtd 820328
PAGE,R G Uranium Fuel Licensing Branch 83/05/03 REGAN,N Babcock & Wilcox Co 2pp 18462:357

DOCKET 70-0033 TEXAS INSTRUMENTS, INC , ATTLEBORO, MA

8305190001 Advises that official files for License SNM-23 transferred to Region I due to regionalization,effective 830401.
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 SHERMAN,F L Texas Instruments, Inc. 1p 18523 244

8305190008 Advises of 830418 transfer of official docket file & outstanding licensing action from NMSS to Region I
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 STARDSTECKI,R Division of Project & Resident Programs 1p 18523,220

8305250601 Requests change of address for transmitting future correspondence as result of further implementation of regional licensing program,per 830505 ltr
PAGE,R G Uranium Fuel Licensing Branch 83/05/18 SHERMAN,F L Texas Instruments, Inc 1p 18594 322

DOCKET 70-0082 NUCLEAR METALS, INC , WEST CONCORD, MA

8305120224 Addl response to FOIA request for license applications, license & insp repts re Nuclear Metals,Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6)
FELTON,J M Division of Rules and Records 83/03/01 MOONEY,B C Lowell Sun, Lowell, MA 9pp 18460 050

--8305120246 Notifies that Nuclear Metals Div of Textron,Inc acquired by Whittaker Corp Approval for transfer of licenses requested.
THOMPSON,P Nuclear Metals, Inc 66/08/11 Atomic Energy Commission 1p 18460 063

--8305120260 IE Insp Findings & Licensee Ack dtd 691202-03 of License SMB-179 Insp findings no noncompliance noted
SMITH,R H Atomic Energy Commission 69/12/03 1p 18460 066

--8305120264 Advises that response to 690822 application for License SMB-179 has not been received Info re issuance of license requested
LEE,M R Whittaker Corp 69/10/22 NUSSBAUMER,D.A Atomic Energy Commission 1p 18460 067

--8305120268 Submits list of replacement pages to application for License SNM-65,in response to 690923 comments
ISSEROW,S Whittaker Corp 69/10/22 NUSSBAUMER,D A Atomic Energy Commission 2pp 18460 068

--8305120269 Forwards application for renewal of License SNM-65 Application refiled in loose leaf format incorporating 17 items from 680806 ltr W/o encl
KNEPPEL,D S Whittaker Corp 69/02/26. NUSSBAUMER,D.A. Atomic Energy Commission 1p 18460 070

--8305120274 IE Insp Findings & Licensee Ack dtd 690903 & 04 of Licenses SNM-65 & SMB-179 Insp findings proper evaluations not made of certain aspects of health physics program per Sections II b 4 through II b 6(b) of License Condition 8
BROWNE,W G Atomic Energy Commission 69/09/18 1p 18460 071.

--8305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & SMB-179 Insp findings no noncompliance noted
SMITH,R H Atomic Energy Commission 70/07/16. 1p 18460 076

--8305120289 Notifies that no items of noncompliance observed during insp of Licenses SNM-65 & SMB-179 Corrective measures implemented re item of noncompliance during 690903 & 04 insp 8 Isserow replaced DS Kneppel as criticality officer
SMITH,R H Atomic Energy Commission 70/01/06 Atomic Energy Commission 1p 18460 077

--8305120294 IE Insp Findings & Licensee Ack dtd 710513 & 14 of Licenses SNM-65 & SMB-179 Insp findings no noncompliance noted Related info encl
SMITH,R H Atomic Energy Commission 71/05/14 22pp 18460:078

--8305120316 Ack receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr
O'REILLY,J P Region 1, Philadelphia, Office of the Director. 74/04/26 TUFFIN,W B Nuclear Metals, Inc 1p. 18460 140.

--8305120352 Supplx 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler,in response to 740404 telcon.Related info encl.
TUFFIN,W B Nuclear Metals, Inc 74/04/16 O'REILLY,J P. Region 1, Philadelphia, Office of the Director 5pp 18460.141.

--8305120356 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-28 & 740108-09 & notice of violation W/o insp repts.
O'REILLY,J P Region 1, Philadelphia, Office of the Director. 74/02/13 TUFFIN,W B Nuclear Metals, Inc 2pp. 18460.146

--8305120369 Responds to NRC 740215 ltr re violations noted in Insp Rpts 70-0082/73-05 & 40-0672/73-02 Corrective actions:finger dosimeters placed on individual employees monthly on rotating basis U handling employees surveyed.
TUFFIN,W Nuclear Metals, Inc 74/03/27 O'REILLY,J P Region 1, Philadelphia, Office of the Director 11pp 18460 153.

--8305120372 Insp Repts 40-0672/73-02 & 70-0082/73-05 on 721227-28 & 740108-09 Noncompliance noted failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products
JERMAN,P C , KNAPP,P J Region 1, Philadelphia, Office of the Director 74/02/01 20pp 18460 164

--8305120381 Responds to IE Bulletin 75-07 re emission of corrosive gases into ventilation sys filtered by HEPA filters No HEPA or other cellulosic filters used in ventilation sys exhausting nitrogen oxides Plastic overwrap used in disposal
GILMAN,A R Nuclear Metals, Inc 75/12/22 Region 1, Philadelphia, Office of the Director 1p 18460 187

DOCKET 70-0124 TELEDYNE ISOTOPES, INC , WESTWOOD, NJ

8305180759 Lists official docket files & outstanding licensing actions transferred to Region I,effective 830401
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 MARTIN,T T Division of Engineering & Technical Programs 1p 18506 053

8305180858 Advises that official files for License SNM-107 transferred to Region I due to regionalization,effective 830401
PAGE,R G Uranium Fuel Licensing Branch 83/05/05 BLACK,S A Teledyne Isotopes 1p 18506 039

DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC , ERWIN, TN

8305030099 Forwards Rev 51 to Section 2 0 of fundamental nuclear matl control plan,Rev 40 Rev withheld (ref 10CFR2 790) No 10CFR170 fees applicable
HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/02/16. SMITH,C N Fuel Facility Safeguards Licensing Branch 1p 18342 011

8305030699 Provides status of progress in const phase of ventilation upgrade project & correction to schedule contained in 821203 ltr Ventilation sys expected to be fully operational by 830430
MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/03/29. PAGE,R G Division of Fuel Cycle & Material Safety 2pp 18309 111

8305030694 Requests procedures forwarded in encl 811109 ltr to recent request re new ventilation sys be treated as proprietary info
IDEKER,R L Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/04/07. SOONG,A L Uranium Fuel Licensing Branch 1p 18309 113

8305190003 "Daily Summary of Stack Monitoring for Mar 1983 "
MANSER,W.C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/04/14. O'REILLY,J P. Region 2, Office of Director 5pp 18523 238

8305180852 Responds to alleged violation noted in IE Insp Rept 70-0143/83-14 Corrective actions personnel performing calibr & testing sample counting (Procedure NFS-HS-A-4) reinstructed in procedure requirements
MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/04/22 STOHR,J P Region 2, Office of Director 2pp 18506.027

8305190033 Amends 821209 application for amend to License SNM-124, revising Page 79 to apply specifically to proposed unsafe geometry pits in floor beneath processing furnaces W/three oversize drawings.Aperture cards are available in PDR.
IDEKER,R L Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/04/25 PAGE,R G Uranium Fuel Licensing Branch 3pp 18523 169

8305270640 Forwards IE Insp Rept 70-0143/83-15 on 830405-08 No noncompliance noted.
STOHR,J.P Division of Emergency Preparedness & Materials Safety 83/04/25. MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co). 2pp 18646 201

--8305270648 IE Insp Rept 70-0143/83-15 on 830405-08 No noncompliance noted Major areas inspected organization,10CFR21 implementation,facility mods,safety committees,operations, nuclear criticality safety & previous insp findings
CORYELL,G P Region 2, Office of Director MCALPINE,E J Division of Emergency Preparedness & Materials Safety 83/04/25 4pp 18646 203.

8305200638 Forwards Rev 53 to Feb 1983 fundamental nuclear matl control plan Section B 0,per 10CFR70 32 Changes upgrade mods & do not decrease effectiveness of plan No fees required Rev withheld (ref 10CFR2 790)
HENSLEY,K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/05/04 MCALPINE,E J NRC - No Detailed Affiliation Given 1p 18519 319

8305270155 Ack receipt of 830422 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/83-14
STOHR,J P Division of Emergency Preparedness & Materials Safety 83/05/04 MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 1p 18638 070

8305130173 PNO-II-83-037 on 830510,unusual event declared per emergency plan after ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by electric motor & backup blower
CORYELL,G P , GIBSON,A F Region 2, Office of Director 83/05/10 1p 18437 205

8305130055 Order CLI-83-12 approving 830406 joint motion to suspend proceeding Proceeding held in abeyance NRC directed to implement agreement Dissenting views of Commissioners Ahearne & Roberts encl
CHILK,S J Office of the Secretary of the Commission 83/05/11 Nuclear Fuel Services, Inc (subs of Getty Oil Co) 3pp 18436 212

8305200310 Forwards IE Safeguards Insp Rept 70-0143/83-20 on 830404-29 No noncompliance noted
STOHR,J P Division of Emergency Preparedness & Materials Safety 83/05/17 GUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18516 290

--8305200318 IE Safeguards Insp Rept 70-0143/83-20 on 830404-29 No noncompliance noted Major areas inspected facility operation,facility changes & mods,criticality safety & environ protection Details withheld (ref 10CFR2 790)
LEE,T D , MCALPINE,E J Region 2, Office of Director 83/05/13 1p 18516 292

8305270161 Forwards IE Safeguards Insp Rept 70-0143/83-19 on 830418-22 No noncompliance noted
STOHR,J P Division of Project & Resident Programs 83/05/18 GUINN,F K Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18638 134

--8305270167 IE Safeguards Insp Rept 70-0143/83-19 on 830418-22 No noncompliance noted Major areas inspected storage & internal control,records & repts & shipping & receiving Details withheld (ref 10CFR2 790)
JONES,D W , RICHARDS,B L , LANKFORD,J B Region 2, Office of Director 83/05/17 1p 18638 136

8305250537 PNO-II-83-041 on 830520,unusual event declared 1 h after process ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by failure of electric motor Employees evacuated No contamination noted
KAHLE,J D , GIBSON,A F Region 2, Office of Director 83/05/20 1p 18588 226

8305270600 Forwards IE Safeguards Insp Rept 70-0143/83-12 on 830207-0304 No noncompliance noted
STOHR,J P Division of Emergency Preparedness & Materials Safety 83/05/25 MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 2pp 18646 324

--8305270613 IE Safeguards Insp Rept 70-0143/83-12 on 830207-0304 No noncompliance noted Major areas inspected licensee action on previous insp findings,facility operation,facility changes & mods & criticality safety
LEE,T D , MCALPINE,E J Region 2, Office of Director 83/03/23 7pp 18646 326

DOCKET 70-0371 UNC NAVAL PRODUCTS, INC , UNCASVILLE, CT

8305200177 Forwards revised fundamental nuclear matl control plan,Page 3-4 & request to revise Mass Measurement 8 used to overcheck gross weight of clad matl W/o encl
WOLVENDYK,A United Nuclear Corp 83/03/10 HAYNES,R C Region 1, Office of Director 2pp 18540 230

8305190350 Forwards IE Safeguards Insp Rept 70-0371/83-02 on 830317-23 & notice of violation Encls withheld (ref 10CFR2 790)
MARTIN,T T Division of Engineering & Technical Programs 83/05/06 AMY,G D United Nuclear Corp 2pp 18501 023

8305250563 Ack receipt of 830228,0310 & 0406 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/82-14 & forwards revised notice of violation
STAROSTECKI,R Division of Project & Resident Programs 83/05/13
AMY,G O United Nuclear Corp 2pp 18588 187

--8305250569 Revised notice of violation from insp on 821110-12 Noncompliance noted raw fuel storage vault & three trailers containing U-bearing waste not posted w/authorized criticality safety limits
* Region 1, Office of Director 83/05/02 2pp 18588 189

--8305250578 Suppls 830228 & 0310 ltrs re violations noted in IE Insp Rept 70-0371/82-14 Corrective actions air flow restored to license requirements between metallography exam area & sample preparation room & between lab & sectioning
AMY,G O United Nuclear Corp 83/04/06 MARTIN,T T Division of Engineering & Technical Programs 5pp 18588 191

--8305250582 Notifies that response to 830228 ltr re Item A of App A & Paragraph 3 of details re air balance,addressed in 820224 renewal application for License SNM-368 Pending disposition of mod,no other change will be proposed
KIRK,W F United Nuclear Corp 83/03/10 MARTIN,T T Division of Engineering & Technical Programs 1p 18588 196

--8305250586 Responds to NRC 830121 ltr re violation noted in IE Insp Rept 70-0371/82-14 Corrective actions raw fuel storage vault modified during Sept & Oct 1982 Conservative posting of "cans on their side," remains until shelves modified
AMY,G O United Nuclear Corp 83/02/28 MARTIN,T T Division of Engineering & Technical Programs 2pp 18588 202

8305250603 Issues Amend 20 to License SNM-368,authorizing fabrication of new fuel parts SER encl
PAGE,R G Uranium Fuel Licensing Branch 83/05/18 KIRK,W F. United Nuclear Corp 2pp 18594 309

--8305250607 SER supporting Amend 20 to License SNM-368,authorizing fabrication of new fuel elements using new individual unit & spacing requirements
BIDINGER,G H Uranium Fuel Licensing Branch 83/05/18 5pp 18594 311

DOCKET 70-0378 ARMY, DEPT OF, ADELPHI, MD

8305020007 Partial response to FOIA request for documents re Harry Diamond Labs located at 2800 Powder Mill Road,Adelphi,MD from 1965 to present Forwards documents responsive to request Documents also available in PDR
FELTON,J M Division of Rules and Records 83/01/11 SIMPSON,C Affiliation Unknown 1p 18356 003

--8305020081 Forwards Harry Diamond Labs application to amend Licenses 19-17250-01,19-17250-03,19-17250-04,19-17250-05 & SNM-0348 Amend removes JE Stafford as radiation protection officer & substitutes CA Rowe
QUEEN,W G Army, Dept of 78/09/06 Radioisotopes Licensing Branch (Pre 790501) 3pp 18355 047

--8305020095 Application to amend Licenses 19-17250-01,19-17250-03, 19-17250-04,19-17250-05 & SNM-0348,removing JE Stafford as radiation protection officer & substituting CA Rowe
GOODWIN,C R Army, Dept of 78/08/11 2pp 18355 048

--8305020539 Application for amend to Licenses 19-17250-04,19-17250-03, 19-17250-01,19-17250-05 & SNM-0348,removing JE Stafford as radiation protection officer & replacing CA Rowe
QUEEN,W G Army, Dept of 78/09/11 Radioisotopes Licensing Branch (Pre 790501) 2pp 18355 117

--8305030189 Amend 3 to License SNM-348,revising Subitems 9 A-9 F & Conditions 10,12 & 18 re dosimetry studies & calibr studies
WALKER,W J Division of Fuel Cycle & Material Safety 82/12/21 1p 18355 259

--8305030195 Amend 2 to License SNM-348,revising Condition 18 re possession & use of licensed matl described in Items 6,7 & 8
GUINN,P R Division of Fuel Cycle & Material Safety 80/07/09 1p 18355 260

--8305030201 Amend 1 to License SNM-348,revising possession amounts for Pu-239,Np-237,depleted U,U-235 & U-238 encapsulated fission foils & sources
COMBS,F C Division of Fuel Cycle & Material Safety 78/10/30 3pp 18355 261

--8305030207 Renewed License SNM-348 for Harry Diamond Labs,authorizing possession & use of Pu-239,U-235,natural & depleted U & Np-237 encapsulated fission foils
LAYFIELD,R L Atomic Energy Commission, Directorate of Licensing 72/12/19 2pp 18355 264

--8305030212 License SNM-348 for Harry Diamond Labs,authorizing possession & use of Pu-239,U-235,natural & depleted U & Np-237 encapsulated fission foils
LAYFIELD,R L Atomic Energy Commission 68/07/15 3pp 18355 266

--8305030213 License SNM-348 for Harry Diamond Labs,authorizing possession & use of Pu & U enriched in U-235 fission foil
JOHNSON,L Atomic Energy Commission 65/07/16 3pp 18355 269

--8305030218 Application to amend License SNM-348,requesting storage of matls prior to transfer,substituting CA Rowe as alternate radiation officer & listing MJ Borisky as radiation protection officer
MOTHERSBAUGH,L Army, Dept of 82/11/22 Radioisotopes Licensing Branch (Pre 790501) 12pp 18355 272

--8305030225 Forwards resume of MD Funkhouser,designated new radiation protection officer at Harry Diamond Labs replacing C Rowe W/o encl
TARAS,D N Army, Dept of 80/05/22 Radioisotopes Licensing Branch (Pre 790501) 6pp 18355 284

--8305030233 Forwards Harry Diamond Labs response to 780706 ltr re License SNM-348 Headquarters concurs w/response Ack of receipt of correspondence requested W/o encl
TARAS,D N Army, Dept of 78/07/24 COMBS,F Radioisotopes Licensing Branch (Pre 790501) 1p 18355 289

--8305030239 Submits addl info re security requirements,radiation safety facilities & procedures for storage & use of Np-237 foil matl listed on Harry Diamond Labs application for renewal of License SNM-348
GOODWIN,C R Army, Dept of 78/07/19 COMBS,F Radioisotopes Licensing Branch (Pre 790501) 2pp 18355 290

--8305030249 Requests addl info re security requirements,radiation safety facilities & procedures for use & storage of Np-237 & description of leak testing procedures for fission foils
COMBS,F Radioisotopes Licensing Branch (Pre 790501) 78/07/06
TARAS,D N Army, Dept of, Headquarters Materiel Development & Readiness Command 1p 18355 292

--8305030251 Application for renewal of License SNM-348,reflecting changes in location of lab headquarters,amount of Pu-239 in Pu-Be neutron source & radiation protection officers & users
TARAS,D N Army, Dept of 77/11/18 Radioisotopes Licensing Branch (Pre 790501). 17pp 18355 293

--8305030255 Ack receipt of application to renew License SNM-348 License will not expire until final action taken
BROWN,J M Radioisotopes Licensing Branch (Pre 790501). 77/12/05
TARAS,D N Army, Dept of 1p 18355 310

--8305030260 Application for amend & renewal of License SNM-348, authorizing possession & use of 9 76 mg Pu-239,0 24 g U-235, 1 72 g U-235 & 5 0 g Np-237
REHRIG,A W Army, Dept of 72/12/04 Atomic Energy Commission 21pp 18355 311

--8305030264 Amend 4 to License SNM-348,revising expiration date to 650731,TB Grucci qualifications added to license record.
LAYFIELD,R L Atomic Energy Commission 65/01/12 FLYNN,R.M Army, Dept of 1p 18355 332

--8305030268 Amend 3 to License SNM-348,revising Items 7 & 8 & adding Item 14 re licensee compliance w/attached leak test conditions for Pu alpha sources
DOULOS,N , NUSSBAUMER,D Atomic Energy Commission 64/01/21
GOLDSTEIN,B L. Army, Dept of 1p 18355 333.

--8305030278 Forwards Amend 2 to License SNM-348 License does not authorize insertion of matls into nuclear reactor Insertions must be authorized W/o encl
JOHNSON,L Atomic Energy Commission 63/09/26 GOLDSTEIN,B L. Army, Dept of 1p 18355 334

--8305030281 Amended License SNM-348 for Harry Diamond Labs,authorizing enriched U-235 as Pu-Be neutron source & 64.6 g as fission foils
* Atomic Energy Commission. 63/09/26 4pp. 18355 335

--8305030286 License SNM-348 for Harry Diamond Labs, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source, 12 micrograms encapsulated in fast neutron detectors & 10 g encapsulated as neutron activation detectors
JOHNSON, L Atomic Energy Commission 62/02/27 1p 18355 339

--8305030289 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source 12 micrograms encapsulated in fast neutron detectors
* Atomic Energy Commission 61/11/14 2pp 18355 340

--8305030296 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu encapsulated as Pu-Be neutron source & 12 micrograms encapsulated in fast neutron detectors
NUSSBAUMER, D Atomic Energy Commission 61/05/18 1p 18355 342

--8305030301 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu as encapsulated Pu-Be neutron source
DELANEY, J C Atomic Energy Commission 60/02/03 2pp 18355 343

--8305030304 Amend to License SNM-348, correcting docket number error in Item 5 Correct number should be 70-0378
LAYFIELD, R L Atomic Energy Commission 68/07/24 HAAS, C F Army, Dept of 1p 18355 345

--8305030309 Forwards renewed License SNM-348, reflecting leak test condition for Pu as sealed source W/o encl
LAYFIELD, R L Atomic Energy Commission 68/07/15 HAAS, C F Army, Dept of 1p 18355 346

--8305030312 Application for renewal & amend of License SNM-348, authorizing possession & use of 54.7 g Pu & 16 g Pu-239, Np-237, depleted U, U-235 & U-238 neutron source in encapsulated calibr sources & fission foils
HAAS, C F Army, Dept of 68/06/25 11pp 18355 347

--8305030320 Notifies that License SNM-348 expires on 680731 Application for renewal of license should be filed within 30 days Notification should be given at decision not to renew by completing encl form W/o encl
NUSSBAUMER, D A Atomic Energy Commission 68/05/26 SEIDLER, G Army, Dept of 1p 18355 358

--8305030323 Forwards renewed License SNM-348 W/o encl
JOHNSON, L Atomic Energy Commission 65/07/16 SEIDLER, G Army, Dept of 1p 18355 359

--8305030326 Forwards addl info re use & storage of Pu neutron source, per AEC 650604 request Includes description of Pu neutron source & dimensions of tantalum & stainless steel source container
SEIDLER, G Army, Dept of 65/07/06 Atomic Energy Commission 2pp 18355 360

--8305030332 Requests addl info re use & storage of Pu neutron source & personnel monitoring program, in response to 650505 application to renew License SNM-348
LAYFIELD, R L Atomic Energy Commission 65/06/04 FLYNN, R M Army, Dept of 1p 18355 362

--8305030335 Application for renewal & amend to License SNM-348, authorizing 13 4 g Np-237, 54 5 g Pu-239, 54 5 g U-235 & 143 g U-238 in form of fission foils for calibr studies
FLYNN, R M Army, Dept of 65/05/05 Atomic Energy Commission 12pp 18356 001

--8305040060 Application to amend License 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-348, removing JE Stafford as radiation protection officer & substituting CA Rowe
GOODWIN, C R , QUEEN, W G Army, Dept of, Headquarters Materiel Development & Readiness Command 78/08/11 Radioisotopes Licensing Branch (Pre 790501) 3pp 18356 023

--8305040468 Forwards Harry Diamond Labs application to amend Matl/ Byproduct Licenses 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-348.
QUEEN, W G Army, Dept of, Headquarters Materiel Development & Readiness Command 78/09/06 Radioisotopes Licensing Branch (Pre 790501) 1p 18356 326

--8305040478 Application for amend to Matl/Byproduct Licenses 19-17250-01, 19-17250-03, 19-17250-05 & SNM-348 Amend requests removal of JE Stafford as radiation protection officer & substitutes CA Rowe.
GOODWIN, C R Army, Dept of 78/08/11 2pp 18356 327

--8305040583 Application for renewal & amend to License SNM-348, including TB Grucci as authorized user
FLYNN, R M Army, Dept of 64/12/30 4pp 18357 036

--8305040586 Notifies that License SNM-348 expires on 650131 Application for renewal should be submitted 30 days prior to expiration of license Notification of nonrenewal should be given by completing encl form W/o encl
NUSSBAUMER, D A Atomic Energy Commission 64/12/19
GOLDSTEIN, B L Army, Dept of 1p 18357 040

--8305040587 Notifies that no action will be taken on Harry Diamond Labs 640417 application to amend License SNM-348, per 640605 telcon
LAYFIELD, R L Atomic Energy Commission 64/06/24 SEIDLER, G Army, Dept of 1p 18357 041

--8305040593 Application for amend to License SNM-348 re periodic leak tests
SIEDLER, G Army, Dept of 64/05/22 Atomic Energy Commission 2pp 18357 042

--8305040599 Application for amend of License SNM-348 to include 5 mCi Pu-239 for Harry Diamond Labs
GOLDSTEIN, B L Army, Dept of 63/12/17 Atomic Energy Commission 3pp 18357 044

--8305040603 Discusses Condition 13 of License SNM-348, in response to 631011 ltr & 631003 telcon Condition 13 does not authorize actual insertion of matl held under license into any reactor Insertions should be authorized
NUSSBAUMER, D A Atomic Energy Commission 63/10/23 BERMAN, P G Army, Dept of 1p 18357 047

--8305040674 Requests cancellation ltr requesting allocation of 99 8% U-235 for use as threshold detector for fast neutron dosimetry
BERMAN, P G Army, Dept of 63/10/11 LAYFIELD, R Atomic Energy Commission 1p 18357 048

--8305040678 Forwards addl info re Harry Diamond Labs application for amend to License SNM-348 per request
GOLDSTEIN, B L Army, Dept of 63/09/13 Atomic Energy Commission 7pp 18357 049

--8305040687 Requests addl info re procedures for use & storage of Np-237, Pu-239 & U-238 fission foils, in response to 630531 request for amend to License SNM-348 for Harry Diamond Labs
NUSSBAUMER, D Atomic Energy Commission 63/07/17 DANIELS, R G Army, Dept of 6pp 18357 056

--8305040696 Requests allocation of 31 g U-235 as metal of 99 8% purity for fission foil fast neutron dosimetry sys for DORF-Triga reactor
BERMAN, P G Army, Dept of 63/08/21 NUSSBAUMER, D A Atomic Energy Commission 1p 18357 062

--8305050292 Requests addl info re procedures for use & storage & description of foils, in response to 630531 application to amend License SNM-348
NUSSBAUMER, D A Atomic Energy Commission 63/07/15 DANIELS, R G Army, Dept of 1p 18357 063

--8305050297 Application for amend to License SNM-348, authorizing possession & use of 13 4 g Np-237, 54 5 g Pu-239, 54 5 g U-235 & 143 g U-238
DANIELS, R G Army, Dept of 63/05/31 Atomic Energy Commission 9pp 18357 064

--8305050301 Notifies that RW McEvoy 621115 ltr made part of records under Docket 70-378 Changes in technical & supervisory personnel having health-safety responsibilities should be provided on continual basis
NUSSBAUMER, D A Atomic Energy Commission 63/01/29 DANIELS, R G Army, Dept of 1p 18357 073

--8305050306 Application for amend to License SNM-348, substituting WL Gieseler for W Hunker as supervisor of instruments incorporating Pu calibr sources
DANIELS, R G Army, Dept of 63/01/22 Atomic Energy Commission 3pp 18357 074

--8305050310 Requests nuclear matl draft re receipt of 5 g Pu foils contained in nuclear accident dosimetry sys
HANSON, G P Army, Dept of 62/11/26 LANE, J Atomic Energy Commission 1p 18357 077

--8305050312 Amend to License SNM-348, revising Item 8 re authorized use of licensed matl
NUSSBAUMER, D A Atomic Energy Commission 62/08/15 DANIELS, R G Army, Dept of 1p 18357 078

--8305050316 Application for amend to License SNM-348, revising Item 8 re calibr of neutron survey meters & designating GP Hanson as authorized matl user
DANIELS, R G Army, Dept of 62/08/07 Atomic Energy Commission 3pp 18357 079

--8305050319 Forwards amended License SNM-348 W/o encl
NUSSBAUMER, D A Atomic Energy Commission 62/02/27 DANIELS, R G Army, Dept of 1p 18357 082

--8305050322 Application for renewal of License SNM-348 for possession & use of 26 g Pu, 12 mg Pu, 1 g Np-237 & 50 g depleted U
DANIELS, R G Army, Dept of 62/01/15 Atomic Energy Commission 1p 18357 083

--8305050326 Notifies that License SNM-348 expires on 620131 Renewal application should be filed within 30 days
NUSSBAUMER, D A Atomic Energy Commission 61/12/01 DANIELS, R G Army, Dept of 1p 18357 085

--8305050328 Forwards diagram of cannister used in nuclear accident dosimetry sys, per telcon request
MCCOSKEY, R E Army, Dept of 61/10/24 NUSSBAUMER, D Atomic Energy Commission 2pp 18357 086

--8305050330 Forwards application to amend License SNM-348, authorizing possession & use of 50 g depleted U, 10 g Pu-239 & 1 g Np-237
DANIELS, R G Army, Dept of 61/10/09 Atomic Energy Commission 3pp 18357 088

--8305050333 Application to amend License SNM-348, authorizing possession & use of addl 12 micrograms Pu in form of calibr devices
KRAUL, C W Army, Dept of 61/05/01 Atomic Energy Commission 2pp 18357 091

--8305050335 Forwards License SNM-348 W/o encl
DELANEY, J C Atomic Energy Commission 60/02/03 HIRMAN, W S Army, Dept of 1p 18357 093

--8305050337 Forwards Diamond Ordnance Fuze Lab 591113 application for SNM license Classification review requested W/o encl
FLEURY, E R Atomic Energy Commission 60/01/28 STRAUSER, W A Atomic Energy Commission 1p 18357 094

--8305050339 Application for amend to License SNM-348, authorizing possession & use of Pu
KRAUL, C W Army, Dept of 59/12/21 Atomic Energy Commission 5pp 18357 095

DOCKET 70-0466 MAINE MARITIME ACADEMY, CASTINE, ME

8305050132 Discusses IE Insp Rept 70-0466/83-01 conducted on 830322 No noncompliance noted Major areas inspected activities re Pu/Be sealed sources
MARTIN, T T Division of Engineering & Technical Programs. 83/05/02 CUMIERSKI, M W Maine Maritime Academy 2pp 18341 351.

DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8305020075 Forwards "Rept on Results of Quarterly Ground Water Monitoring Samples at Waltz Mill Site "
GALM, D T Westinghouse Electric Corp 83/03/30 HAYNES, R C. Region 1, Office of Director 2pp 18308 265

--8305020076 "Rept on Results of Quarterly Ground Water Monitoring Samples at Waltz Mill Site "
* Westinghouse Electric Corp 83/02/28 18pp 18308 267.

DOCKET 70-0712 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

al response to FOIA request for insp repts of safety
t Kerr-McGee Pu plant at Cresant, OK from Aug-
JF Donahue 731102 memo transmitting IE
, 70-1193/73-01 w/portions deleted
ion of Rules and Records 83/03/22 WIDMER, R R.
m 1p 18543 154

usses closeout insp of Licenses SMB-664 & SNM-695 on
ends that licensee be authorized to transfer
ities to unlicensed recipient
mic Energy Commission 66/07/29 DUBINSKI, L
mmission. 4pp 18543 223

--8305230233 Requests authorization to release vacated facilities at Cushing, OK to refining div for unrestricted use Bldgs used by nuclear products dept cleaned & decontaminated Health physics survey indicates contamination below limits
WULLER, G B Kerr-McGee Nuclear Corp 66/06/09 NUSSBAUMER, D A Atomic Energy Commission 4pp 18543 227

DOCKET 70-0734 GA TECHNOLOGIES, INC , SAN DIEGO, CA

8305100127 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE physical security insp rept
NORDERHAUG, L R Region 5, Office of Director 83/05/04 PARKER, J W GA Technologies, Inc /General Atomic Co 1p 18375 018

DOCKET 70-0754 GENERAL ELECTRIC CO , PLEASANTON, CA

8305020520 Forwards Annual Financial Rept 1982
CUNNINGHAM, G E General Electric Co 83/04/04 CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety 1p 18284 337

8305160067 Forwards IE Insp Rept 70-0754/83-01 on 830314-16, 18, 21 & 22 No noncompliance noted
BOOK, H E Region 5, Office of Director 83/04/29 DARMITZEL, R. W General Electric Co 3pp 18453 089

--8305160078 IE Insp Rept 70-0754/83-01 on 830314-16, 18, 21 & 22 No noncompliance noted Major areas inspected organization, facility changes & mods, internal review & audit, radwaste mgt, criticality safety & radiation protection
BROCK, B L , THOMAS, R D , BOOK, H E Region 5, Office of Director 83/04/29 13pp 18453 092.

8305130035 Memorandum & order extending GE time to respond to ASLB 830408 inquiry into license renewal application until 15 days following svc of Commission decision whether to review ALAB-720
FRYE, J H Atomic Safety and Licensing Board Panel 83/05/12 General Electric Co 2pp 18436 315 24X Fiche 50-070, 83/05/12, 8305130035

DOCKET 70-0820 UNITED NUCLEAR CORP , WOOD RIVER JCT , RI

8305260371 Forwards drawings w/marked locations of concrete core samples taken during site characterization survey & drawings showing location of underground piping W/o encl
HELGESON, K A United Nuclear Corp 83/05/06 CROW, W T Office of Nuclear Material Safety & Safeguards, Director 1p 18647.286

DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA

8305020523 Forwards decommissioning plan for facility
OLSEN, A F. Babcock & Wilcox Co 83/03/28 CROW, W T Uranium Fuel Licensing Branch 1p 18284 294

--8305020526 Decommissioning plan for facility
* Babcock & Wilcox Co 83/03/30 27pp 18284 295

DOCKET 70-0846 TEXAS NUCLEAR CORP , AUSTIN, TX

8305030297 Forwards IE Insp Rept 70-0846/83-01 on 830301 No noncompliance noted
BROWN, G D Region 4, Office of Director 83/04/28 Ramsey Engineering Company 2pp. 18298 133

--8305030308 IE Insp Rept 70-0846/83-01 on 830301 No noncompliance noted. Major areas inspected nuclear matl control & accountability, including Facility organization & operation, measurement & controls & shipping & receiving
CALDWELL, R A , EVERETT, R J , KELLY, J. A Region 4, Office of Director 83/04/20. 3pp 18298 135

DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8305120224 Addl response to FOIA request for license applications, license & insp repts re Nuclear Metals, Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6).
FELTON, J M Division of Rules and Records 83/03/01 MOONEY, B C Lowell Sun, Lowell, MA 9pp 18460.050

--8112290557 Ack agreement w/proposed enforcement action per 811016 memo, since revised, based on NRC consultant conclusion that evaluation of U uptake could not establish that regulatory limit was exceeded
THOMPSON, D Enforcement & Investigation Staff (Pre 820201) 81/12/01 KEPPLER, J Region 3, Chicago, Office of the Director (81/03/01) 2pp 18462 107

--8305120656 Forwards Enforcement Guidance Memorandum 81-31 re proposed enforcement action for facility
CARLSON, R T Enforcement & Investigation Staff 81/12/15 STAROSTECKI, R Division of Resident & Project Inspection MARTIN, T T Division of Engineering & Technical Inspection SMITH, G H Division of Emergency Preparedness & Operational Suppport 1p 18462 106

8305180319 Advises of transfer of official docket files & outstanding licensing actions for listed licenses, from U Fuel Licensing Branch to Region III
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 HIND, J A Region 3, Office of Director 1p 18505 075

8305180850 Notifies that official files for License SNM-928 transferred to Region III as of 830401, as part of regional licensing program W/o stated FR notice
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 SHELLEY, W J Kerr-McGee Corp 1p 18506 026

8305200472 Forwards IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted
MILLER, J R Region 3, Office of Director 83/05/17 SHELLEY, W J Kerr-McGee Corp 2pp 18516 112

--8305200482 IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted Major areas inspected facility organization & operations, records & repts & mgt of matl control sys Details withheld (ref 10CFR2 790)
MADEDA, T J , KNICELEY, J R , CREED, J R Region 3, Office of Director 83/05/16 2pp 18516 114

DOCKET 70-0992 DAVID WITHERSPOON, INC , KNOXVILLE, TN

8305180765 Lists official docket file & outstanding licensing action transferred to Region II, effective 830401
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 OLSHINSKI, J A Division of Engineering & Radiological Safety Programs 1p 18506 054

8305180859 Advises that official files for License SNM-992 transferred to Region II due to regionalization, effective 830401
PAGE, R G Uranium Fuel Licensing Branch 83/05/05 WITHERSPOON, D David Witherspoon, Inc 1p 18506 040

DOCKET 70-1007 GENERAL ELECTRIC CO , SAN JOSE, CA

8305020050 Forwards Annual Financial Rept 1982
CUNNINGHAM, G E General Electric Co 83/04/04 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 1p 18285 304

DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NC

8305310109 Ack receipt of 830317 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-1113/83-03
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/06 LONG, J A General Electric Co 1p 18653 117

--8305310115 Responds to NRC 830216 ltr re violation noted in IE Safeguards Insp Rept 70-1113/83-03 Corrective actions withheld (ref 10CFR2.790).
VAUGHAN, C M General Electric Co 83/03/17 STOHR, J P Division of Emergency Preparedness & Materials Safety 1p 18653 118

8305310132 Forwards IE Safeguards Insp Rept 70-1113/83-09 on 830314-18 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/04/06 LONG, J A General Electric Co 2pp 18653 119

--8305310134 IE Safeguards Insp Rept 70-1113/83-09 on 830314-18 No noncompliance noted Major areas inspected records & repts & internal controls. Details withheld (ref 10CFR2 790)
LANKFORD, J.B Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/04/06 1p 18653 121

8305270113 Forwards IE Insp Rept 70-1113/83-08 on 830307-11 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/11 LONG, J A General Electric Co 2pp 18638 225

--8305270116 IE Insp Rept 70-1113/83-08 on 830307-11 No noncompliance noted Major area inspected emergency preparedness
MARSTON, R R Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 83/04/08 7pp 18638 227

8305050168 Forwards revised pages to fundamental nuclear matl control plan Pages withheld (ref 10CFR2 790)
VAUGHAN, C M General Electric Co 83/04/22 O'REILLY, J P Region 2, Office of Director 1p 18341 092

8305270156 Forwards IE Safeguards Insp Rept 70-1113/83-10 on 830404-08 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/27 LONG, J A General Electric Co 2pp 18638 131

--8305270159 IE Safeguards Insp Rept 70-1113/83-10 on 830404-08 No noncompliance noted Major areas inspected MC-852068 measurements & statistical controls Details withheld (ref 10CFR2 790)
CLAY, E L Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/04/27 1p 18638 133

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8304180541 Forwards IE Safeguards Insp Rept 70-1143/83-02 on 830316 No noncompliance noted
MARTIN, T T Division of Engineering & Technical Programs 83/04/05 JACOBI, W M Westinghouse Electric Corp 2pp 17996 159

--8304180554 IE Safeguards Insp Rept 70-1143/83-02 on 830316 No noncompliance noted Major areas inspected physical protection measures for protecting SNM of moderate, strategic significance
SMITH, G C , GODY, A T Region 1, Office of Director 83/04/01 2pp 17996 161

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

8305270450 Ack receipt of 830317 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1151/83-03
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/06 D'AMORE, M Westinghouse Electric Corp 1p 18644 176

--8305270459 Responds to NRC 830215 ltr re viuzation noted in IE Insp Rept 70-1151/83-03 Corrective actions signs identifying nuclear criticality control parameters replaced on 830120
D'AMORE, M Westinghouse Electric Corp 83/03/17 O'REILLY, J P Region 2, Office of Director 2pp 18644 177

--8305270467 Forwards IE Insp Rept 70-1151/83-03 on 830117-21 & notice of violation
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/02/15 D'AMORE, M Westinghouse Electric Corp 2pp 18644 179

--8305270471 Notice of violation from insp on 830117-21
* Region 2, Office of Director 83/02/15 1p 18644 181

--8305270480 IE Insp Rept 70-1151/83-03 on 830117-21 Noncompliance noted failure to post critical control parameters on equipment in SNM areas
CORYELL, G P Region 2, Office of Director MCALPINE, E. J Division of Emergency Preparedness & Materials Safety 83/02/15 5pp 18644 182

8305310120 Ack receipt of 830329 & 10 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1151/83-01
STOHR, J P Division of Emergency Preparedness & Materials Safety. 83/04/12 D'AMORE, M Westinghouse Electric Corp 1p 18656 128

8305270142 Forwards IE Safeguards Insp Rept 70-1151/83-06 on 830411-15 No noncompliance noted
STOHR, J P Division of Project & Resident Programs 83/05/18 BRITTON, W. H Westinghouse Electric Corp 2pp 18638 137

--8305270145 IE Safeguards Insp Rept 70-1151/83-06 on 830411-15 No noncompliance noted Major areas inspected export & import verification & followup on previous insp findings Details withheld (ref 10CFR2 790)
BATES, J W Region 2, Office of Director MCALPINE, E J Division of Project & Resident Programs 83/05/16 1p 18638 139

DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

8305230112 Final response to FOIA request for insp repts of safety violations at Kerr-McGee Pu plant at Cresant, OK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted
FELTON, J M Division of Rules and Records 83/03/22 WIDMER, R R Affiliation Unknown 1p 18543 154

--8305230134 Forwards Regulatory Investigation Rept 70-1193/73-01 on 730917-21 No significant health & safety problems associated w/occurrences reported in allegations
DONAHUE, J F Atomic Energy Commission 73/11/02 FIORELLI, G Atomic Energy Commission 4pp 18543 155

--8305230139 Regulatory Investigation Rept 70-1193/73-01 on 730917-21 Major area investigated anonymous allegations re leaks in Pu waste drums & unsafe practices Info re personnel interviews deleted
DONAHUE, J F , FINN, J A , RIDGWAY, K R Atomic Energy Commission 73/11/01 18pp 18543 159

--8305230179 Discusses licensee employee allegations re spills of Pu & leaking tanks Facility insp w/emphasis on incidents, spills, decontamination & personnel exposures scheduled for 730917
DONAHUE, J F Atomic Energy Commission 73/09/04 Atomic Energy Commission 4pp 18543 177

--8305230186 Updates 730904 memo re licensee employee allegations concerning unsafe working conditions due to possible contamination of work sites Related news articles & press release encl
DONAHUE, J F Atomic Energy Commission 73/09/13 Atomic Energy Commission 10pp 18543 181

--8305230196 Rev 1 to Pu Plant Std Operating Procedure KM-NP-37-2, "Liquid Waste Solidification " Related info encl
MULKIN, R Kerr-McGee Nuclear Corp 72/05/02 31pp 18543 191

8305200472 Forwards IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted
MILLER, J R Region 3, Office of Director 83/05/17 SHELLEY, W J Kerr-McGee Corp 2pp 18516 112

--8305200482 IE Insp Repts 70-0925/83-02 & 70-1193/83-03 on 830502-04 No noncompliance noted Major areas inspected facility organization & operations, records & repts & mgt of matl control sys Details withheld (ref 10CFR2 790)
MADEDA, T J , KNICELEY, J R , CREED, J R Region 3, Office of Director 83/05/16 2pp. 18516 114

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

8305050100 Forwards revised pages to fundamental nuclear matls control plan Revs incorporate reorgnization of matls mgt group change from nuclear power to util power generation group & provide new facility layout Pages withheld (ref 10CFR2 790)
FORD, J T Babcock & Wilcox Co 83/02/28 Region 2, Office of Director 1p 18341 361

8305050205 Forwards revised Pages ii, iii & 1 & revised Figures 2 & 5 to security plan Encl withheld (ref 10CFR2 790)
FORD, J T Babcock & Wilcox Co 83/03/03 Region 2, Office of Director 1p 18338 146

8305270174 Forwards IE Safeguards Insp Rept 70-1201/83-04 on 830321-24 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/22 ALTO, R A Babcock & Wilcox Co 2pp 18638 128

--8305270254 IE Safeguards Insp Rept 70-1201/83-04 on 830321-24 No noncompliance noted Major areas inspected measurement & independent insp effort Details withheld (ref 10CFR2 790)
BATES, J W Region 2, Office of Director MCALPINE, E J Division of Emergency Preparedness & Materials Safety 83/04/20 1p 18638 130

8305310016 Forwards IE Safeguards Insp Rept 70-1201/83-05 on 830405-08 No noncompliance noted
STOHR, J P Division of Emergency Preparedness & Materials Safety 83/04/28 ALTO, R A Babcock & Wilcox Co. 2pp 18653 122

--8305310022 IE Safeguards Insp Rept 70-1201/83-05 on 830405-08 No noncompliance noted Major areas inspected inventory difference & associated limit of error & records & repts Details withheld (ref 10CFR2 790)
JONES, D W , RICHARDS, B L , LANKFORD, J B Region 2, Office of Director 83/04/27 1p 18653 124

8305260376 Application for amend to License SNM-1168 changing health physics & conditions sections re reactor insp sys
FORD, J T Babcock & Wilcox Co 82/05/04 PAGE, R. G Uranium Fuel Licensing Branch 20pp 18647 258

DOCKET 70-1224 TELEFLEX, INC , NORTH WALES, PA

8305050176 Discusses IE Insp Rept 70-1224/83-01 on 830331 & forwards notice of violation
MARTIN, T T Division of Engineering & Technical Programs 83/04/21
ALBOM, I Teleflex, Inc 2pp 18341 118

--8305050182 Notice of violation from insp on 830331 Noncompliance noted required inventory of SNM not conducted & records not maintained
* Region 1, Office of Director 83/04/21 1p 18341 120

DOCKET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA

8305100184 RO on 820403, routine sampling of solutions between top & bottom liners of Lagoon 2 revealed top liner leaking Lagoon emptied, solids removed & liner cleaned Slit & blisters in lining repaired
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp.)
82/05/05 ENGELKEN, R H Region 5, Office of Director. 2pp
18374 316

8305100178 RO on 830113, large quantity of air or gas existed between liners causing large bulge Caused by rotten upper lagoon liner Upper liner patched at deteriorated area
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp.)
83/04/04 ENGELKEN, R H Region 5, Office of Director 2pp.
18374 288

8305180642 Advises that state-approved sys for monitoring fluoride emissions in stack gases operational, satisfying License Condition 20 requirements Determination of line loss as part of std sampling procedure not required
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp),
83/04/19 CROW, W T Uranium Recovery Licensing Branch 2pp
18504 020

--8305180648 "Control & Monitoring of Fluoride Emissions for Exxon Nuclear Fuel Fabrication Facility " Draft Procedure P69261, Rev 1 to XN-NF-103, "Determination of Fluoride as HF in Environ Filters or Liquid Samples," encl
* Exxon Nuclear Co., Inc (subs of Exxon Corp) 83/01/31,
22pp 18504 050

8305030074 Notifies of issuance of Amend 9 to License SNM-1227, authorizing const & operation of liquid waste treatment facilities Condition 9 date for insp of feed tank changed to 830103
PAGE, R G , CROW, W T Uranium Fuel Licensing Branch 83/04/20
MALODY, C W Exxon Nuclear Co , Inc (subs of Exxon Corp) 1p
18326 110

--8305030077 SER supporting Amend 9 to License SNM-1227
BIDINGER, G H Uranium Fuel Licensing Branch 83/04/20 3pp.
18326 111

DOCKET 70-1301 FLORIDA POWER CORP , ST PETERSBURG, FL

8305240034 Submits annual rept re changes, tests & experiments at Morris Operations facility during period 820504-830430, per 10CFR72 35(b)2
EGER, K. J General Electric Co 83/05/02 Region 3, Office of Director 1p 18577 359

DOCKET 70-1308 GENERAL ELECTRIC CO , SAN JOSE, CA

8305170548 Forwards addendum consisting of confirmatory measurements program data sheet of analysis of waste lagoon sample completed after onsite insp, transmitted by 830215 ltr
PAPERIELLO, C J Region 3, Office of Director 83/05/09. VAN HOOMISSEN General Electric Co 2pp 18468 031

8305130227 Forwards IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-02 on 830419-21 No noncompliance noted
MILLER,J R Region 3, Office of Director. 83/05/10 VAN HOOMISSEN General Electric Co 2pp 18439 171

--8305130234 IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-01 on 830419-21 No noncompliance noted Major areas inspected matl control & accountability,measurement & statistical control Details withheld (ref 10CFR2 790)
MADEDA,T J , STAPLETON,B W , CREED,J R Region 3, Office of Director 83/05/10 1p 18439 173

DOCKET 70-1359 IRT CORP , SAN DIEGO, CA

8305230026 Application for amend to License SNM-1405 deleting provision for licensee use of bldg located at 7070 Convoy Court
CROSBIE,K L IRT Corp 83/01/25 PAGE,R G Uranium Fuel Licensing Branch 3pp 18543 126

--8305230033 Requests payment of fee for review of 830125 application for amend to License SNM-1405
WEISS,D License Fee Management Branch 83/03/07 CROSBIE,K L IRT Corp 1p 18543 130

--8305230035 Forwards fee for amend requested in 830125 ltr
CROSBIE,K L IRT Corp 83/03/14 WEISS,D License Fee Management Branch 1p 18543 131

DOCKET 70-1402 ABINGTON MEMORIAL HOSP , ABINGTON, PA

8305050134 Discusses IE Insp Repts 70-1402/83-01,30-02948/83-01 & 30-00453/83-01 on 830315 & forwards notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/04/21 CANDIA,G Abington Radiology Services, Ltd 2pp 18341 348

--8305050140 Notice of violation from insp on 830315 Noncompliance noted one patient implanted w/pacemaker did not have required 6-month followup exam,per Condition 16 (10CFR2,App C) Reply expected within 30 days
* Region 1, Office of Director 83/04/21 1p 18341 350

DOCKET 70-1621 DUQUESNE LIGHT CO., PITTSBURGH, PA

8305120011 Forwards Endorsement 63 to NELIA Policy NF-226 & Endorsement 54 to MAELU Policy MF-87.
BARNETT,J E Conover & Associates, Inc Insurance 83/05/05 DINITZ,J Office of Nuclear Reactor Regulation, Director 3pp 18423 070

DOCKET 70-2926 DETROIT EDISON CO , DETROIT, MI

8305030706 Discusses items of interest,including DOE 830419 visit to NMSS to examine docket files of Kerr-McGee West Chicago Rare Earths Facility & Detroit Edison Co 830419 visit to discuss proposed license conditions for SNM-1915 for fuel storage
PAGE,R G Uranium Fuel Licensing Branch 83/04/20 DAVIS,J G Division of Fuel Cycle & Material Safety 3pp 18309 105

8305170662 Advises that proposed statutory merger of Wolverine Electric Cooperative,Inc & Northern Michigan Electric Cooperative,Inc completed on 821231 Wolverine Power Supply Cooperative,Inc is new company name
TAUBER,H Detroit Edison Co. 83/04/20 SERINI,B L Uranium Fuel Licensing Branch. 1p. 18496 346.

DOCKET 70-2932 TEXAS UTILITIES GENERATING CO , DALLAS, TX

8305170029 Application for amend to License SNM-1912 adding other matls requiring NRC license specifically & seeking authorization to receive,own & use certain byproduct matl in connection w/preoperation & startup activities
GARY,R J. Texas Utilities Generating Co 83/04/11 Office of Nuclear Material Safety & Safeguards,Director 138pp 18494:017.

8305190002 Forwards executed Indemnity Agreement B-96,per 830214 request
COBB,B W Texas Utilities Generating Co 83/04/18. PAGE,R G Uranium Fuel Licensing Branch 14pp 18502.021

DOCKET 70-2953 CONNECTICUT, UNIV OF, STORRS, CT

8304250152 Discusses IE insp of Licenses SNM-1889,06-01450-47 & 06-01450-48 on 830303-04 & forwards notice of violation
MARTIN,T T Division of Engineering & Technical Programs 83/04/11 VAN GELDER,A Connecticut, Univ of 2pp 18179 275

--8304250163 Notice of violation from insp on 830303-04 Noncompliance noted Rooms 302R & 32d containing licensed matl not posted, current copies of Form NRC-3 not posted & Room 472 not secured
* Region 1, Office of Director 83/04/11 1p 18179 277

DOCKET 70-2973 COMMONWEALTH EDISON CO , CHICAGO, IL

8305180787 Executed Indemnity Agreement B-97
SALTZMAN,J Assistant Director for State & Licensee Relations *
Commonwealth Edison Co 83/05/06 13pp 18505 332

8305190004 Forwards Matls License SNM-1917 & safety evaluation License SNM-1917 authorizes receipt,possession,insp & storage of U enriched in U-235 isotope,contained in fuel assemblies
PAGE,R G Uranium Fuel Licensing Branch 83/05/06 TRAMM,T R Commonwealth Edison Co 2pp 18523 221

--8305190006 Matls License SNM-1917,authorizing receipt,possession,insp & storage of U enriched in U-235 isotope contained in fuel assemblies
* Division of Fuel Cycle & Material Safety 83/05/06 3pp 18523 223

--8305190007 Safety evaluation supporting License SNM-1917,authorizing receipt,possession,insp & storage of fuel assemblies containing U enriched to 3 55%
SERINI,B L Uranium Fuel Licensing Branch 83/05/06 12pp 18523 226

8305240339 Forwards executed copy of Indemnity Agreement B-97
OSTER,J Commonwealth Edison Co 83/05/19 SALTZMAN,J Assistant Director for State & Licensee Relations 13pp 18572 342

DOCKET 70-2982 ROCHESTER, UNIV OF, ROCHESTER, NY

8305200139 Forwards License SNM-1918 for Univ of Rochester,authorizing possession of 456 g enriched U,in form of U hexafluride
PAGE,R G Uranium Fuel Licensing Branch 83/05/13 GREGORY,W D Rochester, Univ of, 1p 18540 239

--8305200165 License SNM-1918 for Univ of Rochester authorizing possession of 456 g enriched U as U hexafluoride
PAGE,R G Division of Fuel Cycle & Material Safety 83/05/13 4pp 18540 240

DOCKET 70-2983 PENNSYLVANIA POWER & LIGHT ALLENTOWN, PA

8305180646 Application for license to receive,possess,store,inspect & package for transport nuclear fuel bundle/assemblies Supporting documentation encl
CURTIS,N W Pennsylvania Power & Light Co 83/04/12 Office of Nuclear Material Safety & Safeguards,Director 25pp 18505 204

8305240559 Forwards 830412 application for receipt & storage of new fuel W/o encl
KETZLACH,N Uranium Fuel Licensing Branch 83/05/17 CUTCHIN,J M Office of the Executive Legal Director 1p 18593 337

8305240563 Forwards 830412 application for receipt & storage of new fuel W/o encl
KETZLACH,N Uranium Fuel Licensing Branch 83/05/17 PERCH,R L Licensing Branch 2 1p 18593 327

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0001 ANEFCO, INC

8305040700 Requests addl info re 830315 application for review & approval of Rev 7 to QA program concerning requirements for Anefco shipping packages
MACDONALD,C E Transportation Branch 83/04/29 MURPHY,D J Anefco,Inc 3pp 18336 250

DOCKET 71-0143 RANCHERS EXPLORATION & DEV CO

8305240051 Advises that final testing,balancing adjustment & acceptance of new ventilation sys scheduled for completion by 830630 Entire sys must be rebalanced each time addl process component added to sys
MANSER,W C Nuclear Fuel Services, Inc (subs of Getty Oil Co) 83/05/03 PAGE,R G Uranium Fuel Licensing Branch 2pp 18594 302

DOCKET 71-0166 NEW YORK TESTING LABS, INC

8305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source,Model IR-50 source changer & Model 7 encapsulated source
ROCKETT,D R Babcock & Wilcox Co 83/04/19 MACDONALD,C E Transportation Branch 1p 18594 301

DOCKET 71-0494 MONTANA X-RAY, INC

8304130034 Forwards Montana X-Ray,Inc QA program,implemented for License 25-21134-01 per 10CFR71 12(b)(1)(iii)
STRINGHAM,S D Montana X-Ray, Inc 83/03/05 Office of Nuclear Material Safety & Safeguards,Director 1p 17958 290

--8304130042 QA program for QA procedures,engineering procedures & specific package design approval provisions
STRINGHAM,S D Montana X-Ray, Inc 83/03/05 2pp 17958 291

DOCKET 71-0495 SOUTHWEST X-RAY CORP

8305040671 Forwards QA program for License 42-19788-01
TILLEY,R Southwest X-Ray 83/04/13 MACDONALD,C E Transportation Branch 1p 18336 258

--8305040679 QA program for compliance w/10CFR71,App E
TILLEY,R Southwest X-Ray 83/04/13 3pp 18336 259

8305130256 Forwards QA program approval for Radioactive Matl Package 0495,Rev 0
MACDONALD,C E Transportation Branch 83/05/03 TILLEY,R Southwest X-Ray 1p 18457 172

--8305130261 QA program approval for Radioactive Matl Package 0495,Rev 0
MACDONALD,C E Transportation Branch 83/05/03 1p 18457 173

DOCKET 71-0496 NUS CORP

8305230165 Forwards Revs A & B to QA program manual for packaging used in transport of radioactive matl
MOTL,G P NUS Corp 83/05/02 MACDONALD,C E Transportation Branch 1p 18546 141

--8305230176 Revs A & B to QA program manual for packaging used in transport of radioactive matls
CASELLI,A E , MOTL,G P NUS Corp 83/05/02 91pp 18546:143

DOCKET 71-4986 MODEL RA-2, RA-3, RA-J, GENERAL ELECTRIC CO

8305110015 Notification of registration as user of Model RA-3 in response to 830217 request
MACDONALD,C E Transportation Branch 83/05/03 COUNSIL,W G Northeast Utilities 1p 18421 242

8305170097 Forwards Rev 14 to Certificate of Compliance 4986 for Models RA-2 & RA-3
MACDONALD,C E Transportation Branch 83/05/11 VAUGHAN,C M General Electric Co 2pp 18495 331.

--8305170102 Certificate of Compliance 4986,Rev 14,for Models RA-2 & RA-3
MACDONALD,C E Transportation Branch 83/05/11. 5pp. 18495 333.

DOCKET 71-5026 MODEL CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC

8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded
POPPE,L W Chem-Nuclear Systems, Inc 83/04/14 MACDONALD,C E Transportation Branch 2pp 18496 183

DOCKET 71-5332 MODEL 2030-1, ENERGY, DEPT OF

8305040782 Informs that Certificate of Compliance 5332 for Model 2030-1 shipping package expired on 830131
MACDONALD,C E Transportation Branch 83/04/19 BARRACLAUGH,E Energy, Dept of 1p 18327 245

DOCKET 71-5552 MODEL GAS CYLINDER FIRE IMPACT SHIELD, ENERGY, DEPT

8305260003 Forwards Rev 1 to ORNL/ENG/TM-5, "SAR for Packaging ORNL Gas Cylinder Fire & Impact Shield," final draft
TRAVIS,W H Energy, Dept of 83/04/18 MACDONALD,C E Transportation Branch 2pp 18648 123

--8305260004 Rev 1 to "SAR for Packaging ORNL Gas Cylinder Fire & Impact Shield," final draft W/six oversize drawings Aperture cards are available in PDR
EVANS,J H , LEVINE,D L , EVERBOLE,R E Oak Ridge National Laboratory ORNL/ENG/TM-5 DRF 01 83/04/30 129pp 18648 125

DOCKET 71-5607 MODEL T-2, ENERGY, DEPT OF

8305230080 Forwards revised pages to ANL "T-2 Shipping Package SAR."
MOSER,R M Energy, Dept of 83/04/12 MACDONALD,C E Transportation Branch 3pp 18546 001

--8305230096 "T-2 Shipping Package SAR," revised pages
FRANKLIN,E.M Argonne National Laboratory 83/03/31 137pp 18546 004

8305180626 Documents 830414 telcon re registration for QE T-2 package. No ltr of registration located in files Current validity of NRC 770428 notice of registration questioned
DEIGL,H J Texas A&M Univ , College Station, TX 83/04/18.
MACDONALD,C E Transportation Branch 1p 18505 325

--8305180630 Notification of registration as user of Model QE T-2 in response to 770404 request
MACDONALD,C E. Transportation Branch 77/04/28 RANDALL,J D Texas A&M Univ , College Station, TX 1p. 18505 326

8305230697 Requests clarification as to whether licensee may continue to use QA procedure already approved or whether request for registration should be amended based on mod to inner basket on QE T-2 package
DEIGL,H J Texas A&M Univ , College Station, TX. 83/05/02
MACDONALD,C E. Transportation Branch 1p 18542 325

DOCKET 71-5814 MODEL NRBK-41, -42 & -43, ENERGY, DEPT. OF

8305090048 Forwards Rev 1 to Certificate of Compliance 5814 for Models NRBK-41,NRBK-42 & NRBK-43
MACDONALD,C.E. Transportation Branch 83/04/28 ENGEL,W.P. Energy, Dept of 4pp 18381 176.

--8305090056 Certificate of Compliance 5814,Rev 1,for Models NRBK-41, NRBK-42 & NRBK-43
MACDONALD,C E Transportation Branch 83/04/28 4pp 18381 180

DOCKET 71-5874 MODEL. WAPD-40, ENERGY, DEPT. OF

8305090145 Forwards Rev 1 to Certificate of Compliance 5874 for Model WAPD-40.
MACDONALD,C E. Transportation Branch. 83/04/28 ENGEL,W P Energy, Dept. of. 4pp 18381 113

--8305090150 Certificate of Compliance 5874,Rev 1,for Model WAPD-40
MACDONALD,C E Transportation Branch 83/04/28 3pp 18381 117

DOCKET 71-5875 MODEL WAPD-39 & NRBK-44, ENERGY, DEPT OF

8305090133 Forwards Rev 1 to Certificate of Compliance 5875 for Models WAPD-39 & NRBK-44
MACDONALD,C E Transportation Branch 83/04/28 ENGEL,W P Energy, Dept of 4pp 18381 120

--8305090140 Certificate of Compliance 5875,Rev 1,for Models WAPD-39 & NRBK-44
MACDONALD,C E Transportation Branch 83/04/28 4pp 18381 124

DOCKET 71-5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY

8305230016 Requests registration as user of Model BMI-1
WETHY,C M Florida Power & Light Co 83/04/20 MCDONALD,C E Transportation Branch 1p 18542 256

DOCKET 71-5979 MODEL 5979, ALPHA-OMEGA SERVICES, INC

8305060208 Forwards Rev 4 to Certificate of Compliance 5979 for Model 5979
MACDONALD,C E Transportation Branch 83/04/21 BRADLEY,W. Alpha-Omega Services,Inc 1p 18359 357

--8305060212 Certificate of Compliance 5979,Rev 4,for Model 5979
MACDONALD,C E Transportation Branch 83/04/21 3pp 18359 358

DOCKET 71-5980 MODEL GE-600, GENERAL ELECTRIC CO

8305090113 Forwards Rev 7 to Certificate of Compliance 5980 for Model GE-600
MACDONALD,C E Transportation Branch 83/04/28 CUNNINGHAM,G E General Electric Co 2pp 18381:132

--8305090121 Certificate of Compliance 5980,Rev 7 for Model GE-600
MACDONALD,C E Transportation Branch 83/04/28 6pp 18381 134

DOCKET 71-6244 MODEL 6244, CHEM-NUCLEAR SYSTEMS, INC

8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded
POPPE,L K Chem-Nuclear Systems, Inc 83/04/14 MACDONALD,C E Transportation Branch 2pp 18496 183

DOCKET 71-6272 MODEL 6272, U S ECOLOGY

8305180670 Forwards revised application for amend to Certificates of Compliance 6400 & 6272
MOSER,R M Energy, Dept of 83/04/15 MACDONALD,C E Transportation Branch 2pp 18505 154

--8305180676 Revised application for amend to Certificates of Compliance 6400 & 6272 Approval for special packaged solidified waste as authorized contents in shipping containers requested
* Energy, Dept of 83/04/30 24pp 18505 156

DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING CO , INC

8305030001 Forwards changes to 821217 request for amend of Certificate of Compliance 6294 W/three oversize drawings Aperture cards are available in PDR
FORD,J T Babcock & Wilcox Co 83/04/15 MACDONALD,C E Transportation Branch 55pp 18309,243

8305060187 Forwards Rev 6 to Certificate of Compliance 6294 for Model UNC-2901
MACDONALD,C E Transportation Branch 83/04/25 ESKRIDGE,H K Combustion Engineering, Inc. 2pp 18364 302.

--8305060190 Certificate of Compliance 6294,Rev 6,for Model UNC-2901
MACDONALD,C E Transportation Branch 83/04/25 5pp 18364.304

DOCKET 71-6346 MODEL FSV-1, GENERAL ATOMIC CO

8305090231 Requests registration as user of Model FSV-1
KALIVIANAKIS,N Commonwealth Edison Co 83/04/15 MACDONALD,C E Transportation Branch 1p 18381 101

8305170586 Notification of registration as user of Model FSV-1 in response to 830415 request
MACDONALD,C E Transportation Branch 83/05/09 KALIVIANAKIS,N Commonwealth Edison Co 1p 18496 107

DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP

8305180670 Forwards revised application for amend to Certificates of Compliance 6400 & 6272
MOSER,R M Energy, Dept of 83/04/15 MACDONALD,C E Transportation Branch 2pp 18505 154

--8305180676 Revised application for amend to Certificates of Compliance 6400 & 6272 Approval for special packaged solidified waste as authorized contents in shipping containers requested
* Energy, Dept of 83/04/30 24pp 18505 156

DOCKET 71-6495 MODEL PADUCAH DEMONSTRATION CASK, ENERGY

8305160278 Forwards request for addl info re 821117 application requesting approval of model Paducah demonstration cask packaging Response must be received within 30 days of ltr receipt
MACDONALD,C E Transportation Branch 83/05/06 PRICHARD,R P Energy, Dept of 3pp 18475 038

DOCKET 71-6550 MODEL 6-GB-1, ENERGY, DEPT OF

8305240552 Forwards Certificate of Compliance 6550,Rev 0,for Model 6-GB-1
HARVEY,R V Lawrence Berkeley Laboratory 83/05/03 MACDONALD,C E Transportation Branch 1p 18594 220

--8305240556 Certificate of Compliance 6550,Rev 0,for Model 6-GB-1
MACDONALD,C E Transportation Branch 83/05/03 2pp 18594 221

DOCKET 71-6553 MODEL PADUCAH TIGER, ENERGY, DEPT OF

8305040791 Informs that Certificate of Compliance 6553 for Paducah Tiger shipping package expired on 830331
MACDONALD,C.E Transportation Branch 83/04/19 BLALOCK,L Energy, Dept of 2pp 18327 194

8305240064 Requests extension of Certificate of Compliance 6553 for use in moving U hexafluoride between gaseous diffusion plants Leak test data forthcoming
PRICHARD,R P Energy, Dept of 83/04/29 MACDONALD,C E Transportation Branch 1p 18577 361

DOCKET 71-6601 MODEL CNS 8-120, CHEM-NUCLEAR SYSTEMS, INC

8305020535 Requests mailing address change for BD Withers
* Portland General Electric Co 83/04/08 NRC - No Detailed Affiliation Given 1p 18284 258

8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded
POPPE,L K Chem-Nuclear Systems, Inc 83/04/14 MACDONALD,C E Transportation Branch 2pp 18496 183

8305170589 Notification of registration as user of Model CNS 8-120 in response to 830304 request
MACDONALD,C.E Transportation Branch 83/05/09 COONEY,M J Philadelphia Electric Co 1p 18496 105

DOCKET 71-6639 MODEL MH-1A, ENERGY, DEPT OF

8305180210 Responds to 830224 ltr requesting addl info re approval of Model MH-1A Estimates that 4 months will be required to respond to questions Packaging engineers will arrange meeting to discuss request
PRICHARD,R P Energy, Dept. of 83/04/20 MACDONALD,C E Transportation Branch 1p 18503 331

8305170573 Summary of 830502 meeting w/DOE & Sandia in Silver Spring, MD re review of SAR for 820907 MH-1A application
ODEGAARDEN, R H Transportation Branch 83/05/06 Transportation Branch 2pp 18496 124

DOCKET 71-6708 MODEL C-6, ENERGY, DEPT OF

8305090214 Informs that Certificate of Compliance 6708 for Model C-6 shipping package expired on 821031
MACDONALD, C Transportation Branch 83/04/19 PETERSON, J M Energy, Dept of 1p 18381 110

DOCKET 71-6717 MODEL 6717-B, GAMMA INDUSTRIES

8305020061 Requests registration as user of Gulf Nuclear 10X, 20V, U-110A & Gamma Industries Models C-10 & Century & Pipeliner 1
TILLEY, R Southwest X-Ray 83/04/13 MACDONALD, C E Transportation Branch 1p 18308 286

8305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source, Model IR-50 source changer & Model 7 encapsulated source
ROCKETT, D R Babcock & Wilcox Co 83/04/19 MACDONALD, C E Transportation Branch 1p 18594 301

8305110023 Notification of registration as user of Model 6717-B in response to 830413 request
MACDONALD, C E Transportation Branch 83/05/03 TILLEY, R Sooner X-Ray & Mag , Inc 1p 18411 357

DOCKET 71-9010 MODEL NLI-1/2, NL INDUSTRIES, INC

8305170108 Forwards Rev 9 to Certificate of Compliance 9010 for Model NLI-1/2
MACDONALD, C E Transportation Branch 83/05/10 JOHNSON, C R Nuclear Assurance Corp 3pp 18495 348

--8305170113 Certificate of Compliance 9010, Rev 9, for Model NLI-1/2
MACDONALD, C E Transportation Branch 83/05/10 8pp 18495 351

DOCKET 71-9015 MODEL TN-8, -8L, NO USERS

8305230107 Forwards Rev 1 to second addendum to TN-8/9 SAR
GOLDMANN, K Transnuclear, Inc 83/05/03 MACDONALD, C E Transportation Branch 1p 18546 303

--8305230118 Forwards Rev 1 to second addendum of TN-8 & TN-9 SAR Issuance of Rev 3 to Certificate of Compliance 9015 for Models TN-8 & TN-8L packaging requested
GOLDMANN, K Transnuclear, Inc 83/04/26 MACDONALD, C E Transportation Branch 2pp 18546 304

--8305230125 Rev 1 to "TN-8 & TN-9 SAR, Second Addendum for TN-8 & TN-8L Packagings "
* Transnuclear, Inc E-3508 R01 83/04/26 33pp 18546 307

8305170245 Forwards Rev 4 to Certificate of Compliance 9015 for Models TN-8 & TN-8L
MACDONALD, C E Transportation Branch 83/05/12 GOLDMANN, K Transnuclear, Inc 1p 18493 343

--8305170251 Certificate of Compliance 9015, Rev 4, for Models TN-8 & TN-8L
MACDONALD, C E Transportation Branch 83/05/12 7pp 18493 344

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

8305170738 Application for registration as user of Tech/OPs Model 660
KAWACHI, M Navy, Dept of, Pearl Harbor Naval Shipyard 83/02/11 MACDONALD, C E Transportation Branch 1p 18496 182

DOCKET 71-9044 MODEL QE-1600, GENERAL ELECTRIC CO

8305110143 Notification of registration as user of Model QE-1600 in response to 830331 request
MACDONALD, C E Transportation Branch 83/05/06 JONES, W C Omaha Public Power District 1p 18421 349

DOCKET 71-9049 MODEL QE-500, GENERAL ELECTRIC CO

8305110021 Notification of registration as user of Model QE-500 in response to 830412 request
MACDONALD, C E Transportation Branch 83/05/03 STEIN, S B Advanced Medical Systems, Inc 1p 18411 358

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

8305180019 Application for exemption from requirement of Certificate of Compliance 9070 for Model N-55 Requests one time shipment of Pu fluoride neutron source containing 35 Ci Pu-238 in encapsulated form
NARDI, A J Westinghouse Electric Corp 83/04/29 MACDONALD, C E Division of Fuel Cycle & Material Safety 3pp 18497 200

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

8305040147 Advises that encl Hittman Nuclear & Development Corp 830406 proprietary application & associated repts & drawings re Model HN-100, Series 2 package design should be placed in PDR, per 830216 ltr
MACDONALD, C E Transportation Branch 83/04/25 SCOTT, S Document Management Branch 1p 18336 231

--8305040159 Forwards addl info to support 830216 request that HN-100, Series 2 casks be included in renewal of Certificate of Compliance 9079 Rev 6 to "Cask Handling Procedure for HN-100, Series 2 & Series 3 " encl
MALLORY, C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/06 MACDONALD, C Transportation Branch. 3pp. 18336 232

--8305040176 Rev 6 to "Cask Handling Procedure for HN-100, Series 2 & Series 3 Shielded Transport Casks " W/three oversize drawings Aperture cards are available in PDR
* Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/06 15pp 18336 235

8305110211 Notification of registration as user of Model HN-100 Series 2 in response to 830401 request
MACDONALD, C E Transportation Branch 83/05/06 MINECK, D L Iowa Electric Light & Power Co 1p 18411 352

DOCKET 71-9080 MODEL 9080, HITTMAN NUCLEAR & DEVELOPMENT CORP.

8305180816 Requests registration as user of Model 9080 radioactive matls shipping cask
MIS, F J Rochester Gas & Electric Corp 83/04/21 MACDONALD, C E Transportation Branch 1p 18505 356

8305110019 Notification of registration as user of Model 9080 in response to 830218 request
MACDONALD, C E Transportation Branch 83/05/03 FAY, C W. Wisconsin Electric Power Co 1p 18411 359

DOCKET 71-9081 MODEL CNSI 1-13C, CHEM-NUCLEAR SYSTEMS, INC

8305170587 Notification of registration as user of Model CNS 1-13C in response to 830228 request
MACDONALD, C E Transportation Branch 83/05/09 BORST, F J Public Service Co of Colorado 1p 18496 106

DOCKET 71-9096 MODEL CNS 21-300, CHEM-NUCLEAR SYSTEMS, INC

8305160280 Forwards request for addl info supporting 830228 application for amend to Model CNS 21-300 Response should include drawings, shielding & operating procedures & acceptance tests Response requested within 30 days
MACDONALD, C E Transportation Branch 83/05/03 POPPE, L K Chem-Nuclear Systems, Inc 3pp 18475 008

DOCKET 71-9100 MODEL KKP-20-4950, KERR-MCGEE NUCLEAR CORP

8305030181 Requests registration as user of Model KKP-20-4950.
O'HEA, P B. Rhone-Poulenc, Inc 83/04/14. MACDONALD, C. E Transportation Branch 1p 18310 030

8305110150 Forwards Rev 2 to Certificate of Compliance 9100 for Model KKP-20-4950
MACDONALD,C E Transportation Branch 83/05/06 SHELLEY,W J
Kerr-McGee Nuclear Corp 2pp 18434 105

--8305110151 Certificate of Compliance 9100,Rev 2,for Model KKP-20-4950
MACDONALD,C E Transportation Branch 83/05/06 4pp 18434 107

DOCKET 71-9103 MODEL NLI-6502, NO USERS

8305110011 Forwards Rev 3 to Certificate of Compliance 9103 for Model NLI-6502
MACDONALD,C E Transportation Branch 83/05/03 JOHNSON,C R
Nuclear Assurance Corp 1p 18421 243

--8305110013 Certificate of Compliance 9103,Rev 3 for Model NLI-6502
MACDONALD,C E Transportation Branch 83/05/03 5pp 18421 251

DOCKET 71-9105 MODEL RAD-WASTE CR I, CHEM-NUCLEAR SYSTEMS, INC

8305030716 Forwards Rev 2 to Certificate of Compliance 9105 for Model RAD-WASTE CARRIER I
MACDONALD,C E Transportation Branch 83/04/25 DEAL,R
Chem-Nuclear Systems, Inc 4pp 18309 075

--8305030720 Certificate of Compliance 9105,Rev 2,for Model RAD-WASTE CARRIER I
MACDONALD,C E Transportation Branch 83/04/25 2pp 18309 079

DOCKET 71-9106 MODEL BW-20WC-3, BABCOCK & WILCOX CO

8305040772 Informs that Certificate of Compliance 9106 for Model BW-20WC-3 shipping package expired on 830228
MACDONALD,C E Transportation Branch 83/04/19 CORDANI,R A
Babcock & Wilcox Co 1p 18327 299

DOCKET 71-9111 MODEL CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC

8305170733 Requests amend to Certificates of Compliance 6244,9111,6601 & 5026 allowing fissile matls in byproduct matl providing 10CFR170 limits are not exceeded
POPPE,L K Chem-Nuclear Systems, Inc 83/04/14 MACDONALD,C E
Transportation Branch 2pp 18496 183

8305110017 Notification of registration as user of Model CNS 6-80-2 in response to 830314 request
MACDONALD,C E Transportation Branch 83/05/03 MUSOLF,D
Northern States Power Co 1p 18411 360

DOCKET 71-9135 MODEL CENTURY S & SA, CEN UNIV S & SA, GAMMMA IND

8304270399 Ack receipt of response to error notice for Model C-10 Identical typographical error observed on Page 5 of 820430 safety evaluation
RIDDLE,D H Nuclear System 83/04/08 MACDONALD,C E
Transportation Branch 1p 18244 311

8305230104 Requests registration as user of Model Century S & SA
ENGBLOM,M R Hardy Associates, Inc 83/04/18 MACDONALD,C E
Transportation Branch 1p 18546 342

8305050436 Forwards revised Page 5 to SER on Model Century series packaging per 830408 ltr
MACDONALD,C E Transportation Branch 83/04/26 RICHARDSON,H D
Nuclear System 2pp 18352 049

DOCKET 71-9148 MODEL 770, TECHNICAL OPERATIONS, INC.

8305170592 Notification of registration as user of Model 770 in response to 830323 request
MACDONALD,C E Transportation Branch, 83/05/09 CUNNINGHAM,G E
General Electric Co 1p 18496 103

DOCKET 71-9150 MODEL PAT-2, ENERGY, DEPT OF

8305180684 Forwards application for amend to Certificate of Compliance 9150 revising operational controls for shipping Pu safeguards samples
CAUDLE,R E Energy, Dept of 83/04/19 CUNNINGHAM,R F Division of Fuel Cycle & Material Safety 2pp 18504 073

--8305180688 Application for amend to Certificate of Compliance 9150, revising operational controls for shipping Pu safeguards samples
* Sandia Laboratories 83/04/30 33pp 18504 076

DOCKET 71-9151 MODEL HN-100, SERIES 3, HITTMAN NUCLEAR & DEV CORP

8305230730 Submits rev to Paragraph 5(b)(2) of revised Certificate of Compliance 9151 for Model HN-100 Series 3 re max quantity of matl
MALLORY,C W Hittman Corp 83/04/29 MACDONALD,C Transportation Branch 3pp 18576 175

8305170591 Notification of registration as user of Model CNS 14-170 in response to 830228 request
MACDONALD,C E Transportation Branch 83/05/09 MUSOLF,D
Northern States Power Co 1p 18496 104

8305170255 Forwards Rev 2 to Certificate of Compliance 9151 for Models HN-100 Series 3 & CNS 14-170 Series 3
MACDONALD,C E Transportation Branch 83/05/12 SILLYMAN,D
Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 18493 351

--8305170260 Certificate of Compliance 9151,Rev 2,for Model HN-100 Series 3 & CNS-14-170 Series 3
MACDONALD,C E Transportation Branch 83/05/12 5pp 18493 353

8305260350 Advises that encl Hittman Nuclear & Development Corp 830427 ltr re 830203 application for amend to Certificate of Compliance 9151 & associated proprietary SARs & drawings should be placed in PDR
MACDONALD,C E Transportation Branch 83/05/13 SCOTT,S Document Management Branch 1p 18648 025

--8305260355 Forwards addl info supporting 830203 application for amend to Certificate of Compliance 9151 to permit use of stainless steel shielding insert,in response to NRC request W/four oversize drawings Aperture cards are available in PDR
MALLORY,C W Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/27 MACDONALD,C Transportation Branch 6pp 18648 026

--8305260373 Rev 7 to "Cask Handling Procedure for HN-100 Series 2 & Series 3 Shielded Transport Casks "
* Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/26 16pp 18648 032

DOCKET 71-9156 MODEL, IR-50, INDUSTRIAL NUCLEAR CO

8305240046 Requests registration as user of Model C-10 source changer, Model T-3-T encapsulated source,Model IR-50 source changer & Model 7 encapsulated source
ROCKETT,D R Babcock & Wilcox Co 83/04/19 MACDONALD,C E
Transportation Branch 1p 18594 301

DOCKET 71-9163 MODEL GNG-20, GULF NUCLEAR, INC

8305240031 Forwards revised info re Model GNG-20 source container
HOPCRAFT,C P Gulf Nuclear, Inc 83/04/28 MACDONALD,C.E
Transportation Branch 35pp 18594 224

DOCKET 71-9175 MODEL CNS6-80B, NUCLEAR PACKAGING, INC

8305060133 Releases Nuclear Packaging,Inc 830304 application for certificate of compliance,SAR & drawings to public W/o drawings
MACDONALD,C E Transportation Branch 83/04/25 SCOTT,S Document Management Branch 1p 18354 029

--8305060142 Responds to 830318 request for addl application fee for certificate of compliance Intent is to limit payload so Model CNS 6-80B can be licensed under Category IIC so no addl fee required.
STREUTKER,S R Nuclear Packaging, Inc 83/03/24 JACKSON,G
License Fee Management Branch 2pp 18354 030

--8305060148 Application for certificate of compliance for Model CNS6-80B bulk resin shipping flask
STREUTKER, S R Nuclear Packaging, Inc 83/03/04 MACDONALD, C E
Transportation Branch 8pp 18354 032

--8305060152 "SAR for CNS 6-80B Shielded Cask to 10CFR71 Type B Packaging Requirements "
* Nuclear Packaging, Inc 83/03/04 226pp 18354 040

--8305060154 Requests addl fee re 830304 application for certificate of compliance for Model CNS6-80B bulk resin shipping flask
JACKSON, G License Fee Management Branch 83/03/18
STREUTKER, S R Nuclear Packaging, Inc 2pp 18354 266

DOCKET 71-9177 MODEL NUPAC 10/140, NUCLEAR PACKAGING, INC

8305020002 Forwards Rev 0 to Certificate of Compliance 9177 for Model NUPAC 10/140
MACDONALD, C E Transportation Branch 83/04/18 SIMCHUK, J D
Nuclear Packaging, Inc 1p 18308 289

--8305020004 Certificate of Compliance 9177, Rev 0, for Model NUPAC 10/140
MACDONALD, C E Transportation Branch 83/04/18 12pp
18308 290

--8305020008 Safety evaluation approving use of Model Series A waste shipping packages for shipment of low-specific activity radioactive matl
MACDONALD, C E Transportation Branch 83/03/28 9pp 18308 293

DOCKET 71-9180 MODEL 500-SU, AUTOMATION INDUSTRIES, INC

8305180194 Forwards addl info on operating instructions, acceptance criteria & general maint for Model 500SU-OP, per 830411 request
SANTORO, M P Automation Industries, Inc 83/04/21 MACDONALD, C E
Transportation Branch 6pp 18503 324

DOCKET 71-9181 MODEL PAS-2, NUCLEAR PACKAGING, INC

8305040096 Releases Nuclear Packaging, Inc 830331 application for certificate of compliance & SAR for placement in PDR
MACDONALD, C E Transportation Branch 83/04/25 SCOTT, S Document Management Branch 1p 18331 267

--8305040105 Application for certificate of compliance for NUPAC Post-Accident Sampling Cask PAS-2
STREUTKER, S R Nuclear Packaging, Inc 83/03/31
Transportation Branch 4pp 18331 268

--8305040110 "SAR for NUPAC PAS-2 Packaging to 10CFR71 Type B Packaging Requirements "
* Nuclear Packaging, Inc 83/03/31 91pp 18331 272

DOCKET 71-9510 MODEL GPHS, ENERGY, DEPT OF

8305020036 Forwards info on shipping cylinder for GPHS module & welding & insp procedures, in response to NRC 820930 request W/three oversize drawings Aperture cards are available in PDR
MILLER, R L Energy, Dept of 83/04/18 MACDONALD, C E
Transportation Branch 10pp 18308 251

DOCKET 71-9788 MODEL S5W REACTOR COMPARTMENT, ENERGY, DEPT OF

8305110612 Forwards Rev 0 to Certificate of Compliance 9788 for Model S5W reactor compartment
MACDONALD, C E Transportation Branch 83/05/06 ENGEL, W P
Energy, Dept of 1p 18415 354

--8305110614 Certificate of Compliance 9788, Rev 0, for Model S5W reactor compartment
MACDONALD, C E Transportation Branch 83/05/06 4pp 18415 355.

DOCKET 71-9901 MODEL 120, ENERGY, DEPT OF

8305040786 Notifies that Certificate of Compliance 9901 for Model 120 shipping package expired on 830228
MACDONALD, C E Transportation Branch 83/04/19 PETERSON, J M.
Energy, Dept of 1p 18327 196

8305110033 Forwards Rev 1 to Certificate of Compliance 9901 for Model 120
MACDONALD, C E Transportation Branch 83/05/06 PETERSON, J M
Energy, Dept of 1p 18421 304

--8305110035 Certificate of Compliance 9901, Rev 1, for Model 120
MACDONALD, C E Transportation Branch 83/05/06 6pp 18421 305

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

8305240034 Submits annual rept re changes, tests & experiments at Morris Operations facility during period 820504-830430, per 10CFR72 35(b)2
EGER, K J General Electric Co 83/05/02 Region 3, Office of Director 1p 18577 359

8305170548 Forwards addendum consisting of confirmatory measurements program data sheet of analysis of waste lagoon sample completed after onsite insp, transmitted by 830215 ltr
PAPERIELLO, C J Region 3, Office of Director 83/05/09 VAN HOOMISSEN General Electric Co 2pp 18468 031

8305130227 Forwards IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-02 on 830419-21 No noncompliance noted
MILLER, J R Region 3, Office of Director 83/05/10 VAN HOOMISSEN
General Electric Co 2pp 18439 171

--8305130234 IE Safeguards Insp Repts 70-1308/83-02 & 72-0001/83-01 on 830419-21 No noncompliance noted Major areas inspected matl control & accountability, measurement & statistical control. Details withheld (ref 10CFR2 790)
MADEDA, T J , STAPLETON, B W , CREED, J R Region 3, Office of Director 83/05/10 1p 18439 173

NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS

8305020529 Unofficial transcript of Commission 830426 public meeting re possible vote on restart in Washington,DC Pp 1-107
* Commissioners. 83/04/26 127pp 18284 075 24X
Fiche 50-272,83/04/26,8305020529

8305040054 Discusses status of B&W-GPU lawsuit document review Next rept expected within 2 wks
DIRCKS,W J Office of the Executive Director for Operations
83/04/20 PALLADINO,N , GILINSKY,V. , AHEARNE,J Commissioners
2pp 18336,325 24X Fiche 50-289,83/04/20,8305040054

--8305040068 Staff requirements memo re 830330 briefing on investigation & possible enforcement action IE requested to submit investigation results based on review of all documents for new info within 3 wks.
CHILK,S J Office of the Secretary of the Commission M830330B
83/04/08 DIRCKS,W J Office of the Executive Director for Operations HAYES,B.B. NRC - No Detailed Affiliation Given
CUMMINGS,J.J Office of Inspector & Auditor 2pp 18336 327
24X Fiche 50-289,83/04/20,8305040054

8305040086 Transcript of 830422 briefing in Washington,DC re TMI-2 cleanup Pp 1-98
* Commissioners 83/04/22 124pp. 18328 242 24X
Fiche 50-320,83/04/22,8305040086

8305040755 Transcript of Commission 830427 public meeting in Washington,DC re midyr program review,Pp 1-90
* Commissioners 83/04/27 50pp 18351 260.

8305060696 Staff requirements memo re Nuclear Waste Policy Act of 1982 (ref SECY-83-107)
CHILK,S J Office of the Secretary of the Commission M830318
83/03/28. DIRCKS,W J Office of the Executive Director for Operations. 2pp. 18358.128.

--8305060700 Discusses co-location of test & evaluation facility & geologic repository,per 830318 Commission briefing on Nuclear Waste Policy Act of 1982 Related info encl
DIRCKS,W J Office of the Executive Director for Operations.
83/04/05 CHILK,S J Office of the Secretary of the Commission
15pp. 18358.130

8305090512 Responds to 830406 staff requirements memo re briefing on DHR studies on C-E plants.Investigation will be completed by 830630 & results of study,conclusions & recommendations will be presented to Commission by Aug-Sept.
DIRCKS,W.J. Office of the Executive Director for Operations.
83/04/25. CHILK,S.J Office of the Secretary of the Commission.
1p. 18381.246.

--8305090516 Staff requirements memo re 830404 briefing on DHR studies on C-E plants.Commission requested NRC accelerate study & solicit & address ACRS views on issue
CHILK,S.J Office of the Secretary of the Commission M830404
83/04/04. DIRCKS,W J Office of the Executive Director for Operations. 1p. 18381 249

8305090645 Transcript of Commission 830504 briefing on state of nuclear industry in Washington,DC Pp 1-47.Supporting documentation encl
* Commissioners 83/05/04 88pp 18366.017

8305110604 Transcript of Commission 830429 briefing in Washington,DC re U mill tailings stds.Pp 1-61 Viewgraphs encl
* Commissioners. 83/04/29. 62pp. 18421:001.

8305120611 Board Notification 83-59 forwards info re component cooling water sys discussed at 830419 meeting w/PG&E in San Francisco,CA
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 3pp 18440 228 24X
Fiche 50-275,83/05/04,8305120611.

--8305120621 Transcript of 830419 public meeting in San Francisco,CA re review of component cooling water sys Pp 1-121
* Commissioners 83/04/19 123pp 18440 231 24X
Fiche 50-275,83/05/04,8305120611

8305130327 Transcript of Commission 830505 meeting,discussion & possible vote in Washington,DC re status of emergency planning at facilities Pp 1-22
* Commissioners 83/05/05 27pp 18457 277 24X
Fiche.50-247,83/05/05,8305130327

8305170089 Transcript of Commission 830512 meeting in Washington,DC to discuss evaluation of implications of Salem event (Part 1) Pp 1-78 Supporting documentation encl
* Commissioners 83/05/12 81pp 18495 226 24X
Fiche 50-272,83/05/12,8305170089

8305170192 Transcript of Commission 830512 meeting in Washington,DC to discuss Regulatory Task Force administrative proposals re backfit rule Pp 1-78 Supporting documentation encl
* Commissioners 83/05/12 87pp 18492 213

8305180076 Transcript of Commission 830513 affirmation/discussion & vote in Washington,DC re proposed rule on storage & disposal of high level waste Pp 1-5.
* Commissioners 83/05/13 6pp 18499.350

8305180082 Transcript of Commission 830512 affirmation/discussion & vote on SECY-83-157 concerning facility OL in Washington,DC Pp 1-4
* Commissioners 83/05/12 7pp 18503 279 24X
Fiche 50-322,83/05/12,8305180082

8305180391 Transcript of Commission 830513 public meeting w/ACRS in Washington,DC to discuss severe accident research program & accident source term program Pp 1-66
* Commissioners. 83/05/13 66pp 18482 041

8305230130 Transcript of Commission 830518 public meeting in Washington,DC re evaluation of implications of facility event (Part I) Pp 1-82.Supporting documentation encl
* Commissioners. 83/05/18 97pp 18577 110 24X
Fiche 50-272,83/05/18,8305230130

8305240566 Releases transcript of Commission 821222 discussion & possible vote on emergency planning actions for placement in PDR,per 10CFR9 Commission determination statement encl
CHILK,S J Office of the Secretary of the Commission 83/05/18
Public Document Branch 2pp 18593 063 24X Fiche 50-003,83/05/18,
8305240566

--8305240570 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners 82/12/22. 15pp 18593 065. 24X
Fiche 50-003,83/05/18,8305240566

--8305240574 Transcript of 821222 discussion & possible vote on emergency planning actions in Washington,DC
* Commissioners. 82/12/22. 59pp 18593.082. 24X
Fiche.50-003,83/05/18,8305240566

8305250256 Staff requirements memo re 830504 briefing on state of nuclear industry in Washington,DC
CHILK,S J Office of the Secretary of the Commission M830504A.
83/05/05 Office of the Secretary of the Commission. 1p
18595 343.

8305250305 Requests info on why resolution of Unresolved Issue A-17 will precede Unresolved Issue A-47 since both items are closely related Response requested by 830517 using std question & answer format
FUNCHES, J. L. Planning & Program Analysis Staff 83/05/11
SPEIS, T P. Division of Safety Technology 2pp 18594 356

--8305250308 Staff requirements memo re 830427 midyr program review on info requested on number of people & dollars necessary to handle Waste Mgt Act as well as questions Chairman Palladino will be addressing by separate memo
CHILK, S. J Office of the Secretary of the Commission M830427 83/05/06 DIRCKS, W J Office of the Executive Director for Operations. 3pp 18594 358

8305250588 Responds to 830415 staff requirements memo re schedule for decision on license amend request to permit operation of steam generators. Schedule for decision contingent upon outcome of significant hazards determination
DIRCKS, W J Office of the Executive Director for Operations 83/05/19 CHILK, S. J Office of the Secretary of the Commission 9pp 18594:337 24X Fiche 50-289, 83/05/19, 8305250588

--8305250590 Staff requirements memo re 830415 briefing on status of TMI-1 steam generator repairs Commission requested info on differing dates for decision on license amend request depending on significant hazards determination
CHILK, S J. Office of the Secretary of the Commission. M830415B 83/04/25 DIRCKS, W. J. Office of the Executive Director for Operations. 1p. 18594 346 24X Fiche 50-289, 83/05/19, 8305250588.

8305260195 Transcript of Commission 830523 affirmation/discussion & vote in Washington, DC re SECY 83-117, 83-059 & 83-059B
* Commissioners 83/05/23 14pp 18648.074

8305270041 Transcript of Commission 830523 briefing on NRC comments on EPA proposed Title II Stds (U mill tailings) in Washington, DC. Pp 1-90 Viewgraphs encl
* Commissioners. 83/05/23 94pp 18661 363

8305310055 Transcript of Commission 830523 discussion of Indian Point order in Washington, DC Pp 1-19.
* Commissioners 83/05/23 23pp 18663 128 24X
Fiche 50-247, 83/05/23, 8305310055.

8305310071 Transcript of Commission 830524 briefing in Washington, DC re NRC revalidation of mgt competence for restart Pp 1-57
Viewgraphs encl
* Commissioners 83/05/24 73pp 18663 025 24X
Fiche 50-289, 83/05/24, 8305310071

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

8304140158 Summary of ACRS CRBR Subcommittee meeting on 821027 in Washington, DC re plant design criteria; rationale of selection of DBA spectrum & associated prevention/ mitigation sys & plant safeguards & security
* ACRS - Advisory Committee on Reactor Safeguards 82/10/29
ACRS - Advisory Committee on Reactor Safeguards 21pp 18541·047
24X Fiche 50-537, 82/10/29, 8304140158

8305020087 Transcript of ACRS Subcommittee on Reactor Radiological Effects 830428 meeting in Washington, DC Pp 1-298 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/04/28.
512pp 18279 279.

8305020174 Transcript of ACRS Subcommittee on GE Water Reactors, GESSAR-II 830422 meeting in Santa Monica, CA Pp 361-609. Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 83/04/22
357pp 18281 299 24X Fiche 50-447, 83/04/22, 8305020174

8305030327 Transcript of ACRS Subcommittee on Reactor Radiological Effects 830429 hearing in Washington, DC Pp 299-567 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 83/04/29
310pp 18297.183.

8305040552 Notification of contract execution· "Extreme External Phenomena Subcommittee," awarded to George Washington Univ.
HOYLE, A Administrative Contracts Branch FIN B-1557
NRC-11-83-703. 83/04/25. FRALEY, R F. ACRS - Advisory Committee on Reactor Safeguards SAVIO, R. NRC - No Detailed Affiliation Given
1p. 18351 234.

--8305040553 Contract "Extreme External Phenomena Subcommittee," awarded to George Washington Univ
FOX, R. R George Washington Univ. REBELLO, J E. Division of Contracts. FIN B-1557. NRC-11-83-703 83/04/25 4pp
18351:235

8305090366 Comments on proposed plan for regionalization of certain NRC operations reviewed during ACRS 274th, 275th & 276th meetings on 830210-12, 0310-12 & 0414-16 respectively Potential negative impact on reactor safety discussed.
EBERSOLE, J. C ACRS - Advisory Committee on Reactor Safeguards
83/04/19 PALLADINO, N J Commissioners 3pp 18367.216

8305100164 Transcript of ACRS LACBWR SEP Subcommittee 830506 hearing in Washington, DC Pp 1-166 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/06
229pp 18370 265 24X Fiche 50-409, 83/05/06, 8305100164

8305120001 Transcript of ACRS Subcommittee on Electrical Sys 830510 hearing in Washington, DC Pp 1-155. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/10
231pp 18428 001

8305120002 Transcript of ACRS Subcommittee on ECCS 830510 hearing in Washington, DC, Pp 1-294 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/10.
379pp 18423 077

8305120127 Transcript of ACRS Subcommittee on AC/DC Power Sys 830510 meeting in Washington, DC. Pp 1-173 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/10
232pp. 18422:004.

8305120556 "Consultant Rept for ACRS Review of CRBR Thermal Margin Beyond Design Basis."
POWERS, D. A Sandia Laboratories POWERS, D. A ACRS - Advisory Committee on Reactor Safeguards. 83/05/10 30pp. 18443·090 24X Fiche·50-537, 83/05/10, 8305120556.

8305120562 Summary of 269th ACRS meeting on 820909-11 re safety goals for nuclear power plants.
* ACRS - Advisory Committee on Reactor Safeguards 83/05/05.
ACRS - Advisory Committee on Reactor Safeguards. 239pp 18442:211.

8305130005 Transcript of ACRS Subcommittee on Safety Research Program 830511 meeting in Washington, DC Pp 1-322. Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/11.
399pp 18438 132.

8305130015 Transcript of ACRS Combined Subcommittees on Reliability & Probabilistic Assessment & Extreme External Phenomena 830511 meeting in Washington, DC. Pp 1-136 Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/11
188pp. 18436.020.

8305130290 Summary of 268th ACRS meetings on 820812-14 in Washington, DC
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/05
ACRS - Advisory Committee on Reactor Safeguards. 529pp. 18458:225
24X Fiche: 50-000, 83/05/05, 8305130290.

8305130321 Comments on ACRS Equipment Qualification Subcommittee 830315 meeting. Mild environs need attention, equipment vibration qualification incomplete & plant aging research required.
CATTON, I. ACRS - Advisory Committee on Reactor Safeguards.
83/04/04. CAPPUCCI, A. J ACRS - Advisory Committee on Reactor Safeguards. 1p 18457 307

8305130326 Comments on NUREG/CR-3324 items Unprotected transient overpower accident & unprotected loss-of-flow accident should be reviewed at ACRS full committee meeting.
KASTENBERG, W. E ACRS - Advisory Committee on Reactor Safeguards.
83/03/28. CARBON, M ACRS - Advisory Committee on Reactor Safeguards 4pp. 18457·303.

8305130340 Responds to ACRS 830315 meeting request for comments on qualification program for safety-related equipment Analysis of equipment in mild & extreme environs, comparative seismic stresses & electrical distribution sys recommended.
LIPINSKI, W. C. Argonne National Laboratory LIPINSKI, W. C. ACRS - Advisory Committee on Reactor Safeguards 83/03/28. EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 2pp. 18457.338.

8305130346 Comments on qualification program for ACRS Subcommittee on Safety-Related Equipment 830315 meeting.
PICKEL, T. W. Union Carbide Corp. PICKEL, T W ACRS - Advisory Committee on Reactor Safeguards. 83/03/23. CAPPUCCI, A J. ACRS - Advisory Committee on Reactor Safeguards. 2pp 18443:340.

8305130347 Concurs w/NRC & applicant position establishing Cape Ann earthquake as controlling earthquake for facilities
Supporting documentation encl.
MAXWELL, J C Maxwell, J C MAXWELL, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/05 KERR, W ACRS - Advisory Committee on Reactor Safeguards 5pp 18443:335 24X Fiche 50-443, 83/05/05, 8305130347

8305130349 Submits comments on core disruptive accidents & seismic margins per request made at ACRS 830316-17 meetings
Applicant energetic source term acceptable Seismic margin calculations not acceptable
LIPINSKI, W C Argonne National Laboratory LIPINSKI, W C ACRS - Advisory Committee on Reactor Safeguards 83/03/31 CARBON, M W ACRS - Advisory Committee on Reactor Safeguards. 5pp 18457 340 24X Fiche 50-537, 83/03/31, 8305130349.

8305130350 Comments on seismic design safety margin for facility Addl comments to be made at ACRS 830414 meeting
SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS - Advisory Committee on Reactor Safeguards 83/03/31 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards. 3pp. 18443 357 24X Fiche 50-537, 83/03/31, 8305130350.

8305130352 Informs of uneasiness on selection of 1755 Cape Ann earthquake as facility std for design response spectra.
Critical safety-related components should be designed to withstand larger Charleston event.
POMEROY, P.W Rondout Associates. POMEROY, P. W. ACRS - Advisory Committee on Reactor Safeguards 83/04/05 KERR, W. ACRS - Advisory Committee on Reactor Safeguards 2pp. 18443:333 24X Fiche. 50-443, 83/04/05, 8305130352.

8305130355 Provides input re seismic safety margins for CRBR, based on ongoing seismic safety margins research program at lab.
BOHM, M P Lawrence Livermore Laboratory. BOHM, M. P. ACRS - Advisory Committee on Reactor Safeguards. SB-83-78/0911U. 83/04/08
CARBON, M ACRS - Advisory Committee on Reactor Safeguards. 6pp 18443:326 24X Fiche 50-537, 83/04/08, 8305130355

8305130359 Telecopy of comments on CRBR re pressure boundary Design of reactor pressure vessel meets & usually exceeds requirements of ASME III & relevant code cases.
BUSH, S H Battelle Memorial Institute, Pacific Northwest Laboratory
BUSH, S H ACRS - Advisory Committee on Reactor Safeguards 83/03/30. CARBON, M. ACRS - Advisory Committee on Reactor Safeguards. 2pp 18443:324 24X Fiche: 50-537, 83/03/30, 8305130359

8305160030 Transcript of ACRS 277th general meeting on 830512 in Washington, DC. Pp 1-241. Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/05/12 315pp. 18452 023

8305160246 Comments on SSMRP risk analysis. Risks from seismic events should be analyzed separately from internal events w/results treated independently. Only upper limits need be estimated to determine if risks acceptable.
DAVIS, P.R. Affiliation Unknown DAVIS, P.R ACRS - Advisory Committee on Reactor Safeguards. 83/04/16. OKRENT, D ACRS - Advisory Committee on Reactor Safeguards 1p. 18472.001 24X Fiche. 50-295, 83/04/16, 8305160246.

8305160299 Forwards rept summarizing review of TMBDB presentation at ACRS 830310-11 meetings Review confined to thermomechanics, engineering design & finite element analysis. Review will be summarized at 830414 meeting.
ANDERSON, C.A. Los Alamos Scientific Laboratory ANDERSON, C A. ACRS - Advisory Committee on Reactor Safeguards G-13-83 163. 83/03/29
CARBON, M ACRS - Advisory Committee on Reactor Safeguards. 6pp. 18472:069 24X Fiche: 50-537, 83/03/29, 8305160299.

8305170301 Transcript of ACRS 277th general meeting on 830513 in Washington, DC Pp 242-438 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards. 83/05/13 321pp. 18463:188

8305180391 Transcript of Commission 830513 public meeting w/ACRS in Washington, DC to discuss severe accident research program & accident source term program. Pp 1-66
* Commissioners 83/05/13. 66pp. 18482:041

8305180620 Summary of ACRS Subcommittees on Metal Components & TMI-1 830128 meeting in Washington, DC re review of potential steam generator generic requirements & current steam generator repair program
* ACRS - Advisory Committee on Reactor Safeguards. 83/04/12.
ACRS - Advisory Committee on Reactor Safeguards. 19pp. 18504:001. 24X Fiche: 50-289, 83/04/12, 8305180620

8305180637 Expresses appreciation for opportunity to participate in CRBR project review Seismic safety margin estimates probably conservative Failure of small diameter pipes will be discussed
SEIDENSTICKER Argonne National Laboratory SEIDENSTICKER ACRS - Advisory Committee on Reactor Safeguards 83/04/15 CARBON, M ACRS - Advisory Committee on Reactor Safeguards 1p 18505 329 24X Fiche 50-537, 83/04/15, 8305180637

8305180664 Summary of ACRS 830223 meeting w/Subcommittee on SEP in Washington, DC to review facility integrated safety assessment
* ACRS - Advisory Committee on Reactor Safeguards ACRS-2078 83/04/07. ACRS - Advisory Committee on Reactor Safeguards 18pp 18502 327 24X Fiche 50-029, 83/04/07, 8305180664

8305180668 Summary of ACRS Subcommittee on Regulatory Policy & Procedures 830207 & 08 meetings in Washingon, DC re briefing by Regulatory Reform Task Force, Ofc of General Counsel & Ad Hoc Committee on Regulatory Reform
* ACRS - Advisory Committee on Reactor Safeguards 83/04/14
ACRS - Advisory Committee on Reactor Safeguards 12pp 18505 062

--8305180674 Summary of ACRS 830208 meeting w/Subcommittee on Regulatory Policy & Procedures in Washington, DC re Ofc of Executive Director briefing on concept of regionalization
* ACRS - Advisory Committee on Reactor Safeguards. 83/04/14
ACRS - Advisory Committee on Reactor Safeguards 3pp 18505 071

--8305180678 Certifies minutes of ACRS Subcommittee on Regulatory Policy & Procedures 830207-08 meetings issued on 830331
LEWIS, H ACRS - Advisory Committee on Reactor Safeguards 83/03/31 GASKE, M C Deputy Executive Legal Director. 1p 18505 074

8305230002 Transcript of ACRS Subcommittee on Human Factors 830319 meeting in Washington, DC Pp 1-290 Supporting documentation encl
* ACRS - Advisory Committee on Reactor Safeguards 83/03/19 369pp. 18533 273

8305240033 Forwards comments on ACRS Subcommittee on Reactor Radiological Effects 830428 meeting re use of potassium iodine as thyroid blocking agent. NRC risk/benefit analyses not compatible w/comparable approaches.
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/17 DIRCKS, W J. Office of the Executive Director for Operations 26pp 18577 333

8305250074 Comments on Task IC 126-5, "Reg Guide on Instrument Sensing Lines," dtd 821108 Provisions of guide & referenced std not to be backfitted to nuclear plants now operating or under const
EBERSOLE, J C. ACRS - Advisory Committee on Reactor Safeguards. 83/05/23. DIRCKS, W J. Office of the Executive Director for Operations 1p 18596.306

8305250078 Clarifies major concerns w/plan for regionalization of certain NRC operations, per 830210-12, 0310-12, 0414-16 & 0512-14 ACRS 274-277th meetings
EBERSOLE, J. C ACRS - Advisory Committee on Reactor Safeguards 83/05/16 PALLADINO, N J Commissioners 2pp. 18596:309

8305260008 Comments on recent work & proposed programs re accident sequence precursor study & use of operational experience, at 276th & 277th ACRS meetings on 830414-16 & 0512-14 respectively.
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/05/18. DIRCKS, W J. Office of the Executive Director for Operations. 7pp 18649:098

8305260104 Forwards summary of ACRS Subcommittee on Reactor Radiological Effects 830428 meeting re control room habitability. Evaluation of potential need for monitoring oxygen concentrations recommended
EBERSOLE, J. C. ACRS - Advisory Committee on Reactor Safeguards 83/05/17. DIRCKS, W J. Office of the Executive Director for Operations 5pp 18649:068

8305310162 Transcript of ACRS Subcommittee on Joint Metal Components/ Reactor Fuel 830526 meeting in Washington, DC. Pp 1-217. Supporting documentation encl.
* ACRS - Advisory Committee on Reactor Safeguards 83/05/26 325pp 18651:306.

ADVCM NRC ADVISORY COMMITTEE

8305230006 Forwards draft ltrs to individuals willing to appear at next advisory committee meeting in order to expedite preparation for 830526 meeting.
LEVI, R P. NRC - No Detailed Affiliation Given 83/04/29.
BILBERT, E. J Schwalb, Donnenfeld, Bray & Bilbert 3pp. 18542 215

--8305230010 Forwards transcript of Advisory Committee on Rights of Licensee Employees Under Investigation 830413 meeting, copy of committee charter & questions for committee in response to E Silbert request
LEVI, R P. Office of the General Counsel 83/04/29 DEVINE, T Institute for Policy Studies 1p 18542 219

--8305230012 Discusses possibility of having investigators from other agencies testify at Advisory Committee on Rights of Employees Under Investigation 830526 meeting re procedures & practices
SILBERT, E S Schwalb, Donnenfeld, Bray & Silbert 83/05/03 FITZGERALD, J A Office of Investigation REUBHAUSEN, O Debevoise & Plimpton SCOTT, J B Kator, Scott & Heller 2pp 18542 220

--8305230017 Confirms appearance at Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting. Transcript of last meeting, list of questions for committee & committee charter encl
LEVI, R P NRC - No Detailed Affiliation Given 83/05/04 SHOOP, P. Affiliation Unknown 1p 18542 222

--8305230025 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting
LEVI, R P. NRC - No Detailed Affiliation Given 83/05/03. REUBHAUSEN, O Debevoise & Plimpton 1p 18542:223

--8305230032 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting
LEVI, R P NRC - No Detailed Affiliation Given. 83/05/05. SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert. 1p 18542 224.

--8305230040 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting
LEVI, R P NRC - No Detailed Affiliation Given. 83/05/05 SCOTT, J B. Kator, Scott & Heller. 1p. 18542 225.

--8305230048 Forwards draft FR notice announcing Advisory Committee on Rights of Licensee Employees Under Investigation 830526 meeting
LEVI, R P. NRC - No Detailed Affiliation Given. 83/05/05 SPRITZER, R S Pennsylvania, Univ. of. 5pp 18542.226

8305230384 Submits questions Advisory Committee on Rights of Employees Under Investigation should address to aid in deliberations.
PALLADINO, N J Commissioners 83/04/11 SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert 2pp. 18543:360.

COMMISSION NRC COMMISSIONERS

8305040138 Forwards proposed Chairman testimony before Udall Subcommittee 830406 hearing re developments since Apr 1982 at TMI, responding to items in Congressman Udall 830413 ltr. W/o proposed testimony
DENTON, H R. Office of Nuclear Reactor Regulation, Director. 83/04/20 DIRCKS, W J. Office of the Executive Director for Operations 2pp 18327:011 24X Fiche. 50-289, 83/04/20, 8305040138.

--8305040145 Enumerates items to be addressed by Commission at Subcommittee on Energy & Environ 830426 oversight hearing on major developments at TMI since last hearing in Apr 1982
UDALL, M K House of Rep , Interior & Insular Affairs. 83/04/13 PALLADINO, N Commissioners 2pp. 18327.013 24X Fiche: 50-289, 83/04/20, 8305040138

8305040777 Weekly info rept for wk ending 830422.
REHM, T A Office of the Executive Director for Operations 83/04/29 42pp 18327:257

8305110135 Weekly info rept for wk ending 830429.
REHM, T A Office of the Executive Director for Operations. 83/05/06 47pp 18421 257.

8305170717 Weekly info rept for wk ending 830506.
REHM, T. A Office of the Executive Director for Operations. 83/05/12. 42pp. 18496.202

8305230121 Weekly info rept for wk ending 830513.
REHM, T. A Office of the Executive Director for Operations. 83/05/20. 44pp. 18577:066

8305230354 Forwards rept on nondisclosure of safeguards info for quarter ending Mar 1983.
PALLADINO, N J. Commissioners 83/05/06. BUSH, G H. Senate. O'NEILL, T. P House of Rep. 5pp 18542:001.

8305230360 Responds to 830406 ltr re basis for not implementing or enforcing codified U mill licensing regulations contained in App A to 10CFR40. Prior approval from Committee on Appropriations sought appropriating spending funds
PALLADINO, N J Commissioners 83/05/05 UDALL, M. K House of Rep., Interior & Insular Affairs. 2pp 18542 007

--8305230369 Expresses concern re status of implementation & enforcement of U mill licensing regulations to have been effective beginning 830101
UDALL, M K. House of Rep , Interior & Insular Affairs. 83/04/06 PALLADINO, N J Commissioners 2pp 18542:009

8305230377 Responds to questions in 830323 ltr re steam generator tube rupture scenario at TMI-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items provided on 830325
PALLADINO, N J Commissioners 83/05/05 MARKEY, E J House of Rep., Interior & Insular Affairs 8pp 18683:307 24X Fiche: 50-289, 83/05/05, 8305230377

--8305230388 Requests further response to issues in 830121 ltr re steam generator tube degradation at TMI-1 & Subcommittee on Oversight & Investigation 821213 hearing Updated status of TMI action plan items also requested.
MARKEY, E. J House of Rep., Interior & Insular Affairs. 83/03/23. PALLADINO, N J Commissioners 2pp 18542:019. 24X Fiche: 50-289, 83/05/05, 8305230377

8305230384 Submits questions Advisory Committee on Rights of Employees Under Investigation should address to aid in deliberations.
PALLADINO, N J. Commissioners 83/04/11. SILBERT, E. J. Schwalb, Donnenfeld, Bray & Silbert. 2pp 18543:360

8305230397 Responds to 830330 request for views on S. B 388, creating offense for aggravated property destruction at energy facility. Position not taken as legislation not applicable to facilities under NRC jurisdiction.
PALLADINO, N J. Commissioners 83/05/05. THURMOND, S Senate, Judiciary Committee. 1p. 18542 021

--8305230406 Requests views on encl S. B 388 to create offense for aggravated property destruction at energy facility. Response requested within 20 days.
THURMOND, S Senate, Judiciary Committee 83/03/30. PALLADINO, N. J. Commissioners 4pp. 18542:022.

8305230413 Advises of Commission decision not to make any changes in present structure for provision of legal svcs within Commission; in response to request in House Rept 97-850. Commissioners Gilinsky & Roberts advocate further study.
PALLADINO, N J. Commissioners 83/05/05. BEVILL, T. House of Rep., Appropriations. 1p 18542:026

8305230420 Responds to 830314 ltr urging implementation of spent fuel provisions of Nuclear Waste Policy Act (P. L 97-425). Proposed rule 10CFR53, "Criteria for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity" encl
PALLADINO, N. J. Commissioners. 83/04/27. RILEY, R. W. South Carolina, State of. 2pp. 18542:027.

--8305230425 Proposed rule 10CFR53, "Criteria & Procedures for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity."
CHILK, S J Office of the Secretary of the Commission. 83/04/26. 20pp 18542.029.

--8305230428 Urges vigorous implementation of spent fuel provisions of Nuclear Waste Policy Act (P. L. 97-425) & development of proposed rule re criteria for determining if util qualifies for emergency federal storage of spent fuel.
RILEY, R. W. South Carolina, State of. 83/03/14. PALLADINO, N. J. Commissioners. 2pp. 18542.049.

8305230435 Forwards response to Question 20 in 830223 ltr re NRC review of B&W/OPU trial record.
PALLADINO, N J. Commissioners 83/04/28. UDALL, M K. House of Rep., Interior & Insular Affairs 2pp 18542:051 24X Fiche: 50-289, 83/04/28, 8305230435.

--8305230440 Informs of dissenting opinion re Commission majority decision blocking General Counsel review of B&W/OPU trial record in TMI-1 restart proceeding. Decision will hamper ability of individual Commissioners to obtain needed info.
GILINSKY, V. Commissioners. 83/04/07 SIMPSON, A. K. Senate, Environment & Public Works. 2pp. 18542:053. 24X Fiche: 50-289, 83/04/28, 8305230435.

--8305230443 Responds to Chairman Palladino 830309 request for views on legality of Commission decision directing Executive Director for Operations, rather than Ofc of General Counsel, to review B&W/GPU trial record Actions supported
PLAINE, H H E Office of the General Counsel 83/03/25
PALLADINO, N J , GILINSKY, V , AHEARNE, J Commissioners 5pp
18542 055 24X Fiche 50-289, 83/04/28, 8305230435

--8305230446 Provides Commission response to Commissioner Gilinsky 830407 ltr disagreeing w/Commission majority decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding Commission actions justified
PALLADINO, N J Commissioners 83/04/19 UDALL, M K House of Rep., Interior & Insular Affairs 4pp 18542 060 24X
Fiche 50-289, 83/04/28, 8305230435

--8305230453 Disagrees w/Commission majority views in Chairman Palladino 830419 ltr justifying Commission decision to block General Counsel review of B&W/GPU trial record in TMI-1 restart proceeding
ASSELSTINE, J K Commissioners 83/04/25 UDALL, M K House of Rep , Interior & Insular Affairs 3pp 18542 064 24X
Fiche 50-289, 83/04/28, 8305230435

8305230457 Forwards NRC "Rept to Congress on Study of Financial Impacts on Resident Inspectors "
PALLADINO, N. J Commissioners 83/04/29 OTTINGER, R L House of Rep , Energy & Commerce SIMPSON, A Senate, Environment & Public Works UDALL, M K House of Rep , Interior & Insular Affairs 3pp
18542:067.

--8305230461 "Rept to Congress on Study of Financial Impacts on Resident Inspectors "
* NRC - No Detailed Affiliation Given 83/03/31 81pp
18542·070

8305230465 Responds to 830322 ltr discussing activities of ANS Special Committee on Source Terms Info meeting to present work of committee welcomed
PALLADINO, N. J Commissioners 83/05/02 STRATTON, W R. American Nuclear Society. 1p. 18542:151

--8305230469 Discusses activities of ANS Special Committee on Source Terms Meeting to discuss source term issue & present work of committee proposed
STRATTON, W. R American Nuclear Society 83/03/22 PALLADINO, N J Commissioners. 2pp 18542·152

8305230474 Forwards "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness, Jan-Mar 1983 "
PALLADINO, N J. Commissioners. GIUFFRIDA, L O Federal Emergency Management Agency 83/05/03 SIMPSON, A K. Senate, Environment & Public Works. 2pp. 18542·154

--8305230479 "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness, Jan-Mar 1983. "
* NRC - No Detailed Affiliation Given * Federal Emergency Management Agency 83/03/31. 59pp 18542.156

8305230660 Forwards current long-range research plan, in response to 830325 request for info on ongoing & anticipated research activities using existing source terms
PALLADINO, N J Commissioners 83/04/21 BOUGARD, M House of Rep., Science & Technology. 3pp 18542 333

--8305230664 Ack receipt of 830104 response to request for Commission views on implementing recommendations in committee rept on NRC research program (H R 97-795) List of ongoing & anticipated research activities requested
BOUGUARD, M. L. House of Rep., Science & Technology 83/03/25.
PALLADINO, N. Commissioners. 3pp. 18542.336

8305230670 Advises that state can choose to offset or substitute compensatory planning measures in lieu of local level emergency plan per cited conditions. NUREG-0654-FEMA-REP-1, Rev 1 stds would place heavy resource burden on state.
GIUFFRIDA, L. O Federal Emergency Management Agency 83/04/18.
PALLADINO, N. J Commissioners. 1p 18542·329. 24X
Fiche·50-003, 83/04/18, 8305230670.

--8305230676 Seeks clarification of issue re FEMA review of offsite emergency planning around facilities Questions whether state can substitute for county w/o own emergency plan.
PALLADINO, N. J Commissioners. 83/03/30. GIUFFRIDA, L O. Federal Emergency Management Agency 2pp. 18542:330. 24X
Fiche:50-003, 83/04/18, 8305230670.

8305230692 Comments on H R. 600 re federal monitoring, analysis, reporting & policy on foreign acquisition of US businesses & assets in vital & sensitive natl interest sectors of economy, in response to 830218 ltr. NRC cannot support bill as drafted.
PALLADINO, N. J. Commissioners. 83/04/20 BROOKS, J. House of Rep , Government Operations. 2pp. 18543:063.

--8305230695 Forwards H R 600 for comment Transmittal of reply in triplicate requested
BROOKS, J House of Rep , Government Operations 83/02/18
PALLADINO, N J Commissioners 61pp 18543 065

8305230703 Urges resolution of remaining questions re facility restart Delay in resolving restart issue unacceptable when jobs at stake Restart issue should receive high priority this Spring
BROYHILL, J T , MOORHEAD, C J , RITTER, D House of Rep , Energy & Commerce 83/03/16 PALLADINO, N Commissioners 3pp 18542 317
24X Fiche 50-289, 83/03/16, 8305230703

8305230732 Concurs w/830307 ltr re informal resolution of NRC response to Congressional correspondence Senior Commission staff may sign responses involving submittal of factual info, per 830218 ltr
PALLADINO, N J Commissioners 83/04/13 MARKEY, E J House of Rep , Interior & Insular Affairs 1p 18542 260

--8305230735 Objects to Congressional response procedure outlined in 830218 ltr. Commission should be accountable to members of Congress for accuracy & completeness of info Commissioners requested to review issues
MARKEY, E J House of Rep , Interior & Insular Affairs 83/03/07
PALLADINO, N J Commissioners 2pp. 18542 261

8305240019 Responds to 830418 ltr recommending retention of technical cadre of experts to review CRBR & overall DOE breeder program Maint of CRBR Program Ofc at adequate level planned. Decision on issuance of CP expected by June 1984
DIRCKS, W J Office of the Executive Director for Operations
83/05/10 LLOYD, M House of Rep , Science & Technology 3pp
18577 308 24X Fiche 50-537, 83/05/10, 8305240019

--8305240023 Recommends that Commission retain technical cadre of experts to review CRBR & overall DOE breeder program
LLOYD, M House of Rep , Science & Technology 83/04/18
PALLADINO, N J Commissioners 1p. 18577 310 24X
Fiche 50-537, 83/05/10, 8305240019

8305240075 Discusses study of significant hazards consideration posed by reracking of spent fuel pools, in response to 830414 memo. Science Applications, Inc will provide independent assessment. Final rept will be submitted by 830801
DIRCKS, W J. Office of the Executive Director for Operations
83/05/06 PALLADINO, N , GILINSKY, V. , AHEARNE, J F Commissioners
3pp 18594·305

--8305240084 Requests description of plans for completing study on potential significant hazards of spent fuel pool reracking amends Description should include study approach & schedules for assuring submittal of final study by 830801
PALLADINO, N J Commissioners 83/04/14 DIRCKS, W J Office of the Executive Director for Operations 1p 18594 308

8305240155 Ack receipt of 830315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis
PALLADINO, N J Commissioners 83/04/22 SIMPSON, A K House of Rep., Environment & Public Works 2pp 18594 001

--8305240167 Ack receipt of 830315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis
PALLADINO, N Commissioners 83/04/22. HART, G. House of Rep , Environment & Public Works. 2pp. 18594 003

--8305240179 Ack receipt of 830315 & 24 ltrs expressing concern re Commission treatment of license amend requests concerning reracking of spent fuel storage pools in interim final rule Amend requests examined on case-by-case basis.
PALLADINO, N J. Commissioners 83/04/22 MITCHELL, G J House of Rep , Environment & Public Works 2pp. 18594·005

--8305240190 "Stds for Determining Whether License Amends Involve No Significant Hazards Considerations," 10CFR50 interim final rule. Amends regulation to specify stds for determining if requested amend to OL involves significant hazards
CHILK, S J Office of the Secretary of the Commission 83/04/04
44pp 18594.007.

--8305110584 Discusses Sholly provision in FY82-83 NRC Authorization Act re treatment of amends to rerack spent fuel storage pools Treatment unacceptable
SIMPSON, A K., HART, G., MITCHELL, G J Senate, Environment & Public Works 83/03/15 PALLADINO, N J Commissioners 3pp. 18594 051

--8305110601 Confirms 830323 telcon re proposed regulations for Shelly provision on amends to rerack spent fuel storage pools Proposed case-by-case exam for reracking unacceptable MITCHELL, O J Senate 83/03/24 PALLADINO, N J Commissioners 2pp 18594 054

8305240216 Advises that 830323 ltr requesting immediate halt to all work at TMI-1 & 2, w/exception of maint necessary for safety, will receive consideration as request for action under 10CFR2.206 FR notice encl. DENTON, H R Office of Nuclear Reactor Regulation, Director 83/05/17 KING, R. Three Mile Island Public Interest Resource Center 2pp 18593 306. 24X Fiche 50-289, 83/05/17, 8305240216

--8305240220 Notice of request for action under 10CFR2 206 re immediate halt to work at TMI-1 & 2 DENTON, H R Office of Nuclear Reactor Regulation, Director. 83/05/17 1p 18593 308 24X Fiche 50-289, 83/05/17, 8305240216.

8305240252 Responds to 821207 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All NRC ofcs will comply w/FOIA request. Request Requests will be coordinated w/Ofc of General Counsel PALLADINO, N J Commissioners. 83/04/14 UDALL, M K. House of Rep , Interior & Insular Affairs 7pp. 18594 131 24X Fiche 50-358, 83/04/14, 8305240252

--8305240256 Responds to 830302 ltr re processing of T Applegate FOIA request for documents on investigation into alleged const deficiencies All FOIA requests will be coordinated w/Ofc of General Counsel Commissioners views encl PALLADINO, N J Commissioners. 83/04/14 SEIBERLING, J F House of Rep , Interior & Insular Affairs 12pp 18594 138 24X Fiche 50-358, 83/04/14, 8305240252

--8108250739 Submits minor organizational change & reaffirms previously established administrative procedures. CUMMINGS, J J. Office of Inspector & Auditor 80/06/20. Office of Inspector & Auditor 2pp. 18594 150

--8305240263 Discusses investigation of Applegate allegations. "Adequacy of IE Investigation 50-358/80-09 at WH Zimmer Nuclear Power Station," per Udall 821207 ltr IE investigation found unsatisfactory in Aug 1981 T Harpster interview encl CUMMINGS, J J Office of Inspector & Auditor 83/01/05 BICKWIT, L Office of the General Counsel. 8pp. 18594.153 24X Fiche 50-358, 83/04/14, 8305240252

--8305240267 Forwards addl info re NRC withholding of T Harpster interview w/Govt Accountability Project 811123 FOIA request, per Commission 830207 instructions CUMMINGS, J Office of Inspector & Auditor. 83/02/16 MALSCH, H G Office of the General Counsel 6pp 18594 163 24X Fiche 50-358, 83/04/14, 8305240252

--8305240272 Requests info re Ofc of Inspector & Auditor (OIA) inquiry into Zimmer matter Reasons for removal of documents from OIA ofcs questioned Withholding of documents contributed to delay in public recognition of true status of project. UDALL, M K. House of Rep , Interior & Insular Affairs 82/12/07 PALLADINO, N J. Commissioners. 1p 18594 169 24X Fiche 50-358, 83/04/14, 8305240252

--8305240275 Requests addl info re 821207 ltr seeking explanation of circumstances surrounding compliance w/FOIA request for documents pertaining to facility Adequacy of Cummings reply questioned UDALL, M , SIEBERLING, J. House of Rep., Interior & Insular Affairs 83/03/02. PALLADINO, N Commissioners. 2pp 18594.170 24X Fiche 50-358, 83/04/14, 8305240252

8305250311 Responds to 830414 request for info re frequency of reactor scrams for US plants & explanation why comparable Japanese plants experience fewer reactor scrams. Table providing number of trips experienced for 1980, 81 & 82 encl DIRCKS, W J Office of the Executive Director for Operations. 83/05/04. AHEARNE, J Commissioners. 9pp 18595:317

--8305250313 Requests info re trips per yr per plant for US plants for last 3 yrs of operation & explanation why Japanese plants experience fewer trips. AHEARNE, J. Commissioners 83/04/14. Office of the Executive Director for Operations. 1p 18595.327

CONTRACT NRC CONTRACTS AND MODIFICATIONS

8305030707 Corrected notification of contract execution, Mod 3 to "Earthquake Recurrence Intervals at Nuclear Power Plant Sites " Contractor: Ertec Western, Inc GUSTAVE, R P Technical Assistance Contracts Branch FIN B-7226. NRC-04-81-167 83/04/14 BATSON, W Office of Nuclear Regulatory Research, Director. MURPHY, A NRC - No Detailed Affiliation Given 1p 18309 104

8305040280 Notification of contract execution, Mod 6 to "Electrostatic Copying Svcs " Contractor: Literature Research Co SMITH, P. A Division of Contracts NRC-10-79-361 83/04/25. BESAW, W. J Division of Technical Information & Document Control. BAGGETT, M NRC - No Detailed Affiliation Given 1p 18326.345

--8305040284 Mod 6, deobligating balance of funds for closeout, to "Electrostatic Copying Svcs " BULLINGTON, R L Literature Research Corp. SMITH, P A Division of Contracts NRC-10-79-361. 83/04/25 1p 18326.346.

8305040341 Notification of contract execution, Mod 10 to "Career Counseling." Contractor. Binder, Elster, Mendelson & Wheeler, Inc SMITH, P. A Division of Contracts. NRC-10-79-387 83/04/28. SPRINGER, M. Office of Administration. TAYLOR, K. Management Development & Training Staff. 1p 18326.333

--8305040345 Mod 10, deobligating balance of funds remaining under contract for official closeout, to "Career Counseling." MENDELSON, I N. Binder, Elster, Mendelson & Wheeler, Inc. SMITH, A. Division of Contracts NRC-10-79-387. 83/04/28 1p. 18326:334.

8305040552 Notification of contract execution: "Extreme External Phenomena Subcommittee," awarded to George Washington Univ HOYLE, A. Administrative Contracts Branch FIN B-1557. NRC-11-83-703 83/04/25. FRALEY, R F ACRS - Advisory Committee on Reactor Safeguards SAVIO, R NRC - No Detailed Affiliation Given. 1p. 18351.234.

--8305040553 Contract "Extreme External Phenomena Subcommittee," awarded to George Washington Univ FOX, R R George Washington Univ. REBELLO, J. E. Division of Contracts FIN B-1557 NRC-11-83-703. 83/04/25. 4pp 18351 235.

8305040635 Notification of contract execution: "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities," awarded to NUSAC, Inc. WIGGINS, E Technical Assistance Contracts Branch. FIN B-7379. NRC-02-83-027 83/04/21 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director. MILLER, M. NRC - No Detailed Affiliation Given 1p 18336:283

--8305040643 Contract. "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities," awarded to NUSAC, Inc. PERENSTEIN, J. E NUSAC, Inc. MORTON, K. V. Division of Contracts. FIN B-7379 NRC-02-83-027. 83/04/21 22pp. 18336:284

8305040650 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ. .." Contractor State of WI. SILVIS, R M Technical Assistance Contracts Branch. NRC-05-73-014. 83/04/29. Director's Office, Office of Inspection and Enforcement. 1p. 18336.269

--8305040660 Mod 1, deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ Around Selected Commission Licensed Activities." REIVITZ, L Wisconsin, State of. GUSTAVE, R P. Division of Contracts. NRC-05-73-014. 83/04/29. 1p. 18336:270.

8305050385 Notification of contract execution, Mod 3 to "Lease of Vehicles." Contractor: We Try Harder, Inc. BROMBERG, B Administrative Contracts Branch. FIN B-8153. NRC-10-82-377. 83/04/26. CORLEY, J. , GRANT, L. NRC - No Detailed Affiliation Given 1p 18352.063.

--8305050389 Mod 3, extending period of performance to 840512, to "Lease of Vehicles." * We Try Harder, Inc. SMITH, P. A. Division of Contracts. FIN B-8153 NRC-10-82-377. 83/04/26 1p. 18352:064.

8305050400 Notification of contract execution, Mod 5 to "Performance of Engineered Barriers in Geologic Repository " Contractor Golder Assoc, Inc
FIELDS, J A Division of Contracts FIN B-6986-3 NRC-02-81-027 83/03/28 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director PITTIGLIO, L NRC - No Detailed Affiliation Given 1p 18352 060

--8305050404 Mod 5, establishing provisional overhead rate for labor costs & increasing funding, to "Performance of Engineered Barriers in Geologic Repository "
PENTZ, D L Golder Associates GUSTAVE, R P Division of Contracts FIN B-6986-3. NRC-02-81-027 83/03/28 2pp 18352 061

8305060174 Notification of contract execution, Mod 7 to "Energetic Thermal Interactions & Coolant Flow Phenomena Associated W/Nuclear Reactor Concepts." Contractor Purdue Research Foundation
FLEENOR, C Division of Contracts NRC-03-80-102 83/02/25
MATTSON, R J Division of Systems Integration (post 811005)
MEYER, J NRC - No Detailed Affiliation Given 1p 18359.354

--8305060183 Mod 7, extending period of performance through 830322 & revising billing instructions, to "Energetic Thermal Interactions & Coolant Flow Phenomena Associated W/Nuclear Reactor Concepts."
GREENKORN, R A Purdue Research Foundation GUSTAVE, R P. Division of Contracts NRC-03-80-102 83/02/25 2pp 18359.355

8305060235 Notification of contract execution, Mod 5 to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1 - Final Rept.'"
Contractor Univ of California at San Diego
SMITH, P A Division of Contracts FIN B-6531. NRC-03-78-186 83/04/25 DENTON, H R Office of Nuclear Reactor Regulation, Director. REITER, L. NRC - No Detailed Affiliation Given 1p. 18359 352. 24X Fiche 50-206, 83/04/25, 8305060235.

--8305060239 Mod 5, deobligating funds for closeout, to "Review of Rept Entitled 'Simulation of Earthquake Ground Motions for San Onofre Nuclear Generating Station Unit 1 - Final Rept.'"
* California, Univ of, San Diego SMITH, P A Division of Contracts FIN B-6531. NRC-03-78-186 83/04/25 1p 18359.353 24X Fiche. 50-206, 83/04/25, 8305060235.

8305060246 Notification of contract execution. "Perform Studies Re Data & Analysis of Nuclear Fuel Cycle," awarded to Nuclear Assurance Corp
HOYLE, A Administrative Contracts Branch FIN B-7386-3
NRC-02-83-037 83/04/26 BROWN, R S Program Support Branch.
LOWENBERG, H. NRC - No Detailed Affiliation Given 1p. 18359·346

--8305060251 Contract· "Perform Studies Re Data & Analysis of Nuclear Fuel Cycle," awarded to Nuclear Assurance Corp
DOIRON, D. G Nuclear Assurance Corp REBELLO, J. E. Division of Contracts FIN B-7386-3 NRC-02-83-037. 83/04/26 5pp. 18359 347

8305060320 Notification of contract execution. "Development of Reg Guide & Regulatory Analyses," awarded to Analysis & Technology
WIGGINS, E. Division of Contracts. FIN B-8645 NRC-03-83-107. 83/04/01. THOMPSON, H. L. Division of Human Factors Safety
BENDER, L NRC - No Detailed Affiliation Given. 1p. 18353·035

--8305060326 Contract "Development of Reg Guide & Regulatory Analyses," awarded to Analysis & Technology
NOLF, D M Analysis & Technology, Inc. MORTON, K V Division of Contracts. FIN B-8645. NRC-03-83-107. 83/04/01 28pp. 18353·036.

8305060341 Notification of contract execution, Mod 1 to "Geotechnical On-Call Assistance for Case Reviews." Contractor, US Army Corps of Engineers.
FIELDS, J. A. Division of Contracts. NRC-03-82-107. 83/02/23.
VOLLMER, R. H. Division of Engineering. HELLER, L. NRC - No Detailed Affiliation Given. 1p. 18353: 024.

--8305060351 Mod 1, changing address for submission of invoices to, "Geotechnical On-Call Assistance for Case Reviews "
KAVANAUGH, P F Army, Dept. of, Corps of Engineers HAGAN, T. F. Division of Contracts. NRC-03-82-107. 83/02/23 1p. 18353: 025.

8305060379 Notification of contract execution, Mod 6 to "Foundations & Underpinning, Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2." Contractor· Geotechnical Engineers, Inc.
FIELDS, J. A. Division of Contracts. NRC-03-82-092 83/04/12
VOLLMER, R. H. Division of Engineering. KANE, J. NRC - No Detailed Affiliation Given. 1p 18353: 086. 24X Fiche: 50-329, 83/04/12, 8305060379.

--8305060384 Mod 6, modifying monthly business ltr reporting requirements, to "Foundations & Underpinning Review of Remedial Measures for Structures on Fill for Midland Plants 1 & 2 "
POULOS, S J Geotechnical Engineers, Inc GUSTAVE, R P Division of Contracts NRC-03-82-092 83/04/12 3pp 18353 087 24X Fiche 50-329, 83/04/12, 8305060379

8305090009 Notification of contract execution, Mod 9 to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations "
Contractor Williams-Robinette & Assoc
DELOATCH, V Technical Assistance Contracts Branch FIN B-7383-3
NRC-02-81-039 83/04/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director 1p 18369 360

--8305090012 Mod 9, extending period of performance to 830520, to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations "
WILLIAMS, R. E Williams-Robinette & Associates, Inc GUSTAVE, R P. Division of Contracts FIN B-7383-3 NRC-02-81-039 83/04/29 1p 18369 361

8305090050 Notification of contract execution, Mod 7 to "Fire Protection Research Program " Contractor Underwriter Labs, Inc
WOLLETT, S Technical Assistance Contracts Branch FIN B-6197
NRC-04-77-122. 83/04/29 BATSON, W Office of Nuclear Regulatory Research, Director NOTLEY, D NRC - No Detailed Affiliation Given. 1p 18381 174

--8305090058 Mod 7, providing no cost extension until 830930, to "Fire Protection Research Program "
* Underwriters Laboratory GUSTAVE, R. P Division of Contracts FIN B-6197 NRC-04-77-122 83/04/29 1p. 18381 175

8305090068 Notification of contract execution, Mod 3 to "Coordination of Cooperative Organizations Participating in Geological, Geophysical & Seismological Studies " Contractor St Louis Univ.
WOLLETT, S Technical Assistance Contracts Branch. FIN B-7242.
NRC-04-80-229 83/04/29 BATSON, W Office of Nuclear Regulatory Research, Director WASTLER, S NRC - No Detailed Affiliation Given 1p 18381.156

--8305090117 Mod 3, extending performance to 831109 at no addl cost, to "Coordination of Cooperative Organizations Participating in Geological, Geophysical & Seismological Studies "
* St Louis Univ , St Louis, MO GUSTAVE, R P Division of Contracts FIN B-7242 NRC-04-80-229 83/04/29. 1p 18381·157

8305090122 Notification of contract execution, Mod 2 to "Manual to Define Lower Limits of Detection in Radiological Effluent & Environ Measurements " Contractor NBS.
DELOATCH, V. Technical Assistance Contracts Branch FIN B-8615
NRC-03-82-126 83/04/28 MATTSON, R Office of Nuclear Reactor Regulation, Director MEINKE, W NRC - No Detailed Affiliation Given 1p 18381.128.

--8305090131 Mod 2, changing period of performance to 840501 & increasing funds, to "Manual to Define Lower Limits of Detection in Radiological Effluent & Environ Measurements "
SHREVE, D B Commerce, Dept of, National Bureau of Standards.
GUSTAVE, R. P. Division of Contracts FIN B-8615 NRC-03-82-126 83/04/28 2pp 18381.129

8305090291 Notification of contract execution, Mod 2 to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys." Contractor, WSI Corp.
COLEMAN, R Administrative Contracts Branch. NRC-33-83-456.
83/05/03 BASSETT, H Division of Data Automation & Management Information JOHNSON, C. NRC - No Detailed Affiliation Given 1p 18381.235

--8305090300 Mod 2, correctly stating amount certified under Mod 1, to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys "
* WSI Corp MATTIA, M. J. Division of Contracts NRC-33-83-456 83/05/03 1p 18381 236

8305110005 Notification of contract execution, Mod 4 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals." Contractor, G Charnoff
TOWNSEND, B Administrative Contracts Branch. FIN B-8179.
NRC-18-82-481 83/05/03 ROTHSCHILD, T Office of the General Counsel 1p. 18421 249.

--8305110008 Mod 4, extending period of performance to 831231, to "Ad Hoc Committee for Review & Licensing Reform Proposals."
* Charnoff, G. REBELLO, J E. Division of Contracts FIN B-8179. NRC-18-82-481. 83/05/03 1p 18421 250.

8305110031 Notification of contract execution, Mod 7 to "Technical Assistance on Site Characterization & Monitoring " Contractor US Army Corps of Engineers
FLEENOR, C Technical Assistance Contracts Branch NRC-02-81-056 83/04/29 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director. PENNIFILL, R NRC - No Detailed Affiliation Given 1p 18421 311

--8305110041 Mod 7, revising delivery schedule for task repts to extend period of performance to 830228, to "Technical Assistance on Site Characterization & Monitoring "
MARCUSON, W F Army, Dept of, Corps of Engineers GUSTAVE, R. P Technical Assistance Contracts Branch NRC-02-81-056. 83/04/29 1p 18421 312

8305110146 Notification of contract execution "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Debevoise & Plimpton
TOWNSEND, B Administrative Contracts Branch FIN B-8182 NRC-18-83-407 83/05/03 ROTHSCHILD, T Office of the General Counsel LEVI, R NRC - No Detailed Affiliation Given 1p 18421 341

--8305110152 Contract "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Debevoise & Plimpton
RUEBHAUSEN, D M Pickard, Lowe & Garrick, Inc REBELLO, J E. Division of Contracts. FIN B-8182 NRC-18-83-407 83/05/03 4pp 18421 342

8305110159 Notification of contract execution, Mod 3 to "Computer Based Software, Installation, Testing Documentation, Training & Sys Integration for Implementation of NRC TLD Direct Radiation Monitoring Network " Contractor Applied Physical Technology
GILDENHORN, A J Administrative Contracts Branch NRC-10-80-691 83/04/26 DORIE, W Office of Administration COSTELLO, F NRC - No Detailed Affiliation Given 1p. 18434:241

--8305110163 Mod 3, reducing total amount of contract, to "Computer Based Software, Installation, Testing Documentation, Training & Sys Integration for Implementation of NRC TLD Direct Radiation Monitoring Network Program "
* Applied Physical Technology, Inc HAGAN, T F Division of Contracts NRC-10-80-691. 83/04/26 2pp 18434 242.

8305110190 Notification of contract execution, Mod 3 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals " Contractor, Ohio State Univ
HOYLE, A. Administrative Contracts Branch. FIN B-8179 NRC-18-82-481 83/04/25 ROTHSCHILD, T Office of the General Counsel. 1p 18434 280.

--8305110192 Mod 3, extending period of performance to 831231 & increasing total funding, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals "
REDMOND, R F Ohio State Univ REBELLO, J E Division of Contracts FIN B-8179 NRC-18-82-481 83/04/25 1p 18434 281.

8305110194 Notification of contract execution, Mod 23 to "Security Survey Guides & Appraisal Guide " Contractor: D Wright.
HOYLE, A Administrative Contracts Branch. NRC-10-82-385 83/05/03. BRADY, R. J. Division of Security KIDD, D NRC - No Detailed Affiliation Given 1p 18434 277.

--8305110198 Mod 3, reflecting new delivery schedule & payment, to "Security Survey Guides & Appraisal Guide "
WRIGHT, D Wright, D. REBELLO, J E. Division of Contracts. NRC-10-82-385 83/05/03. 1p 18434 278

8305110229 Notification of contract execution "Automated Library Sys," awarded to On-Line Computer Sys, Inc.
COLEMAN, R Administrative Contracts Branch NRC-33-83-454. 83/05/05 BASSETT, H Office of Resource Management, Director. ZUNGOLI, S NRC - No Detailed Affiliation Given. 1p. 18434 285.

--8305110232 Contract "Automated Library Sys," awarded to On-Line Computer Sys, Inc.
LYNN, D. L. On-Line Computer Systems, Inc. MATTIA, M J. Division of Contracts NRC-33-83-454 83/05/05. 12pp. 18434 286.

8305110233 Notification of contract execution, Mod 3 to "Investigation Into State of Stress in Crust Under Northeastern US."
Contractor Columbia Univ.
FIELDS, J. A Technical Assistance Contracts Branch. NRC-04-81-180 83/04/29 BATSON, W. F. Office of Nuclear Reactor Regulation, Director. ZURFLUEH, E NRC - No Detailed Affiliation Given 1p. 18434 283

--8305110236 Mod 23, extending expiration date to 831014, to "Investigation Into State of Stress in Crust Under Northeastern US."
STAMBAUGH, P. Columbia Univ GUSTAVE, R. P. Division of Contracts. NRC-04-81-180 83/04/29 1p. 18434·284.

8305110504 Notification of contract execution, Mod 4 to "Radiological Evaluation of Burial Grounds " Contractor Radiation Mgt Corp
FLEENOR, C Technical Assistance Contracts Branch. NRC-02-80-034 83/04/15 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director CROW, B. NRC - No Detailed Affiliation Given. 1p 18415 359

--8305110509 Mod 4, extending period of performance to 830501, to "Radiological Evaluation of Burial Grounds."
BOOTH, L F Radiation Management Corp GUSTAVE, R P Division of Contracts NRC-02-80-034 83/04/15 1p 18415 360

8305110539 Notification of contract execution, Mod 10 to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 " Contractor·Franklin Inst
FLYNN, M Technical Assistance Contracts Branch NRC-03-81-130 83/04/14 EISENHUT, D G Division of Licensing CARRINGTON, M. NRC - No Detailed Affiliation Given 1p 18415 112

--8305110545 Mod 10, replacing project officer & certain members of performance evaluation board & incorporating revised Manual Chapter 3202, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 "
ASHTON, A. M. Franklin Institute/Franklin Research Center GUSTAVE, R P Division of Contracts NRC-03-81-130 83/04/14 2pp 18415.113

8305120142 Notification of contract execution. "Listing of High Technology B(a) Firms," awarded to Miranda Assoc, Inc
BAZIN, J Administrative Contracts Branch NRC-13-83-446. 83/05/03. KERR, W Ofc of Small & Disadvantaged Bus. Utilization & Civil Rights. COLEMAN, H NRC - No Detailed Affiliation Given 1p. 18435 289

--8305120150 Contract· "Listing of High Technology B(a) Firms," awarded to Miranda Assoc, Inc
BERODOLL, T. E Miranda Associates, Inc MATTIA, M J Division of Contracts NRC-13-83-446 83/05/03 21pp. 18435·290.

8305120513 Notification of contract execution· "Fire Protection Program Review Casework Plants 6," awarded to Rolf Jensen & Assoc, Inc
EDGEWORTH, P , FLEENOR, C. Technical Assistance Contracts Branch FIN B-8642. NRC-03-83-104 83/05/03 VOLLMER, R H Division of Engineering NOLAN, F. NRC - No Detailed Affiliation Given. 1p. 18443:125.

--8305120517 Contract. "Fire Protection Program Review·Casework Plants 6," awarded to Rolf Jensen & Assoc, Inc
WEBB, W. A. Rolf Jensen & Associates, Inc. MORTON, K. V. Division of Contracts. FIN B-8642. NRC-03-83-104 83/05/03 15pp 18443·126

8305120555 Notification of contract execution· "Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation," awarded to Schwalb, Donnenfeld, Bray & Silbert
TOWNSEND, B. Administrative Contracts Branch FIN B-8182. NRC-18-83-406 83/05/06. ROTHSCHILD, T. Office of the General Counsel LEVI, R. NRC - No Detailed Affiliation Given. 1p. 18441.358.

--8305120560 Contract: "Advisory Committee for Review of Ofc of Investigation Policy Rights of Licensee Employees Under Investigation," awarded to Schwalb, Donnenfeld, Bray & Silbert
SILBERT, E J Schwalb, Donnenfeld, Bray & Silbert. REBELLO, J. E Division of Contracts FIN B-8182. NRC-18-83-406. 83/05/06. 4pp 18441·359.

8305130299 Notification of contract execution, Mod 1 to "Career Counseling for NRC Participants, Region II." Contractor·R Nawyn
HOPPER, A. Division of Contracts NRC-10-82-370. 83/05/09. GOLDMAN, P. J. Management Development & Training Staff VAN SANTEN, L. NRC - No Detailed Affiliation Given. 1p. 18460:042.

--8305130300 Mod 1, increasing funding, to "Career Counseling for NRC Participants, Region II."
* Nawyn, R. REBELLO, J. E. Division of Contracts. NRC-10-82-370. 83/05/09. 1p 18460:043.

8305130356 Notification of contract execution: "Grievance Review Examiner," awarded to JE Kaufmann.
HOYLE, A Administrative Contracts Branch. NRC-10-83-359. 83/05/10. BIRD, P. E. Division of Organization and Personnel JACKSON, J NRC - No Detailed Affiliation Given 1p. 18460:044.

--8305130361 Contract: "Grievance Review Examiner," awarded to JE Kaufmann.
KAUFMANN, J E Kaufmann, J. E. REBELLO, J E. Administrative Contracts Branch NRC-10-83-359. 83/05/10. 5pp. 18460:045.

8305160304 Notification of contract execution "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc
MILES, E B Administrative Contracts Branch FIN B-8855
NRC-33-83-460 83/05/02 BASSETT, H S Office of Resource Management, Director FITTI, C Atomic Safety and Licensing Board Panel 1p 18471 247 24X Fiche 50-247, 83/05/02, 8305160304

--8305160312 Contract "Conversion of Prefiled Testimony for Indian Point Hearings," awarded to Central Data Processing, Inc
* Central Data Processing, Inc MATTIA, M J Division of Contracts FIN B-8855 NRC-33-83-460 83/05/02 2pp 18471 248 24X Fiche 50-247, 83/05/02, 8305160304

--8305160316 Solicitation, offer & award to "Conversion of Prefiled Testimony for Indian Point Hearings," to Central Data Processing, Inc
COUCH, M J Central Data Processing, Inc MATTIA, M J Administrative Contracts Branch FIN B-8855 NRC-33-83-460 83/04/26 56pp 18471 250 24X Fiche 50-247, 83/05/02, 8305160304

8305160318 Notification of contract execution, Mod 1 to "Div of Engineering Review Support on Bailly Nuclear Plant I " Contractor MT Davisson
FIELDS, J. A. Technical Assistance Contracts Branch FIN B-7505
NRC-03-81-092 83/05/06 VOLLMER, R H Division of Engineering LEAR, Q. NRC - No Detailed Affiliation Given 1p 18472 051 24X Fiche. 50-367, 83/05/06, 8305160318.

--8305160332 Mod 1, terminating contract & deobligating funds, to "Div of Engineering Review Support on Bailly Nuclear Plant I "
DAVISSON, M T Darisson, M T GUSTAVE, R P Division of Contracts FIN B-7505 NRC-03-81-092 83/05/06 2pp 18472·052. 24X Fiche 50-367, 83/05/06, 8305160318

8305170065 Notification of contract execution. "Development of Reg Guide & Regulatory Analysex," awarded to Analysis & Technology.
WIGGINS, E Division of Contracts FIN B-8645 NRC-03-83-107
83/04/01 THOMAS, H L Division of Human Factors Safety BENDER, L NRC - No Detailed Affiliation Given 1p 18495 030

--8305170070 Forwards two fully executed copies of NRC-03-83-107, "Development of Reg Guide & Regulatory Analyses "
KRAVITS, D. L Analysis & Technology, Inc FIN B-8645
NRC-03-83-107. 83/04/06. MORTON, K. V Division of Contracts 1p 18495·031

--8305170077 Contract· "Development of Reg Guide & Regulatory Analyses," awarded to Analysis & Technology
NOLF, D M Analysis & Technology, Inc FIN B-8645 NRC-03-83-107 83/04/01 134pp 18495 032

8305170603 Notification of contract execution, Mod 1 to "Reviewing Hydrogeologic Investigations of NV Test Site-Project C " Contractor·Williams-Robinette
SILVIS, R Technical Assistance Contracts Branch. NRC-02-82-046
83/05/03. DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. JEFFREY, P NRC - No Detailed Affiliation Given 1p 18497·044

--8305170614 Mod 1, adding new project officer, to "Reviewing Hydrogeologic Investigations of NV Test Site-Project C."
* Williams-Robinette & Associates, Inc GUSTAVE, R. P. Division of Contracts NRC-02-82-046. 83/05/03 1p 18497.045.

8305170606 Notification of contract execution, Mod 5 to "QA for Geotechnical GC." Contractor, US Army Corps of Engineers
FLEENOR, C. Technical Assistance Contracts Branch NRC-02-82-035
83/04/28 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director. PENNIFILL, R NRC - No Detailed Affiliation Given. 1p. 18497·024

--8305170607 Mod 5, modifying reporting requirement, revising schedule for submission of task & updating billing instructions, to "QA for Geotechnical GC "
MARCUSON, W F. Army, Dept. of, Corps of Engineers GUSTAVE, R. P Technical Assistance Contracts Branch. NRC-02-82-035. 83/04/28. 2pp. 18497.025

8305170648 Notification of contract execution, Mod 1 to "Installation, Deinstallation & Maint Support Svcs for High Frequency, Very High Frequency & Ultra High Frequency Radio Equipment Owned & Operated by NRC." Contractor, Metrocom, Inc
MCLEAREN, T. Division of Contracts NRC-10-83-331 83/05/13
CORLEY, J Division of Facilities & Operations COHEN, S NRC - No Detailed Affiliation Given 1p. 18496.347

--8305170661 Mod 1, raising contract ceiling & adding project officer, to "Installation, Deinstallation & Maint of Support Svcs for High Frequency, Very High Frequency & Ultra High Frequency Radio Equipment Owned & Operated by NRC "
* Metrocom, Inc SMITH, P A Division of Contracts NRC-10-83-331 83/05/13 1p 18496 348

8305170688 Notification of contract execution, Mod 5 to "Presentation of GE BWR/6 Design & Operation Courses " Contractor GE
WOLLETT, S Technical Assistance Contracts Branch FIN B-1224
NRC-05-80-282 83/05/13 BLAHA, J Program Support Branch HAVENS, D NRC - No Detailed Affiliation Given 1p 18496 318

--8305170693 Mod 5, reducing rates for three courses & canceling one course, to "Presentation of GE BWR/6 Design & Operation Courses "
PIERCE, R L General Electric Co GUSTAVE, R P Division of Contracts FIN B-1224 NRC-05-80-282 83/05/13 2pp 18496 319

8305180038 Notification of contract execution, Mod 1 to "Consulting Svc on Indian Point Probabilistic Safety Study " Contractor Columbia Univ
HOYLE, A Administrative Contracts Branch FIN B-8644
NRC-03-83-106 83/05/10 DENTON, H Office of Nuclear Reactor Regulation, Director CODELL, R NRC - No Detailed Affiliation Given 1p 18499·289 24X Fiche 50-247, 83/05/10, 8305180038

--8305180047 Mod 1, extending period of performance to 830630 & changing payment & general provisions, to "Consulting Svc on Indian Point Probabilistic Safety Study "
LEWIS, J P Columbia Univ REBELLO, J E Division of Contracts NRC-03-83-106 83/05/10 1p 18499 290 24X Fiche 50-247, 83/05/10, 8305180038

8305180412 Notification of contract execution, Mod 3 to "On Call Maint for NRC Computer Peripheral Equipment " Contractor·Computer Sys Support Corp
PERLMAN, J Division of Contracts FIN B-8174 NRC-33-83-451
83/05/12 BASSETT, H S Division of Data Automation & Management Information JOHNSON, C NRC - No Detailed Affiliation Given 1p 18503 359

--8305180421 Mod 3, increasing funds, to "On Call Maint for NRC Computer Peripheral Equipment "
* Computer Systems Support Corp SMITH, P A Division of Contracts FIN B-8174 NRC-33-83-451 83/05/12 1p 18503·360

8305180557 Notification of contract execution "Purchase & Installation of Multichannel Analyzer Sys," awarded to Nuclear Data, Inc
MILES, E B Administrative Contracts Branch FIN B-8855
NRC-31-83-662 83/05/13 ENGELKEN, R Region 5, Office of Director COLLINS, J. T , WISE, R Region 4, Office of Director 1p. 18505 121

--8305180560 Contract "Purchase & Installation of Multichannel Analyzer Sys," awarded to Nuclear Data, Inc
* Nuclear Data, Inc MATTIA, M J Division of Contracts FIN B-8855 NRC-31-83-662 83/05/13 3pp 18505·122

--8305180562 Solicitation, offer & award to "Purchase & Installation of Multichannel Analyzer Sys," to Nuclear Data, Inc
RISSO, R P Nuclear Data, Inc MATTIA, M J Division of Contracts. FIN B-8855 NRC-31-83-662 83/03/01 29pp 18505 123

8305180795 Notification of contract execution, Mod 4 to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals." Contractor Trial Lawyers for Public Justice
HOPPER, A Division of Contracts FIN B-8179 NRC-18-82-418
83/05/13 ROTHSCHILD, T Office of the General Counsel 1p 18505 330

--8305180792 Mod 4, extending period of performance to 831231, to "Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals "
ROISMAN, A Z Trial Lawyers for Public Justice REBELLO, J E. Division of Contracts FIN B-8179 NRC-18-82-418 83/05/13 1p 18505 331

8305190506 Notification of contract execution, Mod 8 to "Review & Evaluation of Geologic & Seismic Features of Nuclear Power Sites " Contractor USGS
FIELDS, J A Technical Assistance Contracts Branch. NRC-03-80-113.
83/04/12 VOLLMER, R H Division of Engineering JACKSON, R NRC - No Detailed Affiliation Given 1p 18523 154

--8305190514 Mod 8, correcting mod number to 7 in previous mod, to "Review & Evaluation of Geologic & Seismic Features of Nuclear Power Sites "
* Interior, Dept of, Geological Survey. GUSTAVE, R P Division of Contracts NRC-03-80-113. 83/04/12 1p 18523; 155

8305200002 Notification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations Contractor Barr Engineering Co FIELD, J A Administrative Contracts Branch NRC-02-80-033-03 83/05/13 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC - No Detailed Affiliation Given 1p 18528 358

--8305200004 Mod 4, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluations "
* Barr Engineering Co GUSTAVE, R P Division of Contracts NRC-02-80-033-03 83/05/13 1p 18528·359

8305200062 Notification of contract execution, Mod 1 to "ABC Stenoscript Shorthand " Contractor Montgomery County MD Public Schools DORSEY, M Administrative Contracts Branch NRC-10-79-385. 83/05/11 DORIE, W M Office of Administration GALLAGHER, J M NRC - No Detailed Affiliation Given 1p 18540·126

--8305200071 Mod 1, deobligating remaining balance, to "ABC Stenoscript Shorthand "
PASCOE, S Montgomery County, MD SMITH, P A Division of Contracts NRC-10-79-385 83/05/11 1p 18540 127

8305200131 Notification of contract execution, Mod 4 to "Microfiche Verification & Retrofit " Contractor SBA Subcontractor Labat-Anderson, Inc
GILDENHORN, A J. Administrative Contracts Branch. NRC-10-82-425 83/04/29 BEBAW, W J Division of Technical Information & Document Control SKOCZLAS, J , SCOTT, S NRC - No Detailed Affiliation Given 1p 18528 340

--8305200134 Mod 4, extending period of performance to 830605, to "Microfiche Verification & Retrofit "
BERGDOLL, T E Small Business Administration LABAT, V Labat-Anderson, Inc HAGAN, T F Division of Contracts NRC-10-82-425 83/04/29 2pp 18528 341

8305200145 Notification of execution, Mod 2 to "Const & Calibr of Sr-90 Irradiator Multiple Dosimeter Irradiations " Contractor Univ of MI
FLYNN, M Technical Assistance Contracts Branch. FIN B-8285 NRC-04-82-024 83/05/13 FOREHAND, M Office of Nuclear Regulatory Research, Director DENNIS, N NRC - No Detailed Affiliation Given 1p 18540 245

--8305200149 Mod 2, extending completion date for 3 months, to "Const & Calibr of Sr-90 Irradiator for Multiple Dosimeter Irradiations "
STEMPLE, P J Michigan, Univ of GUSTAVE, R P Division of Contracts. FIN B-8285 NRC-04-82-024 83/05/13 1p. 18540: 246

8305230024 Notification of contract execution, Mod 1 to "Interagency Agreement to Provide NRC Power Plant Location Mapping Svcs " Contractor USGS
DORSEY, M Administrative Contracts Branch FIN B-1299 NRC-05-81-268 83/05/09 COBB, L I Training & Administration Staff WEINSTEIN, E NRC - No Detailed Affiliation Given 1p. 18542 258

--8305230031 Mod 1, deobligating funds, to "Interagency Agreement to Provide NRC Power Plant Location Mapping Svcs "
SOUTHARD, R B Interior, Dept of, Geological Survey SMITH, P. A Division of Contracts FIN B-1299 NRC-05-81-268 83/05/09 1p 18542 259

8305230139 Notification of contract execution, Mod 4 to "Transient Prototypical Steam Generator (MB-2) Research Testing Program " Contractor Westinghouse & EPRI
BAISDEN, L Technical Assistance Contracts Branch FIN B-8252 NRC-04-82-020. 83/05/13 BATSON, W Office of Nuclear Regulatory Research, Director HOFENFELD, J. NRC - No Detailed Affiliation Given 1p 18543 345

--8305230169 Ltr contract NRC-04-82-020, Mod 4, extending period of performance to 830531, to "Transient Prototypical Steam Generator (MB-2) Research Testing Program "
MORTON, K. V NRC - No Detailed Affiliation Given. FIN B-8252. NRC-04-82-020 83/05/13 SPENCE, L W Westinghouse Electric Corp RYTKONEN, B. B Electric Power Research Institute 2pp. 18543 346

8305230245 Notification of contract execution. "Executive Development Program." awarded to USDA Graduate School
BAZIN, J Administrative Contracts Branch. STEWART, S D. Division of Contracts NRC-10-83-299. 83/05/17 GOLDMAN, P J Management Development & Training Staff ALLEN, R A. NRC - No Detailed Affiliation Given 1p 18543 237.

--8305230249 Contract "Executive Development Program." awarded to USDA Graduate School
* Agriculture, Dept of, Graduate School MATTIA, M J Division of Contracts NRC-10-83-299 83/05/17. 6pp 18543 238

8305230256 Notification of contract execution "Managerial Competencies." awarded to USDA Graduate School
STEWART, S. D , BAZIN, J Administrative Contracts Branch NRC-10-83-300 83/05/17 GOLDMAN, P J Management Development & Training Staff ALLEN, R A. NRC - No Detailed Affiliation Given. 1p 18543·251

--8305230274 Ltr contract "Managerial Competencies." detailing terms of Task 3, providing & developing training programs for selected NRC personnel in accordance w/statement of work & listed terms & conditions
MATTIA, M J Division of Contracts NRC-10-83-300 83/04/13. VARNER, S Agriculture, Dept of, Graduate School 6pp. 18543 252

8305230281 Notification of contract execution, Mod 6 to "Canadian Seismic Agreement " Contractor·Canadian Commercial Corp.
WOLLETT, S Technical Assistance Contracts Branch. FIN B-6275. NRC-04-79-180 83/05/13 BATSON, W. Office of Nuclear Regulatory Research, Director MURPHY NRC - No Detailed Affiliation Given. 1p. 18576: 329

--8305230289 Mod 6, providing addl funding & extending period of performance to 840331 to "Canadian Commerical Corp "
SHAW, L Canadian Commercial Corp GUSTAVE, R. P Division of Contracts FIN B-6275. NRC-04-79-180 83/05/13 2pp. 18576: 330

8305230287 Notification of contract execution, Mod 17 to "On-Call Maint for NRC Computer Peripheral Equipment "
DORSEY, M Administrative Contracts Branch FIN B-8162. NRC-10-79-395. 83/05/02. DORIE, W M Office of Administration JOHNSON, C NRC - No Detailed Affiliation Given 1p 18543·290

--8305230293 Mod 17, deobligating balance of funds for contract closeout, to "On-Call Maint for NRC Computer Peripheral Equipment "
ROOT, L E Computer Systems Support Corp SMITH, P. Division of Contracts. FIN B-8162 NRC-10-79-395 83/05/02 1p 18543: 291

8305230298 Notification of grant execution, Mod 3 to "Natural Convection Heat Transfer in Spent Breeder Fuel Shipping Configurations " Grantee, Howard Univ
MCDERMOTT, D. Technical Assistance Contracts Branch. FIN G-1015. NRC-G-04-81-007 83/05/11 BATSON, W Office of Nuclear Regulatory Research, Director. MURPHY, J NRC - No Detailed Affiliation Given. 1p 18576 327

--8305230311 Mod 3, providing addl funds, extending period of performance to 840901 & incorporating renewal proposal, to "Natural Convection Heat Transfer in Spent Breeder Fuel Shipping Configurations."
HARRIS, C L Howard Univ MORTON, K V Division of Contracts. FIN G-1015 NRC-G-04-81-007. 83/05/11 1p. 18576. 328.

8305230326 Notification of contract execution· "Radiation Monitoring Program Requirements;" awarded to State of PA.
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8356. NRC-28-83-607. 83/05/12 MCOSCAR, J. Region 1, Office of Director. COSTELLO, F NRC - No Detailed Affiliation Given. 1p 18577: 291

--8305230332 Contract. "Radiation Monitoring Program Requirements." awarded to State of PA Cooperative agreement encl
* Pennsylvania, Commonwealth of, MORTON, K. V Division of Contracts FIN B-8356 NRC-28-83-607 83/05/12. 16pp. 18577·292

8305260081 Notification of contract execution, Mod 1 to "Comprehensive Current (Real-Time) Geophysical Data Storage & Retrieval Sys." Contractor: WSI Corp
GILDENHORN, A J , COLEMAN, R C Administrative Contracts Branch. NRC-33-83-456 83/04/08 BASSETT, H Division of Data Automation & Management Information. JOHNSON, C NRC - No Detailed Affiliation Given 1p. 18649 076

--8305260087 Mod 1, adjusting language of statement of work, travel ceilings, overhead rate ceiling, adding special provisions & increasing contract amount, to "Comprehensive Current (Real-Time) Geophysical Data Storag & Retrieval Sys "
* WSI Corp. MATTIA, M. J Division of Contracts. NRC-33-83-456. 83/04/08. 3pp 18649: 077

8305260206 Notification of contract execution, Mod 1 to "Computer Output Microfilm Production " Contractor Anacomp, Inc.
MCLEAREN, T Administrative Contracts Branch NRC-10-83-297 83/05/23. BEBAW, W J. Division of Technical Information & Document Control. SKOCZLAS, J. NRC - No Detailed Affiliation Given. 1p. 18647: 184.

--8305260222 Mod 1, changing location for pickup & delivery, to "Computer Output Microfilm Production "
SEYMOUR, L A Anacomp, Inc HAGAN, T F Division of Contracts
NRC-10-83-297 83/05/23 1p 18647 183

8305260340 Notification of grant execution, Mod 1 to "Condensation & Evaporation Rates for Nuclear Aerosols Fission Product Release & Hydrogen Mitigation " Grantee Univ of MO - Columbia
MCDERMOTT, D Technical Assistance Contracts Branch FIN G-1024
NRCG-04-81-26 83/05/13 BATSON, W Office of Nuclear Regulatory Research, Director LARKINS, J NRC - No Detailed Affiliation Given.
1p. 18629 288.

--8305260341 Mod 1, increasing funds & extending period of performance to 840930, to "Condensation & Evaporation Rates for Nuclear Aerosols Fission Product Release & Hydrogen Mitigation "
BLOUNT, D H Missouri, Univ of, Columbia MORTON, K V Technical Assistance Contracts Branch FIN G-1024 NRCG-04-81-026
83/05/13. 1p. 18629 289.

8305260377 Notification of contract execution, Mod 3 to "Exam of Agreement State Program " Contractor, Natl Governors Assoc
MCLEAREN, T Administrative Contracts Branch NRC-06-81-293.
83/05/16 KERR, G W Office of State Programs, Director LUBENAU, J
NRC - No Detailed Affiliation Given 1p 18647, 256

--8305260380 Mod 3, providing consideration to govt for late delivery of contract deliverables, to "Exam of Agreement State Program "
SCHEPPACH, R C National Governors' Association SMITH, P A.
Division of Contracts NRC-06-18-293 83/05/16 1p 18647 257

8305270090 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements. " Contractor State of NE.
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8503.
NRC-31-83-670 83/05/16 MEYERS, D M Region 4, Office of Director
NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18661 352.

--8305270093 Mod 1, correcting B&R numbers, to "Radiation Monitoring Program Requirements "
* Nebraska, State of. MORTON, K. V Division of Contracts FIN
B-8503 NRC-31-83-670 83/05/16 1p 18661, 353.

8305270097 Notification of contract execution, Mod 5 to "Source Term Characterization Resulting From Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks "
Contractor, BMI
WOLLETT, S. Technical Assistance Contracts Branch. FIN B-6710
NRC-04-80-180 83/04/28 FOREHAND, W Office of Nuclear Regulatory Research, Director LAHS, B. NRC - No Detailed Affiliation Given
1p 18661:350

--8305270100 Mod 5, deobligating funds, to "Source Term Characterization Resulting From Explosively-Caused Secondary Violations of Spent Fuel Shipping Casks."
LUKZ, F J Battelle Memorial Institute, Columbus Laboratories
GUSTAVE, R P. Division of Contracts. FIN B-6710. NRC-04-80-180
83/04/28 1p 18661·351.

8305270103 Notification of contract execution, Mod 28 to "Downcomer Effects Experimental Program " Contractor Creare, Inc
WOLLETT, S. Technical Assistance Contracts Branch FIN A-4070
NRC-04-75-162. 83/05/06. BATSON, W Office of Nuclear Regulatory Research, Director REYES, J. NRC - No Detailed Affiliation Given
1p. 18661 342

--8305270105 Mod 28, increasing funding, to "Downcomer Effects Experimental Program "
HICKIN, R. A. Creare, Inc MORTON, K V. Division of Contracts FIN
A-4070 NRC-04-75-162. 83/05/06. 7pp 18661, 343.

8305270108 Notification of contract execution, Mod 3 to "Technical Assistance in Nuclear Reactor Core Physics. " Contractor, Pickard, Lowe & Garrick Assoc, Inc.
SILVIS, R. M Technical Assistance Contracts Branch. FIN B-5547
NRC-04-75-213. 83/05/18. BATSON, W. Office of Nuclear Regulatory Research, Director. 1p. 18661:340

--8305270110 Mod 3, deobligating funds, to "Technical Assistance in Nuclear Reactor Core Physics."
PICKARD, J K Pickard, Lowe & Garrick, Inc. GUSTAVE, R P. Division of Contracts FIN B-5547. NRC-04-75-213. 83/05/18 1p.
18661,341.

FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES

8305020006 FOIA request for documents re Harry Diamond Labs located at 2800 Powder Mill Road, Adelphi, MD from 1965 to present.
SIMPSON, C Affiliation Unknown. 82/12/15. Office of Administration 2pp. 18355.001.

8305020007 Partial response to FOIA request for documents re Harry Diamond Labs located at 2800 Powder Mill Road, Adelphi, MD from 1965 to present. Forwards documents responsive to request Documents also available in PDR
FELTON, J M Division of Rules and Records 83/01/11 SIMPSON, C
Affiliation Unknown 1p 18356 003

--8006180578 Requests amend of Matl/Byproduct Licenses 19-17250-01, 19-17250-04, 19-17250-05 & SNM-348 Amend replaces C Rowe w/MD Funkhouser as radiation protection officer Resume for MD Funkhouser encl.
TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command 03952 80/05/22 Licensing Management Branch 5pp 18355 109

--8008250310 Matl/Byproduct License 19-17250-05 for Dept of Army, Harry Diamond Labs is amended per 800505 ltr Amend 4 adds conditions of use of licensed matl
QUINN, P R Licensing Management Branch 80/07/15 2pp
18355 090

--8008250337 Matl/Byproduct License 19-17250-04 for Dept of Army, Harry Diamond Labs is amended per 800505 ltr Amend 3 authorizes use of licensed matl per 780118 & 0811 applications & 800505 ltr.
QUINN, P R Licensing Management Branch 80/07/09 1p
18356 015

--8008250463 Matl/Byproduct License 19-17250-01 for Dept of Army, Harry Diamond Labs is amended per 800505 ltr Amend 3 adds conditions of use of licensed matl.
QUINN, P R Licensing Management Branch 80/07/02. 1p
18356 211

--8103130267 Requests amend of Matl/Byproduct License 19-17250-01 to delete PA Caldwell, WE Biesieler & JE Stafford, add KG Kerris, CC Casser & P Sarigianis & remove radiation detection instruments
BENOIT, W R Army, Dept of 06602 81/01/22 NRC - No
Detailed Affiliation Given 3pp 18356 314

--8104030770 Matl/Byproduct License 19-17250-01 for Dept of Army, Harry Diamond Labs is amended per 810122 ltr Amend 4 changes reading of Conditions 12 & 16 re names of users of licensed matl
QUINN, P R Licensing Management Branch 81/02/25 1p.
18356 210

--8104060899 Requests amend of Matl/Byproduct License 19-17250-05 to add P Sarigianis as alternate operator of Co-60 facility & delete obsolete radiation detection instruments
TARAS, D. Army, Dept of, Headquarters Materiel Development & Readiness Command 26974 81/02/09 Licensing Management Branch 1p 18355 104

--8305020010 Amend 1 to Matl/Byproduct License 19-17250-04 for Dept of Army, Harry Diamond Labs, authorizing use of irradiated electronic equipment & threshold detectors.
QUINN, P. R Licensing Management Branch 78/06/07 2pp.
18355 004

--8305020015 Application to renew & amend Matl/Byproduct License 08-02434-01 for Harry Diamond Labs, authorizing listed individuals as users of Co-60 & Cs-137 sealed sources for calibr of radiation detection instruments
CAMPAGNA, J H. Army, Dept of 93820 67/04/03 10pp.
18355 006.

--8305020016 Forwards application to renew Matl/Byproduct License 08-02434-01 for Harry Diamond Labs. Approval recommended.
MCGRAW, T. L Army, Dept. of 93820 67/04/10. Atomic Energy Commission. 1p 18355·016

--8305020019 Application to renew Matl/Byproduct License 08-02534-01, for Harry Diamond Labs, authorizing listed individuals as users of Co-60 & Cs-137 sources for calibr of radiation detection instruments
SISCO, H W. Army, Dept of 69029 65/05/17 2pp 18355·017

--8305020022 Recommends that encl application for renewal of Matl/Byproduct License 08-02534-01 for Harry Diamond Labs be approved. W/o encl
FLYNN, R. M. Army, Dept. of. 69029. 65/06/17 Atomic Energy Commission 3pp. 18355 019

--8305020027 Ack receipt of 620417 notification designating QP Hanson as radiation protection officer & chairman of radioactive matls control board Application to amend license requested.
CUNNINGHAM, R Atomic Energy Commission ORDTL-032 62/06/15
Army, Dept. of 1p. 18355·020

--8305020031 Recommends approval of encl request for changes in Diamond Ordnance Fuze Lab radiation protection program Radioisotope facilities adequate
DANIELS,R Q Army, Dept of MEDPS-PO 82/04/25 Atomic Energy Commission 3pp 18355 021

--8305020035 Submits results of leakage tests on Co-60 sealed sources per Condition 15 of Matl/Byproduct License 08-02534-01 Smear test removed contamination of 0 5 mCi from one sealed source
MCCOSKEY,R E Army, Dept of ORDTL-230 82/02/08 Atomic Energy Commission 1p 18355 024

--8305020039 Matl/Byproduct License 08-02534-01 for Diamond Ordnance Fuze Labs, authorizing possession & use of Co-60 tracerlab silver soldered sealed sources
* Atomic Energy Commission 57/05/01 2pp 18355 025

--8305020042 Recommends approval of encl application for renewal of Matl/Byproduct Licenses 08-02534-01 & 08-02534-02 for Diamond Ordnance Fuze Labs, requesting use & possession of 246 2 mCi Co-60 & 15 mCi Cs-137
DANIELS,R Q Army, Dept of MEDPS-PO 81/08/01 Atomic Energy Commission 1p 18355 027

--8305020047 Application for renewal of Matl/Byproduct License 08-02534-01, authorizing RE McCoskey as radiation protection officer & possession & use of 245 mCi Co-60 & 15 mCi Cs-137 stored in lead pigs
* Army, Dept of 36390 81/07/12 6pp 18355 028

--8305020049 Trip rept of 590414 visit to Diamond Ordnance Fuze Lab, Washington, DC re radioisotope program at facility Program is limited & does not require svcs of full-time health physicist
BASSIN,N Atomic Energy Commission 59/04/14 Atomic Energy Commission 3pp 18355 036

--8305020057 Application for renewal of Matl/Byproduct License 08-02534-01, authorizing R McCoskey as development supervisor & EE Conrad as radiological safety officer as users of Co-60 & Cs-137 sealed sources
* Army, Dept of 17455 59/03/03 4pp 18355 039

--8305020063 Forwards Diamond Ordnance Fuze Lab application for matl/byproduct license, authorizing use of 225 mCi cobalt Expedited handling requested License needed by 570515 Related matl encl
BARKER,R F Atomic Energy Commission 57/04/15 BUCHANAN,C R Atomic Energy Commission 3pp 18355 043

--8305020070 Recommends approval of encl application for matl/byproduct license for Diamond Ordnance Fuze lab, authorizing use of 245 mCi Co-60 & 15 mCi Cs-137 in sealed sources
CALLISON,R L Army, Dept of MEDCE-OH 57/04/17 BUCHANAN,C R Atomic Energy Commission 1p 18355 046

--8305020081 Forwards Harry Diamond Labs application to amend Licenses 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-0348 Amend removes JE Stafford as radiation protection officer & substitutes CA Rowe
QUEEN,W Q Army, Dept of 96381 78/09/06 Radioisotopes Licensing Branch (Pre 790501) 3pp 18355 047

--8305020095 Application to amend Licenses 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-0348, removing JE Stafford as radiation protection officer & substituting CA Rowe
GOODWIN,C R Army, Dept of 96381 78/08/11 2pp 18355 048

--8305020152 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-04 Current license will not expire until final action taken
* Division of Fuel Cycle & Material Safety 88400 77/07/15
TARAS,D N Army, Dept of 1p 18355·051

--8305020158 Submits addl info to be added to application for matl/byproduct license re handling & storage of sources
HINMAN,W.S Army, Dept of, 57/04/30 BASSIN,N Atomic Energy Commission. 2pp 18355.052.

--8305020169 Recommends approval of Diamond Ordnance Fuze Lab application for Licenses 08-02534-05, 08-02534-04, 08-2534-01 & 08-02534-03 & 08-02534-02, authorizing possession of listed radioactive matls
KRAUL,C W Army, Dept of. 17455 59/03/24. Atomic Energy Commission 1p 18355 054

--8305020178 Application for matl/byproduct license, authorizing possession & use of 245 mCi Co-60 & 15 mCi Cs-137 in tracerlab & sealed sources.
* Army, Dept of 57/04/12 5pp 18355.055.

--8305020187 Amend 3 to Matl/Byproduct License 19-17250-03, authorizing Sr-90 for use as check source
QUINN,P Division of Fuel Cycle & Material Safety 82/08/30 3pp 18355 060

--8305020191 Amend 2 to Matl/Byproduct License 19-17250-08, revising Condition 16 re possession & use of licensed matls
COMBS,F Radioisotopes Licensing Branch (Pre 790501) 78/09/29 1p 18355 063

--8305020196 Amend 1 to Matl/Byproduct License 19-17250-03, authorizing storage of Am-241, Sr-90 as check source in Victoreen Models AGB-10KG-SR survey instrument & 716A remote area monitors
BASSIN,N Radioisotopes Licensing Branch (Pre 790501) 77/08/29 3pp 18355 064

--8305020200 Matl/Byproduct License 19-17250-03 for Harry Diamond Labs, authorizing use of Am-241, Sr-90 sealed sources for startup of Triga Mark F Reactor & check sources in Victoreen Models AGB-10KG-SR & 716A remote area monitors
BASSIN,N Radioisotopes Licensing Branch (Pre 790501) 76/11/23. 3pp 18355·067

--8305020201 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-03 License will not expire until final action taken
HICKEY,J,W Division of Fuel Cycle & Material Safety 12134 82/08/05 TARAS,D Army, Dept. of 1p 18355 070.

--8305020204 Forwards application to renew Matl/Byproduct License 19-17250-03, authorizing possession & use of Sr-90 Victoreen BB-1010A sealed source as calibr source
TARAS,D N Army, Dept of DRCSF-P/82-0075 82/07/27 Radioisotopes Licensing Branch (Pre 790501) 1p 18355.071

--8305020207 Application for matl/byproduct license, authorizing MJ Borisky as radiation protection officer & JM McGarrity as alternate, for use of Sr-90 Victoreen BB-1010A sealed source as calibr source
* Army, Dept of. 12134 82/06/02 17pp 18355 072.

--8305020212 Notifies that Matl/Byproduct License 19-17250-03 expires on 820831 Renewal application must be filed w/updated info re radioisotope program
* Licensing Management Branch 12134. 82/05/20 Army, Dept. of 1p 18355·089

--8305020220 Matl/Byproduct License 19-17250-05 for Harry Diamond Labs, authorizing possession & use of Co-60
QUINN,P R Licensing Management Branch 79/05/10 3pp. 18355 092.

--8305020306 Amend 1 to Matl/Byproduct License 19-17250-05, adding Co-60 sealed source to Items 6, 7 & 8, per 780112 application
COMBS,F C Radioisotopes Licensing Branch (Pre 790501). 78/05/15. 1p 18355,095

--8305020318 Amend 2 to Matl/Byproduct License 19-17250-05, revising Condition 17 re possession & use of licensed matl, per 780811 application.
COMBS,F C Radioisotopes Licensing Branch (Pre 790501) 78/09/29. 1p 18355 096

--8305020323 Matl/Byproduct License 19-17250-05 for Harry Diamond Labs, authorizing possession of 37,296 Ci Co-60 sealed source for use in water pool irradiator for irradiation of matls excluding explosives & flammable matls.
BASSIN,N Radioisotopes Licensing Branch (Pre 790501) 77/11/14. 3pp 18355,097

--8305020505 Matl/Byproduct License 19-17250-05 for Harry Diamond Labs, authorizing use 37,296 Ci Co-60 sealed sources in water pool irradiator for irradiation of matls exluding explosive & flammable matls.
BASSIN,N. Radioisotopes Licensing Branch (Pre 790501). 77/11/03. 3pp 18355;100

--8305020525 Amend 4 to Matl/Byproduct License 19-17250-05 for Harry Diamond Lab, listing P Sarigianis as alternate operator of Co-60 facility & removing listed radiation detection instruments from Item 10.
BENAIT,W,R Army, Dept. of 06974. 81/01/03. 4pp. 18355;105.

--8305020539 Application for amend to Licenses 19-17250-04, 19-17250-03, 19-17250-01, 19-17250-05 & SNM-0348, removing JE Stafford as radiation protection officer & replacing CA Rowe
QUEEN,W Q Army, Dept. of 78/08/11. Radioisotopes Licensing Branch (Pre 790501). 2pp. 18355·117.

--8305020545 Forwards Harry Diamond Labs application for renewal & amend of Matl/Byproduct License 19-17250-03 Amend deletes 16 g Pu/Be neutron source from list of sources available for calibr & inclusion of storage for Am-241 source
TARAS,D N Army, Dept of 88400 77/06/30 Division of Fuel Cycle & Material Safety 1p 18355 120

--8305020550 Application for renewal of Matl/Byproduct License 19-17250-03,authorizing JE Stafford as radiation protection officer & JM McGarrity & CA Rowe as alternates & listed users of Am-241 & Sr-90 sealed sources
LOWREY,A Army, Dept of 88400 77/05/23. 14pp 18355 121

--8305020554 Application for amend to Matl/Byproduct License 08-02534-10,authorizing TB Grucci,radiation protection officer,as user of Am-241 beryllium neutron source as startup source for Triga reactor
* Army, Dept of 71783 76/10/06 3pp 18355 135

--8305020558 Application for amend of Matl/Byproduct License 08-02534-09, authorizing JE Stafford as radiation protection officer
MCGREGOR,T. Army, Dept. of 84025 76/10/04 6pp 18355 138

--8305020560 Forwards Harry Diamond Labs application to renew & amend Matl/Byproduct Licenses 08-02534-01 & 08-02534-09 Licenses will expire on 720831 Approval requested
REHRIG,A W Army, Dept. of 28995 72/06/29 Atomic Energy Commission 2pp 18355 144

--8305020564 Application for renewal of Matl/Byproduct License 08-02534-09,authorizing KA Camann as radiation protection officer & JM McGarrity & CA Rowe as alternate users of Am-241 & Sr-90 sources for Triga Mark F reactor
MOONEY,T Army, Dept of 29041 72/06/12. 17pp 18355 146

--8305020567 Application for renewal of Matl/Byproduct License 08-02534-09,authorizing TB Grucci as radiation protection officer & WL Giesler,JM McGarrity,ED McGarry & RB Oswald as users of Am-241,Sr-90 & Hf-198
CAMPAGNA,J.H Army, Dept of 95702 67/06/12 12pp 18355 162

--8305020571 Forwards Harry Diamond Labs application for renewal of Matl/Byproduct License 08-02534-09.Approval recommended.W/o encl.
MCKEEN,C M. Army, Dept of LOG/PE-188 67/07/17 Atomic Energy Commission 1p 18355 174

--8305030008 Recommends that encl application for amend to License 08-02534-10 be approved
FLYNN,R M Army, Dept of LOG/E2 65/09/29 Atomic Energy Commission. 1p 18355.175.

--8305030020 Application for renewal of Matl/Byproduct License 08-02534-10,authorizing possession & use of 50 uCi Am-241 & 10 Ci beryllium neutron source
BISCO,H W Army, Dept of 74495. 66/01/11 9pp 18355 176.

--8305030023 Notifies that amend to License 08-02534-09 requesting possession of 5 mCi Au-198 in liquid form canceled Au-198 sealed sources consist of solid metallic foils
GRUCCI,T.B Army, Dept. of 65/06/25. BASSIN,N Atomic Energy Commission 1p. 18355 185

--8305030027 Recommends that Au-198 in liquid form be deleted from 650416 application to renew License 08-02534-09 Approval also requested
FLYNN,R.M. Army, Dept of 65/07/19. Atomic Energy Commission 1p 18355.186

--8305030035 Application for renewal of Matl/Byproduct License 08-02539-09,authorizing TB Grucci as radiation protection officer & possession & use of Sr-90,Au-198 & Po-210
BISCO,H.W. Army, Dept. of 65/06/01 11pp. 18355:187.

--8305030047 Requests addl info re use & handling of Au-198 & drawings or specs for sealed sources containing Au-198,in response to 650416 application to amend License 08-02534-09
BASSIN,N. Atomic Energy Commission. 68231. 65/06/21 Army, Dept of. 1p. 18355.199

--8305030055 Application for matl/byproduct license,authorizing TB Grucci as radiation protection officer & listed individuals as users of 5 mCi Au-198 auric chloride liquid for use w/Triga dosimetry studies
BISCO,H.W Army, Dept of 89291. 65/04/16 9pp 18355·200.

--8305030063 Application to amend Matl/Byproduct License 08-02534-09, substituting TB Grucci in place of GP Hanson as radiation protection officer
FLYNN,R M Army, Dept of 65/05/18 Atomic Energy Commission 3pp 18355 209

--8305030073 Application to amend Matl/Byproduct License 08-02534-09, substituting TB Grucci in place of GP Hanson as radiation protection officer W/o encl resume
FLYNN,R M Army, Dept of 66549 65/03/09 1p 18355 212

--8305030080 Forwards Harry Diamond Labs application for renewal of Matl/Byproduct License 08-02534-10 Approval recommended
SEIDLER,G Army, Dept of 65/01/27 Atomic Energy Commission 1p 18355 213

--8305030087 Forwards drawings for encapsulation of 10 Ci Am/Be neutron source for use as startup source in HDL-DORF Triga Mark F reactor Both vendors should be approved as possible sources for item Related info encl
BERMAN,P G Army, Dept of 66/02/01 BASSIN,N Atomic Energy Commission 4pp 18355 214

--8305030092 Submits addl info in response to 651101 request re 650819 application for possession & use of Am-241 beryllium neutron source US Nuclear Corp has two sources of 6 48 & 10 Ci designated as Models AM-200 & Am-309
GRUCCI,T B Army, Dept of 65/11/30 BASSIN,N Atomic Energy Commission 1p 18398 066

--8305030098 Requests addl info re model numbers of Monsanto Research Corp & Numec Instrument & Contols Corp sources,in response to 650819 application for Am-241 beryllium neutron source
BASSIN,N Atomic Energy Commission 65/11/01 Army, Dept of 7pp 18355 219

--8305030105 Application for renewal of Matl/Byproduct License 08-02534-09,authorizing GP Hanson as radiation protection officer & WL Giesler & PG Berman as users of Po-210 & Sr-90
BISCO,H W Army, Dept of 53145. 63/08/05 11pp 18355·226

--8305030125 Recommends that amends & renewals of Matl/Byproduct Licenses 08-02534-01 & 08-02534-09 for Harry Diamond Labs be approved & disposition of isotopes on License 08-02534-02 be shown as stated on encl certificate W/o encl
DANIELS,R.G Army, Dept of. 63/08/01. Atomic Energy Commission 1p 18355 237

--8305030142 Forwards Diamond Ordnance Fuze Labs application for amend to Matl/Byproduct License 08-02534-09 for 2,430 mCi Sr-90. Approval recommended.Radiation protection program adequate for proposed use
DANIELS,R G Army, Dept of 49063 63/01/22 Atomic Energy Commission 1p 18355 238

--8305030147 Application for amend to Matl/Byproduct License 08-02534-09 for possession & use of Po-210
DANIELS,R.G Army, Dept of 62/08/28 Atomic Energy Commission 2pp 18355.241

--8305030154 Forwards Diamond Ordnance Fuze Labs application to amend Matl/Byproduct License 08-02534-09 to include one addl Sr-90 sealed source Approval recommended
DANIELS,R.G Army, Dept of. 41312 62/02/28 Atomic Energy Commission 5pp 18399 007.

--8305030163 Application for amend to Matl/Byproduct License 08-02534-09, authorizing GP Hanson to perform tests for leakage & contamination,replacing A Schwebel
MCEVOY,R W. Army, Dept of. 62/07/11 2pp 18355 244.

--8305030169 Application for matl/byproduct license,authorizing possession & use of Sr-90 sealed sources included in listed monitoring instruments.
FLYNN,R M. Army, Dept of 68281 61/10/30 5pp 18355·247.

--8305030174 Forwards Diamond Ordnance Fuze Lab application for matl/byproduct license for 1820 mCi Sr-90.Approval recommended Radioisotope facilities adequate
DANIELS,R.G. Army, Dept. of. 61/11/01 Atomic Energy Commission 1p. 18355:252

--8305030179 Forwards Diamond Ordnance Fuze Lab application for matl/byproduct license for possession & use of 20 Ci Po-210
DANIELS,R G Army, Dept. of 38700 61/08/17 Atomic Energy Commission. 1p 18355.253

--8305030185 Application for matl/byproduct license,authorizing possession & use of 20 Ci Po-210 sealed neutron sources
BISCO,H.W. Army, Dept of 61/08/16 5pp 18355·254.

--8305030189 Amend 3 to License SNM-348, revising Subitems 9 A-9 F & Conditions 10, 12 & 18 re dosimetry studies & calibr studies
WALKER, W J Division of Fuel Cycle & Material Safety 82/12/21
1p 18355 259

--8305030195 Amend 2 to License SNM-348, revising Condition 18 re possession & use of licensed matl described in Items 6, 7 & 8
QUINN, P R Division of Fuel Cycle & Material Safety 80/07/09
1p 18355 260

--8305030201 Amend 1 to License SNM-348, revising possession amounts for Pu-239, Np-237, depleted U, U-235 & U-238 encapsulated fission foils & sources
COMBS, F C Division of Fuel Cycle & Material Safety 78/10/30
3pp 18355 261

--8305030207 Renewed License SNM-348 for Harry Diamond Labs, authorizing possession & use of Pu-239, U-235, natural & depleted U & Np-237 encapsulated fission foils
LAYFIELD, R L Atomic Energy Commission, Directorate of Licensing
72/12/19 2pp 18355 264

--8305030212 License SNM-348 for Harry Diamond Labs, authorizing possession & use of Pu-239, U-235, natural & depleted U & Np-237 encapsulated fission foils
LAYFIELD, R L Atomic Energy Commission 68/07/15 3pp
18355 266

--8305030213 License SNM-348 for Harry Diamond Labs, authorizing possession & use of Pu & U enriched in U-235 fission foil
JOHNSON, L Atomic Energy Commission 65/07/16 3pp 18355 269

--8305030218 Application to amend License SNM-348, requesting storage of matls prior to transfer, substituting CA Rowe as alternate radiation officer & listing MJ Borisky as radiation protection officer
MOTHERSBAUGH, L Army, Dept of 21639 82/11/22
Radioisotopes Licensing Branch (Pre 790501) 12pp 18355 272

--8305030225 Forwards resume of MD Funkhouser, designated new radiation protection officer at Harry Diamond Labs replacing C Rowe W/o encl
TARAS, D N Army, Dept of 16469 80/05/22 Radioisotopes Licensing Branch (Pre 790501) 6pp 18355 284

--8305030233 Forwards Harry Diamond Labs response to 780706 ltr re License SNM-348 Headquarters concurs w/response
Ack of receipt of correspondence requested W/o encl
TARAS, D N Army, Dept of 70667. 78/07/24 COMBS, F
Radioisotopes Licensing Branch (Pre 790501) 1p 18355 289

--8305030239 Submits addl info re security requirements, radiation safety facilities & procedures for storage & use of Np-237 foil matl listed on Harry Diamond Labs application for renewal of License SNM-348
GOODWIN, C R Army, Dept of 78/07/19 COMBS, F Radioisotopes Licensing Branch (Pre 790501) 2pp 18355; 290

--8305030249 Requests addl info re security requirements, radiation safety facilities & procedures for use & storage of Np-237 & description of leak testing procedures for fission foils
COMBS, F Radioisotopes Licensing Branch (Pre 790501) 78/07/06
TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command 1p 18355 292

--8305030251 Application for renewal of License SNM-348, reflecting changes in location of lab headquarters, amount of Pu-239 in Pu-Be neutron source & radiation protection officers & users
TARAS, D N Army, Dept of 77/11/18 Radioisotopes Licensing Branch (Pre 790501) 17pp 18355 293

--8305030255 Ack receipt of application to renew License SNM-348 License expire until final action taken
Radioisotopes Licensing Branch (Pre 790501) 08143
TARAS, D N Army, Dept of 1p 18355 310

amend & renewal of License SNM-348,
use of 9 76 mg Pu-239, 0 24 g U-235,

/04 Atomic Energy

evising expiration date to
to license record
on 65/01/12 FLYNN, R M

--8305030268 Amend 3 to License SNM-348, revising Items 7 & 8 & adding Item 14 re licensee compliance w/attached leak test conditions for Pu alpha sources
DOULOS, N , NUSSBAUMER, D Atomic Energy Commission 64/01/21
GOLDSTEIN, B L Army, Dept of 1p 18355 333

--8305030278 Forwards Amend 2 to License SNM-348 License does not authorize insertion of matls into nuclear reactor Insertions must be authorized W/o encl
JOHNSON, L Atomic Energy Commission 63/09/26 GOLDSTEIN, B L
Army, Dept of 1p 18355 334

--8305030281 Amended License SNM-348 for Harry Diamond Labs, authorizing enriched U-235 as Pu-Be neutron source & 64 6 g as fission foils
* Atomic Energy Commission 63/09/26 4pp 18355 335

--8305030286 License SNM-348 for Harry Diamond Labs, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source, 12 micrograms encapsulated in fast neutron detectors & 10 g encapsulated as neutron activation detectors
JOHNSON, L Atomic Energy Commission 62/02/27 1p 18355 339.

--8305030289 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing use of 16 g Pu encapsulated as Pu-Be neutron source 12 micrograms encapsulated in fast neutron detectors
* Atomic Energy Commission 61/11/14 2pp 18355 340

--8305030296 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu encapsulated as Pu-Be neutron source & 12 micrograms encapsulated in fast neutron detectors
NUSSBAUMER, D Atomic Energy Commission 61/05/18 1p
18355 342

--8305030301 License SNM-348 for Diamond Ordnance Fuze Lab, authorizing possession & use of 16 g Pu as encapsulated Pu-Be neutron source
DELANEY, J C Atomic Energy Commission 60/02/03 2pp
18355 343

--8305030304 Amend to License SNM-348, correcting docket number error in Item 5 Correct number should be 70-0378
LAYFIELD, R L Atomic Energy Commission 68/07/24 HAAB, C F
Army, Dept of 1p 18355 345

--8305030309 Forwards renewed License SNM-348, reflecting leak test condition for Pu as sealed source W/o encl
LAYFIELD, R L Atomic Energy Commission 68/07/15 HAAB, C F
Army, Dept of 1p 18355 346

--8305030312 Application for renewal & amend of License SNM-348, authorizing possession & use of 54 7 g PU & 16 g PU-239, Np-237, depleted U, U-235 & U-238 neutron source in encapsulated calibr sources & fission foils
HAAS, C F Army, Dept of 68/06/25 11pp 18355·347.

--8305030320 Notifies that License SNM-348 expires on 680731. Application for renewal of license should be filed within 30 days Notification should be given at decision not to renew by completing encl form W/o encl
NUSSBAUMER, D A Atomic Energy Commission 68/05/26 SEIDLER, Q.
Army, Dept of 1p 18355, 358

--8305030323 Forwards renewed License SNM-348, W/o encl
JOHNSON, L Atomic Energy Commission 65/07/16 SEIDLER, Q Army, Dept of 1p 18355·359

--8305030326 Forwards addl info re use & storage of Pu neutron source, per AEC 650604 request Includes description of Pu neutron source & dimensions of tantalum & stainless steel source container.
SEIDLER, Q Army, Dept of 65/07/06 Atomic Energy Commission
2pp 18355 360

--8305030332 Requests addl info re use & storage of Pu neutron source & personnel monitoring program, in response to 650505 application to renew License SNM-348.
LAYFIELD, R L Atomic Energy Commission 65/06/04 FLYNN, R M
Army, Dept of 1p 18355 362

--8305030335 Application for renewal & amend to License SNM-348, authorizing 13. 4 g Np-237, 54 5 g Pu-239, 54 5 g U-235 & 143 g U-238 in form of fission foils for calibr studies
FLYNN, R M. Army, Dept of 65/05/05 Atomic Energy Commission.
12pp 18356 001

--8305030339 Matl/Byproduct License 19-17250-04 for Dept of Army,Harry Diamond Labs,authorizing use of 250 mCi irradiated electronic equipment & threshold detectors for experimental development of laser devices
BASSIN,N Radioisotopes Licensing Branch (Pre 790501) 76/11/24 2pp 18356 013

--8305030684 Amend 2 to Matl/Byproduct License 19-17250-04,making editorial changes to Condition 14
COMBS,F Radioisotopes Licensing Branch (Pre 790501) 78/09/29 1p 18356 016

--8305040060 Application to amend License 19-17250-01,19-17250-03, 19-17250-04,19-17250-05 & SNM-348,removing JE Stafford as radiation protection officer & substituting CA Rowe
GOODWIN,C R , GUEEN,W Q Army, Dept of, Headquarters Materiel Development & Readiness Command 78/08/11 Radioisotopes Licensing Branch (Pre 790501) 3pp 18356 023

--8305040081 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-04 License will not expire until final action taken
QUINN,P R Radioisotopes Licensing Branch (Pre 790501) 92389 78/01/27 TARAS,D.N Army, Dept of, Headquarters Materiel Development & Readiness Command 1p 18356 026

--8305040089 Application for renewal & amend of Matl/Byproduct License 19-17250-04,removing ED McQarry,FW Balicki & MB Rothstein from list of authorized users of licensed matl & adding CR Heimbach,TL Pruitt & S Share as authorized users
TARAS,D N Army, Dept of, Headquarters Materiel Development & Readiness Command 92389, 78/01/16, Radioisotopes Licensing Branch (Pre 790501) 2pp 18356 027

--8305040093 Application for renewal & amend of Matl/Byproduct License 19-17250-04,authorizing listed individuals to use any byproduct matl w/Atomic Numbers 3-83 inclusive,w/activated electronic & threshold detectors
RAMSDEN,J J Army, Dept of 92389 83/01/11 15pp 18356 029

--8305040103 Forwards Harry Diamond Labs application for renewal of Matl/ Byproduct License 19-17250-04.
TARAS,D N Army, Dept of, Headquarters Materiel Development & Readiness Command 94530 78/05/12 Radioisotopes Licensing Branch (Pre 790501) 1p 18356·044

--8305040114 Application for renewal & amend of Matl/Byproduct License 19-17250-04,authorizing listed individuals as users of any byproduct matl w/Atomic Numbers 3-8 & electronic equipment
RAMSDEN,J J Army, Dept of 94530 78/01/16 16pp. 18356 047

--8305040120 "Procedures for Maintaining Radiological Safety," Administrative Circular 6.
* Army, Dept. of 23772. 57/10/31. 48pp 18356 063

--8305040127 Forwards application to amend Matl/Byproduct License 08-02534-06 for Harry Diamond Labs Amend reflects new location of headquarters & removes Semiconductor & Radiation Effects Physics Branch.
TARAS,D N Army, Dept. of, Headquarters Materiel Development & Readiness Command DRCBF-P176-0090 76/10/06 Office of Nuclear Material Safety & Safeguards,Director. 1p. 18356·112

--8305040158 Application for amend of Matl/Byproduct License 08-02534-06 for Harry Diamond Labs No changes indicated
MCGREGOR,T. Army, Dept of 89035 76/10/04. 2pp. 18356 113

--8305040165 Forwards application for amend to Matl/Byproduct License 08-02534-06 for Harry Diamond Labs,authorizing listed individuals as users of any byproduct matl w/Atomic Numbers 3-83 in activated electronic equipment
RATCLIFF,R.H. Army, Dept of DALO-MAB-I 74/04/08. Atomic Energy Commission 1p. 18356.115

--8305040175 Application to amend Matl/Byproduct License 08-02534-06 for Harry Diamond Labs,authorizing listed individuals as users of any byproduct matl w/Atomic Numbers 3-83 in activated electronic equipment & threshold detectors
EINSEL,D.W. Army, Dept. of 47101 74/04/18 16pp 18356·116

--8305040183 Forwards application for renewal of Matl/Byproduct License 08-02534-06 for Harry Diamond Labs,deleting & adding listed names for users of activated electronic equipment & threshold detectors for experimental laser development
REHRIG,A W Army, Dept of DALO-MAI 73/01/11. Atomic Energy Commission. 1p. 18356·132

--8305040189 Application for renewal & amend of Matl/Byproduct License 08-02534-06 for Harry Diamond Labs,deleting & adding listed names for users of activated electronic equipment & threshold detectors for experimental laser development
EINSEL,D W Army, Dept of 73/01/04 14pp 18356 133

--8305040200 Forwards application to amend Matl/Byproduct License 08-02534-06 for Harry Diamond Labs Amend allows for max possession of 100 Ci of isotopes resulting from activation of crystals (laser matls)
KELLEY,W D Army, Dept of DALO-MAE-I 71/11/10 Atomic Energy Commission 1p 18356 146

--8305040211 Application for amend of Matl/Byproduct License 08-02534-06,authorizing listed individuals as users of activated electronic equipment & threshold detectors for experimental development of laser devices
CAMPAGNA,J H Army, Dept of 25039 71/09/24 11pp 18356 147

--8305040217 Application to amend Matl/Byproduct License 08-02534-06, including Connecticut Avenue & Van Ness Street location as place of usage for irradiated electronic equipment
HAAS,C F Army, Dept of LOG/PE-ISB 69/09/05 Atomic Energy Commission 2pp 18356 158

--8305040224 Application for renewal of Matl/Byproduct License 08-02534-06 for Harry Diamond Labs,authorizing listed individuals as users of any matl byproduct w/Atomic Numbers 3-8 w/activated electronic equipment
CAMPAGNA,J H Army, Dept of 99831 67/11/30 10pp 18356 160

--8305040234 Application for renewal of Matl/Byproduct License 08-02534-06,authorizing listed individuals as users of any matl product w/Atomic Numbers 3-83 for activated electronic equipment
SISCO,H W Army, Dept of 74456 66/01/05 10pp 18356 171.

--8305040239 Application for amend to Licenses 08-02534-06 & 08-02534-08, listing TB Grucci as radiation protection officer
FLYNN,R M Army, Dept of 65/02/24 Atomic Energy Commission 1p 18356.181.

--8305040244 Application to amend Licenses 08-02534-06 & 08-02534-08, substituting TB Grucci as radiation protection officer
GRUCCI,T B. Army, Dept of LOG/E2 65/01/28 2pp 18356 182

--8305040250 Application for renewal of Matl/Byproduct License 08-02534-06,authorizing listed individuals as users of activated electronic equipment subj to post-irradiation exam
SISCO,H W Army, Dept of. 57098 63/12/31 8pp 18356 184

--8305040256 Recommends approval of encl request for renewal of Matl/ Byproduct License 08-02534-06 for Harry Diamond Labs W/o encl
CHEATHAM,J R Army, Dept of 57098 64/01/30 Atomic Energy Commission 1p 18356 192

--8305040266 Notifies that no amend to Matl/Byproduct Licenses 08-02534-01,08-02534-06 & 08-02534-10 needed re designation of GP Hanson as radiation protection officer
BASSIN,N Atomic Energy Commission 62/11/05 Army, Dept of 1p 18356 193

--8305040272 Application to amend Matl/Byproduct License 08-02534-06, for Diamond Ordnance Fuze Labs,designating GP Hanson as radiation protection officer,replacing RE McCoskey
MCEVOY,R.W Army, Dept of 62/10/02 Atomic Energy Commission 2pp 18356 194

--8305040279 Recommends approval of Matl/Byproduct License 08-02534-06 for Diamond Ordnance Fuze Labs for 250 mCi of all isotopes w/Atomic Numbers 3-83
DANIELS,R G. Army, Dept. of. 90341 62/02/08 Atomic Energy Commission. 1p. 18356 196

--8305040287 Application for renewal of Matl/Byproduct License 08-02534-06,authorizing listed persons as users of activated electronic equipment subj to post-irradiation exam
HORTON,B.M Army, Dept. of 40841 62/01/11 2pp 18356 197

--8305040290 Application for matl/byproduct license for Diamond Ordnance Fuze Labs,requesting listed individuals as users of all Isotopes 3-83 activated electronic equipment subj to post-irradiation exam
MCCOSKEY,R E Army, Dept. of 23772 60/01/26 7pp 18356.199

--8305040294 Recommends approval of encl application for Matl/Byproduct License 08-02534-06 for Diamond Ordnance Fuze Labs, authorizing use of 250 mCi of all Isotopes 3-83
KRAUL, C.W Army, Dept of 23772 80/01/28 Atomic Energy Commission 1p 18356 206

--8305040297 Amend 5 to Matl/Byproduct License 19-17250-01, authorizing use of listed matl at Harry Diamond Labs
HICKEY, J W Office of Nuclear Material Safety & Safeguards, Director 83/01/11 3pp 18356 207

--8305040310 Amend 2 to Matl/Byproduct License 19-17250-01, adding editorial change to Condition 16
COMBS, F Radioisotopes Licensing Branch (Pre 790501) 78/09/29 1p 18356 212

--8305040366 Amend 1 to Matl/Byproduct License 08-02534-01, authorizing use of tracer lab sealed sources & Nuclear Chicago Model 850233 containing Co-60 & Cs-137 at Harry Diamond Labs
* Radioisotopes Licensing Branch (Pre 790501). 83/01/11 3pp 18356 213

--8305040376 Matl/Byproduct License 19-17250-01 for Harry Diamond Labs, authorizing use of tracerlab sealed sources & Nuclear Chicago Model 850213 sealed sources, containing Co-60 & Cs-137
BASSIN, N Radioisotopes Licensing Branch (Pre 790501). 76/11/23. 4pp 18356 216

--8305040380 Notifies that Matl/Byproduct License 19-17250-01 expires on 820831 W/o encl renewal forms
* Licensing Management Branch 82/05/20 Agriculture, Dept of. 1p 18356 219

--8305040387 Forwards Harry Diamond Labs response to 821007 request for addl info in support of application to renew Matl/Byproduct License 19-17250-01.
TARAS, D N Agriculture, Dept of DRCSF-P/82-0035 82/11/04.
PATTERSON, J M Radioisotopes Licensing Branch (Pre 790501) 1p 18356 220

--8305040392 Forwards instrument calibr procedures, radiation survey program & personnel exposure repts
WILLIAMS, R Agriculture, Dept of 82/10/28 NRC - No Detailed Affiliation Given 68pp 18356 221

--8305040403 Requests addl info re instrument calibr procedure & radiation survey program for renewal of License 19-17250-01 for Harry Diamond Labs Response should be provided per Reg Guide 10 7
PATTERSON, J W Assistant Director for Material Safety & Licensing 12247 82/09/30 Army, Dept of 2pp 18356 292.

--8305040408 Ack receipt of application for renewal of Matl/Byproduct License 19-17250-01
HICKEY, J W Assistant Director for Material Safety & Licensing 12247 82/08/19 Army, Dept of 2pp 18356 294

--8305040414 Forwards Harry Diamond Labs application for renewal of Matl/Byproduct License 19-17250-01 W/o encl
MOTHERSBAUGH, L Army, Dept of DRCSF-P/82-0035. 82/08/09. Radioisotopes Licensing Branch (Pre 790501) 2pp 18356 295

--8305040425 Application for renewal of Matl/Byproduct License 19-17250-01, authorizing KQ Kerris as physicist, CC Casaer & P Sarigianis as Co-60 irradiator operator & MJ Borisky as radiation protection officer
BURKE, A R Army, Dept. of 12247 82/03/12 16pp. 18356 297.

--8305040450 Forwards Harry Diamond Labs application to amend Matl/Byproduct License 19-17250-01 Amend lists new personnel & deletes other personnel from list of individual users, deletes instruments & adds replacement instrumentation
TARAS, D N Army, Dept of. 81/01/27 Radioisotopes Licensing Branch (Pre 790501). 1p 18356 313

--8305040468 Forwards Harry Diamond Labs application to amend Matl/Byproduct Licenses 19-17250-01, 19-17250-03, 19-17250-04, 19-17250-05 & SNM-348
QUEEN, W G Army, Dept of, Headquarters Materiel Development & Readiness Command. 96382 78/09/06 Radioisotopes Licensing Branch (Pre 790501). 1p 18356 326

--8305040478 Application for amend to Matl/Byproduct Licenses 19-17250-01, 19-17250-03, 19-17250-05 & SNM-348 Amend requests removal of JE Stafford as radiation protection officer & substitutes CA Rowe
GOODWIN, C R Army, Dept of. 96382. 78/08/11 2pp 18356, 327.

--8305040484 Ack receipt of application to renew Matl/Byproduct License 19-17250-01 License will not expire until final action taken
COMBS, F C Radioisotopes Licensing Branch (Pre 790501) 88401 77/07/15 TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command 1p 18356 329

--8305040489 Forwards Harry Diamond Labs application to renew Matl/Byproduct License 19-17250-01 Ack of correspondence requested
TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command DRCSF-P/77-0048 77/06/30 Office of Nuclear Material Safety & Safeguards, Director 1p 18356 330

--8305040501 Application for renewal of Matl/Byproduct License 19-17250-01, authorizing listed individuals as users of Co-60 & Cs-137 sealed sources for calibr of radiation detection instruments
LOWREY, A Army, Dept of 88401 77/05/26 14pp 18356 331.

--8305040502 Forwards Harry Diamond Labs application to amend Matl/Byproduct License 08-02534-01
TARAS, D N Army, Dept of, Headquarters Materiel Development & Readiness Command DRCSF-P/76-0093 76/10/06 Office of Nuclear Material Safety & Safeguards, Director. 2pp 18356 345.

--8305040510 Application to amend Matl/Byproduct License 08-02534-01, authorizing JE Stafford as radiation protection officer & JM McGarrity & CA Rowe as alternate radiation protection officer.
MCGREGOR, T Army, Dept of 84012 76/10/04 12pp 18356·347.

--8305040519 Application to renew & amend Matl/Byproduct License 08-02534-01, authorizing listed individuals as users of Co-60 & Cs-137 sealed source, for calibr of radiation detection instruments
MOONEY, T R Army, Dept of 28995 72/06/13. 14pp 18356·361.

--8305040523 Notifies that sources will be used for calibr of scintillation detectors & TLDs in response to 670626 ltr Calibr procedure discussed
GRUCCI, T B Army, Dept of AMXDO-RBB 67/06/29 BASSIN, N Atomic Energy Commission 2pp. 18357 013.

--8305040554 Recommends application to amend Matl/Byproduct Licenses 08-02534-01, 08-02534-06 & 08-02534-10 for Diamond Ordnance Fuze Labs be approved Amend revises name of radiation protection officer
DANIELS, R G Army, Dept. of MEDRS-PO. 62/10/29 Atomic Energy Commission 1p. 18357 015

--8305040556 Application to amend Matl/Byproduct Licenses 08-02534-01, 08-02534-06 & 08-02534-10, revising name of radiation protection officer.
MCEVOY, R W. Army, Dept. of 45482 82/07/14 3pp 18357:016

--8305040559 Application for renewal & amend to Matl/Byproduct Licenses 08-02534-01 & 08-02534-09, designating GP Hanson as radiation protection officer, replacing RE McCaskey
MCEVOY, R.W. Army, Dept of 47842. 62/10/02. 2pp. 18357:020

--8305040562 Recommends approval of encl application for amend of Matl/Byproduct Licenses 08-02534-01 & 08-02534-09 for Diamond Ordnance Fuze Labs. W/o encl
DANIELS, R G. Army, Dept of. 45482 62/08/08 Atomic Energy Commission 1p. 18357 022

--8305040569 Application to renew Matl/Byproduct License 08-02534-01 for Harry Diamond Labs, authorizing GP Hanson as radiation protection officer & listed individuals as users of Co-60 & Cs-137 sources
SISCO, H W Army, Dept of 53144 63/07/16. 9pp. 18357:023.

--8305040573 Requests that Harry Diamond Labs Matl/Byproduct License 08-02534-01 be annotated to list TB Grucci as radiation protection officer Resume encl.
FLYNN, R M. Army, Dept. of 66554 65/03/09. Atomic Energy Commission. 3pp. 18357·032.

--8305040578 Application for Amend 4 to Matl/Byproduct License 08-02534-01, substituting TB Grucci as radiation protection officer
GRUCCI, T.B. Army, Dept. of. 66554 65/02/19. 2pp 18357, 033

--8305040579 Ack receipt of application for renewal of Matl/Byproduct License 08-02534-01. License will remain in effect until final action taken Addl info re use & handling of sources requested
BASSIN, N. Atomic Energy Commission 67/06/26 Army, Dept. of. 1p 18357:035

--8305040583 Application for renewal & amend to License SNM-348, including YB Grucci as authorized user
FLYNN, R M Army, Dept. of 64/12/30 4pp 18357 036

--8305040586 Notifies that License SNM-348 expires on 650131 Application for renewal should be submitted 30 days prior to expiration of license Notification of nonrenewal should be given by completing encl form W/o encl
NUSSBAUMER, D A Atomic Energy Commission 64/12/19
GOLDSTEIN, B L Army, Dept of 1p 18357 040

--8305040587 Notifies that no action will be taken on Harry Diamond Labs 640417 application to amend License SNM-348, per 640605 telcon
LAYFIELD, R L Atomic Energy Commission 64/06/24 SEIDLER, G
Army, Dept of 1p 18357 041

--8305040593 Application for amend to License SNM-348 re periodic leak tests
SIEDLER, G Army, Dept of 64/05/22 Atomic Energy Commission
2pp. 18357·042

--8305040599 Application for amend of License SNM-348 to include 5 mCi Pu-239 for Harry Diamond Labs
GOLDSTEIN, B L Army, Dept of 63/12/17 Atomic Energy
Commission 3pp 18357 044

--8305040603 Discusses Condition 13 of License SNM-348, in response to 631011 ltr & 631003 telcon Condition 13 does not authorize actual insertion of matl held under license into any reactor Insertions should be authorized
NUSSBAUMER, D A Atomic Energy Commission 63/10/23 BERMAN, P G
Army, Dept of, 1p 18357 047

--8305040674 Requests cancellation ltr requesting allocation of 99 8% U-235 for use as threshold detector for fast neutron dosimetry.
BERMAN, P.G. Army, Dept. of. 63/10/11 LAYFIELD, R Atomic Energy
Commission. 1p. 18357 048

--8305040678 Forwards addl info re Harry Diamond Labs application for amend to License SNM-348 per request
GOLDSTEIN, B L Army, Dept of 63/09/13 Atomic Energy
Commission. 7pp 18357·049

--8305040687 Requests addl info re procedures for use & storage of Np-237, Pu-239 & U-238 fission foils, in response to 630531 request for amend to License SNM-348 for Harry Diamond Labs
NUSSBAUMER, D. Atomic Energy Commission 63/07/17 DANIELS, R. G
Army, Dept. of 6pp. 18357·056

--8305040696 Requests allocation of 31 g U-235 as metal of 99 8% purity for fission foil fast neutron dosimetry sys for DORF-Triga reactor
BERMAN, P. G Army, Dept. of 63/08/21 NUSSBAUMER, D. A. Atomic
Energy Commission. 1p 18357.062.

--8305050292 Requests addl info re procedures for use & storage & description of foils, in response to 650531 application to amend License SNM-348
NUSSBAUMER, D. A. Atomic Energy Commission 63/07/15. DANIELS, R. G.
Army, Dept. of. 1p. 18357 063.

--8305050297 Application for amend to License SNM-348, authorizing possession & use of 13.4 g Np-237, 54 5 g Pu-239, 54 5 g U-235 & 143 g U-238.
DANIELS, R. G. Army, Dept. of. 4020. 63/05/31 Atomic Energy
Commission. 9pp. 18357.064.

--8305050301 Notifies that RW McEvoy 621115 ltr made part of records under Docket 70-378. Changes in technical & supervisory personnel having health-safety responsibilities should be provided on continual basis.
NUSSBAUMER, D. A. Atomic Energy Commission. 63/01/29 DANIELS, R G.
Army, Dept. of 1p 18357 073

--8305050306 Application for amend to License SNM-348, substituting WL Gieseler for W Hunker as supervisor of instruments incorporating Pu calibr sources
DANIELS, R. G. Army, Dept of 63/01/22. Atomic Energy
Commission. 3pp. 18357:074

--8305050310 Requests nuclear matl draft re receipt of 5 g Pu foils contained in nuclear accident dosimetry sys.
HANSON, G P. Army, Dept of. 10769 62/11/26 LANE, J Atomic
Energy Commission 1p. 18357·077

--8305050312 Amend to License SNM-348, revising Item 8 re authorized use of licensed matl.
NUSSBAUMER, D. A. Atomic Energy Commission. 62/08/15. DANIELS, R. G
Army, Dept. of. 1p 18357:078

--8305050316 Application for amend to License SNM-348, revising Item 8 re calibr of neutron survey meters & designating GP Hanson as authorized matl user
DANIELS, R G Army, Dept of 62/08/07 Atomic Energy
Commission 3pp 18357 079

--8305050319 Forwards amended License SNM-348 W/o encl
NUSSBAUMER, D A Atomic Energy Commission 62/02/27 DANIELS, R G
Army, Dept of 1p 18357 082

--8305050322 Application for renewal of License SNM-348 for possession & use of 26 g Pu, 12 mg Pu, 1 g Np-237 & 50 g depleted U
DANIELS, R G Army, Dept of 62/01/15 Atomic Energy
Commission 1p 18357 083

--8305050326 Notifies that License SNM-348 expires on 620131 Renewal application should be filed within 30 days
NUSSBAUMER, D A Atomic Energy Commission 61/12/01 DANIELS, R G
Army, Dept of 1p 18357 085

--8305050328 Forwards diagram of cannister used in nuclear accident dosimetry sys, per telcon request
MCCOSKEY, R E Army, Dept of 61/10/24 NUSSBAUMER, D Atomic
Energy Commission 2pp 18357 086

--8305050330 Forwards application to amend License SNM-348, authorizing possession & use of 30 g depleted U, 10 g Pu-239 & 1 g Np-237
DANIELS, R G Army, Dept of 61/10/09 Atomic Energy
Commission 3pp 18357·088

--8305050333 Application to amend License SNM-348, authorizing possession & use of addl 12 micrograms Pu in form of calibr devices
KRAUL, C W Army, Dept of 61/05/01 Atomic Energy Commission
2pp 18357:091

--8305050335 Forwards License SNM-348 W/o encl
DELANEY, J C Atomic Energy Commission 60/02/03 HIRMAN, W S
Army, Dept of. 1p 18357 093

--8305050337 Forwards Diamond Ordnance Fuze Lab 591113 application for SNM license Classification review requested W/o encl
FLEURY, E. R Atomic Energy Commission 60/01/28 STRAUSER, W A
Atomic Energy Commission 1p 18357 094

--8305050339 Application for amend to License SNM-348, authorizing possession & use of Pu
KRAUL, C W Army, Dept of 59/12/21 Atomic Energy Commission
5pp 18357:095

--8305050342 Submits detailed results of radiation survey conducted on 771213-15, per License Condition 16 & NRC requirements
RAMSDEN, J J Army, Dept of 93972 78/01/12 COMBS, F
Radioisotopes Licensing Branch (Pre 790501) 8pp. 18357·100

--8305050346 Concurs w/encl Harry Diamond Labs radiation survey conducted on 771213-15 W/o encl.
TARAS, D. N Army, Dept of. 93972 78/03/28 COMBS, F.
Radioisotopes Licensing Branch (Pre 790501) 1p. 18357 108

--8305050349 Forwards Harry Diamond Labs 770922 response to 770823 inquiry re procedures for obtaining authority to possess, use & transfer radioactive matl, per License 08-02534-12
TARAS, D N Army, Dept of. 77/09/26 COMBS, F. Radioisotopes
Licensing Branch (Pre 790501) 2pp 18357 109

--8305050351 Forwards addl info re Harry Diamond Labs application for amend of License 08-02534-12. Training procedures for individuals using Co-60 discussed W/o encl.
RAMSDEN, J J Army, Dept of 90132 77/09/22 COMBS, F
Radioisotopes Licensing Branch (Pre 790501) 1p. 18357:111

--8305050355 Requests addl info in response to application for license to use radioactive matl in custom-designed water well irradiator Description of operators training program, mods to facility & procedures to conduct daily checks requested
COMBS, F. Radioisotopes Licensing Branch (Pre 790501). 86795
77/08/23. STAFFORD, J Army, Dept of 15pp 18357·114

--8305050359 Application for amend to Matl/Byproduct License 08-02534-12, allowing for establishing Co-60 water-well/free-air irradiation facility.
QUEEN, W. G Army, Dept. of 86795 77/04/07. Radioisotopes
Licensing Branch (Pre 790501) 3pp 18357.130

--8305050361 Application for amend to Matl/Byproduct License 08-02534-12, authorizing possession & use of 269 Ci Co-60 in encapsulated neutron sources.
MCGREGOR, T. Army, Dept. of. 86795 83/01/11. 30pp 18357 133.

--8305050363 "Co-60 Irradiator Sys for Harry Diamond Labs "
* Neutron Products, Inc 86795 83/01/11 123pp 18357 184

8305060073 Addl response to FOIA request for documents re efforts to make facility more earthquake resistant Documents 1 through 7 listed on app encl Documents 8 through 10 withheld (ref FOIA Exemption 5)
FELTON, J M Division of Rules and Records 83/03/14 WHARTON, R J San Diego State College 3pp 18365 023 24X Fiche 50-206, 83/03/14, 8305060073

--8203180052 Discusses facility capability to shut down safely for postulated steam line breaks regardless of whether failure seismically induced Unit to remain shut down until issues resolved
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/03/02 REMICK, F J Office of Policy Evaluations 3pp 18365 121 24X Fiche 50-206, 83/03/14, 8305060073

--8204190027 Updates status of resolution of steam line break & seismic upgrade issues for facility, identified in 820302 memo
DENTON, H R Office of Nuclear Reactor Regulation, Director 82/04/08 REMICK, F J Office of Policy Evaluations 6pp. 18365 126 24X Fiche 50-206, 83/03/14, 8305060073

8305060096 FOIA request for current salary scales &/or QG schedules as applied to NRC staff positions
WILLIAMS, D G NUTECH Engineers, Inc QGW-83-029 83/02/24
FELTON, J M Division of Rules and Records 1p 18354 277.

8305060112 Responds to FOIA request for current salary scales &/or QG schedules as applied to NRC staff positions Forwards App A documents
FELTON, J M Division of Rules and Records 83/03/14 WILLIAMS, D G NUTECH Engineers, Inc 2pp 18354 278

--8305060117 App 4130-C re current pay administration salary schedules for NRC staff positions
* NRC - No Detailed Affiliation Given 82/12/18 12pp 18354 280

8305060123 Addl response to FOIA request for three categories of documents Forwards 29 slides used at 820916 meeting between NRC, GE & BWR licensees. Remaining 33 slides withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/03/15 VAN ALLEN, S Northern Sun Alliance 1p 18359 233

8305060135 Addl response to FOIA request for info re Nuclear Metals, Inc, including incidents of employee overexposures Forwards App A documents Info partially withheld names of overexposed individuals (ref FOIA Exemption 6)
FELTON, J M Division of Rules and Records 83/03/03 MOONEY, B C Lowell Sun, Lowell, MA 3pp 18353 165

--8201070110 Confirms 811215 telcon agreement re consulting svcs for probable U overexposure incident described in encl Work involves analysis of health significance of uptake & most likely initial update of depleted U Guidance & forms encl
HAYNES, R C Region 1, Philadelphia, Office of the Director (81/03/01) 81/12/30 HURSH, J B Hursh, J B 12pp. 18353 190

--8208060242 Forwards rept on last quarter 1981 skin dose to Nuclear Metals, Inc employee
ALLARD, D J Nuclear Metals, Inc 82/03/01. KINNEMAN, J D Division of Engineering & Technical Programs 1p 18353 223

--8208060244 Rept on last quarter 1981 skin dose to Nuclear Metals, Inc employee
ALLARD, D J Nuclear Metals, Inc 82/03/01 15pp. 18353 224

--8305060141 Submits final rept re 740913 smoke & vapor emission at 5 gallon can of depleted U Analysis of container & surrounding area revealed no spread of contamination Control procedures improved Info partially deleted
GILMAN, A R Nuclear Metals, Inc 74/10/24 ALLEN, W Region 1, Philadelphia, Office of the Director 5pp 18353 169

--8305060145 Forwards 771020 complaint re alleged radiation exposure at Nuclear Metals, Inc, in response to 771031 telcon
RILEY, E J Labor, Dept of 77/11/03 MCCLINTOCK, R. Office of Inspection & Enforcement, Office of the Director 3pp 18353 174

--8305060156 Ack receipt of 780630 transmittal of final overexposure rept, per 10CFR20 405(a)
MCCLINTOCK, R. D Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/07/13 GILMAN, A R Nuclear Metals, Inc 2pp 18353 177

--8305060181 Submits rept re employee whole body overexposure to beta plus gamma radiation, per 10CFR20 405(a)(1) Film badge reevaluation & overexposure of U confirmed 780530 Reassignment of personnel & early alert procedure initiated
GILMAN, A R Nuclear Metals, Inc 78/06/30 Region 1, Philadelphia, Office of the Director 3pp 18353 180

--8305060189 Forwards JE Glenn 810106 memo re allegations of unsafe conditions & improper firing of employee by Nuclear Metals, Inc No further action planned unless written complaint filed
KINNEMAN, J D Nuclear Metals, Inc 81/01/13 SMITH, G H Region 1, Philadelphia, Office of the Director 1p 18353 187

--8305060193 Discusses allegations by former Nuclear Metals, Inc employee re unsafe conditions & improper firing. Info partially deleted
GLENN, J E Region 1, Philadelphia, Office of the Director. 81/01/06 KINNEMAN, J D Region 1, Philadelphia, Office of the Director 2pp 18353 188

--8305060200 Forwards "Analysis of Exposure Involving Depleted U at Nuclear Metals, Apr 1981," consultant rept
HURSH, J B Rochester, Univ of, 82/02/18 HAYNES, R C Region 1, Office of Director. 1p 18353 202

--8305060209 Discusses allegations made by Nuclear Metals, Inc employee re unsafe conditions involving risk of employee contamination Related info encl. Info partially deleted
ROWE, C Region 1, Office of Director 82/04/22 KINNEMAN, J. D Region 1, Office of Director 1p 18353 241

--8305060214 Notifies of results of inquiries re allegations made by Nuclear Metals, Inc employee No items of concern represented noncompliance w/NRC regulations or safety hazards
KINNEMAN, J D Region 1, Office of Director 82/04/02 FIATARONE, J V Labor, Dept of 1p. 18353 242

--8305060220 Forwards complaint from Nuclear Metals, Inc employee re unsafe conditions & health hazards at facility Related info encl Info partially deleted
FIATARONE, J V Labor, Dept of 82/02/02 KINNEMAN, J Region 1, Office of Director. 20pp 18353 243

8305060144 Responds to FOIA Requests 82-455, 82-471 & 82-479 re suppression pool dynamic loads. Encls to Documents 3 & 4 & rept encl w/Document 7 withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records 83/03/17 HAFNER, B Affiliation Unknown 2pp 18364 261.

--8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vent clearing & steam quenching phenomena Schedule coordinated w/GE & other utils
WOFFORD, A W Long Island Lighting Co SNRC-50 75/06/03.
STOLZ, J F Light Water Reactors Branch 1 4pp 18364 266

--8305060155 Requests addl info re suppression pool temp limit Responses to Questions 1,2,4 & 5 will be provided by GE Question 3 must be answered by util.
KNIEL, K Light Water Reactors Branch 2 77/08/31. WOFFORD, A W. Long Island Lighting Co 2pp 18364, 283

--8305060160 Forwards rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to NRC questions Applicable subscale test results & field data survey appropriate during low probability events
FULLER, E D General Electric Co. MFN 343-77. 77/09/06
PARR, O D. Light Water Reactors Branch 3 2pp 18364 285.

--8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to Questions 1,2,4 & 5 Submittal date for response to Question 3 will be provided
BURKE, T. J. Long Island Lighting Co 77/09/26 KNIEL, K Light Water Reactors Branch 2 1p. 18364 287

--8305060171 Forwards proprietary "Suppression Pool Temp Response to Safety/Relief Valve Discharge Through Ramshead in Mark I & II Containments," for review as part of Mark I Task 7 5 & Mark II Task 8 6 Withheld (ref 10CFR2 790)
SOBON, L J General Electric Co. MFN-138-78. 78/03/31
STOLZ, J F Light Water Reactors Branch 1. 2pp. 18364, 300

--8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads, safety relief valve vent clearing & steam quenching phenomena. Schedule coordinated w/GE & other utils.
WOFFORD, A W Long Island Lighting Co SNRC-50 75/06/03.
STOLZ, J F Light Water Reactors Branch 1 4pp 18364 266.

--8305060155 Requests addl info re suppression pool temp limit Responses to Questions 1,2,4 & 5 will be provided by GE Question 3 must be answered by util
KNIEL,K Light Water Reactors Branch 2 77/08/31 WOFFORD,A W Long Island Lighting Co 2pp 18364 283

--8305060160 Forwards rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to NRC questions Applicable subscale test results & field data survey appropriate during low probability events
FULLER,E D General Electric Co MFN 343-77 77/09/06
PARR,O D Light Water Reactors Branch 3 2pp 18364 285

--8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to Questions 1,2,4 & 5 Submittal date for response to Question 3 will be provided
BURKE,T J. Long Island Lighting Co 77/09/26 KNIEL,K Light Water Reactors Branch 2 1p 18364 287

--8305060171 Forwards proprietary "Suppression Pool Temp Response to Safety/Relief Valve Discharge Through Ramshead in Mark I & II Containments," for review as part of Mark I Task 7 5 & Mark II Task B.6.Withheld (ref 10CFR2 790)
SOBON,L J General Electric Co MFN-138-78 78/03/31
STOLZ,J F Light Water Reactors Branch 1 2pp 18364 300

--8305060153 Submits schedule & program for analyzing & resolving effects of LOCA re suppression pool hydrodynamic loads,safety relief valve vent clearing & steam quenching phenomena Schedule coordinated w/GE & other utils
WOFFORD,A W Long Island Lighting Co. SNRC-50 75/06/03
STOLZ,J.F Light Water Reactors Branch 1 4pp 18364 266

--8305060155 Requests addl info re suppression pool temp limit Responses to Questions 1,2,4 & 5 will be provided by GE Question 3 must be answered by util.
KNIEL,K Light Water Reactors Branch 2. 77/08/31 WOFFORD,A W Long Island Lighting Co 2pp 18364,283

--8305060160 Forwards rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to NRC questions.Applicable subscale test results & field data survey appropriate during low probability events
FULLER,E.D. General Electric Co MFN 343-77 77/09/06
PARR,O.D. Light Water Reactors Branch 3 2pp. 18364 285

--8305060164 Responds to 770831 ltr ref GE rept "170 F Pool Temp Limit for Safety Relief Valve Ramshead Condensation Stability," in response to Questions 1,2,4 & 5 Submittal date for response to Question 3 will be provided.
BURKE,T J. Long Island Lighting Co 77/09/26 KNIEL,K Light Water Reactors Branch 2 1p 18364,287

--8305060171 Forwards proprietary "Suppression Pool Temp Response to Safety/Relief Valve Discharge Through Ramshead in Mark I & II Containments," for review as part of Mark I Task 7 5 & Mark II Task B.6.Withheld (ref 10CFR2 790)
SOBON,L J General Electric Co MFN-138-78 78/03/31
STOLZ,J.F. Light Water Reactors Branch 1 2pp 18364 300

8305090024 Addl response to FOIA request for documents re 821130 special insp rept.Forwards App A documents Portions of Documents 1 & 2 in App B withheld (ref FOIA Exemption 6) Documents 3 & 4 withheld (ref FOIA Exemption 7)
FELTON,J M. Division of Rules and Records 83/03/21. QARDE,B Government Accountability Project. 4pp 18381 158 24X
Fiche:50-206,83/03/21,8305090024.

--8305090038 Discusses telcon w/B Kohn (Govt Accountability Project (GAP)) on 821101 re tape cassettes & transcript of interview w/EE Kent on 821015 Transcript unsatisfactory & replete w/errors.
SHACKLETON,O.C. Region 5, Office of Director 82/11/04 Region 5, Office of Director. 2pp. 18381·164

--8305090043 Discusses telcon w/unidentified male on 821104 re B Kohn 821015 request for tape cassettes of interview w/EE Kent on 821015.Original tapes sent to headquarters for reproduction
SHACKLETON,O C Region 5, Office of Director 82/11/04 Region 5, Office of Director 1p. 18381:166

--8305090047 Forwards tape cassettes of EE Kent 821015 interview,per request.W/o encl.
SHACKLETON,O.C. Region 5, Office of Director 82/11/02
FAULKENBERRY,B. Region 5, Office of Director 1p. 18381:167.

--8305090055 Requests reproductions of tape cassette of EE Kent 821015 interview,mailed to B Faulkenberry.
SHACKLETON,O.C Region 5, Office of Director. 82/11/03.
WARD,W J Director's Office, Office of Inspection and Enforcement 1p 18381,168

--8305090057 Notifies that seven tape cassettes of EE Kent 821015 interview will be sent for reproduction Tapes will be returned for use at disposition
SHACKLETON,O C Region 5, Office of Director 82/11/03
FAULKENBERRY,B Region 5, Office of Director 1p 18381 169

8305090234 FOIA request for Ohio Citizens for Responsible Energy sixth & seventh set of interrogatories,Sunflower Alliance third set of interrogatories & draft responses to five ASLB questions re hydrogen issue
HIATT,S L Ohio Citizens for Responsible Energy 83/02/14
FELTON,J M Division of Rules and Records 1p 18381 212

8305090241 Responds to FOIA request for Ohio Citizens for Responsible Energy & Sunflower Alliance interrogatories & draft responses to ASLB questions Forwards App A documents Info partially withheld (ref FOIA Exemption 5) W/o encls
FELTON,J M Division of Rules and Records 83/03/21 HIATT,S L Ohio Citizens for Responsible Energy 3pp 18381 213

8305090285 FOIA request for all documents re decision to terminate const of facility
DEVIENCE,A Devience & O'Meara, Ltd 83/02/24 Office of Administration 1p 18381 225 24X Fiche 50-566,83/02/24, 8305090285

8305090292 Responds to FOIA request for all documents re decision to terminate const of facility Forwards documents listed in App A
FELTON,J M Division of Rules and Records 83/03/21 DEVIENCE,A Devience & O'Meara, Ltd 2pp 18381 226 24X Fiche 50-566, 83/03/21,8305090292

8305090306 Addl response to FOIA request for all records prepared at Region III,all investigators involved in investigation of T Howard & S Morella allegations & all internal records re problems discovered at facility Forwards App B documents
FELTON,J.M Division of Rules and Records 83/03/22 QARDE,B Government Accountability Project 2pp 18381 216 24X
Fiche.50-373,83/03/22,8305090306

--8305090313 IE Investigation Repts 50-373/82-51 & 50-374/82-15 on 820721-1001 No noncompliance noted Major areas investigated followup on allegations re matl procurement & QA deficiencies of HVAC sys installed by Zach Co
LANKSBURY,R D., WESTCOTT,H M Region 3, Office of Director 50-374/82-15 82/08/16 4pp 18381 219 24X
Fiche 50-373,83/03/22,8305090306

8305090523 FOIA request for addl info re earlier request on Pilgrim dtd 821105 concerning similar documentation for Seabrook facilities
SHOTWELL,J A Massachusetts, Commonwealth of, 83/01/05
FELTON,J M Division of Rules and Records 2pp 18368 001 24X
Fiche 50-443,83/01/05,8305090523

8305090529 Partial response to FOIA request for addl info re 821105 request pertaining to Facility Forwards App A documents Documents also available in PDR App B documents completely withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/03/10 SHOTWELL,J A Massachusetts, Commonwealth of, 5pp 18368 003 24X
Fiche 50-443,83/03/10,8305090529

--8111030653 Forwards revised draft discussing paper re safety goals for nuclear power plants;for review NRC 810723-24 second workshop in Harpers Ferry comments & new ideas incorporated Comments requested by 811015
REMICK,F.J. Office of Policy Evaluations 81/10/01
PALLADINO,N.J Commissioners. 1p 18368 213

--8111030655 Revised draft discussion paper re safety goals for nuclear power plants,incorporating 810723-24 second workshop in Harpers Ferry comments & other new ideas
* Office of Policy Evaluations 81/10/01 78pp 18368 214

--8203150093 Forwards branch review comments of facility emergency plan, performed against NUREG-0654 criteria Addl info & commitments required prior to acceptance
PAGANO,F.G. EP Licensing Branch 82/03/03 MIRAGLIA,F J. Licensing Branch 3 20pp 18368 014 24X Fiche 50-443,83/03/10, 8305090529.

--8208190078 Requests findings on prompt protective action decisionmaking in States of VT,NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 encl
GRIMES,B.K Division of Emergency Preparedness (Pre 830103), 82/04/27 KRIMM,R M Federal Emergency Management Agency 6pp 18368 034 24X Fiche 50-443,83/03/10,8305090529

--8305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station "
* HMM Associates, Inc 83/03/10 56pp 18368 155 24X
Fiche 50-443, 83/03/10, 8305090529

--8111030653 Forwards revised draft discussing paper re safety goals for nuclear power plants, for review NRC 810723-24 second workshop in Harpers Ferry comments & new ideas incorporated
Comments requested by 811015
REMICK, F J Office of Policy Evaluations 81/10/01
PALLADINO, N J Commissioners 1p 18368 213

--8111030655 Revised draft discussion paper re safety goals for nuclear power plants, incorporating 810723-24 second workshop in Harpers Ferry comments & other new ideas
* Office of Policy Evaluations 81/10/01 78pp 18368 214

--8208190078 Requests findings on prompt protective action decisionmaking in States of VT, NH & MA Significant problem may exist w/offsite preparedness in listed states "Site & Environ Interface," Chapter 2 encl
GRIMES, B K Division of Emergency Preparedness (Pre 830103)
82/04/27 KRIMM, R M Federal Emergency Management Agency 6pp
18368 034 24X Fiche 50-443, 83/03/10, 8305090529

--8305090614 "Estimates of Evacuation Time for Seabrook Nuclear Power Station "
* HMM Associates, Inc 83/03/10 56pp 18368 155 24X
Fiche 50-443, 83/03/10, 8305090529

8305090537 FOIA request for transcript of Commission meetings discussing 821112 order CLI-82-33 & documents supporting NRC recommendation to Commission re issuance of order.
SAMP, R A Shaw, Pittman, Potts & Trowbridge 83/02/09
GRIMSLEY, D H Division of Rules and Records 2pp 18365 134. 24X
Fiche. 50-358, 83/02/09, 8305090537

8305090542 Partial response to FOIA request for transcript of Commission meetings discussing 821112 order & documents supporting NRC recommendations to Commission re issuance of order Forwards App B documents App A documents in PDR
FELTON, J M Division of Rules and Records 83/03/17 SAMP, R A Shaw, Pittman, Potts & Trowbridge. 4pp 18365: 136 24X
Fiche 50-358, 83/03/17, 8305090542

--8305090545 Submits interim rept of Natl Board Notification ASME Code related const at facility, per State of OH, Div of Boiler Insp
MCDONALD, D O Ohio, State of 82/05/12 MILAN, D M Ohio, State of 76pp 18365 140 24X Fiche 50-358, 83/03/17, 8305090542.

--8305090549 Testimony of JO Keppler before US House of Representatives, Committee on Interior & Insular Affairs, Subcommittee on Energy & Environ on 820610 re GA problems & related activites at facility Pp 1-12.
KEPPLER, J O NRC - No Detailed Affiliation Given 82/06/10
12pp 18365 214 24X Fiche 50-358, 83/03/17, 8305090542

--8305090561 Submits Natl Board Audit Interim Rept 3 re ASME Code related const at facility, per State of OH Div of Boiler Insp Rept covers activities from 820807-0930
MCDONALD, D J , ALLISON, C W , SULLIVAN, M F. Ohio, State of
82/09/30 MILAN, D M Ohio, State of 18pp 18365 361 24X
Fiche 50-358, 83/03/17, 8305090542

8305120005 FOIA request for Sandia Lab electromagnetic pulse study
MARSHALL, W H Mapleton Intervenors 83/02/27. PALLADINO, N. J. Commissioners 1p 18435 361

8305120007 Responds to FOIA request for Sandia Lab electromagnetic pulse study NUREG/CR-3069, "Interaction of Electromagnetic Pulse W/Commerical Power Reactor Sys," sent to S Galder, per 830325 telcon.
FELTON, J M Division of Rules and Records 83/03/31. MARSHALL, W H Mapleton Intervenors. 1p 18435 360

8305120010 Addl response to FOIA request for documents re exploration, mining or milling of U in specific areas of NE Forwards documents listed on app Review of remaining documents subj to request in progress.
FELTON, J M Division of Rules and Records 83/03/21. REID, A B Broken Plow Law Office 1p 18443 282

--8305120014 Comments on Proposed Draft LB 550, per 811210 request. Use of word "mining" may cause some problems NRC does not have jurisdiction over conventional mining of source matl or other matl
MONTGOMERY, J L Region 4, Dallas, Office of the Director (81/03/01). 82/01/19 DRAIN, D T Nebraska, State of 2pp
18443 284.

--8305120019 Discusses 820202 telcon w/J Lange re proposed U in situ project in NE by Wyoming Fuels Co State has licensing & insp jurisdiction over project until 821108
MONTGOMERY, J L Region 4, Office of Director 82/02/08
COLLINS, J T Region 4, Office of Director 2pp 18443·286

--8305120023 Forwards info re 810313 meeting w/NE State officials concerning state & UMTRCA topics State will seek amended agreement after 811108 Agency other than E Simmons div assigned to handle U mills
MONTGOMERY, J Region 4, Dallas, Office of the Director (81/03/01)
81/03/18 YOUNG, F Office of State Programs, Director 4pp.
18443 288

--8305120035 Concurs w/D Drain request for assistance in developing MOU to define respective roles in connection w/U or solution mining in northwest NE June 1982 meeting suggested to begin formulating MOU
COLLINS, J T Region 4, Office of Director 82/05/03 DAVIS, J. G. Office of Nuclear Material Safety & Safeguards, Director KERR, G. W. Office of State Programs, Director 1p 18443 292

--8305120041 Requests assistance in arranging meeting in Lincoln, NE to discuss requirements & develop MOU defining roles re U or solution mining in northwest NE
DRAIN, D T Nebraska, State of 82/04/27 COLLINS, T Region 4, Office of Director 2pp 18443 293

--8305120045 Informs that draft MOU ready for signature pending review & concurrence by OELD Due to changes in location & organization of U Recovery Licensing Branch, MOU should be signed by regional administrator
COLLINS, J T Region 4, Office of Director 82/07/28 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p.
18443 295

--8305120052 Forwards draft MOU re site U mining in NE Draft considers all previous NRC ofc comments & is acceptable to State of NE Comments should be provided by 821015
COLLINS, J T Region 4, Office of Director. 82/10/01. DIRCKS, W J. Office of the Executive Director for Operations. STELLO, V Regional Operations & Generic Requirements KERR, G W Office of State Programs, Director 3pp 18443 296

--8305120056 Forwards notice of issuance & availability of MOU between NE Dept of Environ Control & NRC for in situ U mining for filing & publication in FR
COLLINS, J T Region 4, Office of Director. 82/12/01. COMBS, T. R Correspondence & Records Branch 1p 18443 299

--8305120062 Notice of issuance & availability of MOU between NRC & NE Dept of Environ Control re in situ U mining
COLLINS, J T. Region 4, Office of Director 82/11/30 1p.
18443 300

--8305120065 MOU between NRC & NE Dept of Environ Control re in situ U mining
COLLINS, J T. Region 4, Office of Director DRAIN, D T Nebraska, State of. 82/11/02 2pp. 18443 301.

8305120070 Addl response to FOIA request for IE Insp Rept 50-358/81-13 Portions of documents listed on app withheld (ref FOIA Exemption 4)
FELTON, J M Division of Rules and Records. 83/03/21 DEVINE, T., ROSENTHAL Government Accountability Project 3pp 18443 193 24X
Fiche 50-358, 83/03/21, 8305120070

--8305120074 Forwards Electrical Drafting Std EDBB-126 revised on 791005, Pages 2-43 through 2-48 of Electrical Installation Spec H-2173 & Pages B 3-29, B 3-30 & B 3-65 of FSAR, per request re tray loading criteria, Related info encl
COTTA, R E Sargent & Lundy, Inc 81/02/18. BARRETT, P. Region 3, Chicago, Office of the Director 36pp 18443·196 24X
Fiche 50-358, 83/03/21, 8305120070

8305120095 Responds to FOIA request by WH Marshall that S Galder receive "Interaction of Electromagnetic Pulse W/Commercial Power Reactor Sys " Documents forwarded.
FELTON, J M Division of Rules and Records 83/03/31 GADLER, S. Affiliation Unknown 1p. 18435 358.

8305120224 Addl response to FOIA request for license applications, license & insp repts re Nuclear Metals, Inc & correspondence on employee overexposures to 1980 Forwards documents listed in App A Info partially withheld (ref FOIA Exemption 6)
FELTON, J. M Division of Rules and Records 83/03/01. MOONEY, B. C. Lowell Sun, Lowell, MA. 9pp 18460·050.

--8112160259 Forwards urinalysis history form for review by Occupational Health Stds Branch Info requested as result of recent insp at Nuclear Metal in Concord, MA where employees urine showed concentration of U in excess of license guide
KINNEMAN, J D. Materials Radiological Protection Section
81/12/07 ORELLA, A W Fuel Cycle & Materials Safety Section
4pp 18462 186

--8112290557 Ack agreement w/proposed enforcement action per 811016 memo, since revised, based on NRC consultant conclusion that evaluation of U uptake could not establish that regulatory limit was exceeded
THOMPSON, D Enforcement & Investigation Staff (Pre 820201)
EA-82-009 81/12/01 KEPPLER, J Region 3, Chicago, Office of the Director (81/03/01) 2pp 18462 107

--8305120234 Insp Findings & Licensee Ack dtd 620424 of License SMB-179 Insp findings no noncompliance noted
KLEVIN, P B Atomic Energy Commission 62/04/24 2pp 18460 060

--8305120240 Insp Findings & Licensee Ack dtd 651207 & 08 of License SMB-179 Insp findings, no noncompliance noted
* Atomic Energy Commission 65/12/08 1p 18460 062

--8305120246 Notifies that Nuclear Metals Div of Textron, Inc acquired by Whittaker Corp Approval for transfer of licenses requested
THOMPSON, P. Nuclear Metals, Inc 66/08/11 Atomic Energy Commission 1p 18460 063

--8305120251 IE Insp Findings & Licensee Ack dtd 671227 & 28 of License SMB-179. Insp findings no noncompliance noted
ORELLA, A W , BROWNE, W Q Atomic Energy Commission 67/12/28 1p 18460 064

--8305120257 Forwards IE Insp Findings & Licensee Ack dtd 671227 & 28 No noncompliance noted W/o encl
KIRKMAN, R. W Atomic Energy Commission CO I AWQ. 68/01/03
ABREAU, M. A. Whittaker Corp 1p 18460.065

--8305120260 IE Insp Findings & Licensee Ack dtd 691202-03 of License SMB-179. Insp findings no noncompliance noted.
SMITH, R H. Atomic Energy Commission 69/12/03 1p 18460 066

--8305120264 Advises that response to 690822 application for License SMB-179 has not been received Info re issuance of license requested
LEE, M R Whittaker Corp 69/10/22 NUSSBAUMER, D A Atomic Energy Commission 1p 18460·067

--8305120268 Submits list of replacement pages to application for License SNM-65, in response to 690923 comments
ISSEROW, S. Whittaker Corp 69/10/22 NUSSBAUMER, D A Atomic Energy Commission. 2pp. 18460.068.

--8305120269 Forwards application for renewal of License SNM-65. Application refiled in loose leaf format incorporating 17 items from 680806 ltr W/o encl
KNEPPEL, D B Whittaker Corp 69/02/26 NUSSBAUMER, D A Atomic Energy Commission. 1p 18460 070

--8305120274 IE Insp Findings & Licensee Ack dtd 690903 & 04 of Licenses SNM-65 & SMB-179 Insp findings, proper evaluations not made of certain aspects of health physics program per Sections II b 4 through II b 6(b) of License Condition 8
BROWNE, W Q. Atomic Energy Commission 69/09/18 1p 18460 071

--8305120279 Application for renewal of License SMB-179, authorizing possession & use of U-235 solid metal & alloy for fabrication & experimentation
GUMMESON, P. U Whittaker Corp 2696 69/08/22 3pp 18460 072

--8305120283 Notifies that License SMB-179 expires on 690930 Renewal application should be filed within 30 days Encl certification of status of source matl activities form should be completed for nonrenewal of license
NUSSBAUMER, D A. Atomic Energy Commission 69/07/25. HANNA, W. J. Whittaker Corp. 1p. 18460·075.

--8305120284 IE Insp Findings & Licensee Ack dtd 700715 & 16 of Licenses SNM-65 & SMB-179. Insp findings, no noncompliance noted.
SMITH, R H Atomic Energy Commission. 70/07/16. 1p. 18460·076

--8305120289 Notifies that no items of noncompliance observed during insp of Licenses SNM-65 & SMB-179 Corrective measures implemented re item of noncompliance during 690903 & 04 insp S Isserow replaced DB Kneppel as criticality officer
SMITH, R H. Atomic Energy Commission 70/01/06 Atomic Energy Commission. 1p 18460·077.

--8305120294 IE Insp Findings & Licensee Ack dtd 710513 & 14 of Licenses SNM-65 & SMB-179 Insp findings no noncompliance noted Related info encl
SMITH, R H Atomic Energy Commission 71/05/14 22pp 18460 078

--8305120298 Discusses 740913 smoke & paper emission from 5-gallon pail of U Fire dept removed pail Smoke & vapor emission ceased No personnel contamination resulted or radiation released Caused by reaction between metal & oil
GILMAN, A R Nuclear Metals, Inc 74/09/13 Region 1, Philadelphia, Office of the Director 3pp 18460 125

--8305120303 Discusses insp of License SMB-179 radiation control program License classification should be changed from E-3 to B-1 Next insp scheduled during Nov 1974
JERMAN, P C Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22 Atomic Energy Commission, Directorate of Regulatory Operations. 1p 18460 128

--8305120307 Forwards Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance noted
NELSON, P R Atomic Energy Commission, Directorate of Regulatory Operations 74/08/22. TUFFIN, W B Nuclear Metals, Inc 2pp 18460 129

--8305120310 Insp Rept 40-0672/74-01 on 740530 & 31 No noncompliance noted Major areas inspected radiation control program
JERMAN, P C , KNAPP P J Region 1, Philadelphia, Office of the Director. 74/08/20 9pp 18460 131

--8305120316 Ack receipt of 740327 & 0416 ltrs informing of steps taken to correct violations noted in 740215 ltr
O'REILLY, J P Region 1, Philadelphia, Office of the Director 74/04/26 TUFFIN, W B Nuclear Metals, Inc 1p 18460 140

--8305120352 Suppls 740327 ltr re use of gloves for hand protection, monitoring of hand & glove exam & use of breathing zone air sampler, in response to 740404 telcon Related info encl
TUFFIN, W B Nuclear Metals, Inc 74/04/16 O'REILLY, J P Region 1, Philadelphia, Office of the Director 5pp 18460 141

--8305120356 Forwards Insp Repts 40-0672/73-02 & 70-0082/73-05 on 731227-28 & 740108-09 & notice of violation W/o insp repts
O'REILLY, J P Region 1, Philadelphia, Office of the Director 74/02/13 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 146

--8305120359 Notice of violation from insp of 731227-28 & 740108-09 Noncompliances noted failure to conduct adequate evaluations of hand exposures, to survey for airborne U-238 & to analyze environ water & soil samples
* Region 1, Philadelphia, Office of the Director 74/02/15 3pp. 18460 148.

--8305120369 Responds to NRC 740215 ltr re violations noted in insp Repts 70-0082/73-05 & 40-0672/73-02. Corrective actions finger dosimeters placed on individual employees monthly on rotating basis U handling employees surveyed
TUFFIN, W Nuclear Metals, Inc 74/03/27 O'REILLY, J P Region 1, Philadelphia, Office of the Director 11pp 18460·153

--8305120372 Insp Repts 40-0672/73-02 & 70-0082/73-05 on 721227-28 & 740108-09. Noncompliance noted failure to evaluate dose to hands of individuals handling U-238 & wearing gloves contaminated w/U-238 & daughter products
JERMAN, P C , KNAPP, P J Region 1, Philadelphia, Office of the Director. 70-0082/73-05 74/02/01 20pp 18460 164

--8305120376 Confirms 740104 & 07 telcons re actions taken to correct violations noted in insp on 731227 & 28 Representatives will visit plant on 740107 to evaluate corrective actions
O'REILLY, J P Region 1, Philadelphia, Office of the Director 74/01/07 TUFFIN, W B Nuclear Metals, Inc 3pp 18460 184

--8305120381 Responds to IE Bulletin 75-07 re emission of corrosive gases into ventilation sys filtered by HEPA filters No HEPA or other cellulosic filters used in ventilation sys exhausting nitrogen oxides. Plastic overwrap used in disposal.
GILMAN, A R Nuclear Metals, Inc IEB-75-07 75/12/22 Region 1, Philadelphia, Office of the Director 1p 18460 187

--8305120450 Forwards Insp Rept 40-0672/75-01 on 750529 & 30 No noncompliance noted. Major areas inspected selective exam of procedures & representative records, interviews w/personnel, measurements made by inspector & observations W/o encl
NELSON, P. R Region 1, Philadelphia, Office of the Director 75/06/25 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 191

--8305120454 "Nuclear Reactor Fuel Svcs Semiannual Insp II Plan & Field Notes."
EPSTEIN, E. , MCCLINTOCK, R Office of Inspection & Enforcement, Office of the Director 75/06/23 16pp 18460·195

--8305120462 IE Insp Rept 40-0672/75-01 on 750529-30. No noncompliance noted Major areas inspected mgt interview re scope of program & operations, external & internal exposures, stack air monitoring, liquid waste & controls
EPSTEIN, E , MCCLINTOCK, R D Region 1, Philadelphia, Office of the Director 75/06/23 4pp 18460 211

--8305120466 IE Insp Findings & Licensee Ack dtd 760610 of License SMB-179 Insp findings no noncompliance noted Radiation data sheet encl
EPSTEIN, E Region 1, Philadelphia, Office of the Director 76/06/10 9pp 18460 217

--8305120472 Forwards results of analyses of samples taken at Nuclear Metals, in response to 771118 ltr & 771208 telcon W/o stated guidelines for decontamination of facilities
MCCLINTOCK, R D Office of Inspection & Enforcement, Office of the Director 77/12/27 CROWTHER, T Labor, Dept of, Occupational Safety & Health Admin 2pp 18460 236

--8305120474 Forwards samples of lathe turning of depleted U collected on 771116 in machine shop at Nuclear Metals per T Crowther telcon
FIATARONE, J V Labor, Dept of, Occupational Safety & Health Admin 77/11/18 MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 12pp 18460 239

--8305120478 Ack receipt of 770510 ltr re violations noted in IE Insp Rept 40-0672/77-01 Records of evaluations denoting true exposure of individual exposed to contamination should be maintained for review during next insp
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/05/31 TUFFIN, W B Nuclear Metals, Inc 1p 18460 251

--8305120480 Responds to NRC 770418 ltr re violations noted in IE Insp Rept 40-0672/77-01 Corrective actions employee will present badge to guard at exit Badge sealed within cleanable mylar envelope
TUFFIN, W B Nuclear Metals, Inc 77/05/10 NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 3pp 18460 252

--8305120483 Discusses IE Insp Rept 40-0672/77-01 on 770329 & forwards notice of violation
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/04/18 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 255

--8305120489 Notice of violation from insp on 770329 Noncompliance noted failure to perform surveys to assure compliance w/ 10CFR20 101 & 10CFR20 403 re radiation exposure to personnel monitoring (film) badge for Third Quarter 1976
* Region 1, Philadelphia, Office of the Director 77/04/18 1p 18460 257

--8305120493 Ack receipt of 780919 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-02
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/09/27 TUFFIN, W B Nuclear Metals, Inc 1p 18460.258

--8305120494 Responds to NRC 780821 ltr re violations noted in IE Insp Rept 40-0672/78-02 Corrective actions radiation levels along outside rear wall of Outler Bldg 1 reduced to 1 m/h Fencing placed between ends of bldgs
TUFFIN, W B Nuclear Metals, Inc 78/09/19 Region 1, Philadelphia, Office of the Director 1p 18460 259

--8305120500 Forwards notice of violation from insp on 780727-28 Results of smear samples within license guidelines
CROCKER, H W Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/08/21 TUFFIN, W B Nuclear Metals, Inc 3pp 18460 260

--8305120503 Notice of violation from insp on 780727-28 Two individuals working in restricted area received exposures to skin of 8.54 & 8 19 rems, respectively, during First Quarter CY78 *Draft Insp Rept 78-02 encl*
* Region 1, Philadelphia, Office of the Director 78/08/21 2pp

8 Noncompliance noted
rems during
, exceeded

lia, Office of the

--8305120509 Ack receipt of 780418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/78-01 Request to amend license must accompany changes to procedures noted in 780418 ltr
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/05/11 TUFFIN, W B Nuclear Metals, Inc 2pp 18460 275

--8305120511 Responds to NRC 780324 ltr re violations noted in IE insp on 780228-0301 Corrective actions personnel instructed to collect floor sweeping in containers color coded to identify scrap containing licensed matl
TUFFIN, W B Nuclear Metals, Inc 78/04/18 Region 1, Philadelphia, Office of the Director 2pp 18460 277

--8305120514 Forwards notice of violation from insp on 780228 & 0301 Methods for detecting radioactive contamination should be reviewed Comments on smoking in restricted area requested
NELSON, P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/03/24 TUFFIN, W B Nuclear Metals, Inc 3pp 18460 279

--8305120515 Notice of violation from insp on 780228 & 0301 Noncompliance noted failure to perform surveys re disposal of licensed matl in waste & radiation exposure to extremities
* Region 1, Philadelphia, Office of the Director 78/03/24 1p 18460 282

--8305120518 IE Insp Rept 40-0672/78-01 on 780228 & 0301 Noncompliance noted failure to evaluate exposure to extremity & to wear ring dosimeter in restricted area Radwaste found in trash dumpster
GLENN, J , MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 78/03/13 8pp 18460 283

--8305120519 Forwards proposed ack ltr to Nuclear Metals 801003 response to notice of violation & 800929 notice of proposed imposition of civil penalty
ORIER, B H Region 1, Philadelphia, Office of the Director, 80/11/19 THOMPSON, D Executive Officer for Operations Support, 2pp 18461 026

--8305120523 Forwards draft enforcement action ltr & notice of violation & proposed imposition of civil penalty re failure to meet NRC & DOT requirements for shipment of radwaste to Barnwell burial site
ORIER, B H Region 1, Philadelphia, Office of the Director 80/08/26 THOMPSON, D Executive Officer for Operations Support 5pp 18461 107

--8305120527 Amend 2 to License SMB-179, revising Items 6 & 7 re source matl & max possession & use, per 751003 telegram
DRAGONETTE, K S Division of Fuel Cycle & Material Safety 75/10/08 1p 18461:185.

--8305120530 Confirms discussions re possible overexposure of employee to airborne concentration of depleted U JB Hursh & KW Strable engaged as consultants for NRC Assistance requested
KINNEMAN, J D Region 1, Philadelphia, Office of the Director 81/01/15 TUFFIN, W B Nuclear Metals, Inc 3pp 18461 199.

--8305120540 Discusses IE Insp Rept 40-0672/80-04 on 801120 Proposed transmittal ltr & notice of violation & proposed imposition of civil penalties encl
ORIER, B H Region 1, Philadelphia, Office of the Director 81/02/03 THOMPSON, D Office of Inspection & Enforcement, Office of the Director, 10pp 18461 202

--8305120602 Discusses IE insp on 801120 & forwards notice of violation & *proposed imposition of civil penalty*
STELLO, V Director's Office, Office of Inspection and Enforcement, EA-81-23 81/02/24 TUFFIN, W B Nuclear Metals, Inc 2pp. 18461 229

--8305120609 Notice of violation & proposed imposition of civil penalty in amount of $5,000 Noncompliance noted low specific activity radioactive matl found leaking from Drum 58
STELLO, V. Director's Office, Office of Inspection and Enforcement, 81/02/26 2pp 18461 231

--8305120614 Forwards info from State of WA Dept of Social & Health Svcs re transportation discrepancy by licensee Followup action requested.
ORELLA, A W Office of Inspection & Enforcement, Office of the Director 81/03/31 KNAPP, P Region 1, Philadelphia, Office of the Director 2pp 18461.233.

--8305120617 Responds to 810226 ltr re violations noted in IE insp rept Corrective actions staging area completely encl by chain link fencing to clearly delineate region from rest of complex Payment of civil penalty encl
TUFFIN, W B Nuclear Metals, Inc EA-81-23 81/03/16 STELLO, V Director's Office, Office of Inspection and Enforcement 21pp 18461 237

--8305120620 Ack receipt of 810316 ltr & payment of civil penalty proposed in 810226 ltr
THOMPSON, D Director's Office (Pre 820201) 81/03/27
TUFFIN, W B Nuclear Metals, Inc 1p 18461 258

--8305120623 Discusses licensee 810312 fire Approx 10 lb U chips in drum in waste handling area ignited by spontaneous combustion Fire spread to flammable matl Wipes in area revealed gross beta contamination.
COSTELLO, F, M NRC - No Detailed Affiliation Given 81/04/03
KINNEMAN, J, D NRC - No Detailed Affiliation Given 2pp.
18461 259

--8305120627 Discusses 810312 fire caused by auto-ignition of 10 lb of encapsulated U turnings.
GILMAN, A R. Nuclear Metals, Inc 81/04/10. COSTELLO, F Region 1, Philadelphia, Office of the Director (81/03/01) 3pp
18461 261

--8305120630 Forwards IE Insp Rept 40-0672/81-01 on 810219 No noncompliance noted Major areas inspected selective exams of procedures & representative records; interviews w/personnel; measurements & observations by inspector W/o encl
KINNEMAN, J, D Region 1, Philadelphia, Office of the Director (81/03/01). 81/04/16. TUFFIN, W. B Nuclear Metals, Inc 2pp.
18461 264

--8305120633 Responds to 810724 application to amend source matl License Addl infd re incineration of U chips & turnings requested
WANG, J C. Division of Fuel Cycle & Material Safety 19716
81/09/29. GILMAN, A R Nuclear Metals, Inc. 1p 18461 297

--8305120642 Requests addl info re 810527 application to amend License SMB-179, proposing dilution factor of 143 be applied to air effluent releases from ventilation stacks per 10CFR20 106(d)
WANG, J C Division of Fuel Cycle & Material Safety 81/11/12.
GILMAN, A R Nuclear Metals, Inc 2pp 18461 326

--8305120656 Forwards Enforcement Guidance Memorandum 81-31 re proposed enforcement action for facility
CARLSON, R T Enforcement & Investigation Staff EGM-81-31
81/12/15 STARDSTECKI, R Division of Resident & Project Inspection MARTIN, T T Division of Engineering & Technical Inspection SMITH, G H Division of Emergency Preparedness & Operational Suppport 1p. 18462 106

--8305130006 Ack receipt of application for renewal of License SMB-179 License will not expire until final action taken by NRC
HICKEY, J W Division of Fuel Cycle & Material Safety. 20002
81/12/28 GILMAN, A R Nuclear Metals, Inc. 1p 18462 109

--8305130011 Confirms 820216 conversation w/G Rows re possible quarterly skin overexposure to employee Detailed rept forthcoming Info deleted.
VUMBACO, F J Nuclear Metals, Inc 82/02/16 KINNEMAN, J D
Region 1, Office of Director 1p 18462:110

--8305130016 Confirms telcon re application for renewal of License SMB-179 Site visit scheduled for 820304
HICKEY, J W Division of Fuel Cycle & Material Safety. 20002
82/02/18 GILMAN, A.R Nuclear Metals, Inc 1p 18462:111.

--8305130031 Discusses 820126 telcon re small crack in dike during discharge of U neutralized acid waste to lagoon Possibly caused by freeze-thaw cycle. Dike reinforced
KINNEMAN, J D Region 1, Office of Director 82/03/24 Region 1, Office of Director. 1p 18462:130.

--8305130037 Comments on application for renewal of License SMB-179 Application should provide more specific procedures for frisking personnel & clothing at exits from controlled area
KINNEMAN, J D Region 1, Office of Director. 82/04/01
MILLER, V L Office of Nuclear Material Safety & Safeguards, Director. 2pp 18462:131

--8305130042 Forwards Rev 2 to "NMI Scrap Packaging Procedures," for disposal of depleted U wastes, in support of Dec 1981 license renewal submittal.
VUMBACO, F. J Nuclear Metals, Inc. 82/03/10. HICKEY, J. Division of Fuel Cycle & Material Safety 1p. 18462:134

--8305130053 Forwards 820513 request for addl info re licensee application for renewal application
HICKEY, J W Division of Fuel Cycle & Material Safety 82/05/13
KINNEMAN, J D Region 1, Office of Director 2pp 18462 174

--8305130062 Ack receipt of 811116 application for renewal of License SMB-179 Addl info re temporary job sites at which source matls will be possessed or used; radiation survey program & waste disposal requested W/o stated encl
WANG, J C Division of Fuel Cycle & Material Safety 82/05/13
GILMAN, A R Nuclear Metals, Inc 4pp 18462 176

8305120488 Addl response to FOIA request for six categories of documents Forwards App A documents
FELTON, J M Division of Rules and Records 83/03/25 HIATT, S L Ohio Citizens for Responsible Energy 2pp 18457 211 24X Fiche 50-271, 83/03/25, 8305120488

--8207300178 Details of IE Investigation Rept 50-271/82-12 on 820606-10 No noncompliance noted Major areas investigated licensee actions in withholding info re 820424 loss of feedwater transient Proprietary details deleted (ref 10CFR2 790)
* Region 1, Office of Director 82/07/20 38pp 18457 217 24X Fiche 50-271, 83/03/25, 8305120488

--8305130223 Forwards chronology of Region I actions re 820424 loss of feedwater event, insp investigation, documentations, meetings w/state & licensee officials, evaluations of appropriate enforcement action & processing civil penalty
HOLODY, D J Region 1, Office of Director 82/10/13 AXELRAD, J Director's Office, Office of Inspection and Enforcement 3pp 18457 262 24X Fiche 50-271, 83/03/25, 8305120488

8305120573 FOIA request for list of all export licenses for Cf-252 since beginning of 1980, including to whom license issued, quantity for which license issued & ultimate consignee
KRONZEK, A L FOI Services 83/03/02 FELTON, J M Division of Rules and Records 1p 18440 203

8305120576 Responds to FOIA request for list of all export licenses for Cf-252 since beginning of 1980, including to whom license issued, quantity for which license issued & ultimate consignee Forwards requested info
FELTON, J M Division of Rules and Records 83/03/24 KRONZEK, A L FOI Services 7pp 18440 204

8305160192 FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility
CLARK, R San Francisco Examiner 83/02/22 FELTON, J M Division of Rules and Records 1p 18462 190 24X Fiche 50-312, 83/02/22, 8305160192

8305160195 Addl response to FOIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress
FELTON, J M Division of Rules and Records 83/03/31 CLARK, R A San Francisco Examiner 2pp 18462 191 24X Fiche 50-312, 83/03/31, 8305160195

--8211030191 Provides results of reactor operator & senior reactor operator exams administered Jul 1981-Sept 1982, as input to SALP rept All operators passed exams
BECKHAM, D H Operator Licensing Branch 82/10/19 MINER, S Sacramento Municipal Utility District 13pp 18462 211 24X Fiche 50-312, 83/03/31, 8305160195

--8211180501 Forwards NRR input for util SALP, per 821014 memo
MINER, S Operating Reactors Branch 4 82/11/16 STERNBERG, D M Region 5, Office of Director 7pp 18462 226 24X Fiche 50-312, 83/03/31, 8305160195

--8305160200 Notifies that SALP board scheduled to meet 821123 Evaluation period remains Jul 1981 - Sept 1982
ENGELKEN, R H Region 5, Office of Director 82/10/04
DENTON, H R Office of Nuclear Reactor Regulation, Director
DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director MICHELSON, C Director's Office 1p
18462 193 24X Fiche 50-312, 83/03/31, 8305160195

--8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility
GIBSON, J Standardization & Special Projects Branch 82/10/18
MINER, S Operating Reactors Branch 4 2pp 18462 194. 24X Fiche 50-312, 83/03/31, 8305160195

--8305160213 Forwards draft NRR SALP input re licensing activities for Jul 1981 - Sept 1982 Comments received by 821115 will be considered in final rept
MINER, S Operating Reactors Branch 4 82/11/10 EISENHUT, D G Division of Licensing MATTSON, R Division of Systems Integration (post 811005) VOLLMER, R Division of Engineering 15pp
18462 196 24X Fiche 50-312, 83/03/31, 8305160195

--8305160218 Forwards SALP for Jul 1981 - Sept 1982 Overall performance of licensed activities acceptable Prof & responsive attitude in dealings w/NRC & in day-to-day conduct of safety-related activities noteworthy
STERNBERG,D M Region 5, Office of Director 82/12/15
ENGELKEN,R H Region 5, Office of Director 2pp 18462 233 24X Fiche 50-312,83/03/31,8305160195

--8305160222 Forwards SALP evaluation input,per Sternberg 821014 memo Info consists of safeguards licensing portion
MCCORKLE,G W Power Reactor Safeguards Licensing Branch 82/11/04 NORDERHAUG,L Region 5, Office of Director 3pp 18462 235 24X Fiche 50-312,83/03/31,8305160195

8305160255 Partial response to FOIA request for all documents dtd 820101 or after detailing or referring to SALP for facility
FELTON,J M Division of Rules and Records 83/03/24 CLARK,R San Francisco Examiner 2pp 18472 241 24X Fiche 50-312,83/03/24, 8305160255

--8211100028 Provides engineering evaluation of 810807 turbine/reactor trip Event review agrees w/licensee Event had little effect on plant safety Automatic functions occurred substantially as expected given concurrent operator actions
PELLET,J L Reactor Operations Analysis Branch AEOD/E247 82/10/26 SEYFRIT,K V. Reactor Operations Analysis Branch 4pp 18472 290 24X Fiche 50-312,83/03/24,8305160255

--8211110645 Discusses licensee reporting of 810807 turbine/reactor trip Proposed LER rule would require more detailed & complete event rept W/o encl
ORNSTEIN,H L Reactor Operations Analysis Branch AEOD/E249 82/11/04 SEYFRIT,K V. Reactor Operations Analysis Branch 3pp 18473 006 24X Fiche:50-312,83/03/24,8305160255

--8211150068 Discusses performance evaluation of SALP for facility LERs contained adequate info enabling knowledgeable readers to understand events;however,LER 81-39 failed to adequately inform reader of event.
SEYFRIT,K V Reactor Operations Analysis Branch 82/11/05
STERNBERG,D M Division of Resident,Reactor Project & Engineering Programs 1p 18473 005 24X Fiche 50-312,83/03/24,8305160255

--8305160271 Notification of 830105 meeting w/util in Sacramento,CA to discuss SALP for Jul 1981 - Sept 1982 Meeting agenda encl
* Region 5, Office of Director. 82/12/02 Region 5, Office of Director 3pp 18473 018 24X Fiche 50-312,83/03/24,8305160255

8305180001 Addl response to FOIA request for seven categories of documents re Brown & Root,Inc & South Texas project Forwards App B documents Documents also available in PDR Addl documents undergoing review
FELTON,J M Division of Rules and Records 83/03/09 LINDEMAN,H N Lowenstein, Newman, Reis, Axelrad & Toll 6pp 18497 219 24X Fiche 50-000,83/03/09,8305180001

--7908080036 Forwards matl re allegations of harassment & intimidation per 790524 request
THOMPSON,D Executive Officer for Operations Support 79/06/12
FORTUNA,R A Office of Inspector & Auditor 8pp 18499 196 24X Fiche 50-000,83/03/09,8305180001

--7909180214 Requests views re adequacy of QA/QC program in light of PNO-79-179, "Voids in Reactor Containment Wall "
KENNEDY,R T Commissioners 79/06/25 GOSSICK,L.V Office of the Executive Director for Operations 1p 18497 233 24X Fiche 50-000,83/03/09,8305180001

--8005140296 Responds to 800418 memo re concrete voiding Discusses status of problems & repairs
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/25 BRADFORD,P A Commissioners 3pp. 18499 139 24X Fiche 50-000,83/03/09,8305180001

--8005280930 Forwards draft Investigation Repts 50-498/79-19 & 50-499/79-19 Final review is awaiting concurrence by members of team located around country Review is expected to be complete by 800415 briefing
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/11 AHEARNE,J , GILINSKY,V , KENNEDY,R Commissioners 175pp 18498 304. 24X Fiche.50-000,83/03/09, 8305180001

--8006090238 Responds to 800421 request that IE interview former site QC inspectors Of 69 persons identified,23 contacted.
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/13 BRADFORD,P.A Commissioners 3pp. 18499 149. 24X Fiche:50-000,83/03/09,8305180001

--8006090440 Responds to 791010 memo re enforcement action against Brown & Root Enforcement package complete No enforcement action taken previously since earlier insps did not substantiate allegations
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/05/15 BRADFORD,P A Commissioners 2pp 18499 155 24X Fiche 50-000,83/03/09,8305180001

--8006090443 Forwards WA Post article re harassment of QC personnel Lack of enforcement action questioned.
BRADFORD,P.A Commissioners 79/10/10 STELLO,V. Office of Inspection & Enforcement, Office of the Director 2pp. 18497 237 24X Fiche 50-000,83/03/09,8305180001

--8008120773 Forwards outlines of JF Ahearne & V Stello proposed testimony re facility before House Subcommittee on Oversight & Investigation
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/11 AHEARNE,J F , GILINSKY,V , HENDRIE,J Commissioners 6pp 18499 163 24X Fiche 50-000,83/03/09, 8305180001

--8009120352 Advises that Region 4 should assume responsibility for review & verification of corrective actions by licensee as followup action associated w/South Texas problems Headquarters will be responsible for monitoring reviews.
THORNBURG,H D Division of Reactor Construction Inspection 80/06/24 SEYFRIT,K.V. Region 4, Dallas, Office of the Director 3pp 18499 219 24X Fiche 50-000,83/03/09,8305180001

--8010090450 Forwards draft Commission info paper re plan for resumption of const.Comments or concurrences needed by 800912.W/o encl.
THORNBURG,H D Division of Reactor Construction Inspection. 80/09/11 DENTON,H.R. Office of Nuclear Reactor Regulation, Director SHAPAR,H K Office of the Executive Legal Director
STELLO,V Office of Inspection & Enforcement, Office of the Director 9pp. 18499 222 24X Fiche 50-000,83/03/09,8305180001

--8010280578 Responds to Question 4 of 800923 memo re Eckhardt hearing Major Brown & Root Corp nuclear const work & weld deficiency status summarized Licensee will complete visual insp & comply w/corrective actions in encl AWS Code.
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/09/25 AHEARNE,J F. Commissioners 5pp. 18497 228 24X Fiche.50-000,83/03/09,8305180001

--8010280581 Assigns questions resulting from 800923 Eckhardt hearing
AHEARNE,J F Commissioners 80/09/23 Office of the Executive Director for Operations 3pp 18499 193. 24X Fiche 50-000,83/03/09,8305180001

--8103250385 Summarizes events re 810317 telcon w/L Sinkin concerning allegations at facility Improper alteration of documents, removal of documents to prevent NRC insp & intimidation of Brown & Root personnel have been alleged.
WILBER,H A. Reactor Projects Sections (Regions 2,4 & 5) 81/03/17 SEYFRIT,K V Region 4, Dallas, Office of the Director 2pp. 18499,242 24X Fiche 50-000,83/03/09,8305180001

--8305180064 Responds to Gossick request to reply to inquiry re adequacy of QA/QC program.Licensee continuing to look for addl voids & is evaluating possible alternate designs for reinforcing steel & liner stiffeners
STELLO,V Office of Inspection & Enforcement, Office of the Director 79/07/31 KENNEDY,R.T. Commissioners. 3pp. 18497 234 24X Fiche 50-000,83/03/09,8305180001.

--8305180075 Responds to Commissioner Bradford 791019 inquiry re newspaper article concerning facility insps "Surprise insp" announced IE insp of facility QA program Allegations re beating of QC inspector could not be substantiated.
HUBACEK,W G Region 4, Dallas, Office of the Director 79/10/26.
REINMUTH,G.W Division of Reactor Construction Inspection. 2pp. 18497 239 24X Fiche 50-000,83/03/09,8305180001

--8305180083 Requests that responses to Commissioner Bradford inquiries re newspaper article concerning facility insps be revised to accommodate listed comments by Barber/Thompson.
REINMUTH,G.W Division of Reactor Construction Inspection. 79/11/02. SEIDLE,W.C Region 4, Dallas, Reactor Construction & Engineering Support Branch 2pp 18497 241 24X Fiche 50-000,83/03/09,8305180001

--8305180094 Discusses recommendations for further IE investigation & insp efforts at facilities Expanded & comprehensive insp program should be immediately initiated & maintained until confidence established.Related info encl.
HAYES,D W Region 3, Chicago, Office of the Director 80/03/11
THORNBURG,H D. Division of Reactor Construction Inspection. 421pp. 18497 243 24X Fiche.50-000,83/03/09,8305180001.

--8305180121 Requests info re scope & significance of voids in concrete at site Response requested by 800423
BRADFORD,P A Commissioners 80/04/18 DIRCKS,W J Office of the Executive Director for Operations 1p 18499 138 24X
Fiche 50-000,83/03/09,8305180001

--8305180148 Advises that staff should notify Commission in advance of proposed actions re facility investigation,per Commissioner Bradford 800418 memo
CHILK,S J Office of the Secretary of the Commission
COMPB-80-16 80/04/28 DIRCKS,W J Office of the Executive Director for Operations 1p 18499 142 24X
Fiche 50-000,83/03/09,8305180001

--8305180157 Forwards enforcement package including enforcement notice, draft press release,forwarding ltr,notice of violation, proposed imposition of civil penalty & show cause order W/o encls
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/04/28 AHEARNE,J F , GILINSKY,V , KENNEDY,R T Commissioners 1p 18499 143 24X Fiche 50-000,83/03/09, 8305180001

--8305180167 Informs that Commission concensus not in favor of recommendations contained in 800418 memo re facility investigation Modified version of Suggestion I further modified by Commissioner Kennedy.Responses encl W/o encls
CHILK,S J Office of the Secretary of the Commission
COMPB-80-16 80/04/28, BRADFORD,P A Commissioners 1p 18499,144 24X Fiche 50-000,83/03/09,8305180001

--8305180175 Recommends that IE address Ofc of General Counsel Questions 1-7 prior to enforcement action IE will take action on 800501
BRADFORD,P.A Commissioners COMPB-80-19 80/04/30
AHEARNE,J F, Commissioners 1p 18499 145 24X
Fiche 50-000,83/03/09,8305180001

--8305180181 Discusses results of followup inquires by Region IV re terminated Brown & Root,Inc QC civil engineer inspectors
SEYFRIT,K V Region 4, Dallas, Office of the Director 80/04/30
DEYOUNG,R C Office of Inspection & Enforcement, Office of the Director 2pp 18499 146 24X Fiche 50-000,83/03/09,8305180001

--8305180189 Informs that Commissioners have not supported request to ask IE to address Ofc of General Counsel Questions 1-7 prior to time of enforcement action
CHILK,S J Office of the Secretary of the Commission
COMPB-80-19, 80/05/02 BRADFORD,P A Commissioners 1p 18499 148. 24X Fiche.50-000,83/03/09,8305180001

--8305180202 Informs of new allegations concerning possible intimidation of QC inspectors received while preparing response to 791010 memo. Investigation will be conducted to verify facts. Appropriate enforcement action will be taken
STELLO,V. Office of Inspection & Enforcement, Office of the Director 83/03/09 BRADFORD,P A. Commissioners 1p 18499 152 24X Fiche.50-000,83/03/09,8305180001

--8305180211 Responds to 791010 memo re newspaper article concerning facility & question related to enforcement action following Region IV investigation of alleged beating of Brown & Root QC inspector Allegation could not be substantiated.
STELLO,V Office of Inspection & Enforcement, Office of the Director, 83/03/09 BRADFORD,P.A Commissioners 2pp 18499,153. 24X Fiche 50-000,83/03/09,8305180001

--8305180221 Informs that NRC will be requested to testify on first day of House Subcommittee on Oversight & Investigations hearings tentatively scheduled to begin on 800729 re const problem & NRC investigation of facility.
KAMMERER,C. Office of Congressional Affairs 80/07/09
AHEARNE,J.F , GILINSKY,V., HENDRIE,J.M Commissioners 2pp 18499 157 24X Fiche:50-000,83/03/09,8305180001

--8305180236 Submits schedule of Congressional hearings re waste bill H.R.7418,West Valley Bill H R 6868 & South Texas project Related info encl.
REHM,T.A Office of the Executive Director for Operations. 80/07/07. STELLO,V Office of Inspection & Enforcement, Office of the Director DAVIS,J. Office of Nuclear Material Safety & Safeguards,Director 4pp 18499:159. 24X Fiche 50-000,83/03/09, 8305180001

--8305180250 Forwards Chairman Ahearne & V Stello testimony prepared for House Subcommittee on Oversight & Investigation hearing re facility
STELLO,V. Office of Inspection & Enforcement, Office of the Director, 80/07/25. AHEARNE,J.F., GILINSKY,V , HENDRIE,J M Commissioners 2pp. 18499:169 24X Fiche:50-000,83/03/09, 8305180001.

--8305180254 Statement of JF Ahearne to House Subcommittee on Oversight & Investigations Pp 1-5
AHEARNE,J F Commissioners 80/07/29 6pp 18499 171 24X
Fiche 50-000,83/03/09,8305180001

--8305180257 Statement of V Stello before House Subcommittee on Oversight & Investigations 800729 hearing Pp 1-15
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/07/29 16pp 18499 177 24X Fiche 50-000,83/03/09, 8305180001

--8305180276 Forwards draft Commission info paper intended for presentation during wk of 800414 re investigation & proposed enforcement action Comments needed by 800409
THORNBURG,H D Division of Reactor Construction Inspection 80/04/03 DENTON,H R Office of Nuclear Reactor Regulation, Director SHAPAR,H K Office of the Executive Legal Director
STELLO,V Office of Inspection & Enforcement, Office of the Director 11pp 18499 204 24X Fiche 50-000,83/03/09,8305180001

--8305180315 Forwards Part 2 of Commission regulations re practice in conduct of formal hearings before Commission adjudicatory panels & procedures for initiating enforcement actions W/o encl
BURNS,S G Office of the Executive Legal Director 80/05/29
CORTEZ,B Communities Organized for Public Service 1p
18499 218 24X Fiche 50-000,83/03/09,8305180001

--8305180326 Informs that Chairman has requested that encl Commission paper re plan for resumption of const be forwarded through L Bickwit,general counsel
STELLO,V Office of Inspection & Enforcement, Office of the Director 80/09/18 DIRCKS,W J Office of the Executive Director for Operations 11pp 18499 231 24X Fiche 50-000,83/03/09, 8305180001

--8305180337 Discusses importance of NASLAP decision re protection of confidentiality of informers & allegers Dissenting opinion points out cautions that should be observed in informing allegers or informants
THOMPSON,D Enforcement & Investigation Staff (Pre 820201) 81/05/14 GRIER,B H Region 1, Philadelphia, Office of the Director (81/03/01) O'REILLY,J P Region 2, Atlanta, Office of the Director (81/03/01) KEPPLER,J G Region 3, Chicago, Office of the Director (81/03/01) 1p 18499 244 24X
Fiche 50-000,83/03/09,8305180001

8305180003 FOIA request for documents associated w/investigation of Nuclear Pharmacy,Inc by NRC Ofcs of Inspector & Auditor & IE
EMSHWILLER,J R Wall Street Journal 82/10/26 NRC - No Detailed Affiliation Given 1p 18503 051

8305180005 Addl response to FOIA request for documents associated w/ investigation of Nuclear Pharmacy,Inc by Ofcs of Inspector & Auditor & IE Forwards documents listed in Apps A & B Info partially withheld (ref FOIA Exemptions 5 & 7)
FELTON,J M Division of Rules and Records 83/04/12
EMSHWILLER,J R Wall Street Journal 7pp 18503 052

--7911150353 Informs that Nuclear Pharmacy,Inc shipped Xe-133 unit doses not fit for human use List of shipments,date distributed, activity & prescription number encl
KEPPLER,J.G Region 3, Chicago, Office of the Director 79/11/02
COMISKEY,J St Michael Hosp. Milwaukee,WI 2pp 18503 080

--8305180010 Documents basis for certain statements contained in IE Insp Rept 79-01 for Nuclear Pharmacy,Inc Personally identifiable info deleted
DICEY,B B. Region 3, Chicago, Office of the Director 79/09/21
PAPERIELLO,C.J Region 3, Chicago, Office of the Director 3pp. 18503 059

--8305180013 Discusses 800129 interview w/JH Sniezek re 800121 meeting w/Nuclear Pharmacy,Inc concerning notice of violation
GAMBLE,D H. Office of Inspector & Auditor 80/01/31
STRICKLER,L J Office of Inspector & Auditor 4pp 18503,063

--8305180016 Discusses 800129 interview w/PE Baci (DOJ) re 800121 meeting between Nuclear Pharmacy,Inc (NPI) & NRC concerning NPI possession of Xe-133
GAMBLE,D.H Office of Inspector & Auditor 80/02/01
STRICKLER,L J Office of Inspector & Auditor 8pp. 18503 067

--8305180021 Forwards Region III 791102 ltr sent to certain customers (hosps) of Nuclear Pharmacy,Inc (NPI) notifying that NPI sold Xe-133 prepared from chemical-grade bulk matl rather than from pharm-grade bulk matl
STRICKLER,L J Office of Inspector & Auditor 79/11/06 Office of Inspector & Auditor. 1p 18503 079.

--8305180031 Discusses 791108 meeting w/DOJ re potential for developing prosecutable case against Nuclear Pharmacy, Inc DOJ has no interest in proceeding w/criminal action if violation not of sufficient significance to warrant civil penalty
STRICKLER, L J Office of Inspector & Auditor 79/11/13 Office of Inspector & Auditor 2pp 18503 082

--8305180037 Discusses 791108 briefing w/DOJ re deficiencies in case against Nuclear Pharmacy, Inc concerning purchase of Xe-133 from Union Carbide
STRICKLER, L J Office of Inspector & Auditor 79/11/14 Office of Inspector & Auditor 2pp 18503 084

--8305180044 Urges NRC not to mitigate fine for Nuclear Pharmacy, Inc, re unauthorized acquisition & breakdown of packaging & delivery of Xe-133 unfit for human use Other vendor violations cited Personally identifiable info deleted
* Affiliation Unknown 79/12/01 SNIEZEK, J H Division of Fuel Facility & Materials Safety 3pp 18503 085

--8305180052 Documents recollections of statements made during 790323 mgt enforcement conference re procurement & distribution of Union Carbon Xe-133 contrary to FDA & NRC requirements
DICEY, B B Region 3, Chicago, Office of the Director 79/12/05 STRICKLER, J Office of Inspector & Auditor 2pp 18503 089

--8305180056 Submits amended response to 750410 questions re license application Manufacturers package insert for all radiopharms dispensed by use will be forwarded to each user.
SANCHEZ, R L NuPharm, Inc 75/04/23 BOYER, J E Division of Fuel Cycle & Material Safety 3pp 18503 091

--8305180063 Application to amend License 24-16519-01, reflecting corporate name change to Nuclear Pharmacy, Inc & change of address
REAVIS, J H NuPharm, Inc 86499 77/03/18 BOYER, J E Office of Nuclear Material Safety & Safeguards, Director 1p 18503 094

--8305180070 Discusses 791207 telcon re postponement of meeting w/Nuclear Pharmacy, Inc (NPI) Allegations in notice of violation w/o foundation Prompt action to resolve matter requested
VAKERICS, T V O'Connor & Hannan 79/12/07 STELLO, V Director's Office, Office of Inspection and Enforcement 3pp 18503 095

--8305180074 Confirms 791205 telcon re withdrawal of Nuclear Pharmacy, Inc matter from consideration by DOJ Investigation of source of unauthorized disclosures of confidential info requested
VAKERICS, T V O'Connor & Hannan 79/12/07 CUMMINGS, J J Office of Inspector & Auditor 1p 18503 098

--8305180080 Documents recollection of 790323 enforcement mgt meeting re Nuclear Pharmacy, Inc reason for distributing Union Carbide Xe-133
PAPERIELLO, C Region 3, Chicago, Office of the Director 79/12/10 STRICKLER, J Office of Inspector & Auditor 1p 18503 100

--8305180092 Discusses status of other NRC ofc actions from 790614-1127 re NRC criminal referral to DOJ re allegations of improper activities by Nuclear Pharmacy, Inc
STRICKLER, L J Office of Inspector & Auditor 79/12/13 CUMMINGS, J J Office of Inspector & Auditor 3pp 18503 101

--8305180096 Forwards 791201 ltr re allegations of improper activities by Nuclear Pharmacy, Inc Ltr includes number of issues which appear to warrant further investigation Personally identifiable info deleted
GOWER, G C Executive Officer for Operations Support 79/12/19 FORTUNA, R Office of Inspector & Auditor 3pp 18503 106

--8305180100 Discusses 800128 interview w/J Murray re 800121 meeting w/ Nuclear Pharmacy, Inc on proposed notice of violation
SINCLAIR, J.R Office of Inspector & Auditor 81/02/04 STRICKLER, L J Office of Inspector & Auditor 3pp 18503 109

--8305180106 Discusses 800205 interview w/V Stello re 800121 meeting w/ Nuclear Pharmacy, Inc concerning sales of Xe-133 not approved for human use Affidavit encl Personally identifiable info deleted
GAMBLE, D H Office of Inspector & Auditor 81/02/08 STRICKLER, L J Office of Inspector & Auditor 6pp 18503 112

--8305180111 Discusses Senator H Schmitt 800102 ltr re Nuclear Pharmacy, Inc (NPI) & T Brockett responses concerning possible criminal violations by NPI
STRICKLER, L NRC - No Detailed Affiliation Given 80/02/19 NRC - No Detailed Affiliation Given 1p 18503 118

--8305180116 Requests expeditious resolution of notice of violation issued to Nuclear Pharmacy, Inc
SCHMITT, H Senate 80/01/02 AHEARNE, J Commissioners 1p 18503 119

--8305180123 Urges final action to resolve notice of violation issued to Nuclear Pharmacy, Inc in Aug 1979 Review by another agency not sufficient justification to forestall prompt action
DOMENICI, P V Senate 80/01/09 AHEARNE, J F Commissioners 2pp 18503 120

--8305180153 Discusses 800109 ltr re pending administration action against Nuclear Pharmacy, Inc (NPI) DOJ currently reviewing matter No operating restrictions placed on licensee
DIRCKS, W J Office of the Executive Director for Operations 80/02/11 DOMENICI, P V Senate 1p 18503 122

--8305180159 Confirms 800227 telcon re Jan 1979 insp at Nuclear Pharmacy, Inc (NPI) No indication that NPI reused New England Nuclear dose vials for packaging & distributing Xe-133 observed Interview rept encl Personally identifiable info deleted
DICEY, B B Michigan, Univ of 80/02/27 STRICKLER, J Office of Inspector & Auditor 9pp 18503 123

--8305180166 Notifies that D Leggett & J Fischer provided w/listed statements during 800310 visit, per DOJ instructions re Nuclear Pharmacy, Inc investigation Personally identifiable info deleted
STRICKLER, L J Office of Inspector & Auditor 80/03/13 Office of Inspector & Auditor 1p 18503 132

--8305180174 Advises that listed original statements placed in Nuclear Pharmacy, Inc investigation file on 800313. Personally identifiable info deleted
STRICKLER, L J Office of Inspector & Auditor 80/03/13. Office of Inspector & Auditor 1p 18503 133

--8305180178 Forwards DOJ 800307 ltr describing frustrations in dealing w/NRC during consideration of possible criminal aspects of Nuclear Pharmacy, Inc case
CUMMINGS, J J Office of Inspector & Auditor 80/03/13. AHEARNE, J F Commissioners 1p 18503, 134

--8305180186 Disagrees w/800313 memo to Chairman re civil penalties resulting from notice of violation issued to Nuclear Pharmacy, Inc
STELLO, V Director's Office, Office of Inspection and Enforcement 80/03/18 CUMMINGS, J J Office of Inspector & Auditor 2pp 18503 143

--8305180196 Discusses 800321 telcon w/former employee of Nuclear Pharmacy, Inc, re unsafe & unethical practices Interview encl. Personally identifiable info deleted
WARD, W J Executive Officer for Operations Support 80/03/31. Executive Officer for Operations Support 7pp 18503 145

--8305180207 Notifies that final rept of 800401 interview placed in Nuclear Pharmacy, Inc statement file on 800404 Personally identifiable info deleted
STRICKLER, L J Office of Inspector & Auditor 80/04/04 Office of Inspector & Auditor 11pp 18503 152

--8305180223 Notifies that original 800319 statement placed in Nuclear Pharmacy, Inc file on 800404. Personally identifiable info deleted
STRICKLER, L J Office of Inspector & Auditor 80/04/04 Office of Inspector & Auditor 15pp 18503 163.

--8305180233 Discusses conflict of interest on part of former Region I employee re civil penalty action against Elfreth Alley Apothecary, part of Nuclear Pharmacy, Inc. Personally identifiable info deleted
FORTUNA, R A Office of Inspector & Auditor. 80/05/29 BISCUIT, L Office of the General Counsel 1p 18503 199

--8305180241 Discusses corrective actions per 800310 ltr, in response to NRC 800407 & 0219 ltrs re radiation safety for personnel Mar film badge results indicate significant improvement Personally identifiable info deleted
* NuPharm, Inc EA-80-005 80/05/05 STELLO, V Director's Office, Office of Inspection and Enforcement 2pp 18503, 200.

--8305180247 Notifies that 800516 statements placed in Nuclear Pharmacy, Inc file on 800603 Personally identifiable info deleted
STRICKLER, L J Office of Inspector & Auditor 80/06/03 Office of Inspector & Auditor 13pp. 18503 202

--8305180258 Forwards Amend 6 to Matl Byproduct License 48-17466-01MD. License may be subj to subsequent action by NRC or DOJ resulting from exam of past activities involving Xe-133 Personally identifiable info deleted
DELMEDICO, J Division of Fuel Cycle & Material Safety 80/05/03. REAVIS, J M NuPharm, Inc 32pp 18503 215

--8305180263 Forwards Nuclear Pharmacy, Inc 800626 ltr discussing actions initiated to provide max safety for employees
FORTUNA, R A Office of Inspector & Auditor 80/07/07
GREENSPUN, J Justice, Dept of 1p 18503 247

--8305180269 Discusses 800624 meeting re development of corporate radiation safety program Personally identifiable info deleted
* NuPharm, Inc 80/06/26 DAVIS, B Region 3, Chicago, Fuel Facility & Materials Safety Branch 4pp 18503 248

--8305180285 Forwards documents on investigation of Nuclear Pharmacy, Inc (NPI) per 800827 commitment re NPI-Milwaukee distribution of non-NDA Xenon in willful violation of license condition Personally identifiable info deleted W/o encls
FORTUNA, R A Office of Inspector & Auditor 80/09/19
GREENSPUN, J Justice, Dept of 3pp 18503 252

--8305180291 Forwards six interview summaries prepared by Region III re apparent conflict of interest by former Region I employee concerning Nuclear Pharmacy, Inc investigation Personally identifiable info deleted
FORTUNA, R A Office of Inspector & Auditor 80/11/25
GREENSPUN, J Justice, Dept of 10pp 18503 255

8305180308 FOIA request for SECY-83-17 & SECY-83-19
BREADY, J C KMC, Inc 83/02/08 CHILK, S, J Office of the Secretary of the Commission, 1p 18505 229,

8305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/03/29, BREADY, J C KMC, Inc 1p 18505 230 24X Fiche 50-237,83/03/29,8305180316

--8305180322 SECY-83-019
Informs of proposed plan to convert seven remaining provisional OLs to full-term OLs after completion of SEP Phase II
DIRCKS, W J Office of the Executive Director for Operations 83/01/17 15pp 18505 231

--8305180328 SECY-83-017
Notifies of results of SEP review of facility
DIRCKS, W J Office of the Executive Director for Operations 83/01/12 47pp 18505 246 24X Fiche 50-237,83/03/29,8305180316

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B, C, D & E documents withheld (ref FOIA Exemption 7)
FELTON, J M Division of Rules and Records 83/03/11
PRENDERGAST, R Prendergast, R. J 17pp 18506 057 24X Fiche, 50-000,83/03/11,8305190005

--8208250506 Trip rept of 820802 audit, reviewing seismic & qualification file for Zack Co equipment, at Sargent & Lundy Engineers ofc in Chicago, IL
ROBZTOCZY, Z R Equipment Qualification Branch 82/08/06
SCHWENCER, A. Licensing Branch 2 8pp 18507 201 24X
Fiche 50-000,83/03/11,8305190005

--8305190045 Requests vendor insp of facilities having contracts w/Zack Co due to QA/QC problems at Midland re HVAC activities Zack Co correspondence re LaSalle & related info encl
FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 80/04/21 POTOPOUS, U Region 4, Dallas, Vendor Inspection Branch 12pp 18506 077 24X Fiche 50-000,83/03/11, 8305190005

--8305190050 Summarizes 820430 meeting w/president of Zack Co, HVAC contractor at facilities, re potential allegations Zack Co planning to terminate several employees in document control section
HAYES, D W Region 3, Office of Director 82/05/12 Region 3, Office of Director 1p 18506 089 24X Fiche, 50-000,83/03/11, 8305190005

--8305190061 Summarizes 820510 telcon w/T Howard, former employee of Zack Co, re allegations concerning Zack Co, HVAC contractor at various nuclear power const sites Matter will be pursued upon return of C Weil on or about 820517
PHILLIP, G A Region 3, Office of Director EIB 82-25 82/05/21
Region 3, Office of Director 1p 18506 090

--8305190084 RO fire dampers supplied by American Warming & Ventilation, Inc declared inoperative Caused by discrepancy in fuse link assembly size Fuse assemblies will be replaced. JV Winkle ltr re news telecast & J Dierbeck note encl.
HOLYOAK, R. H Commonwealth Edison Co 82/07/01 KEPPLER, J G
Region 3, Office of Director 33pp. 18506 091 24X
Fiche 50-000,83/03/11,8305190005

--8305190088 Repts allegation re Zack Co falsified documents concerning HVAC activities at facilities per NBC Nightly News broadcast
* Radio TV Reports, Inc 82/07/24 NRC - No Detailed Affiliation Given 2pp 18506 124 24X Fiche 50-000,83/03/11, 8305190005

--8305190097 Requests investigation of Region III inadequate investigative oversight re QA breakdown & possible criminal falsification at Zack Co, HVAC contractor at facilities AT Howard & S Marello allegations discussed
DEVINE, T , GARDE, B Government Accountability Project 82/07/26
PALLADINO, N J Commissioners 11pp 18506 128 24X
Fiche 50-000,83/03/11,8305190005

--8305190102 Affidavit of SL Marello re QC breakdown & criminal falsification at Zack Co, HVAC contractor at facilities
MARELLO, S L Affiliation Unknown 82/07/26 22pp 18506 139
24X Fiche 50-000,83/03/11,8305190005

--8305190108 Affidavit of AT Howard re QC breakdown & criminal falsification at Zack Co, HVAC contractor at facilities
HOWARD, A T Affiliation Unknown 82/07/26 55pp 18506 160
24X Fiche 50-000,83/03/11,8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated, document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS, D E , EICHSTAEDT, C L , DEZUTEL, C Z Zack Co 10CFR 050 55E 81/10/23 310pp 18506 215 24X Fiche 50-000,83/03/11, 8305190005

--8305190119 Repts investigation re possible flawed equipment at facilities, per Eyewitness News broadcast
* Radio TV Reports, Inc 82/07/26 NRC - No Detailed Affiliation Given 2pp 18507 165 24X Fiche 50-000,83/03/11, 8305190005

--8305190124 Offers assistance & cooperation in investigating Zack Co Suggestions discussed
DEVINE, T , GARDE, B P Government Accountability Project. 82/07/27 PALLADINO, N J Commissioners 2pp 18507 167 24X
Fiche 50-000,83/03/11,8305190005

--8305190128 Forwards outline of investigation rept re Zack documentation concerning HVAC activities Discussion of matl spec & mechanical properties for galvanized sheet steel & stiffener hanger & support steel & L DelGeorge handwritten notes encl
NORELIUS, C E Region 3, Office of Director 82/07/28
KEPPLER, J G , DAVIS, A B , FOSTER, J Region 3, Office of Director 25pp 18507 169 24X Fiche 50-000,83/03/11,8305190005

--8305190132 Forwards results of analyses of carbon steels received from Region III on 820726 NBS stds used to quality assure phosphorus, manganese & copper results performed on same sample solution
GREEN, D W Argonne National Laboratory 82/08/02 LANKSBURY, R
Region 3, Office of Director 6pp 18507 194

--8305190145 Confirms telcon w/Tongue re Unit 1 switchgear heat removal welds Certain welds on Unit 2, Div II switchgear heat removal sys may not meet applicable code requirements
HOLYOAK, R H Commonwealth Edison Co 82/08/06 Region 3, Office of Director 1p 18507 200 24X Fiche 50-000,83/03/11, 8305190005

--8305190151 Informs of atty general of State of IL intention to attend NRC 820811 meeting w/util & Govt Accountability Project to discuss selection of third party to investigate HVAC allegations
VAN VRANKEN, J Illinois, State of 82/08/09 KEPPLER, J G
Region 3, Office of Director 1p 18507 209 24X
Fiche 50-000,83/03/11,8305190005

--8305190153 Forwards results of reanalyses of carbon steels received on 820726 Analysis results of NBS carbon & sulfur std data submitted
GREEN, D. W Argonne National Laboratory 82/08/10 LANKSBURY, R
Region 3, Office of Director 2pp 18507 210

--8305190162 Introduction of 820811 public meeting to discuss util plans re employment of third party contractor to conduct independent review of HVAC sys at facilities
* NRC - No Detailed Affiliation Given 82/08/11 2pp
18507-214 24X Fiche 50-000,83/03/11,8305190005

--8305190167 Requests that all interested parties be furnished proposed contract between util & CF Braun for independent investigation of facilities & be allowed to submit written comments before agreement finalized
VAN VRANKEN, J Illinois, State of 82/08/12 KEPPLER, J G Region 3, Office of Director 2pp 18507 215 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190179 Requests that Region III monitor CF Braun activities in independent review of HVAC sys at facilities & that T Howard & S Marello experience & knowledge be utilized in review process Util 820813 ltr to CF Braun & Co encl
HOWARD, A T Affiliation Unknown 82/08/13 KEPPLER, J G Region 3, Office of Director 11pp 18507 216 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190184 Confirms 820812 telcon re telephone call from M Cherry concerning Zack investigation & circumstances surrounding termination of Zack employees.
DAVIS, A B Region 3, Office of Director 82/08/16 FITZGERALD, J Office of Investigation 2pp 18507 230 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190189 Notification of 820824 meeting w/util in Glen Ellyn, IL to discuss status of licensee independent HVAC review
* Region 3, Office of Director 82/08/18 Region 3, Office of Director 1p 18507 231 24X Fiche 50-000, 83/03/11, 8305190005

--8305190207 Verifies AT Howard receipt of four cassette tapes of 820730 discussions between NRC & AT Howard, SL Marello & T Devine at Region III ofc in Glen Ellyn, IL
* Region 3, Office of Director HOWARD, A T Affiliation Unknown 82/08/20 Region 3, Office of Director. 1p 18507 258

--8305190232 Requests investigation re discharge of AT Howard & S Marello from Zack Co, per 820819 discussion w/ J Fitzgerald
DAVIS, A B Region 3, Office of Director 82/08/23 FOSTER, J E Region 3, Office of Director 1p 18507 259

--8305190276 Confirms oral direction given to RD Lanksbury requesting that Zack investigation determine adequacy of qualifications of Zack personnel involved in Zack QA/QC program Work may be performed by Region IV
DAVIS, A B Region 3, Office of Director 82/08/23 NORELIUS, C E Division of Engineering 1p 18507 262

--8305190283 Introduction of 820824 public meeting to discuss util preliminary plans re independent review of HVAC sys at facilities Meeting will focus on CF Braun technical proposals
* NRC - No Detailed Affiliation Given 83/08/24 1p 18507 266 24X Fiche 50-000, 83/03/11, 8305190005

--8305190289 Forwards T Devine 820813 ltr, AT Howard 820813 ltr & SS Marello 820816 ltr for NRR consideration in assessment of util proposal on third party review of HVAC sys at facilities
SPESSARD, R L Division of Project & Resident Programs. 82/08/25. EISENHUT, D G Division of Licensing. 1p 18507 293 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190292 Advises that AT Howard & SS Marello do not object to selection of CF Braun to conduct third party investigation of charges against Zack Co, subj to listed conditions Related info encl
DEVINE, T Government Accountability Project 82/08/13
KEPPLER, J Region 3, Office of Director 14pp 18507 294 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190296 Comments on 820811 meeting w/NRC & util re CF Braun audit of facilities. CF Braun should rept directly to NRC & should audit all critical areas at facilities
MARELLO, S L Affiliation Unknown 82/08/16 KEPPLER, J Region 3, Office of Director 3pp 18507 313 24X Fiche 50-000, 83/03/11, 8305190005

--8305190299 Advises that HVAC review consists of independent review & review of allegations & that NRR & Region III responsibilities delineated per 820824 meeting, in response to HR Denton question (draft memo)
BOURNIA, A Licensing Branch 2 82/08/26. NOVAK, T.M. Assistant Director for Licensing. 1p 18507 316

--8305190302 Forwards Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const, LaSalle County Station Units 1 & 2." QC rejectable welds have sufficient strength to meet design requirements of HVAC ductwork & need not be repaired
POLLOCK, R.H. Sargent & Lundy, Inc. 82/08/27. SHELTON, B R Commonwealth Edison Co 1p 18507 317 24X Fiche: 50-000, 83/03/11, 8305190005.

--8305190303 CQD-003490 R00
Rev 0 to "Assessment of Stitch Weld Strength in HVAC Ductwork Const, LaSalle County Station Units 1 & 2 "
CHO, F L , KISISEL, I T , MELIGI, A V Sargent & Lundy, Inc 82/08/27 27pp 18507 318. 24X Fiche 50-000, 83/03/11, 8305190005

--8305190304 Discusses concerns on behalf of AT Howard & S Marello, for NRC consideration in review of CF Braun final proposal to conduct independent review of HVAC sys at facilities, per 820824 meeting
DEVINE, T Government Accountability Project 82/09/04
KEPPLER, J G Region 3, Office of Director 6pp 18507.345 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190306 Clarifies initial actions taken re A Howard allegations concerning Zack Co Agrees w/RF Warnick handling of case w/ relative priority
FOSTER, J E Region 3, Office of Director 82/09/07 KEPPLER, J G, Region 3, Office of Director 2pp 18507 351

--8305190307 Discusses A Howard 820503 allegations re Zack Co tampering w/documents concerning HVAC activities at facilities. Further investigation will be implemented if deemed appropriate by mgt
SHAFER, W.D. Region 3, Office of Director. 82/05/11 WARNICK, R F Region 3, Office of Director. 3pp. 18507·354 24X
Fiche. 50-000, 83/03/11, 8305190005

--8305190329 Responds to 820904 ltr containing comments on CF Braun proposal for independent verification of HVAC sys at facilities Comment taken into consideration in NRR review of proposal
KEPPLER, J G Region 3, Office of Director 82/09/13 DEVINE, T Government Accountability Project. 1p 18507.357 24X
Fiche. 50-000, 83/03/11, 8305190005

--8305190332 Forwards "LaSalle County Station Independent HVAC Review," interim rept. Rept also sent to JG Keppler
KEMPIAK, A J C F Braun & Co BL-6 82/09/15. SHELTON, B R. Commonwealth Edison Co 1p 18507 359 24X Fiche 50-000, 83/03/11, 8305190005

--8305190337 Forwards results of analysis of steel received on 820915.
GREEN, D W Argonne National Laboratory 82/09/29 LANKSBURY, R Region 3, Office of Director 3pp 18508·085

--8305190341 Forwards results of analysis of steels received on 820924
GREEN, D W. Argonne National Laboratory. 82/10/11 LANKSBURY, R. Region 3, Office of Director 2pp 18508·088.

--8305190353 Forwards TE Watts 821019 & 25 memos to CW Schroeder responding to R Lanksbury questions re HVAC ductwork design & transmitting Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station "
SCHROEDER, C W. Commonwealth Edison Co 5332N. 82/10/27
KEPPLER, J G Region 3, Office of Director. 9pp. 18508·093 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190357 Rev 0 to Project Instruction PI-LS-42, "Review of QC Documentation for LaSalle County Station Units 1 & 2 "
* Sargent & Lundy, Inc. 82/10/21 9pp. 18508:102 24X
Fiche 50-000, 83/03/11, 8305190005

--8305190365 Forwards Vols 1-4 to "Independent HVAC Review, LaSalle County Nuclear Plant," final rept.
KEMPIAK, A J. C.F Braun & Co. BL-25 82/10/27 SHELTON, B.R. Commonwealth Edison Co. 1p 18508.111. 24X Fiche·50-000, 83/03/11, 8305190005.

--8305190367 Ack receipt of CF Braun final rept of independent HVAC review at facilities
PHILLIPS, R.W Region 3, Office of Director. 82/10/27 Region 3, Office of Director 1p 18508.112 24X Fiche. 50-000, 83/03/11, 8305190005

--8305190374 Forwards ltr from Chicago-based law firm representing Zack Co, requesting withholding of documents re NRC investigation of Zack Co per 10CFR2 790 Conference call will be held on 821110 to discuss subj W/o encl.
COLLINS, J. T Region 4, Office of Director. 82/11/08 KEPPLER, J. Region 3, Office of Director. CUNNINGHAM, G. Office of the Executive Legal Director 1p. 18508·113

--8305190379 Requests list of results of detailed calculations on rebar damage for 647 concrete elements affecting Unit 1 operation & approved CF Braun proposal for independent HVAC review. Zack Co chronology encl
GOODIE, J S Illinois, State of 82/09/07. KEPPLER, J G. Region 3, Office of Director. 5pp. 18511:278 24X Fiche: 50-000, 83/03/11, 8305190005.

--8305190384 Advises that field insp of HVAC sys at facility completed, including review of Govt Accountability Project allegations against Zack Co No technical basis exists for further restriction of facility power level W/related info
KEPPLER, J G Region 3, Office of Director 82/12/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 18512 038 24X Fiche 50-000, 83/03/11, 8305190005

--8305190387 Rev 1 to "LaSalle County Station Technical Proposal," including scope of work, work plan to accomplish independent HVAC review, organization chart & resumes of personnel assigned to project List of matl specs for HVAC const encl
* C.F Braun & Co 82/08/25 34pp 18512 155 24X Fiche 50-000, 83/03/11, 8305190005

--8305190390 P Donahue show Transcript 08302 re nuclear power safety Info re facilities & Zack Co encl
* Multimedia Program Production, Inc 83/03/11 128pp 18512 189 24X Fiche 50-000, 83/03/11, 8305190005

--8305190393 Discusses Zack Co Part 21 rept re dual traveler record sys for fabrication of duct work & hangers at facility, per 820729 telcon w/L DelGeorge & C Read AT Howard resume encl
WILLIAMS, C C NRC - No Detailed Affiliation Given 83/03/11 LANKSBURY, R.D. NRC - No Detailed Affiliation Given. 6pp 18512 317. 24X Fiche 50-000, 83/03/11, 8305190005

--8305190396 Discusses 820624 telcon w/B Garde of Govt Accountability Project re allegations concerning Zack Co QA program at facilities Personally identifiable info deleted
NORELIUS, C.E Division of Engineering 82/07/12 Division of Engineering 1p. 18512 323 24X Fiche 50-000, 83/03/11, 8305190005

--8305190399 Handwritten notes re meeting w/util on allegations concerning Zack Co activities at facilities
DAVIS, A.B NRC - No Detailed Affiliation Given. 82/07/16 9pp 18512.335 24X Fiche 50-000, 83/03/11, 8305190005

8305200087 Responds to FOIA request for name of manufacturer of fuel rods used at facility Fuel rods mfg by B&W.
FELTON, J M. Division of Rules and Records 83/03/31 WHITED, P. J Affiliation Unknown 1p. 18541.004 24X Fiche 50-320, 83/03/31, 8305200087

8305200101 FOIA request for name of manufacturer of fuel rods used at facility
WHITED, P J. Affiliation Unknown 83/03/23 FELTON, J M Division of Rules and Records. 1p 18541·005 24X Fiche 50-320, 83/03/23, 8305200101.

8305230005 FOIA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp
SHOLLY, S.C Union of Concerned Scientists FIN B-6178
NRC-19-82-493 83/03/11 FELTON, J.M Division of Rules and Records 1p. 18546.262

8305230028 Responds to FOIA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp. Forwards App A documents
FELTON, J M Division of Rules and Records FIN B-6178.
NRC-19-82-493 83/03/31 SHOLLY, S C. Union of Concerned Scientists. 2pp. 18546 263

--8305230039 Comments on NUREG-0880, "Safety Goals for Nuclear Power Plants. Discussion Paper," Feb 1982 Proposed policy does not contain independent numerical guideline for early fatality societal risk.
LEVINE, S NUS Corp CQ-SL-28-82 82/05/26. REMICK, F. J. Office of Policy Evaluations. 9pp. 18546:265.

--8305230047 Advises that S Levine directed to provide followup discussion & advice on safety goals re 820526 written rept & 820715 meeting w/F Remick providing advice on use of PRA, per Article I of Contract NRC-19-82-493
MONTGOMERY, J M. Office of Policy Evaluations NRC-19-82-493 82/07/19. Office of Policy Evaluations. 1p. 18546:274.

--8305230057 Forwards matl from Q Kaiser re calculation of individual & societal risks for comparison w/safety goals Requests meeting w/Q Kaiser & R Bland to discuss differences in predictions of weighted individual risk requested
LEVINE, S NUS Corp. CQ-SL-98-82 82/11/18. ZERBE, J.E. Office of Policy Evaluations. 28pp. 18546.275.

8305230059 FOIA request for SECY-82-13D.
PEDRO, J NUS Corp. CD-LIB-8992. 83/02/28 Division of Rules and Records. 1p 18543 136.

8305230065 Responds to FOIA request for SECY-82-13D Forwards requested document Document also available in PDR
FELTON, J M Division of Rules and Records 83/03/31 PEDRO, J NUS Corp 1p 18543 137

--8305230070 SECY-82-013D
Informs Commission of status of implementation of 10CFR50 4B & App R to 10CFR50 re fire protection rule for Third Quarter 1982, per SJ Chilk 801103 request
DIRCKS, W J Office of the Executive Director for Operations 82/12/10 9pp 18543 138

8305230112 Final response to FOIA request for insp repts of safety violations at Kerr-McGee Pu plant at Cresant, OK from Aug-Nov 1972 Forwards JF Donahue 731102 memo transmitting IE Investigation Rept 70-1193/73-01 w/portions deleted
FELTON, J M Division of Rules and Records 83/03/22 WIDMER, R R Affiliation Unknown 1p 18543 154

--8305230134 Forwards Regulatory Investigation Rept 70-1193/73-01 on 730917-21 No significant health & safety problems associated w/occurrences reported in allegations
DONAHUE, J F Atomic Energy Commission 73/11/02 FIORELLI, G Atomic Energy Commission 4pp 18543 155

--8305230139 Regulatory Investigation Rept 70-1193/73-01 on 730917-21 Major area investigated anonymous allegations re leaks in Pu waste drums & unsafe practices Info re personnel interviews deleted
DONAHUE, J F, FINN, J A, RIDGWAY, K R Atomic Energy Commission 73/11/01 18pp 18543 159

--8305230179 Discusses licensee employee allegations re spills of Pu & leaking tanks Facility insp w/emphasis on incidents, spills, decontamination & personnel exposures scheduled for 730917
DONAHUE, J F Atomic Energy Commission 73/09/04 Atomic Energy Commission 4pp 18543 177

--8305230186 Updates 730904 memo re licensee employee allegations concerning unsafe working conditions due to possible contamination of work sites Related news articles & press release encl
DONAHUE, J F. Atomic Energy Commission 73/09/13 Atomic Energy Commission 10pp 18543 181

--8305230196 Rev 1 to Pu Plant Std Operating Procedure KM-NP-37-2, "Liquid Waste Solidification " Related info encl
MULKIN, R Kerr-McGee Nuclear Corp 72/05/02 31pp 18543 191

--8305230207 Forwards Region IV 660729 memo re facility closeout survey results Licensee measurements in 660609 ltr substantiated by Region IV findings
ROY, Q W. Atomic Energy Commission 66/08/08 NUSSBAUMER, D A Atomic Energy Commission 1p 18543 222

--8305230222 Discusses closeout insp of Licenses SMB-664 & SNM-695 on 660706 Recommends that licensee be authorized to transfer control of facilities to unlicensed recipient.
WALKER, D L. Atomic Energy Commission 66/07/29 DUBINSKI, L Atomic Energy Commission 4pp 18543.223

--8305230233 Requests authorization to release vacated facilities at Cushing, OK to refining div for unrestricted use Bldgs used by nuclear products dept cleaned & decontaminated Health physics survey indicates contamination below limits
WOLLER, O B Kerr-McGee Nuclear Corp 66/06/09 NUSSBAUMER, D A Atomic Energy Commission 4pp 18543 227

8305230203 FOIA request for NRC Investigation Rept 1-83-003
GORELICK, M S Steinberg, Greenstein, Gorelick, Price & Lavecon 83/03/25 CHRISTOPHER, K Office of Investigation 1p 18543 307

8305230215 Responds to FOIA request for NRC Investigation Rept 1-83-003 Rept withheld (ref FOIA Exemptions 5 & 7)
FELTON, J M Division of Rules and Records 83/05/02 GORELICK, M S Steinberg, Greenstein, Gorelick, Price & Lavecon 1p 18543·308

8305230220 FOIA request for names & addresses of outside law firms which have performed legal svc for NRC during past 3 yrs involving Title VII or similar employment discrimation matters, i e age or handicap
SIMPSON, G H Simpson, G.H. 83/03/29 Office of Administration 1p 18543 343

8305230223 Responds to FOIA request for names & addresses of outside law firms which have performed legal svcs for NRC during past 3 yrs involving Title VII or similar employment discrimation matters No records subj to request available
FELTON, J M Division of Rules and Records 83/04/25 SIMPSON, G H Simpson, G H. 1p 18543·344.

8305230229 FOIA request for three categories of documents
PUNTENNEY, J Safe Energy Coalition 83/02/14 Division of Rules and Records 1p 18543 309

8305230232 Partial response to FOIA request for three categories of documents Forwards App A documents Document 3 sent to NRC by State of VT & approved for release by DOT Review of addl documents in progress
FELTON, J M Division of Rules and Records 83/03/21 PUNTENNEY, J Safe Energy Coalition 3pp 18543 310

--8305230234 FR Notice, Vol 47, Number 78 from Research & Special Programs Administration Related news articles & ltr from State of VT to DOT secretary encl
* Transportation, Dept of 82/04/22 30pp 18543 313

8305230243 FOIA request for documents re meeting between representatives of ASEA-ATOM (Sweden) & NRC concerning Process Inherent Ultimate Safety Reactor
SHOLLY, S C Union of Concerned Scientists 83/04/13 FELTON, J M Division of Rules and Records 1p 18545 263

8305230246 Partial response to FOIA request for documents re meeting between representatives of ASEA-ATOM (Sweden) & NRC concerning Process Inherent Ultimate Safety Reactor Forwards App A documents Documents also in PDR
FELTON, J M Division of Rules and Records 83/04/28 SHOLLY, S C Union of Concerned Scientists 2pp 18545 264

--8305230251 Notifies that K Hanner: of ASEA-ATOM (Sweden) has offered to present seminar on 830328 to interested staff re proposed super safe LWR concept called Process Inherent Ultimate Safety (PIUS) reactor List of participants encl
LAFLEUR, J D Director's Office, Office of Inspection and Enforcement 83/03/02 GARNER, D , ABBOTT, E , CORNELL, K NRC - No Detailed Affiliation Given 2pp 18545 266

--8305230254 Draft of "Toward Intrinsically Safe LWRs "
HANNERZ, K Oak Ridge Associated Univ 82/06/04 82pp 18545 268

8305240087 Addl response to FOIA request for draft insp evaluation repts & comments on J Keppler 820719 ltr re special safety insp of Facility during May-Jul 1982 Forwards App C documents
FELTON, J M Division of Rules and Records 83/03/31. GARDE, B Government Accountability Project 2pp 18593 015 24X Fiche 50-373, 83/03/31, 8305240087

--8305240098 Five draft summaries of affidavits & statements, draft comments on followup of allegations; minutes of Region III 820329, 0419, 0503 & 0706 staff meetings & draft investigation schedule. Personally identifiable info deleted
* NRC - No Detailed Affiliation Given 83/03/25 36pp 18593 018 24X Fiche 50-373, 83/03/31, 8305240087.

--8305240125 Discusses actions planned during addl insp to resolve concerns re adequacy of workmanship during const of masonry walls R Lipinski assistance requested to resolve issues starting wk of 820815
SPESSARD, R L Division of Project & Resident Programs. 82/08/17 EISENHUT, D G Division of Licensing 2pp 18593 034 24X Fiche 50-373, 83/03/31, 8305240087

--8305250144 Recommends unescorted access to protected areas for R Lipinski & S Chan Rapifac sheet transmitting evaluation of technical rept, "Assessment of Effects of Nicked Reinforcing Steel," encl
KEPPLER, J G Region 3, Office of Director 82/06/14 REED, C Commonwealth Edison Co 7pp 18593 056 24X Fiche 50-373, 83/03/31, 8305240087

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J M Division of Rules and Records 1p 18593 178 24X Fiche 50-000, 83/03/11, 8305240249

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress
FELTON, J M Division of Rules and Records. 83/03/31 SHOLLY, S C Union of Concerned Scientists. 2pp. 18593 179 24X Fiche 50-000, 83/03/31, 8305240254

--8103300276 Comments on draft "Reactor Safety Study Methodology Applications Program Results for Grand Gulf 1 BWR Power Plant " Omissions & simplifications overstate risk of facility operation
HODGES, W Reactor Systems Branch 81/03/24 CURRY, J Office of Nuclear Regulatory Research, Director 3pp 18593 252 24X Fiche 50-000, 83/03/31, 8305240254

--8305240259 Forwards comments on draft rept re Reactor Safety Study Methodology Applications Program for facility Changes indicated in areas of validity of sys criteria & correctness & appropiateness of assumptions in sys analysis
PARKER, W O Duke Power Co 004022 80/09/22 BERNERO, R Probabilistic Analysis Staff (Pre 801119) 11pp 18593 181 24X Fiche 50-000, 83/03/31, 8305240254

--8305240260 Forwards util comments on Reactor Safety Study Methodology Applications Program results Risks associated w/BWR/6 plant design misrepresented
CESARE, G NRC - No Detailed Affiliation Given 81/02/17 CURRY, J NRC - No Detailed Affiliation Given 5pp 18593 195 24X Fiche 50-000, 83/03/31, 8305240254

--8305240265 Discusses concerns re Reactor Safety Study Methodology Applications Program (RSSMAP) evaluation conducted by Sandia Natl Labs Excessively conservative calculations used Related correspondence encl
DALE, L F Mississippi Power & Light Co AECM-81/184. 81/01/23 BERNERO, R M Office of Nuclear Regulatory Research, Director 49pp 18593 200 24X Fiche 50-000, 83/03/31, 8305240254

--8305240269 Forwards comments & corrections to Reactor Safety Study Methodology Applications Program (RSSMAP) analysis If rept is to be published, clear statement of program assumptions & limitations should be included
TIERNAN, J A Baltimore Gas & Electric Co 82/03/05 BURDICK, G. R. Office of Nuclear Regulatory Research, Director. 35pp 18593 255 24X Fiche 50-000, 83/03/31, 8305240254

8305240355 FOIA request for RFP EDO-83-436, "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements "
NEWMAN, K A Debevoise & Liberman 83/03/24 FELTON, J M. Division of Rules and Records 1p 18627 031

8305240365 Responds to FOIA request for RFP EDO-83-436, "Developing Decisionmaking Rationale for Establishing New Regulatory Requirements " Forwards document Document also available in PDR
FELTON, J M Division of Rules and Records 83/03/31. NEWMAN, K. A. Debevoise & Liberman 1p 18627 032.

--8305240369 RFP RS-EDO-83-436, "Developing Decisionmaking Rational for Establishing New Regulatory Requirements." RFP summary proposal submission instructions, no-offer response form & solicitation package encl
MATTIA, M J Administrative Contracts Branch. 83/01/17 67pp 18627 033

8305250025 FOIA request for RFP-RS-80-102 & technical & business sections of winning proposal for NRC Contract NRC-03-80-102
BURKE, S Affiliation Unknown NRC-03-80-102. 83/03/08 Division of Rules and Records 1p 18596, 207

8305250029 Responds to FOIA request for RFP & winning proposal under Contract NRC-03-80-102 Forwards requested document RFP also available in PDR
FELTON, J M. Division of Rules and Records. NRC-03-80-102 83/03/29 BURKE, S. Affiliation Unknown 1p 18596, 208

--8305250034 RS-NRR-80-102
RFP RS-NRR-80-102 for "Energetic Thermal Interactions, Recriticality & Coolant Flow Phenomena Associated w/ Advanced Nuclear Reactor Concepts "
DOUGHERTY, D J. Division of Contracts 79/08/02 48pp 18596 209

--8305250038 NRC Manual Chapter 3202, "Publication of Unclassified Regulatory & Technical Documents Prepared by NRC Contractors Including Repts Prepared Under or Per Interagency Agreements "
* Office of Administration 78/01/25 7pp 18596 257

--8305250043 "Publication of Regulatory & Technical Documents Prepared by NRC Contractors, Including Repts Prepared Under or Per Interagency Agreements "
* Division of Technical Information & Document Control. 78/01/25. 42pp 18596 264

8305260397 Addl response to FOIA request for transcripts of Commission 821028,1108 & 12 meetings re issuance of 821112 show cause order & supporting documentation Forwards App A documents App B documents withheld (ref FOIA Exemption 5)
FELTON,J M Division of Rules and Records 83/03/28 SAMP,R A Shaw, Pittman, Potts & Trowbridge 4pp 18647 294 24X Fiche 50-358,83/03/28,8305260397

--8305260401 Forwards press release,witness list & J Keppler final testimony for 820914 hearing on status of NRC review of const activities at facility
KAMMERER,C Office of Congressional Affairs 82/09/13 PALLADINO,N , GILINSKY,V , AHEARNE,J Commissioners 1p 18647 298 24X Fiche 50-358,83/03/28,8305260397

--8305260405 Testimony of JG Keppler (Region III) before Subcommittee on Energy & Environ of Committee on Interior & Insular Affairs on 830914 re quality confirmation program in Washington,DC
KEPPLER,J G Region 2, Office of Director 82/09/14 62pp 18647 302 24X Fiche 50-358,83/03/28,8305260397

GEN TEC IS GENERIC TECHNICAL ISSUES

8305020345 Summarizes 830425 meeting w/NRC re reactor vessel internals & thermal shield plant recovery program concerning pressurized thermal shock Plant may safely operate w/o restriction from pressurized thermal shock considerations
UHRIG,R E Florida Power & Light Co L-83-263 83/04/27 CLARK,R A Operating Reactors Branch 3 15pp 18274 079 24X Fiche 50-335,83/04/27,8305020345

8305040323 Board Notification 83-057 Forwards differing prof opinions re sys interaction & safety classification Info relates to Board Notifications 83-17 & 83-44 re Unresolved Safety Issue A-17
EISENHUT,D G Division of Licensing 83/05/04 PALLADINO,N Commissioners 22pp 18337 139 24X Fiche 50-000,83/05/04, 8305040323

8305040405 Memorandum & order denying intervenor 830428 oral motion to keep record open on steam tube integrity subissues Record contains sufficient info to make decision re Unresolved Safety Issue A-3
SMITH,I W Atomic Safety and Licensing Board Panel ISSUANCES OL 83/05/03 League of Women Voters of Rockford, IL 2pp 18323 208 24X Fiche 50-454,83/05/03,8305040405

8305040730 Discusses AEOD/E309, "Potential for Water Hammer Damage During Restart of RHR Pumps at BWR Nuclear Power Plants " Recommendations provided do not extend beyond procedural development & operator awareness
HELTEMES,C J Director's Office AEOD/E309 83/04/22 EISENHUT,D Division of Licensing. SPEIS,T Division of Safety Technology 1p. 18328 067 24X Fiche 50-259,83/04/22,8305040730

--8305040737 Forwards AEOD/E309, "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Plants "
RUBIN,S Reactor Operations Analysis Branch AEOD/E309 83/04/21 SEYFRIT,K V Reactor Operations Analysis Branch 1p 18683 319 24X Fiche 50-259,83/04/22,8305040730

--8305040745 "Potential for Water Hammer During Restart of RHR Pumps at BWR Nuclear Power Plants," AEOD engineering evaluation rept
RUBIN,S , LANIK,G Director's Office AEOD/E309 83/04/30 29pp 18328 069 24X Fiche 50-259,83/04/22,8305040730

8305060395 Forwards response to 820923 ltr re open items in NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants " Dynamic load effects,inservice insp & exam frequency reviewed Phase II results expected by 830601
CROUSE,R P Toledo Edison Co 943 83/05/02 STOLZ,J F. Operating Reactors Branch 4 7pp 18343 167 24X Fiche 50-346,83/05/02,8305060395

8305060397 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions." Rept withheld (ref 10CFR2 790)
BAYNE,J P Power Authority of the State of New York IPN-83-32 83/05/03 VARGA,S A Operating Reactors Branch 1 2pp 18348 203 24X Fiche 50-286,83/05/03,8305060397

--8305060407 Forwards proprietary version of "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions " Rept withheld (ref 10CFR2 790)
COTTER,K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 1p. 18348 205 24X Fiche 50-286,83/05/03,8305060397

--8305060417 Submits application for withholding from public disclose, "Fracture Mechanics Analysis of Indian Point,Unit 3 Nuclear Generating Station,Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions "
COTTER,K H Fracture Proof Design Corp 83/04/29 Office of Nuclear Reactor Regulation, Director 4pp 18348 206 24X Fiche 50-286,83/05/03,8305060397

8305090244 Responds to 830329 memo re mgt & technical issues of ATWS events Issues to be addressed in NUREG-1000, "Generic Implications of ATWS Events at Salem Nuclear Power Plant " RHR capability addressed in Unresolved Safety Issue A-45
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/29 EPLER,E P Epler, E P 8pp 18381 084 24X Fiche 50-272,83/04/29,8305090244

8305090568 Forwards direct testimony & affidavits in response to questions posed by ASLB during 830407 telcon
TREBY,S A Hearing Branch 1 83/05/05 BLOCH,P B Atomic Safety and Licensing Board Panel 2pp 18360 001 24X Fiche 50-445,83/05/05,8305090568

--8305090607 Affidavit of FD Coffman on Unresolved Safety Issue A-17, "Sys Interaction in Nuclear Power Plants," per ASLB 830407 telcon request Prof qualifications encl
COFFMAN,F D Reliability & Risk Assessment Branch 83/05/05 9pp 18360 058 24X Fiche 50-445,83/05/05,8305090568

--8305090640 Affidavit of CE Rossi re ASLB 830407 telcon questions concerning status of NRC position on Unresolved Safety Issue A-9, "ATWS " Prof qualifications encl
ROSSI,C E Instrumentation & Control Systems Branch 83/05/05 5pp 18360 083 24X Fiche 50-445,83/05/05,8305090568

--8305090646 Affidavit of AJ Szukiewicz & TG Dunning re ASLB 830407 questions on Unresolved Safety Issue A-47, "Safety Implications of Control Sys " Prof qualifications encl
SZUKIEWICZ,A J Generic Issues Branch DUNNING,T G Instrumentation & Control Systems Branch 83/05/05 9pp 18360 093 24X Fiche 50-445,83/05/05,8305090568

8305100240 Forwards response to Unresolved Safety Issues A-1,A-5,A-11, A-12,A-17,A-40,A-43,A-44,A-45,A-46,A-47,A-48 & A-49 Responses support position that plant can be operated safely until resolution of open items
MILLS,L M Tennessee Valley Authority 83/05/05 ADENSAM,E Licensing Branch 4 26pp 18372 298 24X Fiche 50-438,83/05/05, 8305100240

8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07,NUREG-0612, "Control of Heavy Loads," to confirm & clarify items discussed in 820804 telcon
LIDEN,E A Public Service Electric & Gas Co of New Jersey GL-81-07 83/04/27 VARGA,S A Operating Reactors Branch 1 8pp 24X Fiche 50-272,83/04/27,8305110154

--8305110156 PSE-0108, "Maint Procedures "
* Public Service Electric & Gas Co of New Jersey GL-81-07 83/04/27 1,057pp 18400 001 24X Fiche 50-272,83/04/27, 8305110154

8305110385 Forwards response to open item on safe load paths contained in NRC 820923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREG-0612)
CROUSE,R P Toledo Edison Co 946 83/05/06 STOLZ,J F Operating Reactors Branch 4 11pp 18406 201 24X Fiche 50-346,83/05/06,8305110385

8305110415 Notification of CRGR Meeting 38 on 830518 in Bethesda,MD to discuss proposed rule, "Analysis of Potential Pressurized Thermal Shock Events," prioritization of generic safety issues & operator requalification program Review matl encl
STELLO,V Regional Operations & Generic Requirements 83/05/10 EISENHUT,D G. Office of Nuclear Reactor Regulation, Director JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 18394 221

--8305110423 Forwards draft FR notice & supporting regulatory assessment on proposed rule re pressurized thermal shock CRGR review requested within 2 wks
DENTON,H R. Office of Nuclear Reactor Regulation, Director 83/05/03 STELLO,V Regional Operations & Generic Requirements 36pp 18394 222

8305120325 Forwards response to NUREG-0612, "Control of Heavy Loads " Ack of receipt of matl requested
CRANE,P A Pacific Gas & Electric Co 83/05/09 KNIGHTON,G W Licensing Branch 3 222pp 18432 042 24X Fiche 50-275,83/05/09, 8305120325

8305120520 Summary of 830425 meeting w/util & C-E in Bethesda, MD re thermal shock to reactor pressure vessel w/removal of thermal shield from facility Viewgraphs encl
SELLS, D E Operating Reactors Branch 3 83/05/03 Operating Reactors Branch 3 17pp 18441 341 24X Fiche 50-335, 83/05/03, 8305120520

8305130054 Ack receipt of 821103 ltr re intention to complete Phase II of control of heavy loads issue (NUREG-0612) Final technical evaluation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested
QARRITY, J H Maine Yankee Atomic Power Co MN-83-94 83/05/10
CLARK, R A Operating Reactors Branch 3 2pp 18437 031 24X Fiche, 50-309, 83/05/10, 8305130054

8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "Control of Heavy Loads (C-10), Oconee Nuclear Power Station, Units 1,2 & 3 " Phase 1 actions acceptable per NUREG-0612
STOLZ, J F Operating Reactors Branch 4 83/04/20 TUCKER, H B Duke Power Co 3pp 18457 179 24X Fiche 50-269, 83/04/20, 8305130294

--8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612)
* Office of Nuclear Reactor Regulation, Director 83/04/20 1p 18457 182 24X Fiche 50-269, 83/04/20, 8305130294

--8304070286 TER-C5506-374/375/37
"Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1,2 & 3," technical evaluation rept
ROBERTS, S Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08065 83/03/31 CLEMENSON, F NRC - No Detailed Affiliation Given 28pp 18437 183 24X Fiche 50-269, 83/04/20, 8305130294

8305170118 NUREG-0897 FC
CONTAINMENT EMERGENCY SUMP PERFORMANCE Technical Findings Related To Unresolved Safety Issue A-43
SERKIZ, A W Division of Safety Technology 83/04/30 129pp 18493 007

8305170123 NUREG-0869 FC
USI A-43 RESOLUTION POSITIONS
SERKIZ, A W Division of Safety Technology 83/04/30 74pp 18496 023

8305170596 Requests attendance at 830519 public meeting in Bethesda, MD to exchange info on two aspects of possible ATWS requirements for final ATWS rule, (Generic Issue A-09)
ERNST, M L Division of Risk Analysis 83/04/28 KNUTH, D F KMC, Inc 4pp 18495 024

8305230255 Summarizes info supporting position that postulated pipe breaks in RCS primary loop piping should be eliminated from structural design basis of all Westinghouse plants Testing program per Generic Issue A-2 documented
RAHE, E P Westinghouse Electric Corp NS-EPR-2768 83/05/11
VOLLMER, R H Division of Engineering 2pp 18537 139

8305230276 Forwards "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept Response within 60 days of receipt of ltr requested
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-044 83/05/19 COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 18539 006 24X Fiche 50-213, 83/05/19, 8305230276

--8305230284 TER-C5506-358 DRFT
"Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept
BOMBERGER, C , AHMED, N Franklin Institute/Franklin Research Center NRC-03-81-130 83/02/15 CLEMENSON, F NRC - No Detailed Affiliation Given 35pp 18539 008 24X Fiche 50-213, 83/05/19, 8305230276

8305240516 First set of interrogatories on pressurized thermal shock contention Certificate of Svc encl Related correspondence
LEWIS, M I Lewis, M 83/05/19 Office of the Executive Legal Director 1p 18571, 175 24X Fiche 50-352, 83/05/19, 8305240516

8305250305 Requests info on why resolution of Unresolved Issue A-17 will precede Unresolved Issue A-47 since both items are closely related Response requested by 830517 using std question & answer format
FUNCHES, J L Planning & Program Analysis Staff 83/05/11
SPEIS, T P Division of Safety Technology 2pp 18594 356

--8305250308 Staff requirements memo re 830427 midyr program review on info requested on number of people & dollars necessary to handle Waste Mgt Act as well as questions Chairman Palladino will be addressing by separate memo
CHILK, S J Office of the Secretary of the Commission M830427, 83/05/06 DIRCKS, W J Office of the Executive Director for Operations 3pp 18594 358

8305260290 Commits to resolution of three open items re NUREG-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable
RYBAK, B Commonwealth Edison Co 6611N 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18625 354 24X Fiche 50-237, 83/05/19, 8305260290

8305260294 Forwards response to 830405 draft technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per 830518 telcon
ASH, R E Baltimore Gas & Electric Co 83/05/24 EISENHUT, D G Division of Licensing 2pp 18625 161 24X Fiche 50-317, 83/05/24, 8305260294

8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Westinghouse rept
STEWART, W L Virginia Electric & Power Co 322 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18637 325 24X Fiche 50-338, 83/05/20, 8305270220

8305310240 Requests addl info for control of heavy loads review, including info open items for updated "Control of Heavy Loads "
CLARK, R A Operating Reactors Branch 3 83/05/17 JONES, W. C Omaha Public Power District 2pp 18662 180 24X Fiche 50-285, 83/05/17, 8305310240

--8305310241 TER-C5506-356 DRFT
"Control of Heavy Loads (C-10), Omaha Public Power District, Fort Calhoun Station," updated draft technical evaluation rept
VOSBURY, F , BOMBERGER, C , SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130, TAC 07991 82/11/29
CLEMENSON, F NRC - No Detailed Affiliation Given 52pp 18662 182 24X Fiche 50-285, 83/05/17, 8305310240

I&E INSPECTION AND ENFORCEMENT

8109040024 PND-II-81-052A on 810715, while performing reactor vessel insp w/remote video cameras, loose parts discovered in bottom of vessel Parts identified as missing from internal vessel structures Caused by corrosion fatigue
BRYANT, J C Region 2, Atlanta, Office of the Director (81/03/01) 81/08/07 1p 18326 300 24X Fiche 50-269, 81/08/07, 8109040024

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin Susceptibility to Exothermic Chemical Reaction " Svc list encl
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/03/21 Consolidated Edison Co of New York, Inc. 112pp, 18308 319 24X Fiche 50-000, 83/03/21, 8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/15 Consolidated Edison Co. of New York, Inc 126pp 18435 155 24X Fiche 50-000, 83/04/15, 8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures," Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc 112pp, 18383 089 24X Fiche 50-000, 83/04/22, 8303040023.

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere Sensing Sys " Svc list encl,
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/25 Consolidated Edison Co. of New York, Inc 119pp 18381 291 24X Fiche 50-000, 83/04/25, 8303040025

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of Steam Generators at PWRs," Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/28 Consolidated Edison Co of New York, Inc 115pp 18382 047, 24X Fiche 50-000, 83/04/28, 8303040026

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High Temp Trip Setpoint Adjustment " Svc list encl
JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/28 Consolidated Edison Co of New York, Inc 118pp, 18382 165 24X Fiche, 50-000, 83/04/28, 8303040027,

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve Discharge Line Vacuum Breakers " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/03 Consolidated Edison Co of New York, Inc 122pp 18441 170 24X Fiche 50-000, 83/05/03, 8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events Concerning Deliberate Acts Directed Against Plant Equipment " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 112pp 18382 282 24X Fiche 50-000, 83/05/04, 8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action Recommendations for General Emergencies " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/04 Consolidated Edison Co of New York, Inc 119pp 18441 001 24X Fiche 50-000, 83/05/04, 8303040031.

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack Deformation " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/06 Consolidated Edison Co of New York, Inc 115pp 18523 248 24X Fiche 50-000, 83/05/06, 8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/11 Consolidated Edison Co of New York, Inc 114pp 18524 003 24X Fiche 50-000, 83/05/11, 8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program " Svc list encl
JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/19 Consolidated Edison Co of New York, Inc 114pp 18697 009 24X Fiche 50-000, 83/05/19, 8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of Contaminated Oil " Svc list encl
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 114pp 18647 007 24X Fiche 50-000, 83/05/26, 8303040046

8304110196 PNO-I-83-025, on 830330, only four of five packages containing radioactive matl received by group carrier Missing package contains 330 mCi Xe-133 encased in two lead pipes Search initiated
DENNIS, N , GODY, A. T Region 1, Office of Director 83/04/04 1p 17918 011

8304120582 PNO-IV-83-014A on 830325, worker received apparent 30-40 rem whole body exposure Addl blood studies being conducted but no apparent symptoms observed from exposure Investigation continuing.
EVERETT, R. J Region 4, Office of Director 83/04/07 1p 17929 237

8304280139 PNA-II-81-042 re mailgram sent on or about 810501 by union at Tennessee Nuclear Specialties, Inc to State of TN alleging unsafe working conditions at Jonesboro, TN plant Licensee cited for inadequate controls over airborne U.
WOODRUFF, R. L , GIBBON, A Region 2, Atlanta, Office of the Director (81/03/01). 81/06/11 1p 18621 190

8304280299 PNS-II-80-030 on 801104, bomb threat received from unknown female caller Const site not evacuated State of NC & local law enforcement agencies notified
HALL, B. L , MCGUIRE, D Region 2, Atlanta, Office of the Director 80/11/04 1p 18255 330 24X Fiche 50-400, 80/11/04, 8304280299

8305020183 PNO-V-83-018 on 830421, util received ltr from C-E informing of error in equivalent voltages corresponding to setpoints associated w/steam generator high delta pressure trip function Corrective action being developed
BISHOP, T W Region 5, Office of Director 83/04/25 1p 18277, 295 24X Fiche 50-361, 83/04/25, 8305020183

8305020252 EN-83-028, on 830503, notice of violation & proposed imposition of civil penalty in amount of $10,000 to be issued. Action based on failure to control access into protected & vital areas & unauthorized entry
ROSANO, R. Director's Office, Office of Inspection and Enforcement. 83/04/28. 1p 18277 277 24X Fiche 50-295, 83/04/28, 8305020252

8305020271 PNO-III-83-031A on 830421, piece of solid radioactive matl appearing to be U metal found in unsecured shed behind residence in Waterford, MI. Matl placed in shipping container & sent to Univ of MI for interim storage
SRENIAWSKI, D , MILLER, J. Region 3, Office of Director 83/04/25 1p 18277, 250

8305020337 PNO-I-83-038A on 830427, recirculation loop A riser exam completed One weld in each of two risers had crack indications Data forwarded to GE for more detailed analysis Licensee addressing repair method & impact on outage
BLOUGH, MCCABE, E Region 1, Office of Director 83/04/27 1p 18277 134 24X Fiche 50-278, 83/04/27, 8305020337

8305020459 PNS-I-83-009 on 830427, bomb threat phoned in by unidentified male caller Evacuation initiated Search conducted w/negative findings Normal operations resumed Authorities notified
MADDEN, W , GODY, A T , JOYNER, J H Region 1, Office of Director 83/04/27 1p 18283 310 24X Fiche 50-219, 83/04/27, 8305020459

8305020511 PNO-III-83-032 on 830426, scram circuitry failed to operate properly when mode switch moved from refuel position to shutdown position Caused by three loose wires in rectifier bridge
JORDAN, M , SHAFER, W Region 3, Office of Director 83/04/27 1p 18281 253 24X Fiche 50-331, 83/04/27, 8305020511

8305030094 PNO-I-83-040 on 830428, protesters arrived at north gate Gate closed & access established through south gate No press release planned
CONTE, R , KEIMIG, R Region 1, Office of Director 83/04/28 1p 18300 179 24X Fiche 50-289, 83/04/28, 8305030094

8305030118 PNO-I-83-038 on 830425, three 1-inch long axial indications & one circumferential indication in heat affected zone of recirculation pump riser discovered Caused by intergranular stress corrosion cracking
BLOUGH, MCCABE Region 1, Office of Director 83/04/26 1p 18308 187 24X Fiche 50-278, 83/04/26, 8305030118

8305030256 PNO-II-83-030 on 830428, controlled shutdown begun due to steam generator tube leak which increased from 0 1 to 0 308 gpm Licensee plans to keep plant out of svc for 3 wks to repair leak & conduct eddy current testing
HARDIN, A K , VERRELLI, D M Region 2, Office of Director 83/04/28 1p 18300 038 24X Fiche 50-261, 83/04/28, 8305030256

8305030294 PNS-I-83-008 on 830424, security officer overheard voices from storage trailer in protected area Officers apprehended four contractor employees exiting trailer rear window Search revealed marijuana cigarette Employees suspended
MCKEOWN, L , GODY, A T , JOYNER, J H Region 1, Office of Director 83/04/25 1p 18297 144 24X Fiche 50-286, 83/04/25, 8305030294

8305030313 PNS-V-83-005 on 830426, region dispatched reactive insp team to review findings & status to date of licensee investigation of safety significance of recent vandalism event on 830419 involving gauges in coolant pipe
MCQUEEN, A D , NORDERHAUG, L R Region 5, Office of Director 83/04/27. 1p. 18297 069 24X Fiche 50-275, 83/04/27, 8305030313

8305030374 PNO-II-83-031 on 830429, Unit 1 cancellation announced Caused by lower than anticipated growth in customer demand for power
IGNATONIS, A , DANCE, H C Region 2, Office of Director 83/04/29 2pp 18306 302 24X Fiche 50-491, 83/04/29, 8305030374

8305030405 EN-83-027 on 830503, notice of violation & proposed imposition of civil penalty in amount $40,000 to be issued for licensee failure to perform evaluations to ensure dose stds for workers exposed to radiation not exceeded
FLACK, E , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/04/28 1p 18306 312 24X Fiche 50-250, 83/04/28, 8305030405

8305030450 PNO-I-83-041 on 830425, while closing reactor trip breaker 1B to test newly installed reactor manual trip switches, breaker would not latch in closed position Caused by unattached coil spring at latch mechanism end
LAZARUS, W , KEIMIG, R Region 1, Office of Director 83/04/28 1p 18306, 249 24X Fiche 50-272, 83/04/28, 8305030450

8305030459 PNS-I-83-010 on 830427, Bechtel safety representative received telephone call that bomb located in reactor. Search of reactor bldg conducted w/negative results Police notified No press release planned
MCKEOWN, L , KUSHNER, W , JOYNER, J Region 1, Office of Director 83/04/28 1p 18294 130 24X Fiche 50-354, 83/04/28, 8305030459

8305030468 EN-83-029 on 830505, notice of violation & proposed imposition of civil penalty in amount of $4,000 will be issued Action based on violation re licensee failure to conduct adequate survey, causing employee overexposure
FLACK, E , AXELRAD, J Region 3, Office of Director 83/05/02 1p 18308 245

8305030534 PNO-I-83-039 small fire occurred beneath auxiliary boiler A located in turbine bldg Caused by small amount of oil on concrete pad Fire extinguished using hand extinguisher
CONTE,R , KEIMIG,R Region 1, Office of Director 83/04/26 1p
18308 190 24X Fiche 50-289,83/04/26,8305030534

8305040192 PNA-83-007 on 830303,100 uCi I-125,3 mCi Tl-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town,NY Packages not found Press release may be issued
CAMPBELL,M Region 1, Office of Director 83/04/04 1p
18326 353

8305040201 PNA-83-007A on 830303,100 uCi I-125,3mCi Tl-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town,NY Package of I-125 found on 830315 in home of suspect
CAMPBELL,M Region 1, Office of Director 83/03/15 1p
18326 354

8305040445 PNO-III-83-033 on 830428,contract health physics technician observed w/small vial containing white powdery substance Preliminary test identified substance as cocaine Individual denied access to site
CHRISTOFFER,G , CREED,J , MILLER,J Region 3, Office of Director
83/04/29 1p 18321 299 24X Fiche 50-331,83/04/29,8305040445

8305050189 PNO-I-83-042 on 830428,during packaging of waste,employee ruptured plastic bag & spread Pu-238 contamination in lab Employee clothes & shoes discarded Employee decontaminated Cleanup will start 830502
GLENN,J , KINNEMAN,J Region 1, Office of Director 83/04/29 1p
18342 258

8305050193 PNO-I-83-043 on 830430,Troxler gauge 34-11-B,containing approx 40 mCi Am-241 damaged at const site Caused by accidentally cracking gauge case w/backhoe bucket Wipes taken & analyzed Gauge shipped to manufacturer for repair
LADUN,R , KINNEMAN,J Region 1, Office of Director 83/05/02 1p
18337 135

8305060387 PNO-I-83-045 on 830503,shutdown initiated due to containment pressure increase to 0 6 psi & unidentified containment leakage of 5 4 gpm Recirculation pump cooling water leakage noted
MCCABE,E , KEIMIG,R Region 1, Office of Director 83/05/03 1p
18343 165 24X Fiche 50-277,83/05/03,8305060387

8305060530 PNO-I-83-044 on 830503,effect of continued feedwater flow due to failed open feedwater regulating valve incorporated per addl questions re licensee response to IE Bulletin 80-04, "Analysis of PWR Main Steam Line Break "
ARCHITZEL, MCCABE Region 1, Office of Director IEB-80-04
83/05/03 1p 18347 292 24X Fiche 50-317,83/05/03,8305060530

8305060558 PNO-I-83-045A on 830503,drywell entry identified packing leak on recirculation pump discharge header cross connect motor operated valve MO-65A Cause not stated Region I will respond to media inquiries
MCCABE, KEIMIG Region 1, Office of Director 83/05/04 1p
18348 262 24X Fiche 50-277,83/05/04,8305060558

8305060580 PNO-V-83-019 on 830502,6 5 Richter scale earthquake occurred approx 85 miles from facility No damage identified Strong motion seismic recorder not actuated Media interest expected
KIRSCH,D F Region 5, Office of Director 83/05/03 1p
18349 057 24X Fiche 50-275,83/05/03,8305060580

8305090184 EN-83-031 on 830510,notice of violation & proposed imposition of civil penalties in amount of $40,000 will be issued to util Action based on Tech Spec limiting condition for operation violation re secondary containment integrity
BARBER,G , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/05/05 1p 18364 001 24X Fiche 50-271,83/05/05,
8305090184

8305090224 EN-83-030 on 830509,notice of violation & proposed imposition of civil penalty in amount of $40,000 issued to licensee Action based on serious weaknesses in internal & external dose monitoring & procedural compliance
FLACK,E , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/05/04 1p 18363 349 24X Fiche 50-280,83/05/04,
8305090224

8305090397 EN-83-032 on 830505,notice of violation & proposed imposition of civil penalties in amount of $850,000 to be issued Action based on violation of Tech Spec requirements re reactor trip breaker failure
KLINGLER,G , AXELRAD,J Director's Office, Office of Inspection and Enforcement 83/05/05 1p. 18363 359 24X Fiche 50-272,83/05/05,
8305090397

8305100004 PNS-I-83-011 on 830504,security officer received bomb threat on inside plant telephone line from male caller Search initiated No bomb found Call considered hoax
MCKEOWN, GODY, JOYNER Region 1, Office of Director 83/05/04 1p
18377 251 24X Fiche 50-272,83/05/04,8305100004

8305100094 PNS-V-83-006 on 830504,article in Tri-City Herald erroneously quoted util spokesman J Britton as saying 1,700 or 1,800 craft workers will be asked to take vacations during 830705-15 or be laid off Util will clarify
MORTENSEN,W P , NORDERHAUG,L R Region 5, Office of Director
83/05/05 1p 18377 261 24X Fiche 50-513,83/05/05,8305100094

8305100098 PNO-II-83-034 on 830504,licensee issued news release re inoperability of two auxiliary feedwater pumps on 830419 Caused by valves inadvertently closed on 830414
JULIAN,C A , LEWIS,R C Region 2, Office of Director 83/05/05
2pp 18377 255 24X Fiche 50-250,83/05/05,8305100098

8305100258 PNO-I-83-046 on 830428,diesel generator 1C tripped off bus during 1 h test Caused by biofouling in svc water sys Licensee plans comprehensive program of svc water sys chlorination & insp to evaluate extent of biofouling
NORRHOLM,L , TRIPP,L , KEIMIG,R Region 1, Office of Director
83/05/04 2pp 18373 317 24X Fiche 50-272,83/05/04,8305100258

8305110258 PNO-I-83-047 on 830504,contractor employee entered roped-off area for radiographic exams of pipe welds & received approx 40 mrem dose No overexposure identified Industrial radiography suspended pending completion of evaluation
MCCANN, MCCABE Region 1, Office of Director 83/05/05 1p
18393 290 24X Fiche 50-388,83/05/05,8305110258

8305110262 PNO-II-83-036 on 830508,unit achieved initial criticality w/o incident Actual parameters in close agreement w/ predicted conditions
NEJFELT,G M , IGNATONIS,A Region 2, Office of Director 83/05/09
1p 18393 158 24X Fiche 50-370,83/05/09,8305110262

8305110299 PNO-I-83-048 on 830429,potential nonconformance identified in conduct of nondestructive evaluation on approx 2,400 safety & nonsafety-related welds,involving procedural violations during magnetic particle exam
CERNE,A , GALLO,R Region 1, Office of Director 83/05/06 1p
18393 333 24X Fiche 50-443,83/05/06,8305110299

8305110399 PNO-II-83-035 on 830507,fire detected in circuitry of one of three component cooling water pumps Licensee declared alert Caused by faulty relay Relay replaced & pump restored to operability
BUTCHER,R C , CANTRELL,F S Region 2, Office of Director 83/05/09
1p 18406 189 24X Fiche 50-395,83/05/09,8305110399

8305110439 PNS-I-83-012 on 830505,licensee informed Region 1 that contract health physics employee of Inst for Resource Mgt arrested on suspected multiple federal drug-related charges Individual access to site voided as of 830505
MCKEOWN, BAILEY, GODY Region 1, Office of Director 83/05/05 1p.
18405 087 24X Fiche 50-286,83/05/05,8305110439

8305120412 PNO-I-83-045B on 830503,ultrasonic testing conducted on Sample 2 recirculation riser welds & one RHR weld on Unit 2 to determine if Unit 3 crack indications exist on Unit 2 RHR showed cracks on both pipe & elbow side
BLOUGH, MCCABE Region 1, Office of Director 83/05/09 1p
18431 153 24X Fiche 50-277,83/05/09,8305120412

8305120434 PNS-I-83-013 on 830502,Lower Alloways Creek,NJ,police dept informed licensee of planned,peaceful demonstration to protest facility restart scheduled for 830508 No press release planned
MCKEOWN,L , GODY,A T , JOYNER,J Region 1, Office of Director
83/05/06 1p 18431 131 24X Fiche 50-272,83/05/06,8305120434.

8305130138 PNO-II-83-032 on 830501,contractor employee suffered broken arm,fractured pelvis & possible skull fracture in machine shop accident Caused by cotton glove caught by valve stem pulling person into lathe w/contaminated valve
ROGGE,J F , DANCE,H C Region 2, Office of Director 83/05/02
2pp 18437 277 24X Fiche 50-321,83/05/02,8305130138

8305130142 PNO-II-83-038 on 830510,safety injection pumps inadvertently actuated during heatup in preparation for restart Caused by loss of vital dc electrical bus Damaged batteries replaced
JENISON,K M , JULIAN,C.A. Region 2, Office of Director. 83/05/10
1p 18438 131 24X Fiche 50-280,83/05/10,8305130142

8305130165 PNO-III-83-034A on 830507,insp performed at refinery facility due to damage caused by fire on 830507 Radiation survey performed on nuclear gauge involved in fire determined gauge intact w/shutter remaining open
WIEDEMAN,D , MILLER,J Region 3, Office of Director 83/05/10 1p
18438 115

8305130173 PNO-II-83-037 on 830510, unusual event declared per emergency plan after ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by electric motor & backup blower
CORYELL, G P , GIBSON, A F Region 2, Office of Director 83/05/10
1p 18437 205

8305130186 PNO-II-83-033 on 830501, inadvertent safety injection occurred Caused by spurious signal during tests of steam generator D. Low power OL received on 830303 & initial criticality planned during wk
NEJFELT, G. , IGNATONIS, A Region 2, Office of Director 83/05/02
1p 18440 049 24X Fiche 50-370, 83/05/02, 8305130186

8305130187 PNO-V-83-022 on 830509, while performing addl ultrasonic exams, RCS piping in area of one weld determined less than min wall thickness specified by code Caused by welds being ground smooth during original preservice exam
KIRSCH, D F Region 5, Office of Director 83/05/11 1p
18439 347 24X Fiche 50-275, 83/05/11, 8305130187

8305160009 PNO-V-83-021 on 830429, leak discovered in component cooling water piping sys Caused by potentially inadequate welds in pipe spool Visual insp & NDE to be performed to verify weld integrity
KIRSCH, D F Region 5, Office of Director 83/05/10 1p
18456 081 24X Fiche 50-275, 83/05/10, 8305160009

8305170559 PNO-III-83-034 two nuclear gauges, containing 150 mCi Cs-137 & 300 mCi Cs-137, involved in facility fire. Cause of fire not stated No evidence of contamination found
WIEDEMAN, D , MILLER, J Region 3, Office of Director 83/05/09 1p
18468 159

8305190072 PNO-I-83-051 on 830516, vehicle ran stop sign & struck licensee-owned van carrying radioactive matl Package not damaged & no contamination found Package returned to site for repackaging.
THOMAS, CONNER Region 1, Office of Director 83/05/16 1p
18502 068 24X Fiche 50-219, 83/05/16, 8305190072

8305190079 EN-83-034 on 830520, notice of violation & proposed imposition of civil penalty in amount of $40,000 to be issued Action based on violation re operating reactor w/one train of HPSI incapable of automatically starting
BARBER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/17 1p 18502 069 24X Fiche 50-309, 83/05/17, 8305190079

8305190161 PNO-III-83-036 bioassays & in vivo count of licensee worker indicated potential thorium uptake Cause unknown No potential exposure sources identified Addl medical tests scheduled for 830516
GREGER, L R. , MILLER, D E , PAPERIELLO, C J Region 3, Office of Director 83/05/13 1p 18502 238

8305190233 PNO-III-83-035, on 830511, licensee stopped work on new installation of pipe-whip restraints on safety-related piping per 830513 confirmatory action ltr Restraints installed w/o adequate procedures or QC insp program
DANIELSON, D H , LITTLE, W B Region 3, Office of Director 83/05/13
1p. 18501 318 24X Fiche 50-454, 83/05/13, 8305190233

8305190336 PNO-I-83-050 on 830513, 100 gallons of contaminated water discharged from auxiliary bldg sump onto ground between auxiliary & fuel handling bldgs Cause under investigation No offsite release occurred Contaminated soil removed.
BUMMERS, R , TRIPP, L Region 1, Office of Director 83/05/13 1p.
18500 233 24X Fiche 50-272, 83/05/13, 8305190336

8305200344 PNO-IV-83-019 on 830517, indications of intergranular stress corrosion cracking in heat-affected zone of welds in RCS identified Data forwarded to GE for detailed analysis. RCS loops inspected
DUBOIS, D , WESTERMAN, T F Region 4, Office of Director IEB-83-02
83/05/17 1p 18516 233 24X Fiche 50-298, 83/05/17, 8305200344

8305200430 PNO-II-83-040 on 830515, two util employees & one former employee arrested for cocaine & marijuana possession Arrest occurred offsite Employees not involved in licensed operator activities.
LANDIS, K D , DANCE, H. C Region 2, Office of Director 83/05/17,
1p 18517 150 24X Fiche 50-335, 83/05/17, 8305200430

8305200497 PNO-I-83-049 all licensee commitments required for restart completed Actions to assess & mitigate svc water biofouling in support of plant heatup anticipated to occur on 830518 completed
NORRHOLM, L , COLLINS, S Region 1, Office of Director 83/05/17
1p 18514 032 24X Fiche 50-272, 82/05/17, 8305200497

8305200588 PNO-II-83-039 two intergranular stress corrosion cracks found on recirculation line end cap weld Cracks found during ultrasonic insp per IE Bulletin 83-02 Further weld insps planned
BLAKE, J J , BUTCHER, R C Region 2, Office of Director IEB-83-02
83/05/16 1p 18514 247 24X Fiche 50-259, 83/05/16, 8305200588

8305240002 PNO-III-83-037 on 830509, Region III radiation specialist learned that main steam line noble gas monitors not yet installed per 830314 commitment date Ofc of Investigation investigating failure Monitors to be installed by mid June
LOVENDALE, P , PAPERIELLO, C Region 3, Office of Director 83/05/18
1p 18549 138 24X Fiche 50-266, 83/05/18, 8305240002

8305240439 EN-83-035 on 830520, notice of violation & proposed imposition of civil penalties in amount of $4,000 issued to licensee Action based on one violation involving falsification of radiation survey records
KLINGLER, G , AXELRAD, J Director's Office, Office of Inspection and Enforcement 83/05/20 1p 18572 337

8305250238 PNO-I-83-052 on 830520, plant went critical for first time since 830225 Reactor startup & required reactor trip breaker testing completed within 24 h Power ascension to 100% expected over next several days
NORRHOLM, L , JACOBS, R , GREENMAN, E Region 1, Office of Director
83/05/23 1p 18592 358 24X Fiche 50-272, 83/05/23, 8305250238

8305250537 PNO-II-83-041 on 830520, unusual event declared 1 h after process ventilation sys stopped operating in bldg where high enriched U recovered from scrap Caused by failure of electric motor Employees evacuated No contamination noted
KAHLE, J B , GIBSON, A F Region 2, Office of Director 83/05/20
1p 18588 226

8305260314 PNO-III-83-038 on 830519, reactor placed in hot shutdown to investigate & repair steam leak in drain line between moisture separator & preheater in nonsafety-related turbine sys Addl steam leak found in turbine control valve flange.
WALKER, R D , SHAFER, W D Region 3, Office of Director 83/05/20
1p 18625 198 24X Fiche 50-263, 83/05/20, 8305260314

8305270115 PNS-V-83-007 on 830520, while performing security duties, upon approaching truck being offloaded, security officer observed individual throwing article into cab Investigation revealed cocaine in small glass container Police notified
SCHAEFER, D. W , NORDERHAUG, L R Region 5, Office of Director
83/05/23 1p 18638 165 24X Fiche 50-312, 83/05/23, 8305270115

8305270152 PNO-III-83-039 on 830323, util employee entered protected area through open & unmonitored entrance to receive whole body count Individual escorted out of area Region III will investigate.
CREED, J , HIND, J Region 3, Office of Director 83/05/23 1p
18638 159 24X Fiche 50-255, 83/05/23, 8305270152

8305310174 PNO-II-83-042 on 830521, employee injured while pressurizing inflatable, bladder-like pipe plug Rupture of bladder caused employee left hand to hit adjacent piping resulting in cuts & broken bones Hand decontaminated
IGNATONIS, A , GIBSON, A F Region 2, Office of Director 83/05/23
2pp 18652 297 24X Fiche 50-369, 83/05/23, 8305310174

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

8305020342 Submits requested info re generic QA problems in equipment qualification industry Problems include failure of organizations to include 10CFR50, App B & Part 21 requirements in purchase orders or contracts.
BANGART, R L Division of Vendor & Technical Programs 83/04/22
TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 3pp 18277 073

8305030704 Forwards comments on NRC reliability program plan repts per 830210 request Foreign experience in reliability programs should be considered
IPPOLITO, T A Operating Reactors Assessment Branch 83/04/18
THADANI, A C Reliability & Risk Assessment Branch. 2pp 18309 109

8305040596 "Performance Tests of Commercial Personnel Monitoring Svcs," 740725-750125
NICHOLS, L L , NEWTON, C E. Commerce, Dept of, National Bureau of Standards NICHOLS, L L Battelle Memorial Institute, Pacific Northwest Laboratory. 75/01/25 18pp 18336 080

---8011180782 BNWL-2159
"Test of Performance of Personnel Dosimeters "
NICHOLS, L L Battelle Memorial Institute, Pacific Northwest Laboratory. NRC-I 77/04/30 37pp 18336 099

8305090204 Responds to 830324 memo requesting assistance in updating safeguards program plan for FY83-89 Standardization & Special Projects Branch responsible for interface w/NMSS on reactor safeguards matters
EISENHUT,D G Division of Licensing 83/04/21 BURNETT,R F Division of Safeguards 2pp 18381 111

8305090279 Responds to 830304 invitation to attend Natl Organization of Test Research & Training Reactors 831020-21 meetings WJ Dircks & V Stello unable to attend due to prior commitments, however,H Denton,Director of NRR,will attend
DIRCKS,W J Office of the Executive Director for Operations 83/05/02 CLARK,L Massachusetts Institute of Technology 3pp 18381 071

--8305090290 Requests designation of appropriate NRR personnel to attend & prepare response to L Clark invitation to attend Natl Organization of Test Research & Training Reactors annual meeting on 831020-21 in Cambridge,MA
DIRCKS,W Office of the Executive Director for Operations 83/04/11 DENTON,H Office of Nuclear Reactor Regulation, Director 1p 18381 073

--8305090315 Extends invitation to attend Natl Organization of Test Research & Training Reactors 831020-21 annual meeting at MIT Agenda for Oct 1982 meeting & list of attendees encl as indication of program format & content
CLARK,L Massachusetts Institute of Technology 83/03/04 DIRCKS,W Office of the Executive Director for Operations 10pp 18381 074

8305090295 Concurs in 830329 statement of work re development of data base for 10CFR50 55(e) & Part 21 deficiency reporting
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/22 HELTEMES,C J Director's Office 2pp 18381 241

--8304140328 Requests comments on development of data base for managing & analyzing info reported under 10CFR21 & 10CFR50 55(e) Data could provide info re capability to determine similarities or trends in reported deficiencies
HELTEMES,C J Director's Office 83/03/29 NRC - No Detailed Affiliation Given 3pp 18381 243

8305120607 Forwards documentation re LERs on reactor trip breaker failures between 800101 & 830222,per 830329 request Many trip breaker failures unreported when occurring during modes when operability not required by Tech Specs
DENTON,H Office of Nuclear Reactor Regulation, Director. 83/04/28 HELTEMES,C J Director's Office 2pp 18440 127

--8212070092 Discusses review of LER failure data for reactor protection sys electrical & mechanical components No basis found to support industry intuitive guess that ratio of electrical to mechanical failures is 10 to 1
KENDALL,R Instrumentation & Control Systems Branch 82/11/17 PYATT,D W Reactor Risk Branch 55pp 18440 129

--8305120613 Summary of 820908 operating reactor events meeting
MIRAGLIA,F J Assistant Director for Safety Assessment 82/09/16 EISENHUT,D G Division of Licensing 11pp 18440 185

--8304040591 Requests documentation or other info re reviews or analyses of reactor trip breaker failure repts performed 800101-830222 by 830411
HELTEMES,C J Director's Office 83/03/29 HAYNES,R C Region 1, Office of Director O'REILLY,J P Region 2, Office of Director KEPPLER,J G Region 3, Office of Director 2pp 18440 196

--8304010139 Discusses study of two issues re implications of reactor trip failure on NRC program for collection & analysis of operational experience Preliminary outline for study encl Preliminary draft of study will be sent by 830401
HELTEMES,C J Director's Office 83/03/28 MATTSON,R J Salem Generic Implications Task Force 5pp 18440 198

8305190356 Notifies that JE Glenn will be available for meeting on 830516 to discuss recent application for Co-60 facility,per 830408 request
ALLAN,J M Region 1, Office of Director 83/05/04 CAMPBELL,E Andover Township, NJ 2pp 18500 025

--8305190361 Requests NRC representative attend meeting of planning board & other municipal agencies to discuss proposed Co-60 facility
CAMPBELL,E Affiliation Unknown 83/04/08. HAYNES,R C Region 1, Office of Director. 1p 18500-026

8305230511 Forwards "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand " Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls
HELTEMES,C J Director's Office 83/04/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18541 277

--8305230519 Forwards "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand " Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls
HELTEMES,C J Director's Office 83/04/29 WILKINSON,E P Institute of Nuclear Power Operations 2pp 18541 279

--8305230524 Forwards "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand." Results suggest that training covering associated logic & operation may be appropriate for breakers equipped w/anti-pumping controls
HELTEMES,C J Director's Office 83/04/29 ROBBIN,D Nuclear Safety Analysis Center 1p 18541 281

--8305230531 "Failures of Class IE Safety-Related Switchgear Circuit Breakers to Close on Demand "
CHIRAMAL,M Reactor Operations Analysis Branch. AEOD/C301. 83/04/30 30pp 18576 356

8305250298 Notification of 830517 meeting w/HAFA Intl Corp,American Nuclear Insurance & TECo in Bethesda,MD to discuss application of acoustic emission testing as alternative to volumetric insp method of inservice insp of components
VISSING,G Operating Reactors Branch 4 83/05/09 STOLZ,J Operating Reactors Branch 4 2pp 18594.361

8305260149 Responds to 830413 ltr re deletion of nonradiological water quality-related requirements from OLs NRC Mar 1983 actions consisted of issuance of license amends to delete requirements from OLs for facilities w/NPDES permit
EISENHUT,D G Division of Licensing 83/05/10 DREY,L A Affiliation Unknown 1p 18648 121

--8304180420 Requests description of NRC actions taken in Mar 1983 re deletion of nonradiological water-quality-related requirements from OLs Also requests info re changes made in requirements on radiological releases
DREY,K Affiliation Unknown 83/04/13 Office of Nuclear Reactor Regulation, Director. 1p 18648 122

8305260151 Forwards DOE responses re review of 81C reactor prototype, Windsor Site,for review & comment Reply requested by 830523 since DOE const mods have already begun at site W/o encls
THOMAS,C O Standardization & Special Projects Branch 83/05/11 LEAR,G. Structural & Geotechnical Engineering Branch. 1p. 18648 120

8305260378 Speech entitled "NRC Views on Svc Suppliers Roles, Qualifications & Acceptability," presented at 830519 conference on nuclear svcs business in 1980s in Washington, DC
STELLO,V Regional Operations & Generic Requirements 83/05/19 5pp 18647.251

NUREG NUREG REPORTS AND RELATED CORRESPONDENCE

8303280319 Forwards order confirming licensee commitments on post-TMI-related issues Order based on commitments contained in util responses to NRC Generic Ltrs 82-05 & 82-10
STOLZ,J F Operating Reactors Branch 4. GL-82-05 83/03/14 HANCOCK,J A Florida Power Corp 3pp 17713 234 24X Fiche 50-302,83/03/14,8303280319

--8303280325 Order confirming licensee commitments on post-TMI-related issues
PURPLE,R.A Assistant Director for Licensing 83/03/14. Florida Power Corp. 10pp. 17713 237 24X Fiche 50-302,83/03/14, 8303280319

8304120027 Forwards revised order confirming licensee commitments on post-TMI-related issues,correcting info re implementation schedule for Item II B 3, "Post-Accident Sampling."
STOLZ,J F Operating Reactors Branch 4 83/03/30 BECKHAM,J T Georgia Power Co. 4pp 17957 320 24X Fiche 50-321,83/03/30, 8304120027

--8304120042 Order revising schedule for submittal of info re Item II B.3. "Post-Accident Sampling," from 830401 to 830701
PURPLE,R A. Division of Licensing GL-82-05 83/03/30. Georgia Power Co 10pp 17957 324 24X Fiche 50-321,83/03/30, 8304120027

8304180548 Forwards proprietary WCAP-8200, Rev 1, WCAP-8301, WCAP-8302, WCAP-8821, draft responses to questions on WCAP-10079 & related info re new small break evaluation model per NUREG-0737, Item II K 3 30 Encls withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2746 83/04/12
THOMAS, C O Standardization & Special Projects Branch 2pp
17997.049

8305020066 Forwards SER based on review of NUREG-0737, Item III D 3 4, "Control Room Habitability," submitted in 801219 & 821019 ltrs Control room habitability sys acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-04-074
83/04/29 VANDEWALLE, D J Consumers Power Co 4pp 18276 236
24X Fiche 50-255, 83/04/29, 8305020066

--8207080528 Notifies that control room meets requirements of SRP 2 2 1 - 2.2.2.2 2 3 & 6 4 & General Design Criteria 4 & 19 Conclusions based on present plant sys & presumes implementation of effective HVAC mods by licensee
MURPHY, D W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/24 HULMAN, L G Accident Evaluation Branch 2pp 18276 242 24X Fiche 50-255, 83/04/29, 8305020066

8305020209 Forwards response to NRC 830316 ltr re NUREG-0737, Item II.K.3 13, "RCIC Automatic Restart " RCIC sys modified to relocate signal for high reactor vessel water level trip from RCIC turbine trip valve to steam supply valve.
BAYNE, J.P Power Authority of the State of New York JPN-83-36
83/04/28 VASBALLO, D B Operating Reactors Branch 2 2pp
18278 133 24X Fiche, 50-333, 83/04/28, 8305020209

8305020359 Forwards supplemental response to Generic Ltr 82-28, "Inadequate Core Cooling Instrumentation Sys" & NUREG-0737, Item II F 2, W/one oversize drawing. Aperture card is available in PDR
CAREY, J. J Duquesne Light Co GL-82-28, 83/04/21 VARGA, B A
Operating Reactors Branch 1 22pp 18273 198 24X
Fiche 50-334, 83/04/21, 8305020359

8305020362 Forwards plant-specific responses to six NRC questions re safety/relief valve testing (NUREG-0737 Item II.D 1), per 821217 request Safety/relief valve discharge piping utilizes Y quencher w/sparger at discharge pipe exit
FIEDLER, P B General Public Utilities - GPU Service Corp 83/04/27
CRUTCHFIELD, D Operating Reactors Branch 5 21pp 18274 058 24X
Fiche, 50-219, 83/04/27, 8305020362

8305020383 Confirms 830502 submittal date for proposed solution to three remaining open items on NRC review of upgraded auxiliary feedwater sys per NUREG-0737, Item II E 1 1 Contractor requested to provide cost estimate for study.
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/27
STOLZ, J.F Operating Reactors Branch 4 1p. 18276 313 24X
Fiche: 50-312, 83/04/27, 8305020383

8305020384 Forwards response to 821115 request for addl info re NUREG-0737, Items II E 1 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/11 oversize drawings Aperture cards are available in PDR.
RODRIGUEZ, R J. Sacramento Municipal Utility District 83/04/28
STOLZ, J F Operating Reactors Branch 4 3pp 18283 329 24X
Fiche, 50-312, 83/04/28, 8305020384

--8305020392 BWNP-20004 (4-76) R3
Rev 3 to "Auxiliary Feedwater Sys Sys Description "
* Babcock & Wilcox Co 15-1120580-03 83/04/04 54pp
18283 332 24X Fiche 50-312, 83/04/28, 8305020384

8305020387 Responds to NRC 830203 & 0330 questions re proposed SRP Amend 19. No need exists to arbitrarily increase initial power to account for uncertainty in power level Errata sheet & transient summary of feedwater controller failure encl.
CURTIS, N W. Pennsylvania Power & Light Co PLA-1640 83/04/28
SCHWENCER, A. Licensing Branch 2, 4pp 18276 314 24X
Fiche 50-387, 83/04/28, 8305020387

8305020388 Responds to 830322 request for addl info on instrumentation sys for detection of inadequate core cooling (Generic Ltr 82-28) Installation completed & sys currently being tested. Status of conformance w/NUREG-0737, Item II F 2 encl
SCHUYLER, J D Pacific Gas & Electric Co GL-82-28 83/04/27
EISENHUT, D.G Division of Licensing. 7pp 18276 329 24X
Fiche 50-275, 83/04/27, 8305020388

8305020421 Forwards addl info re emergency plan per 821206 request Info addresses Question B 4 concerning plant personnel response capability during emergency situation per staffing goals in Suppl 1 to NUREG-0737.
KOESTER, G L Kansas Gas & Electric Co KMLNRC 83-051, 83/04/29.
DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp.
18273:100 24X Fiche 50-482, 83/04/29, 8305020421

8305020449 Application to amend License DPR-46, changing Tech Specs to incorporate NUREG-0737 items per 830110 Generic Ltr 83-02
PILANT, J M Nebraska Public Power District GL-83-02 83/04/27
VASBALLO, D B Operating Reactors Branch 2 3pp 18283 173 24X
Fiche 50-298, 83/04/27, 8305020449

--8305020464 Proposed Tech Specs changes re Generic Ltr 83-02 concerning NUREG-0737 items
* Nebraska Public Power District GL-83-02 83/04/27 3pp
18283 176 24X Fiche 50-298, 83/04/27, 8305020449

8305020453 Forwards addl info per NRC 821210 request re Generic Ltr 82-28 concerning inadequate core cooling sys Procurement of reactor vessel level instrumentation sys completed Sys installation 30% complete
EURY, L W Carolina Power & Light Co LAP-83-83 83/04/26
EISENHUT, D G Division of Licensing 2pp 18281 222 24X
Fiche 50-261, 83/04/26, 8305020453

8305020458 Forwards info re NUREG-0737, Item II D 1, "Performance Testing of BWR Safety/Relief Valves," per NRC 830104 request Applicability of load combination info to BWR Owners Group generic test rept acceptable
RYBAK, B Commonwealth Edison Co 6226N 83/04/27 DENTON, H R
Office of Nuclear Reactor Regulation, Director 18pp 18283 311
24X Fiche 50-254, 83/04/27, 8305020458

8305020538 NUREG/CR-2000 V02 N3
LICENSEE EVENT REPORT (LER) COMPILATION For Month Of March 1983
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
83/04/30 Director's Office 122pp 18285 182

8305020547 NUREG/CR-3091
REVIEW OF WASTE PACKAGE VERIFICATION TESTS Semiannual Report Covering The Period April-September 1982
BIDA, G T , EASTWOOD, D , JAIN, H Brookhaven National Laboratory FIN A-3167 BNL-NUREG-51630 83/04/30 Division of Waste Management
147pp Available at NRC $6 00 18285 035

8305020597 Forwards safety evaluation on NUREG-0737, Item II B 2 2, "Plant Shielding Mods for Vital Area Access " Requirements met
VASBALLO, D B Operating Reactors Branch 2 83/04/22 FARRAR, D
Commonwealth Edison Co 5pp 18284 222, 24X Fiche 50-254, 83/04/22, 8305020597

8305030010 Advises that position concerning nonestablishment of backup emergency operations facility (EOF) unacceptable Plans to establish EOF by 830601 must be submitted & must meet NUREG-0737, Suppl 1 (Generic Ltr 82-33) criteria
EISENHUT, D G Division of Licensing. GL-82-23 83/04/25
DIXON, D W South Carolina Electric & Gas Co 3pp 18310 353 24X
Fiche 50-395, 83/04/25, 8305030010

8305030135 Forwards safety evaluation based on review of util submittals re TMI Action Item II B 1, "RCS Vents " Licensee venting capability acceptable.
VASBALLO, D B Operating Reactors Branch 2 83/04/18 BAYNE, J P
Power Authority of the State of New York 4pp 18309 235 24X
Fiche 50-333, 83/04/18, 8305030135

--8303310020 B14/TER-D-7
"Selected Operating Reactor Issues Program II, RCS Vents (NUREG-0737, Item II B 1)," final technical evaluation rept
HELD, J T Energy Incorporated HELD, J T Lawrence Livermore Laboratory FIN A-0250 TAC 44373 83/03/02 ALBERTHAL, G NRC - No Detailed Affiliation Given 4pp 18309 239 24X
Fiche 50-333, 83/04/18, 8305030135

8305030144 Forwards application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (2B)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737, Item III A 1 2 (Generic Ltr 82-33)
CURTIS, N W Pennsylvania Power & Light Co PLA-1634 83/04/29.
SCHWENCER, A Licensing Branch 2, 1p 18306 328 24X
Fiche 50-387, 83/04/29, 8305030144

--8305030153 Application for proposed Amend 23 to License NPF-14, changing License Condition 2 C (2B)(g)(1) to extend completion date for safety parameter display sys to 831230, as part of NUREG-0737, Item III A 1 2
CURTIS, N W. Pennsylvania Power & Light Co. GL-82-33, 83/04/29
2pp 18306 329 24X Fiche: 50-387, 83/04/29, 8305030144

8305030463 Application for amend to Licenses DPR-62 & DPR-71, supplementing 820616 request for miscellaneous Tech Spec revs originally scheduled for completion during 820901 refueling outage. Outage & mods to be completed by 830624
HOWE, P.W Carolina Power & Light Co LAP-83-100 83/04/28.
VASBALLO, D B. Operating Reactors Branch 2 2pp 18308 222 24X
Fiche, 50-324, 83/04/28, 8305030463

--8305030481 Proposed Tech Specs re safety-related hydraulic snubbers, post-accident monitoring instrumentation, gas analyzer sys, reactor coolant leakage detection sys & remote shutdown monitoring instrumentation
* Carolina Power & Light Co 83/04/28 19pp 18308 224 24X
Fiche 50-324, 83/04/28, 8305030463

8305030491 Forwards response to 821210 Generic Ltr 82-28 re inadequate core cooling instrumentation sys, including reactor coolant inventory sys description, conformance summary to NUREG-0737, Item II F 2 & proposed implementation schedule
RANDAZZA, J B Maine Yankee Atomic Power Co GL-82-28 83/04/29
EISENHUT, D G Division of Licensing 34pp 18295 118 24X
Fiche: 50-309, 83/04/29, 8305030491

8305030519 Advises that separate iodine particulate sampling sys installed & temporary mods performed on vent monitoring sys, per NRC 830314 order re NUREG-0737, Item II F 1, Attachment 2 Unit 1 sys operational Unit 2 sys will be completed shortly
ALEXICH, M P American Electric Power Service Corp AEP NRC 0678E
83/04/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18295 326 24X Fiche 50-315, 83/04/29, 8305030519

8305030558 Advises that applicable recommendations contained in B&W Topical Rept BAW-1564, "Integrated Control Sys Reliability Analysis," will be implemented prior to fuel loading to fulfill requirements of NUREG-0737, Item II K 2 9
MILLS, L M Tennessee Valley Authority 83/04/26 ADENSAM, E
Licensing Branch 4 1p 18303 299 24X Fiche 50-438, 83/04/26, 8305030558

8305030588 Forwards response to 830215 request for addl info re NUREG-0737, Item II B 3 re post-accident sampling sys Areas discussed include radiological & chemical analysis capacity & reactor coolant gas analysis
PILANT, M Nebraska Public Power District LQA8300026 83/04/22
VASSALLO, D B Operating Reactors Branch 2 4pp 18305 354. 24X
Fiche: 50-298, 83/04/22, 8305030588

8305030606 Forwards response to Generic Ltr 83-10C re program for resolution of NUREG-0737, Item II. K 3 5, "Automatic Trip of Reactor Coolant Pumps " Pump trip can be achieved safely & reliably by operator, when required
MILLS, L M Tennessee Valley Authority GL-83-10C 83/04/22
ADENSAM, E Licensing Branch 4 8pp 18303 172 24X
Fiche 50-390, 83/04/22, 8305030606

8305030634 Application to amend Licenses DPR-57 & NPF-5, revising Tech Specs re TMI Action Plan Items I A 1 1 3, I A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II K 3 19, II K 3 27, II K 3 45 & II F 1-4
BECKHAM, J T Georgia Power Co NED-83-267 83/04/22 STOLZ, J F.
Operating Reactors Branch 4 8pp 18305 285 24X
Fiche 50-321, 83/04/22, 8305030634

--8305030665 Revised Tech Specs re TMI Action Plan Items I A 1 1 3, I. A 1 3, II E 4 1, II E 4 2 5-7, II K 3 3, II K 3 13, II K 3 22, II K 3 15, II. K 3 19, II K 3 27, II. K 3 45 & II F 1-4
* Georgia Power Co 83/04/22 31pp 18305 293 24X
Fiche 50-321, 83/04/22, 8305030634.

8305040311 Forwards response to 830202 request for addl info re NUREG-0737, Item II F 1 6, "Containment Hydrogen Monitor " Info re water level monitors to be provided by 830615
BAYNE, J P Power Authority of the State of New York JPN-83-38
83/05/02 VASSALLO, D B Operating Reactors Branch 2 3pp
18323-300 24X Fiche 50-333, 83/05/02, 8305040311

8305040317 Responds to NRC request for addl info re TMI action plan items Matl supports util position that nonsafety-related equipment falls outside scope of Franklin Research Ctr review Justification not necessary
LENTINE, F G Commonwealth Edison Co 6491N 83/05/02 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18323 289
24X Fiche 50-295, 83/05/02, 8305040317.

8305040362 Responds to 830217 & 0407 requests for addl info re NUREG-0737, Item II. K 3 17, "ECCS Outages " Info compiled from equipment inoperability record which is completed each shift during cold shutdown
HURFORD, W J Carolina Power & Light Co LAP-83-144 83/04/29
VAROA, S A Operating Reactors Branch 1 4pp 18323 194 24X
Fiche. 50-261, 83/04/29, 8305040362

8305040474 Informs that analysis of aircraft traffic for facility per integrated assessment rept (NUREG-0822) followup acceptable.
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-005
83/05/03 FIEDLER, P B General Public Utilities - GPU Service Corp
2pp. 18319 315 24X Fiche 50-219, 83/05/03, 8305040474

8305040546 Requests remittance of Class III fee for 821110 application re nonconformance w/NUREG-0737, Item II E 4 2 on containment isolation dependability
DIGGS, R M License Fee Management Branch 83/04/27 CURTIS, N W
Pennsylvania Power & Light Co 1p 18351 230 24X
Fiche 50-387, 83/04/27, 8305040546

8305040664 Forwards Suppl 3 to SER (NUREG-0887) W/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/04/27 EDELMAN, M R
Cleveland Electric Illuminating Co 2pp 18336 266 24X
Fiche 50-440, 83/04/27, 8305040664

8305040669 Forwards SER on BWR Owners Group generic response to NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys (ADS) Logic " Response acceptable w/ stipulated conditions Response requested expediently
SCHWENCER, A Licensing Branch 2 83/04/25 CURTIS, N W
Pennsylvania Power & Light Co 10pp 18336 338 24X
Fiche 50-387, 83/04/25, 8305040669

8305040682 NUREG-0827
INTEGRATED PLANT SAFETY ASSESSMENT REPORT, SYSTEMATIC EVALUATION PROGRAM - LACROSSE BOILING WATER REACTOR. Docket No 50-409 (Dairyland Power Cooperative)
* Division of Licensing 83/04/30 494pp 18334 142 24X
Fiche 50-409, 83/04/30, 8305040682

8305040686 Requests responses re relief from surveillance requirements of equipment which would result in excessive exposure Tech Spec change requests, scheduling for recovering affected sys & rev to recovery plan requested
BARRETT, L H TMI Program Office NRC-TMI-83-024 83/04/27
KANGA, B K General Public Utilities - GPU Service Corp 3pp
18336 329 24X Fiche 50-320, 83/04/27, 8305040686

8305040689 NUREG-0040 V07 N01
LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT Data As Of March 31, 1983 (White Book)
* Region 4, Office of Director 83/04/30 284pp 18332 001

8305040693 NUREG-0540 V04 N01
TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE January 1-31, 1983
* Division of Technical Information & Document Control 83/04/30. 577pp 18332 285

8305040740 NUREG/BR-0051 V04 N6
POWER REACTOR EVENTS September-October 1982.
MASSARO, S A , TRENERY, S E Director's Office 83/04/30 35pp
18327 143

8305040769 Forwards safety evaluation & technical evaluation rept re TMI Items I A 2 1 4 "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4 "Training for Mitigating Core Damage " Programs satisfy NUREG-0737 requirements
STOLZ, J F Operating Reactors Branch 4 83/04/20 BECKHAM, J T.
Georgia Power Co 3pp 18327 300 24X Fiche 50-321, 83/04/20, 8305040769

8305050022 Forwards status, description & schedule for meeting requirements re emergency response capabilities, per Generic Ltr 82-33 (Suppl 1 to NUREG-0737)
FIEDLER, P B General Public Utilities - GPU Service Corp GL-82-33
83/04/15 EISENHUT, D G Division of Licensing 17pp. 18342 118
24X Fiche 50-219, 83/04/15, 8305050022

8305050026 Forwards NEDO-22209, "Analysis of Scram Discharge Vol Sys Piping Integrity " No further action planned re equipment qualification & sys design mods identified in generic SER (NUREG-0803)
BAYNE, J P Power Authority of the State of New York JPN-83-39.
83/05/03 VASSALLO, D B. Operating Reactors Branch 2 2pp.
18339 313 24X Fiche: 50-333, 83/05/03, 8305050026

8305050229 Submits progress rept re TMI Items II F. 1 1 & II F. 1. 2 re effluent monitor mods Vendor schedular uncertainties resolved Remaining work consists of training operators, software changes & minor wiring change
COUNSIL, W G Northeast Nuclear Energy Co (subs. of Northeast Utilities). COUNSIL, W G Northeast Utilities B10767. 83/04/29
CRUTCHFIELD, D Operating Reactors Branch 5 2pp. 18338 062 24X
Fiche 50-245, 83/04/29, 8305050229

8305050293 Forwards draft SER of NUREG-0737, Item II. B 3, "Post-Accident Sampling " Eight of 11 criteria met Criterion 2, 10 & 11 incomplete Addl info requested to complete review of PASS sys
VAROA, S. A Operating Reactors Branch 1 83/04/22. UHRIG, R. E.
Florida Power & Light Co 31pp 18352 074. 24X
Fiche: 50-250, 83/04/22, 8305050293

8305050426 NUREG/CR-2001
BWR REFILL-REFLOOD PROGRAM TASK 4 3-SINGLE HEATED BUNDLE
FINAL REPT
SUTHERLAND,W A , BARTON,J E , FINDLAY,J A General Electric Co FIN
B-5877 EPRI NP-2372 83/04/30 Division of Accident Evaluation
83pp Available at NRC $5 50 18352 299

8305050432 NUREG/CR-3140
CONTAINMENT SUMP TEST DATA
SCHMIDT,W H Sandia Laboratories FIN A-1296 SAND82-2985
83/04/30 Division of Safety Technology 73pp Available at NRC
$5 00 18352 229

8305060001 Forwards EG&G summary of discussion re radiological effluent
Tech Specs during 820602-03 plant visit Final draft of
proposed radiological effluent Tech Specs & offsite dose
calculation manual should be developed within 60 days
CLARK,R A Operating Reactors Branch 3 83/04/25 FAY,C W
Wisconsin Electric Power Co 45pp 18353:263 24X
Fiche 50-266,83/04/25,8305060001

--8305060007 NUREG-0472 D07 R03
STANDARD RADIOLOGICAL EFFLUENT TECHNICAL SPECIFICATIONS
FOR PRESSURIZED WATER REACTORS SEPTEMBER 1982
* NRC - No Detailed Affiliation Given PWR-STS-I 82/09/03
83pp. 18353 308. 24X Fiche 50-266,83/04/25,8305060001

8305060017 Forwards SER re util responses to NUREG-0737,Items II F 1 4,
"Containment Pressure Monitor," II F 1 5, "Containment Water
Level Monitor" & II F 1 6, "Containment Hydrogen Monitor,"
Items resolved
CLARK,R A. Operating Reactors Branch 3 83/04/21 STEWART,W L
Virginia Electric & Power Co 8pp 18354:314 24X
Fiche:50-338,83/04/21,8305060017

8305060045 Forwards SER supporting util responses to NUREG-0737,Items
II.F.1.4, "Containment Pressure Monitor," II F 1 5,
"Containment Water Level Monitor" & II F 1 6, "Containment
Hydrogen Monitor " Items resolved
CLARK,R.A. Operating Reactors Branch 3 83/04/21 LUNDVALL,A E
Baltimore Gas & Electric Co 9pp 18354 299 24X
Fiche 50-317,83/04/21,8305060045

8305060108 Advises that requirements of NUREG-0737,TMI Action Plan
Items II.F 1.4,II F 1 5 & II F.1.6 met & items resolved
Criteria requiring equipment to be environmentally qualified
will be reviewed under environ qualification program
CLARK,R.A Operating Reactors Branch 3 83/04/21 MUSOLF,D.M
Northern States Power Co 9pp 18354 268 24X
Fiche:50-282,83/04/21,8305060108

8305060233 NUREG/CR-3136
AQUIFER RESTORATION AT IN-SITU LEACH URANIUM MINES EVIDENCE
FOR NATURAL RESTORATION PROCESSES
DEUTSCH,W J., SERNE,R J , BELL,N E Battelle Memorial Institute,
Pacific Northwest Laboratory FIN B-2379. PNL-4604 83/04/30
Division of Health, Siting & Waste Management. 96pp Available at
NRC $5.50. 18359:001.

8305060306 Requests that portion of 830422 response to Generic Ltr
83-02 be withdrawn.Portion re Item II.F.1, "Addl Accident
Monitoring Instrumentation," will be reevaluated upon
receipt of NRC guidance
GUCWA,L T Georgia Power Co. NED 83-278 83/05/02 STOLZ,J F.
Operating Reactors Branch 4 1p 18344 323 24X
Fiche:50-321,83/05/02,8305060306

8305060329 Responds to New England Coalition on Nuclear Pollution &
State of NH submittals subsequent to 830407-08 prehearing
conference.Objects to word "omission" in reworded
Coalition Contention I D.2
LESSY,R.P. Hearing Branch 3 ISSUANCES OL 83/05/04. HOYT,H ,
LUEBKE,E.A., HARBOUR,J. Atomic Safety and Licensing Board Panel.
4pp. 18344:081. 24X Fiche:50-443,83/05/04,8305060329

8305060347 NUREG/CR-3229
EXPLORATORY ASSESSMENT OF POSTIRRADIATION HEAT TREATMENT
VARIABLES IN NOTCH DUCTILITY RECOVERY OF A533-B STEEL
HAWTHORNE,J.R. Materials Engineering Testing Services, Inc. *
ENSA, Inc FIN B-6133 83/04/30 Office of Nuclear Regulatory
Research, Director 20pp Available at NRC. $3 25 18359.097.

8305060395 Forwards response to 820923 ltr re open items in NUREG-0612,
"Control of Heavy Loads at Nuclear Power Plants " Dynamic
load effects,inservice insp & exam frequency reviewed Phase
II results expected by 830601
CROUSE,R.P Toledo Edison Co 943 83/05/02 STOLZ,J.F
Operating Reactors Branch 4 7pp. 18343 167. 24X
Fiche.50-346,83/05/02,8305060395.

8305060399 Comments on proposed rule re safety goals evaluation plan
Milano Natl Nuclear Regulatory Agency presently involved in
similar but more restrictive task Requests to be kept
informed of proceedings
GARRIBBA,S Instituto di Ingegneria Nucleare, Milan, Italy
49FR10772 83/04/26 Docketing & Services Branch 1p
18343 159

8305060415 Forwards resolution of open items re NUREG-0737,Item II B 3,
"Post-Accident Sampling Sys," per 830215 evaluation &
830314 telcon No significant radiation effects anticipated.
LATHAM,W K Sacramento Municipal Utility District 83/05/02
STOLZ,J F Operating Reactors Branch 4 2pp 18343 279 24X
Fiche 50-312,83/05/02,8305060415

8305060431 Forwards application for amend to License DPR-64,changing
Tech Specs 6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 & Tables
3 6-1 & 4 4-1 to reflect containment isolation valve mods &
NRC & util organizational changes
BAYNE,J P Power Authority of the State of New York IPN-83-34
83/05/03 VARGA,S A Operating Reactors Branch 1 3pp 18351 199
24X Fiche 50-286,83/05/03,8305060431

--8305060432 Application for amend to License DPR-64,changing Tech Specs
6 9 1,6 9 1 4,6 9 1 7,6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1
to reflect containment isolation valve mods & NRC & util
organizational changes
BAYNE,J.P Power Authority of the State of New York 83/05/03
1p 18351 202 24X Fiche 50-286,83/05/03,8305060431

--8305060433 Proposed changes to Tech Specs 6 9 1,6 9 1 4,6.9 1 7,
6 9 1 8,6 9 2 & Tables 3 6-1 & 4 4-1 to reflect containment
isolation valve mods & organizational changes W/one oversize
drawing Aperture card is available in PDR
* Power Authority of the State of New York 83/05/03 13pp
18351 203 24X Fiche 50-286,83/05/03,8305060431

8305060457 Forwards draft responses to NUREG-0737,Items I C 1,I C 6,
I.D 1,1 D 2,I Q 1 & III A 1 2 Responses will be incorporated
into FSAR by June 1983
BRADLEY,E J Philadelphia Electric Co 83/05/04 SCHWENCER,A
Licensing Branch 2 9pp 18351 160 24X Fiche 50-352,83/05/04,
8305060457

8305060562 Forwards SER (NUREG-0979) re application for final design
approval for GESSAR II & FR notice W/o NUREG
THOMAS,C O Standardization & Special Projects Branch 83/04/28
SHERWOOD,G G General Electric Co 2pp 18359 210 24X
Fiche 50-447,83/04/28,8305060562

--8305060568 Notice of availability of SER (NUREG-0979) on proposed final
design approval for GESSAR II
BRINKMAN,D S Standardization & Special Projects Branch.
83/04/28. 1p 18359:212 24X Fiche 50-447,83/04/28,8305060562

8305060645 Advises that Class III fee appropriate for each listed
application filed w/NRR for review Request of 830331 for
exemption from order,confirming commitment to implement
NUREG-0737,not exempt from fees
MILLER,W D License Fee Management Branch 83/05/02
RODRIGUEZ,R.J Sacramento Municipal Utility District 2pp
18358.362. 24X Fiche:50-312,83/05/02,8305060645

8305060658 Forwards safety evaluation re NUREG-0737,Items II F 1 4,
II F 1 5 & II F 1.6 on containment pressure,water level &
hydrogen monitors Util 801210 submittal & 830218 rev
acceptable Environ qualification to be reviewed separately
VARGA,S A Operating Reactors Branch 1 83/04/22 STEWART,W L
Virginia Electric & Power Co 2pp 18357 357 24X
Fiche 50-280,83/04/22,8305060658

--8305060663 Safety evaluation re TMI Action Plan Items (NUREG-0737)
II.F 1 4, "Containment Pressure Monitor," II F 1 5,
"Containment Water Level Monitor" & II.F 1 5, "Containment
Hydrogen Monitor " Designs acceptable.
* Office of Nuclear Reactor Regulation, Director 83/04/22 5pp
18357:359. 24X Fiche:50-280,83/04/22,8305060658

8305060674 NUREG/CR-2924
RADON DIFFUSION IN CANDIDATE SOILS FOR COVERING URANIUM
MILL TAILINGS
SILKER,W B , KALKWARF,D.R Battelle Memorial Institute, Pacific
Northwest Laboratory. FIN B-2269 PNL-4434 83/04/30 Division
of Health, Siting & Waste Management 52pp Available at NRC
$5 00 18358 200.

8305060675 NUREG/CR-2005 R01
CHECKLIST FOR EVALUATING EMERGENCY OPERATING PROCEDURES USED
IN NUCLEAR POWER PLANTS
BRUNE,R L , WEINSTEIN,M HPT, Inc * Sandia Laboratories FIN
B-3098 SAND81-7074 83/04/30 Division of Safeguards &
Inspection Programs (Post 830103) 35pp Available at NRC. $4 50
18358.262

8305060680 NUREG-0485 V05 N03
SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPT Data As Of March 31,1983 (Buff Book)
* Office of Resource Management, Director 83/03/31 63pp
18358 295

8305090013 Forwards SER (NUREG-0968,Suppl 1) including addl info received from applicant & ACRS comments
GRACE,J N Clinch River Breeder Reactor Program Office 83/05/02
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant
32pp 18369 322 24X Fiche 50-537,83/05/02,8305090013

8305090035 NUREG/BR-0006 R01 ER
INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION REPORTS Forms DOE/NRC-741,741A And 740M
* Office of Nuclear Material Safety & Safeguards,Director
83/05/04 1p 18381 199

8305090040 NUREG/BR-0006 R01
INSTRUCTIONS FOR COMPLETING NUCLEAR MATERIAL TRANSACTION REPORTS Forms DOE/NRC-741,741A And 740M
* Office of Nuclear Material Safety & Safeguards,Director.
83/04/30 102pp 18380 276

8305090046 NUREG-0728 R01
NRC INCIDENT RESPONSE PLAN
* Director's Office, Office of Inspection and Enforcement
83/04/30 27pp Available at NRC $3 75 18381 042

8305090144 Summarizes review of completed Generic Item B-24 re containment purge & vent & TMI Action Plan Item II E 4 2 SER & "Override & Reset of Control Circuitry in Ventilation/Purge Isolation & Other ESF Sys (B-24)," encl
CLARK,R A Operating Reactors Branch 3 83/04/20 STEWART,W L
Virginia Electric & Power Co 3pp 18367 072 24X
Fiche 50-338,83/04/20,8305090144

--8305090147 Safety evaluation approving containment purging/venting during normal operations & override & reset of control circuitry in ventilation/purge isolation & other ESF sys
* Office of Nuclear Reactor Regulation, Director 83/04/20 6pp
18367 075 24X Fiche 50-338,83/04/20,8305090144

8305090162 NUREG/CR-3117
SEISMICITY AND TECTONIC RELATIONSHIPS OF THE NEMAHA UPLIFT AND MIDCONTINENT GEOPHYSICAL ANOMALY Final Project Summary
BURCHETT,R R Nebraska, State of LUZA,K V Oklahoma, State of
VAN ECK,O J Iowa Geological Survey FIN A-5774 83/02/28
Division of Health, Siting & Waste Management 42pp Available at NRC. $12 00 18367 175

8305090200 Forwards response to NUREG-0737 Item II K 3 13, "RCIC Automatic Restart " RCIC sys modified such that reactor high water level signal will automatically close RCIC turbine steam supply valve,should valve be open.
HARRINGTON,W D Boston Edison Co 83-108 83/04/29 VASSALLO,D,B
Operating Reactors Branch 2 1p 18363 361 24X
Fiche 50-293,83/04/29,8305090200

8305090380 Ack receipt of 830131 ltr requesting addl info re NUREG-0737,Item II K 3 28, "Qualification of ADS Accumulator Sys," Info requested from GE Response will be submitted by 830630.
ZIMMERMAN,B R Carolina Power & Light Co LAP-83-119 83/05/03
VASSALLO,D B. Operating Reactors Branch 2 1p 18363 340 24X
Fiche:50-324,83/05/03,8305090380

8305090462 Forwards B&W "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits." per 830331 commitment
WESTAFER,G.R. Florida Power Corp. 3F-0483-32 83/04/29
STOLZ,J.F Operating Reactors Branch 4 1p 18362 153 24X
Fiche 50-302,83/04/29,8305090462

--8305090464 77-1140899-01
"Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits."
* Babcock & Wilcox Co 83/04/29 29pp 18362 154 24X
Fiche 50-302,83/04/29,8305090462

8305090486 Forwards response to Suppl 3 of SER (NUREG-0528), Section 3 10, "Seismic & Dynamic Qualification of Seismic Category 1 Mechanical & Electrical Equipment "
FLYNN,J D Cincinnati Gas & Electric Co 83/05/05, DENTON,H
Office of Nuclear Reactor Regulation, Director 4pp 18360 223
24X Fiche 50-358,83/05/05,8305090486

8305090553 Requests remittance of fee due for review of 830217 amend application re implementation of NUREG-0737 items;providing justification for imposition of fees in response to 830401 ltr contesting fee
MILLER,W O License Fee Management Branch 83/05/02,
RODRIQUEZ,R J, Sacramento Municipal Utility District 1p
18367 360 24X Fiche,50-312,83/05/02,8305090553

8305100108 Application to amend Licenses DPR-32 & DPR-37,revising radiological effluent Tech Specs in accordance w/Rev 3 to NUREG-0472 "Offsite Dose Calculation Manual" also encl
STEWART,W L Virginia Electric & Power Co 179 83/05/04
DENTON,H R Office of Nuclear Reactor Regulation, Director
VARGA,S A Operating Reactors Branch 1 3pp 18371 346 24X
Fiche 50-280,83/05/04,8305100108

--8305100111 Proposed revs to radiological effluent Tech Specs,in accordance w/Rev 3 to NUREG-0472
* Virginia Electric & Power Co 83/05/04 87pp 18371 349. 24X
Fiche 50-280,83/05/04,8305100108

8305100110 Responds to 830413 ltr re TMI Action Item II K 3 18, "Mods to ADS Sys Logic " One of two options (2 or 4) will be implemented Choice based on benefit to design impact on schedule,availability of hardware & analysis & total cost
BOUCHEY,G D Washington Public Power Supply System GO2-83-408
83/05/04 SCHWENCER,A Licensing Branch 2 1p 18375 032 24X
Fiche 50-397,83/05/04,8305100110

8305100114 Forwards review of existing specs re containment cooling sys operability No mods required Revised Section 3 3, "ESF & Auxiliary Sys," will be consistent w/NUREG-0452 & will be submitted as part of Amend 55
GIESLER,C W Wisconsin Public Service Corp. NRC-83-102 83/05/06.
VARGA,S A Operating Reactors Branch 1 6pp 18375 020 24X
Fiche 50-305,83/05/06,8305100114

8305100168 Forwards SER,Suppl 3 (NUREG-0887) W/o encl.
CUTCHIN,J M Hearing Branch 4 ISSUANCES OL 83/05/09
BLOCH,P B , BRIGHT,G D , KLINE,J R. Atomic Safety and Licensing Board Panel 1p 18374 273 24X Fiche 50-440,83/05/09,8305100168

8305100175 Forwards addl info re instrument accuracy & related data for containment pressure monitors,containment water level monitors & containment hydrogen monitors (NUREG-0737,Items II F 1 4,II F 1 5 & II F 1 6),per 821118 request.
O'TOOLE,J D Consolidated Edison Co. of New York, Inc. 83/04/29
VARGA,S A Operating Reactors Branch 1 14pp 18374 274. 24X
Fiche 50-247,83/04/29,8305100175

8305100197 Forwards comments re proposed NUREG-0737 Tech Specs,per 830321 ltr request Comments should not be interpreted as formal position or commitment to specific course of action.
DENTE,T J BWR Owners Group BWROG-8313 83/05/06 EISENHUT,D G.
Division of Licensing 4pp. 18374 311

8305100229 Forwards response to questions raised during 830422 telcon re util plans concerning NUREG-0737,Item II F 1, "Containment Instrumentation Upgrades " Dedicated recorder for hydrogen concentration will be provided
RODRIQUEZ,R J Sacramento Municipal Utility District. 83/05/06.
STOLZ,J F Operating Reactors Branch 4 3pp 18374 128 24X
Fiche:50-312,83/05/06,8305100229.

8305100344 Submits info re NUREG-0737,Item II E 1.1, "Auxiliary Feedwater Sys Upgrade Review." per 830407 request Info resolves protection of sys from internal missiles & addl protection required for condensate storage tank
RODRIQUEZ,R J Sacramento Municipal Utility District. 83/05/02.
STOLZ,J F. Operating Reactors Branch 4 2pp 18378 231 24X
Fiche 50-312,83/05/02,8305100344

8305100347 Forwards addl justification supporting adequacy of test of electrical load to satisfy License Condition 2.C &
WCAP-8921, "Setpoint Study,Duke Power,William B McGuire Nuclear Plant,Units 1 & 2 " Rept withheld (ref 10CFR2 790).
TUCKER,H B. Duke Power Co 83/05/05 DENTON,H R. Office of Nuclear Reactor Regulation, Director ADENSAM,E.G. Licensing Branch 4 2pp 18378 325 24X Fiche 50-369,83/05/05,8305100347.

8305100356 Forwards responses to New England Coalition on Nuclear Pollution fourth,sixth,eighth,twelfth,fourteenth & fifteenth motions for summary disposition
LESSY,R P. Hearing Branch 3 ISSUANCES OL 83/03/21. HOYT,H ,
LUEBKE,E A , HARBOUR,J Atomic Safety and Licensing Board Panel
2pp 18411.001 24X Fiche 50-443,83/03/21,8305100356.

--8305100419 Affidavit of RQ LaGrange on util commitment to qualify wide-range pressure transmitters per NUREG-0588 requirements,Commitment acceptable
LAGRANGE,R.Q. Equipment Qualification Branch ISSUANCES OL.
83/03/18. 3pp 18411 047 24X Fiche 50-443,83/03/21,8305100356.

--8305100429 Affidavit of JT Wiggins on util proposed alternatives to NUREG-0737,Item I.A 1 1 requirements re shift technical advisor position Proposal acceptable.
WIGGINS,J.T Division of Project & Resident Programs. ISSUANCES OL. 83/03/17. 2pp 18411.057. 24X Fiche,50-443,83/03/21,
8305100356

--8305100424 Affidavit of RO LaGrange on qualification of Class IE electric valve operators installed inside containment Util committed to qualification per NUREG-0588
LAGRANGE, R. O Equipment Qualification Branch ISSUANCES OL
83/03/18 3pp 18411.064 24X Fiche 50-443, 83/03/21, 8305100356

8305100368 Advises that w/exception of Item II K 3 31 on compliance w/10CFR50 56, 830324 comments applicable to 830321 draft generic ltr Review of 830324 submittal re comments on draft NUREG-0737 BWR Tech Specs requested
COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities B10783 83/05/05
EISENHUT, D G Division of Licensing 2pp 18378 212 24X
Fiche 50-245, 83/05/05, 8305100368

8305110003 Forwards evaluation of loss of discharge back pressure on pump operability re NUREG-0737, Item II E 1 1 & 830131 SER, per IE Bulletin 80-04, Operability of auxiliary feedwater pumps after extended operation at runout flow addressed
GIEBLER, C W. Wisconsin Public Service Corp NRC-83-103 83/05/06
VARGA, S A Operating Reactors Branch 1. 9pp 18408:280 24X
Fiche, 50-305, 83/05/06, 8305110003

8305110009 Comments on adequacy of implementation of NUREG-0737, Item III. A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50." Offsite & onsite emergency preparedness adequate.
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-023
83/05/09. FIEDLER, P B General Public Utilities - GPU Service Corp
3pp 18409:023 24X Fiche 50-219, 83/05/09, 8305110009

8305110026 Revised statement of P Vacca on 830419 re SECY 83-62 concerning rev to 10CFR35, "Human Use of Byproduct Matl "
VACCA, P C Assistant Director for Material Safety & Licensing
83/04/19. 7pp. 18412 338

--8305110029 Supports J Delmedico 830228 statement of differing prof opinion re SECY 83-62 (proposed rev to 10CFR35)
VACCA, P C. Assistant Director for Material Safety & Licensing
83/03/02. PALLADINO, N , GILINSKY, V., AHEARNE, J Commissioners
10pp. 18412 345.

--8305110030 Testimony of J Delmedico on 830419 in opposition to SECY 83-62 (proposed rev to 10CFR35).
DELMEDICO, J Assistant Director for Material Safety & Licensing
83/04/19 4pp 18412:355.

8305110027 NUREG/CR-3119 V01
NUCLEAR POWER SAFETY REPORTING SYSTEM FEASIBILITY ANALYSIS
FINLAYSON, F., IMS, J Aerospace Corp FIN B-8255. 83/04/30
Division of Facility Operations. 35pp Available at NRC. $4 50
18419:249.

8305110049 Comments on implementation of NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50." Onsite & offsite emergency preparedness adequate.
CRUTCHFIELD, D. Operating Reactors Branch 5. LS05-83-05-024
83/05/10. KAY, J A. Yankee Atomic Electric Co 3pp. 18409.014.
24X Fiche. 50-029, 83/05/10, 8305110049

8305110059 Advises that onsite & offsite emergency preparedness adequate, Emergency plans upgraded per NUREG-0737, Item III A. 2. 1. "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50." Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-022
83/03/09. DIETCH, R. Southern California Edison Co 3pp.
18408.106. 24X Fiche: 50-206, 83/03/09, 8305110059.

8305110114 NUREG-0871 V02 N02
SUMMARY INFORMATION REPORT. Data As Of April 30, 1983.
(Brown Book)
* Management Information Branch 83/04/30. 55pp 18419:195

8305110118 NUREG-0969
REPORT OF THE EVALUATION TEAM ON THE QUALITY OF CONSTRUCTION AT THE ZIMMER NUCLEAR POWER STATION.
* NRC - No Detailed Affiliation Given 83/04/30. 39ipp
18418.001. 24X Fiche 50-358, 83/04/30, 8305110118

8305110119 NUREG/CP-0035
THE MAN-MACHINE INTERFACE AND HUMAN RELIABILITY AN ASSESSMENT AND PROJECTION.
HALL, R. E , FRAGOLA, J. R., LUCKAS, W J Institute of Electrical & Electronic Engineers. FIN A-3217 BNL-NUREG-51579. 83/04/30
Office of Nuclear Regulatory Research, Director 265pp. 18416.001.

8305110120 NUREG/CR-2069 R01
SUMMARY REPORT ON A SURVEY OF LIGHT-WATER-REACTOR SAFETY SYSTEMS.
HEDDLESON, F. A. Oak Ridge National Laboratory. FIN B-0431.
ORNL/NSIC-181/R. 83/05/31 Division of Risk Analysis 356pp.
18417:001.

8305110126 NUREG/CR-3013
REVIEW OF THE RANCHO SECO NUCLEAR GENERATING STATION UNIT NO 1 AUXILIARY FEEDWATER SYSTEM RELIABILITY ANALYSIS Docket No 50-312 (Sacramento Municipal Utility District)
ILBERG, D , YOUNGBLOOD, R , PAPAZOGLOU, I A Brookhaven National Laboratory FIN A-3393 BNL-NUREG-51620 83/04/30 Division of Safety Technology 49pp Available at NRC $4 75 18416 266 24X
Fiche. 50-312, 83/04/30, 8305110126

8305110127 NUREG/CR-3187
CREVICE CORROSION OF TITANIUM ALLOY TICODE-12 IN SIMULATED ROCK SALT BRINE AT 150 CENTIGRADE Topical Report
AHN, T. M , LEE, D S , SOO, P Brookhaven National Laboratory FIN A-3237 BNL-NUREG-51653 83/04/30 Division of Health, Siting & Waste Management 28pp 18416 317

8305110131 NUREG/CR-3073
CONSTITUTIVE RELATIONS IN TRAC-PD2
ROHATGI, U S , JO, J , NEYMOTIN, L Brookhaven National Laboratory
FIN A-3215 BNL-NUREG-51616 83/04/30 Division of Accident Evaluation 43pp 18412 294

8305110148 NUREG/CR-2774 V04
PHYSICS OF REACTOR SAFETY Quarterly Report, October - December 1982
* Argonne National Laboratory FIN A-2015 ANL-82-24 83/04/30
Division of Accident Evaluation 31pp 18412 195

8305110154 Forwards supplementary response to 820223 6-month response to Generic Ltr 81-07, NUREG-0612, "Control of Heavy Loads," to confirm & clarify items discussed in 820804 telcon
LIDEN, E A. Public Service Electric & Gas Co of New Jersey
GL-81-07 83/04/27 VARGA, S A Operating Reactors Branch 1 8pp
18399 007 24X Fiche 50-272, 83/04/27, 8305110154

--8305110156 PSE-0108, "Maint Procedures "
* Public Service Electric & Gas Co of New Jersey GL-81-07
83/04/27 1,317pp. 18399 101 24X Fiche 50-272, 83/04/27, 8305110154

8305110162 NUREG/CR-3220
MECHANISTIC ASPECTS OF STRESS-CORROSION CRACKING OF TYPE 304 STAINLESS STEEL IN LWR SYSTEMS
NICHOLS, F A Argonne National Laboratory FIN A-2212 ANL-83-15
83/04/30 Division of Engineering Technology 67pp 18412 227

8305110174 NUREG-0940 V02 N01
ENFORCEMENT ACTIONS SIGNIFICANT ACTIONS RESOLVED Quarterly Progress Report, January-March 1983
* Director's Office, Office of Inspection and Enforcement
83/04/30 286pp 18411:066

8305110196 NUREG/CR-2568
BWR REFILL-REFLOOD PROGRAM TASK 4 4 - CCFL/REFILL SYSTEM EFFECTS TESTS (30 F SECTOR) SSTF SYSTEM RESPONSE TEST RESULTS
SCHUMACHER, D. O , ECKERT, T. , FINDLAY, J A General Electric Co. FIN B-5877 GEAP-22046 83/04/30 Division of Accident Evaluation
130pp. Available at NRC $6.00 18412 065

8305110208 NUREG/CR-2716 V04
REACTOR SAFETY RESEARCH PROGRAMS Quarterly Report, October - December 1982.
EDLER, S K Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2101 PNL-4275-4. 83/04/30 Division of Accident Evaluation 69pp. Available at NRC $5.00 18412 001

8305110223 Responds to 811031, 820702 & 830104 requests for exception from Table 1 of NUREG-0737, Suppl 1 requirements re location of emergency operations facility Exception granted.
EISENHUT, D G Division of Licensing 83/04/29 UHRIG, R E Florida Power & Light Co 2pp. 18434:334 24X Fiche 50-250, 83/04/29, 8305110223

8305110227 NUREG/CR-3074
APPLICATION OF REDUCTION METHODS TO NUCLEAR POWER PLANT STRUCTURES.
MILLER, C A , PHILIPPACOPOULO Brookhaven National Laboratory FIN A-3216 BNL-NUREG-51623 83/04/30. Division of Engineering Technology. 98pp 18413 008

8305110237 NUREG/CR-2331 V02 N3
SAFETY RESEARCH PROGRAMS SPONSORED BY OFFICE OF NUCLEAR REGULATORY RESEARCH. Quarterly Progress Report, July 1 - September 30, 1982
KOUTS, H J , BARI, R A , CERBONE, R J Brookhaven National Laboratory
FIN A-3011. BNL-NUREG-51454 83/04/30. Division of Accident Evaluation. 163pp 18419:032.

8305110240 NUREG-0748 V03 N03
OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of April 30, 1983 (Orange Book)
* Management Information Branch. 83/04/30. 317pp 18420 001.

8305110308 Application for amend to OLs revising Tech Specs 3/4 8 2 3, 3/4 8 2 4 & 3/4 8 2 5 to increase confidence of battery operability & provide time to correct battery conditions
CLAYTON,F L Alabama Power Co 83/05/03 VARGA,S A Office of Nuclear Reactor Regulation, Director 5pp 18393 198 24X
Fiche 50-348,83/05/03,8305110308

8305110374 Forwards addl info re NUREG-0737, Items II F 1 4,II F 1 5 & II F 1 6 concerning containment pressure,water level & hydrogen monitors,respectively,per 830106 request No obstructions would prevent hydrogen from escaping from core
FIEDLER,P B General Public Utilities - GPU Service Corp 83/05/06
CRUTCHFIELD,D Operating Reactors Branch 5 8pp 18406 279 24X
Fiche 50-219,83/05/06,8305110374

8305110385 Forwards response to open item on safe load paths contained in NRC 820923 technical evaluation rept of util 820201 submittal re control of heavy loads (NUREG-0612)
CROUSE,R P Toledo Edison Co 946 83/05/06 STOLZ,J F
Operating Reactors Branch 4 11pp 18406 201 24X
Fiche 50-346,83/05/06,8305110385

8305110415 Notification of CROR Meeting 38 on 830518 in Bethesda,MD to discuss proposed rule, "Analysis of Potential Pressurized Thermal Shock Events," prioritization of generic safety issues & operator requalification program Review matl encl
STELLO,V Regional Operations & Generic Requirements 83/05/10
EISENHUT,D G Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 18394 221

--8305110428 Forwards proposed Commission paper discussing prioritization of generic safety issues & transmitting draft NUREG-0933, "Prioritization of Generic Safety Issues " Procedures for identifying & managing issues encl
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/05/02 DIRCKS,W J Office of the Executive Director for Operations 771pp 18394 259

8305110437 Forwards "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits," per 830405 ltr
CROUSE,R P Toledo Edison Co 945 83/05/06 STOLZ,J F.
Operating Reactors Branch 4 1p 18404 320 24X
Fiche 50-346,83/05/06,8305110437

--8305110443 77-1142162-00
"Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits "
* Babcock & Wilcox Co 83/05/06 28pp 18404 321 24X
Fiche 50-346,83/05/06,8305110437

8305110457 NUREG/CR-2769
COMPARISON OF FIELD-MEASURED RADON DIFFUSION COEFFICIENTS WITH LABORATORY-MEASURED COEFFICIENTS
LEPEL,E A , SILKER,W B , THOMAS,W V Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2249 PNL-4414 83/04/30
Division of Health, Siting & Waste Management 36pp Available at NRC $4 50 18413 214

8305110467 NUREG/CR-3216
HEISSDAMPFREAKTOR (HDR) STEEL CONTAINMENT VESSEL AND FLOOD WATER STORAGE TANK STRUCTURAL DYNAMICS TEST
OORMAN,V W , ARENDTS,J G , THINNES,G L EG&G, Inc FIN A-6306
EGG-2249 83/04/30 Division of Engineering Technology 108pp
18413 106

8305110476 NUREG/CR-0169 V01
LOFT EXPERIMENTAL MEASUREMENTS UNCERTAINTY ANALYSES METHODOLOGY AND SUMMARY
LASSAHN,G D EG&G, Inc FIN A-6043 EGG-2037 83/04/30
Division of Accident Evaluation 41pp 18415 020

8305110491 NUREG/CR-2744 V02
HUMAN RELIABILITY DATA BANK FOR NUCLEAR POWER PLANT OPERATIONS Volume 2 A Data Bank Concept And System Description
COMER,M K , KOSINSKY,E J , ECKEL,J.S General Physics Corp FIN A-1188 SAND82-7057. 83/04/30 Division of Facility Operations
177pp 18414 001

8305110501 Forwards IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs, 83/04/26
MCNEILL,C A Power Authority of the State of New York 2pp.
18393 350 24X Fiche 50-333,83/04/26,8305110501

--8305110509 IE Insp Rept 50-333/83-07 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737,Item II B 2, "Design Review of Plant Shielding "
BRIGGS,L , HAVERKAMP,D , EAPEN,P Region 1, Office of Director,
83/04/22 8pp 18393 352 24X Fiche 50-333,83/04/26,8305110501

8305110512 NUREG/CR-3261
COOPERATIVE TEST PROGRAM ON CRACK ARREST TOUGHNESS MEASUREMENT Final Report
FOURNEY,W L , HAHN,G T , HOAGLAND,R G Maryland, Univ of FIN B-0119 83/04/30 Division of Engineering Technology 202pp
Available at NRC $7 00 18414 178

8305110518 NUREG/CR-3195
ANALYSIS OF SEMISCALE MOD-2A SYSTEM UHI/SBLOCA EXPERIMENTS
SHIMECK,D J EG&G, Inc FIN A-6038 EGG-2246 83/04/30
Division of Accident Evaluation 42pp 18415 184

8305110523 NUREG/CR-3184
PBF LOCA TEST LOC-6 FUEL BEHAVIOR REPORT
BROUGHTON,J M , VINJAMURI,K , HAGRMAN,D L EG&G, Inc FIN A-6041
EGG-2244 83/04/30 Division of Accident Evaluation 68pp
18415 115

8305110528 NUREG/CR-2743
PROCEDURES FOR USING EXPERT JUDGMENT TO ESTIMATE HUMAN ERROR PROBABILITIES IN NUCLEAR POWER PLANT OPERATIONS
SEAVER,D A , STILLWELL,W G Decision Science Consortium, Inc *
Sandia Laboratories FIN A-1188 SAND82-7054 83/04/30
Division of Facility Operations 127pp 18415 227

8305120003 Responds to 830316 ltr requesting review of RCIC sys automatic restart per TMI Action Item II K 3 13 Acceptance criteria identified in ltr satisfied
ZIMMERMAN,S R Carolina Power & Light Co LAP-83-124 83/05/09,
VASSALLO,D B Operating Reactors Branch 2 1p 18423 076 24X
Fiche 50-324,83/05/09,8305120003

8305120088 Requests review schedule for applicant response to Generic Ltr 82-33 re NUREG-0737,Suppl 1 concerning emergency response capability W/o encl
YOUNGBLOOD,B J Licensing Branch 1 GL-82-33 83/04/29 MOORE,V
Human Engineering Section ROSA,F Instrumentation & Control Branch PAGANO,F Emergency Preparedness Licensing Br (after 801119 see I&E) 2pp 18443.191 24X Fiche 50-000,83/04/29,8305120088

8305120116 Advises that onsite & offsite emergency preparedness adequate per 10CFR50,App E Emergency plans upgraded per NUREG-0737,Item III A 2 1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 LS05-83-05-026,
83/05/11 FARRAR,D L Commonwealth Edison Co 3pp 18423 040
24X Fiche 50-010,83/05/11,8305120116

8305120189 Informs that post-implementation review info on NUREG-0737, Items II F 1 4,II F 1 5 & II F 1 6 will not be provided until 830701 due to higher priority post-TMI work
KRIEGER,R W Southern California Edison Co 83/05/10
CRUTCHFIELD,D Operating Reactors Branch 5, 1p 18427 152. 24X
Fiche 50-206,83/05/10,8305120189

8305120325 Forwards response to NUREG-0612, "Control of Heavy Loads " Ack of receipt of matl requested
CRANE,P A Pacific Gas & Electric Co 83/05/09 KNIGHTON,G.W
Licensing Branch 3 222pp 18432 042 24X Fiche 50-275,83/05/09,
8305120325

8305120370 Forwards Accident Evaluation Branch SER input re NUREG-0737, Item III D 3 4, "Control Room Habitability " Sys acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 LS05-83-05-027
83/05/11 FARRAR,D.L Commonwealth Edison Co 6pp 18432 293
24X Fiche: 50-237,83/05/11,8305120370

--8305120374 Advises that licensee proposed program re NUREG-0737,Item III D 3 4, "Control Room Habitability," acceptable
MURPHY,D W Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2323 82/03/23 HULMAN,L G Accident Evaluation Branch 2pp 18432 301 24X Fiche,50-237,83/05/11,
8305120370

8305120385 Forwards RCS pressure temp (P-T) curves requested in Section 5 3 2 of SER (NUREG-0857) P-T curves will be submitted as part of final Tech Spec submission Submittal resolves issue
VAN BRUNT,E E Arizona Public Service Co ANPP-23714-WFG/
83/05/09 KNIGHTON,G Licensing Branch 3 4pp. 18433 120 24X
Fiche,50-528,83/05/09,8305120385

8305120440 Forwards IE Insp Rept 50-237/83-03 on 830111-0324 & notice of violation
LITTLE,W.S Region 3, Office of Director, 83/04/25 REED,C
Commonwealth Edison Co 2pp 18431.091 24X Fiche,50-237,83/04/25,
8305120440

--8305120449 IE Insp Rept 50-237/83-03 on 830111-0324 Noncompliance noted failure to control recirculation riser pipe weld rod studs,unused rod & unused rolls of E308L-16 stainless steel wire
KEY,W J , DANIELSON,D H Region 3, Office of Director IEB-82-03 83/04/21 1ipp 18431 094 24X Fiche 50-237,83/04/25, 8305120440

8305120562 Summary of 269th ACRS meeting on 820909-11 re safety goals for nuclear power plants
* ACRS - Advisory Committee on Reactor Safeguards 83/05/05. ACRS - Advisory Committee on Reactor Safeguards 239pp 18442 211

8305130008 Informs that emergency offsite facility (EOF) operational w/exception of issuance of Procedure 1212 & installation of dedicated phone lines at near-site support ctr & EOF,per Generic Ltr 82-33
UHRIG,R E Florida Power & Light Co QL-82-33 83/05/09 EISENHUT,D G Division of Licensing 1p 18436 326 24X Fiche 50-250,83/05/09,8305130008

8305130009 Updates progress in meeting schedular commitments per NRC 830314 order re implementation of post-TMI Action Item II F 1, "Addl Accident Monitoring Instrumentation "
FAY,C W Wisconsin Electric Power Co 83/05/06 DENTON,H R. Office of Nuclear Reactor Regulation, Director CLARK,R A Operating Reactors Branch 3 3pp 18436 341 24X Fiche 50-266,83/05/06,8305130009

8305130020 Forwards addl justification required by SER (NUREG-0847) showing that research & test results in area of hydrogen control capabilities independent of containment spray conditions or boundary pressure retaining capabilities
MILLS,L M Tennessee Valley Authority 83/05/10 ADENSAM,E. Licensing Branch 4 4pp 18437 129 24X Fiche 50-390,83/05/10, 8305130020

8305130038 Responds to 830316 request for addl info re NUREG-0737, Item II.K.3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " Environ & seismic qualification will be in accordance w/IE Bulletin 79-01B
RYBAK,B Commonwealth Edison Co IEB-79-01B 83/05/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18436 339 24X Fiche 50-000,83/05/10,8305130038

8305130039 Forwards supplemental info to 821012 response re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys " Response to NRC Question 9(b) not presently available Info will be submitted by 830615
BAYNE,J P Power Authority of the State of New York IPN-83-38 83/05/10 EISENHUT,D G. Division of Licensing 16pp 18437 010 24X Fiche 50-286,83/05/10,8305130039

8305130054 Ack receipt of 821103 ltr re intention to complete Phase II of control of heavy loads issue (NUREG-0612) Final technical evaluation rept & NRC safety evaluation to ensure no outstanding deficiencies remain requested
QARRITY,J.H. Maine Yankee Atomic Power Co MN-83-94 83/05/10. CLARK,R A Operating Reactors Branch 3 2pp 18437 031 24X Fiche. 50-309,83/05/10,8305130054

8305130067 Advises that util endorses Rev 3 to BAW-10092P & BAW-10154P as response to NUREG-0737, Item II K 3 30, "Revised Small Break LOCA Methods to Show Compliance W/10CFR50,App K " Work on item will not commence until repts approved by NRC
WEBTAFER,G R Florida Power Corp 3F-0583-07 83/05/09 STOLZ,J F Operating Reactors Branch 4 1p 18436 245 24X Fiche 50-302,83/05/09,8305130067

8305130099 Forwards licensee 830428 ltr re emergency feedwater instrumentation & control (EFIC) sys & upgraded auxiliary feedwater sys,NUREG-0737,Items II E 1.2 & II K.2 10 Ltr provides new info on mod completion schedule W/svc list
BAXTER,T.A Shaw, Pittman, Potts & Trowbridge BAXTER,T A Sacramento Municipal Utility District 83/05/11 ROSENTHAL,A S , BUCK,J.H, KOHL,C.N Atomic Safety and Licensing Appeal Panel 3pp 18437 223 24X Fiche. 50-312,83/05/11,8305130099

8305130118 Advises that mods to purge sys not required Sufficient margin exists to allow check valve to perform intended safety function. Item closes out 5% of rated thermal power portion of License Condition 2 C.8
UHRIG,R E Florida Power & Light Co. L-83-286. 83/05/10 EISENHUT,D G. Division of Licensing 2pp 18438.057 24X Fiche 50-389,83/05/10,8305130118

8305130146 Lists documentation to be provided re SER Outstanding Issue 3 (NUREG-0853), "Seismic Analysis," per NRC request at 830428 meeting W/Bargent & Lundy in Bethesda,MD,satisfying site-specific spectrum concerns
HULLER,G E Illinois Power Co. U-0636 83/05/10 SCHWENCER,A Licensing Branch 2. 3pp 18438.124 24X Fiche 50-461,83/05/10, 8305130146.

8305130294 Forwards safety evaluation & Franklin Research Ctr technical evaluation rept, "Control of Heavy Loads (C-10),Oconee Nuclear Power Station,Units 1,2 & 3 " Phase I actions acceptable per NUREG-0612
STOLZ,J F Operating Reactors Branch 4 83/04/20 TUCKER,H B Duke Power Co 3pp 18457 179 24X Fiche 50-269,83/04/20, 8305130294

--8305130296 Safety evaluation supporting Phase I actions re control of heavy loads (NUREG-0612)
* Office of Nuclear Reactor Regulation, Director 83/04/20 1p 18457 182 24X Fiche 50-269,83/04/20,8305130294

--8304070286 TER-C5506-374/375/37
"Control of Heavy Loads (C-10), Oconee Nuclear Power Station Units 1,2 & 3," technical evaluation rept
ROBERTS,S Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08065 83/03/31 CLEMENSON,F NRC - No Detailed Affiliation Given 28pp 18457 183 24X Fiche 50-269,83/04/20,8305130294

8305130326 Comments on NUREG/CR-3324 items Unprotected transient overpower accident & unprotected loss-of-flow accident should be reviewed at ACRS full committee meeting
KASTENBERG,W E ACRS - Advisory Committee on Reactor Safeguards 83/03/28 CARBON,M ACRS - Advisory Committee on Reactor Safeguards 4pp 18457 303

8305130341 NUREG/CR-3114 ERR
PROCEEDINGS OF WORKSHOP ON COGNITIVE MODELING OF NUCLEAR PLANT CONTROL ROOM OPERATORS August 15-18,1982,Dedham, Massachusetts
* Oak Ridge National Laboratory ORNL/TM-8614 83/03/10 Office of Nuclear Regulatory Research, Director 1p 18443 352

8305160015 Submits schedule for providing info re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability " Formal procedure for relating radionuclide concentrations to core damage expected by startup from 1984 refueling outage
MANGAN,C V Niagara Mohawk Power Corp 83/05/11 EISENHUT,D G Division of Licensing 1p 18453 162 24X Fiche 50-220,83/05/11, 8305160015

8305160022 Advises that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737,Item III A 2 1 Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 L505-83-05-033 83/05/13 COUNSIL,W G Connecticut Yankee Atomic Power Co 4pp 18452 349 24X Fiche 50-000,83/05/13,8305160022

8305160041 Forwards marked-up FSAR pages describing equipment for sampling & monitoring process & effluent streams during postulated accidents Submittal closes out commitment in Section 11 5 2 (Page 11-14) of SER,NUREG-0892
BOUCHEY,G D Washington Public Power Supply System G02-83-417 83/05/10 SCHWENCER,A Licensing Branch 2 20pp 18444 009 24X Fiche 50-397,83/05/10,8305160041

8305160059 Clarifies commitments re timing for completion of preoperational testing of auxiliary bldg ventilation sys Review of SER,NUREG-0876, indicates misunderstanding may exist
TRAMM,T R Commonwealth Edison Co 6554N 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18453 118 24X Fiche 50-454,83/05/11,8305160059

8305160195 Addl response to FOIA request for all documents dtd 820101 detailing or referring to SALP for facility Forwards documents listed in App A Further search for documents in progress
FELTON,J M Division of Rules and Records 83/03/31 CLARK,R A San Francisco Examiner 2pp. 18462 191 24X Fiche 50-312,83/03/31, 8305160195

--8305160204 Forwards SALP evaluation of IAEA safeguards licensing activities for facility
GIBSON,J Standardization & Special Projects Branch 82/10/18 MINER,S Operating Reactors Branch 4 2pp 18462 194 24X Fiche. 50-312,83/03/31,8305160195

8305170048 Advises that NUREG-0737,Item III A 2 1, "Amend 10CFR50 & App E," considered complete following comprehensive 2-wk onsite emergency preparedness appraisal
VARGA,S A Operating Reactors Branch 1 83/05/11 UTLEY,E E Carolina Power & Light Co 3pp 18494 181 24X Fiche 50-261,83/05/11,8305170048

8305170057 NUREG-0968 S01
SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No 50-537,(U S Department of Energy,Tennessee Valley Authority And Project Management Corporation)
* Clinch River Breeder Reactor Program Office 83/05/31 36pp 18493.159 24X Fiche:50-537,83/05/31,8305170057

8305170064 Responds to 830412 petition & 0418 amend,requesting that NRC order PSE&G to show cause why facility restart should not be restrained Petition denied based on encl Director's Decision
DENTON,H R Office of Nuclear Reactor Regulation, Director 83/04/29 RODRIGUEZ,J H New Jersey, State of 3pp 18494 184 24X Fiche 50-272,83/04/29,8305170064

--8305170095 Safety evaluation re restart of facilities Licensee acceptably revised & expanded surveillance testing programs to address reactor trip issue
* Office of Nuclear Reactor Regulation, Director DD-83-06 83/04/28 45pp 18494 195 24X Fiche 50-272,83/04/29,8305170064

8305170086 NUREG/CR-3240
COMPARISON OF CRBR DESIGN BASIS EVENTS WITH THOSE OF FOREIGN LMFBR PLANTS
AGRAWAL,A K Brookhaven National Laboratory FIN A-3364 BNL-NUREG-51663 83/04/30 Clinch River Breeder Reactor Program Office 85pp Available at NRC $5 00 18493 193 24X Fiche 50-537,83/04/30,8305170086

8305170088 NUREG-0580 V12 N04
REGULATORY LICENSING STATUS SUMMARY REPORT Data As Of April 30,1983 (Blue Book)
* Management Information Branch 83/05/31 68pp 18493 277

8305170092 NUREG-0800 R04
STANDARD REVIEW PLAN Proposed Revision 4 To 6 2 2, Containment Heat Removal Systems
* Office of Nuclear Reactor Regulation, Director PSRP-6 2 2 R4 83/05/16 10pp 18495 308

8305170093 Board Notification 83-62 forwards NRC evaluation team independent assessment of installed safety-related equipment W/o rept
NOVAK,T M Division of Licensing 83/05/10 Atomic Safety and Licensing Appeal Panel 7pp 18495 317 24X Fiche 50-358,83/05/10, 8305170093

--8305170098 Forwards NRC evaluation team rept (NUREG-0969) re onsite hardware evaluation conducted 830124-0304 W/o encl
DIRCKS,W J Office of the Executive Director for Operations 83/05/04 PALLADINO,N , GILINSKY,V , AHEARNE,J Commissioners 1p. 18495 323 24X Fiche 50-358,83/05/10,8305170093

8305170094 NUREG-0887 S03
SAFETY EVALUATION REPORT RELATED TO OPERATION OF THE PERRY NUCLEAR POWER PLANT,UNITS 1 AND 2 Docket Nos 50-440 And 50-441 (Cleveland Electric Illuminating Company)
* Office of Nuclear Reactor Regulation, Director 83/04/30 75pp 18492 303 24X Fiche 50-440,83/04/30,8305170096

8305170101 NUREG/CR-2482 V02
REVIEW OF DOE WASTE PACKAGE PROGRAM Subtask 1 1 - National Waste Package Program Parts 1 And 2
SISKIND,B , HSIEH,D , SHAD,J Brookhaven National Laboratory FIN A-3164 BNL-NUREG-51494 83/04/30 Division of Waste Management 129pp Available at NRC $6 00 18477 087

8305170118 NUREG-0897 FC
CONTAINMENT EMERGENCY SUMP PERFORMANCE Technical Findings Related To Unresolved Safety Issue A-43
SERKIZ,A W Division of Safety Technology 83/04/30 129pp 18493 007

8305170121 NUREG/CR-3173
NEW MADRID SEISMOTECTONIC STUDY Summary Of Activities 1977-1981
BUSCHBACH,T C. St Louis Univ , St Louis, MO 83/03/31, Division of Health, Siting & Waste Management 214pp Available at NRC $7 00 18480 209

8305170122 NUREG/CR-3235 V01
TECHNICAL ASSISTANCE FOR REGULATORY DEVELOPMENT REVIEW AND EVALUATION OF THE DRAFT EPA STANDARD 40CFR191 FOR DISPOSAL OF HIGH-LEVEL WASTE
ORTIZ,N R Sandia Laboratories WAHI,K K Science Applications, Inc FIN A-1165 SAND82-1557 83/04/30 Division of Waste Management 22pp Available at NRC $3 25 18493 136

8305170123 NUREG-0869 FC
USI A-43 RESOLUTION POSITIONS
SERKIZ,A W Division of Safety Technology 83/04/30 74pp 18496 023

8305170128 NUREG-0020 V07 N01
LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As Of December 31,1982 (Gray Book)
* Management Information Branch. 83/01/31 391pp 18478 076.

8305170132 NUREG/CR-3235 V02-04
TECHNICAL ASSISTANCE FOR REGULATORY DEVELOPMENT REVIEW AND EVALUATION OF THE DRAFT EPA STANDARD 40CFR191 FOR DISPOSAL OF HIGH-LEVEL WASTE
* Sandia Laboratories FIN A-1165 SAND82-1557 83/04/30 Division of Waste Management 316pp Available at NRC $9 00, 18479 253

8305170135 NUREG/CR-3235 V05-06
TECHNICAL ASSISTANCE FOR REGULATORY DEVELOPMENT REVIEW AND EVALUATION OF THE DRAFT EPA STANDARD 40CFR191 FOR DISPOSAL OF HIGH-LEVEL WASTE
* Sandia Laboratories FIN A-1165 SAND82-1557 83/04/30 Division of Waste Management 146pp Available at NRC $6.50, 18479 107

8305170137 NUREG/BR-0025 V09 N4
INFORMATION REPORT ON STATE LEGISLATION
KERR,G W Office of State Programs, Director 83/05/31 14pp, 18494.001

8305170149 NUREG-0972
DRAFT ENVIRONMENTAL STATEMENT RELATED TO THE OPERATION OF SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1 AND 2 Docket Nos STN 50-400 And STN 50-401 (Carolina Power And Light Company)
* Office of Nuclear Reactor Regulation, Director. 83/04/30 220pp, 18477:216 24X Fiche 50-400,83/04/30,8305170149

8305170150 Forwards add1 info requested in 830502 ltr re PORV/SV failures & challenges Further ref should be made to 820623 response to NUREG-0737,Item II D 1
GIESLER,C W Wisconsin Public Service Corp NRC-83-108 83/05/13 VARGA,S A Operating Reactors Branch 1 3pp 18466·291. 24X Fiche 50-305,83/05/13,8305170150

8305170218 Forwards response to 830208 & 0317 requests for add1 info re NUREG-0737,Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor" & II F 1.6, "Containment Hydrogen Monitor "
LENTINE,F Q Commonwealth Edison Co 6566N 83/05/13 DENTON,H R. Office of Nuclear Reactor Regulation, Director 8pp 18466 332. 24X Fiche 50-295,83/05/13,8305170218

8305170232 SECY-83-158
Informs Commission of findings of Salem ATWS generic implications task force re overall mgt capability & performance & reactor trip sys reliability
DIRCKS,W J. Office of the Executive Director for Operations. 83/05/02 159pp 18476 184 24X Fiche·50-272,83/05/02,8305170232

8305170346 Forwards IE Insp Rept 50-397/83-13 on 830404-08 No noncompliance noted
STERNBERG,D M Region 5, Office of Director. 83/04/19 CARLISLE,C S Washington Public Power Supply System 2pp 18465 268 24X Fiche 50-397,83/04/19,8305170346

--8305170349 IE Insp Rept 50-397/83-13 on 830404-08 No noncompliance noted Major areas inspected preoperational test program,open items, IE bulletin/circular response,TMI (NUREG-0737) activities & independent insp
WILLETT,D J , DODDS,R T Region 5, Office of Director IE8-82-04 83/04/19 3pp 18465.270 24X Fiche 50-397,83/04/19,8305170346

8305170369 Comments on NUREG-0737,Item III A 2.1, "Emergency Preparedness,Upgrade Emergency Plans to App E, 10CFR50 " Onsite & offsite emergency preparedness adequate.Item complete
CRUTCHFIELD,D Operating Reactors Branch 5 LS05-83-05-036. 83/05/16 VANDEWALLE,D J. Consumers Power Co. 5pp 18466·077. 24X Fiche 50-155,83/05/16,8305170369

8305170416 Notifies that onsite & offsite emergency preparedness adequate.NUREG-0737,Item III.A 2.1, "Emergency Preparedness, Upgrade Emergency Plans to App E,10CFR50," complete
CRUTCHFIELD,D Operating Reactors Branch 5, LS05-83-05-037 83/05/16 LINDER,F Dairyland Power Cooperative 3pp 18469·250. 24X Fiche,50-409,83/05/16,8305170416

8305170459 Forwards proposed schedule for resolution of SEP integrated assessment open items identified in NUREG-0825, "Integrated Plant Safety Assessment " NRC will be informed immediately of any schedular difficulties
KAY,J A Yankee Atomic Electric Co FYR83-48 83/05/02 CRUTCHFIELD,D. Operating Reactors Branch 5. 5pp. 18469.321 24X Fiche 50-029,83/05/02,8305170459

8305170471 Responds to Generic Ltr 82-33 (NUREG-0737,Suppl 1) re emergency response capability requirements.Progress in areas of safety parameter display sys,detailed control room design reviews & emergency response facilities summarized
BASKIN,K P Southern California Edison Co GL-82-33. 83/05/13. EISENHUT,D G. Office of Nuclear Reactor Regulation, Director 8pp 18470 077 24X Fiche·50-361,83/05/13,8305170471

8305170496 Forwards IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted
BOOK, H E Region 5, Office of Director 83/04/22 CRANE, P A
Pacific Gas & Electric Co 2pp 18470 045 24X
Fiche: 50-275, 83/04/22, 8305170496

--8305170501 IE Insp Rept 50-275/83-09 on 830222-25 & 0314-18 No noncompliance noted Major areas inspected implementation of NUREG-0737, Item II F 1, "Addl Accident Monitoring Instrumentation "
GARCIA, E M , WENSLAWSKI, F A , BOOK, H E Region 5, Office of Director 83/04/22 7pp 18470 047 24X Fiche 50-275, 83/04/22, 8305170496

8305170515 Forwards IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 & notice of violation
SCARANO, R A. Division of Radiological Safety & Safeguards Program
83/04/18. PAPAY, L T Southern California Edison Co 2pp
18467 260 24X Fiche 50-361, 83/04/18, 8305170515

--8305170530 IE Insp Repts 50-361/83-14 & 50-362/83-14 on 830321-30 Noncompliance noted failure to perform surveys, inform workers & properly monitor liquid radioactive effluent release
YUHAS, G P , WENSLAWSKI, F A , BOOK, H E Region 5, Office of Director 50-362/83-14 83/04/14 10pp 18467 264 24X
Fiche: 50-361, 83/04/18, 8305170515

8305170556 Forwards SER Suppl 1 (NUREG-0954) W/o encl
JOHNSON, G E Hearing Branch 4 83/05/16 KELLEY, J L , FOSTER, R F , CALLIHAN, D. Atomic Safety and Licensing Board Panel 1p
18468, 160 24X Fiche: 50-413, 83/05/16, 8305170556

8305170579 NUREG-0837 V02 N03ER
NRC TLD DIRECT RADIATION MONITORING NETWORK Progress Report, July - September 1982.
* Division of Technical Information & Document Control. 83/04/28
1p. 18496.115

8305170668 NUREG-0896 S01
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF SEABROOK STATION, UNITS 1 AND 2 Docket Nos 50-443 And 50-444. (Public Service Company of New Hampshire, et al)
* Division of Licensing. 83/04/30 32pp Available at NRC
$4.50 18481 332. 24X Fiche 50-443, 83/04/30, 8305170668

8305170674 NUREG-1000 V01
GENERIC IMPLICATIONS OF ATWS EVENTS AT THE SALEM NUCLEAR POWER PLANT Generic Implications
* Office of Nuclear Reactor Regulation, Director 83/04/30 149pp.
Available at NRC. $6 50 18481.183 24X Fiche: 50-272, 83/04/30, 8305170674

8305170712 NUREG-0954 S01
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CATAWBA NUCLEAR STATION, UNITS 1 AND 2 Docket Nos 50-413 And 50-414 (Duke Power Company, et al)
* Division of Licensing. 83/04/30 56pp Available at NRC
$4.75. 18481.126 24X Fiche 50-413, 83/04/30, 8305170712

8305180081 Forwards Amend 90 to License DPR-49 & notice of issuance & availability Amend deletes requirements for shift technical advisor to be on duty during refueling per TMI Action Item I.A 1 1
VASSALLO, D B. Operating Reactors Branch 2 83/05/03. ARNOLD, D
Iowa Electric Light & Power Co. 3pp. 18503:270 24X
Fiche: 50-331, 83/05/03, 8305180081

--8305180091 Amend 90 to License DPR-49, deleting requirement for shift technical advisor to be on duty during refueling per TMI Action Item I.A 1.1
VASSALLO, D B. Operating Reactors Branch 2. 83/05/03. 4pp
18503:273 24X Fiche 50-331, 83/05/03, 8305180081.

8305180161 Informs that NUREG-0737, Item III.A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," complete.
STOLZ, J F Operating Reactors Branch 4. CLARK, R A. Operating Reactors Branch 3 83/05/11 GRIFFIN, J M. Arkansas Power & Light Co. 3pp 18502 348 24X Fiche 50-313, 83/05/11, 8305180161

8305180169 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737, Item III A 2 1 requirements complete.
VARGA, S A. Operating Reactors Branch 1. 83/05/13 STEWART, W. L.
Virginia Electric & Power Co 3pp 18502:351 24X
Fiche: 50-280, 83/05/13, 8305180169

8305180385 Forwards "Preliminary Design Assessment of Byron/Braidwood Generating Station & Control Room Human Factors Engineering Review," Suppls I & II
SWARTZ, E. D Commonwealth Edison Co. 6546N 83/05/09 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18487:001 24X
Fiche: 50-000, 83/05/09, 8305180385.

--8305180397 "Preliminary Design Assessment of Byron/Braidwood Generating Station Control Room Human Factors Engineering Review," Suppls I & II
* Commonwealth Edison Co 83/04/30 221pp 18487 002 24X
Fiche 50-000, 83/05/09, 8305180385

8305180433 Forwards safety evaluation re BWR Owners Group B01230 response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mods required
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-041
83/05/17 FIEDLER, P. B General Public Utilities - GPU Service Corp
2pp 18486 195 24X Fiche 50-219, 83/05/17, 8305180433

--8305180440 Safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mods required
* Operating Reactors Branch 5 83/05/17 4pp 18486 197 24X
Fiche 50-219, 83/05/17, 8305180433.

8305180468 Forwards responses to NRC concerns raised at 830218 meeting w/util to close out open items re emergency feedwater control sys, per NUREG-0787, Suppl 1 W/23 oversize drawings Aperture cards are available in PDR
MAURIN, L V Louisiana Power & Light Co W3P83-1484 83/05/13
KNIGHTON, G W Licensing Branch 3 31pp 18482 131 24X
Fiche 50-382, 83/05/13, 8305180468

8305180547 Forwards order extending completion date for installation of plant mods needed to comply w/NUREG-0661 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
VASSALLO, D B Operating Reactors Branch 2 83/05/05 PILANT, J M
Nebraska Public Power District 2pp 18505 084 24X
Fiche 50-298, 83/05/05, 8305180547

--8305180548 Order modifying 810113 & 820915 orders, extending completion date for installation of plant mods needed to comply w/NUREG-0661 Extension granted until 90 days after start of Fuel Cycle 9 (1983 refueling outage)
PURPLE, R A Division of Licensing. 83/05/05 Nebraska Public Power District 4pp 18505 086 24X Fiche 50-298, 83/05/05, 8305180547

8305180563 Forwards revised order establishing 830930 completion date for implementing NUREG-0737, Items II B 3 re post-accident sampling & II F 1 1 & II F 1 5 re accident monitoring
VASSALLO, D B Operating Reactors Branch 2 83/05/05 UTLEY, E E
Carolina Power & Light Co. 2pp 18504 354 24X
Fiche 50-324, 83/05/05, 8305180563

--8305180566 Revised order confirming licensee commitments to implement NUREG-0737, Items II B.3 re post-accident sampling & II F.1 1 & II F 1 5 re accident monitoring, by 830930
PURPLE, R A Division of Licensing. 83/05/05 Carolina Power & Light Co 5pp 18504 356 24X Fiche. 50-324, 83/05/05, 8305180563

8305180568 Informs that emergency plan upgrade to meet 10CFR50 App E, NUREG-0737, Item III. A 2 1, complete Item closed
VARGA, S. A Operating Reactors Branch 1 83/05/13. UHRIG, R E
Florida Power & Light Co 3pp 18505 295 24X
Fiche 50-250, 83/05/13, 8305180568

8305180573 Forwards SER supporting licensee responses to NUREG-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F 1 6, "Containment Hydrogen Monitor "
VARGA, S A Operating Reactors Branch 1 83/05/02 GIESLER, C W
Wisconsin Public Service Corp 2pp 18505 308 24X
Fiche 50-305, 83/05/02, 8305180573.

--8305180580 Safety evaluation supporting licensee responses to NUREG-0737, Items II.F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor," & II F.1.6, "Containment Hydrogen Monitor."
* Office of Nuclear Reactor Regulation, Director. 83/05/02 4pp
18505:310 24X Fiche 50-305, 83/05/02, 8305180573

8305180691 Forwards revised order modifying completion dates for NUREG-0737, Items II B 2, "Plant Shielding," II B 3, "Post Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation "
VARGA, S. A Operating Reactors Branch 1 83/04/28 FARRAR, D L
Commonwealth Edison Co 2pp. 18505 181 24X Fiche: 50-295, 83/04/28, 8305180691.

--8305180702 Revised order modifying completion dates for NUREG-0737, Items II B.2, "Plant Shielding," II B 3, "Post-Accident Sampling" & II F 1 2, "Accident Monitoring Instrumentation," per Generic Ltrs 82-05 & 82-10
EISENHUT, D G Division of Licensing GL-82-05 83/04/28.
Commonwealth Edison Co 9pp 18505.183 24X
Fiche 50-295, 83/04/28, 8305180691

8305180745 Informs that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
* Operating Reactors Branch 1 83/05/13 DOLAN, J Indiana & Michigan Electric Co 2pp 18506 045 24X Fiche 50-315, 83/05/13, 8305180745

8305180782 NUREG/CR-3016
EVALUATION OF THE SPLIT-H APPROACH TO MODELING NON-BUOYANT RELEASES FROM VENT STACKS
RAMSDELL, J V Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2514 PNL-4516 83/04/30 Division of Systems Integration (post 811005). 49pp Available at NRC $4 75 18502 277

8305180796 NUREG-0941
THE NRC'S LIMIT ON INTAKE OF URANIUM ORE DUST
MCGUIRE, S A Division of Facility Operations 83/04/30 30pp Available at NRC $3 50 18504 327

8305180854 Forwards safety evaluation of util submittals re NUREG-0737, Items II F 1 4, II F 1 5 & II F 1 6 on containment pressure, water level & hydrogen monitors Requirements resolved Equipment environ qualification to be reviewed separately
VARGA, S A Operating Reactors Branch 1 83/05/02 UHRIG, R E Florida Power & Light Co 2pp 18506 031 24X
Fiche 50-250, 83/05/02, 8305180854

--8305180856 Safety evaluation of util submittals re NUREG-0737, Items II F 1 4 re containment pressure monitor, II F 1 5 on containment water level monitor & II F 1 6 re containment hydrogen monitor Licensee design acceptable
* Office of Nuclear Reactor Regulation, Director 83/05/02 5pp. 18506 033 24X Fiche 50-250, 83/05/02, 8305180854

8305190031 Forwards IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/05 POLLOCK, M S Long Island Lighting Co 2pp 18502 043 24X
Fiche 50-322, 83/05/05, 8305190031

---8305190038 IE Insp Rept 50-322/83-09 on 830412-15 No noncompliance noted Major areas inspected NUREG-0737 items, followup on previous insp findings & review of licensee controls over portable radio transmissions in plant areas
WIGGINS, J T , GALLO, R M Region 1, Office of Director 83/05/03 13pp 18502 045 24X Fiche 50-322, 83/05/05, 8305190031

8305190032 Forwards response to outstanding environ qualification items identified in Section 7 8 of Suppl 6 to SER & technical evaluation rept Info supports full power licensing
TUCKER, H B Duke Power Co 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E. G Licensing Branch 4 5pp 18502 058 24X Fiche 50-370, 83/05/12, 8305190032

8305190096 Advises of NRC evaluation findings of automatic depressurization sys logic mod options in response to TMI Action Item II K 3 18 Util should advise NRC of which action will be implemented & furnish necessary design & info
YOUNGBLOOD, B J Licensing Branch 1 83/04/27. EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18523 194 24X
Fiche 50-440, 83/04/27, 8305190096

8305190099 Forwards safety evaluation for TMI Action Items I A 2 1 4, "Upgrading of Reactor Operator & Senior Reactor Operator Training" & II B 4, "Training for Mitigating Core Damage " Training & requalification programs acceptable
VASSALLO, D B Operating Reactors Branch 2 83/04/29 UTLEY, E E Carolina Power & Light Co 3pp 18523 175. 24X
Fiche 50-324, 83/04/29, 8305190099.

8305190147 Discusses issuance of revised policy statement re util position on NUREG-0737, Item I.C 6, "Verify Performance of Operating Experience " Policy will be integrated into existing operations procedure by 830812
HARRINGTON, W D Boston Edison Co 83-126 83/05/13 VASSALLO, D B Operating Reactors Branch 2 1p 18502 070 24X
Fiche 50-293, 83/05/13, 8305190147

8305190199 Motion to amend petition to intervene by adding Contention SAPL Suppl 7, "Instrumentation for Detection of Inadequate Core Cooling " Good cause exists for late filing Certificate of Svc encl
BACKUS, R A Seacoast Anti-Pollution League BACKUS, R A Backus, Shea & Meyer ISSUANCES OL 83/05/16 Atomic Safety and Licensing Board Panel 5pp 18502 205 24X Fiche 50-443, 83/05/16, 8305190199

8305190253 Informs of status of NUREG-0737, Item II F 1 3 re containment high-range radiation monitors Qualified in-containment electrical terminations will be made per IE Bulletin 79-01B & NUREG-0588 schedule
STEWART, W L Virginia Electric & Power Co IEB-79-01B 83/05/12 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 1p 18501 283 24X
Fiche 50-339, 83/05/12, 8305190253

8305190343 Forwards Rev 1 to NUREG-0728, "NRC Incident Response Plan," in response to 830429 ltr requesting updated ltr of agreement W/o encl
HIND, J A Division of Radiological & Materials Safety Programs, 83/05/13 LARSON, C E Northern States Power Co 2pp 18500-225. 24X Fiche 50-000, 83/05/13, 8305190343

8305200021 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/12 FAY, C W Wisconsin Electric Power Co 3pp 18540 114 24X
Fiche 50-266, 83/05/12, 8305200021

8305200023 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/13. MUSOLF, D. M Northern States Power Co 3pp 18540 117 24X
Fiche 50-282, 83/05/13, 8305200023

8305200030 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/12 WITHERS, B D. Portland General Electric Co 3pp 18540 120. 24X
Fiche 50-344, 83/05/12, 8305200030

8305200060 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1 Item closed
CLARK, R A Operating Reactors Branch 3 83/05/11 JONES, W. C Omaha Public Power District 3pp 18540 123 24X
Fiche 50-285, 83/05/11, 8305200060

8305200068 Informs that 830405 methodology submittal re radiation environ for equipment qualification inside containment acceptable, per NUREG-0588 Submittal also provides ref for radiation levels outside containment
CLARK, R A Operating Reactors Branch 3 83/05/13. GARRITY, J H Maine Yankee Atomic Power Co 2pp 18540 128 24X
Fiche 50-309, 83/05/13, 8305200068

8305200090 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/11 UHRIG, R E Florida Power & Light Co 3pp 18541 001 24X
Fiche 50-335, 83/05/11, 8305200090

8305200094 Notifies that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plants to App E, 10CFR50," completed Item closed
CLARK, R A Operating Reactors Branch 3 83/05/10 STEWART, W L Virginia Electric & Power Co 3pp. 18540 355 24X
Fiche 50-338, 83/05/10, 8305200094

8305200122 Forwards DES & FR notice W/o DES
KNIGHTON, G W Licensing Branch 3 83/05/12 UTLEY, E. E Carolina Power & Light Co. 2pp 18528 346 24X Fiche. 50-400, 83/05/12, 8305200122

--8305200125 Notice of availability of DES
KNIGHTON, G W Licensing Branch 3 83/05/12 2pp 18528 348 24X Fiche 50-400, 83/05/12, 8305200122

8305200195 Supports util onsite emergency preparedness & upgraded plan per NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 " Item complete
VARGA, S A Operating Reactors Branch 1 83/05/11 CAREY, J J. Duquesne Light Co 3pp 18540 222 24X Fiche 50-334, 83/05/11, 8305200195

8305200198 Draft Commission paper re NRC intention to publish NUREG-0906, "Guidance for Implementation of 10CFR50 34(g)," rule requiring applicants to evaluate differences from SRP.
DIRCKS, W J Office of the Executive Director for Operations 83/05/02 21pp 18540 247

--8305200204 Forwards draft Commission paper advising of NRC intent to publish NUREG-0906, "Guidance for Implementation of 10CFR50 34(g) "
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/04/21 DIRCKS,W J Office of the Executive Director for Operations 3pp 18540 266

8305200246 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737,Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved
VASSALLO,D B Operating Reactors Branch 2 83/05/05 BAYNE,J P Power Authority of the State of New York 5pp 18540 206 24X Fiche 50-333,83/05/05,8305200246

8305200435 Forwards revised & reformatted comprehensive list of NUREG-0737 licensing issues containing status & priority assigned for open items
ZIMMERMAN,S R Carolina Power & Light Co LAP-83-180 83/05/17
VARGA,S A Operating Reactors Branch 1 11pp 18517 134 24X Fiche 50-261,83/05/17,8305200435

8305200502 Forwards master lists & sys component evaluation worksheets for NUREG-0737 environ qualification of electrical equipment mods installed in harsh area
HUKILL,H D General Public Utilities - GPU Service Corp
5211-83-076 83/05/16 STOLZ,J F Operating Reactors Branch 4
83pp 18513.082 24X Fiche 50-289,83/05/16,8305200502

8305200516 Forwards order confirming util commitments on post-TMI-related issues Order based on commitments in util 820317 & 0505 ltrs responding to Generic Ltrs 82-05 & 82-10
HADSEN,O L Region 4, Office of Director GL-82-05 83/04/27
LEE,O R Public Service Co of Colorado 4pp 18516 045 24X Fiche 50-267,83/04/27,8305200516

--8305200528 Order confirming licensee commitments on post-TMI-related issues Schedule changes acceptable for TMI Items 1 A 3 1, II.B.2,II B 3,II B.4 & II F 1
GAGLIARDO,J.E. Division of Resident, Reactor Project & Engineering Programs 83/04/27 Public Service Co of Colorado 11pp 18516 049 24X Fiche:50-267,83/04/27,8305200516

8305200517 Forwards list of additions & deletions of safety-related shock suppressors installed to conform w/acceptance criteria in NUREG-0661.Proposed change to Tech Specs will be submitted by 830601
SINCLAIR,J.B Vermont Yankee Nuclear Power Corp FVY 83-37
83/05/17. VASSALLO,D B Operating Reactors Branch 2 3pp 18516:080 24X Fiche 50-271,83/05/17,8305200517

8305200568 Forwards amended Table 3-1 of Section II F.2,App B reflecting clarification of addressing TMI Action Item II F 2 re inadequate core cooling detection instrumentation, Open Item 4 of CESSAR-F SER
SCHERER,A E Combustion Engineering, Inc. LD-83-046 83/05/13
EISENHUT,D G. Division of Licensing 4pp 18514 279 24X Fiche:50-470,83/05/13,8305200568

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876).Supporting documentation encl
REED,C. Commonwealth Edison Co 6434N 83/05/11 DENTON,H R Office of Nuclear Reactor Regulation, Director 10pp 18521 085 24X Fiche 50-000,83/05/11,8305200621

--8305200655 Rept of 810929-30 audit to verify Sargent & Lundy conformance to NUREG-0588 re environ qualification of Class IE electrical equipment.
MARCUS,G.F Commonwealth Edison Co 81/10/06 6pp. 18522 150 24X Fiche 50-000,83/05/11,8305200621

8305200707 Forwards request for addl info on NUREG-0737,Item II K 3 28 re qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO,D B Operating Reactors Branch 2 83/05/11. FARRAR,D L Commonwealth Edison Co. 3pp 18528 350 24X Fiche:50-000,83/05/11, 8305200707.

8305230005 FOIA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp
SHOLLY,S C Union of Concerned Scientists FIN B-8178
NRC-19-82-493. 83/03/11 FELTON,J.M Division of Rules and Records. 1p. 18546.262

8305230028 Responds to FOIA request for all correspondence & repts re NRC Contract NRC-19-82-493, "Expert Opinion on Use of PRA & Safety Goals," between NRC Ofc of Policy Evaluation & NUS Corp.Forwards App A documents
FELTON,J M Division of Rules and Records FIN B-8178.
NRC-19-82-493 83/03/31. SHOLLY,S.C Union of Concerned Scientists 2pp. 18546 263

--8305230039 Comments on NUREG-0880, "Safety Goals for Nuclear Power Plants Discussion Paper," Feb 1982 Proposed policy does not contain independent numerical guideline for early fatality societal risk
LEVINE,S NUS Corp CQ-SL-98-82 82/05/26 REMICK,F J Office of Policy Evaluations 9pp 18546 265

--8305230047 Advises that S Levine directed to provide followup discussion & advice on safety goals re 820526 written rept & 820715 meeting w/F Remick providing advice on use of PRA, per Article I of Contract NRC-19-82-493
MONTGOMERY,J M Office of Policy Evaluations NRC-19-82-493
82/07/19 Office of Policy Evaluations 1p 18546 274

--8305230057 Forwards matl from G Kaiser re calculation of individual & societal risks for comparison w/safety goals Requests meeting w/G Kaiser & R Bland to discuss differences in predictions of weighted individual risk requested
LEVINE,S NUS Corp CQ-SL-98-82 82/11/18 ZERBE,J E Office of Policy Evaluations 28pp 18546 275

8305230115 Forwards safety evaluation of util submittal re procedure verification & design mod per NUREG-0737,Item II K 3 22, "Automatic Switchover of RCIC Suction " Item resolved
VASSALLO,D B Operating Reactors Branch 2 83/05/05 SINCLAIR,J B Vermont Yankee Nuclear Power Corp 5pp 18546 344 24X Fiche 50-271,83/05/05,8305230115

8305230127 Forwards emergency operating procedures generation package, per NUREG-0737,Suppl I (Generic Ltr 82-33) "Requirements for Emergency Response Capability "
GARRITY,J H Maine Yankee Atomic Power Co GL-82-33 83/05/17
CLARK,R A Operating Reactors Branch 3 3pp 18531 263 24X Fiche 50-309,83/05/17,8305230127

8305230128 Forwards SER supporting licensee compliance w/NUREG-0737, Item II B 2 2, "Required Plant Mods." & design review of plant shielding requirements for access to vital areas
CLARK,R A Operating Reactors Branch 3 STOLZ,J F Operating Reactors Branch 4 83/05/11 GRIFFIN,J M Arkansas Power & Light Co 2pp 18546 349 24X Fiche 50-313,83/05/11,8305230128

--8305230145 Safety evaluation supporting licensee compliance w/NUREG-0737,Item II B 2, "Design Review of Plant Shielding Access to Vital Areas "
* Office of Nuclear Reactor Regulation, Director 83/05/11 2pp 18546 351 24X Fiche:50-313,83/05/11,8305230128

8305230230 Advises that Tech Specs from Amends 47 & 36 re auxiliary feedwater sys surveillance satisfy open item noted in 820702 SER on NUREG-0737,Item II E 1 2, "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication "
VARGA,S A Operating Reactors Branch 1 GL-82-16 83/05/16
CARFY,J J Duquesne Light Co 2pp 18543 152 24X
Fiche 50-334,83/05/16,8305230230.

8305230242 Forwards safety evaluation of util 820831 submittal re procedure verification & design mod per NUREG-0737,Item II.K 3 22, "Automatic Switchover of RCIC Suction " Requirements met
VASSALLO,D B Operating Reactors Branch 2 83/05/05 PILANT,J M Nebraska Public Power District 5pp 18543 232 24X
Fiche 50-298,83/05/05,8305230242

8305230248 Forwards safety evaluation supporting resolution of NUREG-0737,Item II K 3 22, "Automatic Switchover of RCIC Suction," based on review of util 811231 & 820908 submittals re procedure verification & design mod
VASSALLO,D B Operating Reactors Branch 2 83/05/05 MUSOLF,D M Northern States Power Co. 5pp 18543 244 24X
Fiche 50-263,83/05/05,8305230248

8305230276 Forwards "Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept Response within 60 days of receipt of ltr requested
CRUTCHFIELD,D Operating Reactors Branch 5 LS05-83-05-044
83/05/19. COUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 18539 006. 24X Fiche 50-213,83/05/19,8305230276

--8305230284 TER-C5506-358 DRFT
"Control of Heavy Loads (C-10) Haddam Neck Plant," draft technical evaluation rept
BOMBERGER,C ; AHMED,N Franklin Institute/Franklin Research Center NRC-03-81-130 83/02/15 CLEMENSON,F. NRC - No Detailed Affiliation Given 35pp 18539 008 24X Fiche 50-213,83/05/19, 8305230276

8305230279 Forwards safety evaluation of plant mods & design review of shielding for vital areas per NUREG-0737,Item II B 2 2 Required mods completed & acceptable.
VASSALLO,D B Operating Reactors Branch 2 83/05/05 SINCLAIR,J B Vermont Yankee Nuclear Power Corp 6pp 18543 268 24X
Fiche 50-271,83/05/05,8305230279

8305230312 Forwards request for addl info needed to complete review of util 810515 response to NUREG-0737, Item II K 3 28, "Qualification of ADS Accumulators " Response requested within 45 days of receipt of ltr
VASSALLO, D B Operating Reactors Branch 2 83/05/11 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp 18543 301 24X
Fiche 50-271, 83/05/11, 8305230312

8305230323 Forwards emergency procedures generation package containing procedure guidelines, writers guide & training program in response to NUREG-0737, Suppl 1 (Generic Ltr 82-33), "Requirements for Emergency Response Capability "
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities A02959 83/05/13
CRUTCHFIELD, D Operating Reactors Branch 5 1p 18538 264 24X
Fiche 50-245, 83/05/13, 8305230323

8305230503 Summary of CROR Meeting 35 on 830425 re Salem Generic Implications Task Force findings, per NUREG-1000
STELLO, V Committee to Review Generic Requirements 83/05/13
DIRCKS, W J Office of the Executive Director for Operations 4pp 18537 164

8305230541 Advises that util endorses BWR Owners Group rept NEDO-2209, "Analysis of Scram Discharge Vol Sys Piping Integrity " Proposed amend to License NPF-14 will be submitted to reflect position
CURTIS, N W Pennsylvania Power & Light Co PLA-1669 83/05/19
SCHWENCER, A Licensing Branch 2 2pp 18537 335 24X
Fiche 50-387, 83/05/19, 8305230541

8305230583 Forwards backfit cost info in response to 830208 ltr Two 3,500 kW standby diesel generators, diesel generator bldg, auxiliary bldg addition, associated electrical equipment & new computer sys added per NUREG-0737
MATTIMOE, J J Sacramento Municipal Utility District 83/03/16
TOURTELLOTTE, J Regulatory Reform Task Force 4pp 18541 318 24X
Fiche 50-312, 83/03/16, 8305230583

8305230584 Submits editorial rev to Specific Action 10 per 821228 response to Generic Ltr 81-04 re measures to minimize intergranular stress corrosion cracking General & specific corrective actions discussed NUREG-0313 compliance achieved
SCHROEDER, C W Commonwealth Edison Co GL-81-04 83/05/19
LAINAS, G C Licensing Branch 2 4pp 18537 313 24X
Fiche 50-373, 83/05/19, 8305230584

8305230639 Advises that NRC has considered & reviewed constituent HD Turner comments on 830228 New Yorker magazine article on safety goal program Misleading impressions corrected
DIRCKS, W J Office of the Executive Director for Operations 83/05/05 JACKSON, H M Senate 22pp 18576 336

8305230645 Forwards NUREG-0887, Suppl 3 to SER W/o encl
YOUNGBLOOD, B J Licensing Branch 1 83/05/09 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18542 360 24X
Fiche 50-440, 83/05/09, 8305230645

8305240015 NUREG/CR-3230
EFFECTS OF TEMPERATURE ON FATIGUE CRACK GROWTH OF A508-2 STEEL IN LWR ENVIRONMENT
CULLEN, W H Materials Engineering Testing Services, Inc
TORRONEN, K , DEMPPAINEN, M Finland FIN B-8133 MEA-2013
83/04/30 Division of Engineering Technology 38pp Available at NRC $4 50 18594 172

8305240022 Forwards Suppl 2 to SER (NUREG-0968) re evaluation of addl info on previously identified outstanding review items
GRACE, J N Clinch River Breeder Reactor Program Office 83/05/20,
LONGENECKER, J Energy, Dept of, Clinch River Breeder Reactor Plant 16pp 18577 314 24X Fiche 50-537, 83/05/20, 8305240022.

8305240036 Forwards request for OMB review & supporting statement re NUREG-0737, TMI action plan
NORRY, P G. Office of Administration 83/05/19 SCURRY, N Office of Management & Budget 1p 18594 260

8305240097 Informs that License Condition 2 C (11)g on NUREG-0737, Item II K 3 10, "Anticipatory Reactor Trip," satisfied Safety evaluation encl
NOVAK, T M Assistant Director for Licensing 83/05/17 TUCKER, H B. Duke Power Co 6pp 18594 125 24X Fiche 50-369, 83/05/17, 8305240097

8305240195 Forwards summary of NUREG-0737 Tech Spec review to determine consistency w/guidance criteria provided in 830110 Generic Ltr 83-02
SINCLAIR, J B Vermont Yankee Nuclear Power Corp GL-83-02. 83/05/17 VASSALLO, D B Operating Reactors Branch 2 5pp 18548 032 24X Fiche 50-271, 83/05/17, 8305240195

8305240198 Provides info re emergency operations facility in response to NRC request When control room HVAC is upgraded as result of NUREG-0737, Item III D 3 4, technical support ctr HVAC will be reviewed to ensure uniformity of design
BASKIN, K P Southern California Edison Co 83/05/20
CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18548 010 24X
Fiche 50-206, 83/05/20, 8305240198

8305240246 Advises that requirements of NUREG-0737, Item III A. 2 1, "Emergency Preparedness, Upgrade Emergency Plans to Meet App E to 10CFR50," satisfied
VARGA, S A Operating Reactors Branch 1 83/05/16 FARRAR, D L Commonwealth Edison Co 3pp 18593 303 24X Fiche 50-295, 83/05/16, 8305240246

8305240249 FOIA request for three categories of documents re Reactor Safety Study Methodology Application Program (NUREG/CR-1659, Vols 1-4) & Interim Reliability Evaluation Program (NUREG/CR-2515, 2787 & 2802)
SHOLLY, S C Union of Concerned Scientists 83/03/11 FELTON, J. M. Division of Rules and Records 1p 18593 178 24X
Fiche 50-000, 83/03/11, 8305240249

8305240254 Partial response to FOIA request for three categories of documents re Reactor Safety Study Methodology Application & Interim Reliability Evaluation Program repts Forwards App A documents Search for addl documents in progress.
FELTON, J M Division of Rules and Records. 83/03/31 SHOLLY, S. C Union of Concerned Scientists 2pp 18593 179 24X
Fiche 50-000, 83/03/31, 8305240254

8305240284 Forwards IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted
PAPERIELLO, C J Region 3, Office of Director 83/05/18. LIU, L Iowa Electric Light & Power Co 2pp 18548 088 24X
Fiche 50-331, 83/05/18, 8305240284

--8305240292 IE Insp Rept 50-331/83-05 on 830321-25 No noncompliance noted Major areas inspected radiation protection program for operation & refueling, including organization & staffing, staff qualifications, training & outage planning.
HUETER, L J , PAUL, R A , GREGER, L R Region 3, Office of Director, 83/05/17 17pp 18548 090 24X Fiche 50-331, 83/05/18, 8305240284

8305240328 Forwards, "Identification & Listing of Electrical Equipment Important to Safety per 10CFR50, 49 " Nonsafety-related electric equipment w/failure that would prohibit accomplishment of safety functions not identified
BAYNE, J P Power Authority of the State of New York IPN-83-45 83/05/20 VARGA, S A Operating Reactors Branch 1 36pp. 18549 239 24X Fiche 50-286, 83/05/20, 8305240328

8305240343 Withdraws commitment re NUREG-0737, Item I A I 3, "Licensing Exam Criteria " Recommendations to delete requirement for use of simulator exam as part of operator license exam program approved per 821012 Generic Ltr 82-18 & SECY 82-232
HEIDER, L H Vermont Yankee Nuclear Power Corp 2 C 2 1, 83/05/19
VASSALLO, D B Operating Reactors Branch 2 2pp 18572:359 24X
Fiche 50-271, 83/05/19, 8305240343

8305240360 Informs that response to NUREG-0737, Item II.E.1 2, "Emergency Feedwater Sys Automatic Initiation & Flow Indication," per 830411 request, will be provided by 830614, Change discussed w/E Tourigny
MARSHALL, J R Arkansas Power & Light Co 2CAN058306 83/05/17
CLARK, R A Operating Reactors Branch 3 1p. 18574:002 24X
Fiche 50-368, 83/05/17, 8305240360

8305240372 Forwards responses to NRC 830118 request for info re accident monitoring, to aid in post-implementation review of NUREG-0737, Items II F 1 4, II F.1 5 & II F 1.6.
UHRIG, R E Florida Power & Light Co L-83-10 83/05/19.
CLARK, R. A Operating Reactors Branch 3 17pp 18575 078 24X
Fiche 50-335, 83/05/19, 8305240372

8305240399 Discusses 830315 commitment to provide results of B&W supplemental ECCS calculations addressing impact of cladding models presented in NUREG-0630, "Results of Bounding Analysis " Revised NUREG-0630 being prepared by B&W
MARSHALL, J R Arkansas Power & Light Co. 1CAN058304 83/05/18
STOLZ, J F Operating Reactors Branch 4. 2pp 18571.042. 24X
Fiche 50-313, 83/05/18, 8305240399

8305240447 Provides status of implementation of SER recommendations re NUREG-0737, Item II.K 3 16, "Feasability Study - Challenges & Valve Failures " Preventive maint program will be available for site review in 2 months.
SMITH, J L Long Island Lighting Co SNRC-893 83/05/20
DENTON, H R. Office of Nuclear Reactor Regulation, Director. 3pp. 18572 338 24X Fiche 50-322, 83/05/20, 8305240447

8305240458 Forwards status of environ qualification of electrical equipment per 10CFR50 49(g) All equipment,except auxiliary feedwater pump motors,meets NUREG-0588 guidelines for Category II plant
BASKIN,K P Southern California Edison Co 83/05/20 KNIGHTON,G W Licensing Branch 3 3pp 18549 286 24X Fiche 50-361,83/05/20, 8305240458

8305240557 Informs that NUREG-0737,Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl
VASSALLO,D B Operating Reactors Branch 2 83/05/18 MUSOLF,D M Northern States Power Co 7pp 18593 290 24X
Fiche 50-263,83/05/18,8305240557

8305240560 Informs that NUREG-0737,Item II F 1, "Containment High Range Radiation Monitor," completed Item closed Safety evaluation encl
VASSALLO,D B Operating Reactors Branch 2 83/05/13 MORISI,A V Boston Edison Co 4pp 18593 356 24X Fiche 50-293,83/05/13, 8305240560

8305240564 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 LIU,L Iowa Electric Light & Power Co 3pp 18593 348 24X
Fiche 50-331,83/05/18,8305240564

8305240571 Notifies that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2, 83/05/18
HARRINGTON,W D Boston Edison Co 3pp 18594 217 24X
Fiche 50-293,83/05/18,8305240571

8305240572 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 MUSOLF,D M Northern States Power Co 3pp 18593 345 24X
Fiche,50-263,83/05/18,8305240572

8305240573 Notifies that NUREG-0737,Item II K 3 45, "Depressurization w/Other than Automatic Depressurization Sys," completed Item closed Safety evaluation encl
VASSALLO,D B Operating Reactors Branch 2 83/05/18 FARRAR,D L Commonwealth Edison Co. 7pp 18593 338 24X Fiche 50-254,83/05/18, 8305240573

8305240576 Informs that NUREG-0737,Item III A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 RHODE,G K Niagara Mohawk Power Corp 3pp 18594 214 24X
Fiche 50-220,83/05/18,8305240576

8305240591 Informs that NUREG-0737,Item III.A 2 1, "Emergency Preparedness,Upgrade Emergency Plans to App E,10CFR50," completed Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 SINCLAIR,J B Vermont Yankee Nuclear Power Corp 3pp 18594 211 24X
Fiche,50-271,83/05/18,8305240591

8305250082 Forwards Suppl 3 to SER (NUREG-0892) W/o encl
SCHWENCER,A Licensing Branch 2 83/05/19 FERGUSON,R L. Washington Public Power Supply System 2pp 18596 307 24X
Fiche,50-397,83/05/19,8305250082

8305250136 Forwards request for addl info re NUREG-0737,Item II K 3 28, "Qualification of ADS Accumulators " Info requested within 45 days.
VASSALLO,D B Operating Reactors Branch 2 83/05/11 PARRIS,H G Tennessee Valley Authority 3pp 18596 204 24X
Fiche:50-259,83/05/11,8305250136

8305250137 Informs that NUREG-0737 Item III A 2.1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility.Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 BAYNE,J.P Power Authority of the State of New York 3pp 18596 201. 24X
Fiche 50-333,83/05/18,8305250137

8305250141 Informs that NUREG-0737,Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed.
VASSALLO,D B Operating Reactors Branch 2 83/05/18 FARRAR,D L Commonwealth Edison Co 3pp 18596 198 24X Fiche 50-254,83/05/18, 8305250141.

8305250145 Informs that NUREG-0737,Item III A 2 1 re emergency plan upgrade to meet 10CFR50 App E requirements complete for facility Item closed
VASSALLO,D B Operating Reactors Branch 2 83/05/18 PILANT,J M Nebraska Public Power District 3pp 18596 195 24X
Fiche 50-298,83/05/18,8305250145

8305250166 Forwards Suppl 1 to SER (NUREG-0968) re evaluation of addl info on previously identified as outstanding review items since preparation of SER Response to comments for ACRS 830419 rept to Commission also encl W/o encls
GRACE,J N Clinch River Breeder Reactor Program Office 83/05/19
LONGENECKER,J Energy, Dept of, Clinch River Breeder Reactor Plant 2pp 18596 140 24X Fiche 50-537,83/05/19,8305250166

8305250183 Forwards IE Insp Rept 50-289/83-10 on 830420-22 & 25-28 Joint headquarters/Region I insp initiated to evaluate effectiveness of GPU actions to ensure adherence to procedures since issuance of NUREG-0080,Suppl J
REHM,T A Office of the Executive Director for Operations 83/05/18 PALLADINO,N J , GILINSKY,V , AHEARNE,J Commissioners 1p 18596 001 24X Fiche 50-289,83/05/18,8305250183

8305250224 Forwards IE Insp Rept 50-286/83-05 on 830328-31 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/13
BRONS,J C Power Authority of the State of New York 2pp 18627 017 24X Fiche 50-286,83/05/13,8305250226

--8305250230 IE Insp Rept 50-286/83-05 on 830328-31 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements of NUREG-0737,Item II B 2, "Design Review of Plant Shielding "
HAVERKAMP,D R , KENNY,T J , EAPEN,P K Region 1, Office of Director 83/05/12 12pp 18627 019 24X Fiche 50-286,83/05/13, 8305250226

8305250231 Summary of Power Sys Branch 830405-09 site audit re power supply for auxiliary feedwater sys per SER Confirmatory Issues 15,17 & 23 (Section 1 7 of NUREG-0830)
EDISON,G E , HOLONICH,J J Licensing Branch 1 83/05/12
YOUNGBLOOD,B J Licensing Branch 1 7pp 18627 100 24X
Fiche 50-000,83/05/12,8305250231

8305250266 Forwards Draft 7 of Rev 3 to NUREG-0742, "Std Radiological Effluent Tech Specs for PWRs," as guidance in developing final submission of radiological effluent Tech Specs Tech Specs requested within 60 days W/o encl
VASSALLO,D B Operating Reactors Branch 2 83/05/18 PILANT,J M Nebraska Public Power District 2pp 18595 336 24X
Fiche 50-298,83/05/18,8305250266

8305250285 Forwards response to 830204 SERs & NRC 830412 ltr re environ qualification of safety-related electrical equipment Util plans to address remaining outstanding action items included
CLAYTON,F L Alabama Power Co 83/05/20 VARGA,S A Office of Nuclear Reactor Regulation, Director 118 p 18696 251 24X
Fiche 50-348,83/05/20,8305250285

8305250294 Memorandum of law supporting motions for summary disposition of emergency planning issues Hearing time should not be spent on baseless allegations Notice of appearance encl
BAXTER,T A Union Electric Co BAXTER,T A Shaw, Pittman, Potts & Trowbridge ISSUANCES OL 83/05/20 Atomic Safety and Licensing Board Panel 14pp 18585 001 24X Fiche 50-483,83/05/20, 8305250294

--8305250587 Affidavit of WM Clark re Reed Contention 20 on authorization of excess exposures to workers & spec of decontamination action levels Planning need for authorization per NUREG-0654,Section III E 3,met Prof qualifications encl
CLARK,W M Union Electric Co CLARK,W M Callaway County, MO
ISSUANCES OL 83/05/18 7pp 18587 273 24X
Fiche 50-483,83/05/20,8305250294

8305250377 Forwards "GE-NEBS Electrical Penetration Assembly Qualification Program," Vols 1 & 2 to "Response to IE Bulletin 79-01B Quad Cities Nuclear Power Station Units 1 & 2" & Vols 1 & 2 to "Response to IE Bulletin 79-01B "
RYBAK,B Commonwealth Edison Co IEB-79-01B 83/05/19
DENTON,H R Office of Nuclear Reactor Regulation, Director, 2,118pp 18578 001 24X Fiche 50-000,83/05/19,8305250377

8305250437 Forwards IE Insp Rept 50-245/83-07 on 830411-14 No noncompliance noted
STAROSTECKI,R Division of Project & Resident Programs 83/05/11
COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588 075 24X Fiche 50-245,83/05/11,8305250437

--8305250443 IE Insp Rept 50-245/83-07 on 830411-14 No noncompliance noted Major areas inspected actions taken to comply w/NUREG-0737, Item II B 2, "Design Review of Plant Shielding "
BRIGGS, L , EAPEN, P , PLISCO, L Region 1, Office of Director
83/05/09 6pp 18588 077 24X Fiche 50-245, 83/05/11, 8305250437

8305250459 Forwards IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/11
COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18588 096 24X Fiche 50-336, 83/05/11, 8305250459

--8305250465 IE Insp Rept 50-336/83-09 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements discussed in NURG-0737, Item II B 2 re design review of plant shielding
LAZARUS, W J , HAVERKAMP, D R , EAPEN, P K Region 1, Office of Director 83/05/09 6pp 18588 098 24X Fiche 50-336, 83/05/11, 8305250459

8305250472 Forwards "St Lucie Units 1 & 2 & Turkey Point Units 3 & 4 Detailed Control Room Design Reviews Program Plan," per 830415 commitment re Suppl 1 to NUREG-0737
UHRIG, R E Florida Power & Light Co L-83-313 83/05/20
EISENHUT, D G Division of Licensing 1p 18588 333 24X
Fiche 50-000, 83/05/20, 8305250472

8305250479 Forwards responses to 830411 ltr re environ qualification of safety-related electrical equipment Justification for continued operation, per NUREG-0737, TMI Action Item II D 4 provided Response to IE Bulletin 79-01B will be revised
TUCKER, H B Duke Power Co IEB-79-01B 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 18589 005 24X Fiche 50-269, 83/05/19, 8305250479

8305250497 Forwards IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted
STAROSTECKI, R Division of Project & Resident Programs 83/05/11
COUNSIL, W G Connecticut Yankee Atomic Power Co 2pp 18588 255 24X Fiche 50-213, 83/05/11, 8305250497

--8305250504 IE Insp Rept 50-213/83-12 on 830411-14 No noncompliance noted Major areas inspected licensee actions taken to comply w/requirements described in NUREG-0737, Item II B 2, "Design Review of Plant Shielding "
BAUNACK, W H , EAPEN, P K , PLISCO, L R Region 1, Office of Director 83/05/10 9pp 18588 257 24X Fiche 50-213, 83/05/11, 8305250497

8305250514 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action on item complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 RHODE, G K Niagara Mohawk Power Corp 2pp 18595 310 24X
Fiche 50-220, 83/05/18, 8305250514

--8305250523 Safety evaluation supporting BWR Owners Group generic response to Item II K 3 45 of NUREG-0737, "Depressurization W/Other Than Automatic Depressurization Sys."
NRC - No Detailed Affiliation Given 83/05/18 5pp 18595 312 24X Fiche 50-220, 83/05/18, 8305250514

8305250556 Notifies that noble gas monitor-stack high-range radiation monitor (NUREG-0737, Item II F 1(1)) reported as being operable in 830318 order, became inoperable on 830426 Caused by moisture contamination New monitors ordered
TUCKER, H B Duke Power Co 83/05/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18588 185 24X
Fiche 50-269, 83/05/19, 8305250556

8305260008 Comments on recent work & proposed programs re accident sequence precursor study & use of operational experience, at 276th & 277th ACRS meetings on 830414-16 & 0512-14 respectively
EBERSOLE, J C ACRS - Advisory Committee on Reactor Safeguards 83/05/18 DIRCKS, W J Office of the Executive Director for Operations 7pp 18649 098

8305260037 Forwards supplemental responses to Power Sys Branch questions re GESSAR-II ac/dc power sys/balance-of-plant interfaces Responses will be included w/Amend 15 to SER
SHERWOOD, G G General Electric Co MFN 091-83 83/05/24
EISENHUT, D G. Division of Licensing 10pp 18622 310 24X
Fiche. 50-447, 83/05/24, 8305260037

--8305260048 Forwards draft Amend 15 to GESSAR-II Amend resolves selected outstanding & confirmatory issues identified in SER (NUREG-0979) & completes Subsection 1 9 1 on GESSAR-II/FSAR interfaces
SHERWOOD, G G General Electric Co MFN 090-83 83/05/24
EISENHUT, D G Division of Licensing 446pp 18622 320 24X
Fiche 50-447, 83/05/24, 8305260037

8305260094 Provides info identifying electrical equipment important to safety within scope of 10CFR50 49(g) already qualified Schedules for qualification of post-accident instrumentation encl
HUKILL, H D General Public Utilities - GPU Service Corp
5211-83-157 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp, 18599 314 24X Fiche 50-289, 83/05/20, 8305260094

8305260114 Informs that response to NUREG-0737, Item II K 3 13 re RCIC restart complete for facility, based on 830415 commitment to follow GE Owners Group conceptual design
VASSALLO, D B Operating Reactors Branch 2 83/05/20 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 2pp 18649 065 24X
Fiche 50-271, 83/05/20, 8305260114

8305260130 Informs that NUREG-0737, Item II K 3 45 re depressurization w/other than automatic deppressurization sys would not contribute to plant safety & no plant design or operation mod required Safety evaluation encl
VASSALLO, D B Operating Reactors Branch 2 83/05/18
HARRINGTON, W D Boston Edison Co 2pp 18649 052 24X
Fiche 50-293, 83/05/18, 8305260130

8305260134 Informs that NUREG-0737, Item III A 2 1 re emergency plan upgrade to meet 10CFR50, App E requirements complete for facility Item closed
VASSALLO, D B Operating Reactors Branch 2 83/05/18 UTLEY, E E Carolina Power & Light Co 3pp 18649 049 24X
Fiche 50-324, 83/05/18, 8305260134

8305260167 Forwards request for addl info re NUREG-0737, Item II K 3.28 on qualification of automatic depressurization sys accumulators Response within 45 days requested
VASSALLO, D B Operating Reactors Branch 2 83/05/11 LIU, L Iowa Electric Light & Power Co 3pp 18648 117 24X
Fiche 50-331, 83/05/11, 8305260167

8305260170 Forwards request for addl info re NUREG-0737, Item II K.3 28 on qualification of automatic depressurization sys accumulators Response requested within 45 days
VASSALLO, D B Operating Reactors Branch 2 83/05/11 PILANT, J.M Nebraska Public Power District 4pp 18648 113 24X
Fiche 50-298, 83/05/11, 8305260170

8305260175 Forwards request for addl info re NUREG-0737, Item II K.3 28 on qualification of automatic depressurization sys accumulators Response within 45 days requested
VASSALLO, D B Operating Reactors Branch 2 83/05/11 MORISI, A V. Boston Edison Co 3pp 18648 110 24X Fiche 50-293, 83/05/11, 8305260175

8305260177 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1.
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PARRIS, H G. Tennessee Valley Authority 3pp 18648 107 24X
Fiche 50-259, 83/05/18, 8305260177

8305260187 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18. PARRIS, H G Tennessee Valley Authority 2pp 18648 099 24X
Fiche 50-259, 83/05/18, 8305260187

8305260192 Forwards safety evaluation re BWR Owners Group response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 LIU, L Iowa Electric Light & Power Co. 2pp 18648 089 24X
Fiche 50-331, 83/05/18, 8305260192

8305260201 Forwards request for addl info re 811231 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt
VASSALLO, D. B Operating Reactors Branch 2 83/05/11 MUSOLF, D M Northern States Power Co 3pp 18648 067 24X
Fiche 50-263, 83/05/11, 8305260201

8305260207 Forwards revised order confirming licensee commitments on NUREG-0737, Item II F. 1. "Post-Accident Monitoring," per 830331 & 0411 ltrs. Extended completion schedule to 840515 acceptable.
VARGA, S A Operating Reactors Branch 1 GL-82-05 83/05/11.
UHRIG, R E Florida Power & Light Co 3pp. 18629 340. 24X
Fiche 50-250, 83/05/11, 8305260207

--8305260211 Revised order confirming licensee commitments on post-TMI related issues
EISENHUT, D G Division of Licensing GL-82-05. 83/05/11.
Florida Power & Light Co 9pp 18629 343 24X
Fiche 50-250, 83/05/11, 8305260207

8305260209 Forwards request for addl info re 820401 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 45 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/05/11 BAYNE, J P
Power Authority of the State of New York 3pp 18629 354 24X
Fiche 50-333, 83/05/11, 8305260209

8305260285 Forwards request for addl info re 810123 response to NUREG-0737, Item II K 3 28, "Qualification of Accumulators on Automatic Depressurization Sys " Reply requested within 30 days of ltr receipt
VASSALLO, D B Operating Reactors Branch 2 83/05/11 UTLEY, E E
Carolina Power & Light Co 3pp 18629 337 24X
Fiche 50-324, 83/05/11, 8305260285

8305260290 Commits to resolution of three open items re NUREG-0612, "Control of Heavy Loads," using Quad Cities guidelines Quad Cities analysis to verify stress design factors for dryer/separator lifting rig applicable
RYBAK, B Commonwealth Edison Co 6611N 83/05/19 DENTON, H R
Office of Nuclear Reactor Regulation, Director 1p 18625 354 24X
Fiche 50-237, 83/05/19, 8305260290

8305260294 Forwards response to 830405 draft technical evaluation rept re control of heavy loads Phase I review complete Util position accepted per 830518 telcon
ASH, R E. Baltimore Gas & Electric Co 83/05/24 EISENHUT, D G
Division of Licensing 2pp 18625 161 24X Fiche 50-317, 83/05/24, 8305260294

8305260296 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mod to plant design or operations required Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 SINCLAIR, J B
Vermont Yankee Nuclear Power Corp 2pp 18629 330 24X
Fiche 50-271, 83/05/18, 8305260296

8305260297 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " No mod to plant design or operations required Action complete
VASSALLO, D B Operating Reactors Branch 2 83/05/18 BAYNE, J P
Power Authority of the State of New York 2pp 18629 323 24X
Fiche 50-333, 83/05/18, 8305260297

8305260300 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 45, "Depressurization W/Other Than Automatic Depressurization Sys " Alternative modes would not contribute to plant safety No mods required
VASSALLO, D B Operating Reactors Branch 2 83/05/18 PILANT, J M
Nebraska Public Power District 2pp 18629 316 24X
Fiche 50-298, 83/05/18, 8305260300

8305260322 Response to ASLB 830516 scheduling order Addl statement re NRC use of PRA & rept on NUREG-0737, Item II K 3 18 encl Schedules for NRC issuance of documents discussed at second special prehearing conference valid W/Certificate of Svc
HODGDON, A P Hearing Branch 2 83/05/24 9pp 18625 019 24X
Fiche 50-352, 83/05/24, 8305260322

--8305260327 Forwards evaluation of BWR Owners Group generic response to NUREG-0737, Item II K 3 18, "Mod of Automatic Depressurization Sys Logic - Feasibility for Increased Diversity of Some Event Sequences " Response requested
SCHWENCER, A Licensing Branch 2 83/05/23 BAUER, E G
Philadelphia Electric Co 9pp 18625 028 24X
Fiche 50-352, 83/05/24, 8305260322

--8304140161 Forwards safety evaluation of mods proposed by BWR Owners Group re NUREG-0737, Item II K 3 18, "Mod of ADS Logic " Two options proposed acceptable W/o encl
HOUSTON, R W Assistant Director for Reactor Safety 83/04/01
LAINAS, G C Assistant Director for Safety Assessment 2pp
18625 037 24X Fiche 50-352, 83/05/24, 8305260322

8305270003 Forwards proposed Tech Specs in form of marked-up Rev 4 to NUREG-0452, "STS for Westinghouse PWRs."
TUCKER, H. B Duke Power Co 83/05/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 741pp 18630 001 24X Fiche 50-413, 83/05/20, 8305270003

8305270026 Provides clarification of util position on NUREG-0737, Items I A 1.3, "Min Shift Crew" & III A 1.2, "Staffing Level for Emergency Situations "
MANGAN, C V Niagara Mohawk Power Corp 83/05/24 VASSALLO, D B
Operating Reactors Branch 2 2pp 18638 304. 24X
Fiche 50-220, 83/05/24, 8305270026

8305270030 Forwards response to 830316 request to document compliance w/acceptance criteria & schedule for NUREG-0737, Item II K 3 13, "Separate HPCI & RCIC Initiation Levels " Criteria will be met
MILLS, L M Tennessee Valley Authority 83/05/24 DENTON, H R
Office of Nuclear Reactor Regulation, Director 2pp 18638 306
24X Fiche 50-259, 83/05/24, 8305270030

8305270039 Forwards request for addl info re personnel training as part of NRC review of application for OL
SCHWENCER, A Licensing Branch 2 83/05/23 CAHILL, W J Gulf States Utilities Co 5pp 18662 097 24X Fiche 50-458, 83/05/23, 8305270039

8305270058 Advises that fuel load scheduled for 840815 & commercial operation planned on 850215 NUREG-0737 Suppl 1 (Generic Ltr 82-33) requirements re emergency plans will be met
CADMAN, W K Kansas Gas & Electric Co GL-82-33 83/05/23
DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
18638 250 24X Fiche 50-482, 83/05/23, 8305270058

8305270060 Forwards safety evaluation of util response to SER, NUREG-0916, Item 3 re effluent radioactivity monitoring sys alarm setpoints & surveillance requirements Monitoring sys acceptable
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-058
83/05/26 MAIER, J E Rochester Gas & Electric Corp 4pp
18638 333 24X Fiche 50-244, 83/05/26, 8305270060

8305270077 Advises that NUREG-0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50," complete
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-054
83/05/25 MAIER, J E Rochester Gas & Electric Corp 3pp
18638 153 24X Fiche 50-244, 83/05/25, 8305270077

8305270080 Requests extension to 831015 to provide schedule for accomplishing proposed actions to close outstanding issue re IE Bulletin 79-01B Items Exemptions from 10CFR50 49 & Rev 2 to Reg Guide 1 97.
RODRIGUEZ, R J Sacramento Municipal Utility District IEB-79-01B
83/05/20 STOLZ, J F Operating Reactors Branch 4 2pp 18638 291
24X Fiche 50-312, 83/05/20, 8305270080

8305270082 Updates 830415 ltr re installation & operability of post-accident sampling sys per NUREG-0737, Item II B 3 Items agreed upon at 830512 meeting listed Installation work will be completed during current refueling outage
FIEDLER, P B General Public Utilities - GPU Service Corp 83/05/20
EISENHUT, D G Division of Licensing 2pp 18638 289 24X
Fiche 50-219, 83/05/20, 8305270082

8305270109 NUREG/CP-0043
JOINT NRC/ANS MEETING ON BASIC THERMAL HYDRAULIC MECHANISMS IN LWR ANALYSIS
HSU, Y Y , LEE, R American Nuclear Society 83/04/30 Office of Nuclear Regulatory Research, Director 612pp 18649 112

8305270128 Advises that updating inservice insp program will be delayed until Aug 1983 Commitment to examine control rod drive scram discharge vol piping welds will be met & unaffected by delay in update of inservice insp program
GUCWA, L T Georgia Power Co NED-83-256 83/05/19 STOLZ, J F
Operating Reactors Branch 4 1p 18638 217 24X
Fiche 50-321, 83/05/19, 8305270128

8305270144 Advises that QA program described in NEDO-11209-04A being implemented satisfactorily Results of insp published quarterly in NUREG-0040
COLLINS, J T Division of Vendor & Technical Programs 83/05/24
BRUGGEMAN, W H General Electric Co 2pp 18638 203

8305270170 Forwards "St Lucie 1 & 2 & Turkey Point 3 & 4 Detailed Control Room Design Reviews Program Plan," fulfilling 830415 commitment per NUREG-0737, Suppl 1
UHRIG, R E Florida Power & Light Co L-83-323 83/05/14
EISENHUT, D G Division of Licensing 1p 18638 072 24X
Fiche 50-335, 83/05/14, 8305270170

8305270210 Forwards div input to emergency planning for suppl to SER Matl updates info contained in Section 13 3, "Emergency Planning of Wolf Creek Generating Station SER," (NUREG-0881, Apr 1982)
PAGANO, F G Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/25 YOUNGBLOOD, B J Licensing Branch 1 43pp 18637 261 24X Fiche 50-482, 83/05/25, 8305270210

8305270215 Forwards IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted
DANCE, H C. Division of Project & Resident Programs 83/05/06
UHRIG, R E Florida Power & Light Co 2pp 18637 329. 24X
Fiche: 50-250, 83/05/06, 8305270215

--8305270219 IE Insp Repts 50-250/83-05 & 50-251/83-05 on 830115-0225 No noncompliance noted Major areas inspected followup on previous insp findings, IE bulletins, post-TMI implementation, surveillance testing & maint activities
VOGT-LOWELL, R , AGLES, J A Region 2, Office of Director
JULIAN, C Division of Project & Resident Programs 50-251/83-05
83/05/05 8pp 18637 331 24X Fiche 50-250, 83/05/06, 8305270215

8305270220 Requests extension until 830620 for completion of special lifting rig analysis per NUREG-0612 Extension required due to late receipt of Westinghouse rept
STEWART, W L Virginia Electric & Power Co 322 83/05/20
DENTON, H R Office of Nuclear Reactor Regulation, Director
CLARK, R A Operating Reactors Branch 3 1p 18637 325 24X
Fiche 50-338, 83/05/20, 8305270220

8305270274 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/82-24
Required actions to improve QA program listed
MARTIN, T T Division of Engineering & Technical Programs 83/05/23
MCNEILL, C A Power Authority of the State of New York 2pp
18643 131 24X Fiche 50-333, 83/05/23, 8305270274

--8305270284 Responds to NRC 830128 ltr re violations noted in IE Insp Rept 50-333/82-24 Corrective actions design verification by supervisors in Design & Analysis Procedure 3 11 & 3 18 revised per insp rept Rev to be completed by Apr 1983
BAYNE, J P Power Authority of the State of New York JPN-83-28
83/04/01 HAYNES, R C Region 1, Office of Director 15pp
18643 133 24X Fiche 50-333, 83/05/23, 8305270274

8305270432 Discusses B&W Owners Group emergency procedure guidelines (abnormal transient operating guidelines - ATOG), per 830505 ltr Detailed schedule for expansion of technical bases for procedure will be submitted by end of June
WHITNEY, D D Babcock & Wilcox Operating Plants Owners Group
WHITNEY, D D Sacramento Municipal Utility District GL-82-33
83/05/21 EISENHUT, D G Division of Licensing 2pp 18642 289

8305270479 Ack receipt of 830325 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-02
LEWIS, R C Division of Project & Resident Programs 83/04/07
UTLEY, R E Carolina Power & Light Co 2pp 18644 032 24X
Fiche 50-261, 83/04/07, 8305270479

--8305270506 IE Insp Rept 50-261/83-02 on 830110-0210 Noncompliance noted failure to implement equipment control procedures, to initiate prompt corrective action & to maintain annunciator procedures
WEISE, S Region 2, Office of Director BEMIS, P Division of Project & Resident Programs 83/02/22 12pp 18644.042 24X
Fiche 50-261, 83/04/07, 8305270479

8305270497 Forwards IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted.
DANCE, H C Division of Project & Resident Programs 50-287/83-09
83/04/05 TUCKER, H B Duke Power Co 2pp 18646 192 24X
Fiche 50-269, 83/04/05, 8305270497

--8305270518 IE Insp Repts 50-269/83-09, 50-270/83-09 & 50-287/83-09 on 830308-11 No noncompliance noted Major areas inspected NUREG-0737, Items II B 2, "Plant Shielding Mods" & II B 3, "Post-Accident Sampling Sys "
COLLINS, T R Region 2, Office of Director 50-270/83-09
83/04/01 7pp 18646 194 24X Fiche 50-269, 83/04/05, 8305270497

8305270561 Forwards IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted
DANCE, H C Division of Project & Resident Programs 83/04/06
UHRIG, R E Florida Power & Light Co 2pp 18645 321 24X
Fiche 50-335, 83/04/06, 8305270561

--8305270576 IE Insp Repts 50-335/83-10 & 50-389/83-25 on 830316-18 No noncompliance noted Major areas inspected Unit 1 plant tours during refueling outage & Unit 2 followup of licensee actions on inspector identified items
WRAY, J R , BARR, K P Region 2, Office of Director 50-389/83-25
83/04/05 8pp 18645 323 24X Fiche 50-335, 83/04/06, 8305270561

8305310028 Advises that requirements of NUREG-0737, Item II F 1 4, "Containment Pressure Monitor," II F 1.5, "Containment Water Level Monitor" & II F 1 6, "Containment Hydrogen Monitor" resolved, per 821220 & 801215 submittals
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-060
83/05/27 FARRAR, D L Commonwealth Edison Co 7pp 18653 213
24X Fiche 50-000, 83/05/27, 8305310028

8305310039 Forwards info re schedule for steam generator mods, per SER (NUREG-0847) design changes
MILLS, L M Tennessee Valley Authority 83/05/27 ADENSAM, E
Licensing Branch 4 2pp 18653 307. 24X Fiche 50-390, 83/05/27, 8305310039

8305310046 Informs of NRC determination that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737, Item III A 2 1 Item complete
CRUTCHFIELD, D Operating Reactors Branch 5 LS05-83-05-065.
83/05/27 VANDEWALLE, D J Consumers Power Co 3pp 18653:149.
24X Fiche 50-255, 83/05/27, 8305310046

8305310073 Submits info re analyses & repairs of large-diameter stainless steel piping welds per inservice insp conducted during 1983 maint/refueling outage identifying unacceptable ultrasonic indications in recirculation & RHR sys
BECKHAM, J T Georgia Power Co IEB-83-02 83/05/26 STOLZ, J F
Operating Reactors Branch 4 9pp 18655 345 24X
Fiche 50-366, 83/05/26, 8305310073

--8305310084 Provides response to IE Bulletin 83-02 re stress corrosion cracking in large-diameter stainless steel recirculation sys piping at BWR plants
BECKHAM, J T Georgia Power Co IEB-83-02 83/05/26
O'REILLY, J P Region 2, Office of Director 39pp 18655 354
24X Fiche 50-366, 83/05/26, 8305310073

--8305310092 Discusses possible imposition of augmented leak detection requirements for RCS due to discovery of unacceptable pipe flaw indications in recirculation & RHR sys Util commitments to incorporate NUREG-0313, Rev 1, Section IV B 1 a 2
BECKHAM, J T Georgia Power Co NED-83-322 83/05/25 STOLZ, J F
Operating Reactors Branch 4 2pp 18656 032 24X
Fiche 50-366, 83/05/26, 8305310073

8305310088 Discusses plant-specific evaluation of relief & safety valves & related discharge piping analysis per 820709 ltr Teledyne analysis revealed that discharge piping sys will be overloaded & supports stressed beyond allowable limits.
HUNTER, R S Indiana & Michigan Electric Co AEP NRC 0585F
83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18658 065 24X Fiche 50-315, 83/05/27, 8305310088

8305310094 Forwards revised description of NUREG-0737, Item II.F 2, "Inadequate Core Cooling Instrumentation," providing sufficient info to close item & corresponding requirement in SER
DRUMMOND, F J Louisiana Power & Light Co. W3P83-1542 83/05/23.
KNIGHTON, G W Licensing Branch 3 34pp 18655 039 24X
Fiche 50-382, 83/05/23, 8305310094

8305310147 Response to SAPL motion to amend petition to intervene re SER open items Motion should be denied on grounds of timeliness. Certificate of Svc encl.
DIGNAN, T G Public Service Co of New Hampshire. DIGNAN, T G Ropes & Gray ISSUANCES OL 83/05/24 Atomic Safety and Licensing Board Panel 8pp 18651 209 24X Fiche 50-443, 83/05/24, 8305310147

8305310170 Advises that table of contents & table of cross-refs to NUREG-0654 planning stds/evaluation criteria adequate to locate portions relevant to contentions Referenced portions of plans listed
BAXTER T A Shaw, Pittman, Potts & Trowbridge. ISSUANCES OL
83/05/26 REED, J G. Affiliation Unknown 7pp 18652 326 24X
Fiche 50-483, 83/05/26, 8305310170

8305310175 Forward Rev 1 to "Rept of Independent Review of Environ Qualification Programs to NUREG-0588 "
PETRICK, N A Standardized Nuclear Unit Power Plant System 83-0030
83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 344pp. 18659 144 24X Fiche 50-000, 83/05/27, 8305310175

8305310200 Informs of plans to perform mods to Westinghouse Model D2/D3 steam generators per SER (NURE-0966) issued on 830316 Plant-specific mod details encl
TUCKER, H B Duke Power Co 83/05/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 7pp. 18651·014 24X Fiche·50-413, 83/05/18, 8305310200.

8305310205 Advises that installation of two Controlotron sonic flow devices on each flow path to once-through steam generators satisfies requirements of restart SER (NUREG-0680), 811214 partial initial decision & NUREG-0737, Item II E.1
HUKILL, H D General Public Utilities - GPU Service Corp
5211-83-156 83/05/24 STOLZ, J.F Operating Reactors Branch 4.
1p 18658 159 24X Fiche. 50-289, 83/05/24, 8305310205.

8305310208 Fowards check in payment of review re nonconformance w/ NUREG-0737, Item II.E 4.2, per 830427 request
CURTIS, N W Pennsylvania Power & Light Co. PLA-1683 83/05/25
SCHWENCER, A Licensing Branch 2 1p 18658.133 24X
Fiche 50-387, 83/05/25, 8305310208

8305310209 NUREG/CR-3100
RELAP5 ASSESSMENT PKL NATURAL CIRCULATION TESTS
THOMPSON, S.L., KMETYK, L.N. Sandia Laboratories FIN A-1205
SAND82-2902 83/04/30. Division of Accident Evaluation 60pp.
18663·152

8305310210 NUREG/CR-2326
CALCULATIONS OF REACTOR ACCIDENT CONSEQUENCES VERSION 2
CRAC2 COMPUTER CODE Users Guide
RITCHIE,L T , JOHNSON,J D , BLOND,R M Sandia Laboratories FIN
A-1042 SAND81-1994 83/04/30 Division of Risk Analysis
146pp 18663 211

8305310213 Forwards safety evaluation of util 830328 response to
NUREG-0737,Item II K 3 21, "Core Spray & LPCI Sys Low Level
Initiation " Proposed mod designs acceptable
CRUTCHFIELD,D Operating Reactors Branch 5 L805-83-05-062
83/05/27 FIEDLER,P B General Public Utilities - GPU Service Corp
4pp. 18658 142 24X Fiche 50-219,83/05/27,8305310213

8305310231 Advises that responses to NUREG-0737,Item III D 3 4,
"Control Room Habitability," acceptable,completing action on
item Safety evaluation encl
VASSALLO,D B Licensing Branch 2 83/05/17 FARRAR,D L
Commonwealth Edison Co 4pp 18662 255 24X Fiche 50-254,83/05/17,
8305310231.

8305310234 Summary of 830411 meeting w/util in Bethesda,MD re schedule
for completing items in Generic Ltr 82-33,Suppl 1 to
NUREG-0737 requirements for emergency response capability
LAZO,L Licensing Branch 3 GL-82-33 83/05/11 Licensing
Branch 3 12pp 18662 234 24X Fiche 50-412,83/05/11,8305310234

8305310237 NUREG/CR-2000 V02 N4
LICENSEE EVENT REPORT (LER) COMPILATION For Month of April
1983
* Oak Ridge National Laboratory FIN A-9135 ORNL/NSIC-200
83/05/31 Director's Office. 114pp 18683 118

8305310240 Requests addl info for control of heavy loads review,
including info open items for updated "Control of Heavy
Loads "
CLARK,R A Operating Reactors Branch 3 83/05/17 JONES,W C
Omaha Public Power District 2pp 18662,180 24X
Fiche 50-285,83/05/17,8305310240

--8305310241 TER-C5506-356 DRFT
"Control of Heavy Loads (C-10),Omaha Public Power District,
Fort Calhoun Station," updated draft technical evaluation
rept
VOSBURY,F , BOMBERGER,C , SARGENT,I H Franklin Institute/Franklin
Research Center NRC-03-81-130 TAC 07991 82/11/29
CLEMENSON,F NRC - No Detailed Affiliation Given 52pp
18662 182 24X Fiche 50-285,83/05/17,8305310240

ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS

8212060385 IE Info Notice 83-14, "Dewatered Spent Ion Exchange Resin
Susceptibility to Exothermic Chemical Reaction " Svc list
encl
TAYLOR,J M Division of Safeguards & Inspection Programs (Post
830103), 83/03/21 Consolidated Edison Co of New York, Inc
112pp 18308 319 24X Fiche 50-000,83/03/21,8212060385

8303040021 IE Info Notice 83-21, "Defective Emergency Use Respirator "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/15 Consolidated Edison Co of New
York, Inc 126pp 18435 155 24X Fiche 50-000,83/04/15,8303040021

8303040023 IE Info Notice 83-22, "BWR Safety/Relief Valve Failures "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/22 Consolidated Edison Co of New
York, Inc 112pp. 18383 089. 24X Fiche 50-000,83/04/22,8303040023

8303040025 IE Info Notice 83-23, "Inoperable Containment Atmosphere
Sensing Sys " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/25 Consolidated Edison Co of New
York, Inc. 119pp. 18381 291 24X Fiche 50-000,83/04/25,8303040025.

8303040026 IE Info Notice 83-24, "Loose Parts in Secondary Side of
Steam Generators at PWRs " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New
York, Inc. 115pp 18382 047. 24X Fiche 50-000,83/04/28,8303040026.

8303040027 IE Info Notice 83-25, "Standby Gas Treatment Sys Heater High
Temp Trip Setpoint Adjustment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/04/28 Consolidated Edison Co. of New
York, Inc 118pp 18382,165 24X Fiche 50-000,83/04/28,8303040027

8303040028 IE Info Notice 83-26, "Failure of Safety/Relief Valve
Discharge Line Vacuum Breakers " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/03 Consolidated Edison Co of New
York, Inc 122pp 18441 170 24X Fiche 50-000,83/05/03,8303040028

8303040030 IE Info Notice 83-27, "Operational Response to Events
Concerning Deliberate Acts Directed Against Plant
Equipment " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 112pp 18382 282 24X Fiche 50-000,83/05/04,8303040030

8303040031 IE Info Notice 83-28, "Criteria for Protective Action
Recommendations for General Emergencies " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/04 Consolidated Edison Co of New
York, Inc 119pp 18441 001 24X Fiche 50-000,83/05/04,8303040031

8303040033 IE Info Notice 83-29, "Fuel Binding Caused by Fuel Rack
Deformation " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/06 Consolidated Edison Co of New
York, Inc 113pp 18523 248 24X Fiche 50-000,83/05/06,8303040033

8303040034 IE Info Notice 83-30, "Misapplication of Generic Emergency
Operating Procedures (EOP) Guidelines " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103). 83/05/11 Consolidated Edison Co of New
York, Inc 114pp 18524 003 24X Fiche 50-000,83/05/11,8303040034

8303040040 IE Info Notice 83-31, "Error in ADLPIPE Computer Program "
Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/19 Consolidated Edison Co of New
York, Inc 114pp 18697 009 24X Fiche 50-000,83/05/19,8303040040

8303040046 IE Info Notice 83-33, "Nonrepresentative Sampling of
Contaminated Oil " Svc list encl
JORDAN,E L Division of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc 114pp 18647 007 24X Fiche 50-000,83/05/26,8303040046

8305020403 Discusses DOE agreement re Region IV equipment qualification
insp program & consultant svc provided from 821001-830328
Areas needing greater emphasis or improvement listed
PHILLIPS,H S Region 4, Office of Director FIN B-3101 83/04/28
BANGART,R L Division of Vendor & Technical Programs 2pp
18273 073

8305020419 Forwards "Indian Point Plans Verification Analysis" re
emergency planning,for info Certificate of Svc encl Related
correspondence
GLASS,S M Federal Emergency Management Agency ISSUANCES SP
83/04/25 OLEASON,J P Atomic Safety and Licensing Board Panel
62pp 18273 128 24X Fiche 50-247,83/04/25,8305020419

8305040001 Responds to approval request for info collection re 10CFR73
concerning physical protection of plants & matls Request
approved through 851031 under OMB Number 3150-0002,per
Paperwork Reduction Act
SCURRY,N Office of Management & Budget OMB 3150-0002 83/04/25
SCOTT,S Document Management Branch 2pp 18336 319

8305040003 Responds to approval request for info collection re
10CFR70 32(E) concerning changes in physical security plans
Request approved through 831231 under OMB Number 3150-0009,
per Paperwork Reduction Act
SCURRY,N Office of Management & Budget OMB 3150-0009 83/04/26
SCOTT,S Document Management Branch 2pp 18336 321

8305060506 Responds to 830426 ltr re Westchester County,NY bus driver
issue,Rockland County,NY plan issue & questions raised re
FEMA briefing & status rept on offsite emergency
preparedness
KRIMM,R W Federal Emergency Management Agency 83/05/04
CHILK,S J Office of the Secretary of the Commission 16pp
18348 331 24X Fiche 50-247,83/05/04,8305060506

--8305060629 Responds to request for clarification of issue on whether
state emergency plan can substitute for county which does
not have emergency plan State can substitute plan but
NUREG-0654 places heavy resource burden on state
GIUFFRIDA,L O Federal Emergency Management Agency 83/04/15
PALLADINO,N J Commissioners 2pp 18348 347 24X
Fiche 50-247,83/05/04,8305060506

8305090006 Responds to approval request for info collection re NRC
Form 5, "Current Occupational External Radiation Exposure "
Request approved through 860430 under OMB Number 3150-0006,
per Paperwork Reduction Act
SCURRY,N Office of Management & Budget OMB 3150-0006 83/04/25
SCOTT,S Document Management Branch 2pp 18369 354

8305090209 Forwards survey of QA procedures applied by INEL to computer code activities for NRC-funded programs
BANGART, R L Division of Vendor & Technical Programs 83/05/04
MATTSON, R J Division of Systems Integration (post 811005) 3pp
18364 041

8305090659 Generic Ltr 83-20 to all operating reactor licensees & holders of CPs re integrated scheduling for implementation of plant mods Svc list encl
EISENHUT, D G Division of Licensing GL-83-20 83/05/09
Consolidated Edison Co of New York, Inc 16pp 18627 153 24X
Fiche 50-000, 83/05/09, 8305090659

8305100122 Forwards post-exercise evaluation for 810729 exercise, final rept of reexercise on 811007 & final exercise rept of 830118 exercise No significant deficiencies cited
KRIMM, R W Federal Emergency Management Agency 83/04/08
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 2pp 18375 048 24X Fiche 50-295, 83/04/08, 8305100122

--8305100126 "Zion Nuclear Generating Station Small-Scale Joint Emergency Exercise, 830118," final rept
* Federal Emergency Management Agency 83/03/04 71pp
18375 050 24X Fiche 50-295, 83/04/08, 8305100122

--8305100131 "Zion Nuclear Power Station Reexercise, WI/Kenosha County (Small-Scale) 811007," final rept
* Federal Emergency Management Agency 82/04/30 32pp
18375 121 24X Fiche 50-295, 83/04/08, 8305100122

--8305100136 "Post-Exercise Evaluation, Exercise of State & Local Radiological Emergency Response Plans for IL & WI (Near Zion Nuclear Power Station) "
* Federal Emergency Management Agency 81/07/29 44pp
18375 153 24X Fiche 50-295, 83/04/08, 8305100122

8305100143 Submits status of offsite emergency preparedness issues re FEMA regional verifications through 830304 & data received through 830331 concerning schedule for completion of issues at facilities
KRIMM, R W Federal Emergency Management Agency 83/04/26
JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 9pp 18375 001 24X Fiche 50-289, 83/04/26, 8305100143

8305120421 Ack receipt of FEMA 830421 ltr & "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise " Emergency preparedness does not provide reasonable assurance that protective measures will be taken
ALLAN, J M Region 1, Office of Director 83/05/04 RANDAZZA, J. B
Maine Yankee Atomic Power Co 2pp. 18433 153 24X
Fiche 50-309, 83/05/04, 8305120421

--8305120426 Forwards "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant," conducted on 821211
MCLOUGHLIN, D Federal Emergency Management Agency 83/04/21
DIRCKS, W J Office of the Executive Director for Operations 1p
18433 155 24X Fiche 50-309, 83/05/04, 8305120421

--8305120427 "Final Exercise Rept - Joint State & Local Radiological Emergency Response Exercise for Maine Yankee Atomic Power Plant "
* Federal Emergency Management Agency 83/03/31 83pp
18433 156 24X Fiche: 50-309, 83/05/04, 8305120421

8305200458 Forwards FEMA evaluation of prompt notification sys proposed for Warren Dunes State Park Proposed sys adequate to warn 100% of surrounding population Sys will be examined by NRC during next emergency preparedness insp
HIND, J A Division of Radiological & Materials Safety Programs.
83/05/20 SOUTHWOOD, R J Michigan, State of 1p 18513:001 24X
Fiche 50-315, 83/05/20, 8305200458

--8305200465 Responds to 821213 ltr re potential inadequacies of public notification sys at Warren Dunes State Park in event of nuclear emergency Based on info provided, proposed sys would be adequate to warn surrounding population
ANDERSON, J T Federal Emergency Management Agency 83/04/01
KEPPLER, J. G Region 3, Office of Director 3pp 18513 002 24X
Fiche 50-315, 83/05/20, 8305200458

8305230465 Responds to 830322 ltr discussing activities of ANS Special Committee on Source Terms Info meeting to present work of committee welcomed
PALLADINO, N J Commissioners 83/05/02 STRATTON, W R American Nuclear Society 1p 18542 151.

--8305230469 Discusses activities of ANS Special Committee on Source Terms Meeting to discuss source term issue & present work of committee proposed
STRATTON, W R American Nuclear Society 83/03/22 PALLADINO, N J Commissioners 2pp 18542 152

8305230474 Forwards "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness, Jan-Mar 1983 "
PALLADINO, N J Commissioners GIUFFRIDA, L O Federal Emergency Management Agency 83/05/03 SIMPSON, A K Senate, Environment & Public Works 2pp 18542 154

--8305230479 "NRC/FEMA Joint Quarterly Rept to Congress on Emergency Preparedness, Jan-Mar 1983 "
* NRC - No Detailed Affiliation Given * Federal Emergency Management Agency 83/03/31 59pp 18542 156

8305240036 Forwards request for OMB review & supporting statement re NUREG-0737, TMI action plan
NORRY, P G Office of Administration 83/05/19 SCURRY, N Office of Management & Budget 1p 18594 260

8305240488 Forwards INPO "Evaluation of Oyster Creek Nuclear Generating Station, 1982 " Evaluation conducted 821025-1101
BRUNNER, E J Division of Project & Resident Programs 83/05/06
TAYLOR, J M Division of Reactor Programs (Pre 830103). 1p
18571 315 24X Fiche 50-219, 83/05/06, 8305240488

--8305240476 "Evaluation of Oyster Creek Nuclear Generating Station, 1982 "
* Institute of Nuclear Power Operations 83/03/31 44pp
18571 316 24X Fiche: 50-219, 83/05/06, 8305240488

8305240510 Forwards "RE Qinna Nuclear Power Plant, 1982 Evaluation "
BRUNNER, E J Division of Engineering & Technical Programs
83/05/06 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) CASE, E G Office of Nuclear Reactor Regulation, Director 1p 18571 274 24X Fiche 50-244, 83/05/06, 8305240510.

--8305240519 "RE Qinna Nuclear Power Plant 1982 Evaluation, " conducted during wks of 820531 & 0607
* Institute of Nuclear Power Operations 83/05/06 41pp
18571 275 24X Fiche 50-244, 83/05/06, 8305240510

8305260375 Speech entitled "NRC Looks Ahead, " presented at 830523 INPO meeting of plant managers in Atlanta, GA
STELLO, V Regional Operations & Generic Requirements 83/05/23
6pp 18647 278

8305270109 NUREG/CP-0043
JOINT NRC/ANS MEETING ON BASIC THERMAL HYDRAULIC MECHANISMS IN LWR ANALYSIS
HSU, Y Y. , LEE, R American Nuclear Society 83/04/30 Office of Nuclear Regulatory Research, Director 612pp 18649 112.

8305310049 Responds to 830523 ltr outlining specific proposals for ameliorating facility offsite preparedness situation & views on emergency preparedness regulation FEMA will assist in improving federal laws re emergency preparedness
GIUFFRIDA, L O Federal Emergency Management Agency 83/05/25
CUOMO, M N New York, State of 4pp 18653 284 24X
Fiche 50-247, 83/05/25, 8305310049

PR PROPOSED RULE

8304270179 Advises of rev in due date for submittal of proposed final rule on Tech Specs to CRGR & AEOD. Final package will be due at CRGR on 830731 & at AEOD on 830830
THOMAS, C O Standardization & Special Projects Branch 83/04/19
EISENHUT, D G Division of Licensing 2pp 18244 169

8304280121 Package of two comments opposing proposed rule re NRC policy statement on regionalization
MAY, D C , TREXLER, R C Affiliation Unknown 48FR12619 83/04/22
Office of the Secretary of the Commission 2pp 18251:293

8305020422 Motion to allow Citizens Assoc for Sound Energy to file written argument on issue in lieu of presenting oral argument at 830119 hearing Citizens do not have finances to come to Bethesda, MD for 40-minute argument.
ELLIS, J Citizens Association for Sound Energy 83/01/11 Atomic Safety and Licensing Appeal Panel 2pp 18283 001 24X
Fiche: 50-445, 83/01/11, 8305020422

--8305020430 Written argument on issues to be argued orally on 830119 in Bethesda, MD Citizens Assoc for Sound Energy unable to attend or find representative Whistleblower protection discussed
ELLIS, J Citizens Association for Sound Energy 83/01/11.
Atomic Safety and Licensing Appeal Panel 65pp 18283 003. 24X
Fiche 50-445, 83/01/11, 8305020422

--8305020437 Forwards Citizens Assoc for Sound Energy witness J Doyle affidavit re blacklisting due to testimony at hearings
ELLIS,J Citizens Association for Sound Energy 83/01/18
ROSENTHAL,A S Atomic Safety and Licensing Appeal Panel 1p
18283 068 24X Fiche 50-445,83/01/11,8305020422

--8305020444 Affidavit of J Doyle re blacklisting due to testimony at hearings NRC should take immediate & stringent measures to stop insidious practice NRC current protection for whistleblowers is farce & charade Certificate of Svc encl
DOYLE,J Affiliation Unknown 83/01/17 4pp 18283 069 24X
Fiche 50-445,83/01/11,8305020422

8305030069 Comments on 830415 final 10CFR50 73 rulemaking package re LERs Concerns listed
MARTIN,J B Region 5, Office of Director 83/04/27 HELTEMES,C J
Director's Office 2pp 18300 358

8305030416 Package of two comments supporting proposed rule 10CFR35 re group licensing for certain Group IV medical devices
ROBINSON,R G American College of Nuclear Physicians STRAUSS,R J
Affiliation Unknown 48FR13189 83/04/29 Docketing & Services
Branch 4pp 18306 316

8305030418 Comments on proposed rules 10CFR2 & 50 re granting temporary OLs Opposes rule
LEWIS,M I Lewis, M 48FR14926 002 83/04/22 Office of the
Secretary of the Commission 1p 18306 247

8305030430 Comments on proposed rule re alternative programs for improving QA & QC in const of nuclear power plants NRC considerations should be to assure that regulatory framework combines activities of licensee & NRC
OPREA,G W Houston Lighting & Power Co 48FR9106 013 83/04/22
CHILK,S J Office of the Secretary of the Commission 9pp
18292 154

8305030437 Comments on proposed rule re QA programs for const of nuclear power plants Supports improvement of QA program
COMPTON,N Affiliation Unknown 48FR9106 014 83/04/25 Office
of the Secretary of the Commission 4pp 18306 320

8305030461 Package of three comments on proposed rule re planned studies of QA programs for const of nuclear power plants
KELLY,R B Stone & Webster Engineering Corp VHRIG,R E Florida
Power & Light Co ALLEN,R E Power Engineering 48FR9106
83/04/29 Docketing & Services Branch 13pp 18306 280

8305030472 Comments on proposed rule re NRC policy statement on regionalization Supports rule Special attention should be given to areas of staffing,regional ofcs & mechanisms to assure uniformity in program administration
QIEBE,D J Minnesota, State of 48FR12619 028 83/04/26
CHILK,S J Office of the Secretary of the Commission 1p
18306 214.

8305030480 Comments on proposed rule 10CFR35 adding Group IV medical device for instantaneous imaging w/I-125 sealed source (liviscope) Supports rule
TANSEY,W J Downers Grove Orthopedic Associates, Downers Grove, IL
48FR13189 007 83/04/22 Docketing & Services Branch 1p
18292 174

8305030487 Comments on proposed rule re policy statement on regionalization Opposes rule
WORTHEN,M Affiliation Unknown 48FR12619 026 83/04/20 Office
of the Secretary of the Commission 1p 18308 250

8305030598 Comments on proposed rule re policy statement on regionalization Supports rule
TEDFORD,C F Arizona, State of 48FR12619 027 83/04/22
Docketing & Services Branch 2pp 18306 089

8305060236 Comments on proposed rule re decentralization of NRC headquarter functions Opposes rule
FREY,D G Sassafras Audubon Society 48FR12619 031 83/05/02
NRC - No Detailed Affiliation Given 2pp 18345 191

8305060244 Comments on proposed rule 10CFR50 re changes to regulations on Tech Specs for nuclear power reactors Endorses concepts embodied in rule Urges Commission to implement rule on schedule reflecting priority
COUNSIL,W G Northeast Utilities Service Co COUNSIL,W G
Northeast Utilities 47FR13369 032 83/04/25 CHILK,S J Office
of the Secretary of the Commission 3pp 18345 193

8305060254 Comments on proposed rule 10CFR140 re removal of Apps A through H from financial protection requirements & indemnity agreements Opposes rule
OUCWA,L T. Georgia Power Co 48FR9284 018 83/04/28 Docketing
& Services Branch 2pp 18345 222

8305060289 Comments on proposed rule re draft NRC policy statement on regionalization Supports rule
EICHBAUM,W M Maryland, State of 48FR12619 029 83/04/20
DIRCKS,W J Office of the Executive Director for Operations 1p
18344 324

8305060294 Comments on proposed rule re decentralization of NRC licensing functions Requests maintaining centralized licensing function for radiopharm business to enhance safety of employees,customers & public
WHITE,L M Syncor Internatinnal 48FR12619 030 83/04/29
Docketing & Services Branch 2pp 18344 320

8305060382 Package of three comments on proposed rule re planned studies of QA programs for const of nuclear power plants
GUSTAFSON,L D Affiliation Unknown HENRY,W O Duke Power Co
WEISS,E R Union of Concerned Scientists 48FR9106 83/05/02
Docketing & Services Branch 29pp 18344 108

8305060436 Comments on proposed rule 10CFR35 re group licensing for certain Group IV medical devices Supports rule
GARCIA,M J Affiliation Unknown 48FR13189 010 83/05/02
Docketing & Services Branch 2pp 18343 149

8305060437 Comments on proposed rule re QA/QC for const of nuclear power plants prepared by D Hubbard on behalf of NRDC Supports rule
O'NEILL,J Affiliation Unknown 48FR9106 022 83/05/03
Commissioners 1p 18343 145

8305060438 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants
TIERNAN,J A Baltimore Gas & Electric Co 48FR9106 021 83/04/29
Docketing & Services Branch 3pp 18343 151

8305060573 Comments on proposed rule 10CFR50 re environ qualification Many operating plants operating w/unqualified equipment & w/o justification NRC made finding that justifications adequate NRC should be obligated to enforce requirements
WEISS,E R Harmon & Weiss 47FR2876 087 83/04/19
PALLADINO,N J , ASSELSTINE,J , AHEARNE,J F Commissioners 2pp
18348 349

8305110012 Comments on methods for improving quality of nuclear power plant const,per 830328 request Focus of NRC QA/QC programs should be shifted away from program content & more towards actual program performance
MARIANI,L P , CARNEY,J American Nuclear Insurers 48FR9106 031
83/05/03 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 18409 020

8305180266 Comments on proposed rule re NRC policy statement on regionalization Supports rule
WITHERS,B D Portland General Electric Co 48FR12619 035
83/05/02 Docketing & Services Branch 2pp 18490 060

8305180272 Comments on proposed rule re NRC policy statement on regionalization Opposes rule
ELLIS,J Citizens Association for Sound Energy 48FR12619 033
83/05/02 STELLO,V Regional Operations & Generic Requirements
7pp 18490 062

8305180306 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants Opposes rule Present QA programs adequate Implementation & timeliness of programs require more active participation
ECKERT,R M Atomic Industrial Forum 48FR9106 023 83/05/06
Docketing & Services Branch 3pp 18486 014

--8305180313 "Positive Experience in Designing & Constructing Nuclear Power Plants "
* Atomic Industrial Forum 83/01/31 38pp 18486 017

8305180330 Comments on proposed rule re planned studies of QA/QC programs for const of nuclear power plants Extension of deadline for public comments requested so public input will be considered in studies
FREY,D G Sassafras Audubon Society 48FR9106 024 83/05/05
HARPSTER,T L QA Branch 2pp 18486 055

8305180334 Package of three comments opposing NRC policy statement on regionalization
PENNER,P S Illinois, State of RUZICKA,W G Union Carbide Corp
RUBLING,D H Interior, Dept of, Geological Survey 48FR12619
83/05/12 Docketing & Services Branch 3pp 18486 288

8305180341 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OL & significant hazards consideration
DOUGHERTY,J B Dougherty, J B LANPHER,L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips 48FR14926 83/05/06 Office of the
Secretary of the Commission 19pp 18486 269

8305180342 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations Supports rule Changes to current Commission practices can be achieved w/o compromising public safety
HELFRICH,R E Yankee Atomic Electric Co 48FR14864 016 83/05/06
Docketing & Services Branch 6pp 18482 001

8305180347 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OL & significant hazards considerations
HIATT,S L Ohio Citizens for Responsible Energy TIEDKE,J H
League of Women Voters of Suffolk Co , NY 48FR14926 83/05/05
Docketing & Services Branch 3pp 18485 291

8305180351 Comments on proposed rule re NRC policy statement on regionalization Policy has potential to improve quality of nuclear regulation if definitive policies & proper mgt controls are developed in advance of implementation
OWEN,W H Atomic Industrial Forum 48FR12619 032 83/05/04
Docketing & Services Branch 4pp 18485 278

8305180353 Package of three comments opposing NRC policy statement re regionalization
LEVINE,S H Pennsylvania State Univ RICHARDS,W J American Nuclear Society BUDNITZ,R J Future Resources Associates, Inc
48FR12619 83/05/09 Docketing & Services Branch 6pp
18485 262

8305180356 Comments on proposed rule 10CFR50 re stds for determining whether license amend involves no significant hazards considerations Rule does not meet Congressional mandate
WEISS,E R , BISHOP,L L Union of Concerned Scientists 48FR14864
003 83/05/06 Commissioners 17pp 18485 245

8305180358 Package of five comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations
KEARNEY,J J Edison Electric Institute TIERNAN,J A Baltimore Gas & Electric Co * LeBoeuf, Lamb, Leiby & MacRae 48FR14864
83/05/09 Docketing & Services Branch 19pp 18485 226

8305180363 Comments on proposed rule 10CFR50 re environ qualification NRC shirking responsibility to enforce environ qualification rule promulgated on 830106
CURRAN,D , WEISS,E R Harmon & Weiss 47FR2876 088 83/05/04
PALLADINO,N J , ASSELSTINE,J , AHEARNE,J F Commissioners 3pp
18485 214

8305180364 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations Rule vague & unsatisfactory
DOUGHTY,J Seacoast Anti-Pollution League 48FR14864 011
83/05/06 Docketing & Services Branch 1p 18490 354

8305180369 Package of two comments opposing 10CFR50 re stds for determining whether license amends involve no significant safety hazards consideration
FREY,D G Sassafras Audubon Society DOROSHOW,J Three Mile Island Alert 48FR14864 83/05/09 Docketing & Services Branch 4pp
18490 350

8305180378 Comments on proposed rules 10CFR2 & 50 re significant hazards consideration & issuance of temporary OL Supports rules
CONWAY,B Atomic Industrial Forum 48FR14926 83/05/06
Docketing & Services Branch 4pp 18482 039

8305180383 Comments on proposed rule 10CFR50 re notification & consultation w/state in emergency situation Situation should exist when plant already in shutdown could be prevented from startup because NRC failed to act in timely manner
BRADBURY,R B Stone & Webster Engineering Corp 48FR14864 004
83/05/04 Docketing & Services Branch 1p 18490 345

8305180404 Package of two comments opposing proposed rule 10CFR50 re stds for determining whether license amend involves no significant hazards considerations & notification of & consultation w/states
AXELRAD,M Lowenstein, Newman, Reis, Axelrad & Toll HIATT,S L
Ohio Citizens for Responsible Energy 48FR14864 83/05/05
CHILK,S J Office of the Secretary of the Commission 8pp
18486 001

8305180425 Comments on proposed rule 10CFR35 re adding device to Schedule A,Group VI used for instantaneous imaging w/I-125 sealed source Supports rule
DEYE,J A American Association of Physicists in Medicine 48FR13189
012 83/05/05 PALLADINO,N J Commissioners 2pp 18485 300

8305180436 Comments on proposed rule 10CFR35 re adding device to Schedule A,Group VI used for instantaneous imaging,w/I-125 sealed source (Lixiscope) Supports rule
SONDAG,T J Good Samaritan Hosp Downers Grove,IL 48FR13189 011
83/05/05 Docketing & Services Branch 1p 18486 194

8305180449 Package of two comments opposing proposed rules 10CFR2 & 50 re issuance of temporary OLs
LATHAM,S B Twomey, Latham & Shea REYNOLDS,N S , HORIN,W A
Debevoise & Liberman 48FR14926 83/05/09 CHILK,S J Office of the Secretary of the Commission 10pp 18486 184

8305180454 Comments on proposed rules 10CFR2 & 50 re issuance of temporary OLs
BRADBURY,R B Stone & Webster Engineering Corp 48FR14926 007
83/05/04 Docketing & Services Branch 1p 18486 183

8305180460 Package of two comments opposing proposed rule 10CFR50 re significant hazards considerations
TIERNEY,J E , AHRENS,P , STERN,P Minnesota, State of 48FR14864
83/05/10 Docketing & Services Branch 13pp 18483 101

8305200218 Package of two comments opposing proposed rule re NRC policy statement on regionalization
DEWITT,R B Consumers Power Co GAGE,K Nuclear Information & Resources Services 48FR12619 83/05/16 Docketing & Services Branch 5pp 18517 095

8305200222 Comments on proposed rule re studies of GA/GC programs at nuclear power plants Supports rule
CAMPBELL,S E Sinnissippi Alliance for the Environment (SAFE)
48FR9106 025 83/05/12 Office of the Secretary of the Commission 2pp 18517 100

8305200296 Comments on proposed rule re NRC policy statement on regionalization Supports regionalization concept
ROBINSON,R G American College of Nuclear Physicians 48FR12619
044 83/05/16 Docketing & Services Branch 1p. 18516 272

8305200304 Comments on proposed rule re NRC policy statement on regionalization Opposes rule Potential problem re handling generic issues as result of occurrences in plants under const foreseen
RAHE,E P Westinghouse Electric Corp 48FR12619 043 83/05/12
CHILK,S J Office of the Secretary of the Commission 2pp
18517 021

8305200441 Package of two comments opposing proposed rule 10CFR50 re notice & state consultation stds for determining whether license amends involve no significant hazards considerations
COUNSIL,W G Northeast Utilities LEWIS,M I Lewis, M 48FR14864.
83/05/16 CHILK,S J Office of the Secretary of the Commission
13pp 18518 128

8305200456 Requests comment period for proposed rule on GA programs be extended until full impact of GA breakdown leading to ATWS at Salem fully assessed & reported
LEWIS,M I Lewis, M 48FR9106 026 83/05/12 Docketing & Services Branch 2pp 18512 360

8305200461 Comments on proposed rules 10CFR2 & 50 re issuance of temporary OL Supports rule
PATTERSON,J D Middle South Utilities, Inc - Middle South Energy, Inc 48FR14926 010 83/05/06 Docketing & Services Branch 2pp
18513 021

8305200470 Submits UCS comments on proposed rule re NRC policy statement on regionalization Opposes rule
WEISS,E R Harmon & Weiss 48FR12619 046 83/05/17
Commissioners 6pp 18513 015

8305230324 Revised procedures for processing license amends for power reactor testing facilities (Sholly legislation). Interim final rules for notice & state consideration & stds for determining whether amends involve no hazards encl
EISENHUT,D G. Division of Licensing 83/05/06 17pp 18576:179.

--8305230333 Interim final rule for 10CFR2 & 10CFR50 re revised procedures for processing license amends & notice & state consultation
CHILK,S Office of the Secretary of the Commission DLOP-228.
83/04/04 34pp 18576 196

--8305110581 "Stds for Determining Whether License Amends Involve No Significant Hazards Considerations " Interim final rule Dissenting views of Commissioners Asselstine & Gilinsky re use of Sholly amend encl
CHILK,S J. Office of the Secretary of the Commission DLOP-228.
83/04/04 45pp 18576 230

8305230420 Responds to 830314 ltr urging implementation of spent fuel provisions of Nuclear Waste Policy Act (P L 97-425) Proposed rule 10CFR53, "Criteria for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity" encl
PALLADINO,N J Commissioners 83/04/27 RILEY,R W South Carolina, State of 2pp 18542 027

--8305230425 Proposed rule 10CFR53, "Criteria & Procedures for Determining Adequacy of Available Spent Nuclear Fuel Storage Capacity "
CHILK,S J Office of the Secretary of the Commission 83/04/26 20pp 18542 029

8305240155 Ack receipt of 830315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis
PALLADINO,N J Commissioners 83/04/22 SIMPSON,A K House of Rep , Environment & Public Works 2pp 18594 001

--8305240167 Ack receipt of 830315 ltr expressing concern re Commission treatment of license amend request concerning reracking of spent fuel storage pools in interim final rule License amend requests examined on case-by-case basis
PALLADINO,N Commissioners 83/04/22 HART,G House of Rep , Environment & Public Works 2pp 18594 003

--8305240179 Ack receipt of 830315 & 24 ltrs expressing concern re Commission treatment of license amend requests concerning reracking of spent fuel storage pools in interim final rule Amend requests examined on case-by-case basis
PALLADINO,N J Commissioners 83/04/22 MITCHELL,G J House of Rep , Environment & Public Works 2pp 18594 005

--8305240190 "Stds for Determining Whether License Amends Involve No Significant Hazards Considerations," 10CFR50 interim final rule. Amends regulation to specify stds for determining if requested amend to OL involves significant hazards
CHILK,S.J Office of the Secretary of the Commission 83/04/04 44pp. 18594 007

8305250378 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants. Supports program
* Affiliation Unknown 48FR9106 028 83/05/14 Docketing & Services Branch 1p 18592 100

8305250381 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants. Supports INPO const & evaluation program. Further use of third-party svcs may result in reduction of util responsibility
EDELMAN,M R Cleveland Electric Illuminating Co 48FR9106 027 83/05/16 Docketing & Services Branch 1p 18592 101

8305250406 Package of two comments supporting proposed rule re NRC policy statement on regionalization
REYNOLDS,N S. Debevoise & Liberman BRADBURY,R B Stone & Webster Engineering Corp 48FR12619 83/05/19 CHILK,S J Office of the Secretary of the Commission 7pp. 18592 084

8305250409 Comments on proposed rule re NRC policy statement on regionalization Supports rule
MUSOLF,D. Northern States Power Co 48FR12619 050 83/05/16 Docketing & Services Branch 2pp 18585 330

8305250415 Package of two comments opposing proposed rule re NRC policy statement on regionalization
UHRIG,R E Florida Power & Light Co * Affiliation Unknown 48FR12619. 83/05/20 Docketing & Services Branch 7pp 18585 274.

8305250420 Comments on proposed rule re NRC policy statement on regionalization Supports rule
KEARNEY,J J Edison Electric Institute 48FR12619 047 83/05/16 CHILK,S J Office of the Secretary of the Commission 2pp 18585:281.

8305250422 Comments on proposed rule 10CFR50 re license amends involving no significant hazards consideration NRC proposal vague & open to interpretation
* Affiliation Unknown 48FR14864 019 83/05/14 Docketing & Services Branch 1p 18583 358

8305250489 Forwards comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations.
FLYNN,S F. Carolina Power & Light Co 48FR14864 018 83/05/16 CHILK,S J Office of the Secretary of the Commission 1p 18588·299.

--8305250493 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards considerations
HURFORD,W J Carolina Power & Light Co 48FR14864 018 83/05/16 CHILK,S J Office of the Secretary of the Commission 3pp 18588 300

8305250517 Package of two comments on proposed rule re QA program for const of nuclear power plants
WILKINSON,E P Institute of Nuclear Power Operations MARIANI,L P , CARNEY,J American Nuclear Society 48FR9106 83/05/23 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp 18588 268

8305250529 Forwards J Jackson comments on proposed rule re QA programs for const of nuclear power plants
STINSON,R C Management Analysis Co 48FR9106 029 83/04/25 DIRCKS,W J Office of the Executive Director for Operations 1p 18588 230

--8305250535 Comments on proposed rule re QA programs for const of nuclear power plants Recommends strong emphasis on QA mgt experience
JACKSON,J Management Analysis Co 48FR9106 029 83/04/22 TAYLOR,J M Division of Safeguards & Inspection Programs (Post 830103) 3pp 18588 231

8305270003 Comments on proposed rule re NRC policy statement on regionalization Major technical activities re plant licensing should remain within NRR jurisdication
BRADBURY,R B Stone & Webster Engineering Corp 48FR12619 049 83/05/16 Docketing & Services Branch 1p 18638 325

PROJ PROJECTS - PREDOCKET LICENSING

8305030688 Clarifies definitions of plant & project low level radwastes to be used in developing West Valley Demonstration Project mgt plan & subsequent environ assessment documentation
HANNUM,W H Energy, Dept of 22157 83/04/01 CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch 2pp 18309 138 24X Fiche 50-201,83/04/01,8305030688

8305040092 Forwards comments on 830224 topical rept, "Topical SAR for Castor Cask Type ISFSI (Dry Storage) " Revised rept still lacks adequate definition re design requirements & objectives
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 83/04/22 ROLLINS,J D Gesellschaft fuer Nuklear Service, mbH 33pp 18328 187

8305060261 Forwards Vol 2 to "Annual Environ Rept,Radiological,1982 "
SIEBER,J D Duquesne Light Co ND1MSL 2463 83/04/25 WIGGINTON,D Operating Reactors Branch 1 1p 18344 193 24X Fiche 50-334,83/04/25,8305060261

--8305060269 Vol 2 to "Annual Environ Rept,Radiological,1982 "
* Duquesne Light Co 83/04/25 126pp 18344 194 24X Fiche 50-334,83/04/25,8305060261

8305090212 Forwards proprietary "Westinghouse Advanced PWR Pretendering Module 5 - Chemical & Vol Control Sys " Application for withholding & affidavit encl Rept withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp NS-EPR-2759 83/04/29 EISENHUT,D G Division of Licensing 2pp 18362 342

--8305090202 Application for withholding proprietary "Westinghouse Advanced PWR Pretendering Module 5 - Chemical & Vol Control Sys " Affidavit encl
WIESEMANN,R A Westinghouse Electric Corp AW-83-36 83/04/29 EISENHUT,D G Division of Licensing 9pp 18362 344

8305100339 Notifies of applicant request for leave to withdraw appeal in instant matter
ADRAGNA,J M Spiegel & McDiarmid ADRAGNA,J M Pacific Gas & Electric Co ISSUANCES A 83/05/09 ROSENTHAL,A S , MOORE,T S , EDLES,G J Atomic Safety and Licensing Appeal Panel 1p 18378 359.

8305100346 Advises that author will present 830518 oral argument on behalf of util re intervenor Northern California Power Agency appeal from 830119 memorandum & order
FALLIN,J F Pacific Gas & Electric Co ISSUANCES A 83/05/04 SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel 1p 18379 018

8305110345 Order granting Northern California Power Agency motion for leave to withdraw appeal from 830119 memorandum & order in antitrust proceeding Order scheduling appeal from 830518 oral argument vacated
SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel ISSUANCES A 83/05/09 Pacific Gas & Electric Co 1p 18406 186

8305130276 Requests addl info re 830201 affidavit requesting Apps 1,3, 5,6 & 10 of Rev 1 to "Topical SAR for Castor Cask Type ISFSI (Dry Storage)," be withheld (ref 10CFR9 5 & 2 790)
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 83/05/03
ROLLINS,J D Gesellschaft fuer Nuklear Service, mbH 1p
18456 226

8305160363 Forwards nonproprietary & proprietary versions of "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," per 10CFR72 Affidavit to withhold proprietary info encl W/o proprietary version
PARKER,P E Ridihalgh, Eggers & Associates 22161 83/04/14
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 4pp
18473 021

--8305160365 "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel "
* Ridihalgh, Eggers & Associates 22161 83/04/06 574pp
18473 023

8305180805 Responds to 830329 ltr requesting records of former NRC-licensed burial area Arrangement should be made w/DOE for site access
WHITE,I L New York, State of, Energy Research & Development Administration 22213 83/04/12 CUNNINGHAM,R E Division of Fuel Cycle & Material Safety 1p 18505 350

8305180810 Responds to 830307 ltr advising of continued monitoring of Series 1980 & 1982 wells by DOE Ultimate disposition of wells will be determined by DOE & ERDA prior to completion of project
DEBOER,T K New York, State of, Energy Research & Development Administration 22214 83/04/15 CUNNINGHAM,R E Division of Fuel Cycle & Material Safety 1p 18505 352

8305230015 Forwards Rev 1 to "Functional & Operational Requirements for Component Test Stand," for comments by 830515
HUNNUM,W H Energy, Dept of, Idaho Operations Ofc 83/04/18
CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch 1p
18542 232 24X Fiche 50-201,83/04/18,8305230015

--8305230020 Rev 1 to "Functional & Operational Requirements for Component Test Stand "
* West Valley Nuclear Services Co , Inc 83/03/23 22pp
18542 233 24X Fiche 50-201,83/04/18,8305230015

8305230041 Forwards "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," for review
PARKER,P E Ridihalgh, Eggers & Associates 1098/83/57 83/04/14
ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p
18543 132

--8305230056 Forwards affidavit requesting withholding of proprietary info included in "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," (ref 10CFR2 790)
PARKER,P E Ridihalgh, Eggers & Associates 1098/83/58 83/04/14 ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18543 133

8305240614 Requests comments on "Geological Recommendations for Investigation of NRC Disposal Area," by 830327
HANNUM,W H Energy, Dept of, Idaho Operations Ofc 22219 83/04/21 CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch 1p 18593 142 24X Fiche 50-201,83/04/21,8305240614

--8305240618 "Geological Recommendations for Investigation of NRC Disposal Area "
* West Valley Nuclear Services Co , Inc 22219 83/03/16 21pp
18593 143 24X Fiche 50-201,83/04/21,8305240614

8305260393 Responds to ltrs requesting comment re disposal of low level radwaste DOE plan for disposal acceptable Detailed waste packaging info,per 10CFR61,requested Comments encl
CLARK,A T Advanced Fuel & Spent Fuel Licensing Branch 83/05/16
HANNUM,W H Energy, Dept of 14pp 18647 193

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

8304150354 Part 21 Rept U-48 & interim deficiency rept re GE ARR-30 & AKR-50 circuit breakers Initially reported on 830211 Assessment of safety implications & corrective actions requested of AE Final rept expected by 830429
SCHNELL,D F. Union Electric Co 10CFR 050 55E 83/04/07
SPESSARD,R L Division of Project & Resident Programs 1p
17982 128 24X Fiche.50-000,83/04/07,8304150354.

8305020133 Supplemental Part 21 Rept 6 re possible thermostatic valve malfunction fail-safe to full cooling position Lower overrun assemblies in Robertshaw valves on diesel generator sets replaced w/assemblies using cotter pins
MORIARTY,J M Colt Industries, Inc 83/04/21 KEPPLER,J G. Region 3, Office of Director 1p 18278 219 24X Fiche 50-483,83/04/21, 8305020133

8305030291 Supplemental response to Part 21 rept re postulated pipe crack in HPCI,RCIC,reactor water cleanup sys & main steam line drains Required mods will be installed to meet requirements of environ qualification program
DIETZ,C R Carolina Power & Light Co BSEP/83-1260 83/04/26
O'REILLY,J P Region 2, Office of Director 1p 18300 061 24X
Fiche 50-324,83/04/26,8305030291

8305030300 Part 21 rept re linear indications identified in BA 106 grade pipe Initially reported on 830413 Caused by mfg process error & ultrasonic exam inadequacies All seamless pipe put on hold & magnetic particle examined
CARLISLE,C S Washington Public Power Supply System 002-83-349
83/04/15 MARTIN,J B Region 5, Office of Director 18pp
18297 070 24X Fiche 50-397,83/04/15,8305030300

8305030370 Seventh interim deficiency rept re failure of bolts & nuts to meet ASTM specs Initially reported on 810924 Results of analysis of bolting matl will be evaluated Next rept will be submitted by 830707 Also reported per 10CFR21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/04/25
O'REILLY,J P Region 2, Office of Director 2pp 18306 217 24X
Fiche 50-438,83/04/25,8305030370

8305030387 Part 21 rept re pipe clamps for snubber/struts oriented in off-axis direction Initially reported on 830224 & by IE Info Notice 83-13 Clamps will be replaced by end of Fall 1983 refueling outage
DIETZ,C R Carolina Power & Light Co BSEP/83-1220 83/04/22
O'REILLY,J P Region 2, Office of Director 2pp 18292 316 24X
Fiche 50-324,83/04/22,8305030387

8305040486 Interim deficiency rept re nonconforming condition on Class IE low voltage switchgear mfg by Brown Boveri Electric Initially reported on 821222 Welding fix planned for cubicle EF2C05 Final rept will be submitted by 831130
EDELMAN,M R Cleveland Electric Illuminating Co 10CFR 050 55E
83/04/27 KEPPLER,J G Region 3, Office of Director 2pp
18319 353 24X Fiche 50-440,83/04/27,8305040486

8305040496 Final deficiency rept re potential breach of seal integrity of hydrogen igniter Model 6043 glow plug component supplied by Power Sys Initially reported on 830207 Igniters repaired Also reportable per Part 21
EDELMAN,M R Cleveland Electric Illuminating Co 10CFR 050 55E
83/04/27 KEPPLER,J G Region 3, Office of Director 2pp
18319 356 24X Fiche 50-440,83/04/27,8305040496

8305050122 Second interim deficiency rept re unqualified flex-hose connections Initially reported on 821027 Problems reanalyzed & flex-hose qualifications performed Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/04/28
O'REILLY,J P Region 2, Office of Director 2pp 18342 198 24X
Fiche 50-438,83/04/28,8305050122

8305050124 Final deficiency & Part 21 repts re pressure boundary matl supplied by Tube Line Corp failing to meet Tech Specs, Item 123 Initially reported on 830330 Items returned to vendor New fittings purchased
PARSONS,R M Carolina Power & Light Co 10CFR 050 55E 83/04/28
O'REILLY,J P Region 2, Office of Director 4pp 18341 343 24X
Fiche 50-400,83/04/28,8305050124

8305050185 Interim deficiency & Part 21 repts re base metal defect in spool piece supplied by Southwest Fabricating & Welding Co. Initially reported on 830126 Vendor directed to show preventive measures Final rept by 830801
PARSONS,R M Carolina Power & Light Co 10CFR 050 55E 83/04/29
O'REILLY,J P Region 2, Office of Director 4pp 18342 240 24X
Fiche 50-400,83/04/29,8305050185

8305050259 Final deficiency & Part 21 repts re 480-volt switchgear design defect in secondary disconnects Initially reported on 821102 Brown-Boveri completed change-out of all old style stationary secondary disconnects
PARSONS,R M Carolina Power & Light Co 10CFR 050 55E. 83/04/29
O'REILLY,J P. Region 2, Office of Director 4pp 18338 016. 24X
Fiche 50-400,83/04/29,8305050259

8305110292 Third interim deficiency rept re linear indications in Natl Valve & Mfg Co spool pieces Initially reported on 820924. Vendor requested to supply list of spool pieces w/Heat Code L63687 Util awaiting reply Also reportable per Part 21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/02
O'REILLY,J P Region 2, Office of Director 2pp 18393.254 24X
Fiche 50-439,83/05/02,8305110292

8305110313 Part 21 rept re blow-out panel in east & west penetration areas Initially reported on 830506 Structural framing sys designed to protect flow transmitter & related instrument tubing
BARKER,N R Gilbert/Commonwealth Cos 83/05/09 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 18393 196 24X Fiche 50-395,83/05/09,8305110313

8305110322 Part 21 rept re ring duct stiffener failure Initially reported on 830506 Design change to eliminate airflow-induced vibration & redesign of ring stiffener submitted to util
BARKER,N R Gilbert/Commonwealth Cos 83/05/09 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 18393 177 24X Fiche 50-395,83/05/09,8305110322

8305110324 Part 21 rept re Type SA-1 Class IE relays Silicon controlled rectifier (SCR) in trip output circuit may cause random trip output Westinghouse corrective action includes replacing SCR w/burn-in SCR
DUVALL,D.D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) PT21 83-807-000 83/04/27 STELLO,V Director's Office, Office of Inspection and Enforcement 5pp 18393 278 24X
Fiche 50-000,83/04/27,8305110324

8305110427 Part 21 & deficiency repts re misoperation of DS-416 reactor trip undervoltage devices Initially reported on 830420 Attachments will be replaced w/devices w/widened grooves to accommodate new retaining rings Mfg drawings revised
RAHE,E.P Westinghouse Electric Corp NS-EPR-2753 83/04/21 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 5pp. 18405 095 24X Fiche 50-000,83/04/21,8305110427

8305110441 Final deficiency rept re faulty relays mfg by Brown Boveri Electric in auxiliary power distribution sys Initially reported on 820528 Four relays returned to vendor for repair & reinstalled at facility Also reported per 10CFR21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/02 O'REILLY,J P Region 2, Office of Director 2pp 18393 348 24X
Fiche 50-439,83/05/02,8305110441

8305120392 Interim deficiency rept re misapplication of ITE Gould circuit breakers in post-LOCA hydrogen recombiners supplied by Rockwell Intl Initially reported on 830328 Matter under investigation Final rept by 830808 Reported per Part 21
MANNO,S F Niagara Mohawk Power Corp 6489 83/04/26 STAROSTECKI,R Region 1, Office of Director 2pp 18433 072 24X
Fiche:50-000,83/04/26,8305120392

--8305120404 Part 21 rept re failure of post-LOCA hydrogen recombiner component during IEEE-323 qualification program Circuit breaker not properly selected for specific application Plant operators notified of deviation
EMPEY,D C Rockwell International Corp 83ESG-1483 83/03/11 COLLINS,J T Region 4, Office of Director 5pp 18433 074 24X
Fiche 50-000,83/04/26,8305120392

8305120475 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels MCC Powers personnel attached hold tags to 13 HVAC control panels w/defect Evaluation being conducted
HALL,D P Illinois Power Co 1606-L 83/05/04 KEPPLER,J G Region 3, Office of Director 2pp 18431 049 24X
Fiche,50-000,83/05/04,8305120475

--8305120484 Part 21 rept re defect in shielded multiconductor cable installed in HVAC control panels All suspect panels inspected & nonconformance rept will be issued for applicable sites
FAUCONNEAU,G Mark Controls Corp 83/04/18 Director's Office, Office of Inspection and Enforcement 2pp 18431 051 24X
Fiche,50-000,83/05/04,8305120475

8305130027 Part 21 & final deficiency repts (Item 106) re incorrect design of 480-volt switchgear on secondary disconnects Disconnects installed in breaker cradle will be replaced
PARSONS,R M Carolina Power & Light Co 10CFR 050 55E 83/04/29 O'REILLY,J P Region 2, Office of Director 4pp 18437 125 24X
Fiche:50-400,83/04/29,8305130027

8305130080 Deficiency rept re Class IE motor control ctrs from ITT Gould containing weld defects Initially reported on 830408 Vendor evaluation to be completed by Jul 1983 Extension until 830713 requested Also reported per Part 21.
PARSONS,R M. Carolina Power & Light Co 10CFR 050 55E 83/05/06 O'REILLY,J P Region 2, Office of Director 1p 18436;264. 24X
Fiche:50-400,83/05/06,8305130080

8305130107 Final Deficiency Rept DER 83-2 re valve operators accidentally interchanged by Posi-Seal on inside & outside containment valves Initially reported on 830125 Operators to be replaced Also reported per Part 21 by Posi-Seal
VAN BRUNT,E E. Arizona Public Service Co 10CFR 050 55E. 83/05/03 STERNBERG,D M. Region 5, Office of Director 4pp 18437 219 24X
Fiche:50-528,83/05/03,8305130107

8305130113 Part 21 rept re low natural frequency of counterbalance assembly,resulting in unacceptable stresses on backdraft damper counterbalance arm Seismic qualification criteria not fully met Investigation & testing underway
HILL,T D Ruskin Manufacturing Co 83/05/10 Director's Office, Office of Inspection and Enforcement 7pp 18438 001 24X
Fiche 50-400,83/05/10,8305130113

8305130148 Revised interim Deficiency Rept DER 82-76 re Target Rock valves not meeting Tech Spec requirements Initially reported on 821124 Revised test plan reviewed by Bechtel Final rept expected by 830823 Also reported per Part 21
VAN BRUNT,E E Arizona Public Service Co DER 82-76 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18438 117 24X
Fiche 50-528,83/05/03,8305130148

8305130154 First interim deficiency rept re defects in pipe clamps mfg by ITT Grinnell Initially reported on 830406 Util requested vendor to provide response re action taken to prevent recurrence of problems Also reportable under Part 21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/06 O'REILLY,J P Region 2, Office of Director 3pp 18437 182 24X
Fiche 50-438,83/05/06,8305130154

8305130189 Final Deficiency Rept DER 83-12 re malfunction of GE add-on electric interlocks used w/Class IE,Size 2,starters in 480-volt motor control ctrs Initially reported on 830309 Design change packages issued Also reportable per Part 21
VAN BRUNT,E E Arizona Public Service Co 10CFR 050 55E 83/05/03 STERNBERG,D M Region 5, Office of Director 5pp 18439 340 24X
Fiche 50-528,83/05/03,8305130189

8305130222 Part 21 rept re potential ASME Section III & V violation Initially reported on 830412 Scope & condition of nonconformance under investigation
WHEATON,W R Borg-Warner Corp G-83-007/WRW 83/04/15 MARTIN,J B Region 5, Office of Director 4pp 18439 336 24X
Fiche 50-440,83/04/15,8305130222

8305130248 Interim Deficiency Rept RDC 70(83) re restart of control complex chiller following loss of offsite power or LOCA Initially reported on 830407 Final rept expected by 830815 Also reported per Part 21
EDELMAN,M R Cleveland Electric Illuminating Co 10CFR 050 55E 83/05/06 KEPPLER,J G Region 3, Office of Director 2pp 18439 212 24X Fiche 50-440,83/05/06,8305130248

8305130264 Interim Deficiency Rept DER 83-16 re failure of diesel generator governor & voltage regulator to automatically reset from manual/test mode upon loss of power Initially reported on 830318 Also reportable per 10CFR21
VAN BRUNT,E E Arizona Public Service Co DER 83-16 55E 83/05/03 STERNBERG,D M Region 5, Office of Director 4pp 18439.238 24X
Fiche 50-528,83/05/03,8305130264

8305190005 Final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities Forwards App A documents Documents denoted w/asterisk available in PDR App B,C,D & E documents withheld (ref FOIA Exemption 7)
FELTON,J M Division of Rules and Records 83/03/11 PRENDERGAST,R Prendergast, R J 17pp 18506 059 24X
Fiche 50-000,83/03/11,8305190005

--8305190112 Deficiency rept re errors & discrepancies contained in HVAC matl certifications Procurement documentation will be revalidated,document & records mgt program will be developed & QA/QC personnel will be added Also reportable per Part 21
CALKINS,D E Zack Co 10CFR 050 55E 81/10/23 310pp 18506 215 24X Fiche 50-000,83/03/11,8305190005

8305200429 Final Significant Deficiency Rept 82-06 re failed sheared pinion keys in Limitorque motor operators supplied by Westinghouse All deficient keys replaced Also reportable per Part 21
WOOLEVER,E J Duquesne Light Co 10CFR 050 55E 83/05/10. ALLAN,J Region 1, Office of Director 5pp 18517 145 24X
Fiche 50-412,83/05/10,8305200429

8305200495 Supplementary Part 21 rept re adequacy of svc water cooling tower structure Transverse shear design adequate No defects exist Design of structure mods expected to be completed by 830630
SARSTEN,G E United Engineers & Constructors, Inc (subs of Raytheon Co) 83/04/29 Region 1, Office of Director 3pp 18514 033 24X Fiche 50-443,83/04/29,8305200495

8305230525 Final deficiency rept re Westinghouse reactor trip switchgear undervoltage attachments w/design discrepancy Initially reported on 830422 Attachments replaced Mfg drawings & QC procedures modified Also reported per Part 21
OPREA,G W Houston Lighting & Power Co 10CFR 050 55E 83/05/18 COLLINS,J T Region 4, Office of Director 4pp 18536 319 24X
Fiche 50-498,83/05/18,8305230525

8305230545 Second interim rept re generic deficiencies at Consolidated Controls Corp Initially reported on 820916 Evaluation indicates QC problems corrected & equipment failures random Also reported per Part 21 Next rept by 831117
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/18
O'REILLY,J P Region 2, Office of Director 2pp 18537 085 24X
Fiche 50-438,83/05/18,8305230545

8305240356 Part 21 rept re bolting parts for ASME III NF Class 1 pipe supports on rigid struts or pipe clamps for struts or snubbers Initially reported on 830513 Bolting parts greater than 2-inch size not examined
HOVE,L NPS Industries, Inc PT21 83-876-000 83/05/16
DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 1p 18574 001 24X Fiche 50-000,83/05/16,8305240356

8305240405 Recommends consideration be afforded to contacting listed utils to determine review & mod status of deficient vertical lift metal-clad switchgear mfg by GE
POTAPOVS,U Division of Vendor & Technical Programs 83/05/19
BAER,R L Engineering & Generic Communications Branch 2pp 18574 279

8305250435 Final rept re deficiencies in Ameron cement mortar lining Initially reported on 820521 Corrections to each deviation listed Also reportable per 10CFR21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/20
O'REILLY,J P Region 2, Office of Director 6pp 18585 293 24X
Fiche 50-390,83/05/20,8305250435

8305270625 Part 21 rept re potential problem w/3-phase rectifier assembly in exciter not connected in parallel which could cause premature failure Initially reported on 830520 Utils will measure vibration
HAISLER,R K Litton Industries, Inc 83/05/20 KEPPLER,J G Region 3, Office of Director 3pp 18646 212 24X Fiche 50-000,83/05/20, 8305270625

8305310138 Seventh interim deficiency rept re inconsistency between assumptions for pipe break in LOCA & structural analyses for connecting pipes in affected loop Initially reported on 801121 Next rept by 831118 Also reported per Part 21
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/23
O'REILLY,J P Region 2, Office of Director 2pp 18656 123 24X
Fiche 50-438,83/05/23,8305310138

8305310214 Eighth interim deficiency rept re B&W nonconservative analysis of neutron flux Initially reported on 801103 Also reportable per Part 21 Util awaiting results of B&W analysis Next rept will be submitted by 831024
MILLS,L M Tennessee Valley Authority 10CFR 050 55E 83/05/23
O'REILLY,J P Region 2, Office of Director 2pp 18658 146 24X
Fiche 50-438,83/05/23,8305310214

QA999 QUALITY ASSURANCE INSPECTIONS

8305020254 Confirms QA program insp on 830324-27 at Radiation Technology,Rockaway,NJ plant,per 830425 telcon
POTAPOVS,U Region 4, Office of Director 83/04/28 WELT,M A
Radiation Technology 1p 18281 298

8305020261 Ack receipt of 830308 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900913/82-02
POTAPOVS,U Region 4, Office of Director 83/04/28 DIETZ,G R
Isomedix, Inc (subs of Masefield Enterprises, Inc) 1p
18277 251

--8305020268 Responds to NRC 830207 ltr re nonconformance noted in QA Program Insp Rept 99900913/82-02 Corrective actions operators given formal instructions re calculation of dose rate & QC manuals revised
TYMPANICK,L Isomedix, Inc (subs of Masefield Enterprises, Inc) 83/03/08 POTAPOVS,U Region 4, Office of Director
12pp 18277 252

8305020289 Forwards QA Program Insp Rept 99900403/82-03 on 820628-0701 & 0713-15 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 83/02/02
BRUGGEMAN,W H General Electric Co 2pp 18277 176

--8305020295 Notice of nonconformance from insp on 820628-0701 & 0713-15
* Region 4, Office of Director 83/02/02 1p 18277 178

--8305020307 QA Program Insp Rept 99900403/82-03 on 820628-0701 & 0713-15 Noncompliance noted documented instructions or procedures not utilized to communicate quality requirements re dispositioning of potential design action items
CHAMBERLAIN,D , HALE,C J Region 4, Office of Director 82/08/19
17pp 18277 179.

8305020316 Forwards QA Program Insp Rept 99900403/82-04 on 820628-0719. No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/02/02 BRUGGEMAN,W H
General Electric Co 2pp 18277 140

--8305020319 QA Program Insp Rept 99900403/82-04 on 820628-0719 No noncompliance noted Major areas inspected interview of former employee re number of Mark III containment unresolved issues per Part 21 requirements
WILLIAMSON,E L , BURCH,R H , ALDERSON,C E Region 4, Office of Director 82/08/20 4pp 18277 142

8305020346 Confirms QA program insp at Tustin,CA plant on 830502-06,per 830415 telcon
POTAPOVS,U Region 4, Office of Director 83/04/28 CHIN,A
Radiation Sterilizers, Inc 1p 18277 064

8305020364 Ack receipt of 830228 & 0407 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900403/82-03
POTAPOVS,U Region 4, Office of Director 83/04/28 BRUGGEMAN,W H
General Electric Co 1p 18284 025

--8305020365 Responds to NRC 830317 ltr requesting addl info re nonconformance noted in QA Program Insp Rept 99900403/82-03 Requirements for design actions formally documented in engineering operation procedures
BOHL,L S General Electric Co. 83/04/07 POTAPOVS,U. Region 4, Office of Director 2pp 18284 026

--8305020366 Ack receipt of 830228 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900403/82-03 Addl info needed re actions on design action item list
POTAPOVS,U Region 4, Office of Director 83/03/17
BRUGGEMAN,W H General Electric Co 1p 18284.028

--8305020369 Forwards response to NRC 830202 ltr re nonconformance noted in QA Program Insp Rept 99900403/82-03 Corrective actions: Engineering Operating Procedure 55-4 00, "Change Control Board," revised on 820714
BOHL,L S General Electric Co 83/02/28 POTAPOVS,U Region 4, Office of Director 2pp 18284 029

8305020420 Summary of 830422 meeting w/Westinghouse in East Pittsburgh, PA re reactor trip breaker problems Changes in mfg controls & QA program planned Attendance list encl
POTAPOVS,U Division of Vendor & Technical Programs 83/04/28
Division of Vendor & Technical Programs 4pp 18273 124

8305020448 Confirms QA program insp at Cherry Hill,NJ ofc on 830502-06 per 830420 telcon
POTAPOVS,U Region 4, Office of Director. 83/04/28 KELLY,R B
Stone & Webster Engineering Corp 1p 18283 179.

8305030330 Forwards QA Program Insp Repts 99900373/83-01 & 99900296/82-01 re Agastat GPDC-740 relay defects Ameraca Corp should be contacted to determine likely customers of grade relays W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/04/29.
BAER,R L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 18297 161

8305030349 Forwards QA Program Insp Rept 99900759/83-01 on 821129-1203
POTAPOVS,U Region 4, Office of Director 83/04/15. BUNDSTEDT,J E
Woodward Governor Co 2pp 18297 118

--8305030351 QA Program Insp Rept 99900759/83-01 on 821129-1203. No noncompliance noted Major areas inspected defective governor furnished to Palisades & deficient EGB-13P actuator furnished to Stewart & Stevenson Svcs,Inc.
FOSTER,W E , BARNES,I Region 4, Office of Director 83/03/31.
13pp 18297.120

8305030358 Forwards QA Program Insp Rept 99900769/83-01 on 830207-10 & notice of nonconformance.
POTAPOVS,U Region 4, Office of Director 83/04/15 HESS,L.R.
Pacific Air Products Co 2pp 18291 342

--8305030362 Notice of nonconformance from insp on 830207-10.
* Region 4, Office of Director 83/04/15. 1p. 18291.344.

--8305030366 QA Program Insp Rept 99900769/83-01 on 830207-10 Noncompliance noted:records not maintained to indicate evaluation made for reportability of defectively-mounted blade locks in safety-related fire dampers.
OLLER,R E , BARNES,I. Region 4, Office of Director. 83/04/15.
16pp 18291 345

8305030363 Forwards GA Program Insp Rept 99900053/83-01 on 830125-28 Followup on failure to perform verification of torque adequacy requested W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/04/28
NORELIUS,C E Division of Engineering 1p 18306 297

8305030377 Forwards GA Program Insp Rept 99900769/83-01 on 830207-10 identifying potential loose locks on fire dampers at McGuire station W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/04/29
LEWIS,R L Division of Project & Resident Programs 1p 18306 293

8305030413 Recommends actions be taken to verify whether welding in place has been accomplished & impact of mounting on seismic qualification re vendor insp at En-Tronic Controls of diesel generator high voltage cubicles & foundations
POTAPOVS,U Division of Vendor & Technical Programs 83/04/29
CREWS,J L Division of Resident,Reactor Project & Engineering Programs 1p 18306 315

8305030427 Informs that AITS F03034682 re defective diesel generator governor at Palisades closed following insp at Engine & Turbine Controls Div of Woodward Governor Co W/o GA Program Insp Rept 99900759/82-01
POTAPOVS,U Division of Vendor & Technical Programs. VITS 82-254 83/04/29 SPESSARD,R L Division of Project & Resident Programs 1p 18306 276

8305030466 Forwards GA Program Insp Rept 99900053/83-01 on 830125-28 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director. 83/04/12 CAROD,A E Anchor/Darling Valve (subs Anchor/Darling Industries) 2pp 18294:152

--8305030471 Notice of nonconformance from insp on 830125-28
* Region 4, Office of Director 83/04/12. 2pp 18294 154

--8305030475 GA Program Insp Rept 99900053/83-01 on 830125-28 Noncompliance noted design rept for 900-lb feedwater isolation valves furnished to Waterford Unit 3 did not address validity of valve closing design
KELLEY,W D., BARNES,I Region 4, Office of Director 83/04/07 10pp 18294 156

8305030509 Forwards GA Program Insp Rept 99900373/83-01 on 830214-18 & notices of nonconformance & violation
POTAPOVS,U Region 4, Office of Director 83/04/12 DEKKER,H A Entronic Co 3pp 18295 305

--8305030511 Notice of violation from insp on 830214-18
* Region 4, Office of Director 83/04/12. 2pp 18295.308

--8305030518 Notice of nonconformance from insp on 830214-18
* Region 4, Office of Director. 83/04/12 2pp 18295 310

--8305030525 GA Program Insp Rept 99900373/83-01 on 830214-18 Noncompliance noted current copies of Section 206 of Energy Reorganization Act not posted & procedures not adopted to provide for deviation evaluations & informing director
FOSTER,W E , BARNES,I Region 4, Office of Director 83/04/04 9pp 18295·312.

8305030520 Requests guidance for insp of vendors not committed to App B of 10CFR50 or 10CFR21. Insp of Woodward Governor Co discussed GA Program Insp Rept 99900759/82-01 not encl.
BANGART,R L Division of Vendor & Technical Programs 83/04/20
TAYLOR,J. Division of Engineering & Quality Assurance (Pre 830103) 2pp. 18295·321

8305030544 Forwards GA Program Insp Rept 99900769/83-01 on 830207-10 re potential loose locks on fire dampers W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/04/29
STAROSTECKI,R Division of Project & Resident Programs 1p. 18303 265

8305050068 Forwards GA Program Insp Rept 99900303/83-01 on 830308-10 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/04/21 METTA,S Applied Engineering Co 2pp 18339.094

--8305050071 GA Program Insp Rept 99900303/83-01 on 830308-10 No noncompliance noted Major areas inspected mgt meeting,status of previous insp findings,10CFR21 insp,GA program,mfg process control,corrective action & audits
SUTTON,J W , BARNES,I Region 4, Office of Director 83/04/20 7pp 18339 096

8305050088 Forwards GA Program Insp Rept 99900017/83-01 on 830228-0304 & notices of nonconformance & violation
POTAPOVS,U Region 4, Office of Director. 83/04/21 ANDERSON,K Dravo Corp 3pp. 18342:028

--8305050090 Notice of violation from insp on 830228-0304
* Region 4, Office of Director 83/04/21 1p 18342 031

--8305050091 Notice of nonconformance from insp on 830228-0304
* Region 4, Office of Director 83/04/21 3pp 18342 032

--8305050093 GA Program Insp Rept 99900017/83-01 on 830228-0304 Noncompliance noted failure to post regulations/procedures in either of two fabrication shop bldgs & failure to generate nonconformance repts for five rejected fittings
CONWAY,J T , BARNES,I Region 4, Office of Director 83/04/20 9pp 18342 035

8305050094 Forwards GA Program Insp Rept 99900401/83-01 on 830308-10 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/04/19 ETHERIDGE,M R Combustion Engineering, Inc 2pp 18342 012

--8305050097 GA Program Insp Rept 99900401/83-01 on 830308-10 No noncompliance noted Major areas inspected status of previous insp findings re shoulder gap problems at five facilities
MCNEILL,W M , BARNES,I Region 4, Office of Director 83/04/15 6pp 18342 014

8305050102 Forwards GA Program Insp Rept 99900002/83-01 on 830308-10 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/04/21
LICHENBERGER,H Combustion Engineering, Inc 3pp 18341 319

--8305050104 Notice of nonconformance from insp on 830308-10
* Region 4, Office of Director 83/04/21 1p 18341 322

--8305050110 GA Program Insp Rept 99900002/83-01 on 830308-10 Noncompliance noted failure to enter release number for poison pellets & compression sleeve used for Lot 115-1 & traveler for Lot 128-1 missing release number
MCNEILL,W M , BARNES,I Region 4, Office of Director. 83/04/19 6pp 18341 323

8305050107 Forwards GA Program Insp Rept 99900348/83-01 on 830222-25 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/04/13 O'CONNELL,T J NPS Industries, Inc 2pp 18342 167

--8305050111 GA Program Insp Rept 99900348/83-01 on 830222-25 No noncompliance noted Major areas inspected status of previous insp findings,mfg process control,equipment calibr & procurement document control
OLLER,R E , BARNES,I Region 4, Office of Director 83/04/04 11pp 18342 169

8305050114 Forwards GA Program Insp Rept 99900911/83-01 on 830207-11 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/04/13 BRUGGEMAN,W H General Electric Co 2pp 18342 180

--8305050115 Notice of nonconformance from insp on 830207-11
* Region 4, Office of Director 83/04/13 2pp 18342 182

--8305050117 GA Program Insp Rept 99900911/83-01 on 830207-11 Noncompliance noted environ qualification testing initiated before review approval & issuance of product performance qualification Spec PPGS 22A5768
AGEE,J R , PHILLIPS,H S Region 4, Office of Director 83/04/08 14pp. 18342:184

8305050145 Forwards GA Program Insp Rept 99900264/83-01 on 830214-18 No noncompliance noted
POTAPOVS,U Division of Vendor & Technical Programs 83/04/19
HAGGARD,K D Dragon Valves, Inc 2pp 18341 093

--8305050149 GA Program Insp Rept 99900264/83-01 on 830214-18 No noncompliance noted Major areas inspected GA program (organization),nonconformance/corrective action,process control,final insp,assembly & test & audits
SUTTON,J W , BARNES,I Region 4, Office of Director 83/04/15 9pp 18341:095

8305050160 Discusses GA Program Insp Rept 99900224/83-01 on 830214-18 Appropriate corrective action taken & problem re ECCS cabinets incorrectly wired determined not generic
POTAPOVS,U Division of Vendor & Technical Programs 83/05/02
SPESSARD,R.L Division of Project & Resident Programs 1p 18341 360

8305050162 Forwards GA Program Insp Rept 99900795/83-01 on 830314-17 & notices of nonconformance & violation
POTAPOVS,U Region 4, Office of Director 83/04/21 LOTT,J E E L Manufacturing Peebles, Inc 3pp 18339 352

--8305050169 Notice of violation from insp on 830314-17
* Region 4, Office of Director 83/04/21 1p 18339 355

--8305050171 Notice of nonconformance from insp on 830314-17
* Region 4, Office of Director 83/04/21 1p 18339 356

--8305050179 QA Program Insp Rept 99900795/83-01 on 830314-17
Noncompliance noted all unidentified electrodes were not discarded & current copy of 10CFR21 not posted
MCNEILL,W M , BARNES,I Region 4, Office of Director 83/04/20
7pp 18339 357

8305050177 Forwards QA Program Insp Rept 99900323/83-01 on 830222-25 & notices of nonconformance & violation
POTAPOVS,V Region 4, Office of Director 83/04/13 ADAMS,J
Conax Corp 2pp 18341 039

--8305050181 Notice of violation from insp on 830222-25
* Region 4, Office of Director. 83/04/13 1p 18341 041

--8305050184 Notice of nonconformance from insp on 830222-25
* Region 4, Office of Director 83/04/13 2pp 18341 042

--8305050192 QA Program Insp Rept 99900323/83-01 on 830222-25
Noncompliance noted records for all lead auditors not updated annually,10CFR21 & procedures not posted & testing for Brand-Rex control cables not performed
SMITH,A L , PHILLIPS,H S Region 4, Office of Director 83/04/07
18pp 18341 044

8305050219 Forwards QA Program Insp Rept 99900525/83-01 on 830228-0304
No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/04/15 LORENZ,H
Gilbert/Commonwealth Cos 2pp. 18338 076

--8305050226 QA Program Insp Rept 99900525/83-01 on 830228-0304 No noncompliance noted Major areas inspected status of previous insp findings,internal audit program & review of design activities associated w/clamp-induced local pipe stresses
HARRELL,P H , HALE,C J Region 4, Office of Director 83/04/13
14pp 18338 078

8305050237 Forwards QA Program Insp Rept 99900224/83-01 on 830214-18
No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/04/15 KEYES,M A
Bailey Controls Co (subs of Babcock & Wilcox Co) 3pp 18337 302

--8305050241 QA Program Insp Rept 99900224/83-01 on 830214-18 No noncompliance noted Major areas inspected 10CFR50 55e rept re wiring errors in emergency core cooling actuation sys at Midland Units 1 & 2
PARKER,L B , BARNES,I Region 4, Office of Director 83/04/14
24pp 18337 305

8305050251 Forwards QA Program Insp Rept 99900905/83-01 on 830117-20 & notices of nonconformance & violation
POTAPOVS,U Region 4, Office of Director 83/04/21 SADLIER,R C
Wyle Laboratories 3pp 18337 342

--8305050255 Notice of violation from insp on 830117-20
* Region 4, Office of Director 83/04/21 1p 18337 345

--8305050258 Notice of nonconformance from insp on 830117-20
* Region 4, Office of Director 83/04/21 2pp 18337 346

--8305050262 QA Program Insp Rept 99900905/83-01 on 830117-20
Noncompliance noted.failure to post current regulations, insufficient info in QA manual & failure to conduct mgt audit of QA program
AGEE,J R Region 4, Office of Director PHILLIPS,H S Division of Vendor & Technical Programs 83/04/14 15pp 18337 348

8305090001 Ack receipt of 830331 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900761/83-01
POTAPOVS,U Region 4, Office of Director 83/04/21. MORROW,R
Reliance Electric Co 1p 18364 052

--8305090003 Responds to NRC 830225 ltr re nonconformances noted in QA Program Insp Rept 99900761/83-01 Corrective actions last phase of retraining program completed 821130 Evaluation of suppliers of calibr svc will be completed 830520
MORROW,R Reliance Electric Co 83/03/31. POTAPOVS,U Region 4, Office of Director 2pp 18364 053

8305090371 Ack receipt of 830418 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900512/83-01
POTAPOVS,U Region 4, Office of Director 83/05/04 BUPP,L P
Quadrex Corp 1p 18363 356

--8305090388 Responds to NRC 830325 ltr re nonconformance noted in QA Program Insp Rept 99900512/83-01 Corrective actions audit completed on 821006 QA procedure revised to require advisement should any response to external insp not be met
BUPP,L P Quadrex Corp LPB-83-022 83/04/18 POTAPOVS,U
Region 4, Office of Director 2pp 18363 357

8305090386 Forwards QA Program Insp Rept 99900283/83-01 on 830228-0304, notice of violation & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/04/20 MANCHESTER,E
BIW Cable Systems, Inc 2pp 18363 038

--8305090393 Notice of violation from insp on 830228-0304
* Region 4, Office of Director 83/04/20 1p 18363 040

--8305090406 Notice of nonconformance from insp on 830228-0304
* Region 4, Office of Director 83/04/20 3pp 18363:041

--8305090413 QA Program Insp Rept 99900283/83-01 on 830228-0304
Noncompliance noted safety-related testing svcs procured from Associated Testing Labs & Isomedix,Inc w/o specifying applicability of 10CFR21 provisions
SMITH,A L , PHILLIPS,H S Region 4, Office of Director 83/04/15
18pp 18363 044

8305090392 Forwards QA Program Insp Rept 99900370/83-01 on 830131-0204 & notice of nonconformance
POTAPOVS,U Region 4, Office of Director 83/04/20 KULB,B.
Garrett Corp 2pp 18363 026

--8305090398 Notice of nonconformance from insp on 830131-0204
* Region 4, Office of Director. 83/04/20 1p 18363 028

--8305090403 QA Program Insp Rept 99900370/83-01 on 830131-0204
Noncompliance noted NRC not formally notified per Part 21 that shipped solenoid valves contained defect & QA program did not include identification & control sys
SUTTON,J W , HAMILTON,J Region 4, Office of Director 83/04/14.
9pp 18363 029

8305090450 Confirms QA program insp at Process Technology on 830607-10, per 820425 telcon
POTAPOVS,U Region 4, Office of Director 83/05/04 WELT,M A
Process Technology, Inc 1p 18362 264

8305090479 Forwards QA Program Insp Rept 99900387/83-01 on 830207-10 & notice of nonconformance
COLLINS,J T Region 4, Office of Director 83/04/20
DISSONNETTE,P QA Technologies, Inc /General Atomic Co 3pp
18362 325

--8305090482 Notice of nonconformance from insp on 830207-10.
* Region 4, Office of Director 83/04/20 3pp 18362 328.

--8305090485 QA Program Insp Rept 99900387/83-01 on 830207-10
Noncompliance noted 820323 ltr to NRC failed to assure adherence to stipulated test methods & series of training sessions did not provide clear direction
MCNEILL,W M , BARNER,I Region 4, Office of Director 83/04/15.
7pp 18362 331

8305100336 Ack receipt of 830125 & 0329 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900902/82-08
POTAPOVS,U Region 4, Office of Director 83/05/04 HOLBROOK,W W
Wyle Laboratories 1p 18378 337

--8305100343 Requests addl info re responses to Nonconformances A 3,A 2 & C noted in QA Program Insp Rept 99900902/82-08 Info requested within 25 days
POTAPOVS,U Region 4, Office of Director 83/03/14
HOLBROOK,W W Wyle Laboratories 2pp 18378 338

--8305100349 Responds to 830314 request for addl info re Nonconformances A 3,A 2 & C QA personnel instructed in responsibilities to keep approved procedure list current
HOLBROOK,W W Wyle Laboratories 83/03/29 POTAPOVS,U. Region 4, Office of Director 3pp 18378 340

--8305100355 Responds to NRC 830104 ltr re nonconformance noted in QA Program Insp Rept 99900902/82-08 Corrective actions QA program changed to eliminate requirement for QA/safety job requirements review
HOLBROOK,W W Wyle Laboratories 83/01/25 POTAPOVS,U Region 4, Office of Director 16pp 18378 343

8305120305 Confirms QA program insp on 830509-13 at Chicago ofc per 830504 telcon
POTAPOVS,U Region 4, Office of Director 83/05/06 PATTERSON,R W Sargent & Lundy, Inc 1p 18424 207

8305120394 Forwards QA Program Insp Rept 99900768/82-02 on 820128-0310 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/02/09 KOH,B Hittman Nuclear & Development Corp (subs Hittman Corp) 2pp 18432 320

--8305120397 QA Program Insp Rept 99900768/82-02 on 820128-0310 No noncompliance noted Major areas inspected allegations by former employee re quality of HN-100 Series 1,HN-1003 & HN-200 shipping casks.
SHEPHERD,R E , CARLSON,R T Region 1, Office of Director 82/07/19 65pp 18432 322

8305120482 Confirms QA program insp at New Haven,CT plant on 830606-10 per 830502 telcon
POTAPOVS,U Region 4, Office of Director 83/05/10 REED,E S Rockbestos Co 1p 18431 054

8305170541 Confirms QA program insp at Culver City,CA plant on 830523-27,per 830504 telcon Insp will cover equipment qualification testing of safety-related equipment
POTAPOVS,U Region 4, Office of Director 83/05/13 ENDLER,G J ANCO Engineers, Inc 1p 18468 027

8305170549 Confirms QA program insp at Whippany,NJ plant on 830531-0602,per 830509 telcon
POTAPOVS,U Region 4, Office of Director 83/05/13 DIETZ,G R Isomedix, Inc (subs of Masefield Enterprises, Inc) 1p 18469 022

8305200308 Ack receipt of 830217 & 0414 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900005/82-02
POTAPOVS,U Region 4, Office of Director 83/05/10 JACOBI,W M Westinghouse Electric Corp 1p 18516 280

--8305200315 Responds to NRC 830322 ltr requesting addl info re nonconformances noted in QA Program Insp Rept 99900005/82-02 Corrective actions meetings held w/quality & customer svcs engineers to review customer needs
RUSSO,H L Westinghouse Electric Corp PA-83-012. 83/04/14 POTAPOVS,U Region 4, Office of Director 2pp. 18516 281

--8305200323 Ack receipt of 820217 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900005/82-02 Addl info needed confirming that actions implemented re documentation of reviews
POTAPOVS,U Region 4, Office of Director 83/03/22 JACOBI,W M Westinghouse Electric Corp 1p 18516 283

--8305200332 Responds to NRC 830118 ltr re nonconformances noted in QA Program Insp Rept 99900005/82-02 Corrective actions procedures for order & spec review evaluated w/quality & customer svc engineers
RUSSO,H L Westinghouse Electric Corp PA-83-008 83/02/17 POTAPOVS,U Region 4, Office of Director 5pp 18516 285

8305200333 Forwards QA Program Insp Rept 99900503/83-01 on 830318 No noncompliance noted
POTAPOVS,U Region 4, Office of Director 83/05/04 HENDRICKSON,T Burns & Roe Co 2pp. 18516 220

--8305200340 QA Program Insp Rept 99900503/83-01 on 830318 No noncompliance noted Major areas inspected piping stress analysis in area of pipe clamps mfg by E-Bys & status of previous nonconformances
BEARS,P , HALE,C J Region 4, Office of Director 83/05/04. 6pp 18516 222

8305200370 Forwards QA Program Insp Rept 99900056/83-01 on 830214-18 & notice of nonconformance Response requested within 30 days.
POTAPOVS,U Region 4, Office of Director 83/04/28. WILSON,A K Henry Pratt Co 3pp 18517 349

--8305200376 Notice of nonconformance from insp on 830214-18
* Region 4, Office of Director 83/04/28 5pp 18517 352

--8305200379 QA Program Insp Rept 99900056/83-01 on 830214-18 Noncompliance noted failure to implement fully QA program to meet training & indoctrination requirements
CONWAY,J T , BARNES,I Region 4, Office of Director 83/04/21 18pp 18517 357

8305200395 Responds to nonconformances noted in QA Program Insp Rept 99900743/82-01 on 821006 & 07 Revs to procedures & data sheets for TVA units returned for mod or rework will be completed by 830130
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/01/04 POTAPOVS,U Region 4, Office of Director 2pp 18518 175

8305200411 Ack receipt of 830104,11 & 0309 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900743/82-01
POTAPOVS,U Region 4, Office of Director 83/05/10 DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 1p 18517 164

--8305200415 Responds to NRC 830215 ltr re nonconformance noted in QA Program Insp Rept 99900743/82-01 Corrective actions QA procedure written to define steps necessary to implement mod of relays returned from field
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/03/09 POTAPOVS,U Region 4, Office of Director 3pp 18517 165

--8305200418 Ack receipt of 830104 & 11 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900743/82-01 Understands procedures will be generated to prevent recurrence Addl info needed re Item C
POTAPOVS,U Region 4, Office of Director 83/02/15 DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 2pp 18517 168

--8305200422 Responds to NRC 821202 ltr re nonconformance noted in QA Program Insp Rept 99900743/82-01.Corrective actions test procedures & data sheets will be revised by 830130
DUVALL,D D Brown Boveri Corp (subs Brown Boveri & Co , Ltd) 83/01/11 POTAPOVS,U Region 4, Office of Director 3pp 18517 172

8305200443 Confirms QA program insp on 830613-16 at Milford,OH plant, per 830427 telcon
POTAPOVS,U Region 4, Office of Director 83/05/17 FARWELL,C R Farwell & Hendrix, Inc 1p 18517 118

8305200444 Ack receipt of 821122 & 830314 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900782/82-01
POTAPOVS,U Region 4, Office of Director 83/05/10 FLANNERY,E J Brunswick Co 1p 18513 045

--8305200457 Responds to NRC 830131 ltr re nonconformance noted in QA Program Insp Rept 99900782/82-01 All procedures will be fully operational by 830630 Rev to QA manual defining procedure for handling latent defects added
FLANNERY,E J Brunswick Co 83/03/14 POTAPOVS,U Region 4, Office of Director 2pp 18513 046

--8305200462 Ack receipt of 821122 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900782/82-01 Requests addl info per F Vollmer 830107 telcon re audits,tool insp card initiation & labeling
POTAPOVS,U Region 4, Office of Director 83/01/31 FLANNERY,E J Brunswick Co 2pp 18513 048

--8305200468 Responds to NRC 821105 ltr re nonconformance noted in QA Program Insp Rept 99900782/82-01 Corrective actions QA procedural changes will be implemented & fully operational by 830630
FLANNERY,E J Brunswick Co 82/11/22 POTAPOVS,U Region 4, Office of Director 27pp 18513 050

8305200589 Ack receipt of 830428 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900519/83-01
POTAPOVS,U Region 4, Office of Director 83/05/13 KOMES,J M Bechtel Corp 1p 18514 041

--8305200593 Responds to NRC 830331 ltr re nonconformance noted in QA Program Insp Rept 99900519/83-01 Corrective actions Procedure EDPI 4.62-12 revised to allow review through approval process of field change notice & request
KOMES,J M Bechtel Corp QA5-83/115 83/04/28 POTAPOVS,U Region 4, Office of Director 3pp 18514 042

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED,C Commonwealth Edison Co 6434N 83/05/11 DENTON,H R
Office of Nuclear Reactor Regulation, Director 10pp 18521 085
24X Fiche 50-000,83/05/11,8305200621

--8305200684 Advises that Westinghouse QA program implementation described in WCAP-8370,Rev 9A,satisfactory
SEYFRIT,K V Region 4, Dallas, Office of the Director (81/03/01)
81/04/30 SLEMBER,R J Westinghouse Electric Corp 2pp
18522 259 24X Fiche 50-373,83/05/11,8305200621

8305200668 Forwards QA Program Insp Rept 99900794/83-01 on 830317 & notice of nonconformance
POTAPOVS,U Division of Vendor & Technical Programs 83/05/04
EGGERS,P E Ridihalgh, Eggers & Associates 2pp 18519 099

--8305200673 Notice of nonconformance from insp on 830317
* Region 4, Office of Director 83/05/04 1p 18519 102

--8305200678 QA Program Insp Rept 99900794/83-01 on 830317 Noncompliance noted design change failed to eliminate formation of void in siphon tube
MCNEILL,W M , BARNES,I Region 4, Office of Director 83/05/03
3pp 18519 103

8305230497 Forwards QA Program Insp Rept 99900056/83-01 on 830214-18 AITS Items F02700250,F02700301,302 & 303 re failed pneumatic actuators closed W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/05/19
LEWIS,R C Division of Project & Resident Programs 1p 18537 141

8305230514 Forwards QA Program Insp Rept 99900056/83-01 on 830214-18 Insp uncovered leakage & closure problems w/Henry Pratt butterfly valves W/o encl
POTAPOVS,U Division of Vendor & Technical Programs 83/05/19
SPESSARD,R L Division of Project & Resident Programs 2pp
18537 168

8305240333 Confirms QA program insp at Huntsville,AL test facility on 830627-0701,per 830511 telcon Insp will address electrical equipment qualification process for safety-related Class IE equipment
POTAPOVS,U Region 4, Office of Director 83/05/20 SMITH,E W
Wyle Laboratories 1p 18572 341

8305240336 Ack receipt of 830415 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900273/83-01 Vendor not excused from compliance Extension for response granted until 830601
POTAPOVS,U Region 4, Office of Director 83/05/20 SCHMIDT,W J
Westinghouse Electric Corp 2pp 18549 361.

8305240344 Ack receipt of 830413 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900900/83-01
POTAPOVS,U Region 4, Office of Director 83/05/20 SLEMBER,R J
Westinghouse Electric Corp 1p 18574:079

--8305240346 Responds to NRC 830317 ltr re nonconformance noted in QA Program Insp Rept 99900900/83-01 Corrective actions test & execution & test data control procedure manual revised to include description & use of route cards
SLEMBER,R J Westinghouse Electric Corp PI&DA-83-719 83/04/13
POTAPOVS,U Region 4, Office of Director 2pp 18574 080

8305240352 Ack receipt of 830302 & 0422 ltrs informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900289/82-03
POTAPOVS,U Region 4, Office of Director 83/05/20 TESTWUIDE,R R
Borg-Warner Corp 1p 18575 073

--8305240357 Responds to NRC 830325 ltr re nonconformance noted in QA Program Insp Rept 99900289/82-03 Corrective actions: personnel instructed not to utilize vendors not appearing on approved vendor list
MILINAZZO,P L Borg-Warner Corp G-83-083/PLM 83/04/22
POTAPOVS,U Region 4, Office of Director. 1p 18575 074

--8305240361 Ack receipt of 830302 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 99900289/82-03 Requests description methods to prevent recurrence & use of vendor not on approved list
POTAPOVS,U Region 4, Office of Director 83/05/25
TESTWUIDE,R R Borg-Warner Corp 1p 18575 075

--8305240363 Responds to NRC 830118 ltr re nonconformance noted in QA Program Insp Rept 99900289/82-03 Corrective actions list of vendors used for calibr svcs reviewed,updated & added to nuclear products approved vendor list
MILINAZZO,P L Borg-Warner Corp G-83-049/NMS 83/03/02.
POTAPOVS,U Division of Vendor & Technical Programs 2pp
18575 076

8305240400 Ack receipt of 830504 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900905/83-01
POTAPOVS,U Region 4, Office of Director 83/05/20 HOUSTEAU,L
Wyle Laboratories 1p 18574 192

--8305240403 Responds to NRC 830421 ltr re nonconformance noted in QA Program Insp Rept 99900905/83-01 Corrective actions procedures revised,mgt audits & purchase orders reviewed & audits supervised by lead auditor
HOUSTEAU,L Wyle Laboratories 83/05/04 POTAPOVS,U Region 4, Office of Director 4pp 18574 193

8305240411 Ack receipt of 830429 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900501/83-01 Extension of 30 days for response granted
POTAPOVS,U Region 4, Office of Director 83/05/20 WAHL,H.W
Bechtel Corp 1p 18573 354

--8305240415 Responds to NRC 830330 ltr re nonconformance noted in QA Program Insp Rept 99900501/83-01 Corrective actions 30-day extension requested to prepare rept re supplier surveillance program improvements Drawings will be revised
WAHL,H W Bechtel Corp 83/04/29 POTAPOVS,U Region 4, Office of Director 2pp 18573 355

8305240419 Confirms QA program insp at Richland,WA site on 830606-10, per 830224 telcon Insp will address QA program implementation
POTAPOVS,U Region 4, Office of Director 83/05/20 VOLMER,C.J
Exxon Nuclear Co , Inc (subs of Exxon Corp), 1p 18574 281

8305240424 Confirms QA program insp at Columbia,SC site on 830620-24, per 830224 telcon Insp will address QA program implementation
POTAPOVS,U Region 4, Office of Director, 83/05/20 JACOBI,W.M.
Westinghouse Electric Corp 1p 18573 035

8305240426 Forwards QA Program Insp Rept 99900311/83-01 on 830228-0304, notices of violation & nonconformance
POTAPOVS,U Region 4, Office of Director 83/04/25, GREENE,R
General Electric Co 3pp 18574.128

--8305240433 Forwards corrected notice of violation for QA Program Insp Rept 99900311/83-01
POTAPOVS,U Region 4, Office of Director 83/05/03 GREENE,R
General Electric Co 1p 18574·131

--8305240437 Corrected notice of violation from insp on 830228-0304
* Region 4, Office of Director, 83/05/03 1p. 18574.132

--8305240445 Notice of violation from insp on 830228-0304
* Region 4, Office of Director, 83/05/03 1p 18574·133

--8305240452 Notice of nonconformance from insp on 830228-0304.
* Region 4, Office of Director 83/04/25 2pp 18574 134.

--8305240462 QA Program Insp Rept 99900311/83-01 on 830228-0304. Noncompliance noted failure to notify NRC of 4 16-kV vertical lift metal-clad switchgear failure to comply w/ momentary current tests per ANSI Std C37 20-1974
FOSTER,W E , BARNES,I Region 4, Office of Director 83/04/21
10pp 18574 136

8305240431 Informs that QA program,per SWSQAP 1-74A,Rev C, satisfactorily implemented.Continuing QA program acceptability contingent upon satisfactory implementation verified through Vendor Programs Branch insps.
COLLINS,J T Region 4, Office of Director, 83/05/20 KELLY,R B
Stone & Webster Engineering Corp 2pp 18574.124.

--8305240435 Advises that S&W satisfactorily implements QA program per SWSQAP 1-74A,Rev C Confirmation recommended.
CHAMBERLAIN,D Region 4, Office of Director 83/05/18.
COLLINS,J T Region 4, Office of Director 2pp 18574.126

8305260291 Forwards 830513 second interim deficiency rept re cable testing,partially responding to enforcement actions from insp of mfg & testing activities Final rept scheduled for 830630 W/o encl
POTAPOVS,U Region 4, Office of Director 83/05/20 BAER,R.L.
Engineering & Generic Communications Branch, 1p 18625 160.

8305270144 Advises that QA program described in NEDO-11209-04A being implemented satisfactorily Results of insp published quarterly in NUREG-0040
COLLINS, J T Division of Vendor & Technical Programs 83/05/24
BRUGGEMAN, W H General Electric Co 2pp 18638 203

--8305270149 Discusses corrective actions on nonconformances noted in IE insps since Jan 1980 GE satisfactorily implemented QA program per NEDO-11209-04A Confirmation of implementation recommended
CHAMBERLAIN, D Division of Vendor & Technical Programs 83/05/20
COLLINS, J T Region 4, Office of Director 1p 18638 205

8305270267 Forwards QA Program Insp Rept 99900722/83-01 on 830228-0304 & notices of violation & nonconformance
POTAPOVS, U Region 4, Office of Director 83/05/13 JOHNSON, I O
Robert Shaw Controls Co 3pp 18644 274

--8305270272 Notice of violation from insp on 830228-0304
* Region 4, Office of Director 83/05/13 1p 18644 277

--8305270277 Notice of nonconformance from insp on 830228-0304
* Region 4, Office of Director 83/05/13 1p 18644 278

--8305270286 QA Program Insp Rept 99900722/83-01 on 830228-0304 Noncompliance noted copies of Part 21 of Energy Reorganization Act of 1974 posted & procedures adopted per regulations not readily available to personnel
PARKER, L B , BARNES, I Region 4, Office of Director. 83/05/12
8pp. 18644 279

8305270291 Forwards QA Program Insp Rept 99900031/83-01 on 830228-0303 & notice of nonconformance
POTAPOVS, U Region 4, Office of Director 83/05/13 PATTY, D F.
Bingham-Willamette Co 3pp. 18644 305

--8305270298 Notice of nonconformance from insp on 830228-0303
* Region 4, Office of Director 83/05/13 2pp 18644 309

--8305270307 QA Program Insp Rept 99900031/83-01 on 830228-0303 Noncompliance noted no documented evidence that committed training of pump engineering personnel re HX design accomplished
KELLEY, W D , BARNES, I Region 4, Office of Director 83/05/12
12pp 18644 311

8305270302 Forwards QA Program Insp Rept 99900404/83-01 on 830314-16 No noncompliance noted
POTAPOVS, U Region 4, Office of Director 83/05/10 SLEMBER, R J
Westinghouse Electric Corp 2pp 18642 048

--8305270311 QA Program Insp Rept 99900404/83-01 on 830314-16 No noncompliance noted, Major areas inspected difference between post-weld heat treatment on Indian Point Unit 3 steam generators & generators in other plants
CONWAY, J T. , BARNES, I Region 4, Office of Director 83/05/04
6pp 18642 050

REGGD REGULATORY GUIDES

8305160302 Reg Guide 8 31 Task OH 941-4, "Info re Ensuring That Occupational Radiation Exposures at U Mills Will be ALARA "
* Office of Nuclear Regulatory Research, Director 83/05/31 12pp
18462 336

8305200619 Notification of CRGR Meeting 40 on 830601 in Bethesda, MD to discuss proposed amend to 10CFR50 re hydrogen control requirements, proposed insider rulemaking package & operator requalification program
STELLO, V Committee to Review Generic Requirements 83/05/18
EISENHUT, D G. Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E. Office of Nuclear Material Safety & Safeguards, Director. 2pp 18520 158

--8305200654 Draft Reg Guide 5 XXX, "Std Format & Content Guide for Nuclear Reactor Access Authorization Plan "
* NRC - No Detailed Affiliation Given 83/05/03 37pp
18520 289

--8305200661 Draft value/impact statement of power reactor access authorization rule Amend to 10CFR73 proposed to establish uniform min criteria for granting individuals unescorted access to protected areas
* NRC - No Detailed Affiliation Given. 83/05/03 47pp
18520 326.

--8305200671 Draft Reg Guide 5 XXX, "Guidance for Miscellaneous Amends to 10CFR73 55 "
* NRC - No Detailed Affiliation Given 83/05/04 26pp
18521 040

--8305200677 Draft value/impact accessment of miscellaneous amends re physical protection of nuclear power plants
* NRC - No Detailed Affiliation Given 83/05/03 19pp
18521 066

RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

8206100204 Forwards SAI-1-186-03-043-1, "Design Review of Fox-Howlett Reinforcing Bar Splice Sys," technical evaluation rept
JOHNSON, B W Science Applications, Inc NRC-03-82-096 82/06/08
NRC - No Detailed Affiliation Given 1p 18683 243

--8206100210 "Design Review of Fox-Howlett Reinforcing Bar Splice Sys," technical evaluation rept "
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-04
82/06/08 62pp 18683 244

8303080182 "Design Review of Dayton Bar-Grip Reinforcing Bar Splice Sys," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 NRC - No Detailed Affiliation Given 60pp 18526 044

--8303080187 "Design Review of Dayton Bar-Grip Reinforcing Bar Splice Sys," technical evaluation rept refs
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 NRC - No Detailed Affiliation Given 475pp
18526 104

8303080194 "Design Review of Dywidag Threadbar Reinforcing Sys," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 NRC - No Detailed Affiliation Given 57pp 18527 219

--8303080202 "Design Review of Dywidag Threadbar Reinforcing Sys," technical evaluation rept refs
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 NRC - No Detailed Affiliation Given 396pp
18527 279

8303080209 "Design Review of Cadweld Reinforcing Bar Splice Sys," technical evaluation rept
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 NRC - No Detailed Affiliation Given 80pp 18524 178

--8303080215 "Design Review of Cadweld Reinforcing Bar Splice Sys," technical evaluation rept refs
* Science Applications, Inc NRC-03-82-096 SAI-1-186-03-61
83/02/28 488pp 18524 258

8305030025 "Quarterly Mgt Rept ORNL Projects for NRC Ofc of NRR "
LOTTS, A L Oak Ridge National Laboratory 83/04/01 Office of Nuclear Regulatory Research, Director 176pp 18326 124

8305060349 "Definition of Scenarios & Evaluation of Methods for Analyzing Source Terms of Major Accidents Involving U Hexafluoride at NRC Licensed Fuel Cycle Facilities," monthly progress rept for Mar 1983
SIMAN-TOV, M Union Carbide Corp FIN B-0495 83/04/29
BERNSTEIN, S Transportation & Materials Risk Branch 3pp
18353 081

8305110062 "Investigation of Ventilation Component Response to Large-Pressure Pulses," monthly progress rept for Feb 1983
GREGORY, W S Los Alamos Scientific Laboratory FIN A-7028
83/04/08 SOLBERG, D E Transportation & Materials Risk Branch
6pp 18420 318

8305110083 "Investigation of Ventilation Component Response to Large-Pressure Pulse," monthly progress rept for Mar 1983
GREGORY, W S Los Alamos Scientific Laboratory FIN A-7028
83/04/21 SOLBERG, D E Transportation & Materials Risk Branch
6pp 18419 354

8305130292 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities," monthly progress rept for Mar 1983
MARTIN, R A , GREGORY, W S Los Alamos Scientific Laboratory FIN A-7029 83/05/10 BERNSTEIN, S Transportation & Materials Risk Branch 7pp 18458 003

8305250155 "Generic Study of Recycle of Contaminated Matls," monthly progress rept for Apr 1983
TRAVIS, C C Oak Ridge National Laboratory FIN B-0824
NRC-60-10-01-05 83/05/10 BICEHOUSE, H J Transportation & Materials Risk Branch 3pp. 18596 188

8305250168 "Accident Aerosol Characterization," informal monthly progress rept for Apr 1983
OWCZARSKI,P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 83/05/11 BERNSTEIN,S Division of Risk Analysis 5pp 18596 142

8305250174 "Accident Aerosol Characterization," informal monthly progress rept for Mar 1983
OWCZARSKI,P C Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2287 83/05/11 BERNSTEIN,S Division of Risk Analysis 5pp 18596 348

REVIEW GRP NRC RESEARCH REVIEW GROUPS

8303180429 Forwards response to 830208 ltr re backfitting costs of two nuclear power plants All three units have combined capability of 1,539 MWE (summer) net
HADLEY,C D Northern States Power Co 83/03/15 TOURTELLOTTE,J Regulatory Reform Task Force 6pp 18541 041 24X
Fiche 50-000,83/03/15,8303180429

8305040630 Notifies of CRGR Meeting 36 on 830429 to discuss findings of Salem Generic Implications Task Force
STELLO,V Committee to Review Generic Requirements 83/04/27
EISENHUT,D G Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E. Office of Nuclear Material Safety & Safeguards,Director 2pp 18336 306 24X Fiche 50-272,83/04/27, 8305040630

8305050354 Summary of 830301 meeting w/Nuclear Util Fire Protection Group,EPM,Debevoise & Liberman,CPC,Bechtel & GPU re clarification of fire protection rule,App R to 10CFR50
WAMBACH,T V Operating Reactors Branch 5 LS05-83-04-019 83/04/11 Operating Reactors Branch 5 4pp 18352 022

8305060399 Comments on proposed rule re safety goals evaluation plan Milano Natl Nuclear Regulatory Agency presently involved in similar but more restrictive task Requests to be kept informed of proceedings
GARRIBBA,S Instituto di Ingegneria Nucleare, Milan, Italy 48FR10772 83/04/26 Docketing & Services Branch 1p 18343 159

8305110415 Notification of CRGR Meeting 38 on 830518 in Bethesda,MD to discuss proposed rule, "Analysis of Potential Pressurized Thermal Shock Events," prioritization of generic safety issues & operator requalification program Review matl encl
STELLO,V Regional Operations & Generic Requirements 83/05/10
EISENHUT,D G Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 18394 221

--8305110423 Forwards draft FR notice & supporting regulatory assessment on proposed rule re pressurized thermal shock CRGR review requested within 2 wks
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/05/03 STELLO,V Regional Operations & Generic Requirements 36pp 18394 222

--8305110428 Forwards proposed Commission paper discussing prioritization of generic safety issues & transmitting draft NUREG-0933, "Prioritization of Generic Safety Issues " Procedures for identifying & managing issues encl
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/05/02 DIRCKS,W J Office of the Executive Director for Operations 771pp 18394 259

--8305110432 Forwards options for operator requalification exams Administered requalifications option recommended
DENTON,H R Office of Nuclear Reactor Regulation, Director
83/03/07 DIRCKS,W J Office of the Executive Director for Operations 8pp 18396 310

--8305110485 Notification of CRGR Meeting 39 on 830525 in Bethesda,MD to discuss proposed amend to 10CFR71 re transportation regulations & to review proposed ATWS rule 10CFR50 60
STELLO,V Regional Operations & Generic Requirements 83/05/10
EISENHUT,D G Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E. Office of Nuclear Material Safety & Safeguards,Director 2pp 18396 314

--8305110493 Forwards proposed FR notice & regulatory analysis on ATWS rule 10CFR50 60 Addl requirements discussed at CRGR 830420 briefing added Expeditious response requested
MINOGUE,R B Office of Nuclear Regulatory Research, Director
83/05/06 STELLO,V Regional Operations & Generic Requirements 58pp. 18396 320

--8305030722 Requests CRGR review of encl Commission paper to amend 10CFR71 re transportation regulations,per 830120 memo
MINOGUE,R B Office of Nuclear Regulatory Research, Director. 83/04/25 STELLO,V Regional Operations & Generic Requirements, 226pp 66766 146

8305120460 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 HOLTZSCHER,D L Illinois Power Co 2pp 18443 173 24X Fiche 50-000,83/05/02, 8305120460

--8305120470 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 POWELL,P Washington Public Power Supply System 1p 18443 174 24X
Fiche 50-000,83/05/02,8305120460

--8305120477 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 REED,W J Gulf States Utilities Co 1p 18443 175 24X Fiche 50-000,83/05/02, 8305120460

--8305120485 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 RICHARDSON,J D. Mississippi Power & Light Co 1p 18443 176 24X
Fiche 50-000,83/05/02,8305120460

--8305120491 Requests info re issue solutions accepted by NRC which have & have not been addressed in SER/supplemental SERs Info needed to document evaluation on each Licensing Review Group II generic issue
STEFANO,J J Licensing Branch 1 83/05/02 BUZZELLI,E M Cleveland Electric Illuminating Co 1p 18443 177 24X
Fiche 50-000,83/05/02,8305120460

8305120569 Discusses guidelines developed to aid in review of IE Bulletin 79-15 re long-term operability of deep draft pumps Alternate qualification method incorporating vibration monitoring & std plant test procedures proposed encl
NOVAK,T M Assistant Director for Licensing IEB-79-15 83/05/03, HOLTZSCHER,D L Licensing Review Group II 6pp 18440,356 24X
Fiche 50-000,83/05/03,8305120569

8305170275 Notification of CRGR Meeting 37 on 830511 in Bethesda,MD to discuss methodology used to prioritize generic safety issues & operator requalification program
STELLO,V Committee to Review Generic Requirements 83/04/27
EISENHUT,D G Division of Licensing JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 18493 358

8305170715 Lists agenda items from CRGR Meeting 37 postponed until 830518 Meeting 38 Items re methodology used by NRR to prioritize generic safety issues & briefing on operator requalification program among items postponed
STELLO,V Regional Operations & Generic Requirements 83/05/06
EISENHUT,D.G Office of Nuclear Reactor Regulation, Director
JORDAN,E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R Office of Nuclear Material Safety & Safeguards,Director 3pp 18496 253

8305170718 Summary of 830503 meeting w/NRR & CRGR to clarify scope & intent of proposed licensee actions stemming from Salem Generic Implications Task Force Rept (NUREG-1000,Vol 2) Meeting suggested to discuss recommendations on Item 3
TAYLOR,M , SCHWINK,W Regional Operations & Generic Requirements 83/05/06 STELLO,V , MURLEY,T Regional Operations & Generic Requirements 3pp 18496 199

8305190010 Summary of CRGR Meeting 34 on 830420 re technical positions concerning waste classification & form,status of proposed ATWS & proposed IE bulletin on Hayward Tyler Pump Co pumps & spare parts
STELLO,V Regional Operations & Generic Requirements 83/05/04, DIRCKS,W J Office of the Executive Director for Operations, 7pp 18523 213

8305190046 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 18523 198 24X
Fiche 50-000,83/05/03,8305190046

--8305190054 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 HALE,D P Illinois Power Co 2pp 18523 200 24X Fiche 50-000,83/05/03, 8305190046

--8305190060 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 FERGUSON,M R Washington Public Power Supply System 2pp 18523 202 24X Fiche 50-000,83/05/03,8305190046

--8305190068 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 MCGAUGHY,J P Mississippi Power & Light Co 2pp 18523 204 24X
Fiche 50-000,83/05/03,8305190046

--8305190077 Commends representatives of BWR/6 utils participating in Licensing Review Group II for efforts in resolving issues generic to BWR/6 OL applicants
EISENHUT,D G Division of Licensing 83/05/03 CAHILL,J Gulf States Utilities Co 2pp 18523 206 24X Fiche 50-000,83/05/03, 8305190046

8305200535 Forwards "Summary of CRGR Activities for Apr 1983 "
SCHWINK,W Committee to Review Generic Requirements 83/05/17 Committee to Review Generic Requirements 4pp 18516 021

8305200619 Notification of CRGR Meeting 40 on 830601 in Bethesda,MD to discuss proposed amend to 10CFR50 re hydrogen control requirements,proposed insider rulemaking package & operator requalification program
STELLO,V Committee to Review Generic Requirements, 83/05/18
EISENHUT,D G Office of Nuclear Reactor Regulation, Director
JORDAN,E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards,Director 2pp 18520 158

--8305200623 Forwards draft Commission paper on amends to 10CFR50 re hydrogen control for review & comment
MINOGUE,R B Office of Nuclear Regulatory Research, Director
83-083 83/05/12 STELLO,V Committee to Review Generic Requirements 1p 18520 160

--8305200627 Draft Commission paper requesting approval for FR publication of amends to 10CFR50 re hydrogen control
Recommends affirmation at open meeting
DIRCKS,W J Office of the Executive Director for Operations
83/05/10 94pp 18520 161

--8305200634 Forwards draft Commission paper re insider safeguards rulemaking package for concurrence List of safety/safeguards review committee recommendations w/appropriate cross-reference to areas changed by CRGR also encl.
DAVIS,J G Office of Nuclear Material Safety & Safeguards,Director 83/05/13 STELLO,V Committee to Review Generic Requirements 34pp 18520 255

--8305200654 Draft Reg Guide 5 XXX, "Std Format & Content Guide for Nuclear Reactor Access Authorization Plan "
* NRC - No Detailed Affiliation Given 83/05/03 37pp
18520 289

--8305200661 Draft value/impact statement of power reactor access authorization rule Amend to 10CFR73 proposed to establish uniform min criteria for granting individuals unescorted access to protected areas
* NRC - No Detailed Affiliation Given 83/05/03 47pp,
18520 326

--8305200664 Draft value/impact accessment of nuclear power reactor search procedures rule Amend to 10CFR73 55(d)(1) proposed to clarify requirements for searches
* NRC - No Detailed Affiliation Given 83/05/03 29pp
18521 011

--8305200671 Draft Reg Guide 5 XXX, "Guidance for Miscellaneous Amends to 10CFR73 55."
* NRC - No Detailed Affiliation Given 83/05/04 26pp
18521 040

--8305200677 Draft value/impact accessment of miscellaneous amends re physical protection of nuclear power plants
* NRC - No Detailed Affiliation Given 83/05/03 19pp
18521 066

8305230270 "Active Mod Projects,Operating PWR,1982 "
* Consumers Power Co 82/12/31 4pp 18576 332 24X
Fiche 50-000,82/12/31,8305230270

8305230283 Forwards capital cost analysis for backfitting expenditures reflecting both actual costs & estimates for mods planned or in progress
SMITH,S H Carolina Power & Light Co 83/03/22 TOURTELLOTTE,J Regulatory Reform Task Force 13pp 18543 277 24X
Fiche 50-000,83/03/22,8305230283

8305230364 Forwards cost info associated w/backfitting nuclear units, per JL Maulden 830224 commitment
MARSHALL,J R Arkansas Power & Light Co 83/03/11 TOURTELLOTTE,J Regulatory Reform Task Force 11pp 18546 234 24X
Fiche 50-313,83/03/11,8305230364

8305230368 Forwards "Rept on DC Cook Nuclear Power Plant Backfitting & Regulatory Impact Costs," providing cost analysis,per 830208 request
WHITE,W S American Electric Power Co , Inc 83/03/30
TOURTELLOTTE,J Regulatory Reform Task Force 7pp 18544 356 24X
Fiche 50-315,83/03/30,8305230368

8305230387 Responds to 830208 request for backfit info Total of $281 million spent on backfitting through Jul 1982 Add1 $50 million required to complete work on NRC imposed backfits
ARTHUR,J M Duquesne Light Co 83/03/09 TOURTELOTTE,J
Regulatory Reform Task Force 17pp 18546 245 21X
Fiche 50-334,83/03/09,8305230387

8305230393 Forwards analysis of estimated backfitting costs per 830208 ltr Estimated $174 million spent for backfitting Backfitting expenditures will average 40% of annual expenditures from 1977 through 1985
HANCOCK,J A Florida Power Corp NCA83-0145 83/03/25
TOURTELLOTTE,J Regulatory Reform Task Force 2pp 18543 358 24X
Fiche 50-302,83/03/25,8305230393

8305230402 Forwards info on costs incurred from backfitting & upgrading facilities,per 830210 request Mods categorized NRC-required, TMI-lessons learned or util-initiated
DIECKAMP,H General Public Utilities - GPU Service Corp 83/03/08
TOURTELLOTTE,J Regulatory Reform Task Force 9pp 18576 318 24X
Fiche 50-000,83/03/08,8305230402

8305230407 Informs that backfitting matl will be forwarded as soon as available,in response to 830208 ltr
FURDUSH,M H Pacific Gas & Electric Co 83/02/23 TOURTELLOTTE,J
Regulatory Reform Task Force 1p 18543 357 24X
Fiche 50-000,83/02/23,8305230407

8305230503 Summary of CRGR Meeting 35 on 830425 re Salem Generic Implications Task Force findings,per NUREG-1000
STELLO,V Committee to Review Generic Requirements 83/05/13
DIRCKS,W J Office of the Executive Director for Operations 4pp
18537 164

8305230507 Summary of CRGR Meeting 36 on 830429 re actions derived from Salem generic implications rept List of attendees encl
STELLO,V Committee to Review Generic Requirements 83/05/13
DIRCKS,W J Office of the Executive Director for Operations 4pp
18537 320

8305230581 Forwards lists of NRC initiated & TMI-related backfit items, in response to 830208 ltr Backfitting costs resulting from utils own needs also provided
WITHERS,B D Portland General Electric Co 83/03/24
TOURTELLOTTE,J Regulatory Reform Task Force 4pp 18541 314 24X
Fiche 50-344,83/03/24,8305230581

8305230583 Forwards backfit cost info in response to 830208 ltr Two 3,500 kW standby diesel generators,diesel generator bldg, auxiliary bldg addition,associated electrical equipment & new computer sys added per NUREG-0737
MATTIMOE,J J Sacramento Municipal Utility District 83/03/16
TOURTELLOTTE,J Regulatory Reform Task Force 4pp 18541 318 24X
Fiche 50-312,83/03/16,8305230583

8305230588 Forwards backfitting & regulatory impact cost data for hardware & nonhardware-related backfits Requirement for adding one add1 senior reactor operator to each operating shift will cost $600,000 per yr
REZNICEK,B W Omaha Public Power District 83/03/04
TOURTELLOTTE,J Regulatory Reform Task Force 16pp 18541 322
24X Fiche 50-285,83/03/04,8305230588

8305230597 Encourages industry approach to formulation of backfitting rule in line w/Regulatory Reform Task Force effort,per 821221 ltr
DYSON,J S, Power Authority of the State of New York 83/03/02
TOURTELLOTTE,J Regulatory Reform Task Force 2pp 18541 338 24X
Fiche 50-000,83/03/02,8305230597

8305230608 Provides lump sum number representing direct cost impact of regulatory proliferation during appror period from NRC CP to low-power OL, in response to 830208 request re backfitting costs
LUTKEN, D C Mississippi Power & Light Co 83/03/04
TOURTELLOTTE, J Regulatory Reform Task Force 2pp 18541 340 24X
Fiche 50-416, 83/03/04, 8305230608

8305230616 Forwards info in response to 830208 ltr requesting backfit cost data for operating nuclear units Cost categorized according to NRC imposed, TMI & non-TMI backfits, util-initiated & hybrid backfits
COUNSIL, W G Connecticut Yankee Atomic Power Co 810721 83/03/21
TOURTELLOTTE, J Regulatory Reform Task Force 25pp 18543 038
24X Fiche 50-000, 83/03/21, 8305230616

8305230634 Ack receipt of ltr requesting cost analysis of backfitting requirements imposed by NRC Facilities will require some backfit mods Costs will be almost identical to Byron increases
SHIELDS, S W Public Service Co of Indiana, Inc SVP-0080-83
83/03/10 TOURTELLOTTE, J Regulatory Reform Task Force 2pp
18542 352 24X Fiche 50-546, 83/03/10, 8305230634

8305230669 Notifies that operator requalification program postponed until CRGR Meeting 40, tentatively scheduled for 830601 CRGR Meeting 38 scheduled for 830518 in Bethesda, MD
STELLO, V Regional Operations & Generic Requirements 83/05/17
EISENHUT, D G Office of Nuclear Reactor Regulation, Director
JORDAN, E L Director's Office, Office of Inspection and Enforcement
CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 18542 332

8305230716 Responds to 830208 request for backfitting expenditures Actual cost at OL date was $583 million Projected addl future cost for NRC imposed mods conservatively estimated at $26,500,000
CROUSE, R P Toledo Edison Co 83/02/18 TOURTELLOTTE, J
Regulatory Reform Task Force 10pp 18542 294 24X
Fiche 50-346, 83/02/18, 8305230716

8305230720 Forwards list of utils responding to requests for cost figures on backfitting
TOURTELLOTTE, J Regulatory Reform Task Force 83/04/11
PALLADINO, N J, GILINSKY, V, AHEARNE, J F Commissioners 2pp
18542 272 24X Fiche 50-000, 83/04/11, 8305230720

8305230724 Forwards estimated annual regulatory & nonregulatory expenditures in 830208 ltrs re cost of backfitting Combined capacity of facilities is 994 MWe
BURSTEIN, S Wisconsin Electric Power Co 83/02/25 TOURTELLOTTE, J
Regulatory Reform Task Force 3pp 18542 269 24X
Fiche 50-266, 83/02/25, 8305230724

8305230728 Forwards listing of regulatory-induced major plant mods & costs Size of nuclear staff nearly doubled since TMI accident Total expenditures for IE Bulletins 79-01, 79-02 & 79-14 mods provided
GIESLER, C W Wisconsin Public Service Corp IEB-79-01 83/03/25
TOURTELLOTTE, J Regulatory Reform Task Force 6pp 18542 263 24X
Fiche 50-305, 83/03/25, 8305230728

SECY POSITION PAPERS BEFORE THE COMMISSION

8302280090 SECY-83-059
Requests approval to publish encl technical criteria for regulating geologic disposal of high level radwaste as final amends to 10CFR60 W/draft final rule on 10CFR60
DIRCKS, W J Office of the Executive Director for Operations
83/02/09 450pp 18629 001

8304220083 SECY-83-059B
Submits proposed responses to comments of Commissioners Gilinsky & Ahearne re SECY-83-59 concerning technical criteria & conforming amends to disposal of high level radwastes in geologic repositories
DIRCKS, W J Office of the Executive Director for Operations
83/04/11 26pp 18627 190

8305020530 SECY-83-140
Presents NRC review of & recommendations on util 830131 revised schedule & cost info re recovery
DIRCKS, W J Office of the Executive Director for Operations
83/04/15 33pp 18284 261 24X Fiche 50-320, 83/04/15, 8305020530

8305170232 SECY-83-158
Informs Commission of findings of Salem ATWS generic implications task force re overall mgt capability & performance & reactor trip sys reliability
DIRCKS, W J Office of the Executive Director for Operations
83/05/02 159pp 18476 184 24X Fiche 50-272, 83/05/02, 8305170232

8305180316 Responds to FOIA request for SECY-83-17 & SECY-83-19 Forwards documents Documents also available in PDR
FELTON, J M Division of Rules and Records 83/03/29 BREADY, J C
KMC, Inc 1p 18505 230 24X Fiche 50-237, 83/03/29, 8305180316

--8305180328 SECY-83-017
Notifies of results of SEP review of facility
DIRCKS, W J Office of the Executive Director for Operations
83/01/12 47pp 18505 246 24X Fiche 50-237, 83/03/29, 8305180316

--8305180322 SECY-83-019
Informs of proposed plan to convert seven remaining provisional OLs to full-term OLs after completion of SEP Phase II
DIRCKS, W J Office of the Executive Director for Operations
83/01/17 15pp 18505 231

8305230065 Responds to FOIA request for SECY-82-13D Forwards requested document Document also available in PDR
FELTON, J M Division of Rules and Records 83/03/31 PEDRO, J NUS
Corp 1p 18543 137

--8305230070 SECY-82-013D
Informs Commission of status of implementation of 10CFR50 48 & App R to 10CFR50 re fire protection rule for Third Quarter 1982, per SJ Chilk 801103 request
DIRCKS, W J Office of the Executive Director for Operations
82/12/10 9pp 18543 138

8305250250 SECY-83-067
Provides Commission w/info rept explaining status of activities re fraudulent practices of Ray Miller, Inc
DIRCKS, W J Office of the Executive Director for Operations
83/02/16 30pp 18627 123

8305270118 SECY-83-195
Requests Commission approval to transmit comments to EPA on proposed stds for U & thorium mill tailings at licensed commercial processing sites Comments re groundwater protection & radon stds not supportive of EPA proposed rule
DIRCKS, W J Office of the Executive Director for Operations
83/05/20 88pp 18661 251

STATE PROG STATE PROGRAMS

8305040192 PNA-83-007 on 830303, 100 uCi I-125, 3 mCi Tl-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town, NY Packages not found Press release may be issued
CAMPBELL, M Region 1, Office of Director 83/04/04 1p
18326 353

8305040201 PNA-83-007A on 830303, 100 uCi I-125, 3mCi Tl-201 & 8 mCi Ga-67 stolen from US Priority Transport vehicle near Colonie Town, NY Package of I-125 found on 830315 in home of suspect.
CAMPBELL, M Region 1, Office of Director 83/03/15 1p
18326, 354

8305040650 Notification of contract execution, Mod 1 to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ " Contractor State of WI
SILVIS, R M Technical Assistance Contracts Branch NRC-05-73-014
83/04/29 Director's Office, Office of Inspection and Enforcement
1p 18336 269

--8305040660 Mod 1, deobligating funds, to "Establish Collaborative Program Between State & Commission to Provide Independent Measurements of Radioactivity in Effluents & in Environ Around Selected Commission Licensed Activities "
REIVITZ, L Wisconsin, State of GUSTAVE, R, P Division of Contracts NRC-05-73-014 83/04/29 1p 18336 270

8305060464 Provides technical comments & recommendations on State of MO radiation control program Program for regulation of agreement matls adequate; however, outdated radiation control regulations prevent compatibility determination
COLLINS, J T Region 4, Office of Director 83/05/02 SABOL, B J
Kansas, State of 5pp. 18351 169

8305100086 Confirms discussion of NRC review & evaluation of State of LA radiation control program Program adequate, State should focus efforts on reducing backlog of insps Technical comments & recommendations encl
COLLINS, J T Region 4, Office of Director 83/05/05
SIMONEAUX, F P Louisiana, State of 4pp 18377 226

8305120010 Add1 response to FOIA request for documents re exploration, mining or milling of U in specific areas of NE Forwards documents listed on app Review of remaining documents subj to request in progress
FELTON, J M Division of Rules and Records 83/03/21 REID, A B Broken Plow Law Office 1p 18443 282

--8305120041 Requests assistance in arranging meeting in Lincoln, NE to discuss requirements & develop MOU defining roles re U or solution mining in northwest NE
DRAIN, D T Nebraska, State of 82/04/27 COLLINS, T Region 4, Office of Director 2pp 18443 293

--8305120045 Informs that draft MOU ready for signature pending review & concurrence by OELD Due to changes in location & organization of U Recovery Licensing Branch, MOU should be signed by regional administrator
COLLINS, J T Region 4, Office of Director 82/07/28 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director 1p 18443 295

--8305120052 Forwards draft MOU re site U mining in NE Draft considers all previous NRC ofc comments & is acceptable to State of NE Comments should be provided by 821015
COLLINS, J T Region 4, Office of Director 82/10/01 DIRCKS, W J Office of the Executive Director for Operations STELLO, V Regional Operations & Generic Requirements KERR, G W Office of State Programs, Director 3pp 18443 296

--8305120056 Forwards notice of issuance & availability of MOU between NE Dept of Environ Control & NRC for in situ U mining for filing & publication in FR
COLLINS, J T Region 4, Office of Director 82/12/01 COMBS, T R Correspondence & Records Branch 1p 18443 299

--8305120062 Notice of issuance & availability of MOU between NRC & NE Dept of Environ Control re in situ U mining.
COLLINS, J T Region 4, Office of Director 82/11/30 1p 18443 300

--8305120065 MOU between NRC & NE Dept of Environ Control re in situ U mining
COLLINS, J T Region 4, Office of Director DRAIN, D T Nebraska, State of 82/11/02 2pp 18443 301

--8305120014 Comments on Proposed Draft LB 550, per 811210 request Use of word "mining" may cause some problems NRC does not have jurisdiction over conventional mining of source matl or other matl
MONTGOMERY, J L Region 4, Dallas, Office of the Director (81/03/01) 82/01/19 DRAIN, D T Nebraska, State of, 2pp 18443 284

--8305120019 Discusses 820202 telcon w/J Lange re proposed U in situ project in NE by Wyoming Fuels Co State has licensing & insp jurisdiction over project until 821108
MONTGOMERY, J L Region 4, Office of Director 82/02/08
COLLINS, J T Region 4, Office of Director 2pp 18443 286

--8305120023 Forwards info re 810313 meeting w/NE State officials concerning state & UMTRCA topics. State will seek amended agreement after 811108 Agency other than E Simmons div assigned to handle U mills
MONTGOMERY, J. Region 4, Dallas, Office of the Director (81/03/01) 81/03/18 YOUNG, F Office of State Programs, Director 4pp 18443 288.

--8305120035 Concurs w/D Drain request for assistance in developing MOU to define respective roles in connection w/U or solution mining in northwest NE. June 1982 meeting suggested to begin formulating MOU
COLLINS, J. T Region 4, Office of Director 82/05/03 DAVIS, J G Office of Nuclear Material Safety & Safeguards, Director KERR, G W Office of State Programs, Director 1p 18443 292

8305170137 NUREG/BR-0025 V09 N4
INFORMATION REPORT ON STATE LEGISLATION
KERR, G.W Office of State Programs, Director, 83/05/31 14pp 18494:001

8305190014 Ack receipt of 830411 ltr re NRC review of Dept of Environ Conservation radiation control program on 830509 or 10 Schedule permitting, author will meet w/representatives on 830510
WILLIAMS, H G New York, State of 83/04/28, ALLAN, J M Region 1, Office of Director 1p, 18501 339

8305190264 Forwards responses to specific technical comments & recommendation per 830225 ltr re evaluation of NY City radiation control program.
SPENCER, D J New York, NY, 83/04/22 HAYNES, R C Region 1, Office of Director 5pp 18501 242

8305200320 Confirms administrative & technical review & evaluation findings re State of ID radiation control program Program adequate Technical comments & recommendations encl
COLLINS, J T Region 4, Office of Director 83/05/13 PURCE, T L Idaho, State of 5pp 18517 038

8305230326 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of PA
MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8356 NRC-28-83-607 83/05/12 MCOSCAR, J Region 1, Office of Director COSTELLO, F NRC - No Detailed Affiliation Given 1p 18577 291

--8305230332 Contract "Radiation Monitoring Program Requirements," awarded to State of PA Cooperative agreement encl
* Pennsylvania, Commonwealth of, MORTON, K V Division of Contracts FIN B-8356 NRC-28-83-607 83/05/12 16pp 18577 292

8305260377 Notification of contract execution, Mod 3 to "Exam of Agreement State Program " Contractor Natl Governors Assoc
MCLEAREN, T Administrative Contracts Branch NRC-06-81-293 83/05/16 KERR, G W Office of State Programs, Director LUBENAU, J NRC - No Detailed Affiliation Given 1p 18647 256

--8305260380 Mod 3, providing consideration to govt for late delivery of contract deliverables, to "Exam of Agreement State Program "
SCHEPPACH, R C National Governors' Association SMITH, P A Division of Contracts NRC-06-18-293 83/05/16 1p 18647 257

8305270090 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements " Contractor State of NE
MCDERMOTT, D. Technical Assistance Contracts Branch FIN B-8503 NRC-31-83-670 83/05/16 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18661 352

--8305270093 Mod 1, correcting B&R numbers, to "Radiation Monitoring Program Requirements "
* Nebraska, State of MORTON, K V Division of Contracts FIN B-8503 NRC-31-83-670 83/05/16 1p 18661 353

8305270130 Ack receipt of 830407 ltr accepting results of NRC review of MD Dept of Health & Mental Hygiene radiation control program
BUCK, C R Maryland, State of 83/05/11 ALLAN, J M Region 1, Office of Director 1p 18638 214

8305270165 Responds to 830502 ltr re RJ Doda evaluation of agreement matls portion of state of LA radiation control program & concern re overdue insps Staff relatively new & several more months of on-the-job training necessary
PORTER, B J Louisiana, State of 83/05/10 COLLINS, J T Region 4, Office of Director 2pp 18638 062

TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

8210190253 Suggests implementation of emergency response guideline program in three steps, including preparation of plant-specific procedures List of questions & concerns encl
EISENHUT, D G Division of Licensing 82/09/17 KINGSLEY, O D Westinghouse Operating Plants Owners Group 10pp 18308 309

8303240026 Discusses review of 820408, 0601, 1103 & 830216 submittals on YAEC-1296P, "DNBR Limit Methodology & Application to ME Yankee Plant " Critical heat flux correlation acceptable for application to facility reload w/14x14 fuel assemblies
CLARK, R A Operating Reactors Branch 3 83/03/09 GARRITY, J H Maine Yankee Atomic Power Co 2pp 17690 299 24X
Fiche 50-309, 83/03/09, 8303240026

--8301060137 FATE-82-114
"Review of YAEC-1296P - DNBR Limit Methodology & Application to Maine Yankee Plant "
HESSON, G M Battelle Memorial Institute, Pacific Northwest Laboratory 82/12/31 NRC - No Detailed Affiliation Given. 7pp 17690 308 24X Fiche 50-309, 83/03/09, 8303240026

8304180548 Forwards proprietary WCAP-8200, Rev 1, WCAP-8301, WCAP-8302, WCAP-8821, draft responses to questions on WCAP-10079 & related info re new small break evaluation model per NUREG-0737, Item II K 3.30 Encls withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2746 83/04/12
THOMAS, C O Standardization & Special Projects Branch 2pp. 17997, 049

--8304180558 Requests that draft answers to NRC questions on WCAP-10079, "NOTRUMP, Nodal Transient Small Break & General Network Code," be withheld per 10CFR2 790
WIESEMANN, R A Westinghouse Electric Corp AW-83-27 83/04/12
THOMAS, C O Standardization & Special Projects Branch 1p 17997 051

8304200001 Forwards Endorsements 106 & 105 to NELIA Policies NF-111 & NF-83, respectively
DOTHMAN, J McDermott, Inc 83/04/11 DINITZ, I Division of Engineering 3pp 18066 092

8305020272 Forwards Affidavit AW-80-27 in support of request to withhold proprietary info re effect of radiation on insulating matls in Westinghouse medium motor per 10CFR2 790 re encl util draft 830413 ltr
WIESEMANN, R A Westinghouse Electric Corp CAW-83-28 83/04/13
THOMAS, C O Division of Licensing 9pp 18277 196 24X
Fiche 50-266, 83/04/13, 8305020272

--8305020292 71-1C2-RADMC-R1
Nonproprietary version of "Effect of Radiation on Insulating Matls Used in Westinghouse Medium Motors "
BARTKO, J Westinghouse Electric Corp 71/04/10 39pp
18277 205 24X Fiche 50-266, 83/04/13, 8305020272

8305020281 Forwards results of survey of QA procedures applied by BNWL to computer code activities for NRC-funded programs
BANGART, R L Division of Vendor & Technical Programs 83/04/28
MATTSON R J Division of Systems Integration (post 811005) 2pp
18277 171

8305020384 Forwards response to 821115 request for addl info re NUREG-0737, Items II E 1 2 & II K 2 10 Schedule for installation of auxiliary feedwater sys confirmed W/11 oversize drawings Aperture cards are available in PDR
RODRIGUEZ, R J Sacramento Municipal Utility District 83/04/28
STOLZ, J F Operating Reactors Branch 4 3pp 18283-329 24X
Fiche 50-312, 83/04/28, 8305020384

--8305020392 BWNP-20004 (6-76) R3
Rev 3 to "Auxiliary Feedwater Sys Sys Description "
* Babcock & Wilcox Co 15-1120580-03 83/04/04 54pp
18283 332 24X Fiche 50-312, 83/04/28, 8305020384

8305020398 Forwards "B&W 177 Fuel Assembly Owners Group Safe-End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking," in response to SER Open Item 8 on cracking in RCS makeup nozzles
COOK, J W Consumers Power Co 22343 83/04/13 DENTON, H R
Office of Nuclear Reactor Regulation, Director 3pp 18273 001
24X Fiche 50-329, 83/04/13, 8305020398

--8305020404 77-1141514-00
"B&W 177 Fuel Assembly Owners Group Safe End Task Force Rept on Generic Investigation of HPI/Makeup Nozzle Component Cracking "
* Babcock & Wilcox Co 83/04/13 61pp 18273 005 24X
Fiche 50-329, 83/04/13, 8305020398

8305020502 Forwards comments on C-E Owners Group calculations re depressurization & DHR capability of C-E plants w/o pressurizer PORVs, discussed at 830112 meeting w/C-E Owners Group in Bethesda, MD
NOVAK, T M Assistant Director for Licensing 83/04/19 MAURIN, L V
Louisiana Power & Light Co 4pp 18284 333 24X
Fiche 50-382, 83/04/19, 8305020502

8305020524 Notification of 830505 meeting w/GE in Bethesda, MD to discuss improvements in physics methods & submittal of topical repts
FIENO, D Core Performance Branch 83/04/20 BERLINGER, C H Core Performance Branch 2pp 18284 202

8305030013 Forwards NRC comments on C-E Owners Group study re depressurization & DHR capability of C-E plants w/o PORVs Info re need for PORVs in plants required by 830630 in order to be considered in final decision
NOVAK, T M Assistant Director for Licensing 83/04/20 VAN
BRUNT, E E Arizona Public Service Co 4pp. 18310 349 24X
Fiche 50-528, 83/04/20, 8305030013

8305030292 Forwards proprietary versions of XN-NF-CC-38 & Suppl 1, "Users Manual for PTSPWR2, FORTRAN Program for Simulation of PWR Plant Transients " Repts withheld (ref 10CFR2 790)
RB Stout affidavit encl.
CHANDLER, J. C Exxon Nuclear Co , Inc (subs. of Exxon Corp)
JCC:061 83 83/04/20 THOMAS, C O Standardization & Special Projects Branch 4pp 18300 023

8305030337 Forwards proprietary & nonproprietary versions of "Radwaste Solidification Sys " Affidavit for withholding document encl Proprietary version withheld (ref 10CFR2 790)
POWELL, R H J NUS Corp PS-53-0387 83/04/27 THOMAS, C O
Standardization & Special Projects Branch 4pp 18292 318.

--8305030343 NP-PS-53-0378 R0
Nonproprietary version of "NUS Process Svcs Corp Topical Rept on Radwaste Solidification Sys "
* NUS Corp 83/04/30 33pp 18292 322

8305030410 Provides further specific info re ATWS Salem incident implications on B&W plants B&W control rod drive trip sys contains higher degree of diversity than any other trip sys in industry
ROY, D H Babcock & Wilcox Co 83/04/28 DENTON, H Office of Nuclear Reactor Regulation, Director 2pp 18306 313

8305030426 Forwards proprietary version of WCAP-10241, "Westinghouse BWR ECCS Evaluation Model " Computer Codes GOBLIN, DRAGON & CHACHA for GE BWR NSSS designs comply w/requirements of App K to 10CFR50 46 Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2750 83/04/28
THOMAS, C O Standardization & Special Projects Branch 2pp
18294 170

--8305030438 Requests withholding of proprietary version of WCAP-10241, "Westinghouse BWR ECCS Evaluation Model," per 10CFR2 790 & 10CFR9 5(4)
WIESEMANN, R A Westinghouse Electric Corp 83/04/28 THOMAS, C O
Standardization & Special Projects Branch 1p 18294 172

8305040302 Summary of 830422 meeting w/Chem-Nuclear & FCTC in Silver Spring, MD re IE Info Notice 83-10, "Clarification of Several Aspects Re Use of NRC-Certified Transport Packages "
ODEGAARDEN, R H Transportation Branch 83/04/26 Transportation Branch 2pp 18326 341

8305040433 Forwards proprietary viewgraphs entitled "Probability of Turbine Overspeed," from 830408 meeting w/NRC in Bethesda, MD Affidavit for withholding encl Viewgraphs withheld (ref 10CFR2 790)
TIMO, P P General Electric Co 83/04/28 IPPOLITO, T A Operating Reactors Branch 2 10pp 18319 135

8305040458 Forwards "Core Spray Design Methodology Confirmation Tests," per established procedures
PFEFFERLEN, M C General Electric Co MFN-067-83 83/04/11
MIRAGLIA, F J Assistant Director for Safety Assessment 1p
18320 251

--8305040466 NEDO-24712-A
"Core Spray Design Methodology Confirmation Tests "
SANDOZ, B A , MYERS, L L , WOOD, J E General Electric Co
79NED122R1 83/03/31 217pp 18320 252

8305040565 Forwards Rev 7 to WPPSS-QA-004, "Operational QA Program Description "
BOUCHEY, G D Washington Public Power Supply System G02-83-384
83/04/26 GRIMES, B K QA Branch 1p 18320 159

--8305040588 Supports Rev 7 to WPPSS-QA-004, "Operational QA Program Description," reflecting organizational changes Revised rept meets criteria of App B to 10CFR50
HARPSTER, T L QA Branch 83/03/23 BOUCHEY, G D Washington Public Power Supply System 2pp 18320 160

--8305040613 WPSS-QA-004 R07
Rev 7 to WPPSS-QA-004, "Operational QA Program Description "
* Washington Public Power Supply System 83/03/16 89pp.
18320 162

8305050026 Forwards NEDO-22209, "Analysis of Scram Discharge Vol Sys Piping Integrity " No further action planned re equipment qualification & sys design mods identified in generic SER (NUREG-0803)
BAYNE, J P Power Authority of the State of New York JPN-83-39.
83/05/03 VASSALLO, D B Operating Reactors Branch 2 2pp
18339 313 24X Fiche 50-333, 83/05/03, 8305050026

8305050034 Forwards correction to Item 5 of 830329 ltr clarifying emergency procedure guidelines in C-E Owners Group 821122 submittal Discrepancies in termination criteria for once-through cooling clarified
WELLS, R W C-E Operating Plants Owners Group WELLS, R W Northeast Utilities RWW-83-23 83/04/22 EISENHUT, D G Division of Licensing 2pp 18339 108

8305050200 Forwards proprietary version of "Counterflow Preheat Steam Generator Tube Expansion Rept " Rept withheld (ref 10CFR2 790)
RAHE, E P Westinghouse Electric Corp NS-EPR-2751 83/04/20
EISENHUT, D G Division of Licensing 1p 18338 153

--8305050208 Application for withholding "Counterflow Preheat Steam Generator Tube Ex,ansion Rept," from public disclosure per 10CFR2 790
WIESEMANN, R A Westinghouse Electric Corp AW-83-32 83/04/20
EISENHUT, D G Division of Licensing 1p 18338 154

8305050347 Informs of fees due for review of Amend 6 to Topical Rept DUKE-1-A re QA program
MILLER,W O License Fee Management Branch 83/04/25 GRIER,G W Duke Power Co 1p 18352 021

8305060060 Application to amend License DPR-49,revising App A Tech Specs re max critical power ratio operating limits for 8x8 & 8x8R/P8x8R fuel types to allow implementation of turbine control valve mod
ROOT,L D Iowa Electric Light & Power Co NG-83-1152 83/05/04 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18345 052 24X Fiche 50-331,83/05/04,8305060060

--8305060076 Y1003J01A46 R01
Rev 1 to "Supplemental Reload Licensing Submittal for Duane Arnold Atomic Energy Ctr,Reload 6 "
WAGNER,R L , ZARBIS,W A , CHARNLEY,J S General Electric Co 83/03/31 20pp 18345 055 24X Fiche 50-331,83/05/04,8305060060

8305060204 Summary of 830320 meeting w/GE in Silver Spring,MD re design criteria for nodular cast iron casks No objections to basic concept expressed.
ODEGAARDEN,R H Transportation Branch 83/04/21 Transportation Branch 1p 18359 361

8305060358 Forwards topical rept evaluation of BAW 10141(P), "TACO-2 Fuel Pin Performance Analysis," Rept acceptable Publication of proprietary & nonproprietary versions of rept requested within 3 months of ltr receipt
THOMAS,C O. Standardization & Special Projects Branch 83/04/13
TAYLOR,J H Babcock & Wilcox Co 2pp 18353 112

--8304080009 Nonproprietary topical rept evaluation of BAW-10141, "TACO-2 Fuel Pin Performance Analysis " Rept acceptable
* NRC - No Detailed Affiliation Given 83/03/31 51pp 18353 114

8305090212 Forwards proprietary "Westinghouse Advanced PWR Pretendering Module 5 - Chemical & Vol Control Sys " Application for withholding & affidavit encl Rept withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp NS-EPR-2759 83/04/29
EIBENHUT,D.G. Division of Licensing 2pp 18362 342

--8305090202 Application for withholding proprietary "Westinghouse Advanced PWR Pretendering Module 5 - Chemical & Vol Control Sys " Affidavit encl
WIESEMANN,R A Westinghouse Electric Corp AW-83-36 83/04/29
EIBENHUT,D G Division of Licensing 9pp 18362 344.

8305090217 Forwards topical rept evaluation of XN-NF-79-6(P&NP), "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs," defining basis for acceptance of rept
THOMAS,C O Standardization & Special Projects Branch TAC 12026
83/04/28 CHANDLER,J C Affiliation Unknown 2pp 18381 103

--8305090228 Topical rept evaluation of XN-NF-79-6 (P&NP), "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Westinghouse PWRs " Rept acceptable
* Core Performance Branch TAC 12026 83/02/23 5pp 18381 105

8305090467 Forwards Rev 6 to "QA Program," per NRC 830414 request
TAYLOR,H S Sargent & Lundy, Inc 0037-00 83/04/29 HAASS,W P Division of Engineering & Quality Assurance (Prn 830103). 1p 18360.154

--8305090469 SL-TR-1A R06
"QA Program "
TAYLOR,H S , ACKMANN,L E Sargent & Lundy, Inc 83/04/22 48pp 18360 155

8305090483 Forwards errata & addenda to NEDO-24011-A-US, "Licensing Topical Rept.GE Std Application for Reactor Fuel (Suppl for US)" & to NEDO-24011-A, "Licensing Topical Rept GE Std Application for Reactor Fuel "
CHARNLEY,J S General Electric Co MFN-078-83 83/05/04
THOMAS,C O Division of Licensing 1p 18360 263

--8305090495 NEDO-24011-A011-A-US
Errata & addenda to "Licensing Topical Rept GE Std Application for Reactor Fuel (Suppl for US) "
SHERWOOD,G G General Electric Co 82NED058. 82/08/31 72pp 18360·264

--8305090497 NEDO-24011-A-5 ERR
Errata & addenda to "Licensing Topical Rept GE Std Application for Reactor Fuel "
* General Electric Co. 82NED057 82/08/31 151pp 18360·336

8305090512 Responds to 830406 staff requirements memo re briefing on DHR studies on C-E plants Investigation will be completed by 830630 & results of study,conclusions & recommendations will be presented to Commission by Aug-Sept
DIRCKS,W J Office of the Executive Director for Operations
83/04/25 CHILK,S J Office of the Secretary of the Commission 1p 18381 246

--8305090516 Staff requirements memo re 830404 briefing on DHR studies on C-E plants Commission requested NRC accelerate study & solicit & address ACRS views on issue
CHILK,S J Office of the Secretary of the Commission M830404
83/04/06 DIRCKS,W J Office of the Executive Director for Operations 1p 18381 249

8305090532 Notification of canceled 830505 meeting w/GE in Bethesda,MD to discuss improvements in GE physics methods & submittal of topical repts
FIEND,D Core Performance Branch 83/04/28 BERLINGER,C H Core Performance Branch 2pp 18367 336

8305090551 Advises that branch has requested Div of Accounting & Finance to bill util for review of Rev 13 to Topical Rept CPC-1A, "QA Manual for Midland Nuclear Plant,Vol 1 "
MILLER,W O License Fee Management Branch 83/04/25 BYRD,W Consumers Power Co 1p 18367 361 24X Fiche 50-329,83/04/25, 8305090551

8305090554 Forwards topical rept evaluation of NEDE-24011-P-A-4, "Barrier Fuel Amend to GE Std Application for Reactor Fuel " Rept acceptable
THOMAS,C O Standardization & Special Projects Branch 83/04/13
CHARNLEY,J S General Electric Co 2pp 18381 254

--8305090557 Topical rept evaluation of NEDE-24011-P-A-4, "Barrier Fuel Amend to GE Std Application for Reactor Fuel " Rept acceptable
* Core Performance Branch 83/04/13 12pp 18381 256

8305090597 Forwards request for addl info re review of Addendum 3 to WCAP-8720, "Improved Analytical Models Used in Westinghouse Fuel Rod Design Computations/Application for BWR Fuel Analysis " Response by 830625 requested
THOMAS,C O Standardization & Special Projects Branch 83/05/02
RAHE,E P Westinghouse Electric Corp 3pp 18367 341

8305100197 Forwards comments re proposed NUREG-0737 Tech Specs,per 830321 ltr request Comments should not be interpreted as formal position or commitment to specific course of action
DENTE,T J BWR Owners Group BWROG-8313 83/05/06 EIBENHUT,D G Division of Licensing 4pp 18374 311

8305100268 Forwards Westinghouse Rev 1 to Procedure 181-154, "Preservice & Inservice Insp of Reactor Vessels " Procedure meets intent of Reg Guide 1.150,Rev 1 as referenced in Generic Ltr 83-15
CAREY,J J Duquesne Light Co 83/05/06 VARGA,S A Operating Reactors Branch 1 1p 18371 160 24X Fiche 50-334,83/05/06, 8305100268

--8305100273 Rev 1 to Procedure 181-154, "Preservice & Inservice Insp of Reactor Vessels "
ADAMONIS,D C , LE FEBVRE,B J , VANO,J A Westinghouse Electric Corp 83/03/16 75pp 18371 161 24X Fiche 50-334,83/05/06, 8305100268

8305100316 Forwards response to 820830 request for addl info & revised pages to BAW-10025(P),Rev 1, "Reactor Vessel Model Flow Tests for 205 Fuel Assembly Core " Encl withheld (ref 10CFR2 790)
TAYLOR,J H Babcock & Wilcox Co 83/05/02 THOMAS,C O Standardization & Special Projects Branch 2pp 18370 098

8305100362 Forwards Y1003J01A53, "Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant,Unit 1, Reload 3(W/o Recirculation Pump Trip)," inadvertently omitted from 830502 Tech Spec rev request
ZIMMERMAN,S R Carolina Power & Light Co LAP-83-167 83/05/06
VASSALLO,D B Operating Reactors Branch 2 1p 18379 059 24X Fiche 50-325,83/05/06,8305100362

--8305100370 Y1003J01A53
"Supplemental Reload Licensing Submittal for Brunswick Steam Electric Plant,Unit 1,Reload 3 (W/o Recirculation Pump Trip) "
ZANARDI,G , HILL,R T , CHARNLEY,J S General Electric Co
83/01/31 28pp 18379 060 24X Fiche 50-325,83/05/06,8305100362

8305110360 Forwards WCAP-10252, nonproprietary version of WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel " Application for withholding WCAP-10196, submitted on 830202 encl
CAREY, J J Duquesne Light Co 83/05/02 VARGA, S A Operating Reactors Branch 1 1p 18392 146 24X Fiche 50-334, 83/05/02, 8305110360

--8305110377 Application for withholding proprietary WCAP-10196, "Second Cycle Performance of Beaver Valley Unit 1 Fuel," per 10CFR2 790 Affidavit encl
WIESEMANN, R A Westinghouse Electric Corp CAW-83-13 83/04/20
VARGA, S A Operating Reactors Branch 1 8pp 18392 147 24X
Fiche 50-334, 83/05/02, 8305110360

--8305110398 WCAP-10252
Nonproprietary version of, "Second Cycle Performance of Beaver Valley Unit 1 Fuel "
PRITCHETT, P A , KUNISHI, H , ROBERTS, E Westinghouse Electric Corp
83/05/02 66pp 18392 156 24X Fiche 50-334, 83/05/02, 8305110360

8305110437 Forwards "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits," per 830405 ltr
CROUSE, R P Toledo Edison Co 945 83/05/06 STOLZ, J F
Operating Reactors Branch 4 1p 18404 320 24X
Fiche: 50-346, 83/05/06, 8305110437

--8305110443 77-1142162-00
"Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/FT Limits "
* Babcock & Wilcox Co 83/05/06 28pp 18404 321 24X
Fiche 50-346, 83/05/06, 8305110437

8305120018 Submits organizational charges within util power generation div Effective 830401, nuclear fuel svc dissolved as business segment & integrated into field technical svc. Organization chart encl.
TAYLOR, J H Babcock & Wilcox Co 83/04/22 HAAS, W P Quality Assurance Branch 3pp 18423.045

8305120029 Forwards request for addl info re WCAP-8720, Addendum 2, "Westinghouse Revised PAD Code Thermal Safety Model " Responses should be received by 830525
THOMAS, C O Standardization & Special Projects Branch 83/05/03
RAHE, E P Westinghouse Electric Corp 21pp 18443 257

8305120073 Apprises of B&W Owners Group plans re plant emergency procedure technical guidelines Abnormal transient operating guidelines program will be enhanced w/higher level generic document, expanding emergency operation technical bases
WHITNEY, D D. Babcock & Wilcox Operating Plants Owners Group
WHITNEY, D D. Sacramento Municipal Utility District 83/05/04
EISENHUT, D G. Division of Licensing 2pp 18427 361

8305120241 Forwards proprietary & nonproprietary responses to NRC 820819 request for addl info re measurement uncertainties & "Shape Annealing Factor Component of Axial Shape Index " Proprietary response & rept withheld (ref 10CFR2 790)
COUNSIL, W G , SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W. G Northeast Utilities A02724
83/05/03 CLARK, R A Operating Reactors Branch 3 16pp
18429 151 24X Fiche 50-336, 83/05/03, 8305120241

--8305120252 CEN-247(N)-NP
"Shape Annealing Factor Component of Axial Shape Index Uncertainty "
* Combustion Engineering, Inc. 83/03/31 48pp 18429 167 24X
Fiche 50-336, 83/05/03, 8305120241

8305130126 Forwards response to questions included in 830203 ltr re Hydrogen Control Owners Group program Questions 8 & 9 must be addressed on plant-specific basis Tentative arrangements made for meeting w/Containment Sys Branch on 830602
RICHARDSON, J D Hydrogen Control Owners Group, BWR-6 Mark III
RICHARDSON, J D Mississippi Power & Light Co HGN-011 83/05/11.
HOUSTON, R W Division of Systems Integration (post 811005) 25pp
18437 231 24X Fiche 50-416, 83/05/11, 8305130126

8305160063 Forwards Endorsement 124 to NELIA Policy NF-1
ROBBINS, J G Marsh & McLennan, Inc 83/03/29 SALTZMAN, J
Assistant Director for State & Licensee Relations 2pp 18451 034

8305160084 Forwards Endorsement 124 to NELIA Policy NF-34 & Endorsement 59 to MAELU Policy MF-59
ASHBURN, D J Marsh & McLennan, Inc 83/05/06 SALTZMAN, J
Assistant Director for State & Licensee Relations 3pp 18450 353
24X Fiche 50-089, 83/05/06, 8305160084

8305160363 Forwards nonproprietary & proprietary versions of "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel," per 10CFR72 Affidavit to withhold proprietary info encl W/o proprietary version
PARKER, P E Ridihalgh, Eggers & Associates 22161 83/04/14
ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 4pp
18473 021

--8305160365 "Topical Rept for REA 2023 Dry Storage Cask for BWR Spent Fuel "
* Ridihalgh, Eggers & Associates 22161 83/04/06 574pp
18473 025

8305170302 Requests withholding proprietary version of "Corrections to Critical Crack Size," per 10CFR2.790 Affidavit encl
COLLIER, A R Westinghouse Electric Corp SE-83-01 83/04/15
SCHIFFGENS, J O Materials Engineering Branch 9pp 18463 001

--8305170307 Forwards proprietary & nonproprietary versions of "Corrections to Critical Crack Size " Proprietary version withheld (ref 10CFR2 790)
DICKINSON, J D Westinghouse Electric Corp. SE-83-02 83/05/13
SCHIFFGENS, J O Materials Engineering Branch 1p 18463 010

--8305170311 CT-25086A
Nonproprietary version of "Corrections to Critical Crack Size "
* Westinghouse Electric Corp 83/04/15 6pp 18463 011

8305170554 Clarifies commitment to apply 100% insp to selected components of DB-50 & DB-416 undervoltage trip attachments, in response to NRC requests New QC procedure will be applied to DB-50 attachments
RAHE, E P Westinghouse Electric Corp NS-EPR-2762. 83/05/06
DENTON, H Office of Nuclear Reactor Regulation, Director 2pp
18467 021

8305180262 Forwards response to 830407 & 28 telcon requests for addl info re Rev 1 to proprietary WCAP-10021 "Westinghouse Wet Annular Burnable Absorber Evaluation Rept " Response withheld (ref 10CFR2 790).
RAHE, E P Westinghouse Electric Corp 83/04/29 THOMAS, C O
Standardization & Special Projects Branch 1p 18487.223.

--8305180273 Application for withholding response to request for addl info re Rev 1 to proprietary WCAP-10021 "Westinghouse Wet Annular Burnable Absorber Evaluation Rept," from public disclosure
WIESEMANN, R A Westinghouse Electric Corp AW-83-39. 83/04/29.
THOMAS, C O Standardization & Special Projects Branch. 1p
18487 224

8305190298 Forwards changes in MPQP-1, Rev 5 re QA engineering, providing insp plan to QC & removing requirement for reviewing design documents NRC approval of activity requested
MILLER, D B Consumers Power Co CSC-6694 83/05/06 HARRISON, J J
Region 3, Office of Director 1p. 18501.083 24X
Fiche 50-329, 83/05/06, 8305190298

--8305190300 MPQP-1 R06 DRFT
Draft quality plan for underpinning activities.
* Consumers Power Co. MPQP-1 83/05/03. 23pp 18501.084. 24X
Fiche 50-329, 83/05/06, 8305190298

8305200072 Forwards revised pages to fundamental nuclear matl control plan, deleting refs to NRC documents & repts no longer applicable. Revs include description of new fuel rod item control sys W/o encl.
LICHTENBERGER Combustion Engineering, Inc 83-04 83/05/04
JACKSON, R NRC - No Detailed Affiliation Given 1p 18540.130.

8305200552 Deficiency rept re potential defect in steel spring bands of 60 ampere fuseholders. Initially reported on 830504 Metallurgical testing of broken bands continuing Next rept will be submitted within 30 days
DWYER, P W General Electric Co. 83/05/10. DEYOUNG, R Director's Office, Office of Inspection and Enforcement 5pp 18516 007.

8305200621 Documents review of procedures & practices used in control of design & const of Byron Station & highlights important findings Const of Byron meets requirements of FSAR & SER (NUREG-0876) Supporting documentation encl
REED, C Commonwealth Edison Co 6434N 83/05/11 DENTON, H. R.
Office of Nuclear Reactor Regulation, Director 10pp 18521 085.
24X Fiche 50-000, 83/05/11, 8305200621.

--8305200684 Advises that Westinghouse QA program implementation described in WCAP-8370, Rev 9A, satisfactory
SEYFRIT, K V Region 4, Dallas, Office of the Director (81/03/01).
81/04/30 SLEMBER, R J Westinghouse Electric Corp. 2pp.
18522 259 24X Fiche 50-373, 83/05/11, 8305200621

8305230255 Summarizes info supporting position that postulated pipe breaks in RCS primary loop piping should be eliminated from structural design basis of all Westinghouse plants Testing program per Generic Issue A-2 documented
RAHE,E P Westinghouse Electric Corp NS-EPR-2768 83/05/11
VOLLMER,R H Division of Engineering 2pp 18537 139

8305230505 Requests addl info to complete review of Rev 12 to QA program topical rept Specific questions will be provided 1 wk prior to 830526 meeting in Framingham,MA,per 830512 telcon
MARTIN,T T Division of Engineering & Technical Programs 83/05/13
JOHNSON,W P Yankee Atomic Electric Co 2pp 18537 172

8305240144 Forwards draft proprietary Amend 2 to Rev 3 to EDR-1(P)-A, "Edarers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes " Affidavit dtd 831008 encl Rept withheld (ref 10CFR2 790)
HOLLDRAN,R W Holloran & Associates 83/05/16 MDRAN,D
Standardization & Special Projects Branch 3pp 18573 126

--8305240154 Forwards draft proprietary Amend 2 to Rev 3 to EDR-1(P)-A, "Edarers Nuclear Safety-Related Extra-Safety & Monitoring (X-SAM) Cranes " Rept withheld (ref 10CFR2 790)
HOLLORAN,R W Holloran & Associates 83/05/13 MDRAN,D
Standardization & Special Projects Branch 2pp 18573 129

8305240310 Forwards Endorsement 59 to NELIA Policy NF-193 & Endorsement 29 to MAELU Policy MF-94
NILSON,R. Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/17
SALTZMAN,J Office of Nuclear Reactor Regulation, Director 3pp 18548 185

8305240431 Informs that QA program,per SWSQAP 1-74A,Rev C, satisfactorily implemented Continuing QA program acceptability contingent upon satisfactory implementation verified through Vendor Programs Brench insps
COLLINS,J T Region 4, Office of Director 83/05/20 KELLY,R B
Stone & Webster Engineering Corp 2pp 18574 124

--8305240435 Advises that S&W satisfactorily implements QA program per SWSQAP 1-74A,Rev C Confirmation recommended
CHAMBERLAIN,D Region 4, Office of Director 83/05/18
COLLINS,J T Region 4, Office of Director 2pp 18574 126

8305240505 Forwards Rev 1 to CPC-2A "QA Program Description for Operational Nuclear Power Plants " Changes do not reduce commitments accepted by NRC on 830112. Submittal serves as annual rept
VANDEWALLE,D J Consumers Power Co 83/05/11 KEPPLER,J G Region 3, Office of Director 2pp 18575 116 24X Fiche 50-000,83/05/11, 8305240505.

--8305240565 CPC-2A R01
Rev 1 to "QA Program Description for Operational Nuclear Power Plants "
REYNOLDS,J.W., DEWITT,R.B , COOK,J.W Consumers Power Co.
83/01/10 90pp 18575 118 24X Fiche 50-000,83/05/11,8305240505.

8305250150 Notification of 830603 meeting w/BWR-Hydrogen Control Owners Group in Bethesda,MD to discuss hydrogen control program & emergency procedure guidelines
HOUSTON,D Licensing Branch 2 83/05/17 SCHWENCER,A Licensing Branch 2 4pp 18596 191 24X Fiche 50-416,83/05/17,8305250150

8305250514 Forwards safety evaluation re BWR Owners Group response to NUREG-0737,Item II K 3 45,"Depressurization W/Other Than Automatic Depressurization Sys " Action on item complete.
VASSALLO,D.B. Operating Reactors Branch 2 83/05/18 RHODE,G K
Niagara Mohawk Power Corp. 2pp 18595 310 24X
Fiche 50-220,83/05/18,8305250514

--8305250523 Safety evaluation supporting BWR Owners Group generic response to Item II K.3.45 of NUREG-0737,"Depressurization W/Other Than Automatic Depressurization Sys "
* NRC - No Detailed Affiliation Given 83/05/18 5pp.
18595 312 24X Fiche:50-220,83/05/18,8305250514

8305260309 Interim deficiency rept re core support structure bolting Initially reported on 830419 Evaluation of corrective action in progress. Next rept will be sent by 831101.
COOK,J W Consumers Power Co 83-05 #1 83/05/19 KEPPLER,J G,
Region 3, Office of Director. 3pp. 18625.200 24X
Fiche:50-000,83/05/19,8305260309

--8305260311 Deficiency rept re ultrasonic test abnormal indications in upper barrel bolting of reactor internals. Initially reported on 830328. Results of internal bolt insp discussed Addl info will be forwarded.
TAYLOR,J H. Babcock & Wilcox Co 83/04/11. DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 5pp
18625 205 24X Fiche.50-000,83/05/19,8305260309

--8305260313 Updated deficiency rept re core barrel bolting ultrasonic test indications Bolts visually inspected Hairline crack at shank to head junction indicated Repair plans dependent on results of lower core barrel insp
TAYLOR,J H Babcock & Wilcox Co 83/04/22 DEYOUNG,R C
Director's Office, Office of Inspection and Enforcement 3pp
18625 210 24X Fiche 50-000,83/05/19,8305260309

8305260320 Forwards NEDO-24582, "Mark I Containment Program Plant-Unique Load Definition,Brunswick Steam Electric Plant Units 1 & 2 " Attachment detailing pressure/temp calculations also encl
ZIMMERMAN,S R Caroline Power & Light Co LAP-83-170 83/05/24
VASSALLO,D B Operating Reactors Branch 2 1p 18625 058 24X
Fiche 50-324,83/05/24,8305260320

--8305260325 NEDO-24582 R01
"Mark I Containment Program Plant-Unique Load Definition, Brunswick Steam Electric Plant Units 1 & 2 "
* General Electric Co 81NED0078 81/10/31 61pp 18625 059
24X Fiche 50-324,83/05/24,8305260320

8305260396 Requests board notification be issued to boards associated w/C-E plants currently w/o PORVs NRC briefed Commission on 830404 re status of DHR studies w/emphasis on need for PORVs in current C-E designs
MATTSON,R J Division of Systems Integration (post 811005)
83/04/28 EISENHUT,D G Division of Licensing 1p 18629 360

8305270006 Forwards proprietary & nonproprietary versions of viewgraphs presented at 830331 meeting re counter flow preheat steam generator program Proprietary version withheld (ref 10CFR2 790)
RAHE,E P Westinghouse Electric Corp NS-EPR-2747 83/04/11
EISENHUT,D G Division of Licensing HOPKINS,B NRC - No Detailed Affiliation Given 1p 18638 140

--8305270012 Submits application for withholding viewgraphs presented at 830331 meeting re counterflow preheat steam generator program from public disclosure (ref 10CFR2 790) Nonproprietary viewgraphs encl
WIESEMANN,R A Westinghouse Electric Corp AW-83-24 83/04/11
EISENHUT,D G Division of Licensing 12pp 18638 141

8305270144 Advises that QA program described in NEDO-11209-04A being implemented satisfactorily Results of insp published quarterly in NUREG-0040
COLLINS,J T. Division of Vendor & Technical Programs 83/05/24
BRUGGEMAN,W H General Electric Co 2pp 18638 203

--8305270149 Discusses corrective actions on nonconformances noted in IE insps since Jan 1980 QE satisfactorily implemented QA program per NEDO-11209-04A Confirmation of implementation recommended
CHAMBERLAIN,D Division of Vendor & Technical Programs 83/05/20
COLLINS,J T Region 4, Office of Director 1p 18638 205

8305270259 Application to amend License DPR-38,changing core protection safety limits,protective sys max allowable setpoints & rod position limits
TUCKER,H B Duke Power Co 83/05/19 DENTON,H R Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 4pp 18641 224 24X Fiche 50-269,83/05/19,8305270259

--8305270309 BAW-1774
"Oconee Unit 1 Cycle 8 Reload Rept "
* Babcock & Wilcox Co 83/02/28 46pp 18641 267 24X
Fiche 50-269,83/05/19,8305270259

8305270340 Forwards application to amend License DPR-59 & "Supplemental Reload Licensing Submittal for JA Fitzpatrick Nuclear Power Plant,Reload 5 " Amend changes std reload licensing submittal for forthcoming Reload 5/Cycle 6 core
BAYNE,J P Power Authority of the State of New York JPN-83-47
83/05/25 VASSALLO,D B Operating Reactors Branch 2 2pp
18643 071 24X Fiche 50-333,83/05/25,8305270340

--8305270378 Y1003J01A56 R01
Rev 0 to "Supplemental Reload Licensing Submittal for JA Fitzpatrick Nuclear Power Plant,Reload 5 "
ZARBIN,W A , WAGNER,R.L , CHARNLEY,J S General Electric Co
83/03/31. 25pp 18643 103 24X Fiche 50-333,83/05/25,8305270340

8305270361 Submits topics to be discussed during 830526 meeting re need for addl info to complete NRC review of Rev 12 to operational QA program topical rept
MARTIN,T.T Division of Engineering & Technical Programs 83/05/20
JOHNSON,W.P Yankee Atomic Electric Co 2pp 18638 361.

8305270432 Discusses B&W Owners Group emergency procedure guidelines (abnormal transient operating guidelines - ATOG), per 830505 ltr Detailed schedule for expansion of technical bases for procedure will be submitted by end of June
WHITNEY, D D Babcock & Wilcox Operating Plants Owners Group
WHITNEY, D D Sacramento Municipal Utility District GL-82-33
83/05/21 EISENHUT, D G Division of Licensing 2pp 18642 289

8305270481 Forwards proprietary "Vantage 5 Fuel Sys, Westinghouse Presentation to NRC Staff," presented at 830510 meeting & application for withholding info from public disclosure
RAHE, E P Westinghouse Electric Corp NS-EPR-2760 83/05/18
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 2pp
18644 054

--8305270488 Submits application for withholding proprietary info re Westinghouse Vantage 5 fuel sys design meeting presentation from public disclosure (ref 10CFR2 790)
WIESEMANN, R A Westinghouse Electric Corp AW-83-37 83/05/18
RUBENSTEIN, L S Assistant Director for Core & Plant Systems 1p
18644 056

WASTE MGT NUCLEAR WASTE MANAGEMENT

8303290556 Forwards proposed schedule for Basalt Waste Isolation Project 810922 visit
WRIGHT, R J High Level Waste Technical Development Branch 00196
81/08/21 GORANSON, R Energy, Dept of 5pp 17743 235

8303290813 Discusses progress made since Jul 1980 site visit re regulations for high level radwaste repository
WRIGHT, R J High Level Waste Technical Development Branch 00266
81/10/07 LIVINGSTON, V E Washington, State of 2pp 17748 073

8305060319 Forwards "Breathing Zone for Airborne Particulates, Cotter Employees for Month of Mar 1983" & "Breathing Zone Summary for CY83 "
CAIN, J Cotter Corp 00232 83/04/13 HAZLE, A J Colorado, State of 2pp 18353 064

--8305060325 "Breathing Zone for Airborne Particulates, Cotter Employees for Month of Mar 1983" & "Breathing Zone Summary for CY83 "
* Cotter Corp 0232 83/04/13 2pp 18353 066

8305090567 Responds to topical rept on RADMAN computer code to classify & document packaged low level waste per 10CFR61 Program shows promise as valid tool for waste generators to use as part of compliance w/Part 61 requirements
ROLES, G W Low Level Waste Licensing Branch 83/03/28. TUITE, P T
Waste Management Group, Inc 1p 18367 359

8305090572 Forwards listed publications per code evaluation "Documentation of Computer Codes for High Level Waste Mgt" also encl No significant changes expected prior to final promulgation W/o encls.
KNAPP, M R High Level Waste Licensing Management Branch 83/04/12
BERMANIS, H L Roy F Weston, Inc 1p 18367 358

8305090576 Forwards first 11 radiological assessment repts for detected areas of residual radioactive matls in Edgemont, SD Addl repts will be submitted as available W/o encls
MARTIN, D E Low Level Waste Licensing Branch 83/04/08. BRICH, R
South Dakota, State of 1p 18367 357

8305090582 Comments on review of Atlantic Research Corp request to allow onsite disposal of soil contaminated w/Sr-90 Potential dose commitment limited to less than 2 mrem to bone provided drinking water not within 250 ft of Sr-90
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/04/21
PAGE, R G Uranium Fuel Licensing Branch 3pp 18367 354

8305090588 Submits current & projected activities in fuel cycle program area Resource estimates & level of effort may change after evaluating 1983 budget
BROWNING, R E Division of Waste Management 83/04/15.
CUNNINGHAM, R E. Division of Fuel Cycle & Material Safety 2pp
18367 348

8305090606 Trip rept of 830324 visit to Rio Algom mill in Grand Junction, CO
PENNIFILL, R A Low Level Waste Licensing Branch 83/04/11
HIGGINBOTHAM, L Low Level Waste Licensing Branch 3pp. 18381:237

8305090617 Comments on Rev 1 to "Selection of West Valley Demonstration Project Low Level & Transuranic Waste Form " Insufficient technical data in document to judge adequacy of either cement or asphalt for solidification
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/04/15
ROUSE, L C. Advanced Fuel & Spent Fuel Licensing Branch 4pp
18367.332.

8305090620 Summary of 830316 meeting w/DOE in Silver Spring, MD re UMTRAP vicinity properties
FLORY, C A Low Level Waste Licensing Branch 83/04/28
HIGGINBOTHAM, L Low Level Waste Licensing Branch 2pp 18367 330

8305090626 Forwards list of documents within Div of Waste Mgt re K Dunn FOIA 83-153 request
STILL, N Division of Waste Management 83/04/06 BEVERIDGE, G
Program Support Branch 4pp 18367 325

8305090643 Forwards NRC comments to DOE on proposed high level waste repository siting guidelines W/o encl
BROWNING, R E Division of Waste Management 83/04/18 LEWIS, N D
Washington, State of 1p 18367 306

8305090647 Trip rept of 830419-21 USGS low level waste research meetings in Urbana, IL & at Sheffield site
SIEFKEN, D L Low Level Waste Licensing Branch 83/04/27.
HAWKINS, E F Low Level Waste Licensing Branch 4pp 18381 208.

8305090653 Trip rept of low level waste compact negotiators 830315-16 meetings in Atlanta, GA
JACKSON, K Low Level Waste Licensing Branch 83/04/27
HIGGINBOTHAM, L Low Level Waste Licensing Branch 5pp 18381·279

8305090656 Forwards, for concurrence review, Commission paper recommending publication of proposed suspension of portions of App A to 10CFR40 re U mill tailings regulations Telephone response by 830429 requested W/o encl
BROWNING, R E Division of Waste Management 83/04/28 KERR, G W
Office of State Programs, Director CUNNINGHAM, G. H Office of the Executive Legal Director CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp 18381 277

8305090661 Ack receipt of 830308 ltr inviting participation in 2-day meeting on "WIPP Site Suitability for Radwaste Disposal," on 830512-13 in Carlsbad, NM NRC cannot participate in meeting or evaluation
MILLER, H J High Level Waste Technical Development Branch.
83/03/31 NEILL, R H New Mexico, State of 2pp 18381 040.

8305090670 Forward comments on topical rept "Results of Test Program for Solidification of Contaminated Waste Lubricating Oils." State of WA comments should be addressed separately W/o encl
JOHNSON, T C Low Level Waste Licensing Branch 83/04/27
IRVING, B A Vikem Industries, Inc 1p 18369 362

8305090675 Reviews marked-up handout on high level waste reflecting enactment of Nuclear Waste Policy Act in Jan 1983 W/o encl
BROWNING, R E Division of Waste Management 83/03/29 COOK, J
Office of Public Affairs 2pp 18381 289

8305090679 Forwards 24 radiological assessment repts for properties in Edgemont, SD re presence of residual radioactive matl Repts submitted to DOE for remedial action W/o encls
MARTIN, D E Low Level Waste Licensing Branch 83/04/28 GEIDT, J R
Environmental Protection Agency 1p 18381.288

8305090696 Forwards NRC "Technical Criteria for Disposal of High Level Radwaste in Geologic Repositories," 10CFR60, Subpart E, per 830412 ltr Final version to be released on NRC approval W/o encl
BALL, M J High Level Waste Licensing Management Branch 83/04/25
SMITH, G R Michigan, State of 1p 18381.287

8305090705 Forwards response to 830312 request for comment on remedial action concept paper for U mill tailings site at Green River, UT
MARTIN, D E Low Level Waste Licensing Branch 83/04/22
MARLEY, J A Energy, Dept of 3pp 18381·284

8305110024 Forwards comments to DOE on 830207 proposed siting guidelines (10CFR960), established in response to Nuclear Waste Policy Act of 1982 requirements NRC comments on DOE FR notice also provided W/o encl
DIRCKS, W J Office of Nuclear Reactor Regulation, Director
83/04/25 MATHESON, S M Utah, State of. 1p 18411.356.

8305110068 Informs that 830406 ltr & attachments sent to M Bell. Copy of Reg Guide 4 17 encl. W/o encl
WRIGHT, R J High Level Waste Technical Development Branch
83/04/26 HOVIS, J. B Hovis, Cockrill, Weaver & Bjur 1p.
18421 237

8305110138 Forwards info on 20 contaminated properties in vicinity of Grand Junction site Remedial action being prepared. W/o encl.
BAUBLITZ, J E Energy, Dept of 83/04/15. HAWKINS, E P Low Level Waste Licensing Branch 1p 18421 358

8305110142 Forwards final draft remedial action concept paper for Gunnison inactive U mill tailings site Comments requested by 830506 W/o encl
MORLEY, J. A Energy, Dept of 83/04/18 HAWKINS, E Low Level Waste Licensing Branch 1p 18421 350

8305110147 Forwards J Hayes comments on draft ANS 16 1 std W/o encl
JOHNSON, J C Low Level Waste Licensing Branch 83/04/07 GODBEE, H Oak Ridge National Laboratory 1p 18434 111

8305110158 Forwards separate responses to RADMAN code topical comments provided by States of SC, WA & NV Code will reinforce QA program & survey acceptabilities
TUITE, P T Waste Management Group, Inc 83/04/13 JOHNSON, T NRC - No Detailed Affiliation Given 6pp 18434 097

8305110178 Summarizes 830418 meeting w/DOE & Battelle in Gaithersburg, MD re siting guidelines (proposed 10CFR96)
PFLUM, C. G High Level Waste Licensing Management Branch 83/04/22 BOYLE, R. R High Level Waste Licensing Management Branch 2pp 18434 260

8305110183 Forwards 24 radiological assessment repts for properties in Edgemont, SD w/detected presence of residual radioactive matls Addl repts will be submitted W/o encl
MARTIN, D. E Low Level Waste Licensing Branch 83/04/28 BRITCH, R South Dakota, State of 1p 18434 282

8305110218 Forwards comments on proposal for transuranic waste sorting at West Valley per 830405 request Concept acceptable
HIGGINBOTHAM, L Low Level Waste Licensing Branch 83/04/15 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 4pp 18434 350

8305260356 "RADON-222 Repts for Feb & Mar 1983," based on TLD chips for probes placed on 830211 & removed 830405 Replacement probes not available during Mar due to procurement of new lab to perform svcs.
CAIN, J Cotter Corp 00287 83/04/25 HAZLE, A J Colorado, State of 3pp 18647 291

8305260360 "Breathing Zone Rept for Apr 1983" & "Cumulative Breathing Zone Summary for CY83 "
CAIN, J Cotter Corp 00277 83/05/13 HAZLE, A J Colorado, State of. 2pp 18648 021

8305310211 CGS/8116R028
"Geology & Hydrology of Yucca Mountain & Vicinity, NV Test Site," final rept W/three oversize figures Aperture cards are available in PDR
READE, M T , MCKAY, E D CGS, Inc 83/03/31 71pp 18651 230

8305310217 Confirms 830601 meeting W/J Baublitz (DOE) in Bethesda, MD to discuss implementation of UMTRCA for Cannonsburg site.
PAGE, R. G Uranium Fuel Licensing Branch 83/05/23 HIGGINBOTHAM, L High Level Waste Licensing Management Branch FONNER, R Office of the Executive Legal Director CROW, W T NRC - No Detailed Affiliation Given 1p 18662 268

XPORTLIC EXPORT AND IMPORT LICENSES

8305020001 License for GE to export 500 pieces of zirconium tubing to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-044-83 83/04/25 1p 18308:308

8305020003 Requests Executive Branch position re QA Technologies, Inc application to amend license to export, decreasing quantity from 1.1 kg U-235 to 250 g U-235
ZIMMERMAN, S V. Assistant Director for Export/Import & International Safeguards 83/04/26 STOIBER, C R State, Dept of 1p 18308:307

8305020005 Application to amend license to export, adding addl 120 g U-235 & addl ultimate consignee
MARCHAL, J European Communities, Commission of AQ/1543 83/04/14 GRIFFIN, J A. Energy, Dept. of 1p 18308, 306

8305020021 Application to amend licenses for export & import, extending expiration date by 1 yr
BALALIS, C G. Union Carbide Corp 83/04/18 WRIGHT, B NRC - No Detailed Affiliation Given 1p 18308 305.

8305020096 Ltr of assurance re Westinghouse application to export 200 g U-235, contained in 5,600 g total U, to United Kingdom
MARCHAL, J European Communities, Commission of. 83/04/14 GRIFFIN, J A Energy, Dept. of 1p 18308 264.

8305020098 License for Mitsubishi Intl Corp to export 500 mCi Cf-252 to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 64-7739-83 83/04/26 1p 18308 263

8305020288 Forwards application to export six depleted U blanks to United Kingdom
GOMER, D Nuclear Metals, Inc 83/04/14 WRIGHT, B Office of International Programs, Director 1p 18308 261

--8305020296 Application to export 30 4 kg depleted U, in six depleted blanks, to United Kingdom
* Nuclear Metals, Inc 83/04/14 1p 18308 262

8305020553 Forwards application for license to export slightly enriched U hexafluoride to Japan
OSHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-01 83/04/14 Assistant Director for Export/Import & International Safeguards 3pp 18284 071

--8305020557 Application for license to export 80,420 kg slightly enriched U hexafluoride to Japan
SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-01 83/04/14 1p 18284 074

8305030018 Forwards application for license to export one fission counter, Model RS-P6-0805-134, to West Germany
BAER, D Disc Corp C-4422 83/04/11 HEMBY, E Assistant Director for Export/Import & International Safeguards 2pp 18310 286

--8305030056 Application for license to export one fission counter, Model RS-P6-0805-134, to West Germany
BAER, D Disc Corp C-4422 83/04/11 2pp 18310 288

8305030097 Requests Executive Branch position re Transnuclear, Inc application for license to export highly enriched U to Denmark W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 00290 82/10/06 STOIBER, C R State, Dept of 1p 18310 358

8305030250 Application to export 500 liters deuterium to Korea
HWANG, T Pacific International 455 83/04/18 1p 18309 339

8305040395 Addl info re 830225 application to export 1 kg U-235 to Indonesia Quantity reduced to 250 g, contained in reactor irradiation targets, to allay concerns raised re export
MOWRY, W R GA Technologies, Inc /General Atomic Co IEL-4069 83/04/13 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 9pp 18326 301

8305040558 Forwards applications for licenses to export 500 pieces scrap zirconium tubing to West Germany & 10 pieces zirconium tube shell to Japan
WILSON, B D General Electric Co BDW-046-83 83/04/14 HEMBY, E G NRC - No Detailed Affiliation Given 1p 18351 239

--8305040561 Application for license to export 500 pieces scrap zirconium tubing to West Germany
* General Electric Co. BDW-044-83 83/04/14 1p 18351 240

--8305040567 Application for license to export 10 pieces zirconium tube shell to Japan
WILSON, B D General Electric Co BDW-045-83 83/04/14 1p 18351 241

8305040637 Application to import zirc clad U/Zircaloy & U/Zircaloy & metal components & scrap waste from Canada
REGAN, N A Babcock & Wilcox Co 83/04/15 Assistant Director for Export/Import & International Safeguards 2pp 18336 281

8305040639 Informs that Disc Corp 830411 application for license to export proportional counter to West Germany meets requirements of Atomic Energy Act License issued w/o normal 15 day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/22 Assistant Director for Export/Import & International Safeguards 1p 18336 280

8305040644 Notifies that GE 830414 application for license to export zirconium tube shells to Japan meets requirements of Atomic Energy Act License issued w/o normal 15 day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/25 Assistant Director for Export/Import & International Safeguards 1p 18336 279

8305040658 Amend 2 to Edlow Intl Co as agent for Microtec, Inc export license, changing name of ultimate consignee & extending expiration date to 900501
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards M&B-1 83/04/26 1p 18336 268

8305040665 Requests Executive Branch position re Mitsubishi Intl Corp application for license to export enriched U to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/26 STOIBER, C R State, Dept of 1p 18336 265

8305050440 Amend 3 to GA Technologies, Inc export license, adding ultimate consignee & increasing quantity of matl to 3 167 kg U-235, contained in 15 989 kg U, for export to Italy
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-2013 83/04/28 1p 18352 228

8305060006 Application to export two fission counters, Model RS-P9-2403-114, to Argentina
SKARUPA, J D Reuter-Stokes, Inc A-9705 83/04/19 2pp 18354 309

8305060014 Notifies that OE 830414 application for license to export zirconium tubing to West Germany meets requirements of Atomic Energy Act. License issued w/o normal 15 day waiting period
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/25 Assistant Director for Export/Import & International Safeguards 1p 18354 313

8305060052 Ltr of assurance re amend to license to export 33,750 kg U, contained in 1,135 kg U-235, to Sweden
MAGNUSON, L Sweden, Govt of, 83/04/19 GRIFFIN, J A Energy, Dept of 1p 18354 361

8305060687 Executive Branch position re SWUCO, Inc application to export 5 kg U-235, contained in 70 kg U, to Taiwan License should be granted
DEVINE, J B State, Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs 83/04/25 SHEA, J R Office of International Programs, Director 3pp 18357-308

8305060690 Application for amend to export license, increasing SNM by 312 39 g U-235, contained in 1,373 74 g U, to Japan
MOWRY, W R GA Technologies, Inc /General Atomic Co IEL-4072 83/04/25 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards. 1p 18357 307

8305090010 Application to import 26,000 kg U, enriched to 3 30% U-235, from France
MARCHAL, J Exxon Nuclear Co , Inc (subs of Exxon Corp) 11003189 83/04/25 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 18369 358

8305090014 Application for license to export 2,205 lb Zircaloy trex, w/pure zirconium liner, to West Germany
AERNI, B L Teledyne Wah Chang Albany 2625(2) (JFM) 83/04/27 1p 18369 356

8305090015 Application for license to export one in-core detector containing 0 001 g U-235 to West Germany
POCHAL Westinghouse Electric Corp ZE10534 83/04/21. 1p 18369 357

8305090042 Amend 2 to Union Carbide Corp license to import 10,8 kg U, containing up to 10 % g U-235 in 55 MTR plate-type fuel elements, from France.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/29 1p 18381 198

8305090114 Application for license to export 97,000 lb Zircaloy trex to West Germany.
AERNI, B L Teledyne Wah Chang Albany 2907(JFM) 83/04/21 1p 18381-131

8305090498 License for GA Co to export miscellaneous specially design or prepared replacement parts & components for use in Triga II research reactor to Zaire
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards IEL-3096. 83/04/29 1p 18381 240

8305090500 License for Westinghouse to export one compensated ionization chamber, Model WL-6377, to Zaire.
ZIMMERMAN, J. V Assistant Director for Export/Import & International Safeguards IE 20594. 83/05/02 1p. 18381 251

8305090723 Requests renewal of Export Licenses XU-8498 & XU-8499 which expire on 830601 No change in quantity & matls expected
GOMER, D A Nuclear Metals, Inc 83/04/25 HEMBY, E Office of International Programs, Director 1p 18381 276

8305090730 Forwards FR notice re applications for licenses to import/export nuclear facilities or matls
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 82/05/03 COMBS, T R Correspondence & Records Branch 1p 18381 273

--8305090731 Notice of receipt of applications for licenses to import/export nuclear facilities or matls
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/03 2pp 18381 274

8305090733 License for Westinghouse to export 200 g U-235, contained in 5,600 g U, to United Kingdom
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MMH-353 83/04/29 2pp 18381 271

8305090736 Amend 2 to Union Carbide Corp export license, extending expiration date to 840701
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 281 83/04/29 1p 18381 270.

8305090779 Amend 1 to Exxon export license, increasing quantity to 1,135 kg U-235, contained in 33,750 kg U, to Sweden
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/04/29 1p 18381 269

8305090782 Informs that Amend 1 to Export License XSNM-1903 may be issued No matl changed circumstances since issuance of License XSNM-1974
MOORE, R N Assistant Director for Export/Import & International Safeguards. 83/04/28 Assistant Director for Export/Import & International Safeguards 1p 18381 268

8305130254 Application for license to export one component case stud for specially prepared coolant pumps for nuclear svc, to Spain
PEARSON, A Borg-Warner Corp 836V3070 83/05/02 1p 18457:174

8305130265 Amend 1 to Nuclear Metals, Inc export license, extending expiration date until 860601
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/05 1p 18457 171

8305130269 Amend 1 to Nuclear Metals, Inc export license, extending expiration date until 860601
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/05 1p 18457 170

8305130273 Executive Branch position re Edlow Intl Co application for license to export 40 mg Cf-252, in form of cermet wire, to United Kingdom License should be amended
DEVINE, J B State, Dept of 83/05/03 SHEA, J R Office of International Programs, Director 1p 18457-169

8305130301 Application for license to export 2,002 mCi Cf-252, in form of cermet wire, to France.
HANNETT, B Transnuclear, Inc. TNP-426 83/05/02 2pp 18457,167.

8305130303 Application for license to export two WX-33356 BF3 counter tubes & eight WX-3335B uncompensated ionization chambers to West Germany
POCHAL, W F Westinghouse Electric Corp ZE 10149 83/05/03 1p. 18457 166

8305130305 Application for license to export primary recirculation pump accessories to Spain
PEARSON, A Borg-Warner Corp. 823-V-2207 B1 83/05/02 1p. 18457 165

8305160294 Forwards application for export license for minor nuclear export Ltr of assurance required, W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/11 RAYMOND, J F Energy, Dept of 1p. 18472 078

8305160296 Forwards Exxon Nuclear Co, Inc application for amend to export license increasing quantity of U-235 Ltr of assurance required W/o encl
ZIMMERMAN, J. V. Assistant Director for Export/Import & International Safeguards 83/05/11 RAYMOND, J F Energy, Dept. of 1p 18472 077

8305160298 Application for license to export 200 guide thimble tubes to Japan.
YUMOTO,H C Itoh & Co (America), Inc MGI-144 83/05/10 2pp
18472:075

8305160300 Amend 1 to QA Co export license,changing name of licensee to QA Technologies,Inc
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards IEL-3096 83/05/12 1p 18472 068

8305160301 Forwards application for license to export cerium fluoride to Canada,United Kingdom,Australia,West Germany,Japan,France & The Netherlands
BENNER,R Q M & T Chemicals, Inc 83/05/03 HENLEY,E NRC - No Detailed Affiliation Given 2pp 18472 063

--8305160303 Application for license to export cerium fluoride to Canada, United Kingdom,Australia,West Germany,Japan,France & The Netherlands
BENNER,R Q M & T Chemicals, Inc 83/05/03 1p 18472 065

--8305160305 Requests info whether new license required to export cerium fluoride to Canada,United Kingdom,Australia,West Germany, Japan,France & The Netherlands
BENNER,R Q M & T Chemicals, Inc 83/04/07. NRC - No Detailed Affiliation Given 2pp 18472 066

8305160306 Informs that License XSNM-2030 may be issued No matl changed circumstances since issuance of License XSNM-2005
MOORE,R.N Assistant Director for Export/Import & International Safeguards 83/05/10 Assistant Director for Export/Import & International Safeguards 1p 18472 062.

8305160307 License for Mitsubishi Intl Corp to export 365 kg U-235, contained in 10,554 kg U, to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards HSA-5482-09 83/05/11 2pp 18472 060

8305160309 License for Mitsubishi Intl Corp to export 682 kg U-235, contained in 19,754 kg U, to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards HSA-5482-08 83/05/11 2pp 18472 058

8305160310 License for Edlow Intl Co to export 382 kg U-235,contained in 14,410 kg U, to Japan
ZIMMERMAN,J.V Assistant Director for Export/Import & International Safeguards. 83/05/11 2pp. 18472 056

8305160313 License for Teledyne Wah Chang Albany to export 2,205 lb Zircaloy to West Germany
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 2625(2)(JFM) 83/05/01 1p 18472.055

8305160315 License for Nuclear Metals,Inc to export 30 4 kg depleted U,contained in 6 U blanks,to United Kingdom
ZIMMERMAN,J V. Assistant Director for Export/Import & International Safeguards I-201-7 83/05/11 1p 18472 054

8305170120 Requests Executive Branch position re Nissho Iwai American Corp application for amend to licenses,increasing quantity of highly enriched U for export to Japan
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards. 83/05/11 STOIBER,C R State, Dept of 1p 18496·021

--8305170125 Application to amend licenses,changing quantity to 12,270 kg,contained in 27 026 kg & 25,049 kg,contained in 55 174 kg,for export to Japan
YAMANA,K Nissho-Iwai American Corp MPD-0763 83/05/04
MOORE,N Assistant Director for Export/Import & International Safeguards 1p. 18496 022

8305170575 Ltr of assurance re export of 382 kg U-235,contained in 14,410 kg U,to Japan
SHIRAKAWA,T Japan, Govt of,. 83/05/03 GRIFFIN,J.A Energy, Dept. of 1p 18496.120

8305170578 Application for amend to export license,extending expiration date to 860630
WILSON,B D General Electric Co BDW-050-83 83/05/02.
WRIGHT,B.L Office of International Programs, Director. 1p 18496.116

8305170580 Ltr of assurance re export of 365 kg U-235,contained in 10,554 kg U,to Japan.
SHIRAKAWA,T. Japan, Govt of, 83/05/03 GRIFFIN,J A Energy, Dept. of. 1p. 18496·114.

8305170582 Ltr of assurance re export of 403 kg U-235,contained in 13,418 kg U,to Japan
SHIRAKAWA,T Japan, Govt of. 83/05/03 GRIFFIN,J A Energy, Dept of 1p 18496 113

8305170584 Application for license to import 28,600 kg U,containing 1,000 kg U-235,from France
KIEL,G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/04/29
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 2pp 18496 109

8305170594 License for Westinghouse to export 5 kg U-235,contained in 150 kg U,to Sweden
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards MMH-341 83/05/10 2pp 18495 028

8305170609 Informs that License XSNM-2023 may be issued No matl changed circumstances since issuance of License XSNM-2005
MOORE,R N Assistant Director for Export/Import & International Safeguards 83/05/10 Assistant Director for Export/Import & International Safeguards 1p 18497 023

8305170611 Informs that License XSNM-2017 may be issued No matl changed circumstances since issuance of License XSNM-2005
MOORE,R N Assistant Director for Export/Import & International Safeguards 83/05/10 Assistant Director for Export/Import & International Safeguards 1p 18497 022

8305170616 Forwards applications to export 52,000 kg U,enriched to 3 85% U-235 & nuclear fuel hardware,to France W/o application to export hardware
KIEL,G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/05
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 1p 18497 015

--8305170621 Application for license to export 52,000 kg U,enriched to 3 85% U-235,to France
KIEL,G R Exxon Nuclear Co , Inc (subs of Exxon Corp)
83/05/05 1p 18497 016

8305180067 Forwards applications for licenses to export 52,000 kg U, enriched to 3 85% U-235 & nuclear fuel hardware to France W/o XSNM-2043 application
KIEL,G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/05
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 1p 18499 349

--8305180073 Application for license to export nuclear fuel rod hardware & cage assemblies to France
KIEL,G R Exxon Nuclear Co , Inc. (subs of Exxon Corp)
83/05/05 1p 18499 348

8305180078 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 83/05/11 RAYMOND,J F Energy, Dept of 1p 18499 339

8305180086 Amend 3 to QE & QE Technical Svcs Co,Inc export license, extending expiration date to 830630
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards BDW-050-83 83/05/12 1p 18499 360

8305180090 Amend 5 to QE export license,extending expiration date to 860630
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards BDW-053-83 83/05/12 1p 18499 361

8305180551 License for GM Corp to export stainless steel spare parts to Canada
ZIMMERMAN,J V. Assistant Director for Export/Import & International Safeguards 84068 83/05/09 1p. 18504 353

8305180617 Application to amend export license,extending expiration date to 860630
WILSON,B.D General Electric Co. BDW-053-83 83/05/02
WRIGHT,B L Office of International Programs, Director 1p 18505 316

8305180629 Ltr of assurance re export of 297 kg U-235,contained in 8,601 kg U,to Japan
SHIRAKAWA,T Japan, Govt of. 83/05/03 GRIFFIN,J A Energy, Dept of 1p. 18505.328

8305180703 License for Cerac,Inc to export 11 31 kg thorium,contained in 15 0 kg thorium fluoride,to Switzerland.
ZIMMERMAN,J V Assistant Director for Export/Import & International Safeguards 83/05/01 2pp 18506 041

8305180709 Application to amend Export Licenses XSNM-1778 & XSNM-1779, changing quantities to 12 270 kg & 25 049 kg, respectively
YAMANA, K Nissho-Iwai American Corp MPD-0763 83/05/04 MOORE, N Assistant Director for Export/Import & International Safeguards 1p 18506 043

8305180713 Application for license to export 77 kg U oxide powder to Japan
WILSON, B D General Electric Co BDW-051-83 83/05/02 1p 18506 044

8305180818 Ltr of assurance re export of 65,000 kg U, containing 2,652 kg U-235 & 150 kg U, containing 5 kg U-235, to Sweden
MAGNUSON, L Sweden, Govt of, 83/05/09 RAYMOND, J F Energy, Dept of 1p 18505 358

8305180819 Ltr of assurance re export of 682 kg U-235, contained in 19,754 kg U, to Japan
SHIRAKAWA, T Japan, Govt of, 83/05/03 GRIFFIN, J A Energy, Dept of 1p 18505 359

8305180826 Ltr of assurance re export of 341 kg U-235, contained in 11,439 kg U, to Japan
SHIRAKAWA, T Japan, Govt of, 83/05/03 GRIFFIN, J A Energy, Dept of 1p. 18505 362

8305180831 Application to amend export license, increasing quantity to 901 325 kg U-235 contained in 27,509 kg U
HANNETT, B A Transnuclear, Inc TNP-398 83/05/03 MOORE, N Office of International Programs, Director 1p 18506 008

8305180833 Application to amend export license, increasing quantity to 2,330 kg U-235
KIEL, G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/05 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18506 009

8305180835 Forwards application to amend license to export 625 62 g U-235, to japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/10. GRIFFIN, J A Energy, Dept of 1p 18506 011

--8305180839 Application to amend license to export 625 62 g U-235, to Japan
MOHRY, W R. GA Technologies, Inc /General Atomic Co IEL-4072 83/04/25 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 1p 18506 012

8305190053 Requests Executive Branch position re Safety Light Corp application for license to export dispersed tritium, contained in self-luminous devices, gas chromatograph detector foils & accelerator target devices
ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards 83/05/09 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ. & Scientific Affairs 1p 18523 196.

--8305190057 Application for license to export 120,000 Ci tritium to various countries
MILLER, J Safety Light Corp 83/04/22 HEMBRY, E Assistant Director for Export/Import & International Safeguards. 1p 18523 197

8305190452 Withdraws 830503 request for amend to export license
HANNETT, B A Transnuclear, Inc TNP-398 83/05/10 MOORE, N Office of International Programs, Director 1p 18523-167

8305200129 Forwards notice of receipt of applications for licenses to export/import nuclear matl Request for hearing or petition for leave to intervene may be filed within 30 days of FR notice publication
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/11 COMBS, T R Correspondence & Records Branch 1p. 18528 343

--8305200137 Notice of receipt of applications for licenses to export/import nuclear matl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/11. 2pp 18528 344

8305250165 Forwards updated rept of export licensing actions & summary of pending export applications as of 830430
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/13 Assistant Director for Export/Import & International Safeguards. 40pp 18596 147

8305260016 Requests Executive Branch position re Exxon Nuclear application for license to export U to Taiwan
ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards 83/05/17 STOIBER, C R State, Dept of 1p 18649 097

8305260018 Application to amend license increasing dollar amount of export to West Germany
KIEL, G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/10 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18649 096

8305260027 License for C Itoh & Co (America) Inc to export 200 guide thimble tubes to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards MOI-144 83/05/13 1p 18649 095

8305260029 License for Byron Jackson Pump Div to export case stud for use in coolant pump to Spain
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 836V3070 83/05/20 1p 18649 094

8305260034 License for Reactor Experiments, Inc to export 11 5 mg Pu-239, as metal disc, encapsulated on nickel, to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1046 83/05/20 2pp 18649 092

8305260055 Requests Executive Branch position re Westinghouse application for amend to license increasing quantity of U-235 for export to Yugoslavia
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/18 STOIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p 18649 086

--8305260057 Application to amend license increasing quantity of U-235 for export to Yugoslavia
HERSCH, M M Westinghouse Electric Corp MMH-373 83/05/11.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18649 087

8305260060 Ltr of assurance re Edlow Intl Co export of 75,000 kg U, containing 3,037 5 kg U-235 & Transnuclear, Inc export of 19 735 kg U, containing 593 2 kg U-235 to Sweden.
MAGNUSON, L Sweden, Govt of,. 83/05/12 RAYMOND, J F Energy, Dept of 1p 18649 085

8305260064 Application to amend license to import 23,000 kg U, containing 782 kg U-235, from France
KIEL, G R Exxon Nuclear Co , Inc (subs of Exxon Corp) 83/05/13 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 18649 083

8305260067 License for Pacific Intl to export 90 g deuterium to South Korea
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 455 83/05/13 1p 18649 082

8305260070 Application to amend license to export addl 3,210 kg U, contained in 90,420 kg U-235, to Yugoslavia
HERSCH, M M Westinghouse Electric Corp MMH-373 83/05/11.
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 1p 18649 081

8305260075 Application for Amend 1 to license increasing dollar amount of export
WILSON, B D General Electric Co BDW-058-83 83/05/10. HEMBY, E D NRC - No Detailed Affiliation Given 1p 18649.080

8305260090 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/19 HART, T Energy, Dept of, 1p. 18649 075

8305260097 Responds to 830503 request for confirmation of end use of matl for export license application End use statment encl
HANNETT, B A Transnuclear, Inc TNP-426 83/05/16 HEMBY, E. Office of International Programs, Director 2pp. 18649.073

8305260113 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/17 RAYMOND, J J Energy, Dept of 1p 18649 067

8305260185 Amend 7 to Edlow Intl Co export license, authorizing retransfer of Cf-252 microgram source from United Kingdom to Iraq
ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards TRC-4 83/05/12. 1p 18648 106

8305260189 License for OE to export 0.125 kg U-235, contained in 12 fully-clad, irradiated fuel segments & 0 070 kg Pu to Denmark & 0 250 kg U-235, contained in 22 fully-clad irradiated fuel segments & 0 110 kg Pu to Norway
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-005-83 83/05/17 2pp 18648-097

8305260191 Amend 1 to QE export license, revising total value of items to be exported to Japan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards BDW-058-83 83/05/16 1p 18648 096

8305260194 License for Teledyne Wah Chang Albany to export 2,205 lb Zircaloy trex, w/pure Zirconium liner, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards. JFM-2625 83/05/18 1p 18648 088

8305260197 License for Separative Work Unit Corp, Inc to export 5 kg U-235, contained in 70 kg U, to Taiwan
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/13 2pp 18648 072

8305260198 Amend 1 to Mitsubishi Intl Corp export license, reflecting change in end use to Genkai Unit 1
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HSA-5482-09 83/05/19 1p 18648 071

8305260199 License for Westinghouse to export one unit in-core detector, Model WL23798, to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards. ZE1053H 83/05/19 1p 18648 070

8305260203 License for Westinghouse to export two BF 3 counter tubes & eight uncompensated ionization chambers to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards ZE 10149 83/05/20 1p 18648 066

8305260204 License for Teledyne Wah Chang Albany to export 97,000 lb Zircaloy trex to West Germany
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards JFM-2907 83/05/18 1p 18648 065

8305260317 Application for license to export 26,865 kg U-235, as enriched U dioxide, to Japan
OKADA, S Mitsui & Co (U S A), Inc (subs of Mitsui & Co , Ltd)
MBK-F3-R8 83/05/11 1p 18629 291

8305260330 Application for license to export 3 modules (75-MOD-287) including support matl for penetration to Switzerland
POCHAL, W , SCHNAUTZ, C E Westinghouse Electric Corp ZE-10503
83/05/11 1p 18629 290

8305270032 Forwards FR notice of applications for licenses to import/export nuclear facilities or matls
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/16 COMBS, T R Public Document Branch 1p
18662 102

--8305270034 Notice of applications for licenses to import/export nuclear facilities or matls
ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/16 2pp 18662 103

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AAHODT, K M.	8305100205	50-289 Q
AAHODT, K. M	8305100406	50-289 Q
ACKMANN, L E	8305090469*	TOPREP
ADAMONIS, D C	8305100273*	50-334 Q
ADENSAM, E. Q.	8305020556	50-413 A
ADENSAM, E Q.	8305040021*	50-395 P
ADENSAM, E. Q	8305060130	50-395 P
ADENSAM, E Q.	8305060282*	50-395 P
ADENSAM, E Q.	8305060295*	50-395 P
ADENSAM, E. Q.	8305110136	50-395 P
ADENSAM, E Q.	8305110246	50-327 P
ADENSAM, E. Q.	8305110249*	50-327 P
ADENSAM, E Q	8305110253*	50-327 P
ADENSAM, E. Q	8305160196	50-413 E
ADENSAM, E. Q	8305160362	50-327 P
ADENSAM, E Q	8305160366*	50-327 P
ADENSAM, E Q	8305160369*	50-327 P
ADENSAM, E Q.	8305170730*	50-369 P
ADENSAM, E. Q.	8305180012	50-395 P
ADENSAM, E. Q	8305180023*	50-395 P
ADENSAM, E Q	8305180053	50-369 P
ADENSAM, E Q	8305180072*	50-369 P
ADENSAM, E Q.	8305180234*	50-327 P
ADENSAM, E. Q	8305200113	50-395 P
ADENSAM, E. Q	8305310187	50-390 F
ADRAGNA, J. M.	8305100339	PROJ
ADRAGNA, J. M	8305100339	PROJ
AERNI, B L.	8305090014	XPORTLIC
AERNI, B L	8305090114	XPORTLIC
AGEE, J R	8305050117*	GA999
AGEE, J R	8305050262*	GA999
AGLES, J. A.	8305270219*	50-250 Q
AGRAWAL, A. K	8305170086	50-537 A
AHEARNE, J.	8305250313*	COMMISSION
AHEARNE, J. F	8010280581*	50-498 A
AHEARNE, J. F.	8305180254*	50-498 T
AHEARNE, J. F.	8305230209*	50-320 T
AHMED, I	8305030474*	50-483 G
AHMED, I.	8305120368*	50-374 G
AHMED, N.	8305230284*	50-213 P
AHN, T. H	8305110127	NUREG
AHRENS, P.	8305030567*	50-309 Q
AHRENS, P.	8305180460	PR
AHRENS, P.	8305240386	50-309 Q
ALBERT, W. Q	8305170498*	50-508 G
ALBRECHT, V S.	8305200659	50-338 Q
ALBRECHT, V. S.	8305200659	50-338 Q
ALBRIGHT, R H.	8305270231*	50-261 Q
ALBRIGHT, R H.	8305270428*	50-369 Q
ALDERSON, C E	8305020319*	GA999
ALEXICH, M. P	8305030519	50-315 P
ALEXICH, M. P.	8305120108	50-315 F
ALLAN, J. M	8304270278	50-244 F
ALLAN, J. M.	8305040785*	50-322 Q
ALLAN, J M.	8305040790*	50-322 Q
ALLAN, J M	8305120421	50-309 F
ALLAN, J M	8305190356	MISC
ALLAN, J. M	8305230139*	FOIA
ALLAN, J. M.	8305250274	50-29 F
ALLAN, J M	8305250426	50-334 F
ALLAN, J M.	8305250572	50-271 Q
ALLAN, J M	8305250577*	50-271 Q
ALLAN, J M	8305270434	50-309 Q
ALLAN, J M	8305270445*	50-309 Q
ALLARD, D J	8208060242*	40-672
ALLARD, D J	8208060244*	40-672
ALLEN, R E	8305030461	PR
ALLENSPACH, F R	8305170047*	50-289 Q
ALLENSPACH, F R	8305230440*	50-289 Q
ALLISON, C W	8305090541*	50-358 A
ALLISON, D. P	8305030474*	50-483 Q
AMICO, P J	8305180146*	50-247 Q
AMICO, P J	8305180146*	50-247 Q
AMIN, M.	8305270501*	50-454 Q
AMY, Q Q	8305250578*	70-371
AMY, Q Q	8305250586*	70-371
ANAND, R K	8305100400*	50-443 Q
ANANDAPPA, A	8305020256*	50-249 S
ANANDAPPA, A	8305060422*	50-237 S
ANANDAPPA, A	8305060599*	50-237 S
ANDERSON, C A	8305160299	50-537 Q
ANDERSON, C A	8305160299	50-537 Q
ANDERSON, J. T	8305200465*	50-315 F
ANDERSON, R D	8305100144*	50-293 R
ANG, W P	8305270094*	50-395 Q
ANG, W P	8305270315*	50-389 Q
ANG, W P	8305270389*	50-261 Q
APICELLA, F L	8305110100	50-331 P
APICELLA, F L	8305110549	50-331 P
APPEL, R R	8305130281	40-8728
ARAND, J.	8305060401*	50-373 S
ARAND, J J	8305020353*	50-373 S
ARAND, J J	8305240354	50-373 S
ARCHITZEL	8305060530	50-317 S
ARCHITZEL, R E	8305030208*	50-317 Q
ARENDTS, J Q	8305110467	NUREG
ARMSTRONG, A B	8305090510*	50-445 T
ARNOLD, R C	8305090351	50-289 P
ARTHUR, J M	8305230387	50-334 P
ASH, R E	8305260294	50-317 P
ASHBURN, D. J	8305160084	50-89 J
ASHE, F.	8305230430	50-213 S
ASHE, F	8305230441*	50-213 S
ASHE, F	8305230531*	MISC
ASHE, F S	8305050341	50-269 S
ASHE, F S.	8305050353*	50-269 S
ASHTON, A M	8305110545*	CONTRACT
ASSELSTINE, J K	8305230453*	50-289 U
AU, T. Y	8305120278	50-352 Q
AU, T Y	8305120280*	50-352 Q
AUGER, J C	8305120317*	50-320 T
AULUCK, R	8305250261	50-397 A
AUSTIN, Q	8305120016*	50-295 R
AUTIO, H A	8305030590	50-29 S
AUTIO, H A	8305050263	50-29 S
AXELRAD, J	8305030405	50-250 S
AXELRAD, J	8305030468	I&E
AXELRAD, J	8305090184	50-271 Q
AXELRAD, J	8305090224	50-280 Q
AXELRAD, J	8305090397	50-272 Q
AXELRAD, J	8305190079	50-309 Q
AXELRAD, J	8305240439	I&E
AXELRAD, J A	8305200291	50-263 Q
AXELRAD, J A	8305200294	50-315 Q
AXELRAD, J A	8305200303	50-269 Q
AXELRAD, J A	8305200338	70-25
AXELRAD, J A	8305270164	50-272 Q
AXELRAD, J A	8305270216	50-254 Q
AXELRAD, M	8305180404	PR
AXELSON, W L	8305100090*	50-346 Q
AXELSON, W L	8305270614*	50-346 Q
AXELSON, W L	8305310181*	50-331 Q
BACHMANN, R Q	8305100314	50-266 Q
BACHMANN, R Q	8305240513	50-155 Q
BACHMANN, R Q	8305270020	50-155 Q
BACKUS, R A	8305190199	50-443 Q
BACKUS, R A	8305190199	50-443 Q
BAER, J W	8305250394*	50-483 Q
BAER, J W	8305250394*	50-483 Q
BAER, J W	8305250496*	50-483 Q
BAER, J W	8305250496*	50-483 Q
BAER, J W	8305250511*	50-483 Q
BAER, J W	8305250511*	50-483 Q
BAER, J W	8305250589*	50-483 Q
BAER, J W	8305250589*	50-483 Q
BAER, D	8305030018	XPORTLIC
BAER, D	8305030056*	XPORTLIC
BAER, R E	8305240005*	50-445 Q
BAILEY	8305110439	50-286 S
BAILEY, R. J	8305050190*	50-247 Q
BAIR, G Q	8305130152*	50-344 S
BAISDEN, L	8305230159	CONTRACT
BALALIS, C Q	8305020021	XPORTLIC
BALL, M J	8305090696	WASTE MGT
BALLARD, T A	8303240487*	50-313 P
BALLARD, T A	8303240495*	50-313 P
BANGART, R L	8305020281	TOPREP
BANGART, R L	8305020342	MISC
BANGART, R L	8305030520	GA999
BANGART, R L	8305090209	ORG
BARAN, R	8305230437*	50-219 R
BARBER, Q	8305090184	50-271 Q
BARBER, Q	8305190079	50-309 Q
BARHAM, C D	8305160045	50-261 J
BARHAM, C D	8305160135	50-324 J

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
BARI, R A	8305110237	NUREG	
BARKER, N R	8305110313	50-395	S
BARKER, N R	8305110322	50-395	S
BARKER, R F	8305020063*	FOIA	
BARNER, I	8305090485*	QA999	
BARNES, I	8305030351*	QA999	
BARNES, I	8305030366*	QA999	
BARNES, I	8305030475*	QA999	
BARNES, I	8305030525*	QA999	
BARNES, I	8305050071*	QA999	
BARNES, I	8305050093*	QA999	
BARNES, I	8305050097*	QA999	
BARNES, I	8305050110*	QA999	
BARNES, I	8305050111*	QA999	
BARNES, I	8305050149*	QA999	
BARNES, I	8305050179*	QA999	
BARNES, I	8305050241*	QA999	
BARNES, I	8305200379*	QA999	
BARNES, I	8305200678*	QA999	
BARNES, I	8305240462*	QA999	
BARNES, I	8305270286*	QA999	
BARNES, I	8305270307*	QA999	
BARNES, I	8305270311*	QA999	
BARNETT, J E	8305120011	70-1621	
BARR, K	8305030164*	50-320	Q
BARR, K	8305160199*	50-289	Q
BARR, K P	8305270121*	50-302	Q
BARR, K P	8305270231*	50-261	Q
BARR, K P	8305270265*	50-280	Q
BARR, K P	8305270322*	50-327	Q
BARR, K P	8305270325*	50-62	Q
BARR, K P	8305270357*	50-321	Q
BARR, K P	8305270384*	50-250	Q
BARR, K P	8305270428*	50-369	Q
BARR, K P	8305270458*	50-395	Q
BARR, K P	8305270469*	50-111	Q
BARR, K P	8305270518*	50-269	Q
BARR, K P	8305270534*	50-338	Q
BARR, K P	8305270576*	50-335	Q
BARR, K P	8305270666*	50-259	Q
BARR, K P	8305270668*	50-259	Q
BARRETT, L H	8305040163	50-320	R
BARRETT, L H	8305040170	50-320	R
BARRETT, L H	8305040686	50-320	P
BARRETT, L H	8305060668	50-320	R
BARRETT, L H	8305240561	50-320	R
BARRETT, L H	8305240603	50-320	R
BARRETT, P A	8305260231*	50-358	Q
BARTH, C A	8305190231	50-400	G
BARTH, C A	8305240077	50-400	T
BARTKO, J	8305020292*	50-266	P
BARTON, J E	8305050426	NUREG	
BARTON, J J	8305040580*	50-320	F
BASKIN, K P	8305020427	50-206	P
BASKIN, K P	8305170278	50-361	S
BASKIN, K P	8305170471	50-361	F
BASKIN, K P	8305190028	50-361	P
BASKIN, K P	8305240198	50-206	F
BASKIN, K P	8305240498	50-361	P
BASKIN, K P	8305240501	50-206	P
BASKIN, K P	8305240509	50-206	P
BASKIN, K P	8305250512	50-206	P
BASS, G W	8305100036*	50-260	S
BASS, G W	8305100292*	50-260	S
BASS, G W	8305250508	50-296	S
BASSIN, N	8305020049*	FOIA	
BASSIN, N	8305020196*	FOIA	
BASSIN, N	8305020200*	FOIA	
BASSIN, N	8305020323*	FOIA	
BASSIN, N	8305020505*	FOIA	
BASSIN, N	8305030047*	FOIA	
BASSIN, N	8305030098*	FOIA	
BASSIN, N	8305030339*	FOIA	
BASSIN, N.	8305040266*	FOIA	
BASSIN, N	8305040376*	FOIA	
BASSIN, N	8305040579*	FOIA	
BASSO, L F	8305190352*	50-318	S
BASSO, L F	8305230528*	50-318	S
BATEMAN, W H	8305160091*	50-354	Q
BATES, J W	8305270145*	70-1151	
BATES, J W	8305270254*	70-1201	
BAUBLITZ, J E	8305110138	WASTE MGT	
BAUER, E Q	8305030307*	50-352	A
BAUER, T L.	8305100005	50-192	P
BAUM, A	8305270035*	50-320	P
BAUNACK, W H	8305250453*	50-244	Q
BAUNACK, W H	8305250504*	50-213	Q
BAUSER, D B	8305100310	50-289	Q
BAUSER, D B	8305100310	50-289	Q
BAUSER, D B	8305250448*	50-483	Q
BAUSER, D B	8305250448	50-483	Q
BAUSER, D B	8305250451*	50-483	Q
BAUSER, D B	8305250451*	50-483	Q
BAUSER, D B	8305250461*	50-483	Q
BAUSER, D B	8305250461*	50-483	Q
BAUSER, D B	8305250463*	50-483	Q
BAUSER, D B	8305250463*	50-483	Q
BAUSER, D B	8305250474*	50-483	Q
BAUSER, D B	8305250474*	50-483	Q
BAUSER, D B	8305250477*	50-483	Q
BAUSER, D B	8305250477*	50-483	Q
BAXTER, T A	8305030467	50-483	Q
BAXTER, T A	8305030467	50-483	Q
BAXTER, T A	8305030591	50-289	Q
BAXTER, T A	8305030591	50-289	Q
BAXTER, T A	8305100283	50-289	Q
BAXTER, T A	8305100283	50-289	Q
BAXTER, T A	8305100357	50-289	Q
BAXTER, T A	8305100357	50-289	Q
BAXTER, T A	8305110266	50-483	Q
BAXTER, T A	8305130099	50-312	Q
BAXTER, T A	8305130099	50-312	Q
BAXTER, T A	8305170450	50-400	Q
BAXTER, T A	8305170450	50-400	Q
BAXTER, T A	8305170497	50-400	Q
BAXTER, T A	8305170497	50-400	Q
BAXTER, T A	8305190249	50-483	Q
BAXTER, T A	8305190249	50-483	Q
BAXTER, T A	8305250205	50-483	Q
BAXTER, T A	8305250205	50-483	Q
BAXTER, T A	8305250294	50-483	Q
BAXTER, T A	8305250294	50-483	Q
BAXTER, T A	8305250297*	50-483	Q
BAXTER, T A	8305250297*	50-483	Q
BAXTER, T A	8305250300*	50-483	Q
BAXTER, T A	8305250300*	50-483	Q
BAXTER, T A	8305250346*	50-483	Q
BAXTER, T A	8305250346*	50-483	Q
BAXTER, T A	8305250351*	50-483	Q
BAXTER, T A	8305250351*	50-483	Q
BAXTER, T A	8305250358*	50-483	Q
BAXTER, T A	8305250358*	50-483	Q
BAXTER, T A	8305250359*	50-483	Q
BAXTER, T A	8305250359*	50-483	Q
BAXTER, T A	8305250383*	50-483	Q
BAXTER, T A	8305250383*	50-483	Q
BAXTER, T A	8305250388*	50-483	Q
BAXTER, T A	8305250388*	50-483	Q
BAXTER, T A	8305250401*	50-483	Q
BAXTER, T A	8305250401*	50-483	Q
BAXTER, T A	8305250403*	50-483	Q
BAXTER, T A	8305250403*	50-483	Q
BAXTER, T A	8305250412*	50-483	Q
BAXTER, T A	8305250412*	50-483	Q
BAXTER, T A	8305250419*	50-483	Q
BAXTER, T A	8305250419*	50-483	Q
BAXTER, T A	8305250440*	50-483	Q
BAXTER, T A	8305250440*	50-483	Q
BAXTER, T A	8305250444*	50-483	Q
BAXTER, T A	8305250444*	50-483	Q
BAXTER, T A	8305250486*	50-483	Q
BAXTER, T A	8305250486*	50-483	Q
BAXTER, T. A	8305250490*	50-483	Q
BAXTER, T A	8305250490*	50-483	Q
BAXTER, T. A	8305250502*	50-483	Q
BAXTER, T A	8305250502*	50-483	Q
BAXTER, T A	8305250506*	50-483	Q
BAXTER, T. A	8305250506*	50-483	Q
BAXTER, T A	8305250515*	50-483	Q
BAXTER, T. A	8305250515*	50-483	Q
BAXTER, T A	8305250521*	50-483	Q
BAXTER, T A	8305250521*	50-483	Q
BAXTER, T A	8305250524*	50-483	Q
BAXTER, T A	8305250524*	50-483	Q
BAXTER, T A	8305250531*	50-483	Q
BAXTER, T A	8305250540*	50-483	Q
BAXTER, T. A	8305250540*	50-483	Q
BAXTER, T. A	8305250542*	50-483	Q
BAXTER, T A	8305250542*	50-483	Q
BAXTER, T. A	8305250553*	50-483	Q
BAXTER, T A	8305250553*	50-483	Q
BAXTER, T A	8305250557*	50-483	Q
BAXTER, T A	8305250557*	50-483	Q
BAXTER, T A	8305250559*	50-483	Q
BAXTER, T A	8305250559*	50-483	Q
BAXTER, T A	8305250562*	50-483	Q
BAXTER, T A	8305250562*	50-483	Q
BAXTER, T A	8305250583*	50-483	Q
BAXTER, T A	8305250583*	50-483	Q
BAXTER, T A	8305250584*	50-483	Q
BAXTER, T A	8305250584*	50-483	Q
BAXTER, T A	8305260164	50-483	Q
BAXTER, T A	8305260164	50-483	Q
BAXTER, T A	8305260168	50-483	Q
BAXTER, T A	8305260168	50-483	Q
BAXTER, T A	8305260173*	50-483	Q
BAXTER T A	8305310170	50-483	Q
BAY, J H	8305050041	50-142	H
BAYNARD, P Y	8305240359	50-302	P
BAYNARD, P Y	8305270092	50-302	P
BAYNARD, P Y	8305270295	50-302	Q
BAYNE, J D	8305240529	50-286	P
BAYNE, J P	8305020209	50-333	P
BAYNE, J P	8305020381	50-286	P
BAYNE, J P	8305030409	50-286	P
BAYNE, J P	8305040311	50-333	P
BAYNE, J P	8305040424	50-333	P
BAYNE, J P	8305040434*	50-333	P
BAYNE, J P	8305050026	50-333	P
BAYNE, J P	8305050037	50-247	Q
BAYNE, J P	8305060397	50-286	P
BAYNE, J P	8305060427	50-286	P
BAYNE, J P	8305060431	50-286	P
BAYNE, J P	8305060432*	50-286	P
BAYNE, J P	8305060439	50-286	P
BAYNE, J P	8305060446*	50-286	P
BAYNE, J P	8305060496	50-247	Q
BAYNE, J P	8305060500	50-286	Q
BAYNE, J P	8305100360	50-333	S
BAYNE, J P	8305110053	50-286	P
BAYNE, J P.	8305110058*	50-286	P
BAYNE, J P	8305110167	50-286	Q
BAYNE, J P	8305130039	50-286	P
BAYNE, J P	8305130117	50-286	P
BAYNE, J P	8305160106	50-333	P
BAYNE, J P	8305200265	50-333	P
BAYNE, J P	8305200268*	50-333	P
BAYNE, J P	8305200405	50-286	P
BAYNE, J P	8305230375	50-333	F
BAYNE, J P	8305240090	50-286	P
BAYNE, J. P	8305240099	50-286	F
BAYNE, J P	8305240234	50-286	F
BAYNE, J P	8305240328	50-286	P
BAYNE, J P	8305240338	50-286	F
BAYNE, J P	8305240349	50-286	P
BAYNE, J. P	8305240442	50-333	P
BAYNE, J P	8305240463	50-333	P
BAYNE, J P	8305240492	50-333	P
BAYNE, J P	8305270284*	50-333	Q
BAYNE, J P	8305270340	50-333	P
BAYNE, J P	8305270352*	50-333	P
BAZIN, J	8305120142	CONTRACT	
BAZIN, J	8305230245	CONTRACT	
BAZIN, J	8305230256	CONTRACT	
BEACH, A B	8305090660*	50-445	Q
BEACH, A. B	8305120155*	50-445	Q
BEACH, A B	8305130021*	50-445	Q
BEACH, Q	8305060226	40-8380	
BEACH, Q.	8305160211	40-8584	
BEACH, Q	8305160274	40-8380	
BEAVER, J R.	8305040580*	50-320	F
BECHHOEFER, C	8305130045	50-498	Q
BECHHOEFER, C.	8305200511	50-498	Q
BECHHOEFER, C	8305240472	50-329	Q
BECHHOEFER, C	8305270606	50-329	Q
BECK, J. W.	8305200575*	50-329	A
BECKER, B D.	8305110215	50-454	Q
BECKER, B D	8305110215	50-454	Q
BECKHAM, D H	8211030191*	50-312	Q
BECKHAM, J T	8305030634	50-321	F
BECKHAM, J. T	8305270336*	50-321	Q
BECKHAM, J T.	8305310073	50-366	Q
BECKHAM, J T	8305310084*	50-366	Q
BECKHAM, J. T	8305310092*	50-366	Q
BEHAN, J L	8305180260*	50-322	V

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
BELANGER, J L	8305020397*	50-255	G
BELANGER, J. L	8305060418*	50-295	G
BELIBLE, G A	8305270356*	50-321	G
BELIBLE, G A	8305270442*	50-338	G
BELIBLE, G A	8305270594*	50-335	G
BELL, N	8305100263	50-460	G
BELL, N	8305240347	50-460	G
BELL, N	8305310005	50-460	G
BELL, N E	8305060233	NUREG	
BELLAMY, R R	8305020340	50-317	G
BELLAMY, R. R	8305250560	50-213	G
BELTZ, I L.	8305100369*	50-438	A
BEMIS, P	8305270308*	50-400	G
BEMIS, P	8305270401*	50-261	G
BEMIS, P.	8305270506*	50-261	G
BEMIS, P	8305270631*	50-400	G
BEMIS, P.	8305270635*	50-324	G
BENAIT, W. R	8305020525*	FOIA	
BENNER, R G	8305160301	XPORTLIC	
BENNER, R G	8305160303*	XPORTLIC	
BENNER, R. G	8305160305*	XPORTLIC	
BENOIT, W R	8103130267*	FOIA	
BENTON, J	8305090592*	50-445	G
BERGDOLL, T. E.	8305120150*	CONTRACT	
BERGDOLL, T. E	8305200134*	CONTRACT	
BERGIN, J. M	8305270239	50-336	S
BERLIN, K.	8305160032	50-529	G
BERLIN, K.	8305160034	50-529	G
BERLIN, K	8305160080	50-529	G
BERLIN, K	8305160080	50-529	G
BERLIN, K	8305160086	50-529	G
BERLIN, K	8305160086	50-529	G
BERMAN, P G	8305030087*	FOIA	
BERMAN, P. G	8305040674*	70-378	
BERMAN, P. G	8305040696*	70-378	
BERNABEI, L	8305190216	50-329	G
BERNABEI, L	8305190216	50-329	G
BERNABEI, L	8305260166	50-329	G
BERNABEI, L	8305260166	50-329	G
BERNARD, H	8305170100	50-225	P
BERNARD, H	8305170114	50-112	P
BERNHOFT, S. L	8305100397*	50-305	S
BERNHOFT, S L	8305270198	50-305	S
BERRY, Z. E	8305100253*	50-251	S
BERRY, Z E.	8305110496*	50-250	S
BESS, J. E.	8305230314*	50-458	G
BEVERLY, K	8305310149	50-237	S
BEVERLY, K P	8305310158	50-237	S
BEYER, B R	8305060702*	50-346	F
BIDA, G. T	8305020547	NUREG	
BIDINGER, G H	8305030077*	70-1257	
BIDINGER, G. H.	8305250607*	70-371	
BIELAWSKI, A P	8305060461	50-599	G
BIELAWSKI, A P	8305060461	50-599	G
BIELAWSKI, A P	8305170297	50-454	G
BIELAWSKI, A P	8305170297	50-454	G
BIELAWSKI, A P	8305170565	50-454	G
BIELAWSKI, A P	8305170565	50-454	G
BIER, J	8305040542*	50-155	G
BIER, J	8305040543*	50-155	G
BIGBEE, D	8305200691*	50-373	P
BILANIN, A. J	8305130104*	50-271	P
BIMBER, R M	8305170464	50-440	G
BIRCH, M L.	8305200440*	50-369	P
BIRKEL, R A	8303300370	50-369	P
BIRKEL, R A	8305030675	50-369	S
BISCHOFF, C A	8305240482	50-529	G
BISHOP, L L.	8305030541	50-443	G
BISHOP, L L	8305030541	50-443	G
BISHOP, L. L	8305040449	50-329	G
BISHOP, L L	8305040449	50-329	G
BISHOP, L. L	8305060382	PR	
BISHOP, L. L	8305180356	PR	
BISHOP, R. W	8305020093	50-245	I
BISHOP, T W	8305020183	50-361	S
BISHOP, T. W	8305170332	50-275	G
BISHOP, T. W	8305170359	50-361	G
BISHOP, T. W.	8305170363	50-206	G
BISHOP, T. W.	8305170417	50-361	G
BISHOP, T. W	8305170474	50-361	G
BISHOP, T W	8305240393*	50-275	G
BISHOP, T W	8305260257	50-275	G
BISSETT, P.	8305250505*	50-289	G
BLACKMON, T G	8305130155*	50-373	F
BLAKE, E L	8305180277	50-289	G
BLAKE, E L	8305180277	50-289	G
BLAKE, J J.	8305200588	50-259	S
BLAKE, J J	8305270094*	50-395	G
BLAKE, J J	8305270244*	50-338	G
BLAKE, J J	8305270269*	50-302	G
BLAKE, J J	8305270276*	50-324	G
BLAKE, J J	8305270315*	50-389	G
BLAKE, J J	8305270339*	50-335	G
BLAKE, J J	8305270342*	50-324	G
BLAKE, J J	8305270389*	50-261	G
BLAKE, J J	8305270402*	50-369	G
BLAKE, J J	8305270406*	50-400	G
BLAKE, J J	8305270478*	50-395	G
BLAKE, J J	8305270492*	50-400	G
BLAKE, J J	8305270537*	50-438	G
BLAKE, J J	8305270574*	50-280	G
BLAKE, J J.	8305270657*	50-390	G
BLOCH, P B	8305090560	50-445	G
BLOCK, J. D	8305240527	50-247	G
BLOND, R. M	8305310210	NUREG	
BLOSSOM, J N	8305020363	40-8452	
BLOUGH	8305020337	50-278	S
BLOUGH	8305030118	50-278	S
BLOUGH	8305120412	50-277	S
BLOUNT, D H	8305260341*	CONTRACT	
BLUBAUGH, R E	8305130362	40-3453	
BODGEN, G	8305250175	40-1162	
BOERGERS, M	8305180439*	50-170	U
BOGARDUS, R H.	8305240530	50-247	G
BOGART, D	8305130047*	50-302	R
BOGDEN, G	8305020407	40-1162	
BOGER, B. A	8305170054*	50-289	G
BOHL, L S	8305020365*	GA999	
BOHL, L S	8305020369*	GA999	
BOHM, M P	8305130355	50-537	D
BOLIN, R	8305270048*	50-320	P
BOLON, A E	8305030375	50-123	R
BOLON, A E	8305310006	50-123	P
BOMBERGER, C	8305230284*	50-213	P
BOMBERGER, C	8305310241*	50-285	P
BOOK, H E	8305100416*	50-237	G
BOOK, H E	8305160029	50-142	G
BOOK, H E	8305160067	70-754	
BOOK, H E	8305160078*	70-754	
BOOK, H E.	8305170335	50-397	G
BOOK, H E	8305170343*	50-397	G
BOOK, H E	8305170496	50-275	G
BOOK, H E	8305170501*	50-275	G
BOOK, H E	8305170530*	50-361	G
BOOK, H E	8305170562	50-344	G
BOOK, H E	8305170567*	50-344	G
BOOK, H E	8305260269	40-8137	
BOOK, H E	8305260273*	40-8137	
BOOKER, J. E	8305030422	50-458	S
BOOKER, J E	8305060435	50-458	S
BOOKER, J. E	8305060475	50-458	S
BOOKER, J E.	8305100198	50-458	A
BOOKER, J E	8305120321	50-458	S
BOOKER, J E	8305120343	50-458	G
BOOKER, J E	8305120367	50-458	S
BOOKER, J E	8305120409	50-458	S
BOOKER, J E	8305120413	50-458	S
BOOKER, J E	8305120424	50-458	S
BOOKER, J E	8305170281	50-458	S
BOOKER, J E	8305170385	50-458	S
BOOKER, J E	8305170479	50-458	S
BOOKER, J E	8305200151	50-458	S
BOOKER, J E	8305200264	50-458	S
BOOKER, J E	8305200390	50-458	S
BOOKER, J E	8305230009*	50-458	F
BOOKER, J. E	8305230438	50-458	S
BOOKER, J. E	8305230462	50-458	S
BOOKER, J. E	8305240468	50-458	S
BOOKER, J. E	8305260268	50-458	S
BOOKER, J E.	8305260299	50-458	S
BOOKER, J E	8305260318	50-458	S
BOOKER, J. E	8305310042	50-458	S
BOOKER, J. E	8305310102	50-458	I
BOOTH, L. F	8305110509*	CONTRACT	
BORDENICK, B M	8305030488	50-322	G
BORDENICK, B M	8305090129	50-322	G
BORDENICK, B M	8305090136*	50-322	G
BORDENICK, B M	8305100196	50-322	G
BORDENICK, B M	8305100222	50-322	G
BORDENICK, B M	8305100223	50-322	G
BORDENICK, B M	8305100224	50-322	G
BORDENICK, B M	8305100238	50-322	G
BORDENICK, B M	8305100239*	50-322	G
BORDENICK, B M	8305100255	50-322	G
BORDENICK, B M	8305100380	50-322	G
BORDENICK, B M	8305100398	50-322	G
BORDENICK, B M	8305200590	50-322	G
BORDENICK, B M	8305250373	50-322	G
BORDINE, T C	8305020294	50-155	P
BORDINE, T C	8305130215	50-155	G
BORDINE, T C	8305190317	50-155	G
BORDINE, T. C	8305230044	50-155	G
BORGMANN, E A	8305030528	50-358	K
BORGMANN, E A	8305170454*	50-358	G
BORGMANN, E A	8305170553*	50-358	A
BORGMANN, E A	8305190168	50-358	A
BORGMANN, E A	8305190278	50-358	A
BORGMANN, E A	8305190314*	50-358	A
BORGMANN, E A	8305240012*	50-358	G
BORGMANN, E A	8305240016*	50-358	G
BORN, C L	8305090510*	50-445	T
BOSNAK, R J	8305130040*	50-445	G
BOTHMAN, J	8304200001	TOPREP	
BOUCHEY, G D	8305030166	50-460	K
BOUCHEY, G D	8305040565	TOPREP	
BOUCHEY, G D	8305050159	50-397	G
BOUCHEY, G. D	8305100097	50-508	A
BOUCHEY, G. D	8305100110	50-397	A
BOUCHEY, G. D	8305100246	50-460	K
BOUCHEY, G. D	8305100304	50-508	A
BOUCHEY, G. D	8305120233	50-397	K
BOUCHEY, G D	8305160041	50-397	E
BOUCHEY, G. D	8305170156	50-397	A
BOUKNIGHT, R J	8305200633*	50-395	S
BOUKNIGHT, R J	8305250349	50-395	S
BOUQUARD, M L	8305230664*	COMMISSION	
BOURNIA, A	8305190299*	FOIA	
BOWDEN, T J	8305240481	50-348	I
BOWMAN, M E	8305030388*	50-318	S
BOYD, D C	8305020348*	50-315	G
BOYD, D C	8305100271*	50-295	G
BOYD, D C	8305170174*	50-155	G
BOYD, D C	8305200247*	50-255	G
BOYD, D C	8305240037*	50-255	G
BOYD, D C	8305240309*	50-315	G
BOYER, V S	8305060513	50-277	G
BOYER, V S	8305100359	50-277	F
BRADBURY, R B	8305180383	PR	
BRADBURY, R B	8305180454	PR	
BRADBURY, R B	8305250406	PR	
BRADBURY, R B	8305270003	PR	
BRADFORD, L	8305100212	50-289	G
BRADFORD, P A	8006090443*	50-498	A
BRADFORD, P A	8305180121*	50-498	A
BRADFORD, P A	8305180175*	50-498	G
BRADFORD, W H	8305270370*	50-348	G
BRADHAM, A S	8305050321*	50-395	F
BRADLEY, E J	8301310260	50-352	K
BRADLEY, E J	8305020255	50-352	E
BRADLEY, E J	8305020454	50-352	E
BRADLEY, E J	8305030299	50-352	A
BRADLEY, E J	8305030307*	50-352	A
BRADLEY, E J	8305050021	50-277	P
BRADLEY, E J	8305050027*	50-277	P
BRADLEY, E J	8305060457	50-352	A
BRADLEY, E J	8305120320	50-352	A
BRADLEY, E J	8305130096	50-353	A
BRADLEY, E J	8305170187	50-352	A
BRADLEY, E J	8305170228	50-352	E
BRADLEY, E J	8305180343	50-352	A
BRADLEY, E J	8305180389	50-352	E
BRADLEY, E J	8305180402	50-352	A
BRADLEY, E J	8305180414	50-352	E
BRADLEY, E J	8305180419	50-352	A
BRADLEY, E J	8305180432	50-352	A
BRADLEY, E J	8305180451	50-352	E
BRADLEY, E J	8305190359	50-352	C
BRADLEY, E J	8305200615	50-352	E
BRADLEY, E J	8305230496	50-352	A
BRADLEY, E J	8305240307	50-277	J
BRADLEY, E J	8305250133	50-352	A
BRADLEY, E J.	8305270375	50-352	A
BRADLEY, E J	8305310009	50-352	E
BRADLEY, E J	8305310045	50-352	E

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
BRAEGER, C B	8305200688*	50-373 P
BRANDENBURG, B	8305020428	50-247 G
BRANDENBURG, B	8305030583	50-247 G
BRANDENBURG, B	8305040505	50-247 G
BRANDENBURG, B	8305100208	50-247 G
BRANDENBURG, B	8305130064	50-247 G
BRANDENBURG, B	8305130071	50-247 G
BRANDENBURG, B	8305240527	50-247 G
BRANDI, V A	8305200549	50-322 S
BRANNEN, J	8305180459*	50-322 H
BRANNEN, J	8305180461*	50-322 H
BRANNIN, J P	8305170250*	50-335 S
BRANSCOME, J M	8305170601	40-3453
BREADY, J C	8305180308	FOIA
BREAKEY, T	8305260180	50-155 G
BRENIZER, J S	8305230548	50-396 P
BRENIZER, J S	8305270226*	50-62 G
BRENNAN, P J	8305240517	50-247 H
BRENNER, L	8305020390	50-322 G
BRENNER, L	8305040429	50-322 G
BRENNER, L	8305060459	50-322 G
BRENNER, L	8305090505	50-322 G
BRENNER, L	8305170538	50-352 G
BRENNER, L	8305180136	50-352 G
BRENNER, L	8305240432	50-322 G
BRENNER, L	8305240460	50-322 G
BRENNER, L	8305250334	50-322 G
BRENNER, L	8305270563	50-322 G
BRENNER, L	8305270595	50-322 T
BREWSTER, A	8305190201*	50-155 P
BREY, H L	8305020462	50-267 P
BREY, H L	8305160048	50-267 P
BREY, H L	8305160053	50-267 P
BREY, H L	8305170380	50-267 P
BREY, H L	8305240477	50-267 P
BRICKS, G	83051300B6*	50-244 P
BRIDEN, D W	8303060702*	50-346 F
BRIGGS, L	8305110508*	50-333 G
BRIGGS, L	8305250443*	50-245 G
BRIGHT, G O	8305030582	50-142 G
BRIGHT, G O	8305060520	50-142 G
BRIGHT, G O	8305100330	50-142 G
BRIGHT, G O	8305130076	50-142 G
BRIGHT, G O	8305130079	50-142 G
BRIGHT, G O	8305130150	50-142 G
BRIGHT, G O	8305160163	50-142 G
BRINKMAN, D S	8305060568*	50-447 E
BRIXEY, P	8305190181*	50-293 S
BROBST, G E	8305190290*	50-317 S
BROCK, B L	8305160078*	70-754
BROMBERG, B.	8305050385	CONTRACT
BROMET, E J.	8305270022	50-320 P
BROMET, E J.	8305270027*	50-320 P
BROOKS, E H	8305270306*	50-416 G
BROOKS, J	8305230695*	COMMISSION
BROPHY, J J	8305190349	50-407 P
BROUGHTON, J. M	8305110523	NUREG
BROWN, C. H	8305200611*	50-263 G
BROWN, E. J	8305050341	50-269 S
BROWN, E. J	8305050353*	50-269 S
BROWN, E J.	8305230573	50-237 S
BROWN, E. J	8305230619*	50-237 S
BROWN, G D	8305030297	70-846
BROWN, G. D	8305030499	40-299
BROWN, G. D	8305120479	40-8027
BROWN, H H	8305060518	50-322 G
BROWN, H H	8305060518	50-322 G
BROWN, H. H	8305120300*	50-322 G
BROWN, H H	8305120300*	50-322 G
BROWN, J. M	8305030255*	70-378
BROWN, R. L.	8305050163*	50-458 G
BROWN, S D.	8305250271*	50-289 P
BROWNE, W G	8305120251*	40-672
BROWNE, W G	8305120274*	40-672
BROWNING, R E	8305090588	WASTE MGT
BROWNING, R E	8305090643	WASTE MGT
BROWNING, R E	8305090656	WASTE MGT
BROWNING, R E	8305090675	WASTE MGT
BROWNLEE, V L	8305270328*	50-424 G
BROWNLEE, V L.	8305270337*	50-424 G
BROWNLEE, V L	8305270338*	50-269 G
BROWNLEE, V L	8305270462*	50-395 G
BROWNLEE, V L	8305270482*	50-537 G
BROWNLEE, V L	8305270525*	50-302 G
BROWNLEE, V L	8305270550*	50-366 G
BROYHILL, J T	8305230703	50-289 U
BRUNE, R L	8305060675	NUREG
BRUNNER, E J	8305240488	50-219 R
BRUNNER, E J	8305240510	50-244 R
BRUNNER, J E	8305240322	50-329 G
BRUTSCH, W A	8305100309	50-213 F
BRYANT, D	8305200656	50-440 G
BRYANT, J	8305270338*	50-269 G
BRYANT, J	8305270411*	50-269 G
BRYANT, J C	8109040024	50-269 S
BUCK, C R	8305270130	State Prog
BUCKLES, J	8305160026	50-315 J
BUCKLEY, B	8305060312*	50-389 P
BUDNITZ, R J	8305180353	PR
BUDWANI, R N	8305170701	50-461 A
BUDZIK, D M	8305240137	50-329 K
BUFE, J L	8305050025*	50-302 S
BUFE, J L	8305170402*	50-302 S
BULLINGTON, R L	8305040284*	CONTRACT
BUPP, L P	8305090388*	GA999
BURCH, R H	8305020319*	GA999
BURCHETT, R R	8305090162	NUREG
BURDOIN, J	8305170564*	50-528 G
BURDOIN, J F	8305170390*	50-508 G
BURDOIN, J F	8305170537*	50-528 G
BURGE, C A	8305130309*	50-272 F
BURGER, F J	8305170607*	50-271 R
BURKE, A R	8305040425*	FOIA
BURKE, D J	8305270439*	50-280 G
BURKE, D J	8305270490*	50-280 G
BURKE, S	8305250025	FOIA
BURKE, T J.	8305060164*	FOIA
BURNETT, P. T	8305270470*	50-416 G
BURNETT, P. T	8305270521*	50-369 G
BURNS, S G	8305180315*	50-498 A
BURSTEIN, S	8305060408	50-266 P
BURSTEIN, S.	8305110075	50-266 P
BURSTEIN, S	8305110181	50-266 P
BURSTEIN, S	8305110201	50-266 P
BURSTEIN, S	8305120408	50-266 G
BURSTEIN, S	8305170144*	50-266 G
BURSTEIN, S	8305230724	50-266 P
BURTON, J W	8305310054	50-296 S
BURWELL, S.	8305090578*	50-445 G
BURWELL, S. B	8305090600*	50-445 G
BURWELL, S. B	8305120109	50-445 A
BURWELL, S. B	8305160244*	50-445 G
BUSCHBACH, T C	8305170121	NUREG
BUSH, M W	8305160174	50-352 G
BUSH, M. W	8305240316	50-352 H
BUSH, S H	8305130359	50-537 G
BUSH, S. H	8305130359	50-537 G
BUSHNELL, T E	8305130232*	50-344 S
BUTCHER, R C	8305110399	50-395 S
BUTCHER, R C	8305200588	50-259 S
BYRD, R.	8305050178*	50-416 S
BYRD, R.	8305130200*	50-416 S
BYRD, R.	8305170431*	50-416 S
BYRD, R.	8305170433*	50-416 S
BYRD, R.	8305200286*	50-416 S
BYRD, R	8305250579	50-416 S
BYRD, R	8305310204	50-416 S
BYRON, P M	8305020285*	50-341 G
CADMAN, W K	8305230570*	50-482 I
CADMAN, W K	8305270058	50-482 A
CAHILL, W J	8305170468	50-458 K
CAIN, J	8305060319	WASTE MGT
CAIN, J.	8305260356	WASTE MGT
CAIN, J.	8305260360	WASTE MGT
CALDWELL, R A	8305030308*	70-846
CALKINS, D E	8305190112*	50-329 S
CALLAN, L J	8304150154*	50-313 G
CALLISON, R L	8305020070*	FOIA
CAMP, M J	8305240370*	50-315 S
CAMPAGNA, J H	8305020015*	FOIA
CAMPAGNA, J H	8305020567*	FOIA
CAMPAGNA, J H	8305040211*	FOIA
CAMPAGNA, J. H.	8305040224*	FOIA
CAMPBELL, E	8305190361*	MISC
CAMPBELL, M	8305040192	I&E
CAMPBELL, M	8305040201	I&E
CAMPBELL, S E	8305200222	PR
CANTER, H L	8305170421*	50-361 G
CANTRELL, F S	8305110399	50-395 S
CANTRELL, F S	8305270370*	50-348 G
CANTRELL, F S	8305270381*	50-259 G
CANTRELL, F S	8305270439*	50-416 G
CANTRELL, F S	8305270496*	50-518 G
CANTRELL, F S	8305270502*	50-395 G
CANTWELL, P F	8305060572*	50-295 S
CANTWELL, P F	8305310160	50-304 S
CAPHTON, D L	8305230460*	50-289 G
CAPHTON, D L	8305250306*	50-277 G
CAREY, J J	8305020359	50-334 P
CAREY, J J	8305060604	50-334 P
CAREY, J J	8305060609*	50-334 P
CAREY, J J	8305100268	50-334 G
CAREY, J J	8305100337	50-334 P
CAREY, J. J	8305110360	50-334 P
CAREY, J J	8305110424	50-334 R
CAREY, J. J	8305200439*	50-334 G
CAREY, J J	8305240401	50-334 P
CAREY, J J	8305240404	50-334 G
CAREY, J J	8305250516	50-334 P
CAREY, J J.	8305270187	50-334 P
CARFAGNO, P	8209210332*	50-336 P
CARLISLE, C. S	8305030300	50-397 S
CARLISLE, C S	8305030324	50-397 A
CARLISLE, C S	8305030500	50-397 S
CARLISLE, C S	8305030507	50-397 S
CARLISLE, C S	8305130106	50-397 S
CARLISLE, C S	8305130245	50-397 R
CARLISLE, R W	8305310002	50-247 T
CARLSON, J	8305240393*	50-275 G
CARLSON, J D	8305170339*	50-275 G
CARLSON, J. D	8305260262*	50-275 G
CARLSON, R T	8305120397*	GA999
CARLSON, R T	8305120656*	70-925
CARNEY, J	8305110012	PR
CARNEY, J	8305250517	PR
CARR, A V	8305090468	50-413 G
CARR, A V	8305100282	50-413 G
CARR, A V	8305100342	50-413 G
CARR, A V.	8305100415	50-413 G
CARR, A V	8305310025	50-413 G
CARROW, H.	8305040479	50-400 G
CARROW, H	8305040485*	50-400 G
CARROW, H.	8305040492*	50-400 G
CARROW, H	8305040498*	50-400 G
CARROW, H	8305060471	50-400 G
CARROW, H	8305130075	50-400 G
CARROW, H	8305130088	50-400 G
CARROW, H.	8305240446	50-400 G
CARROW, H	8305240551	50-400 G
CARTEAUX, P.	8305120399*	50-315 S
CARTEAUX, P	8305170444*	50-315 S
CARTEAUX, P	8305170451*	50-316 S
CARUSO, R.	8305020561	50-322 R
CARUSO, R	8305190491	50-322 A
CARVER, A M	8305030579*	50-327 S
CARVER, A. M	8305050128*	50-327 S
CARVER, A. M.	8305050217*	50-328 S
CASE, E G	8305170110*	50-272 S
CASELLI, A E	8305230176*	71-496
CASSELL, A	8305200720*	50-338 P
CATTON, I	8305130321	ACRS
CAUDLE, R. E	8305180684	71-9150
CAVANAGH, R.	8305170272	50-522 G
CAVANAGH, R	8305170272	50-522 G
CAVANAGH, R	8305170272	50-522 G
CAVANAGH, R.	8305170272	50-522 G
CAVANAGH, R	8305170272	50-522 G
CAVANAGH, R	8305170279	50-522 G
CAVANAGH, R	8305170347	50-522 G
CAVANAUGH, W	8305170290	50-382 H
CAVANAUGH, W	8305200451*	50-313 S
CERBONE, R J	8305110237	NUREG
CERNE, A	8305110299	50-443 S
CERNE, A. C	8305050119*	50-443 G
CESARE, G.	8305240260*	50-416 P
CHACKES, K M	8305100257	50-483 G
CHAFFEE, A E.	8305170421*	50-361 G
CHAMBERLAIN, D	8305020307*	GA999
CHAMBERLAIN, D	8305030474*	50-483 G
CHAMBERLAIN, D	8305240435*	GA999
CHAMBERLAIN, D.	8305270149*	GA999
CHAN, E. I	8305160146	50-546 G
CHAN, E. I.	8305160158	50-546 G
CHAN, E I.	8305170003	50-546 G
CHANDLER, J. C.	8305030292	TOPREP

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
CHANDLER, L J	8305100199	50-361	G
CHANDLER, L J	8305100220	50-361	G
CHANDLER, L J	8305160127	50-275	G
CHANDRA, U	8305230292*	50-537	A
CHANG, G	8305200598	50-440	G
CHAPLIN, S D	8305030535*	50-320	S
CHAPLIN, S D	8305110378*	50-320	S
CHAPLIN, S D	8305310004*	50-320	S
CHAPLIN, S D	8305310007*	50-320	S
CHAPLIN, S D	8305310010*	50-320	S
CHAPLIN, S D	8305310014*	50-320	S
CHAPLIN, S D	8305310019*	50-320	S
CHAPLIN, S D	8305310024*	50-320	S
CHAPLIN, S D	8305310030*	50-320	S
CHAPLIN, S D	8305310036*	50-320	S
CHAPLIN, S D	8305310041*	50-320	S
CHAPLIN, S D	8305310047*	50-320	S
CHAPLIN, S D	8305310056*	50-320	S
CHAPLIN, S D	8305310066*	50-320	S
CHAPLIN, S D	8305310072*	50-320	S
CHAPLIN, S D	8305310087*	50-320	S
CHAPLIN, S D	8305310091*	50-320	S
CHAPLIN, S D	8305310096*	50-320	S
CHAPLIN, S D	8305310101*	50-320	S
CHAPLIN, S D	8305310107*	50-320	S
CHAPLIN, S D	8305310114*	50-320	S
CHARNLEY, J. E	8305060055*	50-321	P
CHARNLEY, J S	8305060076*	50-331	P
CHARNLEY, J B.	8305090483	TOPREP	
CHARNLEY, J B	8305100370*	50-325	P
CHARNLEY, J. B	8305270378*	50-333	P
CHEATHAM, J. R	8305040256*	FOIA	
CHEN, C	8305060277*	50-244	P
CHEN, S	8305200720*	50-338	P
CHEN, W. P	8305090578*	50-445	G
CHEN, W P	8305230449*	50-445	G
CHIANGI, N J	8305030601	50-400	S
CHIANGI, N. J	8305110252	50-400	S
CHICK, D E	8305020482	50-443	G
CHICK, D E	8305020486*	50-443	G
CHILK, S	8305230333*	PR	
CHILK, S J.	8304040470	50-277	G
CHILK, S. J.	8305030522	50-445	G
CHILK, S. J.	8305030532	50-70	G
CHILK, S J	8305040068*	50-289	G
CHILK, S. J.	8305040436	50-358	G
CHILK, S. J.	8305050015	50-445	G
CHILK, S J	8305060274	50-498	G
CHILK, S J	8305060696	10CFR	
CHILK, S. J.	8305090516*	10CFR	
CHILK, S J	8305100299	50-289	G
CHILK, S. J	8305110581*	PR	
CHILK, S. J.	8305120309	50-247	G
CHILK, S. J.	8305130055	70-143	
CHILK, S. J.	8305130061	50-277	G
CHILK, S. J.	8305130068	50-322	G
CHILK, S. J.	8305160130	50-289	G
CHILK, S J.	8305160167	50-247	G
CHILK, S J.	8305170488	40-2061	
CHILK, S. J.	8305170493	50-272	G
CHILK, S J	8305180148*	50-498	A
CHILK, S. J.	8305180167*	50-498	G
CHILK, S. J	8305180189*	50-498	G
CHILK, S. J	8305200481	50-373	G
CHILK, S J.	8305200488	50-528	G
CHILK, S. J.	8305200525	50-358	G
CHILK, S. J.	8305200548	50-155	G
CHILK, S. J.	8305200554	50-445	G
CHILK, S. J.	8305200560	50-277	G
CHILK, S. J	8305200570	40-2061	
CHILK, S. J.	8305230425*	COMMISSION	
CHILK, S. J.	8305240190*	COMMISSION	
CHILK, S J.	8305240522	50-361	G
CHILK, S J.	8305240523	50-247	G
CHILK, S. J.	8305240566	50-3	T
CHILK, S. J.	8305250256	10CFR	
CHILK, S. J.	8305250308*	GEN TEC	IB
CHILK, S. J.	8305250324	50-289	G
CHILK, S. J.	8305250590*	50-289	P
CHILK, S J.	8305260174	50-397	G
CHILK, S. J.	8305260176	50-498	G
CHILK, S. J.	8305260178	50-556	G
CHILK, S. J.	8305310008	50-272	G
CHILK, S. J.	8305310011	50-445	G
CHILK, S. J.	8305310015	50-498	G
CHILK, S J	8305310017	50-277	G
CHILK, S J	8305310018	50-358	G
CHILK, S J	8305310021	50-155	G
CHIRAMAL, M	8305230531*	MISC	
CHO, F L	8305190303*	50-373	P
CHOULES, N C	8305260334*	50-373	G
CHRISSOTIMOS, N	8305310112*	50-254	G
CHRISTA-MARIA	8305040542*	50-155	G
CHRISTEL, B	8305310165	50-237	S
CHRISTIANSON, W	8305260231*	50-358	G
CHRISTMAN, J N	8305040461	50-322	G
CHRISTMAN, J N	8305040461	50-322	G
CHRISTMAN, J N	8305130077	50-322	G
CHRISTMAN, J N	8305130077	50-322	G
CHRISTMAN, J N	8305160006	50-322	G
CHRISTMAN, J N	8305160006	50-322	G
CHRISTOFFER, G	8305020397*	50-255	G
CHRISTOFFER, G	8305040445	50-331	S
CHURCHILL, B W	8305020438	50-266	G
CHURCHILL, B W	8305020438	50-266	G
CHURCHILL, B W	8305170291	50-266	G
CHURCHILL, B W	8305170291	50-266	G
CHWASTYK, J J	8305120323*	50-320	T
CILIMBERG, R L	8304150364*	50-440	G
CILIMBERG, R L	8305120420*	50-373	G
CILLIS, M	8305170367*	50-344	G
CINGUEMANI, D	8305240537	50-247	H
CINTULA, T C	8305040146	50-318	S
CINTULA, T C	8305040150*	50-318	S
CLARDY, L B	8305100218*	50-331	G
CLARK, A T	8305260393	PROJ	
CLARK, D G	8305030333*	50-254	S
CLARK, L	8305090315*	MISC	
CLARK, L	8305160043	50-20	S
CLARK, R.	8305160192	50-312	G
CLARK, R. A	8303240026	50-309	P
CLARK, R. A.	8305020600	50-309	P
CLARK, R A	8305020602	50-335	P
CLARK, R A	8305040789*	50-317	P
CLARK, R A	8305040795*	50-317	P
CLARK, R A	8305060001	50-266	P
CLARK, R. A	8305060013	50-282	P
CLARK, R A	8305060017	50-338	P
CLARK, R A	8305060023	50-282	P
CLARK, R A.	8305060039	50-335	P
CLARK, R A	8305060042	50-309	P
CLARK, R A	8305060045	50-317	P
CLARK, R. A	8305060058	50-336	P
CLARK, R A	8305060065	50-338	P
CLARK, R. A.	8305060077	50-317	F
CLARK, R. A	8305060108	50-282	P
CLARK, R A.	8305060120*	50-338	P
CLARK, R. A	8305060140*	50-338	P
CLARK, R. A	8305060666	50-344	P
CLARK, R A	8305060669*	50-344	P
CLARK, R. A	8305060670*	50-344	P
CLARK, R A	8305090144	50-338	P
CLARK, R A	8305090460*	50-245	P
CLARK, R. A	8305090546	50-266	P
CLARK, R A	8305110128	50-335	P
CLARK, R A	8305110169*	50-368	P
CLARK, R A	8305110193	50-313	P
CLARK, R. A	8305110199*	50-313	P
CLARK, R. A.	8305110205*	50-313	P
CLARK, R. A.	8305110224*	50-336	P
CLARK, R A.	8305110540	50-266	F
CLARK, R A.	8305110625	50-313	P
CLARK, R. A.	8305120153*	50-335	P
CLARK, R A	8305120498*	50-266	P
CLARK, R. A.	8305120504	50-313	P
CLARK, R. A	8305120506*	50-313	P
CLARK, R. A	8305130010	50-338	P
CLARK, R. A	8305130017*	50-338	P
CLARK, R A.	8305160188	50-213	P
CLARK, R. A.	8305160201	50-309	P
CLARK, R A.	8305170259*	50-317	P
CLARK, R. A.	8305170612	50-309	P
CLARK, R. A.	8305170619	50-301	P
CLARK, R A	8305170622	50-313	P
CLARK, R. A	8305170657	50-282	F
CLARK, R. A.	8305180036*	50-368	P
CLARK, R A.	8305180161	50-313	F
CLARK, R. A.	8305180567	50-335	P
CLARK, R. A.	8305180579*	50-317	P
CLARK, R. A.	8305180849	50-313	P
CLARK, R A	8305200021	50-266	
CLARK, R A	8305200023	50-282	
CLARK, R A	8305200030	50-344	
CLARK, R A	8305200060	50-285	
CLARK, R A	8305200068	50-309	G
CLARK, R A	8305200078	50-317	
CLARK, R A	8305200081	50-336	
CLARK, R A	8305200090	50-335	
CLARK, R A	8305200094	50-338	
CLARK, R A	8305200710*	50-338	
CLARK, R A	8305230128	50-313	
CLARK, R A	8305310240	50-285	
CLARK, R J	8303300387	50-260	
CLARK, W M	8305250304*	50-483	G
CLARK, W M	8305250304*	50-483	G
CLARK, W M	8305250304*	50-483	G
CLARK, W M	8305250354*	50-483	G
CLARK, W M	8305250354*	50-483	G
CLARK, W M	8305250354*	50-483	G
CLARK, W M	8305250536*	50-483	G
CLARK, W M	8305250536*	50-483	G
CLARK, W M	8305250536*	50-483	G
CLARK, W M	8305250587*	50-483	G
CLARK, W M	8305250587*	50-483	G
CLAY, E L	8305270159*	70-1113	
CLAYTON, F L	8305020456	50-348	
CLAYTON, F L	8305030580	50-364	
CLAYTON, F L	8305050148	50-348	
CLAYTON, F L	8305050195	50-348	
CLAYTON, F L	8305100132	50-364	
CLAYTON, F L	8305110257	50-364	
CLAYTON, F L	8305110308	50-348	
CLAYTON, F L	8305160094	50-348	
CLAYTON, F L	8305200306	50-348	
CLAYTON, F L	8305200357	50-364	
CLAYTON, F L	8305200579	50-348	
CLAYTON, F L	8305230540	50-348	
CLAYTON, F L	8305240191	50-348	
CLAYTON, F L	8305240440	50-348	
CLAYTON, F L	8305250285	50-348	
CLAYTON, F L	8305250353	50-348	
CLAYTON, F L	8305250391	50-348	
CLAYTON, F. L	8305250581	50-348	
CLAYTON, F. L	8305310201	50-348	
CLEMONS, P	8305110320*	50-309	G
CLEMONS, P	8305190191*	50-271	G
CLINE, W. E	8305270427*	50-416	G
CLINE, W E	8305270446*	50-395	G
COCHRAN, T B	8305100276	50-537	G
COEN, R.	8305240366	50-249	
COFFEY, J A	8305030501	50-259	
COFFEY, J A.	8305250402	50-259	
COFFMAN, F. D	8305090607*	50-445	G
COGAN, N	8305250505*	50-289	G
COGAN, N J	8305230460*	50-289	G
COHEN, L A	8305090425	50-247	
COHEN, W S	8305310239*	50-309	
COLBURN, T G	8305120495	50-266	
COLEMAN, R	8305090291	CONTRACT	
COLEMAN, R	8305110229	CONTRACT	
COLEMAN, R C	8305260081	CONTRACT	
COLEY, J L	8305270179*	50-389	G
COLEY, J L	8305270276*	50-324	G
COLEY, J. L	8305270342*	50-324	G
COLEY, J L	8305270657*	50-390	G
COLLIER, A R	8305170302	TOPREP	
COLLINS, D. J	8305110267*	50-277	G
COLLINS, D. L	8305270035*	50-320	G
COLLINS, J T	8305030435*	50-285	G
COLLINS, J T.	8305060466	State Pro	
COLLINS, J. T	8305090479	QA999	
COLLINS, J. T.	8305100086	State Pro	
COLLINS, J. T	8305100303	50-482	
COLLINS, J T	8305120035*	FOIA	
COLLINS, J T	8305120045*	FOIA	
COLLINS, J T	8305120052*	FOIA	
COLLINS, J. T	8305120056*	FOIA	
COLLINS, J. T	8305120062*	FOIA	
COLLINS, J. T	8305120065*	FOIA	
COLLINS, J. T	8305190374*	FOIA	
COLLINS, J. T	8305200285	50-382	
COLLINS, J. T	8305200320	State Pro	
COLLINS, J. T.	8305240431	QA999	
COLLINS, J. T	8305270144	QA999	
COLLINS, B.	8305200497	50-272	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
COLLINS, S J	8305250431*	50-29	Q
COLLINS, T R	8305270322*	50-327	Q
COLLINS, T R	8305270428*	50-369	Q
COLLINS, T R	8305270518*	50-269	Q
COLLINS, T R	8305270666*	50-259	Q
COLLINS, W E	8305260308	50-129	W
COLOMBO, R	8305240326	50-312	R
COLOMBO, R W	8305030290*	50-312	S
COLOMBO, R W	8305030561*	50-312	S
COLOMBO, R W	8305130231*	50-312	S
COMBS, F	8305020191*	FOIA	
COMBS, F	8305030249*	70-378	
COMBS, F	8305030684*	FOIA	
COMBS, F	8305040310*	FOIA	
COMBS, F	8305050355*	FOIA	
COMBS, F C	8305020306*	FOIA	
COMBS, F C	8305020318*	FOIA	
COMBS, F C	8305030201*	70-378	
COMBS, F C	8305040484*	FOIA	
COMER, M K	8305110491	NUREG	
COMPTON, N	8305030437	PR	
CONLEY, C H	8305110476	NUREG	
CONLON, T E,	8305260243*	50-440	Q
CONLON, T E	8305270101*	50-389	Q
CONLON, T E	8305270200*	50-537	Q
CONLON, T E,	8305270236*	50-389	Q
CONLON, T E	8305270293*	50-389	Q
CONLON, T E	8305270348*	50-400	Q
CONLON, T E	8305270379*	50-389	Q
CONLON, T E	8305270404*	50-413	Q
CONLON, T E	8305270415*	50-438	Q
CONLON, T E	8305270420*	50-390	Q
CONLON, T E	8305270542*	50-389	Q
CONLON, T E	8305270551*	50-400	Q
CONLON, T E	8305270618*	50-438	Q
CONLON, T E	8305270632*	50-400	Q
CONNAUGHTON, K	8305100176*	50-454	Q
CONNER	8305190072	50-219	S
CONNER, E. L	8305090078	50-269	P
CONRAN, J	8305050295*	50-247	P
CONTE, R.	8305030094	50-289	S
CONTE, R	8305030534	50-289	S
CONTE, R.	8305160199*	50-289	Q
CONTE, R J	8305230460*	50-289	Q
CONWAY, B.	8305180378	PR	
CONWAY, J T	8305020466	50-529	Q
CONWAY, J T	8305050093*	GA999	
CONWAY, J T	8305200379*	GA999	
CONWAY, J. T	8305270311*	GA999	
COOK, G S.	8305160122	50-440	Q
COOK, J	8305130134*	50-333	R
COOK, J W	8305020398	50-329	E
COOK, J W	8305030111	50-329	R
COOK, J W	8305060483	50-329	A
COOK, J W	8305090052	50-329	R
COOK, J W	8305110305	50-329	E
COOK, J W	8305130182*	50-329	Q
COOK, J W	8305170283	50-329	S
COOK, J W	8305170391	50-329	S
COOK, J W	8305170409	50-329	S
COOK, J W	8305170440	50-329	S
COOK, J W	8305170489	50-329	S
COOK, J W	8305170539	50-329	A
COOK, J W	8305200349	50-329	S
COOK, J W	8305200680	50-329	S
COOK, J W	8305240008*	50-329	Q
COOK, J W	8305240010	50-329	S
COOK, J W	8305240565*	50-155	P
COOK, J W	8305260218	50-329	S
COOK, J W	8305260235	50-329	S
COOK, J W	8305260309	50-330	S
COOK, J W	8305260324	50-329	S
COOK, J W	8305270057	50-329	K
COOK, J W	8305270063*	50-329	K
COOK, R J	8305100217	50-329	T
COONEY, M J	8305110316	50-277	S
COONEY, M J	8305110340	50-278	S
COONEY, M J	8305110349*	50-278	S
COONEY, M J	8305120358	50-277	S
COONEY, M J	8305120473	50-277	S
COOPER, W E	8305050299	50-275	R
COOPER, W. E	8305180395	50-275	R
COOPER, W E	8305200358	50-275	R
COOPER, W E	8305270296	50-275	P
COOPER, W E	8305270305*	50-275	P
COOPER, W E	8305270317	50-275	P
COPELAND, V Q	8305110141	50-155	Q
CORMIER, W	8305170067*	50-142	Q
CORMIER, W H	8305030524	50-142	Q
CORMIER, W H	8305030568	50-142	Q
CORMIER, W H	8305030574	50-142	Q
CORMIER, W H	8305090473	50-142	Q
CORMIER, W H	8305240479	50-142	Q
CORMIER, W H	8305240499	50-142	Q
CORREN, D	8305250223	50-247	Q
CORYELL, Q P	8305130173	70-143	
CORYELL, Q P	8305270304*	50-332	Q
CORYELL, Q P	8305270480*	70-1151	
CORYELL, Q P	8305270556*	70-27	
CORYELL, Q P	8305270648*	70-143	
COSS, B W	8305190002	70-2932	
COSTELLO, F M	8305120623*	40-672	
COTTA, R E	8305120074*	50-358	Q
COTTER, B P	8305030548	50-458	Q
COTTER, B P	8305130050	50-322	Q
COTTER, B P	8305130110	50-508	Q
COTTER, K H	8305030412*	50-286	P
COTTER, K. H	8305060407*	50-286	P
COTTER, K H	8305060417*	50-286	P
COTTER, K H	8305200412*	50-286	P
COUCH, M J	8305160316*	50-247	Q
COUNSIL, W Q	8304110686	50-213	Q
COUNSIL, W Q	8305020399*	50-213	Q
COUNSIL, W Q	8305030404	50-245	P
COUNSIL, W Q	8305030404	50-245	P
COUNSIL, W Q	8305030620	50-245	P
COUNSIL, W Q	8305030620	50-245	P
COUNSIL, W Q	8305040034*	50-245	F
COUNSIL, W Q	8305040447	50-336	P
COUNSIL, W Q	8305040447	50-336	P
COUNSIL, W Q	8305050054	50-213	P
COUNSIL, W Q	8305050054	50-213	P
COUNSIL, W Q	8305050054	50-213	P
COUNSIL, W Q	8305050112	50-213	P
COUNSIL, W Q	8305050229	50-245	P
COUNSIL, W Q	8305050229	50-245	P
COUNSIL, W Q	8305060213	50-213	F
COUNSIL, W Q	8305060213	50-213	F
COUNSIL, W Q	8305060244	PR	
COUNSIL, W. Q	8305060244	PR	
COUNSIL, W Q	8305060424	50-336	Q
COUNSIL, W Q	8305060424	50-336	Q
COUNSIL, W Q	8305060455	50-423	S
COUNSIL, W Q	8305060455	50-423	S
COUNSIL, W Q	8305090404	50-213	P
COUNSIL, W Q	8305090465	50-213	P
COUNSIL, W Q	8305090465	50-213	P
COUNSIL, W Q	8305090465	50-213	P
COUNSIL, W. Q	8305090471	50-245	P
COUNSIL, W Q	8305090471	50-245	P
COUNSIL, W Q	8305100331	50-213	P
COUNSIL, W Q	8305100368	50-245	P
COUNSIL, W Q	8305100368	50-245	P
COUNSIL, W Q	8305100385	50-213	P
COUNSIL, W Q	8305110069	50-213	F
COUNSIL, W Q	8305110574*	50-213	F
COUNSIL, W Q	8305110574*	50-213	F
COUNSIL, W Q	8305110574*	50-213	F
COUNSIL, W. Q	8305120241	50-336	P
COUNSIL, W. Q	8305120241	50-336	P
COUNSIL, W Q	8305160183	50-213	P
COUNSIL, W Q	8305170213	50-213	F
COUNSIL, W Q	8305180268	50-245	P
COUNSIL, W Q	8305180268	50-245	P
COUNSIL, W Q	8305180304	50-245	F
COUNSIL, W Q	8305180304	50-245	P
COUNSIL, W Q	8305190305	50-213	Q
COUNSIL, W Q	8305200441	PR	
COUNSIL, W Q	8305200533	50-423	S
COUNSIL, W Q	8305200533	50-423	S
COUNSIL, W Q	8305200587	50-423	A
COUNSIL, W Q	8305230323	50-245	F
COUNSIL, W Q	8305230323	50-245	F
COUNSIL, W Q	8305230508	50-336	P
COUNSIL, W Q	8305230508	50-336	P
COUNSIL, W Q	8305230616	50-213	P
COUNSIL, W Q.	8305230616	50-213	P
COUNSIL, W. Q	8305230616	50-213	P
COUNSIL, W Q	8305250510	50-213	P
COUNSIL, W Q	8305250510	50-213	P
COUNSIL, W Q	8305250565*	50-213	Q
COUNSIL, W Q	8305270036	50-423	S
COUNSIL, W Q	8305270036	50-423	S
COUNSIL, W Q	8305270037*	50-423	Q
COUNSIL, W Q	8305270037*	50-423	Q
COUNSIL, W Q	8305270074	50-336	Q
COUNSIL, W Q	8305270074	50-336	Q
COUNSIL, W Q	8305270114	50-245	P
COUNSIL, W Q	8305270114	50-245	P
COUNTS, M	8305050321*	50-395	F
COWGILL, C	8305190266*	50-219	Q
COX, H T	8305110256*	50-261	S
COX, H T	8305250423	50-261	S
COYLE, L M	8305060594*	50-249	S
COYLE, L M	8305060611*	50-237	S
CRAGIN, J G	8305270317	50-275	P
CRANE, P A	8305020108	50-133	F
CRANE, P A	8305030188*	50-275	F
CRANE, P A	8305030510	50-275	P
CRANE, P. A.	8305040320	50-275	P
CRANE, P A	8305040328*	50-275	P
CRANE, P A.	8305050198	50-275	P
CRANE, P A	8305060299	50-323	Q
CRANE, P. A	8305120042	50-275	P
CRANE, P A.	8305120325	50-275	P
CRANE, P A	8305120333	50-275	P
CRANE, P A	8305160172	50-275	P
CRANE, P. A	8305190157	50-275	F
CRANE, P A	8305240238	50-275	R
CRANE, P A.	8305240375	50-275	P
CRANE, P A	8305260274*	50-275	Q
CRANE, P A	8305270622	50-275	Q
CRANE, P A	8305310130	50-275	P
CRANE, P A	8305310135*	50-275	P
CRAWFORD, V A	8305030594	50-529	Q
CRAWFORD, V. A	8305030594	50-529	Q
CREED, J	8305040445	50-331	B
CREED, J	8305270152	50-255	B
CREED, J R	8305020397*	50-255	Q
CREED, J R	8305030521*	50-264	Q
CREED, J. R	8305060418*	50-295	Q
CREED, J. R	8305100365*	50-156	Q
CREED, J R	8305100371*	50-156	Q
CREED, J R	8305130234*	70-1308	
CREED, J. R	8305200482*	70-925	
CREWS, J L	8305030075	50-361	Q
CREWS, J L	8305030200*	50-275	P
CREWS, J. L.	8305160089	50-528	Q
CREWS, J L	8305170531	50-528	Q
CRLENJAK, R V	8305270550*	50-366	Q
CROCKER, H W.	8305050151*	50-293	Q
CROCKER, H W	8305120493*	40-672	
CROCKER, H. W	8305120500*	40-672	
CROCKER, H W.	8305240232*	50-29	Q
CROCKER, L P	8305170044*	50-289	Q
CROCKER, L. P	8305230460*	50-289	Q
CROSBIE, K L	8305230026	70-1359	
CROSBIE, K. L	8305230035*	70-1359	
CROSS, R. W.	8305120250*	50-281	P
CROSSMAN, W A.	8305050163*	50-459	Q
CROSSMAN, W. A	8305100142*	50-458	Q
CROSSMAN, W. A	8305170009*	50-382	Q
CROSSMAN, W A	8305170224*	50-498	Q
CROSSMAN, W A	8305230314*	50-458	Q
CROUSE, R P.	8305040305	50-346	P
CROUSE, R P.	8305040472	50-346	P
CROUSE, R. P.	8305040491	50-346	P
CROUSE, R. P.	8305040497*	50-346	P
CROUSE, R. P.	8305060395	50-346	P
CROUSE, R P	8305060519	50-346	Q
CROUSE, R P.	8305110385	50-346	P
CROUSE, R P	8305110437	50-346	P
CROUSE, R. P.	8305130032	50-346	P
CROUSE, R. P	8305170462	50-346	P
CROUSE, R P	8305180411	50-346	P
CROUSE, R. P.	8305200337*	50-346	Q
CROUSE, R. P.	8305200514*	50-346	Q
CROUSE, R. P.	8305200520*	50-346	Q
CROUSE, R. P.	8305200527*	50-346	Q
CROUSE, R P.	8305200592	50-346	P
CROUSE, R. P	8305230716	50-346	P
CROUSE, R. P.	8305240072*	50-346	Q
CROUSE, R. P.	8305240251	50-346	P
CROUSE, R P.	8305240351	50-346	P
CROUSE, R P	8305240423	50-346	P

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
CROUSE, R P	8305260241	50-346	P
CROUSE, R P	8305260245*	50-346	P
CROUSE, R P	8305260303	50-346	Q
CROW, W T	8305030074	70-1257	
CROW, W T	8305110117	40-8035	
CROWDER, J D	8305190029*	50-293	S
CROWE, J	8305250372*	50-483	Q
CROWE, J	8305250372*	50-483	Q
CROWLEY, B. R	8305270339*	50-335	Q
CRUTCHFIELD, D	8305020060	50-244	P
CRUTCHFIELD, D	8305020066	50-255	P
CRUTCHFIELD, D	8305020121	50-245	P
CRUTCHFIELD, D	8305020499	50-244	P
CRUTCHFIELD, D	8305040166	50-155	P
CRUTCHFIELD, D	8305040312	50-255	P
CRUTCHFIELD, D	8305040474	50-219	P
CRUTCHFIELD, D	8305040488	50-237	P
CRUTCHFIELD, D	8305040526	50-29	P
CRUTCHFIELD, D	8305040537*	50-155	Q
CRUTCHFIELD, D	8305040540*	50-155	Q
CRUTCHFIELD, D	8305060228*	50-206	P
CRUTCHFIELD, D	8305060234*	50-206	P
CRUTCHFIELD, D	8305060372	50-206	P
CRUTCHFIELD, D	8305060381*	50-206	P
CRUTCHFIELD, D	8305060385*	50-206	P
CRUTCHFIELD, D	8305090426	50-245	P
CRUTCHFIELD, D	8305090436*	50-245	P
CRUTCHFIELD, D	8305090463*	50-245	P
CRUTCHFIELD, D	8305090488	50-213	P
CRUTCHFIELD, D	8305090491*	50-213	P
CRUTCHFIELD, D	8305090492*	50-213	P
CRUTCHFIELD, D	8305110009	50-219	F
CRUTCHFIELD, D	8305110049	50-29	F
CRUTCHFIELD, D	8305110059	50-206	F
CRUTCHFIELD, D	8305110067	50-155	F
CRUTCHFIELD, D.	8305110074	50-255	F
CRUTCHFIELD, D	8305120116	50-10	F
CRUTCHFIELD, D	8305120370	50-237	P
CRUTCHFIELD, D	8305160022	50-213	F
CRUTCHFIELD, D	8305160250	50-155	Q
CRUTCHFIELD, D	8305170369	50-155	F
CRUTCHFIELD, D	8305170416	50-409	F
CRUTCHFIELD, D	8305180292	50-155	P
CRUTCHFIELD, D	8305180433	50-219	P
CRUTCHFIELD, D	8305190016	50-409	F
CRUTCHFIELD, D	8305200200	50-255	Q
CRUTCHFIELD, D	8305200452	50-409	Q
CRUTCHFIELD, D	8305230276	50-213	P
CRUTCHFIELD, D	8305240490	50-29	P
CRUTCHFIELD, D	8305260082	50-409	P
CRUTCHFIELD, D	8305270002	50-409	P
CRUTCHFIELD, D	8305270007	50-255	F
CRUTCHFIELD, D	8305270060	50-244	P
CRUTCHFIELD, D.	8305270077	50-244	F
CRUTCHFIELD, D	8305310028	50-237	P
CRUTCHFIELD, D	8305310046	50-255	F
CRUTCHFIELD, D.	8305310108	50-219	P
CRUTCHFIELD, D	8305310150	50-206	S
CRUTCHFIELD, D	8305310213	50-219	P
CULLEN, W. H.	8305240015	NUREG	
CULVER, M W	8305130047*	50-302	R
CUMINGS, E	8305200598	50-440	Q
CUMMINGS, J.	8305240267*	50-358	Q
CUMMINGS, J. J.	8108250739*	COMMISSION	
CUMMINGS, J. J.	8305180178*	FOIA	
CUMMINGS, J. J.	8305240263*	50-358	Q
CUMMINS, J. E.	8304150154*	50-313	Q
CUNNINGHAM, A L.	8305270354*	50-302	Q
CUNNINGHAM, A L.	8305270528*	50-259	Q
CUNNINGHAM, G E.	8305020050	70-1007	
CUNNINGHAM, G E	8305020520	70-754	
CUNNINGHAM, G H.	8305100214	50-409	Q
CUNNINGHAM, R.	8305020027*	FOIA	
CUOMO, M. M.	8305130204*	50-322	Q
CUOMO, M. M	8305310070*	50-247	U
CURRAN, D.	8305030541	50-443	Q
CURRAN, D.	8305160002	50-443	Q
CURRAN, D	8305160002	50-443	Q
CURRAN, D.	8305160019	50-443	Q
CURRAN, D.	8305160019	50-443	Q
CURRAN, D	8305180363	PR	
CURRAN, R. N	8305200637*	50-373	P
CURRAN, R. N	8305200691*	50-373	P
CURTIS, N. W	8305020387	50-387	P
CURTIS, N. W.	8305030144	50-387	P
CURTIS, N W	8305030153*	50-387	P
CURTIS, N W	8305060543	50-387	Q
CURTIS, N W	8305100308	50-387	P
CURTIS, N W	8305110097	50-387	K
CURTIS, N W	8305130114	50-387	P
CURTIS, N W	8305180646	70-2983	
CURTIS, N W	8305190285	50-387	P
CURTIS, N W	8305190295	50-387	P
CURTIS, N W	8305190319	50-387	S
CURTIS, N W	8305230541	50-387	P
CURTIS, N W	8305270064	50-387	P
CURTIS, N W	8305310208	50-387	P
CUTCHIN, J M	8305020477	50-440	Q
CUTCHIN, J M	8305030326	50-440	T
CUTCHIN, J M	8305090487	50-440	Q
CUTCHIN, J M	8305100168	50-440	Q
D'AMORE, M	8305270459*	70-1151	
D'AMOURS, N E	8305130087	50-443	Q
DALE, L F	8304190378	50-416	P
DALE, L F.	8305110275	50-416	S
DALE, L F.	8305110418	50-416	S
DALE, L F.	8305190015	50-416	J
DALE, L. F.	8305240143	50-416	P
DALE, L F.	8305240265*	50-416	P
DALE, L F.	8305240496	50-416	P
DALTROFF, S L	8305020099	50-277	P
DALTROFF, S. L	8305050027*	50-277	P
DALTROFF, S L	8305170401	50-277	P
DALTROFF, S L	8305240428	50-277	P
DALZELL, G W	8305240517	50-247	H
DANCE, H C	8305030374	50-491	S
DANCE, H C	8305130138	50-321	S
DANCE, H C	8305200430	50-335	S
DANCE, H C	8305200556	50-369	Q
DANCE, H C	8305270098	50-389	Q
DANCE, H C	8305270112	50-302	Q
DANCE, H C	8305270146	50-369	Q
DANCE, H. C	8305270154	50-369	Q
DANCE, H C	8305270176	50-389	Q
DANCE, H C	8305270197	50-537	Q
DANCE, H C	8305270209	50-302	Q
DANCE, H. C.	8305270215	50-250	Q
DANCE, H C	8305270232	50-389	Q
DANCE, H C	8305270238	50-338	Q
DANCE, H. C	8305270240	50-389	Q
DANCE, H C	8305270242	50-280	Q
DANCE, H C	8305270247	50-302	Q
DANCE, H C	8305270252*	50-280	Q
DANCE, H C	8305270260*	50-302	Q
DANCE, H C	8305270273	50-537	Q
DANCE, H. C.	8305270287	50-335	Q
DANCE, H. C.	8305270289	50-389	Q
DANCE, H C	8305270310	50-389	Q
DANCE, H C	8305270314	50-537	Q
DANCE, H C	8305270320	50-424	Q
DANCE, H C	8305270324	50-413	Q
DANCE, H C	8305270326	50-269	Q
DANCE, H C.	8305270327	50-369	Q
DANCE, H. C.	8305270329	50-335	Q
DANCE, H C	8305270330	50-424	Q
DANCE, H. C.	8305270332	50-321	Q
DANCE, H C.	8305270343*	50-321	Q
DANCE, H. C	8305270347	50-302	Q
DANCE, H. C.	8305270350	50-321	Q
DANCE, H C.	8305270359	50-335	Q
DANCE, H C	8305270374	50-269	Q
DANCE, H. C.	8305270376	50-250	Q
DANCE, H C	8305270382*	50-369	Q
DANCE, H C	8305270385	50-369	Q
DANCE, H. C.	8305270393	50-413	Q
DANCE, H C	8305270403	50-269	Q
DANCE, H C.	8305270414	50-338	Q
DANCE, H C	8305270423	50-280	Q
DANCE, H C	8305270435*	50-269	Q
DANCE, H C	8305270447	50-389	Q
DANCE, H C.	8305270449*	50-395	Q
DANCE, H. C	8305270456	50-302	Q
DANCE, H. C	8305270472	50-537	Q
DANCE, H. C.	8305270483	50-280	Q
DANCE, H C	8305270491	50-366	Q
DANCE, H C	8305270497	50-269	Q
DANCE, H C.	8305270511	50-369	Q
DANCE, H C.	8305270517	50-338	Q
DANCE, H C.	8305270523*	50-366	Q
DANCE, H C	8305270530	50-338	Q
DANCE, H C	8305270561	50-335	
DANCE, H C	8305270565	50-280	
DANCE, H. C	8305270568	50-251	
DANCE, H C	8305270570	50-321	
DANCE, H C	8305270590	50-413	
DANIELS, R G	8305020031*	FOIA	
DANIELS, R G	8305020042*	FOIA	
DANIELS, R G	8305030125*	FOIA	
DANIELS, R G	8305030142*	FOIA	
DANIELS, R G	8305030147*	FOIA	
DANIELS, R. G	8305030154*	FOIA	
DANIELS, R. G	8305030174*	FOIA	
DANIELS, R. G	8305030179*	FOIA	
DANIELS, R G	8305040279*	FOIA	
DANIELS, R G	8305040554*	FOIA	
DANIELS, R G	8305040562*	FOIA	
DANIELS, R G	8305050297*	70-378	
DANIELS, R G	8305050306*	70-378	
DANIELS, R G	8305050316*	70-378	
DANIELS, R G	8305050322*	70-378	
DANIELS, R. G	8305050330*	70-378	
DANIELSON, D H	8304150364*	50-440	
DANIELSON, D H	8305020360*	50-331	
DANIELSON, D H	8305120348*	50-461	
DANIELSON, D H	8305120420*	50-373	
DANIELSON, D H	8305120449*	50-237	
DANIELSON, D H	8305190027*	50-454	
DANIELSON, D H	8305190183*	50-255	
DANIELSON, D H	8305190233	50-454	
DAVIS, A B	8305190184*	50-373	
DAVIS, A B	8305190232*	FOIA	
DAVIS, A B	8305190276*	FOIA	
DAVIS, A B	8305190399*	50-373	
DAVIS, F X.	8305170314	50-454	
DAVIS, F X	8305170319	50-454	
DAVIS, F X	8305170334	50-454	
DAVIS, F X	8305170522	50-454	
DAVIS, J G	8305200634*	REVIEW G	
DAVIS, M J	8305270439*	50-280	
DAVIS, M J	8305270490*	50-280	
DAVIS, P R	8305160246	50-295	
DAVIS, P R	8305160246	50-295	
DAVISSON, M T.	8305160332*	50-367	
DE AGAZIO, A W	8305170669	50-346	
DEANDA, L	8305200656	50-440	
DEB, A K	8305170116	40-6500	
DEBBAGE, A G	8305270356*	50-321	
DEBOER, T K	8305180810	PROJ	
DEBS, B. T.	8305270384*	50-250	
DEBS, B T	8305270668*	50-259	
DEIGL, H J	8305180626	71-5407	
DEIGL, H J	8305230697	71-5407	
DELANEY, J C	8305030301*	70-378	
DELANEY, J C	8305050335*	70-378	
DELGAIZO, T J	8206300177*	50-309	
DELMEDICO, J.	8305110030*	NUREG	
DELMEDICO, J	8305180258*	FOIA	
DELOATCH, V	8305090009	CONTRACT	
DELOATCH, V	8305090122	CONTRACT	
DEMPPAINEN, M	8305240015	NUREG	
DENISON, E	8305030573	50-275	
DENISON, E	8305030581*	50-275	
DENISON, E	8305180417	50-275	
DENISON, E	8305230224*	50-275	
DENNIS, N	8304110196	I&E	
DENTE, T. J	8305100197	TOPREP	
DENTON, H	8305120607	MISC	
DENTON, H R.	8203180052*	50-206	
DENTON, H R	8204190027*	50-206	
DENTON, H R	8305020573	50-447	
DENTON, H R	8305030019*	50-389	
DENTON, H R	8305040056	50-146	
DENTON, H R	8305040138	50-289	
DENTON, H. R	8305040534	50-155	
DENTON, H R	8305040536*	50-155	
DENTON, H R	8305040625	50-155	
DENTON, H. R.	8305040727	50-317	
DENTON, H R	8305090244	50-272	
DENTON, H R	8305090295	MISC	
DENTON, H R	8305110423*	REVIEW GR	
DENTON, H R	8305110428*	REVIEW GR	
DENTON, H R.	8305110432*	REVIEW GR	
DENTON, H R	8305170064	50-272	
DENTON, H R	8305170085*	50-272	
DENTON, H R	8305200204*	NUREG	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
DENTON, H R	8305230189	50-320	T
DENTON, H R	8305240216	50-289	Q
DENTON, H R	8305240220*	50-289	Q
DEUTSCH, W J	8305060233	NUREG	
DEVIENCE, A	8305090285	50-366	A
DEVINCENTIS, J	8305050006	50-443	F
DEVINCENTIS, J	8305050006	50-443	F
DEVINCENTIS, J	8305160039	50-443	S
DEVINCENTIS, J	8305190164	50-443	S
DEVINCENTIS, J	8305190164	50-443	S
DEVINCENTIS, J	8305200353	50-443	S
DEVINCENTIS, J	8305200353	50-443	S
DEVINCENTIS, J	8305200402	50-443	S
DEVINCENTIS, J	8305200402	50-443	S
DEVINCENTIS, J	8305250244	50-443	S
DEVINCENTIS, J	8305250244	50-443	S
DEVINCENTIS, J	8305270019	50-443	A
DEVINCENTIS, J	8305270019	50-443	A
DEVINE, A	8305200598	50-440	Q
DEVINE, H F	8305230029	50-409	J
DEVINE, J B	8305060687	XPORTLIC	
DEVINE, J B	8305130273	XPORTLIC	
DEVINE, T	8305190097*	50-329	Q
DEVINE, T	8305190124*	50-373	Q
DEVINE, T	8305190292*	50-373	Q
DEVINE, T	8305190304*	50-373	Q
DEWEY, L S	8305030498	50-529	Q
DEWEY, L S	8305110268	50-529	Q
DEWEY, L S	8305270024	50-529	Q
DEWEY, L S	8305310074	50-529	Q
DEWITT, R B	8305020079	50-255	F
DEWITT, R B	8305100287*	50-255	P
DEWITT, R B	8305200218	PR	
DEWITT, R B	8305240565*	50-155	P
DEYE, J A	8305180425	PR	
DEYOUNG, R C	8305030469	50-483	Q
DEYOUNG, R C	8305120145	50-445	Q
DEZUTEL, C Z	8305190112*	50-329	S
DI GIACOMO, C Q	8305240554	50-247	T
DIAB, S	8305090618*	50-445	Q
DICEY, B B	8305180010*	FOIA	
DICEY, B B	8305180052*	FOIA	
DICEY, B B	8305180159*	FOIA	
DICK, G F	8305110426	50-244	P
DICK, G F	8305180340	50-244	P
DICK, G F	8305180361	50-244	F
DICK, G F	8305260237	50-244	P
DICKEY, F	8304180513*	50-311	S
DICKHONER, W H	8305190190	50-358	A
DICKINSON, A C	8305030447*	50-219	S
DICKINSON, J D	8305170307*	TQPREP	
DIECKAMP, H	8305020465*	50-219	I
DIECKAMP, H	8305230402	50-219	P
DIEDERICH, G J	8305240318	50-373	S
DIEDERICH, G J	8305020086	50-373	S
DIEDERICH, G J	8305020109	50-373	S
DIEDERICH, G J	8305020205	50-373	S
DIEDERICH, G J	8305020241	50-373	S
DIEDERICH, G J	8305020351	50-373	S
DIEDERICH, G J	8305040365	50-373	R
DIEDERICH, G J	8305060398	50-373	S
DIEDERICH, G J	8305060493	50-373	S
DIEDERICH, G J	8305110447	50-373	R
DIEDERICH, G J	8305170374	50-373	S
DIEDERICH, G J	8305170383	50-373	S
DIEDERICH, G J	8305240007	50-373	S
DIEDERICH, G J	8305240025	50-373	S
DIEDERICH, G J	8305240073	50-373	S
DIEDERICH, G J	8305240229	50-373	S
DIEDERICH, G J	8305240334	50-373	S
DIEDERICH, G J	8305240354	50-373	S
DIEDERICH, G J	8305240381	50-373	S
DIEDERICH, G J	8305240425	50-373	S
DIEDERICH, G J	8305270195	50-373	S
DIEDERICH, G J	8305270237	50-373	S
DIETZ, C R	8305030291	50-324	S
DIETZ, C R	8305030355	50-324	S
DIETZ, C R	8305030387	50-324	S
DIETZ, C R	8305030411	50-324	S
DIETZ, C. R	8305030465	50-325	S
DIETZ, C R	8305030497	50-324	S
DIETZ, C R	8305030505	50-325	S
DIETZ, C. R	8305030512	50-324	S
DIETZ, C R	8305030530	50-324	S
DIETZ, C. R	8305030540	50-324	S
DIETZ, C R	8305030612	50-324	S
DIETZ, C R	8305050143	50-325	S
DIETZ, C R	8305050201	50-325	S
DIETZ, C R	8305050242	50-324	S
DIETZ, C R	8305050265	50-324	S
DIETZ, C R.	8305100412	50-324	R
DIETZ, C R.	8305110282	50-325	S
DIETZ, C R.	8305130108	50-325	S
DIETZ, C R.	8305130167	50-324	S
DIETZ, C R.	8305130170	50-324	S
DIETZ, C R	8305130177	50-324	S
DIETZ, C R	8305200538	50-324	S
DIETZ, C R.	8305270256*	50-324	Q
DIETZ, C R.	8305270531	50-324	Q
DIETZ, C R.	8305270588*	50-324	Q
DIETZ, C R	8305270599*	50-324	Q
DIETZ, C R	8305270610*	50-324	Q
DIETZ, C R	8305270617*	50-324	Q
DIGGS, R M	8305030014	50-395	P
DIGGS, R M	8305040084	50-328	P
DIGGS, R M	8305040546	50-387	P
DIGGS, R M	8305040547	50-244	Q
DIGGS, R M	8305060638	50-312	P
DIGGS, R M	8305090357	50-315	P
DIGGS, R M	8305180791	50-369	P
DIGGS, R M	8305200186	50-237	P
DIGGS, R M	8305260379	50-293	P
DIGGS, R M	8305260381	50-389	P
DIGGS, R M	8305310224	50-395	P
DIGNAN, T Q	8305040300	50-443	Q
DIGNAN, T Q	8305040300	50-443	Q
DIGNAN, T Q	8305040316	50-443	Q
DIGNAN, T Q	8305040533	50-309	Q
DIGNAN, T Q	8305040533	50-309	Q
DIGNAN, T Q	8305310147	50-443	Q
DIGNAN, T. Q	8305310147	50-443	Q
DIMEGLIO, A F	8305240384	50-193	S
DIMEGLIO, A F	8305250445	50-193	S
DIRCKS, W	8305090290*	MISC	
DIRCKS, W. J	8302280090	SECY	
DIRCKS, W J	8304220083	SECY	
DIRCKS, W J	8305020530	50-320	P
DIRCKS, W J	8305040054	50-289	Q
DIRCKS, W J	8305060700*	10CFR	
DIRCKS, W J.	8305090279	MISC	
DIRCKS, W J.	8305090504	50-289	Q
DIRCKS, W J.	8305090512	10CFR	
DIRCKS, W J.	8305110024	WASTE MGT	
DIRCKS, W J	8305170098*	50-358	A
DIRCKS, W. J.	8305170232	50-272	S
DIRCKS, W J.	8305180153*	FOIA	
DIRCKS, W J	8305180322*	FOIA	
DIRCKS, W J.	8305180328*	50-237	P
DIRCKS, W J	8305200198	NUREG	
DIRCKS, W J.	8305200627*	REVIEW GRP	
DIRCKS, W J	8305230070*	FOIA	
DIRCKS, W J	8305230639	NUREG	
DIRCKS, W. J	8305240019	50-537	U
DIRCKS, W J	8305240075	COMMISSION	
DIRCKS, W J.	8305240213	50-275	F
DIRCKS, W J.	8305240457*	50-289	Q
DIRCKS, W J.	8305250162	50-358	R
DIRCKS, W J.	8305250228*	50-361	P
DIRCKS, W J.	8305250250	SECY	
DIRCKS, W J.	8305250311	COMMISSION	
DIRCKS, W J	8305250588	50-289	P
DIRCKS, W. J	8305270118	SECY	
DIRCKS, W J	8305310238	50-309	H
DIXON, O. W	8305030627	50-395	S
DIXON, O. W	8305050057	50-395	S
DIXON, O. W	8305050233	50-395	S
DIXON, O. W	8305050317*	50-395	F
DIXON, O. W	8305060619	50-395	P
DIXON, O. W	8305100089	50-395	S
DIXON, O. W	8305100301	50-395	P
DIXON, O W	8305180373	50-395	F
DIXON, O W	8305180442	50-395	P
DIXON, O. W	8305180465	50-395	Q
DIXON, O W	8305200311	50-395	Q
DIXON, O. W	8305200510	50-395	S
DIXON, O W	8305200513	50-395	E
DIXON, O. W	8305200626	50-395	S
DIXON, O W	8305250349	50-395	S
DIXON, O W	8305250492	50-395	P
DIXON, O W	8305270422*	50-395	Q
DIXON, O W	8305270441*	50-395	Q
DOBEL, H F	8305270539	50-358	J
DODDS, R T	8305170349*	50-397	Q
DODDS, R T	8305170381*	50-397	Q
DODDS, R T	8305170387*	50-508	Q
DODDS, R T	8305170390*	50-508	Q
DODDS, R T	8305170439*	50-397	Q
DODDS, R T	8305170498*	50-508	Q
DOERFLEIN, L T	8305110391*	50-333	Q
DOIRON, D Q	8305060251*	CONTRACT	
DOMENICI, P V	8305180123*	FOIA	
DONAHUE, J F	8305230134*	70-1193	
DONAHUE, J F	8305230139*	70-1193	
DONAHUE, J F	8305230179*	70-1193	
DONAHUE, J F	8305230186*	70-1193	
DONNELLY, P M	8305270451*	50-331	S
DONNELLY, P M	8305270460*	50-331	S
DOOLITTLE, E L	8305250185	50-423	A
DOROSHOW, J	8305180369	PR	
DOROSHOW, J	8305200669	50-289	Q
DOROSHOW, J	8305240444	50-289	Q
DOROSHOW, J	8305240449	50-289	Q
DORSEY, M	8305200062	CONTRACT	
DORSEY, M	8305230024	CONTRACT	
DORSEY, M	8305230287	CONTRACT	
DOUGHERTY, D J	8305250034*	FOIA	
DOUGHERTY, J B	8305130072	50-322	Q
DOUGHERTY, J B	8305130072	50-322	Q
DOUGHERTY, J B	8305180341	PR	
DOUGHTY, J	8305180364	PR	
DOULOS, N	8305030268*	70-378	
DOYLE, A J	8305230572*	50-482	I
DOYLE, J.	8305020444*	50-445	Q
DOYLE, J	8305040515*	50-445	T
DOYLE, J.	8305040535	50-445	T
DOYLE, J.	8305110354	50-445	T
DOYLE, J	8305130157	50-445	T
DRAGONETTE, K S	8305120527*	40-672	
DRAIN, D. T	8305120041*	FOIA	
DRAIN, D. T.	8305120065*	FOIA	
DREY, K	8304180420*	MISC	
DRISKILL, D. D	8305200256*	50-382	Q
DRUGA, R J	8305030316*	50-334	S
DRUGA, R. J	8305110353*	50-334	S
DRUGA, R. J.	8305120411*	50-334	S
DRUGA, R J	8305160064*	50-334	S
DRUGA, R. J	8305190309*	50-334	S
DRUMMOND, F. J	8305200542	50-382	S
DRUMMOND, F J	8305270138	50-382	S
DRUMMOND, F J	8305270147	50-382	S
DRUMMOND, F J	8305270194	50-382	S
DRUMMOND, F J	8305270373	50-382	S
DRUMMOND, F J	8305310094	50-382	E
DUBOIS, D.	8305200344	50-298	S
DUBRY, N	8305020348*	50-315	Q
DUBRY, N. E	8305240309*	50-315	Q
DUCK, J. R.	8305030379	50-389	J
DUCK, J R	8305040180	50-348	J
DUCK, J R	8305040186	50-335	J
DUCK, J. R.	8305040202	50-321	J
DUCK, J R	8305040204	50-302	J
DUCK, J. R.	8305040208	50-250	J
DUCK, J R	8305040243	50-327	J
DUCK, J R	8305160005	50-259	J
DUCK, J. R	8305190022	50-302	J
DUCK, J. R	8305200270	50-321	J
DUCK, J R	8305230027	50-321	J
DUGGAN, J Q.	8305160004	40-7580	
DUGGAN, J Q	8305160258	40-7580	
DUGGAN, J. Q	8305160261*	40-7580	
DUGSTAD, D	8305160076*	50-282	R
DUNAWAY, F R	8305100271*	50-295	Q
DUNCAN, P. S.	8305060536*	50-352	A
DUNLAP, J M.	8305190313*	50-271	Q
DUNN, W L	8305310157*	50-244	P
DUNNING, T. Q.	8305090625*	50-445	Q
DUNNING, T Q	8305090646*	50-445	Q
DUPONT, S Q	8305170403*	50-373	Q
DUPREE, D.	8305240323	50-327	R
DURDEL, R	8305060608*	50-346	F
DURR, J.	8305050147*	50-277	Q
DURR, J.	8305250509*	50-286	Q
DURR, J. P.	8305110338*	50-289	Q
DURR, J. P	8305250295*	50-219	Q
DURR, J. P	8305250575*	50-387	Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
DUTTON, D E	8305050086	50-424 A
DUVALL, D D	8305110324	50-269 S
DUVALL, D D	8305200395	GA999
DUVALL, D D	8305200415*	GA999
DUVALL, D D	8305200422*	GA999
DWYER, P W	8305200552	TOPREP
DYNNER, A R	8305050005*	50-322 Q
DYNNER, A R	8305050005*	50-322 Q
DYNNER, A R	8305090136*	50-322 Q
DYNNER, A R	8305240548	50-322 Q
DYNNER, A R	8305240548	50-322 Q
DYNNER, A R	8305310063	50-322 Q
DYNNER, A R	8305310063	50-322 Q
DYSON, J B	8305230597	50-286 P
EAPEN, P	8305110508*	50-333 Q
EAPEN, P	8305250443*	50-245 Q
EAPEN, P K	8305250230*	50-286 Q
EAPEN, P K	8305250314*	50-309 Q
EAPEN, P K	8305250465*	50-336 Q
EAPEN, P K	8305250504*	50-213 Q
EARLEY, A. F	8305030557	50-322 Q
EARLEY, A F	8305050024	50-322 T
EARLEY, A F	8305050024	50-322 T
EARLEY, A F	8305050029*	50-322 T
EARLEY, A F	8305050029*	50-322 T
EARLEY, A. F.	8305090136*	50-322 Q
EARLEY, A F	8305100239*	50-322 Q
EARLEY, A F	8305190378	50-322 Q
EARLEY, A F	8305190378	50-322 Q
EARLEY, A F	8305190382*	50-322 Q
EARLEY, A. F	8305190382*	50-322 Q
EARLEY, A F	8305200651	50-322 Q
EARLEY, A F	8305310051	50-322 Q
EARLEY, A F	8305310051	50-322 Q
EASON, T. D	8305180466*	50-395 Q
EASTWOOD, D	8305020547	NUREG
EBERSOLE, J C	8305090366	ACRS
EBERSOLE, J C	8305130339*	50-443 A
EBERSOLE, J C	8305240033	ACRS
EBERSOLE, J C	8305250074	ACRS
EBERSOLE, J C	8305250078	ACRS
EBERSOLE, J. C	8305260008	ACRS
EBERSOLE, J C	8305260104	ACRS
EBNETER, S	8305250505*	50-289 Q
ECCLESTON, K T	8305040295	50-293 P
ECCLESTON, K. T	8305060266	50-293 P
ECCLESTON, K T	8305120163	50-293 P
ECCLESTON, K T	8305180197	50-293 P
ECKART, D E	8305170457	50-440 Q
ECKEL, J. S	8305110491	NUREG
ECKERT, R M.	8305180306	PR
ECKERT, T.	8305110196	NUREG
ECKHARDT, J H	8305170361*	50-361 Q
ECKHARDT, J H	8305170537*	50-528 Q
ECONOMOS, N	8305270244*	50-338 Q
ECONOMOS, N	8305270269*	50-302 Q
EDDLEMAN, W	8305060485	50-400 Q
EDDLEMAN, W.	8305110145	50-400 Q
EDDLEMAN, W	8305110222	50-400 Q
EDDLEMAN, W	8305110361	50-400 Q
EDDLEMAN, W.	8305110366	50-400 Q
EDDLEMAN, W.	8305120288	50-400 Q
EDDLEMAN, W	8305170528	50-400 Q
EDELMAN, M. R.	8303280059	50-440 A
EDELMAN, M. R.	8305020308	50-440 S
EDELMAN, M. R	8305020500	50-440 S
EDELMAN, M. R	8305040465	50-440 S
EDELMAN, M R.	8305040486	50-440 S
EDELMAN, M R	8305040496	50-440 S
EDELMAN, M R	8305040516*	50-440 T
EDELMAN, M. R	8305090490*	50-440 Q
EDELMAN, M. R	8305100013	50-440 S
EDELMAN, M. R	8305100333	50-440 S
EDELMAN, M. R.	8305100394	50-440 S
EDELMAN, M R	8305110300	50-440 E
EDELMAN, M. R	8305130236	50-440 S
EDELMAN, M. R	8305130248	50-440 S
EDELMAN, M. R.	8305170203	50-440 Q
EDELMAN, M. R	8305230106	50-440 E
EDELMAN, M. R.	8305230143	50-440 A
EDELMAN, M. R.	8305230290	50-440 A
EDELMAN, M. R.	8305250381	PR
EDELMAN, M. R	8305260267	50-440 E
EDGAR, E. C.	8305110328*	50-244 S
EDGAR, G L.	8303240390	50-537 Q
EDGAR, G L	8303240394*	50-537 Q
EDGAR, G L	8305110220	50-537 Q
EDGAR, G L	8305120313	50-537 Q
EDGAR, G L	8305190339	50-537 Q
EDGAR, G L	8305200636	50-537 Q
EDGAR, G L	8305200648*	50-537 Q
EDGAR, G. L	8305240475	50-537 Q
EDGAR, G L	8305240480	50-537 Q
EDGAR, G L	8305240503	50-537 Q
EDGAR, G L	8305310188	50-537 Q
EDGEWORTH, P	8305120513	CONTRACT
EDISON, G E	8305250231	50-482 E
EDLER, S K	8305110208	NUREG
EGER, K J	8305240034	70-1301
EGLE, D M	8305250478	50-112 H
EICHBAUM, W M	8305060289	PR
EICHENHOLZ, H	8305160142*	50-293 Q
EICHSTAEDT, C L	8305190112*	50-329 S
EINBEL, D W	8305040175*	FOIA
EINBEL, D W	8305040189*	FOIA
EISENHUT, D G	8210190253	TOPREP
EISENHUT, D G	8303040044	50-275 P
EISENHUT, D G	8305020455	50-3 P
EISENHUT, D G	8305030010	50-395 F
EISENHUT, D G	8305030016	50-389 P
EISENHUT, D G	8305030191	50-275 P
EISENHUT, D. G	8305030577	50-312 P
EISENHUT, D G	8305040323	50-247 P
EISENHUT, D G	8305040549	50-329 H
EISENHUT, D G	8305040550	50-329 H
EISENHUT, D G	8305060084*	50-317 F
EISENHUT, D G	8305060553*	50-333 F
EISENHUT, D G	8305060660	50-407 P
EISENHUT, D G	8305060694*	50-361 P
EISENHUT, D G	8305090197*	50-331 F
EISENHUT, D G	8305090204	MISC
EISENHUT, D G	8305090282	50-275 P
EISENHUT, D G	8305090659	50-3 P
EISENHUT, D G	8305110034	50-3 F
EISENHUT, D G	8305110037	50-331 P
EISENHUT, D. G	8305110223	50-250 F
EISENHUT, D G	8305110513	50-289 P
EISENHUT, D G	8305110542*	50-266 F
EISENHUT, D G	8305120085	50-275 P
EISENHUT, D G	8305120524	50-128 P
EISENHUT, D G	8305120532*	50-128 P
EISENHUT, D G	8305120544*	50-128 P
EISENHUT, D G	8305120585*	50-373 P
EISENHUT, D. G.	8305120611	50-275 P
EISENHUT, D G	8305130343	50-382 A
EISENHUT, D G.	8305160185	50-275 R
EISENHUT, D G	8305160331	50-331 P
EISENHUT, D G	8305170233*	50-361 P
EISENHUT, D G	8305170649	50-369 S
EISENHUT, D. G.	8305170666*	50-282 F
EISENHUT, D G	8305170685*	50-313 F
EISENHUT, D G	8305180015*	50-395 P
EISENHUT, D. G	8305180034	50-269 P
EISENHUT, D G	8305180058*	50-369 P
EISENHUT, D G	8305180097	50-146 P
EISENHUT, D G	8305180224*	50-327 P
EISENHUT, D. G	8305180577*	50-333 F
EISENHUT, D G	8305180622	50-275 H
EISENHUT, D. G	8305180702*	50-295 P
EISENHUT, D G	8305180790	50-361 S
EISENHUT, D G	8305180830	50-272 S
EISENHUT, D G	8305180836*	50-272 S
EISENHUT, D G	8305190046	50-397 A
EISENHUT, D. G	8305190054*	50-397 A
EISENHUT, D G	8305190060*	50-397 A
EISENHUT, D. G	8305190068*	50-397 A
EISENHUT, D G	8305190077*	50-397 A
EISENHUT, D G.	8305200190	50-382 Q
EISENHUT, D. G	8305200266	50-275 P
EISENHUT, D G	8305230206	50-275 R
EISENHUT, D G	8305230216	50-275 R
EISENHUT, D. G.	8305230324	PR
EISENHUT, D. G	8305230381	50-309 P
EISENHUT, D G	8305230704	50-470 A
EISENHUT, D G.	8305250066	50-275 R
EISENHUT, D G.	8305260149	MISC
EISENHUT, D G	8305260211*	50-280 P
EL-ASHRY, M. T	8305260307	50-327 S
ELDRINGHOFF, V	8305250576*	50-483 Q
ELDRINGHOFF, V	8305250576*	50-483 Q
ELIN, J O	8305170537*	50-528
ELLIOTT, C W	8305090478	50-352
ELLIOTT, N R	8305240541	50-247
ELLIOTT, N R	8305240546	50-247
ELLIOTT, N R	8305270583	50-247
ELLIS, J	8212300009	50-445
ELLIS, J	8305020422	50-445
ELLIS, J	8305020430*	50-445
ELLIS, J	8305020437*	50-445
ELLIS, J	8305040296	50-445
ELLIS, J	8305040499	50-445
ELLIS, J	8305040507	50-445
ELLIS, J	8305040513	50-445
ELLIS, J	8305090443	50-445
ELLIS, J	8305110137	50-445
ELLIS, J	8305110332	50-445
ELLIS, J	8305110347	50-445
ELLIS, J	8305110357	50-445
ELLIS, J	8305110368	50-445
ELLIS, J	8305110397	50-445
ELLIS, J	8305130066	50-445
ELLIS, J	8305130175	50-445
ELLIS, J	8305170287	50-445
ELLIS, J	8305170513	50-445
ELLIS, J	8305180272	PR
ELLIS, J	8305200504	50-445
ELSASSER, T	8305160142*	50-293
ELSASSER, T	8305250443*	50-245
ELSASSER, T C	8305020332*	50-57
ELSASSER, T C	8305050236*	50-97
ELSASSER, T C	8305060029	50-293
ELSASSER, T C	8305110395*	50-225
ELSASSER, T C	8305250307*	50-213
ELSASSER, T C	8305250456*	50-184
ELSASSER, T C	8305250465*	50-336
ELSASSER, T C	8305250504*	50-213
ELSASSER, T C	8305270208*	50-184
ELSEN, M J	8305100416*	50-237
EMCH, R L	8305040196	50-155
EMCH, R L	8305090484	50-155
EMCH, R L	8305160031	50-155
EMCH, R L	8305310145	50-155
EMERSON, W	8305050069	50-423
EMPEY, D C	8305120404*	50-410
EMSHWILLER, J R	8305180003	FOIA
ENGBLOM, M. R	8305230104	71-9135
ENGELKEN, R H	8305160200*	50-312
ENGELMANN, R	8305040002	40-8584
ENGLE, L B	8305060109	50-338
ENGLE, L B	8305200709	50-338
EPLER, E P	8305090255*	50-272
EPPLE, O	8305250573*	50-483
EPPLE, O	8305250573*	50-483
EPSTEIN, E	8305120454*	40-672
EPSTEIN, E	8305120462*	40-672
EPSTEIN, E	8305120466*	40-672
EPSTEIN, R B	8305270566	50-247
ERICKSON, K T	8305030646*	50-247
ERICKSON, K T	8305030646*	50-247
ERICKSON, K T	8305030646*	50-247
ERNST, M L	8305170596	QEN TEC
ESTEY, H P.	8305030719	40-8064
EURY, L W	8305020453	50-261
EURY, L W	8305200009	50-261
EURY, L W	8305250249	50-261
EVANS, C. A	8305260304*	50-298
EVANS, C D	8305270086*	50-395
EVANS, J H	8305260004*	71-5552
EVERETT, R J	8304120582	I&E
EVERETT, R. J	8305030308*	70-846
EVERETT, R. J	8305060462	40-8084
EVERBOLE, R E	8305260004*	71-5552
FAIR, J R.	8305030474*	50-483
FALCONER, D	8305270338*	50-269
FALCONER, D	8305270411*	50-269
FALCONER, J C	8305020425	50-443
FALCONER, J C	8305020429*	50-443
FALLIN, J F	8305100346	PROJ
FARIS, J. A.	8305060608*	50-346
FARLEY, J M	8305240484*	50-348
FARMAN, R. F	8305200691*	50-373
FARRAR, D. L	8305020106*	50-10
FARRAR, D L	8305020115*	50-456
FARRAR, D L	8305060184	50-454
FARRAR, D L	8305130144*	50-373

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
FARRAR, D L	8305170331*	50-374	Q
FARRAR, D L	8305170425*	50-373	Q
FARRAR, D L	8305200522*	50-454	Q
FARRAR, D L	8305200540*	50-454	Q
FARRAR, D L	830524030B*	50-373	Q
FARRAR, D L	8305240315*	50-373	Q
FARRAR, D L	8305260282*	50-454	Q
FARRAR, D L	8305270193*	50-456	Q
FARRAR, D L	8305270489*	50-454	Q
FARRAR, D L	8305310095	50-295	Q
FARRAR, D L.	8305310117*	50-237	Q
FARRELL, R E	8305260334*	50-373	Q
FARRELLY, T J	8305030531	50-247	Q
FASANO, A	8305030164*	50-320	Q
FAUCONNEAU, G	8305120484*	50-461	S
FAULKENBERRY, B	8305240390	50-275	Q
FAULKENBERRY, B	8305240393*	50-275	Q
FAY, C W	8305030275	50-301	S
FAY, C W	8305030280*	50-301	S
FAY, C W	8305030376	50-266	S
FAY, C W	8305030382*	50-266	S
FAY, C W	8305030523	50-266	F
FAY, C W	8305130009	50-266	P
FAY, C W	8305130034	50-266	S
FAY, C W	8305160169	50-266	R
FAY, C W	8305160171*	50-266	R
FAY, C W	8305170252*	50-266	Q
FAY, C W	8305170263*	50-266	Q
FAY, C W	8305190226	50-266	S
FAY, C W	8305200229	50-266	Q
FAY, C W	8305240131	50-266	P
FAY, C W	8305240331	50-301	S
FAY, C W	8305240350	50-301	S
FAY, C W	8305240379	50-266	S
FAY, C W	8305240412	50-301	S
FAY, C W	8305240497	50-266	P
FAY, C W	8305270241	50-266	Q
FAY, C W	8305270358	50-266	Q
FEIERABEND, C D	8305240061*	50-282	Q
FEIL, R A	8305170439*	50-397	Q
FEITKNECHT, C	8305030593	50-334	R
FELCH, F B	8305020425	50-443	Q
FELCH, F B	8305020429*	50-443	Q
FELTON, J M	8304270424	50-313	F
FELTON, J M	8305020007	70-378	
FELTON, J M	8305030076	50-295	F
FELTON, J M	8305030104	50-295	F
FELTON, J M	8305030180	50-275	F
FELTON, J M	8305030214	50-282	F
FELTON, J M	8305030231	50-389	F
FELTON, J M	8305030685	50-321	F
FELTON, J M	8305030693	50-289	F
FELTON, J M	8305040007	50-305	F
FELTON, J M	8305040022	50-245	F
FELTON, J M	8305040069	50-454	F
FELTON, J M	8305040235	50-3	F
FELTON, J M	8305040259	50-315	F
FELTON, J M	8305040575	50-320	F
FELTON, J M	8305040584	50-369	F
FELTON, J M	8305040614	50-285	F
FELTON, J M	8305040628	50-259	F
FELTON, J M	830504064B	50-321	F
FELTON, J M	8305050285	50-387	F
FELTON, J M	8305050300	50-289	F
FELTON, J M	8305050311	50-395	F
FELTON, J M	8305050377	50-320	F
FELTON, J. M	8305060073	50-206	P
FELTON, J M	8305060112	FOIA	
FELTON, J M	8305060123	FOIA	
FELTON, J M	8305060135	40-672	
FELTON, J M	8305060144	FOIA	
FELTON, J M	830506033B	50-482	F
FELTON, J M	8305060575	50-313	F
FELTON, J M.	8305060595	50-346	F
FELTON, J M	8305060616	50-348	F
FELTON, J M	8305060627	50-317	F
FELTON, J M	8305060673	50-295	F
FELTON, J M	8305060692	50-346	F
FELTON, J M	8305090024	50-206	H
FELTON, J M	8305090241	FOIA	
FELTON, J M	8305090292	50-566	A
FELTON, J M	8305090306	50-373	Q
FELTON, J. M	8305090529	50-443	F
FELTON, J M	8305090542	50-358	T
FELTON, J M	8305110569	50-213	F
FELTON, J M	8305120007	FOIA	
FELTON, J M	8305120010	FOIA	
FELTON, J M	8305120070	50-358	Q
FELTON, J M	8305120095	FOIA	
FELTON, J M	8305120224	40-672	
FELTON, J M	830512048B	50-271	Q
FELTON, J M	8305120566	50-267	F
FELTON, J M	8305120576	FOIA	
FELTON, J M	8305120594	50-285	F
FELTON, J M	8305130307	50-272	F
FELTON, J M	8305130310	50-387	F
FELTON, J M	8305160195	50-312	Q
FELTON, J M	8305160255	50-312	S
FELTON, J M	8305160279	50-389	F
FELTON, J M	8305160283	50-369	F
FELTON, J M	830516028B	50-313	F
FELTON, J M	8305160292	50-413	F
FELTON, J. M	8305180001	50-498	A
FELTON, J M	8305180005	FOIA	
FELTON, J M	8305180316	50-237	P
FELTON, J M	8305190005	50-329	Q
FELTON, J M	8305200087	50-320	P
FELTON, J M	8305230007	50-458	F
FELTON, J M	8305230028	FOIA	
FELTON, J M	8305230065	FOIA	
FELTON, J M	8305230112	40-1478	
FELTON, J M	8305230215	FOIA	
FELTON, J M	8305230223	FOIA	
FELTON, J M	8305230232	FOIA	
FELTON, J M	8305230246	FOIA	
FELTON, J M	8305240087	50-373	Q
FELTON, J M	8305240254	50-245	P
FELTON, J M	8305240365	FOIA	
FELTON, J M	8305250029	FOIA	
FELTON, J M	8305260397	50-358	A
FELTZ, D E	8305050252	50-128	P
FERO, D A	8305030171	50-341	A
FERO, D A	8305030178*	50-341	A
FERO, D A	8305050004	50-341	A
FERGUSON, R N	8305200637*	50-373	P
FERNANDEZ, C	8209210332*	50-336	P
FIATARONE, J V	8305060220*	40-672	
FIATARONE, J V.	8305120474*	FOIA	
FIEDLER, P B	8305020362	50-219	P
FIEDLER, P B	8305030365	50-219	F
FIEDLER, P B	8305030441	50-219	S
FIEDLER, P B	8305050022	50-219	F
FIEDLER, P B	8305110374	50-219	P
FIEDLER, P B	8305160023*	50-219	Q
FIEDLER, P B.	830517055B	50-219	P
FIEDLER, P B	8305200500	50-219	Q
FIEDLER, P B	8305230436	50-219	R
FIEDLER, P B	8305270082	50-219	P
FIELD, J A	8305200002	CONTRACT	
FIELDS, H C	8305030637*	50-395	S
FIELDS, H C	8305050061*	50-395	S
FIELDS, J A	8305050400	CONTRACT	
FIELDS, J A	8305060341	CONTRACT	
FIELDS, J A	8305060379	50-329	A
FIELDS, J A	8305110233	CONTRACT	
FIELDS, J A	8305160318	50-367	A
FIELDS, J A	8305190506	CONTRACT	
FIENO, D	8305020524	TOPREP	
FIENO, D	8305090532	TOPREP	
FINAMORE, B A	8305030502	50-537	Q
FINAMORE, B A	8305100210	50-537	Q
FINAMORE, B A	8305100350	50-537	Q
FINAMORE, B A	8305100350	50-537	Q
FINAMORE, B A	8305120291	50-537	Q
FINAMORE, B A	8305120291	50-537	Q
FINAMORE, B A	8305160149	50-537	Q
FINAMORE, B A	8305160181	50-537	Q
FINAMORE, B A	8305190221	50-537	Q
FINAMORE, B A	8305240553	50-537	Q
FINDLAY, J A	8305050426	NUREG	
FINDLAY, J A	8305110196	NUREG	
FINK, J	8305240544	50-440	Q
FINLAYSON, F	8305110027	NUREG	
FINN, J A	8305230139*	70-1193	
FINNERAN, J C	8305090525*	50-445	T
FIORELLI, G	830517038Z*	50-528	Q
FIORELLI, G	8305170564*	50-528	Q
FIORELLI, G.	8305190045*	50-329	Q
FIORELLI, G	8305230139*	FOIA	
FIREBAUGH, L	8305040246*	50-369	S
FIREBAUGH, L	8305040260*	50-369	S
FISCHER, D	8305170015	50-311	P
FISCHER, D	8305170079	50-272	P
FISCHER, D	8305170117	50-272	P
FITZGERALD, J A	8304040391	50-322	U
FITZGERALD, J A	8305180252	50-322	U
FITZGERALD, J A	8305180366	50-322	H
FITZGERALD, J A	8305180430	50-322	H
FITZGERALD, J A	8305180437	50-170	U
FITZGERALD, J A	8305180445	50-322	H
FITZPATRICK, B	830512046B*	50-266	Q
FLACK, E	8305030405	50-250	S
FLACK, E	8305030468	I&E	
FLACK, E	8305090224	50-280	Q
FLAGG, D. M	8305240544	50-440	Q
FLANAGAN, D O	8305190208	50-322	Q
FLANAGAN, D O	8305190208	50-322	Q
FLANNERY, E J	8305200457*	GA999	
FLANNERY, E J	8305200468*	GA999	
FLEENOR, C	8305060174	CONTRACT	
FLEENOR, C	8305110031	CONTRACT	
FLEENOR, C	8305110504	CONTRACT	
FLEENOR, C	8305120513	CONTRACT	
FLEENOR, C.	8305170606	CONTRACT	
FLEISCHAKER, D.	8305060451	50-275	Q
FLEISCHAKER, D	8305090438	50-275	Q
FLEISCHAKER, D	8305090438	50-275	Q
FLEISCHAKER, D	8305200273*	50-275	P
FLEISCHAKER, D	8305200273*	50-275	P
FLEISCHMANN, R	8305270117	50-278	S
FLEISCHMANN, R	8305270184	50-277	S
FLEISCHMANN, R	8305270235	50-277	S
FLEISHER, Z S	8305050035	50-247	Q
FLEISHER, Z S	8305200605	50-247	Q
FLEURY, E R.	8305050337*	70-378	
FLORY, C A	8305090620	WASTE MGT	
FLYNN, J. D.	8305090486	50-358	E
FLYNN, M.	8305110539	CONTRACT	
FLYNN, M	8305200145	CONTRACT	
FLYNN, R M	8305020022*	FOIA	
FLYNN, R M	8305030008*	FOIA	
FLYNN, R M	8305030027*	FOIA	
FLYNN, R. M	8305030063*	FOIA	
FLYNN, R. M	8305030073*	FOIA	
FLYNN, R M	8305030169*	FOIA	
FLYNN, R M	8305030335*	70-378	
FLYNN, R. M	8305040239*	FOIA	
FLYNN, R M	8305040573*	FOIA	
FLYNN, R. M.	8305040583*	70-378	
FLYNN, S F.	8305240446	50-400	Q
FLYNN, S. F.	8305240551	50-400	Q
FLYNN, S. F	8305250489	PR	
FOLEY, T	8305100433*	50-247	Q
FORD, J T.	8305030001	71-6294	
FORD, J. T	8305050100	70-1201	
FORD, J T	8305050205	70-1201	
FORD, J T	8305260376	70-1201	
FOREMAN, H	8305270634	50-382	Q
FORTUNA, R. A	8305180233*	FOIA	
FORTUNA, R A	8305180263*	FOIA	
FORTUNA, R A.	8305180285*	FOIA	
FORTUNA, R A	8305180291*	FOIA	
FOSTER, D O	8305100161	50-424	S
FOSTER, D O	8305250452	50-424	S
FOSTER, E R.	8305270089	50-336	S
FOSTER, J. E	8305190306*	FOIA	
FOSTER, W. E.	8305030351*	GA999	
FOSTER, W E	8305030525*	GA999	
FOSTER, W E	8305240462*	GA999	
FOURNEY, W L	8305110512	NUREG	
FOX, R. R	8305040553*	CONTRACT	
FRAGOLA, J. R	8305110119	NUREG	
FRAHM, R	8305060482*	50-272	S
FRAHM, R.	8305060489*	50-311	S
FRAHM, R.	8305110274*	50-311	S
FRAHM, R	8305160057*	50-311	S
FRAHM, R.	8305160102*	50-311	S
FRAHM, R	8305160123*	50-311	S
FRAHM, R	8305170370*	50-311	S
FRAHM, R	8305200397*	50-272	S
FRAHM, R	8305200546*	50-311	S
FRAHM, R.	8305250501	50-311	S
FRANCIS, E.	8305030253	40-8728	
FRANCIS, E.	8305030262*	40-8728	
FRANK, L.	8305190440	50-244	Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
FRANK, L	8305190462	50-369	Q
FRANKLIN, E M	8305230086*	71-5607	
FREDRICKSON, P	8305270629*	50-438	Q
FREEMAN, M D	8305260404	40-8768	
FRENCH, J F	8305240517	50-247	H
FRENCH, L D	8305030597*	50-29	S
FREUDENTHAL, N	8305030273*	40-8728	
FREUDENTHAL, N	8305130363	40-8064	
FREUDENTHAL, N	8305170242	40-8064	
FREUDENTHAL, N	8305250195	40-8102	
FREUDENTHAL, N	8305260389	40-299	
FREY, D Q	8305060236	PR	
FREY, D Q	8305180330	PR	
FREY, D Q	8305180369	PR	
FRIZZLE, C D	8305130128	50-309	P
FROUNFELKER, R	8305240280	50-155	J
FROUNFELKER, R	8305240290	50-255	J
FRYE, J H	8305030582	50-142	Q
FRYE, J H	8305060520	50-142	Q
FRYE, J H	8305100330	50-142	Q
FRYE, J H	8305130035	50-70	Q
FRYE, J. H	8305130076	50-142	Q
FRYE, J. H	8305130079	50-142	Q
FRYE, J H	8305130150	50-142	Q
FRYE, J H	8305160163	50-142	Q
FRYE, J H.	8305260171	50-358	Q
FRYLING, R	8305200067	50-272	I
FUHRMAN, Q R	8305020509	50-317	S
FUHS, A	8305260286	50-265	S
FULLER, C H	8305230427*	50-267	R
FULLER, E D	8305060160*	FOIA	
FULTON, J F	8305060277*	50-244	P
FUNCHES, J L	8305250305	GEN TEC	IS
FURBUSH, M H	8305230407	50-133	P
GAD, R. K	8305040300	50-443	Q
GAD, R K	8305040300	50-443	Q
GAD, R K	8305040316	50-443	Q
GAD, R. K	8305040533	50-309	Q
GAD, R. K	8305040533	50-309	Q
GAGE, J	8305190209	50-440	Q
GAGE, K.	8305200218	PR	
GAGLIARDO, J E	8305020229	50-482	A
GAGLIARDO, J E	8305100093	50-445	Q
GAGLIARDO, J E	8305200528*	50-267	Q
GALEF, S. R.	8305190342	50-247	Q
GALLAGHER, P J	8305240454	50-247	Q
GALLO, J	8305060495	50-155	Q
GALLO, J.	8305060495	50-155	Q
GALLO, J	8305120299	50-454	Q
GALLO, J	8305120299	50-454	Q
GALLO, J.	8305130185	50-155	Q
GALLO, J	8305130185	50-155	Q
GALLO, J	8305200610	50-155	Q
GALLO, J	8305200610	50-155	Q
GALLO, J	8305240438	50-155	Q
GALLO, J.	8305240438	50-155	Q
GALLO, R	8305030353*	50-309	Q
GALLO, R	8305110299	50-443	S
GALLO, R M	8305050119*	50-443	Q
GALLO, R. M	8305190038*	50-322	Q
GALLO, R M	8305250431*	50-29	Q
GALLO, R M	8305250450*	50-271	Q
GALM, D T	8305020075	70-698	
GAMBLE, D H	8305180013*	FOIA	
GAMBLE, D H	8305180016*	FOIA	
GAMBLE, D. H.	8305180104*	FOIA	
GAMMIE, G. B	8305260302	50-317	J
GARCIA, E M	8305170501*	50-275	Q
GARCIA, M J	8305060436	PR	
GARCIA, P. J.	8305120496	40-3453	
GARCIA, P J.	8305130297	40-3453	
GARDE, B	8305190097*	50-329	Q
GARDE, B. P.	8305190124*	50-373	Q
GARDNER, R. N	8305100217	50-329	T
GARLAND, W L.	8305260363	40-299	
GARLAND, W L	8305260368	40-299	
GARNER, L. W.	8305270635*	50-324	Q
GARRIBBA, S.	8305060399	NUREG	
GARRITY, J. H	8305020393*	50-309	Q
GARRITY, J H	8305050220	50-309	P
GARRITY, J. H.	8305060494	50-309	S
GARRITY, J. H.	8305060538	50-309	S
GARRITY, J H.	8305110425	50-309	S
GARRITY, J H	8305130054	50-309	P
GARRITY, J H	8305130078	50-309	P
GARRITY, J H	8305160065	50-309	S
GARRITY, J H	8305190308	50-309	P
GARRITY, J H	8305200341	50-309	F
GARRITY, J H	8305200360	50-309	S
GARRITY, J H	8305200467	50-309	S
GARRITY, J H	8305200469	50-309	P
GARRITY, J H	8305200529	50-309	S
GARRITY, J H	8305200578	50-309	I
GARRITY, J H	8305230127	50-309	F
GARRITY, J H	8305230383	50-309	P
GARRITY, J H	8305230472	50-309	S
GARRITY, J H	8305240266	50-309	P
GARRITY, J H	8305240270	50-309	P
GARRITY, J H	8305250429	50-309	Q
GARRITY, J H	8305310067	50-309	Q
GARY, R J	8305160138	50-445	K
GARY, R J	8305170029	70-2932	
GARY, R. J	8305200298	50-445	S
GARY, R. J	8305200419*	50-445	Q
GARY, R. J	8305200674*	50-445	Q
GDANSKI, S	8305180424	50-247	Q
GEARS, Q	8305060684	50-278	P
GEARS, Q.	8305190522	50-277	F
GEARS, Q	8305230318	50-277	P
GEARS, Q E	8305040704	50-277	P
GEARS, Q. E	8305040716	50-277	F
GEARS, Q E	8305180007	50-278	P
GEHR, A C	8305240482	50-529	Q
GEHR, A C	8305310215	50-528	Q
GEHR, A C	8305310215	50-528	Q
GELMAN, M R	8305030355	50-338	Q
GELMAN, M R	8305030355	50-338	Q
GELMAN, M R	8305190219	50-338	Q
GERDEMAN, F W	8305040047	40-7869	
GERDEMAN, F W	8305260418	40-8698	
GERETY, H. F	8305230037	50-219	J
GERGELY, P	8305110476	NUREG	
GETTY, B. C.	8305170342*	50-133	S
GIBBONS, T D	8305270420*	50-390	Q
GIBBONS, T D	8305270542*	50-389	Q
GIBBON, A	8304280139	I&E	
GIBBON, A F	8305130173	70-143	
GIBBON, A F	8305250537	70-143	
GIBBON, A F	8305310174	50-369	S
GIBBON, J	8305160204*	50-312	Q
GIBBON, J	8305170014*	50-336	R
GIBBON, R L	8305040455	50-413	H
GIBBON, R L.	8305310035	50-413	Q
GIESE, D. J	8305030472	PR	
GIESLER, C. W	8305030314	50-305	Q
GIESLER, C W	8305030600	50-305	P
GIESLER, C W	8305040009*	50-305	F
GIESLER, C W	8305050106	50-305	R
GIESLER, C W	8305100102	50-305	P
GIESLER, C W	8305100114	50-305	P
GIESLER, C W	8305100389	50-305	S
GIESLER, C W	8305110003	50-305	P
GIESLER, C W	8305130250	50-305	R
GIESLER, C W	8305170150	50-305	P
GIESLER, C W	8305170267	50-305	S
GIESLER, C. W	8305170323	50-305	S
GIESLER, C W	8305230300	50-305	P
GIESLER, C. W	8305230728	50-305	P
GIESLER, C W	8305270009	50-305	P
GIESLER, C W	8305270198	50-305	S
GIGGEY, C A	8305200473*	50-309	P
GILBERT, L D.	8305230314*	50-458	Q
GILBERT, R A	8305310086	50-237	P
GILDENHORN, A J.	8305110159	CONTRACT	
GILDENHORN, A J	8305200131	CONTRACT	
GILDENHORN, A. J	8305260081	CONTRACT	
GILDNER, M. L	8305030537*	50-440	T
GILINSKY, V	8305230209*	50-320	T
GILINSKY, V	8305230440*	50-289	U
GILLEN, D M	8305130325*	40-8752	
GILLEN, D. M	8305130337	40-8768	
GILLEN, D. M.	8305160259*	40-8675	
GILLEN, J.	8305130123*	50-286	P
GILLMAN, D.	8305110290	50-358	Q
GILMAN, A R	8305060141*	40-672	
GILMAN, A. R.	8305060181*	40-672	
GILMAN, A R	8305120298*	40-672	
GILMAN, A R	8305120381*	70-82	
GILMAN, A R	8305120627*	40-672	
GILRAY, J W	8305100261	50-329	T
GINSBERG, T	8305110237	NUREG	
GIRARD, E H	8305270574*	50-280	Q
GIUFFRIDA, L D	8305060629*	50-247	Q
GIUFFRIDA, L D	8305230474	COMMISSION	
GIUFFRIDA, L D	8305230670	50-3	F
GIUFFRIDA, L D	8305310049	50-247	F
GLASS, S M	8305020419	50-247	Q
GLASSPIEGEL, H	8305040506	50-440	T
GLEASON, J P	8305040464	50-247	Q
GLEASON, J P	8305160133	50-247	Q
GLEASON, J P	8305180143	50-247	Q
GLEISSEN, A	8305160153	50-440	Q
GLENN, J	8305050189	I&E	
GLENN, J	8305120518*	40-672	
GLENN, J E	8305060193*	40-672	
GLENN, J E	8305120507*	40-672	
GLOERSEN, W D	8305270614*	50-346	Q
GLOVER, M S	8305040606*	50-369	F
GODDARD, R J	8305100404	50-155	Q
GODDARD, R J	8305120336	50-461	Q
GODDARD, R. J	8305170552	50-309	Q
GODY	8305100004	50-272	S
GODY	8305110439	50-286	S
GODY, A T	8304110176	I&E	
GODY, A T	8304180554*	70-1143	
GODY, A T	8305020459	50-219	S
GODY, A T	8305030274	50-286	S
GODY, A T.	8305050190*	50-247	Q
GODY, A T	8305120434	50-272	S
GODY, A T.	8305190313*	50-271	Q
GOLDBERG, J H	8305250056	50-498	K
GOLDBERG, J H	8305250058*	50-498	K
GOLDBERG, J H	8305310177	50-498	A
GOLDBERG, J R	8305050053	50-289	Q
GOLDBERG, J R	8305090481	50-289	Q
GOLDBERG, J R	8305100231	50-289	Q
GOLDBERG, J R	8305170039	50-289	Q
GOLDBERG, J R	8305200632	50-289	Q
GOLDBERG, J R	8305240525	50-289	Q
GOLDBERG, M L	8305250337	50-247	Q
GOLDEN, D W	8305110523	NUREG	
GOLDEN, M P	8305120208	50-286	J
GOLDEN, M P	8305160105	50-346	J
GOLDEN, M P	8305160157	50-272	J
GOLDMANN, K	8305230107	71-9015	
GOLDMANN, K	8305230118*	71-9015	
GOLDSTEIN, B L	8305040599*	70-378	
GOLDSTEIN, B L	8305040678*	70-378	
GOLDSTEIN, D B	8305170557	50-522	Q
GOMER, D	8305020288	XPORTLIC	
GOMER, D A	8305090723	XPORTLIC	
GOODIE, J S	8305190379*	50-373	P
GOODMAN, L S	8305020170*	50-409	S
GOODMAN, L S	8305020182*	50-409	S
GOODMAN, M J	8305170225*	50-528	A
GOODWIN, C R	8305020095*	FOIA	
GOODWIN, C R	8305030239*	70-378	
GOODWIN, C R	8305040060*	70-378	
GOODWIN, C R	8305040478*	FOIA	
GORELICK, M S	8305230203	FOIA	
GORMAN, V W	8305110467	NUREG	
GOWER, Q. C	8305120155*	50-445	Q
GOWER, Q. C	8305180096*	FOIA	
GRACE, J. N	8305090013	50-537	E
GRACE, J N	8305240022	50-537	E
GRACE, J N	8305250166	50-537	E
GRACE, J N	8305260001	50-537	L
GRACE, J N	8305260002*	50-537	L
GRAESSER, K L	8305030440	50-304	S
GRAESSER, K L	8305060443	50-295	S
GRAESSER, K L	8305060528	50-295	S
GRAESSER, K L.	8305060567	50-295	S
GRAESSER, K L	8305120013	50-295	R
GRAESSER, K L	8305130196	50-304	S
GRAESSER, K L	8305240214	50-304	S
GRAESSER, K L	8305240311	50-295	S
GRAESSER, K L	8305310160	50-304	S
GRAHAM, E T	8305160145	50-293	S
GRAHAM, E T	8305230538*	50-293	S
GRAMM, R. A	8305050119*	50-443	Q
GRANNIS, A B	8305240541	50-247	H
GRAVES, R H	8305200608	50-213	S
GRAVES, R H	8305270224	50-213	Q
GRAY, E	8305110338*	50-289	Q
GREEN, D. W	8305190132*	FOIA	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
GREEN, D W	8305190153*	FOIA	
GREEN, D W	8305190337*	FOIA	
GREEN, D W	8305190341*	FOIA	
GREEN, H J	8304190499	50-327	S
GREEN, H J	8305030176	50-327	S
GREEN, H J	8305030266	50-296	S
GREEN, H J	8305030569	50-327	S
GREEN, H J	8305050123	50-327	S
GREEN, H J	8305050183	50-327	S
GREEN, H J	8305050211	50-328	S
GREEN, H J	8305050218	50-328	S
GREEN, H J	8305050238	50-260	S
GREEN, H J	8305050266	50-259	S
GREEN, H J	8305100012	50-259	S
GREEN, H J	8305100031	50-260	S
GREEN, H J	8305100081	50-259	S
GREEN, H J	8305100107	50-296	S
GREEN, H J	8305100285	50-260	S
GREEN, H J	8305110325	50-327	S
GREEN, H J	8305110355	50-259	S
GREEN, H J	8305110373	50-327	S
GREEN, H J	8305110409	50-328	S
GREEN, H J	8305130085	50-259	S
GREEN, H J	8305130131	50-260	S
GREEN, H J	8305170030	50-296	S
GREEN, H J	8305170330	50-260	S
GREEN, H J	8305200288	50-260	S
GREEN, H J	8305200420	50-260	S
GREEN, H J	8305200427	50-327	S
GREEN, H J	8305200577	50-327	S
GREEN, H J	8305230530	50-327	S
GREEN, H J	8305250342	50-328	S
GREEN, H J	8305250357	50-260	S
GREEN, H J	8305250380	50-328	S
GREEN, H J	8305250400	50-328	S
GREEN, H J	8305250433	50-328	S
GREEN, H J	8305250526	50-327	S
GREEN, H J	8305250532	50-327	S
GREEN, H J	8305310054	50-296	S
GREENBAUM, R	8305180448*	50-322	H
GREENBAUM, R L	8305190209	50-440	Q
GREENE, G A	8305110237	NUREG	
GREENE, H J	8305250508	50-296	S
GREENKORN, R A	8305060183*	CONTRACT	
GREENMAN, E	8305250238	50-272	S
GREGER, L R	8305060634*	40-8202	
GREGER, L R	8305100402*	50-237	Q
GREGER, L R	8305120353*	50-374	Q
GREGER, L R	8305170353*	50-295	Q
GREGER, L R	8305190161	70-8	
GREGER, L R	8305240026*	50-255	Q
GREGER, L R	8305240292*	50-331	Q
GREGER, L R	8305240340*	40-3392	
GREGG, H	8305250505*	50-289	Q
GREGORY, E	8305180459*	50-322	H
GREGORY, W S	8305110062	RES	
GREGORY, W S	8305110083	RES	
GREGORY, W S	8305130292	RES	
GRELLA, A W	8305120251*	40-672	
GRELLA, A W	8305120614*	FOIA	
GRIER, B H	8305120519*	40-672	
GRIER, B H	8305120523*	40-672	
GRIER, B H	8305120540*	40-672	
GRIFFIN, H B	8305100307*	50-482	Q
GRIFFIN, J	8305260260	50-313	S
GRIMES, B K	8208190078*	50-443	F
GRIMES, B K	8305030474*	50-483	Q
GRIMES, B K	8305100414*	50-155	Q
GROSCUP, G W	8305030456	50-247	P
GROSSMAN, H	8305260172	50-460	Q
GROTENHUIS, M	8305110050	50-305	P
GRUCCI, T. B	8305030023*	FOIA	
GRUCCI, T. B	8305030092*	FOIA	
GRUCCI, T B	8305040244*	FOIA	
GRUCCI, T. B	8305040523*	FOIA	
GRUCCI, T B	8305040578*	FOIA	
GUCWA, L T	8305030261	50-321	H
GUCWA, L T	8305060051	50-321	P
GUCWA, L. T	8305060254	PR	
GUCWA, L T	8305060306	50-321	P
GUCWA, L. T	8305060469	50-321	F
GUCWA, L T	8305160144	50-321	G
GUCWA, L. T	8305160159	50-366	P
GUCWA, L. T.	8305200453	50-321	P
GUCWA, L. T	8305240250	50-366	P
GUCWA, L T	8305250530	50-321	F
GUCWA, L T	8305260298	50-366	P
GUCWA, L T	8305270128	50-321	Q
QUERRY, J E	8305060377	50-238	R
GUILD, R	8305060252	50-413	Q
GUILD, R	8305060252	50-413	Q
GUILD, R	8305310155	50-413	Q
GUINN, P	8305020187*	FOIA	
QUINN, P R	8008250310*	FOIA	
QUINN, P R	8008250337*	FOIA	
QUINN, P R	8008250463*	FOIA	
QUINN, P R	8104030770*	FOIA	
QUINN, P R	8305020010*	FOIA	
QUINN, P R	8305020220*	FOIA	
QUINN, P R	8305030195*	70-378	
QUINN, P R	8305040081*	FOIA	
GULDEMOND, W G	8305240247*	50-373	Q
GUMMESON, P U	8305120279*	40-672	
GUMMO, R	8305120326*	50-320	T
GUPPY, J Q	8305110237	NUREG	
GUSTAFSON, L D	8305060382	PR	
GUSTAVE, R P	8305030707	CONTRACT	
GUSTAVE, R P	8305040660*	CONTRACT	
GUSTAVE, R. P	8305050404*	CONTRACT	
GUSTAVE, R. P	8305060183*	CONTRACT	
GUSTAVE, R P	8305060384*	50-329	A
GUSTAVE, R. P	8305090012*	CONTRACT	
GUSTAVE, R. P	8305090058*	CONTRACT	
GUSTAVE, R P	8305090117*	CONTRACT	
GUSTAVE, R P	8305090131*	CONTRACT	
GUSTAVE, R. P	8305110041*	CONTRACT	
GUSTAVE, R P	8305110236*	CONTRACT	
GUSTAVE, R P	8305110509*	CONTRACT	
GUSTAVE, R P	8305110545*	CONTRACT	
GUSTAVE, R P	8305160332*	50-367	A
GUSTAVE, R P	8305170607*	CONTRACT	
GUSTAVE, R P	8305170614*	CONTRACT	
GUSTAVE, R. P	8305170693*	CONTRACT	
GUSTAVE, R P	8305190514*	CONTRACT	
GUSTAVE, R P	8305200004*	CONTRACT	
GUSTAVE, R P	8305200149*	CONTRACT	
GUSTAVE, R P	8305230289*	CONTRACT	
GUSTAVE, R P	8305270100*	CONTRACT	
GUSTAVE, R P	8305270110*	CONTRACT	
GUSTIN, H L	8305310097*	50-366	Q
GUTMAN, D.	8305030619*	50-247	Q
GUTMAN, D	8305030619*	50-247	Q
GUTMAN, D	8305030619*	50-247	Q
GWYNN, T P.	8305260231*	50-358	Q
HAAS, C F	8305030312*	70-378	
HAAS, C F	8305040217*	FOIA	
HAASS, W P.	8305090632*	50-445	Q
HAASS, W P	8305230004*	50-528	A
HADLEY, C D	8303180429	50-263	P
HAGAN, T F	8305060351*	CONTRACT	
HAGAN, T F.	8305110163*	CONTRACT	
HAGAN, T F	8305200134*	CONTRACT	
HAGAN, T F	8305260222*	CONTRACT	
HAGRMAN, D L	8305110523	NUREG	
HAGUE, R L	8305120468*	50-266	Q
HAHN, G T.	8305110512	NUREG	
HAIRSTON, W G	8305030589*	50-364	S
HAIRSTON, W G	8305050154*	50-348	S
HAIRSTON, W G	8305050158*	50-348	S
HAIRSTON, W G	8305050203*	50-348	S
HAIRSTON, W G	8305100139*	50-364	S
HAIRSTON, W G	8305110260*	50-364	S
HAIRSTON, W G	8305200327*	50-348	R
HAIRSTON, W G	8305200362*	50-364	R
HAIRSTON, W G	8305230544*	50-348	S
HAIRSTON, W G	8305230550*	50-348	S
HAIRSTON, W G	8305250353	50-348	S
HAIRSTON, W. G.	8305250581	50-348	S
HAISLER, R K	8305270625	50-321	S
HAIST, D P.	8305170390*	50-508	Q
HALE, C J	8305020307*	GA999	
HALE, C J	8305050226*	GA999	
HALE, C J	8305200340*	GA999	
HALL, B.	8305100109*	50-324	Q
HALL, B L.	8304280299	50-400	S
HALL, D. P	8304050243	50-461	K
HALL, D P.	8305020111	50-461	Q
HALL, D P	8305040298	50-461	S
HALL, D. P.	8305060576	50-461	Q
HALL, D. P.	8305120475	50-461	S
HALL, D P	8305240413*	50-461	A
HALL, D P	8305240421*	50-461	A
HALL, D P	8305260247*	50-461	A
HALL, D P	8305270017	50-461	A
HALL, D P	8305310129	50-461	B
HALL, D P	8305310183	50-461	B
HALL, R E	8305110119	NUREG	
HALL, R E	8305110237	NUREG	
HAMILTON, J	8305090403*	GA999	
HAMMOND, W J	8305100099	50-312	F
HANCOCK, J A	8305230393	50-302	P
HANDBOY, L	8305200656	50-440	Q
HANNERZ, K	8305230254*	FOIA	
HANNETT, B	8305130301	XPORTLIC	
HANNETT, B A	8305180831	XPORTLIC	
HANNETT, B A	8305190452	XPORTLIC	
HANNETT, B. A	8305260097	XPORTLIC	
HANNUM, W H	8305030688	50-201	P
HANNUM, W H	8305240614	50-201	P
HANSON, Q P	8305050310*	70-378	
HANSON, W A	8305120135*	50-445	Q
HARDIN, A K	8305030256	50-261	S
HARDIN, A K	8305270401*	50-261	Q
HARDING, M R	8304190537*	50-327	S
HARDING, M R	8305030183*	50-327	S
HARDING, M R	8305030579*	50-327	S
HARDING, M. R	8305050128*	50-327	S
HARDING, M R	8305050206*	50-327	S
HARDING, M R.	8305050217*	50-328	S
HARDING, M R	8305050224*	50-328	S
HARDING, M R	8305110329*	50-327	S
HARDING, M. R	8305110382*	50-327	S
HARDING, M R	8305110419*	50-328	S
HARDING, M R	8305200432*	50-327	S
HARDING, M R	8305200581*	50-327	S
HARDING, M R	8305230536*	50-327	S
HARDING, M R	8305250342	50-328	S
HARDING, M R	8305250380	50-328	S
HARDING, M R.	8305250400	50-328	S
HARDING, M R	8305250433	50-328	S
HARDING, M R	8305250526	50-327	S
HARDING, M R	8305250532	50-327	S
HARFSTER, T L	8305040588*	TOPREP	
HARRELL, E W	8305030158	50-338	S
HARRELL, E W	8305030165*	50-338	S
HARRELL, E. W	8305030279	50-339	S
HARRELL, E W	8305030283*	50-339	S
HARRELL, E. W	8305030357	50-339	S
HARRELL, E W	8305030364*	50-339	S
HARRELL, E W	8305030611	50-338	S
HARRELL, E W	8305030615*	50-338	S
HARRELL, E W	8305030635	50-339	S
HARRELL, E W	8305030640*	50-339	S
HARRELL, E. W	8305050186	50-338	S
HARRELL, E W	8305050191*	50-338	S
HARRELL, E. W	8305050210	50-339	S
HARRELL, E W	8305050215*	50-339	S
HARRELL, E W	8305050271	50-339	S
HARRELL, E. W	8305050276*	50-339	S
HARRELL, E. W	8305100023	50-339	S
HARRELL, E. W	8305100029*	50-339	S
HARRELL, E W	8305100259	50-339	S
HARRELL, E W	8305100265*	50-339	S
HARRELL, E W	8305110285	50-338	S
HARRELL, E W	8305110288*	50-338	S
HARRELL, E W	8305110330	50-339	S
HARRELL, E W	8305110336*	50-339	S
HARRELL, E W	8305110453	50-339	S
HARRELL, E W	8305110465*	50-339	S
HARRELL, E W	8305170406	50-338	S
HARRELL, E W	8305170412*	50-338	S
HARRELL, E. W	8305200146	50-338	S
HARRELL, E W	8305200279	50-339	S
HARRELL, E W	8305200284*	50-339	S
HARRELL, E W	8305200574	50-338	S
HARRELL, E. W	8305200583*	50-338	S
HARRELL, E W	8305250288	50-339	S
HARRELL, E W	8305250384	50-339	S
HARRELL, E. W	8305250417	50-338	S
HARRELL, E W	8305270323	50-338	S
HARRELL, E. W	8305270335	50-339	S
HARRELL, P. H	8305050226*	GA999	
HARRINGTON, W. D.	8304180590	50-293	P
HARRINGTON, W. D	8305020134	50-293	R
HARRINGTON, W D.	8305050250	50-293	G

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
HARRINGTON, W D	8305090200	50-293	P
HARRINGTON, W D	8305100138	50-293	R
HARRINGTON, W D	8305110334	50-293	S
HARRINGTON, W D	8305110356	50-293	S
HARRINGTON, W D	8305110384	50-293	S
HARRINGTON, W D	8305130153	50-293	H
HARRINGTON, W D	8305160044	50-293	P
HARRINGTON, W D	8305160061	50-293	P
HARRINGTON, W D	8305160134	50-293	R
HARRINGTON, W D	8305170173	50-293	F
HARRINGTON, W D	8305170345	50-293	P
HARRINGTON, W D	8305170418	50-293	P
HARRINGTON, W D	8305170529	50-293	R
HARRINGTON, W D	8305190024	50-293	S
HARRINGTON, W D	8305190147	50-293	P
HARRINGTON, W D	8305190176	50-293	S
HARRINGTON, W D	8305190326	50-293	S
HARRINGTON, W D	8305200259	50-293	P
HARRINGTON, W D	8305200447	50-293	P
HARRINGTON, W D	8305230434*	50-293	Q
HARRINGTON, W D	8305230450	50-293	F
HARRINGTON, W. D	8305230509	50-293	S
HARRINGTON, W D	8305230516	50-293	S
HARRINGTON, W D	8305230533	50-293	S
HARRINGTON, W D	8305270073	50-293	Q
HARRIS, C L	8305230311*	CONTRACT	
HARRIS, D.	8305170466	50-225	F
HARRIS, J. R	8305270200*	50-537	Q
HARRIS, J R	8305270415*	50-438	Q
HARRIS, J R	8305270551*	50-400	Q
HARRIS, R J.	8305200637*	50-373	P
HARRIS, S	8305250436*	50-483	Q
HARRISON, F.	8305100417*	50-324	R
HART, Q.	8305110584*	COMMISSION	
HARTMAN, S L	8305240465	50-460	Q
HARTMAN, S. L.	8305240465	50-460	Q
HARTMANN, P. L	8305100271*	50-275	Q
HARTZMAN, R M	8305160024	50-247	Q
HARTZMAN, R M	8305160024	50-247	Q
HARVEY, R V	8305240552	71-6550	
HASSE, R.	8305120447*	50-373	Q
HASSE, R A.	8305260250*	50-461	Q
HASSE, R. A.	8305260334*	50-373	Q
HAUGHEY, M F.	8305180054	50-410	A
HAVERKAMP, D	8305110508*	50-333	Q
HAVERKAMP, D. R.	8305250230*	50-286	Q
HAVERKAMP, D R	8305250465*	50-336	Q
HAWKINS, E F	8305170571*	70-8	
HAWKINS, F C.	8305170153*	50-346	Q
HAWKINS, F. C.	8305170315*	50-346	Q
HAWKINS, F. C.	8305190256*	50-331	Q
HAWKINS, F. C.	8305260250*	50-461	Q
HAWKINS, F. C	8305260258*	50-409	Q
HAWKINS, F C	8305260334*	50-373	Q
HAWTHORNE, J. R	8305060347	NUREG	
HAYES, D. W.	8305020339*	50-461	Q
HAYES, D. W	8305100176*	50-454	Q
HAYES, D W.	8305170022*	50-461	Q
HAYES, D W	8305180094*	50-498	Q
HAYES, D. W.	8305190050*	50-329	Q
HAYES, D W.	8305240268*	50-456	Q
HAYNES, R. C.	8201070110*	40-672	
HAZELTINE, J	8305110089*	50-373	P
HEAD, Q F	8305270508*	50-366	Q
HEALEY, J. A	8305240517	50-247	H
HEATHERLY, T. L.	8305270303*	50-390	Q
HEBEL, C	8305130220*	50-254	S
HEDDLESON, F. A	8305110120	NUREG	
HEIDER, L. H.	8305240343	50-271	V
HEIDER, L H.	8305240358	50-29	P
HEIDER, L. H.	8305250569	50-271	P
HEIMBACH, L.	8305240312	50-247	F
HEISHMAN, R. F.	8305120155*	50-445	Q
HEISHMAN, R. F.	8305260255*	50-397	Q
HELD, J. T.	8303310020*	50-333	P
HELD, J T	8303310020*	50-333	P
HELFRICH, R. E	8305180342	PR	
HELGESON, K. A.	8305260371	70-820	
HELLER, J	8305020348*	50-315	Q
HELLER, J K	8305200247*	50-255	Q
HELLER, J. K.	8305240037*	50-255	Q
HELTEMES, C. J.	8304010159*	MISC	
HELTEMES, C. J.	8304040591*	MISC	
HELTEMES, C. J	8304140328*	MISC	
HELTEMES, C. J.	8305040730	50-259	P
HELTEMES, C J	8305230511	MISC	
HELTEMES, C J	8305230519*	MISC	
HELTEMES, C J	8305230524*	MISC	
HENRY, L Q	8305100252	50-57	S
HENRY, P. C	8305110380	50-302	S
HENRY, W. O	8305060382	PR	
HENSLEY, K D	8305050099	70-143	
HENSLEY, K D	8305200658	70-143	
HERDT, A R	8305270179*	50-389	Q
HERING, R F	8305030257	50-315	P
HERING, R F	8305090363	50-315	R
HERING, R F	8305160054	50-315	R
HERING, R F	8305160121	50-315	P
HERING, R F	8305260281	50-315	P
HERMANN, R	8305170027	50-220	P
HERNAN, R W	8305040336	50-329	E
HERNANDEZ, G H	8305260242*	50-275	Q
HERR, J C	8305060277*	50-244	P
HERR, R K	8305100307*	50-482	Q
HERRINGTON, F A	8305060383*	50-298	I
HERSCH, M M	8305260057*	XPORTLIC	
HERSCH, M M	8305260070	XPORTLIC	
HESSON, G M.	8301060137*	50-309	P
HIATT, S L	8305040528	50-440	Q
HIATT, S L	8305040541	50-440	Q
HIATT, S L	8305040544	50-440	Q
HIATT, S L	8305090234	FOIA	
HIATT, S L	8305170305	50-440	Q
HIATT, S L	8305170341	50-440	Q
HIATT, S L	8305180347	PR	
HIATT, S L	8305180404	PR	
HICKEY, J W	8305020201*	FOIA	
HICKEY, J W.	8305040297*	FOIA	
HICKEY, J W.	8305040408*	FOIA	
HICKEY, J W	8305130006*	40-672	
HICKEY, J W.	8305130016*	40-672	
HICKEY, J W	8305130053*	40-672	
HICKIN, R A	8305270105*	CONTRACT	
HICKS, M M	8305240454	50-247	Q
HIGGINBOTHAM, L	8305090582	WASTE MGT	
HIGGINBOTHAM, L.	8305090617	WASTE MGT	
HIGGINBOTHAM, L	8305110218	WASTE MGT	
HILL, D W	8305060383*	50-298	I
HILL, R T	8305100370*	50-325	P
HILL, T. D.	8305130113	50-400	S
HILL, T K	8305200598	50-440	Q
HILL, T K	8305200656	50-440	Q
HILL, W H	8305170224*	50-498	Q
HIND, J	8305270152	50-255	S
HIND, J A.	8303280177	40-2061	
HIND, J A	8305100379	50-237	Q
HIND, J A	8305100387*	50-237	Q
HIND, J. A.	8305100409*	50-155	Q
HIND, J. A	8305170138	50-266	Q
HIND, J. A	8305190343	50-263	F
HIND, J A	8305200458	50-315	F
HIND, J. A	8305270486	50-305	Q
HIND, J A	8305270493*	50-305	Q
HINDS, J M.	8305240268*	50-456	Q
HINMAN, W. S	8305020158*	FOIA	
HINRICHS, G	8305030380*	50-247	S
HINRICHS, G	8305030407*	50-247	S
HINRICHS, G	8305160025*	50-247	S
HIPSHER, W M	8305110134	27-48	
HIPSHER, W M	8305110155	27-48	
HIRSCH, D	8305170325	50-142	Q
HIRSCH, D	8305200496	50-142	Q
HIRSCH, D.	8305200652	50-142	Q
HOAGLAND, R G.	8305110512	NUREG	
HODGDON, A P	8305060339	50-352	Q
HODGDON, A P	8305260322	50-352	Q
HODGES, W.	8103300276*	50-416	A
HOGAN, C. F.	8305190209	50-440	Q
HOGAN, J. J	8305240517	50-247	H
HOLBROOK, W W	8305100349*	GA999	
HOLBROOK, W. W.	8305100355*	GA999	
HOLCOMBE, J. C	8305120178	50-206	H
HOLDEN, C. F	8305250450*	50-271	Q
HOLDER, E T	8305050245*	50-260	S
HOLDER, E T.	8305050272*	50-259	S
HOLDER, E T.	8305100014*	50-259	S
HOLDER, E. T.	8305170034*	50-296	S
HOLLAND, S A	8305250271*	50-289	P
HOLLORAN, R W.	8305240144	TOPREP	
HOLLORAN, R. W	8305240154*	TOPREP	
HOLMBECK, P	8305170569*	50-454	
HOLMBECK, P	8305170569*	50-454	
HOLMBECK, P	8305170569*	50-454	
HOLMES-RAY, P	8305270550*	50-366	
HOLODY, D J	8305130223*	50-271	
HOLONICH, J J	8305250193	50-482	
HOLONICH, J J	8305250231	50-482	
HOLT, R R	8305030629*	50-247	
HOLT, R R	8305030629*	50-247	
HOLT, R R	8305030629*	50-247	
HOLWAY, F I	8305250331	50-443	
HOLYOAK, R H	8305190084*	50-373	
HOLYOAK, R H	8305190145*	50-373	
HOLZMER, M	8305020348*	50-315	
HOPCRAFT, C P	8305240031	71-9163	
HOPPER, A	8305130299	CONTRACT	
HOPPER, A	8305180785	CONTRACT	
HORIN, W A	8305050018	50-445	
HORIN, W A.	8305050018	50-445	
HORIN, W A	8305100267	50-445	
HORIN, W A	8305100267	50-445	
HORIN, W A	8305130260	50-445	
HORIN, W A	8305130260	50-445	
HORIN, W A	8305180449	PR	
HORTON, B M	8305040287*	FOIA	
HOSEY, C M	8305270265*	50-280	
HOSEY, C M	8305270384*	50-250	
HOUSTEAU, L	8305240403*	GA999	
HOUSTON, D	8305250150	50-416	
HOUSTON, R W	8304140161*	50-352	
HOUSTON, R W	8305020090*	50-373	
HOUSTON, R. W	8305170378*	50-373	
HOUSTON, R W	8305170388*	50-373	
HOUTS, P S	8305270040*	50-320	
HOUTS, P S	8305270046*	50-320	
HOVI, L	8305240356	50-445	
HOWARD, A T	8305190108*	50-329	
HOWARD, A T	8305190179*	50-373	
HOWARD, A T	8305190207*	FOIA	
HOWARD, T R	8305030705	40-8584	
HOWE, P W	8305030288	50-324	
HOWE, P W	8305030463	50-324	
HOWE, P W	8305060176	50-325	
HOWE, P W	8305200597	50-324	
HOWE, P W	8305200625	50-324	
HOWE, P W	8305240434	50-324	
HOWE, R. S	8305200314	50-309	
HOYLE, A	8305040552	CONTRACT	
HOYLE, A.	8305060246	CONTRACT	
HOYLE, A	8305110190	CONTRACT	
HOYLE, A	8305110194	CONTRACT	
HOYLE, A	8305130356	CONTRACT	
HOYLE, A	8305180038	50-247	
HOYLE, J	8305060468	50-247	
HOYLE, J C	8305060250	50-277	
HOYLE, J C	8305060258	50-289	
HOYLE, J C	8305090499	50-537	
HOYT, H F	8304250241	50-443	
HOYT, H. F	8305030570	50-443	
HOYT, H F	8305060463	50-443	
HOYT, H F	8305090508	50-443	
HOYT, H F	8305100200	50-443	
HOYT, H F	8305130181	50-443	
HOYT, H F.	8305170478	50-443	
HOYT, H F	8305240451	50-443	
HOYT, H F	8305270598	50-443	
HSIEH, D	8305170101	NUREG	
HSU, Y Y	8305270109	NUREG	
HU, C. K	8305100281*	50-352	
HUANG, A Y	8305100281*	50-352	
HUBACEK, W Q	8305180075*	50-498	
HUBBARD, K. S	8305190209	50-440	
HUBBARD, M J	8305200656	50-440	
HUBBARD, R B	8305260183*	50-275	
HUDSON, S. D	8305200392*	50-220	
HUDSPETH, J B	8305060621*	50-348	
HUEBNER, L Q	8305030592*	50-461	
HUETER, L. J	8305240292*	50-331	
HUFFMAN, D N	8305270297*	50-335	
HUFFMAN, D N	8305270387*	50-269	
HUFFMAN, D N	8305270466*	50-302	
HUGHES, J	8305030516*	50-454	
HUGHES, J	8305030516*	50-454	
HUGHES, J	8305030516*	50-454	
HUGHES, J	8305030516*	50-454	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
HUGHES, P G	8305110390*	50-302	S
HUGHES, P G	8305131088*	50-302	S
HUKILL, H D	8305020232*	50-289	G
HUKILL, H D	8305030075	50-289	S
HUKILL, H D	8305030102	50-289	S
HUKILL, H D	8305030436	50-289	S
HUKILL, H D	8305060394	50-289	P
HUKILL, H D	8305060458	50-289	R
HUKILL, H D	8305060649	50-289	R
HUKILL, H D	8305090453	50-289	P
HUKILL, H D	8305110286	50-289	S
HUKILL, H D	8305110333	50-289	S
HUKILL, H D	8305110346	50-289	S
HUKILL, H D	8305120055	50-289	P
HUKILL, H D	8305130065	50-289	P
HUKILL, H D	8305130070*	50-289	P
HUKILL, H D	8305130180	50-289	F
HUKILL, H D	8305190158	50-289	P
HUKILL, H D	8305190240	50-289	R
HUKILL, H. D	8305200173	50-289	P
HUKILL, H D	8305200502	50-289	P
HUKILL, H D	8305200547	50-289	S
HUKILL, H D	8305250269	50-289	P
HUKILL, H. D	8305260085	50-289	G
HUKILL, H D	8305260094	50-289	P
HUKILL, H D	8305270203	50-289	R
HUKILL, H D	8305310205	50-289	P
HULMAN, L G	8305100248*	50-329	T
HUNNICUTT, D M	8305100009*	50-192	G
HUNNICUTT, D M	8305100142*	50-458	G
HUNNICUTT, D M	8305100249*	50-445	G
HUNNICUTT, D M	8305230314*	50-458	G
HUNNICUTT, D M	8305230449*	50-445	G
HUNNUM, W H	8305230015	50-201	P
HUNSTAD, A A	8305240153	50-306	S
HUNSTAD, A A	8305240166	50-282	S
HUNT, M D	8305270101*	50-389	G
HUNTER, D R	8305260231*	50-358	G
HUNTER, R S	8305160104	50-315	P
HUNTER, R S	8305240086*	50-315	G
HUNTER, R S	8305310088	50-315	P
HURFORD, W J	8305040362	50-261	P
HURFORD, W J	8305240004	50-324	P
HURFORD, W J	8305250493*	PR	
HURSH, J B	8305060200*	40-672	
HWANG, T	8305030250	XPORTLIC	
HYLKA, R	8305060517*	50-237	S
IAVENDITTI, A	8305270075	50-220	S
IBEN, C A	8305020154*	50-254	S
IDEKER, R L	8305030694	70-143	
IDEKER, R L	8305190033	70-143	
IGNATONIS, A	8305030374	50-491	S
IGNATONIS, A	8305110262	50-370	S
IGNATONIS, A	8305130186	50-370	S
IGNATONIS, A	8305270160*	50-369	G
IGNATONIS, A	8305310174	50-369	S
IGNATONIS, A J	8305270334*	50-413	G
IGNATONIS, A J	8305270411*	50-269	G
IGNATONIS, A J	8305270482*	50-537	G
IGNATONIS, A J	8305270602*	50-413	G
ILBERG, D	8305110126	50-312	P
IMS, J	8305110027	NUREG	
IPPOLITO, T. A	8305030704	MISC	
IRBY, B J	8305030272*	50-296	S
IRWIN, G R	8305110512	NUREG	
IRWIN, R B	8305240517	50-247	H
ISLEY, T	8305130205*	50-346	S
ISLEY, T	8305240341	50-346	S
ISSEROW, S	8305120268*	40-672	
JABBOUR, K N	8305020028	50-413	E
JABBOUR, K N	8305240021	50-413	E
JABBOUR, K N	8305250211	50-413	G
JACKIW, I N.	8305020356*	50-305	G
JACKIW, I N	8305120468*	50-266	G
JACKIW, I N	8305240061*	50-282	G
JACKSON, G	8305060154*	71-9175	
JACKSON, J	8305250535*	PR	
JACKSON, K	8305090653	WASTE MGT	
JACKSON, L	8305270278*	50-537	G
JACKSON, L H	8305270442*	50-338	G
JACOBS, R	8305250238	50-272	S
JACQUES, P	8305020078*	50-316	S
JACQUES, P	8305020151*	50-315	S
JACQUES, P H	8305130101*	50-315	S
JAFFE, D H	8305040783	50-317	P
JAFFE, D H	8305170246	50-317	P
JAFFE, D H	8305180556	50-317	P
JAFFE, D H	8305180768	50-317	P
JAFFE, H	8305240441	50-247	H
JAIN, H	8305020547	NUREG	
JAKUBAITIS, T C	8305060544*	50-295	S
JAKUBAITIS, T C	8305240214	50-304	S
JANO, J C	8305110277*	50-317	G
JAPE, F	8305270151*	50-369	G
JAPE, F	8305270245*	50-389	G
JAPE, F	8305270306*	50-416	G
JAPE, F	8305270367*	50-335	G
JAPE, F	8305270453*	50-389	G
JAPE, F	8305270470*	50-416	G
JAPE, F	8305270521*	50-369	G
JAPE, F	8305270526*	50-259	G
JAPE, F	8305270562*	50-390	G
JAPE, F	8305270587*	50-251	G
JARBOE, E D	8305180183	40-8035	
JAUDON, J P	8305100361*	50-313	G
JAUDON, J P	8305230348*	50-313	G
JENISON, K M	8305130142	50-280	S
JENKINS, G R	8305270116*	70-1113	
JENKINS, G R	8305270297*	50-335	G
JENKINS, G R	8305270387*	50-269	G
JENKINS, G R	8305270427*	50-416	G
JENKINS, G R	8305270446*	50-395	G
JENKINS, G R	8305270466*	50-302	G
JENNINGS, F	8305050257*	50-128	P
JERMAN, P C	8305120303*	40-672	
JERMAN, P C	8305120310*	40-672	
JERMAN, P C	8305120372*	40-672	
JO, J	8305110131	NUREG	
JOHNSON, A	8305170564*	50-528	G
JOHNSON, B D	8305020138	50-255	S
JOHNSON, B D	8305020173	50-255	S
JOHNSON, B D	8305040475	50-255	G
JOHNSON, B D	8305060388	50-255	S
JOHNSON, B D	8305100076	50-255	R
JOHNSON, B D	8305100170	50-255	P
JOHNSON, B D	8305100378	50-255	S
JOHNSON, B D	8305100396	50-255	S
JOHNSON, B D	8305130140	50-255	S
JOHNSON, B D	8305130208	50-255	S
JOHNSON, B D	8305130225	50-255	S
JOHNSON, B D	8305240011	50-255	S
JOHNSON, B D	8305240043	50-255	G
JOHNSON, B D	8305240371*	50-255	G
JOHNSON, B D	8305240410	50-255	R
JOHNSON, B D	8305310168	50-255	S
JOHNSON, B D	8305310197	50-255	S
JOHNSON, B D	8305310202	50-255	S
JOHNSON, B W	8206100204	RES	
JOHNSON, C E	8305100142*	50-458	G
JOHNSON, C E	8305230314*	50-458	G
JOHNSON, E H	8305200256*	50-382	G
JOHNSON, F	8305110089*	50-373	P
JOHNSON, G E	8305030504	50-413	G
JOHNSON, G E	8305030576	50-413	G
JOHNSON, G E	8305050080	50-413	G
JOHNSON, G E	8305100232	50-413	G
JOHNSON, G. E	8305110462	50-413	G
JOHNSON, G E	8305130036	50-413	G
JOHNSON, G E	8305170556	50-413	G
JOHNSON, G E	8305230055	50-413	G
JOHNSON, J	8305160142*	50-293	G
JOHNSON, J. C	8305110147	WASTE MGT	
JOHNSON, J D	8305310210	NUREG	
JOHNSON, L	8305030213*	70-378	
JOHNSON, L	8305030278*	70-378	
JOHNSON, L	8305030286*	70-378	
JOHNSON, L	8305030323*	70-378	
JOHNSON, P H	8305170437*	50-89	G
JOHNSON, T C	8305090670	WASTE MGT	
JOHNSON, T L	8305030086	40-1341	
JOHNSON, T L	8305250199	40-7869	
JOHNSON, T L	8305250270	40-8786	
JOHNSON, T. L	8305250593	40-8786	
JOHNSON, W	8305230475*	50-285	G
JOHNSON, W D	8304150154*	50-313	G
JOHNSON, W D	8305100116*	50-482	G
JOHNSON, W D	8305100160*	50-482	G
JOHNSON, W D	8305100244*	50-285	G
JOHNSON, W. D	8305100361*	50-313	G
JOHNSON, W D	8305230348*	50-313	G
JOHNSON, W D	8305230480*	50-482	G
JOHNSON, W K	8305250548*	50-483	G
JOHNSON, W K	8305250548*	50-483	G
JOHNSTON, G	8305170382*	50-528	G
JONES, D W	8305270167*	70-143	
JONES, D W	8305310022*	70-1201	
JONES, W C	8305030156	50-285	P
JONES, W C	8305030429*	50-285	F
JONES, W C	8305040619*	50-285	F
JONES, W C	8305060069	50-285	I
JONES, W C	8305060186	50-285	P
JONES, W C	8305120603*	50-285	F
JONES, W C	8305160027	50-285	P
JONES, W. C.	8305160111	50-285	R
JONES, W C	8305170465	50-285	R
JONES, W C	8305240474	50-285	P
JONESON, B J	8305120471*	40-215	
JONESON, B J	8305120476*	40-215	
JORDAN, E L	8303040021	50-3	G
JORDAN, E L	8303040023	50-3	G
JORDAN, E. L	8303040025	50-3	G
JORDAN, E L	8303040026	50-3	G
JORDAN, E L	8303040027	50-3	G
JORDAN, E L.	8303040028	50-3	G
JORDAN, E L	8303040030	50-3	G
JORDAN, E L	8303040031	50-3	G
JORDAN, E. L.	8303040033	50-3	G
JORDAN, E L	8303040034	50-3	G
JORDAN, E L	8303040040	50-3	G
JORDAN, E L	8303040046	50-3	G
JORDAN, H	8305270011*	50-261	P
JORDAN, M.	8305020511	50-331	S
JORDAN, M J	8305020480*	50-10	G
JORDAN, M J	8305100218*	50-331	G
JORDAN, W. H	8305270634	50-382	G
JORDAN, W S	8305160002	50-443	G
JORDAN, W S	8305160002	50-443	G
JORDAN, W S	8305160019	50-443	G
JORDAN, W S	8305160019	50-443	G
JORGENSEN, B L	8305200247*	50-255	G
JORGENSEN, B L	8305240037*	50-255	G
JOSHUA, C	8305240517	50-247	H
JOY, J	8305240454	50-247	G
JOYNER	8305100004	50-272	S
JOYNER, J.	8305030459	50-354	S
JOYNER, J	8305120434	50-272	S
JOYNER, J H	8305020459	50-219	S
JOYNER, J. H.	8305030294	50-286	S
JULIAN, C	8305270219*	50-250	G
JULIAN, C	8305270439*	50-280	G
JULIAN, C	8305270544*	50-338	G
JULIAN, C. A.	8305100098	50-250	S
JULIAN, C A.	8305130142	50-280	S
JULIAN, C. A.	8305270455*	50-338	G
JULIAN, C A	8305270490*	50-280	G
JUNGE, M A	8305110363*	50-317	S
JUNGE, M A	8305190352*	50-318	S
JUNGE, M. A.	8305230560*	50-317	S
KAHLE, J B.	8305250537	70-143	
KAHLE, J B	8305270121*	50-302	G
KAHLE, J B	8305270469*	50-111	G
KALIVIANAKIS, N	8305020142	50-254	S
KALIVIANAKIS, N	8305030321	50-254	S
KALIVIANAKIS, N	8305060390	50-254	S
KALIVIANAKIS, N.	8305090231	71-6346	
KALIVIANAKIS, N	8305130212	50-254	S
KALIVIANAKIS, N.	8305170372	50-254	R
KALIVIANAKIS, N	8305240317	50-254	S
KALIVIANAKIS, N	8305240321	50-254	S
KALIVIANAKIS, N.	8305260286	50-265	S
KALIVIANAKIS, N	8305310142	50-254	S
KALIVIANAKIS, N.	8305310152	50-265	S
KALKWARF, D. R	8305060674	NUREG	
KALKWARF, D. R	8305110457	NUREG	
KALMAN, K L	8305250283	40-8697	
KALNINS, A	8305250271*	50-289	P
KAMMER, D S	8305030543	50-390	E
KAMMER, D. S	8305040633*	50-259	F
KAMMER, D S	8305130029	50-327	P
KAMMER, D S	8305130041	50-327	F
KAMMER, D S	8305240394	50-327	P
KAMMER, D. S.	8305250473	50-259	P
KAMMER, D. S.	8305270233*	50-390	G
KAMMER, D. S.	8305270592*	50-438	G
KAMMERER, C	8305180221*	50-498	A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
KAMMERER, C	8305230199*	50-320	T
KAMMERER, C	8305260401*	50-358	A
KANGA, B K	8305030462	50-320	R
KANGA, B K	8305030527	50-320	S
KANGA, B K	8305060082	50-320	F
KANGA, B K	8305110321	50-320	S
KANGA, B K	8305110370	50-320	S
KANGA, B K	8305120015	50-320	H
KANGA, B K	8305120312	50-320	T
KANGA, B K	8305170435	50-320	P
KANGA, B K	8305170448	50-320	P
KANGA, B K	8305200563	50-320	F
KANGA, B K	8305240348	50-320	R
KANGA, B, K	8305250255	50-320	P
KANGA, B K	8305250385	50-320	R
KANGA, B K	8305310001	50-320	S
KANGA, B K	8305310058	50-320	P
KANGA, B K	8305310118	50-320	P
KANGA, B K	8305310156	50-320	P
KANTOR, F.	8305170058*	50-289	G
KAPLAN, C	8305030608	50-247	G
KAPLAN, C	8305240532	50-247	G
KAPLAN, C	8305240532	50-247	G
KARMAN, M	8305170002	50-482	G
KARMAN, M	8305170555	50-261	G
KARSCH, R. D	8305030474*	50-483	G
KASTENBERG, W E.	8305130326	ACRS	
KAUFMAN, P H	8305260182	50-275	G
KAUFMANN, J. E	8305130361*	CONTRACT	
KAVANAUGH, P F	8305060351*	CONTRACT	
KAWACHI, M.	8305170738	71-9033	
KAY, J A	8305060192	50-29	F
KAY, J A	8305060215	50-29	F
KAY, J. A.	8305100228	50-29	P
KAY, J A	8305110010	50-29	F
KAY, J. A.	8305170459	50-29	P
KAY, J A	8305240364	50-29	P
KEARNEY, B	8305030711	40-2259	
KEARNEY, B.	8305060222	40-8348	
KEARNEY, B	8305160276	40-299	
KEARNEY, J. J	8305180358	PR	
KEARNEY, J J	8305250420	PR	
KEARNY, B.	8305130312	40-2259	
KEATING, D. E	8305120348*	50-461	G
KEATING, D E	8305120420*	50-373	G
KEATING, D E.	8305190183*	50-255	G
KEATING, D E	8305260231*	50-358	G
KEATING, L A	8305100225*	50-322	G
KEIMIG	8305060558	50-277	S
KEIMIG, R	8305030094	50-289	S
KEIMIG, R	8305030450	50-272	S
KEIMIG, R	8305030534	50-289	S
KEIMIG, R.	8305060387	50-277	S
KEIMIG, R	8305100258	50-272	S
KEIMIG, R.	8305160199*	50-289	G
KEIMIG, R. R	8305170051*	50-289	G
KEIMIG, R R	8305190266*	50-219	G
KEISER, H W	8305030334	50-387	S
KEISER, H W	8305060442	50-387	S
KEISER, H. W	8305060592	50-387	S
KEISER, H W.	8305110241	50-387	S
KEISER, H. W	8305110348	50-387	S
KEISER, H W	8305110421	50-387	S
KEISER, H W	8305120422	50-387	S
KEISER, H W	8305160124	50-387	S
KEISER, H W.	8305160132	50-387	S
KEISER, H W	8305160140	50-387	S
KEISER, H. W.	8305200555	50-387	S
KEISER, H W.	8305200640	50-387	S
KEISER, H W.	8305230471	50-387	S
KEITH, H. N.	8305110264*	50-333	S
KEITH, H N	8305110408*	50-333	S
KEITH, H N	8305110416*	50-333	S
KELLEY, D. L.	8305170318*	50-445	G
KELLEY, J L.	8305040412	50-400	G
KELLEY, J. L	8305170472	50-413	G
KELLEY, W. D.	8305030475*	GA999	
KELLEY, W D.	8305040200*	FOIA	
KELLEY, W. D	8305270307*	GA999	
KELLY, E M.	8305030353*	50-309	G
KELLY, J A	8305020436	50-313	G
KELLY, J. A	8305030308*	70-846	
KELLY, J. A	8305260304*	50-298	G
KELLY, R. B.	8305030461	PR	
KELLY, W J	8305240397	50-275	S
KELLY, W J	8305270249	50-275	S
KEMPER, J S	8305020335	50-352	A
KEMPER, J S	8305050202	50-352	G
KEMPER, J S	8305060507	50-352	A
KEMPER, J S	8305100275	50-352	A
KEMPIAK, A J	8305190332*	50-373	P
KEMPIAK, A J	8305190365*	50-373	P
KENDALL, R	8212070092*	MISC	
KENNEDY, D M	8305110396	50-255	R
KENNEDY, R P	8305170544*	50-329	A
KENNEDY, R T	7909180214*	50-498	S
KENNY, T J	8305100410*	50-286	G
KENNY, T J	8305250230*	50-286	G
KENYON, B D	8305100016	50-387	P
KENYON, B D	8305100019*	50-387	P
KENYON, B D	8305270255	50-387	G
KENYON, T J	8305240660	50-390	A
KEPPLER, J G	7911150353*	FOIA	
KEPPLER, J G	8305020336	50-461	G
KEPPLER, J G	8305020339*	50-461	G
KEPPLER, J G	8305060410	50-295	G
KEPPLER, J G	8305090549*	50-358	T
KEPPLER, J G	8305100124	50-329	T
KEPPLER, J G	8305130258	50-409	G
KEPPLER, J G	8305170392	50-329	H
KEPPLER, J G	8305170458	50-454	G
KEPPLER, J G	8305190269	50-358	G
KEPPLER, J G	8305190329*	50-373	G
KEPPLER, J G	8305190384*	50-373	G
KEPPLER, J G	8305200454	50-358	A
KEPPLER, J G	8305200558	50-358	A
KEPPLER, J G	8305240080	40-2061	
KEPPLER, J G	8305240380	50-266	G
KEPPLER, J G	8305240406	50-461	A
KEPPLER, J G	8305240407	50-461	A
KEPPLER, J G	8305250144*	50-373	F
KEPPLER, J. G	8305260246	50-461	A
KEPPLER, J G	8305260310	50-329	G
KEPPLER, J G	8305260405*	50-358	T
KERCH, H	8305250575*	50-387	G
KERN, P	8305180459*	50-322	H
KERNS, M	8305130120*	50-286	P
KERR, G W	8305170137	NUREG	
KESHISHIAN, P I	8305120155*	50-445	G
KESSLER, P J	8305240517	50-247	H
KETZLACH, N	8305240559	70-2983	
KETZLACH, N	8305240563	70-2983	
KEUPER, J S	8305250135*	50-352	A
KEY, W J	8305020360*	50-331	G
KEY, W J	8305120449*	50-237	G
KHLAFALLAH, M Z	8305100281*	50-352	A
KIBLER, D R	8305240221	50-331	S
KIBLER, D R.	8305270429	50-331	S
KIEL, G R.	8305170584	XPORTLIC	
KIEL, G R.	8305170616	XPORTLIC	
KIEL, G R	8305170621*	XPORTLIC	
KIEL, G R	8305180067	XPORTLIC	
KIEL, G R	8305180073*	XPORTLIC	
KIEL, G R	8305180833	XPORTLIC	
KIEL, G. R	8305260018	XPORTLIC	
KIEL, G R	8305260064	XPORTLIC	
KIMBRELL, M	8305270011*	50-261	P
KINCAID, R H	8305170544*	50-329	A
KING, J P.	8305240342	50-322	A
KINNEMAN, J.	8305050187	I&E	
KINNEMAN, J.	8305050193	I&E	
KINNEMAN, J. D	8112160259*	40-672	
KINNEMAN, J. D	8305050166*	40-3079	
KINNEMAN, J. D	8305060189*	40-672	
KINNEMAN, J. D	8305060214*	40-672	
KINNEMAN, J. D	8305120530*	40-672	
KINNEMAN, J. D	8305120630*	40-672	
KINNEMAN, J. D	8305130031*	40-672	
KINNEMAN, J. D	8305130037*	40-672	
KINNEY, W W	8305020332*	50-57	G
KINNEY, W W.	8305050236*	50-97	G
KINNEY, W. W	8305110395*	50-225	G
KINNEY, W. W.	8305250456*	50-184	G
KINNEY, W W	8305270208*	50-184	G
KINTNER, L L	8305120022	50-358	A
KIRK, W F.	8305250582*	70-371	
KIRKMAN, R W	8305120257*	40-672	
KIRSCH, D F	8305060580	50-275	S
KIRSCH, D F	8305130187	50-275	S
KIRSCH, D F.	8305160009	50-275	S
KIRSCH, D F	8305170339*	50-275	G
KIRSCH, D F	8305170361*	50-361	G
KIRSCH, D F	8305170365*	50-206	G
KIRSCH, D F	8305170420*	50-361	G
KIRSCH, D F	8305170421*	50-361	G
KIRSCH, D F	8305170432*	50-89	G
KIRSCH, D F	8305170437*	50-89	G
KIRSCH, D F	8305170480*	50-361	G
KIRSCH, D F	8305260262*	50-275	G
KIRSCH, D F	8305260272*	50-275	G
KIRSLIS, S S	8305100166*	50-443	G
KISH, J N	8305170153*	50-546	G
KISISEL, I T	8305190303*	50-373	P
KISTER, H	8305100410*	50-286	G
KISTER, H B	8305100433*	50-247	G
KISTER, H B	8305110391*	50-333	G
KISTER, H B	8305110509*	50-333	G
KISTER, H B	8305190334*	50-410	G
KISTER, H B	8305200392*	50-220	G
KISTER, H B	8305250230*	50-286	G
KISTER, H B	8305250453*	50-244	G
KISTER, H B	8305250538	50-286	G
KITLER, E J	8305120330*	50-320	T
KLEIN, D	8305100005	50-192	P
KLEINSORGE, W P	8305270402*	50-369	G
KLEINSORGE, W P	8305270406*	50-400	G
KLEINSORGE, W P	8305270478*	50-395	G
KLEVIN, P B	8305120234*	40-672	
KLIMA, D L	8305110296	50-410	D
KLINGLER, G	8305090397	50-272	G
KLINGLER, G	8305240439	I&E	
KMETYK, L N	8305310209	NUREG	
KNAPP, M R	8305090572	WASTE MGT	
KNAPP, P J	8305120310*	40-672	
KNAPP, P J	8305120372*	40-672	
KNEPPEL, D S	8305120269*	70-82	
KNICELEY, J. R	8305030521*	50-264	G
KNICELEY, J R	8305100365*	50-156	G
KNICELEY, J R	8305200482*	70-925	
KNIEL, K.	8305060155*	FOIA	
KNIGHT, M R	8305260233	50-546	F
KNIGHTON, G W	8305020306	50-400	A
KNIGHTON, G W	8305020590	50-389	E
KNIGHTON, G W	8305030022*	50-389	P
KNIGHTON, G W	8305060278	50-389	P
KNIGHTON, G W	8305060303*	50-389	P
KNIGHTON, G W	8305060683	50-361	P
KNIGHTON, G W	8305110179	50-361	P
KNIGHTON, G W	8305110182*	50-361	P
KNIGHTON, G W	8305110188*	50-361	P
KNIGHTON, G W	8305130332	50-443	A
KNIGHTON, G W	8305130335	50-443	A
KNIGHTON, G W	8305170229	50-361	P
KNIGHTON, G W	8305170236*	50-361	P
KNIGHTON, G W.	8305170577	50-400	A
KNIGHTON, G W	8305180024	50-275	P
KNIGHTON, G W	8305180025*	50-275	P
KNIGHTON, G W	8305180032*	50-275	P
KNIGHTON, G W	8305200122	50-400	D
KNIGHTON, G W	8305200125*	50-400	D
KNIGHTON, G W	8305200197	50-400	D
KNIGHTON, G W	8305200205	50-400	D
KNIGHTON, G W	8305200209	50-400	D
KNIGHTON, G W	8305230003	50-528	A
KNIGHTON, G W	8305230263	50-412	A
KNIGHTON, G W	8305230273	50-528	E
KNIGHTON, G. W	8305230296	50-400	E
KNIGHTON, G. W	8305240038	50-528	A
KNIGHTON, G W	8305260038	50-443	E
KNOP, R C	8305020339*	50-461	G
KNOP, R C	8305170013	50-461	G
KNOP, R C.	8305240264	50-456	G
KOESTER, G L	8305020421	50-482	F
KOESTER, G L	8305030354	50-482	S
KOESTER, G L	8305030378	50-482	S
KOESTER, G L	8305030492	50-482	S
KOESTER, G L	8305030622*	50-482	G
KOESTER, G L	8305060346*	50-482	F
KOESTER, G L	8305200335	50-482	S
KOESTER, G L	8305230489*	50-482	G
KOESTER, G. L	8305230567	50-482	I
KOESTER, G L	8305310110*	50-482	G
KOESTER, G L	8305310148	50-482	S
KOLTAY, P	8305100433*	50-247	G
KOMES, J M	8305200593*	GA999	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
KONKLIN, J E	8305020285*	50-341	G
KONKLIN, J. E	8305030537*	50-440	T
KOSINSKY, E J	8305110491	NUREG	
KOSLA, B	8305120129	40-3392	
KOSLA, B	8305170724	40-3392	
KOSMAN, H D	8305060383*	50-298	I
KOUTS, H J	8305110237	NUREG	
KRAFT, D C.	8305200196*	50-148	G
KRAUL, C W	8305020169*	FOIA	
KRAUL, C W	8305040294*	FOIA	
KRAUL, C W	8305050333*	70-378	
KRAUL, C W	8305050339*	70-378	
KRAUSE, D F	8305060414*	50-315	S
KRAUSE, D F	8305240374*	50-315	S
KRAUSE, R W	8305120439*	50-298	S
KRAVITS, D L	8305170070*	CONTRACT	
KRECHTING, J E	8305030271	50-275	R
KRECHTING, J E	8305030538	50-275	R
KRECHTING, J E	8305100173	50-275	R
KRECHTING, J E	8305120203	50-275	R
KRECHTING, J E	8305170511	50-275	R
KRECHTING, J E	8305180377	50-275	R
KRECHTING, J E	8305230213	50-275	R
KRECHTING, J E	8305230556	50-275	R
KRECHTING, J E	8305250466	50-275	R
KRECHTING, J E	8305310186	50-275	R
KRICH, R M.	8305030155	50-255	S
KRICH, R M	8305030642	50-255	S
KRICH, R M.	8305100306	50-255	S
KRIEGER, R W	8305100377	50-206	P
KRIEGER, R W	8305120166	50-206	P
KRIEGER, R W	8305120189	50-206	P
KRIMM, R W	8305060506	50-247	G
KRIMM, R W	8305100122	50-295	F
KRIMM, R W	8305100143	50-289	F
KROONZEK, A L	8305120573	FOIA	
KRUG, H E	8305270587*	50-251	G
KUCZYNSKI, L A	8305030338*	50-387	S
KUCZYNSKI, L A	8305060598*	50-387	S
KUCZYNSKI, L A	8305110247*	50-387	S
KUCZYNSKI, L A	8305110358*	50-387	S
KUCZYNSKI, L A	8305160151*	50-387	S
KUCZYNSKI, L A	8305200646*	50-387	S
KUHNS, W G	8305020465*	50-219	I
KUNDER, G A	8305120335*	50-320	T
KUNISHI, H	8305110398*	50-334	P
KUNKEL, T C	8305270575	50-247	H
KUSHNER, W	8305030459	50-354	S
KUZO, G B	8305270354*	50-302	G
KWOK, K	8305160043	50-20	S
LABAT, V	8305200134*	CONTRACT	
LACEY, W S	8305030311	50-334	S
LACEY, W S	8305110343	50-334	S
LACEY, W S	8305120402	50-334	S
LACEY, W S	8305160058	50-334	S
LACEY, W. S	8305191185	50-334	S
LACEY, W S	8305230520	50-334	S
LADUN, R	8305050193	I&E	
LAFLAMME, S J	8305230483*	50-309	S
LAFLEUR, J D	8305230251*	FOIA	
LAGRANGE, R G	8305100419*	50-443	G
LAGRANGE, R G	8305100424*	50-443	G
LAINAS, G C	8305060355	50-247	P
LALK, H	8305250363*	50-483	G
LALK, H	8305250363*	50-483	G
LAMB, C	8305170581*	50-454	G
LAMB, C	8305170581*	50-454	G
LAMB, C	8305170581*	50-454	G
LAMBERT, N E	8305160129	50-262	P
LANDERS, D F	8305270001	50-322	A
LANDGRAF, L C	8305090480	50-341	F
LANDGRAF, L. C	8305090480	50-341	F
LANDIS, K D	8305200430	50-335	S
LANDRIEU, P R H	8305250387	50-354	R
LANDSMAN, R B	8305100217	50-329	T
LANDSMAN, R B	8305100261	50-329	T
LANE, V M	8305270553	50-322	G
LANIK, G	8305040745*	50-259	P
LANKFORD, J	8305090461*	50-395	G
LANKFORD, J B	8305270167*	70-143	
LANKFORD, J B	8305310022*	70-1201	
LANKFORD, J. B	8305310134*	70-1113	
LANKSBURY, R D	8305090313*	50-373	G
LANKSBURY, R D	8305170403*	50-373	G
LANKSBURY, R D	8305240247*	50-373	G
LANKSBURY, R D	8305260224*	50-440	G
LANPHER, L C	8305050001	50-322	G
LANPHER, L C	8305050001	50-322	G
LANPHER, L C	8305100157	50-322	G
LANPHER, L C	8305100157	50-322	G
LANPHER, L C	8305180341	PR	
LARIZZA, G F	8305230564*	50-244	S
LARSON, C E	8305180352	50-263	G
LASSAHN, G D	8305110482	NUREG	
LATHAM, S B	8305100201	50-322	G
LATHAM, S B	8305180449	PR	
LATHAM, W K	8305060413	50-312	P
LATHAM, W K	8305060429	50-312	P
LATHAM, W K	8305130160	50-312	S
LAURENSON, J A	8305090496	50-482	G
LAURENSON, J A	8305090503	50-482	G
LAURENSON, J A	8305160131	50-322	G
LAWSON, L T	8305260261	50-269	J
LAYFIELD, R L	8305030207*	70-378	
LAYFIELD, R L	8305030212*	70-378	
LAYFIELD, R L	8305030264*	70-378	
LAYFIELD, R L	8305030304*	70-378	
LAYFIELD, R L	8305030309*	70-378	
LAYFIELD, R L	8305030332*	70-378	
LAYFIELD, R L	8305040587*	70-378	
LAZARUS, W	8305030450	50-272	S
LAZARUS, W J	8305250465*	50-336	G
LAZO, L	8305170186	50-412	F
LAZO, L	8305170199	50-412	C
LAZO, L	8305310234	50-412	F
LE FEBVRE, B J	8305100273*	50-334	G
LE, N B	8305120155*	50-445	G
LEAVERTON, W	8305240317	50-254	S
LEDDICK, R S	8305030489	50-508	S
LEDDICK, R S	8305160049	50-508	S
LEE, B S	8305110127	NUREG	
LEE, M R	8305120264*	40-672	
LEE, N R	8305310102	50-458	I
LEE, O R	8305050214	50-267	P
LEE, O R	8305050222*	50-267	P
LEE, R	8305270109	NUREG	
LEE, T D	8305200318*	70-143	
LEE, T D	8305270613*	70-143	
LEECH, P H	8305110219	50-336	P
LEFAVE, W T	8305100166*	50-443	G
LEIDICH, G R.	8305040516*	50-440	T
LEMON, C E	8305200575*	50-329	A
LEMPGES, T E	8304110516	50-220	R
LEMPGES, T E	8305060426	50-220	S
LEMPGES, T E	8305060533	50-220	S
LEMPGES, T E	8305160097	50-220	R
LEMPGES, T E	8305170393	50-220	R
LEMPGES, T. E	8305200283	50-220	S
LEMPGES, T E	8305200383*	50-220	G
LENAHAN, J J	8305270236*	50-389	G
LENAHAN, J J	8305270348*	50-400	G
LENAHAN, J J	8305270379*	50-389	G
LENAHAN, J J	8305270632*	50-400	G
LENTINE, F G	8305040317	50-295	P
LENTINE, F G	8305170218	50-295	P
LENTINE, F G	8305200351	50-295	G
LENTINE, F G	8305240473	50-295	P
LENTINE, F G	8305240506	50-295	P
LENTINE, F G	8305250077	50-295	P
LEONARD, J R	8305160286*	50-369	F
LEPEL, E A	8305110457	NUREG	
LESSY, R P	8305030517	27-39	
LESSY, R. P	8305060329	50-443	G
LESSY, R P	8305100158	50-443	G
LESSY, R P	8305100219	50-443	G
LESSY, R P	8305100221*	50-443	G
LESSY, R. P	8305100334	50-443	G
LESSY, R P	8305100356	50-443	G
LESSY, R P	8305100375*	50-443	G
LESSY, R. P	8305100392*	50-443	G
LESSY, R P.	8305100411*	50-443	G
LESSY, R. P	8305100425*	50-443	G
LESSY, R. P	8305100430*	50-443	G
LESSY, R. P	8305100432*	50-443	G
LETSCHE, K J	8305120297	50-322	G
LETSCHE, K. J	8305120297	50-322	G
LETSCHE, K J	8305120329	50-322	G
LETSCHE, K J	8305120329	50-322	G
LEVI, I	8305160028*	50-247	G
LEVI, I	8305160028*	50-247	G
LEVI, R P	8305230006	ADVCM	
LEVI, R P	8305230010*	ADVCM	
LEVI, R P.	8305230017*	ADVCM	
LEVI, R P	8305230025*	ADVCM	
LEVI, R P	8305230032*	ADVCM	
LEVI, R P	8305230040*	ADVCM	
LEVI, R P	8305230048*	ADVCM	
LEVIN, H	8305200553	50-329	A
LEVIN, H A	8304220515	50-329	A
LEVIN, H A	8305200575*	50-329	A
LEVIN, H A	8305310198	50-329	R
LEVIN, H A	8305310203*	50-329	R
LEVINE, D L	8305260004*	71-5552	
LEVINE, J M	8305060591*	50-313	F
LEVINE, J M	8305260249	50-368	S
LEVINE, S	8305230039*	FOIA	
LEVINE, S	8305230057*	FOIA	
LEVINE, S H	8305180353	PR	
LEWIS, H	8305180678*	ACRS	
LEWIS, J P	8305180047*	50-247	P
LEWIS, K. S	8305160177	50-352	G
LEWIS, M I	8305030418	PR	
LEWIS, M I	8305200441	PR	
LEWIS, M I	8305200456	PR	
LEWIS, M I	8305240516	50-352	G
LEWIS, N. D	8305310076	50-460	G
LEWIS, R C	8305100098	50-250	S
LEWIS, R C.	8305270202	50-259	G
LEWIS, R C	8305270280	50-302	G
LEWIS, R C	8305270345	50-259	G
LEWIS, R C	8305270349	50-389	G
LEWIS, R C	8305270362*	50-259	G
LEWIS, R. C.	8305270365*	50-389	G
LEWIS, R C	8305270394	50-338	G
LEWIS, R C	8305270412	50-395	G
LEWIS, R C	8305270421*	50-338	G
LEWIS, R C	8305270433*	50-395	G
LEWIS, R C	8305270437*	50-338	G
LEWIS, R C	8305270474*	50-261	G
LEWIS, R C	8305270479	50-261	G
LEWIS, R C	8305270494*	50-261	G
LEWIS, R C	8305270499	50-302	G
LEWIS, R C	8305270507	50-389	G
LEWIS, R C	8305270509*	50-302	G
LEWIS, R C	8305270512	50-395	G
LEWIS, R C	8305270519*	50-395	G
LEWIS, R. C	8305270527*	50-280	G
LEWIS, R C	8305270529*	50-389	G
LEWIS, R C	8305270559	50-335	G
LEWIS, R. C	8305270579*	50-335	G
LEWIS, R C	8305270580	50-324	G
LEWIS, R. C	8305270596*	50-416	G
LEWIS, R C	8305270621*	50-324	G
LIANG, C Y	8305100166*	50-443	G
LICHTENBERGER	8305200072	TOPREP	
LICITRA, E A	8305110022	50-528	A
LICITRA, E A	8305170219	50-528	A
LICITRA, E. A	8305240253	50-528	A
LIDEN, E A	8305050013	50-272	P
LIDEN, E. A	8305090457	50-272	P
LIDEN, E A	8305110007	50-311	P
LIDEN, E. A	8305110154	50-272	P
LIDEN, E A.	8305170328	50-272	P
LIDEN, E. A.	8305230094	50-311	P
LIDEN, E. A	8305230304	50-272	P
LIEBERMAN, J.	8305040545*	50-155	G
LIEBLER, G. H	8305040247*	50-3	F
LIN, D L	8305110452*	50-373	R
LINDELL, M	8305270046*	50-320	P
LINDER, F	8305020146	50-409	S
LINDER, F	8305100025	50-409	P
LINDER, F.	8305120066	50-409	P
LINDER, F	8305130112*	50-409	G
LINDER, F	8305160050	50-409	F
LINDER, F.	8305230398	50-409	P
LINDER, F.	8305240327	50-409	G
LINDER, F.	8305310169	50-409	F
LINDSAY, F J	8305130211*	50-304	S
LINDSAY, I D	8305100328	50-458	G
LINEHAN, J J	8305030086	40-1341	
LINEHAN, J J	8305060369*	40-8783	
LINEHAN, J. J	8305130319	40-4492	
LINEHAN, J J	8305130333*	40-8783	
LINEHAN, J J	8305130336	40-8663	
LINEHAN, J. J.	8305170585	40-8084	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LINEHAN, J J	8305170595	40-8064
LINEHAN, J J	8305250199	40-7869
LINEHAN, J J	8305250270	40-8786
LINEHAN, J J	8305250275	40-8786
LINEHAN, J J	8305250279	40-8786
LINEHAN, J J	8305250283	40-8697
LINEHAN, J J	8305250593	40-8786
LINNEMANN, R E	8305250428*	50-483 G
LINNEMANN, R E	8305250428*	50-483 G
LINNEMANN, R E	8305250458*	50-483 G
LINNEMANN, R E	8305250458*	50-483 G
LINNEMANN, R E	8305250468*	50-483 G
LINNEMANN, R E	8305250468*	50-483 G
LINNEMANN, R E	8305250482*	50-483 G
LINNEMANN, R E	8305250482*	50-483 G
LINVILLE, J C	8305110391*	50-333 G
LIPINSKI, W.C	8305130340	ACRS
LIPINSKI, W C	8305130340	ACRS
LIPINSKI, W C	8305130349	50-937 O
LIPINSKI, W C	8305130349	50-537 O
LISEND, R T	8305110514*	50-333 S
LITTLE, B H	8305020285*	50-341 G
LITTLE, G. V	8305130141*	50-260 S
LITTLE, W. S.	8304120409	50-373 G
LITTLE, W S	8304150362	50-440 G
LITTLE, W. S	8305020358	50-331 G
LITTLE, W S	8305040518	50-305 G
LITTLE, W S	8305120345	50-461 G
LITTLE, W S	8305120361	50-374 G
LITTLE, W. S	8305120364*	50-374 G
LITTLE, W. S	8305120415	50-373 G
LITTLE, W S	8305120440	50-237 G
LITTLE, W S	8305120444*	50-237 G
LITTLE, W. S	8305190019	50-454 G
LITTLE, W S	8305190178	50-255 G
LITTLE, W S	8305190233	50-454 S
LITTLE, W S	8305260236	50-440 G
LITTLE, W S	8305260239*	50-440 G
LITTLE, W S	8305310113	50-237 G
LIU, W C	8305270492*	50-400 G
LIU, W. C	8305270537*	50-438 G
LIVERMORE, H H	8305170022*	50-461 G
LLOYD, M	8305240023*	50-537 U
LOCHBAUM, D A.	8305100083*	50-259 S
LOCHBAUM, D. A	8305250357	50-260 S
LONGENECKER, J	8305060524	50-537 E
LONGENECKER, J	8305170449	50-537 A
LONGENECKER, J	8305200459	50-537 B
LONGENECKER, J.	8305230113	50-537 A
LONGENECKER, J	8305230285	50-537 A
LOOKABAUGH, A	8305090592*	50-445 G
LOTITO, E.	8305200584*	50-317 R
LOTITO, E. M	8305200564	50-317 R
LOTTS, A. L	8305030025	RES
LOUDERBACK, T E.	8305160232	40-8714
LOUDERBACK, T E	8305260383	40-8714
LOVE, R. S.	8305120428*	50-546 G
LOVENDALE, P.	8305240002	50-266 S
LOVENDALE, P C	8305100402*	50-237 G
LOVENDALE, P C.	8305170353*	50-295 G
LOVENDALE, P C.	8305240026*	50-255 G
LOWREY, A.	8305020550*	FOIA
LOWREY, A	8305040501*	FOIA
LUCK, W D.	8303240390	50-537 G
LUCK, W. D	8305110220	50-537 G
LUCK, W. D	8305190339	50-537 G
LUCK, W. D.	8305200636	50-537 G
LUCK, W. D.	8305200648*	50-537 G
LUCK, W D.	8305240475	50-537 G
LUCK, W. D.	8305240480	50-537 G
LUCK, W. D	8305240503	50-537 G
LUCK, W. D.	8305310188	50-537 G
LUCKAS, W J	8305110119	NUREG
LUDWIG, W. C.	8305110329*	50-327 S
LUDWIG, W. C	8305110382*	50-327 S
LUDWIG, W. C	8305200432*	50-327 S
LUDWIG, W. C.	8305230536*	50-327 S
LUDWIG, W. C	8305250380	50-328 S
LUDWIG, W C	8305250532	50-327 S
LUEBKE, E. A	8305030592	50-142 G
LUEBKE, E. A	8305060520	50-142 G
LUEBKE, E. A	8305100330	50-142 G
LUEBKE, E. A.	8305130076	50-142 G
LUEBKE, E. A.	8305130079	50-142 G
LUEBKE, E. A.	8305130150	50-142 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
LUEBKE, E A	8305160163	50-142 G
LUKZ, F J	8305270100*	CONTRACT
LUNDVALL, A E	8305020344*	50-317 G
LUNDVALL, A E	8305060402	50-317 P
LUNDVALL, A E	8305060412	50-317 G
LUNDVALL, A E	8305190293	50-317 P
LUNDVALL, A E	8305200620	50-317 G
LUNDVALL, A E	8305200628*	50-317 G
LUNDVALL, A E	8305200631	50-317 R
LUTKEN, D. C	8305230608	50-416 P
LUTKIN, M H	8305260388	40-229
LUZA, K V	8305090162	NUREG
LYNCH, M D	8305110620	50-341 F
LYNCH, M D	8305120231	50-341 A
LYNCH, M D	8305230207	50-341 A
LYNCH, M D	8305250219	50-341 F
LYNCH, D. D	8305180030	50-368 P
LYNCH, D D	8305180041*	50-368 P
LYNN, D L	8305110232*	CONTRACT
LYONS, J E	8305110214	50-29 P
LYONS, P. J	8305260386	40-299
LYONS, P J	8305260395	40-299
LYONS, P J	8305260399*	40-299
MA, J S.	8305030474*	50-483 G
MA, J. S.	8305270501*	50-454 G
MACDONALD, C	8305090214	71-6708
MACDONALD, C E	8305020002	71-9177
MACDONALD, C E	8305020004*	71-9177
MACDONALD, C E	8305020008*	71-9177
MACDONALD, C E	8305030716	71-9105
MACDONALD, C E	8305030720*	71-9105
MACDONALD, C. E	8305040096	71-9181
MACDONALD, C. E	8305040147	71-9079
MACDONALD, C E	8305040700	71-1
MACDONALD, C. E.	8305040772	71-9106
MACDONALD, C. E	8305040782	71-5332
MACDONALD, C E	8305040786	71-9901
MACDONALD, C E	8305040791	71-6553
MACDONALD, C E	8305050436	71-9135
MACDONALD, C E	8305060133	71-9175
MACDONALD, C E	8305060187	71-6294
MACDONALD, C E	8305060190*	71-6294
MACDONALD, C E	8305060208	71-5979
MACDONALD, C E	8305060212*	71-5979
MACDONALD, C E	8305090048	71-5814
MACDONALD, C E.	8305090056*	71-5814
MACDONALD, C E	8305090113	71-5980
MACDONALD, C E.	8305090121*	71-5980
MACDONALD, C E	8305090133	71-5875
MACDONALD, C E	8305090140*	71-5875
MACDONALD, C E	8305090145	71-5874
MACDONALD, C E	8305090150*	71-5874
MACDONALD, C E	8305110011	71-9103
MACDONALD, C E	8305110013*	71-9103
MACDONALD, C E	8305110015	71-4986
MACDONALD, C. E	8305110017	71-9111
MACDONALD, C E	8305110019	71-9080
MACDONALD, C E	8305110021	71-9049
MACDONALD, C E	8305110023	71-6717
MACDONALD, C E.	8305110033	71-9901
MACDONALD, C. E	8305110035*	71-9901
MACDONALD, C. E	8305110143	71-9044
MACDONALD, C E	8305110150	71-9100
MACDONALD, C E	8305110151*	71-9100
MACDONALD, C E	8305110211	71-9079
MACDONALD, C. E.	8305110612	71-9788
MACDONALD, C E	8305110614*	71-9788
MACDONALD, C E	8305130256	71-493
MACDONALD, C E	8305130261*	71-493
MACDONALD, C E	8305160278	71-6495
MACDONALD, C E.	8305160280	71-9096
MACDONALD, C E	8305170097	71-4986
MACDONALD, C. E	8305170102*	71-4986
MACDONALD, C. E	8305170108	71-9010
MACDONALD, C. E	8305170113*	71-9010
MACDONALD, C E	8305170245	71-9015
MACDONALD, C. E	8305170251*	71-9015
MACDONALD, C. E	8305170255	71-9151
MACDONALD, C. E	8305170260*	71-9151
MACDONALD, C. E.	8305170586	71-6346
MACDONALD, C E.	8305170587	71-9081
MACDONALD, C E.	8305170589	71-6601
MACDONALD, C. E.	8305170591	71-9151
MACDONALD, C. E	8305170592	71-9148
MACDONALD, C. E.	8305180630*	71-5607

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
MACDONALD, C E	8305240556*	71-6550
MACDONALD, C E	8305260350	71-9151
MACDONALD, P E	8305110523	NUREG
MACKAY, S D	8305180040	50-324
MADDEN, W	8305020459	50-219
MADEDA, T J	8305030521*	50-264
MADEDA, T J	8305060418*	50-295
MADEDA, T J	8305130234*	70-1300
MADEDA, T J	8305200482*	70-925
MADSEN, G L	8305030157	50-458
MADSEN, G L	8305090066	50-128
MADSEN, G L	8305100137	50-458
MADSEN, G L	8305100247	50-445
MADSEN, G L	8305120373	50-445
MADSEN, G L	8305170004	50-382
MADSEN, G L	8305170212	50-498
MADSEN, G L	8305170309	50-445
MADSEN, G L	8305170329	50-298
MADSEN, G L	8305200192	50-148
MADSEN, G L	8305200251	50-382
MADSEN, G L	8305200328	50-298
MADSEN, G L	8305200416	50-445
MADSEN, G L.	8305200516	50-267
MADSEN, G L	8305200666	50-445
MADSEN, G L	8305230305	50-458
MADSEN, G. L	8305230445	50-445
MADSEN, G. L	8305230566	50-267
MADSEN, G L	8305240003	50-445
MADSEN, G L	8305260301	50-298
MADSEN, G. L	8305310090	50-267
MADSEN, G L	8305310229	50-267
MAGNUSON, L	8305060052	XPORTLIC
MAGNUSON, L	8305180818	XPORTLIC
MAGNUSON, L	8305260060	XPORTLIC
MAIER, J E	8305030021	50-244
MAIER, J E	8305030352	50-244
MAIER, J E	8305050248*	50-244
MAIER, J E.	8305060271	50-244
MAIER, J E	8305060404	50-244
MAIER, J E	8305110065	50-244
MAIER, J E	8305110318	50-244
MAIER, J E	8305130084	50-244
MAIER, J E	8305160114	50-244
MAIER, J E	8305190170	50-244
MAIER, J E	8305190234	50-244
MAIER, J E	8305230452	50-244
MAIER, J. E.	8305230561	50-244
MAIER, J. E	8305270578*	50-244
MAIER, J E	8305310020	50-244
MAIER, J E	8305310085	50-244
MAIER, J. E	8305310125	50-244
MAIER, J. E	8305310218	50-244
MAIER, J. E	8305310232	50-244
MALLETT, R H	8305230292*	50-537
MALLORY, C W	8305040159*	71-9079
MALLORY, C W	8305230730	71-9151
MALLORY, C W	8305260355*	71-9151
MALLOY, E A	8305240517	50-247
MALODY, C W	8305100178	70-1257
MALODY, C W	8305100184	70-1257
MALODY, C W	8305180642	70-1257
MALONEY, J M	8305170576*	50-454
MALONEY, J M	8305170576*	50-454
MALONEY, J M	8305170576*	50-454
MANGAN, C V	8304210238	50-410
MANGAN, C V	8305030515	50-410
MANGAN, C V	8305040483	50-220
MANGAN, C V.	8305040493*	50-220
MANGAN, C V	8305050020	50-220
MANGAN, C V	8305050031*	50-220
MANGAN, C V.	8305100272	50-220
MANGAN, C. V	8305110315	50-410
MANGAN, C. V	8305130028	50-410
MANGAN, C. V	8305160015	50-220
MANGAN, C. V	8305200345	50-220
MANGAN, C. V	8305230574	50-410
MANGAN, C. V	8305240402	50-220
MANGAN, C. V	8305240498	50-410
MANGAN, C. V	8305260086	50-410
MANGAN, C V.	8305270026	50-220
MANGAN, C. V	8305270075	50-220
MANLEY, J	8305130086*	50-244
MANNO, S. F	8305120334	50-410
MANNO, S. F	8305120392	50-410
MANNO, S F.	8305140093	50-410

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MANNO, S F	8305250430	50-410	S
MANNO, S F	8305270645*	50-410	G
MANSER, W C	8305030699	70-143	
MANSER, W C	8305180852	70-143	
MANSER, W C	8305190003	70-143	
MANSER, W C	8305240051	71-143	
MARCHAL, J	8305020005	XPORTLIC	
MARCHAL, J	8305020096	XPORTLIC	
MARCHAL, J	8305090010	XPORTLIC	
MARCONNET, J	8305270011*	50-261	P
MARCUS, G F	8305200655*	50-373	P
MARCUS, G F	8305200665*	50-373	P
MARCUS, G F	8305200675*	50-373	P
MARCUSON, W F	8305110041*	CONTRACT	
MARCUSON, W F	8305170607*	CONTRACT	
MARELLO, S L	8305190102*	50-329	G
MARELLO, S L	8305190296*	50-373	G
MARGULIES, M B	8305100413	50-261	G
MARGULIES, M B	8305170483	50-508	G
MARGULIES, M B	8305270014	50-261	G
MARIANI, L P	8305110012	PR	
MARIANI, L P	8305250517	PR	
MARKEY, E J	8305230388*	50-289	U
MARKEY, E J	8305230735*	COMMISSION	
MARSHALL, J R	8303240480	50-313	P
MARSHALL, J R	8304270426*	50-313	F
MARSHALL, J R	8305020373	50-368	S
MARSHALL, J R	8305020416	50-368	P
MARSHALL, J R	8305030331*	50-313	G
MARSHALL, J R	8305030385	50-313	S
MARSHALL, J R	8305040453	50-313	R
MARSHALL, J R	8305050125	50-313	P
MARSHALL, J R	8305050216	50-313	P
MARSHALL, J R	8305060452	50-313	S
MARSHALL, J R	8305090333	50-313	P
MARSHALL, J R	8305090421	50-313	J
MARSHALL, J R	8305090440	50-313	P
MARSHALL, J R	8305100351	50-313	P
MARSHALL, J R	8305120414	50-313	S
MARSHALL, J R	8305120451*	50-313	G
MARSHALL, J R	8305160290*	50-313	F
MARSHALL, J R	8305170551	50-313	G
MARSHALL, J R	8305190363	50-313	J
MARSHALL, J R	8305200319*	50-313	G
MARSHALL, J R	8305200326	50-313	F
MARSHALL, J R	8305200445	50-313	S
MARSHALL, J R	8305200490	50-313	S
MARSHALL, J R	8305200541	50-313	P
MARSHALL, J R	8305200573	50-368	R
MARSHALL, J R	8305200580	50-368	P
MARSHALL, J R	8305230364	50-313	P
MARSHALL, J R	8305230723	50-368	P
MARSHALL, J R	8305240054*	50-313	G
MARSHALL, J R	8305240139	50-313	H
MARSHALL, J R	8305240360	50-368	P
MARSHALL, J R	8305240399	50-313	P
MARSHALL, J R	8305260260	50-313	S
MARSHALL, J R	8305270065	50-313	P
MARSHALL, J R	8305310199*	50-313	G
MARSHALL, J S	8305090517*	50-445	T
MARSHALL, W H	8305120005	FOIA	
MARSHALL, W J	8305120338*	50-320	T
MARSTON, R R	8305270116*	70-1113	
MARTIN	8305120364	50-354	S
MARTIN, D E	8305090576	WASTE MGT	
MARTIN, D E	8305090679	WASTE MGT	
MARTIN, D. E	8305090705	WASTE MGT	
MARTIN, D E	8305110183	WASTE MGT	
MARTIN, D. E	8305170599	40-299	
MARTIN, D E	8305250597	40-299	
MARTIN, J	8305050164*	50-397	G
MARTIN, J B	8305030069	PR	
MARTIN, J B	8305100011	50-346	F
MARTIN, J B	8305260264	50-361	G
MARTIN, J B	8305260270	50-275	G
MARTIN, R A	8305130292	RES	
MARTIN, R E	8305110072	50-352	F
MARTIN, R E	8305110079	50-352	A
MARTIN, R E	8305130026	50-352	A
MARTIN, R E	8305190012	50-352	A
MARTIN, R E.	8305200170	50-352	A
MARTIN, T J.	8305060470	50-354	S
MARTIN, T. J.	8305110255	50-354	S
MARTIN, T J	8305170490*	50-354	G
MARTIN, T T	8304180541	70-1143	
MARTIN, T T	8304250152	70-2953	
MARTIN, T T	8305020258	50-272	G
MARTIN, T T	8305020386	50-309	G
MARTIN, T T	8305020395	50-213	G
MARTIN, T T	8305050132	70-466	
MARTIN, T T	8305050134	70-1402	
MARTIN, T T	8305050141	50-277	G
MARTIN, T T	8305050144	50-293	G
MARTIN, T T	8305050161	40-3079	
MARTIN, T T	8305050176	70-1224	
MARTIN, T T	8305050187	50-247	G
MARTIN, T T	8305050246	50-244	G
MARTIN, T T	8305110261	50-277	G
MARTIN, T T	8305110276	50-317	G
MARTIN, T T	8305110314	50-309	G
MARTIN, T T	8305110331	50-289	G
MARTIN, T T	8305120378	50-322	G
MARTIN, T T	8305160018	50-219	G
MARTIN, T T	8305190163	50-272	G
MARTIN, T T	8305190187	50-271	G
MARTIN, T T	8305190310	50-271	G
MARTIN, T T	8305190350	70-371	
MARTIN, T T	8305200382	50-220	G
MARTIN, T T	8305200436	50-334	G
MARTIN, T T	8305230455	50-289	G
MARTIN, T T	8305230505	TOPREP	
MARTIN, T T	8305230571	50-309	P
MARTIN, T T	8305240227	50-29	G
MARTIN, T T	8305240285	50-272	G
MARTIN, T T	8305250291	50-219	G
MARTIN, T T	8305250299	50-277	G
MARTIN, T T	8305250310	50-309	G
MARTIN, T T	8305250314*	50-309	G
MARTIN, T T	8305250480	50-271	G
MARTIN, T T	8305250488	50-412	G
MARTIN, T T	8305250495	50-289	G
MARTIN, T T	8305250503	50-286	G
MARTIN, T T	8305250571	50-387	G
MARTIN, T T	8305270033	50-423	G
MARTIN, T T	8305270274	50-333	G
MARTIN, T T	8305270361	TOPREP	
MARTIN, T T	8305270392	50-333	G
MARTIN, W J	8305060233	NUREG	
MARTINOVICH, M	8305020114*	50-373	S
MARUCUT, C R	8305030592*	50-461	R
MASON, C C	8305240323	50-327	R
MASSARO, S A	8305040740	NUREG	
MAST, L	8305200598	50-440	G
MASTERSON, V	8305240381	50-373	S
MASTERSON, V	8305270193	50-373	S
MASTERSON, V V	8305060509*	50-373	S
MATHENY, D C	8305130195*	50-346	S
MATHEWS, T. P	8305170470*	50-285	R
MATHIS, C J.	8304110696	50-293	S
MATHIS, C J	8305230535	50-293	R
MATHIS, C J	8305230537*	50-293	R
MATHIS, J	8305270367*	50-335	G
MATHIS, J L	8305270562*	50-390	G
MATTHEWS, B A	8305030477	50-261	H
MATTHEWS, B A	8305030486	50-261	G
MATTHEWS, B A	8305030493	50-261	G
MATTHEWS, B A	8305180299	50-261	G
MATTHEWS, B A	8305180452	50-261	G
MATTHEWS, H	8305250580*	50-483	G
MATTHEWS, H	8305250580*	50-483	G
MATTIA, M J	8305090300*	CONTRACT	
MATTIA, M J	8305110232*	CONTRACT	
MATTIA, M J	8305120150*	CONTRACT	
MATTIA, M J	8305160312*	50-247	G
MATTIA, M J	8305160316*	50-247	G
MATTIA, M J	8305180560*	CONTRACT	
MATTIA, M J	8305180562*	CONTRACT	
MATTIA, M J	8305230249*	CONTRACT	
MATTIA, M J	8305230274*	CONTRACT	
MATTIA, M J	8305240369*	FOIA	
MATTIA, M J	8305260087*	CONTRACT	
MATTIMOE, J J	8305230583	50-312	P
MATTSON, R J	8305030587*	50-312	P
MATTSON, R J	8305250221*	50-361	P
MATTSON, R J	8305260396	TOPREP	
MAURA, F A	8304120412*	50-373	G
MAURIN, L V	8305020341	50-382	A
MAURIN, L V	8305020411	50-382	S
MAURIN, L V	8305020450	50-382	S
MAURIN, L V	8305020479	50-382	S
MAURIN, L V	8305050017	50-382	R
MAURIN, L V	8305060367	50-382	S
MAURIN, L V	8305060425	50-382	S
MAURIN, L V	8305060566	50-382	S
MAURIN, L V.	8305060587	50-382	S
MAURIN, L V	8305130019	50-382	S
MAURIN, L V	8305170223	50-382	S
MAURIN, L V	8305170265	50-382	S
MAURIN, L V	8305170327	50-382	S
MAURIN, L V	8305170351	50-382	S
MAURIN, L V	8305170484	50-382	S
MAURIN, L V	8305170492	50-382	S
MAURIN, L V	8305170500	50-382	S
MAURIN, L V	8305180468	50-382	A
MAXWELL, G F	8305030537*	50-440	T
MAXWELL, G F	8305270308*	50-400	G
MAXWELL, G F	8305270631*	50-400	G
MAXWELL, J C	8305130347	50-443	G
MAXWELL, J C	8305130347	50-443	G
MAY, D C	8304280121	PR	
MAYWEATHER, L	8304150372*	50-341	R
MCALPINE, E J	8305200318*	70-143	
MCALPINE, E J	8305270145*	70-1151	
MCALPINE, E J.	8305270159*	70-1113	
MCALPINE, E J	8305270167*	70-143	
MCALPINE, E J	8305270254*	70-1201	
MCALPINE, E J	8305270304*	50-332	G
MCALPINE, E J	8305270480*	70-1151	
MCALPINE, E J	8305270556*	70-27	
MCALPINE, E J	8305270613*	70-143	
MCALPINE, E J	8305270648*	70-143	
MCALPINE, E J	8305310022*	70-1201	
MCALPINE, E J	8305310134*	70-1113	
MCBREARTY, R A	8305250295*	50-219	G
MCBRIDE, L M	8305050146	50-267	F
MCCABE	8305030118	50-278	S
MCCABE	8305060530	50-317	S
MCCABE	8305060558	50-277	S
MCCABE	8305110258	50-388	S
MCCABE	8305120412	50-277	S
MCCABE, E	8305020337	50-278	S
MCCABE, E.	8305060387	50-277	S
MCCABE, E. C	8305030208*	50-317	G
MCCABE, E. C.	8305110149	50-387	G
MCCANN	8305110258	50-388	S
MCCARTY, C L.	8305030709	40-8728	
MCCLINTOCK, R	8305120454*	40-672	
MCCLINTOCK, R	8305120507*	40-672	
MCCLINTOCK, R	8305120518*	40-672	
MCCLINTOCK, R D	8305060156*	40-672	
MCCLINTOCK, R D	8305120462*	40-672	
MCCLINTOCK, R. D	8305120472*	FOIA	
MCCLUSKEY, G	8305160156	50-440	G
MCCOLLUM, W	8305030628*	50-245	P
MCCOLLUM, W.	8305030628*	50-245	P
MCCONNELL, T	8305160286*	50-369	F
MCCORKLE, G W	8305160222*	50-312	G
MCCOSKEY, R. E	8305020035*	FOIA	
MCCOSKEY, R E	8305040290*	FOIA	
MCCOSKEY, R E	8305050328*	70-378	
MCCRORY, S L	8305170318*	50-445	G
MCCRORY, S L.	8305230475*	50-285	G
MCDERMOTT, D	8305230298	CONTRACT	
MCDERMOTT, D	8305230326	CONTRACT	
MCDERMOTT, D	8305260340	CONTRACT	
MCDERMOTT, D	8305270090	CONTRACT	
MCDONALD, D G	8305090545*	50-358	A
MCDONALD, D G	8305170104	50-250	F
MCDONALD, D G.	8305180541	50-250	P
MCDONALD, D. J	8305090561*	50-358	A
MCDONNELL, L J	8305310154	50-305	R
MCDUFFIE, M A	8305020124	50-400	E
MCDUFFIE, M A.	8305060555	50-400	E
MCDUFFIE, M A	8305110248	50-400	E
MCDUFFIE, M. A	8305110294	50-400	E
MCDUFFIE, M. A	8305120467	50-400	A
MCDUFFIE, M. A	8305160017	50-400	E
MCDUFFIE, M A	8305160021	50-400	E
MCDUFFIE, M A.	8305160109	50-400	E
MCDUFFIE, M A	8305170282	50-400	A
MCDUFFIE, M A	8305180400	50-400	E
MCDUFFIE, M A	8305200329	50-400	E
MCDUFFIE, M A	8305200384	50-400	E
MCDUFFIE, M A	8305200442	50-400	E
MCDUFFIE, M A	8305200676	50-400	K

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MCDUFFIE, M A	8305250494	50-400	E
MCDUFFIE, M A	8305260234	50-400	E
MCEVOY, R W	8305030163*	FOIA	
MCEVOY, R W	8305040272*	FOIA	
MCEVOY, R W	8305040556*	FOIA	
MCEVOY, R W	8305040559*	FOIA	
MCFARLAND, C R	8305270319*	50-537	G
MCGARRY, J M	8305040538	50-413	G
MCGARRY, J M	8305040538	50-413	G
MCGARRY, J M	8305090511	50-413	G
MCGARRY, J M	8305100289*	50-413	G
MCGARRY, J M	8305100289*	50-413	G
MCGARRY, J. M	8305100297*	50-413	G
MCGARRY, J M	8305100297*	50-413	G
MCGARRY, J M	8305100305*	50-413	G
MCGARRY, J M	8305100305*	50-413	G
MCGARRY, J M	8305180358	PR	
MCGARRY, J M	8305240485	50-413	G
MCGARRY, J M	8305240485	50-413	G
MCGAUGHY, J	8305110291	50-416	S
MCGAUGHY, J P	8304110321	50-416	P
MCGAUGHY, J. P.	8304110328*	50-416	P
MCGAUGHY, J P	8304280037	50-416	P
MCGAUGHY, J P	8305030553	50-416	S
MCGAUGHY, J P	8305030562	50-416	S
MCGAUGHY, J P	8305050075	50-416	F
MCGAUGHY, J P	8305050077	50-416	F
MCGAUGHY, J. P	8305050131	50-416	S
MCGAUGHY, J P	8305050167	50-416	S
MCGAUGHY, J P	8305050227	50-416	S
MCGAUGHY, J. P	8305130194	50-416	S
MCGAUGHY, J P	8305170424	50-416	S
MCGAUGHY, J P.	8305170427	50-416	S
MCGAUGHY, J P	8305170430	50-416	S
MCGAUGHY, J. P	8305200280	50-416	S
MCGAUGHY, J. P	8305200484	50-416	S
MCGAUGHY, J P	8305200523	50-416	S
MCGAUGHY, J P	8305200604	50-416	S
MCGAUGHY, J P	8305250072	50-416	R
MCGAUGHY, J P.	8305250365	50-416	S
MCGAUGHY, J P	8305250405	50-416	S
MCGAUGHY, J P	8305250434	50-416	S
MCGAUGHY, J. P	8305250487	50-416	S
MCGAUGHY, J P	8305250513	50-416	S
MCGAUGHY, J P	8305250579	50-416	S
MCGAUGHY, J P.	8305270400*	50-416	G
MCGAUGHY, J P	8305270410*	50-416	G
MCGAUGHY, J P	8305270473	50-416	S
MCGAUGHY, J. P.	8305270515	50-416	S
MCGAUGHY, J. P.	8305270593*	50-416	G
MCGAUGHY, J P	8305310065	50-416	S
MCGAUGHY, J. P.	8305310069	50-416	S
MCGAUGHY, J. P.	8305310146	50-416	S
MCGAUGHY, J. P	8305310196	50-416	S
MCGAUGHY, J. P.	8305310204	50-416	S
MCGAUGHY, J. P	8305310207	50-416	S
MCGRATH, R.	8305200374*	50-309	S
MCGRAW, T. L	8305020016*	FOIA	
MCGREGOR, T.	8305020558*	FOIA	
MCGREGOR, T.	8305040158*	FOIA	
MCGREGOR, T.	8305040510*	FOIA	
MCGREGOR, T.	8305050361*	FOIA	
MCGUIRE, D	8304280299	50-400	S
MCGUIRE, D. R.	8305030371*	70-27	
MCGUIRE, D. R	8305090418*	50-390	G
MCGUIRE, D R.	8305090461*	50-395	G
MCGUIRE, D. R.	8305100109*	50-324	G
MCGUIRE, D. R	8305270212*	50-302	G
MCGUIRE, S. A	8305180796	NUREG	
MCGURREN, H J	8305190223	50-338	G
MCINTOSH, M. D.	8305200440*	50-369	P
MCKAY, E. D.	8305310211	WASTE MGT	
MCKEEN, C. M	8305020571*	FOIA	
MCKEOWN	8305100004	50-272	S
MCKEOWN	8305110439	50-286	S
MCKEOWN, L	8305030294	50-286	S
MCKEOWN, L	8305030459	50-354	S
MCKEOWN, L.	8305120434	50-272	S
MCKINNEY, C. J	8305050239*	50-395	S
MCKINNEY, C J.	8305100091*	50-395	S
MCKINNEY, C J	8305200515*	50-395	S
MCLAUGHLIN, L	8305250302	50-335	S
MCLEAREN, T.	8305170648	CONTRACT	
MCLEAREN, T.	8305260206	CONTRACT	
MCLEAREN, T.	8305260377	CONTRACT	
MCLOUGHLIN, D	8305120426*	50-309	F
MCNEILL, C A	8305110259	50-333	S
MCNEILL, C A	8305110400	50-333	S
MCNEILL, C A	8305110405	50-333	S
MCNEILL, C A	8305110510	50-333	S
MCNEILL, C A	8305130132	50-333	R
MCNEILL, C A	8305230454	50-333	S
MCNEILL, C A	8305270189	50-333	R
MCNEILL, C A	8305270399*	50-333	G
MCNEILL, W M	8305050097*	GA999	
MCNEILL, W M	8305050110*	GA999	
MCNEILL, W M	8305050179*	GA999	
MCNEILL, W M	8305090485*	GA999	
MCNEILL, W M	8305200678*	GA999	
MCPHERSON, D M	8305190209	50-440	G
MCQUEEN, A D	8305030313	50-275	S
MCQUEEN, A D	8305240393*	50-275	G
MCGUIRE, D R	8305200565*	50-369	G
MCGPEDON, T G	8305240517	50-247	H
MEIBENHEIMER, J	8305190201*	50-155	P
MEIBENHEIMER, J	8305190284*	50-329	A
MEISTER, J R	8305200688*	50-373	P
MELIQI, A V	8305190303*	50-373	P
MELLO, R M	8305230292*	50-537	A
MENCZER, W B	8305160202	50-358	H
MENDELSON, I N	8305040345*	CONTRACT	
MENDEZ, R	8305120428*	50-546	G
MENDONCA, M M	8305170339*	50-275	G
MENDONCA, M M	8305170480*	50-361	G
MENDONCA, M M	8305260262*	50-275	G
MERRITT, S	8305060571*	50-249	S
MERRITT, S	8305170140*	50-237	S
MERRITT, S	8305240335	50-237	S
MERRITT, S	8305240494	50-237	S
MERRIWEATHER, N	8305260243*	50-440	G
MERRIWEATHER, N	8305270542*	50-389	G
MEYER, G	8305250314*	50-309	G
MEYER, G W	8305230460*	50-289	G
MEYER, G W	8305250306*	50-277	G
MEYER, T A	8305160119*	50-244	S
MIDDENDORF, W D	8305060536*	50-352	A
MIDURA, H J	8304180491	50-311	S
MIDURA, H J	8305130309*	50-272	F
MILES, E B.	8305160304	50-247	G
MILES, E B.	8305180557	CONTRACT	
MILINAZZO, P L	8305240357*	GA999	
MILINAZZO, P L	8305240363*	GA999	
MILLER, C A	8305110227	NUREG	
MILLER, D	8305170590*	50-454	G
MILLER, D	8305170590*	50-454	G
MILLER, D	8305170590*	50-454	G
MILLER, D B.	8305170131	50-329	A
MILLER, D B	8305170373	50-329	R
MILLER, D. B	8305170397	50-329	A
MILLER, D B	8305170422	50-329	A
MILLER, D. B	8305170467	50-329	A
MILLER, D B	8305190065	50-329	A
MILLER, D B	8305190280	50-329	A
MILLER, D B	8305190298	50-329	G
MILLER, D B.	8305200389	50-329	A
MILLER, D B	8305240353	50-329	A
MILLER, D B.	8305240427	50-329	A
MILLER, D. B	8305310190	50-329	A
MILLER, D E	8305120353*	50-374	G
MILLER, D E	8305170353*	50-295	G
MILLER, D. E	8305190161	70-8	
MILLER, D. E	8305240340*	40-3392	
MILLER, D F	8305110491	NUREG	
MILLER, D S.	8305160099	50-309	G
MILLER, D S.	8305160099	50-309	G
MILLER, D S	8305190255	50-309	G
MILLER, D S.	8305190255	50-309	G
MILLER, D S	8305240483	50-309	G
MILLER, D. S.	8305240493	50-309	G
MILLER, D S	8305240493	50-309	G
MILLER, H J	8305090661	WASTE MGT	
MILLER, J.	8305020271	I&E	
MILLER, J	8305040445	50-331	S
MILLER, J	8305130165	I&E	
MILLER, J	8305170559	I&E	
MILLER, J.	8305190057*	XPORTLIC	
MILLER, J. R	8305020389	50-255	G
MILLER, J R	8305030513	50-264	G
MILLER, J R	8305100323	50-156	G
MILLER, J R	8305100363	50-156	G
MILLER, J R	8305130227	70-1308	
MILLER, J R	8305170423	50-373	
MILLER, J R	8305200472	70-925	
MILLER, K V	8305250424*	50-483	
MILLER, K V	8305250424*	50-483	
MILLER, K V	8305250544*	50-483	
MILLER, K V	8305250544*	50-483	
MILLER, L F	8305170421*	50-361	
MILLER, L K	8305170021*	50-272	
MILLER, L K	8305170147*	50-311	
MILLER, M A	8305110122	50-329	
MILLER, M E	8305110337	50-537	
MILLER, M E	8305190204	50-537	
MILLER, M I	8305120273	50-329	
MILLER, M. I	8305120273	50-329	
MILLER, M S	8305050007	50-322	
MILLER, M S	8305050007	50-322	
MILLER, M S	8305130069	50-322	
MILLER, M S	8305130069	50-322	
MILLER, M T	8305050151*	50-293	
MILLER, M. T	8305240232*	50-29	
MILLER, R L	8305020036	71-9510	
MILLER, R W	8305270046*	50-320	
MILLER, W	8305180349*	50-331	
MILLER, W H	8305270293*	50-389	
MILLER, W H	8305270404*	50-413	
MILLER, W O	8305020513	50-219	
MILLER, W. O	8305030679	50-259	
MILLER, W O	8305050347	TDPREP	
MILLER, W. O	8305060645	50-312	
MILLER, W O	8305090551	50-329	
MILLER, W O	8305090553	50-312	
MILLER, W O	8305110028	50-266	
MILLER, W. O	8305110144	50-295	
MILLER, W O	8305180853	50-213	
MILLER, W O	8305200073	50-320	
MILLER, W O	8305200172	50-331	
MILLER, W O	8305200178	50-267	
MILLER, W O	8305260372	50-259	
MILLER, W O	8305310227	50-206	
MILLIGAN, M H	8305030274	50-322	
MILLIGAN, M H	8305200594*	50-322	
MILLS, L M	8305030041	50-390	
MILLS, L. M	8305030072	50-390	
MILLS, L M	8305030082	50-390	
MILLS, L M	8305030121	50-390	
MILLS, L M	8305030252	50-438	
MILLS, L M	8305030370	50-438	
MILLS, L. M.	8305030434	50-390	
MILLS, L. M	8305030558	50-438	
MILLS, L M	8305030578	50-390	
MILLS, L. M	8305030606	50-390	
MILLS, L M	8305030625	50-259	
MILLS, L M	8305040253	50-390	
MILLS, L M	8305040511	50-259	
MILLS, L. M	8305050047	50-390	
MILLS, L. M	8305050067	50-390	
MILLS, L M	8305050078	50-390	
MILLS, L M	8305050120	50-438	
MILLS, L M	8305050122	50-438	
MILLS, L M	8305050152	50-328	
MILLS, L M	8305050188	50-390	
MILLS, L. M	8305050232	50-390	
MILLS, L. M	8305050243	50-390	
MILLS, L. M	8305100101	50-327	
MILLS, L M	8305100189	50-518	
MILLS, L M	8305100234	50-259	
MILLS, L M	8305100240	50-438	
MILLS, L M	8305100359	50-438	
MILLS, L M	8305110292	50-439	
MILLS, L M	8305110304	50-438	
MILLS, L M	8305110317	50-390	
MILLS, L M	8305110319	50-390	
MILLS, L M	8305110406	50-438	
MILLS, L M	8305110441	50-439	
MILLS, L M	8305110505	50-391	
MILLS, L M	8305130003	50-259	
MILLS, L M	8305130020	50-390	
MILLS, L M	8305130089	50-439	
MILLS, L M	8305130133	50-390	
MILLS, L. M	8305130147	50-438	
MILLS, L M	8305130154	50-438	
MILLS, L M	8305130217	50-390	
MILLS, L M	8305170145	50-327	
MILLS, L M	8305170237	50-566	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MANNO, S F	8305250430	50-410	S
MANNO, S F	8305270645*	50-410	Q
MANSER, W C	8305030699	70-143	
MANSER, W C	8305180852	70-143	
MANSER, W C	8305190003	70-143	
MANSER, W C	8305240051	71-143	
MARCHAL, J	8305020005	XPORTLIC	
MARCHAL, J	8305020096	XPORTLIC	
MARCHAL, J	8305090010	XPORTLIC	
MARCONNET, J	8305270011*	50-261	P
MARCUS, G F	8305200655*	50-373	P
MARCUS, G F	8305200665*	50-373	P
MARCUS, G F	8305200675*	50-373	P
MARCUSON, W F	8305110041*	CONTRACT	
MARCUSON, W F	8305170607*	CONTRACT	
MARELLO, S L	8305190102*	50-329	Q
MARELLO, S L	8305190296*	50-373	Q
MARGULIES, M B	8305100413	50-261	Q
MARGULIES, M B	8305170493	50-508	Q
MARGULIES, M B	8305270014	50-261	Q
MARIANI, L P	8305110012	PR	
MARIANI, L P	8305250517	PR	
MARKEY, E J	8305230388*	50-289	U
MARKEY, E J	8305230735*	COMMISSION	
MARSHALL, J R	8303240480	50-313	P
MARSHALL, J R	8304270426*	50-313	F
MARSHALL, J R	8305020373	50-368	S
MARSHALL, J R	8305020416	50-368	P
MARSHALL, J. R	8305030331*	50-313	Q
MARSHALL, J R	8305030385	50-313	S
MARSHALL, J R	8305040453	50-313	R
MARSHALL, J R	8305050125	50-313	P
MARSHALL, J R	8305050216	50-313	P
MARSHALL, J R	8305060452	50-313	S
MARSHALL, J R.	8305090333	50-313	P
MARSHALL, J R	8305090421	50-313	J
MARSHALL, J. R	8305090440	50-313	P
MARSHALL, J R	8305100351	50-313	P
MARSHALL, J R	8305120414	50-313	S
MARSHALL, J R	8305120451*	50-313	Q
MARSHALL, J R	8305160290*	50-313	F
MARSHALL, J R	8305170551	50-313	Q
MARSHALL, J R	8305190363	50-313	J
MARSHALL, J R	8305200319*	50-313	Q
MARSHALL, J R	8305200326	50-313	F
MARSHALL, J R	8305200445	50-313	S
MARSHALL, J R	8305200490	50-313	S
MARSHALL, J R	8305200541	50-313	P
MARSHALL, J R	8305200573	50-368	R
MARSHALL, J R	8305200580	50-368	P
MARSHALL, J R	8305230364	50-313	P
MARSHALL, J R	8305230723	50-368	P
MARSHALL, J R	8305240054*	50-313	Q
MARSHALL, J R	8305240139	50-313	H
MARSHALL, J R	8305240360	50-368	P
MARSHALL, J R	8305240399	50-313	P
MARSHALL, J R	8305260260	50-313	S
MARSHALL, J R	8305270065	50-313	P
MARSHALL, J R	8305310199*	50-313	Q
MARSHALL, J S	8305090517*	50-445	T
MARSHALL, W H	8305120005	FOIA	
MARSHALL, W J	8305120338*	50-320	T
MARSTON, R R	8305270116*	70-1113	
MARTIN	8305120384	50-354	S
MARTIN, D E	8305090576	WASTE MGT	
MARTIN, D E	8305090679	WASTE MGT	
MARTIN, D E	8305090705	WASTE MGT	
MARTIN, D E	8305110183	WASTE MGT	
MARTIN, D E	8305170599	40-299	
MARTIN, D E	8305250597	40-299	
MARTIN, J	8305050164*	50-397	Q
MARTIN, J B	8305030069	PR	
MARTIN, J B	8305100011	50-346	F
MARTIN, J B	8305260264	50-361	Q
MARTIN, J B	8305260270	50-275	Q
	8305130292	RES	
	8305110072	50-352	F
	8305110079	50-352	A
	8305130026	50-352	A
	8305190012	50-352	A
	8305200170	50-352	A
	8305060470	50-354	S
	8305110255	50-354	S
	8305170490*	50-354	Q
	8304180541	70-1143	
MARTIN, T T	8304250152	70-2953	
MARTIN, T T	8305020259	50-272	Q
MARTIN, T T	8305020386	50-309	Q
MARTIN, T T	8305020395	50-213	Q
MARTIN, T T	8305050132	70-466	
MARTIN, T T	8305050134	70-1402	
MARTIN, T T	8305050141	50-277	Q
MARTIN, T T	8305050144	50-293	Q
MARTIN, T T	8305050161	40-3079	
MARTIN, T T	8305050176	70-1224	
MARTIN, T T	8305050187	50-247	Q
MARTIN, T T	8305050246	50-244	Q
MARTIN, T T	8305110261	50-277	Q
MARTIN, T T	8305110276	50-317	Q
MARTIN, T T	8305110314	50-309	Q
MARTIN, T T	8305110331	50-289	Q
MARTIN, T T	8305120378	50-322	Q
MARTIN, T T	8305160018	50-219	Q
MARTIN, T T	8305190163	50-272	Q
MARTIN, T T	8305190187	50-271	Q
MARTIN, T T	8305190310	50-271	Q
MARTIN, T T	8305190350	70-371	
MARTIN, T T	8305200382	50-220	Q
MARTIN, T T	8305200436	50-334	Q
MARTIN, T T	8305230455	50-289	Q
MARTIN, T T	8305230505	TOPREP	
MARTIN, T T	8305230571	50-309	P
MARTIN, T T	8305240227	50-29	Q
MARTIN, T T	8305240285	50-272	Q
MARTIN, T T	8305250291	50-219	Q
MARTIN, T T	8305250299	50-277	Q
MARTIN, T T	8305250310	50-309	Q
MARTIN, T T	8305250314*	50-309	Q
MARTIN, T T	8305250480	50-271	Q
MARTIN, T T	8305250498	50-412	Q
MARTIN, T T	8305250495	50-289	Q
MARTIN, T T	8305250503	50-286	Q
MARTIN, T T	8305250571	50-387	Q
MARTIN, T T	8305270033	50-423	Q
MARTIN, T T	8305270274	50-333	Q
MARTIN, T T	8305270361	TOPREP	
MARTIN, T T	8305270392	50-333	Q
MARTIN, W J	8305060233	NUREG	
MARTINOVICH, M	8305020114*	50-373	S
MARUCUT, C R	8305030592*	50-461	R
MASON, C C	8305240323	50-327	R
MASSARO, S A	8305040740	NUREG	
MAST, L	8305200598	50-440	Q
MASTERSON, V	8305240381	50-373	S
MASTERSON, V	8305270195	50-373	S
MASTERSON, V V	8305060509*	50-373	S
MATHENY, D C	8305130195*	50-346	S
MATHEWS, T P	8305170470*	50-285	R
MATHIS, C J	8304110696	50-293	S
MATHIS, C J	8305230535	50-293	R
MATHIS, C J	8305230537*	50-293	R
MATHIS, J	8305270367*	50-335	Q
MATHIS, J L	8305270562*	50-390	Q
MATTHEWS, B A	8305030477	50-261	H
MATTHEWS, B A	8305030486	50-261	Q
MATTHEWS, B A	8305030493	50-261	Q
MATTHEWS, B A	8305180299	50-261	Q
MATTHEWS, B A	8305180452	50-261	Q
MATTHEWS, H	8305250580*	50-483	Q
MATTHEWS, H	8305250580*	50-483	Q
MATTIA, M J	8305090300*	CONTRACT	
MATTIA, M J	8305110232*	CONTRACT	
MATTIA, M J	8305120150*	CONTRACT	
MATTIA, M J	8305160312*	50-247	Q
MATTIA, M J	8305160316*	50-247	Q
MATTIA, M J	8305180560*	CONTRACT	
MATTIA, M J	8305180562*	CONTRACT	
MATTIA, M J	8305230249*	CONTRACT	
MATTIA, M J	8305230274*	CONTRACT	
MATTIA, M J	8305240369*	FOIA	
MATTIA, M J	8305260087*	CONTRACT	
MATTIMOE, J J	8305230583	50-312	P
MATTSON, R J	8305030587*	50-312	P
MATTSON, R J	8305250221*	50-361	P
MATTSON, R J	8305260396	TOPREP	
MAURA, F A.	8304120412*	50-373	Q
MAURIN, L V	8305020341	50-382	A
MAURIN, L V	8305020411	50-382	S
MAURIN, L V	8305020450	50-382	S
MAURIN, L V	8305020479	50-382	S
MAURIN, L V	8305050017	50-382	R
MAURIN, L V	8305060367	50-382	S
MAURIN, L V	8305060425	50-382	S
MAURIN, L V	8305060566	50-382	S
MAURIN, L V	8305060587	50-382	S
MAURIN, L V	8305130019	50-382	S
MAURIN, L V	8305170223	50-382	S
MAURIN, L V	8305170265	50-382	S
MAURIN, L V	8305170327	50-382	S
MAURIN, L V	8305170351	50-382	S
MAURIN, L V	8305170484	50-382	S
MAURIN, L V	8305170492	50-382	S
MAURIN, L V	8305170500	50-382	S
MAURIN, L V	8305180468	50-382	A
MAXWELL, G F	8305030537*	50-440	T
MAXWELL, G F	8305270308*	50-400	Q
MAXWELL, G F	8305270631*	50-400	Q
MAXWELL, J C	8305130347	50-443	D
MAXWELL, J C	8305130347	50-443	D
MAY, D C	8304280121	PR	
MAYWEATHER, L	8304150372*	50-361	R
MCALPINE, E J	8305200318*	70-143	
MCALPINE, E J	8305270145*	70-1151	
MCALPINE, E. J	8305270159*	70-1113	
MCALPINE, E J	8305270167*	70-143	
MCALPINE, E J	8305270254*	70-1201	
MCALPINE, E J	8305270304*	50-332	Q
MCALPINE, E J	8305270480*	70-1151	
MCALPINE, E J	8305270556*	70-27	
MCALPINE, E J	8305270613*	70-143	
MCALPINE, E J	8305270648*	70-143	
MCALPINE, E J	8305310022*	70-1201	
MCALPINE, E J	8305310134*	70-1113	
MCBREARTY, R A	8305250295*	50-219	Q
MCBRIDE, L M	8305050146	50-267	F
MCCABE	8305030118	50-278	S
MCCABE	8305060530	50-317	S
MCCABE	8305060558	50-277	S
MCCABE	8305110258	50-388	S
MCCABE	8305120412	50-277	S
MCCABE, E	8305020337	50-278	S
MCCABE, E	8305060387	50-277	S
MCCABE, E C	8305030208*	50-317	Q
MCCABE, E. C	8305110149	50-387	Q
MCCANN	8305110258	50-388	S
MCCARTY, C L	8305030709	40-8728	
MCCLINTOCK, R.	8305120454*	40-672	
MCCLINTOCK, R	8305120507*	40-672	
MCCLINTOCK, R	8305120518*	40-672	
MCCLINTOCK, R D	8305060156*	40-672	
MCCLINTOCK, R D	8305120462*	40-672	
MCCLINTOCK, R D	8305120472*	FOIA	
MCCLUSKEY, G	8305160156	50-440	Q
MCCOLLUM, W	8305030628*	50-245	P
MCCOLLUM, W	8305030628*	50-245	P
MCCONNELL, T	8305160286*	50-369	F
MCCORKLE, G W	8305160222*	50-312	Q
MCCOSKEY, R E	8305020035*	FOIA	
MCCOSKEY, R E	8305040290*	FOIA	
MCCOSKEY, R E	8305050328*	70-378	
MCCRORY, S L	8305170318*	50-445	Q
MCCRORY, S L	8305230475*	50-285	Q
MCDERMOTT, D	8305230298	CONTRACT	
MCDERMOTT, D	8305230326	CONTRACT	
MCDERMOTT, D	8305260340	CONTRACT	
MCDERMOTT, D	8305270090	CONTRACT	
MCDONALD, D G	8305090545*	50-358	A
MCDONALD, D. G.	8305170104	50-250	F
MCDONALD, D G.	8305180541	50-250	P
MCDONALD, D J	8305090561*	50-358	A
MCDONNELL, L. J.	8305310154	50-305	R
MCDUFFIE, M A	8305020124	50-400	E
MCDUFFIE, M. A	8305060555	50-400	E
MCDUFFIE, M A	8305110248	50-400	E
MCDUFFIE, M A	8305110294	50-400	E
MCDUFFIE, M. A	8305120467	50-400	A
MCDUFFIE, M. A	8305160017	50-400	E
MCDUFFIE, M A	8305160021	50-400	E
MCDUFFIE, M. A	8305160109	50-400	E
MCDUFFIE, M. A	8305170282	50-400	A
MCDUFFIE, M A	8305180400	50-400	E
MCDUFFIE, M. A	8305200329	50-400	E
MCDUFFIE, M. A.	8305200384	50-400	E
MCDUFFIE, M A	8305200442	50-400	E
MCDUFFIE, M A	8305200676	50-400	K

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MCDUFFIE, M A	8305250494	50-400	E
MCDUFFIE, M A	8305260234	50-400	E
MCEVOY, R W	8305030163*	FOIA	
MCEVOY, R W	8305040272*	FOIA	
MCEVOY, R W	8305040556*	FOIA	
MCEVOY, R W	8305040559*	FOIA	
MCFARLAND, C R	8305270319*	50-537	G
MCGARRY, J M	8305040538	50-413	G
MCGARRY, J M	8305040538	50-413	G
MCGARRY, J M	8305090511	50-413	G
MCGARRY, J M	8305100289*	50-413	G
MCGARRY, J. M	8305100289*	50-413	G
MCGARRY, J M	8305100297*	50-413	G
MCGARRY, J M	8305100297*	50-413	G
MCGARRY, J M	8305100305*	50-413	G
MCGARRY, J M	8305100305*	50-413	G
MCGARRY, J M	8305180358	PR	
MCGARRY, J M	8305240485	50-413	G
MCGARRY, J M	8305240485	50-413	G
MCGAUGHY, J	8305110291	50-416	S
MCGAUGHY, J P	8304110321	50-416	P
MCGAUGHY, J P	8304110328*	50-416	P
MCGAUGHY, J P	8304280037	50-416	P
MCGAUGHY, J P	8305030553	50-416	S
MCGAUGHY, J P	8305030562	50-416	S
MCGAUGHY, J P	8305050075	50-416	F
MCGAUGHY, J P	8305050077	50-416	F
MCGAUGHY, J P	8305050131	50-416	S
MCGAUGHY, J P	8305050167	50-416	S
MCGAUGHY, J. P	8305050227	50-416	S
MCGAUGHY, J P	8305130194	50-416	S
MCGAUGHY, J. P	8305170424	50-416	S
MCGAUGHY, J P	8305170427	50-416	S
MCGAUGHY, J P	8305170430	50-416	S
MCGAUGHY, J P	8305200280	50-416	S
MCGAUGHY, J. P	83052004B4	50-416	S
MCGAUGHY, J P	8305200523	50-416	S
MCGAUGHY, J. P	8305200604	50-416	S
MCGAUGHY, J P	8305250072	50-416	R
MCGAUGHY, J P	8305250365	50-416	S
MCGAUGHY, J P	8305250405	50-416	S
MCGAUGHY, J. P	8305250434	50-416	S
MCGAUGHY, J P	8305250487	50-416	S
MCGAUGHY, J P	8305250513	50-416	S
MCGAUGHY, J. P	8305250579	50-416	S
MCGAUGHY, J. P	8305270400*	50-416	Q
MCGAUGHY, J P	8305270410*	50-416	Q
MCGAUGHY, J. P	8305270473	50-416	S
MCGAUGHY, J P	8305270515	50-416	S
MCGAUGHY, J. P.	8305270593*	50-416	Q
MCGAUGHY, J P	8305310065	50-416	S
MCGAUGHY, J P	8305310069	50-416	S
MCGAUGHY, J P	8305310146	50-416	S
MCGAUGHY, J P.	8305310196	50-416	S
MCGAUGHY, J P	8305310204	50-416	S
MCGAUGHY, J. P	8305310207	50-416	S
MCGRATH, R	8305200374*	50-309	S
MCGRAW, T L	8305020016*	FOIA	
MCGREGOR, T	8305020558*	FOIA	
MCGREGOR, T	8305040158*	FOIA	
MCGREGOR, T.	8305040510*	FOIA	
MCGREGOR, T.	8305050361*	FOIA	
MCGUIRE, D	8304280299	50-400	S
MCGUIRE, D R	8305030371*	70-27	
MCGUIRE, D R.	8305090418*	50-390	Q
MCGUIRE, D. R	8305090461*	50-395	Q
MCGUIRE, D R.	8305100109*	50-324	Q
MCGUIRE, D. R.	8305270212*	50-302	Q
MCGUIRE, S. A	8305180796	NUREG	
MCGURREN, H J	8305190223	50-338	Q
MCINTOSH, M D	8305200440*	50-369	P
MCKAY, E. D.	8305310211	WASTE MGT	
MCKEEN, C M	8305020571*	FOIA	
MCKEOWN	8305100004	50-272	S
MCKEOWN	8305110439	50-286	S
MCKEOWN, L.	8305030294	50-286	S
MCKEOWN, L	8305030459	50-354	S
MCKEOWN, L	8305120434	50-272	S
MCKINNEY, C. J	8305050239*	50-395	S
MCKINNEY, C J	8305100091*	50-395	S
MCKINNEY, C J.	8305200515*	50-395	S
MCLAUGHLIN, L.	8305250302	50-335	S
MCLEAREN, T.	8305170648	CONTRACT	
MCLEAREN, T.	8305260206	CONTRACT	
MCLEAREN, T.	8305260377	CONTRACT	
MCLOUGHLIN, D	8305120426*	50-309	F
MCNEILL, C A	8305110259	50-333	S
MCNEILL, C A	8305110400	50-333	S
MCNEILL, C A	8305110405	50-333	S
MCNEILL, C A	8305110510	50-333	S
MCNEILL, C A	8305130132	50-333	R
MCNEILL, C. A	8305230454	50-333	S
MCNEILL, C A	8305270189	50-333	R
MCNEILL, C A	8305270399*	50-333	Q
MCNEILL, W M	8305050097*	GA999	
MCNEILL, W M	8305050110*	GA999	
MCNEILL, W M	8305050179*	GA999	
MCNEILL, W M	8305090485*	GA999	
MCNEILL, W M	8305200678*	GA999	
MCPHERSON, D M	8305190209	50-440	Q
MCQUEEN, A. D	8305030313	50-275	S
MCQUEEN, A D	8305240393*	50-275	Q
MCQUIRE, D R	8305200565*	50-369	Q
MCSPEDON, T G	8305240517	50-247	H
MEISENHEIMER, J	8305190201*	50-155	P
MEISENHEIMER, J	8305190284*	50-329	A
MEISTER, J R	8305200688*	50-373	P
MELIQI, A V	8305190303*	50-373	P
MELLO, R M.	8305230292*	50-537	A
MENCZER, W. B	8305160202	50-358	H
MENDELSON, I N	8305040345*	CONTRACT	
MENDEZ, R	8305120428*	50-546	G
MENDONCA, M M	8305170399*	50-275	G
MENDONCA, M M	83051704B0*	50-361	G
MENDONCA, M M	8305260262*	50-275	G
MERRITT, S	8305060571*	50-249	S
MERRITT, S	8305170140*	50-237	S
MERRITT, S	8305240335	50-237	S
MERRITT, S	8305240494	50-237	S
MERRIWEATHER, N	8305260243*	50-440	Q
MERRIWEATHER, N	8305270542*	50-389	Q
MEYER, Q	8305250314*	50-309	Q
MEYER, Q W	8305230460*	50-289	Q
MEYER, Q W	8305250306*	50-277	Q
MEYER, T A	8305160119*	50-244	S
MIDDENDORF, W B	8305060536*	50-352	A
MIDURA, H J	8304180491	50-311	S
MIDURA, H J	8305130309*	50-272	F
MILES, E. B	8305160304	50-247	Q
MILES, E. B.	8305180557	CONTRACT	
MILINAZZO, P L	8305240357*	GA999	
MILINAZZO, P L	8305240363*	GA999	
MILLER, C A.	8305110227	NUREG	
MILLER, D	8305170590*	50-454	Q
MILLER, D.	8305170590*	50-454	Q
MILLER, D.	8305170590*	50-454	Q
MILLER, D B	8305170131	50-329	A
MILLER, D B	8305170373	50-329	R
MILLER, D B.	8305170397	50-329	A
MILLER, D B	8305170422	50-329	A
MILLER, D B	8305170467	50-329	A
MILLER, D B.	8305190065	50-329	A
MILLER, D B	8305190280	50-329	A
MILLER, D B	8305190298	50-329	Q
MILLER, D B	8305200389	50-329	A
MILLER, D. B	8305240353	50-329	A
MILLER, D B	8305240427	50-329	A
MILLER, D. B	8305310190	50-329	A
MILLER, D. E	8305120353*	50-374	Q
MILLER, D. E	8305170353*	50-295	Q
MILLER, D. E	8305190161	70-8	
MILLER, D. E	8305240340*	40-3392	
MILLER, D. P	8305110491	NUREG	
MILLER, D S	8305160099	50-309	Q
MILLER, D S	8305160099	50-309	Q
MILLER, D S.	8305190255	50-309	Q
MILLER, D S	8305190255	50-309	Q
MILLER, D S	8305240483	50-309	Q
MILLER, D. S	8305240493	50-309	Q
MILLER, D S	8305240493	50-309	Q
MILLER, H. J	8305090661	WASTE MGT	
MILLER, J	8305020271	I&E	
MILLER, J	8305040445	50-331	S
MILLER, J	8305130165	I&E	
MILLER, J	8305170559	I&E	
MILLER, J.	8305190057*	XPORTLIC	
MILLER, J R.	8305020389	50-255	Q
MILLER, J R	8305030513	50-264	Q
MILLER, J. R	8305100323	50-156	Q
MILLER, J. R	8305100363	50-156	Q
MILLER, J R	8305130227	70-1308	
MILLER, J R	8305170423	50-373	Q
MILLER, J R	8305200472	70-925	
MILLER, K V	8305250424*	50-483	Q
MILLER, K V	8305250424*	50-483	Q
MILLER, K V	8305250544*	50-483	Q
MILLER, K V	8305250544*	50-483	Q
MILLER, L F	8305170421*	50-361	Q
MILLER, L K	8305170021*	50-272	R
MILLER, L K	8305170147*	50-311	R
MILLER, M A	8305110122	50-329	Q
MILLER, M E	8305110337	50-537	Q
MILLER, M E	8305190204	50-537	Q
MILLER, M I	8305120273	50-329	Q
MILLER, M I	8305120273	50-329	Q
MILLER, M S	8305050007	50-322	Q
MILLER, M S	8305050007	50-322	Q
MILLER, M S	8305130069	50-322	Q
MILLER, M S	8305130069	50-322	Q
MILLER, M T	8305050151*	50-293	Q
MILLER, M T	8305240232*	50-29	Q
MILLER, R L	8305020036	71-9510	
MILLER, R W	8305270046*	50-320	P
MILLER, W	8305180349*	50-331	R
MILLER, W H	8305270293*	50-389	Q
MILLER, W H	8305270404*	50-413	Q
MILLER, W O	8305020513	50-219	P
MILLER, W. O	8305030679	50-259	X
MILLER, W O	8305050347	TOPREP	
MILLER, W O	8305060645	50-312	P
MILLER, W O	8305090551	50-329	A
MILLER, W O	8305090553	50-312	P
MILLER, W O	8305110028	50-266	P
MILLER, W O	8305110144	50-295	P
MILLER, W O	8305180853	50-213	F
MILLER, W O	8305200073	50-320	P
MILLER, W O	8305200172	50-331	F
MILLER, W O	8305200178	50-267	P
MILLER, W O	8305260372	50-259	P
MILLER, W O	8305310227	50-206	P
MILLIGAN, M H	8305030274	50-322	S
MILLIGAN, M H	8305200594*	50-322	Q
MILLS, L M	8305030041	50-390	A
MILLS, L M	8305030072	50-390	S
MILLS, L M.	8305030082	50-390	S
MILLS, L M	8305030121	50-390	A
MILLS, L M	8305030252	50-438	S
MILLS, L M	8305030370	50-438	S
MILLS, L M	8305030434	50-390	A
MILLS, L M	8305030558	50-438	A
MILLS, L M	8305030578	50-390	S
MILLS, L M	8305030606	50-390	A
MILLS, L M	8305030625	50-259	Q
MILLS, L M	8305040253	50-390	A
MILLS, L M	8305040511	50-259	P
MILLS, L M	8305050047	50-390	S
MILLS, L M	8305050067	50-390	S
MILLS, L M	8305050078	50-390	S
MILLS, L M	8305050120	50-438	S
MILLS, L M	8305050122	50-438	S
MILLS, L M	8305050152	50-328	S
MILLS, L M	8305050188	50-390	S
MILLS, L M	8305050232	50-390	S
MILLS, L. M	8305050243	50-390	S
MILLS, L M	8305100101	50-327	F
MILLS, L M	8305100189	50-518	A
MILLS, L M	8305100234	50-259	F
MILLS, L M	8305100240	50-438	A
MILLS, L M	8305100358	50-438	A
MILLS, L M	8305110292	50-439	S
MILLS, L M	8305110304	50-438	S
MILLS, L. M	8305110317	50-390	S
MILLS, L M	8305110319	50-390	S
MILLS, L M	8305110406	50-438	S
MILLS, L M	8305110441	50-439	S
MILLS, L M	8305110505	50-391	S
MILLS, L M	8305130003	50-259	P
MILLS, L M	8305130020	50-390	E
MILLS, L M	8305130089	50-439	S
MILLS, L M	8305130133	50-390	S
MILLS, L. M	8305130147	50-438	S
MILLS, L M	8305130154	50-438	S
MILLS, L M	8305130217	50-390	S
MILLS, L M	8305170145	50-327	P
MILLS, L M	8305170237	50-566	A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
MILLS,L M	8305170288	50-390	S
MILLS,L M	8305170299	50-390	S
MILLS,L M	8305200187	50-438	S
MILLS,L M	8305200274	50-390	S
MILLS,L M	8305200275	50-390	S
MILLS,L M	8305200325	50-390	A
MILLS,L M	8305200343	50-390	S
MILLS,L M	8305200387	50-390	S
MILLS,L M	8305200519	50-438	S
MILLS,L M	8305200569	50-438	S
MILLS,L M	8305230433	50-390	S
MILLS,L M	8305230447	50-390	S
MILLS,L M	8305230482	50-390	S
MILLS,L M	8305230545	50-438	S
MILLS,L M	8305230551	50-438	S
MILLS,L M	8305230565	50-438	S
MILLS,L M	8305230569	50-390	S
MILLS,L M	8305230575	50-390	S
MILLS,L M	8305250421	50-390	S
MILLS,L M	8305250425	50-390	A
MILLS,L M	8305250435	50-390	S
MILLS,L M	8305270021	50-259	P
MILLS,L M	8305270030	50-259	P
MILLS,L M	8305270133	50-390	Q
MILLS,L M	8305270171	50-259	Q
MILLS,L M	8305270177	50-259	Q
MILLS,L M	8305270206*	50-259	Q
MILLS,L M	8305270359*	50-259	Q
MILLS,L M	8305270386*	50-438	Q
MILLS,L M	8305270567*	50-390	Q
MILLS,L M	8305270597*	50-438	Q
MILLS,L M	8305270608*	50-438	Q
MILLS,L M	8305270652*	50-259	Q
MILLS,L M	8305270660*	50-259	Q
MILLS,L M	8305310039	50-390	E
MILLS,L M	8305310053	50-327	P
MILLS,L M	8305310077	50-327	Q
MILLS,L M	8305310138	50-438	S
MILLS,L M	8305310167	50-327	F
MILLS,L M	8305310172	50-390	S
MILLS,L M	8305310189	50-327	P
MILLS,L M	8305310193	50-438	S
MILLS,L M	8305310214	50-438	S
MINECK,D L	8305030394	50-331	S
MINECK,D L	8305060472	50-331	S
MINECK,D L	8305130094	50-331	S
MINECK,D L	8305180346	50-331	R
MINECK,D L	8305240221	50-331	S
MINECK,D.L	8305240236	50-331	S
MINECK,D.L	8305270429	50-331	S
MINECK,D L	8305270440	50-331	S
MINER,S	8211180501*	50-312	Q
MINER,S	8305060365	50-269	P
MINER,S	8305160213*	50-312	Q
MINOGUE,R B	8305030722*	REVIEW GRP	
MINOGUE,R B	8305110493*	REVIEW GRP	
MINOGUE,R B	8305200623*	REVIEW GRP	
MINOR,G C	8305160068	50-443	Q
MIRAGLIA,F J	8305120613*	MISC	
MIRAGLIA,F J	8305260306	50-458	E
MIS,F J	8305180816	71-9080	
MISAK,A	8305060391*	50-254	S
MISAK,A	8305170376*	50-254	R
MITCHELL,G J	8305110584*	COMMISSION	
MITCHELL,G J	8305110601*	COMMISSION	
MITCHELL,J	8305250360*	50-483	Q
MITCHELL,J	8305250360*	50-483	Q
MITCHELL,J A	8305100248*	50-329	T
MITTL,R L	8305310185	50-354	V
MIZUNO,G S	8305030464	50-445	Q
MIZUNO,G S	8305030483	50-537	Q
MIZUNO,G S	8305030490	50-537	Q
MIZUNO,G S	8305040560*	50-445	Q
MIZUNO,G S	8305090568	50-445	Q
MIZUNO,G S	8305130033	50-445	Q
MOLCHANY,W J	8305110160	50-387	P
MONTEL,G	8305170572*	50-454	Q
MONTEL,G	8305170572*	50-454	Q
MONTEL,G	8305170572*	50-454	Q
MONTGOMERY,D	8305270086*	50-395	Q
MONTGOMERY,D M	8305270354*	50-302	Q
MONTGOMERY,D M	8305270528*	50-259	Q
MONTGOMERY,J	8305120023*	FOIA	
MONTGOMERY,J L	8305120014*	FOIA	
MONTGOMERY,J L	8305120019*	FOIA	
MONTGOMERY,J M	8305230047*	FOIA	
MOONEY,G	8305030713	40-8697	
MOONEY,G	8305160209	40-8502	
MOONEY,G	8305250241	40-8697	
MOONEY,J	8305110403*	50-247	S
MOONEY,J	8305160079*	50-247	S
MOONEY,J	8305250483	50-247	S
MOONEY,T	8305020564*	FOIA	
MOONEY,T R	8305040519*	FOIA	
MOORE,D E	8305090418*	50-390	Q
MOORE,D E	8305270212*	50-302	Q
MOORE,J E	8305020451	50-247	Q
MOORE,R N	8305090782	XPORTLIC	
MOORE,R N	8305160306	XPORTLIC	
MOORE,R N	8305170609	XPORTLIC	
MOORE,R N	8305170611	XPORTLIC	
MOORHEAD,C J	8305230703	50-289	U
MORGAN,C	8305030549	50-247	Q
MORGAN,C	8305030549	50-247	Q
MORGAN,C	8305100208	50-247	Q
MORGAN,C	8305100208	50-247	Q
MORGAN,C	8305130064	50-247	Q
MORGAN,C	8305130064	50-247	Q
MORGAN,C	8305130071	50-247	Q
MORGAN,C	8305130071	50-247	Q
MORGAN,C	8305240466	50-247	Q
MORGAN,C	8305240466	50-247	Q
MORIARTY,J M	8305020133	50-483	S
MORLEY,J A	8305110142	WASTE MGT	
MORRILL,P J	8305260272*	50-275	Q
MORRISON,G M	8305110433*	50-309	S
MORROW,R	8305090003*	QA999	
MORTENSEN,W P	8305100094	50-513	S
MORTON,D K	8305030474*	50-483	Q
MORTON,K V	8305040643*	CONTRACT	
MORTON,K V	8305060326*	CONTRACT	
MORTON,K V	8305120517*	CONTRACT	
MORTON,K V	8305170077*	CONTRACT	
MORTON,K V	8305230169*	CONTRACT	
MORTON,K V	8305230311*	CONTRACT	
MORTON,K V	8305230332*	CONTRACT	
MORTON,K V	8305260341*	CONTRACT	
MORTON,K V	8305270093*	CONTRACT	
MORTON,K V	8305270105*	CONTRACT	
MOSER,R M	8305180670	71-6272	
MOSER,R M	8305230080	71-5607	
MOSLAK,T	8305030164*	50-320	Q
MOTHERSBAUGH,L	8305030218*	70-378	
MOTHERSBAUGH,L	8305040414*	FOIA	
MOTL,G.P	8305230165	71-496	
MOTL,G P	8305230176*	71-496	
MOWRY,W R	8305040395	XPORTLIC	
MOWRY,W R	8305060690	XPORTLIC	
MOWRY,W R	8305180839*	XPORTLIC	
MROCZKA,E J	8305060501	50-245	S
MROCZKA,E J	8305170010	50-336	R
MROCZKA,E J	8305170010	50-336	R
MROCZKA,E J	8305230549	50-245	S
MROCZKA,E J	8305270089	50-336	S
MROCZKA,E J	8305270089	50-336	S
MROCZKA,E J	8305270239	50-336	S
MROCZKA,E J	8305270239	50-336	S
MROCZKA,E J	8305270454	50-336	S
MROCZKA,E J	8305270454	50-336	S
MUDUFFIE,M A	8305270023	50-400	E
MULKIKIN,R P	8305100249*	50-445	Q
MULKIN,R	8305230196*	70-1193	
MUMA,F E	8305260180	50-155	Q
MURPHY,D.	8305110367*	50-259	S
MURPHY,D W	8207080528*	50-255	P
MURPHY,D W	8305120374*	50-237	P
MURPHY,J L	8305170593*	50-454	Q
MURPHY,J L	8305170593*	50-454	Q
MURPHY,J L	8305170593*	50-454	Q
MURPHY,M E	8305100361*	50-313	Q
MURPHY,M E	8305230475*	50-285	Q
MURPHY,W P	8305170006	50-271	R
MURRAY,B	8305240005*	50-443	Q
MURRAY,T.D	8305060608*	50-346	F
MURRAY,T D	8305060702*	50-346	F
MURRAY,T D	8305130093	50-346	S
MURRAY,T D	8305130190	50-346	S
MURRAY,T D	8305170162	50-346	S
MURRAY,T D	8305170201	50-346	S
MURRAY,T D	8305190149	50-346	R
MURRAY,T D	8305240219	50-346	S
MURRAY,T D	8305240341	50-346	S
MURRAY,T D	8305260293	50-346	S
MURRAY,T D	8305310038	50-346	S
MURRILL,P W	8305310102	50-458	I
MUSELER,W J	8305180244	50-322	Q
MUSELER,W J	8305180324*	50-322	Q
MUSOLF,D	8305020320	50-282	Q
MUSOLF,D	8305020488	50-263	S
MUSOLF,D	8305030603	50-263	X
MUSOLF,D	8305120389	50-282	P
MUSOLF,D	8305160056	50-282	R
MUSOLF,D	8305160092	50-263	R
MUSOLF,D	8305230523	50-282	F
MUSOLF,D	8305240153	50-306	S
MUSOLF,D	8305240166	50-282	S
MUSOLF,D	8305250409	PR	
MYERS,D D	8305270635*	50-324	Q
MYERS,L L	8305040466*	TOPREP	
MYRABO,A L	8305160098*	50-263	R
NADEAU,J P	8305250331	50-443	H
NAIDU,K R	8305120368*	50-374	Q
NAPUDA,G	8305230460*	50-289	Q
NAPUDA,G	8305250314*	50-309	Q
NARDACCI,G A	8305020215*	50-289	R
NARDACCI,G A	8305060465*	50-289	R
NARDI,A J	8305180019	71-9070	
NARDOCI,P B	8305100003*	50-369	S
NARDOCI,P.B	8305110283*	50-369	S
NARDOCI,P.B	8305170269*	50-370	S
NARDOCI,P.B	8305170358*	50-369	S
NARDOCI,P B	8305250404	50-369	S
NARDOCI,P B	8305250439	50-370	S
NARDOCI,P B	8305250499	50-370	S
NARDOCI,P B	8305310052	50-369	S
NARROW,L M	8305050119*	50-443	Q
NASH,B	8305050304*	50-289	F
NEIGHBORS,J D	8305090045	50-280	P
NEIGHBORS,J D	8305090321	50-280	P
NEJFELT,G	8305130186	50-370	S
NEJFELT,G M	8305110262	50-370	S
NELSON,P R	8305120307*	40-672	
NELSON,P R	8305120450*	40-672	
NELSON,P R	8305120478*	40-672	
NELSON,P R	8305120483*	40-672	
NELSON,P R	8305120509*	40-672	
NELSON,P R	8305120514*	40-672	
NELSON,R H	8305060549*	50-309	S
NELSON,R L	8305020356*	50-305	Q
NERSES,V	8305170141	50-335	F
NEVEL,M	8305180367*	50-322	H
NEWMAN,J H	8305240517	50-247	H
NEWMAN,J R	8305020434	50-498	Q
NEWMAN,J R.	8305020434	50-498	Q
NEWMAN,J.R.	8305060499	50-498	Q
NEWMAN,J R	8305110225	50-498	Q
NEWMAN,J R	8305110225	50-498	Q
NEWMAN,K A	8305240355	FOIA	
NEWMAN,P.T	8305040421*	50-400	Q
NEWTON,C E	8305040596	MISC	
NEYLAN,A.J	8305020367	50-358	A
NEYLAN,A J	8305020432	50-358	A
NEYLAN,A.J.	8305020435	50-358	A
NEYMOTIN,L	8305110131	NUREG	
NICHOLS,F A	8305110162	NUREG	
NICHOLS,L L	8011180782*	MISC	
NICHOLS,L L	8305040596	MISC	
NICHOLS,L L.	8305040596	MISC	
NICHOLSON,N A	8303280182*	40-2061	
NICHOLSON,N A	8305270502*	50-305	Q
NIGHTINGALE,E	8305260231*	50-358	Q
NILSON,R	8305240310	TOPREP	
NIMITZ,R L	8305190174*	50-272	Q
NIX,H	8305030690*	50-321	F
NIX,H.C	8305030687*	50-321	F
NIX,H C	8305050030	50-321	S
NIX,H C	8305050083	50-321	S
NIX,H.C	8305110269	50-321	S
NIX,H C	8305110270	50-321	S
NIX,H C.	8305110289	50-321	S
NIX,H C	8305110364	50-321	S
NIX,H C	8305110375	50-366	S
NIX,H C.	8305110404	50-321	S
NIX,H.C.	8305110410	50-366	S
NIX,H C	8305110429	50-366	S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NIX, H C	8305110431	50-321 S
NIX, H C	8305130235	50-366 S
NIX, H C	8305170178	50-321 S
NIX, H C	8305170254	50-321 S
NIX, H C	8305170276	50-366 S
NIX, H C	8305170389	50-366 S
NIX, H. C	8305170434	50-321 S
NIX, H C	8305170442	50-321 S
NIX, H C	8305170481	50-366 S
NIX, H. C	8305170502	50-366 S
NIX, H C	8305180279	50-321 R
NIX, H. C	8305230463	50-366 S
NIX, H C	8305230486	50-366 S
NIX, H C	8305230495	50-366 S
NIX, H C	8305230568	50-321 S
NIX, H C	8305270123	50-366 S
NIX, H C	8305270234	50-321 S
NIX, H C	8305310124	50-366 S
NIX, H C	8305310166	50-321 S
NIX, H C	8305310180	50-321 S
NIX, H C	8305310206	50-366 S
NOLF, D. M	8305060326*	CONTRACT
NOLF, D M	8305170077*	CONTRACT
NORDERHAUG, L R	8303240506	70-25
NORDERHAUG, L R	8305030313	50-275 S
NORDERHAUG, L R	8305100094	50-513 S
NORDERHAUG, L R	8305100127	70-734
NORDERHAUG, L R	8305240314	50-312 G
NORDERHAUG, L R	8305260242	50-206 G
NORDERHAUG, L R.	8305270115	50-312 S
NORELIUS, C E	8305020094	50-373 G
NORELIUS, C E	8305020110	50-456 G
NORELIUS, C. E	8305020128	50-266 P
NORELIUS, C. E	8305020224	50-456 G
NORELIUS, C. E	8305020264	50-341 G
NORELIUS, C E	8305020274*	50-341 G
NORELIUS, C E	8305020347	50-315 G
NORELIUS, C E.	8305020349	50-305 G
NORELIUS, C E.	8305060441	50-237 G
NORELIUS, C. E	8305100087	50-305 G
NORELIUS, C E	8305100096	50-346 G
NORELIUS, C E	8305170295	50-255 G
NORELIUS, C E	8305170477	50-373 P
NORELIUS, C E	8305170485	50-315 G
NORELIUS, C. E	8305190128*	50-373 G
NORELIUS, C. E	8305190396*	50-329 G
NORELIUS, C E.	8305200312	50-483 G
NORELIUS, C E	8305240241	50-373 G
NORELIUS, C. E	8305240244*	50-373 G
NORELIUS, C E.	8305240301	50-373 G
NORELIUS, C. E	8305240524	50-454 G
NORELIUS, C E	8305260278	50-454 G
NORELIUS, C E.	8305260315	50-331 G
NORKIN, D P.	8305030474*	50-483 G
NORRHOLM, L.	8305100258	50-272 S
NORRHOLM, L	8305200497	50-272 S
NORRHOLM, L	8305250238	50-272 S
NORRHOLM, L. J.	8305250314*	50-309 G
NORRY, P. O.	8305240036	ORG
NORTON, J. F.	8305040522*	50-305 G
NOTHELFER, T	8305200307*	50-237 S
NOVAK, T M.	8305020502	50-382 A
NOVAK, T. M	8305030013	50-528 A
NOVAK, T. M.	8305040010	50-395 P
NOVAK, T. M	8305040289	50-397 A
NOVAK, T. M.	8305040780	50-322 G
NOVAK, T. M.	8305060008	50-382 S
NOVAK, T M	8305090277	50-440 A
NOVAK, T M	8305090594	50-329 E
NOVAK, T M.	8305090722	50-445 A
NOVAK, T. M.	8305110140	50-329 A
NOVAK, T. M.	8305120569	50-416 G
NOVAK, T. M	8305130344*	50-382 A
NOVAK, T. M.	8305160240	50-445 G
NOVAK, T M.	8305170093	50-358 A
NOVAK, T. M.	8305170615	50-413 E
NOVAK, T. M.	8305170721	50-460 A
NOVAK, T. M.	8305170723	50-369 P
NOVAK, T M	8305180213	50-327 P
NOVAK, T. M	8305200015	50-373 P
NOVAK, T. M.	8305200199*	50-382 G
NOVAK, T M	8305200723	50-275 R
NOVAK, T M	8305230155	50-508 A
NOVAK, T. M.	8305230624	50-390 A
NOVAK, T. M.	8305230717	50-369 S
NOVAK, T M	8305240097	50-369 P
NOVAK, T M	8305250209	50-361 P
NOVAK, T M	8305250267	50-369 P
NOVAK, T M	8305260122	50-361 P
NOVAK, T M	8305260205	50-508 E
NOVE, E D	8305200300*	50-260 S
NOWLES, B W	8305270573	50-443 G
NUGENT, E L	8305260357	40-2259
NUSSBAUMER, D	8305030268*	70-378
NUSSBAUMER, D	8305030296*	70-378
NUSSBAUMER, D	8305040687*	70-378
NUSSBAUMER, D A	8305030320*	70-378
NUSSBAUMER, D A	8305040586*	70-378
NUSSBAUMER, D A	8305040603*	70-378
NUSSBAUMER, D A	8305050292*	70-378
NUSSBAUMER, D A	8305050301*	70-378
NUSSBAUMER, D A	8305050312*	70-378
NUSSBAUMER, D A	8305050319*	70-378
NUSSBAUMER, D A	8305050326*	70-378
NUSSBAUMER, D A	8305120283*	40-672
NYKIRK, J W	8305030091*	50-295 F
NYKIRK, J W	8305030117*	50-295 F
NYSTROM, R H	8305100382*	50-438 A
NYSTROM, R H	8305100395*	50-438 A
O'BRIEN, J P	8305170480*	50-361 G
O'HEA, P B	8305030181	71-9100
O'NEIL, J H	8305240550	50-400 G
O'NEIL, J. H	8305240550	50-400 G
O'NEILL, B	8305030164*	50-320 G
O'NEILL, B	8305160199*	50-289 G
O'NEILL, J	8305060437	PR
O'NEILL, J	8305120287	50-155 G
O'NEILL, J	8305240528	50-155 G
O'NEILL, J H	8305190245	50-155 G
O'NEILL, J H	8305200630	50-400 G
O'NEILL, J H	8305200630	50-400 G
O'NEILL, K	8305240512	50-440 G
O'REILLY, J P	8305090191	50-259 G
O'REILLY, J P	8305090454	50-395 G
O'REILLY, J P	8305120316*	40-672
O'REILLY, J P	8305120356*	40-672
O'REILLY, J P	8305120376*	40-672
O'REILLY, J P	8305120598	50-250 G
O'REILLY, J P	8305120604*	50-250 G
O'REILLY, J P	8305250541	50-280 G
O'REILLY, J P	8305250546*	50-280 G
O'REILLY, J P	8305270275	50-416 G
O'REILLY, J P	8305270425	50-269 G
O'REILLY, J P	8305270461	50-261 G
O'REILLY, J P	8305270513	50-280 G
O'REILLY, J P	8305270585	50-416 G
O'REILLY, J P	8305270664*	50-259 G
O'ROURKE, A P	8305240533	50-247 T
O'ROURKE, A P.	8305240539*	50-247 T
O'TOOLE, J	8305250483	50-247 S
O'TOOLE, J. D	8305030373	50-247 S
O'TOOLE, J. D	8305030400	50-247 S
O'TOOLE, J D	8305040242*	50-3 F
O'TOOLE, J D	8305100175	50-247 P
O'TOOLE, J D	8305110302	50-3 R
O'TOOLE, J D	8305110393	50-247 S
O'TOOLE, J D	8305130018	50-247 P
O'TOOLE, J D	8305130022*	50-247 P
O'TOOLE, J D	8305160020	50-247 S
O'TOOLE, J D	8305160075	50-247 S
OBERG, C R.	8305170009*	50-382 G
ODEGAARDEN, R H	8305040302	TOPREP
ODEGAARDEN, R H	8305060204	TOPREP
ODEGAARDEN, R H	8305170573	71-6639
OESTMANN, M J	8305170248*	50-454 G
OESTMANN, M. J	8305270270*	50-341 G
OGLE, K M.	8305060357	40-8714
OKADA, S	8305260317	XPORTLIC
OLLER, R E	8305030366*	GA999
OLLER, R E.	8305050111*	GA999
OLLINGER, W H	8305040654*	50-321 F
OLSEN, A F	8305020523	70-824
OLSHAN, L N	8305110216	50-454 A
OPREA, G. W.	8305030430	PR
OPREA, G W.	8305060456	50-498 S
OPREA, G. W	8305170510	50-498 S
OPREA, G. W	8305230416	50-498 S
OPREA, G. W	8305230525	50-498 S
ORDERS, W.	8305270160*	50-369 G
ORNSTEIN, H L	8211110645*	50-312 S
ORTIZ, N R	8305170122	NUREG
OSHIMA, S	8305020553	XPORTLIC
OSTER, J	8305230500	50-10 J
OSTER, J	8305240339	70-2973
OUBRE, R P	8305240326	50-312 R
OWCZARSKI, P C	8305250168	RES
OWCZARSKI, P C	8305250174	RES
OWEN, W H	8305050008	50-413 A
OWEN, W H	8305180351	PR
PAGANO, F G	8203150093*	50-443 F
PAGANO, F G	8305270210	50-482 E
PAGE, R G	8305030074	70-1257
PAGE, R G	8305030237	40-8027
PAGE, R G	8305030706	40-2061
PAGE, R G	8305040707	40-8035
PAGE, R G	8305160178	70-27
PAGE, R G	8305180176	40-6500
PAGE, R G	8305180319	40-7708
PAGE, R G	8305180325	40-86
PAGE, R G	8305180759	40-8406
PAGE, R G	8305180765	70-992
PAGE, R G	8305180820	40-8406
PAGE, R G	8305180824	40-7708
PAGE, R G	8305180834	40-8763
PAGE, R G	8305180850	70-925
PAGE, R G	8305180858	70-124
PAGE, R G	8305180859	70-992
PAGE, R G	8305190001	70-33
PAGE, R G	8305190004	70-2973
PAGE, R G	8305190008	70-33
PAGE, R G	8305200154	40-7708
PAGE, R. G	8305200159	70-2982
PAGE, R G	8305200165*	70-2982
PAGE, R G	8305250601	70-33
PAGE, R G	8305250603	40-8027
PAGE, R G	8305250605	70-371
PAGE, R. G	8305310217	WASTE MGT
PALLADINO, N	8305230209*	50-320 T
PALLADINO, N	8305240167*	COMMISSION
PALLADINO, N J	8305100141*	50-329 T
PALLADINO, N J	8305130060	50-277 G
PALLADINO, N J	8305130090	50-322 G
PALLADINO, N J	8305230334	COMMISSION
PALLADINO, N J	8305230360	COMMISSION
PALLADINO, N J	8305230377	50-289 U
PALLADINO, N J	8305230384	ADVCM
PALLADINO, N J	8305230397	COMMISSION
PALLADINO, N J	8305230413	COMMISSION
PALLADINO, N J	8305230420	COMMISSION
PALLADINO, N J	8305230435	50-289 U
PALLADINO, N J	8305230446*	50-289 U
PALLADINO, N J	8305230457	COMMISSION
PALLADINO, N J	8305230465	COMMISSION
PALLADINO, N J	8305230474	COMMISSION
PALLADINO, N J	8305230660	COMMISSION
PALLADINO, N J	8305230676*	50-3 F
PALLADINO, N J	8305230692	COMMISSION
PALLADINO, N J	8305230732	COMMISSION
PALLADINO, N J	8305240084*	COMMISSION
PALLADINO, N J	8305240155	COMMISSION
PALLADINO, N J	8305240179*	COMMISSION
PALLADINO, N J	8305240252	50-358 G
PALLADINO, N J	8305240256*	50-358 G
PALLADINO, N J	8305310059	50-247 U
PALMER, R A.	8303280136*	50-315 S
PALMER, R A	8305020177*	50-316 S
PALMER, R A.	8305020198*	50-316 S
PALMER, R A.	8305060406*	50-315 S
PALMER, R. A	8305130174*	50-316 S
PALMER, R A	8305130191*	50-315 S
PALMER, R A	8305240330	50-315 S
PALMER, R A	8305270107	50-315 S
PALMER, R A	8305270227*	50-316 S
PALMER, R A.	8305270230*	50-316 S
PALMER, R. A.	8305270444	50-315 S
PALMER, R A.	8305310179	50-316 S
PANDEY, S	8209210332*	50-336 P
PANDEY, S	8305200720*	50-338 P
PANOBURN, G. C	8305250245	40-8452
PANOBURN, G. C	8305250591	40-8452
PAPAY, L T	8305090278	50-361 G
PAPAZOGLOU, I A	8305110126	50-312 P
PAPERIELLO, C	8305180080*	FOIA
PAPERIELLO, C	8305240002	50-266 S
PAPERIELLO, C J	8305030336	50-10 G

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
PAPERIELLO, C J	8305060623	40-8202	
PAPERIELLO, C J	8305100080	50-346	Q
PAPERIELLO, C J	8305120346	50-374	Q
PAPERIELLO, C J	8305130149	50-373	F
PAPERIELLO, C J	8305170238	50-454	Q
PAPERIELLO, C J	8305170337	50-295	Q
PAPERIELLO, C J	8305170344*	50-295	Q
PAPERIELLO, C J	8305170503	50-315	Q
PAPERIELLO, C J	8305170548	70-1308	
PAPERIELLO, C J	8305190161	70-8	
PAPERIELLO, C J	8305240020	50-255	Q
PAPERIELLO, C J	8305240284	50-331	Q
PAPERIELLO, C J	8305240337	40-3392	
PAPERIELLO, C J	8305240376	50-155	F
PAPERIELLO, C J	8305240389	50-282	F
PAPERIELLO, C J	8305270261	50-341	Q
PAPERIELLO, C J	8305270605	50-346	Q
PAPERIELLO, C J	8305310176	50-331	Q
PARIS, O H	8305040464	50-247	Q
PARIS, O H	8305090458	50-247	Q
PARIS, O H	8305130030	50-247	Q
PARIS, P. C	8305030412*	50-286	P
PARIS, P C	8305200412*	50-286	P
PARKER, L B	8305050241*	GA999	
PARKER, L B	8305270286*	GA999	
PARKER, M E	8305170174*	50-155	Q
PARKER, P E	8305160363	PROJ	
PARKER, P E	8305230041	PROJ	
PARKER, P E	8305230056*	PROJ	
PARKER, W O	8305020326	50-413	A
PARKER, W O	8305240259*	50-287	P
PARSONS, R M	8305050124	50-400	S
PARSONS, R M	8305050185	50-400	S
PARSONS, R M	8305050259	50-400	S
PARSONS, R M	8305130027	50-400	S
PARSONS, R M	8305130080	50-400	S
PARSONS, R M	8305130216	50-400	S
PARSONS, R M	8305230442	50-400	S
PARSONS, R M	8305270281*	50-400	Q
PARSONS, R M	8305270383*	50-400	Q
PARSONS, R M	8305270615*	50-400	Q
PASCIAK, W J	8305110277*	50-317	Q
PASCOE, S	8305200071*	CONTRACT	
PASTVA, M J	8305030361*	50-324	S
PASTVA, M J	8305030419*	50-324	S
PASTVA, M J	8305030473*	50-325	S
PASTVA, M J	8305030534*	50-324	S
PASTVA, M J	8305030547*	50-324	S
PASTVA, M J	8305030618*	50-324	S
PASTVA, M J	8305050244*	50-324	S
PASTVA, M J	8305050267*	50-324	S
PASTVA, M J	8305110284*	50-325	S
PASTVA, M J	8305130172*	50-324	S
PASTVA, M J	8305130184*	50-324	S
PATE, D S	8305030572	50-537	Q
PATE, R J	8305170480*	50-361	Q
PATERSON, D A	8305110402*	50-255	R
PATTERSON, J D	8305200461	PR	
PATTERSON, J P	8305310181*	50-331	Q
PATTERSON, J W	8305040403*	FOIA	
PATTERSON, M D	8305270029	50-317	P
PATTERSON, W F	8305100158	50-443	Q
PATTERSON, W F	8305100221*	50-443	Q
PATTERSON, W F	8305100392*	50-443	Q
PATTERSON, W F	8305100411*	50-443	Q
PATTERSON, W F	8305100430*	50-443	Q
PATTERSON, W F	8305100432*	50-443	Q
PAUL, R A	8305100402*	50-237	Q
PAUL, R A	8305240292*	50-331	Q
PAULK, G L	8305270381*	50-259	Q
PAULSON, W A	8305030414	50-206	P
PAULSON, W A	8305050038	50-206	P
PAULSON, W A	8305060225	50-206	P
PAULSON, W A	8305260263	50-206	P
PAVIS, G S	8305230560*	50-317	S
PAYNE, M T	8305240500	50-400	Q
PAYNE, M T	8305240500	50-400	Q
PAYNE, M T	8305240507	50-400	Q
PAYNE, M T	8305240507	50-400	Q
PEARSON, A	8305130254	XPORTLIC	
PEARSON, A	8305130305	XPORTLIC	
PECK, C C.	8305060634*	40-8202	
PECK, C C	8305240340*	40-3392	
PEDRO, J	8305230059	FOIA	
PEERY, W W	8305270325*	50-62	Q
PEERY, W W	8305270458*	50-395	Q
PELIZZA, M S	8305160228	40-8786	
PELL, W R	8305190059	50-322	H
PELLET, J L	8211100028*	50-312	S
PELLETIER, J P	8305050101	50-271	S
PELLETIER, J P	8305050108*	50-271	S
PENNER, P S	8305180334	PR	
PENNIFILL, R A	8305090606	WASTE MGT	
PENTZ, D L	8305050404*	CONTRACT	
PERCH, R	8305100426	50-388	A
PERENSTEIN, J E	8305040643*	CONTRACT	
PERLIS, R G	8305090143	50-498	Q
PERLIS, R G	8305100334	50-443	Q
PERLIS, R G	8305100375*	50-443	Q
PERLIS, R G	8305100425*	50-443	Q
PERLIS, R G	8305110339	50-498	Q
PERLMAN, J	8305180412	CONTRACT	
PERNY, C	8305090461*	50-395	Q
PERRY, J F	8305120341*	50-320	T
PESCHEL, J	8305020348*	50-315	Q
PETERS, R	8305230459*	50-333	S
PETERSEN, J C	8305200624*	50-142	T
PETRICK, N A	8305110014	50-482	A
PETRICK, N A	8305110047	50-482	E
PETRICK, N A	8305130007	50-482	A
PETRICK, N A	8305180393	50-482	E
PETRICK, N A	8305310175	50-482	A
PETTENGILL, H J	8305120490	40-8602	
PETTENGILL, H J	8305120496	40-3453	
PETTENGILL, H J	8305120501	40-299	
PETTENGILL, H J	8305130297	40-3453	
PETTENGILL, H J	8305130317	40-8584	
PETTENGILL, H J	8305130328	40-6622	
PETTENGILL, H J	8305160259*	40-8675	
PETTENGILL, H J	8305250245	40-8452	
PETTENGILL, H J	8305250591	40-8452	
PETTENGILL, H J	8305250594	40-8550	
PETTY, J C	8305110335*	50-270	S
PETTY, J C	8305170338*	50-269	S
PETTY, J C	8305170566*	50-269	S
PFAFF, S J	8305020439	40-6659	
PFEFFERLEN, M C	8305040458	TOPREP	
PFLUM, C G	8305110178	WASTE MGT	
PHILIPPACOPOULO	8305110227	NUREG	
PHILLIP, G A	8305190061*	FOIA	
PHILLIPS, D	8305200598	50-440	Q
PHILLIPS, H S	8305020403	ORG	
PHILLIPS, H S	8305050117*	GA999	
PHILLIPS, H S	8305050192*	GA999	
PHILLIPS, H S	8305050262*	GA999	
PHILLIPS, H S	8305090413*	GA999	
PHILLIPS, H W	8305120155*	50-445	Q
PHILLIPS, M P	8305270614*	50-346	Q
PHILLIPS, R W	8305190367*	50-373	P
PICKARD, J K	8305270110*	CONTRACT	
PICKEL, T W	8305130346	ACRS	
PICKEL, T W	8305130346	ACRS	
PIEHL, R H	8305240329	50-315	S
PIEMONTESE, A P.	8305110430*	50-387	S
PIEMONTESE, A P	8305230477*	50-387	S
PIERCE, F W	8305240547	50-247	Q
PIERCE, R L	8305170693*	CONTRACT	
PIERINGER, P A	8305030388*	50-318	S
PIERINGER, P A	8305230528*	50-318	S
PIGOTT, D R	8305190195	50-361	Q
PIGOTT, D R	8305190195	50-361	Q
PIGOTT, D R	8305190212	50-361	Q
PIGOTT, D R	8305190212	50-361	Q
PIGOTT, D R	8305190252	50-361	Q
PILANT, J M	8305020449	50-298	P
PILANT, J M	8305030393	50-298	P
PILANT, J M	8305030554	50-298	P
PILANT, J M	8305050113	50-298	P
PILANT, J M	8305060380	50-298	I
PILANT, J M	8305270369	50-298	P
PILANT, M	8305030588	50-298	P
PLAINE, H H	8305230700	50-289	Q
PLAINE, H H E	8305230443*	50-289	U
PLATT, W E	8305240482	50-529	Q
PLIML, G	8305030084*	50-295	F
PLIML, G	8305030114*	50-295	F
PLIML, G	8305060679*	50-295	F
PLISCO, L	8305110508*	50-333	Q
PLISCO, L	8305250443*	50-245	Q
PLISCO, L R	8305230460*	50-289	Q
PLISCO, L R	8305250230*	50-286	Q
PLISCO, L R	8305250465*	50-336	Q
PLISCO, L R	8305250504*	50-213	Q
PLOSKI, T J	8305100090*	50-346	Q
PLOSKI, T J	8305270614*	50-346	Q
PLUMMER, M C	8305200307*	50-237	S
POCHAL	8305090015	XPORTLIC	
POCHAL, W	8305260330	XPORTLIC	
POCHAL, W F	8305130303	XPORTLIC	
POLK, P J	8305030284	50-286	P
POLLOCK, M S	8305050109	50-322	Q
POLLOCK, M S	8305120306*	50-322	Q
POLLOCK, M S	8305120311*	50-322	Q
POLLOCK, M. S	8305120380*	50-322	Q
POLLOCK, M S	8305180331*	50-322	Q
POLLOCK, R H	8305190302*	50-373	P
POMEROY, P W	8305130352	50-443	Q
POMEROY, P W	8305130352	50-443	Q
POOLE, J W	8305200352*	50-395	Q
POPPE, L K	8305170733	71-5026	
PORTER, B J.	8305270165	State Prog	
PORTER, D W	8305050164*	50-397	Q
PORTER, W A	8305090073*	50-128	Q
POSNER, P	8305030633*	50-247	Q
POSNER, P	8305240543	50-247	Q
POTAPOVS, U.	8305020254	GA999	
POTAPOVS, U	8305020261	GA999	
POTAPOVS, U	8305020289	GA999	
POTAPOVS, U	8305020316	GA999	
POTAPOVS, U	8305020346	GA999	
POTAPOVS, U	8305020364	GA999	
POTAPOVS, U	8305020366*	GA999	
POTAPOVS, U	8305020420	GA999	
POTAPOVS, U	8305020448	GA999	
POTAPOVS, U	8305030330	GA999	
POTAPOVS, U	8305030349	GA999	
POTAPOVS, U	8305030358	GA999	
POTAPOVS, U	8305030363	GA999	
POTAPOVS, U	8305030377	GA999	
POTAPOVS, U	8305030413	GA999	
POTAPOVS, U	8305030427	GA999	
POTAPOVS, U.	8305030466	GA999	
POTAPOVS, U	8305030509	GA999	
POTAPOVS, U	8305030544	GA999	
POTAPOVS, U.	8305050068	GA999	
POTAPOVS, U	8305050088	GA999	
POTAPOVS, U	8305050094	GA999	
POTAPOVS, U	8305050102	GA999	
POTAPOVS, U	8305050107	GA999	
POTAPOVS, U	8305050114	GA999	
POTAPOVS, U	8305050145	GA999	
POTAPOVS, U	8305050160	GA999	
POTAPOVS, U	8305050162	GA999	
POTAPOVS, U	8305050177	GA999	
POTAPOVS, U	8305050219	GA999	
POTAPOVS, U	8305050237	GA999	
POTAPOVS, U.	8305050251	GA999	
POTAPOVS, U.	8305090001	GA999	
POTAPOVS, U	8305090371	GA999	
POTAPOVS, U	8305090386	GA999	
POTAPOVS, U	8305090392	GA999	
POTAPOVS, U	8305090450	GA999	
POTAPOVS, U	8305100336	GA999	
POTAPOVS, U	8305100343*	GA999	
POTAPOVS, U.	8305120305	GA999	
POTAPOVS, U	8305120394	GA999	
POTAPOVS, U	8305120482	GA999	
POTAPOVS, U	8305170541	GA999	
POTAPOVS, U	8305170549	GA999	
POTAPOVS, U	8305200308	GA999	
POTAPOVS, U	8305200323*	GA999	
POTAPOVS, U	8305200333	GA999	
POTAPOVS, U	8305200370	GA999	
POTAPOVS, U	8305200411	GA999	
POTAPOVS, U	8305200418*	GA999	
POTAPOVS, U.	8305200443	GA999	
POTAPOVS, U	8305200446	GA999	
POTAPOVS, U	8305200462*	GA999	
POTAPOVS, U	8305200589	GA999	
POTAPOVS, U.	8305200668	GA999	
POTAPOVS, U	8305230497	GA999	
POTAPOVS, U	8305230514	GA999	
POTAPOVS, U	8305240333	GA999	
POTAPOVS, U	8305240336	GA999	
POTAPOVS, U	8305240344	GA999	

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
POTAPOVS, U	8305240352	QA999	
POTAPOVS, U	8305240361*	QA999	
POTAPOVS, U	8305240400	QA999	
POTAPOVS, U	8305240405	PT21	
POTAPOVS, U	8305240411	QA999	
POTAPOVS, U	8305240419	QA999	
POTAPOVS, U	8305240424	QA999	
POTAPOVS, U	8305240426	QA999	
POTAPOVS, U	8305240433*	QA999	
POTAPOVS, U	8305260291	QA999	
POTAPOVS, U	8305270267	QA999	
POTAPOVS, U	8305270291	QA999	
POTAPOVS, U	8305270302	QA999	
POTTERFIELD, A	8305030608	50-247	Q
POTTERFIELD, A	8305030608	50-247	Q
POTTERFIELD, A	8305030608	50-247	Q
POTTERFIELD, A	8305030641*	50-247	Q
POTTERFIELD, A	8305030641*	50-247	Q
POTTERFIELD, A	8305030652*	50-247	Q
POULK, R M	8305130176*	50-324	S
POULK, R M	8305200543*	50-324	S
POULOS, S J	8305060384*	50-329	A
POWELL, R H J	8305030337	TOPREP	
POWERS, D A	8305120556	50-537	D
POWERS, D A	8305120556	50-537	D
PRELL, J. A	8305250306*	50-277	Q
PRICHARD, R P	8305180210	71-4639	
PRICHARD, R P	8305240064	71-6553	
PRITCHETT, P A	8305110398*	50-334	P
PROCTOR, S D	8305100264	50-329	Q
PROCTOR, S. D	8305100264	50-329	Q
PROCTOR, S D	8305100418	50-329	Q
PROCTOR, S D	8305240373	50-329	Q
PROCTOR, S D	8305240491	50-329	Q
PROCTOR, S D	8305240491	50-329	Q
PROVENZANO, V P	8305040441	50-329	Q
PROVENZANO, V P	8305040509	50-329	Q
PUCEL, P	8305030709	40-8728	
PUNTENNEY, J	8305230229	FOIA	
PURPLE, R A	8303280325*	50-302	P
PURPLE, R A.	8304120042*	50-321	P
PURPLE, R A	8305170645*	50-301	P
PURPLE, R A	8305180548*	50-298	P
PURPLE, R A	8305180566*	50-324	P
QUEEN, W Q	8305020081*	70-378	
QUEEN, W Q	8305020539*	70-378	
QUEEN, W Q	8305040060*	70-378	
QUEEN, W. Q	8305040468*	70-378	
QUEEN, W Q.	8305050359*	FOIA	
QUICK, D	8305270303*	50-390	Q
RAHE, E. P	8304180548	TOPREP	
RAHE, E. P	8305030426	TOPREP	
RAHE, E P	8305050200	TOPREP	
RAHE, E P	8305090212	PROJ	
RAHE, E P	8305110427	50-334	S
RAHE, E. P	8305170408	50-454	T
RAHE, E. P	8305170554	TOPREP	
RAHE, E P	8305180262	TOPREP	
RAHE, E P	8305200304	PR	
RAHE, E P.	8305230255	TOPREP	
RAHE, E. P	8305270006	TOPREP	
RAHE, E P	8305270481	TOPREP	
RAJAN	8305170413*	50-454	T
RAJAN, J R	8305090578*	50-445	Q
RAJKI, S	8305170452	50-440	Q
RAMSDELL, J V	8305180782	NUREG	
RAMSDEN, J J	8305040093*	FOIA	
RAMSDEN, J. J	8305040114*	FOIA	
RAMSDEN, J J	8305050342*	FOIA	
RAMSDEN, J J	8305050351*	FOIA	
RAMSEY, C.	8305120447*	50-373	Q
RANDALL, R Q	8305060428*	50-220	S
RANDALL, R Q	8305060540*	50-220	S
RANDALL, R Q	8305200290*	50-220	S
RANDALL, W. I	8305020425	50-443	Q
RANDALL, W I	8305020429*	50-443	Q
RANDAZZA, J. B	8305030491	50-309	P
RATCLIFF, R H	8305040165*	FOIA	
RAWSON, R. J.	8305170545	50-322	Q
RAWSON, R. J.	8305250367	50-322	Q
RAY, H. B	8305030356	50-361	S
RAY, H B	8305030359*	50-361	S
RAY, H. B	8305030360	50-361	S
RAY, H B	8305030432	50-361	S
RAY, H B	8305060448	50-362	S
RAY, H B	8305060450*	50-362	S
RAY, H B	8305060467	50-361	S
RAY, H B	8305060505	50-361	S
RAY, H B	8305060514*	50-361	S
RAY, H B	8305160011	50-361	S
RAY, H. B	8305160014*	50-361	S
RAY, H B	8305160047	50-362	S
RAY, H B	8305160051*	50-362	S
RAY, H B	8305160055	50-361	S
RAY, H B	8305160069*	50-361	S
RAY, H B	8305160101*	50-361	S
RAY, H B	8305160110	50-362	S
RAY, H B	8305160115*	50-362	S
RAY, H B	8305160120	50-362	S
RAY, H B	8305160125*	50-362	S
RAY, H B	8305270131	50-361	S
RAY, H B	8305270157	50-362	S
RAY, H B	8305270243	50-361	S
RAY, H B	8305270321	50-361	S
RAY, H B	8305270408	50-361	S
READE, M T	8305310211	WASTE MGT	
REAVIS, J A	8305170460*	50-269	R
REAVIS, J A	8305170540*	50-369	R
REAVIS, J H	8305180063*	FOIA	
REBELLO, J E	8305040553*	CONTRACT	
REBELLO, J E	8305060251*	CONTRACT	
REBELLO, J E	8305110008*	CONTRACT	
REBELLO, J E	8305110152*	CONTRACT	
REBELLO, J E	8305110192*	CONTRACT	
REBELLO, J E	8305110198*	CONTRACT	
REBELLO, J E	8305120560*	CONTRACT	
REBELLO, J E	8305130300*	CONTRACT	
REBELLO, J E	8305130361*	CONTRACT	
REBELLO, J E	8305180047*	50-247	P
REBELLO, J E	8305180792*	CONTRACT	
REBELOWSKI, T H	8305250309*	50-213	Q
REDANO, R T	8305170333*	50-298	Q
REDMOND, R F	8305110192*	CONTRACT	
REDWANZ, F J	8305180284*	50-321	R
REED, C	8305020234*	50-456	Q
REED, C	8305060554*	50-373	Q
REED, C	8305170167	50-254	Q
REED, C	8305170184*	50-254	Q
REED, C	8305200621	50-373	P
REED, J R	8305240544	50-440	Q
REEDY, R F	8305180427	50-275	R
REESIDE, B.	8305040260*	50-369	S
REESIDE, W Q	8305040246*	50-369	S
REEVES, E A	8305090016	50-348	P
REGAN, N A	8305040637	XPORTLIC	
REHM, T	8305020565	50-329	A
REHM, T A	8305040777	COMMISSION	
REHM, T A	8305110135	COMMISSION	
REHM, T A	8305170717	COMMISSION	
REHM, T A	8305180236*	50-498	A
REHM, T A	8305230121	COMMISSION	
REHM, T A	8305250183	50-289	Q
REHRIG, A W	8305020560*	FOIA	
REHRIG, A W	8305030260*	70-378	
REHRIG, A W	8305040183*	FOIA	
REIMANN, F W	8305170304*	50-341	Q
REIMANN, F W	8305260224*	50-440	Q
REIMERS, G A	8305030396*	50-331	S
REIMERS, G A	8305240236	50-331	S
REINMUTH, G W	8305180083*	50-498	Q
REIS, M P	8305160176*	50-275	P
REIVITZ, L	8305040660*	CONTRACT	
REMICK, F J	8111030653*	FOIA	
REMLEY, M E	8305310219	70-25	
REMLEY, M E	8305310220*	70-25	
RENNER, A E	8305120304	50-440	Q
REPKA, D A	8305100222	50-322	Q
REPKA, D. A	8305170563	50-322	Q
REPKA, D A	8305200590	50-322	Q
REPKA, D A	8305260271	50-322	Q
REQUA, G	8305060378	50-261	P
REQUA, G	8305060678	50-261	P
REQUA, G	8305110618	50-261	F
REQUA, G	8305160346	50-261	P
RESETAR, J	8305270454	50-336	S
REBBLER, W C.	8305020210	50-289	R
REVELEY, W T	8305100391	50-322	Q
REYES, L A.	8304120412*	50-373	Q
REYES, L A	8305020357*	50-483	Q
REYES, L A	8305170304*	50-341	Q
REYES, L A	8305170403*	50-373	
REYES, L A	8305260224*	50-440	
REYNOLDS, J R	8305110212	50-275	
REYNOLDS, J R	8305110383	50-275	
REYNOLDS, J R	8305120285	50-275	
REYNOLDS, J R	8305120285	50-275	
REYNOLDS, J W	8305240565*	50-155	
REYNOLDS, N S	8303290382	50-397	
REYNOLDS, N S	8303290382	50-397	
REYNOLDS, N S	8305020473	50-460	
REYNOLDS, N S	8305020473	50-460	
REYNOLDS, N S	8305050009	50-460	
REYNOLDS, N S	8305050009	50-460	
REYNOLDS, N S	8305050018	50-445	
REYNOLDS, N S	8305050018	50-445	
REYNOLDS, N S	8305050019	50-460	
REYNOLDS, N S	8305050019	50-460	
REYNOLDS, N S	8305060491	50-508	
REYNOLDS, N S	8305060491	50-508	
REYNOLDS, N S	8305090507	50-445	
REYNOLDS, N S	8305090507	50-445	
REYNOLDS, N S	8305100270	50-445	
REYNOLDS, N S	8305100270	50-445	
REYNOLDS, N S	8305100295	50-445	
REYNOLDS, N S	8305100295	50-445	
REYNOLDS, N S	8305100321	50-445	
REYNOLDS, N S	8305100321	50-445	
REYNOLDS, N S	8305130260	50-445	
REYNOLDS, N S	8305130260	50-445	
REYNOLDS, N S	8305170516	50-460	
REYNOLDS, N S	8305170516	50-460	
REYNOLDS, N S	8305180449	PR	
REYNOLDS, N S	8305250406	PR	
REYNOLDS, S	8305110338*	50-289	
REYNOLDS, S	8305240321	50-254	
REYNOLDS, S D	8305050147*	50-277	
REYNOLDS, S D	8305250509*	50-286	
REZNICEK, B W	8305230588	50-285	
RHEE, S	8305240207	50-237	
RHODE, G K	8305060043	50-220	
RHODE, G. K	8305060046*	50-220	
RHODE, G K	8305230582*	50-410	
RHODES, M	8305030246*	40-8027	
RICCARDELLA, P	8305060055*	50-321	
RICE, D A	8305050268*	50-29	
RICHARDS, B L	8305270167*	70-143	
RICHARDS, B L	8305310022*	70-1201	
RICHARDS, J	8305050256	50-416	
RICHARDS, S	8305250505*	50-289	
RICHARDS, W J	8305180353	PR	
RICHARDSON, J D	8305130126	50-416	
RICHARDSON, J D	8305130126	50-416	
RICHARDSON, J D	8305250072	50-416	
RICHMOND, J S	8305310164	50-305	
RICHTER, L	8305130095*	50-346	
RICHTER, L.	8305170171*	50-346	
RIDDLE, D H	8304270399	71-9135	
RIDGWAY, D	8305120391	50-482	
RIDGWAY, D	8305120391	50-482	
RIDGWAY, D A	8305060488	50-482	
RIDGWAY, D A	8305130137	50-261	
RIDGWAY, D A	8305180429	50-382	
RIDGWAY, D. A	8305180429	50-382	
RIDGWAY, D. A	8305240487	50-289	
RIDGWAY, K R	8305230139*	70-1193	
RILEY, E J	8305060145*	FOIA	
RILEY, J L	8305060252	50-413	
RILEY, J L	8305060252	50-413	
RILEY, R W	8305230428*	COMMISSIO	
RINQ, M A	8305020357*	50-483	
RIPLINQ, E J	8305110512	NUREG	
RISSO, R. P	8305180562*	CONTRACT	
RITCHIE, L T	8305310210	NUREG	
RITTER, D	8305230703	50-289	
RIVENBARK, G W	8305040711	50-366	
RIVENBARK, G W	8305040748	50-321	
ROBBINS, J. G	8305160063	TOPREP	
ROBERDS, H W	8305100116*	50-482	
ROBERDS, H W	8305230480*	50-482	
ROBERTS, E	8305110398*	50-334	
ROBERTS, H R	8305020481	40-8681	
ROBERTS, S	8304070286*	50-269	
ROBERTS, W	8305110089*	50-373	
ROBINSON, D	8305020171*	50-316	
ROBINSON, D.	8305020312*	50-315	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
ROBINSON, D	8305020321*	50-315	S
ROBINSON, D	8305060411*	50-315	S
ROBINSON, D.	8305120324*	50-316	S
ROBINSON, D	8305240145	50-316	S
ROBINSON, D.	8305240345	50-315	S
ROBINSON, R Q	8305030416	PR	
ROBINSON, R Q	8305200296	PR	
ROCKETT, D R	8305240046	71-166	
RODGERS, H R	8305250526	50-327	S
RODRIGUEZ, P	8305190220	50-247	Q
RODRIGUEZ, R J	8305020383	50-312	P
RODRIGUEZ, R J	8305020384	50-312	P
RODRIGUEZ, R J	8305020415	50-312	P
RODRIGUEZ, R J	8305020483	50-312	Q
RODRIGUEZ, R J	8305030287	50-312	S
RODRIGUEZ, R J	8305030551	50-312	S
RODRIGUEZ, R J	8305060419	50-312	P
RODRIGUEZ, R J	8305100229	50-312	P
RODRIGUEZ, R J	8305100296	50-312	P
RODRIGUEZ, R J	8305100338	50-312	P
RODRIGUEZ, R J	8305100344	50-312	P
RODRIGUEZ, R J	8305100381	50-312	Q
RODRIGUEZ, R J	8305130105	50-312	S
RODRIGUEZ, R J	8305130163	50-312	S
RODRIGUEZ, R J	8305130219	50-312	S
RODRIGUEZ, R J	8305230456	50-312	Q
RODRIGUEZ, R J	8305270080	50-312	Q
RODRIGUEZ, R J	8305310171	50-312	P
ROGAN, R E	8305240536	50-219	Q
ROGERS, H R	8304190537*	50-327	S
ROGERS, H. R	8305030183*	50-327	S
ROGERS, H R	8305050206*	50-327	S
ROGERS, H R	8305050224*	50-328	S
ROGERS, H R	8305110419*	50-328	S
ROGERS, H R	8305200581*	50-327	S
ROGERS, H R	8305250342	50-328	S
ROGERS, H R	8305250400	50-328	S
ROGERS, L C	8305120347*	50-320	T
ROGERS, P	8305020378*	50-368	S
ROGERS, P.	8305030390*	50-313	S
ROGERS, P.	8305060454*	50-313	S
ROGERS, P	8305120418*	50-313	S
ROGERS, W H	8305030690*	50-321	F
ROGGE, J	8305270160*	50-369	Q
ROGGE, J F	8305130138	50-321	S
ROHATGI, U S	8305110131	NUREG	
ROHRER, D M	8305090586*	50-445	Q
ROHRER, M V	8305050261*	50-416	S
ROHRER, M V	8305110279*	50-416	S
ROHRER, M V	8305170426*	50-416	S
ROHRER, M V	8305200493*	50-416	S
ROHRER, M V	8305200532*	50-416	S
ROHRER, M V	8305250487	50-416	S
ROHRER, M V	8305310065	50-416	S
ROHRER, M V	8305310207	50-416	S
ROISMAN, A Z	8305180792*	CONTRACT	
ROLES, G W	8305090567	WASTE MGT	
ROMAN, T W	8305170395*	50-220	R
ROMANO, F R	8305040470	50-352	Q
ROMANO, F. R	8305260181	50-352	Q
ROMO, L R	8305170396*	50-329	H
ROONEY, V L	8305110045*	50-331	P
ROONEY, V L	8305170069	50-271	P
ROONEY, V L	8305180093*	50-331	P
ROONEY, V L	8305180229*	50-293	P
ROOT, L D	8305030131	50-331	Q
ROOT, L D	8305040389	50-331	Q
ROOT, L D	8305060060	50-331	P
ROOT, L D	8305100095	50-331	P
ROOT, L D.	8305100320	50-331	Q
ROOT, L D	8305100372*	50-331	Q
ROOT, L D	8305230562	50-331	P
ROOT, L. D	8305240120	50-331	P
ROOT, L D.	8305240511	50-331	Q
ROOT, L E.	8305230293*	CONTRACT	
ROSAK, S	8305270502*	50-305	Q
ROSANO, R	8305020252	50-295	Q
ROSE, J J	8305040514*	50-322	E
ROSS, F W	8305060369*	40-8783	
ROSS, F. W	8305170595	40-8064	
ROSS, W J	8305270574*	50-280	Q
ROSSBACH, L W	8305100410*	50-286	Q
ROSSI, C E	8305090640*	50-445	Q
ROSZTOCZY, Z R.	8208250506*	50-373	P
ROTE, A	8305200656	50-440	Q
ROTHSCHILD, M U	8305030514	50-445	Q
ROTHSCHILD, M U	8305040557	50-445	Q
ROTHSCHILD, M U	8305090568	50-445	Q
ROTHSCHILD, M U	8305130013	50-445	Q
ROTHSCHILD, M U	8305160147	50-445	Q
ROTHSCHILD, M U	8305270015	50-445	Q
ROUSE, L C	8305040092	PROJ	
ROUSE, L C	8305130276	PROJ	
ROUSE, L C	8305170568	70-8	
ROUSE, L C	8305170570*	70-8	
ROWE, C	8305060209*	40-672	
ROWE, C A	8305050166*	40-3079	
ROWSOME, F	8305100245*	50-329	T
ROY, D. H	8305030410	TOPREP	
ROY, G W	8305230207*	40-1478	
ROZAK, S	8305270270*	50-341	Q
RUBENSTEIN, D	8301120436*	50-247	P
RUBENSTEIN, D	8305050287*	50-247	P
RUBENSTEIN, L S	8304150458*	50-454	F
RUBIN, S	8305040737*	50-259	P
RUBIN, S	8305040745*	50-259	P
RUDD, C C.	8305190214	50-440	Q
RUDIN, L	8305240517	50-247	H
RUDY, C R	8305180117	40-6500	
RUEBHAUSEN, O M	8305110152*	CONTRACT	
RUFF, A B.	8305270618*	50-438	Q
RUITER, G. H.	8305130251*	50-305	R
RULAND, W. H	8305270370*	50-348	Q
RUNCO, F	8305180459*	50-322	H
RUNCO, F	8305180461*	50-322	H
RUNKLE, J	8305060532	50-400	Q
RUNKLE, J	8305060532	50-400	Q
RUNKLE, J.	8305090475	50-400	Q
RUSLING, D H	8305180334	PR	
RUSSELL, L B.	8305030383	50-318	S
RUSSELL, L B	8305060635*	50-317	F
RUSSELL, L B	8305110352	50-317	S
RUSSELL, L B	8305160081	50-318	S
RUSSELL, L B	8305190287	50-317	S
RUSSELL, L B	8305190348	50-318	S
RUSSELL, L B	8305230510	50-317	S
RUSSELL, L B	8305230522	50-318	S
RUSSELL, L B.	8305230555	50-317	S
RUSSELL, L B.	8305270072	50-317	S
RUSSELL, L B	8305270603	50-317	S
RUSSO, H L	8305200315*	GA999	
RUSSO, H L	8305200332*	GA999	
RUTLEDGE, C	8305260144	40-8502	
RUTTENBERG, J I	8305120296	50-352	Q
RUZICKA, W O.	8305170504*	50-54	Q
RUZICKA, W O	8305170508*	50-54	Q
RUZICKA, W Q	8305180334	PR	
RYAN, R F	8305120344*	50-320	T
RYBAK, B	8304040268	50-237	Q
RYBAK, B	8305020458	50-254	P
RYBAK, B.	8305040446	50-237	P
RYBAK, B	8305040520	50-237	P
RYBAK, B	8305040551	50-237	P
RYBAK, B	8305050043	50-254	P
RYBAK, B	8305100092	50-237	Q
RYBAK, B	8305100190*	50-10	Q
RYBAK, B	8305130038	50-237	P
RYBAK, B	8305130209	50-237	P
RYBAK, B	8305180376	50-237	P
RYBAK, B	8305200295	50-237	S
RYBAK, B	8305240245	50-237	P
RYBAK, B	8305250377	50-237	Q
RYBAK, B	8305260290	50-237	P
RYBAK, B.	8305270395	50-237	Q
RYBAK, B	8305270419	50-237	P
RYBAK, B.	8305310037	50-237	P
SALTZMAN, J	8305180767	70-2973	
SAMP, R A	8305090537	50-358	T
SANCHEZ, R. L	8305180056*	FOIA	
SANDERS, W. F	8305270328*	50-424	Q
SANDERS, W F	8305270337*	50-424	Q
SANDOZ, S A	8305040466*	TOPREP	
SANDQUIST, G M.	8305190380*	50-407	P
SANTORO, M P	8305180194	71-9180	
SARGENT, A. V	8305090501	50-443	Q
SARGENT, A V	8305090502*	50-443	Q
SARGENT, I	8208060249*	50-338	P
SARGENT, I H	8305310241*	50-285	P
SARSTEN, G E	8305200495	50-443	S
SAUBERMAN, A	8305240517	50-247	H
SAWICKI, J	8304040394*	50-322	U
SCALETTI, D C	8305120078*	50-70	P
SCARANO, R A	8305170515	50-361	Q
SCARANO, R A	8305240393*	50-275	Q
SCHAEFER, D W	8305270115	50-312	S
SCHAEFFER, M A	8305270035*	50-320	P
SCHAPKER, J F	8305270496*	50-318	Q
SCHEPPACH, R C	8305260380*	CONTRACT	
SCHERER, A E	8305020400	50-470	E
SCHERER, A E	8305090338	50-470	E
SCHERER, A E	8305120120	50-470	S
SCHERER, A E	8305120185	50-470	E
SCHERER, A E	8305130081	50-470	E
SCHERER, A E	8305170326	50-470	A
SCHERER, A E	8305170527	50-335	S
SCHERER, A E	8305200568	50-470	E
SCHMIDT, H C	8305100125	50-445	A
SCHMIDT, H C	8305100130	50-445	R
SCHMIDT, H C	8305310151	50-445	A
SCHMIDT, W H	8305050432	NUREG	
SCHMITT, H	8305180116*	FOIA	
SCHMITTDIEL, P	8305060651	40-8697	
SCHMUTZ, T. A	8305110445	50-537	Q
SCHNAUTZ, C E	8305260330	XPORTLIC	
SCHNELL, D F	8303240307	50-483	A
SCHNELL, D F	8304150354	50-482	S
SCHNELL, D F	8305030263*	50-483	Q
SCHNELL, D F	8305060293*	50-483	Q
SCHNELL, D F	8305170136*	50-483	Q
SCHNELL, D F	8305170188*	50-483	Q
SCHNELL, D F	8305170227*	50-483	Q
SCHNELL, D F	8305200518*	50-483	Q
SCHROCK, C A	8305170271*	50-305	S
SCHROEDER, B A	8305130202*	50-237	R
SCHROEDER, C W	8304290034	50-373	P
SCHROEDER, C W	8305030161	50-373	P
SCHROEDER, C W	8305060569*	50-373	Q
SCHROEDER, C. W.	8305100352	50-374	S
SCHROEDER, C W	8305110082	50-373	P
SCHROEDER, C W	8305190353*	50-373	P
SCHROEDER, C W	8305230584	50-373	P
SCHROEDER, C W	8305240110	50-373	P
SCHROEDER, C W	8305240111	50-374	A
SCHULER, R. T.	8305240517	50-247	H
SCHULER, R T	8305240517	50-247	H
SCHULER, T. R	8305190175*	50-244	S
SCHULER, T R	8305190238*	50-244	S
SCHULLKE, D. A	8305030226*	50-282	F
SCHULTZ, C	8305060444*	50-295	S
SCHULZ, R. D.	8305190334*	50-410	Q
SCHUM, W S	8305100160*	50-482	Q
SCHUMACHER, D G	8305110196	NUREG	
SCHUMACHER, M	8305270270*	50-341	Q
SCHUMACHER, M C	8303280182*	40-2061	
SCHUMACHER, M C	8305170248*	50-454	Q
SCHUMACHER, M C	8305270502*	50-305	Q
SCHUYLER, J D	8305020388	50-275	P
SCHUYLER, J D	8305040328*	50-275	P
SCHUYLER, J D	8305310135*	50-275	P
SCHWENCER, A.	8303300772	50-387	P
SCHWENCER, A	8304290013	50-352	F
SCHWENCER, A	8305030106	50-458	E
SCHWENCER, A	8305040527	50-352	A
SCHWENCER, A.	8305040616	50-387	P
SCHWENCER, A	8305040669	50-387	P
SCHWENCER, A	8305040677	50-458	A
SCHWENCER, A	8305050366	50-387	Q
SCHWENCER, A	8305050402	50-373	F
SCHWENCER, A	8305090602	50-458	A
SCHWENCER, A	8305090633	50-410	A
SCHWENCER, A	8305090648*	50-410	A
SCHWENCER, A	8305110171	50-373	P
SCHWENCER, A	8305110616	50-458	E
SCHWENCER, A.	8305120580	50-373	P
SCHWENCER, A	8305120593*	50-373	P
SCHWENCER, A	8305170604	50-459	E
SCHWENCER, A	8305170705*	50-461	A
SCHWENCER, A	8305200091	50-387	F
SCHWENCER, A	8305200176	50-387	P
SCHWENCER, A	8305250082	50-397	E
SCHWENCER, A.	8305260327*	50-352	Q
SCHWENCER, A	8305260348	50-458	E
SCHWENCER, A	8305270028	50-416	F
SCHWENCER, A	8305270039	50-458	A
SCHWINK, W	8305170718	REVIEW GRP	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
SCHWINK, W	8305200535	REVIEW ORP	
SCOTT, D E	8305270438*	50-416	Q
SCOTT, D J	8305020246	50-249	S
SCOTT, D J	8305060416	50-237	S
SCOTT, D J	8305060486	50-237	S
SCOTT, D J	8305060511	50-237	S
SCOTT, D J	8305060563	50-249	S
SCOTT, D J	8305060581	50-249	S
SCOTT, D J	8305060590	50-237	S
SCOTT, D J	8305060603	50-237	S
SCOTT, D J	8305130197	50-237	R
SCOTT, D J	8305170134	50-237	S
SCOTT, D J	8305170159	50-237	S
SCOTT, D J	8305240202	50-237	S
SCOTT, D J	8305240207	50-237	S
SCOTT, D J	8305240335	50-237	S
SCOTT, D J	8305240366	50-249	S
SCOTT, D J	8305240494	50-237	S
SCOTT, D J	8305310149	50-237	S
SCOTT, D J	8305310158	50-237	S
SCOTT, D J	8305310165	50-237	S
SCOTT, D J	8305310182	50-237	S
SCOTTON, L N	8305100144*	50-293	R
SCURRY, N	8305040001	ORG	
SCURRY, N	8305040003	ORG	
SCURRY, N	8305090006	ORG	
SEARS, C F	8305030404	50-245	P
SEARS, C F	8305030404	50-245	P
SEARS, C F	8305060213	50-213	F
SEARS, C. F	8305060213	50-213	F
SEARS, C F.	8305060455	50-423	S
SEARS, C. F	8305060455	50-423	S
SEARS, C F	8305090404	50-213	P
SEARS, C F	8305090465	50-213	P
SEARS, C F.	8305090465	50-213	P
SEARS, C F	8305090465	50-213	P
SEARS, C F.	8305090471	50-245	P
SEARS, C. F	8305090471	50-245	P
SEARS, C. F.	8305100385	50-213	P
SEARS, C F.	8305120241	50-336	P
SEARS, C F	8305120241	50-336	P
SEARS, C F	8305160183	50-213	P
SEARS, C. F.	8305250510	50-213	P
SEARS, C. F.	8305250510	50-213	P
SEARS, C F	8305270036	50-423	S
SEARS, C. F.	8305270036	50-423	S
SEARS, C. F	8305270037*	50-423	Q
SEARS, C F.	8305270037*	50-423	Q
SEARS, C. F	8305270074	50-336	Q
SEARS, C F	8305270074	50-336	Q
SEARS, C F.	8305270114	50-245	P
SEARS, C. F	8305270114	50-245	P
SEARS, F	8305200340*	QA999	
SEAVER, D A.	8305110528	NUREG	
SEIDENSTICKER	8305130350	50-537	Q
SEIDENSTICKER	8305130350	50-537	Q
SEIDENSTICKER	8305180637	50-537	Q
SEIDENSTICKER	8305180637	50-537	Q
SEIDLE, W. C.	8304150143	50-313	Q
SEIDLE, W. C	8305020445*	50-313	Q
SEIDLE, W. C.	8305030325	50-313	Q
SEIDLE, W C	8305030425	50-285	F
SEIDLE, W C	8305030617	50-482	Q
SEIDLE, W C	8305100006	50-192	Q
SEIDLE, W. C.	8305100009*	50-192	Q
SEIDLE, W. C	8305100112	50-482	Q
SEIDLE, W C.	8305100151	50-482	Q
SEIDLE, W. C.	8305100241	50-285	Q
SEIDLE, W. C.	8305100348	50-313	Q
SEIDLE, W C	8305120445	50-313	Q
SEIDLE, W. C.	8305200313	50-313	Q
SEIDLE, W C.	8305230337	50-313	Q
SEIDLE, W. C.	8305230464	50-285	Q
SEIDLE, W. C.	8305230473	50-482	Q
SEIDLE, W. C.	8305230485	50-482	Q
SEIDLE, W C	8305240049	50-313	Q
SEIDLE, W. C.	8305240173	50-285	Q
SEIDLE, W. C.	8305310104	50-482	Q
SEIDLE, W C	8305310194	50-313	Q
SEIDLER, Q.	8305030080*	FOIA	
SEIDLER, Q.	8305030326*	70-378	
SEIFFERT, S. Q.	8305160205	40-2259	
SEIFFERT, B Q.	8305200031	40-4492	
SEIKEN, S.	8305040430	50-482	S
SEIKEN, S. J.	8305020073	50-482	S
SELAN, J C	8209020602*	50-335	P
SELAN, J C	8304060471*	50-335	P
SELJON, R	8305200656	50-440	Q
SELLS, D E	8305110105	50-335	P
SELLS, D E	8305120146	50-335	P
SELLS, D E	8305120499	50-335	P
SELLS, D E	8305120520	50-335	P
SELLS, D E	8305170103	50-335	P
SELLS, D E	8305240599	50-335	P
SEMMEL, H	8305100290	50-155	Q
SEMMEL, H	8305100290	50-155	Q
SEMMEL, H	8305190366	50-155	Q
SEMMEL, H	8305190366	50-155	Q
SEMMEL, H	8305190371*	50-155	Q
SEMMEL, H	8305190371*	50-155	Q
SEMMEL, H	8305190375*	50-155	Q
SENCER, D J	8305190264	State Prog	
SERINI, B L	8305190007*	70-2973	
SERKIZ, A W	8305170118	NUREG	
SERKIZ, A W	8305170123	NUREG	
SERNE, R J	8305060233	NUREG	
SERRANO, W	8304220257*	50-321	P
SESTAK, F	8305030282*	50-275	R
SESTAK, F	8305030545*	50-275	R
SESTAK, F	8305100179*	50-275	R
SESTAK, F	8305100185*	50-275	R
SESTAK, F	8305120211*	50-275	R
SESTAK, F	8305120216*	50-275	R
SESTAK, F.	8305170517*	50-275	R
SESTAK, F	8305230221*	50-275	R
SESTAK, F	8305230559*	50-275	R
SESTAK, F	8305250467*	50-275	R
SESTAK, F	8305310191*	50-275	R
SEYFRIT, K V	8211150068*	50-312	Q
SEYFRIT, K V	8305180181*	50-498	Q
SEYFRIT, K V	8305200684*	50-373	P
SEYMOUR, L A	8305260222*	CONTRACT	
SHACKLETON, O C	8305090038*	FOIA	
SHACKLETON, O C .	8305090043*	FOIA	
SHACKLETON, O C	8305090047*	FOIA	
SHACKLETON, O C	8305090055*	FOIA	
SHACKLETON, O C	8305090057*	FOIA	
SHAFER, W	8305020511	50-331	S
SHAFER, W D	8305020100	50-10	Q
SHAFER, W D	8305100181	50-10	Q
SHAFER, W D.	8305100215	50-331	Q
SHAFER, W. D.	8305100216*	50-331	Q
SHAFER, W D	8305100217	50-329	T
SHAFER, W. D	8305100261	50-329	T
SHAFER, W D	8305100262	50-295	Q
SHAFER, W D.	8305100266*	50-295	Q
SHAFER, W D	8305120456	50-266	Q
SHAFER, W D	8305120463*	50-266	Q
SHAFER, W. D	8305130109	50-409	Q
SHAFER, W. D	8305170166	50-155	Q
SHAFER, W D	8305170168*	50-155	Q
SHAFER, W. D.	8305190307*	50-329	Q
SHAFER, W. D	8305200239	50-255	Q
SHAFER, W. D	8305200244*	50-255	Q
SHAFER, W D.	8305200591	50-263	Q
SHAFER, W. D	8305240029	50-282	Q
SHAFER, W. D	8305240032	50-255	Q
SHAFER, W. D	8305240067	50-346	Q
SHAFER, W D	8305240078	50-315	Q
SHAFER, W D	8305240302	50-315	Q
SHAFER, W. D	8305240306*	50-315	Q
SHAFER, W. D	8305240367	50-255	Q
SHAFER, W D.	8305260314	50-263	S
SHAFER, W. D.	8305310105	50-254	Q
SHAFFNER, J A	8305110180	27-39	
SHAHBAKY, M	8305110320*	50-309	Q
SHAHBAKY, M	8305190174*	50-272	Q
SHAHBAKY, M	8305190191*	50-271	Q
SHAHBAKY, M M.	8305110267*	50-277	Q
SHANNON, J B.	8305260145	40-8064	
SHAO, J	8305170101	NUREG	
SHAPIRO, R.	8305100256	50-322	Q
SHAPIRO, R.	8305100274	50-322	Q
SHAUB, E T	8305230460*	50-289	Q
SHAUB, E T.	8305250306*	50-277	Q
SHAUB, E. T	8305250505*	50-289	Q
SHAW, L.	8305230289*	CONTRACT	
SHELLEY, W J	8305200052	40-8027	
SHEPHERD, R. E	8305120397*	QA999	
SHERWOOD, G. G	8303240338	50-447	A
SHERWOOD, G G	8305020355	50-447	E
SHERWOOD, G G	8305030403	50-447	A
SHERWOOD, G G	8305090495*	TOPREP	
SHERWOOD, G G	8305100298	50-447	E
SHERWOOD, G G	8305200157	50-447	A
SHERWOOD, G G	8305260037	50-447	E
SHERWOOD, G G	8305260048*	50-447	E
SHEWMAKER, R E	8305030474*	50-483	Q
SHIELDS, S W	8304250167	50-546	A
SHIELDS, S W	8305020118	50-546	S
SHIELDS, S W	8305020291	50-546	S
SHIELDS, S W	8305040494	50-546	S
SHIELDS, S W	8305120457	50-546	A
SHIELDS, S W	8305130119	50-546	A
SHIELDS, S W	8305130207	50-546	S
SHIELDS, S W	8305170306	50-546	A
SHIELDS, S W	8305170306	50-546	A
SHIELDS, S W	8305200289	50-546	F
SHIELDS, S W	8305200289	50-546	F
SHIELDS, S W	8305230654	50-546	A
SHIELDS, S W	8305240408	50-546	S
SHIELDS, S W	8305260332	50-546	S
SHIFFER, J D	8305170336	50-133	S
SHIFFER, J D	8305240397	50-275	S
SHIFFER, J D	8305270249	50-275	S
SHIMA, S	8305020557*	XPORTLIC	
SHIMECK, D J	8305110518	NUREG	
SHINE, C	8305030624*	50-245	P
SHINE, C	8305030624*	50-245	P
SHINGLETON, E B	8305050261*	50-416	S
SHINGLETON, E B	8305110279*	50-416	S
SHINGLETON, E B	8305170426*	50-416	S
SHINGLETON, E B	8305310065	50-416	S
SHINGLETON, E B	8305310207	50-416	S
SHIRAKAWA, T	8305170575	XPORTLIC	
SHIRAKAWA, T	8305170580	XPORTLIC	
SHIRAKAWA, T	8305170582	XPORTLIC	
SHIRAKAWA, T	8305180629	XPORTLIC	
SHIRAKAWA, T	8305180819	XPORTLIC	
SHIRAKAWA, T	8305180826	XPORTLIC	
SHIVELY, C	8305180467	50-368	P
SHOEMAKER, C J	8305030550	50-352	Q
SHOEMAKER, C J	8305040504	50-358	Q
SHOEMAKER, C J	8305110345	PROJ	
SHOEMAKER, C J	8305110350	50-358	Q
SHOEMAKER, C J	8305120314	50-483	Q
SHOEMAKER, C J	8305120319	50-289	Q
SHOEMAKER, C J	8305130083	50-483	Q
SHOEMAKER, C J	8305200657	50-275	Q
SHOEMAKER, C J	8305240520	50-155	Q
SHOEMAKER, C J	8305270604	50-289	Q
SHOLLY, S C	8305230005	FOIA	
SHOLLY, S C	8305230243	FOIA	
SHOLLY, S C	8305240249	50-245	P
SHON, F J	8305040464	50-247	Q
SHON, F J	8305130030	50-247	Q
SHOTWELL, J A	8305090523	50-443	F
SHREVE, D. B	8305090131*	CONTRACT	
SHYMLOCK, M B	8305270455*	50-338	Q
SHYMLOCK, M B	8305270544*	50-338	Q
SIEBER, J D	8305060261	50-334	R
SIEBERLING, J	8305240275*	50-358	Q
SIEDLER, Q	8305040593*	70-378	
SIEFKEN, D L	8305090647	WASTE MGT	
SIEGEL, B.	8305160337	50-298	P
SILBERG, J E	8305020470	50-440	Q
SILBERG, J E	8305020470	50-440	Q
SILBERG, J E	8305040307	50-440	Q
SILBERG, J E	8305040307	50-440	Q
SILBERG, J E	8305040506	50-440	T
SILBERG, J E	8305240313	50-482	Q
SILBERG, J E	8305240313	50-482	Q
SILBERT, E J	8305120560*	CONTRACT	
SILBERT, E. S	8305230012*	ADVCM	
SILKER, W B	8305060674	NUREG	
SILKER, W B	8305110457	NUREG	
SILVER, H	8305170105	50-289	P
SILVER, H	8305240028	50-289	P
SILVIS, R	8305170603	CONTRACT	
SILVIS, R M	8305040630	CONTRACT	
SILVIS, R M	8305270108	CONTRACT	
SIMAN-TOV, M	8305060349	RES	
SIMPSON, A K	8305110584*	COMMISSION	
SIMPSON, C	8305020006	FOIA	
SIMPSON, G H	8305230220	FOIA	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
SIMPSON, J M	8305180288	50-482 G
SIMPSON, J M	8305180288	50-482 G
SINCLAIR, J B	8305130103	50-271 P
SINCLAIR, J B	8305200517	50-271 P
SINCLAIR, J B	8305240195	50-271 P
SINCLAIR, J B	8305270141	50-271 P
SINCLAIR, J B	8305310212	50-271 F
SINCLAIR, J R	8305180100*	FOIA
SINCLAIR, L W	8305160088	50-286 P
SINCLAIR, M	8305250215	50-329 G
SINCLAIR, M	8305260169	50-329 G
SINISI, J M	8305120006	50-213 J
SINISI, J M	8305120059	50-293 J
SINISI, J M	8305120110	50-244 J
SINISI, J M	8305120156	50-245 J
SINISI, J M	8305120200	50-29 J
SISCO, H W	8305020019*	FOIA
SISCO, H W	8305030020*	FOIA
SISCO, H W	8305030035*	FOIA
SISCO, H W	8305030055*	FOIA
SISCO, H W	8305030105*	FOIA
SISCO, H W	8305030185*	FOIA
SISCO, H W	8305040234*	FOIA
SISCO, H W	8305040250*	FOIA
SISCO, H W	8305010569*	FOIA
SISKIND, B	8305020547	NUREG
SISKIND, B	8305170101	NUREG
SKARUPA, J D	8305060006	XPORTLIC
SKILES, L J	8305090510*	50-445 T
SKINNER, P H	8305270442*	50-338 G
SKINNER, P H	8305270594*	50-335 G
SKOLDS, J L	8305270462*	50-395 G
SKOLDS, J L	8305270532*	50-395 G
SKOV, D D	8305260273*	40-8137
SLATEN, N G	8305250432*	50-483 G
SLATEN, N G	8305250552*	50-483 G
SLEMBER, R J	8305240346*	QA999
SMITH, A	8305040345*	CONTRACT
SMITH, A L	8305050192*	QA999
SMITH, A L	8305090413*	QA999
SMITH, B G	8305120350*	50-320 T
SMITH, C F	8305310143	50-329 A
SMITH, G C	8304180554*	70-1143
SMITH, G C	8305190313*	50-271 G
SMITH, I W	8305040405	50-454 G
SMITH, I W	8305160162	50-454 G
SMITH, I W	8305200521	50-454 G
SMITH, J A	8305120355*	50-320 T
SMITH, J C	8305020410	40-6622
SMITH, J C	8305030277	40-6622
SMITH, J L	8305040303	50-322 E
SMITH, J L	8305040508	50-322 E
SMITH, J L	8305120328	50-322 S
SMITH, J L	8305160070	50-322 E
SMITH, J L	8305160095	50-322 A
SMITH, J L	8305240447	50-322 A
SMITH, J L	8305270013	50-322 E
SMITH, J L	8305310050	50-322 A
SMITH, M	8305170242	40-8064
SMITH, N A	8305120250*	50-281 P
SMITH, P	8305230293*	CONTRACT
SMITH, P A	8305040280	CONTRACT
SMITH, P A	8305040284*	CONTRACT
SMITH, P. A	8305040341	CONTRACT
SMITH, P A	8305050389*	CONTRACT
SMITH, P. A	8305060235	50-206 P
SMITH, P A	8305060239*	50-206 P
SMITH, P A	8305170661*	CONTRACT
SMITH, P A	8305180421*	CONTRACT
SMITH, P. A	8305200071*	CONTRACT
SMITH, P A	8305230031*	CONTRACT
SMITH, P. A	8305260380*	CONTRACT
SMITH, R	8305050151*	50-293 G
SMITH, R D	8305060363	40-8783
SMITH, R D	8305130322	40-8752
SMITH, R D	8305130330	40-8783
SMITH, R D	8305160251	40-8693
SMITH, R D	8305160253	40-8745
SMITH, R D	8305160256	40-8675
SMITH, R D	8305240596	40-8663
SMITH, R. H	8305120260*	40-672
SMITH, R H	8305120284*	40-672
SMITH, R. H	8305120289*	40-672
SMITH, R H	8305120294*	40-672
SMITH, S H	8305230283	50-261 P
SMITH, W G	8303280126	50-315 S
SMITH, W G	8305020072	50-316 S
SMITH, W G	8305020141	50-315 S
SMITH, W G	8305020161	50-316 S
SMITH, W G	8305020192	50-316 S
SMITH, W G	8305020299	50-315 S
SMITH, W G	8305020317	50-315 S
SMITH, W G	8305020440	50-315 S
SMITH, W G	8305060400	50-315 S
SMITH, W G	8305120318	50-316 S
SMITH, W G	8305120396	50-315 S
SMITH, W G	8305130097	50-315 S
SMITH, W G	8305130166	50-316 S
SMITH, W G	8305130178	50-315 S
SMITH, W G	8305130206	50-315 S
SMITH, W G	8305170441	50-315 S
SMITH, W G	8305170446	50-316 S
SMITH, W G	8305240145	50-316 S
SMITH, W G	8305240329	50-315 S
SMITH, W G	8305240330	50-315 S
SMITH, W G	8305240345	50-315 S
SMITH, W G	8305240362	50-315 S
SMITH, W G	8305270087	50-315 S
SMITH, W G	8305270107	50-315 S
SMITH, W G	8305270223	50-316 S
SMITH, W G	8305270444	50-315 S
SMITH, W G	8305310179	50-316 S
SMYTH, C W	8305190247*	50-289 R
SNELL, W G	8305310181*	50-331 G
SNOW, B A	8305230526	50-244 S
SNYDER, B J	8305180238	50-320 P
SNYDER, B J	8305180245*	50-320 P
SNYDER, B J	8305180253*	50-320 P
SNYDER, H L	8305060389	40-8584
SOBON, L J	8305060171*	FOIA
SODERSTROM, J	8305270048*	50-320 P
SOLLENBERGER, D	8305170399	40-299
SOLLENBERGER, D	8305250397	40-299
SOLNIT, A J	8305030646*	50-247 G
SOLNIT, A J	8305030646*	50-247 G
SOLTIS, K S	8305190209	50-440 G
SONDAG, T J	8305180436	PR
SOO, P	8305020547	NUREG
SOO, P	8305110127	NUREG
SOO, P	8305170101	NUREG
SORENSEN, J	8305270048*	50-320 P
SOUDER, J L	8305020563	50-146 H
SOUTHARD, R B	8305230031*	CONTRACT
SPECTOR, S M	8305230458*	50-244 S
SPENCE, G P	8305060091*	50-285 I
SPENCER, D	8305020236*	50-373 S
SPENCER, D	8305020251*	50-373 S
SPENCER, D A	8305240318	50-373 S
SPENCER, D A	8305240425	50-373 S
SPESSARD, R L	8305020350	50-483 G
SPESSARD, R L	8305020354*	50-483 G
SPESSARD, R L	8305030258	50-483 G
SPESSARD, R L	8305060284	50-483 G
SPESSARD, R L	8305060542	50-373 G
SPESSARD, R L	8305060547	50-456 G
SPESSARD, R L	8305100388	50-341 G
SPESSARD, R L	8305120419	50-546 G
SPESSARD, R L	8305120423*	50-546 G
SPESSARD, R L	8305120438	50-373 G
SPESSARD, R L	8305120443*	50-373 G
SPESSARD, R L	8305130129	50-454 G
SPESSARD, R L	8305130139	50-373 G
SPESSARD, R L	8305170130	50-483 G
SPESSARD, R L	8305170182	50-483 G
SPESSARD, R L	8305170222	50-483 G
SPESSARD, R L	8305170241	50-266 G
SPESSARD, R L	8305170294	50-341 G
SPESSARD, R L	8305170298*	50-341 G
SPESSARD, R L	8305170322	50-374 G
SPESSARD, R L	8305190289*	50-373 G
SPESSARD, R L	8305200330	50-346 G
SPESSARD, R L	8305200407	50-255 S
SPESSARD, R L.	8305200421	50-237 G
SPESSARD, R L	8305200508	50-454 G
SPESSARD, R L	8305200509	50-346 G
SPESSARD, R L	8305200586	50-454 G
SPESSARD, R L	8305240125*	50-373 G
SPESSARD, R L	8305260259	50-155 G
SPESSARD, R L	8305270191	50-456 G
SPESSARD, R L	8305270476	50-454 G
SPIELES, P. R	8305250171	40-8697
SPIELES, P R	8305260364	40-8380
SPITZBERG, D B	8305020476	40-8452
SPRAGUE, R L	8305030474*	50-483 G
SRENIAWSKI, D	8305020271	I&E
STACHNIAK, R	8305170163*	50-237 B
STAMBAUGH, P	8305110236*	CONTRACT
STANFILL, G W	8305250341*	50-483 G
STANFILL, G W	8305250341*	50-483 G
STANFILL, G W	8305250356*	50-483 G
STANFILL, G W	8305250356*	50-483 G
STANGE, S J	8305030695*	50-289 F
STANGE, S J	8305050307*	50-289 F
STANGE, S J	8305050381*	50-320 F
STANGBERRY, W W	8305270446*	50-395 G
STAPLETON, B W	8305100371*	50-156 G
STAPLETON, B W	8305130234*	70-1308
STARK, R M	8305110590	50-537 A
STARKEY, R B	8305030599	50-261 S
STARKEY, R B	8305050249	50-261 S
STARKEY, R B	8305110251	50-261 S
STARKEY, R B	8305250423	50-261 S
STARKEY, R B	8305270487*	50-261 G
STAROSTECKI, R	8305020226	50-289 G
STAROSTECKI, R	8305020322	50-57 G
STAROSTECKI, R	8305020343	50-277 G
STAROSTECKI, R	8305030139	50-277 G
STAROSTECKI, R	8305030151	50-320 G
STAROSTECKI, R	8305030198	50-317 G
STAROSTECKI, R	8305030350	50-309 G
STAROSTECKI, R	8305050116	50-443 G
STAROSTECKI, R	8305050172	50-334 G
STAROSTECKI, R	8305050223	50-97 G
STAROSTECKI, R	8305100405	50-286 G
STAROSTECKI, R	8305100427	50-247 G
STAROSTECKI, R	8305110369	50-333 G
STAROSTECKI, R	8305110388	50-225 G
STAROSTECKI, R	8305110501	50-333 G
STAROSTECKI, R	8305120301	50-322 G
STAROSTECKI, R	8305160083	50-354 G
STAROSTECKI, R	8305160137	50-293 G
STAROSTECKI, R	8305160194	50-289 G
STAROSTECKI, R	8305170487	50-354 G
STAROSTECKI, R	8305170495	50-54 G
STAROSTECKI, R	8305190017	50-29 G
STAROSTECKI, R	8305190031	50-322 G
STAROSTECKI, R	8305190260	50-219 G
STAROSTECKI, R	8305190331	50-410 G
STAROSTECKI, R	8305200386	50-220 G
STAROSTECKI, R	8305230429	50-293 G
STAROSTECKI, R	8305230529	50-410 G
STAROSTECKI, R	8305250226	50-286 G
STAROSTECKI, R	8305250307	50-213 G
STAROSTECKI, R	8305250427	50-29 G
STAROSTECKI, R	8305250437	50-245 G
STAROSTECKI, R	8305250438	50-244 G
STAROSTECKI, R	8305250447	50-271 G
STAROSTECKI, R	8305250454	50-184 G
STAROSTECKI, R	8305250459	50-336 G
STAROSTECKI, R	8305250497	50-213 G
STAROSTECKI, R	8305250563	70-371
STAROSTECKI, R	8305270043	50-272 G
STAROSTECKI, R	8305270204	50-184 G
STAROSTECKI, R	8305270571	50-244 G
STAROSTECKI, R	8305270638	50-410 G
STAROSTECKI, R	8305270656	50-412 G
STASEK, S.	8305020480*	50-10 G
STEFANO, J J	8305120130	50-440 G
STEFANO, J J	8305120460	50-397 E
STEFANO, J J	8305120470*	50-397 E
STEFANO, J J	8305120477*	50-397 E
STEFANO, J J	8305120485*	50-397 E
STEFANO, J J	8305120491*	50-397 E
STEFANO, J J.	8305250189	50-440 A
STELLO, V	8005140296*	50-498 A
STELLO, V.	8005280930*	50-498 G
STELLO, V.	8006090238*	50-498 G
STELLO, V.	8006090440*	50-498 G
STELLO, V.	8008120773*	50-498 A
STELLO, V.	8010280578*	50-324 P
STELLO, V	8305040630	50-272 S
STELLO, V	8305110415	REVIEW GRP
STELLO, V	8305110485*	REVIEW GRP
STELLO, V	8305120602*	40-672
STELLO, V	8305120609*	40-672

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
STELLO, V	8305170275	REVIEW GRP
STELLO, V	8305170715	REVIEW GRP
STELLO, V	8305180064*	50-498 G
STELLO, V	8305180157*	50-498 G
STELLO, V	8305180184*	FOIA
STELLO, V	8305180202*	50-498 G
STELLO, V	8305180211*	50-498 G
STELLO, V	8305180250*	50-498 A
STELLO, V	8305180257*	50-498 T
STELLO, V	8305180326*	50-498 A
STELLO, V	8305190010	REVIEW GRP
STELLO, V	8305200619	REVIEW GRP
STELLO, V	8305230503	REVIEW GRP
STELLO, V	8305230507	REVIEW GRP
STELLO, V	8305230669	REVIEW GRP
STELLO, V	8305260375	ORG
STELLO, V	8305260378	MISC
STEMPLE, P J	8305200149*	CONTRACT
STEPHENSON, C J	8305110342*	50-289 S
STEPTOE, P	8305100341	50-329 G
STEPTOE, P	8305100341	50-329 G
STEPTOE, P P	8305270547	50-329 G
STEPTOE, P P	8305270547	50-329 G
STERN, P	8305030565	50-309 G
STERN, P	8305030567*	50-309 G
STERN, P.	8305180460	PR
STERN, P	8305240386	50-309 G
STERNBERG, D M.	8305160218*	50-312 G
STERNBERG, D M	8305170346	50-397 G
STERNBERG, D M	8305170375	50-397 G
STERNBERG, D M	8305170377	50-528 G
STERNBERG, D M	8305170384	50-508 G
STERNBERG, D M	8305170421*	50-361 G
STERNBERG, D M	8305170429	50-89 G
STERNBERG, D M	8305170436	50-397 G
STERNBERG, D M	8305170494	50-508 G
STERNBERG, D M	8305170560	50-528 G
STERNBERG, D M	8305170564*	50-528 G
STERNBERG, D M	8305260252	50-397 G
STERNBERG, D M	8305260319	50-528 G
STETKA, T F	8305270525*	50-302 G
STEWART, J. M	8305200440*	50-369 P
STEWART, S D	8305230245	CONTRACT
STEWART, S D	8305230256	CONTRACT
STEWART, W L	8305040173	50-338 P
STEWART, W L	8305040409	50-338 P
STEWART, W L.	8305050126	50-280 F
STEWART, W L	8305060061	50-281 G
STEWART, W. L	8305060100	50-281 F
STEWART, W L	8305060283	50-339 P
STEWART, W L	8305060556	50-280 P
STEWART, W L	8305090139	50-280 G
STEWART, W L	8305100108	50-280 P
STEWART, W. L	8305100315	50-280 G
STEWART, W. L	8305120047	50-339 G
STEWART, W L	8305120244	50-281 P
STEWART, W L	8305120386	50-339 P
STEWART, W. L	8305130058	50-280 F
STEWART, W. L	8305180372	50-280 P
STEWART, W L	8305190253	50-339 P
STEWART, W L	8305200163	50-280 P
STEWART, W. L	8305200499	50-280 P
STEWART, W. L	8305260232	50-280 P
STEWART, W L.	8305260323	50-338 P
STEWART, W L	8305270143	50-338 G
STEWART, W L	8305270150	50-339 P
STEWART, W. L	8305270220	50-338 P
STEWART, W L.	8305270248*	50-280 G
STEWART, W. L	8305270407*	50-338 G
STEWART, W L	8305270416*	50-338 G
STEWART, W. L	8305270426*	50-338 G
STEWART, W L	8305310099	50-339 P
STIEDE, W L	8305130135*	50-454 G
STILES, H	8305200426*	50-260 S
STILES, H. A	8305100113*	50-296 S
STILL, N.	8305090626	WASTE MGT
STILLER, M. A	8305250408*	50-483 G
STILLWELL, W G	8305110528	NUREG
STINSON, R C	8305250529	PR
STOETZEL, G A	8305030317	50-331 G
STOHR, J P.	8305030368	70-27
STOHR, J P.	8305200310	70-143
STOHR, J P	8305270113	70-1113
STOHR, J P.	8305270142	70-1151
STOHR, J P.	8305270155	70-143
STOHR, J P	8305270156	70-1113
STOHR, J P	8305270161	70-143
STOHR, J P	8305270174	70-1201
STOHR, J P	8305270288	50-332 G
STOHR, J P	8305270450	70-1151
STOHR, J P	8305270467*	70-1151
STOHR, J P	8305270548	70-27
STOHR, J P	8305270600	70-143
STOHR, J P	8305270640	70-143
STOHR, J P	8305310016	70-1201
STOHR, J P	8305310109	70-1113
STOHR, J P	8305310120	70-1151
STOHR, J P	8305310132	70-1113
STOLZ, J F	8303280319	50-302 P
STOLZ, J F	8304120027	50-321 P
STOLZ, J F	8305020592	50-312 P
STOLZ, J F	8305030389	50-346 F
STOLZ, J F	8305040769	50-321 P
STOLZ, J F	8305060671	50-321 P
STOLZ, J F	8305090111*	50-269 P
STOLZ, J F	8305090138*	50-269 P
STOLZ, J F	8305090147	50-313 P
STOLZ, J F	8305090154*	50-313 P
STOLZ, J F	8305090179*	50-313 P
STOLZ, J F	8305090584	50-302 G
STOLZ, J F	8305090589*	50-302 G
STOLZ, J F	8305090608	50-269 P
STOLZ, J F	8305110625	50-313 P
STOLZ, J F	8305120037	50-302 P
STOLZ, J F	8305120504	50-313 P
STOLZ, J F	8305120506*	50-313 P
STOLZ, J F.	8305130294	50-269 P
STOLZ, J F.	8305170622	50-313 P
STOLZ, J F.	8305170673*	50-346 P
STOLZ, J F	8305170677	50-313 F
STOLZ, J F	8305170682*	50-346 P
STOLZ, J F.	8305180008*	50-278 P
STOLZ, J F.	8305180014*	50-278 P
STOLZ, J F	8305180045*	50-269 P
STOLZ, J F	8305180068*	50-269 P
STOLZ, J F	8305180099	50-289 P
STOLZ, J F	8305180102	50-344 P
STOLZ, J F	8305180104*	50-289 P
STOLZ, J F.	8305180114*	50-346 P
STOLZ, J F.	8305180128*	50-289 P
STOLZ, J F	8305180151	50-269 P
STOLZ, J F	8305180161	50-313 F
STOLZ, J F	8305180187*	50-346 P
STOLZ, J. F	8305180694	50-313 P
STOLZ, J F	8305180849	50-313 P
STOLZ, J F	8305200100	50-277 G
STOLZ, J F	8305200103	50-269 P
STOLZ, J F	8305200238*	50-277 G
STOLZ, J F	8305230014	50-313 G
STOLZ, J F.	8305230128	50-313 P
STOLZ, J F.	8305310083	50-269 P
STONE, J	8208060249*	50-338 P
STORR, J F.	8305230603*	50-410 A
STOTZ, J.	8305130195*	50-346 S
STOTZ, J	8305310038	50-346 S
STRAKA, M	8305030375	50-123 R
STRATOULY, D C	8305030282*	50-275 R
STRATOULY, D C	8305030545*	50-275 R
STRATOULY, D C	8305170517*	50-275 R
STRATTON, W R	8305230469*	COMMISSION
STRAUSS, R. J	8305030416	PR
STREETER, J F	8305020352*	50-305 G
STREETER, J F	8305020467	50-10 G
STREETER, J F	8305100364	50-331 G
STREETER, J. F	8305170148	50-546 G
STREETER, J F	8305170303	50-346 G
STREETER, J F	8305170308*	50-346 G
STREETER, J F	8305170398	50-373 G
STREETER, J F	8305170400*	50-373 G
STREETER, J F	8305190251	50-331 G
STREETER, J F.	8305260221	50-440 G
STREETER, J F	8305260244	50-461 G
STREETER, J F	8305260256	50-409 G
STREETER, J F	8305260329	50-373 G
STREETER, J F	8305260331*	50-373 G
STREUTKER, S R	8305040105*	71-9181
STREUTKER, S R	8305060142*	71-9175
STREUTKER, S R	8305060148*	71-9175
STRICKLER, L	8305180111*	FOIA
STRICKLER, L J	8305180021*	FOIA
STRICKLER, L J	8305180031*	FOIA
STRICKLER, L J	8305180037*	FOIA
STRICKLER, L J	8305180092*	FOIA
STRICKLER, L J	8305180166*	FOIA
STRICKLER, L J	8305180174*	FOIA
STRICKLER, L J	8305180207*	FOIA
STRICKLER, L J	8305180223*	FOIA
STRICKLER, L J	8305180247*	FOIA
STRINGHAM, S D	8304130034	71-494
STRINGHAM, S D	8304130042*	71-494
STRUMWASSER, M	8305110212	50-275 G
STRUMWASSER, M	8305110217	50-275 G
STRUMWASSER, M	8305110383	50-275 G
STUART, D L	8305250327	50-443 G
STUCKY, S W	8305200638	50-155 G
STURKEY, J J	8303240487*	50-313 P
STURKEY, J J	8303240495*	50-313 P
SUERMANN, J F	8305230499	50-269 P
SUGARMAN, R J	8305310013	50-352 G
SUGARMAN, R J	8305310013	50-352 G
SULLIVAN, M F	8305090561*	50-358 A
SUMMERFIELD, T	8305200665*	50-373 P
SUMMERS, R	8305190336	50-272 S
SUMNER, H L	8305170445*	50-321 S
SUMNER, H L	8305170499*	50-366 S
SUNDIN, R E	8305250195	40-8102
SUTHERLAND, W A	8305050426	NUREG
SUTPHIN, R N	8305170315*	50-346 G
SUTPHIN, R N	8305190256*	50-331 G
SUTPHIN, R N	8305260258*	50-409 G
SUTTON, J W	8305050071*	GA999
SUTTON, J W	8305050149*	GA999
SUTTON, J W	8305090403*	GA999
SUWAL, G M	8305120250*	50-281 P
SWAN, W	8305270303*	50-390 G
SWANSON, E	8305020348*	50-315 G
SWANSON, E R	8305240309*	50-315 G
SWARTZ, E D	8305030270	50-454 S
SWARTZ, E D	8305060559*	50-456 G
SWARTZ, E D	8305100237	50-454 A
SWARTZ, E D	8305130001	50-456 A
SWARTZ, E D	8305130051	50-454 A
SWARTZ, E D	8305180385	50-454 A
SWARTZ, E D	8305260287	50-456 A
SWARTZ, E D	8305270079	50-456 F
SWARTZWELDER, R	8305310061*	50-320 S
SWARTZWELDER, R	8305310078*	50-320 S
SWARTZWELDER, R	8305310080*	50-320 S
SWETLAND, P	8305250314*	50-309 G
SWEZEY, M	8305240517	50-247 H
SWIGER, M A	8305240515	50-440 G
SWIGER, M A	8305240515	50-440 G
SYLVIA, B R	8305190273*	50-358 G
SZCZECH, R A	8305030112*	50-289 S
SZCZECH, R A	8305030127*	50-289 S
SZCZECH, R A	8305110287*	50-289 S
SZCZECH, R A	8305110351*	50-289 S
SZCZECH, R A	8305200551*	50-289 S
SZUKIEWICZ, A J	8305090646*	50-445 G
TAM, P S	8305040621	50-334 P
TANGHEE, D.	8305240202	50-237 S
TANSEY, W J	8305030480	PR
TAPIA, J I	8305090578*	50-445 G
TAPIA, J I	8305100009*	50-192 G
TAPIA, J I	8305230449*	50-445 G
TARAS, D.	8104060899*	FOIA
TARAS, D N	8006180578*	FOIA
TARAS, D N	8305020204*	FOIA
TARAS, D. N	8305020545*	FOIA
TARAS, D. N	8305030225*	70-378
TARAS, D. N	8305030233*	70-378
TARAS, D. N	8305030251*	70-378
TARAS, D. N	8305040089*	FOIA
TARAS, D N	8305040103*	FOIA
TARAS, D N	8305040127*	FOIA
TARAS, D. N	8305040387*	FOIA
TARAS, D N	8305040450*	FOIA
TARAS, D N.	8305040489*	FOIA
TARAS, D N	8305040502*	FOIA
TARAS, D N.	8305050346*	FOIA
TARAS, D N	8305050349*	FOIA
TAUBER, H	8305020370	50-341 A
TAUBER, H	8305100119	50-341 A
TAUBER, H	8305170662	70-2926
TAUBER, H	8305230552	50-341 A

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
TAYLOR, H S	8305090467	TOPREP	
TAYLOR, H S	8305090469*	TOPREP	
TAYLOR, J H	8305100316	TOPREP	
TAYLOR, J H	8305120019	TOPREP	
TAYLOR, J H	8305260311*	50-330	S
TAYLOR, J H	8305260313*	50-330	S
TAYLOR, J M	8212060385	50-3	Q
TAYLOR, J M	8305160082*	50-309	S
TAYLOR, J W	8305130267*	50-409	Q
TAYLOR, M	8305170718	REVIEW GRP	
TAYLOR, P A	8305270245*	50-389	Q
TAYLOR, P A	8305270453*	50-389	Q
TAYLOR, R	8305240229	50-373	S
TAYLOR, R G	8305090578*	50-445	Q
TAYLOR, R G	8305090650*	50-445	Q
TEDFORD, C F	8305030598	PR	
TENNYSON, V H	8305120099*	50-275	P
TERAO, D	8305090654*	50-445	Q
THIEB, A C	8305090435	50-287	P
THINNES, G L	8305110467	NUREG	
THOMAS	8305190072	50-219	S
THOMAS, C O	8304270179	PR	
THOMAS, C O	8305050379	50-447	E
THOMAS, C O	8305060358	TOPREP	
THOMAS, C O	8305060562	50-447	E
THOMAS, C O	8305090217	TOPREP	
THOMAS, C O	8305090554	TOPREP	
THOMAS, C O	8305090597	TOPREP	
THOMAS, C O	8305120029	TOPREP	
THOMAS, C O	8305120057	50-70	P
THOMAS, C. O	8305120067*	50-70	P
THOMAS, C O	8305120089	50-73	P
THOMAS, C O	8305120094*	50-73	P
THOMAS, C O	8305180017	50-470	E
THOMAS, C O	8305180060	50-447	A
THOMAS, C O	8305260151	MISC	
THOMAS, J	8305190266*	50-219	Q
THOMAS, M	8305270151*	50-369	Q
THOMAS, M	8305270562*	50-390	Q
THOMAS, R D	8305100416*	50-237	G
THOMAS, R D	830516007B*	70-754	
THOMAS, R D	8305260273*	40-8137	
THOMAS, S	8305200398	50-440	Q
THOMAS, W V	8305100011	50-346	F
THOMAS, W V	8305110457	NUREG	
THOMASON, P V	8305060574	50-298	S
THOMASON, P V	8305120433	50-298	S
THOMPSON, D	7908080036*	50-498	G
THOMPSON, D.	8112290557*	70-925	
THOMPSON, D	8305120620*	40-672	
THOMPSON, D	8305170047*	50-142	Q
THOMPSON, D	8305180337*	50-498	A
THOMPSON, D	8305200398	50-440	Q
THOMPSON, H L	8305030587*	50-312	P
THOMPSON, P	8305120246*	40-672	
THOMPSON, S L	8305310209	NUREG	
THOMSEN, F T	8305310029	50-522	Q
THOMSEN, F T	8305310029	50-522	Q
THOMSEN, F T	8305310082	50-522	Q
THOMSEN, F T	8305310082	50-522	Q
THONUS, L	8305030164*	50-320	Q
THONUS, L	8305160199*	50-289	Q
THORGERSEN, J G	8305100397*	50-305	S
THORGERSEN, J G	8305270198	50-305	S
THORNBURG, H D	8009120352*	50-498	G
THORNBURG, H D	8010090450*	50-498	A
THORNBURG, H D	8305180276*	50-498	G
THORSEN, E O	8305270586	50-247	G
THULL, T. S	8305060512*	50-245	S
THULL, T S	8305230557*	50-245	S
THURMOND, S.	8305230406*	COMMISSION	
TIEDKE, J H.	8305180347	PR	
TIERMAN, J A	8305060396	50-317	P
TIERNAN, J A	8305060438	PR	
TIERNAN, J A	8305180358	PR	
TIERNAN, J. A	8305240269*	50-317	P
TIERNEY, J. E	8305180460	PR	
TIETZ, G	8305310142	50-254	S
TILLEY, R	8305020061	71-6717	
TILLEY, R	8305040671	71-495	
TILLEY, R	8305040679*	71-495	
TILLMAN, A	8305030371*	70-27	
TILLMAN, A.	8305200565*	50-369	Q
TIMO, P P.	8305040433	TOPREP	
TIPPS, S B	8305050040*	50-321	S
TIPPS, S B	8305050087*	50-321	S
TIPPS, S B	8305110272*	50-321	S
TIPPS, S B	8305110273*	50-321	S
TIPPS, S B	8305110293*	50-321	S
TIPPS, S B	8305110389*	50-366	S
TIPPS, S. B.	8305110412*	50-321	S
TIPPS, S B.	8305110417*	50-366	S
TIPPS, S B	8305110434*	50-321	S
TIPPS, S B	8305110436*	50-366	S
TIPPS, S B	8305130242*	50-366	S
TIPPS, S B	8305170262*	50-321	S
TIPPS, S B.	8305170284*	50-366	S
TIPPS, S B.	8305170394*	50-366	S
TIPPS, S B	8305170438*	50-321	S
TIPPS, S B	8305170506*	50-366	S
TIPPS, S B	8305230468*	50-366	S
TIPPS, S B	8305230490*	50-366	S
TIPPS, S B	8305230498*	50-366	S
TIPPS, S B	8305230577*	50-321	S
TIPPS, S B	8305270123	50-366	S
TIPPS, S B	8305270234	50-321	S
TIPPS, S B	8305310124	50-366	S
TIPPS, S B.	8305310166	50-321	S
TIPPS, S B.	8305310180	50-321	S
TIPPS, S B.	8305310206	50-366	S
TOBIN, W J.	8305090461*	50-395	Q
TOBIN, W J.	8305100109*	50-324	Q
TODD, J T.	8305120430*	50-387	S
TODD, J T.	8305200561*	50-387	S
TODOROVICH, M H	8305240453	50-247	H
TOMAN, G J	8305170106*	50-272	S
TOMPKINS, B. A	8305020394	50-483	Q
TOMPKINS, B A.	8305020405	50-352	Q
TONER, K A	8305020202	50-155	P
TONER, K A	8305160090	50-255	P
TONER, K. A	8305190196	50-155	P
TONQUE, T. M	8305020480*	50-10	Q
TORRONEN, K	8305240015	NUREG	
TOSCANI, K	8305200645	50-247	Q
TOTH, A. D.	8305170381*	50-397	Q
TOTH, A D.	8305170439*	50-397	Q
TOURIGNY, E G.	8305110165	50-368	P
TOURTELLOTTE, J	8305230720	50-313	P
TOWNBEND, B	8305110005	CONTRACT	
TOWNBEND, B	8305110146	CONTRACT	
TOWNSEND, B	8305120555	CONTRACT	
TRAMM, T. R	8305040074*	50-454	F
TRAMM, T. R	8305160059	50-454	E
TRAMMELL, C M	8305110176*	50-368	P
TRAMMELL, C M	8305110230*	50-336	P
TRAMMELL, C M	8305120171*	50-335	P
TRAMMELL, C M	8305120505*	50-266	P
TRAMMELL, C. M	8305120512*	50-313	P
TRAMMELL, C M	8305130023*	50-338	P
TRAMMELL, C M	8305170273*	50-317	P
TRAMMELL, C M	8305180049*	50-368	P
TRAMMELL, C M	8305180614*	50-317	P
TRAMMELL, C. M	8305200089*	50-336	P
TRAMMELL, C M	8305200724*	50-338	P
TRAUTMAN, D J	8305130201*	50-346	S
TRAVIS, C. C	8305250155	RES	
TRAVIS, W. H.	8305260003	71-5552	
TREBY, S A	8305040531	50-445	Q
TREBY, S. A	8305090568	50-445	Q
TRENERY, S E	8305040740	NUREG	
TREXLER, R C	8304280121	PR	
TRIMBLE, D C	8305030208*	50-317	Q
TRIPP, L.	8305100258	50-272	S
TRIPP, L.	8305190336	50-272	S
TRIPP, L E	8305040184	50-219	Q
TRIPP, L. E.	8305050180*	50-334	Q
TRIPP, L. E	8305060057	50-352	Q
TRIPP, L. E	8305160091*	50-354	Q
TROBKOSKI, W. M	8305050180*	50-334	Q
TROWBRIDGE, G F	8305090431	50-289	Q
TROWBRIDGE, G F	8305090431	50-289	Q
TROWBRIDGE, G F.	8305090470	50-261	Q
TROWBRIDGE, G F	8305090470	50-261	Q
TROWBRIDGE, G F	8305120292	50-289	Q
TROWBRIDGE, G F.	8305120292	50-289	Q
TROWBRIDGE, G F	8305130092	50-261	Q
TROWBRIDGE, G F.	8305130092	50-261	Q
TROWBRIDGE, G F	8305130162	50-261	Q
TROWBRIDGE, G F	8305130162	50-261	Q
TROWBRIDGE, G F	8305160012	50-289	Q
TROWBRIDGE, G F	8305240487	50-289	Q
TUCKER, H B	8305020020	50-413	E
TUCKER, H. B	8305020372	50-269	P
TUCKER, H. B	8305040229	50-369	S
TUCKER, H B	8305040273	50-369	S
TUCKER, H. B.	8305040469	50-370	P
TUCKER, H B	8305040564	50-269	P
TUCKER, H B	8305040597*	50-369	F
TUCKER, H B	8305050135	50-369	F
TUCKER, H B	8305050153	50-370	S
TUCKER, H B	8305050254	50-269	S
TUCKER, H B	8305050283	50-369	P
TUCKER, H. B	8305060224	50-369	P
TUCKER, H B	8305060403	50-369	S
TUCKER, H B	8305060413	50-369	P
TUCKER, H B	8305090472	50-369	S
TUCKER, H B	8305100002	50-369	S
TUCKER, H B	8305100007	50-369	P
TUCKER, H B	8305100148	50-369	Q
TUCKER, H B.	8305100327	50-369	S
TUCKER, H B	8305100347	50-369	P
TUCKER, H B.	8305100366	50-369	S
TUCKER, H B	8305100383	50-369	P
TUCKER, H B	8305110085	50-369	S
TUCKER, H B.	8305110281	50-369	S
TUCKER, H B	8305110323	50-270	S
TUCKER, H. B	8305130025	50-269	P
TUCKER, H B	8305130159	50-369	S
TUCKER, H B	8305130192	50-369	F
TUCKER, H B	8305160285*	50-369	F
TUCKER, H B	8305160293*	50-413	F
TUCKER, H B	8305170258	50-370	S
TUCKER, H B	8305170277	50-369	P
TUCKER, H B	8305170292	50-413	S
TUCKER, H. B.	8305170296	50-413	F
TUCKER, H B	8305170324	50-269	S
TUCKER, H. B	8305170355	50-369	S
TUCKER, H B	8305170455	50-269	R
TUCKER, H B	8305170507	50-369	S
TUCKER, H B.	8305170536	50-369	R
TUCKER, H. B.	8305170561	50-269	S
TUCKER, H. B	8305190020	50-370	F
TUCKER, H B	8305190032	50-370	E
TUCKER, H. B	8305200401	50-413	E
TUCKER, H B	8305200438	50-369	P
TUCKER, H B	8305200476	50-413	E
TUCKER, H B	8305200544	50-269	Q
TUCKER, H B	8305250278	50-369	F
TUCKER, H B.	8305250281	50-369	P
TUCKER, H B	8305250282	50-413	S
TUCKER, H B	8305250287	50-369	P
TUCKER, H B	8305250290	50-370	P
TUCKER, H B.	8305250404	50-369	S
TUCKER, H. B.	8305250439	50-370	S
TUCKER, H B	8305250442	50-369	P
TUCKER, H. B	8305250449	50-414	S
TUCKER, H B	8305250479	50-269	P
TUCKER, H. B	8305250499	50-370	S
TUCKER, H. B	8305250507	50-370	S
TUCKER, H B	8305250525	50-370	S
TUCKER, H B	8305250549	50-369	S
TUCKER, H B.	8305250556	50-269	S
TUCKER, H B	8305270005	50-413	A
TUCKER, H B	8305270069	50-413	S
TUCKER, H. B.	8305270259	50-269	P
TUCKER, H B	8305270366*	50-369	Q
TUCKER, H B.	8305310052	50-369	S
TUCKER, H. B	8305310081	50-269	Q
TUCKER, H. B.	8305310200	50-413	E
TUETKEN, R. P	8305160060	50-454	Q
TUFFIN, W.	8305120369*	40-672	
TUFFIN, W B	8305120352*	40-672	
TUFFIN, W. B.	8305120480*	40-672	
TUFFIN, W B.	8305120494*	40-672	
TUFFIN, W. B.	8305120511*	40-672	
TUFFIN, W B	8305120617*	FOIA	
TUITE, P. T.	8305110158	WASTE MGT	
TULODIESKI, D	8305310203*	50-329	R
TURCOTTE, R. L	8305310012	50-131	P
TURK, S. E.	8305060317	50-537	Q
TURK, S E	8305100022	50-537	Q
TURK, S E	8305110450	50-537	Q
TURK, S. E.	8305110455*	50-537	Q
TURK, S E.	8305130063	50-537	Q
TURK, S. E.	8305160128	50-537	Q

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
TURK, B E	8305200642	50-382 Q
TURK, B E	8305240070	50-537 Q
TURNER, D	8305170588*	50-454 Q
TURNER, D	8305170588*	50-454 Q
TURNER, D	8305170588*	50-454 Q
TURNQUEST, L	8305310182	50-237 S
TWISDALE, L A	8305310157*	50-244 P
TYMPANICK, L	8305020268*	GA999
UDALL, M	8305240275*	50-358 Q
UDALL, M K	8305040145*	50-289 U
UDALL, M K	8305230369*	COMMISSION
UDALL, M K	8305240272*	50-358 Q
UDERITZ, R A	8305020150	50-272 S
UDERITZ, R, A	8305020186	50-272 P
UDERITZ, R A	8305020267*	50-272 Q
UDERITZ, R A	8305040262	50-272 S
UDERITZ, R A	8305160085	50-272 Q
UDERITZ, R A	8305240291*	50-272 Q
UDERITZ, R A	8305270053*	50-272 Q
UHRIQ, R E	8305020084	50-335 Q
UHRIQ, R E	8305020168	50-335 P
UHRIQ, R, E,	8305020345	50-335 P
UHRIQ, R, E	8305020519	50-335 P
UHRIQ, R E	8305030168	50-251 R
UHRIQ, R, E	8305030306	50-389 S
UHRIQ, R E	8305030340	50-335 Q
UHRIQ, R, E,	8305030341	50-335 R
UHRIQ, R, E	8305030392	50-250 Q
UHRIQ, R, E	8305030461	PR
UHRIQ, R, E	8305030604	50-389 S
UHRIQ, R E	8305040563	50-335 F
UHRIQ, R, E	8305090432	50-250 P
UHRIQ, R E	8305090476	50-335 P
UHRIQ, R E	8305100001	50-250 Q
UHRIQ, R E	8305100088	50-389 S
UHRIQ, R, E	8305100103	50-335 P
UHRIQ, R E	8305100165	50-250 P
UHRIQ, R, E	8305100182	50-335 J
UHRIQ, R E	8305100227	50-389 S
UHRIQ, R E	8305100236	50-335 P
UHRIQ, R, E	8305130008	50-250 F
UHRIQ, R, E	8305130118	50-389 P
UHRIQ, R, E	8305130121	50-335 P
UHRIQ, R, E	8305160010	50-251 P
UHRIQ, R, E	8305170356	50-389 F
UHRIQ, R, E	8305170463	50-335 P
UHRIQ, R, E	8305170520	50-250 P
UHRIQ, R, E	8305170546	50-250 F
UHRIQ, R, E,	8305200181	50-389 S
UHRIQ, R, E	8305200346	50-335 F
UHRIQ, R E	8305200489	50-335 F
UHRIQ, R, E,	8305230532	50-335 P
UHRIQ, R E	8305240372	50-335 P
UHRIQ, R E	8305250272	50-335 P
UHRIQ, R, E	8305250395	50-335 P
UHRIQ, R, E,	8305250397	50-335 P
UHRIQ, R, E	8305250415	PR
UHRIQ, R, E,	8305250416	50-389 S
UHRIQ, R, E	8305250455	50-389 P
UHRIQ, R E	8305250462	50-335 P
UHRIQ, R, E,	8305250472	50-250 P
UHRIQ, R, E	8305250481	50-335 P
UHRIQ, R, E,	8305250519	50-250 P
UHRIQ, R, E,	8305270104	50-389 P
UHRIQ, R, E	8305270125	50-389 P
UHRIQ, R, E,	8305270129	50-250 Q
UHRIQ, R, E,	8305270153	50-389 P
UHRIQ, R, E,	8305270168	50-335 P
UHRIQ, R, E	8305270170	50-335 P
UHRIQ, R, E,	8305270251	50-389 P
UHRIQ, R E	8305270360*	50-389 Q
UHRIQ, R, E	8305270520*	50-389 Q
UHRIQ, R, E,	8305270572*	50-335 Q
UHRIQ, R E,	8305310034	50-250 P
UHRIQ, R E	8305310184	50-389 P
ULIE, J,	8305120447*	50-373 Q
UNKLE, T, J	8305110363*	50-317 S
UPRIGHT, C, M	8305270278*	50-537 Q
UPRIGHT, C, M	8305270319*	50-537 Q
UPRIGHT, C, M	8305270356*	50-321 Q
UPRIGHT, C M	8305270442*	50-338 Q
UPRIGHT, C, M	8305270594*	50-335 Q
URBANIK, T,	8305090586*	50-445 Q
URYC, B,	8305030371*	70-27
URYC, B,	8305200565*	50-369 Q
URYC, B	8305270212*	50-302 Q
UTLEY, E E	8305060620	50-324 Q
UTLEY, E E	8305270008	50-261 P
VACCA, P C	8305110026	NUREG
VACCA, P C	8305110029*	NUREG
VAKERICS, T V	8305180070*	FOIA
VAKERICS, T V	8305180074*	FOIA
VALDES, S A	8305170197*	50-389 S
VAN BRUNT, E E	8305020089	50-528 K
VAN BRUNT, E E	8305030285	50-528 S
VAN BRUNT, E E	8305030346	50-529 S
VAN BRUNT, E E	8305030626	50-528 S
VAN BRUNT, E E,	8305120385	50-528 E
VAN BRUNT, E E	8305130082	50-528 S
VAN BRUNT, E E	8305130107	50-528 S
VAN BRUNT, E E	8305130124	50-528 S
VAN BRUNT, E E	8305130127	50-528 S
VAN BRUNT, E E	8305130148	50-528 S
VAN BRUNT, E E	8305130159	50-528 S
VAN BRUNT, E E	8305130161	50-529 S
VAN BRUNT, E E	8305130168	50-528 S
VAN BRUNT, E E	8305130169	50-528 S
VAN BRUNT, E E	8305130183	50-528 S
VAN BRUNT, E E	8305130189	50-528 S
VAN BRUNT, E E	8305130210	50-528 S
VAN BRUNT, E E	8305130226	50-528 S
VAN BRUNT, E E	8305130229	50-528 S
VAN BRUNT, E E	8305130264	50-528 S
VAN BRUNT, E E	8305160071	50-528 A
VAN BRUNT, E E	8305160072*	50-528 A
VAN BRUNT, E E	8305200322	50-528 F
VAN BRUNT, E E	8305200417	50-528 A
VAN BRUNT, E E	8305230517	50-528 S
VAN BRUNT, E E	8305260321*	50-528 Q
VAN BRUNT, E E	8305260326*	50-528 Q
VAN BRUNT, E E	8305310161	50-528 A
VAN DE KAMP, J	8305120093*	50-275 P
VAN ECK, O, J	8305090162	NUREG
VAN KOVICS, J	8305180459*	50-322 H
VAN KOVICS, J	8305180461*	50-322 H
VAN VRANKEN, J	8305190151*	50-373 Q
VAN VRANKEN, J	8305190167*	50-373 Q
VANDEL, T, E	8305170153*	50-344 Q
VANDEWALLE, D J	8305060477	50-255 S
VANDEWALLE, D J	8305100250	50-255 S
VANDEWALLE, D J	8305100279	50-255 P
VANDEWALLE, D J	8305120147	50-255 F
VANDEWALLE, D J,	8305170300*	50-255 Q
VANDEWALLE, D J	8305170404	50-155 F
VANDEWALLE, D J	8305170410	50-155 P
VANDEWALLE, D J	8305240505	50-155 P
VANDEWALLE, D, J	8305260266*	50 155 Q
VANDOORN, P, K	8305270334*	50-413 Q
VANDOORN, P, K,	8305270602*	50-413 Q
VANO, J A	8305100273*	50-334 Q
VARELA, A	8305160199*	50-289 Q
VARGA, S A	8303300001	50-295 P
VARGA, S A	8303300002*	50-295 P
VARGA, S A	8303300003*	50-295 P
VARGA, S A	8304270053	50-295 P
VARGA, S A	8305020548	50-3 F
VARGA, S A	8305020575	50-3 F
VARGA, S A,	8305040090	50-305 P
VARGA, S, A	8305040117	50-305 Q
VARGA, S A	8305040125*	50-305 G
VARGA, S, A	8305040363*	50-315 P
VARGA, S A,	8305040382*	50-315 P
VARGA, S A	8305040512	50-334 P
VARGA, S A	8305040649	50-315 P
VARGA, S A	8305040667	50-305 P
VARGA, S A	8305040672	50-250 P
VARGA, S A,	8305050073	50-286 F
VARGA, S, A,	8305050280	50-286 G
VARGA, S, A	8305050293	50-250 P
VARGA, S A	8305060653	50-250 P
VARGA, S, A	8305060658	50-280 P
VARGA, S, A	8305090019*	50-348 F
VARGA, S, A	8305090029	50-280 Q
VARGA, S A	8305090032*	50-348 P
VARGA, S, A,	8305090037*	50-280 Q
VARGA, S, A,	8305090051*	50-280 P
VARGA, S, A	8305090070*	50-280 P
VARGA, S A	8305090085	50-250 Q
VARGA, S, A	8305090104*	50-250 Q
VARGA, S, A	8305090327*	50-280 P
VARGA, S A	8305090335*	50-280 P
VARGA, S A	8305110052*	50-305 P
VARGA, S A	8305110056*	50-305 P
VARGA, S A	8305110538	50-286 F
VARGA, S A	8305160349*	50-261 P
VARGA, S A	8305160356*	50-261 P
VARGA, S A	8305170019*	50-311 P
VARGA, S A	8305170028*	50-311 P
VARGA, S A	8305170048	50-261 F
VARGA, S A	8305170080*	50-315 P
VARGA, S A	8305170084*	50-272 P
VARGA, S A	8305170090*	50-272 P
VARGA, S A	8305170112*	50-315 P
VARGA, S A	8305170119*	50-272 P
VARGA, S A	8305170129*	50-272 P
VARGA, S A	8305170597	50-261 P
VARGA, S A	8305170637	50-286 P
VARGA, S, A	8305170644	50-247 P
VARGA, S, A	8305170654	50-261 Q
VARGA, S A	8305170659	50-364 P
VARGA, S, A	8305170711	50-315 P
VARGA, S A	8305180169	50-280 F
VARGA, S, A	8305180536	50-315 P
VARGA, S A	8305180568	50-250 F
VARGA, S A	8305180573	50-305 P
VARGA, S A	8305180586	50-261 P
VARGA, S A	8305180691	50-295 P
VARGA, S, A	8305180712	50-348 P
VARGA, S A	8305180731*	50-348 P
VARGA, S, A	8305180814	50-316 P
VARGA, S A	8305180838	50-315 P
VARGA, S A	8305180854	50-250 P
VARGA, S, A	8305200099	50-250 F
VARGA, S A	8305200171	50-247 Q
VARGA, S A	8305200195	50-334 F
VARGA, S A	8305230230	50-334 P
VARGA, S, A	8305240104	50-305 Q
VARGA, S, A	8305240246	50-295 F
VARGA, S, A	8305260207	50-250 P
VARGA, S, A	8305310221	50-272 P
VASBALLO, D B	8303300396*	50-260 P
VASBALLO, D B	8303300409*	50-260 P
VASBALLO, D B	8304210030	50-220 P
VASBALLO, D B	8305020056	50-293 P
VASBALLO, D B	8305020552	50-271 P
VASBALLO, D B	8305020569	50-220 F
VASBALLO, D B	8305020597	50-254 P
VASBALLO, D B	8305030066	50-333 P
VASBALLO, D B	8305030135	50-333 P
VASBALLO, D B	8305040075	50-331 P
VASBALLO, D B	8305040108*	50-331 P
VASBALLO, D, B	8305040115*	50-331 P
VASBALLO, D, B	8305060279*	50-293 P
VASBALLO, D B	8305060291*	50-293 P
VASBALLO, D B	8305060548	50-333 P
VASBALLO, D B	8305090186	50-331 P
VASBALLO, D B	8305110039*	50-331 P
VASBALLO, D B	8305110234*	50-331 P
VASBALLO, D, B	8305110243*	50-331 P
VASBALLO, D B	8305110556*	50-331 P
VASBALLO, D B	8305110566*	50-331 P
VASBALLO, D B	8305120169*	50-293 P
VASBALLO, D B,	8305120187*	50-293 P
VASBALLO, D, B	8305160340*	50-298 P
VASBALLO, D B	8305160342*	50-298 P
VASBALLO, D, B	8305170052*	50-220 P
VASBALLO, D, B	8305170060*	50-220 P
VASBALLO, D, B	8305170071*	50-271 P
VASBALLO, D B	8305170075*	50-271 P
VASBALLO, D B	8305170716	50-254
VASBALLO, D B	8305170719	50-331
VASBALLO, D, B	8305180026	50-298
VASBALLO, D, B	8305180039*	50-298
VASBALLO, D, B	8305180048*	50-324 P
VASBALLO, D, B	8305180061*	50-324 P
VASBALLO, D, B	8305180071*	50-298
VASBALLO, D B	8305180081	50-331
VASBALLO, D B	8305180091*	50-331
VASBALLO, D, B,	8305180204*	50-293
VASBALLO, D B	8305180547	50-298
VASBALLO, D B	8305180563	50-324
VASBALLO, D, B,	8305180572	50-333
VASBALLO, D B	8305180752	50-331
VASBALLO, D B	8305180771	50-260
VASBALLO, D B	8305180801	50-331

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
VASSALLO, D B	8305180845	50-259	P
VASSALLO, D B	8305190099	50-324	P
VASSALLO, D B	8305200246	50-333	P
VASSALLO, D B	8305200707	50-237	P
VASSALLO, D B	8305200708	50-271	F
VASSALLO, D B	8305230068	50-271	P
VASSALLO, D B	8305230115	50-271	P
VASSALLO, D B	8305230178	50-324	P
VASSALLO, D B	8305230242	50-298	P
VASSALLO, D B	8305230248	50-263	P
VASSALLO, D B	8305230253	50-271	Q
VASSALLO, D B	8305230279	50-271	P
VASSALLO, D B	8305230312	50-271	P
VASSALLO, D B	8305240557	50-263	P
VASSALLO, D B	8305240560	50-293	P
VASSALLO, D B	8305240562	50-263	P
VASSALLO, D B	8305240564	50-331	F
VASSALLO, D B	8305240571	50-293	F
VASSALLO, D B	8305240572	50-263	F
VASSALLO, D B	8305240573	50-254	P
VASSALLO, D B	8305240576	50-220	F
VASSALLO, D B	8305240591	50-271	F
VASSALLO, D B	8305250136	50-259	P
VASSALLO, D B	8305250137	50-333	F
VASSALLO, D B	8305250141	50-254	F
VASSALLO, D B	8305250145	50-298	F
VASSALLO, D B	8305250266	50-298	P
VASSALLO, D B	8305250514	50-220	P
VASSALLO, D B	8305260114	50-271	P
VASSALLO, D B	8305260130	50-293	P
VASSALLO, D B	8305260134	50-324	F
VASSALLO, D B	8305260167	50-331	P
VASSALLO, D B	8305260170	50-298	P
VASSALLO, D B	8305260175	50-293	P
VASSALLO, D B	8305260177	50-259	F
VASSALLO, D B	8305260187	50-259	P
VASSALLO, D B	8305260192	50-331	P
VASSALLO, D B	8305260201	50-263	P
VASSALLO, D B	8305260209	50-333	P
VASSALLO, D B	8305260285	50-324	P
VASSALLO, D B	8305260296	50-271	P
VASSALLO, D B	8305260297	50-333	P
VASSALLO, D B	8305260300	50-298	P
VASSALLO, D B	8305270045	50-271	Q
VASSALLO, D B	8305270055*	50-271	Q
VASSALLO, D B	8305310231	50-254	P
VAUGHAN, C M	8305050168	70-1113	
VAUGHAN, C M	8305310115*	70-1113	
VEGA, A	8305090513*	50-445	T
VENDER, J	8305190330*	50-293	S
VERRELLI, D	8305090409	50-390	Q
VERRELLI, D	8305100100	50-324	Q
VERRELLI, D M	8305030256	50-261	S
VERRELLI, D M	8305270083	50-395	Q
VERRELLI, D M	8305270091	50-395	Q
VERRELLI, D M	8305270196	50-62	Q
VERRELLI, D M	8305270228	50-390	Q
VERRELLI, D M	8305270229	50-261	Q
VERRELLI, D M	8305270250	50-324	Q
VERRELLI, D M	8305270263*	50-324	Q
VERRELLI, D M	8305270266	50-259	Q
VERRELLI, D M	8305270271	50-400	Q
VERRELLI, D M	8305270283*	50-416	Q
VERRELLI, D M	8305270290	50-390	Q
VERRELLI, D M	8305270292*	50-400	Q
VERRELLI, D M	8305270300	50-416	Q
VERRELLI, D M	8305270313	50-327	Q
VERRELLI, D M	8305270316	50-62	Q
VERRELLI, D M	8305270333	50-324	Q
VERRELLI, D M	8305270341	50-400	Q
VERRELLI, D M	8305270358	50-348	Q
VERRELLI, D M	8305270372	50-438	Q
VERRELLI, D M	8305270377	50-400	Q
VERRELLI, D M	8305270380	50-261	Q
VERRELLI, D M	8305270388	50-416	Q
VERRELLI, D M	8305270390	50-261	Q
VERRELLI, D M	8305270391*	50-400	Q
VERRELLI, D M	8305270396*	50-438	Q
VERRELLI, D M	8305270409	50-416	Q
VERRELLI, D M	8305270413	50-390	Q
VERRELLI, D M	8305270417*	50-416	Q
VERRELLI, D M	8305270418*	50-416	Q
VERRELLI, D M	8305270431	50-395	Q
VERRELLI, D M	8305270436	50-395	Q
VERRELLI, D M	8305270463	50-416	Q
VERRELLI, D M	8305270464	50-395	Q
VERRELLI, D M	8305270465	50-111	Q
VERRELLI, D M	8305270468	50-518	Q
VERRELLI, D M	8305270484	50-400	Q
VERRELLI, D M	8305270510	50-259	Q
VERRELLI, D M	8305270514	50-259	Q
VERRELLI, D M	8305270524	50-438	Q
VERRELLI, D M	8305270540	50-390	Q
VERRELLI, D M	8305270546	50-400	Q
VERRELLI, D M	8305270557	50-390	Q
VERRELLI, D M	8305270582	50-438	Q
VERRELLI, D M	8305270589	50-438	Q
VERRELLI, D M	8305270601*	50-438	Q
VERRELLI, D M	8305270609	50-400	Q
VERRELLI, D M	8305270616*	50-438	Q
VERRELLI, D M	8305270620*	50-400	Q
VERRELLI, D M	8305270623	50-400	Q
VERRELLI, D M	8305270642	50-259	Q
VERRELLI, D M	8305270651	50-390	Q
VERRELLI, D M	8305270653	50-259	Q
VERRELLI, D M	8305270658*	50-259	Q
VIETTI, A	8305100422	50-275	P
VINJAMURI, K	8305110523	NUREG	
VISSING, G	8305250298	MISC	
VISSING, G S	8305230019	50-313	P
VOGLER, B H	8305230239	50-352	Q
VOGT, H E	8305240517	50-247	H
VOGT-LOWELL, R	8305270219*	50-250	Q
VOIGT, H H	8305130098	50-546	Q
VOIGT, H H	8305130098	50-546	Q
VOIGT, H H	8305130098	50-546	Q
VOIGT, H H	8305130244	50-546	Q
VOIGT, H H	8305130244	50-546	Q
VOIGT, H H	8305130244	50-546	Q
VOLLMER, R H	8302250480*	50-470	A
VOLLMER, R H	8303170135*	50-423	A
VORDERBRUEGGEN	8305170537*	50-528	Q
VORDERBRUEGGEN	8305170564*	50-528	Q
VOSBURY, F	8305310241*	50-285	P
VUMBACO, F J	8305130011*	40-672	
VUMBACO, F J	8305130042*	40-672	
WADE, D H	8305090521*	50-445	T
WAGNER, A Q	8305270438*	50-416	Q
WAGNER, M E	8305050053	50-289	Q
WAGNER, M E	8305050082	50-460	Q
WAGNER, M E	8305090481	50-289	Q
WAGNER, M E	8305100231	50-289	Q
WAGNER, M E	8305170039	50-289	Q
WAGNER, M E	8305200576	50-460	Q
WAGNER, M E	8305200582	50-460	Q
WAGNER, P C	8305200167	50-267	P
WAGNER, P C	8305310027	50-267	P
WAGNER, R L	8305060076*	50-331	P
WAGNER, R L	8305270378*	50-333	P
WAHI, K K	8305170122	NUREG	
WAHL, H W	8305240415*	GA999	
WALDORF, E J	8305170461	50-440	Q
WALDRUP, U	8305060613*	50-238	R
WALKER, D L	8305230222*	40-1478	
WALKER, J R	8305190346	50-443	Q
WALKER, R D	8305100218*	50-331	Q
WALKER, R D	8305200611*	50-263	Q
WALKER, R D	8305240247*	50-373	Q
WALKER, R D	8305260314	50-263	S
WALKER, R D	8305310112*	50-254	Q
WALKER, W J	8305030189*	70-378	
WALL, R B	8305130288	40-8829	
WALLING, G E	8305050138*	50-335	S
WALLING, G E	8305100278*	50-389	S
WALSH, M A	8305040529	50-445	Q
WALSH, M A	8305110157	50-445	T
WAMBACH, T V	8305050354	REVIEW GRP	
WANG, J C	8305120633*	40-672	
WANG, J C	8305120642*	40-672	
WANG, J C	8305130062*	40-672	
WARCLOUD, J	8305200656	50-440	Q
WARD, E C	8305030221*	50-282	F
WARD, K D	8304150364*	50-440	Q
WARD, K D	8305190027*	50-454	Q
WARD, W J	8305100307*	50-482	Q
WARD, W J.	8305180196*	FOIA	
WAREMBOURG, D	8305060479	50-267	S
WAREMBOURG, D	8305060546	50-267	R
WAREMBOURG, D	8305090489	50-267	R
WAREMBOURG, D	8305230426	50-267	R
WAREMBOURG, D	8305310111	50-267	P
WAREMBOURG, D W	8305120570*	50-267	F
WAREMBOURG, D W	8305120578*	50-267	F
WAREMBOURG, D W	8305200494	50-267	P
WARHOL, W N	8305180200	40-7097	
WARNICK, R F	8305130171	50-329	Q
WARNICK, R F	8305170321	50-329	A
WARNICK, R F	8305170447	50-358	Q
WARNICK, R F	8305170550	50-358	A
WARNICK, R F	8305190312	50-358	A
WARNICK, R F	8305190316	50-358	S
WARNICK, R F	8305200557	50-329	Q
WARNICK, R F	8305240001	50-358	Q
WARNICK, R F	8305240006	50-329	Q
WARNICK, R F	8305260223	50-358	Q
WARNICK, R F	8305260225*	50-358	Q
WARNICK, R F	8305260336	50-358	A
WARNICK, R F	8305270076	50-329	Q
WARNICK, R F	8305270299	50-329	A
WARREN, R P	8305120357*	50-320	T
WASSERMAN, S P	8305020401	50-247	Q
WASSERMAN, S P	8305020401	50-247	Q
WASTLER, S L	8305130298	40-8348	
WASTLER, S. L	8305170585	40-8084	
WASTLER, S L	8305170585	40-8084	
WATERS, J J	8305200701*	50-213	S
WATERS, J R	8305100271*	50-295	Q
WATFORD, P S	8305240025	50-373	S
WATTELET, P L	8305200688*	50-373	P
WEBB, W A	8305120517*	CONTRACT	
WEGBT, W F	8305160037*	50-142	Q
WEIGANDT, J T	8305270575	50-247	H
WEINKAM, E J	8305190482	50-458	F
WEINKAM, E J	8305260305	50-458	C
WEINSTEIN, M	8305060675	NUREG	
WEISE, S.	8305270401*	50-261	Q
WEISE, S	8305270506*	50-261	Q
WEISS, D.	8305110298	50-409	R
WEISS, D	8305230033*	70-1359	
WEISS, E R	8305030502	50-537	Q
WEISS, E R	8305030502	50-537	Q
WEISS, E R.	8305030502	50-537	Q
WEISS, E R	8305060382	PR	
WEISS, E R	8305060573	PR	
WEISS, E R	8305100204	50-247	Q
WEISS, E R	8305100204	50-247	Q
WEISS, E R	8305160073	50-289	Q
WEISS, E. R	8305160073	50-289	Q
WEISS, E R	8305160149	50-537	Q
WEISS, E R	8305160149	50-537	Q
WEISS, E R	8305160149	50-537	Q
WEISS, E R	8305160181	50-537	Q
WEISS, E R	8305160181	50-537	Q
WEISS, E R	8305160181	50-537	Q
WEISS, E R	8305180356	PR	
WEISS, E R	8305180363	PR	
WEISS, E R	8305190221	50-537	Q
WEISS, E R	8305190221	50-537	Q
WEISS, E R	8305190221	50-537	Q
WEISS, E R	8305200470	PR	
WEISS, E R	8305240538	50-247	Q
WEISS, E. R	8305240538	50-247	Q
WEISS, E R	8305240542*	50-247	Q
WEISS, E R	8305240542*	50-247	Q
WEISS, E R	8305240553	50-537	Q
WEISS, E R.	8305240553	50-537	Q
WEISS, E R	8305240553	50-537	Q
WEISS, T	8305240555	50-247	T
WEISS, T	8305240558*	50-247	T
WELLS, D A	8305020085	50-341	S
WELLS, D. A.	8305030476	50-341	S
WELLS, D A	8305030585	50-341	S
WELLS, D A	8305030596	50-341	S
WELLS, D A	8305100015	50-341	S
WELLS, D A	8305100118	50-341	S
WELLS, D A	8305100154	50-341	S
WELLS, D A	8305100393*	50-341	Q
WELLS, D A	8305100399*	50-341	Q
WELLS, D. A	8305170207	50-341	S
WELLS, D A	8305170535	50-341	S
WELLS, R	8305110326*	50-320	S
WELLS, R A	8305030369	50-341	S
WELLS, R. W	8305050034	TOPREP	
WELLS, R. W	8305050034	TOPREP	
WENDERLICH, R L	8305230513*	50-317	S

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
WENSLAWSKI, F A	8305170343*	50-397	G
WENSLAWSKI, F A	8305170501*	50-275	G
WENSLAWSKI, F A	8305170521*	50-361	G
WENSLAWSKI, F A	8305170530*	50-361	G
WENSLAWSKI, F A	8305170567*	50-344	G
WERNER, R P	8305110069	50-213	F
WERSAN, D	8305170533	50-352	G
WESCOTT, H M	8305020285*	50-341	G
WESLEY, D A	8305170544*	50-329	A
WESTAFER, G R	8305030036	50-302	P
WESTAFER, G R	8305030050	50-302	P
WESTAFER, G. R	8305050016	50-302	S
WESTAFER, G R	8305090462	50-302	P
WESTAFER, G R	8305130002	50-302	P
WESTAFER, G R	8305130012	50-302	P
WESTAFER, G R	8305130043	50-302	R
WESTAFER, G R	8305130067	50-302	P
WESTAFER, G R	8305130179	50-302	S
WESTAFER, G R	8305170399	50-302	S
WESTAFER, G R	8305190344	50-302	P
WESTAFER, G. R	8305200378	50-302	P
WESTAFER, G R	8305270253*	50-302	G
WESTAFER, G R	8305270258*	50-302	G
WESTAFER, G R	8305270312*	50-302	G
WESTAFER, G R	8305270318*	50-302	G
WESTAFER, G R	8305270503*	50-302	G
WESTBROOK, K B	8305250275	40-8786	
WESTBROOK, K B	8305250279	40-8786	
WESTCOTT, H M	8305090313*	50-373	G
WESTERMAN, T	8305230475*	50-285	G
WESTERMAN, T F	8305100249*	50-445	G
WESTERMAN, T. F.	8305170318*	50-445	G
WESTERMAN, T F	8305170333*	50-298	G
WESTERMAN, T F	8305200344	50-298	S
WESTERMAN, T F	8305230449*	50-445	G
WESTERMAN, T F	8305240005*	50-445	G
WESTERMAN, T F	8305260304*	50-298	G
WESTON, R. T	8305060529	50-352	A
WESTON, R T	8305060536*	50-352	A
WETHY, C. M.	8305030240*	50-389	F
WETHY, C M	8305160282*	50-389	F
WETHY, C M.	8305170310	50-389	S
WETHY, C. M.	8305230016	71-5957	
WETTERHAHN, M J	8305020441	50-352	G
WETTERHAHN, M J	8305020441	50-352	G
WETTERHAHN, M. J	8305030517	27-39	
WETTERHAHN, M J.	8305030563	50-352	G
WETTERHAHN, M J.	8305030563	50-352	G
WETTERHAHN, M J.	8305060478	50-352	G
WETTERHAHN, M. J.	8305060478	50-352	G
WETTERHAHN, M J.	8305240489	50-352	G
WETTERHAHN, M J.	8305240489	50-352	G
WHALEN, R J	8305060492*	50-237	S
WHEATON, W. R	8305130222	50-440	S
WHEELER, L.	8305110018	50-508	A
WHEELER, L L	8305110016	50-443	A
WHICHER, J. M	8305030508	50-454	T
WHICHER, J. M	8305030508	50-454	T
WHICHER, J. M.	8305030508	50-454	T
WHICHER, J M	8305100286	50-454	G
WHICHER, J. M	8305100286	50-454	G
WHICHER, J. M.	8305100286	50-454	G
WHITAKER, W A.	8305200683*	50-373	P
WHITE, I. L	8305180805	PROJ	
WHITE, L. M	8305060294	PR	
WHITE, R N	8305110476	NUREG	
WHITE, W. S	8305230368	50-315	P
WHITED, P. J	8305200101	50-320	P
WHITENER, H L	8305270367*	50-335	G
WHITENER, H. L	8305270526*	50-259	G
WHITNEY, D D.	8305120073	TOPREP	
WHITNEY, D. D	8305120073	TOPREP	
WHITNEY, D D	8305270432	TOPREP	
WHITNEY, D. D.	8305270432	TOPREP	
WHITNEY, G. G	8304110706*	50-293	S
WHITNEY, G. G	8305110341*	50-293	S
WHITNEY, G. G.	8305110365*	50-293	S
WHITNEY, G. G.	8305110392*	50-293	S
WHITNEY, G. G	8305170532*	50-293	R
WHITNEY, G G	8305230515*	50-293	S
WHITNEY, G G	8305230521*	50-293	S
WHITNEY, M. A	8305060503*	50-309	S
WHITSON, D. R	8305130091*	50-259	S
WICKS, F	8305170466	50-225	F
WIEBE, J	8305030164*	50-320	G
WIEDEMAN, D	8305130165	I&E	
WIEDEMAN, D	8305170559	I&E	
WIEDEMAN, D G	8305120465	40-215	
WIELAND, R H	8305190284*	50-329	A
WIESEMANN, R A	8304180558*	TOPREP	
WIESEMANN, R A	8305020272	50-266	P
WIESEMANN, R A	8305030438*	TOPREP	
WIESEMANN, R A	8305050208*	TOPREP	
WIESEMANN, R A	8305050288*	50-369	P
WIESEMANN, R A	8305090202*	PROJ	
WIESEMANN, R A	8305110377*	50-334	P
WIESEMANN, R A	8305170411*	50-454	T
WIESEMANN, R A	8305180273*	TOPREP	
WIESEMANN, R A	8305270012*	TOPREP	
WIESEMANN, R A	8305270488*	TOPREP	
WIGGINS, E	8305040635	CONTRACT	
WIGGINS, E	8305060320	CONTRACT	
WIGGINS, E	8305170065	CONTRACT	
WIGGINS, J T	8305100429*	50-443	G
WIGGINS, J T	8305190038*	50-322	G
WIGGINS, J T	8305250314*	50-309	G
WIGGINTON, D L	8305040354	50-315	P
WIGGINTON, D L	8305170076	50-315	P
WILBER, H A	8103250385*	50-498	G
WILCOVE, M N	8305100147	50-329	T
WILCOVE, M N	8305120295	50-329	G
WILCOVE, M N	8305190225	50-329	G
WILCOVE, M N	8305240059	50-329	G
WILCOVE, M N	8305250376	50-320	G
WILCOVE, M N	8305260276	50-329	G
WILCOX, J D	8305270629*	50-438	G
WILD, P. A	8305240223	50-329	A
WILKENSON	8304060126*	50-440	E
WILKINSON, E P	8305250517	PR	
WILLETT, D J	8305170349*	50-397	G
WILLIAMS, C C	8305030537*	50-440	T
WILLIAMS, C C	8305040522*	50-305	G
WILLIAMS, C C	8305120368*	50-374	G
WILLIAMS, C C	8305120428*	50-546	G
WILLIAMS, C C	8305120447*	50-373	G
WILLIAMS, C C	8305190393*	50-373	S
WILLIAMS, D L	8305240061*	50-282	G
WILLIAMS, H G	8305190014	State Prog	
WILLIAMS, J	8305120342	50-358	S
WILLIAMS, J	8305120410	50-358	S
WILLIAMS, J	8305120429	50-358	S
WILLIAMS, J	8305120432	50-358	S
WILLIAMS, J	8305120446	50-358	S
WILLIAMS, J	8305120487	50-358	S
WILLIAMS, J	8305130111	50-358	K
WILLIAMS, J	8305170524	50-358	S
WILLIAMS, J	8305180458	50-358	F
WILLIAMS, J	8305190228	50-358	S
WILLIAMS, J	8305200536	50-358	S
WILLIAMS, J	8305260227	50-358	S
WILLIAMS, J	8305260337*	50-358	A
WILLIAMS, J W	8305050127	50-335	S
WILLIAMS, J W	8305100251	50-251	S
WILLIAMS, J W	8305100269	50-389	S
WILLIAMS, J. W	8305110487	50-250	S
WILLIAMS, J. W	8305170191	50-389	S
WILLIAMS, J W	8305170244	50-335	S
WILLIAMS, J. W	8305250302	50-335	S
WILLIAMS, O. G	8305060096	FOIA	
WILLIAMS, R	8305040392*	FOIA	
WILLIAMS, R E	8305020491	40-6622	
WILLIAMS, R E	8305090012*	CONTRACT	
WILLIAMS, V S	8305030446*	50-304	S
WILLIAMS, V. S.	8305240311	50-295	S
WILLIAMSON, E L	8305020319*	GA999	
WILSON, B. D	8305040558	XPORTLIC	
WILSON, B. D.	8305040567*	XPORTLIC	
WILSON, B. D	8305170578	XPORTLIC	
WILSON, B. D	8305180617	XPORTLIC	
WILSON, B D.	8305180713	XPORTLIC	
WILSON, B. D.	8305260075	XPORTLIC	
WILSON, F. W	8305090162	NUREG	
WILSON, J. H.	8305240258	50-382	A
WILSON, J. L	8305050118	50-281	S
WILSON, J L	8305050121*	50-281	S
WILSON, J L	8305050130*	50-281	S
WILSON, J L.	8305100115	50-280	S
WILSON, J. L	8305100120*	50-280	S
WILSON, J. L	8305100129*	50-280	S
WILSON, J. L.	8305130125	50-281	S
WILSON, J L	8305130130*	50-281	
WILSON, J L	8305130136*	50-281	
WILSON, J L	8305130198	50-280	
WILSON, J L	8305130203*	50-280	
WILSON, J L	8305130228	50-280	
WILSON, J L	8305130243*	50-280	
WILSON, J L	8305230424	50-281	
WILSON, J L	8305230432*	50-281	
WILSON, J L	8305230451*	50-281	
WILSON, R	8305170456	50-400	
WILSON, R	8305170486	50-400	
WILSON, R	8305170491	50-400	
WILT, D D	8305040325	50-440	
WILT, D. D	8305040487	50-440	
WILT, D D	8305040487	50-440	
WILT, D D	8305040548	50-440	
WILT, D. D	8305040548	50-440	
WILT, D. D	8305100294	50-440	
WILT, D. D	8305100294	50-440	
WILT, D D	8305100367	50-440	
WILT, D D	8305100367	50-440	
WILT, D D	8305310031	50-440	
WINGO, M D	8305170340*	50-260	
WIRE, K. R	8305060584*	50-298	
WISENBURG, M R	8305180358	PR	
WISHNIE, R G	8305240508	50-247	
WITHERS, B D	8305040417	50-344	
WITHERS, B D	8305060600	50-344	
WITHERS, B D	8305060606*	50-344	
WITHERS, B D	8305130164	50-344	
WITHERS, B D	8305130224	50-344	
WITHERS, B D	8305130240	50-344	
WITHERS, B D	8305180266	PR	
WITHERS, B D	8305200013	50-344	
WITHERS, B D	8305230581	50-344	
WITHERS, B D	8305260275	50-344	
WITHERS, B D	8305270182	50-344	
WITHERS, B D	8305270186*	50-344	
WITHERS, B D	8305270205	50-344	
WITHERS, B D	8305270211*	50-344	
WIZNER, D G	8305270087	50-315	
WOFFORD, A W	8305060153*	FOIA	
WOHLD, P R	8305020357*	50-483	
WOJCHOUSKI, A V	8305020492*	50-263	
WOLFE, S J	8305120322	50-382	
WOLFE, S J.	8305270634	50-382	
WOLLETT, S.	8305090050	CONTRACT	
WOLLETT, S	8305090068*	CONTRACT	
WOLLETT, S.	8305170688	CONTRACT	
WOLLETT, S.	8305230281	CONTRACT	
WOLLETT, S	8305270097	CONTRACT	
WOLLETT, S	8305270103	CONTRACT	
WOLVENDYK, A	8305200177	70-371	
WOOD, E C	8305110344	50-309	
WOOD, J. E	8305040465*	TOPREP	
WOODHEAD, C P	8305030494	50-142	
WOODHEAD, C P	8305100312	50-142	
WOODHEAD, C P	8305160164	50-142	
WOODHEAD, C. P	8305170001	50-142	
WOODHEAD, C P	8305170063	50-142	
WOODHEAD, C P	8305170067*	50-142	
WOODHEAD, C P	8305200613	50-142	
WOODHEAD, C P	8305240521	50-142	
WOODLAN, D R	8305090530*	50-445	
WOODRUFF, R L	8304280139	I&E	
WOOLEVER, E J	8305020426	50-412	
WOOLEVER, E J	8305100104	50-412	
WOOLEVER, E J	8305110295	50-412	
WOOLEVER, E J.	8305180256	50-412	
WOOLEVER, E. J	8305180283	50-412	
WOOLEVER, E J	8305180559	50-412	
WOOLEVER, E. J	8305200429	50-412	
WOOLEVER, E J	8305240248	50-412	
WOOLEVER, E J	8305250498*	50-412	
WOOLEVER, E. J	8305270662*	50-412	
WOOLSEY, R T	8305120490	40-8602	
WOOLSEY, R T	8305120501	40-299	
WOOLSEY, R. T	8305130295	40-2259	
WOOLSEY, R. T	8305170583	40-299	
WOOLSEY, R T	8305170583	40-299	
WORTHEN, M.	8305030487	PR	
WRAY, J R	8305270357*	50-321	
WRAY, J R	8305270534*	50-338	
WRAY, J R	8305270576*	50-335	
WRIGHT, D	8305110198*	CONTRACT	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	
WRIGHT, G C	8305170174*	50-155	G
WRIGHT, N A	8305100243	50-329	T
WRIGHT, N A	8305240065	50-329	Q
WRIGHT, R G	8305250566*	50-483	G
WRIGHT, R G	8305250566*	50-483	G
WRIGHT, R J	8303290556	WASTE MGT	
WRIGHT, R J	8303290813	WASTE MGT	
WRIGHT, R J	8305110068	WASTE MGT	
WRIGHT, R W	8305270179*	50-389	G
WULLER, G E	8303240346	50-461	A
WULLER, G E	8305030559	50-461	R
WULLER, G E	8305130146	50-461	E
WULLER, G E	8305200667	50-461	A
WULLER, G E	8305240142	50-461	A
WULLER, G B	8305230233*	40-1478	
WUNDERLICH, J	8305310152	50-265	S
WYNGARDEN, S	8305030671	40-3392	
WYNGARDEN, S D	8305250604*	40-8027	
YAMANA, K	8305170125*	XPORTLIC	
YAMANA, K	8305180709	XPORTLIC	
YANDELL, L A	8305100244*	50-285	G
YANG, M S	8305270501*	50-454	G
YARGER, K	8305170205*	50-346	S
YARGER, K	8305260293	50-346	S
YARGER, K	8305310038	50-346	S
YORK, J W	8305270492*	50-400	G
YOUNG, F	8305160199*	50-289	G
YOUNG, M A	8305100172	50-454	G
YOUNG, M A	8305230236	50-142	G
YOUNG, M L	8305250331	50-443	H
YOUNG, T	8305170382*	50-528	G
YOUNG, T.	8305170537*	50-528	G
YOUNG, T	8305170564*	50-528	G
YOUNG, Y. A	8305060369*	40-8783	
YOUNG, Y. A	8305130333*	40-8783	
YOUNGBLOOD, B J	8305040006	50-482	A
YOUNGBLOOD, B J	8305040062	50-454	F
YOUNGBLOOD, B J	8305040664	50-440	E
YOUNGBLOOD, B J	8305060648	50-423	A
YOUNGBLOOD, B J	8305110185	50-546	A
YOUNGBLOOD, B J	8305120088	50-482	F
YOUNGBLOOD, B J	8305120552	50-454	A
YOUNGBLOOD, B J	8305120610	50-445	G
YOUNGBLOOD, B J	8305190096	50-440	A
YOUNGBLOOD, B J	8305230427	50-445	A
YOUNGBLOOD, B J	8305230630	50-358	A
YOUNGBLOOD, B J	8305230635	50-546	A
YOUNGBLOOD, B J	8305230645	50-440	E
YOUNGBLOOD, B J	8305230649	50-440	E
YOUNGBLOOD, B J	8305230658	50-358	A
YOUNGBLOOD, R	8305110126	50-312	P
YOUNGLING, E J	8305190271	50-322	G
YUHAS, G P	8305170343*	50-397	G
YUHAS, G P	8305170530*	50-361	G
YUMOTO, H	8305160298	XPORTLIC	
YUNDT, C P	8305130143	50-344	S
ZAHLER, R E	8305240287	50-289	G
ZAHLER, R E	8305240287	50-289	G
ZAHLER, R E	8305240486	50-289	G
ZAHLER, R E	8305240487	50-289	G
ZAHLER, R E	8305250202	50-289	G
ZAHLER, R E	8305250202	50-289	G
ZAHLER, R E	8305250208*	50-289	G
ZAHLER, R E	8305250208*	50-289	G
ZAHLER, R E	8305250225*	50-289	G
ZAHLER, R E	8305250225*	50-289	G
ZANARDI, G	8305100370*	50-325	P
ZARBIS, W A	8305060076*	50-331	P
ZARBIS, W A	8305270378*	50-333	P
ZIEMER, P D	8305180261	50-305	G
ZIMMERMAN, J V	8305020001	XPORTLIC	
ZIMMERMAN, J V	8305020098	XPORTLIC	
ZIMMERMAN, J V	8305030097	XPORTLIC	
ZIMMERMAN, J V	8305040639	XPORTLIC	
ZIMMERMAN, J V	8305040644	XPORTLIC	
ZIMMERMAN, J V	8305040658	XPORTLIC	
ZIMMERMAN, J V	8305040665	XPORTLIC	
ZIMMERMAN, J V	8305050440	XPORTLIC	
ZIMMERMAN, J V	8305060014	XPORTLIC	
ZIMMERMAN, J V	8305090042	XPORTLIC	
ZIMMERMAN, J V	8305090498	XPORTLIC	
ZIMMERMAN, J V	8305090500	XPORTLIC	
ZIMMERMAN, J V	8305090730	XPORTLIC	
ZIMMERMAN, J V	8305090731*	XPORTLIC	
ZIMMERMAN, J V	8305090733	XPORTLIC	
ZIMMERMAN, J V	8305090736	XPORTLIC	
ZIMMERMAN, J V	8305090779	XPORTLIC	
ZIMMERMAN, J V	8305130265	XPORTLIC	
ZIMMERMAN, J V	8305130269	XPORTLIC	
ZIMMERMAN, J V	8305160294	XPORTLIC	
ZIMMERMAN, J V	8305160296	XPORTLIC	
ZIMMERMAN, J V	8305160300	XPORTLIC	
ZIMMERMAN, J V	8305160307	XPORTLIC	
ZIMMERMAN, J V	8305160309	XPORTLIC	
ZIMMERMAN, J V	8305160310	XPORTLIC	
ZIMMERMAN, J V	8305160313	XPORTLIC	
ZIMMERMAN, J V	8305160315	XPORTLIC	
ZIMMERMAN, J V	8305170120	XPORTLIC	
ZIMMERMAN, J V	8305170594	XPORTLIC	
ZIMMERMAN, J V	8305180078	XPORTLIC	
ZIMMERMAN, J V	8305180086	XPORTLIC	
ZIMMERMAN, J V	8305180090	XPORTLIC	
ZIMMERMAN, J V	8305180551	XPORTLIC	
ZIMMERMAN, J V	8305180703	XPORTLIC	
ZIMMERMAN, J V	8305180835	XPORTLIC	
ZIMMERMAN, J V	8305190053	XPORTLIC	
ZIMMERMAN, J V	8305200129	XPORTLIC	
ZIMMERMAN, J V	8305200137*	XPORTLIC	
ZIMMERMAN, J V	8305250165	XPORTLIC	
ZIMMERMAN, J V	8305260016	XPORTLIC	
ZIMMERMAN, J V	8305260027	XPORTLIC	
ZIMMERMAN, J V	8305260029	XPORTLIC	
ZIMMERMAN, J V	8305260034	XPORTLIC	
ZIMMERMAN, J V	8305260055	XPORTLIC	
ZIMMERMAN, J V	8305260067	XPORTLIC	
ZIMMERMAN, J V	8305260090	XPORTLIC	
ZIMMERMAN, J V	8305260113	XPORTLIC	
ZIMMERMAN, J V	8305260185	XPORTLIC	
ZIMMERMAN, J V	8305260189	XPORTLIC	
ZIMMERMAN, J V	8305260191	XPORTLIC	
ZIMMERMAN, J V.	8305260194	XPORTLIC	
ZIMMERMAN, J V	8305260197	XPORTLIC	
ZIMMERMAN, J V	8305260198	XPORTLIC	
ZIMMERMAN, J V	8305260199	XPORTLIC	
ZIMMERMAN, J V	8305260203	XPORTLIC	
ZIMMERMAN, J V	8305260204	XPORTLIC	
ZIMMERMAN, J V	8305270032	XPORTLIC	
ZIMMERMAN, J V	8305270034*	XPORTLIC	
ZIMMERMAN, R P	8305250453*	50-244	G
ZIMMERMAN, S R	8305020003	XPORTLIC	
ZIMMERMAN, S R	8305020165	50-400	R
ZIMMERMAN, S R	8305090380	50-324	P
ZIMMERMAN, S R	8305090456	50-324	P
ZIMMERMAN, S R	8305100342	50-325	P
ZIMMERMAN, S R	8305120003	50-324	P
ZIMMERMAN, S R	8305200435	50-261	P
ZIMMERMAN, S R	8305200600	50-261	H
ZIMMERMAN, S R	8305240417	50-400	K
ZIMMERMAN, S R	8305260022	50-261	P
ZIMMERMAN, S R	8305260320	50-324	P
ZIVKOVICH, E A	8305200656	50-440	G
ZUPKO, J M	8305060476	50-272	B
ZUPKO, J M	8305060480	50-311	B
ZUPKO, J M	8305110271	50-311	B
ZUPKO, J M	8305110274*	50-311	B
ZUPKO, J M	8305160052	50-311	B
ZUPKO, J. M	8305160096	50-311	B
ZUPKO, J M	8305160118	50-311	B
ZUPKO, J M	8305170018	50-272	R
ZUPKO, J M	8305170142	50-311	R
ZUPKO, J M	8305170367	50-311	B
ZUPKO, J. M	8305200394	50-272	B
ZUPKO, J M	8305200537	50-311	B
ZUPKO, J M	8305250501	50-311	B

CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Aamodt, The	8305100163	50-289 Q
	8305100205	50-289 Q
	8305100406	50-289 Q
Advisory Council on Historic Preservation	8305110296	50-410 D
Aerospace Corp.	8305110027	NUREG
Agriculture, Dept of	8305040387*	FOIA
	8305040392*	FOIA
Agriculture, Dept of, Graduate School	8305230249*	CONTRACT
Air and Water Pollution Patrol	8305040470	50-352 Q
	8305260181	50-352 Q
Alabama Power Co	8305020456	50-348 P
	8305030580	50-364 B
	8305030589*	50-364 B
	8305050148	50-348 B
	8305050154*	50-348 B
	8305050158*	50-348 B
	8305050195	50-348 B
	8305050203*	50-348 B
	8305060621*	50-348 F
	8305060626*	50-348 F
	8305100132	50-364 B
	8305100139*	50-364 B
	8305110257	50-364 B
	8305110260*	50-364 B
	8305110308	50-348 P
	8305110308	50-348 P
	8305110311*	50-348 P
	8305110311*	50-348 P
	8305160094	50-348 Q
	8305160094	50-348 Q
	8305160100*	50-348 Q
	8305160107*	50-348 Q
	8305160107*	50-348 Q
	8305200306	50-348 R
	8305200327*	50-348 R
	8305200357	50-364 R
	8305200362*	50-364 R
	8305200579	50-348 R
	8305200579	50-348 R
	8305230540	50-348 B
	8305230544*	50-348 B
	8305230550*	50-348 B
	8305240191	50-348 F
	8305240191	50-348 F
	8305240440	50-348 P
	8305240481	50-348 I
	8305240481	50-348 I
	8305240484*	50-348 I
	8305250285	50-348 F
	8305250285	50-348 F
	8305250353	50-348 B
	8305250391	50-348 F
	8305250391	50-348 F
	8305250581	50-348 B
	8305310201	50-348 B
American Association of Physicists in Medicine	8305180425	PR
American College of Nuclear Physicians	8305030416	PR
	8305200296	PR
American Electric Power Co , Inc	8305160062*	50-315 R
	8305230368	50-315 P
American Electric Power Service Corp	8305030257	50-315 P
	8305030519	50-315 P
	8305120108	50-315 F
American Nuclear Insurers	8305110012	PR
American Nuclear Society	8305180353	PR
	8305230469*	COMMISSION
	8305250517	PR
	8305270109	NUREG
Amesbury, MA	8305250327	50-443 Q
Anacomp, Inc	8305260222*	CONTRACT
Analysis & Technology, Inc	8305060326*	CONTRACT
	8305170070*	CONTRACT
	8305170077*	CONTRACT
Antioch School of Law, Washington, DC	8305100290	50-155 Q
	8305190366	50-155 Q
	8305190371*	50-155 Q
Applied Biology, Inc	8305030347*	50-335 R
Applied Physical Technology, Inc.	8305110163*	CONTRACT
Applied Research Associates, Inc.	8305310157*	50-244 P
Applied Risk Technology Corp	8305180146*	50-247 Q
Argonne National Laboratory	8305110148	NUREG
	8305110162	NUREG
	8305130340	ACRS
	8305130349	50-537 O
	8305130350	50-537 O
	8305180637	50-537 O
	8305190132*	FOIA
	8305190153*	FOIA
	8305190337*	FOIA
	8305190341*	FOIA
	8305230086*	71-5607
Arizona Public Service Co	8305020089	50-528 K
	8305020089	50-528 K
	8305020089	50-528 K
	8305020092*	50-528 K
	8305030285	50-528 B
	8305030346	50-529 B
	8305030626	50-528 B
	8305030626	50-528 B
	8305120385	50-528 E
	8305130082	50-528 B
	8305130107	50-528 B
	8305130124	50-528 B
	8305130124	50-528 B
	8305130124	50-528 B
	8305130127	50-528 B
	8305130148	50-528 B
	8305130148	50-528 B
	8305130148	50-528 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305130159	50-528	S
	8305130159	50-528	S
	8305130159	50-528	S
	8305130161	50-529	S
	8305130168	50-528	S
	8305130169	50-528	S
	8305130183	50-528	S
	8305130189	50-528	S
	8305130189	50-528	S
	8305130210	50-528	S
	8305130210	50-528	S
	8305130210	50-528	S
	8305130226	50-528	S
	8305130226	50-528	S
	8305130226	50-528	S
	8305130229	50-528	S
	8305130229	50-528	S
	8305130264	50-528	S
	8305130264	50-528	S
	8305130264	50-528	S
	8305160071	50-528	A
	8305160072*	50-528	A
	8305200322	50-528	F
	8305200417	50-528	A
	8305230517	50-528	S
	8305260321*	50-528	G
	8305260326*	50-528	G
	8305310161	50-528	A
	8305310215	50-528	G
Arizona, State of	8305030598	PR	
Arkansas Power & Light Co	8303240480	50-313	P
	8304270426*	50-313	F
	8304270426*	50-313	F
	8304270427*	50-313	F
	8305020373	50-368	S
	8305020378*	50-368	S
	8305020416	50-368	P
	8305030331*	50-313	G
	8305030385	50-313	S
	8305030390*	50-313	S
	8305040453	50-313	R
	8305040459*	50-313	R
	8305050125	50-313	P
	8305050125	50-313	P
	8305050216	50-313	P
	8305060452	50-313	S
	8305060454*	50-313	S
	8305060583*	50-313	F
	8305060583*	50-313	F
	8305060591*	50-313	F
	8305060591*	50-313	F
	8305090333	50-313	P
	8305090333	50-313	P
	8305090421	50-313	J
	8305090440	50-313	P
	8305100351	50-313	P
	8305100351	50-313	P
	8305120414	50-313	S
	8305120418*	50-313	S
	8305120451*	50-313	G
	8305160290*	50-313	F
	8305160290*	50-313	F
	8305170551	50-313	G
	8305180467	50-368	P
	8305190363	50-313	J
	8305200319*	50-313	G
	8305200326	50-313	F
	8305200445	50-313	S
	8305200451*	50-313	S
	8305200490	50-313	S
	8305200541	50-313	P
	8305200541	50-313	P
	8305200573	50-368	R
	8305200580	50-368	P
	8305230364	50-313	P
	8305230723	50-368	P
	8305230725*	50-368	P
	8305240054*	50-313	G
	8305240139	50-313	H
	8305240360	50-368	P
	8305240399	50-313	P
	8305260249	50-368	S
	8305260260	50-313	S
	8305270065	50-313	P
	8305310199*	50-313	G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305310199*	50-313	G
Army, Dept of	8103130267*	FOIA	
	8305020015*	FOIA	
	8305020016*	FOIA	
	8305020019*	FOIA	
	8305020022*	FOIA	
	8305020031*	FOIA	
	8305020035*	FOIA	
	8305020042*	FOIA	
	8305020047*	FOIA	
	8305020057*	FOIA	
	8305020070*	FOIA	
	8305020081*	FOIA	
	8305020095*	FOIA	
	8305020095*	FOIA	
	8305020095*	FOIA	
	8305020095*	FOIA	
	8305020095*	FOIA	
	8305020158*	FOIA	
	8305020169*	FOIA	
	8305020178*	FOIA	
	8305020204*	FOIA	
	8305020207*	FOIA	
	8305020325*	FOIA	
	8305020539*	70-378	
	8305020539*	70-378	
	8305020539*	FOIA	
	8305020539*	70-378	
	8305020545*	FOIA	
	8305020550*	FOIA	
	8305020554*	FOIA	
	8305020558*	FOIA	
	8305020560*	FOIA	
	8305020564*	FOIA	
	8305020567*	FOIA	
	8305020571*	FOIA	
	8305030008*	FOIA	
	8305030020*	FOIA	
	8305030023*	FOIA	
	8305030027*	FOIA	
	8305030035*	FOIA	
	8305030055*	FOIA	
	8305030063*	FOIA	
	8305030073*	FOIA	
	8305030080*	FOIA	
	8305030087*	FOIA	
	8305030092*	FOIA	
	8305030105*	FOIA	
	8305030125*	FOIA	
	8305030142*	FOIA	
	8305030147*	FOIA	
	8305030154*	FOIA	
	8305030163*	FOIA	
	8305030169*	FOIA	
	8305030174*	FOIA	
	8305030179*	FOIA	
	8305030185*	FOIA	
	8305030218*	70-378	
	8305030225*	70-378	
	8305030233*	70-378	
	8305030239*	70-378	
	8305030251*	70-378	
	8305030260*	70-378	
	8305030312*	70-378	
	8305030326*	70-378	
	8305030335*	70-378	
	8305040093*	FOIA	
	8305040114*	FOIA	
	8305040120*	FOIA	
	8305040158*	FOIA	
	8305040165*	FOIA	
	8305040175*	FOIA	
	8305040183*	FOIA	
	8305040189*	FOIA	
	8305040200*	FOIA	
	8305040211*	FOIA	
	8305040217*	FOIA	
	8305040224*	FOIA	
	8305040234*	FOIA	
	8305040239*	FOIA	
	8305040244*	FOIA	
	8305040250*	FOIA	
	8305040256*	FOIA	
	8305040272*	FOIA	
	8305040279*	FOIA	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305040287*	FOIA	
	8305040290*	FOIA	
	8305040294*	FOIA	
	8305040414*	FOIA	
	8305040425*	FOIA	
	8305040450*	FOIA	
	8305040478*	FOIA	
	8305040478*	FOIA	
	8305040478*	FOIA	
	8305040501*	FOIA	
	8305040510*	FOIA	
	8305040519*	FOIA	
	8305040523*	FOIA	
	8305040554*	FOIA	
	8305040556*	FOIA	
	8305040559*	FOIA	
	8305040559*	FOIA	
	8305040562*	FOIA	
	8305040569*	FOIA	
	8305040573*	FOIA	
	8305040578*	FOIA	
	8305040583*	70-378	
	8305040593*	70-378	
	8305040599*	70-378	
	8305040674*	70-378	
	8305040678*	70-378	
	8305040696*	70-378	
	8305050297*	70-378	
	8305050306*	70-378	
	8305050310*	70-378	
	8305050316*	70-378	
	8305050322*	70-378	
	8305050328*	70-378	
	8305050330*	70-378	
	8305050333*	70-378	
	8305050339*	70-378	
	8305050342*	FOIA	
	8305050346*	FOIA	
	8305050349*	FOIA	
	8305050351*	FOIA	
	8305050359*	FOIA	
	8305050361*	FOIA	
Army, Dept. of, Corps of Engineers	8305060351*	CONTRACT	
	8305110041*	CONTRACT	
	8305170607*	CONTRACT	
Army, Dept of, Headquarters Materiel Development & Readiness Command	8006180578*	FOIA	
	8104060899*	FOIA	
	8305040060*	FOIA	
	8305040089*	FOIA	
	8305040103*	FOIA	
	8305040127*	FOIA	
	8305040468*	70-378	
	8305040489*	FOIA	
	8305040502*	FOIA	
Atlas Minerals	8305130362	40-3453	
Atomic Industrial Forum	8305180306	PR	
	8305180313*	PR	
	8305180351	PR	
	8305180378	PR	
Audubon Society	8305160024	50-247	Q
	8305160024	50-247	Q
	8305160028*	50-247	Q
	8305160028*	50-247	Q
Automation Industries, Inc.	8305180194	71-9180	
BWR Owners Group	8305100197	TOPREP	
Babcock & Wilcox Co.	8305020392*	50-312	P
	8305020404*	50-329	E
	8305020523	70-824	
	8305020526*	70-824	
	8305030001	71-6294	
	8305030410	TOPREP	
	8305040637	XPORTLIC	
	8305050100	70-1201	
	8305050205	70-1201	
	8305090464*	50-302	P
	8305100316	TOPREP	
	8305110443*	50-346	P
	8305120018	TOPREP	
	8305120344*	50-320	T
	8305120347*	50-320	T
	8305240046	71-166	
	8305260311*	50-330	S
	8305260313*	50-330	S
	8305260376	70-1201	
	8305270309*	50-269	P
Babcock & Wilcox Operating Plants Owners Group	8305120073	TOPREP	
	8305270432	TOPREP	
Backus, Shea & Meyer	8305190199	50-443	Q
Baltimore Gas & Electric Co	8305020344*	50-317	Q
	8305020344*	50-317	Q
	8305020509	50-317	S
	8305030383	50-318	S
	8305030388*	50-318	S
	8305060396	50-317	P
	8305060396	50-317	P
	8305060402	50-317	P
	8305060405*	50-317	P
	8305060405*	50-317	P
	8305060412	50-317	Q
	8305060412	50-317	Q
	8305060438	PR	
	8305060631*	50-317	F
	8305060635*	50-317	F
	8305060635*	50-317	F
	8305110352	50-317	S
	8305110363*	50-317	S
	8305160081	50-318	S
	8305180358	PR	
	8305190287	50-317	S
	8305190290*	50-317	S
	8305190293	50-317	P
	8305190348	50-318	S
	8305190352*	50-318	S
	8305200564	50-317	R
	8305200584*	50-317	R
	8305200620	50-317	Q
	8305200620	50-317	Q
	8305200628*	50-317	Q
	8305200628*	50-317	Q
	8305200631	50-317	R
	8305200631	50-317	R
	8305200644*	50-317	R
	8305200644*	50-317	R
	8305200650*	50-317	R
	8305200650*	50-317	R
	8305230513*	50-317	S
	8305230522	50-318	S
	8305230528*	50-318	S
	8305230555	50-317	S
	8305230560*	50-317	S
	8305240269*	50-317	P
	8305260294	50-317	P
	8305260294	50-317	P
	8305260302	50-317	J
	8305270029	50-317	P
	8305270029	50-317	P
	8305270072	50-317	S
	8305270603	50-317	S
Barr Engineering Co	8305200004*	CONTRACT	
Basic Energy Technology Associates	8305020160*	50-272	S
Battelle Memorial Institute, Columbus Laboratories	8305270100*	CONTRACT	
Battelle Memorial Institute, Pacific Northwest Laboratory	8011180782*	MISC	
	8207080528*	50-255	P
	8301060137*	50-309	P
	8305030317	50-331	Q
	8305040596	MISC	
	8305060233	NUREG	
	8305060674	NUREG	
	8305100011	50-346	F
	8305110208	NUREG	
	8305110457	NUREG	
	8305120374*	50-237	P
	8305130359	50-537	Q
	8305180782	NUREG	
	8305250168	RES	
	8305250174	RES	
Bear Creek Uranium Co	8305020363	40-8452	
Bechtel Corp	8305100281*	50-352	A
	8305120330*	50-320	T
	8305200593*	GA999	
	8305240415*	GA999	
	8305250393*	50-237	Q
	8305250399*	50-237	Q
	8305250399*	50-237	Q
	8305250407*	50-237	Q
	8305250407*	50-237	Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305250413*	50-237 Q
	8305250413*	50-237 Q
	8305250320*	50-206 P
	8305310143	50-329 A
Berlin, Roisman, Kessler & Cashdan	8305160080	50-529 Q
	8305160086	50-529 Q
Beveridge, Fairbanks & Diamond	8305200659	50-338 Q
Binder, Elster, Mendelson & Wheeler, Inc	8305040345*	CONTRACT
Borg-Warner Corp	8305130222	50-440 S
	8305130254	XPORTLIC
	8305130305	XPORTLIC
	8305240357*	GA999
	8305240363*	GA999
Boston Edison Co	8304110696	50-293 S
	8304110706*	50-293 S
	8304180590	50-293 P
	8305020134	50-293 R
	8305050250	50-293 Q
	8305090200	50-293 P
	8305100138	50-293 R
	8305100144*	50-293 R
	8305110334	50-293 S
	8305110341*	50-293 S
	8305110356	50-293 S
	8305110365*	50-293 S
	8305110384	50-293 S
	8305110392*	50-293 S
	8305130153	50-293 H
	8305160044	50-293 P
	8305160061	50-293 P
	8305160134	50-293 R
	8305160136*	50-293 R
	8305160145	50-293 S
	8305170173	50-293 F
	8305170345	50-293 P
	8305170418	50-293 P
	8305170529	50-293 R
	8305170532*	50-293 R
	8305190024	50-293 S
	8305190029*	50-293 S
	8305190147	50-293 P
	8305190176	50-293 S
	8305190181*	50-293 S
	8305190326	50-293 S
	8305190330*	50-293 S
	8305200259	50-293 P
	8305200447	50-293 P
	8305230434*	50-293 Q
	8305230450	50-293 F
	8305230509	50-293 S
	8305230515*	50-293 S
	8305230516	50-293 S
	8305230521*	50-293 S
	8305230533	50-293 S
	8305230535	50-293 R
	8305230537*	50-293 R
	8305230538*	50-293 S
	8305270073	50-293 Q
Botein, Hays, Sklar & Herzberg	8305020401	50-247 Q
Brigham Young Univ	8305160129	50-262 P
Brookhaven National Laboratory	8305020547	NUREG
	8305110126	50-312 P
	8305110127	NUREG
	8305110131	NUREG
	8305110227	NUREG
	8305110237	NUREG
	8305170086	50-537 A
	8305170101	NUREG
Brose & Poswistillo	8305090478	50-352 Q
Brown Boveri Corp (subs Brown Boveri & Co , Ltd.)	8305110324	50-269 S
	8305120437*	50-358 S
	8305200395	GA999
	8305200415*	GA999
	8305200422*	GA999
Brunswick Co	8305200457*	GA999
	8305200468*	GA999
	8305240347	50-247 Q
'oup	8305050034	TOPREP
	8305160298	XPORTLIC
	8305190332*	50-373 P
	8305190365*	50-373 P
	8305190387*	50-373 Q
	8305310211	WASTE MGT
	8305110212	50-275 Q
	8305110212	50-275 Q
	8305110217	50-275 Q
	8305110217	50-275 Q
	8305110383	50-275 Q
	8305110383	50-275 Q
	8305120093*	50-275 P
	8305260182	50-275 Q
	8305260183*	50-275 Q
	8305260183*	50-275 Q
California, Univ of, Los Angeles	8305030524	50-142 Q
	8305030568	50-142 Q
	8305030574	50-142 Q
	8305090473	50-142 Q
	8305160037*	50-142 Q
	8305170067*	50-142 Q
	8305240479	50-142 Q
	8305240499	50-142 Q
California, Univ of, San Diego	8305060239*	50-206 P
Callaway County, MO	8305250304*	50-483 Q
	8305250354*	50-483 Q
	8305250536*	50-483 Q
	8305250566*	50-483 Q
	8305250587*	50-483 Q
Cammer & Bhapiro	8305100256	50-322 Q
	8305100274	50-322 Q
Canadian Commercial Corp	8305230289*	CONTRACT
Carolina Environmental Study Group	8305060252	50-413 Q
Carolina Power & Light Co.	8305020124	50-400 E
	8305020124	50-400 E
	8305020165	50-400 R
	8305020165	50-400 R
	8305020172*	50-400 R
	8305020172*	50-400 R
	8305020453	50-261 P
	8305030288	50-324 P
	8305030291	50-324 S
	8305030293*	50-324 P
	8305030355	50-324 S
	8305030361*	50-324 S
	8305030387	50-324 S
	8305030387	50-324 S
	8305030411	50-324 S
	8305030419*	50-324 S
	8305030463	50-324 P
	8305030463	50-324 P
	8305030465	50-325 S
	8305030473*	50-325 S
	8305030481*	50-324 P
	8305030481*	50-324 P
	8305030497	50-324 S
	8305030497	50-324 S
	8305030505	50-325 S
	8305030512	50-324 S
	8305030530	50-324 S
	8305030536*	50-324 S
	8305030540	50-324 S
	8305030547*	50-324 S
	8305030599	50-261 S
	8305030601	50-400 S
	8305030612	50-324 S
	8305030618*	50-324 S
	8305040362	50-261 P
	8305040479	50-400 Q
	8305040479	50-400 Q
	8305040485*	50-400 Q
	8305040485*	50-400 Q
	8305040492*	50-400 Q
	8305040492*	50-400 Q
	8305040498*	50-400 Q
	8305040498*	50-400 Q
	8305050124	50-400 S
	8305050143	50-325 S
	8305050185	50-400 S
	8305050201	50-325 S
	8305050242	50-324 S
	8305050244*	50-324 S
	8305050249	50-261 S
	8305050259	50-400 S
	8305050265	50-324 S
	8305050267*	50-324 S
	8305060176	50-325 P
	8305060180*	50-325 P
	8305060471	50-400 Q
	8305060555	50-400 E
	8305060620	50-324 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305060620	50-324 G
	8305090380	50-324 P
	8305090380	50-324 P
	8305090456	50-324 P
	8305090456	50-324 P
	8305090470	50-261 G
	8305100362	50-325 P
	8305100412	50-324 R
	8305100412	50-324 R
	8305100417*	50-324 R
	8305110248	50-400 E
	8305110248	50-400 E
	8305110251	50-261 S
	8305110252	50-400 S
	8305110252	50-400 S
	8305110256*	50-261 S
	8305110282	50-325 S
	8305110284*	50-325 S
	8305110294	50-400 E
	8305110294	50-400 E
	8305120003	50-324 P
	8305120467	50-400 A
	8305120467	50-400 A
	8305130027	50-400 S
	8305130075	50-400 Q
	8305130075	50-400 Q
	8305130080	50-400 S
	8305130080	50-400 S
	8305130088	50-400 Q
	8305130088	50-400 Q
	8305130092	50-261 Q
	8305130108	50-325 S
	8305130162	50-261 Q
	8305130167	50-324 S
	8305130170	50-324 S
	8305130172*	50-324 S
	8305130176*	50-324 S
	8305130177	50-324 S
	8305130184*	50-324 S
	8305130216	50-400 S
	8305130216	50-400 S
	8305160017	50-400 E
	8305160017	50-400 E
	8305160021	50-400 E
	8305160021	50-400 E
	8305160045	50-261 J
	8305160109	50-400 E
	8305160109	50-400 E
	8305160135	50-324 J
	8305160135	50-324 J
	8305170282	50-400 A
	8305170282	50-400 A
	8305170285*	50-400 A
	8305170285*	50-400 A
	8305170450	50-400 Q
	8305170450	50-400 Q
	8305170497	50-400 Q
	8305180400	50-400 E
	8305180400	50-400 E
	8305200009	50-261 Q
	8305200329	50-400 E
	8305200329	50-400 E
	8305200384	50-400 E
	8305200384	50-400 E
	8305200435	50-261 P
	8305200442	50-400 E
	8305200442	50-400 E
	8305200538	50-324 S
	8305200543*	50-324 S
	8305200597	50-324 F
	8305200597	50-324 F
	8305200600	50-261 H
	8305200625	50-324 F
	8305200625	50-324 F
	8305200630	50-400 Q
	8305200630	50-400 Q
	8305200676	50-400 K
	8305200676	50-400 K
	8305200679*	50-400 K
	8305200679*	50-400 K
	8305230283	50-261 P
	8305230442	50-400 S
	8305240004	50-324 P
	8305240417	50-400 K
	8305240434	50-324 P
	8305240446	50-400 Q
	8305240446	50-400 Q
	8305240550	50-400 Q
	8305240550	50-400 Q
	8305240551	50-400 Q
	8305240551	50-400 Q
	8305250249	50-261 P
	8305250423	50-261 S
	8305250489	PR
	8305250493*	PR
	8305250494	50-400 E
	8305260022	50-261 P
	8305260234	50-400 E
	8305260320	50-324 P
	8305270009	50-261 P
	8305270023	50-400 E
	8305270256*	50-324 Q
	8305270281*	50-400 Q
	8305270281*	50-400 Q
	8305270383*	50-400 Q
	8305270487*	50-261 Q
	8305270531	50-324 Q
	8305270588*	50-324 Q
	8305270599*	50-324 Q
	8305270599*	50-324 Q
	8305270615*	50-400 Q
	8305270617*	50-324 Q
Center for Law in the Public Interest	8305120285	50-275 Q
Central Data Processing, Inc	8305160312*	50-247 Q
	8305160316*	50-247 Q
Chackes & Hoare	8305100257	50-483 Q
Charlevoix, MI	8305260180	50-155 Q
Charnoff, G.	8305110008*	CONTRACT
Chem-Nuclear Systems, Inc.	8305170733	71-5026
Christa-Maria	8305040542*	50-155 Q
	8305100290	50-155 Q
	8305190366	50-155 Q
	8305190371*	50-155 Q
	8305190375*	50-155 Q
Christy, W., Intervenor	8305180288	50-482 Q
Cincinnati Gas & Electric Co	8305030528	50-358 K
	8305030533*	50-358 K
	8305090486	50-358 E
	8305120342	50-358 S
	8305120410	50-358 S
	8305120429	50-358 S
	8305120432	50-358 S
	8305120446	50-358 S
	8305120487	50-358 S
	8305130111	50-358 K
	8305170454*	50-358 G
	8305170524	50-358 S
	8305170553*	50-358 A
	8305180458	50-358 F
	8305190168	50-358 A
	8305190190	50-358 A
	8305190228	50-358 S
	8305190273*	50-358 Q
	8305190278	50-358 A
	8305190281*	50-358 A
	8305190314*	50-358 A
	8305200536	50-358 S
	8305240012*	50-358 G
	8305240016*	50-358 G
	8305260227	50-358 S
	8305260337*	50-358 A
	8305260338*	50-358 A
Citizens Against Nuclear Power	8305040421*	50-400 Q
Citizens Association for Sound Energy	8212300009	50-445 Q
	8305020422	50-445 Q
	8305020422	50-445 Q
	8305020430*	50-445 Q
	8305020430*	50-445 Q
	8305020437*	50-445 Q
	8305040296	50-445 Q
	8305040296	50-445 Q
	8305040499	50-445 Q
	8305040499	50-445 Q
	8305040507	50-445 T
	8305040507	50-445 T
	8305040513	50-445 Q
	8305040513	50-445 Q
	8305040515*	50-445 T
	8305040515*	50-445 T
	8305040529	50-445 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305040529	50-445	G
	8305040535	50-445	T
	8305040535	50-445	T
	8305090443	50-445	G
	8305110137	50-445	G
	8305110137	50-445	G
	8305110157	50-445	T
	8305110157	50-445	T
	8305110332	50-445	G
	8305110332	50-445	G
	8305110347	50-445	G
	8305110347	50-445	G
	8305110354	50-445	T
	8305110354	50-445	T
	8305110357	50-445	G
	8305110368	50-445	G
	8305110368	50-445	G
	8305110397	50-445	G
	8305110397	50-445	G
	8305130066	50-445	G
	8305130066	50-445	G
	8305130157	50-445	T
	8305130157	50-445	T
	8305130175	50-445	G
	8305130175	50-445	G
	8305170287	50-445	G
	8305170287	50-445	G
	8305170513	50-445	G
	8305170513	50-445	G
	8305180272	PR	
	8305200504	50-445	G
Cleveland Electric Illuminating Co	8303280059	50-440	A
	8305020308	50-440	S
	8305020500	50-440	S
	8305040307	50-440	G
	8305040307	50-440	G
	8305040465	50-440	S
	8305040465	50-440	S
	8305040486	50-440	S
	8305040486	50-440	S
	8305040496	50-440	S
	8305040496	50-440	S
	8305040516*	50-440	T
	8305040516*	50-440	T
	8305090490*	50-440	G
	8305090493*	50-440	G
	8305100013	50-440	S
	8305100013	50-440	S
	8305100333	50-440	S
	8305100333	50-440	S
	8305100394	50-440	S
	8305110300	50-440	E
	8305130236	50-440	S
	8305130236	50-440	S
	8305130248	50-440	S
	8305130248	50-440	S
	8305170203	50-440	G
	8305230106	50-440	E
	8305230143	50-440	A
	8305230290	50-440	A
	8305240515	50-440	G
	8305240515	50-440	G
	8305250381	PR	
	8305260267	50-440	E
	8305260267	50-440	E
Cleveland-Cliffs Iron Co	8305160232	40-8714	
	8305260383	40-8714	
Coalition for Safe Power	8305100263	50-460	G
	8305170272	50-522	G
	8305240347	50-460	G
	8305310005	50-460	G
Colt Industries, Inc.	8305020133	50-483	S
Columbia River Inter-Tribal Fish Commission	8305170272	50-522	G
Columbia Univ	8305110236*	CONTRACT	
	8305180047*	50-247	P
Combustion Engineering, Inc	8305020400	50-470	E
	8305020406*	50-470	E
	8305090338	50-470	E
	8305090372*	50-470	E
	8305120120	50-470	B
	8305120124*	50-470	B
	8305120185	50-470	E
	8305120252*	50-336	P
	8305130081	50-470	E
	8305170326	50-470	A
	8305170527	50-335	B
	8305200072	TOPREP	
	8305200568	50-470	E
Commerce, Dept of, National Bureau of Standards	8305040596	MISC	
	8305090131*	CONTRACT	
Committee to Bridge the Gap	8305170067*	50-142	G
	8305170325	50-142	G
	8305200496	50-142	G
	8305200652	50-142	G
Commonwealth Edison Co	8304040268	50-237	G
	8304290034	50-373	P
	8304290034	50-373	P
	8305020086	50-373	B
	8305020090*	50-373	B
	8305020106*	50-10	G
	8305020109	50-373	B
	8305020114*	50-373	B
	8305020115*	50-456	G
	8305020142	50-254	B
	8305020154*	50-254	B
	8305020205	50-373	B
	8305020234*	50-456	G
	8305020236*	50-373	B
	8305020241	50-373	B
	8305020246	50-249	B
	8305020251*	50-373	B
	8305020256*	50-249	B
	8305020351	50-373	B
	8305020353*	50-373	B
	8305020458	50-254	P
	8305020458	50-254	P
	8305020470	50-440	G
	8305030084*	50-295	F
	8305030084*	50-295	F
	8305030091*	50-295	F
	8305030091*	50-295	F
	8305030114*	50-295	F
	8305030114*	50-295	F
	8305030117*	50-295	F
	8305030117*	50-295	F
	8305030161	50-373	P
	8305030270	50-454	B
	8305030274	50-322	B
	8305030321	50-254	B
	8305030333*	50-254	B
	8305030440	50-304	B
	8305030446*	50-304	B
	8305040074*	50-454	F
	8305040080*	50-454	F
	8305040080*	50-454	F
	8305040317	50-295	P
	8305040365	50-373	R
	8305040371*	50-373	R
	8305040446	50-237	P
	8305040446	50-237	P
	8305040456*	50-237	P
	8305040456*	50-237	P
	8305040520	50-237	P
	8305040520	50-237	P
	8305040524*	50-237	P
	8305040524*	50-237	P
	8305040551	50-237	P
	8305040551	50-237	P
	8305040551	50-237	P
	8305040551	50-237	P
	8305040551	50-237	P
	8305040555*	50-237	P
	8305040555*	50-237	P
	8305040555*	50-237	P
	8305040555*	50-237	P
	8305040555*	50-237	P
	8305050043	50-254	P
	8305050043	50-254	P
	8305060184	50-454	F
	8305060184	50-454	F
	8305060390	50-254	B
	8305060391*	50-254	B
	8305060398	50-373	B
	8305060401*	50-373	B
	8305060416	50-237	B
	8305060422*	50-237	B
	8305060443	50-295	B
	8305060444*	50-295	B

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305060486	50-237 S
	8305060492*	50-237 S
	8305060493	50-373 S
	8305060509*	50-373 S
	8305060511	50-237 S
	8305060517*	50-237 S
	8305060528	50-295 S
	8305060544*	50-295 S
	8305060554*	50-373 Q
	8305060554*	50-373 Q
	8305060559*	50-456 Q
	8305060563	50-249 S
	8305060567	50-295 S
	8305060569*	50-373 Q
	8305060571*	50-249 S
	8305060572*	50-295 S
	8305060581	50-249 S
	8305060590	50-237 S
	8305060594*	50-249 S
	8305060599*	50-237 S
	8305060603	50-237 S
	8305060611*	50-237 S
	8305060679*	50-295 F
	8305060686*	50-295 F
	8305090231	71-6346
	8305100018	50-374 S
	8305100092	50-237 Q
	8305100190*	50-10 Q
	8305100237	50-454 A
	8305100237	50-454 A
	8305100237	50-454 A
	8305100237	50-454 A
	8305100352	50-374 S
	8305110082	50-373 P
	8305110082	50-373 P
	8305110215	50-454 Q
	8305110447	50-373 R
	8305110452*	50-373 R
	8305120013	50-295 R
	8305120013	50-295 R
	8305120016*	50-295 R
	8305120016*	50-295 R
	8305120299	50-454 Q
	8305130001	50-456 A
	8305130001	50-456 A
	8305130038	50-237 P
	8305130038	50-237 P
	8305130038	50-237 P
	8305130051	50-454 A
	8305130051	50-454 A
	8305130051	50-454 A
	8305130051	50-454 A
	8305130135*	50-454 Q
	8305130144*	50-373 Q
	8305130155*	50-373 F
	8305130155*	50-373 F
	8305130196	50-304 B
	8305130197	50-237 R
	8305130202*	50-237 R
	8305130209	50-237 P
	8305130211*	50-304 B
	8305130212	50-254 B
	8305130220*	50-254 B
	8305160059	50-454 E
	8305160059	50-454 E
	8305160060	50-454 Q
	8305160060	50-454 Q
	8305170134	50-237 B
	8305170140*	50-237 B
	8305170159	50-237 B
	8305170163*	50-237 B
	8305170167	50-254 Q
	8305170167	50-254 Q
	8305170184*	50-254 Q
	8305170184*	50-254 Q
	8305170218	50-295 P
	8305170218	50-295 P
	8305170297	50-454 Q
	8305170297	50-454 Q
	8305170331*	50-374 Q
	8305170372	50-254 R
	8305170372	50-254 R
	8305170374	50-373 B
	8305170376*	50-254 R
	8305170376*	50-254 R
	8305170378*	50-373
	8305170383	50-373
	8305170388*	50-373
	8305170425*	50-373
	8305170565	50-454
	8305170565	50-454
	8305180376	50-237
	8305180376	50-237
	8305180376	50-237
	8305180376	50-237
	8305180385	50-454
	8305180385	50-454
	8305180397*	50-454
	8305180787	70-2973
	8305190084*	50-373
	8305190145*	50-373
	8305190353*	50-373
	8305200295	50-237
	8305200307*	50-237
	8305200351	50-295
	8305200522*	50-454
	8305200522*	50-454
	8305200540*	50-454
	8305200540*	50-454
	8305200621	50-373
	8305200621	50-373
	8305200621	50-373
	8305200621	50-373
	8305200621	50-373
	8305200647*	50-373
	8305200655*	50-373
	8305200665*	50-373
	8305200675*	50-373
	8305200681*	50-373
	8305230500	50-10
	8305230500	50-10
	8305230500	50-10
	8305230584	50-373
	8305230584	50-373
	8305240007	50-373
	8305240007	50-373
	8305240025	50-373
	8305240073	50-373
	8305240110	50-373
	8305240110	50-373
	8305240111	50-374
	8305240202	50-237
	8305240207	50-237
	8305240214	50-304
	8305240229	50-373
	8305240245	50-237
	8305240245	50-237
	8305240308*	50-373
	8305240308*	50-373
	8305240311	50-295
	8305240315*	50-373
	8305240315*	50-373
	8305240317	50-254
	8305240318	50-373
	8305240321	50-254
	8305240334	50-373
	8305240335	50-237
	8305240339	70-2973
	8305240354	50-373
	8305240366	50-249
	8305240381	50-373
	8305240425	50-373
	8305240473	50-295
	8305240473	50-295
	8305240494	50-237
	8305240506	50-295
	8305250077	50-295
	8305250077	50-295
	8305250377	50-237
	8305250377	50-237
	8305250377	50-237
	8305260282*	50-454
	8305260286	50-265
	8305260287	50-456
	8305260287	50-456
	8305260290	50-237
	8305260290	50-237
	8305270079	50-456
	8305270079	50-456
	8305270193*	50-456

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305270195	50-373	S
	8305270237	50-373	S
	8305270395	50-237	Q
	8305270395	50-237	Q
	8305270419	50-237	P
	8305270419	50-237	P
	8305270419	50-237	P
	8305270489*	50-454	Q
	8305270489*	50-454	Q
	8305270489*	50-454	Q
	8305310037	50-237	P
	8305310095	50-295	Q
	8305310117*	50-237	Q
	8305310142	50-254	S
	8305310149	50-237	S
	8305310152	50-265	S
	8305310158	50-237	S
	8305310160	50-304	S
	8305310165	50-237	S
	8305310182	50-237	S
Computech Engineering Services, Inc	8305020433*	50-206	P
Computer Systems Support Corp	8305180421*	CONTRACT	
	8305230293*	CONTRACT	
Connecticut Yankee Atomic Power Co	8304110686	50-213	Q
	8305020399*	50-213	Q
	8305050054	50-213	P
	8305050054	50-213	P
	8305050054	50-213	P
	8305050112	50-213	P
	8305060213	50-213	F
	8305090404	50-213	P
	8305090465	50-213	P
	8305090465	50-213	P
	8305090465	50-213	P
	8305100331	50-213	P
	8305100385	50-213	P
	8305110069	50-213	F
	8305110071*	50-213	F
	8305110574*	50-213	F
	8305160183	50-213	P
	8305160189*	50-213	P
	8305170213	50-213	F
	8305190305	50-213	Q
	8305200608	50-213	S
	8305200701*	50-213	S
	8305230616	50-213	P
	8305250310	50-213	P
	8305250565*	50-213	Q
	8305270224	50-213	Q
Conner & Wetterhahn	8305020441	50-352	Q
	8305030563	50-352	Q
	8305060478	50-352	Q
	8305240489	50-352	Q
Conover & Associates, Inc Insurance	8305120011	70-1621	
Conservation Council of North Carolina	8305060532	50-400	Q
	8305090475	50-400	Q
Consolidated Edison Co of New York, Inc	8305020428	50-247	Q
	8305030373	50-247	S
	8305030380*	50-247	S
	8305030400	50-247	S
	8305030407*	50-247	S
	8305030456	50-247	P
	8305030458*	50-247	P
	8305030531	50-247	Q
	8305030531	50-247	Q
	8305040242*	50-3	F
	8305040247*	50-3	F
	8305040247*	50-3	F
	8305040249*	50-3	F
	8305040249*	50-3	F
	8305040254*	50-3	F
	8305040505	50-247	Q
	8305040505	50-247	Q
	8305060461	50-599	Q
	8305090425	50-247	T
	8305090425	50-247	T
	8305100175	50-247	P
	8305100208	50-247	Q
	8305110302	50-3	R
	8305110309	50-3	R
		50-3	R
		50-3	R
		50-3	R
		50-3	R
		50-3	R

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305110310*	50-3	R
	8305110310*	50-3	R
	8305110393	50-247	S
	8305110403*	50-247	S
	8305130018	50-247	P
	8305130022*	50-247	P
	8305130024*	50-247	P
	8305130064	50-247	Q
	8305130071	50-247	Q
	8305160020	50-247	S
	8305160025*	50-247	S
	8305160075	50-247	S
	8305160079*	50-247	S
	8305240527	50-247	Q
	8305250483	50-247	S
Consumers Power Co	8305020079	50-255	F
	8305020083*	50-255	F
	8305020138	50-255	S
	8305020145*	50-255	S
	8305020173	50-255	S
	8305020179*	50-255	S
	8305020202	50-155	P
	8305020294	50-155	P
	8305020398	50-329	E
	8305030111	50-329	R
	8305030155	50-255	S
	8305030642	50-255	S
	8305040441	50-329	Q
	8305040441	50-329	Q
	8305040455	50-410	H
	8305040475	50-255	Q
	8305040509	50-329	Q
	8305040509	50-329	Q
	8305060388	50-255	S
	8305060393*	50-255	S
	8305060477	50-255	S
	8305060483	50-329	A
	8305060483	50-329	A
	8305060495	50-155	Q
	8305090052	50-329	R
	8305090052	50-329	R
	8305090060*	50-329	R
	8305090060*	50-329	R
	8305100076	50-255	R
	8305100085*	50-255	R
	8305100170	50-255	P
	8305100250	50-255	S
	8305100264	50-329	Q
	8305100264	50-329	Q
	8305100279	50-255	P
	8305100287*	50-255	P
	8305100291*	50-255	P
	8305100306	50-255	S
	8305100341	50-329	Q
	8305100378	50-255	S
	8305100384*	50-255	S
	8305100396	50-255	S
	8305100403*	50-255	S
	8305110305	50-329	E
	8305110305	50-329	E
	8305110396	50-255	R
	8305110402*	50-255	R
	8305120147	50-255	F
	8305120273	50-329	Q
	8305120273	50-329	Q
	8305130140	50-255	S
	8305130145*	50-255	S
	8305130182*	50-329	Q
	8305130185	50-155	Q
	8305130208	50-255	S
	8305130214*	50-255	S
	8305130215	50-155	Q
	8305130225	50-255	S
	8305130230*	50-255	S
	8305160090	50-255	P
	8305170131	50-329	A
	8305170131	50-329	A
	8305170283	50-329	S
	8305170283	50-329	S
	8305170300*	50-255	Q
	8305170373	50-329	R
	8305170391	50-329	S
	8305170391	50-329	S
	8305170397	50-329	A
	8305170397	50-329	A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305170404	50-155 F
	8305170409	50-329 S
	8305170409	50-329 S
	8305170410	50-155 P
	8305170422	50-329 A
	8305170422	50-329 A
	8305170440	50-329 S
	8305170440	50-329 S
	8305170467	50-329 A
	8305170467	50-329 A
	8305170489	50-329 S
	8305170489	50-329 S
	8305170539	50-329 A
	8305170539	50-329 A
	8305190065	50-329 A
	8305190065	50-329 A
	8305190196	50-155 P
	8305190280	50-329 A
	8305190284*	50-329 A
	8305190298	50-329 Q
	8305190298	50-329 Q
	8305190300*	50-329 Q
	8305190300*	50-329 Q
	8305190317	50-155 Q
	8305200218	PR
	8305200349	50-329 S
	8305200349	50-329 S
	8305200389	50-329 A
	8305200610	50-155 Q
	8305200680	50-329 S
	8305200680	50-329 S
	8305230044	50-155 Q
	8305230270	50-155 R
	8305240008*	50-329 Q
	8305240008*	50-329 Q
	8305240010	50-329 S
	8305240011	50-255 B
	8305240043	50-255 Q
	8305240137	50-329 K
	8305240137	50-329 K
	8305240280	50-155 J
	8305240290	50-255 J
	8305240322	50-329 Q
	8305240353	50-329 A
	8305240353	50-329 A
	8305240371*	50-255 Q
	8305240410	50-255 R
	8305240427	50-329 A
	8305240427	50-329 A
	8305240438	50-155 Q
	8305240491	50-329 Q
	8305240491	50-329 Q
	8305240505	50-155 P
	8305240505	50-155 P
	8305240565*	50-155 P
	8305260218	50-329 S
	8305260218	50-329 S
	8305260235	50-329 S
	8305260235	50-329 S
	8305260266*	50-155 Q
	8305260309	50-330 S
	8305260309	50-330 S
	8305260324	50-329 S
	8305260324	50-329 S
	8305270057	50-329 K
	8305270057	50-329 K
	8305270063*	50-329 K
	8305270063*	50-329 K
	8305270066*	50-329 K
	8305270547	50-329 Q
	8305270610*	50-324 Q
	8305310168	50-255 B
	8305310190	50-329 A
	8305310190	50-329 A
	8305310197	50-255 B
	8305310202	50-255 B
Continuum Dynamics, Inc.	8305130104*	50-271 P
Cornell Univ.	8305110476	NUREG
Cortland, NY	8305240554	50-247 T
Cotter Corp.	8305060319	WASTE MGT
	8305060325*	WASTE MGT
	8305260356	WASTE MGT
	8305260360	WASTE MGT
Creare, Inc	8305270105*	CONTRACT
Cygna Energy Services	8305030171	50-341 A
	8305030178*	50-341 A
	8305050004	50-341 A
	8305050010*	50-341 A
Dairyland Power Cooperative	8305020146	50-409 S
	8305020170*	50-409 S
	8305020182*	50-409 S
	8305100025	50-409 P
	8305110298	50-409 R
	8305120066	50-409 P
	8305130112*	50-409 Q
	8305130267*	50-409 Q
	8305130271*	50-409 Q
	8305160050	50-409 F
	8305230029	50-409 J
	8305230398	50-409 P
	8305240327	50-409 Q
	8305310169	50-409 F
Davisson, M T	8305160332*	50-367 A
DeKalb Area Alliance for Responsible Energy	8305030508	50-454 T
	8305030516*	50-454 T
	8305100286	50-454 Q
	8305170569*	50-454 Q
	8305170572*	50-454 Q
	8305170572*	50-454 Q
	8305170576*	50-454 Q
	8305170581*	50-454 Q
	8305170581*	50-454 Q
	8305170588*	50-454 Q
	8305170590*	50-454 Q
	8305170590*	50-454 Q
	8305170593*	50-454 Q
	8305170593*	50-454 Q
Debevoise & Liberman	8303290382	50-397 Q
	8305020473	50-460 Q
	8305040538	50-413 Q
	8305050009	50-460 Q
	8305050018	50-445 Q
	8305050019	50-460 Q
	8305060491	50-508 Q
	8305090507	50-445 T
	8305090511	50-413 Q
	8305100267	50-445 Q
	8305100267	50-445 Q
	8305100270	50-445 Q
	8305100270	50-445 Q
	8305100289*	50-413 Q
	8305100289*	50-413 Q
	8305100295	50-445 Q
	8305100295	50-445 Q
	8305100297*	50-413 Q
	8305100297*	50-413 Q
	8305100305*	50-413 Q
	8305100305*	50-413 Q
	8305100321	50-445 Q
	8305100321	50-445 Q
	8305130260	50-445 Q
	8305170516	50-460 Q
	8305180358	PR
	8305180449	PR
	8305240355	FOIA
	8305240465	50-460 Q
	8305240485	50-413 Q
	8305250406	PR
Decision Science Consortium, Inc	8305110528	NUREG
Del-Aware Unlimited, Inc	8305310013	50-352 Q
Detroit Edison Co.	8305020085	50-341 S
	8305020370	50-341 A
	8305030369	50-341 S
	8305030476	50-341 S
	8305030585	50-341 S
	8305030596	50-341 S
	8305090480	50-341 F
	8305100015	50-341 S
	8305100118	50-341 S
	8305100119	50-341 A
	8305100154	50-341 S
	8305100393*	50-341 Q
	8305100399*	50-341 Q
	8305170207	50-341 S
	8305170535	50-341 S
	8305170662	70-2926
	8305230552	50-341 A
Devience & O'Meara, Ltd	8305090285	50-566 A
Disc Corp.	8305030018	XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305030056*	XPORTLIC
Dougherty, J B	8305130072	50-322 Q
	8305180341	PR
Downers Grove Orthopedic Associates, Downers Grove, IL	8305030480	PR
Duke Power Co	8305020020	50-413 E
	8305020326	50-413 A
	8305020372	50-269 P
	8305020375*	50-269 P
	8305040229	50-369 S
	8305040229	50-369 S
	8305040240*	50-369 S
	8305040240*	50-369 S
	8305040246*	50-369 S
	8305040260*	50-369 S
	8305040273	50-369 S
	8305040273	50-369 S
	8305040469	50-370 P
	8305040538	50-413 Q
	8305040564	50-269 P
	8305040564	50-269 P
	8305040564	50-269 P
	8305040568*	50-269 P
	8305040568*	50-269 P
	8305040568*	50-269 P
	8305040597*	50-369 F
	8305040606*	50-369 F
	8305050008	50-413 A
	8305050014*	50-413 A
	8305050135	50-369 F
	8305050135	50-369 F
	8305050153	50-370 S
	8305050254	50-269 S
	8305050254	50-269 S
	8305050283	50-369 P
	8305060224	50-369 P
	8305060382	PR
	8305060403	50-369 S
	8305060403	50-369 S
	8305060413	50-369 P
	8305060413	50-369 P
	8305090435	50-287 P
	8305090468	50-413 Q
	8305090468	50-413 Q
	8305090472	50-369 S
	8305090472	50-369 S
	8305100002	50-369 S
	8305100003*	50-369 S
	8305100007	50-369 P
	8305100148	50-369 Q
	8305100148	50-369 Q
	8305100282	50-413 Q
	8305100282	50-413 Q
	8305100289*	50-413 Q
	8305100289*	50-413 Q
	8305100297*	50-413 Q
	8305100297*	50-413 Q
	8305100305*	50-413 Q
	8305100305*	50-413 Q
	8305100327	50-369 S
	8305100342	50-413 Q
	8305100342	50-413 Q
	8305100347	50-369 P
	8305100366	50-369 S
	8305100383	50-369 P
	8305100383	50-369 P
	8305100390*	50-369 P
	8305100390*	50-369 P
	8305100415	50-413 Q
	8305100415	50-413 Q
	8305110085	50-369 S
	8305110281	50-369 S
	8305110283*	50-369 S
	8305110323	50-270 S
	8305110335*	50-270 S
	8305130025	50-269 P
	8305130158	50-369 S
	8305130192	50-369 F
	8305130192	50-369 F
	8305160285*	50-369 F
	8305160286*	50-369 F
	8305160293*	50-413 F
	8305170258	50-370 S
	8305170269*	50-370 S
	8305170277	50-369 P
	8305170292	50-413 S
	8305170296	50-413 F
	8305170324	50-269 S
	8305170338*	50-269 S
	8305170355	50-369 S
	8305170358*	50-369 S
	8305170455	50-269 R
	8305170455	50-269 R
	8305170455	50-269 R
	8305170460*	50-269 R
	8305170460*	50-269 R
	8305170460*	50-269 R
	8305170507	50-369 S
	8305170536	50-369 R
	8305170536	50-369 R
	8305170540*	50-369 R
	8305170540*	50-369 R
	8305170561	50-269 S
	8305170566*	50-269 S
	8305190020	50-370 F
	8305190032	50-370 E
	8305200401	50-413 E
	8305200401	50-413 E
	8305200438	50-369 P
	8305200440*	50-369 P
	8305200440*	50-369 P
	8305200476	50-413 E
	8305200476	50-413 E
	8305200544	50-269 Q
	8305240259*	50-287 P
	8305240485	50-413 Q
	8305240485	50-413 Q
	8305250278	50-369 F
	8305250281	50-369 P
	8305250281	50-369 P
	8305250282	50-413 S
	8305250287	50-369 P
	8305250287	50-369 P
	8305250290	50-370 P
	8305250404	50-369 S
	8305250439	50-370 S
	8305250442	50-369 P
	8305250449	50-414 S
	8305250479	50-269 P
	8305250479	50-269 P
	8305250479	50-269 P
	8305250499	50-370 S
	8305250507	50-370 S
	8305250523	50-370 S
	8305250549	50-369 S
	8305250549	50-369 S
	8305250556	50-269 S
	8305250556	50-269 S
	8305250556	50-269 S
	8305260261	50-269 J
	8305260261	50-269 J
	8305260261	50-269 J
	8305260261	50-269 J
	8305260261	50-269 J
	8305270003	50-413 A
	8305270069	50-413 S
	8305270259	50-269 P
	8305270279*	50-269 P
	8305270294*	50-269 P
	8305270366*	50-369 Q
	8305310025	50-413 Q
	8305310025	50-413 Q
	8305310035	50-413 Q
	8305310035	50-413 Q
	8305310052	50-369 S
	8305310081	50-269 Q
	8305310081	50-269 Q
	8305310081	50-269 Q
	8305310200	50-413 E
	8305310200	50-413 E
Duquesne Light Co	8305020359	50-334 P
	8305020426	50-412 F
	8305030311	50-334 S
	8305030316*	50-334 S
	8305030593	50-334 R
	8305030595*	50-334 R
	8305060261	50-334 R
	8305060269*	50-334 R
	8305060604	50-334 P
	8305060609*	50-334 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305060614*	50-334	P
	8305100104	50-412	S
	8305100268	50-334	Q
	8305100337	50-334	P
	8305110295	50-412	S
	8305110343	50-334	S
	8305110353*	50-334	S
	8305110360	50-334	P
	8305110424	50-334	R
	8305120402	50-334	S
	8305120411*	50-334	S
	8305160058	50-334	S
	8305160064*	50-334	S
	8305180256	50-412	F
	8305180259*	50-412	F
	8305180283	50-412	K
	8305180287*	50-412	K
	8305180559	50-412	K
	8305180569*	50-412	K
	8305180576*	50-412	C
	8305180585*	50-412	K
	8305180592*	50-412	K
	8305180598*	50-412	K
	8305180606*	50-412	K
	8305180613*	50-412	K
	8305180625*	50-412	K
	8305180634*	50-412	K
	8305180641*	50-412	K
	8305180650*	50-412	K
	8305180655*	50-412	K
	8305180661*	50-412	K
	8305180666*	50-412	K
	8305180673*	50-412	K
	8305180681*	50-412	K
	8305180685*	50-412	K
	8305180693*	50-412	K
	8305180695*	50-412	K
	8305180697*	50-412	K
	8305180705*	50-412	K
	8305180708*	50-412	K
	8305180715*	50-412	K
	8305180720*	50-412	K
	8305180728*	50-412	K
	8305180735*	50-412	K
	8305180740*	50-412	K
	8305180746*	50-412	K
	8305180749*	50-412	K
	8305180755*	50-412	K
	8305180760*	50-412	K
	8305180764*	50-412	K
	8305180767*	50-412	K
	8305180769*	50-412	K
	8305190185	50-334	B
	8305190309*	50-334	B
	8305200429	50-412	B
	8305200439*	50-334	Q
	8305230387	50-334	P
	8305230520	50-334	B
	8305230527*	50-334	B
	8305240248	50-412	K
	8305240401	50-334	P
	8305240404	50-334	Q
	8305250498*	50-412	Q
	8305250516	50-334	P
	8305270187	50-334	P
	8305270190*	50-334	P
	8305270662*	50-412	Q
EDS Nuclear, Inc.	8305030564*	50-298	P
EG&G, Inc	8304220257*	50-321	P
	8305030474*	50-483	Q
	8305110467	NUREG	
	8305110482	NUREG	
	8305110518	NUREG	
	8305110523	NUREG	
ENSA, Inc	8305060347	NUREG	
	8305240015	NUREG	
Eason Diving & Marine Contractors, Inc	8305180466*	50-395	Q
Ebasco Services, Inc (subs of Enserch Corp.)	8305060440*	50-286	P
Ecological Analysts, Inc	8304110519*	50-220	R
Eddleman, H	8305060485	50-400	Q
	8305110145	50-400	Q
	8305110145	50-400	Q
	8305110222	50-400	Q
	8305110222	50-400	Q
	8305110361	50-400	Q
	8305110361	50-400	Q
	8305110366	50-400	Q
	8305110366	50-400	Q
	8305120288	50-400	Q
	8305170528	50-400	Q
Edelstein & Payne	8305240500	50-400	Q
	8305240500	50-400	Q
	8305240507	50-400	Q
	8305240507	50-400	Q
Edison Electric Institute	8305180358	PR	
	8305250420	PR	
Electric Power Research Institute	8305110196	NUREG	
Energy Consultants, Inc	8305250394*	50-483	Q
	8305250496*	50-483	Q
	8305250511*	50-483	Q
	8305250589*	50-483	Q
Energy Fuels Nuclear, Inc	8305020481	40-8681	
	8305020484*	40-8681	
Energy Incorporated	8303310020*	50-333	P
	8305200637*	50-373	P
	8305200691*	50-373	P
Energy, Dept of	8303240390	50-537	Q
	8305020036	71-9510	
	8305030688	50-201	P
	8305060524	50-537	E
	8305090578*	50-445	Q
	8305110138	WASTE MGT	
	8305110142	WASTE MGT	
	8305110220	50-537	Q
	8305110438	50-537	Q
	8305110448	50-537	Q
	8305110449*	50-537	Q
	8305180210	71-6639	
	8305180670	71-6272	
	8305180676*	71-6272	
	8305180684	71-9150	
	8305190339	50-537	Q
	8305200636	50-537	Q
	8305200648*	50-537	Q
	8305230080	71-5607	
	8305240064	71-6553	
	8305240475	50-537	Q
	8305240480	50-537	Q
	8305240503	50-537	Q
	8305260003	71-5552	
	8305310003*	50-537	A
	8305310188	50-537	Q
Energy, Dept of, Clinch River Breeder Reactor Plant	8305170449	50-537	A
	8305200459	50-537	B
	8305200463*	50-537	B
	8305230113	50-537	A
	8305230283	50-537	A
	8305230292*	50-537	A
Energy, Dept of, Idaho Operations Ofc	8305230015	50-201	P
	8305240614	50-201	P
Epler, E P	8305090255*	50-272	B
European Communities, Commission of	8305020005	XPORTLIC	
	8305020096	XPORTLIC	
Exeter, NH	8305020482	50-443	Q
	8305020482	50-443	Q
	8305020486*	50-443	Q
	8305020486*	50-443	Q
Exxon Corp	8305030719	40-8064	
	8305260145	40-8064	
Exxon Nuclear Co , Inc (subs of Exxon Corp)	8305030292	TOPREP	
	8305090010	XPORTLIC	
	8305100178	70-1257	
	8305100184	70-1257	
	8305170584	XPORTLIC	
	8305170616	XPORTLIC	
	8305170621*	XPORTLIC	
	8305180067	XPORTLIC	
	8305180073*	XPORTLIC	
	8305180642	70-1257	
	8305180648*	70-1257	
	8305180833	XPORTLIC	
	8305240310	TOPREP	
	8305260018	XPORTLIC	
	8305260064	XPORTLIC	
FOI Services	8305120573	FOIA	
Fansteel Metals (subs of Fansteel, Inc.)	8305160004	40-7580	
Fansteel, Inc	8305160258	40-7580	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305160261*	40-7580	
Federal American Partners	8305200037*	40-4492	
Federal Emergency Management Agency	8305020419	50-247	Q
	8305060506	50-247	Q
	8305060629*	50-247	Q
	8305090592*	50-445	Q
	8305100122	50-295	F
	8305100126*	50-295	F
	8305100131*	50-295	F
	8305100136*	50-295	F
	8305100143	50-289	F
	8305120426*	50-309	F
	8305120427*	50-309	F
	8305200465*	50-315	F
	8305230474	COMMISSION	
	8305230479*	COMMISSION	
	8305230670	50-3	F
	8305310049	50-247	F
Ferguson, Inc	8305200637*	50-373	P
Finland	8305240015	NUREG	
Fleischaker, D S	8305060451	50-275	Q
	8305090438	50-275	Q
	8305200272*	50-275	P
Florida Power & Light Co	8305020084	50-335	Q
	8305020168	50-335	P
	8305020345	50-335	P
	8305020519	50-335	P
	8305030168	50-251	R
	8305030173*	50-251	R
	8305030240*	50-389	F
	8305030244*	50-389	F
	8305030306	50-389	S
	8305030340	50-335	Q
	8305030341	50-335	R
	8305030341	50-335	R
	8305030392	50-250	Q
	8305030392	50-250	Q
	8305030461	PR	
	8305030604	50-389	S
	8305040563	50-335	F
	8305040566*	50-335	F
	8305050127	50-335	S
	8305050138*	50-335	S
	8305090432	50-250	P
	8305090476	50-335	P
	8305100001	50-250	Q
	8305100088	50-389	S
	8305100103	50-335	P
	8305100165	50-250	P
	8305100182	50-335	J
	8305100227	50-389	S
	8305100236	50-335	P
	8305100251	50-251	S
	8305100253*	50-251	S
	8305100269	50-389	S
	8305110487	50-250	S
	8305110496*	50-250	S
	8305130008	50-250	F
	8305130118	50-389	P
	8305130121	50-335	P
	8305160010	50-251	P
	8305160282*	50-389	F
	8305160284*	50-389	F
	8305170191	50-389	S
	8305170197*	50-389	S
	8305170244	50-335	S
	8305170250*	50-335	S
	8305170310	50-389	S
	8305170356	50-389	F
	8305170463	50-335	P
	8305170520	50-250	P
	8305170520	50-250	P
	8305170525*	50-250	P
	8305170525*	50-250	P
	8305170546	50-250	F
	8305200181	50-389	S
	8305200346	50-335	F
	8305200346	50-335	F
	8305200489	50-335	F
	8305230016	71-5957	
	8305230532	50-335	P
	8305240372	50-335	P
	8305250272	50-335	P
	8305250302	50-335	S
	8305250395	50-335	P
	8305250397	50-335	P
	8305250415	PR	
	8305250416	50-389	S
	8305250455	50-389	P
	8305250462	50-335	P
	8305250472	50-250	P
	8305250472	50-250	P
	8305250481	50-335	P
	8305250484*	50-335	P
	8305250491*	50-250	P
	8305250519	50-250	P
	8305250519	50-250	P
	8305270104	50-389	P
	8305270125	50-389	P
	8305270129	50-250	Q
	8305270153	50-389	P
	8305270168	50-335	P
	8305270170	50-335	P
	8305270251	50-389	P
	8305270360*	50-389	Q
	8305270520*	50-389	Q
	8305270572*	50-335	Q
	8305310034	50-250	P
	8305310184	50-389	P
Florida Power Corp	8305030036	50-302	P
	8305030050	50-302	P
	8305050016	50-302	S
	8305050025*	50-302	S
	8305090462	50-302	P
	8305100278*	50-389	S
	8305110380	50-302	S
	8305110390*	50-302	S
	8305130002	50-302	P
	8305130012	50-302	P
	8305130043	50-302	R
	8305130047*	50-302	R
	8305130067	50-302	P
	8305130179	50-302	S
	8305130188*	50-302	S
	8305170399	50-302	S
	8305170402*	50-302	S
	8305190344	50-302	P
	8305200378	50-302	P
	8305230393	50-302	P
	8305240359	50-302	P
	8305270092	50-302	P
	8305270253*	50-302	Q
	8305270258*	50-302	Q
	8305270295	50-302	Q
	8305270312*	50-302	Q
	8305270318*	50-302	Q
	8305270503*	50-302	Q
Fracture Proof Design Corp	8305030412*	50-286	P
	8305060407*	50-286	P
	8305060417*	50-286	P
	8305200412*	50-286	P
Franklin Institute/Franklin Research Center	8206300177*	50-309	P
	8208060249*	50-338	P
	8209210332*	50-336	P
	8304070286*	50-269	P
	8305110545*	CONTRACT	
	8305170106*	50-272	S
	8305190322*	50-387	S
	8305200720*	50-338	P
	8305230284*	50-213	P
	8305310241*	50-285	P
Friends of the Earth	8305160024	50-247	Q
	8305160024	50-247	Q
	8305160028*	50-247	Q
	8305160028*	50-247	Q
Fulton, MO	8305250304*	50-483	Q
	8305250354*	50-483	Q
	8305250536*	50-483	Q
Future Coatings, Inc.	8305180183	40-8035	
Future Resources Associates, Inc	8305180353	PR	
GA Technologies, Inc./General Atomic Co	8305020435	50-358	A
	8305040395	XPORTLIC	
	8305060690	XPORTLIC	
	8305180839*	XPORTLIC	
Gasconade County, MO	8305250363*	50-483	Q
	8305250573*	50-483	Q
General Electric Co.	8303240338	50-447	A
	8305020050	70-1007	
	8305020355	50-447	E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305020365*	QA999
	8305020369*	QA999
	8305020520	70-754
	8305030403	50-447 A
	8305040433	TOPREP
	8305040458	TOPREP
	8305040466*	TOPREP
	8305040558	XPORTLIC
	8305040561*	XPORTLIC
	8305040567*	XPORTLIC
	8305050168	70-1113
	8305050426	NUREG
	8305060076*	50-331 P
	8305060160*	FOIA
	8305060171*	FOIA
	8305090483	TOPREP
	8305090495*	TOPREP
	8305090497*	TOPREP
	8305100298	50-447 E
	8305100370*	50-325 P
	8305110196	NUREG
	8305170578	XPORTLIC
	8305170693*	CONTRACT
	8305180617	XPORTLIC
	8305180713	XPORTLIC
	8305200157	50-447 A
	8305200552	TOPREP
	8305240034	70-1301
	8305260037	50-447 E
	8305260048*	50-447 E
	8305260075	XPORTLIC
	8305260325*	50-324 P
	8305270378*	50-333 P
	8305310115*	70-1113
General Physics Corp	8305110491	NUREG
General Public Utilities - GPU Service Corp	8305020210	50-289 R
	8305020232*	50-289 Q
	8305020362	50-219 P
	8305020465*	50-219 I
	8305030095	50-289 S
	8305030102	50-289 S
	8305030112*	50-289 S
	8305030127*	50-289 S
	8305030365	50-219 F
	8305030436	50-289 S
	8305030441	50-219 S
	8305030447*	50-219 S
	8305030462	50-320 R
	8305030470*	50-320 R
	8305030478*	50-320 R
	8305030484*	50-320 R
	8305030527	50-320 S
	8305030535*	50-320 S
	8305030695*	50-289 F
	8305040580*	50-320 F
	8305050022	50-219 F
	8305050304*	50-289 F
	8305050307*	50-289 F
	8305050381*	50-320 F
	8305060082	50-320 F
	8305060394	50-289 P
	8305060458	50-289 R
	8305060459	50-289 R
	8305060460*	50-289 R
	8305060464*	50-289 R
	8305060649	50-289 R
	8305060649	50-289 R
	8305090351	50-289 P
	8305090453	50-289 P
	8305110286	50-289 S
	8305110287*	50-289 S
	8305110321	50-320 S
	8305110326*	50-320 S
	8305110333	50-289 S
	8305110342*	50-289 S
	8305110346	50-289 S
	8305110351*	50-289 S
	8305110370	50-320 S
	8305110374	50-219 P
	8305110378*	50-320 S
	8305120015	50-320 H
	8305120055	50-289 P
	8305120064*	50-289 P
	8305120064*	50-289 P
	8305120068*	50-289 P
	8305120312	50-320 T
	8305120317*	50-320 T
	8305120323*	50-320 T
	8305120326*	50-320 T
	8305120335*	50-320 T
	8305120338*	50-320 T
	8305120341*	50-320 T
	8305120350*	50-320 T
	8305120357*	50-320 T
	8305130065	50-289 P
	8305130070*	50-289 P
	8305130074*	50-289 P
	8305130180	50-289 F
	8305160023*	50-219 Q
	8305170435	50-320 P
	8305170448	50-320 P
	8305170558	50-219 P
	8305190158	50-289 P
	8305190240	50-289 R
	8305190247*	50-289 R
	8305200173	50-289 P
	8305200179*	50-289 P
	8305200500	50-219 Q
	8305200502	50-289 P
	8305200547	50-289 S
	8305200551*	50-289 S
	8305200563	50-320 F
	8305230037	50-219 J
	8305230402	50-219 P
	8305230436	50-219 R
	8305230437*	50-219 R
	8305240348	50-320 R
	8305240536	50-219 Q
	8305240536	50-219 Q
	8305240536	50-219 Q
	8305250208*	50-289 Q
	8305250255	50-320 P
	8305250263*	50-320 P
	8305250269	50-289 P
	8305250271*	50-289 P
	8305250385	50-320 R
	8305260085	50-289 Q
	8305260074	50-289 P
	8305270092	50-219 P
	8305270203	50-289 R
	8305310001	50-320 S
	8305310004*	50-320 S
	8305310007*	50-320 S
	8305310010*	50-320 S
	8305310014*	50-320 S
	8305310019*	50-320 S
	8305310024*	50-320 S
	8305310030*	50-320 S
	8305310036*	50-320 S
	8305310041*	50-320 S
	8305310047*	50-320 S
	8305310056*	50-320 S
	8305310058	50-320 P
	8305310061*	50-320 S
	8305310066*	50-320 S
	8305310072*	50-320 S
	8305310078*	50-320 S
	8305310080*	50-320 S
	8305310087*	50-320 S
	8305310091*	50-320 S
	8305310096*	50-320 S
	8305310101*	50-320 S
	8305310103*	50-320 P
	8305310107*	50-320 S
	8305310114*	50-320 S
	8305310118	50-320 P
	8305310156	50-320 P
	8305310205	50-289 P
George Washington Univ	8305040553*	CONTRACT
Georgia Power Co.	8305030261	50-321 H
	8305030261	50-321 H
	8305030261	50-321 H
	8305030634	50-321 P
	8305030634	50-321 P
	8305030665*	50-321 P
	8305030665*	50-321 P
	8305030687*	50-321 F
	8305030690*	50-321 F
	8305040654*	50-321 F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305040659*	50-321	F
	8305050030	50-321	S
	8305050040*	50-321	S
	8305050083	50-321	S
	8305050086	50-424	A
	8305050087*	50-321	S
	8305060051	50-321	P
	8305060254	PR	
	8305060306	50-321	P
	8305060306	50-321	P
	8305060469	50-321	F
	8305060469	50-321	F
	8305100161	50-424	S
	8305110269	50-321	S
	8305110270	50-321	S
	8305110272*	50-321	S
	8305110273*	50-321	S
	8305110289	50-321	S
	8305110293*	50-321	S
	8305110364	50-321	S
	8305110364	50-321	S
	8305110375	50-366	S
	8305110389*	50-366	S
	8305110404	50-321	S
	8305110410	50-366	S
	8305110412*	50-321	S
	8305110417*	50-366	S
	8305110429	50-366	S
	8305110431	50-321	S
	8305110434*	50-321	S
	8305110436*	50-366	S
	8305130235	50-366	S
	8305130242*	50-366	S
	8305160144	50-321	G
	8305160144	50-321	G
	8305160159	50-366	P
	8305170178	50-321	S
	8305170254	50-321	S
	8305170262*	50-321	S
	8305170276	50-366	S
	8305170284*	50-366	S
	8305170389	50-366	S
	8305170394*	50-366	S
	8305170434	50-321	S
	8305170438*	50-321	S
	8305170442	50-321	S
	8305170445*	50-321	S
	8305170481	50-366	S
	8305170499*	50-366	S
	8305170502	50-366	S
	8305170506*	50-366	S
	8305180279	50-321	R
	8305180279	50-321	R
	8305180284*	50-321	R
	8305180284*	50-321	R
	8305200453	50-321	P
	8305200453	50-321	P
	8305230463	50-366	S
	8305230468*	50-366	S
	8305230486	50-366	S
	8305230490*	50-366	S
	8305230495	50-366	S
	8305230498*	50-366	S
	8305230568	50-321	S
	8305230577*	50-321	S
	8305240250	50-366	P
	8305250452	50-424	S
	8305250530	50-321	F
	8305250530	50-321	F
	8305260298	50-366	P
	8305270123	50-366	S
	8305270128	50-321	G
	8305270128	50-321	G
	8305270234	50-321	S
	8305270336*	50-321	G
	8305270508*	50-366	G
	8305310073	50-366	G
	8305310084*	50-366	G
	8305310092*	50-366	G
	8305310124	50-366	S
	8305310166	50-321	S
	8305310180	50-321	S
	8305310206	50-366	S
Geotechnical Engineers, Inc	8305060384*	50-329	A
Getty Oil Co (Petrotomics)	8305020439	40-6659	
	8305020443*	40-6659	
Gilbert/Commonwealth Cos	8305060277*	50-244	P
	8305110313	50-395	S
	8305110322	50-395	S
	8305120355*	50-320	T
	8305190201*	50-155	P
Golder Associates	8305050404*	CONTRACT	
Good Samaritan Hosp Downers Grove, IL	8305180436	PR	
Government Accountability Project	8305190097*	50-329	G
	8305190124*	50-373	G
	8305190216	50-329	G
	8305190292*	50-373	G
	8305190304*	50-373	G
	8305260166	50-329	G
Greater New York Council on Energy	8305250223	50-247	G
Guild, R	8305060252	50-413	G
Gulf Nuclear, Inc	8305240031	71-9163	
Gulf States Utilities Co	8305030422	50-458	S
	8305060435	50-458	S
	8305060475	50-458	S
	8305100198	50-458	A
	8305100198	50-458	A
	8305120321	50-458	S
	8305120343	50-458	G
	8305120367	50-458	S
	8305120409	50-458	S
	8305120413	50-458	S
	8305120424	50-458	S
	8305170281	50-458	S
	8305170385	50-458	S
	8305170468	50-458	K
	8305170468	50-458	K
	8305170473*	50-458	K
	8305170479	50-458	S
	8305200151	50-458	S
	8305200264	50-458	S
	8305200390	50-458	S
	8305230009*	50-458	F
	8305230438	50-458	S
	8305230462	50-458	S
	8305240469	50-458	S
	8305260268	50-458	S
	8305260299	50-458	S
	8305260318	50-458	S
	8305310042	50-458	S
	8305310102	50-458	I
HMM Associates, Inc	8305090614*	50-443	F
HPT, Inc	8305060675	NUREG	
Hampton, NH	8305180448*	50-322	H
	8305190346	50-443	G
Hardy Associates, Inc	8305230104	71-9135	
Harmon & Weiss	8305030502	50-537	G
	8305030541	50-443	G
	8305040449	50-329	G
	8305060382	PR	
	8305060573	PR	
	8305100204	50-247	G
	8305160002	50-443	G
	8305160002	50-443	G
	8305160019	50-443	G
	8305160019	50-443	G
	8305160073	50-289	G
	8305160149	50-537	G
	8305160181	50-537	G
	8305180363	PR	
	8305190221	50-537	G
	8305200470	PR	
	8305240538	50-247	G
	8305240538	50-247	G
	8305240542*	50-247	G
	8305240542*	50-247	G
	8305240553	50-537	G
Hartford Insurance Group	8305270539	50-358	J
Hartsville Group	8305180299	50-261	G
	8305180452	50-261	G
Hazleton Laboratories America, Inc	8305030592*	50-461	R
Hittman Corp	8305230730	71-9151	
Hittman Nuclear & Development Corp (subs Hittman Corp.)	8305040159*	71-9079	
	8305040176*	71-9079	
	8305260355*	71-9151	
	8305260373*	71-9151	
Holloran & Associates	8305240144	TOPREP	
	8305240154*	TOPREP	
House of Rep	8305130087	50-443	G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305170457	50-440 Q
	8305240355	50-247 T
	8305240358*	50-247 T
House of Rep , Energy & Commerce	8305230703	50-289 U
House of Rep , Government Operations	8305230695*	COMMISSION
House of Rep , Interior & Insular Affairs	8305040145*	50-289 U
	8305230369*	COMMISSION
	8305230388*	50-289 U
	8305230735*	COMMISSION
	8305240272*	50-358 Q
	8305240275*	50-358 Q
House of Rep , Science & Technology	8305230664*	COMMISSION
	8305240023*	50-537 U
Houston Lighting & Power Co	8305030430	PR
	8305060456	50-498 S
	8305110225	50-498 Q
	8305170510	50-498 S
	8305180358	PR
	8305230416	50-498 S
	8305230416	50-498 S
	8305230525	50-498 S
	8305230525	50-498 S
	8305250056	50-498 K
	8305250056	50-498 K
	8305250058*	50-498 K
	8305250058*	50-498 K
	8305310177	50-498 A
Howard Univ	8305230311*	CONTRACT
Hunton & Williams	8305030555	50-338 Q
	8305030557	50-322 Q
	8305030560	50-322 Q
	8305040461	50-322 Q
	8305050024	50-322 T
	8305050029*	50-322 T
	8305100391	50-322 Q
	8305130077	50-322 Q
	8305160006	50-322 Q
	8305170208	50-322 Q
	8305170378	50-322 Q
	8305170382*	50-322 Q
	8305310040	50-322 Q
	8305310051	50-322 Q
Hydrogen Control Owners Group, BWR-6 Mark III	8305130126	50-416 P
IRT Corp	8305230026	70-1359
	8305230035*	70-1359
Ichthyological Associates, Inc	8305020215*	50-289 R
	8305060465*	50-289 R
Illinois Power Co	8303240346	50-461 A
	8304050243	50-461 K
	8304050254*	50-461 K
	8305020111	50-461 Q
	8305030559	50-461 R
	8305040298	50-461 S
	8305060576	50-461 Q
	8305120475	50-461 S
	8305130146	50-461 E
	8305200667	50-461 A
	8305240142	50-461 A
	8305240413*	50-461 A
	8305240421*	50-461 A
	8305260247*	50-461 A
	8305260253*	50-461 A
	8305270017	50-461 A
	8305310129	50-461 B
	8305310183	50-461 B
Illinois, State of	8305180334	PR
	8305190151*	50-373 Q
	8305190167*	50-373 Q
	8305190379*	50-373 P
Indiana & Michigan Electric Co	8303280126	50-315 S
	8303280136*	50-315 S
	8305020072	50-316 S
	8305020078*	50-316 S
	8305020141	50-315 S
	8305020151*	50-315 S
	8305020161	50-316 S
	8305020171*	50-316 S
	8305020177*	50-316 S
	8305020192	50-316 S
	8305020198*	50-316 S
	8305020299	50-315 S
	8305020312*	50-315 S
	8305020317	50-315 S
	8305020321*	50-315 S
	8305020440	50-315 S
	8305040265*	50-315 F
	8305040265*	50-315 F
	8305040268*	50-315 F
	8305040268*	50-315 F
	8305060400	50-315 S
	8305060406*	50-315 S
	8305060411*	50-315 S
	8305060414*	50-315 S
	8305090363	50-315 R
	8305090363	50-315 R
	8305120318	50-316 S
	8305120324*	50-316 S
	8305120396	50-315 S
	8305120399*	50-315 S
	8305130097	50-315 S
	8305130101*	50-315 S
	8305130166	50-316 S
	8305130174*	50-316 S
	8305130178	50-315 S
	8305130191*	50-315 S
	8305130206	50-315 S
	8305160054	50-315 R
	8305160054	50-315 R
	8305160062*	50-315 R
	8305160062*	50-315 R
	8305160104	50-315 P
	8305160108*	50-315 P
	8305160121	50-315 P
	8305160121	50-315 P
	8305160126*	50-315 P
	8305160126*	50-315 P
	8305170270	50-315 F
	8305170270	50-315 F
	8305170274*	50-315 F
	8305170441	50-315 S
	8305170444*	50-315 S
	8305170446	50-316 S
	8305170451*	50-316 S
	8305240086*	50-315 Q
	8305240145	50-316 S
	8305240329	50-315 S
	8305240330	50-315 S
	8305240345	50-315 S
	8305240362	50-315 S
	8305240370*	50-315 S
	8305240374*	50-315 S
	8305260281	50-315 P
	8305260281	50-315 P
	8305270087	50-315 S
	8305270107	50-315 S
	8305270223	50-316 S
	8305270227*	50-316 S
	8305270230*	50-316 S
	8305270444	50-315 S
	8305310088	50-315 P
	8305310179	50-316 S
Institute of Electrical & Electronic Engineers	8305110119	NUREG
Institute of Nuclear Power Operations	8305240476*	50-219 R
	8305240519*	50-244 R
	8305250517	PR
Instituto di Ingegneria Nucleare, Milan, Italy	8305040399	NUREG
Interior, Dept of, Geological Survey	8305180334	PR
	8305190514*	CONTRACT
	8305230031*	CONTRACT
International Brotherhood of Electrical Workers	8305240517	50-247 H
Iowa Electric Light & Power Co	8305030131	50-331 Q
	8305030394	50-331 S
	8305030396*	50-331 S
	8305040389	50-331 Q
	8305060060	50-331 P
	8305060066*	50-331 P
	8305060472	50-331 S
	8305100095	50-331 P
	8305100320	50-331 Q
	8305100372*	50-331 Q
	8305130094	50-331 S
	8305180346	50-331 R
	8305180349*	50-331 R
	8305230562	50-331 P
	8305240120	50-331 P
	8305240221	50-331 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305240236	50-331	S
	8305240511	50-331	Q
	8305270429	50-331	S
	8305270440	50-331	S
	8305270451*	50-331	S
	8305270460*	50-331	S
Iowa Geological Survey	8305090162	NUREG	
Isham, Lincoln & Beale	8305060461	50-599	Q
	8305060495	50-155	Q
	8305100264	50-329	Q
	8305100264	50-329	Q
	8305100341	50-329	Q
	8305100418	50-329	Q
	8305100418	50-329	Q
	8305110141	50-155	Q
	8305110215	50-454	Q
	8305120273	50-329	Q
	8305120299	50-454	Q
	8305130185	50-155	Q
	8305170297	50-454	Q
	8305170297	50-454	Q
	8305170565	50-454	Q
	8305170565	50-454	Q
	8305200610	50-155	Q
	8305240373	50-329	Q
	8305240438	50-155	Q
	8305240491	50-329	Q
	8305270547	50-329	Q
Isomedix, Inc (subs of Masefield Enterprises, Inc)	8305020268*	QA999	
Japan	8305170375	XPORTLIC	
	8305170580	XPORTLIC	
	8305170582	XPORTLIC	
	8305180629	XPORTLIC	
	8305180819	XPORTLIC	
	8305180826	XPORTLIC	
Jersey Central Power & Light Co	8305130308*	50-272	F
	8305130308*	50-272	F
	8305130309*	50-272	F
	8305130309*	50-272	F
Joint Applicants-Clinch River Breeder Reactor	8305030542	50-537	Q
Joint Applicants-Palo Verde	8305030594	50-529	Q
Joint Applicants-South Texas Project	8305020434	50-498	Q
	8305060499	50-498	Q
Joint Intervenors-Diablo Canyon	8305090438	50-275	Q
	8305110212	50-275	Q
	8305110212	50-275	Q
	8305110383	50-275	Q
	8305110383	50-275	Q
	8305120285	50-275	Q
	8305200273*	50-275	P
KMC, Inc	8305180308	FOIA	
Kansas City Power & Light	8305230572*	50-482	I
Kansas Gas & Electric Co	8305020421	50-482	F
	8305030354	50-482	S
	8305030378	50-482	S
	8305030492	50-482	S
	8305030622*	50-482	Q
	8305060346*	50-482	F
	8305060354*	50-482	F
	8305060498	50-482	Q
	8305120391	50-482	Q
	8305200335	50-482	S
	8305230489*	50-482	Q
	8305230567	50-482	I
	8305230570*	50-482	I
	8305240313	50-482	Q
	8305270058	50-482	A
	8305310110*	50-482	Q
	8305310148	50-482	S
Kansas, State of	8305090162	NUREG	
Kansas, Univ of	8305200196*	50-148	Q
Kaufmann, J E	8305130361*	CONTRACT	
Kerr-McGee Nuclear Corp	8305200052	40-8027	
	8305230196*	70-1193	
		'78	
		8	
			Q
			Q
			)
	8305120297	50-322	Q
	8305120300*	50-322	Q
	8305120329	50-322	Q
	8305130069	50-322	Q
	8305180341	PR	
	8305240548	50-322	Q
	8305310063	50-322	Q
Kudzu Alliance	8305240500	50-400	Q
	8305240500	50-400	Q
	8305240507	50-400	Q
	8305240507	50-400	Q
Labat-Anderson, Inc	8305200134*	CONTRACT	
Labor, Dept of	8305060145*	FOIA	
	8305060220*	40-672	
Labor, Dept of, Occupational Safety & Health Admin	8305120474*	FOIA	
Lawler, Matusky & Skelly Engineers	8305230587*	50-410	A
	8305230650*	50-410	A
	8305230650*	50-410	A
	8305230656*	50-410	A
	8305230656*	50-410	A
	8305230661*	50-410	A
	8305230666*	50-410	A
	8305230666*	50-410	A
	8305230678*	50-410	A
	8305230678*	50-410	A
Lawrence Berkeley Laboratory	8305240552	71-6550	
Lawrence Livermore Laboratory	8209020602*	50-335	P
	8303310020*	50-333	P
	8304060471*	50-335	P
	8305130355	50-537	D
LeBoeuf, Lamb, Leiby & MacRae	8305090480	50-341	F
	8305130073	50-546	Q
	8305130073	50-546	Q
	8305130098	50-546	Q
	8305130098	50-546	Q
	8305130244	50-546	Q
	8305130244	50-546	Q
	8305180358	PR	
League of Women Voters of Rockford, IL	8305030508	50-454	T
	8305030516*	50-454	T
	8305100286	50-454	Q
	8305170569*	50-454	Q
	8305170572*	50-454	Q
	8305170572*	50-454	Q
	8305170576*	50-454	Q
	8305170581*	50-454	Q
	8305170581*	50-454	Q
	8305170588*	50-454	Q
	8305170590*	50-454	Q
	8305170590*	50-454	Q
	8305170593*	50-454	Q
	8305170593*	50-454	Q
League of Women Voters of Suffolk Co., NY	8305180347	PR	
Lewis, M	8305030418	PR	
	8305200441	PR	
	8305200456	PR	
	8305240516	50-352	Q
Literature Research Corp.	8305040284*	CONTRACT	
Litton Industries, Inc	8305270625	50-321	B
Lone Tree Council	8305170396*	50-329	H
Long Island Lighting Co	8305030560	50-322	Q
	8305040303	50-322	E
	8305040461	50-322	Q
	8305040508	50-322	E
	8305040514*	50-322	E
	8305050024	50-322	T
	8305050029*	50-322	T
	8305050109	50-322	Q
	8305060153*	FOIA	
	8305060164*	FOIA	
	8305090136*	50-322	Q
	8305100239*	50-322	Q
	8305120306*	50-322	Q
	8305120311*	50-322	Q
	8305120328	50-322	S
	8305120380*	50-322	Q
	8305130077	50-322	Q
	8305160006	50-322	Q
	8305160070	50-322	E
	8305160095	50-322	A
	8305180244	50-322	Q
	8305180324*	50-322	Q
	8305180331*	50-322	Q
	8305190208	50-322	Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305190271	50-322 Q
	8305190378	50-322 Q
	8305190382*	50-322 Q
	8305200549	50-322 S
	8305200594*	50-322 Q
	8305200651	50-322 Q
	8305240447	50-322 A
	8305270013	50-322 E
	8305310040	50-322 Q
	8305310050	50-322 A
	8305310051	50-322 G
Los Alamos Scientific Laboratory	8305110062	RES
	8305110083	RES
	8305130292	RES
	8305160299	50-537 D
Louisa County, VA	8305200659	50-338 G
Louisiana Power & Light Co	8305020341	50-382 A
	8305020411	50-382 S
	8305020450	50-382 S
	8305020479	50-382 S
	8305050017	50-382 R
	8305060367	50-382 S
	8305060425	50-382 S
	8305060566	50-382 S
	8305060587	50-382 S
	8305130019	50-382 S
	8305170223	50-382 S
	8305170265	50-382 S
	8305170290	50-382 H
	8305170327	50-382 S
	8305170351	50-382 S
	8305170494	50-382 S
	8305170492	50-382 S
	8305170500	50-382 S
	8305180429	50-382 Q
	8305180468	50-382 A
	8305200542	50-382 S
	8305270138	50-382 S
	8305270147	50-382 S
	8305270194	50-382 S
	8305270373	50-382 S
	8305310094	50-382 E
Louisiana, State of	8305100328	50-458 Q
	8305270165	State Prog
Lowenstein, Newman, Reis, Axelrad & Toll	8305020434	50-498 Q
	8305110225	50-498 Q
	8305180404	PR
M & T Chemicals, Inc	8305160301	XPORTLIC
	8305160303*	XPORTLIC
	8305160305*	XPORTLIC
Magnaflux, Corp	8305130221*	50-155 Q
	8305130233*	50-155 Q
	8305130237*	50-155 Q
	8305130241*	50-155 Q
Maine Yankee Atomic Power Co	8305020393*	50-309 Q
	8305030491	50-309 P
	8305030496*	50-309 P
	8305040533	50-309 Q
	8305050220	50-309 P
	8305050225*	50-309 P
	8305060494	50-309 S
	8305060503*	50-309 S
	8305060538	50-309 S
	8305060549*	50-309 S
	8305110344	50-309 S
	8305110425	50-309 S
	8305110433*	50-309 S
	8305130054	50-309 P
	8305130078	50-309 P
	8305130128	50-309 P
	8305160065	50-309 S
	8305160082*	50-309 S
	8305190308	50-309 F
	8305200314	50-309 I
	8305200341	50-309 F
	8305200360	50-309 S
	8305200374*	50-309 S
	8305200467	50-309 S
	8305200469	50-309 P
	8305200473*	50-309 P
	8305200529	50-309 S
	8305200578	50-309 I
	8305230127	50-309 F
	8305230137*	50-309 F
	8305230140*	50-309 F
	8305230142*	50-309 F
	8305230146*	50-309 F
	8305230151*	50-309 F
	8305230154*	50-309 F
	8305230157*	50-309 F
	8305230162*	50-309 F
	8305230167*	50-309 F
	8305230175*	50-309 F
	8305230181*	50-309 F
	8305230383	50-309 P
	8305230472	50-309 S
	8305230483*	50-309 S
	8305240266	50-309 P
	8305240270	50-309 P
	8305250429	50-309 Q
	8305310067	50-309 Q
Maine, State of	8305030565	50-309 Q
	8305030567*	50-309 Q
	8305240386	50-309 Q
Management Analysis Co	8305250529	PR
	8305250535*	PR
Mapleton Intervenors	8305120005	FOIA
Mark Controls Corp	8305120484*	50-461 B
Marsh & McLennan, Inc	8305030379	50-389 J
	8305040180	50-348 J
	8305040186	50-335 J
	8305040202	50-321 J
	8305040202	50-321 J
	8305040204	50-302 J
	8305040208	50-250 J
	8305040243	50-327 J
	8305120006	50-213 J
	8305120039	50-293 J
	8305120110	50-244 J
	8305120156	50-245 J
	8305120156	50-245 J
	8305120200	50-29 J
	8305120208	50-286 J
	8305120208	50-286 J
	8305120208	50-286 J
	8305160005	50-259 J
	8305160005	50-259 J
	8305160026	50-315 J
	8305160063	TOPREP
	8305160084	50-89 J
	8305160105	50-346 J
	8305160157	50-272 J
	8305190022	50-302 J
	8305200270	50-321 J
	8305200270	50-321 J
	8305230027	50-321 J
	8305230027	50-321 J
Maryland, State of	8305060289	PR
	8305180439*	50-170 U
	8305270130	State Prog
Maryland, Univ of	8305110512	NUREG
Massachusetts Institute of Technology	8305090315*	MISC
	8305160043	50-20 S
Massachusetts, Commonwealth of,	8305090523	50-443 F
	8305100309	50-213 F
Materials Engineering Testing Services, Inc	8305060347	NUREG
	8305240015	NUREG
Maxwell, J C	8305130347	50-443 D
McDermott, Inc.	8304200001	TOPREP
Metal Bellows Corp	8305100382*	50-438 A
	8305100382*	50-438 A
	8305100395*	50-438 A
	8305100395*	50-438 A
Metrocom, Inc	8305170661*	CONTRACT
Metropolitan Edison Co	8305030591	50-289 Q
	8305090431	50-289 Q
	8305100283	50-289 Q
	8305100310	50-289 Q
	8305100357	50-289 Q
	8305120292	50-289 Q
	8305180277	50-289 Q
	8305240287	50-289 Q
	8305240487	50-289 Q
	8305250202	50-289 Q
	8305250225*	50-289 Q
Metropolitan Transportation Authority New York, NY	8305020401	50-247 Q
Michigan, Univ. of	8305180159*	FOIA
	8305200149*	CONTRACT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Middle South Utilities, Inc - Middle South Energy, Inc	8305200461	PR
Miller, D S	8305160099	50-309 Q
	8305190255	50-309 Q
	8305240493	50-309 Q
Minnesota, State of	8305030472	PR
	8305180460	PR
Miranda Associates, Inc	8305120150*	CONTRACT
Mississippi Power & Light Co	8304110321	50-416 P
	8304110328*	50-416 P
	8304110335*	50-416 P
	8304190378	50-416 P
	8304280037	50-416 P
	8304280049*	50-416 P
	8305030553	50-416 S
	8305030562	50-416 S
	8305050075	50-416 F
	8305050077	50-416 F
	8305050131	50-416 S
	8305050167	50-416 S
	8305050178*	50-416 S
	8305050227	50-416 S
	8305050256	50-416 S
	8305050261*	50-416 S
	8305110275	50-416 S
	8305110279*	50-416 S
	8305110291	50-416 S
	8305110418	50-416 S
	8305130126	50-416 P
	8305130126	50-416 P
	8305130194	50-416 S
	8305130200*	50-416 S
	8305170424	50-416 S
	8305170426*	50-416 S
	8305170427	50-416 S
	8305170430	50-416 S
	8305170431*	50-416 S
	8305170433*	50-416 S
	8305190015	50-416 J
	8305190015	50-416 J
	8305200280	50-416 S
	8305200286*	50-416 S
	8305200484	50-416 S
	8305200493*	50-416 S
	8305200523	50-416 S
	8305200532*	50-416 S
	8305200604	50-416 S
	8305230608	50-416 P
	8305240143	50-416 P
	8305240143	50-416 P
	8305240265*	50-416 P
	8305240496	50-416 P
	8305250072	50-416 R
	8305250365	50-416 S
	8305250405	50-416 S
	8305250434	50-416 S
	8305250487	50-416 S
	8305250513	50-416 S
	8305250579	50-416 S
	8305270400*	50-416 Q
	8305270410*	50-416 Q
	8305270473	50-416 S
	8305270515	50-416 S
	8305270593*	50-416 Q
	8305310065	50-416 S
	8305310069	50-416 S
	8305310146	50-416 S
	8305310196	50-416 S
	8305310204	50-416 S
	8305310207	50-416 S
Missouri, State of	8305250341*	50-483 Q
	8305250356*	50-483 Q
	8305250424*	50-483 Q
	8305250544*	50-483 Q
	8305250548*	50-483 Q
Missouri, Univ. of, Columbia	8305260341*	CONTRACT
Missouri, Univ of, Rolla	8305030375	50-123 R
	8305310006	50-123 P
Mitsubishi International Corp (subs of Mitsubishi Corp)	8305020553	XPORTLIC
	8305020557*	XPORTLIC
Mitsui & Co (U S A), Inc (subs of Mitsui & Co , Ltd.)	8305260317	XPORTLIC
Molycorp, Inc.	8305180200	40-7097
Monsanto Co	8305180117	40-6500
	8305180125*	40-6500
Montana X-Ray, Inc	8304130034	71-494
	8304130042*	71-494
Montgomery County, MD	8305200071*	CONTRACT
	8305250576*	50-483 Q
Morgan Associates	8305030549	50-247 Q
	8305100208	50-247 Q
	8305130064	50-247 Q
	8305130071	50-247 Q
	8305240466	50-247 Q
Morgan, Lewis & Bockius	8305240394*	50-537 Q
	8305110445	50-537 Q
Multimedia Program Production, Inc	8305190390*	50-373 P
NPB Industries, Inc	8305240356	50-445 B
NUS Corp	8304060126*	50-440 E
	8305030337	TOPREP
	8305030343*	TOPREP
	8305230039*	FOIA
	8305230057*	FOIA
	8305230059	FOIA
	8305230165	71-496
	8305230176*	71-496
	8305270095*	50-302 P
NUSAC, Inc	8305040643*	CONTRACT
NUTECH Engineers, Inc	8305060055*	50-321 P
	8305060096	FOIA
	8305200307*	50-237 S
	8305310097*	50-366 Q
National Electrical Contractors Association	8305240517	50-247 H
National Emergency Civil Liberties Committee	8305240532	50-247 Q
National Governors' Association	8305260380*	CONTRACT
National Wildlife Federation	8305170272	50-522 Q
Natural Resources Defense Council	8305030502	50-537 Q
	8305100210	50-537 Q
	8305100276	50-537 Q
	8305100350	50-537 Q
	8305120291	50-537 Q
	8305160149	50-537 Q
	8305160181	50-537 Q
	8305170272	50-522 Q
	8305170272	50-522 Q
	8305170279	50-522 Q
	8305170279	50-522 Q
	8305170347	50-522 Q
	8305170347	50-522 Q
	8305170357	50-522 Q
	8305170357	50-522 Q
	8305190221	50-537 Q
	8305240553	50-537 Q
Navy, Dept of, Pearl Harbor Naval Shipyard	8305170738	71-9033
Nawyn, R	8305130300*	CONTRACT
Nebraska Public Power District	8305020449	50-298 P
	8305020464*	50-298 P
	8305030393	50-298 P
	8305030554	50-298 P
	8305030588	50-298 P
	8305050113	50-298 P
	8305060380	50-298 I
	8305060383*	50-298 I
	8305060574	50-298 S
	8305060584*	50-298 S
	8305120433	50-298 S
	8305120439*	50-298 S
	8305270369	50-298 P
Nebraska, State of	8305090162	NUREG
	8305120041*	FOIA
	8305120065*	FOIA
	8305130288	40-8829
	8305270093*	CONTRACT
Neutron Products, Inc	8305050363*	FOIA
New England Coalition on Nuclear Pollution	8305030541	50-443 Q
	8305160002	50-443 Q
	8305160002	50-443 Q
	8305160019	50-443 Q
	8305160019	50-443 Q
	8305160068	50-443 Q
New Mexico State Univ	8305270048*	50-320 P
New York, NY	8305030608	50-247 Q
	8305030608	50-247 Q
	8305030619*	50-247 Q
	8305030619*	50-247 Q
	8305030629*	50-247 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305030629*	50-247 Q
	8305190264	State Prog
	8305240532	50-247 Q
New York, State Univ of, Buffalo	8305100232	50-57 S
New York, State of	8304040394*	50-322 U
	8305130204*	50-322 Q
	8305180260*	50-322 U
	8305190014	State Prog
	8305240312	50-247 F
	8305240312	50-247 F
	8305240541	50-247 H
	8305240541	50-247 H
	8305310070*	50-247 U
New York, State of, Energy Research & Development Administration	8305180805	PROJ
	8305180810	PROJ
Niagara Mohawk Power Corp	8304110516	50-220 R
	8304210238	50-410 K
	8304210240*	50-410 K
	8305030515	50-410 F
	8305040483	50-220 P
	8305040493*	50-220 P
	8305040500*	50-220 P
	8305050020	50-220 P
	8305050031*	50-220 P
	8305060043	50-220 P
	8305060046*	50-220 P
	8305060048*	50-220 P
	8305060426	50-220 S
	8305060428*	50-220 S
	8305060533	50-220 S
	8305060540*	50-220 S
	8305100272	50-220 R
	8305100277*	50-220 R
	8305110315	50-410 A
	8305110359*	50-410 C
	8305110372*	50-410 K
	8305120334	50-410 S
	8305120392	50-410 S
	8305130028	50-410 M
	8305160015	50-220 P
	8305160093	50-410 Q
	8305160097	50-220 R
	8305160103*	50-220 R
	8305170393	50-220 R
	8305170395*	50-220 R
	8305200283	50-220 S
	8305200290*	50-220 S
	8305200345	50-220 P
	8305200383*	50-220 Q
	8305230431*	50-220 P
	8305230574	50-410 A
	8305230582*	50-410 A
	8305230585*	50-410 A
	8305230585*	50-410 A
	8305230681*	50-410 A
	8305230681*	50-410 A
	8305230684*	50-410 A
	8305230684*	50-410 A
	8305230687*	50-410 A
	8305230687*	50-410 A
	8305230691*	50-410 A
	8305230691*	50-410 A
	8305230696*	50-410 A
	8305230696*	50-410 A
	8305230699*	50-410 A
	8305230699*	50-410 A
	8305240402	50-220 P
	8305240498	50-410 A
	8305250430	50-410 S
	8305260086	50-410 K
	8305270026	50-220 P
	8305270073	50-220 S
	8305270645*	50-410 Q
Nissho-Iwai American Corp	8305170125*	XPORTLIC
	8305180709	XPORTLIC
Northampton County, PA	8305270573	50-443 Q
Northeast Nuclear Energy Co (subs of Northeast Utilities)	8305030404	50-245 P
	8305030620	50-245 P
	8305030624*	50-245 P
	8305030628*	50-245 P
	8305040034*	50-245 F
	8305040039*	50-245 F
	8305040447	50-336 P
	8305050054	50-213 P
	8305050054	50-213 P
	8305050054	50-213 P
	8305050229	50-245 P
	8305050229	50-245 P
	8305060424	50-336 Q
	8305060455	50-423 S
	8305060501	50-245 S
	8305060512*	50-245 S
	8305090465	50-213 P
	8305090465	50-213 P
	8305090465	50-213 P
	8305090465	50-213 P
	8305090471	50-245 P
	8305090474*	50-245 P
	8305100368	50-245 P
	8305110574*	50-213 F
	8305110579*	50-213 F
	8305120241	50-336 P
	8305170010	50-336 R
	8305170014*	50-336 R
	8305180268	50-245 P
	8305180304	50-245 P
	8305180311*	50-245 P
	8305200533	50-423 S
	8305230323	50-245 F
	8305230330*	50-245 F
	8305230338*	50-245 F
	8305230508	50-336 P
	8305230549	50-245 S
	8305230557*	50-245 S
	8305230616	50-213 P
	8305250510	50-213 P
	8305250510	50-213 P
	8305250510	50-213 P
	8305250510	50-213 P
	8305250518*	50-213 P
	8305250518*	50-213 P
	8305250518*	50-213 P
	8305250518*	50-213 P
	8305270036	50-423 S
	8305270037*	50-423 Q
	8305270074	50-336 Q
	8305270089	50-336 S
	8305270114	50-245 P
	8305270239	50-336 S
	8305270454	50-336 S
Northeast Utilities	8305020093	50-245 I
	8305020093	50-245 I
	8305020093	50-245 I
	8305030404	50-245 P
	8305030620	50-245 P
	8305030624*	50-245 P
	8305030628*	50-245 P
	8305040447	50-336 P
	8305050034	TOPREP
	8305050054	50-213 P
	8305050054	50-213 P
	8305050054	50-213 P
	8305050229	50-245 P
	8305050229	50-245 P
	8305060213	50-213 F
	8305060244	PR
	8305060424	50-336 Q
	8305060455	50-423 S
	8305090465	50-213 P
	8305090465	50-213 P
	8305090465	50-213 P
	8305090471	50-245 P
	8305100368	50-245 P
	8305110574*	50-213 F
	8305120241	50-336 P
	8305170010	50-336 R
	8305180268	50-245 P
	8305180304	50-245 P
	8305200441	PR
	8305200533	50-423 S
	8305200587	50-423 A
	8305230323	50-245 F
	8305230508	50-336 P
	8305230616	50-213 P
	8305270036	50-423 S
	8305270037*	50-423 Q
	8305270074	50-336 Q
	8305270089	50-336 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305270114	50-245	P
	8305270239	50-336	S
	8305270454	50-336	S
Northeast Utilities Service Co	8305060244	PR	
	8305100335*	50-213	P
	8305110071*	50-213	F
Northern States Power Co	8303180429	50-263	P
	8305020320	50-282	G
	8305020320	50-282	G
	8305020329*	50-282	G
	8305020329*	50-282	G
	8305020488	50-263	S
	8305020492*	50-263	S
	8305030221*	50-282	F
	8305030226*	50-282	F
	8305030603	50-263	K
	8305030610*	50-263	K
	8305030613*	50-263	K
	8305120389	50-282	P
	8305160056	50-282	R
	8305160076*	50-282	R
	8305160092	50-263	R
	8305160098*	50-263	R
	8305180352	50-263	G
	8305230523	50-282	F
	8305230523	50-282	F
	8305240153	50-306	S
	8305240166	50-282	S
	8305250409	PR	
NuPharm, Inc	8305180056*	FOIA	
	8305180063*	FOIA	
	8305180241*	FOIA	
	8305180269*	FOIA	
Nuclear Assurance Corp	8305060251*	CONTRACT	
Nuclear Data, Inc	8305180560*	CONTRACT	
	8305180562*	CONTRACT	
Nuclear Fuel Services, Inc. (subs of Getty Oil Co)	8305030694	70-143	
	8305030699	70-143	
	8305050099	70-143	
	8305180852	70-143	
	8305190003	70-143	
	8305190033	70-143	
	8305200658	70-143	
	8305240051	71-143	
Nuclear Information & Resources Services	8305200218	PR	
Nuclear Metals, Inc	8208060242*	40-672	
	8208060244*	40-672	
	8305020288	XPORTLIC	
	8305020296*	XPORTLIC	
	8305060141*	40-672	
	8305060181*	40-672	
	8305060189*	40-672	
	8305090723	XPORTLIC	
	8305120246*	40-672	
	8305120298*	40-672	
	8305120352*	40-672	
	8305120369*	40-672	
	8305120381*	70-82	
	8305120480*	40-672	
	8305120494*	40-672	
	8305120511*	40-672	
	8305120617*	FOIA	
	8305120627*	40-672	
	8305130011*	40-672	
	8305130042*	40-672	
Nuclear Packaging, Inc.	8305040105*	71-9181	
	8305040110*	71-9181	
	8305060142*	71-9175	
	8305060148*	71-9175	
	8305060152*	71-9175	
Nuclear Power Services, Inc	8305200683*	50-373	P
Nuclear System	8304270399	71-9135	
O'Connor & Hannan	8305180070*	FOIA	
	8305180074*	FOIA	
O'Neill, J	8305120287	50-155	G
	8305190245	50-155	G
	8305240328	50-155	G
Oak Ridge Associated Univ	8305230254*	FOIA	
Oak Ridge National Laboratory	8305020938	NUREG	
	8305030025	RES	
	8305110120	NUREG	
	8305130341	NUREG	
	8305250155	RES	
	8305260004*	71-5552	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305270048*	50-320	P
	8305310237	NUREG	
Office of Management & Budget	8305040001	ORG	
	8305040003	ORG	
	8305090006	ORG	
Ohio Citizens for Responsible Energy	8305040528	50-440	G
	8305040528	50-440	G
	8305040541	50-440	G
	8305040541	50-440	G
	8305040544	50-440	G
	8305040544	50-440	G
	8305090234	FOIA	
	8305170305	50-440	G
	8305170305	50-440	G
	8305170341	50-440	G
	8305170341	50-440	G
	8305180347	PR	
	8305180404	PR	
Ohio State Univ	8305110192*	CONTRACT	
Ohio, State of	8305090545*	50-358	A
	8305090561*	50-358	A
Oklahoma, State of	8305090162	NUREG	
Oklahoma, Univ of	8305250478	50-112	H
Omaha Public Power District	8305030156	50-285	P
	8305030160*	50-285	P
	8305030429*	50-285	F
	8305040619*	50-285	F
	8305040624*	50-285	F
	8305060069	50-285	I
	8305060091*	50-285	I
	8305060186	50-285	P
	8305100226	50-285	F
	8305120603*	50-285	F
	8305160027	50-285	P
	8305160111	50-285	R
	8305160116*	50-285	R
	8305170465	50-285	R
	8305170470*	50-285	R
	8305230588	50-285	P
	8305240474	50-285	P
On-Line Computer Systems, Inc.	8305110232*	CONTRACT	
Oregon Environmental Council	8305170272	50-522	G
Orrick, Herrington & Sutcliffe	8305190195	50-361	G
	8305190195	50-361	G
	8305190212	50-361	G
	8305190212	50-361	G
Osage County, MO	8305250372*	50-483	G
Ossining, NY	8305240508	50-247	G
Pacific Gas & Electric Co	8305020106	50-133	F
	8305020388	50-275	P
	8305020388	50-275	P
	8305030188*	50-275	F
	8305030188*	50-275	F
	8305030193*	50-275	F
	8305030193*	50-275	F
	8305030510	50-275	P
	8305040320	50-275	P
	8305040328*	50-275	P
	8305040473*	50-275	P
	8305050198	50-275	P
	8305060299	50-323	G
	8305100339	PROJ	
	8305100346	PROJ	
	8305120042	50-275	P
	8305120325	50-275	P
	8305120333	50-275	P
	8305120339*	50-275	P
	8305160172	50-275	P
	8305160176*	50-275	P
	8305170336	50-133	B
	8305170342*	50-133	B
	8305190157	50-275	F
	8305230407	50-133	P
	8305240238	50-275	R
	8305240242*	50-275	R
	8305240375	50-275	P
	8305240397	50-275	B
	8305260274*	50-275	G
	8305260274*	50-275	G
	8305270249	50-275	B
	8305270622	50-275	G
	8305270622	50-275	G
	8305310130	50-275	P
	8305310135*	50-275	P
	8305310140*	50-275	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pacific International	8305030250	XPORTLIC
Palmetto Alliance	8305060252	50-413 Q
	8305310155	50-413 Q
Parents Concerned About Indian Point	8305030633*	50-247 Q
	8305190220	50-247 Q
	8305240543	50-247 Q
Pathfinder Mines Corp	8305020410	40-6622
	8305020504*	40-6622
	8305030277	40-6622
	8305260357	40-2259
Pennsylvania Power & Light Co	8305020387	50-387 P
	8305030144	50-387 P
	8305030153*	50-387 P
	8305030334	50-387 S
	8305030338*	50-387 S
	8305050289*	50-387 F
	8305060442	50-387 S
	8305060543	50-387 Q
	8305060592	50-387 S
	8305060598*	50-387 S
	8305100016	50-387 P
	8305100019*	50-387 P
	8305100021*	50-387 P
	8305100308	50-387 P
	8305100317*	50-387 P
	8305110097	50-387 K
	8305110097	50-387 K
	8305110104*	50-387 K
	8305110104*	50-387 K
	8305110108*	50-387 K
	8305110160	50-387 P
	8305110160	50-387 P
	8305110241	50-387 S
	8305110247*	50-387 S
	8305110348	50-387 S
	8305110358*	50-387 S
	8305110421	50-387 S
	8305110430*	50-387 S
	8305120422	50-387 S
	8305120430*	50-387 S
	8305130114	50-387 P
	8305130311*	50-387 F
	8305130311*	50-387 F
	8305130314*	50-387 F
	8305130314*	50-387 F
	8305160124	50-387 S
	8305160132	50-387 S
	8305160140	50-387 S
	8305160151*	50-387 S
	8305180646	70-2983
	8305190285	50-387 P
	8305190285	50-387 P
	8305190295	50-387 P
	8305190319	50-387 S
	8305200555	50-387 S
	8305200561*	50-387 S
	8305200640	50-387 S
	8305200646*	50-387 S
	8305230471	50-387 S
	8305230477*	50-387 S
	8305230541	50-387 P
	8305270064	50-387 P
	8305270064	50-387 P
	8305270255	50-387 Q
	8305310208	50-387 P
Pennsylvania State Univ.	8305180353	PR
	8305270040*	50-320 P
	8305270046*	50-320 P
Pennsylvania, Commonwealth of,	8305060529	50-352 A
	8305060536*	50-352 A
	8305120278	50-352 Q
	8305120278	50-352 Q
	8305120280*	50-352 Q
	8305120280*	50-352 Q
	8305170533	50-352 Q
	8305230332*	CONTRACT
Perkins, Coie, Stone, Olsen & Williams	8305310029	50-522 Q
	8305310029	50-522 Q
	8305310082	50-522 Q
	8305310082	50-522 Q
Philadelphia Electric Co.	8301310260	50-352 K
	8301310274*	50-352 K
	8305020099	50-277 P
	8305020099	50-277 P
	8305020255	50-352 E
	8305020255	50-352 E
	8305020335	50-352 A
	8305020335	50-352 A
	8305020441	50-352 Q
	8305020441	50-352 Q
	8305020454	50-352 E
	8305020454	50-352 E
	8305030299	50-352 A
	8305030299	50-352 A
	8305030307*	50-352 A
	8305030307*	50-352 A
	8305030563	50-352 Q
	8305030563	50-352 Q
	8305050021	50-277 P
	8305050021	50-277 P
	8305050027*	50-277 P
	8305050027*	50-277 P
	8305050033*	50-277 P
	8305050033*	50-277 P
	8305050202	50-352 Q
	8305060457	50-352 A
	8305060457	50-352 A
	8305060478	50-352 Q
	8305060507	50-352 A
	8305060513	50-277 Q
	8305060513	50-277 Q
	8305100275	50-352 A
	8305100275	50-352 A
	8305100359	50-277 F
	8305110316	50-277 S
	8305110340	50-278 S
	8305110349*	50-278 S
	8305120320	50-352 A
	8305120358	50-277 S
	8305120473	50-277 S
	8305130096	50-353 A
	8305160001	50-352 C
	8305160001	50-352 C
	8305160117	50-352 K
	8305160117	50-352 K
	8305170187	50-352 A
	8305170228	50-352 E
	8305170401	50-277 P
	8305180343	50-352 A
	8305180343	50-352 A
	8305180389	50-352 E
	8305180389	50-352 E
	8305180402	50-352 A
	8305180402	50-352 A
	8305180414	50-352 E
	8305180414	50-352 E
	8305180414	50-352 E
	8305180419	50-352 A
	8305180419	50-352 A
	8305180426*	50-352 E
	8305180426*	50-352 E
	8305180426*	50-352 E
	8305180431*	50-352 E
	8305180431*	50-352 E
	8305180431*	50-352 E
	8305180432	50-352 A
	8305180432	50-352 A
	8305180438*	50-352 E
	8305180438*	50-352 E
	8305180438*	50-352 E
	8305180443*	50-352 E
	8305180443*	50-352 E
	8305180443*	50-352 E
	8305180451	50-352 E
	8305180451	50-352 E
	8305190359	50-352 C
	8305190359	50-352 C
	8305200615	50-352 E
	8305230496	50-352 A
	8305240307	50-277 J
	8305240428	50-277 P
	8305240489	50-352 Q
	8305240489	50-352 Q
	8305250133	50-352 A
	8305250133	50-352 A
	8305250135*	50-352 A
	8305250135*	50-352 A
	8305270117	50-278 S
	8305270184	50-277 S
	8305270235	50-277 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305270375	50-352	A
	8305270375	50-352	A
	8305310009	50-352	E
	8305310009	50-352	E
	8305310045	50-352	E
	8305310045	50-352	E
Philadelphia, PA	8305160174	50-352	G
	8305160174	50-352	G
	8305160177	50-352	G
	8305160177	50-352	G
	8305240316	50-352	H
Pickard, Lowe & Garrick, Inc	8305110152*	CONTRACT	
	8305270110*	CONTRACT	
	8305310141*	50-244	P
Pittsburgh Testing Laboratory	8305030516*	50-454	T
	8305310159*	50-244	P
Pittsburgh, Univ of	8305270022	50-320	P
	8305270027*	50-320	P
Planning Research Corp	8305160295*	50-413	F
Plateau Resources, Ltd	8305040047	40-7869	
	8305040052*	40-7869	
	8305260418	40-8698	
Portland General Electric Co	8305020535	71-6601	
	8305040417	50-344	F
	8305060600	50-344	P
	8305060606*	50-344	P
	8305130143	50-344	S
	8305130152*	50-344	S
	8305130164	50-344	Q
	8305130224	50-344	S
	8305130232*	50-344	S
	8305130240	50-344	P
	8305180266	PR	
	8305200013	50-344	P
	8305230581	50-344	P
	8305260275	50-344	P
	8305270182	50-344	P
	8305270186*	50-344	P
	8305270188*	50-344	P
	8305270205	50-344	P
	8305270211*	50-344	P
	8305270282*	50-344	P
Potterfield, A	8305030608	50-247	Q
Power Authority of the State of New York	8305020209	50-333	P
	8305020381	50-286	P
	8305030408	50-286	P
	8305030549	50-247	Q
	8305040311	50-333	P
	8305040424	50-333	P
	8305040434*	50-333	P
	8305040438*	50-333	P
	8305050026	50-333	P
	8305050037	50-247	Q
	8305050037	50-247	Q
	8305060397	50-286	P
	8305060427	50-286	P
	8305060431	50-286	P
	8305060432*	50-286	P
	8305060433*	50-286	P
	8305060439	50-286	P
	8305060446*	50-286	P
	8305060449*	50-286	P
	8305060496	50-247	Q
	8305060496	50-247	Q
	8305060500	50-286	Q
	8305100208	50-247	Q
	8305100360	50-333	S
	8305110053	50-286	P
	8305110058*	50-286	P
	8305110063*	50-286	P
	8305110167	50-286	Q
	8305110259	50-333	S
	8305110264*	50-333	S
	8305110400	50-333	S
	8305110405	50-333	S
	8305110408*	50-333	S
	8305110416*	50-333	S
	8305110510	50-333	S
	8305110514*	50-333	S
	8305130039	50-286	P
	8305130064	50-247	Q
	8305130071	50-247	Q
	8305130117	50-286	P
	8305130120*	50-286	P
	8305130123*	50-286	P
	8305130132	50-333	R
	8305130134*	50-333	R
	8305160088	50-286	P
	8305160106	50-333	P
	8305160112*	50-333	P
	8305200265	50-333	P
	8305200268*	50-333	P
	8305200272*	50-333	P
	8305200405	50-286	P
	8305230375	50-333	F
	8305230454	50-333	S
	8305230459*	50-333	S
	8305230592*	50-410	A
	8305230592*	50-410	A
	8305230597	50-286	P
	8305230599*	50-410	A
	8305230599*	50-410	A
	8305240090	50-286	P
	8305240099	50-286	F
	8305240234	50-286	F
	8305240328	50-286	P
	8305240338	50-286	F
	8305240347	50-286	P
	8305240442	50-333	P
	8305240463	50-333	P
	8305240466	50-247	Q
	8305240466	50-247	Q
	8305240492	50-333	P
	8305240529	50-286	P
	8305270189	50-333	R
	8305270284*	50-333	Q
	8305270340	50-333	P
	8305270352*	50-333	P
	8305270364*	50-333	P
	8305270399*	50-333	Q
Power Engineering	8305030461	PR	
Project Management Corp	8303240390	50-537	Q
	8305110220	50-537	Q
	8305110438	50-537	Q
	8305110448	50-537	Q
	8305110449*	50-537	Q
	8305120313	50-537	Q
	8305190339	50-537	Q
	8305200636	50-537	Q
	8305200648*	50-537	Q
	8305240475	50-537	Q
	8305240480	50-537	Q
	8305240503	50-537	Q
	8305310188	50-537	Q
Public Interest Research Group, New York	8305030608	50-247	Q
	8305030608	50-247	Q
	8305030619*	50-247	Q
	8305030619*	50-247	Q
	8305030629*	50-247	Q
	8305030629*	50-247	Q
	8305030641*	50-247	Q
	8305030641*	50-247	Q
	8305030646*	50-247	Q
	8305030646*	50-247	Q
	8305250337	50-247	Q
Public Service Co of Colorado	8305020462	50-267	P
	8305050146	50-267	F
	8305050214	50-267	P
	8305050222*	50-267	P
	8305050228*	50-267	P
	8305060479	50-267	B
	8305060484*	50-267	B
	8305060546	50-267	R
	8305060552*	50-267	R
	8305090489	50-267	R
	8305090565*	50-267	R
	8305120570*	50-267	F
	8305120578*	50-267	F
	8305160048	50-267	P
	8305160053	50-267	P
	8305170380	50-267	P
	8305200494	50-267	P
	8305230426	50-267	R
	8305230427*	50-267	R
	8305240477	50-267	P
	8305310111	50-267	P
Public Service Co of Indiana, Inc	8304250167	50-546	A
	8304250167	50-546	A
	8304250190*	50-546	K
	8305020118	50-546	S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305020291	50-546 S
	8305020291	50-546 S
	8305040494	50-546 S
	8305120457	50-546 A
	8305130073	50-546 Q
	8305130073	50-546 Q
	8305130098	50-546 Q
	8305130098	50-546 Q
	8305130119	50-546 A
	8305130119	50-546 A
	8305130207	50-546 S
	8305130207	50-546 S
	8305130244	50-546 Q
	8305130244	50-546 Q
	8305170306	50-546 A
	8305170312*	50-546 A
	8305200289	50-546 F
	8305200289	50-546 F
	8305230654	50-546 A
	8305240408	50-546 S
	8305240408	50-546 S
	8305260233	50-546 F
	8305260233	50-546 F
	8305260332	50-546 S
	8305260332	50-546 S
Public Service Co of New Hampshire	8305040300	50-443 Q
	8305040300	50-443 Q
	8305040316	50-443 Q
	8305040316	50-443 Q
	8305050006	50-443 F
	8305160039	50-443 S
	8305190164	50-443 S
	8305200353	50-443 S
	8305200353	50-443 S
	8305200402	50-443 S
	8305200402	50-443 S
	8305250244	50-443 S
	8305270019	50-443 A
	8305270019	50-443 A
	8305310147	50-443 Q
Public Service Electric & Gas Co of New Jersey	8304180491	50-311 S
	8304180513*	50-311 S
	8305020150	50-272 S
	8305020186	50-272 P
	8305020186	50-272 P
	8305020267*	50-272 Q
	8305040262	50-272 S
	8305040262	50-272 S
	8305050013	50-272 P
	8305060470	50-354 S
	8305060476	50-272 S
	8305060480	50-311 S
	8305060482*	50-272 S
	8305060489*	50-311 S
	8305090457	50-272 P
	8305090457	50-272 P
	8305090459*	50-272 P
	8305090459*	50-272 P
	8305110007	50-311 P
	8305110154	50-272 P
	8305110154	50-272 P
	8305110156*	50-272 P
	8305110156*	50-272 P
	8305110255	50-354 S
	8305110271	50-311 S
	8305110274*	50-311 S
	8305120384	50-354 S
	8305160052	50-311 S
	8305160057*	50-311 S
	8305160085	50-272 Q
	8305160085	50-272 Q
	8305160096	50-311 S
	8305160102*	50-311 S
	8305160118	50-311 S
	8305160123*	50-311 S
	8305170018	50-272 R
	8305170021*	50-272 R
	8305170142	50-311 R
	8305170147*	50-311 R
	8305170328	50-272 P
	8305170328	50-272 P
	8305170367	50-311 S
	8305170370*	50-311 S
	8305170490*	50-354 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305200067	50-272 I
	8305200394	50-272 S
	8305200397*	50-272 S
	8305200537	50-311 S
	8305200546*	50-311 S
	8305230094	50-311 P
	8305230504	50-272 P
	8305230504	50-272 P
	8305230510	50-317 S
	8305240291*	50-272 Q
	8305250387	50-354 R
	8305250501	50-311 S
	8305270053*	50-272 Q
	8305270053*	50-272 Q
	8305310185	50-354 V
Puget Sound Power & Light Co	8305310029	50-522 Q
	8305310029	50-522 Q
	8305310082	50-522 Q
	8305310082	50-522 Q
Purdue Research Foundation	8305060183*	CONTRACT
Quadrex Corp	8305090388*	GA999
Quirk, Lawler & Matusky Engineers	8305230607*	50-410 A
	8305230607*	50-410 A
	8305230614*	50-410 A
	8305230614*	50-410 A
	8305230622*	50-410 A
	8305230622*	50-410 A
	8305230628*	50-410 A
	8305230628*	50-410 A
	8305230637*	50-410 A
	8305230637*	50-410 A
	8305230644*	50-410 A
	8305230644*	50-410 A
R E Williams & Associates, Inc	8305020491	40-6622
	8305030705	40-8584
R F Reedy, Inc	8305180427	50-275 R
Radiation Management Corp	8305110509*	CONTRACT
	8305250428*	50-483 Q
	8305250458*	50-483 Q
	8305250468*	50-483 Q
	8305250482*	50-483 Q
Radio TV Reports, Inc	8305190088*	50-329 Q
	8305190119*	50-373 Q
Reliance Electric Co	8305090003*	GA999
Rensselaer Polytechnic Inst	8305170466	50-225 F
Reuter-Stokes, Inc	8305060006	XPORTLIC
Rhode Island & Providence Plantation	8305240384	50-193 S
	8305250445	50-193 S
Rhone-Poulenc, Inc	8305030181	71-9100
Ridihalgh, Eggers & Associates	8305160363	PROJ
	8305160365*	PROJ
	8305230041	PROJ
	8305230056*	PROJ
Riley, J L	8305060252	50-413 Q
Robert L Cloud Associates, Inc	8305030573	50-275 R
	8305030581*	50-275 R
	8305180417	50-275 R
	8305230224*	50-275 R
Rochester Gas & Electric Corp	8305030021	50-244 P
	8305030024*	50-244 P
	8305030352	50-244 P
	8305050248*	50-244 Q
	8305060271	50-244 P
	8305060404	50-244 P
	8305110065	50-244 Q
	8305110318	50-244 S
	8305110328*	50-244 S
	8305130084	50-244 P
	8305130086*	50-244 P
	8305160114	50-244 S
	8305160119*	50-244 S
	8305180816	71-9080
	8305190170	50-244 S
	8305190175*	50-244 S
	8305190234	50-244 S
	8305190238*	50-244 S
	8305230452	50-244 S
	8305230458*	50-244 S
	8305230526	50-244 S
	8305230561	50-244 S
	8305230564*	50-244 S
	8305270578*	50-244 Q
	8305310020	50-244 P
	8305310085	50-244 P
	8305310125	50-244 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305310133*	50-244 P
	8305310218	50-244 F
	8305310232	50-244 P
Rochester, Univ of,	8305060200*	40-672
Rockland County, NY	8305180424	50-247 G
	8305180424	50-247 G
	8305240535	50-247 G
	8305240535	50-247 G
	8305270586	50-247 G
Rockwell International Corp	8305120404*	50-410 S
	8305310219	70-25
	8305310220*	70-25
Rocky Mountain Energy Co	8305250171	40-8697
	8305260364	40-8380
Rolf Jansen & Associates, Inc	8305120517*	CONTRACT
Rondout Associates	8305130352	50-443 O
Ropes & Gray	8305040300	50-443 G
	8305040300	50-443 G
	8305040316	50-443 G
	8305040316	50-443 G
	8305040533	50-309 G
	8305310147	50-443 G
Roy F Weston, Inc	8305170116	40-6500
Runkle, J D	8305060532	50-400 G
Ruskin Manufacturing Co	8305130113	50-400 S
Rye, NH	8305250331	50-443 H
Sacramento Municipal Utility District	8305020383	50-312 P
	8305020384	50-312 P
	8305020415	50-312 P
	8305020483	50-312 G
	8305030287	50-312 S
	8305030290*	50-312 S
	8305030551	50-312 S
	8305030561*	50-312 S
	8305060415	50-312 P
	8305060419	50-312 P
	8305060421*	50-312 P
	8305060429	50-312 P
	8305100099	50-312 F
	8305100229	50-312 P
	8305100296	50-312 P
	8305100338	50-312 P
	8305100344	50-312 P
	8305100381	50-312 G
	8305120073	TOPREP
	8305130099	50-312 G
	8305130105	50-312 S
	8305130160	50-312 S
	8305130163	50-312 S
	8305130219	50-312 S
	8305130231*	50-312 S
	8305230456	50-312 G
	8305230583	50-312 P
	8305240326	50-312 R
	8305270080	50-312 G
	8305270432	TOPREP
	8305310171	50-312 P
Safe Energy Coalition	8305230229	FOIA
Safe Energy for New Haven	8305030508	50-454 T
	8305030516*	50-454 T
Safety Light Corp	8305190057*	XPORTLIC
Sag Harbor, NY	8305180459*	50-322 H
	8305180461*	50-322 H
Salava, M E , Intervenor	8305180288	50-482 G
Salisbury,MA	8305090501	50-443 G
	8305090501	50-443 G
	8305090502*	50-443 G
	8305090502*	50-443 G
San Diego Gas & Electric Co	8305120178	50-206 H
San Francisco Examiner	8305160192	50-312 G
Sandia Laboratories	8305050432	NUREG
	8305060675	NUREG
	8305110491	NUREG
	8305110528	NUREG
	8305120556	50-537 O
	8305170122	NUREG
	8305170132	NUREG
	8305170135	NUREG
	8305180688*	71-9150
	8305310209	NUREG
	8305310210	NUREG
Sargent & Lundy, Inc.	8305090467	TOPREP
	8305090469*	TOPREP
	8305120074*	50-358 G
	8305190302*	50-373 P
	8305190302*	50-373 P
	8305190303*	50-373 P
	8305190303*	50-373 P
	8305190303*	50-373 P
	8305190357*	50-373 P
	8305200301*	50-237 S
	8305200681*	50-373 P
	8305200698*	50-373 P
	8305250084*	50-295 P
	8305270501*	50-454 G
Sassafras Audubon Society	8305060236	PR
	8305180330	PR
	8305180369	PR
Schwalb, Donnenfeld, Bray & Silbert	8305120560*	CONTRACT
	8305230012*	ADVCM
Science Applications, Inc	8206100204	REG
	8206100210*	REG
	8207080458*	50-321 P
	8209150251*	50-250 G
	8209200375*	50-313 P
	8303080182	REG
	8303080187*	REG
	8303080194	REG
	8303080202*	REG
	8303080209	REG
	8303080215*	REG
	8305170122	NUREG
	8305200110*	50-277 G
	8305270052*	50-271 G
Seabrook, NH	8305020425	50-443 G
	8305020425	50-443 G
	8305020429*	50-443 G
	8305020429*	50-443 G
Seacoast Anti-Pollution League	8305180364	PR
	8305190199	50-443 G
Senate	8305110601*	COMMISSION
	8305180116*	FOIA
	8305180123*	FOIA
	8305310239*	50-309 H
Senate, Environment & Public Works	8305110584*	COMMISSION
Senate, Judiciary Committee	8305230406*	COMMISSION
Sensible Maine Power	8305160099	50-309 G
	8305190255	50-309 G
	8305240483	50-309 G
	8305240493	50-309 G
Shaw, Pittman, Potts & Trowbridge	8305020438	50-266 G
	8305020470	50-440 G
	8305030467	50-483 G
	8305030591	50-289 G
	8305040307	50-440 G
	8305040307	50-440 G
	8305040506	50-440 T
	8305040506	50-440 T
	8305090431	50-289 G
	8305090470	50-261 G
	8305090537	50-358 T
	8305100283	50-289 G
	8305100310	50-289 G
	8305100357	50-289 G
	8305110266	50-483 G
	8305120292	50-289 G
	8305120391	50-482 G
	8305130092	50-261 G
	8305130099	50-312 G
	8305130137	50-261 G
	8305130162	50-261 G
	8305160012	50-289 G
	8305170291	50-266 G
	8305170450	50-400 G
	8305170497	50-400 G
	8305180277	50-289 G
	8305180429	50-382 G
	8305190249	50-483 G
	8305200630	50-400 G
	8305240287	50-289 G
	8305240313	50-482 G
	8305240486	50-289 G
	8305240515	50-440 G
	8305240550	50-400 G
	8305250202	50-289 G
	8305250205	50-483 G
	8305250208*	50-289 G
	8305250225*	50-289 G
	8305250294	50-483 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305250297*	50-483	Q
	8305250300*	50-483	Q
	8305250346*	50-483	Q
	8305250351*	50-483	Q
	8305250358*	50-483	Q
	8305250359*	50-483	Q
	8305250383*	50-483	Q
	8305250388*	50-483	Q
	8305250401*	50-483	Q
	8305250403*	50-483	Q
	8305250412*	50-483	Q
	8305250419*	50-483	Q
	8305250440*	50-483	Q
	8305250444*	50-483	Q
	8305250448*	50-483	Q
	8305250451*	50-483	Q
	8305250461*	50-483	Q
	8305250463*	50-483	Q
	8305250474*	50-483	Q
	8305250477*	50-483	Q
	8305250486*	50-483	Q
	8305250490*	50-483	Q
	8305250502*	50-483	Q
	8305250506*	50-483	Q
	8305250515*	50-483	Q
	8305250521*	50-483	Q
	8305250524*	50-483	Q
	8305250540*	50-483	Q
	8305250542*	50-483	Q
	8305250553*	50-483	Q
	8305250557*	50-483	Q
	8305250559*	50-483	Q
	8305250562*	50-483	Q
	8305250583*	50-483	Q
	8305250584*	50-483	Q
	8305260164	50-483	Q
	8305260168	50-483	Q
	8305310170	50-483	Q
Shelter Island, NY	8305180367*	50-322	H
Shoreham Opponents Coalition	8305130072	50-322	Q
Sierra Club	8305030502	50-537	Q
	8305100350	50-537	Q
	8305120291	50-537	Q
	8305160149	50-537	Q
	8305160181	50-537	Q
	8305190221	50-537	Q
	8305240553	50-537	Q
Simpson, G H	8305230220	FOIA	
Sinclair, M	8305040449	50-329	Q
	8305250215	50-329	Q
	8305250215	50-329	Q
	8305260169	50-329	Q
	8305260169	50-329	Q
Sinnissippi Alliance for the Environment (SAFE)	8305100286	50-454	Q
	8305170569*	50-454	Q
	8305170572*	50-454	Q
	8305170572*	50-454	Q
	8305170576*	50-454	Q
	8305170581*	50-454	Q
	8305170581*	50-454	Q
	8305170588*	50-454	Q
	8305170590*	50-454	Q
	8305170590*	50-454	Q
	8305170593*	50-454	Q
	8305170593*	50-454	Q
	8305200222	PR	
Small Business Administration	8305200134*	CONTRACT	
Snell & Wilmer	8305030594	50-529	Q
	8305240482	50-529	Q
	8305310215	50-528	Q
South Carolina Electric & Gas Co.	8305030627	50-395	S
	8305030637*	50-395	S
	8305050057	50-395	S
	8305050061*	50-395	S
	8305050233	50-395	S
	8305050239*	50-395	S
	8305050317*	50-395	F
	8305050321*	50-395	F
	8305060619	50-395	P
	8305100089	50-395	S
	8305100091*	50-395	S
	8305100301	50-395	P
	8305180379	50-395	F
	8305180442	50-395	P
	8305180465	50-395	Q
	8305200311	50-395	Q
	8305200352*	50-395	Q
	8305200510	50-395	S
	8305200513	50-395	E
	8305200515*	50-395	S
	8305200626	50-395	S
	8305200633*	50-395	S
	8305250349	50-395	S
	8305250492	50-395	P
	8305270422*	50-395	Q
	8305270441*	50-395	Q
South Carolina, State of	8305060577	50-238	R
	8305060582*	50-238	R
	8305060586*	50-238	R
	8305060613*	50-238	R
	8305230428*	COMMISSION	
Southern California Edison Co	8304150372*	50-361	R
	8305020427	50-206	P
	8305030356	50-361	S
	8305030359*	50-361	S
	8305030360	50-361	S
	8305030432	50-361	S
	8305060448	50-362	S
	8305060450*	50-362	S
	8305060467	50-361	S
	8305060505	50-361	S
	8305060514*	50-361	S
	8305090278	50-361	Q
	8305100377	50-206	P
	8305120166	50-206	P
	8305120189	50-206	P
	8305160011	50-361	S
	8305160014*	50-361	S
	8305160047	50-362	S
	8305160051*	50-362	S
	8305160055	50-361	S
	8305160055	50-361	S
	8305160069*	50-361	S
	8305160101*	50-361	S
	8305160110	50-362	S
	8305160115*	50-362	S
	8305160120	50-362	S
	8305160125*	50-362	S
	8305170278	50-361	S
	8305170278	50-361	S
	8305170471	50-361	F
	8305170471	50-361	F
	8305190028	50-361	P
	8305190028	50-361	P
	8305190195	50-361	Q
	8305190195	50-361	Q
	8305190212	50-361	Q
	8305190212	50-361	Q
	8305190252	50-361	Q
	8305190252	50-361	Q
	8305240198	50-206	F
	8305240458	50-361	P
	8305240458	50-361	P
	8305240501	50-206	P
	8305240509	50-206	P
	8305250512	50-206	P
	8305270131	50-361	S
	8305270157	50-362	S
	8305270243	50-361	S
	8305270321	50-361	S
	8305270408	50-361	S
Southold, NY	8305190039	50-322	H
Southwest X-Ray	8305020061	71-6717	
	8305040671	71-495	
	8305040679*	71-495	
Spiegel & McDiarmid	8305100339	PROJ	
St Louis Univ , St Louis, MO	8305090117*	CONTRACT	
	8305170121	NUREG	
Stamiris, B	8305190216	50-329	Q
	8305260166	50-329	Q
Standardized Nuclear Unit Power Plant System	8305020073	50-482	S
	8305040430	50-482	S
	8305110014	50-482	A
	8305110014	50-482	A
	8305110014	50-482	A
	8305110047	50-482	E
	8305110047	50-482	E
	8305110047	50-482	E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305130007	50-482 A
	8305130007	50-482 A
	8305130007	50-482 A
	8305180393	50-482 E
	8305310175	50-482 A
State, Dept of	8305130273	XPORTLIC
State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs	8305060687	XPORTLIC
Steinberg, Greenstein, Gorelick, Price & Lavezon	8305230203	FOIA
Stone & Webster Engineering Corp	8305030271	50-275 R
	8305030282*	50-275 R
	8305030461	PR
	8305050069	50-423 K
	8305100173	50-275 R
	8305100179*	50-275 R
	8305100185*	50-275 R
	8305120203	50-275 R
	8305120211*	50-275 R
	8305120216*	50-275 R
	8305170511	50-275 R
	8305170517*	50-275 R
	8305180377	50-275 R
	8305180383	PR
	8305180454	PR
	8305180463*	50-358 F
	8305230213	50-275 R
	8305230221*	50-275 R
	8305230556	50-275 R
	8305230559*	50-275 R
	8305230701*	50-410 A
	8305250406	PR
	8305250466	50-275 R
	8305250467*	50-275 R
	8305270003	PR
	8305310186	50-275 R
	8305310191*	50-275 R
Stone & Webster, Inc	8305030539	50-275 R
	8305030545*	50-275 R
	8305240223	50-329 A
Storr, J F.	8305230603*	50-410 A
Structural Dynamics Research Corp	8303240487*	50-313 P
	8303240495*	50-313 P
Structural Mechanics Associates	8305170544*	50-329 A
Suffolk County, NY	8305050001	50-322 G
	8305050005*	50-322 G
	8305050007	50-322 G
	8305060518	50-322 G
	8305090136*	50-322 G
	8305100157	50-322 G
	8305100239*	50-322 G
	8305120297	50-322 G
	8305120300*	50-322 G
	8305120329	50-322 G
	8305120332*	50-322 G
	8305130069	50-322 G
	8305240548	50-322 G
	8305310063	50-322 G
Sugarman, R J	8305310013	50-352 G
Sunflame Appliances, Ltd	8305120471*	40-215
	8305120476*	40-215
Sunflower Alliance	8305040325	50-440 G
	8305040325	50-440 G
	8305040487	50-440 G
	8305040487	50-440 G
	8305040548	50-440 G
	8305040548	50-440 G
	8305100294	50-440 G
	8305100294	50-440 G
	8305100367	50-440 G
	8305100367	50-440 G
Sweden	8305060052	XPORTLIC
	8305180818	XPORTLIC
	8305260060	XPORTLIC
Syncor International	8305060294	PR
TERA Corp	8304220515	50-329 A
	8305200553	50-329 A
	8305200553	50-329 A
	8305200567*	50-329 A
	8305200567*	50-329 A
	8305200575*	50-329 A
	8305310198	50-329 R
	8305310198	50-329 R
	8305310203*	50-329 R
	8305310203*	50-329 R
Teledyne Engineering Services	8305030282*	50-275 R
	8305050299	50-275 R
	8305050303*	50-275 R
	8305100225*	50-322 G
	8305180393	50-275 R
	8305180403*	50-275 R
	8305200358	50-275 R
	8305200364*	50-275 R
	8305240342	50-322 A
	8305270001	50-322 A
	8305270119*	50-245 P
	8305270296	50-275 P
	8305270305*	50-275 P
	8305270317	50-275 P
Teledyne Wah Chang Albany	8305090014	XPORTLIC
	8305090114	XPORTLIC
Tennessee Valley Authority	8304190499	50-327 B
	8304190537*	50-327 B
	8305030041	50-390 A
	8305030041	50-390 A
	8305030072	50-390 B
	8305030072	50-390 B
	8305030082	50-390 B
	8305030082	50-390 B
	8305030121	50-390 A
	8305030121	50-390 A
	8305030176	50-327 B
	8305030183*	50-327 B
	8305030252	50-438 B
	8305030252	50-438 B
	8305030266	50-296 B
	8305030272*	50-296 B
	8305030370	50-438 B
	8305030370	50-438 B
	8305030434	50-390 A
	8305030434	50-390 A
	8305030501	50-259 B
	8305030543	50-390 E
	8305030543	50-390 E
	8305030558	50-438 A
	8305030569	50-327 B
	8305030578	50-390 B
	8305030578	50-390 B
	8305030579*	50-327 B
	8305030606	50-390 A
	8305030606	50-390 A
	8305030625	50-259 G
	8305030631*	50-259 G
	8305040253	50-390 A
	8305040253	50-390 A
	8305040511	50-259 P
	8305040511	50-259 P
	8305040511	50-259 P
	8305040517*	50-259 P
	8305040517*	50-259 P
	8305040517*	50-259 P
	8305040633*	50-259 F
	8305040655*	50-259 F
	8305050047	50-390 B
	8305050047	50-390 B
	8305050067	50-390 B
	8305050067	50-390 B
	8305050078	50-390 B
	8305050078	50-390 B
	8305050120	50-438 B
	8305050120	50-438 B
	8305050122	50-438 B
	8305050122	50-438 B
	8305050123	50-327 B
	8305050128*	50-327 B
	8305050152	50-328 B
	8305050152	50-328 B
	8305050152	50-328 B
	8305050152	50-328 B
	8305050152	50-328 B
	8305050152	50-328 B
	8305050183	50-327 B
	8305050188	50-390 B
	8305050188	50-390 B
	8305050188	50-390 B
	8305050188	50-390 B
	8305050188	50-390 B
	8305050206*	50-327 B
	8305050211	50-328 B
	8305050217*	50-328 B

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305050218	50-328	S
	8305050224*	50-328	S
	8305050232	50-390	S
	8305050232	50-390	S
	8305050238	50-260	S
	8305050243	50-390	S
	8305050243	50-390	S
	8305050245*	50-260	S
	8305050266	50-259	S
	8305050272*	50-259	S
	8305100012	50-259	S
	8305100014*	50-259	S
	8305100031	50-260	S
	8305100036*	50-260	S
	8305100081	50-259	S
	8305100083*	50-259	S
	8305100101	50-327	F
	8305100101	50-327	F
	8305100107	50-296	S
	8305100113*	50-296	S
	8305100189	50-518	A
	8305100193*	50-518	A
	8305100234	50-259	F
	8305100234	50-259	F
	8305100234	50-259	F
	8305100240	50-438	A
	8305100240	50-438	A
	8305100285	50-260	S
	8305100292*	50-260	S
	8305100358	50-438	A
	8305100369*	50-438	A
	8305110292	50-439	S
	8305110304	50-438	S
	8305110304	50-438	S
	8305110317	50-390	S
	8305110319	50-390	S
	8305110319	50-390	S
	8305110319	50-390	S
	8305110319	50-390	S
	8305110325	50-327	S
	8305110329*	50-327	S
	8305110355	50-259	S
	8305110367*	50-259	S
	8305110373	50-327	S
	8305110382*	50-327	S
	8305110406	50-438	S
	8305110406	50-438	S
	8305110409	50-328	S
	8305110419*	50-328	S
	8305110438	50-537	Q
	8305110441	50-439	S
	8305110448	50-537	Q
	8305110449*	50-537	Q
	8305110505	50-391	S
	8305130003	50-259	P
	8305130020	50-390	E
	8305130029	50-327	P
	8305130029	50-327	P
	8305130041	50-327	F
	8305130085	50-259	S
	8305130089	50-439	S
	8305130091*	50-259	S
	8305130131	50-260	S
	8305130133	50-390	S
	8305130133	50-390	S
	8305130141*	50-260	S
	8305130147	50-438	S
	8305130147	50-438	S
	8305130154	50-438	S
	8305130154	50-438	S
	8305130217	50-390	S
	8305130217	50-390	S
	8305170030	50-296	S
	8305170034*	50-296	S
	8305170145	50-327	P
	8305170145	50-327	P
	8305170237	50-566	A
	8305170240*	50-566	A
	8305170288	50-390	S
	8305170289	50-390	S
	8305170299	50-390	S
	8305170299	50-390	S
	8305170330	50-260	S
	8305170340*	50-260	S
	8305200187	50-438	S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305200187	50-438	S
	8305200274	50-390	S
	8305200274	50-390	S
	8305200275	50-390	S
	8305200275	50-390	S
	8305200288	50-260	S
	8305200300*	50-260	S
	8305200325	50-390	A
	8305200325	50-390	A
	8305200343	50-390	S
	8305200343	50-390	S
	8305200387	50-390	S
	8305200420	50-260	S
	8305200426*	50-260	S
	8305200427	50-327	S
	8305200432*	50-327	S
	8305200519	50-438	S
	8305200519	50-438	S
	8305200569	50-438	S
	8305200577	50-327	S
	8305200581*	50-327	S
	8305230433	50-390	S
	8305230433	50-390	S
	8305230447	50-390	S
	8305230447	50-390	S
	8305230482	50-390	S
	8305230482	50-390	S
	8305230530	50-327	S
	8305230536*	50-327	S
	8305230545	50-438	S
	8305230545	50-438	S
	8305230551	50-438	S
	8305230551	50-438	S
	8305230565	50-438	S
	8305230565	50-438	S
	8305230569	50-390	S
	8305230569	50-390	S
	8305230575	50-390	S
	8305240323	50-327	R
	8305240323	50-327	R
	8305240394	50-327	P
	8305250342	50-328	S
	8305250357	50-260	S
	8305250380	50-328	S
	8305250400	50-328	S
	8305250402	50-259	S
	8305250421	50-390	S
	8305250421	50-390	S
	8305250425	50-390	A
	8305250425	50-390	A
	8305250433	50-328	S
	8305250439	50-390	S
	8305250473	50-259	P
	8305250473	50-259	P
	8305250508	50-296	S
	8305250526	50-327	S
	8305250532	50-327	S
	8305260307	50-327	S
	8305270021	50-259	P
	8305270030	50-259	P
	8305270133	50-390	Q
	8305270171	50-259	Q
	8305270177	50-259	Q
	8305270206*	50-259	Q
	8305270206*	50-259	Q
	8305270206*	50-259	Q
	8305270233*	50-390	Q
	8305270233*	50-390	Q
	8305270355*	50-259	Q
	8305270386*	50-438	Q
	8305270567*	50-390	Q
	8305270592*	50-438	Q
	8305270592*	50-438	Q
	8305270597*	50-438	Q
	8305270608*	50-438	Q
	8305270652*	50-259	Q
	8305270660*	50-259	Q
	8305270660*	50-259	Q
	8305270660*	50-259	Q
	8305310039	50-390	E
	8305310053	50-327	P
	8305310053	50-327	P
	8305310054	50-296	S
	8305310057*	50-327	P
	8305310057*	50-327	P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305310077	50-327 Q
	8305310138	50-438 S
	8305310138	50-438 S
	8305310167	50-327 F
	8305310172	50-390 S
	8305310189	50-327 P
	8305310193	50-438 S
	8305310193	50-438 S
	8305310214	50-438 S
	8305310214	50-438 S
Teton Exploration Drilling Co , Inc	8305130281	40-8728
Texas A&M Univ , College Station, TX	8305050252	50-128 P
	8305050257*	50-128 P
	8305090073*	50-128 Q
	8305090586*	50-445 Q
	8305180626	71-5607
	8305230697	71-5607
	8305250328	50-128 R
Texas Instruments, Inc	8305230680*	50-410 A
Texas Utilities Generating Co	8305050018	50-445 Q
	8305090507	50-445 T
	8305090507	50-445 T
	8305090513*	50-445 T
	8305090513*	50-445 T
	8305090517*	50-445 T
	8305090517*	50-445 T
	8305090521*	50-445 T
	8305090521*	50-445 T
	8305090523*	50-445 T
	8305090525*	50-445 T
	8305090530*	50-445 T
	8305090530*	50-445 T
	8305090726*	50-445 A
	8305100267	50-445 Q
	8305100267	50-445 Q
	8305100270	50-445 Q
	8305100270	50-445 Q
	8305100295	50-445 Q
	8305100295	50-445 Q
	8305100321	50-445 Q
	8305100321	50-445 Q
	8305130260	50-445 Q
	8305130260	50-445 Q
	8305160138	50-445 K
	8305160138	50-445 K
	8305160141*	50-445 K
	8305160141*	50-445 K
	8305170029	70-2932
	8305190002	70-2932
	8305200298	50-445 S
	8305200298	50-445 S
	8305200419*	50-445 Q
	8305200674*	50-445 Q
Texas Utilities Services, Inc	8305100125	50-445 A
	8305100130	50-445 R
	8305100135*	50-445 R
	8305310151	50-445 A
Texas, State of	8305090510*	50-445 T
Texas, Univ of	8305100005	50-192 P
Three Mile Island Alert	8305100212	50-289 Q
	8305180369	PR
	8305200669	50-289 Q
	8305240444	50-289 Q
	8305240449	50-289 Q
Toledo Edison Co	8305040305	50-346 P
	8305040472	50-346 P
	8305040480*	50-346 P
	8305040491	50-346 P
	8305040497*	50-346 P
	8305040503*	50-346 P
	8305060395	50-346 P
	8305060519	50-346 Q
	8305060523*	50-346 Q
	8305060601*	50-346 F
	8305060608*	50-346 F
	8305060699*	50-346 F
	8305060702*	50-346 F
	8305110385	50-346 P
	8305110437	50-346 P
	8305130032	50-346 P
	8305130093	50-346 S
	8305130095*	50-346 S
	8305130190	50-346 S
	8305130195*	50-346 S
	8305130201*	50-346 S
	8305130205*	50-346 S
	8305170162	50-346 S
	8305170171*	50-346 S
	8305170201	50-346 S
	8305170205*	50-346 S
	8305170462	50-346 P
	8305180411	50-346 P
	8305190149	50-346 R
	8305190154*	50-346 R
	8305200337*	50-346 Q
	8305200514*	50-346 Q
	8305200520*	50-346 Q
	8305200527*	50-346 Q
	8305200592	50-346 P
	8305230716	50-346 P
	8305240072*	50-346 Q
	8305240219	50-346 S
	8305240251	50-346 F
	8305240341	50-346 S
	8305240351	50-346 P
	8305240423	50-346 P
	8305240241	50-346 P
	8305260245*	50-346 P
	8305260248*	50-346 P
	8305260293	50-346 S
	8305260303	50-346 Q
	8305310038	50-346 S
Torrey Pines Technology	8305020367	50-358 A
	8305020368*	50-358 A
	8305020432	50-358 A
Transnuclear, Inc	8305130301	XPORTLIC
	8305180831	XPORTLIC
	8305190452	XPORTLIC
	8305230107	71-9015
	8305230118*	71-9015
	8305230125*	71-9015
	8305260097	XPORTLIC
Transportation, Dept of	8305230234*	FOIA
Trial Lawyers for Public Justice	8305180792*	CONTRACT
Twomey, Latham & Shea	8305100201	50-322 Q
	8305180449	PR
US Ecology, Inc (formerly Nuclear Engineering)	8305030517	27-39
	8305110134	27-48
	8305110155	27-48
Underwriters Laboratory	8305090058*	CONTRACT
Uniformed Services Univ of the Health Sciences	8305270035*	50-320 P
Union 76 Minerals Exploration Co	8305060389	40-8584
Union Carbide Corp	8305020021	XPORTLIC
	8305060349	REG
	8305130346	ACRS
	8305170504*	50-54 Q
	8305170508*	50-54 Q
	8305180334	PR
	8305260386	40-299
	8305260395	40-299
	8305260399*	40-299
Union Electric Co	8303240307	50-483 A
	8303240311*	50-483 A
	8304150354	50-482 S
	8305030263*	50-483 Q
	8305030467	50-483 Q
	8305060293*	50-483 Q
	8305170136*	50-483 Q
	8305170188*	50-483 Q
	8305170227*	50-483 Q
	8305190249	50-483 Q
	8305200518*	50-483 Q
	8305250205	50-483 Q
	8305250294	50-483 Q
	8305250297*	50-483 Q
	8305250300*	50-483 Q
	8305250304*	50-483 Q
	8305250341*	50-483 Q
	8305250346*	50-483 Q
	8305250351*	50-483 Q
	8305250354*	50-483 Q
	8305250356*	50-483 Q
	8305250358*	50-483 Q
	8305250359*	50-483 Q
	8305250360*	50-483 Q
	8305250363*	50-483 Q
	8305250372*	50-483 Q
	8305250383*	50-483 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8305250388*	50-483	Q
	8305250394*	50-483	Q
	8305250401*	50-483	Q
	8305250403*	50-483	Q
	8305250408*	50-483	Q
	8305250412*	50-483	Q
	8305250419*	50-483	Q
	8305250424*	50-483	Q
	8305250428*	50-483	Q
	8305250432*	50-483	Q
	8305250436*	50-483	Q
	8305250440*	50-483	Q
	8305250444*	50-483	Q
	8305250448*	50-483	Q
	8305250451*	50-483	Q
	8305250458*	50-483	Q
	8305250461*	50-483	Q
	8305250463*	50-483	Q
	8305250468*	50-483	Q
	8305250474*	50-483	Q
	8305250477*	50-483	Q
	8305250482*	50-483	Q
	8305250486*	50-483	Q
	8305250490*	50-483	Q
	8305250496*	50-483	Q
	8305250502*	50-483	Q
	8305250506*	50-483	Q
	8305250511*	50-483	Q
	8305250515*	50-483	Q
	8305250521*	50-483	Q
	8305250524*	50-483	Q
	8305250531*	50-483	Q
	8305250536*	50-483	Q
	8305250540*	50-483	Q
	8305250542*	50-483	Q
	8305250544*	50-483	Q
	8305250548*	50-483	Q
	8305250552*	50-483	Q
	8305250553*	50-483	Q
	8305250557*	50-483	Q
	8305250559*	50-483	Q
	8305250562*	50-483	Q
	8305250566*	50-483	Q
	8305250573*	50-483	Q
	8305250576*	50-483	Q
	8305250580*	50-483	Q
	8305250583*	50-483	Q
	8305250584*	50-483	Q
	8305250587*	50-483	Q
	8305250589*	50-483	Q
	8305260164	50-483	Q
	8305260168	50-483	Q
	8305260173*	50-483	Q
Union of Concerned Scientists	8305030608	50-247	Q
	8305030608	50-247	Q
	8305030619*	50-247	Q
	8305030619*	50-247	Q
	8305030629*	50-247	Q
	8305030629*	50-247	Q
	8305030641*	50-247	Q
	8305030641*	50-247	Q
	8305030646*	50-247	Q
	8305030646*	50-247	Q
	8305030652*	50-247	Q
	8305060382	PR	
	8305100204	50-247	Q
	8305160073	50-289	Q
	8305180356	PR	
	8305230005	FOIA	
	8305230243	FOIA	
	8305240249	50-245	P
	8305240538	50-247	Q
	8305240538	50-247	Q
	8305240542*	50-247	Q
	8305240542*	50-247	Q
United Engineers & Constructors, Inc (subs. of Raytheon Co.)	8305200495	50-443	S
United Nuclear Corp	8305200177	70-371	
	8305250578*	70-371	
	8305250582*	70-371	
	8305250586*	70-371	
	8305260371	70-820	
Uranium Resources, Inc	8305160228	40-8786	
Utah, Univ. of	8305190349	50-407	P
	8305190360*	50-407	P
	8305190369*	50-407	P
	8305190380*	50-407	P
Utility Workers Union of America	8305240454	50-247	Q
Vermont Yankee Nuclear Power Corp	8305050101	50-271	S
	8305050108*	50-271	S
	8305130103	50-271	P
	8305170006	50-271	R
	8305170007*	50-271	R
	8305200517	50-271	P
	8305240195	50-271	P
	8305240343	50-271	V
	8305250569	50-271	P
	8305250574*	50-271	P
	8305270141	50-271	P
	8305310212	50-271	F
Vet Admin Hosp Omaha, NE	8305310012	50-131	P
Virginia Electric & Power Co	8305030158	50-338	S
	8305030165*	50-338	S
	8305030279	50-339	S
	8305030283*	50-339	S
	8305030357	50-339	S
	8305030364*	50-339	S
	8305030555	50-338	Q
	8305030555	50-338	Q
	8305030611	50-338	S
	8305030615*	50-338	S
	8305030635	50-339	S
	8305030640*	50-339	S
	8305040173	50-338	P
	8305040173	50-338	P
	8305040409	50-338	P
	8305040409	50-338	P
	8305050118	50-281	S
	8305050121*	50-281	S
	8305050126	50-280	F
	8305050130*	50-281	S
	8305050186	50-338	S
	8305050191*	50-338	S
	8305050210	50-339	S
	8305050215*	50-339	S
	8305050271	50-339	S
	8305050276*	50-339	S
	8305060061	50-281	Q
	8305060100	50-281	F
	8305060283	50-339	P
	8305060556	50-280	P
	8305060556	50-280	P
	8305060561*	50-280	P
	8305060561*	50-280	P
	8305090139	50-280	Q
	8305100023	50-339	S
	8305100029*	50-339	S
	8305100108	50-280	P
	8305100108	50-280	P
	8305100111*	50-280	P
	8305100111*	50-280	P
	8305100115	50-280	S
	8305100120*	50-280	S
	8305100129*	50-280	S
	8305100259	50-339	S
	8305100265*	50-339	S
	8305100315	50-280	Q
	8305110285	50-338	S
	8305110288*	50-338	S
	8305110330	50-339	S
	8305110336*	50-339	S
	8305110453	50-339	S
	8305110465*	50-339	S
	8305120047	50-339	Q
	8305120244	50-281	P
	8305120250*	50-281	P
	8305120386	50-339	P
	8305130058	50-280	F
	8305130058	50-280	F
	8305130058	50-280	F
	8305130058	50-280	F
	8305130125	50-281	S
	8305130130*	50-281	S
	8305130136*	50-281	S
	8305130198	50-280	S
	8305130203*	50-280	S
	8305130228	50-280	S
	8305130243*	50-280	S
	8305170406	50-338	S
	8305170412*	50-338	S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305180372	50-280 P
	8305180372	50-280 P
	8305190219	50-338 Q
	8305190253	50-339 P
	8305200146	50-338 S
	8305200163	50-280 P
	8305200163	50-280 P
	8305200279	50-339 S
	8305200284*	50-339 S
	8305200499	50-280 P
	8305200499	50-280 P
	8305200574	50-338 S
	8305200583*	50-338 S
	8305230424	50-281 S
	8305230432*	50-281 S
	8305230451*	50-281 S
	8305250288	50-338 S
	8305250384	50-339 S
	8305250417	50-338 S
	8305260232	50-280 P
	8305260323	50-338 P
	8305260323	50-338 P
	8305270143	50-338 Q
	8305270150	50-339 P
	8305270220	50-338 P
	8305270220	50-338 P
	8305270248*	50-280 Q
	8305270323	50-338 S
	8305270335	50-339 S
	8305270407*	50-338 Q
	8305270416*	50-338 Q
	8305270426*	50-338 Q
	8305310099	50-339 P
Virginia, Univ of, Charlottesville, VA	8305230548	50-396 P
	8305270226*	50-62 Q
WSI Corp	8305090300*	CONTRACT
	8305260087*	CONTRACT
Wabash Valley Power Association, Inc	8305130073	50-546 Q
	8305130073	50-546 Q
	8305130098	50-546 Q
	8305130098	50-546 Q
	8305130244	50-546 Q
	8305130244	50-546 Q
	8305170306	50-546 A
	8305200289	50-546 F
Wall Street Journal	8305180003	FOIA
Washington Public Power Supply System	8303290382	50-397 G
	8305020473	50-460 Q
	8305030166	50-460 K
	8305030172*	50-460 K
	8305030300	50-397 S
	8305030324	50-397 A
	8305030489	50-508 S
	8305030500	50-397 S
	8305030507	50-397 S
	8305040365	TOPREP
	8305040613*	TOPREP
	8305050009	50-460 Q
	8305050019	50-460 Q
	8305050159	50-397 Q
	8305050164*	50-397 Q
	8305060491	50-508 Q
	8305100097	50-508 A
	8305100110	50-397 A
	8305100246	50-460 K
	8305100304	50-508 A
	8305120233	50-397 K
	8305120236*	50-397 K
	8305130106	50-397 S
	8305130245	50-397 R
	8305160041	50-397 E
	8305160049	50-508 S
	8305170156	50-397 A
	8305170516	50-460 Q
	8305230300	50-305 P
	8305230308*	50-305 P
	8305240465	50-460 Q
	8305310164	50-305 R
Washington, State of	8305100416*	50-237 Q
	8305310076	50-460 Q
Waste Management Group, Inc	8305110158	WASTE MGT
Water, Waste & Land, Inc	8305260388	40-229
We Try Harder, Inc	8305050389*	CONTRACT
West Branch Conservation Association	8305050035	50-247 Q
	8305200605	50-247 Q
West Valley Agricultural Protection Council, Inc	8305160032	50-529 Q
	8305160032	50-529 Q
	8305160034	50-529 Q
	8305160034	50-529 Q
	8305160080	50-529 Q
	8305160086	50-529 Q
West Valley Nuclear Services Co , Inc	8305230020*	50-201 P
	8305240618*	50-201 P
West Virginia Univ	8305260308	50-129 M
Westchester County Association, Inc	8305240517	50-247 H
Westchester County, NY	8305190342	50-247 Q
	8305240533	50-247 T
	8305240533	50-247 T
	8305240539*	50-247 T
	8305240539*	50-247 T
Western Nuclear, Inc (subs of Phelps Dodge Corp)	8305020407	40-1162
	8305020417*	40-1162
	8305250175	40-1162
Westinghouse Electric Corp	8304180548	TOPREP
	8304180558*	TOPREP
	8305020075	70-698
	8305020076*	70-698
	8305020272	50-266 P
	8305020292*	50-266 P
	8305030426	TOPREP
	8305030438*	TOPREP
	8305050200	TOPREP
	8305050208*	TOPREP
	8305050288*	50-369 P
	8305090015	XPORTLIC
	8305090202*	PROJ
	8305090212	PROJ
	8305100273*	50-334 Q
	8305110377*	50-334 P
	8305110398*	50-334 P
	8305110427	50-334 S
	8305130303	XPORTLIC
	8305170302	TOPREP
	8305170307*	TOPREP
	8305170311*	TOPREP
	8305170314	50-454 Q
	8305170314	50-454 Q
	8305170319	50-454 Q
	8305170319	50-454 Q
	8305170334	50-454 Q
	8305170334	50-454 Q
	8305170408	50-454 T
	8305170408	50-454 T
	8305170411*	50-454 T
	8305170411*	50-454 T
	8305170522	50-454 Q
	8305170522	50-454 Q
	8305170554	TOPREP
	8305180019	71-9070
	8305180262	TOPREP
	8305180273*	TOPREP
	8305200304	PR
	8305200315*	GA999
	8305200332*	GA999
	8305200681*	50-373 P
	8305230255	TOPREP
	8305240346*	GA999
	8305260057*	XPORTLIC
	8305260070	XPORTLIC
	8305260330	XPORTLIC
	8305270006	TOPREP
	8305270012*	TOPREP
	8305270459*	70-1151
	8305270481	TOPREP
	8305270488*	TOPREP
Whittaker Corp	8305120264*	40-672
	8305120268*	40-672
	8305120269*	70-82
	8305120279*	40-672
Williams-Robinette & Associates, Inc.	8305090012*	CONTRACT
Wilson, R.	8305170614*	CONTRACT
	8305170456	50-400 Q
	8305170456	50-400 Q
	8305170486	50-400 Q
	8305170486	50-400 Q
	8305170491	50-400 Q
Wilt, D D	8305170491	50-400 Q
	8305040487	50-440 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8305040487	50-440 G
	8305040548	50-440 G
	8305040548	50-440 G
	8305100294	50-440 G
	8305100294	50-440 G
	8305100367	50-440 G
	8305100367	50-440 G
	8305310031	50-440 H
Wisconsin Electric Power Co	8305020438	50-266 G
	8305030275	50-301 S
	8305030280*	50-301 S
	8305030376	50-266 S
	8305030382*	50-266 S
	8305030523	50-266 F
	8305060408	50-266 P
	8305060408	50-266 P
	8305110075	50-266 P
	8305110075	50-266 P
	8305110181	50-266 P
	8305110181	50-266 P
	8305110187*	50-266 P
	8305110187*	50-266 P
	8305110201	50-266 P
	8305110201	50-266 P
	8305120408	50-266 G
	8305120408	50-266 G
	8305130009	50-266 P
	8305130009	50-266 P
	8305130034	50-266 S
	8305160169	50-266 R
	8305160171*	50-266 R
	8305170144*	50-266 G
	8305170252*	50-266 G
	8305170263*	50-266 G
	8305170291	50-266 G
	8305190226	50-266 S
	8305200229	50-266 G
	8305200229	50-266 G
	8305230724	50-266 P
	8305240131	50-266 P
	8305240331	50-301 S
	8305240350	50-301 S
	8305240379	50-266 S
	8305240412	50-301 S
	8305240497	50-266 P
	8305240497	50-266 P
	8305270241	50-266 G
	8305270558	50-266 G
	8305270558	50-266 G
Wisconsin Public Service Corp	8305030314	50-305 G
	8305030600	50-305 P
	8305030602*	50-305 P
	8305040009*	50-305 F
	8305040014*	50-305 F
	8305050106	50-305 R
	8305100102	50-305 P
	8305100114	50-305 P
	8305100389	50-305 S
	8305100397*	50-305 S
	8305110003	50-305 P
	8305130250	50-305 R
	8305130251*	50-305 R
	8305170150	50-305 P
	8305170267	50-305 S
	8305170271*	50-305 S
	8305170323	50-305 S
	8305180261	50-305 G
	8305230728	50-305 P
	8305270009	50-305 P
	8305270198	50-305 S

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Wisconsin, State of	8305040660*	CONTRACT
	8305310154	50-305 R
Wright, D	8305110198*	CONTRACT
Wyle Laboratories	8305100349*	GA999
	8305100355*	GA999
	8305110089*	50-373 P
	8305240403*	GA999
	8305270011*	50-261 P
Wyoming Mineral Corp	8305260144	40-8502
Wyoming, State of	8305030253	40-8728
	8305030262*	40-8728
	8305030273*	40-8728
	8305030709	40-8728
	8305030711	40-2259
	8305030713	40-8697
	8305040002	40-8584
	8305060222	40-8348
	8305060226	40-8380
	8305060357	40-8714
	8305060651	40-8697
	8305130363	40-8064
	8305160205	40-2259
	8305160209	40-8502
	8305160211	40-8584
	8305160274	40-8380
	8305160276	40-299
	8305170242	40-8064
	8305200031	40-4492
	8305250193	40-8102
	8305250241	40-8697
	8305260363	40-299
	8305260368	40-299
	8305260389	40-299
Yale Univ , New Haven, CT	8305030646*	50-247 G
Yankee Atomic Electric Co	8305030590	50-29 S
	8305030597*	50-29 S
	8305050006	50-443 F
	8305050263	50-29 S
	8305050268*	50-29 S
	8305060192	50-29 F
	8305060215	50-29 F
	8305100228	50-29 P
	8305110010	50-29 F
	8305110020*	50-29 F
	8305170459	50-29 P
	8305180342	PR
	8305190164	50-443 S
	8305200353	50-443 S
	8305200353	50-443 S
	8305200402	50-443 S
	8305200402	50-443 S
	8305240358	50-29 P
	8305240364	50-29 P
	8305250244	50-443 S
	8305270019	50-443 A
	8305270019	50-443 A
Yorktown, NY	8305240541	50-247 H
	8305240546	50-247 G
	8305240546	50-247 G
	8305270583	50-247 G
	8305270583	50-247 G
Zack Co	8305190112*	50-329 S

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY		OTHER REPORT NUMBER
0383-03	8305130086*	50-244	P	
04-0640-0062 R01	8305030564*	50-298	P	
186-028-14	8305200110*	50-277	G	
186-028-24	8305270052*	50-271	G	
282 R01	8305120250*	50-281	P	
45307-1	8305270011*	50-261	P	
46511-3	8305110089*	50-373	P	
71-1C2-RADMC-R1	8305020292*	50-266	P	
77-1140899-01	8305090464*	50-302	P	
77-1141514-00	8305020404*	50-329	E	
77-1142162-00	8305110443*	50-346	P	
8 15 1-0 R01	8305270501*	50-454	G	SAD-401
8206100210	8206100210*	RES		SAI-1-186-03-04
83-154 R02	8305030412*	50-286	P	
83-154 R03	8305200412*	50-286	P	
8303080182	8303080182	RES		SAI-1-186-03-61
8303080187	8303080187*	RES		SAI-1-186-03-61
8303080194	8303080194	RES		SAI-1-186-03-61
8303080202	8303080202*	RES		SAI-1-186-03-61
8303080209	8303080209	RES		SAI-1-186-03-61
8303080215	8303080215*	RES		SAI-1-186-03-61
8305030025	8305030025	RES		
8305060349	8305060349	RES		
8305110062	8305110062	RES		
8305110083	8305110083	RES		
8305130292	8305130292	RES		
8305250155	8305250155	RES		NRC-60-10-01-05
8305250168	8305250168	RES		
8305250174	8305250174	RES		
AB-442	8305030347*	50-335	R	
APL-01-014	8303240487*	50-313	P	
APL-02-013	8303240495*	50-313	P	
B14/TER-B-7	8303310020*	50-333	P	TAC 44373
BAW-1774	8305270309*	50-269	P	
BNWL-2159	8011180782*	MISC		NRC-1
BWNP-20004 (6-76) R3	8305020392*	50-312	P	15-1120580-03
CEN-247(N)-NP	8305120252*	50-336	P	
CGS/B116R02B	8305310211	WASTE MGT		
COM05B 0011 0007	8305200307*	50-237	S	
CPC-2A R01	8305240565*	50-155	P	
CQD-003490 R00	8305190303*	50-373	P	
CR 729 RA	8305100395*	50-438	A	
CR 730 RA	8305100382*	50-438	A	
CRBRP-3 V02 R05	8305310003*	50-537	A	
CT-25086A	8305170311*	TOPREP		
DRR-AF-001-DB R00	8305200688*	50-373	P	
E-3508 R01	8305230125*	71-9015		
EMD-043449	8305200301*	50-237	S	5484-23
EB-LPD-83-001 R01	8305230292*	50-537	A	
F-A5818-1	8305190322*	50-387	S	
FATE-82-114	8301060137*	50-309	P	
GPC-04-104 R01	8305060055*	50-321	P	GPC004 0104
GPC-07-102 RA DRFT	8305310097*	50-366	G	
LMBE-75/0363&191/029	8305230687*	50-410	A	
LMBE-76/0081&191-033	8305230661*	50-410	A	
LMBE-82/0091&191-058	8305230587*	50-410	A	
MPGP-1 R06 DRFT	8305190300*	50-329	G	MPGP-1
NEDO-24011-A-5 ERR	8305090497*	TOPREP		B2NED057
NEDO-24011-A011-A-US	8305090495*	TOPREP		B2NED058
NEDO-24592 R01	8305260325*	50-324	P	B1NED0078
NEDO-24712-A	8305040466*	TOPREP		79NED122R1
NMP11K	8304110519*	50-220	R	
NP-PS-53-0378 R0	8305030343*	TOPREP		
NUC3-E1	8305100144*	50-293	R	
NUREG-0020 V07 N01	8305170128	NUREG		
NUREG-0040 V07 N01	8305040689	NUREG		
NUREG-0472 D07 R03	8305060007*	50-266	P	PWR-BTB-1
NUREG-0485 V05 N03	8305060680	NUREG		
NUREG-0540 V04 N01	8305040693	NUREG		
NUREG-0590 V12 N04	8305170098	NUREG		
NUREG-0728 R01	8305090046	NUREG		
NUREG-0748 V03 N03	8305110240	NUREG		
NUREG-0800 R04	8305170092	NUREG		PSRP-6 2 2 R4
NUREG-0827	8305040682	50-409	P	
NUREG-0837 V02 N03ER	8305170579	NUREG		
NUREG-0869 FC	8305170123	NUREG		
NUREG-0871 V02 N02	8305110114	NUREG		
NUREG-0887 S03	8305170096	50-440	E	
NUREG-0896 S01	8305170668	50-443	E	
NUREG-0897 FC	8305170118	NUREG		
NUREG-0940 V02 N01	8305110174	NUREG		
NUREG-0941	8305190796	NUREG		
NUREG-0954 S01	8305170712	50-413	E	
NUREG-0968 S01	8305170057	50-537	E	
NUREG-0969	8305110118	50-358	A	
NUREG-0972	8305170149	50-400	D	
NUREG-1000 V01	8305170674	50-272	S	
NUREG/BR-0006 R01	8305090040	NUREG		
NUREG/BR-0006 R01 ER	8305090035	NUREG		
NUREG/BR-0025 V09 N4	8305170137	NUREG		
NUREG/BR-0051 V04 N6	8305040740	NUREG		
NUREG/CP-0035	8305110119	NUREG		BNL-NUREG-51579
NUREG/CP-0043	8305270109	NUREG		
NUREG/CR-0169 V01	8305110482	NUREG		EGG-2037
NUREG/CR-2000 V02 N3	8305020338	NUREG		ORNL/NSIC-200
NUREG/CR-2000 V02 N4	8305310237	NUREG		ORNL/NSIC-200
NUREG/CR-2001	8305050426	NUREG		EPRI NP-2372
NUREG/CR-2003 R01	8305060675	NUREG		SAND81-7074
NUREG/CR-2069 R01	8305110120	NUREG		ORNL/NSIC-181/R
NUREG/CR-2326	8305310210	NUREG		SAND81-1994
NUREG/CR-2331 V02 N3	8305110237	NUREG		BNL-NUREG-51454
NUREG/CR-2482 V02	8305170101	NUREG		BNL-NUREG-51494
NUREG/CR-2568	8305110196	NUREG		GEAP-22046
NUREG/CR-2716 V04	8305110208	NUREG		PNL-4275-4
NUREG/CR-2743	8305110528	NUREG		SAND82-7054
NUREG/CR-2744 V02	8305110491	NUREG		SAND82-7057
NUREG/CR-2769	8305110457	NUREG		PNL-4414
NUREG/CR-2774 V04	8305110148	NUREG		ANL-82-24
NUREG/CR-2924	8305060674	NUREG		PNL-4434
NUREG/CR-3013	8305110126	50-312	P	BNL-NUREG-

REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG/CR-3016	8305180782	NUREG	PNL-4516
NUREG/CR-3073	8305110131	NUREG	BNL-NUREG-51616
NUREG/CR-3074	8305110227	NUREG	BNL-NUREG-51623
NUREG/CR-3091	8305020547	NUREG	BNL-NUREG-51630
NUREG/CR-3100	8305310209	NUREG	SAND82-2902
NUREG/CR-3114 ERR	8305130341	NUREG	ORNL/TM-8614
NUREG/CR-3117	8305090162	NUREG	
NUREG/CR-3119 V01	8305110027	NUREG	
NUREG/CR-3136	8305060233	NUREG	PNL-4604
NUREG/CR-3140	8305050432	NUREG	SAND82-2985
NUREG/CR-3173	8305170121	NUREG	
NUREG/CR-3184	8305110523	NUREG	EGG-2244
NUREG/CR-3187	8305110127	NUREG	BNL-NUREG-51653
NUREG/CR-3195	8305110518	NUREG	EGG-2246
NUREG/CR-3216	8305110467	NUREG	EGG-2249
NUREG/CR-3220	8305110162	NUREG	ANL-83-15
NUREG/CR-3229	8305060347	NUREG	
NUREG/CR-3230	8305240015	NUREG	MEA-2013
NUREG/CR-3233 V01	8305170122	NUREG	SAND82-1557
NUREG/CR-3233 V02-04	8305170132	NUREG	SAND82-1557
NUREG/CR-3235 V05-06	8305170135	NUREG	SAND82-1557
NUREG/CR-3240	8305170086	50-537	A BNL-NUREG-51663
NUREG/CR-3255	8305110476	NUREG	
NUREG/CR-3261	8305110512	NUREG	
ORNL/ENG/TM-5 DRF 01	8305260004*	71-5552	22245
P105-4-839-033 R01	8305030581*	50-275	R
PALEX-83	8305020083*	50-255	F
RB-NRR-80-102	8305250034*	FOIA	
SAI-186-028-18	8209150251*	50-250	G
SAI-186-028-39	8209200375*	50-313	P
SAI-186-029-34	8207080458*	50-321	P
SECY-82-013D	8305230070*	FOIA	
SECY-83-017	8305180328*	50-237	P
SECY-83-019	8305180322*	FOIA	
SECY-83-059	8302280090	SECY	
SECY-83-059B	8304220083	SECY	
SECY-83-067	8305250250	SECY	
SECY-83-140	8305020530	50-320	P
SECY-83-158	8305170232	50-272	S
SECY-83-195	8305270118	SECY	
SL-TR-1A R06	8305090469*	TOPREP	
SMA 13701 05R003 V05	8305170544*	50-329	A ISSUANCES DM
SR 8031-SS10 R00	8305100281*	50-352	A
TER-C5257-207/208	8208060249*	50-338	P
TER-C5257-28	8206300177*	50-309	P
TER-C5506-101/102	8305200720*	50-339	P TAC 8147
TER-C5506-356 DRFT	8305310241*	50-285	P TAC 07991
TER-C5506-358 DRFT	8305230284*	50-213	P
TER-C5506-374/375/37	8304070286*	50-269	P TAC 08065
TER-C5506-99	8209210332*	50-336	P
TR-5318-1 R01	8305270119*	50-245	P
TR-83021-1 R00	8305030178*	50-341	A
TR-83021-1 R00 ERR	8305050010*	50-341	A
UCID-19450	8209020602*	50-335	P
UCID-19450 R01	8304060471*	50-335	P
WCAP-10252	8305110398*	50-334	P
WP-0676	8305230725*	50-368	P
WPBS-GA-004 R07	8305040613*	TOPREP	
Y1003J01A46 R01	8305060076*	50-331	P
Y1003J01A53	8305100370*	50-325	P
Y1003J01A56 R01	8305270378*	50-333	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCESSION NUMBER: ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
7908080036	8305180001	83/03/09	50-498	Q
7909180214	8305180001	83/03/09	50-498	S
7911150353	8305180005	83/04/12	FOIA	
8005140296	8305180001	83/03/09	50-498	A
8005280930	8305180001	83/03/09	50-498	Q
8006090238	8305180001	83/03/09	50-498	Q
8006090440	8305180001	83/03/09	50-498	Q
8006090443	8305180001	83/03/09	50-498	A
8006180578	8305020007	83/01/11	FOIA	
8008120773	8305180001	83/03/09	50-498	A
8008250310	8305020007	83/01/11	FOIA	
8008250337	8305020007	83/01/11	FOIA	
8008250463	8305020007	83/01/11	FOIA	
8009120352	8305180001	83/03/09	50-498	Q
8010090450	8305180001	83/03/09	50-498	A
8010280578	8305180001	83/03/09	50-324	P
8010280581	8305180001	83/03/09	50-498	A
8011180782	8305040596	75/01/25	MISC	
8103130267	8305020007	83/01/11	FOIA	
8103250385	8305180001	83/03/09	50-498	Q
8103300276	8305240254	83/03/31	50-416	A
8104030770	8305020007	83/01/11	FOIA	
8104060899	8305020007	83/01/11	FOIA	
8108250739	8305240252	83/04/14	COMMISSION	
8111030653	8305090529	83/03/10	FOIA	
8111030655	8305090529	83/03/10	FOIA	
8112160259	8305120224	83/03/01	40-672	
8112290557	8305120224	83/03/01	70-925	
8201070110	8305060135	83/03/03	40-672	
8203150093	8305090529	83/03/10	50-443	F
8203180052	8305060073	83/03/14	50-206	P
8204190027	8305060073	83/03/14	50-206	P
8206100210	8206100204	82/06/08	REG	
8206300177	8305230381	83/05/11	50-309	P
8207080458	8305040769	83/04/20	50-321	P
8207080528	8305020066	83/04/29	50-255	P
8207300178	8305120488	83/03/25	50-271	Q
8208060242	8305060135	83/03/03	40-672	
8208060244	8305060135	83/03/03	40-672	
8208060249	8305090144	83/04/20	50-338	P
8208190078	8305090529	83/03/10	50-443	F
8208250506	8305190005	83/03/11	50-373	P
8209020602	8305120146	83/05/03	50-335	P
8209150251	8305090085	83/04/26	50-250	Q
8209200375	8305090147	83/04/18	50-313	P
8209210332	8305060058	83/04/21	50-336	P
8211030191	8305160195	83/03/31	50-312	Q
8211100028	8305160255	83/03/24	50-312	S
8211110645	8305160255	83/03/24	50-312	S
8211150068	8305160255	83/03/24	50-312	Q

ACCESSION NUMBER: ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8211180501	8305160195	83/03/31	50-312	Q
8212070092	8305120607	83/04/28	MISC	
8301060137	8303240026	83/03/09	50-309	P
8301120436	8305040323	83/05/04	50-247	P
8301310274	8301310260	83/01/28	50-352	K
8302250480	8305230704	83/05/16	50-470	A
8303080187	8303080182	83/02/28	REG	
8303080202	8303080194	83/02/28	REG	
8303080215	8303080209	83/02/28	REG	
8303170135	8305060648	83/05/03	50-423	A
8303240029	8303240026	83/03/09	50-309	P
8303240311	8303240307	83/03/21	50-483	A
8303240394	8303240390	83/03/23	50-537	Q
8303240487	8303240480	83/03/22	50-313	P
8303240495	8303240480	83/03/22	50-313	P
8303280136	8303280126	83/03/17	50-315	S
8303280182	8303280177	83/02/23	40-2061	
8303280325	8303280319	83/03/14	50-302	P
8303300002	8303300001	83/03/11	50-295	P
8303300003	8303300001	83/03/11	50-295	P
8303300396	8303300387	83/03/11	50-260	P
8303300401	8303300387	83/03/11	50-260	P
8303300408	8303300387	83/03/11	50-260	P
8303310020	8305030135	83/04/18	50-333	P
8304010159	8305120607	83/04/28	MISC	
8304040394	8304040391	83/03/30	50-322	U
8304040591	8305120607	83/04/28	MISC	
8304050254	8304060243	83/03/28	50-461	K
8304060126	8304060118	83/04/04	50-440	E
8304060471	8305120146	83/05/03	50-335	P
8304070286	8305130294	83/04/20	50-269	P
8304080009	8305060358	83/04/13	TOPREP	
8304110328	8304110321	83/04/07	50-416	P
8304110335	8304110321	83/04/07	50-416	P
8304110519	8304110516	83/03/30	50-220	R
8304110706	8304110696	83/03/24	50-293	S
8304120042	8304120027	83/03/30	50-321	P
8304120412	8304120409	83/03/23	50-373	Q
8304130042	8304130034	83/03/05	71-494	
8304140161	8305260322	83/05/24	50-352	Q
8304140328	8305090295	83/04/22	MISC	
8304150147	8304150143	83/03/30	50-313	Q
8304150154	8304150143	83/03/30	50-313	Q
8304150364	8304150362	83/04/01	50-440	Q
8304150372	8304150368	83/03/15	50-361	R
8304150458	8305040062	83/04/11	50-454	F
8304180420	8305260149	83/05/10	MISC	
8304180513	8304180491	83/04/06	50-311	S
8304180554	8304180541	83/04/05	70-1143	
8304180558	8304180548	83/04/12	TOPREP	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8304190537	8304190499	83/04/13	50-327	S
8304210240	8304210238	83/04/13	50-410	K
8304220257	8305060671	83/04/22	50-321	P
8304250163	8304250152	83/04/11	70-2953	
8304250190	8304250167	83/04/21	50-346	K
8304270426	8304270424	83/04/22	50-313	F
8304270427	8304270424	83/04/22	50-313	F
8304280049	8304280037	83/04/25	50-416	P
8305020004	8305020002	83/04/18	71-9177	
8305020008	8305020002	83/04/18	71-9177	
8305020010	8305020007	83/01/11	FOIA	
8305020015	8305020007	83/01/11	FOIA	
8305020016	8305020007	83/01/11	FOIA	
8305020019	8305020007	83/01/11	FOIA	
8305020022	8305020007	83/01/11	FOIA	
8305020027	8305020007	83/01/11	FOIA	
8305020031	8305020007	83/01/11	FOIA	
8305020035	8305020007	83/01/11	FOIA	
8305020039	8305020007	83/01/11	FOIA	
8305020042	8305020007	83/01/11	FOIA	
8305020047	8305020007	83/01/11	FOIA	
8305020049	8305020007	83/01/11	FOIA	
8305020057	8305020007	83/01/11	FOIA	
8305020063	8305020007	83/01/11	FOIA	
8305020070	8305020007	83/01/11	FOIA	
8305020076	8305020075	83/03/30	70-698	
8305020078	8305020072	83/04/19	50-316	S
8305020081	8305020007	83/01/11	70-378	
8305020083	8305020079	83/04/11	50-255	F
8305020090	8305020086	83/04/21	50-373	S
8305020092	8305020089	83/04/28	50-528	K
8305020095	8305020007	83/01/11	FOIA	
8305020106	8305020100	83/04/25	50-10	G
8305020114	8305020109	83/04/21	50-373	S
8305020115	8305020110	83/04/25	50-456	G
8305020137	8305020128	83/04/25	50-266	P
8305020145	8305020138	83/04/21	50-255	S
8305020151	8305020141	83/04/19	50-315	S
8305020152	8305020007	83/01/11	FOIA	
8305020154	8305020142	83/04/20	50-254	S
8305020158	8305020007	83/01/11	FOIA	
8305020160	8305020150	83/04/27	50-272	S
8305020169	8305020007	83/01/11	FOIA	
8305020170	8305020146	83/04/21	50-409	S
8305020171	8305020161	83/04/22	50-316	S
8305020172	8305020165	83/04/27	50-400	R
8305020177	8305020161	83/04/22	50-316	S
8305020178	8305020007	83/01/11	FOIA	
8305020179	8305020173	83/04/21	50-255	S
8305020182	8305020146	83/04/21	50-409	S
8305020187	8305020007	83/01/11	FOIA	
8305020191	8305020007	83/01/11	FOIA	
8305020196	8305020007	83/01/11	FOIA	
8305020198	8305020192	83/04/22	50-316	S
8305020200	8305020007	83/01/11	FOIA	
8305020201	8305020007	83/01/11	FOIA	
8305020204	8305020007	83/01/11	FOIA	
8305020207	8305020007	83/01/11	FOIA	
8305020212	8305020007	83/01/11	FOIA	
8305020215	8305020210	83/04/28	50-289	R
8305020220	8305020007	83/01/11	FOIA	
8305020232	8305020226	83/04/26	50-289	G
8305020234	8305020224	83/04/26	50-456	G
8305020236	8305020205	83/04/15	50-373	S
8305020251	8305020241	83/04/15	50-373	S
8305020256	8305020246	83/04/21	50-249	S
8305020267	8305020258	83/04/26	50-272	G
8305020268	8305020261	83/04/28	GA999	
8305020274	8305020264	83/04/11	50-341	G
8305020285	8305020264	83/04/11	50-341	G
8305020292	8305020272	83/04/13	50-266	P
8305020295	8305020289	83/02/02	GA999	
8305020296	8305020288	83/04/14	XPORTLIC	
8305020306	8305020007	83/01/11	FOIA	
8305020307	8305020289	83/02/02	GA999	
8305020312	8305020299	83/04/22	50-315	S
8305020318	8305020007	83/01/11	FOIA	
8305020319	8305020316	83/02/02	GA999	
8305020321	8305020317	83/04/22	50-315	S
8305020323	8305020007	83/01/11	FOIA	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305020324	8305020322	83/04/18	50-57	G
8305020327	8305020322	83/04/18	50-57	G
8305020329	8305020320	83/04/19	50-282	G
8305020332	8305020322	83/04/18	50-57	G
8305020339	8305020336	83/04/08	50-461	G
8305020344	8305020340	83/04/26	50-317	G
8305020348	8305020347	83/04/15	50-315	G
8305020352	8305020349	83/04/11	50-305	G
8305020353	8305020351	83/04/13	50-373	S
8305020354	8305020350	83/04/18	50-483	G
8305020356	8305020349	83/04/11	50-305	G
8305020357	8305020350	83/04/18	50-483	G
8305020360	8305020358	83/04/18	50-331	G
8305020365	8305020364	83/04/28	GA999	
8305020366	8305020364	83/04/28	GA999	
8305020368	8305020367	83/04/21	50-358	A
8305020369	8305020364	83/04/28	GA999	
8305020375	8305020372	83/04/22	50-269	P
8305020378	8305020373	83/04/25	50-368	S
8305020392	8305020384	83/04/28	50-312	P
8305020393	8305020386	83/04/26	50-309	G
8305020397	8305020389	83/04/27	50-255	G
8305020399	8305020395	83/04/26	50-213	G
8305020404	8305020398	83/04/13	50-329	E
8305020406	8305020400	83/04/26	50-470	E
8305020417	8305020407	83/03/31	40-1162	
8305020429	8305020425	83/04/22	50-443	G
8305020430	8305020422	83/01/11	50-445	G
8305020433	8305020427	83/04/28	50-206	P
8305020437	8305020422	83/01/11	50-445	G
8305020443	8305020439	83/03/02	40-6659	
8305020444	8305020422	83/01/11	50-445	G
8305020445	8305020436	83/04/28	50-313	G
8305020464	8305020449	83/04/27	50-298	P
8305020465	8305020461	83/04/27	50-219	I
8305020480	8305020467	83/04/13	50-10	G
8305020484	8305020481	83/02/28	40-8681	
8305020486	8305020482	83/04/26	50-443	G
8305020492	8305020488	83/04/22	50-263	S
8305020504	8305020410	83/03/24	40-6622	
8305020505	8305020007	83/01/11	FOIA	
8305020525	8305020007	83/01/11	FOIA	
8305020526	8305020523	83/03/28	70-824	
8305020539	8305020007	83/01/11	70-378	
8305020545	8305020007	83/01/11	FOIA	
8305020550	8305020007	83/01/11	FOIA	
8305020554	8305020007	83/01/11	FOIA	
8305020557	8305020553	83/04/14	XPORTLIC	
8305020558	8305020007	83/01/11	FOIA	
8305020560	8305020007	83/01/11	FOIA	
8305020564	8305020007	83/01/11	FOIA	
8305020567	8305020007	83/01/11	FOIA	
8305020571	8305020007	83/01/11	FOIA	
8305020603	8305020602	83/04/21	50-335	P
8305030008	8305020007	83/01/11	FOIA	
8305030019	8305030016	83/04/06	50-389	P
8305030020	8305020007	83/01/11	FOIA	
8305030022	8305030016	83/04/06	50-389	P
8305030023	8305020007	83/01/11	FOIA	
8305030024	8305030021	83/04/22	50-244	P
8305030027	8305020007	83/01/11	FOIA	
8305030035	8305020007	83/01/11	FOIA	
8305030047	8305020007	83/01/11	FOIA	
8305030055	8305020007	83/01/11	FOIA	
8305030056	8305030018	83/04/11	XPORTLIC	
8305030063	8305020007	83/01/11	FOIA	
8305030070	8305030066	83/04/19	50-333	P
8305030073	8305020007	83/01/11	FOIA	
8305030077	8305030074	83/04/20	70-1257	
8305030080	8305020007	83/01/11	FOIA	
8305030084	8305030076	83/04/22	50-295	F
8305030087	8305020007	83/01/11	FOIA	
8305030091	8305030076	83/04/22	50-295	F
8305030092	8305020007	83/01/11	FOIA	
8305030098	8305020007	83/01/11	FOIA	
8305030105	8305020007	83/01/11	FOIA	
8305030112	8305030102	83/04/20	50-289	B
8305030114	8305030104	83/04/22	50-295	F
8305030117	8305030104	83/04/22	50-295	F
8305030125	8305020007	83/01/11	FOIA	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305030127	8305030095	83/04/19	50-289	S
8305030142	8305020007	83/01/11	FOIA	
8305030145	8305030139	83/04/18	50-277	G
8305030147	8305020007	83/01/11	FOIA	
8305030153	8305030144	83/04/29	50-387	P
8305030154	8305020007	83/01/11	FOIA	
8305030160	8305030156	83/04/28	50-285	P
8305030163	8305020007	83/01/11	FOIA	
8305030164	8305030151	83/04/19	50-320	G
8305030165	8305030158	83/04/20	50-338	S
8305030169	8305020007	83/01/11	FOIA	
8305030172	8305030166	83/04/18	50-460	K
8305030173	8305030168	83/04/29	50-251	R
8305030174	8305020007	83/01/11	FOIA	
8305030178	8305030171	83/04/29	50-341	A
8305030179	8305020007	83/01/11	FOIA	
8305030183	8305030176	83/04/26	50-327	S
8305030185	8305020007	83/01/11	FOIA	
8305030188	8305030180	83/04/22	50-275	F
8305030189	8305020007	83/01/11	70-378	
8305030193	8305030180	83/04/22	50-275	F
8305030195	8305020007	83/01/11	70-378	
8305030200	8305030191	83/04/15	50-275	P
8305030201	8305020007	83/01/11	70-378	
8305030207	8305020007	83/01/11	70-378	
8305030208	8305030198	83/04/19	50-317	G
8305030212	8305020007	83/01/11	70-378	
8305030213	8305020007	83/01/11	70-378	
8305030218	8305020007	83/01/11	70-378	
8305030221	8305030214	83/04/22	50-282	F
8305030225	8305020007	83/01/11	70-378	
8305030226	8305030214	83/04/22	50-282	F
8305030233	8305020007	83/01/11	70-378	
8305030239	8305020007	83/01/11	70-378	
8305030240	8305030231	83/04/22	50-389	F
8305030244	8305030231	83/04/22	50-389	F
8305030246	8305030237	83/04/20	40-8027	
8305030249	8305020007	83/01/11	70-378	
8305030251	8305020007	83/01/11	70-378	
8305030255	8305020007	83/01/11	70-378	
8305030260	8305020007	83/01/11	70-378	
8305030262	8305030253	83/03/25	40-8728	
8305030263	8305030258	83/04/28	50-483	G
8305030264	8305020007	83/01/11	70-378	
8305030268	8305020007	83/01/11	70-378	
8305030272	8305030266	83/04/26	50-296	S
8305030273	8305030253	83/03/25	40-8728	
8305030278	8305020007	83/01/11	70-378	
8305030280	8305030275	83/04/26	50-301	S
8305030281	8305020007	83/01/11	70-378	
8305030282	8305030271	83/04/25	50-275	R
8305030283	8305030279	83/04/20	50-339	S
8305030286	8305020007	83/01/11	70-378	
8305030289	8305020007	83/01/11	70-378	
8305030290	8305030287	83/04/12	50-312	S
8305030293	8305030288	83/04/28	50-324	P
8305030296	8305020007	83/01/11	70-378	
8305030301	8305020007	83/01/11	70-378	
8305030304	8305020007	83/01/11	70-378	
8305030307	8305030299	83/04/29	50-352	A
8305030308	8305030297	83/04/28	70-946	
8305030309	8305020007	83/01/11	70-378	
8305030312	8305020007	83/01/11	70-378	
8305030316	8305030311	83/04/13	50-334	S
8305030320	8305020007	83/01/11	70-378	
8305030323	8305020007	83/01/11	70-378	
8305030326	8305020007	83/01/11	70-378	
8305030331	8305030325	83/04/27	50-313	G
8305030332	8305020007	83/01/11	70-378	
8305030333	8305030321	83/04/22	50-254	S
8305030335	8305020007	83/01/11	70-378	
8305030338	8305030334	83/04/21	50-387	S
8305030339	8305020007	83/01/11	FOIA	
8305030343	8305030337	83/04/27	TOPREP	
8305030347	8305030341	83/04/28	50-335	R
8305030348	8305030336	83/04/29	50-10	G
8305030351	8305030349	83/04/15	GA999	
8305030353	8305030350	83/04/19	50-309	G
8305030359	8305030356	83/04/18	50-361	S
8305030361	8305030355	83/04/20	50-324	S

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305030362	8305030358	83/04/15	GA999	
8305030364	8305030357	83/04/20	50-339	S
8305030366	8305030358	83/04/15	GA999	
8305030371	8305030368	83/04/28	70-27	
8305030380	8305030373	83/04/21	50-247	S
8305030382	8305030376	83/04/25	50-266	S
8305030388	8305030383	83/04/18	50-318	S
8305030390	8305030385	83/04/25	50-313	S
8305030396	8305030394	83/04/25	50-331	S
8305030407	8305030400	83/04/15	50-247	S
8305030412	8305030408	83/04/28	50-286	P
8305030419	8305030411	83/04/22	50-324	S
8305030429	8305030425	83/04/29	50-285	F
8305030435	8305030425	83/04/29	50-285	F
8305030438	8305030426	83/04/28	TOPREP	
8305030446	8305030440	83/04/25	50-304	S
8305030447	8305030441	83/04/20	50-219	S
8305030458	8305030456	83/04/28	50-247	P
8305030470	8305030462	83/04/28	50-320	R
8305030471	8305030466	83/04/12	GA999	
8305030473	8305030465	83/04/25	50-325	S
8305030474	8305030469	83/04/04	50-483	G
8305030475	8305030466	83/04/12	GA999	
8305030478	8305030462	83/04/28	50-320	R
8305030481	8305030463	83/04/28	50-324	P
8305030484	8305030462	83/04/28	50-320	R
8305030496	8305030491	83/04/29	50-309	P
8305030511	8305030509	83/04/12	GA999	
8305030516	8305030508	83/04/27	50-454	T
8305030518	8305030509	83/04/12	GA999	
8305030521	8305030513	83/04/29	50-264	G
8305030525	8305030509	83/04/12	GA999	
8305030533	8305030528	83/04/29	50-358	K
8305030535	8305030527	83/04/20	50-320	S
8305030536	8305030512	83/04/22	50-324	S
8305030537	8305030526	83/05/02	50-440	T
8305030545	8305030538	83/04/25	50-275	R
8305030547	8305030540	83/04/22	50-324	S
8305030561	8305030551	83/04/19	50-312	S
8305030564	8305030554	83/04/29	50-298	P
8305030567	8305030565	83/04/29	50-309	G
8305030579	8305030569	83/04/26	50-327	S
8305030581	8305030573	83/04/29	50-275	R
8305030587	8305030577	83/04/28	50-312	P
8305030589	8305030580	83/04/22	50-364	S
8305030592	8305030559	83/04/26	50-461	R
8305030595	8305030593	83/04/27	50-334	R
8305030597	8305030590	83/04/19	50-29	S
8305030602	8305030600	83/04/29	50-305	P
8305030610	8305030603	83/04/29	50-263	K
8305030613	8305030603	83/04/29	50-263	K
8305030615	8305030611	83/04/21	50-338	S
8305030618	8305030612	83/04/20	50-324	S
8305030619	8305030608	83/04/19	50-247	G
8305030622	8305030617	83/04/27	50-482	G
8305030624	8305030620	83/04/26	50-245	P
8305030628	8305030620	83/04/26	50-245	P
8305030629	8305030608	83/04/19	50-247	G
8305030631	8305030625	83/04/22	50-259	G
8305030633	8305030608	83/04/19	50-247	G
8305030637	8305030627	83/04/22	50-395	S
8305030640	8305030635	83/04/21	50-339	S
8305030641	8305030608	83/04/19	50-247	G
8305030646	8305030608	83/04/19	50-247	G
8305030652	8305030608	83/04/19	50-247	G
8305030665	8305030634	83/04/22	50-321	P
8305030684	8305020007	83/01/11	FOIA	
8305030687	8305030685	83/04/25	50-321	F
8305030690	8305030685	83/04/25	50-321	F
8305030695	8305030693	83/04/22	50-289	F
8305030720	8305030716	83/04/25	71-9105	
8305030722	8305110415	83/05/10	REVIEW GRP	
8305040009	8305040007	83/04/25	50-305	F
8305040014	8305040007	83/04/25	50-305	F
8305040016	8305040010	83/04/22	50-395	P
8305040021	8305040010	83/04/22	50-395	P
8305040034	8305040022	83/04/25	50-245	F
8305040039	8305040022	83/04/25	50-245	F
8305040052	8305040047	83/04/13	40-7869	
8305040060	8305020007	83/01/11	70-378	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305040068	8305040054	83/04/20	50-289	G
8305040074	8305040069	83/04/22	50-454	F
8305040080	8305040069	83/04/22	50-454	F
8305040081	8305020007	83/01/11	FOIA	
8305040089	8305020007	83/01/11	FOIA	
8305040093	8305020007	83/01/11	FOIA	
8305040103	8305020007	83/01/11	FOIA	
8305040105	8305040096	83/04/25	71-9181	
8305040108	8305040095	83/04/18	50-331	P
8305040110	8305040096	83/04/25	71-9181	
8305040114	8305020007	83/01/11	FOIA	
8305040115	8305040095	83/04/18	50-331	P
8305040120	8305020007	83/01/11	FOIA	
8305040122	8305040117	83/04/19	50-305	G
8305040125	8305040117	83/04/19	50-305	G
8305040127	8305020007	83/01/11	FOIA	
8305040145	8305040138	83/04/20	50-289	U
8305040150	8305040146	83/04/25	50-318	S
8305040158	8305020007	83/01/11	FOIA	
8305040159	8305040147	83/04/25	71-9079	
8305040165	8305020007	83/01/11	FOIA	
8305040175	8305020007	83/01/11	FOIA	
8305040176	8305040147	83/04/25	71-9079	
8305040183	8305020007	83/01/11	FOIA	
8305040189	8305020007	83/01/11	FOIA	
8305040200	8305020007	83/01/11	FOIA	
8305040211	8305020007	83/01/11	FOIA	
8305040217	8305020007	83/01/11	FOIA	
8305040224	8305020007	83/01/11	FOIA	
8305040234	8305020007	83/01/11	FOIA	
8305040239	8305020007	83/01/11	FOIA	
8305040240	8305040229	83/05/02	50-369	S
8305040242	8305040235	83/04/22	50-3	F
8305040244	8305020007	83/01/11	FOIA	
8305040246	8305040229	83/05/02	50-369	S
8305040247	8305040235	83/04/22	50-3	F
8305040249	8305040235	83/04/22	50-3	F
8305040250	8305020007	83/01/11	FOIA	
8305040254	8305040235	83/04/22	50-3	F
8305040256	8305020007	83/01/11	FOIA	
8305040260	8305040229	83/05/02	50-369	S
8305040265	8305040259	83/04/25	50-315	F
8305040266	8305020007	83/01/11	FOIA	
8305040268	8305040259	83/04/25	50-315	F
8305040272	8305020007	83/01/11	FOIA	
8305040279	8305020007	83/01/11	FOIA	
8305040284	8305040280	83/04/25	CONTRACT	
8305040287	8305020007	83/01/11	FOIA	
8305040290	8305020007	83/01/11	FOIA	
8305040294	8305020007	83/01/11	FOIA	
8305040297	8305020007	83/01/11	FOIA	
8305040310	8305020007	83/01/11	FOIA	
8305040328	8305040320	83/05/02	50-275	P
8305040345	8305040341	83/04/28	CONTRACT	
8305040363	8305040354	83/04/25	50-315	P
8305040366	8305020007	83/01/11	FOIA	
8305040371	8305040365	83/04/19	50-373	R
8305040374	8305040354	83/04/25	50-315	P
8305040376	8305020007	83/01/11	FOIA	
8305040380	8305020007	83/01/11	FOIA	
8305040382	8305040354	83/04/25	50-315	P
8305040387	8305020007	83/01/11	FOIA	
8305040392	8305020007	83/01/11	FOIA	
8305040403	8305020007	83/01/11	FOIA	
8305040408	8305020007	83/01/11	FOIA	
8305040414	8305020007	83/01/11	FOIA	
8305040421	8305040412	83/05/03	50-400	G
8305040425	8305020007	83/01/11	FOIA	
8305040434	8305040424	83/04/29	50-333	P
8305040438	8305040424	83/04/29	50-333	P
8305040450	8305020007	83/01/11	FOIA	
8305040456	8305040446	83/05/02	50-237	P
8305040459	8305040453	83/04/29	50-313	R
8305040466	8305040458	83/04/11	TOPREP	
8305040468	8305020007	83/01/11	70-378	
8305040473	8305040320	83/05/02	50-275	P
8305040478	8305020007	83/01/11	FOIA	
8305040480	8305040472	83/05/02	50-346	P
8305040484	8305020007	83/01/11	FOIA	
8305040485	8305040479	83/04/28	50-400	Q

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305040489	8305020007	83/01/11	FOIA	
8305040492	8305040479	83/04/28	50-400	Q
8305040493	8305040483	83/05/02	50-220	P
8305040497	8305040491	83/05/02	50-346	P
8305040498	8305040479	83/04/28	50-400	Q
8305040500	8305040483	83/05/02	50-220	P
8305040501	8305020007	83/01/11	FOIA	
8305040502	8305020007	83/01/11	FOIA	
8305040503	8305040491	83/05/02	50-346	P
8305040510	8305020007	83/01/11	FOIA	
8305040514	8305040508	83/04/22	50-322	E
8305040515	8305040507	83/04/26	50-445	T
8305040516	8305040506	83/05/02	50-440	T
8305040517	8305040511	83/04/28	50-259	P
8305040519	8305020007	83/01/11	FOIA	
8305040522	8305040518	83/04/20	50-305	G
8305040523	8305020007	83/01/11	FOIA	
8305040524	8305040520	83/05/02	50-237	P
8305040536	8305040534	83/05/03	50-155	Q
8305040537	8305040534	83/05/03	50-155	Q
8305040539	8305040534	83/05/03	50-155	Q
8305040540	8305040534	83/05/03	50-155	Q
8305040542	8305040534	83/05/03	50-155	Q
8305040543	8305040534	83/05/03	50-155	Q
8305040545	8305040534	83/05/03	50-155	Q
8305040553	8305040552	83/04/25	CONTRACT	
8305040554	8305020007	83/01/11	FOIA	
8305040555	8305040551	83/05/02	50-237	P
8305040556	8305020007	83/01/11	FOIA	
8305040559	8305020007	83/01/11	FOIA	
8305040560	8305040557	83/05/03	50-445	Q
8305040561	8305040558	83/04/14	XPORTLIC	
8305040562	8305020007	83/01/11	FOIA	
8305040566	8305040563	83/04/12	50-335	F
8305040567	8305040558	83/04/14	XPORTLIC	
8305040568	8305040564	83/04/28	50-269	P
8305040569	8305020007	83/01/11	FOIA	
8305040573	8305020007	83/01/11	FOIA	
8305040578	8305020007	83/01/11	FOIA	
8305040579	8305020007	83/01/11	FOIA	
8305040580	8305040575	83/04/25	50-320	F
8305040583	8305020007	83/01/11	70-378	
8305040586	8305020007	83/01/11	70-378	
8305040587	8305020007	83/01/11	70-378	
8305040588	8305040565	83/04/26	TOPREP	
8305040593	8305020007	83/01/11	70-378	
8305040597	8305040584	83/04/26	50-369	F
8305040599	8305020007	83/01/11	70-378	
8305040603	8305020007	83/01/11	70-378	
8305040606	8305040584	83/04/26	50-369	F
8305040613	8305040565	83/04/26	TOPREP	
8305040619	8305040614	83/04/25	50-285	F
8305040624	8305040614	83/04/25	50-285	F
8305040626	8305040621	83/04/26	50-334	P
8305040633	8305040628	83/04/26	50-259	F
8305040643	8305040635	83/04/21	CONTRACT	
8305040654	8305040648	83/04/25	50-321	F
8305040655	8305040628	83/04/26	50-259	F
8305040659	8305040648	83/04/25	50-321	F
8305040660	8305040650	83/04/29	CONTRACT	
8305040674	8305020007	83/01/11	70-378	
8305040678	8305020007	83/01/11	70-378	
8305040679	8305040671	83/04/13	71-495	
8305040687	8305020007	83/01/11	70-378	
8305040696	8305020007	83/01/11	70-378	
8305040737	8305040730	83/04/22	50-259	P
8305040745	8305040730	83/04/22	50-259	P
8305040785	8305040780	83/04/25	50-322	Q
8305040789	8305040783	83/04/21	50-317	P
8305040790	8305040780	83/04/25	50-322	Q
8305040793	8305040783	83/04/21	50-317	P
8305040795	8305040783	83/04/21	50-317	P
8305050005	8305050001	83/05/02	50-322	Q
8305050010	8305050004	83/05/03	50-341	A
8305050014	8305050008	82/12/30	50-413	A
8305050025	8305050016	83/04/27	50-302	B
8305050027	8305050021	83/05/04	50-277	P
8305050029	8305050024	83/05/02	50-322	T
8305050031	8305050020	83/05/02	50-220	P
8305050033	8305050021	83/05/04	50-277	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305050040	8305050030	83/04/21	50-321	S
8305050061	8305050057	83/04/29	50-395	S
8305050071	8305050068	83/04/21	QA999	
8305050076	8305050073	83/04/21	50-286	F
8305050087	8305050083	83/04/21	50-321	S
8305050090	8305050088	83/04/21	QA999	
8305050091	8305050088	83/04/21	QA999	
8305050093	8305050088	83/04/21	QA999	
8305050097	8305050094	83/04/19	QA999	
8305050104	8305050102	83/04/21	QA999	
8305050108	8305050101	83/04/25	50-271	S
8305050110	8305050102	83/04/21	QA999	
8305050111	8305050107	83/04/13	QA999	
8305050115	8305050114	83/04/13	QA999	
8305050117	8305050114	83/04/13	QA999	
8305050119	8305050116	83/04/01	50-443	Q
8305050121	8305050118	83/04/27	50-281	S
8305050128	8305050123	83/04/29	50-327	S
8305050130	8305050118	83/04/27	50-281	S
8305050138	8305050127	83/04/28	50-335	S
8305050140	8305050134	83/04/21	70-1402	
8305050147	8305050141	83/04/21	50-277	Q
8305050149	8305050145	83/04/19	QA999	
8305050151	8305050144	83/04/20	50-293	Q
8305050154	8305050148	83/04/27	50-348	S
8305050158	8305050148	83/04/27	50-348	S
8305050163	8305050157	83/04/21	50-458	Q
8305050164	8305050159	83/05/03	50-397	Q
8305050166	8305050161	83/04/20	40-3079	
8305050169	8305050162	83/04/21	QA999	
8305050171	8305050162	83/04/21	QA999	
8305050175	8305050172	83/04/20	50-334	Q
8305050178	8305050167	83/04/28	50-416	S
8305050179	8305050162	83/04/21	QA999	
8305050180	8305050172	83/04/20	50-334	Q
8305050181	8305050177	83/04/13	QA999	
8305050182	8305050176	83/04/21	70-1224	
8305050184	8305050177	83/04/13	QA999	
8305050190	8305050187	83/04/20	50-247	Q
8305050191	8305050186	83/04/27	50-338	S
8305050192	8305050177	83/04/13	QA999	
8305050203	8305050195	83/04/29	50-348	S
8305050206	8305050183	83/04/27	50-327	S
8305050208	8305050200	83/04/20	TOPREP	
8305050215	8305050210	83/04/27	50-339	S
8305050217	8305050211	83/04/29	50-328	S
8305050222	8305050214	83/04/19	50-267	P
8305050224	8305050218	83/04/27	50-328	S
8305050225	8305050220	83/04/25	50-309	P
8305050226	8305050219	83/04/15	QA999	
8305050228	8305050214	83/04/19	50-267	P
8305050230	8305050223	83/04/21	50-97	Q
8305050236	8305050223	83/04/21	50-97	Q
8305050239	8305050233	83/04/29	50-395	S
8305050241	8305050237	83/04/15	QA999	
8305050244	8305050242	83/04/29	50-324	S
8305050245	8305050238	83/04/28	50-260	S
8305050248	8305050246	83/04/27	50-244	Q
8305050255	8305050251	83/04/21	QA999	
8305050257	8305050252	83/04/29	50-128	P
8305050258	8305050251	83/04/21	QA999	
8305050261	8305050256	83/04/27	50-416	S
8305050262	8305050251	83/04/21	QA999	
8305050267	8305050265	83/04/28	50-324	S
8305050268	8305050263	83/04/27	50-29	S
8305050272	8305050266	83/04/29	50-259	S
8305050276	8305050271	83/04/27	50-339	S
8305050287	8305040323	83/05/04	50-247	P
8305050288	8305050283	83/04/26	50-369	P
8305050289	8305050285	83/04/25	50-387	F
8305050292	8305020007	83/01/11	70-378	
8305050295	8305040323	83/05/04	50-247	P
8305050297	8305020007	83/01/11	70-378	
8305050301	8305020007	83/01/11	70-378	
8305050303	8305050299	83/05/02	50-275	R
8305050304	8305050300	83/04/25	50-289	F
8305050306	8305020007	83/01/11	70-378	
8305050307	8305050300	83/04/25	50-289	F
8305050310	8305020007	83/01/11	70-378	
8305050312	8305020007	83/01/11	70-378	

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305050316	8305020007	83/01/11	70-378	
8305050317	8305050311	83/04/25	50-395	F
8305050319	8305020007	83/01/11	70-378	
8305050321	8305050311	83/04/25	50-395	F
8305050322	8305020007	83/01/11	70-378	
8305050326	8305020007	83/01/11	70-378	
8305050328	8305020007	83/01/11	70-378	
8305050330	8305020007	83/01/11	70-378	
8305050333	8305020007	83/01/11	70-378	
8305050335	8305020007	83/01/11	70-378	
8305050337	8305020007	83/01/11	70-378	
8305050339	8305020007	83/01/11	70-378	
8305050342	8305020007	83/01/11	FOIA	
8305050346	8305020007	83/01/11	FOIA	
8305050349	8305020007	83/01/11	FOIA	
8305050351	8305020007	83/01/11	FOIA	
8305050353	8305050341	83/04/13	50-269	S
8305050355	8305020007	83/01/11	FOIA	
8305050359	8305020007	83/01/11	FOIA	
8305050361	8305020007	83/01/11	FOIA	
8305050363	8305020007	83/01/11	FOIA	
8305050373	8305050366	83/04/25	50-387	Q
8305050381	8305050377	83/04/25	50-320	F
8305050389	8305050385	83/04/26	CONTRACT	
8305050404	8305050400	83/03/28	CONTRACT	
8305060007	8305060001	83/04/25	50-266	P
8305060036	8305060023	83/04/25	50-282	P
8305060046	8305060043	83/05/03	50-220	P
8305060048	8305060043	83/05/03	50-220	P
8305060049	8305060042	83/04/25	50-309	P
8305060055	8305060051	83/04/28	50-321	P
8305060062	8305060058	83/04/21	50-336	P
8305060066	8305060060	83/05/04	50-331	P
8305060076	8305060060	83/05/04	50-331	P
8305060084	8305060077	83/04/21	50-317	F
8305060091	8305060069	83/04/29	50-285	I
8305060117	8305060112	83/03/14	FOIA	
8305060120	8305060109	83/04/22	50-338	P
8305060136	8305060109	83/04/22	50-338	P
8305060140	8305060109	83/04/22	50-338	P
8305060141	8305060135	83/03/03	40-672	
8305060142	8305060133	83/04/25	71-9175	
8305060145	8305060135	83/03/03	FOIA	
8305060148	8305060133	83/04/25	71-9175	
8305060152	8305060133	83/04/25	71-9175	
8305060153	8305060144	83/03/17	FOIA	
8305060154	8305060133	83/04/25	71-9175	
8305060155	8305060144	83/03/17	FOIA	
8305060156	8305060135	83/03/03	40-672	
8305060160	8305060144	83/03/17	FOIA	
8305060164	8305060144	83/03/17	FOIA	
8305060171	8305060144	83/03/17	FOIA	
8305060180	8305060176	83/05/02	50-325	P
8305060181	8305060135	83/03/03	40-672	
8305060183	8305060174	83/02/25	CONTRACT	
8305060189	8305060135	83/03/03	40-672	
8305060190	8305060187	83/04/25	71-6294	
8305060193	8305060135	83/03/03	40-672	
8305060200	8305060135	83/03/03	40-672	
8305060209	8305060135	83/03/03	40-672	
8305060212	8305060208	83/04/21	71-5979	
8305060214	8305060135	83/03/03	40-672	
8305060220	8305060135	83/03/03	40-672	
8305060228	8305060225	83/05/03	50-206	P
8305060232	8305060225	83/05/03	50-206	P
8305060234	8305060225	83/05/03	50-206	P
8305060239	8305060235	83/04/25	50-206	P
8305060251	8305060246	83/04/26	CONTRACT	
8305060269	8305060261	83/04/25	50-334	R
8305060277	8305060271	83/04/28	50-244	P
8305060279	8305060266	83/04/22	50-293	P
8305060282	8305060130	83/04/27	50-395	P
8305060287	8305060266	83/04/22	50-293	P
8305060288	8305060130	83/04/27	50-395	P
8305060291	8305060266	83/04/22	50-293	P
8305060293	8305060284	83/05/03	50-483	Q
8305060295	8305060130	83/04/27	50-395	P
8305060303	8305060298	83/04/22	50-389	P
8305060308	8305060298	83/04/22	50-389	P
8305060312	8305060298	83/04/22	50-389	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305060325	8305060319	83/04/13	WASTE MGT	
8305060326	8305060320	83/04/01	CONTRACT	
8305060346	8305060338	83/04/25	50-482	F
8305060351	8305060341	83/02/23	CONTRACT	
8305060354	8305060338	83/04/25	50-482	F
8305060369	8305060363	83/03/25	40-8783	
8305060381	8305060372	83/05/03	50-206	P
8305060383	8305060380	83/05/07	50-298	I
8305060384	8305060379	83/04/12	50-329	A
8305060385	8305060372	83/05/03	50-206	P
8305060391	8305060390	83/04/27	50-254	S
8305060393	8305060388	83/04/29	50-255	S
8305060401	8305060398	83/04/28	50-373	S
8305060405	8305060402	83/04/27	50-317	P
8305060406	8305060400	83/04/29	50-315	S
8305060407	8305060397	83/05/03	50-286	P
8305060411	8305060400	83/04/29	50-315	S
8305060414	8305060400	83/04/29	50-315	S
8305060417	8305060397	83/05/03	50-286	P
8305060418	8305060410	83/05/03	50-295	G
8305060421	8305060419	83/04/19	50-312	P
8305060422	8305060416	83/04/26	50-237	S
8305060428	8305060426	83/04/27	50-220	S
8305060432	8305060431	83/05/03	50-286	P
8305060433	8305060431	83/05/03	50-286	P
8305060440	8305060439	83/05/03	50-286	P
8305060444	8305060443	83/04/08	50-295	S
8305060446	8305060427	83/05/03	50-286	P
8305060449	8305060427	83/05/03	50-286	P
8305060450	8305060448	83/03/31	50-362	S
8305060454	8305060452	83/04/25	50-313	S
8305060460	8305060458	83/04/29	50-289	R
8305060464	8305060458	83/04/29	50-289	R
8305060465	8305060458	83/04/29	50-289	R
8305060482	8305060476	83/04/28	50-272	S
8305060484	8305060479	83/04/28	50-267	S
8305060489	8305060480	83/04/29	50-311	S
8305060492	8305060486	83/04/29	50-237	S
8305060503	8305060494	83/04/28	50-309	S
8305060509	8305060493	83/04/27	50-373	S
8305060512	8305060501	83/04/29	50-245	S
8305060514	8305060505	83/04/08	50-361	S
8305060517	8305060511	83/04/25	50-237	S
8305060523	8305060519	83/04/29	50-346	G
8305060536	8305060529	83/04/26	50-352	A
8305060540	8305060533	83/04/27	50-220	S
8305060544	8305060528	83/04/29	50-295	S
8305060549	8305060538	83/04/25	50-309	S
8305060552	8305060546	83/04/13	50-267	R
8305060553	8305060548	83/04/26	50-333	F
8305060554	8305060542	83/05/03	50-373	G
8305060557	8305060548	83/04/26	50-333	F
8305060559	8305060547	83/05/02	50-456	G
8305060561	8305060556	83/05/02	50-280	P
8305060568	8305060562	83/04/28	50-447	E
8305060569	8305060542	83/05/03	50-373	G
8305060571	8305060563	83/04/22	50-249	S
8305060572	8305060567	83/04/29	50-295	S
8305060582	8305060577	83/02/28	50-238	R
8305060583	8305060575	83/04/25	50-313	F
8305060584	8305060574	83/04/29	50-298	S
8305060586	8305060577	83/02/28	50-238	R
8305060591	8305060575	83/04/25	50-313	F
8305060594	8305060581	83/03/25	50-249	S
8305060598	8305060592	83/04/29	50-387	S
8305060599	8305060590	83/04/27	50-237	S
8305060601	8305060595	83/04/25	50-346	F
8305060606	8305060600	83/05/02	50-344	P
8305060608	8305060595	83/04/25	50-346	F
8305060609	8305060604	83/04/28	50-334	P
8305060611	8305060603	83/04/27	50-237	S
8305060613	8305060577	83/02/28	50-238	R
8305060614	8305060604	83/04/28	50-334	P
8305060621	8305060616	83/04/26	50-348	F
8305060626	8305060616	83/04/26	50-348	F
8305060629	8305060506	83/05/04	50-247	G
8305060631	8305060627	83/04/25	50-317	F
8305060634	8305060623	83/05/03	40-8202	
8305060635	8305060627	83/04/25	50-317	F
8305060663	8305060658	83/04/22	50-280	P

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305060669	8305060666	83/04/27	50-344	P
8305060670	8305060666	83/04/27	50-344	P
8305060679	8305060673	83/04/25	50-295	F
8305060686	8305060673	83/04/25	50-295	F
8305060694	8305060683	83/04/27	50-361	P
8305060699	8305060692	83/04/25	50-346	F
8305060700	8305060696	83/03/28	10CFR	
8305060702	8305060692	83/04/25	50-346	F
8305060703	8305060683	83/04/27	50-361	P
8305090003	8305090001	83/04/21	GA999	
8305090012	8305090009	83/04/29	CONTRACT	
8305090019	8305090016	83/04/15	50-348	P
8305090023	8305090016	83/04/15	50-348	P
8305090027	8305090016	83/04/15	50-348	P
8305090032	8305090016	83/04/15	50-348	P
8305090037	8305090029	83/04/27	50-280	G
8305090038	8305090024	83/03/21	FOIA	
8305090043	8305090024	83/03/21	FOIA	
8305090047	8305090024	83/03/21	FOIA	
8305090051	8305090045	83/04/27	50-280	P
8305090055	8305090024	83/03/21	FOIA	
8305090056	8305090048	83/04/28	71-5814	
8305090057	8305090024	83/03/21	FOIA	
8305090058	8305090050	83/04/29	CONTRACT	
8305090060	8305090052	83/04/29	50-329	R
8305090062	8305090045	83/04/27	50-280	P
8305090070	8305090045	83/04/27	50-280	P
8305090073	8305090066	83/05/04	50-128	G
8305090091	8305090085	83/04/26	50-250	G
8305090104	8305090085	83/04/26	50-250	G
8305090111	8305090078	83/04/15	50-269	P
8305090117	8305090068	83/04/29	CONTRACT	
8305090121	8305090113	83/04/28	71-5980	
8305090124	8305090078	83/04/15	50-269	P
8305090131	8305090122	83/04/28	CONTRACT	
8305090136	8305090129	83/05/05	50-322	G
8305090138	8305090078	83/04/15	50-269	P
8305090140	8305090133	83/04/28	71-5875	
8305090149	8305090144	83/04/20	50-338	P
8305090150	8305090145	83/04/28	71-5874	
8305090154	8305090147	83/04/18	50-313	P
8305090160	8305090147	83/04/18	50-313	P
8305090179	8305090147	83/04/18	50-313	P
8305090197	8305090186	83/04/26	50-331	F
8305090202	8305090212	83/04/29	PROJ	
8305090228	8305090217	83/04/28	TOPREP	
8305090255	8305090244	83/04/29	50-272	S
8305090290	8305090279	83/05/02	MISC	
8305090300	8305090291	83/05/03	CONTRACT	
8305090313	8305090306	83/03/22	50-373	G
8305090315	8305090279	83/05/02	MISC	
8305090327	8305090321	83/04/26	50-280	P
8305090331	8305090321	83/04/26	50-280	P
8305090335	8305090321	83/04/26	50-280	P
8305090372	8305090338	83/05/03	50-470	E
8305090388	8305090371	83/05/04	GA999	
8305090393	8305090386	83/04/20	GA999	
8305090398	8305090392	83/04/20	GA999	
8305090403	8305090392	83/04/20	GA999	
8305090406	8305090386	83/04/20	GA999	
8305090413	8305090386	83/04/20	GA999	
8305090418	8305090409	83/05/06	50-390	G
8305090436	8305090426	83/05/05	50-245	P
8305090442	8305090426	83/05/05	50-245	P
8305090459	8305090457	83/05/04	50-272	P
8305090460	8305090426	83/05/05	50-245	P
8305090461	8305090454	83/05/06	50-395	G
8305090463	8305090426	83/05/05	50-245	P
8305090464	8305090462	83/04/29	50-302	P
8305090469	8305090467	83/04/29	TOPREP	
8305090474	8305090471	83/05/02	50-245	P
8305090482	8305090479	83/04/20	GA999	
8305090485	8305090479	83/04/20	GA999	
8305090490	8305090487	83/05/06	50-440	G
8305090491	8305090488	83/05/02	50-213	P
8305090492	8305090488	83/05/02	50-213	P
8305090493	8305090487	83/05/06	50-440	G
8305090495	8305090483	83/05/04	TOPREP	
8305090497	8305090483	83/05/04	TOPREP	
8305090502	8305090501	83/05/02	50-443	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305090510	8305090507	83/05/05	50-445	T
8305090513	8305090507	83/05/05	50-445	T
8305090516	8305090512	83/04/25	10CFR	
8305090517	8305090507	83/05/05	50-445	T
8305090521	8305090507	83/05/05	50-445	T
8305090525	8305090507	83/05/05	50-445	T
8305090530	8305090507	83/05/05	50-445	T
8305090545	8305090542	83/03/17	50-358	A
8305090549	8305090542	83/03/17	50-358	T
8305090557	8305090554	83/04/13	TOPREP	
8305090561	8305090542	83/03/17	50-358	A
8305090565	8305090489	83/04/25	50-267	R
8305090578	8305090568	83/05/05	50-445	G
8305090586	8305090568	83/05/05	50-445	G
8305090589	8305090584	83/04/27	50-302	G
8305090592	8305090568	83/05/05	50-445	G
8305090600	8305090568	83/05/05	50-445	G
8305090607	8305090568	83/05/05	50-445	G
8305090612	8305090608	83/04/27	50-269	P
8305090614	8305090529	83/03/10	50-443	F
8305090618	8305090568	83/05/05	50-445	G
8305090625	8305090568	83/05/05	50-445	G
8305090632	8305090568	83/05/05	50-445	G
8305090640	8305090568	83/05/05	50-445	G
8305090646	8305090568	83/05/05	50-445	G
8305090648	8305090633	83/05/02	50-410	A
8305090650	8305090568	83/05/05	50-445	G
8305090652	8305090633	83/05/02	50-410	A
8305090654	8305090568	83/05/05	50-445	G
8305090660	8305090568	83/05/05	50-445	G
8305090726	8305090722	83/05/02	50-445	A
8305090731	8305090730	83/05/03	XPORTLIC	
8305100003	8305100002	83/04/26	50-369	B
8305100009	8305100006	83/04/11	50-192	G
8305100014	8305100012	83/05/04	50-259	B
8305100019	8305100016	83/05/04	50-387	P
8305100021	8305100016	83/05/04	50-387	P
8305100029	8305100023	83/04/29	50-339	B
8305100036	8305100031	83/05/04	50-260	B
8305100082	8305100080	83/04/22	50-346	G
8305100083	8305100081	83/05/03	50-259	B
8305100084	8305100080	83/04/22	50-346	G
8305100085	8305100074	83/04/27	50-255	R
8305100090	8305100080	83/04/22	50-346	G
8305100091	8305100089	83/05/02	50-395	B
8305100109	8305100100	83/05/05	50-324	G
8305100111	8305100108	83/05/04	50-280	P
8305100113	8305100107	83/05/03	50-296	B
8305100116	8305100112	83/04/12	50-482	G
8305100120	8305100115	83/05/03	50-280	B
8305100126	8305100122	83/04/08	50-295	F
8305100129	8305100115	83/05/03	50-280	B
8305100131	8305100122	83/04/08	50-295	F
8305100135	8305100130	83/05/06	50-445	R
8305100136	8305100122	83/04/08	50-295	F
8305100139	8305100132	83/05/03	50-364	B
8305100141	8305100124	83/03/25	50-329	T
8305100142	8305100137	83/04/11	50-458	G
8305100144	8305100138	83/04/29	50-293	R
8305100155	8305100151	83/04/22	50-482	G
8305100160	8305100151	83/04/22	50-482	G
8305100166	8305100158	83/04/20	50-443	G
8305100174	8305100172	83/05/09	50-454	G
8305100179	8305100173	83/05/04	50-275	R
8305100185	8305100173	83/05/04	50-275	R
8305100190	8305100181	83/05/03	50-10	G
8305100193	8305100189	83/05/05	50-518	A
8305100216	8305100215	83/04/18	50-331	G
8305100218	8305100215	83/04/18	50-331	G
8305100221	8305100219	83/04/20	50-443	G
8305100225	8305100224	83/05/06	50-322	G
8305100239	8305100238	83/04/01	50-322	G
8305100242	8305100241	83/04/22	50-285	G
8305100244	8305100241	83/04/22	50-285	G
8305100245	8305100243	83/03/18	50-329	T
8305100248	8305100243	83/03/18	50-329	T
8305100249	8305100247	83/04/13	50-445	G
8305100253	8305100251	83/05/02	50-251	B
8305100265	8305100259	83/04/29	50-339	B
8305100266	8305100262	83/04/20	50-295	G

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305100271	8305100262	83/04/20	50-295	G
8305100273	8305100268	83/05/06	50-334	G
8305100277	8305100272	83/04/29	50-220	R
8305100278	8305100269	83/05/02	50-389	B
8305100281	8305100275	83/05/04	50-352	A
8305100287	8305100279	83/05/05	50-255	P
8305100289	8305100282	83/05/04	50-413	G
8305100291	8305100279	83/05/05	50-255	P
8305100292	8305100285	83/05/04	50-260	B
8305100297	8305100282	83/05/04	50-413	G
8305100305	8305100282	83/05/04	50-413	G
8305100307	8305100303	83/04/05	50-482	G
8305100317	8305100308	83/05/05	50-387	P
8305100335	8305100331	83/04/14	50-213	P
8305100343	8305100336	83/05/04	GA999	
8305100349	8305100336	83/05/04	GA999	
8305100353	8305100348	83/04/14	50-313	G
8305100355	8305100336	83/05/04	GA999	
8305100361	8305100348	83/04/14	50-313	G
8305100365	8305100323	83/05/06	50-156	G
8305100369	8305100358	83/05/04	50-438	A
8305100370	8305100362	83/05/06	50-325	P
8305100371	8305100363	83/05/04	50-156	G
8305100372	8305100364	83/05/04	50-331	G
8305100375	8305100356	83/03/21	50-443	G
8305100382	8305100358	83/05/04	50-438	A
8305100384	8305100378	83/04/27	50-255	B
8305100387	8305100379	83/04/22	50-237	G
8305100390	8305100383	83/05/04	50-369	P
8305100392	8305100356	83/03/21	50-443	G
8305100393	8305100388	83/05/04	50-341	G
8305100395	8305100358	83/05/04	50-438	A
8305100397	8305100389	83/05/03	50-305	B
8305100399	8305100388	83/05/04	50-341	G
8305100400	8305100356	83/03/21	50-443	G
8305100402	8305100379	83/04/22	50-237	G
8305100403	8305100376	83/04/27	50-255	B
8305100409	8305100404	83/04/07	50-155	G
8305100410	8305100405	83/04/25	50-286	G
8305100411	8305100356	83/03/21	50-443	G
8305100414	8305100404	83/04/07	50-155	G
8305100416	8305100379	83/04/22	50-237	G
8305100417	8305100412	83/05/05	50-324	R
8305100419	8305100356	83/03/21	50-443	G
8305100424	8305100356	83/03/21	50-443	G
8305100425	8305100356	83/03/21	50-443	G
8305100428	8305100427	83/04/25	50-247	G
8305100429	8305100356	83/03/21	50-443	G
8305100430	8305100356	83/03/21	50-443	G
8305100431	8305100427	83/04/25	50-247	G
8305100432	8305100356	83/03/21	50-443	G
8305100433	8305100427	83/04/25	50-247	G
8305110008	8305110005	83/05/03	CONTRACT	
8305110013	8305110011	83/05/03	71-9103	
8305110020	8305110010	83/03/15	50-29	F
8305110029	8305110026	83/04/19	NUREG	
8305110030	8305110026	83/04/19	NUREG	
8305110035	8305110033	83/05/06	71-9901	
8305110039	8305110037	83/05/03	50-331	P
8305110041	8305110031	83/04/29	CONTRACT	
8305110043	8305110037	83/05/03	50-331	P
8305110045	8305110037	83/05/03	50-331	P
8305110052	8305110050	83/04/29	50-305	P
8305110055	8305110050	83/04/29	50-305	P
8305110056	8305110050	83/04/29	50-305	P
8305110058	8305110053	83/05/05	50-286	P
8305110063	8305110053	83/05/05	50-286	P
8305110071	8305110069	83/03/09	50-213	F
8305110089	8305110082	83/05/03	50-373	P
8305110104	8305110097	83/05/05	50-387	K
8305110108	8305110097	83/05/05	50-387	K
8305110132	8305110128	83/04/26	50-335	P
8305110151	8305110150	83/05/06	71-9100	
8305110152	8305110146	83/05/03	CONTRACT	
8305110156	8305110154	83/04/27	50-272	P
8305110163	8305110159	83/04/26	CONTRACT	
8305110169	8305110165	83/05/03	50-368	P
8305110173	8305110165	83/05/03	50-368	P
8305110175	8305110171	83/05/03	50-373	P
8305110176	8305110165	83/05/03	50-368	P

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305110182	8305110179	83/04/25	50-361 P
8305110186	8305110179	83/04/25	50-361 P
8305110187	8305110181	83/05/04	50-266 P
8305110188	8305110179	83/04/25	50-361 P
8305110192	8305110190	83/04/25	CONTRACT
8305110198	8305110194	83/05/03	CONTRACT
8305110199	8305110193	83/04/29	50-313 P
8305110205	8305110193	83/04/29	50-313 P
8305110224	8305110219	83/05/05	50-336 P
8305110228	8305110219	83/05/05	50-336 P
8305110230	8305110219	83/05/05	50-336 P
8305110232	8305110229	83/05/05	CONTRACT
8305110234	8305110100	83/04/29	50-331 P
8305110236	8305110233	83/04/29	CONTRACT
8305110242	8305110100	83/04/29	50-331 P
8305110243	8305110100	83/04/29	50-331 P
8305110247	8305110241	83/04/22	50-387 S
8305110249	8305110246	83/05/03	50-327 P
8305110250	8305110246	83/05/03	50-327 P
8305110253	8305110246	83/05/03	50-327 P
8305110256	8305110251	83/05/06	50-261 S
8305110260	8305110257	83/05/05	50-364 S
8305110264	8305110259	83/04/21	50-333 S
8305110265	8305110261	83/04/29	50-277 G
8305110267	8305110261	83/04/29	50-277 G
8305110272	8305110269	83/04/26	50-321 S
8305110273	8305110270	83/04/26	50-321 S
8305110274	8305110271	83/04/26	50-311 S
8305110277	8305110276	83/04/27	50-317 G
8305110279	8305110275	83/04/29	50-416 S
8305110283	8305110281	83/04/29	50-369 S
8305110284	8305110282	83/05/04	50-325 S
8305110287	8305110286	83/04/29	50-289 S
8305110288	8305110285	83/05/05	50-338 S
8305110293	8305110289	83/05/03	50-321 S
8305110307	8305110302	83/05/02	50-3 R
8305110310	8305110302	83/05/02	50-3 R
8305110311	8305110308	83/05/03	50-348 P
8305110320	8305110314	83/04/27	50-309 G
8305110326	8305110321	83/04/28	50-320 S
8305110328	8305110318	83/04/25	50-244 S
8305110329	8305110325	83/05/05	50-327 S
8305110335	8305110323	83/04/29	50-270 S
8305110336	8305110330	83/05/05	50-339 S
8305110338	8305110331	83/04/29	50-289 G
8305110341	8305110334	83/04/25	50-293 S
8305110342	8305110333	83/04/29	50-289 S
8305110349	8305110340	83/04/21	50-278 S
8305110351	8305110346	83/04/25	50-289 S
8305110353	8305110343	83/04/25	50-334 S
8305110358	8305110348	83/04/25	50-387 S
8305110359	8305110315	83/05/05	50-410 C
8305110363	8305110352	83/04/27	50-317 S
8305110365	8305110356	83/04/25	50-293 S
8305110367	8305110355	83/05/06	50-259 S
8305110372	8305110315	83/05/05	50-410 K
8305110376	8305110369	83/04/28	50-333 G
8305110377	8305110360	83/05/02	50-334 P
8305110378	8305110370	83/04/25	50-320 S
8305110382	8305110373	83/05/05	50-327 S
8305110389	8305110375	83/04/26	50-366 S
8305110390	8305110380	83/05/02	50-302 S
8305110391	8305110369	83/04/28	50-333 G
8305110392	8305110384	83/04/25	50-293 S
8305110395	8305110388	83/04/29	50-225 G
8305110398	8305110360	83/05/02	50-334 P
8305110402	8305110396	83/05/05	50-255 R
8305110403	8305110393	83/04/27	50-247 S
8305110408	8305110400	83/04/25	50-333 S
8305110412	8305110404	83/04/29	50-321 S
8305110416	8305110405	83/04/21	50-333 S
8305110417	8305110410	83/04/28	50-366 S
8305110419	8305110409	83/05/06	50-328 S
8305110423	8305110415	83/05/10	REVIEW GRP
8305110428	8305110415	83/05/10	REVIEW GRP
8305110430	8305110421	83/04/28	50-387 S
8305110432	8305110415	83/05/10	REVIEW GRP
8305110433	8305110425	83/05/03	50-309 S
8305110434	8305110431	83/04/26	50-321 S
8305110436	8305110429	83/04/28	50-366 S

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305110443	8305110437	83/05/06	50-346 P
8305110449	8305110445	83/05/10	50-537 G
8305110452	8305110447	83/05/05	50-373 R
8305110455	8305110450	83/05/10	50-537 G
8305110465	8305110453	83/05/05	50-339 S
8305110485	8305110415	83/05/10	REVIEW GRP
8305110493	8305110415	83/05/10	REVIEW GRP
8305110496	8305110487	83/05/03	50-250 S
8305110508	8305110501	83/04/26	50-333 G
8305110509	8305110504	83/04/15	CONTRACT
8305110514	8305110510	83/04/27	50-333 S
8305110542	8305110540	83/04/28	50-266 F
8305110543	8305110538	83/04/21	50-286 F
8305110545	8305110539	83/04/14	CONTRACT
8305110546	8305110538	83/04/21	50-286 F
8305110556	8305110549	83/04/25	50-331 P
8305110560	8305110549	83/04/25	50-331 P
8305110566	8305110549	83/04/25	50-331 P
8305110574	8305110569	83/04/26	50-213 F
8305110579	8305110569	83/04/26	50-213 F
8305110581	8305230324	83/05/06	PR
8305110584	8305240155	83/04/22	COMMISSION
8305110601	8305240155	83/04/22	COMMISSION
8305110614	8305110612	83/05/06	71-9788
8305110626	8305110625	83/04/27	50-313 P
8305120014	8305120010	83/03/21	FOIA
8305120016	8305120013	83/05/09	50-295 R
8305120019	8305120010	83/03/21	FOIA
8305120023	8305120010	83/03/21	FOIA
8305120035	8305120010	83/03/21	FOIA
8305120041	8305120010	83/03/21	FOIA
8305120045	8305120010	83/03/21	FOIA
8305120052	8305120010	83/03/21	FOIA
8305120056	8305120010	83/03/21	FOIA
8305120062	8305120010	83/03/21	FOIA
8305120064	8305120055	83/05/06	50-289 P
8305120065	8305120010	83/03/21	FOIA
8305120067	8305120057	83/05/03	50-70 P
8305120068	8305120055	83/05/06	50-289 P
8305120072	8305120057	83/05/03	50-70 P
8305120074	8305120070	83/03/21	50-358 G
8305120078	8305120057	83/05/03	50-70 P
8305120093	8305120085	83/05/05	50-275 P
8305120096	8305120089	83/05/03	50-73 P
8305120099	8305120085	83/05/05	50-275 P
8305120100	8305120089	83/05/03	50-73 P
8305120124	8305120120	83/05/10	50-470 S
8305120150	8305120142	83/05/03	CONTRACT
8305120153	8305120146	83/05/03	50-335 P
8305120155	8305120145	83/04/11	50-445 G
8305120160	8305120146	83/05/03	50-335 P
8305120169	8305120163	83/04/26	50-293 P
8305120171	8305120146	83/05/03	50-335 P
8305120180	8305120163	83/04/26	50-293 P
8305120187	8305120163	83/04/26	50-293 P
8305120211	8305120203	83/05/09	50-275 R
8305120216	8305120203	83/05/09	50-275 R
8305120234	8305120224	83/03/01	40-672
8305120236	8305120233	83/03/15	50-397 K
8305120240	8305120224	83/03/01	40-672
8305120246	8305120224	83/03/01	40-672
8305120250	8305120244	83/05/09	50-281 P
8305120251	8305120224	83/03/01	10-672
8305120252	8305120241	83/05/03	50-336 P
8305120257	8305120224	83/03/01	40-672
8305120260	8305120224	83/03/01	40-672
8305120264	8305120224	83/03/01	40-672
8305120268	8305120224	83/03/01	40-672
8305120269	8305120224	83/03/01	70-82
8305120274	8305120224	83/03/01	40-672
8305120279	8305120224	83/03/01	40-672
8305120280	8305120278	83/05/09	50-352 G
8305120283	8305120224	83/03/01	40-672
8305120284	8305120224	83/03/01	40-672
8305120289	8305120224	83/03/01	40-672
8305120294	8305120224	83/03/01	40-672
8305120298	8305120224	83/03/01	40-672
8305120300	8305120297	83/05/09	50-322 G
8305120303	8305120224	83/03/01	40-672
8305120306	8305120301	83/05/06	50-322 G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305120307	8305120224	83/03/01	40-672	
8305120310	8305120224	83/03/01	40-672	
8305120311	8305120301	83/05/06	50-322	G
8305120316	8305120224	83/03/01	40-672	
8305120317	8305120312	83/05/06	50-320	T
8305120323	8305120312	83/05/06	50-320	T
8305120324	8305120318	83/05/04	50-316	S
8305120326	8305120312	83/05/06	50-320	T
8305120330	8305120312	83/05/06	50-320	T
8305120332	8305120329	83/05/09	50-322	G
8305120335	8305120312	83/05/06	50-320	T
8305120338	8305120312	83/05/06	50-320	T
8305120339	8305120333	83/05/10	50-275	P
8305120341	8305120312	83/05/06	50-320	T
8305120344	8305120312	83/05/06	50-320	T
8305120347	8305120312	83/05/06	50-320	T
8305120348	8305120345	83/04/27	50-461	G
8305120350	8305120312	83/05/06	50-320	T
8305120352	8305120224	83/03/01	40-672	
8305120353	8305120346	83/03/16	50-374	G
8305120355	8305120312	83/05/06	50-320	T
8305120356	8305120224	83/03/01	40-672	
8305120357	8305120312	83/05/06	50-320	T
8305120359	8305120224	83/03/01	40-672	
8305120364	8305120361	83/04/26	50-374	G
8305120368	8305120361	83/04/26	50-374	G
8305120369	8305120224	83/03/01	40-672	
8305120372	8305120224	83/03/01	40-672	
8305120374	8305120370	83/05/11	50-237	P
8305120376	8305120224	83/03/01	40-672	
8305120380	8305120378	83/05/05	50-322	G
8305120381	8305120224	83/03/01	70-82	
8305120397	8305120394	83/02/09	GA999	
8305120399	8305120396	83/05/04	50-315	B
8305120404	8305120392	83/04/26	50-410	B
8305120411	8305120402	83/05/02	50-334	B
8305120418	8305120414	83/05/02	50-313	B
8305120420	8305120415	83/04/27	50-373	G
8305120423	8305120419	83/04/25	50-546	G
8305120426	8305120421	83/05/04	50-309	F
8305120427	8305120421	83/05/04	50-309	F
8305120428	8305120419	83/04/25	50-546	G
8305120430	8305120422	83/04/21	50-387	B
8305120437	8305120429	83/04/29	50-358	B
8305120439	8305120433	83/04/29	50-298	B
8305120443	8305120438	83/04/28	50-373	G
8305120444	8305120440	83/04/25	50-237	G
8305120447	8305120438	83/04/28	50-373	G
8305120449	8305120440	83/04/25	50-237	G
8305120450	8305120224	83/03/01	40-672	
8305120451	8305120445	83/05/06	50-313	G
8305120454	8305120224	83/03/01	40-672	
8305120462	8305120224	83/03/01	40-672	
8305120463	8305120456	83/04/25	50-266	G
8305120466	8305120224	83/03/01	40-672	
8305120468	8305120456	83/04/25	50-266	G
8305120470	8305120460	83/05/02	50-397	E
8305120471	8305120465	83/04/29	40-215	
8305120472	8305120224	83/03/01	FOIA	
8305120474	8305120224	83/03/01	FOIA	
8305120476	8305120465	83/04/29	40-215	
8305120477	8305120460	83/05/02	50-397	E
8305120478	8305120224	83/03/01	40-672	
8305120480	8305120224	83/03/01	40-672	
8305120483	8305120224	83/03/01	40-672	
8305120484	8305120475	83/05/04	50-461	B
8305120485	8305120460	83/05/02	50-397	E
8305120489	8305120224	83/03/01	40-672	
8305120491	8305120460	83/05/02	50-397	E
8305120493	8305120224	83/03/01	40-672	
8305120494	8305120224	83/03/01	40-672	
8305120498	8305120495	83/05/04	50-266	P
8305120500	8305120224	83/03/01	40-672	
8305120502	8305120495	83/05/04	50-266	P
8305120503	8305120224	83/03/01	40-672	
8305120505	8305120495	83/05/04	50-266	P
8305120506	8305120504	83/05/03	50-313	P
8305120507	8305120224	83/03/01	40-672	
8305120508	8305120504	83/05/03	50-313	P
8305120509	8305120224	83/03/01	40-672	

ACCESSION NUMBER				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305120511	8305120224	83/03/01	40-672	
8305120512	8305120504	83/05/03	50-313	P
8305120514	8305120224	83/03/01	40-672	
8305120515	8305120224	83/03/01	40-672	
8305120517	8305120513	83/05/03	CONTRACT	
8305120518	8305120224	83/03/01	40-672	
8305120519	8305120224	83/03/01	40-672	
8305120523	8305120224	83/03/01	40-672	
8305120527	8305120224	83/03/01	40-672	
8305120530	8305120224	83/03/01	40-672	
8305120532	8305120524	83/03/30	50-128	P
8305120537	8305120524	83/03/30	50-128	P
8305120540	8305120224	83/03/01	40-672	
8305120544	8305120524	83/03/30	50-128	P
8305120560	8305120555	83/05/06	CONTRACT	
8305120570	8305120566	83/05/02	50-267	F
8305120578	8305120566	83/05/02	50-267	F
8305120585	8305120580	83/05/05	50-373	P
8305120589	8305120580	83/05/05	50-373	P
8305120593	8305120580	83/05/05	50-373	P
8305120602	8305120224	83/03/01	40-672	
8305120603	8305120594	83/05/02	50-285	F
8305120604	8305120598	83/05/03	50-250	G
8305120609	8305120224	83/03/01	40-672	
8305120613	8305120607	83/04/28	MISC	
8305120614	8305120224	83/03/01	FOIA	
8305120617	8305120224	83/03/01	FOIA	
8305120620	8305120224	83/03/01	40-672	
8305120621	8305120611	83/05/04	50-275	P
8305120623	8305120224	83/03/01	40-672	
8305120627	8305120224	83/03/01	40-672	
8305120630	8305120224	83/03/01	40-672	
8305120633	8305120224	83/03/01	40-672	
8305120642	8305120224	83/03/01	40-672	
8305120656	8305120224	83/03/01	70-925	
8305130006	8305120224	83/03/01	40-672	
8305130011	8305120224	83/03/01	40-672	
8305130016	8305120224	83/03/01	40-672	
8305130017	8305130010	83/05/04	50-338	P
8305130021	8305130013	83/05/11	50-445	G
8305130022	8305130018	83/05/09	50-247	P
8305130023	8305130010	83/05/04	50-338	P
8305130024	8305130018	83/05/09	50-247	P
8305130031	8305120224	83/03/01	40-672	
8305130037	8305120224	83/03/01	40-672	
8305130040	8305130033	83/05/11	50-445	G
8305130042	8305120224	83/03/01	40-672	
8305130047	8305130043	83/05/09	50-302	R
8305130053	8305120224	83/03/01	40-672	
8305130062	8305120224	83/03/01	40-672	
8305130070	8305130065	83/05/09	50-289	P
8305130074	8305130065	83/05/09	50-289	P
8305130086	8305130084	83/05/02	50-244	P
8305130091	8305130085	83/05/06	50-259	B
8305130095	8305130093	83/05/05	50-346	B
8305130101	8305130097	83/04/15	50-315	B
8305130104	8305130103	83/05/11	50-271	P
8305130112	8305130109	83/05/10	50-409	G
8305130120	8305130117	83/05/03	50-286	P
8305130123	8305130117	83/05/03	50-286	P
8305130130	8305130125	83/05/06	50-281	B
8305130134	8305130132	83/05/09	50-333	R
8305130135	8305130129	83/05/10	50-454	G
8305130136	8305130125	83/05/06	50-281	B
8305130141	8305130131	83/05/05	50-260	B
8305130144	8305130139	83/05/10	50-373	G
8305130145	8305130140	83/05/09	50-255	B
8305130152	8305130143	83/04/27	50-344	B
8305130155	8305130149	83/05/11	50-373	P
8305130172	8305130167	83/05/05	50-324	B
8305130174	8305130166	83/04/15	50-316	B
8305130176	8305130170	83/05/06	50-324	B
8305130182	8305130171	83/05/11	50-329	G
8305130184	8305130177	83/05/04	50-324	B
8305130188	8305130179	83/05/06	50-302	B
8305130191	8305130178	83/05/09	50-315	B
8305130195	8305130190	83/05/05	50-346	B
8305130200	8305130194	83/05/06	50-416	B
8305130201	8305130190	83/05/05	50-346	B
8305130202	8305130197	83/05/02	50-237	R

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305130203	8305130198	83/05/06	50-280	S
8305130204	8305130090	83/05/10	50-322	Q
8305130205	8305130190	83/05/05	50-346	S
8305130211	8305130196	83/05/10	50-304	S
8305130214	8305130208	83/05/09	50-255	S
8305130220	8305130212	83/05/03	50-254	S
8305130221	8305130215	83/05/04	50-155	Q
8305130223	8305120488	83/03/25	50-271	Q
8305130230	8305130225	83/05/09	50-255	S
8305130231	8305130219	83/04/28	50-312	S
8305130232	8305130224	83/04/22	50-344	S
8305130233	8305130215	83/05/04	50-155	Q
8305130234	8305130227	83/05/10	70-1308	
8305130237	8305130215	83/05/04	50-155	Q
8305130241	8305130215	83/05/04	50-155	Q
8305130242	8305130235	83/04/28	50-366	S
8305130243	8305130228	83/05/06	50-280	S
8305130251	8305130250	83/05/10	50-305	R
8305130261	8305130256	83/05/03	71-495	
8305130267	8305130258	83/05/05	50-409	Q
8305130271	8305130258	83/05/05	50-409	Q
8305130296	8305130294	83/04/20	50-269	P
8305130300	8305130299	83/05/09	CONTRACT	
8305130308	8305130307	83/05/02	50-272	F
8305130309	8305130307	83/05/02	50-272	F
8305130311	8305130310	83/05/02	50-387	F
8305130314	8305130310	83/05/02	50-387	F
8305130325	8305130322	83/04/22	40-8752	
8305130333	8305130330	83/04/15	40-8783	
8305130339	8305130335	83/04/25	50-443	A
8305130344	8305130343	83/05/10	50-382	A
8305130361	8305130356	83/05/10	CONTRACT	
8305160014	8305160011	83/05/05	50-361	S
8305160023	8305160018	83/05/10	50-219	Q
8305160025	8305160020	83/05/01	50-247	S
8305160028	8305160024	83/05/10	50-247	Q
8305160037	8305160029	83/05/11	50-142	Q
8305160051	8305160047	83/05/03	50-362	S
8305160057	8305160052	83/05/06	50-311	S
8305160062	8305160054	83/05/03	50-315	R
8305160064	8305160058	83/05/02	50-334	S
8305160069	8305160055	83/05/05	50-361	S
8305160072	8305160071	83/05/12	50-528	A
8305160076	8305160056	83/05/11	50-282	R
8305160078	8305160067	83/04/29	70-754	
8305160079	8305160075	83/04/30	50-247	S
8305160082	8305160065	83/05/03	50-309	S
8305160087	8305160083	83/05/02	50-354	Q
8305160091	8305160083	83/05/02	50-354	Q
8305160098	8305160092	83/05/11	50-263	R
8305160100	8305160094	83/05/10	50-348	Q
8305160101	8305160055	83/05/05	50-361	S
8305160102	8305160096	83/04/28	50-311	S
8305160103	8305160097	83/04/25	50-220	R
8305160107	8305160094	83/05/10	50-348	Q
8305160108	8305160104	83/05/11	50-315	P
8305160112	8305160106	83/05/12	50-333	P
8305160115	8305160110	83/05/03	50-362	S
8305160116	8305160111	83/05/11	50-285	R
8305160119	8305160114	83/05/03	50-244	S
8305160123	8305160118	83/05/05	50-311	S
8305160125	8305160120	83/05/03	50-362	S
8305160126	8305160121	83/05/10	50-315	P
8305160136	8305160134	83/05/09	50-293	R
8305160139	8305160137	83/05/02	50-293	Q
8305160141	8305160138	83/05/09	50-445	X
8305160142	8305160137	83/05/02	50-293	Q
8305160151	8305160124	83/05/06	50-387	S
8305160171	8305160169	83/05/10	50-266	R
8305160176	8305160172	83/05/11	50-275	P
8305160179	8305160089	83/05/10	50-528	Q
8305160189	8305160183	83/05/02	50-213	P
8305160199	8305160194	83/05/02	50-289	Q
8305160200	8305160195	83/03/31	50-312	Q
8305160204	8305160195	83/03/31	50-312	Q
8305160213	8305160195	83/03/31	50-312	Q
8305160218	8305160195	83/03/31	50-312	Q
8305160222	8305160195	83/03/31	50-312	Q
8305160244	8305160240	83/05/04	50-445	Q
8305160259	8305160256	83/04/19	40-8675	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305160261	8305160258	83/03/22	40-7580	
8305160271	8305160255	83/03/24	50-312	Q
8305160282	8305160279	83/05/02	50-389	F
8305160284	8305160279	83/05/02	50-389	F
8305160285	8305160283	83/05/02	50-369	F
8305160286	8305160283	83/05/02	50-369	F
8305160290	8305160288	83/05/02	50-313	F
8305160293	8305160292	83/05/02	50-413	F
8305160295	8305160292	83/05/02	50-413	F
8305160303	8305160301	83/05/03	XPORTLIC	
8305160305	8305160301	83/05/03	XPORTLIC	
8305160312	8305160304	83/05/02	50-247	Q
8305160316	8305160304	83/05/02	50-247	Q
8305160332	8305160318	83/05/06	50-367	A
8305160340	8305160337	83/05/04	50-298	P
8305160341	8305160337	83/05/04	50-298	P
8305160342	8305160337	83/05/04	50-298	P
8305160349	8305160346	83/04/26	50-261	P
8305160351	8305160346	83/04/26	50-261	P
8305160356	8305160346	83/04/26	50-261	P
8305160365	8305160363	83/04/14	PROJ	
8305160366	8305160362	83/05/05	50-327	P
8305160368	8305160362	83/05/05	50-327	P
8305160369	8305160362	83/05/05	50-327	P
8305170007	8305170006	83/05/12	50-271	R
8305170009	8305170004	83/04/29	50-382	Q
8305170014	8305170010	83/05/12	50-336	R
8305170019	8305170015	83/05/05	50-311	P
8305170021	8305170018	83/05/10	50-272	R
8305170022	8305170013	83/04/27	50-461	Q
8305170023	8305170015	83/05/05	50-311	P
8305170028	8305170015	83/05/05	50-311	P
8305170034	8305170030	83/05/09	50-296	S
8305170044	8305170039	83/05/13	50-289	Q
8305170047	8305170039	83/05/13	50-289	Q
8305170051	8305170039	83/05/13	50-289	Q
8305170052	8305170027	83/05/04	50-220	P
8305170054	8305170039	83/05/13	50-289	Q
8305170056	8305170027	83/05/04	50-220	P
8305170058	8305170039	83/05/13	50-289	Q
8305170060	8305170027	83/05/04	50-220	P
8305170067	8305170063	83/05/13	50-142	Q
8305170070	8305170065	83/04/01	CONTRACT	
8305170071	8305170069	83/05/02	50-271	P
8305170072	8305170069	83/05/02	50-271	P
8305170075	8305170069	83/05/02	50-271	P
8305170077	8305170065	83/04/01	CONTRACT	
8305170080	8305170076	83/05/04	50-315	P
8305170084	8305170079	83/05/05	50-272	P
8305170085	8305170064	83/04/29	50-272	S
8305170087	8305170079	83/05/05	50-272	P
8305170090	8305170079	83/05/05	50-272	P
8305170095	8305170064	83/04/29	50-272	S
8305170098	8305170093	83/05/10	50-358	A
8305170102	8305170097	83/05/11	71-4986	
8305170106	8305170064	83/04/29	50-272	S
8305170109	8305170076	83/05/04	50-315	P
8305170110	8305170064	83/04/29	50-272	S
8305170112	8305170076	83/05/04	50-315	P
8305170113	8305170108	83/05/10	71-9010	
8305170119	8305170117	83/05/05	50-272	P
8305170124	8305170117	83/05/05	50-272	P
8305170125	8305170120	83/05/11	XPORTLIC	
8305170129	8305170117	83/05/05	50-272	P
8305170136	8305170130	83/05/09	50-483	Q
8305170140	8305170134	83/05/04	50-237	S
8305170144	8305170138	83/05/10	50-266	Q
8305170147	8305170142	83/05/10	50-311	R
8305170153	8305170148	83/04/27	50-346	Q
8305170163	8305170159	83/05/05	50-237	S
8305170168	8305170166	83/04/27	50-155	Q
8305170171	8305170162	83/05/05	50-346	S
8305170174	8305170166	83/04/27	50-155	Q
8305170184	8305170167	83/05/09	50-254	Q
8305170188	8305170182	83/05/09	50-483	Q
8305170197	8305170191	83/05/09	50-389	S
8305170205	8305170201	83/05/05	50-346	S
8305170224	8305170212	83/05/04	50-498	Q
8305170225	8305170219	83/05/06	50-528	A
8305170227	8305170222	83/05/09	50-483	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305170233	8305170229	83/05/04	50-361	P
8305170234	8305170229	83/05/04	50-361	P
8305170236	8305170229	83/05/04	50-361	P
8305170240	8305170237	83/05/12	50-566	A
8305170248	8305170238	83/04/26	50-454	G
8305170250	8305170244	83/05/09	50-335	S
8305170251	8305170245	83/05/12	71-9015	
8305170252	8305170241	83/05/09	50-266	G
8305170259	8305170246	83/05/05	50-317	P
8305170260	8305170255	83/05/12	71-9151	
8305170262	8305170254	83/05/05	50-321	S
8305170263	8305170241	83/05/09	50-266	G
8305170266	8305170246	83/05/05	50-317	P
8305170269	8305170258	83/05/06	50-370	S
8305170271	8305170267	83/05/06	50-305	S
8305170273	8305170246	83/05/05	50-317	P
8305170274	8305170270	83/04/19	50-315	F
8305170284	8305170276	83/05/05	50-366	S
8305170285	8305170282	83/05/09	50-400	A
8305170298	8305170294	83/04/27	50-341	G
8305170300	8305170295	83/05/05	50-255	G
8305170304	8305170294	83/04/27	50-341	G
8305170307	8305170302	83/04/15	TOPREP	
8305170308	8305170303	83/04/27	50-346	G
8305170311	8305170302	83/04/15	TOPREP	
8305170312	8305170306	83/05/13	50-346	A
8305170313	8305170309	83/04/29	50-445	G
8305170315	8305170303	83/04/27	50-346	G
8305170318	8305170309	83/04/29	50-445	G
8305170331	8305170322	83/05/11	50-374	G
8305170333	8305170329	83/04/29	50-298	G
8305170338	8305170324	83/04/22	50-269	S
8305170339	8305170332	83/04/08	50-275	G
8305170340	8305170330	83/05/07	50-260	S
8305170342	8305170336	83/05/06	50-133	S
8305170343	8305170335	83/05/05	50-397	G
8305170344	8305170337	83/04/27	50-295	G
8305170348	8305170337	83/04/27	50-295	G
8305170349	8305170346	83/04/19	50-397	G
8305170353	8305170337	83/04/27	50-295	G
8305170358	8305170355	83/05/05	50-369	S
8305170361	8305170359	83/04/26	50-361	G
8305170365	8305170363	83/05/03	50-206	G
8305170370	8305170367	83/05/06	50-311	S
8305170376	8305170372	83/05/02	50-254	R
8305170378	8305170374	83/05/03	50-373	S
8305170381	8305170375	83/04/18	50-397	G
8305170382	8305170377	83/05/04	50-528	G
8305170387	8305170384	83/04/08	50-508	G
8305170388	8305170383	83/05/04	50-373	S
8305170390	8305170384	83/04/08	50-508	G
8305170394	8305170389	83/05/05	50-366	S
8305170395	8305170393	83/05/10	50-220	R
8305170396	8305170392	83/05/13	50-329	H
8305170400	8305170398	83/04/28	50-373	G
8305170402	8305170399	83/05/09	50-302	S
8305170403	8305170398	83/04/28	50-373	G
8305170411	8305170408	83/04/26	50-454	T
8305170412	8305170406	83/05/10	50-338	S
8305170413	8305170408	83/04/26	50-454	T
8305170420	8305170417	83/04/14	50-361	G
8305170421	8305170417	83/04/14	50-361	G
8305170425	8305170423	83/05/12	50-373	G
8305170426	8305170424	83/05/09	50-416	S
8305170431	8305170427	83/05/09	50-416	S
8305170432	8305170429	83/04/25	50-89	G
8305170433	8305170430	83/05/09	50-416	S
8305170437	8305170429	83/04/25	50-89	G
8305170438	8305170434	83/05/05	50-321	S
8305170439	8305170436	83/04/26	50-397	G
8305170444	8305170441	83/05/06	50-315	S
8305170445	8305170442	83/05/05	50-321	S
8305170451	8305170446	83/05/06	50-316	S
8305170454	8305170447	83/05/13	50-358	G
8305170460	8305170455	83/05/13	50-269	R
8305170470	8305170465	83/05/12	50-285	R
8305170473	8305170468	83/05/13	50-458	K
8305170480	8305170474	83/04/14	50-361	G
8305170490	8305170487	83/05/11	50-354	G
8305170498	8305170494	83/05/04	50-508	G

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305170499	8305170481	83/05/05	50-366	S
8305170501	8305170496	83/04/22	50-275	G
8305170504	8305170495	83/05/10	50-54	G
8305170506	8305170502	83/05/05	50-366	S
8305170508	8305170495	83/05/10	50-54	G
8305170517	8305170511	83/05/12	50-275	R
8305170521	8305170515	83/04/18	50-361	G
8305170525	8305170520	83/05/13	50-250	P
8305170530	8305170515	83/04/18	50-361	G
8305170532	8305170529	83/05/13	50-293	R
8305170537	8305170531	83/04/22	50-528	G
8305170540	8305170536	83/05/13	50-369	R
8305170544	8305170539	83/04/28	50-329	A
8305170553	8305170550	83/05/06	50-358	A
8305170564	8305170560	83/04/25	50-528	G
8305170566	8305170561	83/05/05	50-269	S
8305170567	8305170562	83/04/08	50-344	G
8305170569	8305170565	83/05/12	50-454	G
8305170570	8305170568	83/04/29	70-8	
8305170571	8305170568	83/04/29	70-8	
8305170572	8305170565	83/05/12	50-454	G
8305170576	8305170565	83/05/12	50-454	G
8305170581	8305170565	83/05/12	50-454	G
8305170588	8305170565	83/05/12	50-454	G
8305170590	8305170565	83/05/12	50-454	G
8305170593	8305170565	83/05/12	50-454	G
8305170607	8305170606	83/04/28	CONTRACT	
8305170614	8305170603	83/05/03	CONTRACT	
8305170621	8305170616	83/05/05	XPORTLIC	
8305170645	8305170619	83/05/09	50-301	P
8305170661	8305170648	83/05/13	CONTRACT	
8305170666	8305170657	83/05/04	50-282	F
8305170673	8305170669	83/05/05	50-346	P
8305170678	8305170669	83/05/05	50-346	P
8305170682	8305170669	83/05/05	50-346	P
8305170683	8305170657	83/05/04	50-282	F
8305170685	8305170677	83/05/11	50-313	F
8305170693	8305170688	83/05/13	CONTRACT	
8305170705	8305170701	83/05/06	50-461	A
8305170726	8305170723	83/05/09	50-369	P
8305170730	8305170723	83/05/09	50-369	P
8305180008	8305180007	83/05/04	50-278	P
8305180010	8305180005	83/04/12	FOIA	
8305180011	8305180007	83/05/04	50-278	P
8305180013	8305180005	83/04/12	FOIA	
8305180014	8305180007	83/05/04	50-278	P
8305180015	8305180012	83/05/05	50-395	P
8305180016	8305180005	83/04/12	FOIA	
8305180020	8305180012	83/05/05	50-395	P
8305180021	8305180005	83/04/12	FOIA	
8305180023	8305180012	83/05/05	50-395	P
8305180025	8305180024	83/05/03	50-275	P
8305180031	8305180005	83/04/12	FOIA	
8305180032	8305180024	83/05/05	50-275	P
8305180036	8305180030	83/05/05	50-368	P
8305180037	8305180005	83/04/12	FOIA	
8305180039	8305180026	83/04/29	50-298	P
8305180041	8305180030	83/05/05	50-368	P
8305180044	8305180005	83/04/12	FOIA	
8305180045	8305180034	83/05/05	50-269	P
8305180047	8305180038	83/05/10	50-247	P
8305180048	8305180040	83/05/05	50-324	P
8305180049	8305180030	83/05/05	50-368	P
8305180050	8305180026	83/04/29	50-298	P
8305180052	8305180005	83/04/12	FOIA	
8305180056	8305180005	83/04/12	FOIA	
8305180057	8305180040	83/05/05	50-324	P
8305180058	8305180053	83/05/05	50-369	P
8305180059	8305180034	83/05/05	50-269	P
8305180061	8305180040	83/05/05	50-324	P
8305180063	8305180005	83/04/12	FOIA	
8305180064	8305180001	83/03/09	50-498	G
8305180066	8305180053	83/05/05	50-369	P
8305180068	8305180034	83/05/05	50-269	P
8305180070	8305180005	83/04/12	FOIA	
8305180071	8305180026	83/04/29	50-298	P
8305180072	8305180053	83/05/05	50-369	P
8305180073	8305180067	83/05/05	XPORTLIC	
8305180074	8305180005	83/04/12	FOIA	
8305180075	8305180001	83/03/09	50-498	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305180080	8305180005	83/04/12	FOIA	
8305180083	8305180001	83/03/09	50-498	Q
8305180091	8305180081	83/05/03	50-331	P
8305180092	8305180005	83/04/12	FOIA	
8305180093	8305180081	83/05/03	50-331	P
8305180094	8305180001	83/03/09	50-498	Q
8305180096	8305180005	83/04/12	FOIA	
8305180100	8305180005	83/04/12	FOIA	
8305180104	8305180099	83/05/05	50-289	P
8305180106	8305180005	83/04/12	FOIA	
8305180111	8305180005	83/04/12	FOIA	
8305180114	8305180102	83/05/05	50-346	P
8305180116	8305180005	83/04/12	FOIA	
8305180121	8305180001	83/03/09	50-498	A
8305180123	8305180005	83/04/12	FOIA	
8305180125	8305180117	83/04/15	40-8500	
8305180126	8305180099	83/05/05	50-289	P
8305180128	8305180099	83/05/05	50-289	P
8305180135	8305180102	83/05/05	50-346	P
8305180146	8305180143	83/05/16	50-247	G
8305180148	8305180001	83/03/09	50-498	A
8305180153	8305180005	83/04/12	FOIA	
8305180157	8305180001	83/03/09	50-498	Q
8305180159	8305180005	83/04/12	FOIA	
8305180166	8305180005	83/04/12	FOIA	
8305180167	8305180001	83/03/09	50-498	Q
8305180174	8305180005	83/04/12	FOIA	
8305180175	8305180001	83/03/09	50-498	Q
8305180178	8305180005	83/04/12	FOIA	
8305180181	8305180001	83/03/09	50-498	Q
8305180186	8305180005	83/04/12	FOIA	
8305180187	8305180102	83/05/05	50-346	P
8305180189	8305180001	83/03/09	50-498	Q
8305180196	8305180005	83/04/12	FOIA	
8305180202	8305180001	83/03/09	50-498	Q
8305180204	8305180197	83/05/03	50-293	P
8305180207	8305180005	83/04/12	FOIA	
8305180211	8305180001	83/03/09	50-498	Q
8305180216	8305180197	83/05/03	50-293	P
8305180221	8305180001	83/03/09	50-498	A
8305180223	8305180005	83/04/12	FOIA	
8305180224	8305180213	83/05/04	50-327	P
8305180229	8305180197	83/05/03	50-293	P
8305180233	8305180005	83/04/12	FOIA	
8305180234	8305180213	83/05/04	50-327	P
8305180236	8305180001	83/03/09	50-498	A
8305180241	8305180005	83/04/12	FOIA	
8305180245	8305180238	83/05/06	50-320	P
8305180247	8305180005	83/04/12	FOIA	
8305180248	8305180213	83/05/04	50-327	P
8305180249	8305180238	83/05/06	50-320	P
8305180250	8305180001	83/03/09	50-498	A
8305180253	8305180238	83/05/06	50-320	P
8305180254	8305180001	83/03/09	50-498	T
8305180257	8305180001	83/03/09	50-498	T
8305180258	8305180005	83/04/12	FOIA	
8305180259	8305180256	83/05/16	50-412	F
8305180260	8305180252	83/05/17	50-322	U
8305180263	8305180005	83/04/12	FOIA	
8305180269	8305180005	83/04/12	FOIA	
8305180273	8305180262	83/04/29	TOPREP	
8305180276	8305180001	83/03/09	50-498	Q
8305180284	8305180279	83/05/06	50-321	R
8305180285	8305180005	83/04/12	FOIA	
8305180287	8305180283	83/05/16	50-412	K
8305180291	8305180005	83/04/12	FOIA	
8305180297	8305180292	83/05/16	50-155	P
8305180311	8305180304	83/05/10	50-245	P
8305180313	8305180306	83/05/06	PR	
8305180315	8305180001	83/03/09	50-498	A
8305180322	8305180316	83/03/29	FOIA	
8305180324	8305180244	83/05/12	50-322	Q
8305180326	8305180001	83/03/09	50-498	A
8305180328	8305180316	83/03/29	50-237	P
8305180331	8305180244	83/05/12	50-322	Q
8305180337	8305180001	83/03/09	50-498	A
8305180349	8305180346	83/05/13	50-331	R
8305180367	8305180366	83/05/17	50-322	H
8305180397	8305180385	83/05/09	50-454	A
8305180403	8305180395	83/05/13	50-275	R

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305180421	8305180412	83/05/12	CONTRACT	
8305180426	8305180414	83/05/16	50-352	E
8305180431	8305180414	83/05/16	50-352	E
8305180438	8305180414	83/05/16	50-352	E
8305180439	8305180437	83/05/17	50-170	U
8305180440	8305180433	83/05/17	50-219	P
8305180443	8305180414	83/05/16	50-352	E
8305180448	8305180445	83/05/17	50-322	H
8305180459	8305180430	83/05/17	50-322	H
8305180461	8305180430	83/05/17	50-322	H
8305180463	8305180458	83/05/13	50-358	F
8305180466	8305180465	83/05/11	50-395	Q
8305180548	8305180547	83/05/05	50-298	P
8305180560	8305180557	83/05/13	CONTRACT	
8305180562	8305180557	83/05/13	CONTRACT	
8305180566	8305180563	83/05/05	50-324	P
8305180569	8305180559	83/05/16	50-412	K
8305180576	8305180559	83/05/16	50-412	C
8305180577	8305180572	83/04/28	50-333	F
8305180579	8305180556	83/05/05	50-317	P
8305180580	8305180573	83/05/02	50-305	P
8305180585	8305180559	83/05/16	50-412	K
8305180589	8305180586	83/05/03	50-261	P
8305180592	8305180559	83/05/16	50-412	K
8305180598	8305180559	83/05/16	50-412	K
8305180606	8305180559	83/05/16	50-412	K
8305180607	8305180556	83/05/05	50-317	P
8305180613	8305180559	83/05/16	50-412	K
8305180614	8305180556	83/05/05	50-317	P
8305180625	8305180559	83/05/16	50-412	K
8305180630	8305180626	83/04/18	71-5607	
8305180634	8305180559	83/05/16	50-412	K
8305180641	8305180559	83/05/16	50-412	K
8305180648	8305180642	83/04/19	70-1257	
8305180650	8305180559	83/05/16	50-412	K
8305180655	8305180559	83/05/16	50-412	K
8305180661	8305180559	83/05/16	50-412	K
8305180666	8305180559	83/05/16	50-412	K
8305180673	8305180559	83/05/16	50-412	K
8305180674	8305180668	83/04/14	ACRS	
8305180676	8305180670	83/04/15	71-6272	
8305180678	8305180668	83/04/14	ACRS	
8305180681	8305180559	83/05/16	50-412	K
8305180685	8305180559	83/05/16	50-412	K
8305180688	8305180684	83/04/19	71-9150	
8305180693	8305180559	83/05/16	50-412	K
8305180695	8305180559	83/05/16	50-412	K
8305180697	8305180559	83/05/16	50-412	K
8305180702	8305180691	83/04/28	50-275	P
8305180705	8305180559	83/05/16	50-412	K
8305180708	8305180559	83/05/16	50-412	K
8305180715	8305180559	83/05/16	50-412	K
8305180720	8305180559	83/05/16	50-412	K
8305180721	8305180712	83/05/02	50-348	P
8305180725	8305180712	83/05/02	50-348	P
8305180728	8305180559	83/05/16	50-412	K
8305180731	8305180712	83/05/02	50-348	P
8305180735	8305180559	83/05/16	50-412	K
8305180740	8305180559	83/05/16	50-412	K
8305180743	8305180694	83/05/05	50-313	P
8305180746	8305180559	83/05/16	50-412	K
8305180749	8305180559	83/05/16	50-412	K
8305180755	8305180559	83/05/16	50-412	K
8305180760	8305180559	83/05/16	50-412	K
8305180764	8305180559	83/05/16	50-412	K
8305180767	8305180559	83/05/16	50-412	K
8305180769	8305180559	83/05/16	50-412	K
8305180792	8305180785	83/05/13	CONTRACT	
8305180804	8305180790	83/05/02	50-361	S
8305180836	8305180830	83/05/06	50-272	S
8305180839	8305180835	83/05/10	XPORTLIC	
8305180856	8305180854	83/05/02	50-250	P
8305190006	8305190004	83/05/08	70-2973	
8305190007	8305190004	83/05/08	70-2973	
8305190027	8305190019	83/05/06	50-454	Q
8305190029	8305190024	83/05/04	50-293	S
8305190038	8305190031	83/05/05	50-322	Q
8305190045	8305190005	83/03/11	50-329	Q
8305190050	8305190005	83/03/11	50-329	Q
8305190054	8305190046	83/05/03	50-397	A

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305190057	8305190053	83/05/09	XPORTLIC	
8305190060	8305190046	83/05/03	50-397	A
8305190061	8305190005	83/03/11	FOIA	
8305190068	8305190046	83/05/03	50-397	A
8305190077	8305190046	83/05/03	50-397	A
8305190084	8305190005	83/03/11	50-373	S
8305190088	8305190005	83/03/11	50-329	G
8305190097	8305190005	83/03/11	50-329	G
8305190102	8305190005	83/03/11	50-329	G
8305190108	8305190005	83/03/11	50-329	G
8305190112	8305190005	83/03/11	50-329	S
8305190119	8305190005	83/03/11	50-373	G
8305190124	8305190005	83/03/11	50-373	G
8305190128	8305190005	83/03/11	50-373	G
8305190132	8305190005	83/03/11	FOIA	
8305190145	8305190005	83/03/11	50-373	P
8305190151	8305190005	83/03/11	50-373	G
8305190153	8305190005	83/03/11	FOIA	
8305190154	8305190149	83/05/11	50-346	R
8305190162	8305190005	83/03/11	50-373	G
8305190167	8305190005	83/03/11	50-373	G
8305190169	8305190163	83/05/06	50-272	G
8305190174	8305190163	83/05/06	50-272	G
8305190175	8305190170	83/05/06	50-244	S
8305190179	8305190005	83/03/11	50-373	G
8305190181	8305190176	83/05/09	50-293	S
8305190183	8305190178	83/05/06	50-255	G
8305190184	8305190005	83/03/11	50-373	G
8305190189	8305190005	83/03/11	50-373	G
8305190191	8305190187	83/05/04	50-271	G
8305190201	8305190196	83/05/13	50-155	P
8305190207	8305190005	83/03/11	FOIA	
8305190232	8305190005	83/03/11	FOIA	
8305190238	8305190234	83/05/06	50-244	S
8305190247	8305190240	83/05/13	50-289	R
8305190256	8305190251	83/05/06	50-331	G
8305190263	8305190260	83/05/05	50-219	G
8305190266	8305190260	83/05/05	50-219	G
8305190273	8305190269	83/05/16	50-358	G
8305190276	8305190005	83/03/11	FOIA	
8305190281	8305190278	83/03/31	50-358	A
8305190283	8305190005	83/03/11	50-373	G
8305190284	8305190280	83/05/12	50-329	A
8305190289	8305190005	83/03/11	50-373	G
8305190290	8305190287	83/05/05	50-317	S
8305190292	8305190005	83/03/11	50-373	G
8305190296	8305190005	83/03/11	50-373	G
8305190299	8305190005	83/03/11	FOIA	
8305190300	8305190298	83/05/06	50-329	G
8305190302	8305190005	83/03/11	50-373	P
8305190303	8305190005	83/03/11	50-373	P
8305190304	8305190005	83/03/11	50-373	G
8305190306	8305190005	83/03/11	FOIA	
8305190307	8305190005	83/03/11	50-329	G
8305190309	8305190185	83/04/25	50-334	S
8305190311	8305190310	83/05/05	50-271	G
8305190313	8305190310	83/05/05	50-271	G
8305190314	8305190312	83/05/16	50-358	A
8305190322	8305190319	83/05/06	50-387	S
8305190329	8305190005	83/03/11	50-373	G
8305190330	8305190326	83/05/09	50-293	S
8305190332	8305190005	83/03/11	50-373	P
8305190334	8305190331	83/05/04	50-410	G
8305190337	8305190005	83/03/11	FOIA	
8305190341	8305190005	83/03/11	FOIA	
8305190352	8305190348	83/05/05	50-318	S
8305190353	8305190005	83/03/11	50-373	P
8305190357	8305190005	83/03/11	50-373	P
8305190360	8305190349	83/05/12	50-407	P
8305190361	8305190356	83/05/04	MISC	
8305190365	8305190005	83/03/11	50-373	P
8305190367	8305190005	83/03/11	50-373	P
8305190369	8305190349	83/05/12	50-407	P
8305190371	8305190366	83/05/16	50-155	G
8305190374	8305190005	83/03/11	FOIA	
8305190375	8305190366	83/05/16	50-155	G
8305190379	8305190005	83/03/11	50-373	P
8305190380	8305190349	83/05/12	50-407	P
8305190382	8305190378	83/05/16	50-322	G
8305190384	8305190005	83/03/11	50-373	G

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305190387	8305190005	83/03/11	50-373	G
8305190390	8305190005	83/03/11	50-373	P
8305190393	8305190005	83/03/11	50-373	S
8305190396	8305190005	83/03/11	50-329	G
8305190399	8305190005	83/03/11	50-373	G
8305190514	8305190506	83/04/12	CONTRACT	
8305200004	8305200002	83/05/13	CONTRACT	
8305200037	8305200031	83/03/23	40-4492	
8305200071	8305200062	83/05/11	CONTRACT	
8305200085	8305200081	83/05/04	50-336	P
8305200089	8305200081	83/05/04	50-336	P
8305200106	8305200103	83/04/28	50-269	P
8305200107	8305200100	83/05/02	50-277	G
8305200110	8305200100	83/05/02	50-277	G
8305200125	8305200122	83/05/12	50-400	D
8305200134	8305200131	83/04/29	CONTRACT	
8305200137	8305200129	83/05/11	XPORTLIC	
8305200149	8305200145	83/05/13	CONTRACT	
8305200165	8305200159	83/05/13	70-2982	
8305200179	8305200173	83/05/17	50-289	P
8305200196	8305200192	83/05/16	50-148	G
8305200199	8305200190	83/04/19	50-382	G
8305200204	8305200198	83/05/02	NUREG	
8305200238	8305200100	83/05/02	50-277	G
8305200244	8305200239	83/05/03	50-255	G
8305200247	8305200239	83/05/03	50-255	G
8305200253	8305200251	83/05/04	50-382	G
8305200256	8305200251	83/05/04	50-382	G
8305200268	8305200265	83/05/13	50-333	P
8305200272	8305200265	83/05/13	50-333	P
8305200273	8305200266	83/05/04	50-275	P
8305200284	8305200279	83/05/11	50-339	S
8305200286	8305200280	83/05/09	50-416	S
8305200290	8305200283	83/05/11	50-220	S
8305200300	8305200288	83/05/12	50-260	S
8305200301	8305200295	83/05/13	50-237	S
8305200307	8305200295	83/05/13	50-237	S
8305200315	8305200308	83/05/10	GA999	
8305200318	8305200310	83/05/17	70-143	
8305200319	8305200313	83/05/13	50-313	G
8305200323	8305200308	83/05/10	GA999	
8305200327	8305200306	83/05/12	50-348	R
8305200332	8305200308	83/05/10	GA999	
8305200337	8305200330	83/05/18	50-346	G
8305200340	8305200333	83/05/04	GA999	
8305200352	8305200311	83/05/12	50-395	G
8305200362	8305200357	83/05/12	50-364	R
8305200364	8305200358	83/05/16	50-275	R
8305200374	8305200360	83/05/12	50-309	S
8305200376	8305200370	83/04/28	GA999	
8305200379	8305200370	83/04/28	GA999	
8305200383	8305200382	83/05/17	50-220	G
8305200392	8305200386	83/04/25	50-220	G
8305200397	8305200394	83/05/09	50-272	S
8305200412	8305200405	83/05/16	50-286	P
8305200415	8305200411	83/05/10	GA999	
8305200418	8305200411	83/05/10	GA999	
8305200419	8305200416	83/05/18	50-445	G
8305200422	8305200411	83/05/10	GA999	
8305200426	8305200420	83/05/11	50-260	S
8305200432	8305200427	83/05/13	50-327	S
8305200439	8305200436	83/05/17	50-334	G
8305200440	8305200438	83/05/17	50-369	P
8305200451	8305200445	83/04/04	50-313	S
8305200457	8305200446	83/05/10	GA999	
8305200462	8305200446	83/05/10	GA999	
8305200463	8305200459	83/05/20	50-537	B
8305200465	8305200458	83/05/20	50-315	F
8305200468	8305200446	83/05/10	GA999	
8305200473	8305200469	83/05/16	50-309	P
8305200482	8305200472	83/05/17	70-925	
8305200493	8305200484	83/05/12	50-416	S
8305200514	8305200509	83/05/17	50-346	G
8305200515	8305200510	83/05/13	50-395	S
8305200518	8305200512	83/05/13	50-483	G
8305200520	8305200509	83/05/17	50-346	G
8305200522	8305200508	83/05/17	50-454	G
8305200527	8305200509	83/05/17	50-346	G
8305200528	8305200516	83/04/27	50-267	G
8305200532	8305200523	83/05/11	50-416	S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305200540	8305200508	83/05/17	50-454 Q
8305200543	8305200538	83/05/06	50-324 S
8305200546	8305200537	83/05/11	50-311 S
8305200551	8305200547	83/05/06	50-289 S
8305200561	8305200555	83/05/11	50-387 S
8305200565	8305200556	83/05/17	50-369 Q
8305200567	8305200553	83/05/18	50-329 A
8305200575	8305200553	83/05/18	50-329 A
8305200581	8305200577	83/05/12	50-327 S
8305200583	8305200574	83/05/13	50-338 S
8305200584	8305200564	83/05/13	50-317 R
8305200593	8305200589	83/05/13	QA999
8305200594	8305200590	83/05/18	50-322 Q
8305200611	8305200591	83/05/02	50-263 Q
8305200623	8305200619	83/05/18	REVIEW GRP
8305200624	8305200613	83/05/19	50-142 T
8305200627	8305200619	83/05/18	REVIEW GRP
8305200628	8305200620	83/05/17	50-317 Q
8305200633	8305200626	83/05/12	50-395 S
8305200634	8305200619	83/05/18	REVIEW GRP
8305200637	8305200621	83/05/11	50-373 P
8305200644	8305200631	83/05/04	50-317 R
8305200646	8305200640	83/05/11	50-387 S
8305200647	8305200621	83/05/11	50-373 P
8305200648	8305200636	83/05/19	50-537 Q
8305200650	8305200631	83/05/04	50-317 R
8305200654	8305200619	83/05/18	REVIEW GRP
8305200655	8305200621	83/05/11	50-373 P
8305200661	8305200619	83/05/18	REVIEW GRP
8305200664	8305200619	83/05/18	REVIEW GRP
8305200665	8305200621	83/05/11	50-373 P
8305200671	8305200619	83/05/18	REVIEW GRP
8305200673	8305200668	83/05/04	QA999
8305200674	8305200666	83/05/18	50-445 Q
8305200675	8305200621	83/05/11	50-373 P
8305200677	8305200619	83/05/18	REVIEW GRP
8305200678	8305200668	83/05/04	QA999
8305200679	8305200676	83/05/13	50-400 K
8305200681	8305200621	83/05/11	50-373 P
8305200683	8305200621	83/05/11	50-373 P
8305200684	8305200621	83/05/11	50-373 P
8305200688	8305200621	83/05/11	50-373 P
8305200691	8305200621	83/05/11	50-373 P
8305200701	8305200608	83/05/12	50-213 S
8305200710	8305200709	83/05/05	50-338 P
8305200717	8305200709	83/05/05	50-338 P
8305200720	8305200709	83/05/05	50-338 P
8305200724	8305200709	83/05/05	50-338 P
8305230004	8305230003	83/05/03	50-528 A
8305230009	8305230007	83/05/20	50-458 F
8305230010	8305230006	83/04/29	ADVCM
8305230012	8305230006	83/04/29	ADVCM
8305230017	8305230006	83/04/29	ADVCM
8305230020	8305230015	83/04/18	50-201 P
8305230025	8305230006	83/04/29	ADVCM
8305230031	8305230024	83/05/09	CONTRACT
8305230032	8305230006	83/04/29	ADVCM
8305230033	8305230026	83/01/25	70-1359
8305230035	8305230026	83/01/25	70-1359
8305230039	8305230028	83/03/31	FOIA
8305230040	8305230006	83/04/29	ADVCM
8305230047	8305230028	83/03/31	FOIA
8305230048	8305230006	83/04/29	ADVCM
8305230056	8305230041	83/04/14	PROJ
8305230057	8305230028	83/03/31	FOIA
8305230070	8305230065	83/03/31	FOIA
8305230086	8305230080	83/04/12	71-5607
8305230118	8305230107	83/05/03	71-9015
8305230125	8305230107	83/05/03	71-9015
8305230134	8305230112	83/03/22	70-1193
8305230137	8305230127	83/05/17	50-309 F
8305230139	8305230112	83/03/22	70-1193
8305230140	8305230127	83/05/17	50-309 F
8305230142	8305230127	83/05/17	50-309 F
8305230145	8305230128	83/05/11	50-313 P
8305230146	8305230127	83/05/17	50-309 F
8305230151	8305230127	83/05/17	50-309 F
8305230154	8305230127	83/05/17	50-309 F
8305230157	8305230127	83/05/17	50-309 F
8305230162	8305230127	83/05/17	50-309 F

ACCESSION NUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305230167	8305230127	83/05/17	50-309 F
8305230169	8305230159	83/05/13	CONTRACT
8305230175	8305230127	83/05/17	50-309 F
8305230176	8305230165	83/05/02	71-496
8305230179	8305230112	83/03/22	70-1193
8305230181	8305230127	83/05/17	50-309 F
8305230186	8305230112	83/03/22	70-1193
8305230196	8305230112	83/03/22	70-1193
8305230199	8305230189	83/05/17	50-320 T
8305230207	8305230112	83/03/22	40-1478
8305230209	8305230189	83/05/17	50-320 T
8305230221	8305230213	83/05/18	50-275 R
8305230222	8305230112	83/03/22	40-1478
8305230224	8305230216	83/05/11	50-275 R
8305230233	8305230112	83/03/22	40-1478
8305230234	8305230232	83/03/21	FOIA
8305230249	8305230245	83/05/17	CONTRACT
8305230251	8305230246	83/04/28	FOIA
8305230254	8305230246	83/04/28	FOIA
8305230274	8305230256	83/05/17	CONTRACT
8305230284	8305230276	83/05/19	50-213 P
8305230289	8305230281	83/05/13	CONTRACT
8305230292	8305230285	83/05/19	50-537 A
8305230293	8305230287	83/05/02	CONTRACT
8305230308	8305230300	83/05/13	50-305 P
8305230311	8305230298	83/05/11	CONTRACT
8305230314	8305230305	83/04/29	50-458 Q
8305230330	8305230323	83/05/13	50-245 F
8305230332	8305230326	83/05/12	CONTRACT
8305230333	8305230324	83/05/06	PR
8305230338	8305230323	83/05/13	50-245 F
8305230348	8305230337	83/05/06	50-313 Q
8305230367	8305230360	83/05/05	COMMISSION
8305230388	8305230377	83/05/05	50-289 U
8305230399	8305230381	83/05/11	50-309 P
8305230406	8305230397	83/05/05	COMMISSION
8305230425	8305230420	83/04/27	COMMISSION
8305230427	8305230426	83/05/12	50-267 R
8305230428	8305230420	83/04/27	COMMISSION
8305230431	8305050020	83/05/02	50-220 P
8305230432	8305230424	83/05/13	50-281 S
8305230434	8305230429	83/05/13	50-293 Q
8305230437	8305230436	83/05/17	50-219 R
8305230440	8305230435	83/04/28	50-289 U
8305230441	8305230430	83/04/18	50-213 S
8305230443	8305230435	83/04/28	50-289 U
8305230446	8305230435	83/04/28	50-289 U
8305230449	8305230445	83/05/13	50-445 Q
8305230451	8305230424	83/05/13	50-281 S
8305230453	8305230435	83/04/28	50-289 U
8305230458	8305230452	83/05/06	50-244 S
8305230459	8305230454	83/05/04	50-333 S
8305230460	8305230455	83/05/17	50-289 Q
8305230461	8305230457	83/04/29	COMMISSION
8305230467	8305230464	83/05/06	50-285 Q
8305230468	8305230463	83/05/09	50-366 S
8305230469	8305230465	83/05/02	COMMISSION
8305230475	8305230464	83/05/06	50-285 Q
8305230476	8305230473	83/05/06	50-482 Q
8305230477	8305230471	83/05/04	50-387 S
8305230479	8305230474	83/05/03	COMMISSION
8305230480	8305230473	83/05/06	50-482 Q
8305230483	8305230472	83/05/10	50-309 S
8305230489	8305230485	83/05/18	50-482 Q
8305230490	8305230486	83/05/09	50-366 S
8305230498	8305230495	83/05/09	50-366 S
8305230513	8305230510	83/05/05	50-317 S
8305230515	8305230509	83/05/09	50-293 S
8305230519	8305230511	83/04/29	MISC
8305230521	8305230516	83/04/27	50-293 S
8305230524	8305230511	83/04/29	MISC
8305230527	8305230520	83/05/09	50-334 S
8305230528	8305230522	83/05/05	50-318 S
8305230531	8305230511	83/04/29	MISC
8305230536	8305230530	83/05/16	50-327 S
8305230537	8305230535	83/05/12	50-293 R
8305230538	8305230533	83/05/04	50-293 S
8305230544	8305230540	83/05/13	50-348 S
8305230550	8305230540	83/05/13	50-348 S
8305230557	8305230549	83/05/10	50-245 S

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305230559	8305230556	83/05/18	50-275	R
8305230560	8305230555	83/05/05	50-317	S
8305230564	8305230561	83/04/29	50-244	S
8305230570	8305230567	83/05/18	50-482	I
8305230572	8305230567	83/05/18	50-482	I
8305230577	8305230568	83/05/09	50-321	S
8305230582	8305230574	83/05/13	50-410	A
8305230585	8305230574	83/05/13	50-410	A
8305230587	8305230574	83/05/13	50-410	A
8305230592	8305230574	83/05/13	50-410	A
8305230599	8305230574	83/05/13	50-410	A
8305230603	8305230574	83/05/13	50-410	A
8305230607	8305230574	83/05/13	50-410	A
8305230614	8305230574	83/05/13	50-410	A
8305230619	8305230573	83/04/19	50-237	S
8305230622	8305230574	83/05/13	50-410	A
8305230628	8305230574	83/05/13	50-410	A
8305230637	8305230574	83/05/13	50-410	A
8305230644	8305230574	83/05/13	50-410	A
8305230650	8305230574	83/05/13	50-410	A
8305230656	8305230574	83/05/13	50-410	A
8305230661	8305230574	83/05/13	50-410	A
8305230664	8305230660	83/04/21	COMMISSION	
8305230666	8305230574	83/05/13	50-410	A
8305230676	8305230670	83/04/18	50-3	F
8305230678	8305230574	83/05/13	50-410	A
8305230680	8305230574	83/05/13	50-410	A
8305230681	8305230574	83/05/13	50-410	A
8305230684	8305230574	83/05/13	50-410	A
8305230687	8305230574	83/05/13	50-410	A
8305230691	8305230574	83/05/13	50-410	A
8305230695	8305230692	83/04/20	COMMISSION	
8305230696	8305230574	83/05/13	50-410	A
8305230699	8305230574	83/05/13	50-410	A
8305230701	8305230574	83/05/13	50-410	A
8305230719	8305230717	83/05/18	50-369	S
8305230725	8305230723	83/05/12	50-368	P
8305230735	8305230732	83/04/13	COMMISSION	
8305240005	8305240003	83/05/20	50-445	Q
8305240008	8305240006	83/05/20	50-329	Q
8305240012	8305240001	83/05/20	50-358	Q
8305240016	8305240001	83/05/20	50-358	Q
8305240023	8305240019	83/05/10	50-537	U
8305240026	8305240020	83/05/09	50-255	G
8305240037	8305240032	83/05/17	50-255	Q
8305240054	8305240049	83/05/19	50-313	Q
8305240061	8305240029	83/05/06	50-282	Q
8305240072	8305240067	83/05/17	50-346	Q
8305240084	8305240073	83/05/06	COMMISSION	
8305240086	8305240078	83/05/17	50-315	Q
8305240098	8305240087	83/03/31	50-373	Q
8305240125	8305240087	83/03/31	50-373	Q
8305240154	8305240144	83/05/16	TOPREP	
8305240167	8305240155	83/04/22	COMMISSION	
8305240179	8305240155	83/04/22	COMMISSION	
8305240190	8305240155	83/04/22	COMMISSION	
8305240220	8305240216	83/05/17	50-289	Q
8305240232	8305240227	83/05/10	50-29	Q
8305240242	8305240238	83/05/13	50-275	R
8305240244	8305240241	83/05/06	50-373	Q
8305240247	8305240241	83/05/06	50-373	Q
8305240256	8305240252	83/04/14	50-358	Q
8305240259	8305240254	83/03/31	50-287	P
8305240260	8305240254	83/03/31	50-416	P
8305240263	8305240252	83/04/14	50-358	Q
8305240265	8305240254	83/03/31	50-416	P
8305240267	8305240252	83/04/14	50-358	Q
8305240268	8305240264	83/05/04	50-456	Q
8305240269	8305240254	83/03/31	50-317	P
8305240272	8305240252	83/04/14	50-358	Q
8305240275	8305240252	83/04/14	50-358	Q
8305240291	8305240285	83/05/19	50-272	Q
8305240292	8305240284	83/05/18	50-331	Q
8305240306	8305240302	83/05/06	50-315	Q
8305240308	8305240301	83/05/17	50-373	Q
8305240309	8305240302	83/05/06	50-315	Q
8305240315	8305240301	83/05/17	50-373	Q
8305240340	8305240337	83/05/09	40-3392	
8305240346	8305240344	83/05/20	GA999	
8305240357	8305240352	83/05/20	GA999	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305240361	8305240352	83/05/20	GA999	
8305240363	8305240352	83/05/20	GA999	
8305240369	8305240365	83/03/31	FOIA	
8305240370	8305240362	83/05/16	50-315	S
8305240371	8305240367	83/05/17	50-255	G
8305240374	8305240362	83/05/16	50-315	S
8305240393	8305240390	83/05/20	50-275	Q
8305240403	8305240400	83/05/20	GA999	
8305240413	8305240407	83/05/19	50-461	A
8305240415	8305240411	83/05/20	GA999	
8305240421	8305240407	83/05/19	50-461	A
8305240433	8305240426	83/04/25	GA999	
8305240435	8305240431	83/05/20	GA999	
8305240437	8305240426	83/04/25	GA999	
8305240445	8305240426	83/04/25	GA999	
8305240452	8305240426	83/04/25	GA999	
8305240457	8305240449	83/05/23	50-289	Q
8305240462	8305240426	83/04/25	GA999	
8305240476	8305240488	83/05/06	50-219	R
8305240484	8305240481	83/05/20	50-348	I
8305240519	8305240510	83/05/06	50-244	R
8305240539	8305240533	83/05/20	50-247	T
8305240542	8305240538	83/05/23	50-247	Q
8305240556	8305240552	83/05/03	71-6550	
8305240558	8305240555	83/05/20	50-247	T
8305240565	8305240505	83/05/11	50-155	P
8305240570	8305240566	83/05/18	50-3	T
8305240574	8305240566	83/05/18	50-3	T
8305240618	8305240614	83/04/21	50-201	P
8305250034	8305250029	83/03/29	FOIA	
8305250038	8305250029	83/03/29	FOIA	
8305250043	8305250029	83/03/29	FOIA	
8305250058	8305250056	83/05/20	50-498	K
8305250084	8305250077	83/05/19	50-295	P
8305250135	8305250133	83/05/20	50-352	A
8305250144	8305240087	83/03/31	50-373	F
8305250186	8305250066	83/05/18	50-275	R
8305250208	8305250202	83/05/23	50-289	Q
8305250221	8305250209	83/05/18	50-361	P
8305250225	8305250202	83/05/23	50-289	Q
8305250228	8305250209	83/05/18	50-361	P
8305250230	8305250226	83/05/13	50-286	Q
8305250263	8305250255	83/05/19	50-320	P
8305250271	8305250269	83/05/20	50-289	P
8305250295	8305250291	83/05/12	50-219	Q
8305250297	8305250294	83/05/20	50-483	Q
8305250300	8305250294	83/05/20	50-483	Q
8305250303	8305250299	83/05/13	50-277	Q
8305250304	8305250294	83/05/20	50-483	Q
8305250306	8305250299	83/05/13	50-277	Q
8305250308	8305250305	83/05/11	GEN TEC	IB
8305250309	8305250307	83/05/13	50-213	Q
8305250312	8305250310	83/05/11	50-309	Q
8305250313	8305250311	83/05/04	COMMISSION	
8305250314	8305250310	83/05/11	50-309	Q
8305250341	8305250294	83/05/20	50-483	Q
8305250346	8305250294	83/05/20	50-483	Q
8305250351	8305250294	83/05/20	50-483	Q
8305250354	8305250294	83/05/20	50-483	Q
8305250356	8305250294	83/05/20	50-483	Q
8305250358	8305250294	83/05/20	50-483	Q
8305250359	8305250294	83/05/20	50-483	Q
8305250360	8305250294	83/05/20	50-483	Q
8305250363	8305250294	83/05/20	50-483	Q
8305250372	8305250294	83/05/20	50-483	Q
8305250383	8305250294	83/05/20	50-483	Q
8305250388	8305250294	83/05/20	50-483	Q
8305250393	8305250377	83/05/19	50-237	Q
8305250394	8305250294	83/05/20	50-483	Q
8305250399	8305250377	83/05/19	50-237	Q
8305250401	8305250294	83/05/20	50-483	Q
8305250403	8305250294	83/05/20	50-483	Q
8305250407	8305250377	83/05/19	50-237	Q
8305250408	8305250294	83/05/20	50-483	Q
8305250412	8305250294	83/05/20	50-483	Q
8305250413	8305250377	83/05/19	50-237	Q
8305250419	8305250294	83/05/20	50-483	Q
8305250424	8305250294	83/05/20	50-483	Q
8305250428	8305250294	83/05/20	50-483	Q
8305250431	8305250427	83/05/11	50-29	Q

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305250432	8305250294	83/05/20	50-483	G
8305250436	8305250294	83/05/20	50-483	G
8305250440	8305250294	83/05/20	50-483	G
8305250441	8305250438	83/05/12	50-244	G
8305250443	8305250437	83/05/11	50-245	G
8305250444	8305250294	83/05/20	50-483	G
8305250446	8305250438	83/05/12	50-244	G
8305250448	8305250294	83/05/20	50-483	G
8305250450	8305250447	83/05/11	50-271	G
8305250451	8305250294	83/05/20	50-483	G
8305250453	8305250438	83/05/12	50-244	G
8305250456	8305250454	83/05/19	50-184	G
8305250458	8305250294	83/05/20	50-483	G
8305250461	8305250294	83/05/20	50-483	G
8305250463	8305250294	83/05/20	50-483	G
8305250465	8305250459	83/05/11	50-336	G
8305250467	8305250466	83/05/20	50-275	R
8305250468	8305250294	83/05/20	50-483	G
8305250474	8305250294	83/05/20	50-483	G
8305250477	8305250294	83/05/20	50-483	G
8305250482	8305250294	83/05/20	50-483	G
8305250484	8305250481	83/05/20	50-335	P
8305250486	8305250294	83/05/20	50-483	G
8305250490	8305250294	83/05/20	50-483	G
8305250491	8305250472	83/05/20	50-250	P
8305250493	8305250489	83/05/16	PR	
8305250496	8305250294	83/05/20	50-483	G
8305250498	8305250488	83/05/20	50-412	G
8305250500	8305250495	83/05/13	50-289	G
8305250502	8305250294	83/05/20	50-483	G
8305250504	8305250497	83/05/11	50-213	G
8305250505	8305250495	83/05/13	50-289	G
8305250506	8305250294	83/05/20	50-483	G
8305250509	8305250503	83/05/12	50-286	G
8305250511	8305250294	83/05/20	50-483	G
8305250515	8305250294	83/05/20	50-483	G
8305250518	8305250510	83/05/18	50-213	P
8305250520	8305250512	83/05/23	50-206	P
8305250521	8305250294	83/05/20	50-483	G
8305250523	8305250514	83/05/18	50-220	P
8305250524	8305250294	83/05/20	50-483	G
8305250531	8305250294	83/05/20	50-483	G
8305250535	8305250529	83/04/25	PR	
8305250536	8305250294	83/05/20	50-483	G
8305250540	8305250294	83/05/20	50-483	G
8305250542	8305250294	83/05/20	50-483	G
8305250544	8305250294	83/05/20	50-483	G
8305250546	8305250541	83/05/09	50-280	G
8305250548	8305250294	83/05/20	50-483	G
8305250552	8305250294	83/05/20	50-483	G
8305250553	8305250294	83/05/20	50-483	G
8305250557	8305250294	83/05/20	50-483	G
8305250559	8305250294	83/05/20	50-483	G
8305250562	8305250294	83/05/20	50-483	G
8305250565	8305250560	83/05/20	50-213	G
8305250566	8305250294	83/05/20	50-483	G
8305250568	8305250563	83/05/13	70-371	
8305250573	8305250294	83/05/20	50-483	G
8305250574	8305250569	83/05/20	50-271	P
8305250575	8305250571	83/05/13	50-387	G
8305250576	8305250294	83/05/20	50-483	G
8305250577	8305250572	83/05/10	50-271	G
8305250578	8305250563	83/05/13	70-371	
8305250580	8305250294	83/05/20	50-483	G
8305250582	8305250563	83/05/13	70-371	
8305250583	8305250294	83/05/20	50-483	G
8305250584	8305250294	83/05/20	50-483	G
8305250586	8305250563	83/05/13	70-371	
8305250587	8305250294	83/05/20	50-483	G
8305250589	8305250294	83/05/20	50-483	G
8305250590	8305250588	83/05/19	50-289	P
8305250604	8305250603	83/05/18	40-8027	
8305250607	8305250605	83/05/18	70-371	
8305260002	8305260001	83/05/19	50-537	L
8305260004	8305260003	83/04/18	71-5552	
8305260048	8305260037	83/05/24	50-447	E
8305260057	8305260055	83/05/18	XPORTLIC	
8305260087	8305260081	83/04/08	CONTRACT	
8305260173	8305260168	83/05/23	50-483	G
8305260183	8305260182	83/05/17	50-275	G

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305260211	8305260207	83/05/11	50-250	P
8305260222	8305260206	83/05/23	CONTRACT	
8305260224	8305260221	83/05/12	50-440	G
8305260225	8305260223	83/05/13	50-358	G
8305260231	8305260223	83/05/13	50-358	G
8305260239	8305260236	83/05/09	50-440	G
8305260243	8305260236	83/05/09	50-440	G
8305260245	8305260241	83/05/19	50-346	P
8305260247	8305260246	83/05/19	50-461	A
8305260248	8305260241	83/05/19	50-346	P
8305260250	8305260244	83/05/12	50-461	G
8305260253	8305260246	83/05/19	50-461	A
8305260255	8305260252	83/05/05	50-397	G
8305260258	8305260256	83/05/12	50-409	G
8305260262	8305260257	83/05/19	50-275	G
8305260266	8305260259	83/05/20	50-155	G
8305260272	8305260270	83/05/23	50-275	G
8305260273	8305260269	83/05/10	40-8137	
8305260274	8305260270	83/05/23	50-275	G
8305260282	8305260278	83/05/20	50-454	G
8305260304	8305260301	83/05/23	50-298	G
8305260311	8305260309	83/05/19	50-330	B
8305260313	8305260309	83/05/19	50-330	B
8305260321	8305260319	83/05/03	50-528	G
8305260325	8305260320	83/05/24	50-324	P
8305260326	8305260319	83/05/03	50-528	G
8305260327	8305260322	83/05/24	50-352	G
8305260331	8305260329	83/05/12	50-373	G
8305260334	8305260329	83/05/12	50-373	G
8305260337	8305260336	83/05/23	50-358	A
8305260338	8305260336	83/05/23	50-358	A
8305260341	8305260340	83/05/13	CONTRACT	
8305260355	8305260350	83/05/13	71-9151	
8305260373	8305260350	83/05/13	71-9151	
8305260380	8305260377	83/05/16	CONTRACT	
8305260399	8305260395	83/04/28	40-299	
8305260401	8305260397	83/03/28	50-358	A
8305260405	8305260397	83/03/28	50-358	T
8305270010	8305270007	83/05/26	50-255	F
8305270011	8305270008	83/05/20	50-261	P
8305270012	8305270006	83/04/11	TOPREP	
8305270027	8305270022	83/03/08	50-320	P
8305270034	8305270032	83/05/16	XPORTLIC	
8305270035	8305270022	83/03/08	50-320	P
8305270037	8305270033	83/05/20	50-423	G
8305270040	8305270022	83/03/08	50-320	P
8305270046	8305270022	83/03/08	50-320	P
8305270048	8305270022	83/03/08	50-320	P
8305270050	8305270045	83/05/19	50-271	G
8305270052	8305270045	83/05/19	50-271	G
8305270053	8305270043	83/05/23	50-272	G
8305270055	8305270045	83/05/19	50-271	G
8305270063	8305270057	83/05/16	50-329	K
8305270066	8305270057	83/05/16	50-329	K
8305270071	8305270060	83/05/26	50-244	P
8305270086	8305270083	83/04/20	50-395	G
8305270093	8305270090	83/05/16	CONTRACT	
8305270094	8305270091	83/04/18	50-395	G
8305270095	8305270092	83/05/20	50-302	P
8305270100	8305270097	83/04/28	CONTRACT	
8305270101	8305270098	83/04/19	50-389	G
8305270105	8305270103	83/05/06	CONTRACT	
8305270110	8305270108	83/05/18	CONTRACT	
8305270116	8305270113	83/04/11	70-1113	
8305270119	8305270114	83/05/18	50-245	P
8305270121	8305270112	83/04/06	50-302	G
8305270145	8305270142	83/05/18	70-1151	
8305270149	8305270144	83/05/24	QA999	
8305270151	8305270146	83/03/25	50-369	G
8305270159	8305270156	83/04/27	70-1113	
8305270160	8305270154	83/03/29	50-369	G
8305270167	8305270161	83/05/18	70-143	
8305270179	8305270176	83/05/05	50-389	G
8305270186	8305270182	83/05/24	50-344	P
8305270188	8305270182	83/05/24	50-344	P
8305270190	8305270187	83/05/23	50-334	P
8305270193	8305270191	83/05/23	50-456	G
8305270200	8305270197	83/05/02	50-537	G
8305270206	8305270202	83/04/07	50-259	G
8305270208	8305270204	83/05/13	50-184	G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305270211	8305270205	83/05/24	50-344 P
8305270212	8305270209	83/05/25	50-302 G
8305270219	8305270215	83/05/06	50-250 G
8305270226	8305270196	83/05/10	50-62 G
8305270227	8305270223	83/05/20	50-316 S
8305270230	8305270223	83/05/20	50-316 S
8305270231	8305270229	83/04/01	50-261 G
8305270233	8305270228	83/05/19	50-390 G
8305270236	8305270232	83/05/05	50-389 G
8305270244	8305270238	83/04/18	50-338 G
8305270245	8305270240	83/04/15	50-389 G
8305270248	8305270242	83/05/03	50-280 G
8305270252	8305270242	83/05/03	50-280 G
8305270253	8305270247	83/04/29	50-302 G
8305270254	8305270174	83/04/22	70-1201
8305270256	8305270250	83/04/29	50-324 G
8305270257	8305270242	83/05/03	50-280 G
8305270258	8305270247	83/04/29	50-302 G
8305270260	8305270247	83/04/29	50-302 G
8305270263	8305270250	83/04/29	50-324 G
8305270264	8305270247	83/04/29	50-302 G
8305270265	8305270242	83/05/03	50-280 G
8305270268	8305270250	83/04/29	50-324 G
8305270269	8305270247	83/04/29	50-302 G
8305270270	8305270261	83/05/25	50-341 G
8305270272	8305270267	83/05/13	QA999
8305270276	8305270250	83/04/29	50-324 G
8305270277	8305270267	83/05/13	QA999
8305270278	8305270273	83/05/06	50-537 G
8305270279	8305270259	83/05/19	50-269 P
8305270281	8305270271	83/05/16	50-400 G
8305270282	8305270205	83/05/24	50-344 P
8305270283	8305270275	83/05/12	50-416 G
8305270284	8305270274	83/05/23	50-333 G
8305270286	8305270267	83/05/13	QA999
8305270292	8305270271	83/05/16	50-400 G
8305270293	8305270289	83/03/29	50-389 G
8305270294	8305270259	83/05/19	50-269 P
8305270297	8305270287	83/05/06	50-335 G
8305270298	8305270291	83/05/13	QA999
8305270301	8305270271	83/05/16	50-400 G
8305270303	8305270290	83/03/23	50-390 G
8305270304	8305270288	83/03/23	50-332 G
8305270305	8305270296	83/05/20	50-275 P
8305270306	8305270300	83/03/30	50-416 G
8305270307	8305270291	83/05/13	QA999
8305270308	8305270271	83/05/16	50-400 G
8305270309	8305270259	83/05/19	50-269 P
8305270311	8305270302	83/05/10	QA999
8305270312	8305270280	83/05/20	50-302 G
8305270315	8305270310	83/03/30	50-389 G
8305270318	8305270260	83/05/20	50-302 G
8305270319	8305270314	83/04/14	50-537 G
8305270322	8305270313	83/03/23	50-327 G
8305270325	8305270316	83/03/23	50-62 G
8305270328	8305270320	83/05/10	50-424 G
8305270334	8305270324	83/03/25	50-413 G
8305270336	8305270332	83/04/27	50-321 G
8305270337	8305270330	83/03/28	50-424 G
8305270338	8305270326	83/05/06	50-269 G
8305270339	8305270329	83/05/06	50-335 G
8305270342	8305270333	83/05/10	50-324 G
8305270343	8305270332	83/04/27	50-321 G
8305270348	8305270341	83/03/31	50-400 G
8305270351	8305270332	83/04/27	50-321 G
8305270352	8305270340	83/05/25	50-333 P
8305270354	8305270347	83/04/06	50-302 G
8305270355	8305270345	83/05/09	50-259 G
8305270356	8305270350	83/05/11	50-321 G
8305270357	8305270332	83/04/27	50-321 G
8305270360	8305270349	83/04/19	50-389 G
8305270362	8305270345	83/05/09	50-259 G
8305270364	8305270340	83/05/25	50-333 P
8305270365	8305270349	83/04/19	50-389 G
8305270366	8305270327	83/04/04	50-369 G
8305270367	8305270359	83/04/26	50-335 G
8305270368	8305270345	83/05/09	50-259 G
8305270370	8305270358	83/03/30	50-348 G
8305270371	8305270349	83/04/19	50-389 G
8305270378	8305270340	83/05/25	50-333 P

ACCESSION NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY
8305270379	8305270349	83/04/19	50-389 G
8305270381	8305270345	83/05/09	50-259 G
8305270382	8305270327	83/04/04	50-369 G
8305270383	8305270377	83/04/14	50-400 G
8305270384	8305270376	83/05/06	50-250 G
8305270386	8305270372	83/05/04	50-438 G
8305270387	8305270374	83/05/06	50-269 G
8305270389	8305270380	83/05/04	50-261 G
8305270391	8305270377	83/04/14	50-400 G
8305270396	8305270372	83/05/04	50-438 G
8305270397	8305270377	83/04/14	50-400 G
8305270398	8305270372	83/05/04	50-438 G
8305270399	8305270392	83/05/20	50-333 G
8305270400	8305270388	83/05/19	50-416 G
8305270401	8305270390	83/04/26	50-261 G
8305270402	8305270385	83/03/29	50-369 G
8305270404	8305270393	83/04/21	50-413 G
8305270405	8305270327	83/04/04	50-369 G
8305270406	8305270377	83/04/14	50-400 G
8305270407	8305270394	83/04/07	50-338 G
8305270410	8305270388	83/05/19	50-416 G
8305270411	8305270403	83/04/05	50-269 G
8305270415	8305270372	83/05/04	50-438 G
8305270416	8305270394	83/04/07	50-338 G
8305270417	8305270409	83/03/28	50-416 G
8305270418	8305270388	83/05/19	50-416 G
8305270420	8305270413	83/05/09	50-390 G
8305270421	8305270394	83/04/07	50-338 G
8305270422	8305270412	83/04/11	50-395 G
8305270424	8305270388	83/05/19	50-416 G
8305270426	8305270414	83/05/09	50-338 G
8305270427	8305270409	83/03/28	50-416 G
8305270428	8305270327	83/04/04	50-369 G
8305270430	8305270394	83/04/07	50-338 G
8305270433	8305270412	83/04/11	50-395 G
8305270435	8305270425	83/05/11	50-269 G
8305270437	8305270414	83/05/09	50-338 G
8305270438	8305270388	83/05/19	50-416 G
8305270439	8305270423	83/04/29	50-280 G
8305270441	8305270431	83/04/13	50-395 G
8305270442	8305270394	83/04/07	50-338 G
8305270443	8305270412	83/04/11	50-395 G
8305270445	8305270434	83/05/20	50-309 G
8305270446	8305270436	83/04/25	50-395 G
8305270448	8305270414	83/05/09	50-338 G
8305270449	8305270431	83/04/13	50-395 G
8305270451	8305270440	83/05/16	50-331 S
8305270452	8305270431	83/04/13	50-395 G
8305270453	8305270447	83/04/04	50-389 G
8305270455	8305270414	83/05/09	50-338 G
8305270458	8305270431	83/04/13	50-395 G
8305270459	8305270450	83/04/06	70-1151
8305270460	8305270440	83/05/16	50-331 S
8305270462	8305270412	83/04/11	50-395 G
8305270466	8305270456	83/03/28	50-302 G
8305270467	8305270450	83/04/06	70-1151
8305270469	8305270465	83/04/22	50-111 G
8305270470	8305270463	83/04/05	50-416 G
8305270471	8305270450	83/04/06	70-1151
8305270474	8305270461	83/04/11	50-261 G
8305270478	8305270464	83/05/05	50-395 G
8305270480	8305270450	83/04/06	70-1151
8305270482	8305270472	83/04/06	50-537 G
8305270487	8305270479	83/04/07	50-261 G
8305270488	8305270481	83/05/18	TOPREP
8305270489	8305270476	83/05/24	50-454 G
8305270490	8305270483	83/04/04	50-280 G
8305270492	8305270484	83/05/04	50-400 G
8305270493	8305270486	83/05/06	50-305 G
8305270494	8305270479	83/04/07	50-261 G
8305270496	8305270468	83/03/25	50-518 G
8305270500	8305270479	83/04/07	50-261 G
8305270501	8305270476	83/05/24	50-454 G
8305270502	8305270486	83/05/06	50-305 G
8305270503	8305270499	83/04/13	50-302 G
8305270506	8305270479	83/04/07	50-261 G
8305270508	8305270491	83/04/07	50-366 G
8305270509	8305270499	83/04/13	50-302 G
8305270516	8305270499	83/04/13	50-302 G
8305270518	8305270497	83/04/05	50-269 G

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305270519	8305270512	83/05/10	50-395	Q
8305270520	8305270507	83/05/02	50-389	Q
8305270521	8305270511	83/04/27	50-369	Q
8305270522	8305270512	83/05/10	50-395	Q
8305270523	8305270491	83/04/07	50-366	Q
8305270525	8305270499	83/04/13	50-302	Q
8305270526	8305270514	83/03/30	50-259	Q
8305270527	8305270513	83/04/22	50-280	Q
8305270528	8305270510	83/04/22	50-259	Q
8305270529	8305270507	83/05/02	50-389	Q
8305270532	8305270512	83/05/10	50-395	Q
8305270534	8305270517	83/03/29	50-338	Q
8305270535	8305270507	83/05/02	50-389	Q
8305270536	8305270491	83/04/07	50-366	Q
8305270537	8305270524	83/04/11	50-438	Q
8305270541	8305270513	83/04/22	50-280	Q
8305270542	8305270507	83/05/02	50-389	Q
8305270544	8305270530	83/04/01	50-338	Q
8305270550	8305270491	83/04/07	50-366	Q
8305270551	8305270546	83/04/05	50-400	Q
8305270556	8305270548	83/04/20	70-27	
8305270562	8305270540	83/04/15	50-390	Q
8305270567	8305270557	83/05/02	50-390	Q
8305270572	8305270559	83/04/14	50-335	Q
8305270574	8305270565	83/03/29	50-280	Q
8305270576	8305270561	83/04/06	50-335	Q
8305270578	8305270571	83/05/19	50-244	Q
8305270579	8305270559	83/04/14	50-335	Q
8305270584	8305270559	83/04/14	50-335	Q
8305270587	8305270568	83/04/05	50-251	Q
8305270588	8305270580	83/05/06	50-324	Q
8305270592	8305270582	83/05/05	50-438	Q
8305270593	8305270585	83/04/25	50-416	Q
8305270594	8305270559	83/04/14	50-335	Q
8305270596	8305270585	83/04/25	50-416	Q
8305270597	8305270589	83/04/29	50-438	Q
8305270599	8305270580	83/05/06	50-324	Q
8305270601	8305270582	83/05/05	50-438	Q
8305270602	8305270590	83/04/13	50-413	Q
8305270607	8305270582	83/05/05	50-438	Q
8305270608	8305270589	83/04/29	50-438	Q
8305270610	8305270580	83/05/06	50-324	Q
8305270613	8305270600	83/05/25	70-143	
8305270614	8305270605	83/05/12	50-346	Q
8305270615	8305270609	83/05/10	50-400	Q
8305270616	8305270589	83/04/29	50-438	Q
8305270617	8305270580	83/05/06	50-324	Q
8305270618	8305270582	83/05/05	50-438	Q
8305270619	8305270589	83/04/29	50-438	Q
8305270620	8305270609	83/05/10	50-400	Q
8305270621	8305270580	83/05/06	50-324	Q
8305270626	8305270609	83/05/10	50-400	Q
8305270628	8305270580	83/05/06	50-324	Q
8305270629	8305270589	83/04/29	50-438	Q
8305270631	8305270609	83/05/10	50-400	Q
8305270632	8305270623	83/05/03	50-400	Q
8305270635	8305270580	83/05/06	50-324	Q
8305270639	8305270585	83/04/25	50-416	Q
8305270645	8305270638	83/05/19	50-410	Q
8305270648	8305270640	83/04/25	70-143	

ACCESSION NUMBER ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	
8305270652	8305270642	83/04/07	50-259	Q
8305270658	8305270642	83/04/07	50-259	Q
8305270659	8305270651	83/04/11	50-390	Q
8305270660	8305270653	83/04/13	50-259	Q
8305270661	8305270642	83/04/07	50-259	Q
8305270662	8305270656	83/05/24	50-412	Q
8305270664	8305270653	83/04/13	50-259	Q
8305270665	8305270653	83/04/13	50-259	Q
8305270666	8305270642	83/04/07	50-259	Q
8305270668	8305270653	83/04/13	50-259	Q
8305310003	8305230113	83/05/17	50-337	A
8305310004	8305310001	83/05/19	50-320	S
8305310007	8305310001	83/05/19	50-320	S
8305310010	8305310001	83/05/19	50-320	S
8305310014	8305310001	83/05/19	50-320	S
8305310019	8305310001	83/05/19	50-320	S
8305310022	8305310016	83/04/28	70-1201	
8305310024	8305310001	83/05/19	50-320	S
8305310030	8305310001	83/05/19	50-320	S
8305310036	8305310001	83/05/19	50-320	S
8305310041	8305310001	83/05/19	50-320	S
8305310047	8305310001	83/05/19	50-320	S
8305310056	8305310001	83/05/19	50-320	S
8305310057	8305310053	83/05/25	50-327	P
8305310061	8305310001	83/05/19	50-320	S
8305310066	8305310001	83/05/19	50-320	S
8305310070	8305310059	83/05/25	50-247	U
8305310072	8305310001	83/05/19	50-320	S
8305310078	8305310001	83/05/19	50-320	S
8305310080	8305310001	83/05/19	50-320	S
8305310084	8305310073	83/05/26	50-366	Q
8305310087	8305310001	83/05/19	50-320	S
8305310089	8305310083	83/05/20	50-269	P
8305310091	8305310001	83/05/19	50-320	S
8305310092	8305310073	83/05/26	50-366	Q
8305310096	8305310001	83/05/19	50-320	S
8305310097	8305310073	83/05/26	50-366	Q
8305310101	8305310001	83/05/19	50-320	S
8305310103	8305310058	83/05/25	50-320	P
8305310107	8305310001	83/05/19	50-320	S
8305310110	8305310104	83/05/25	50-482	Q
8305310112	8305310105	83/05/12	50-254	Q
8305310114	8305310001	83/05/19	50-320	S
8305310115	8305310109	83/04/06	70-1113	
8305310117	8305310113	83/05/24	50-237	Q
8305310133	8305310125	83/05/19	50-244	P
8305310134	8305310132	83/04/06	70-1113	
8305310135	8305310130	83/05/23	50-275	P
8305310140	8305310130	83/05/23	50-275	P
8305310141	8305310125	83/05/19	50-244	P
8305310153	8305310150	83/05/27	50-206	S
8305310157	8305310125	83/05/19	50-244	P
8305310159	8305310125	83/05/19	50-244	P
8305310181	8305310176	83/05/16	50-331	Q
8305310191	8305310186	83/05/26	50-275	R
8305310199	8305310194	83/05/25	50-313	Q
8305310203	8305310198	83/05/27	50-329	R
8305310220	8305310219	83/05/05	70-25	
8305310239	8305310238	83/05/20	50-309	H
8305310241	8305310240	83/05/17	50-285	P

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

1. Application for construction permit.
2. General Information submitted with construction permit application.
3. Amendments and changes to items 1 and 2.
4. NRC questions, requests for additional information, and applicant responses.
5. Correspondence and documents relating to unresolved design and construction issues.
6. Meeting announcements and summaries of meeting discussions on issues of item 5.
7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
9. Construction Permit, amendments, and correspondence relating to the construction permit.
10. Scheduling of license application submission or review.
11. Environmental review information.
12. Application for operating license.
13. General Information submitted with operating license application.
14. Amendments and changes to items 12 and 13.
15. Correspondence regarding the Final Safety Analysis Report (FSAR).
16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
17. Reports of site visits.
18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
2. Amendments and changes to the PSAR.

3. Transmittal and acknowledgement letters.

4. Certificates of service to the PSAR.

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

1. Environmental Report (ER) submitted by the utility

2. Amendments and supplements to the ER.

3. Transmittal and acknowledgement letters.

4. Information on scheduling of submittal or review of ER.

5. NRC questions, requests for additional information, and applicant responses.

6. Federal register notices citing the availability of items 1 and 2.

7. Correspondence relating to the review of ER.

8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.

2. Supplements to the DES and FES.

3. Correspondence relating to the DES and FES.

4. Comments from other federal, state and local government agencies.

5. Transmittal and acknowledgement letters.

6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.

7. Backup technical documents submitted in connection with above.

8. Federal register notice citing availability of items 1 and 2.

9. Site visits to obtain information for DES or FES.

10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report).

2. Supplements to SER.

3. Correspondence relating to SER.

4. Federal register notices citing availability of items 1 and 2.

5 Information on scheduling of SER submittals and review.

6. Requests for additional information for use in preparing SER; responses to such requests.

7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.

8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

1. Fire Hazard Protection Plan and surveys.

2 Plant evacuation correspondence.

3. Safeguards Contingency Plans.

4. Review of Health Physics Program.

5. Correspondence relating to aforementioned plans.

6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.

2. Federal register notices regarding hearings.

3. Requests to make appearances at hearings.

4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.

5. Transmittal of supporting documents (e.g., SER, FES) to the boards.

6. Correspondence to and from intervenors.

7. Board orders and decisions.

8. Petitions for Commission action.

9. Legal filings and Commission orders and decisions resulting from item 8.

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license Items that have no substantive technical content or meaning for the status of the license or application are included.

1. Change of address notifications.
2. Changes in structure of organization.
3. Changes in service lists.
4. NRC requests to applicant for additional copies of documents.
5. Correspondence from the public requesting information about the facility and NRC responses.
6. Correspondence on strictly administrative matters.
7. Letters of support, concern or opposition to the facility.
8. Correspondence regarding the Local Public Document Rooms (LPDRs).
9. Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

1. Company annual reports.
2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

1. Indemnity agreements and amendments.
2. Endorsements insurance policies.
3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
2. Amendments and changes to the FSAR.
3. Federal register notices citing availability of items 1 and 2.
4. Transmittal and acknowledgement letters.
5. Certificates of service to the FSAR.

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

1. Limited Work Authorizations (LWA) and amendments.

2. Correspondence pertaining to work performed under LWA s.

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

1. Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review".

2. Correspondence where the primary topic of discussion is antitrust matters.

3. All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.

2. Correspondence from ACRS.

3. Announcement of ACRS meetings.

4. Transmittal and acknowledgement letters.

5. ACRS reports.

6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.

7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

1. Operating license, amendments, proposed amendments, changes and related correspondence.

2. Technical specifications and changes.

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

1 Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches

2. Preparatory and backup documents for item 1.

3 Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

1. Operator licenses or administrative information bearing on licensing of operators.

2. NRC examination results.

3. Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

1. Application for authority to voluntarily surrender license.

2. Application to dismantle the facility and dispose of component parts.

3 Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.

4. Documents relating to disposal of radioactive material and decontamination of the site.

5. Other correspondence relating to above items.

6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)

2. All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR – Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

1. Sunshine Act Federal Register notices.
2. Full, written explanation of closed meetings.
3. Certification of General Counsel on closed meetings.
4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS – Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
2. ACRS meeting announcements; description of meeting agendas.
3. ACRS-generated reports, memoranda and correspondence that are publicly available.
4. ACRS consultant reports, comments and related correspondence.
5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM – NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

1. Charters of each advisory committee.
2. Verbatim transcripts of committee meetings.

3. Meeting announcements, description of meeting agendas.

4. Committee generated reports, memoranda, and correspondence that are publicly available.

5. Committee related correspondence.

COMMISSION – NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.

2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners

3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT – NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including

1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).

2. Solicitations (RFP or IFB) issued by the NRC.

3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.

4. Contractual documents and contract modifications, if any.

DISCLOSURE – Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA – Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year-numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.

2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.

3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS – Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues
3. Meeting notifications and minutes.
4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E – Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE. For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC – Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG – NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:
   a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
   b. They present the results of Commission licensing and policy decisions.
   c. They present the results of technical research conducted for the Commission.
2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG – Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are.

1 Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.

2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.

3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.

4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE. For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR – Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.

2. Text of the Proposed Rule (PR).

3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM – Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.

2. Federal Register cause notices of the filing of the petition.

3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.

4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ – Projects–Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for whicl NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

I. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

A. Application/Construction Stage

1. Application submitted by the utility.

2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.

3. Applicant's Quality Assurance Manual.

4. Early site review information.

5. Backup technical documents submitted in support of the application.

6. Early site visits.

B. Utility PSAR and Amendments

1. PSARs submitted by the utility.

2. Amendments and changes to the PSAR.

3. Transmittal letters.

4. Letters acknowledging receipt of the PSAR.

G. Adjudicatory Correspondence

1. Motions, briefs, orders, *et al.* pertaining to pre-hearing conferences, if any.

M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

1. Inspection reports of the applicant's quality assurance program.

2. Notices of deviations.

3. Follow-up correspondence resolving deviations cited.

2 Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 – Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.

2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.

3. NRC inspection reports of defects cited.

4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 – Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.

2. Notices of deviations.

3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD – Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

1 Federal Register notices announcing the issuance and availability of a proposed regulatory guide.

2. Revised or newly issued Regulatory Guides.

3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide

4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.

5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES – Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

1. Project description documents.

2. Letter reports of accomplishments and data reports; for example,

   a. model documentation reports
   b. code documentation reports
   c. code verification reports

3. Pre-test prediction reports.

4. "Quick look" reports.

5. Informal experimental data reports and post-irradiation examination analyses.

6. Conceptual design descriptions.

7. Letter reports of foreign travel and site visits by contractors.

8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.

9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.

10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP – NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

1. Agendas for quarterly review group meetings.
2. Summary minutes of review group meetings representing views expressed, including dissenting views.
3. Research plans and predicted results of major experiments; presentations by research contractors.
4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
5. Internal memoranda relating to topics under discussion.

RM – Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

1. Designations of the presiding officer and any special directions for the conduct of the hearing.
2. Notifications of hearing board meetings.
3. Petitions, motions, testimony and statements submitted by parties to the hearings.
4. Hearing board orders and rulings.
5. Technical reports submitted as evidence in the proceeding.
6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY – Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG – State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (5) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes

1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:

   a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.

   b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.

2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting

3. State Legislative Reports.

4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP – Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.

2. Revisions, modifications and amendments to topical reports.

3. Correspondence between NRC and vendors pertaining to the review of submittals.

4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT – Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.

2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

3 Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.

4 NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC – Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
3. Commission letters requesting Executive Branch views.
4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
5. Correspondence from foreign governments, international organizations, and members of the public
6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
7. Filings pursuant to hearing requests or intervention petitions, if any.
8. Hearing records and decisions.
9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 (11 81)

U.S NUCLEAR REGULATORY COMMISSION

BIBLIOGRAPHIC DATA SHEET

1 REPORT NUMBER (Assigned by DDC)
NUREG-0540
Vol. 5, No. 5

4 TITLE AND SUBTITLE (Add Volume No., if appropriate)
Title List of Documents Made Publicly Available
May 1-31, 1983

2 (Leave blank)

3 RECIPIENT'S ACCESSION NO

7 AUTHOR(S)

5 DATE REPORT COMPLETED
MONTH | YEAR

9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)
Division of Technical Information and Document Control
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, DC 20555

DATE REPORT ISSUED
MONTH: August | YEAR: 1983

6 (Leave blank)

8 (Leave blank)

12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)
Same as 9, above.

10 PROJECT/TASK/WORK UNIT NO

11 FIN NO

13 TYPE OF REPORT
Monthly

PERIOD COVERED (Inclusive dates)
May 1-31, 1983

15. SUPPLEMENTARY NOTES

14 (Leave blank)

16 ABSTRACT (200 words or less)

This document is a monthly publication containing descriptions of information received and generated by the U.S. NRC. This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials, and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. The following indexes are included: Personal Author Index, Corporate Source Index, Report Number Index, and Cross Reference to Principal Documents Index.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a DESCRIPTORS

17b IDENTIFIERS/OPEN-ENDED TERMS

18 AVAILABILITY STATEMENT
Unlimited

19 SECURITY CLASS (This report)
Unclassified

20 SECURITY CLASS (This page)
Unclassified

21 NO OF PAGES

22 PRICE
$